




Golder Associates Inc.

5200 Pasadena N.E., Suite C
Albuquerque, NM USA 87113
Telephone (505) 821-3043
Fax (505) 821-5273
www.golder.com



December 11, 2006

Rod B



Mr. Steve Reuter
NMED PSTB
5500 San Antonio Drive NE
Albuquerque, New Mexico 87109

**RE: WELL PLUGGING AND ABANDONMENT REPORT,
RENTAL PROPERTY SITE, MURRAY ROAD,
ALBUQUERQUE, NEW MEXICO**

Dear Mr. Reuter:

On December 5, 2006 Golder representatives provided oversight for the plugging and abandonment of the monitor wells MW-1, MW-2, MW-4 and vapor well VW-1 at the Rental Property Site located at 204 Murray Road, Albuquerque, New Mexico.

The wells were plugged and abandoned by removing the concrete pad and well vaults. The wells were then grouted to within one foot of the surface with bentonite/cement grout pumped through a tremmie pipe, followed by the removal of the top foot of casing. Finally, the remaining hole was filled with neat cement grout to the surface and soil placed on top. Attached is photographic documentation of the well abandonments.

If you have any questions please do not hesitate to call me at (505) 821-3043.

Sincerely,

GOLDER ASSOCIATES INC.

Teri McMillan

Teri McMillan
Senior Scientist

Attachments: Photographic Documentation

cc: Karen Macy
Bart Farris, NMED GWQB



MW-1 - BEFORE ABANDONMENT



MW-1 - AFTER CONCRETE REMOVED



MW-1 - FILLED WITH BENTONITE / CEMENT GROUT BY TREMIE PIPE



MW-1 - FINISHED COVER

PROJECT

PHOTOGRAPHS
WELLS PLUGGED AND
ABANDONED

TITLE

PROJECT No. XXX

FILE No.

PLUG & ABANDONED.DWG

REV.

DESIGN TM 12/07/06

CADD RLO

12/07/06

CHECK

TM 12/07/06

REVIEW

JS 12/07/06

PHOTO SET
1



MW-2 - BEFORE ABANDONMENT



MW-2 - FILLED WITH BENTONITE / CEMENT GROUT BY TREMIE PIPE



MW-2 - FINISHED COVER

PROJECT		RENTAL PROPERTY	
PHOTOGRAPHS		MURRAY ROAD	
WELLS PLUGGED AND		ALBUQUERQUE, NEW MEXICO	
TITLE			
PROJECT No.	XXX		
FILE No.	PLUG & ABANDONED.DWG		
REV.			
DESIGN	TM	12/07/06	
CADD	RLO	12/07/06	
CHECK	TM	12/07/06	
REVIEW	JS	12/07/06	
PHOTO SET		2	




MW-4 - BEFORE ABANDONMENT



MW-4 - FILLING WITH BENTONITE / CEMENT GROUT BY TREMIE PIPE



MW-4 - FILLED WITH BENTONITE / CEMENT GROUT BY TREMIE PIPE



MW-4 - FINISHED COVER

PROJECT		PHOTOGRAPHS		RENTAL PROPERTY	
TITLE		WELLS PLUGGED AND ABANDONED		MURRAY ROAD ALBUQUERQUE, NEW MEXICO	
FILE No.	PROJECT No.	PLUG & ABANDONED.DWG	XXX		
REV.	DESIGN	TM	12/07/06		
	CADD	RLO	12/07/06		
	CHECK	TM	12/07/06		
	REVIEW	JS	12/07/06		
PHOTO SET					
3					



VM-1 - BEFORE ABANDONMENT



VM-1 - FILLED WITH BENTONITE / CEMENT GROUT BY TREMIE PIPE



VM-1 - FINISHED COVER

PROJECT	PHOTOGRAPHS	RENTAL PROPERTY
FILE No. PLUG & ABANDONED.DWG	WELLS PLUGGED AND ABANDONED	MURRAY ROAD
REV.		ALBUQUERQUE, NEW MEXICO
DESIGN	TM	12/07/06
CADD	RLO	12/07/06
CHECK	TM	12/07/06
REVIEW	JS	12/07/06
PHOTO SET		4