Phase I Environmental Site Assessment

Lopez Cleaners

838 East Palace Avenue

Santa Fe, New Mexico 87501

Prepared for:

New Mexico Environment Department
Ground Water Quality Bureau
1190 S St Francis Dr
Santa Fe, NM 87505

Prepared by:

INTERA Incorporated
2440 Louisiana Blvd SE Suite 700
Albuquerque, NM 87110
505.246.1600

JUNE 12, 2026

Executive Summary

This report documents the methods, findings, opinions, and conclusions of a Phase I Environmental Site Assessment (ESA) performed by INTERA Incorporated (INTERA) for Lopez Cleaners located at 838 East Palace Avenue (Ave) Santa Fe, Santa Fe County, New Mexico (**Figure 1**). The New Mexico Environment Department (NMED) Ground Water Quality Bureau (GWQB) (User) is using its Professional Services Contract #24-667-2030-27724, Work Order Number INTE08-ROS-21, to contract the performance of a due diligence assessment of the Subject Property. The Phase I ESA was conducted to document current and former conditions relative to historical operations at the Site.

INTERA performed this Phase I ESA following the procedures of Standard Practice E1527-21 of American Society for Testing and Materials International (ASTM), entitled *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process* (ASTM, 2021). The objective of the Phase I ESA was (1) to identify, to the extent possible, any *recognized environmental conditions* (RECs) as defined by the ASTM and (2) to collect reasonably ascertainable information about the environmental condition of the Subject Property. Additionally, based on reviews of Subject Property, adjoining properties, and vicinity properties' findings within the default *area of concern* (AOC) as defined by ASTM Standard E2600-22, *Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions* (ASTM, 2022), *vapor encroachment conditions* (VECs) were also assessed for the migration potential of hazardous substances and/or petroleum products within or near the Subject Property.

The Subject Property is an approximately 0.17-acre parcel located in a residential area, developed with a two-story and a single-story structure, both of which are listed as dwellings and were built in 1927. Property records indicate the only other onsite structure as a utility shed constructed in 2005 (Santa Fe County Assessor [SFCA], 2026). The Subject Property is surrounded by other residential parcels to the north, west, and south. East Palace Avenue bounds the Subject Property on the east side with a vacant commercial property across the street, and is otherwise surrounded by residential properties. The Subject Property's immediate vicinity is depicted on **Figure 2**.

The Phase I ESA included:

- a review of the Subject Property and adjoining properties' historical and current land use records,
- review of standard environmental regulatory agency records, and
- a limited visual site reconnaissance.

These activities were performed to assess sources of surface and subsurface contamination that potentially exist at the Subject Property and within ASTM-specified distances from the Subject Property. This information was integrated with the physical setting data and future occupancy or development plans for the Subject Property to form an opinion concerning whether properties found to be a potential source of contamination may, in fact, be a REC with regard to the Subject Property as defined by ASTM. The Phase I ESA was performed by environmental professional(s) as defined in 40 Code of Federal Regulations (CFR) §312.10 and as identified in this report.

INTERA has performed a Phase I ESA in conformance with the scope and limitations of ASTM Standard E1527-21 for the Subject Property. Based on the completion of the scope of services provided in support of this Phase I ESA, one REC and one VEC were identified in connection with the Subject Property, as follows:

- Approximately 23 years (1955-1978) of dry cleaning operations conducted at the Subject Property and the *significant data gap* identified due to the environmental professional not having physical access to the Subject Property or building interiors nor anyone with firsthand knowledge of the historical use of the Subject Property is considered a **REC**/**VEC** in connection with the Subject Property.

Based on the conclusions of this Phase I ESA, INTERA recommends the following:

- Perform a Phase II site investigation to assess the potential impacts to environmental media from the REC identified in connection with the Subject Property.

Table of Contents

1.0 Introduction 1
1.1 Purpose 1
1.2 Detailed Scope of Services 1
1.2.1 Vapor Encroachment Considerations 2
1.2.2 Non-Scope Environmental Considerations 3
1.3 Significant Assumptions 3
1.4 Limitations and Exceptions 4
1.5 Special Terms and Conditions 4
1.6 User Reliance 4
2.0 Site Description 6
2.1 Location and Legal Description 6
2.2 Site Vicinity and General Characteristics 6
2.3 Physical Setting 7
2.3.1 Topography and Watershed 7
2.3.2 Average Precipitation and Temperature 7
2.3.3 Flood Plain 7
2.3.4 Soil Characterization 7
2.3.5 Geology and Hydrogeology 7
2.4 Descriptions and Current Uses of Adjoining Properties 8
3.0 User-Provided Information 10
4.0 Records Review 11
4.1 Historical Use of the Site and Adjoining Properties 11
4.1.1 Chain of Title and Environmental Lien Search 11
4.1.2 Historical Topographic Maps 11
4.1.3 Historical Aerial Photographs 12
4.1.4 Fire Insurance Maps 14
4.1.5 Historical City Directories 14
4.2 Environmental Database Records Review 15
4.2.1 Mapped Locations 16
4.3 Regulatory Agency and Supplemental Records Review 16
5.0 Site Reconnaissance 17
5.1 Methodology and Limiting Conditions 17

5.2 Subject Property 17
5.3 Adjoining Properties 18
5.4 Surrounding Properties 18
6.0 Interviews 19
6.1 Key Site Manager 19
6.2 Local Government Officials 19
7.0 Findings and Opinions 20
7.1 Subject Property Findings and Opinions 20
7.2 Adjoining Property Findings and Opinions 20
7.3 Vicinity Findings and Opinions 20
7.4 Tier 1 Vapor Encroachment Screening 20
7.5 Data Gaps 21
8.0 Conclusions 22
9.0 Recommendations 23
10.0 References 24
11.0 Disclaimer 25
12.0 Qualifications and Signatures of Environmental Professionals 26

List of Appendices

Appendix A Environmental Lien and Activity and Use Limitation Search
Appendix B Historical Topographic Maps
Appendix C Historical Aerial Photographs
Appendix D Physical Setting Documentation
Appendix E User Provided Information [RESERVED]
Appendix F Historical Fire Insurance Maps
Appendix G Historical City Directories
Appendix H Database Report
Appendix I Supplemental Records [RESERVED]
Appendix J Photographic Log
Appendix K Interviews [RESERVED]
Appendix L Qualifications of Environmental Professionals

List of Figures

Figure 1 Site Location Map
Figure 2 Site Plan

List of Tables

Table 1. Summary of Subject Property Tax Parcel(s) Information 6
Table 2. User-Provided Information 10
Table 3. City Directory Listings 15
Table 4. File Review Information 16

Acronyms and Abbreviations

AAI	All Appropriate Inquiry
AMSD	approximate minimum search distance
AOC	Area of Concern
ASTM	American Society for Testing and Materials International
AUL	Activity and Use Limitation
bgs	below ground surface
CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act
CFR	Code of Federal Regulations
COC	chemical of concern
EPA	United States Environmental Protection Agency
ERIS	Environmental Risk Information Services
ESA	Environmental Site Assessment
°F	degrees Fahrenheit
FIM	Fire Insurance Map
ft	foot/feet
ft^2	square foot/feet
GWQB	Ground Water Quality Bureau
INTERA	INTERA Incorporated
msl	mean sea level
NMED	New Mexico Environment Department
NMOSE	New Mexico Office of the State Engineer
NOAA	National Oceanic and Atmospheric Administration
PCB	polychlorinated biphenyl
POD	Point of Diversion
RCRA	Resource Conservation and Recovery Act of 1976
REC	Recognized Environmental Condition
Site or Subject Property	838 East Palace Ave Santa Fe, New Mexico
SFCA	Santa Fe County Assessor
User	New Mexico Environment Department Ground Water Quality Bureau
USGS	United States Geological Survey

UST	underground storage tank
VEC	Vapor Encroachment Condition
VES	Vapor Encroachment Screening

1.0 Introduction

INTERA Incorporated (INTERA) under contract with the New Mexico Environment Department (NMED) Ground Water Quality Bureau (GWQB) (User), was tasked to perform a Phase I Environmental Site Assessment (ESA) of the former Lopez Cleaners located at 838 East Palace Avenue in Santa Fe, Santa Fe County, New Mexico 87501, hereafter referred to as the Site or Subject Property (Santa Fe County Assessor [SFCA], 2026). The location of the Subject Property is illustrated in **Figure 1.**

The User is funding consultant resources from its Professional Services Contract #24-667-2030-27724, Work Order Number INTE08-ROS-21, to document current and historical conditions relative to historical operations at the Site.

1.1 Purpose

This Phase I ESA was performed (1) to identify, to the extent possible, any recognized environmental conditions (RECs), defined below in **Section 1.2**, and (2) to collect all reasonably ascertainable information about the environmental condition of the Subject Property. This was performed, consistent with good commercial and customary practice, to allow potential future redevelopment of the Subject Property and to qualify the User for statutory limitations on potential liability under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), a.k.a. Superfund.

This Phase I ESA was performed to meet the assessment and all appropriate inquiries (AAIs) requirements of American Society for Testing and Materials International (ASTM) Standard E1527-21, *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process* (ASTM, 2021). In 2005, the United States Environmental Protection Agency (EPA) issued *Standards and Practices for All Appropriate Inquiries, Final Rule* (EPA final rule; EPA, 2005), and in 2021 ASTM issued ASTM Standard E1527-21 (ASTM, 2021). Both the EPA final rule and the 2021 ASTM Standard E1527-21 implement the CERCLA as amended by the Small Business Liability Relief and Brownfields Revitalization Act of 2002. Under the EPA final rule, effective on November 1, 2006, satisfaction of the CERCLA AAI requirement for liability protection as an innocent landowner, a bona fide prospective purchaser, or a contiguous landowner is met by an assessment conducted in accordance with ASTM Standard E1527-21.

1.2 Detailed Scope of Services

In general, the Phase I ESA scope of services included the following four components:

- Records review,
- Site reconnaissance,
- Interviews, and
- Report.

INTERA has completed a Phase I ESA for the Subject Property in accordance with ASTM Standard E1527-21, with the exception of any deviations listed in **Section 1.4** or data gaps listed in **Section 7.5**.

For the purposes of this Phase I ESA report, the definition of the term "*Recognized Environmental Condition*" is as outlined in Section 3.2.73 of ASTM Standard E1527-21:

> "(1) the presence of *hazardous substances* or *petroleum products* in, on, or at the *subject property* due to *release or likely release* to the *environment*; (2) the likely presence of *hazardous substances* or *petroleum products* in, on, or at the *subject property* due to a *release* to the *environment*; or (3) the presence of *hazardous substances* or *petroleum products* in, on, or at the *subject property* under conditions that pose a *material threat* of a future *release* to the *environment.*" (ASTM, 2021, p. 8)

For the purposes of this Phase I ESA report, the definition of the term "*Historical Recognized Environmental Condition*" is as outlined in Section 3.2.39 of ASTM Standard E1527-21:

> "A previous *release* of any *hazardous substances* or *petroleum products* affecting the *subject property* that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the *subject property* to any controls (for example, *activity and use limitations* or other *property use limitations*). A *historical recognized environmental condition* is not a *recognized environmental condition*." (ASTM, 2021, p. 6)

For the purposes of this Phase I ESA report, the definition of the term "*Controlled Recognized Environmental Condition*" is as outlined in Section 3.2.17 of ASTM Standard E1527-21:

> "*A recognized environmental condition* affecting the *subject property* that has been addressed to the satisfaction of the applicable regulatory authority or authorities with *hazardous substances* or *petroleum products* allowed to remain in place subject to the implementation of required controls (for example, activity and use limitations or other property use limitations)." (ASTM, 2021, p. 4)

An additional term related to this Phase I ESA report is "*de minimis condition*". It is defined by Section 3.2.20 of ASTM Standard E1527-21 as:

> "a condition related to a *release* that generally does not present a threat to human health or the *environment* and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. A condition determined to be a *de minimis condition* is not a *recognized environmental condition* nor a *controlled recognized environmental condition.*" (ASTM, 2021, pp. 4-5)

1.2.1 Vapor Encroachment Considerations

ASTM Standard E1527-21 requires the assessment of the migration potential of hazardous substances and/or petroleum products within or near the Subject Property.

The definition of the term "*migrate/migration*" is outlined in Section 3.2.53 of ASTM Standard E1527-21:

> "…the movement of *hazardous substances* or *petroleum products* in any form, including, for example, solid and liquid at the surface or subsurface, and vapor in the subsurface." (ASTM, 2021, p. 7)

Vapor migration in the subsurface is described in ASTM Standard E2600-22, *Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions* (ASTM, 2022); however, ASTM Standard E1527-21 does not require its application to achieve compliance with AAI (ASTM, 2021, p. 7).

In order to assess potential migration of hazardous substances and/or petroleum products that may migrate as vapors into the vadose zone as a result of contaminated soil and/or groundwater on or near the Subject Property, INTERA has completed a Tier 1 Vapor Encroachment Screening (VES) in accordance with ASTM Standard E2600-22 for the Subject Property. The objective of the VES is to determine if a vapor encroachment condition (VEC) exists at the Subject Property. For the purposes of this Phase I ESA report, the definition of the term "*Vapor Encroachment Condition*" is as outlined in Section 3.2.37 of ASTM Standard E2600-22:

> "[The] presence or likely presence of [chemical of concern (COC)] vapors in the vadose zone of the [Subject Property] caused by the release of vapors from contaminated soil and/or groundwater either on or near the [Subject Property]…" (ASTM, 2022, p. 4)

The results of the Tier 1 VES are presented in **Section 7.4.**

1.2.2 Non-Scope Environmental Considerations

Non-scope environmental considerations such as those identified in Section 13.1.5 of ASTM E1527-21 were not evaluated as part of this ESA. Non-scope considerations may include, but are not limited to: presence of potential asbestos-containing building materials unrelated to releases into the environment; biological agents; cultural and historic resources, ecological resources; endangered species; health and safety; indoor air quality unrelated to releases of hazardous substances or petroleum products into the environment; industrial hygiene; presence of potential lead-based paint unrelated to releases into the environment; lead in drinking water; mold or microbial growth conditions; polychlorinated biphenyl (PCB)-containing building materials; naturally-occurring radon; regulatory compliance; substances not defined as hazardous substances (including some substances sometimes generally referred to as emerging contaminants) unless or until such substances are classified as a CERCLA hazardous substance; and wetlands (ASTM, 2021, p. 25).

1.3 Significant Assumptions

Significant assumptions pertaining to this Phase I ESA are briefly summarized as follows:

- Environmental database information (and facility locations) generated by Environmental Risk Information Services (ERIS) is accurate and complete,
- The User has provided INTERA with all the information in its possession that would help determine the presence of RECs,
- Interview information provided to INTERA by various parties and individuals is accurate and was provided without bias, and
- Publicly available reasonably ascertainable information accessed by INTERA is accurate and complete.

The significant assumptions underlying the preparation of any Phase I ESA are specified in the principles set forth by ASTM Standard E1527-21. The principles are presented in their entirety in Section 4.5 of ASTM Standard E1527-21 (ASTM, 2021, p. 10).

1.4 Limitations and Exceptions

Any Phase I ESA is by nature limited and qualitative in scope, being based predominantly on the examination of selected maps, agency records, interviews, and visual and/or physical observations made during the site reconnaissance. As such, this Phase I ESA should not be construed to be a complete characterization of environmental regulatory compliance of conditions above or below ground surface (bgs) at the Subject Property. Instead, the ESA process is designed to provide information regarding apparent existing or potential adverse environmental conditions related to the Subject Property in accordance with good commercial and customary practice. Any significant data gaps that would further limit the scope of the Phase I ESA are identified in **Section 7.5**.

This Phase I ESA is limited to the reasonably ascertainable information available or known to INTERA as of the date of this report. Consistent with ASTM Standard E1527-21, no intrusive testing or sampling of concealed or subsurface conditions was performed at the Subject Property as part of this Phase I ESA. The findings, opinions, and conclusions contained in this report are limited to those that could be identified during the Phase I ESA performed in accordance with ASTM Standard E1527-21. INTERA has accepted as true the information provided by interviewees on current and historical uses of the Subject Property and surrounding area. INTERA does not warrant or guarantee the accuracy or completeness of information provided by other sources.

INTERA represents that the Phase I ESA was performed in a competent manner by environmental professionals, consistent with the practices and procedures contemplated under ASTM E1527-21. However, even with proper application of the ASTM methodology, environmental conditions may be present that cannot be identified within the scope of the Phase I ESA or that may not be reasonably identifiable from the available information. As such, no warranty is expressed or implied as to the findings, conclusions, and/or recommendations presented in this Phase I ESA Report beyond matters amenable to empirical review and visual confirmation within the limits under ASTM E1527-21 and/or the specified scope of work.

1.5 Special Terms and Conditions

Since a property transaction was not part of the rationale for conducting the Phase I ESA, some of the discussion related to purpose, liability protection, and User reliance herein may not be relevant. This language is included for consistency and transparency of describing the intention of the Phase I ESA to meet the ASTM Standard.

1.6 User Reliance

This Phase I ESA has been prepared for the use of the User. There are no third-party rights or benefits conferred under this report. Use of or reliance on this Phase I ESA report by any third party is at the sole risk of that party.

This Phase I ESA is valid for 180 days prior to acquisition of the Site and/or transactions not involving acquisition of the Site. In accordance with the ASTM Standard, if the Phase I ESA is to be used by a different user other than the intended user within the 180 days, then the new user must satisfy the requirements in Section 6 of ASTM E1527-21. The Phase I ESA can be valid for longer if the Phase I ESA has been updated within one year of the date of acquisition or intended transaction, provided that the following components have been completed within 180 days of the acquisition or transaction: interviews; searches for recorded environmental cleanup liens; review of federal, tribal, state, and local government records; visual inspection of the property and of adjoining properties; and the declaration by the environmental professional responsible for the assessment or update (ASTM, 2021, p. 11).

2.0 Site Description

As required by ASTM Standard E1527-21, INTERA gathered information concerning the location, characteristics, current land uses, and physical improvements of the Subject Property, adjoining properties, and vicinity properties. Sources for this information were United States Geological Survey (USGS) 7.5-minute historical topographic maps, geologic and hydrologic publications, aerial photographs, observations made during the site reconnaissance, interviews, and consulting other publicly available information.

The Subject Property is a residential property developed with two residential free-standing structures, a 2,166-square-foot (ft^2) dwelling and a 662-ft^2 dwelling, both of which were built in 1927. An additional free-standing 100-ft^2 structure, listed as a utility shed, was built in 2005 (SFCA, 2026). The remainder of the rectangular parcel is covered by a gravel surface with a perimeter fence, and vegetated with trees along the south and east property lines. Adjoining properties are described in **Section 2.4.** The Site and immediate vicinity thereof are depicted in **Figure 2.**

2.1 Location and Legal Description

The Subject Property is composed of one approximately 0.17-acre Santa Fe County parcel of land in Santa Fe, New Mexico. General real estate property tax information for the Subject Property was gathered from Santa Fe County Assessor's website, summarized in **Table 1** (SFCA, 2026).

Table 1. Summary of Subject Property Tax Parcel(s) Information

Physical Address	838 E PALACE AVE and 838 1/2 E PALACE AVE
Owner Name	BURCHELL PALACE LLC
Parcel ID	11377792 AND 1-055-098-150-524
Legal Description	T17N R10E S30, TRACT OF LAND SITUATE AT 838 EAST PALACE AVENUE, BLK 7, LOT 19~
Size (acres)	0.16550000
Deed Date	10/12/2024
Instrument	2046489

An Environmental Lien and Activity and Use Limitation (AUL) search was performed for the Subject Property parcel for the current owner. No environmental liens or AULs were identified for the Subject Property in the Liean Search Report (ERIS, 2025a – **Appendix A**).

2.2 Site Vicinity and General Characteristics

ASTM Standard E1527-21 specifies that the only standard physical setting source that must be checked during the Phase I ESA is the current USGS 7.5-minute topographic map (or equivalent) (USGS, 2022). Other physical setting sources used for this Phase I ESA were historical topographic maps (ERIS, 2025b – **Appendix B**) and historical aerial photographs (ERIS, 2025c – **Appendix C**), discussed in **Section 4.**

2.3 Physical Setting

Several sources were reviewed to determine the physical setting of the Subject Property. Information from published physical settings maps (ERIS, 2025d – **Appendix D**) are discussed in the following subsections.

2.3.1 Topography and Watershed

The most recent (2023) USGS 7.5-minute topographic map of the site area was obtained and reviewed as specified in ASTM Standard E1527-21 Section 8.2.1 (ASTM, 2021). The USGS Santa Fe, NM quadrangle provides coverage of the Subject Property and vicinity (USGS, 2023). Historical topographic maps were reviewed for surface topography and drainage information in the vicinity of the Subject Property, and are provided in **Appendix B.**

The topographic maps indicate the Subject Property is relatively flat, with a surface elevation of approximately 7,080 feet (ft) mean seal level (msl) with the 7,080 ft elevation contour bisecting the eastern and western portions of the Site with the land surface gently sloping to the west away from East Palace Avenue. The nearest body of water is the Santa Fe River, which is immediately west of East Alameda Street, approximately 100 ft west of the western Subject Property boundary. The site topography was confirmed during the site reconnaissance (**Section 5**). Surface drainage at the Subject Property appears to follow the land surface topography (**Figure 1**).

2.3.2 Average Precipitation and Temperature

The average annual precipitation in Santa Fe, New Mexico is approximately 13.69 inches per year. Most of the precipitation historically occurs in July. The highest average temperature historically is in July, at 72.2 degrees Fahrenheit (°F); the lowest average temperature historically is in January, at 31.6 °F (NOAA, 2026).

2.3.3 Flood Plain

Approximately 50% of the Subject Property, the western side, is within the 500-year floodplain, indicating a 0.2% annual chance of flooding hazard (Flood Zone X-01). The eastern half of the Subject Property is within an area of “minimal flood hazard” (Flood Zone X-12) (ERIS, 2025d – **Appendix D**).

2.3.4 Soil Characterization

The soil map provided by ERIS was reviewed to identify local surface soils underlying the Site. The soil at the Subject Property is composed entirely of the Delvalle-Urban land complex, 0 to 2 percent slopes. This is a well-drained soil with a low runoff potential when thoroughly wet. Water is generally transmitted freely through the soil (ERIS, 2025d).

2.3.5 Geology and Hydrogeology

The Subject Property is located near the foot of the Sangre de Cristo Mountains, the southernmost subrange of the Rocky Mountains. Santa Fe is located on a large system of dissected alluvial fans stretching from the foot of the Sangre de Cristos to the bottom of the Rio Grande rift valley. The

geologic map provided by ERIS (ERIS 2025d – **Appendix D**) and the USGS Geologic Map Viewer (2025) were reviewed to determine the general geologic setting at the Subject Property (USGS, 2025). The geologic maps show that the Subject Property is underlain by older Quaternary alluvium (Qoa). In the immediate area, there are also Quaternary piedmont deposits and older (Quaternary to Oligocene) alluvial fan-type deposits of the Santa Fe Group. The low hills to the south of the Subject Property are made up of younger Quaternary-aged Santa Fe Group, and the taller hills to the north are made up of older Tertiary-aged Santa Fe Group. The source of the sediment that makes up this alluvial fan system is primarily the Mesoproterozoic and Paleoproterozoic plutonic bedrock that makes up the Sangre de Cristo Mountains directly to the east.

The primary source of groundwater around the Subject Property is the series of aquifers within the Santa Fe Group, which is primarily unconsolidated silts, sands, and gravels. ERIS reports a total of 364 water wells within a one-mile radius of the Subject Property. Sources queried included:

- Public Water Systems Violations and Enforcement Data,
- Safe Drinking Water Information System,
- USGS National Water Information System,
- The New Mexico Office of the State Engineer (NMOSE) Point of Diversion (POD) Database.

Of the four wells listed within 500 ft of the Subject Property, the reported depth to water is 21 ft bgs (ERIS, 2025d). Groundwater generally flows to the northwest in this area, following the surface gradient down to the Santa Fe River.

The geologic map provided by ERIS (ERIS 2025d – **Appendix D**) was reviewed to determine the general geologic setting at the Subject Property. The geologic maps show that the Subject Property is underlain entirely by middle to lower Pleistocene alluvial deposits (Qoa) of upland plains and piedmont areas, and calcic soils and eolian cover sediments of the High Plains region.

2.4 Descriptions and Current Uses of Adjoining Properties

The Subject Property is bound by the following:

- The northern adjoining property is developed with a multi-unit residential dwelling listed as 836 East Palace Avenue A and 836 East Palace Avenue B on Santa Fe County Tax Parcel No. 11531392. The northern Subject Property boundary is demarcated by a fence.
- A municipal sidewalk is observed along the eastern Subject Property boundary, beyond which is East Palace Avenue. A vacant commercial building located at 853 East Palace Avenue (Santa Fe County Tax Parcel No. 99306029) is the adjoining property across East Palace Avenue.
- The southern adjoining property is developed with a multi-tenant residential dwelling listed by the Santa Fe County Tax Assessor's office with the physical address 840 East Palace Avenue and Santa Fe County Tax Parcel No. 12172416. This rectangular parcel extends west from East Palace Avenue to East Alameda Street and developed with multiple residential units. The southern Subject Property boundary is demarcated by a low stucco wall.

- The western adjoining property is a single-family residential dwelling listed as 839 East Alameda Street with Santa Fe County Tax Parcel No. 10193280.

The Site and immediate vicinity thereof are depicted in **Figure 2.**

3.0 User-Provided Information

During project initiation, the User provided a summary of their knowledge of the Subject Property, summarized below in **Table 2**.

Table 2. User-Provided Information

Site Type	Dry cleaner
Site Name	Lopez Cleaners
Location	838 East Palace Avenue
Source of Identification	Historical City Directories in 1953, 1971, and 1979
Previous Investigations	Groundwater sampling
Major Contaminant Concern	1,1-dichloroethane (1,1-DCA); 1,1-dicloroethylene (1,1-DCE); 1,1,1-trichlorethane (1,1,1-TCA); trichloroethylene (TCE), tetrachloroethylene (PCE), vinyl chloride (VC)

Other than the information provided in **Table 2**, it is INTERA's understanding that the User has no additional knowledge of the Subject Property including those topics outlined in Section 6 of ASTM Standard E1527-21 as the User's responsibilities, summarized as follows:

- The User has no knowledge of any environmental liens or AULs for the Subject Property. However, INTERA has performed a review of land title records and performed a search for environmental liens and AULs on behalf of the User (**Section 4.1.1**).
- The User had no specialized knowledge or experience related to the Subject Property beyond the standard knowledge of a regulatory authority relative to common contaminants associated with dry cleaning operations in general.
- Since a property transaction is not part of the rationale for this Phase I ESA, INTERA did not inquire about the purchase price or fair market value of the Subject Property.
- The User was unaware of any commonly known or reasonably ascertainable information other than what is summarized in **Table 2**, including knowledge of any contamination, spills/releases, or cleanups that have taken place at the Subject Property.
- The User was unaware of any obvious indicators of the presence or likely presence of releases at the Subject Property.

Any supplemental information relative to the User's responsibilities as defined in Section 6 of ASTM Standard E1521-21 is provided in **Appendix E**.

4.0 Records Review

In accordance with ASTM requirements, INTERA reviewed historical topographic maps and aerial imagery, and standard federal, state, local, and tribal environmental regulatory agency documents. A discussion of records reviewed is provided in the following subsections.

4.1 Historical Use of the Site and Adjoining Properties

INTERA contracted ERIS to search for and provide historical topographic maps, historical aerial photographs, historical city directories, and historical fire insurance maps (FIMs) for the Subject Property and surrounding properties. ERIS also provided environmental lien and AUL search services. INTERA reviewed the historical sources of information to investigate the history of development and prior land uses associated with the Subject Property, adjoining properties, and surrounding area, and to identify past land uses that may indicate that hazardous substances or petroleum products were used. A summary of the historical records reviewed is provided below.

4.1.1 Chain of Title and Environmental Lien Search

INTERA contracted ERIS to perform historical chain of title and environmental lien and AUL search for the Subject Property. ERIS searched county, state, and federal records associated with the Subject Property address and parcel identifier back to 1932 for the chain of title and back to 1980 for the lien and AUL search.

The Chain of Title Report identified nine deed conveyances, with the earliest recorded being in 1936. The conveyance details indicated that the several individuals with the last name Lopez held the property between 1936 and 1991. However, a deed conveyance in 1962 indicate that ownership of the property was transferred to the City of Santa Fe. In 1964 the deed was conveyed back to Max Lopez by the State Tax Commission of New Mexico. The conveyance details did not otherwise indicate any new information related to the use or activities at the Subject Property, including dry cleaning operations. No environmental liens and/or AULs were found (ERIS, 2025a). A copy of the combined Chain of Title Report and Environmental Lien Report is included in **Appendix A**.

4.1.2 Historical Topographic Maps

INTERA reviewed historical topographic maps provided by ERIS dated 1952, 1961, 1977, 1993, 2002, 2013, 2017, 2020, and 2023 (ERIS, 2025b), which are provided in **Appendix B**. A brief description of the Subject Property and the surrounding area derived from the review of historical and recent topographic maps is provided below.

- 1952:
  - The Subject Property vicinity appears undeveloped with East Palace Avenue and East Alameda Street depicted. The Santa Fe River is shown with a dark blue line south of Alameda Street roughly following the path of the road in the immediate vicinity of the Subject Property. Several structures, likely single-family residential dwellings, are observed north, northeast and northwest of the Subject Property. Manderfield School and Quarries (Inactive) are visible to the northeast and southeast, respectively.

- 1961:
  - The Subject Property and surrounding area are depicted in red indicating an urban or developed area. Residential developments to the north, northeast and northwest are observed, along with the other features visible in the 1952 map. No developments are depicted on the Subject Property and adjoining properties.
- 1977:
  - The Subject Property and adjoining properties are unchanged with no structures or developments depicted. Although significant development has occurred throughout the map area, the Subject Property and surrounding area are unchanged with Alameda Street labeled.
- 1993:
  - The Subject Property and adjoining properties appear unchanged from the previous map. The inactive quarries to the northeast of the Subject Property are no longer depicted on the map area and the structures to the north and northeast of the Subject Property were shown on the 1977 map, but are not depicted here.
- 2002:
  - The Subject Property and vicinity appear relatively unchanged from the previous map. The footprint of the urban area first depicted in red on the 1961 topographic map is depicted in light green on this map area.
- 2013:
  - As compared with the five previous topographic map years, the 2013 map area has far less detail in terms of structures and developments depicted, with streets and bodies of water being the primary map features. East Palace Avenue and the Santa Fe River are labeled for the first time on this map. The 7,080-ft elevation contour is observed roughly bisecting the Subject Property into eastern and western halves.
- 2017:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.
- 2020:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.
- 2023:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.

4.1.3 Historical Aerial Photographs

INTERA reviewed historical aerial photographs provided by ERIS dated 1935, 1948, 1951, 1960, 1967, 1975, 1981, 1991, 1996, 2005, 2009, 2011, 2014, 2016, 2016, 2018, 2020, and 2022 (ERIS, 2025c – **Appendix C**). A brief description of each historical aerial photograph reviewed is provided below**.**

- 1935: Image Resolution – Poor

  - Although the image resolution is poor, The Subject Property and vicinity appear to be undeveloped land with East Palace Avenue and East Alameda Street observed as unimproved roads. Lots of potential agricultural use are observed in the southern image area south of the Santa Fe River.
- 1948: Image Resolution – Poor
  - The resolution of this image makes distinguishing features difficult, but East Palace Avenue is observed along the eastern Subject Property boundary. There are no distinguishable developments present on the Subject Property and the areas to the east, south, and west appear to be vegetated while the northern portion of the image area appear to be vacant land with surface drainage features observed.
- 1951: Image Resolution – Fair
  - The Subject Property and vicinity have undergone significant change, with the immediate vicinity having been developed with small structures. The Subject Property building along the East Palace Avenue frontage appears on this image for the first time. East Palace Ave and East Alameda are distinguishable, and the adjoining and adjacent properties all have structures on them, apart from the western adjoining property, which appears as undeveloped, unvegetated land.
- 1960: Image Resolution – Fair
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 1967: Image Resolution – Fair
  - The improved image resolution in this image allows for more detailed observation with the primary Subject Property building's footprint being distinguishable along with developments on the adjoining and adjacent properties, although no developments are observed on the western adjoining property.
- 1975: Image Resolution – Poor
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 1981: Image Resolution – Poor
  - Although this is the first color image in the set, the resolution is such that individual features for the Site and surrounding area are not distinguishable aside from East Palace Avenue and East Alameda Street.
- 1991: Image Resolution – Poor
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 1996: Image Resolution – Poor
  - The Subject Property and surrounding area appear relatively unchanged since the previous image, with the exception of a structure observed on the western adjoining property.
- 2005: Image Resolution – Fair

  - An additional structure is observed along the western Subject Property boundary along with a cleared parking area on the eastern adjacent property. The surrounding area generally appears to be treed residential lots with a network of roads. The northern quarter of the image area has cleared, undeveloped lots with unimproved roads, likely for subdivision development.
- 2009: Image Resolution – Fair
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2011: Image Resolution – Fair
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2014: Image Resolution – Fair
  - The primary Subject Property feature distinguishable in this image is the gravel surface extending to the western boundary. Aside from this, the Subject Property and vicinity appear relatively unchanged since the previous image.
- 2016: Image Resolution – Fair
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2018: Image Resolution – Fair
  - The Subject Property and vicinity appear relatively unchanged since the previous image, but the slight improvement in image resolution allows for rough footprint of the eastern and western structures to be observed along with the gravel surface separating them and the vegetation along the southern Subject Property boundary.
- 2020: Image Resolution – Poor
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2022: Image Resolution – Fair
  - The Subject Property and vicinity appear relatively unchanged since the previous image. Nearly the entire image area has been developed with what appear to be residential structures on relatively small lots with a network of roads and sparser vegetation present in the northern approximately quarter of the image.

4.1.4 Fire Insurance Maps

Historical FIMs can be used to identify historical uses of a property including the presence of hazardous substances and petroleum products. No information was found for the Subject Property or adjacent properties (ERIS, 2025e – **Appendix F**).

4.1.5 Historical City Directories

Historical city directories provide a method for researching historical uses of property. INTERA reviewed historical city directories obtained from ERIS to determine current and historical uses of the Subject Property and adjoining properties (ERIS, 2025f – **Appendix G**). ERIS provided historical City Directory Reports for 825-870 East Alameda Street and 825-880 East Palace Avenue. Additional results may be provided if included on the historical directory pages for the ranges provided by ERIS. ERIS provided

results for the years 1928 to 1929, 1930 to 1931, 1936 to 1937, 1940, 1944, 1949, 1955, 1960, 1964, 1968, 1973, 1978, 1983, 1988, 1993, 1996, 2000, 2003, 2007, 2012, 2016, 2020, 2023, and 2024. The city directory listings that could be reasonably presumed to be commercial or retail properties that may be associated with historical operations utilizing petroleum products (e.g., filling stations, gas stations) or other hazardous substances (e.g., drycleaners or manufacturing facilities) are as follows:

Table 3. City Directory Listings

Address	Property Listing(s) (Year(s))
211-213 West Alameda or 209-213 West Alameda	White Swan Laundry Co (1936-1937, 1940, and 1949)
Southwest Corner of West Palace Avenue and Lincoln	Cassell Motor Co (Rent a Car Co) (1936-1937) Beers Don Motor Co (1940)
140 West Palace Avenue	Packard Service Station (1936-1937) Emblem & Lawrence Autos (1940)
Northeast corner of Grant Avenue and West Palace Avenue	Standard Stations (1936-1937)
548 West Alameda	Help Yourself Laundry (1940)
1201 Agua Fria	Settys Body Shop Auto Repair (1944)
519 East Palace Avenue	Control Devices Corp oil burners (1949)
100 Palace Avenue West	Hudson Dealer autos (1949)
116 Palace Avenue West	Gallette Automotive Service (1949)
838 Palace Avenue East	Lopez Cleaners 3-6712 (1955 and 1960) Lopez Dry Cleaners (1964, 1968, 1973, and 1978)
122-124 Palace Avenue West	Senutovish Andre Uranium Mining 3-6115 and 3-7898 US Uranium Corp mining (1955)
135 Palace Avenue West	Sherwood Cecil Chevron Service Station 3-9035 (1955 and 1978)
136 Palace Avenue West	Pueblo Southern Corp mining 3-7213 (1955)
425 Alameda Street West	Sebastian's Firestone tires & appliances (1978)
300 Palace Avenue West	Bokum Resources Corp mining (1978)
868 East Palace Avenue	Palace Laundromat (1988 and 1996)

4.2 Environmental Database Records Review

ERIS was contracted to provide a listing of standard environmental records within the ASTM-specified approximate minimum search distance (AMSD) from the Subject Property. ERIS also provides results from non-standard databases that may be relevant with respect to the objective of a Phase I ESA (i.e., without a specified AMSD). ERIS provided results from 104 unique federal, state, and tribal databases

using the ASTM-specified AMSD or otherwise relevant search distance for each database. The ASTM-compliant regulatory database report is included as **Appendix H.**

4.2.1 Mapped Locations

Based on eight total results of the database search, ERIS identified seven sites (mapped locations) within a 1-mile radius of the Subject Property. Of these seven sites, one was identified for the Subject Property, a double listing in the Historical Business Activity Risk database for dry cleaning operations. The remaining six sites fell within the AMSD, when applicable, aside from one. Findings based on results of select databases that returned significant results that support the objective of the Phase I ESA and opinions of those findings are discussed in **Section 7.** The mapped locations are summarized below in **Table 2.** The ERIS Database Report, which describes and shows these facility locations, is included in **Appendix H** (ERIS, 2025g).

Table 4. File Review Information

Database Record[1]	AMSD (miles)	Total Sites Identified	Within AMSD	On Site Property	Data Source
Standard ASTM Environmental Record Resources					
Federal – RCRA Non-Generators	Subject Property and Adjoining Properties	1	0	0	ERIS
State – SCS	1.0	2	2	0	ERIS
Non-Standard Environmental Records Resources					
Federal – FUDS	NA	1	NA	0	ERIS
State – Spills	NA	1	NA	0	ERIS
Federal – Historical Business Activity Risk	NA	3[2]	NA	2	ERIS

Notes:
1 – Full descriptions of the database sources of information can be found in the ERIS Database Report (Appendix H)
2 – One or more mapped locations listed more than one time
NA = Not Applicable

4.3 Regulatory Agency and Supplemental Records Review

If the Subject Property or a property adjoining the Subject Property is identified in a review of standard ASTM environmental records resources, supplemental records review must be conducted (Section 8.2.3.1 of ASTM E1527-21). Neither the Subject Property nor adjoining properties were identified during review of standard ASTM environmental records resources and therefore mandatory supplemental review was not conducted.

If records review was required, relevant supplemental records obtained would be presented in **Appendix I**. Since no records were required/obtained, **Appendix I** is "reserved."

5.0 Site Reconnaissance

In general, the following was observed during the site reconnaissance to obtain information for the evaluation of RECs in connection with the Subject Property:

- The Subject Property.
- Adjoining properties from the Subject Property boundary and/or the public right-of-way.
- General topography and surface drainage in the vicinity of the Subject Property.

INTERA personnel conducted the site reconnaissance on February 12, 2026. It should be noted that access to the interior portions of the property was not provided by the property owner, so observations from Site reconnaissance are from public right-of-way outside of the property only. Photographic documentation of the site visit is included in **Appendix J.** Findings documented during the site reconnaissance are summarized in **Section 7** of this report.

Conditions observed are presented below; a check mark in any box indicates that INTERA observed evidence of the item during the Site reconnaissance.

☐ Hazardous substances and/ or petroleum products	☐ Unidentified substance containers	☐ Stressed vegetation
☐ Storage tanks	☐ PCBs	☐ Solid waste
☐ Odors	☐ Drains and Sumps	☐ Utilities/Pipelines
☐ Pools of liquid	☐ Pits, ponds, or lagoons	☐ Wastewater
☐ Drums/Containers	☐ Stained soil or pavement	☐ Wells
☐ Hazardous substance and/or petroleum product containers	☐ Stains or Corrosion	☐ Septic systems

Relevant discussion of the conditions observed, including but not limited to the items identified above, is discussed in the following subsections.

5.1 Methodology and Limiting Conditions

The methodology for the site reconnaissance was based on ASTM Standard E1527-21 (ASTM, 2021). INTERA physically inspected the Subject Property and adjoining properties to the extent possible from the right-of-way, and the general site vicinity, to identify RECs or evidence of RECs as specified in Section 9 of ASTM Standard E1527-21 (ASTM, 2021).

5.2 Subject Property

The Subject Property is composed of one approximately 0.17-acre Santa Fe County parcel of land in Santa Fe, New Mexico (**Figure 1**). The Subject Property is a rectangular residential parcel with three structures, a perimeter fence, and vegetated with trees along the south and east property boundaries.

East Palace Avenue bounds the Subject Property on the east side with a vacant commercial property across the street and is otherwise surrounded by residential properties. The Site and immediate vicinity thereof are depicted in **Figure 2.**

Generally, the limited visual site reconnaissance identified actively inhabited residential dwellings without any evidence of active commercial operations.

Photographs taken during the site reconnaissance are included in **Appendix J.**

5.3 Adjoining Properties

INTERA observed properties from the boundary of the Subject Property and from public rights-of-way to the extent possible. Evidence of petroleum products or hazardous substances was not directly observed. Descriptions of adjoining properties are provided in **Section 2.4.**

5.4 Surrounding Properties

Surrounding properties were generally residential. However, a vacant retail/commercial building was observed at 853 East Palace Avenue, adjoining the Subject Property on the opposite side of Palace Avenue.

6.0 Interviews

In accordance with requirements of Sections 10 and 11 of ASTM Standard E1527-21 (ASTM, 2021 pp. 21-23), INTERA interviewed the *key site manager* and *local government officials* for knowledge of any past or present RECs in connection with the Subject Property.

Any findings associated with these interviews are indicated in **Section 7.**

6.1 Key Site Manager

INTERA staff physically visited the Subject Property on December 12, 2025, and February 12, 2026, to contact the property owner and obtain consent for access, but contact was not achieved. INTERA also sent a request for access via certified mail on December 18, 2026. A signed acknowledgment of receipt of the certified letter was returned but subsequent contact was not achieved. Since an interview with a Key Site Manager did not occur, **Appendix K** is "reserved."

6.2 Local Government Officials

NMED provided available information for the Subject Property during project initiation as described in **Section 3**. The information provided is considered satisfactory to meet the requirements of the Standard. No additional information from local government officials was obtained.

7.0 Findings and Opinions

This section presents the findings of the Phase I ESA Report for the Subject Property and summarizes the results of the Phase I ESA records review, site reconnaissance, and interviews as they relate to the potential presence of RECs. A discussion of Subject Property findings related to the use, storage, and disposal of hazardous substances and petroleum products is presented in **Section 7.1.** A discussion of the findings for adjoining and surrounding vicinity properties is included in **Sections 7.2** and **7.3,** respectively. **Section 7.4** discusses the results of the Tier 1 VES. This section also presents INTERA's opinions concerning the potential of the findings to contaminate Subject Property environmental media and whether the finding is considered a REC. The findings presented in this section are the basis for the Phase I ESA conclusions presented by INTERA in **Section 8** of this Phase I ESA Report.

7.1 Subject Property Findings and Opinions

The Subject Property is an approximately 0.17-acre parcel located in a residential area, developed with a two-story and a single-story structure, both of which are listed as dwellings and were built in 1927. Property records indicate the only other onsite structure as a utility shed constructed in 2005 (SFCA, 2026). The Subject Property is surrounded by other residential parcels to the north, west, and south. East Palace Avenue bounds the Subject Property on the east side with a vacant commercial property across the street and is otherwise surrounded by residential properties.

The Subject Property is identified twice in the Historic Potential Business Activity Risk database for its potential history as a dry cleaning facility. Historical city directories identify the Subject Property as Lopez Cleaners in 1955 and 1960, and as Lopez Dry Cleaners in 1964, 1968, 1973, and 1978. Additional corroborating evidence of dry cleaning activities and the use of chlorinated solvents was not identified.

Based on the information available, a **REC** exists in connection with the Subject Property due to its operational history as a dry cleaner for approximately 23 years and the probability of the use of hazardous chemicals including chlorinated solvents during a time when regulations for the use, storage, and disposal of those chemicals were limited.

7.2 Adjoining Property Findings and Opinions

No relevant findings were identified associated with adjoining properties.

7.3 Vicinity Findings and Opinions

No relevant findings were identified associated with adjoining properties.

7.4 Tier 1 Vapor Encroachment Screening

ASTM Standard E2600-22 defines the default area of concern (AOC) based on $^{1}/_{3}$-mile for hazardous substances and $^{1}/_{10}$-mile for petroleum hydrocarbon contaminants. The AOC is measured from the

Subject Property boundary to a contaminated property with known or suspected contamination of soil and/or groundwater (ASTM, 2022).

Based on review of Subject Property, adjoining property, and vicinity property findings within the default AOC, the dry cleaning operations that likely occurred at the Subject Property are considered a **VEC**.

7.5 Data Gaps

A *data gap* exists in connection with the Subject Property due to the environmental professional not being able to observe all areas of the Subject Property because access to the Subject Property was not obtained, and because an interview with a Key Site Manager did not occur. It is our professional opinion that this is a *significant data gap* as the environmental professional was unable to make any conclusions based on the current condition of the property nor obtain firsthand knowledge of the historical use of the property.

8.0 Conclusions

INTERA has performed a Phase I ESA in conformance with the scope and limitations of ASTM Standard E1527-21 for the Subject Property. Any exceptions to or deletions from this practice are described in **Section 7.5**. Based on the completion of the scope of services provided in support of this Phase I ESA, one REC and one VEC were identified in connection with the Subject Property, as follows:

- Approximately 23 years (1955-1978) of dry cleaning operations conducted at the Subject Property and the *significant data gap* identified due to the environmental professional not having physical access to the Subject Property or building interiors nor anyone with firsthand knowledge of the historical use of the Subject Property is considered a **REC**/**VEC** in connection with the Subject Property.

9.0 Recommendations

Based on the AAIs performed by the environmental professional in conformance with 40 CFR 312.31(a) and (b), this Phase I ESA has revealed evidence of one or more RECs/VECs or *significant data gaps* in connection with the Subject Property. Based on the conclusions of this Phase I ESA, INTERA recommends the following:

- Perform a Phase II site investigation to assess the potential impacts to environmental media from the REC identified in connection with the Subject Property.

10.0 References

ASTM International (ASTM). 2021. *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process.* Standard E1527-21. West Conshohocken, Pennsylvania: ASTM International.

———. 2022. *Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions*. Standard E2600-22. West Conshohocken, Pennsylvania. May 18.

Environmental Risk Information Services (ERIS). 2026a. Chain of Title Report and Environmental Lien Search.

———. 2025b. Topographic Maps.

———. 2025c. Historical Aerials.

———. 2025d. Physical Setting Report.

———. 2025e. Fire Insurance Maps.

———. 2025f. City Directory.

———. 2025g. Database Report.

National Oceanic and Atmospheric Administration (NOAA). 2026. National Weather Service Climate Data. https://www.weather.gov/wrh/Climate?wfo=hgx. Accessed March 31, 2026.

Santa Fe County Assessor (SFCA) Parcel Viewer. 2026. https://www.santafecountynm.gov/assessor/tools. Accessed January 6, 2026.

United States Environmental Protection Agency (EPA). 2005. *Standards and Practices for All Appropriate Inquiries*, Final Rule. 40 CFR Part 312. Washington, D.C.: Government Printing Office. Federal Register 70(210): November 1.

United States Geological Survey (USGS). 2023. *Santa Fe Quadrangle, New Mexico – Santa Fe County 7.5 Minute Series.* Accessed January 2026.

11.0 Disclaimer

The findings and conclusions contained in this report were derived using the methodologies provided in ASTM Standard E1527-21 (ASTM, 2021). The findings and conclusions contain all limitations inherent in these methodologies. There is the possibility that even with proper application of these methodologies, conditions may exist at the Subject Property that could not be identified within the scope of the Phase I ESA or that were not reasonably identifiable from the available information.

INTERA has prepared this report in accordance with the generally accepted environmental professional practices in use at the time of our study. This report may be used only by the User(s) and only for the purposes stated within a reasonable time from its issuance as outlined in ASTM Standard E1527-21 (ASTM, 2021). Land use, Site conditions (both onsite and offsite), or other factors may change over time, and additional work may be required with the passage of time. Any party other than the User(s) who wishes to use this report shall notify the User(s) of the intended use. Non-compliance with any of these requirements will release INTERA from any liability resulting from the use of this report.

INTERA does not warrant or guarantee in any manner, expressed or implied, that the conclusions and findings reported in this Phase I ESA, or the information obtained for this Phase I ESA from the records review or from other sources, including site reconnaissance observations, personal interviews, and correspondence, are accurate or complete beyond the limits of the methods applied. The methodologies of this Phase I ESA assessment are intended to meet the scope of a Phase I ESA in accordance with ASTM Standard E1527-21 (ASTM, 2021).

INTERA conducted this Phase I ESA and AAI into previous property ownership and uses in a manner consistent with ASTM Standard E1527-21 and the EPA AAI Final Rule (EPA, 2005) definitions of good commercial and customary ESA and AAI practices in the United States of America.

This Phase I ESA report is intended for use solely by the User(s). Any party other than the User(s) is explicitly denied any rights to rely on the findings, opinions, and conclusions of this Phase I ESA report.

12.0 Qualifications and Signatures of Environmental Professionals


Complete copies of resumes outlining the qualifications of the individuals completing this Phase I ESA report are included as **Appendix L.**

"I declare that, to the best of my professional knowledge and belief, I meet the definition of environmental professional as defined in Section 312.10 of 40 CFR 312. I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the Subject Property. I have developed and performed all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR part 312."

Matt Hubbard, Senior Environmental Scientist/Environmental Professional

Signature: 

Joeseph Tracy, P.G., Principal Geologist/Environmental Professional

Signature: 

FIGURES




Figure 1
Site Location
Lopez Cleaners
838 East Palace Avenue, Santa Fe, New Mexico


Exported: 6/11/2026 2:43 PM

S:\ABQ\NMENV.M007.SF-WALDO\Graphics\SantaFe_Waldo_P1P2_Proposal\SantaFe_Waldo_P1P2_Proposal.aprx

User: mhubbard

Layout: Figure 1 - 838 Palace Location

INTERA



Legend

- Subject Property Parcels
- Subject Property Addresses

0 75 150

US Feet

N

Figure 2
Site Plan
Lopez Cleaners
838 East Palace Avenue, Santa Fe, New Mexico

Exported: 6/11/2026 3:31 PM

S:\ABQ\NMENV.M007.SF-WALDO\Graphics\SantaFe_Waldo_P1P2_Proposal\SantaFe_Waldo_P1P2_Proposal.aprx

User: mhubbard

Layout: Figure 2 - Site Plan 838 Palace

INTERA

APPENDIX A

Chain of Title Report and Environmental Lien and Activity and Use Limitation Search

CHAIN OF TITLE

Project Property: *838 EAST PALACE AVENUE*
SANTA FE, NM 87501
Order No: *25121700727-COT1*
Date Completed: *01/05/2026*

ERIS – Environmental Risk Information Services hereby submits the following historical chain-of-title to the land described below.

Title to the estate or interest covered by this report appears to be vested in:

BURCHELL PALACE, LLC

The following is the current property legal description (See deed for full legal description):

T17N R10E S30, TRACT OF LAND SITUATE AT 838 EAST PALACE AVENUE, BLK 7, LOT 19

Assessor's Parcel Number(s): 011377792 AND 1-055-098-150-524

CHAIN OF TITLE REPORT

Order No: *25121700727-COT1*

HISTORICAL CHAIN OF TITLE

Public Records were searched at the SANTA FE COUNTY Assessor's office and the SANTA FE COUNTY Clerk's office back to 1932. The following conveyances were found of record.

1.	Deed Type:	WARRANTY DEED
	Deed Date:	10/12/2024
	Recorded:	11/13/2024
	Grantor:	ELIZABETH RUTH BURCHELL (A/K/A ELIZABETH RUTH MERIN), SUSAN TAYLOR BURCHELL, TRUSTEES OF THE ROBERT CLAY BURCHELL AND SARA JANE BURCHELL REVOCABLE TRUST
	Grantee:	BURCHELL PALACE, LLC
	Instrument:	2046489
	Notes:	NA
2.	Deed Type:	DEED
	Deed Date:	03/12/2009
	Recorded:	03/12/2009
	Grantor:	ROBERT CLAY BURCHEL, SARA JANE BURCHELL, AND ELIZABETH RUTH BURCHELL
	Grantee:	ELIZABETH RUTH BURCHELL (A/K/A ELIZABETH RUTH MERIN), SUSAN TAYLOR BURCHELL, TRUSTEES OF THE ROBERT CLAY BURCHELL, SARA JANE BURCHELL REVOCABLE TRUST
	Instrument:	1555248
	Notes:	NA
3.	Deed Type:	DEED
	Deed Date:	09/02/1999
	Recorded:	09/02/1999
	Grantor:	ROBERT CLAY BURCHEL, SARA JANE BURCHELL, AND ELIZABETH RUTH BURCHELL
	Grantee:	ROBERT CLAY BURCHEL, SARA JANE BURCHELL
	Instrument:	BOOK 1682 / PAGE 791
	Notes:	NA

4. Deed Type: DEED
   Deed Date: 01/29/1998
   Recorded: 01/29/1998
   Grantor: ROBERT CLAY BURCHEL, SARA JANE BURCHELL, AND ELIZABETH RUTH BURCHELL
   Grantee: ROBERT CLAY BURCHEL, SARA JANE BURCHELL
   Instrument: BOOK 1450 / PAGE 843
   Notes: NA

5. Deed Type: DEED
   Deed Date: 08/23/1991
   Recorded: 08/23/1991
   Grantor: PAT M. LOPEZ AND CHRISTINE E. GABALDON
   Grantee: ROBERT CLAY BURCHEL, SARA JANE BURCHELL, AND SUSAN T. BURCHELL
   Instrument: BOOK 748 / PAGE 591
   Notes: NA

6. Deed Type: DEED
   Deed Date: 08/31/1990
   Recorded: 08/31/1990
   Grantor: JOSEPHINA R. LOPEZ
   Grantee: PAT M. LOPEZ AND CHRISTINE E. GABALDON
   Instrument: BOOK 693 / PAGE 60
   Notes: NA

LEASES AND MISCELLANEOUS

Comments: NONE IDENTIFIED.

Thank You for Your Business
Please contact ERIS at **416-510-5204** or **info@erisinfo.com**
with any questions or comments

LIMITATION

This report is neither a guarantee of title, a commitment to insure, or a policy of title insurance. ERIS – Environmental Risk Information Services does not guarantee nor include any warranty of any kind whether expressed or implied, about the validity of all information included in this report since this information is retrieved as it is recorded from various agencies that make it available. The total liability is limited to the fee paid for this report.

WARRANTY DEED

ELIZABETH RUTH BURCHELL (a/ka Elizabeth Ruth Merin) and SUSAN TAYLOR BURCHELL, the Trustees of the ROBERT CLAY BURCHELL AND SARA JANE BURCHELL REVOCABLE TRUST UTA dtd. May 8, 1981, as amended and/or restated, for consideration paid, grant to BURCHELL PALACE, LLC, a New Mexico limited liability company, whose address is 213 Poplar Ave., Wayne, Pennsylvania 19087, the following described real estate in Santa Fe County, New Mexico:

SEE **EXHIBIT A** ATTACHED HERETO AND MADE A PART HEREOF

SUBJECT to reservations, restrictions, easements and encumbrances of record.

with warranty covenants.

WITNESS their hands and seals this 17 day of October, 2024.

Elizabeth Ruth Burchell

ELIZABETH RUTH BURCHELL (a/k/a Elizabeth Ruth Merin), Trustee of the ROBERT CLAY BURCHELL AND SARA JANE BURCHELL REVOCABLE TRUST

Susan T Burchell

SUSAN TAYLOR BURCHELL, the Trustees of the ROBERT CLAY BURCHELL AND SARA JANE BURCHELL REVOCABLE TRUST

Commonwealth of Pennsylvania-Notary Seal
TRACY MAURICE PRESSLEY, NOTARY PUBLIC
CHESTER COUNTY
MY COMMISSION EXPIRES DECEMBER 19, 2026
COMMISSION NUMBER 1431040

STATE OF Pennsylvania)
) ss.
COUNTY OF Delaware)

On this 17th day of October, 2024, before me personally appeared ELIZABETH RUTH BURCHELL (a/k/a Elizabeth Ruth Merin), Trustee of the ROBERT CLAY BURCHELL AND SARA JANE BURCHELL REVOCABLE TRUST, and to me known to be the person described in and who executed the foregoing instrument, and acknowledged that she executed the same as her free act and deed.

My Commission Expires: 12/19/2026

NOTARY PUBLIC

STATE OF Rhode Island)
) ss.
COUNTY OF Newport)

On this 16th day of October, 2024, before me personally appeared SUSAN TAYLOR BURCHELL, Trustee of the ROBERT CLAY BURCHELL AND SARA JANE BURCHELL REVOCABLE TRUST ARY McCABE ROSS, and to me known to be the person described in and who executed the foregoing instrument, and acknowledged that she executed the same as her free act and deed.

My Commission Expires:

Slater Harnett
Notary Public
State of Rhode Island
MY COMMISSION EXPIRES 04/06/2028
Commission # 762297

Slater T. Harnett
NOTARY PUBLIC
STATE OF RHODE ISLAND

NOTARY PUBLIC

SFC CLERK RECORDED 11/13/2024

A tract of land situate at 838 East Palace Avenue, City and County of Santa Fe, State of New Mexico and being more particularly described as follows:

Beginning at the northerly most point of the tract herein described, from whence the southeast corner of west concrete culvert headwall bears:

North 25 deg. 38' West, 317.1 feet;
Thence from said point and place of beginning along the following bearings and distances:
South 26 deg. 20' East, 53.05 feet along the west right of way line of East Palace Avenue;
South 64 deg. 51' West, 133.75 feet;
Thence North 29 deg. 44' West, 51.67 feet;
Thence North 64 deg. 14' East, 136.9 feet, to the point and place of beginning.

All as shown on plat of survey by James C. Harvey dated January 21, 1936 "Tract of Land Surveyed for Max Lopez," and dated April 30, 1957 entitled "Tract of Land Surveyed for Augustin Baros."

WARRANTY DEED
PAGES: 2

COUNTY OF SANTA FE)
STATE OF NEW MEXICO) ss

I Hereby Certify That This Instrument Was Filed for Record On The 13TH Day Of November, 2024 at 08:16:02 AM
And Was Duly Recorded as Instrument # 2046489
Of The Records Of Santa Fe County

Witness My Hand And Seal Of Office
Katharine E. Clark
Deputy _____ County Clerk, Santa Fe, NM

SFC CLERK RECORDED 11/13/2024

CHAIN OF TITLE & LIEN SEARCHES

Project Property: *838 EAST PALACE AVENUE*
SANTA FE, NM 87501
Order No: *25121700727-COTEL1*
Date Completed: *01/05/2026*

Title to the estate or interest covered by this report appears to be vested in:
BURCHELL PALACE, LLC

The following is the current property legal description (See deed for full legal description):
T17N R10E S30, TRACT OF LAND SITUATE AT 838 EAST PALACE AVENUE, BLK 7, LOT 19

Assessor's Parcel Number(s):
011377792 AND 1-055-098-150-524

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

TARGET PROPERTY INFORMATION

ADDRESS

838 EAST PALACE AVENUE
SANTA FE, NM 87501

RESEARCH SOURCES

RECORDER:	SANTA FE COUNTY RECORDER'S OFFICE
ASSESSOR:	SANTA FE COUNTY ASSESSOR'S OFFICE
STATE:	NEW MEXICO ENVIRONMENT DEPARTMENT
FEDERAL:	UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
OTHER:	JUDICIAL RECORDS NOT SEARCHED. BASED ON AVAILABLE INFORMATION EVALUATED BY THE TITLE SEARCH PROFESSIONAL, THE JURISDICTION DOES NOT REQUIRE A SEARCH OF JUDICIAL RECORDS IN ORDER TO IDENTIFY ENVIRONMENTAL LIENS.
NOTES:	PUBLIC RECORDS OF SANTA FE COUNTY, NM WERE SEARCHED FROM JANUARY 1, 1980 TO DECEMBER 29, 2025, AND NO OTHER DEEDS VESTING TITLE IN THE SUBJECT PROPERTY WERE FOUND OF RECORD DURING THE PERIOD SEARCHED.

ENVIRONMENTAL LIENS

Environmental Lien: [X] NOT FOUND

ACTIVITY AND USE LIMITATIONS (AULs)

AULs: [X] NOT FOUND

CHAIN OF TITLE TO 1980

1. Deed Type: WARRANTY DEED
   Deed Date: 10/12/2024
   Recorded: 11/13/2024
   Grantor: ELIZABETH RUTH BURCHELL (A/K/A ELIZABETH RUTH MERIN), SUSAN TAYLOR BURCHELL, TRUSTEES OF THE ROBERT CLAY BURCHELL AND SARA JANE BURCHELL REVOCABLE TRUST
   Grantee: BURCHELL PALACE, LLC
   Instrument: 2046489
   Notes:

2. Deed Type: DEED
   Deed Date: 03/12/2009
   Recorded: 03/12/2009
   Grantor: ROBERT CLAY BURCHEL, SARA JANE BURCHELL, AND ELIZABETH RUTH BURCHELL
   Grantee: ELIZABETH RUTH BURCHELL (A/K/A ELIZABETH RUTH MERIN), SUSAN TAYLOR BURCHELL, TRUSTEES OF THE ROBERT CLAY BURCHELL, SARA JANE BURCHELL REVOCABLE TRUST
   Instrument: 1555248
   Notes:

3. Deed Type: DEED
   Deed Date: 09/02/1999
   Recorded: 09/02/1999
   Grantor: ROBERT CLAY BURCHEL, SARA JANE BURCHELL, AND ELIZABETH RUTH BURCHELL
   Grantee: ROBERT CLAY BURCHEL, SARA JANE BURCHELL
   Instrument: BOOK 1682 / PAGE 791
   Notes:

4. Deed Type: DEED
   Deed Date: 01/29/1998
   Recorded: 01/29/1998
   Grantor: ROBERT CLAY BURCHEL, SARA JANE BURCHELL, AND ELIZABETH RUTH BURCHELL
   Grantee: ROBERT CLAY BURCHEL, SARA JANE BURCHELL
   Instrument: BOOK 1450 / PAGE 843
   Notes:

5. Deed Type: DEED
   Deed Date: 08/23/1991
   Recorded: 08/23/1991
   Grantor: PAT M. LOPEZ AND CHRISTINE E. GABALDON
   Grantee: ROBERT CLAY BURCHEL, SARA JANE BURCHELL, AND SUSAN T. BURCHELL
   Instrument: BOOK 748 / PAGE 591
   Notes:

6.	Deed Type:	DEED
	Deed Date:	08/31/1990
	Recorded:	08/31/1990
	Grantor:	JOSEPHINA R. LOPEZ
	Grantee:	PAT M. LOPEZ AND CHRISTINE E. GABALDON
	Instrument:	BOOK 693 / PAGE 60
	Notes:	RESEARCH CONDUCTED BACK TO 1980. THIS IS THE OLDEST DEED OF RECORD FOUND POST DECEMBER 31, 1979 (BETWEEN 01/01/1980 AND 08/31/1990).

LEASES AND MISCELLANEOUS

Comments: NONE IDENTIFIED.

ENVIRONMENTAL LIEN TO 1980 REPORT

Order No: *25121700727-COTEL1*

The ERIS Environmental Lien Search Report to 1980 provides results from a search of available current land title records for environmental cleanup liens and other activity and use limitations, such as engineering and institutional controls.

A network of professional, trained researchers, following established procedures, uses client supplied property information to:

- Search for parcel information and / or legal description
- Search for ownership information
- Research official land title documents recorded at jurisdictional agencies such as recorder's' office, registries of deeds, county clerks' offices, etc.
- Access copies of deeds to 1980
- Search for environmental encumbrance(s) associated with the deeds
- Provide a copy of any environmental encumbrance(s) based upon a review of keywords in the instrument(s) (title, parties involved and description)
- Provide a copy of the deeds or cite documents reviewed

Thank You for Your Business
Please contact ERIS at **416-510-5204** or **info@erisinfo.com**
with any questions or comments

LIMITATION

This report is neither a guarantee of title, a commitment to insure, or a policy of title insurance. ERIS – Environmental Risk Information Services does not guarantee nor include any warranty of any kind whether expressed or implied, about the validity of all information included in this report since this information is retrieved as it is recorded from various agencies that make it available. The total liability is limited to the fee paid for this report.

DEED EXHIBIT

WARRANTY DEED

ELIZABETH RUTH BURCHELL (a/ka Elizabeth Ruth Merin) and SUSAN TAYLOR BURCHELL, the Trustees of the ROBERT CLAY BURCHELL AND SARA JANE BURCHELL REVOCABLE TRUST UTA dtd. May 8, 1981, as amended and/or restated, for consideration paid, grant to BURCHELL PALACE, LLC, a New Mexico limited liability company, whose address is 213 Poplar Ave., Wayne, Pennsylvania 19087, the following described real estate in Santa Fe County, New Mexico:

SEE **EXHIBIT A** ATTACHED HERETO AND MADE A PART HEREOF

SUBJECT to reservations, restrictions, easements and encumbrances of record.

with warranty covenants.

WITNESS their hands and seals this 17 day of October, 2024.

Elizabeth Ruth Burchell

ELIZABETH RUTH BURCHELL (a/k/a Elizabeth Ruth Merin), Trustee of the ROBERT CLAY BURCHELL AND SARA JANE BURCHELL REVOCABLE TRUST

Susan T Burchell

SUSAN TAYLOR BURCHELL, the Trustees of the ROBERT CLAY BURCHELL AND SARA JANE BURCHELL REVOCABLE TRUST

Commonwealth of Pennsylvania-Notary Seal
TRACY MAURICE PRESSLEY, NOTARY PUBLIC
CHESTER COUNTY
MY COMMISSION EXPIRES DECEMBER 19, 2026
COMMISSION NUMBER 1431040

STATE OF Pennsylvania)
) ss.
COUNTY OF Delaware)

On this 17th day of October, 2024, before me personally appeared ELIZABETH RUTH BURCHELL (a/k/a Elizabeth Ruth Merin), Trustee of the ROBERT CLAY BURCHELL AND SARA JANE BURCHELL REVOCABLE TRUST, and to me known to be the person described in and who executed the foregoing instrument, and acknowledged that she executed the same as her free act and deed.

My Commission Expires: 12/19/2026

NOTARY PUBLIC

STATE OF Rhode Island)
) ss.
COUNTY OF Newport)

On this 16th day of October, 2024, before me personally appeared SUSAN TAYLOR BURCHELL, Trustee of the ROBERT CLAY BURCHELL AND SARA JANE BURCHELL REVOCABLE TRUST ARY McCABE ROSS, and to me known to be the person described in and who executed the foregoing instrument, and acknowledged that she executed the same as her free act and deed.

My Commission Expires:

Slater Harnett
Notary Public
State of Rhode Island
MY COMMISSION EXPIRES 04/06/2028
Commission # 762297

Slater T. Harnett
NOTARY PUBLIC
STATE OF RHODE ISLAND

NOTARY PUBLIC

SFC CLERK RECORDED 11/13/2024

A tract of land situate at 838 East Palace Avenue, City and County of Santa Fe, State of New Mexico and being more particularly described as follows:

Beginning at the northerly most point of the tract herein described, from whence the southeast corner of west concrete culvert headwall bears:

North 25 deg. 38' West, 317.1 feet;
Thence from said point and place of beginning along the following bearings and distances:
South 26 deg. 20' East, 53.05 feet along the west right of way line of East Palace Avenue;
South 64 deg. 51' West, 133.75 feet;
Thence North 29 deg. 44' West, 51.67 feet;
Thence North 64 deg. 14' East, 136.9 feet, to the point and place of beginning.

All as shown on plat of survey by James C. Harvey dated January 21, 1936 "Tract of Land Surveyed for Max Lopez," and dated April 30, 1957 entitled "Tract of Land Surveyed for Augustin Baros."

WARRANTY DEED
PAGES: 2

COUNTY OF SANTA FE)
STATE OF NEW MEXICO) ss

I Hereby Certify That This Instrument Was Filed for Record On The 13TH Day Of November, 2024 at 08:16:02 AM
And Was Duly Recorded as Instrument # 2046489
Of The Records Of Santa Fe County

Witness My Hand And Seal Of Office
Katharine E. Clark
Deputy _____ County Clerk, Santa Fe, NM

SFC CLERK RECORDED 11/13/2024

APPENDIX B

Historical Topographic Maps

TOPOGRAPHIC MAPS

Project Property:	Lopez Cleaners
	838 East Palace Avenue
	Santa Fe NM 87501
Project No:	NMENV.M007.SF-WALDO
Requested By:	INTERA Incorporated
Order No:	25121700727
Date Completed:	December 18, 2025

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

We have searched USGS collections of current topographic maps and historical topographic maps for the project property. Below is a list of maps found for the project property and adjacent area. Maps are from 7.5 and 15 minute topographic map series, if available.

Year	Map Series
2023	7.5
2020	7.5
2017	7.5
2013	7.5
2002	7.5
1993	7.5
1977	7.5
1961	7.5
1952	7.5

Topographic Map Symbology for the maps may be available in the following documents:

Pre-1947

Page 223 of 1918 Topographic Instructions

Page 130 of 1928 Topographic Instructions


1947-2009

Topographic Map Symbols

2009-present

US Topo Map Symbols

Topographic Maps included in this report are produced by the USGS and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property.
No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc.(in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS', using Topographic Maps produced by the USGS. This maps contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.




2023

Order No. 25121700727

Available Quadrangle(s): Santa Fe, NM



Source: USGS 7.5 Minute Topographic Map




2020

Order No. 25121700727

Available Quadrangle(s): Santa Fe, NM



Source: USGS 7.5 Minute Topographic Map



2017

Order No. 25121700727

Available Quadrangle(s): Santa Fe, NM



Source: USGS 7.5 Minute Topographic Map

ERIS




2013

Order No. 25121700727

Available Quadrangle(s): Santa Fe, NM



Source: USGS 7.5 Minute Topographic Map



2002 (1-2002)

Aerial Photo Year: 1996


Order No. 25121700727


Available Quadrangle(s): Santa Fe, NM(1-2002)



Source: USGS 7.5 Minute Topographic Map

ERIS


SANTA FE
(BM 6989)
GRANT
Governors Mansion
St Catherines Indian School
Fort Marcy Park
Rosario Cem
BM 6945
Magers Field
Carlos Gilbert Sch
Federal Courthouse
Ft Marcy
Martyrs Cross
Old Fort Marcy Park
Hillside Park
Radio Tower
The Santa Fe Plaza Nat Hist Lmrk
STATE CAPITOL
Acequia Madre School
Wood-Gormley Sch
Orlando Fernandez Park
Amelia White Park
Cornell Park
Martinez Sch
Saint Vincent Hospital
Manderfield Sch
Cristo Rey Ch
Cristo Rey Cemetery
Talaya Hill
Atalaya Sch
Atalaya Park
Mt Carmel Chapel
National Park Service
Saint Johns College
Museum of International Folk Art
Laboratory of Anthropology
Wheelwright Museum
Cerro Gordo
Cerro Gordo Park
Sun Mtn
Water Tanks
Water Tank
Gravel Pit
Cañada
Arroyo del Rosario
Arroyo de Los Loveros
Arroyo
Bishops Lodge
Hyde Park
Gonzales Road
Salvador
Santa Fe Canyon
Tierra Blanca
San Antonio
Tenorio
Old Santa Fe Trail
Galisteo
Paseo de Peralta
Alameda Street
Santa Fe River
State Park
Cordova Rd
Old Pecos Trail
Santa Fe Union
Arroyo Mascaras
Arroyo Hondo
Arroyo Tenorio
Arroyo de Los Loveros
Arroyo Tierra Blanca
Arroyo San Antonio
Arroyo de Los Loveros
Arroyo Mascaras
Arroyo Hondo
Arroyo Tenorio



1977 (1-1977)

Aerial Photo Year: 1976


Photo Revision Year: 1977

Order No. 25121700727

Available Quadrangle(s): Santa Fe, NM(1-1977)



Source: USGS 7.5 Minute Topographic Map


SANTA FE
(BM 6989)
Governors Mansion
Fort Marcy Park
St Catherines Indian Sch
Martyrs Cross
Rosario Cem
Magers Field
Mascaras
Federal Courthouse
City Hall
Radio Tower
Post Office
The Plaza
St Vincents Sanatorium
STATE CAPITOL
St Michaels High Sch
Acequia Madre Sch
Manderfield Sch
Cristo Rey Ch
Los Cerros Res
Talaya Hill Res
Cristo Rey Cem
National Guard Armory
Mt Carmel Chapel
National Park Service
Museum of International Folk Art
Laboratory of Anthropology
Navajo Museum of Ceremonial Art
Martinez Sch
Cerro Gordo
Sun Mtn
Arroyo del Rosario
Arroyo de los Lovatos
Arroyo
Arroyo Tierra Blanca
Arroyo San Antonio
Cañada
Cañada de los
Santa Fe Canyon
Bishops Lodge Road
Hyde Park Road
Aqueduct
Quarries
Salz Road
Gonzales Road
Salvador
Alameda
Manhattan
Pecos Trail
Cordova Rd
E Cordova Rd
Tenorio Road
Galisteo
Santa Fe
Drive
Street
T A L A Y A
7205
7052
7062
7100
7200
7300
7400
7500
7600
7700
7800
7900
7268
7278
7617
7439
7164
7366
7955
7068
7147
7088
7323
7219
7224
7201
7847
7326
7322
7561
7569
7000
6997
6999
7711
7227
7139
7108
7100
7000
7200
7300
7400
7500
7600
7700
7800
7900
7000
7100



1952 (1-1952)

Aerial Photo Year: 1951

Order No. 25121700727

Available Quadrangle(s): Santa Fe, NM(1-1952)



Source: USGS 7.5 Minute Topographic Map

APPENDIX C

Historical Aerial Photographs

HISTORICAL AERIALS

Project Property: Lopez Cleaners
838 East Palace Avenue
Santa Fe NM 87501

Project No: NMENV.M007.SF-WALDO

Requested By: INTERA Incorporated


Order No: 25121700727

Date Completed: December 19,2025

Aerial Maps included in this report are produced by the sources listed above and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property. ERIS provides no warranty of accuracy or liability. The information contained in this report has been produced using aerial photos listed in above sources by ERIS Information Inc. (in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS'. The maps contained in this report do not purport to be and do not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Date	Source	Scale	Comments
2022	United States Department of Agriculture	1" = 500'	
2020	United States Department of Agriculture	1" = 500'	
2018	United States Department of Agriculture	1" = 500'	
2016	United States Department of Agriculture	1" = 500'	
2014	United States Department of Agriculture	1" = 500'	
2011	United States Department of Agriculture	1" = 500'	
2009	United States Department of Agriculture	1" = 500'	
2005	United States Geological Survey	1" = 500'	
1996	United States Geological Survey	1" = 500'	
1991	United States Geological Survey	1" = 500'	
1981	United States Geological Survey	1" = 500'	
1975	Pacific Western Techonolgies	1" = 500'	
1967	Pacific Western Techonolgies	1" = 500'	Adjacent Frame Unavailable
1960	United States Geological Survey	1" = 500'	
1951	United States Geological Survey	1" = 500'	
1948	United States Geological Survey	1" = 500'	
1935	Agricultural Stabilization & Conserv. Service	1" = 500'	




Year: 2022
Source: USDA
Scale: 1" = 500'
Comment:

Address: 838 East Palace Avenue, Santa Fe, NM
Approx Center: -105.9242855,35.68203566

Order No: 25121700727

ERIS




Year: 2020
Source: USDA
Scale: 1" = 500'
Comment:

Address: 838 East Palace Avenue, Santa Fe, NM
Approx Center: -105.9242855,35.68203566

Order No: 25121700727

ERIS




Year: 2018
Source: USDA
Scale: 1" = 500'
Comment:

Address: 838 East Palace Avenue, Santa Fe, NM
Approx Center: -105.9242855,35.68203566

Order No: 25121700727

ERIS




Year: 2016
Source: USDA
Scale: 1" = 500'
Comment:

Address: 838 East Palace Avenue, Santa Fe, NM
Approx Center: -105.9242855,35.68203566

Order No: 25121700727

ERIS



Year: 2014
Source: USDA
Scale: 1" = 500'
Comment:

Address: 838 East Palace Avenue, Santa Fe, NM
Approx Center: -105.9242855,35.68203566

Order No: 25121700727

ERIS




Year: 2011
Source: USDA
Scale: 1" = 500'
Comment:

Address: 838 East Palace Avenue, Santa Fe, NM
Approx Center: -105.9242855,35.68203566

Order No: 25121700727

ERIS




Year: 2009
Source: USDA
Scale: 1" = 500'
Comment:

Address: 838 East Palace Avenue, Santa Fe, NM
Approx Center: -105.9242855,35.68203566

Order No: 25121700727

ERIS



Year: 2005
Source: USGS
Scale: 1" = 500'
Comment:

Address: 838 East Palace Avenue, Santa Fe, NM
Approx Center: -105.9242855,35.68203566

Order No: 25121700727

ERIS




Year: 1996
Source: USGS
Scale: 1" = 500'
Comment:

Address: 838 East Palace Avenue, Santa Fe, NM
Approx Center: -105.9242855,35.68203566

Order No: 25121700727

ERIS




Year: 1991
Source: USGS
Scale: 1" = 500'
Comment:

Address: 838 East Palace Avenue, Santa Fe, NM
Approx Center: -105.9242855,35.68203566

Order No: 25121700727

ERIS




Year: 1981
Source: USGS
Scale: 1" = 500'
Comment:

Address: 838 East Palace Avenue, Santa Fe, NM
Approx Center: -105.9242855,35.68203566

Order No: 25121700727

ERIS



Year: 1975
Source: PWT
Scale: 1" = 500'
Comment:

Address: 838 East Palace Avenue, Santa Fe, NM
Approx Center: -105.9242855,35.68203566

Order No: 25121700727

ERIS

500
Feet




Year: 1967
Source: PWT
Scale: 1" = 500'
Comment: Adjacent Frame Unavailable

Address: 838 East Palace Avenue, Santa Fe, NM
Approx Center: -105.9242855,35.68203566

Order No: 25121700727

ERIS




Year: 1960
Source: USGS
Scale: 1" = 500'
Comment:

Address: 838 East Palace Avenue, Santa Fe, NM
Approx Center: -105.9242855,35.68203566

Order No: 25121700727

ERIS



Year: 1951
Source: USGS
Scale: 1" = 500'
Comment:

Address: 838 East Palace Avenue, Santa Fe, NM
Approx Center: -105.9242855,35.68203566

Order No: 25121700727

ERIS



Year: 1948
Source: USGS
Scale: 1" = 500'
Comment:

Address: 838 East Palace Avenue, Santa Fe, NM
Approx Center: -105.9242855,35.68203566

Order No: 25121700727

ERIS



Year: 1935
Source: ASCS
Scale: 1" = 500'
Comment:

Address: 838 East Palace Avenue, Santa Fe, NM
Approx Center: -105.9242855,35.68203566

Order No: 25121700727

ERIS

APPENDIX D

Physical Setting Documentation

PSR
PHYSICAL SETTING REPORT

Property Information

Order Number:		25121700727p
Date Completed:		December 17, 2025
Project Number:		NMENV.M007.SF-WALDO
Project Property:		Lopez Cleaners 838 East Palace Avenue Santa Fe NM 87501
Coordinates:		
	Latitude:	35.68203566
	Longitude:	-105.9242855
	UTM Northing:	3949076.0106 Meters
	UTM Easting:	416362.060624 Meters
	UTM Zone:	UTM Zone 13S
	Elevation:	7,083.32 ft
	Slope Direction:	W

Topographic Information....2
Hydrologic Information....4
Geologic Information....7
Soil Information....10
Wells and Additional Sources....24
Summary....25
Detail Report....32
Radon Information....418
Appendix....419
Liability Notice....421

The ERIS ***Physical Setting Report - PSR*** provides comprehensive information about the physical setting around a site and includes a complete overview of topography and surface topology, in addition to hydrologic, geologic and soil characteristics. The location and detailed attributes of oil and gas wells, water wells, public water systems and radon are also included for review.

The compilation of both physical characteristics of a site and additional attribute data is useful in assessing the impact of migration of contaminants and subsequent impact on soils and groundwater.

Disclaimer

This Report does not provide a full environmental evaluation for the site or adjacent properties. Please see the terms and disclaimer at the end of the Report for greater detail.

Topographic Information



Current USGS Topo (2023)

Quadrangle(s): Santa Fe,NM


Source: USGS 7.5 Minute Topographic Map

Topographic Information


The previous topographic map(s) are created by seamlessly merging and cutting current USGS topographic data. Below are shaded relief map(s), derived from USGS elevation data to show surrounding topography in further detail.

Topographic information at project property:

Elevation: 7,083.32 ft
Slope Direction: W



Hydrologic Information



Wetland

Miles
0 0.075 0.15 0.3


N

This map shows wetland existence using data from US Fish & Wildlife.
Data coverage is shown to the right. Gray indicates no data available in the area.

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland
- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond
- Lake
- Other
- Riverine

ERIS

Hydrologic Information



Flood Hazard Zones

This map shows FEMA flood hazard zones based on FEMA's National Flood Hazard Layer. FIRM Panels are overlayed. An absent FIRM panel represents no data available.

Miles
0 0.05 0.1

N

- 1% Annual Chance Flood Hazard
- Regulatory Floodway
- Special Floodway
- Area of Undetermined Flood Hazard
- 0.2% Annual Chance Flood Hazard
- Future Conditions 1% Annual Chance Flood Hazard
- Area with Reduced Risk Due to Levee
- Area with Risk Due to Levee
- Open Water

Quadrangle(s): Santa Fe,NM

ERIS

Hydrologic Information

The Wetland Type map shows wetland existence overlaid on an aerial imagery. The Flood Hazard Zones map shows FEMA flood hazard zones overlaid on an aerial imagery. Relevant FIRM panels and detailed zone information is provided below.
For detailed Zone descriptions please click the link: https://floodadvocate.com/fema-zone-definitions

Available FIRM Panels in area:	35049C0416E(effective:2012-12-04)

Flood Zone AE-11

Zone:	AE
Zone subtype:	FLOODWAY


Flood Zone X-01

Zone:	X
Zone subtype:	0.2 PCT ANNUAL CHANCE FLOOD HAZARD

Flood Zone X-12

Zone:	X
Zone subtype:	AREA OF MINIMAL FLOOD HAZARD

Geologic Information



Geologic Units

This maps shows geologic units in the area. Please refer to the report for detailed descriptions.

N

Miles
0 0.125 0.25

ERIS

Geologic Information

The previous page shows USGS geology information. Detailed information about each unit is provided below.

Geologic Unit Qoa

Unit Name:	Older alluvial deposits of upland plains and piedmont areas, and calcic soils and eolian cover sediments of High Plains region
Unit Age:	Middle to lower Pleistocene
Primary Rock Type:	Unconsolidated
Secondary Rock Type:	
Unit Description:	Includes scattered lacustrine, playa, and alluvial deposits of the Tahoka, Double Tanks, Tule, Blanco, Blackwater Draw, and Gatuna Formations, the latter of which may be Pliocene at base; outcrops, however, are basically of Quaternary deposits.

Geologic Unit Qp

Unit Name:	Piedmont alluvial deposits
Unit Age:	Holocene to lower Pleistocene
Primary Rock Type:	Unconsolidated
Secondary Rock Type:	
Unit Description:	Includes deposits of higher gradient tributaries bordering major stream valleys, alluvial veneers of the piedmont slope, and alluvial fans. May locally include uppermost Pliocene deposits.

Geologic Unit QTs

Unit Name:	Upper Santa Fe Group
Unit Age:	Middle Pleistocene to uppermost Miocene
Primary Rock Type:	Conglomerate-sandstone
Secondary Rock Type:	Coarse-detrital
Unit Description:	Includes Camp Rice, Fort Hancock, Palomas, Sierra Ladrones, Arroyo Ojito, Ancha, Puye, and Alamosa Formations.

Geologic Unit Tsf

Unit Name:	Lower Santa Fe Group
Unit Age:	Upper Miocene to uppermost Oligocene
Primary Rock Type:	Conglomerate-sandstone
Secondary Rock Type:	Coarse-detrital
Unit Description:	Includes Hayner Ranch, Rincon Valley, Popotosa, Cochiti, Tesuque, Chamita, Abiquiu, Zia, and other formations.


Geologic Unit YXp

Unit Name:	Mesoproterozoic and Paleoproterozoic plutonic rocks, undivided
Unit Age:	Mesoproterozoic and Paleoproterozoic
Primary Rock Type:	Plutonic
Secondary Rock Type:	

Geologic Information

Unit Description:	Mesoproterozoic and Paleoproterozoic plutonic rocks, undivided

Soil Information



SSURGO Soils

N

0 0.125 0.25 Miles

This maps shows SSURGO soil units around the target property. Please refer to the report for detailed soil descriptions.

ERIS

Soil Information

The previous page shows a soil map using SSURGO data from USDA Natural Resources Conservation Service. Detailed information about each unit is provided below.

Map Unit 113 (2.48%)

Map Unit Name:	Delvalle-Urban land complex, 0 to 2 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.
Major components are printed below	
Delvalle(60%)	
horizon A(0cm to 8cm)	Fine sandy loam
horizon Bk1(8cm to 25cm)	Fine sandy loam
horizon Bk2(25cm to 48cm)	Fine sandy loam
horizon Bk3(48cm to 86cm)	Fine sandy loam
horizon Bk4(86cm to 137cm)	Sandy loam
horizon BCk1(137cm to 160cm)	Very gravelly sand
horizon BCk2(160cm to 183cm)	Extremely gravelly coarse sand
horizon C1(183cm to 234cm)	Very gravelly loamy coarse sand
horizon C2(234cm to 266cm)	Sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 113 - Delvalle-Urban land complex, 0 to 2 percent slopes

Component: Delvalle (60%)
The Delvalle component makes up 60 percent of the map unit. Slopes are 0 to 2 percent. This component is on stream terraces, valleys. The parent material consists of alluvium derived from granite, gneiss, and schist. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 3 percent. This component is in the R035XA112NM Loamy ecological site. Nonirrigated land capability classification is 6c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 3 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Urban land (30%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Devargas (5%)
Generated brief soil descriptions are created for major soil components. The Devargas soil is a minor component.

Component: Riovista (3%)
Generated brief soil descriptions are created for major soil components. The Riovista soil is a minor component.

Component: Dumps (2%)
Generated brief soil descriptions are created for major soil components. The Dumps soil is a minor component.

Map Unit 114 (8.98%)

Map Unit Name:	Devargas-Urban land complex, 1 to 3 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	

Soil Information

Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	C - Soils in this group have moderately high runoff potential when thoroughly wet. Water transmission through the soil is somewhat restricted.

Major components are printed below

Devargas(50%)

horizon A(0cm to 5cm)	Loam
horizon Bt1(5cm to 23cm)	Loam
horizon Bt2(23cm to 43cm)	Clay loam
horizon Btk1(43cm to 63cm)	Clay loam
horizon Btk2(63cm to 76cm)	Loam
horizon Bk(76cm to 84cm)	Very gravelly coarse sandy loam
horizon 2BCk(84cm to 107cm)	Extremely gravelly loamy coarse sand
horizon 2C1(107cm to 170cm)	Extremely cobbly coarse sand
horizon 2C2(170cm to 216cm)	Extremely gravelly loamy coarse sand
horizon 2C3(216cm to 239cm)	Very gravelly coarse sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 114 - Devargas-Urban land complex, 1 to 3 percent slopes

Component: Devargas (50%)
The Devargas component makes up 50 percent of the map unit. Slopes are 1 to 3 percent. This component is on high stream terraces, valleys. The parent material consists of alluvium derived from sandstone over alluvium derived from granite, gneiss, and schist. Depth to a root restrictive layer, strongly contrasting textural stratification, is 28 to 31 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the R035XA112NM Loamy ecological site. Nonirrigated land capability classification is 6c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 4 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Urban land (45%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Delvalle (3%)
Generated brief soil descriptions are created for major soil components. The Delvalle soil is a minor component.

Component: Panky (1%)
Generated brief soil descriptions are created for major soil components. The Panky soil is a minor component.

Component: Dumps (1%)
Generated brief soil descriptions are created for major soil components. The Dumps soil is a minor component.

Map Unit 122 (0.7%)

Map Unit Name:	Cuyamungue-Riverwash complex, 0 to 2 percent slopes, flooded
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Excessively drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.

Major components are printed below

Cuyamungue(60%)

horizon AC(0cm to 8cm)	Very gravelly coarse sand
horizon C1(8cm to 43cm)	Stratified gravelly coarse sand to very gravelly coarse sand
horizon C2(43cm to 61cm)	Stratified gravelly coarse sand to very gravelly coarse sand
horizon C3(61cm to 89cm)	Very gravelly coarse sand

horizon C4(89cm to 147cm)	Stratified gravelly coarse sand to extremely gravelly coarse sand
horizon C5(147cm to 218cm)	Stratified very gravelly coarse sand to extremely gravelly coarse sand
horizon C6(218cm to 254cm)	Extremely gravelly loamy coarse sand
Riverwash(30%)	
horizon C1(0cm to 25cm)	Gravelly coarse sand
horizon C2(25cm to 127cm)	Very gravelly coarse sand
horizon C3(127cm to 165cm)	Gravelly sandy loam
horizon C4(165cm to 216cm)	Gravelly coarse sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 122 - Cuyamungue-Riverwash complex, 0 to 2 percent slopes, flooded

Component: Cuyamungue (60%)
The Cuyamungue component makes up 60 percent of the map unit. Slopes are 0 to 2 percent. This component is on flood plains on valley floors, valleys. The parent material consists of alluvium derived from granite, gneiss, schist, and granitic sandstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is excessively drained. Water movement in the most restrictive layer is very high. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is low. This soil is frequently flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 0 percent. This component is in the F036XA005NM Riverine Riparian ecological site. Nonirrigated land capability classification is 4w. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 1 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Riverwash (30%)
Generated brief soil descriptions are created for major soil components. The Riverwash is a miscellaneous area.

Component: Zia (4%)
Generated brief soil descriptions are created for major soil components. The Zia soil is a minor component.

Component: Bosquecito (3%)
Generated brief soil descriptions are created for major soil components. The Bosquecito soil is a minor component.

Component: Mirada (2%)
Generated brief soil descriptions are created for major soil components. The Mirada soil is a minor component.

Component: Scogg (1%)
Generated brief soil descriptions are created for major soil components. The Scogg soil is a minor component.

Map Unit 206 (1.41%)

Map Unit Name:	Encantado very cobbly sandy loam, 25 to 45 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Somewhat excessively drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.
Major components are printed below	
Encantado(90%)	
horizon ABk(0cm to 5cm)	Very cobbly sandy loam
horizon Bk1(5cm to 20cm)	Gravelly sandy loam
horizon Bk2(20cm to 30cm)	Gravelly coarse sandy loam
horizon Bk3(30cm to 61cm)	Very gravelly coarse sandy loam
horizon BCk(61cm to 79cm)	Gravelly loamy sand
horizon BCk1(79cm to 142cm)	Very gravelly loamy coarse sand
horizon BCk2(142cm to 170cm)	Gravelly loamy sand
horizon C(170cm to 208cm)	Gravelly loamy coarse sand

Soil Information

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 206 - Encantado very cobbly sandy loam, 25 to 45 percent slopes

Component: Encantado (90%)
The Encantado component makes up 90 percent of the map unit. Slopes are 25 to 45 percent. This component is on eroded fan remnants, fan piedmonts. The parent material consists of colluvium derived from granite, gneiss, and schist over residuum weathered from granitic fanglomerate and sandstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the F036XA136NM Pinyon-juniper-apache Plume ecological site. Nonirrigated land capability classification is 7e. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 23 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Nazario (4%)
Generated brief soil descriptions are created for major soil components. The Nazario soil is a minor component.

Component: Encantado (3%)
Generated brief soil descriptions are created for major soil components. The Encantado soil is a minor component.

Component: Urban land (2%)
Generated brief soil descriptions are created for major soil components. The Urban land soil is a minor component.

Component: Rock outcrop (1%)
Generated brief soil descriptions are created for major soil components. The Rock outcrop soil is a minor component.

Map Unit 207 (42.19%)

Map Unit Name: Urban land

No more attributes available for this map unit

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 207 - Urban land

Component: Urban land (85%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Alire (4%)
Generated brief soil descriptions are created for major soil components. The Alire soil is a minor component.

Component: Panky (3%)
Generated brief soil descriptions are created for major soil components. The Panky soil is a minor component.

Component: Altazano (2%)
Generated brief soil descriptions are created for major soil components. The Altazano soil is a minor component.

Component: Buckhorse (2%)
Generated brief soil descriptions are created for major soil components. The Buckhorse soil is a minor component.

Component: Predawn (2%)
Generated brief soil descriptions are created for major soil components. The Predawn soil is a minor component.

Component: Delvalle (1%)
Generated brief soil descriptions are created for major soil components. The Delvalle soil is a minor component.

Component: Tanoan (1%)
Generated brief soil descriptions are created for major soil components. The Tanoan soil is a minor component.

Soil Information

Map Unit 208 (23.68%)

Map Unit Name:	Alire-Urban land complex, 2 to 8 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	C - Soils in this group have moderately high runoff potential when thoroughly wet. Water transmission through the soil is somewhat restricted.

Major components are printed below

Alire(50%)

horizon A(0cm to 10cm)	Loam
horizon Bt(10cm to 28cm)	Clay loam
horizon Btk1(28cm to 51cm)	Clay loam
horizon Btk2(51cm to 69cm)	Loam
horizon Bk1(69cm to 107cm)	Loam
horizon Bk2(107cm to 130cm)	Gravelly loam
horizon Bkq1(130cm to 175cm)	Gravelly loam
horizon Bkq2(175cm to 241cm)	Gravelly loam
horizon C(241cm to 251cm)	Gravelly sandy loam

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 208 - Alire-Urban land complex, 2 to 8 percent slopes

Component: Alire (50%)
The Alire component makes up 50 percent of the map unit. Slopes are 2 to 8 percent. This component is on beveled eroded fan remnants, fan piedmonts. The parent material consists of alluvium derived from granite, gneiss, schist, and loess. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is high. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the R035XA112NM Loamy ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 23 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 9 within 30 inches of the soil surface.

Component: Urban land (40%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Predawn (4%)
Generated brief soil descriptions are created for major soil components. The Predawn soil is a minor component.

Component: Tanoan (3%)
Generated brief soil descriptions are created for major soil components. The Tanoan soil is a minor component.

Component: Altazano (2%)
Generated brief soil descriptions are created for major soil components. The Altazano soil is a minor component.

Component: Encantado (1%)
Generated brief soil descriptions are created for major soil components. The Encantado soil is a minor component.

Map Unit 210 (1.09%)

Map Unit Name:	Urban land-Buckhorse-Altazano complex, 2 to 8 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	

Soil Information

Drainage Class - Dominant:

Hydrologic Group - Dominant:

Major components are printed below

Buckhorse(20%)

horizon A(0cm to 10cm)	Coarse sandy loam
horizon Bt(10cm to 28cm)	Coarse sandy loam
horizon Btk1(28cm to 56cm)	Loam
horizon Btk2(56cm to 94cm)	Loam
horizon Bk(94cm to 124cm)	Fine sandy loam
horizon BCk(124cm to 155cm)	Sandy loam
horizon C(155cm to 211cm)	Gravelly coarse sand

Altazano(10%)

horizon AC(0cm to 5cm)	Gravelly sandy loam
horizon C1(5cm to 20cm)	Gravelly coarse sandy loam
horizon C2(20cm to 48cm)	Very gravelly loamy coarse sand
horizon C3(48cm to 74cm)	Gravelly sandy loam
horizon Btkb1(74cm to 117cm)	Loam
horizon Btkb2(117cm to 165cm)	Loam
horizon BCkb(165cm to 188cm)	Gravelly coarse sandy loam
horizon Ckb(188cm to 229cm)	Gravelly loamy coarse sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 210 - Urban land-Buckhorse-Altazano complex, 2 to 8 percent slopes

Component: Urban land (60%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Buckhorse (20%)
The Buckhorse component makes up 20 percent of the map unit. Slopes are 2 to 8 percent. This component is on eroded fan remnants, fan piedmonts. The parent material consists of slope alluvium derived from granite, gneiss, schist, granitic sandstone, fanglomerate, and mudstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the R035XA112NM Loamy ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 10 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Altazano (10%)
The Altazano component makes up 10 percent of the map unit. Slopes are 2 to 8 percent. This component is on eroded fan remnants, fan piedmonts. The parent material consists of slope alluvium derived from granite, gneiss, schist, granitic sandstone, fanglomerate, and mudstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is frequently flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the R035XG114NM Gravelly ecological site. Nonirrigated land capability classification is 4w. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 13 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Levante (7%)
Generated brief soil descriptions are created for major soil components. The Levante soil is a minor component.

Component: Riverwash (3%)
Generated brief soil descriptions are created for major soil components. The Riverwash soil is a minor component.

Map Unit 211 (11.36%)

Soil Information

Map Unit Name:	Tanoan-Encantado-Urban land complex, 5 to 25 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Somewhat excessively drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.

Major components are printed below

Tanoan(35%)

horizon A(0cm to 8cm)	Gravelly sandy loam
horizon Bk1(8cm to 18cm)	Loam
horizon Bk2(18cm to 61cm)	Loam
horizon Bk3(61cm to 81cm)	Sandy loam
horizon Bkq(81cm to 145cm)	Loam
horizon BCk1(145cm to 178cm)	Gravelly loamy coarse sand
horizon BCk2(178cm to 213cm)	Gravelly coarse sandy loam

Encantado(30%)

horizon ABk(0cm to 8cm)	Very gravelly sandy loam
horizon Bk1(8cm to 23cm)	Very gravelly loam
horizon Bk2(23cm to 56cm)	Very gravelly coarse sandy loam
horizon BCk1(56cm to 84cm)	Gravelly loamy coarse sand
horizon BCk2(84cm to 114cm)	Very gravelly loamy coarse sand
horizon BCk3(114cm to 137cm)	Very gravelly loamy coarse sand
horizon C1(137cm to 160cm)	Gravelly loamy sand
horizon C2(160cm to 216cm)	Very gravelly loamy sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 211 - Tanoan-Encantado-Urban land complex, 5 to 25 percent slopes

Component: Tanoan (35%)
The Tanoan component makes up 35 percent of the map unit. Slopes are 5 to 15 percent. This component is on eroded fan remnants, fan piedmonts. The parent material consists of alluvium derived from granite, gneiss, schist, and loess over residuum weathered from basaltic tuff or granitic sandstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the F036XA136NM Pinyon-juniper-apache Plume ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 15 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Encantado (30%)
The Encantado component makes up 30 percent of the map unit. Slopes are 10 to 25 percent. This component is on eroded fan remnants, fan piedmonts. The parent material consists of colluvium and slope alluvium derived from granite, gneiss, and schist over residuum weathered from granitic fanglomerate and sandstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the F036XA136NM Pinyon-juniper-apache Plume ecological site. Nonirrigated land capability classification is 4s. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 27 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Urban land (25%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Altazano (4%)
Generated brief soil descriptions are created for major soil components. The Altazano soil is a minor component.

Component: Junebee (3%)
Generated brief soil descriptions are created for major soil components. The Junebee soil is a minor component.

Soil Information

Component: Nazario (2%)
Generated brief soil descriptions are created for major soil components. The Nazario soil is a minor component.

Component: Alire (1%)
Generated brief soil descriptions are created for major soil components. The Alire soil is a minor component.

Map Unit 213 (0.44%)

Map Unit Name:	Levante-Riverwash complex, 1 to 3 percent slopes, flooded
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Excessively drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.

Major components are printed below

Levante(55%)	
horizon AC(0cm to 10cm)	Loamy sand
horizon C1(10cm to 43cm)	Coarse sand
horizon C2(43cm to 81cm)	Gravelly coarse sand
horizon C3(81cm to 114cm)	Stratified gravelly loamy coarse sand to gravelly coarse sand
horizon C4(114cm to 147cm)	Gravelly loamy coarse sand
horizon C5(147cm to 218cm)	Very gravelly coarse sand
horizon C6(218cm to 310cm)	Very gravelly coarse sand
Riverwash(35%)	
horizon C1(0cm to 25cm)	Gravelly coarse sand
horizon C2(25cm to 127cm)	Very gravelly coarse sand
horizon C3(127cm to 165cm)	Gravelly sandy clay loam
horizon C4(165cm to 216cm)	Gravelly coarse sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 213 - Levante-Riverwash complex, 1 to 3 percent slopes, flooded

Component: Levante (55%)
The Levante component makes up 55 percent of the map unit. Slopes are 1 to 3 percent. This component is on narrow flood plains on valley floors, valleys. The parent material consists of alluvium derived from granite, gneiss, schist, and granitic sandstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is excessively drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is low. This soil is occasionally flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the R035XA113NM Sandy ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 7 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Riverwash (35%)
Generated brief soil descriptions are created for major soil components. The Riverwash is a miscellaneous area.

Component: Altazano (5%)
Generated brief soil descriptions are created for major soil components. The Altazano soil is a minor component.

Component: Dondiego (3%)
Generated brief soil descriptions are created for major soil components. The Dondiego soil is a minor component.

Component: Urban land (2%)
Generated brief soil descriptions are created for major soil components. The Urban land soil is a minor component.

Soil Information

Map Unit 214 (0.95%)

Map Unit Name:	Nazario-Urban land complex, 2 to 8 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	B - Soils in this group have moderately low runoff potential when thoroughly wet. Water transmission through the soil is unimpeded.

Major components are printed below

Nazario(55%)

horizon ABk(0cm to 5cm)	Gravelly loam
horizon Bk1(5cm to 18cm)	Gravelly loam
horizon Bk2(18cm to 38cm)	Gravelly loam
horizon Bk3(38cm to 61cm)	Gravelly loam
horizon 2BCk1(61cm to 109cm)	Very gravelly loamy coarse sand
horizon 2BCk2(109cm to 132cm)	Gravelly loamy coarse sand
horizon 2C1(132cm to 170cm)	Coarse sand
horizon 2C2(170cm to 239cm)	Gravelly coarse sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 214 - Nazario-Urban land complex, 2 to 8 percent slopes

Component: Nazario (55%)
The Nazario component makes up 55 percent of the map unit. Slopes are 2 to 8 percent. This component is on beveled eroded fan remnants, fan piedmonts. The parent material consists of alluvium derived from granite, gneiss, schist, and loess over residuum weathered from granitic fanglomerate and sandstone. Depth to a root restrictive layer, strongly contrasting textural stratification, is 20 to 28 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the F036XA136NM Pinyon-juniper-apache Plume ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 28 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Urban land (30%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Alire (8%)
Generated brief soil descriptions are created for major soil components. The Alire soil is a minor component.

Component: Encantado (4%)
Generated brief soil descriptions are created for major soil components. The Encantado soil is a minor component.

Component: Tanoan (3%)
Generated brief soil descriptions are created for major soil components. The Tanoan soil is a minor component.

Map Unit 301 (1.32%)

Map Unit Name:	Enmedio-Atalaya-Rock outcrop complex, 5 to 60 percent slopes
Bedrock Depth - Min:	117cm
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	C - Soils in this group have moderately high runoff potential when thoroughly wet. Water transmission through the soil is somewhat restricted.

Major components are printed below

Enmedio(60%)

horizon A(0cm to 5cm)	Extremely cobbly sandy loam
horizon Bt1(5cm to 13cm)	Very gravelly sandy clay loam
horizon Bt2(13cm to 32cm)	Very gravelly sandy clay loam
horizon Bt3(32cm to 47cm)	Very gravelly sandy clay loam
horizon 2Ct(47cm to 89cm)	Cobbles
horizon 2C(89cm to 117cm)	Cobbles
horizon 2R(117cm to 142cm)	Bedrock
Atalaya(20%)	
horizon A(0cm to 3cm)	Very gravelly sandy loam
horizon Bt1(3cm to 10cm)	Gravelly coarse sandy loam
horizon Bt2(10cm to 18cm)	Gravelly coarse sandy loam
horizon Bt3(18cm to 31cm)	Gravelly coarse sandy loam
horizon BC1(31cm to 60cm)	Gravelly coarse sandy loam
horizon BC2(60cm to 87cm)	Cobbly coarse sandy loam
horizon 2CBk(87cm to 127cm)	Cobbles
horizon 2R(127cm to 152cm)	Bedrock
Rock outcrop(10%)	
horizon R(0cm to 158cm)	Bedrock

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 301 - Enmedio-Atalaya-Rock outcrop complex, 5 to 60 percent slopes

Component: Enmedio (60%)
The Enmedio component makes up 60 percent of the map unit. Slopes are 15 to 60 percent. This component is on hills, foothills. The parent material consists of colluvium derived from granite, gneiss, and schist over residuum weathered from granite. Depth to a root restrictive layer, strongly contrasting textural stratification, is 18 to 39 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is very low. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the F048AY015NM Unspecified ecological site. Nonirrigated land capability classification is 7e. This soil does not meet hydric criteria. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Atalaya (20%)
The Atalaya component makes up 20 percent of the map unit. Slopes are 5 to 15 percent. This component is on beveled hills, foothills. The parent material consists of slope alluvium derived from granite, gneiss, and schist over residuum weathered from granite and schist. Depth to a root restrictive layer, strongly contrasting textural stratification, is 20 to 39 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is very low. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the F048AY015NM Unspecified ecological site. Nonirrigated land capability classification is 4e. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 3 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Rock outcrop (10%)
Generated brief soil descriptions are created for major soil components. The Rock outcrop is a miscellaneous area.

Component: Setonville (7%)
Generated brief soil descriptions are created for major soil components. The Setonville soil is a minor component.

Component: Urban land (3%)
Generated brief soil descriptions are created for major soil components. The Urban land soil is a minor component.

Map Unit 302 (1.59%)

Map Unit Name:	Setonville-Antonchico complex, 3 to 15 percent slopes
Bedrock Depth - Min:	107cm
Watertable Depth - Annual Min:	

Soil Information

Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	C - Soils in this group have moderately high runoff potential when thoroughly wet. Water transmission through the soil is somewhat restricted.

Major components are printed below

Setonville(70%)

horizon A(0cm to 5cm)	Very gravelly sandy loam
horizon Bt(5cm to 20cm)	Very gravelly clay loam
horizon Btk(20cm to 33cm)	Very gravelly sandy clay loam
horizon Bk1(33cm to 51cm)	Gravelly sandy clay loam
horizon Bk2(51cm to 71cm)	Very gravelly sandy loam
horizon 2BCk1(71cm to 92cm)	Gravel
horizon 2BCk2(92cm to 114cm)	Cobbles
horizon 2R(114cm to 139cm)	Bedrock

Antonchico(20%)

horizon A(0cm to 5cm)	Gravelly sandy loam
horizon Bt1(5cm to 18cm)	Gravelly sandy clay loam
horizon Bt2(18cm to 36cm)	Gravelly sandy clay loam
horizon Bt3(36cm to 52cm)	Gravelly sandy clay loam
horizon 2BCk(52cm to 107cm)	Cobbles
horizon 2R(107cm to 132cm)	Bedrock

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 302 - Setonville-Antonchico complex, 3 to 15 percent slopes

Component: Setonville (70%)
The Setonville component makes up 70 percent of the map unit. Slopes are 5 to 15 percent. This component is on hills, foothills. The parent material consists of slope alluvium derived from granite, gneiss, and schist over residuum weathered from granite. Depth to a root restrictive layer, strongly contrasting textural stratification, is 20 to 31 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is very low. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the F048AY017NM Unspecified ecological site. Nonirrigated land capability classification is 4s. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 32 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Antonchico (20%)
The Antonchico component makes up 20 percent of the map unit. Slopes are 3 to 5 percent. This component is on beveled hills, foothills. The parent material consists of slope alluvium derived from granite, gneiss, and schist over residuum weathered from schist. Depth to a root restrictive layer, strongly contrasting textural stratification, is 20 to 42 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is very low. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the F048AY017NM Unspecified ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 26 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Atalaya (5%)
Generated brief soil descriptions are created for major soil components. The Atalaya soil is a minor component.

Component: Enmedio (4%)
Generated brief soil descriptions are created for major soil components. The Enmedio soil is a minor component.

Component: Urban land (1%)
Generated brief soil descriptions are created for major soil components. The Urban land soil is a minor component.

Map Unit 304 (3.8%)

Map Unit Name:	Legate-Yohalem-Zarmand complex, 5 to 50 percent slopes

Soil Information

Bedrock Depth - Min:	38cm
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Somewhat excessively drained
Hydrologic Group - Dominant:	D - Soils in this group have high runoff potential when thoroughly wet. Water movement through the soil is restricted or very restricted.

Major components are printed below

Legate(60%)	
horizon Ak(0cm to 5cm)	Extremely gravelly sandy loam
horizon Bk1(5cm to 23cm)	Very gravelly fine sandy loam
horizon Bk2(23cm to 36cm)	Very gravelly sandy loam
horizon Bk3(36cm to 46cm)	Very gravelly sandy loam
horizon 2R(46cm to 71cm)	Bedrock
Yohalem(20%)	
horizon A(0cm to 3cm)	Very gravelly clay loam
horizon Bw(3cm to 18cm)	Paragravelly clay loam
horizon BCky(18cm to 38cm)	Extremely paragravelly clay
horizon Cr(38cm to 63cm)	Bedrock
Zarmand(15%)	
horizon A(0cm to 3cm)	Extremely channery fine sandy loam
horizon ABk(3cm to 23cm)	Gravelly fine sandy loam
horizon Bk1(23cm to 43cm)	Gravelly loam
horizon 2Bk2(43cm to 61cm)	Paragravelly loam
horizon 2Crk(61cm to 74cm)	Bedrock
horizon 2R(74cm to 99cm)	Bedrock

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 304 - Legate-Yohalem-Zarmand complex, 5 to 50 percent slopes

Component: Legate (60%)
The Legate component makes up 60 percent of the map unit. Slopes are 15 to 45 percent. This component is on hills, foothills. The parent material consists of colluvium derived from limestone. Depth to a root restrictive layer, bedrock, lithic, is 10 to 20 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is very low. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is moderate. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the F048AY015NM Unspecified ecological site. Nonirrigated land capability classification is 7s. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 72 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Yohalem (20%)
The Yohalem component makes up 20 percent of the map unit. Slopes are 30 to 50 percent. This component is on hills, foothills. The parent material consists of colluvium derived from shale and limestone over residuum weathered from shale. Depth to a root restrictive layer, bedrock, paralithic, is 10 to 20 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is very low. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is very high. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the F048AY015NM Unspecified ecological site. Nonirrigated land capability classification is 6e. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 5 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.


Component: Zarmand (15%)
The Zarmand component makes up 15 percent of the map unit. Slopes are 5 to 15 percent. This component is on foothills. The parent material consists of alluvium derived from limestone and sandstone over residuum weathered from limestone. Depth to a root restrictive layer, bedrock, paralithic, is 20 to 30 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is very low. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is moderate. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the F048AY015NM Unspecified ecological site. Nonirrigated land capability classification is 7s. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 58 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium

adsorption ratio of 2 within 30 inches of the soil surface.

Component: Rock outcrop (3%)
Generated brief soil descriptions are created for major soil components. The Rock outcrop soil is a minor component.

Component: Urban land (2%)
Generated brief soil descriptions are created for major soil components. The Urban land soil is a minor component.

Wells and Additional Sources



Wells & Additional Sources

N

0 0.15 0.3 0.6 Miles

- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- OGW Sites with Higher Elevation
- OGW Sites with Same Elevation
- OGW Sites with Lower Elevation
- OGW Sites with Unknown Elevation

ERIS

Wells and Additional Sources Summary

Federal Sources

Public Water Systems Violations and Enforcement Data

Map Key	PWS ID	Distance (ft)	Direction
227	NM3580226	3995.97	WNW
344	NM3590826	5077.40	NW

Safe Drinking Water Information System (SDWIS)

Map Key	PWS ID	Distance (ft)	Direction
81	NM3591526	2213.23	ESE
227	NM3580226	3995.97	WNW
344	NM3590826	5077.40	NW

USGS National Water Information System

Map Key	Site No	Distance (ft)	Direction
1	USGS-354053105552601	172.20	SSW
77	USGS-354104105555010	2153.28	WNW
113	USGS-354104105555510	2534.14	WNW
141	USGS-354046105560001	2932.88	WSW
152	USGS-354103105560210	3053.20	WNW
179	USGS-354039105560301	3442.32	WSW
181	USGS-354113105560201	3456.62	WNW
211	USGS-354025105555501	3841.02	SW
213	USGS-354019105550701	3933.03	SSE
292	USGS-354113105561801	4633.56	WNW
334	USGS-354032105562001	5012.53	WSW
336	USGS-354052105562701	5020.23	W
337	USGS-354100105562701	5034.03	W
338	USGS-354106105562610	5048.18	WNW
353	USGS-354130105561210	5161.93	NW
354	USGS-354107105562700	5151.28	WNW

State Sources

Oil and Gas Wells

Map Key	ID	Distance (ft)	Direction
	No records found		

Point of Diversion Report

Map Key	POD Rec No	Distance (ft)	Direction
2	170332	283.36	ESE
3	333772	373.08	WNW
4	272507	401.54	ESE
5	19029	564.01	SE
6	51451	625.03	W
7	180566	691.57	SSW

Wells and Additional Sources Summary

8	26213	722.50	N
9	64511	752.40	NNW
10	37398	803.61	SSE
11	7415	844.34	ESE
12	334346	930.18	S
13	17079	921.08	SSW
14	212857	952.89	WNW
15	35434	983.67	S
16	48250	1009.52	WNW
17	196983	1009.33	NE
18	3555	1122.89	WSW
19	66847	1134.76	SSW
20	20448	1149.55	SW
21	51673	1196.72	NW
22	67859	1187.23	WNW
23	23131	1210.07	N
24	147388	1206.50	ESE
25	50259	1217.73	S
26	3523	1266.13	WNW
27	6181	1350.25	SSE
28	11264	1336.01	WSW
29	47351	1335.11	WNW
30	199068	1341.86	W
31	241265	1363.77	ESE
31	13479	1363.77	ESE
32	58289	1432.16	SE
33	39279	1420.31	WSW
34	47085	1444.61	E
35	38433	1546.77	SSE
36	61605	1539.03	NW
37	34043	1566.59	NW
38	2148	1561.09	S
39	49698	1559.58	W
40	54526	1604.45	NW
41	40696	1579.96	W
42	161433	1626.73	WNW
43	12420	1631.23	ESE
44	21582	1642.86	SW
45	287608	1644.83	W
46	11080	1649.57	W
47	334055	1675.67	S
48	28211	1661.48	SSW
49	244529	1667.69	WNW
50	26436	1699.88	NW
51	325503	1728.86	E
52	205389	1748.85	WNW
53	146760	1794.45	NW
54	9958	1775.99	ESE
55	146889	1859.42	SSE
56	22644	1834.12	SW
57	60337	1905.43	S
58	40319	1929.68	SSE
59	42901	1943.84	ESE
60	162543	1988.83	ESE
61	58127	1991.67	SW
62	21922	1992.10	WSW
63	44008	2004.37	SW
64	45725	2048.40	SSW
65	67600	2039.85	ENE
66	18737	2042.24	WSW
67	173238	2059.17	S
68	154803	2080.48	NW
69	147896	2060.85	SSW
70	6748	2101.92	SE
71	59116	2111.80	NW
72	8592	2155.84	NNW

72	26510	2155.84	NNW
72	143661	2155.84	NNW
73	25205	2151.83	S
74	16933	2136.83	SW
75	12381	2141.89	E
76	36099	2144.65	E
78	3655	2151.97	ENE
79	170246	2150.97	W
80	61887	2200.22	N
82	60616	2248.32	NNW
83	51116	2214.07	WNW
84	10217	2243.62	SE
85	236868	2254.69	WSW
85	237237	2254.69	WSW
86	105580	2290.44	S
87	44087	2301.64	W
88	34861	2335.27	S
89	34267	2341.01	S
90	55843	2326.09	W
91	145523	2327.27	W
92	47541	2343.48	WNW
93	25978	2351.37	WSW
94	33301	2363.98	SSW
95	36502	2375.40	ESE
96	37913	2382.98	SW
97	2300	2391.67	SSW
98	152366	2426.35	SE
99	177236	2396.46	ESE
99	151588	2396.46	ESE
100	27388	2414.56	S
101	295910	2398.73	ESE
102	32100	2425.59	ESE
103	14937	2462.82	SSE
104	197078	2437.25	SW
105	48425	2448.29	SSW
106	282754	2460.16	WSW
107	197077	2479.60	W
108	197079	2487.64	SSW
109	24289	2522.50	NW
110	197877	2500.66	SSW
111	285779	2509.77	SW
112	334537	2534.84	WNW
112	8784	2534.84	WNW
114	157764	2535.68	WSW
115	341180	2545.54	SW
116	25067	2582.21	N
117	18083	2558.67	WSW
118	21290	2575.81	E
119	104934	2628.19	E
119	80815	2628.19	E
120	24565	2629.87	W
121	339881	2680.53	WSW
122	339880	2732.51	WSW
123	80814	2730.49	E
123	338069	2730.49	E
124	57818	2745.88	SW
125	146943	2760.89	E
126	339879	2761.83	WSW
127	51104	2777.92	SSW
128	44010	2806.97	SE
129	25832	2801.27	E
130	197575	2826.13	S
131	10548	2802.84	E
132	52131	2842.62	SE
132	17495	2842.62	SE
133	36762	2817.45	W

134	36980	2827.05	W
135	142014	2845.49	SSW
136	23145	2874.62	SSE
137	337651	2850.50	SW
138	139929	2874.67	SW
139	196619	2913.56	S
140	49621	2952.75	NW
142	333151	2943.63	WSW
143	19910	2968.22	ESE
144	42534	2994.63	SSW
145	15825	3017.96	SE
146	195967	3040.87	NW
147	27075	3023.20	W
148	45295	3028.86	SW
149	44800	3032.81	WSW
150	48012	3037.00	ESE
151	15734	3040.35	SSW
153	58088	3056.37	W
154	42592	3072.51	SSW
155	45114	3077.38	S
156	147430	3083.47	WNW
157	65820	3091.00	W
158	50582	3144.97	SW
159	59540	3169.45	S
160	296840	3149.06	SW
161	169331	3151.51	W
162	32816	3188.30	WNW
163	69858	3197.31	S
164	67447	3192.63	W
165	69509	3196.44	SW
165	333099	3196.44	SW
166	275692	3197.55	WSW
166	6700	3197.55	WSW
167	22249	3224.56	ENE
168	11795	3250.01	NW
169	29795	3258.31	NW
170	143277	3296.36	E
171	46176	3300.34	WSW
172	36804	3300.05	E
173	331148	3335.36	ESE
174	2551	3387.94	ESE
175	46479	3394.17	ESE
176	221255	3395.81	WSW
177	62125	3441.34	S
178	52631	3436.12	SW
180	9616	3443.22	E
182	63677	3448.62	W
183	335283	3456.88	W
184	196985	3468.68	E
185	45459	3470.67	E
186	62555	3525.95	ESE
187	22175	3556.58	S
188	12660	3535.86	WSW
189	3509	3555.87	ESE
190	291975	3560.27	W
191	21806	3586.72	ESE
192	2688	3579.55	W
193	130574	3614.94	S
193	148509	3614.94	S
194	290334	3606.58	WSW
194	54561	3606.58	WSW
195	53638	3614.12	WSW
196	202114	3652.64	S
197	16434	3636.83	E
198	36178	3714.09	S
199	70020	3711.42	SSW

200	50448	3731.04	ESE
201	355653	3745.33	WSW
202	142917	3754.34	NNE
203	333096	3777.15	S
204	146884	3766.17	E
205	235372	3769.97	SW
206	35290	3776.25	E
207	63741	3806.39	WSW
208	196558	3828.25	WSW
209	307222	3833.52	SW
210	339032	3837.86	WSW
212	338812	3873.21	W
214	15951	3892.69	WSW
215	40682	3903.08	W
216	13668	3919.09	WSW
217	351493	3919.79	E
218	301879	3939.38	NW
219	131410	3928.13	SW
220	21074	3927.61	E
221	80129	3960.39	SW
222	60584	3961.15	E
223	147367	3981.78	SE
224	42191	3973.64	WSW
225	64655	3988.11	SSW
226	49702	3991.12	ESE
228	49303	3996.61	WNW
229	246340	4002.05	W
230	21085	4028.71	NW
231	67173	4019.41	SSW
232	15787	4023.92	E
233	246341	4049.84	W
234	20920	4060.01	SSW
235	343503	4054.08	W
236	145138	4087.06	S
237	330690	4071.35	WSW
238	343502	4070.68	W
239	16232	4073.49	E
240	246336	4073.53	W
240	271064	4073.53	W
241	343505	4096.95	W
242	343504	4098.19	W
243	343506	4101.01	W
244	16097	4110.11	WSW
245	343507	4109.52	W
246	327368	4111.93	W
247	29206	4117.24	SW
248	291430	4117.37	W
248	291429	4117.37	W
249	56428	4120.96	SW
250	343501	4122.67	W
251	327367	4128.40	W
252	327370	4131.73	W
253	291431	4133.77	W
253	271096	4133.77	W
254	327369	4155.20	W
255	305087	4159.17	W
256	163069	4182.77	SW
257	139844	4190.09	WSW
258	301873	4198.96	WNW
259	199573	4201.32	WSW
260	105647	4210.32	SW
261	275742	4229.55	E
262	32449	4252.56	ENE
263	28075	4264.60	SSW
264	301876	4277.41	NW
265	8265	4265.89	ESE

266	8603	4263.57	E
267	241491	4294.35	SSW
268	146887	4325.12	WSW
269	301874	4351.81	WNW
270	48299	4387.36	SE
271	301872	4400.84	WNW
272	297680	4412.47	WNW
273	9399	4471.05	SE
274	24079	4482.34	SE
275	30009	4465.78	ESE
276	31947	4461.93	W
277	21964	4471.49	ESE
278	158206	4476.22	ESE
278	147427	4476.22	ESE
279	61848	4501.71	S
280	37909	4507.77	S
281	52864	4531.51	WSW
282	57856	4571.86	S
283	6470	4571.00	SSW
284	301877	4584.41	NW
285	155871	4566.10	W
286	24956	4580.33	ESE
287	58504	4577.85	WNW
288	58529	4581.57	SW
289	70853	4628.76	SE
290	301878	4619.08	NW
291	28562	4644.68	SE
293	66581	4641.80	ESE
294	147121	4653.06	SSW
295	324797	4650.53	SW
296	24157	4667.39	SW
297	335808	4665.78	E
298	54636	4676.85	WNW
299	26301	4708.97	SE
300	41448	4714.72	SE
301	8653	4688.77	SW
302	19072	4736.32	NNW
303	139928	4732.82	S
304	42452	4710.99	SW
305	185008	4717.23	ESE
305	68780	4717.23	ESE
306	51211	4727.76	ESE
307	45421	4729.90	E
308	338891	4742.05	WNW
309	147086	4781.84	NNW
310	17464	4776.03	SSW
311	246270	4788.48	ESE
311	22216	4788.48	ESE
312	18487	4828.67	NW
313	301875	4832.57	WNW
314	7604	4835.73	ESE
315	44043	4840.76	S
316	6899	4839.59	SSW
317	18946	4875.63	S
317	52541	4875.63	S
318	3300	4852.31	W
319	43645	4867.37	NE
320	313141	4887.62	ESE
321	8445	4925.65	NNW
322	54226	4882.53	SSW
323	30152	4897.17	ESE
324	36763	4900.89	ESE
325	338183	4908.03	SW
326	17420	4916.06	E
327	2195	4925.67	E
328	41531	4933.08	SSW

329	46802	4931.70	E
330	150306	4937.89	E
331	325652	4959.56	SW
332	30475	4964.23	SW
333	61279	4998.64	SE
335	53338	5054.21	SSE
339	15057	5048.71	SW
340	54726	5052.55	SW
341	297677	5052.93	W
342	63069	5062.80	NNE
343	28666	5062.03	SSW
345	287038	5066.72	W
346	13817	5072.64	SW
347	147732	5091.64	W
348	33152	5101.92	WSW
349	64469	5105.78	E
350	65668	5124.54	WSW
351	63070	5133.39	E
352	28625	5137.95	WSW
352	333618	5137.95	WSW
355	47363	5205.23	NNW
356	27335	5209.33	SSW
357	11048	5220.85	SSW
358	31617	5215.79	WSW
359	43641	5232.50	W
360	46530	5234.22	E
361	44048	5237.03	SW
362	5004	5242.22	WSW
363	297679	5242.27	WNW
364	145898	5256.91	E

Public Water Supply Wells

Map Key	ID	Distance (ft)	Direction
	No records found		

Public Water Systems Violations and Enforcement Data

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
227	WNW	0.76	3,995.97	7,002.29	PWSV

PWS ID:	NM3580226
PWS Type Code:	TNCWS
PWS Type Description:	Transient non-community system
Primary Source Code:	GW
Primary Source Desc:	Ground water
PWS Activity Code:	N
PWS Activity Description:	Changed from public to non-public
PWS Deactivation Date:	01/26/2006
Zip Code:	87501
Phone No:	505-988-9232
Phone Ext No:	
Admin Name:	
Alt Phone No:	
Email Addr:	
Fax No:	
Cds ID:	
Population Served Count:	0
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	05/18/1987
Gw or Sw:	Groundwater
Gw Sw Code:	GW
Is Grant Eligible Ind:	No
Outstanding Performer:	
Is School or Daycare Ind:	No
Is Source Water Protection:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Lt2 Schedule Cat Code:	
Last Reported Date:	06/25/2025
Org Name:	
Outstanding Perform Begin Date:	
Owner Type:	Private
Pop Cat 11:	<=100
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Season Begin Date:	01-01

Wells and Additional Sources Detail Report

Season End Date:	12-31
Service Connections Count:	1
Submission Status Code:	Y
Submissionyearquarter:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin Date:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	
County Served:	Santa Fe
Source Water Protection Code:	N

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
344	NW	0.96	5,077.40	6,996.13	PWSV

PWS ID:	NM3590826
PWS Type Code:	NTNCWS
PWS Type Description:	Non-Transient non-community system
Primary Source Code:	GW
Primary Source Desc:	Ground water
PWS Activity Code:	N
PWS Activity Description:	Changed from public to non-public
PWS Deactivation Date:	02/09/2006
Zip Code:	87504
Phone No:	505-984-6543
Phone Ext No:	
Admin Name:	
Alt Phone No:	
Email Addr:	
Fax No:	
Cds ID:	
Population Served Count:	80
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	03/12/1980
Gw or Sw:	Groundwater
Gw Sw Code:	GW
Is Grant Eligible Ind:	No
Outstanding Performer:	
Is School or Daycare Ind:	No

Is Source Water Protection:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Lt2 Schedule Cat Code:	
Last Reported Date:	06/25/2025
Org Name:	
Outstanding Perform Begin Date:	
Owner Type:	Local government
Pop Cat 11:	<=100
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	12
Submission Status Code:	Y
Submissionyearquarter:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin Date:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	
County Served:	Santa Fe
Source Water Protection Code:	N

Safe Drinking Water Information System (SDWIS)

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	ESE	0.42	2,213.23	7,132.42	SDWIS

PWS ID:	NM3591526
PWS Type Code:	TNCWS
PSW Type:	Transient non-community system
Primary Source Code:	GW
Primary Source:	Ground water
Pws Activity Code:	I
Activity:	Inactive
PWS Deactivation Dt:	03/01/1981

Wells and Additional Sources Detail Report

Phone No:	505-982-4484
Phone Ext No:	
Admin Name:	NAMBE HEADSTART
Alt Phone No:	
Email Addr:	
Fax No:	
Cds ID:	
Population Served Count:	60
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	03/12/1980
Gw or Sw:	Groundwater
Is Grant Eligible Ind:	No
Outstanding Performer:	
Is School or Daycare Ind:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Last Reported Date:	07/24/1995
Org Name:	
Outstanding Perform Begin Date:	
Owner Type:	
Pop Cat 11:	<=100
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Primacy Agency Code:	NM
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	1
Submission Yr Qtr:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	
County Served:	Santa Fe

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
227	WNW	0.76	3,995.97	7,002.29	SDWIS

Wells and Additional Sources Detail Report

PWS ID:	NM3580226
PWS Type Code:	TNCWS
PSW Type:	Transient non-community system
Primary Source Code:	GW
Primary Source:	Ground water
Pws Activity Code:	N
Activity:	Changed from public to non-public
PWS Deactivation Dt:	01/26/2006
Phone No:	505-988-9232
Phone Ext No:	
Admin Name:	
Alt Phone No:	
Email Addr:	
Fax No:	
Cds ID:	
Population Served Count:	0
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	05/18/1987
Gw or Sw:	Groundwater
Is Grant Eligible Ind:	No
Outstanding Performer:	
Is School or Daycare Ind:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Last Reported Date:	06/25/2025
Org Name:	
Outstanding Perform Begin Date:	
Owner Type:	Private
Pop Cat 11:	<=100
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Primacy Agency Code:	NM
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	1
Submission Yr Qtr:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin:	

Reduced Monitoring End Date:
Reduced Rtcr Monitoring:
Seasonal Startup System:
Source Protection Begin Date:
City Served:
County Served: Santa Fe

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
344	NW	0.96	5,077.40	6,996.13	SDWIS

PWS ID: NM3590826
PWS Type Code: NTNCWS
PSW Type: Non-Transient non-community system
Primary Source Code: GW
Primary Source: Ground water
Pws Activity Code: N
Activity: Changed from public to non-public
PWS Deactivation Dt: 02/09/2006
Phone No: 505-984-6543
Phone Ext No:
Admin Name:
Alt Phone No:
Email Addr:
Fax No:
Cds ID:
Population Served Count: 80
Epa Region Desc: Region 6
Epa Region: 06
First Reported Date: 03/12/1980
Gw or Sw: Groundwater
Is Grant Eligible Ind: No
Outstanding Performer:
Is School or Daycare Ind: No
Is Wholesaler Ind: No
Lt2 Schedule Cat:
Last Reported Date: 06/25/2025
Org Name:
Outstanding Perform Begin Date:
Owner Type: Local government
Pop Cat 11: <=100
Pop Cat 2: <10,000
Pop Cat 3: <=3300
Pop Cat 4: <10K
Pop Cat 5: <=500
Primacy Agency: New Mexico

Wells and Additional Sources Detail Report

Primacy Agency Code:	NM
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	12
Submission Yr Qtr:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	
County Served:	Santa Fe

USGS National Water Information System

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	SSW	0.03	172.20	7,079.77	FED USGS

Site No:	USGS-354053105552601
Site Type:	Well
Formation Type:	
Date Drilled:	
Well Depth:	
Well Depth Unit:	
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	17N.10E.30.121
Latitude:	35.68141990000000
Longitude:	-105.9244654000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
77	WNW	0.41	2,153.28	7,025.97	FED USGS

Site No:	USGS-354104105555010
Site Type:	Stream
Formation Type:	
Date Drilled:	
Well Depth:	
Well Depth Unit:	
Well Hole Depth:	
Well Hole Depth Unit:	

Wells and Additional Sources Detail Report

Reporting Agency: USGS New Mexico Water Science Center
Station Name: SANTA FE R AT DELGADO ST BRIDGE,SANTA FE NM
Latitude: 35.68447530000000
Longitude: -105.9311322000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
113	WNW	0.48	2,534.14	7,021.48	FED USGS

Site No: USGS-354104105555510
Site Type: Stream
Formation Type:
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: SANTA FE RIVER ABV CASTILLO ST AT SANTA FE, NM
Latitude: 35.68447530000000
Longitude: -105.9325211000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
141	WSW	0.56	2,932.88	7,053.57	FED USGS

Site No: USGS-354046105560001
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19770524
Well Depth: 243
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.25.21442
Latitude: 35.67947545000000
Longitude: -105.9339100000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
152	WNW	0.58	3,053.20	7,021.18	FED USGS

Site No: USGS-354103105560210
Site Type: Stream
Formation Type:
Date Drilled:
Well Depth:

Well Depth Unit:
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: SANTA FE RIVER BLW CASTILLO ST AT SANTA FE, NM
Latitude: 35.68419750000000
Longitude: -105.9344656000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
179	WSW	0.65	3,442.32	7,062.79	FED USGS

Site No: USGS-354039105560301
Site Type: Well
Formation Type:
Date Drilled: 19510401
Well Depth: 85.0
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.25.232
Latitude: 35.67753105000000
Longitude: -105.9347433000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
181	WNW	0.65	3,456.62	7,021.69	FED USGS

Site No: USGS-354113105560201
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19780124
Well Depth: 165
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.24.414
Latitude: 35.68697520000000
Longitude: -105.9344656000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
211	SW	0.73	3,841.02	7,126.77	FED USGS

Site No: USGS-354025105555501
Site Type: Well

Formation Type:
Date Drilled: 19510801
Well Depth: 255
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.25.421
Latitude: 35.67364229000000
Longitude: -105.9325210000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
213	SSE	0.74	3,933.03	7,285.04	FED USGS

Site No: USGS-354019105550701
Site Type: Well
Formation Type:
Date Drilled: 19310101
Well Depth: 238
Well Depth Unit: ft
Well Hole Depth: 238
Well Hole Depth Unit: ft
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.10E.30.413
Latitude: 35.67197577000000
Longitude: -105.9191875000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
292	WNW	0.88	4,633.56	6,987.92	FED USGS

Site No: USGS-354113105561801
Site Type: Well
Formation Type:
Date Drilled: 19250101
Well Depth: 255
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.24.324
Latitude: 35.68697520000000
Longitude: -105.9389101000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
334	WSW	0.95	5,012.53	7,060.96	FED USGS

Site No:	USGS-354032105562001
Site Type:	Well
Formation Type:	
Date Drilled:	
Well Depth:	50.0
Well Depth Unit:	ft
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	17N.09E.25.144
Latitude:	35.67558660000000
Longitude:	-105.9394656000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
336	W	0.95	5,020.23	7,000.25	FED USGS

Site No:	USGS-354052105562701
Site Type:	Well
Formation Type:	Tesuque Formation, Undifferentiated Unit
Date Drilled:	19761010
Well Depth:	300
Well Depth Unit:	ft
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	17N.09E.25.121
Latitude:	35.68114200000000
Longitude:	-105.9414102000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
337	W	0.95	5,034.03	6,991.45	FED USGS

Site No:	USGS-354100105562701
Site Type:	Well
Formation Type:	Tesuque Formation, Undifferentiated Unit
Date Drilled:	19250101
Well Depth:	180
Well Depth Unit:	ft
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	17N.09E.24.343
Latitude:	35.68336416000000
Longitude:	-105.9414102000000

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
338	WNW	0.96	5,048.18	6,981.04	FED USGS

Site No:	USGS-354106105562610
Site Type:	Stream
Formation Type:	
Date Drilled:	
Well Depth:	
Well Depth Unit:	
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	SANTA FE RIVER AT SANTA FE, NM
Latitude:	35.68503079000000
Longitude:	-105.9411324000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
353	NW	0.98	5,161.93	7,012.49	FED USGS

Site No:	USGS-354130105561210
Site Type:	Stream
Formation Type:	
Date Drilled:	
Well Depth:	
Well Depth Unit:	
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	ARROYO RANCHITO AT SANTA FE, NM
Latitude:	35.69169730000000
Longitude:	-105.9372435000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
354	WNW	0.98	5,151.28	6,977.49	FED USGS

Site No:	USGS-354107105562700
Site Type:	Stream
Formation Type:	
Date Drilled:	
Well Depth:	
Well Depth Unit:	
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	SANTA FE RIVER AT SANTA FE,NM

Wells and Additional Sources Detail Report

Latitude: 35.68530856000000
Longitude: -105.9414102000000

Point of Diversion Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
2	ESE	0.05	283.36	7,112.04	WATER WELLS

License Nb:	547	District Office S:	
POD No:	75949	Surv Map:	
POD Rec No:	170332	Other Loc:	5 Cerro Gordo Rd, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/16/2004, 12:00 AM	Restrict :	0.0
Finish Date:	02/16/2004, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	02/02/2004, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	80	UTM Zone:	13
Depth of Water:	21	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	100	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416457.0
Pcw Rcv Da:		Northing:	3949031.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/13/2019, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1737456.0
Static Lev:	0	Y:	1703545.0
Tract Nbr:		Point Y:	35.68163883
Map Nbr:		Point X:	-105.92323178
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
3	WNW	0.07	373.08	7,062.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34990	Surv Map:	
POD Rec No:	333772	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416241.0
Pcw Rcv Da:		Northing:	3949130.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/19/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596500.0
Static Lev:	0	Y:	1703800.0
Tract Nbr:		Point Y:	35.68251662
Map Nbr:		Point X:	-105.92562887

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	ESE	0.08	401.54	7,126.73	WATER WELLS

License Nb:	0	District Office S:	
POD No:	28711	Surv Map:	
POD Rec No:	272507	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416483.2
Pcw Rcv Da:		Northing:	3949005.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597300.0
Static Lev:	0	Y:	1703400.0
Tract Nbr:		Point Y:	35.68141026

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.92293962
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
5	SE	0.11	564.01	7,120.37	WATER WELLS

License Nb:	228	District Office S:	
POD No:	54428	Surv Map:	
POD Rec No:	19029	Other Loc:	2 Cerro Gordo Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3B SF
Start Date:	11/30/1991, 12:00 AM	Restrict :	0.0
Finish Date:	12/15/1991, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	12/26/1991, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	230	UTM Zone:	13
Depth of Water:	5	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	100	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416506.3
Pcw Rcv Da:		Northing:	3948956.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/03/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1737621.0
Static Lev:	0	Y:	1703302.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.68097047
Map Nbr:		Point X:	-105.92267929
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
6	W	0.12	625.03	7,067.55	WATER WELLS

License Nb:	214	District Office S:	
POD No:	22780	Surv Map:	
POD Rec No:	51451	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/02/1973, 12:00 AM	Restrict :	0.0
Finish Date:	03/03/1973, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	03/08/1973, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	135	UTM Zone:	13
Depth of Water:	43	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	18	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416148.8
Pcw Rcv Da:		Northing:	3949070.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/06/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596200.0

Wells and Additional Sources Detail Report

Static Lev:	0	Y:	1703600.0
Tract Nbr:		Point Y:	35.68196967
Map Nbr:		Point X:	-105.92664143
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
7	SSW	0.13	691.57	7,093.02	WATER WELLS

License Nb:	0	District Office S:	
POD No:	78478	Surv Map:	
POD Rec No:	180566	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	01/01/1700, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	20	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	1	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416298.4
Pcw Rcv Da:		Northing:	3948855.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/12/2002, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:		X:	596700.0
Static Lev:	0	Y:	1702900.0
Tract Nbr:		Point Y:	35.6800423
Map Nbr:		Point X:	-105.92496599
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	N	0.14	722.50	7,126.47	WATER WELLS

License Nb:	253	District Office S:	
POD No:	38853	Surv Map:	
POD Rec No:	26213	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/16/1983, 12:00 AM	Restrict :	0.0
Finish Date:	05/17/1983, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/26/1983, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	188	UTM Zone:	13
Depth of Water:	31	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	180	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416395.7
Pcw Rcv Da:		Northing:	3949311.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/09/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597000.0
Static Lev:	0	Y:	1704400.0
Tract Nbr:		Point Y:	35.68416061
Map Nbr:		Point X:	-105.92393827
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
9	NNW	0.14	752.40	7,102.22	WATER WELLS

License Nb:	253	District Office S:	
POD No:	33401	Surv Map:	
POD Rec No:	64511	Other Loc:	729 E. Palace Ave, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:	04/04/1980, 12:00 AM	Restrict :	0.0
Finish Date:	04/05/1980, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	04/09/1980, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	148	UTM Zone:	13
Depth of Water:	47	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416306.9
Pcw Rcv Da:		Northing:	3949310.1
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	04/27/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	La Reina Compound/Condos	Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416306.9
Static Lev:	0	Y:	3949310.1
Tract Nbr:		Point Y:	35.68414135
Map Nbr:		Point X:	-105.92491937
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055099134063ca0000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
10	SSE	0.15	803.61	7,092.25	WATER WELLS

License Nb:	0	District Office S:	
POD No:	39982	Surv Map:	
POD Rec No:	37398	Other Loc:	909 Canyon Road, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416469.0
Pcw Rcv Da:		Northing:	3948847.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/23/2022, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597260.0
Static Lev:	0	Y:	1702880.0
Tract Nbr:		Point Y:	35.67998194
Map Nbr:		Point X:	-105.92308009
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	909 Canyon Rd Santa Fe Nm		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
11	ESE	0.16	844.34	7,117.22	WATER WELLS

License Nb:	214	District Office S:	
POD No:	30918	Surv Map:	
POD Rec No:	7415	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	S-CLW	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/08/1979, 12:00 AM	Restrict :	0.0
Finish Date:	05/17/1979, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/22/1979, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	264	UTM Zone:	13
Depth of Water:	25	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-30918-X-2/	Easting:	416604.3
Pcw Rcv Da:		Northing:	3948943.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	11/19/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597700.0
Static Lev:	0	Y:	1703200.0
Tract Nbr:		Point Y:	35.68085706
Map Nbr:		Point X:	-105.92159503
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
12	S	0.18	930.18	7,104.54	WATER WELLS

License Nb:	0	District Office S:	
POD No:	36474	Surv Map:	
POD Rec No:	334346	Other Loc:	830 Canyon Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	L 9/10 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416395.6
Pcw Rcv Da:		Northing:	3948781.4
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	11/30/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1737265.0
Static Lev:	0	Y:	1702723.0
Tract Nbr:		Point Y:	35.67938252
Map Nbr:		Point X:	-105.92388428
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	SSW	0.17	921.08	7,098.27	WATER WELLS

License Nb:	790	District Office S:	
POD No:	34376	Surv Map:	
POD Rec No:	17079	Other Loc:	823 Acequia Madre
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	A SF
Start Date:	08/25/1980, 12:00 AM	Restrict :	0.0
Finish Date:	08/26/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	09/04/1980, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	65	UTM Zone:	13
Depth of Water:	21	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	1	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416228.0
Pcw Rcv Da:		Northing:	3948806.4

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/29/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736714.0
Static Lev:	0	Y:	1702798.0
Tract Nbr:		Point Y:	35.67959367
Map Nbr:		Point X:	-105.92573876
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
14	WNW	0.18	952.89	7,059.12	WATER WELLS

License Nb:	49	District Office S:	
POD No:	85765	Surv Map:	
POD Rec No:	212857	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/10/2005, 12:00 AM	Restrict :	0.0
Finish Date:	11/18/2005, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	11/28/2005, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	170	UTM Zone:	13
Depth of Water:	18	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	6.62	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416060.9

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3949157.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/29/2005, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595908.0
Static Lev:	0	Y:	1703881.0
Tract Nbr:	B1A	Point Y:	35.68274471
Map Nbr:		Point X:	-105.92762175
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	S	0.19	983.67	7,107.56	WATER WELLS

License Nb:	0	District Office S:	
POD No:	27033	Surv Map:	
POD Rec No:	35434	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	100	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	416388.7
Pcw Rcv Da:		Northing:	3948762.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/21/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597000.0
Static Lev:	0	Y:	1702600.0
Tract Nbr:		Point Y:	35.67921515
Map Nbr:		Point X:	-105.9239586
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Santa Fe Usgs 7.5 Min Quad "Santa Fe"		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	WNW	0.19	1,009.52	7,046.40	WATER WELLS

License Nb:	622	District Office S:	
POD No:	22780	Surv Map:	
POD Rec No:	48250	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/03/1978, 12:00 AM	Restrict :	0.0
Finish Date:	07/05/1978, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/26/1978, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	140	UTM Zone:	13
Depth of Water:	15	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :	RG-22780-X/	Easting:	416090.2
Pcw Rcv Da:		Northing:	3949254.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/06/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596000.0
Static Lev:	0	Y:	1704200.0
Tract Nbr:		Point Y:	35.68361988
Map Nbr:		Point X:	-105.92730809
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
17	NE	0.19	1,009.33	7,138.29	WATER WELLS

License Nb:	1382	District Office S:	
POD No:	81438	Surv Map:	
POD Rec No:	196983	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N
Log File D:	09/05/2013, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	102	UTM Zone:	13
Depth of Water:	18	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	6.26	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416561.1
Pcw Rcv Da:		Northing:	3949338.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/03/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1737785.0
Static Lev:	0	Y:	1704557.0
Tract Nbr:		Point Y:	35.68441623
Map Nbr:		Point X:	-105.92211337
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
18	WSW	0.21	1,122.89	7,079.75	WATER WELLS

License Nb:	214	District Office S:	
POD No:	28576	Surv Map:	
POD Rec No:	3555	Other Loc:	634 Canyon Road, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	20 8 SF
Start Date:	05/08/1977, 12:00 AM	Restrict :	0.0
Finish Date:	05/13/1977, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	05/24/1977, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	265	UTM Zone:	13
Depth of Water:	40	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416025.6
Pcw Rcv Da:		Northing:	3948937.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/05/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416025.6
Static Lev:	0	Y:	3948937.2
Tract Nbr:		Point Y:	35.68075565
Map Nbr:		Point X:	-105.92798881
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098040483000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
19	SSW	0.21	1,134.76	7,103.08	WATER WELLS

License Nb:	815	District Office S:	
POD No:	53086	Surv Map:	
POD Rec No:	66847	Other Loc:	827 Camino Del Poniente
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TC SF
Start Date:	11/12/1990, 12:00 AM	Restrict :	0.0
Finish Date:	11/19/1990, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	11/28/1990, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	280	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	

Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416198.9
Pcw Rcv Da:		Northing:	3948747.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/19/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736621.0
Static Lev:	0	Y:	1702602.0
Tract Nbr:		Point Y:	35.6790557
Map Nbr:		Point X:	-105.92605411
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
20	SW	0.22	1,149.55	7,090.06	WATER WELLS

License Nb:	0	District Office S:	
POD No:	39401	Surv Map:	
POD Rec No:	20448	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416084.8
Pcw Rcv Da:		Northing:	3948827.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/16/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596000.0
Static Lev:	0	Y:	1702800.0
Tract Nbr:		Point Y:	35.67977352
Map Nbr:		Point X:	-105.92732326
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
21	NW	0.23	1,196.72	7,073.05	WATER WELLS

License Nb:	228	District Office S:	
POD No:	44144	Surv Map:	
POD Rec No:	51673	Other Loc:	639 E Palace Ave
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1A SF
Start Date:	07/18/1985, 12:00 AM	Restrict :	0.0
Finish Date:	07/19/1985, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	08/16/1985, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	160	UTM Zone:	13
Depth of Water:	30	UTM Accura:	10

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416134.3
Pcw Rcv Da:		Northing:	3949375.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/02/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736383.0
Static Lev:	0	Y:	1704661.0
Tract Nbr:		Point Y:	35.68471538
Map Nbr:		Point X:	-105.92683342
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
22	WNW	0.22	1,187.23	7,054.01	WATER WELLS

License Nb:	0	District Office S:	
POD No:	59924	Surv Map:	
POD Rec No:	67859	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415998.0
Pcw Rcv Da:		Northing:	3949194.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/10/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595700.0
Static Lev:	0	Y:	1704000.0
Tract Nbr:		Point Y:	35.68307382
Map Nbr:		Point X:	-105.92832066
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
23	N	0.23	1,210.07	7,161.74	WATER WELLS

License Nb:	0	District Office S:	
POD No:	36973	Surv Map:	
POD Rec No:	23131	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN

Wells and Additional Sources Detail Report

Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416346.4
Pcw Rcv Da:		Northing:	3949459.5
Sched Date:		Latitude Degree:	0
Use of Wel:	COM, IRR	Latitude Minute:	0
Sys Date:	05/10/1991, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596832.0
Static Lev:	0	Y:	1704884.0
Tract Nbr:		Point Y:	35.68549158
Map Nbr:		Point X:	-105.92449844
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	ESE	0.23	1,206.50	7,103.42	WATER WELLS

License Nb:	0	District Office S:	
POD No:	71243	Surv Map:	
POD Rec No:	147388	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416694.9
Pcw Rcv Da:		Northing:	3948880.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/20/1999, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598000.0
Static Lev:	0	Y:	1703000.0
Tract Nbr:		Point Y:	35.68030487
Map Nbr:		Point X:	-105.92058751
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
25	S	0.23	1,217.73	7,113.58	WATER WELLS

License Nb:	214	District Office S:	
POD No:	16898	Surv Map:	
POD Rec No:	50259	Other Loc:	Address: 425 Camino Manzano
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/11/1969, 12:00 AM	Restrict :	0.0
Finish Date:	09/01/1969, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	02/06/1970, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	281	UTM Zone:	13
Depth of Water:	32	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416291.0
Pcw Rcv Da:		Northing:	3948693.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/24/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6785767
Map Nbr:		Point X:	-105.92503085
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
26	WNW	0.24	1,266.13	7,045.34	WATER WELLS

License Nb:	0	District Office S:	
POD No:	36840	Surv Map:	
POD Rec No:	3523	Other Loc:	564 East Alameda, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415998.8
Pcw Rcv Da:		Northing:	3949255.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/15/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595700.0
Static Lev:	0	Y:	1704200.0
Tract Nbr:		Point Y:	35.68362292
Map Nbr:		Point X:	-105.92831818
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
27	SSE	0.26	1,350.25	7,123.76	WATER WELLS

License Nb:	214	District Office S:	
POD No:	28813	Surv Map:	
POD Rec No:	6181	Other Loc:	976 Acequia Madre, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7 10 SF
Start Date:	06/06/1977, 12:00 AM	Restrict :	0.0
Finish Date:	06/10/1977, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	06/22/1977, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	139	UTM Zone:	13
Depth of Water:	40	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416561.9
Pcw Rcv Da:		Northing:	3948706.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416561.9
Static Lev:	0	Y:	3948706.1
Tract Nbr:		Point Y:	35.67871776
Map Nbr:		Point X:	-105.92203896
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:	Parcel Number 1055098220415000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
28	WSW	0.25	1,336.01	7,083.40	WATER WELLS

License Nb:	228	District Office S:	
POD No:	32879	Surv Map:	
POD Rec No:	11264	Other Loc:	739 Acequia Madre, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/09/1980, 12:00 AM	Restrict :	0.0
Finish Date:	07/14/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	07/22/1980, 12:00 AM	Range:	10E

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	60	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415988.1
Pcw Rcv Da:		Northing:	3948868.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/24/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415988.1
Static Lev:	0	Y:	3948868.0
Tract Nbr:		Point Y:	35.6801286
Map Nbr:		Point X:	-105.92839595
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098031453000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
29	WNW	0.25	1,335.11	7,056.66	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34872	Surv Map:	
POD Rec No:	47351	Other Loc:	130 Camino Escondido
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	22 SF
Start Date:		Restrict :	0.0
Finish Date:	08/01/1951, 12:00 AM	Section:	19
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	107	UTM Zone:	13
Depth of Water:	85	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	26	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415945.6
Pcw Rcv Da:		Northing:	3949176.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/27/2024, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735772.0
Static Lev:	0	Y:	1703999.0
Tract Nbr:		Point Y:	35.68290167
Map Nbr:		Point X:	-105.92889773
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
30	W	0.25	1,341.86	7,061.12	WATER WELLS

License Nb:	0	District Office S:	
POD No:	81923	Surv Map:	
POD Rec No:	199068	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	01/01/1957, 12:00 AM	Section:	25

Wells and Additional Sources Detail Report

Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	EA
Depth of Well:	50	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415937.4
Pcw Rcv Da:		Northing:	3949147.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/04/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595503.0
Static Lev:	0	Y:	1703842.0
Tract Nbr:		Point Y:	35.68264133
Map Nbr:		Point X:	-105.92898533
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
31	ESE	0.26	1,363.77	7,142.74	WATER WELLS

License Nb:	1173	District Office S:	
POD No:	13375	Surv Map:	
POD Rec No:	241265	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/18/1990, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	11/01/1990, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	11/20/1990, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	155	UTM Zone:	13
Depth of Water:	24	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	100	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416790.0
Pcw Rcv Da:		Northing:	3948986.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	08/04/2015, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68126041
Map Nbr:		Point X:	-105.91954757
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
31	ESE	0.26	1,363.77	7,142.74	WATER WELLS

License Nb:	253	District Office S:	
POD No:	13375	Surv Map:	
POD Rec No:	13479	Other Loc:	100 Ft North Of Santa Fe River
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:	12/01/1965, 12:00 AM	Restrict :	0.0
Finish Date:	12/03/1965, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	11/30/1966, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	22	UTM Zone:	13
Depth of Water:	4	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416790.0
Pcw Rcv Da:		Northing:	3948986.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	10/05/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68126041
Map Nbr:		Point X:	-105.91954757
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
32	SE	0.27	1,432.16	7,122.60	WATER WELLS

License Nb:	606	District Office S:	
POD No:	29259	Surv Map:	
POD Rec No:	58289	Other Loc:	1015 Canyon Road, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	8 8 SF
Start Date:	08/01/1977, 12:00 AM	Restrict :	0.0
Finish Date:	08/31/1977, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	09/07/1977, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	103	UTM Zone:	13
Depth of Water:	81	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416700.7
Pcw Rcv Da:		Northing:	3948777.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/10/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416700.7
Static Lev:	0	Y:	3948777.1
Tract Nbr:		Point Y:	35.67936958
Map Nbr:		Point X:	-105.92051267
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:	Parcel Number 1055098268432000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
33	WSW	0.27	1,420.31	7,082.06	WATER WELLS

License Nb:	214	District Office S:	
POD No:	28797	Surv Map:	
POD Rec No:	39279	Other Loc:	751 Acequia Madre, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/05/1977, 12:00 AM	Restrict :	0.0
Finish Date:	08/09/1977, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/12/1977, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	252	UTM Zone:	13
Depth of Water:	30	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415963.3
Pcw Rcv Da:		Northing:	3948859.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/02/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595600.0
Static Lev:	0	Y:	1702900.0
Tract Nbr:		Point Y:	35.68005256
Map Nbr:		Point X:	-105.92866912
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	E	0.27	1,444.61	7,150.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	36922	Surv Map:	
POD Rec No:	47085	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416818.4
Pcw Rcv Da:		Northing:	3949001.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/10/1991, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598400.0
Static Lev:	0	Y:	1703400.0
Tract Nbr:		Point Y:	35.68140074
Map Nbr:		Point X:	-105.91923534
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
35	SSE	0.29	1,546.77	7,134.00	WATER WELLS

License Nb:	214	District Office S:	
POD No:	28798	Surv Map:	
POD Rec No:	38433	Other Loc:	934 Acequia Madre
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/06/1977, 12:00 AM	Restrict :	0.0
Finish Date:	06/08/1977, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	06/17/1977, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	115	UTM Zone:	13
Depth of Water:	29	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	150	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416529.2
Pcw Rcv Da:		Northing:	3948625.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1737710.0
Static Lev:	0	Y:	1702218.0
Tract Nbr:		Point Y:	35.67799106
Map Nbr:		Point X:	-105.92239194
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
36	NW	0.29	1,539.03	7,052.61	WATER WELLS

License Nb:	0	District Office S:	
POD No:	38634	Surv Map:	
POD Rec No:	61605	Other Loc:	1317 Cerro Gordo, Santa Fe
POD Basin:	RG	Zone :	

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415997.0
Pcw Rcv Da:		Northing:	3949395.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/31/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68488039
Map Nbr:		Point X:	-105.92835264
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
37	NW	0.30	1,566.59	7,061.31	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35576	Surv Map:	
POD Rec No:	34043	Other Loc:	607 E Palace Ave

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 6 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416023.5
Pcw Rcv Da:		Northing:	3949432.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/04/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736017.0
Static Lev:	0	Y:	1704843.0
Tract Nbr:		Point Y:	35.68521801
Map Nbr:		Point X:	-105.9280637
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
38	S	0.30	1,561.09	7,127.01	WATER WELLS

License Nb:	214	District Office S:	
POD No:	29317	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	2148	Other Loc:	439 Camino Del Monte Sol, Sf
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/13/1978, 12:00 AM	Restrict :	0.0
Finish Date:	02/17/1978, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	02/23/1978, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	211	UTM Zone:	13
Depth of Water:	150	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416289.6
Pcw Rcv Da:		Northing:	3948588.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/11/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416289.6
Static Lev:	0	Y:	3948588.5
Tract Nbr:		Point Y:	35.67763448
Map Nbr:		Point X:	-105.92503545
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098128366000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
39	W	0.30	1,559.58	7,069.47	WATER WELLS

License Nb:	622	District Office S:	

Wells and Additional Sources Detail Report

POD No:	29177	Surv Map:	
POD Rec No:	49698	Other Loc:	544 Canyon Road, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/30/1978, 12:00 AM	Restrict :	0.0
Finish Date:	07/31/1978, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	08/01/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	320	UTM Zone:	13
Depth of Water:	41	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415873.4
Pcw Rcv Da:		Northing:	3948982.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/14/2011, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595300.0
Static Lev:	0	Y:	1703300.0
Tract Nbr:		Point Y:	35.68115377
Map Nbr:		Point X:	-105.92967533
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
40	NW	0.30	1,604.45	7,068.92	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	214	District Office S:	
POD No:	29008	Surv Map:	
POD Rec No:	54526	Other Loc:	607 E Palace Ave, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 6 SF
Start Date:	02/18/1981, 12:00 AM	Restrict :	0.0
Finish Date:	02/20/1981, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	03/13/1981, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	131	UTM Zone:	13
Depth of Water:	30	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416029.6
Pcw Rcv Da:		Northing:	3949452.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/07/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416029.6
Static Lev:	0	Y:	3949452.5
Tract Nbr:		Point Y:	35.68540154
Map Nbr:		Point X:	-105.92799841
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055099038105000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
41	W	0.30	1,579.96	7,066.74	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	214	District Office S:	
POD No:	29622	Surv Map:	
POD Rec No:	40696	Other Loc:	544 Canyon Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TC1 SF
Start Date:	01/30/1978, 12:00 AM	Restrict :	0.0
Finish Date:	02/06/1978, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	02/10/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	417	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	37	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415861.3
Pcw Rcv Da:		Northing:	3949015.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/17/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735502.0
Static Lev:	0	Y:	1703467.0
Tract Nbr:		Point Y:	35.68144303
Map Nbr:		Point X:	-105.92981239
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
42	WNW	0.31	1,626.73	7,041.45	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	74753	Surv Map:	
POD Rec No:	161433	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415908.1
Pcw Rcv Da:		Northing:	3949317.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/06/2000, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595400.0
Static Lev:	0	Y:	1704400.0
Tract Nbr:		Point Y:	35.68417503
Map Nbr:		Point X:	-105.92932691
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

43	ESE	0.31	1,631.23	7,121.49	WATER WELLS

License Nb:	253	District Office S:	
POD No:	28871	Surv Map:	USGS 7.5'QUAD SANTA FE
POD Rec No:	12420	Other Loc:	1117 E. Alameda, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/22/1977, 12:00 AM	Restrict :	0.0
Finish Date:	07/25/1977, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	07/29/1977, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	85	UTM Zone:	13
Depth of Water:	12	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416863.3
Pcw Rcv Da:		Northing:	3948945.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416863.3
Static Lev:	0	Y:	3948945.7
Tract Nbr:		Point Y:	35.68090327
Map Nbr:		Point X:	-105.91873346
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098327485000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

44	SW	0.31	1,642.86	7,090.96	WATER WELLS

License Nb:	228	District Office S:	
POD No:	44736	Surv Map:	
POD Rec No:	21582	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/17/1986, 12:00 AM	Restrict :	0.0
Finish Date:	01/17/1986, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	02/04/1986, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	240	UTM Zone:	13
Depth of Water:	160	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415991.8
Pcw Rcv Da:		Northing:	3948707.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595700.0
Static Lev:	0	Y:	1702400.0
Tract Nbr:		Point Y:	35.67867746
Map Nbr:		Point X:	-105.92833825
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
45	W	0.31	1,644.83	7,059.03	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94235	Surv Map:	
POD Rec No:	287608	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EG
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415841.0
Pcw Rcv Da:		Northing:	3949127.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/13/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1735430.7
Static Lev:	0	Y:	1703833.9
Tract Nbr:		Point Y:	35.682451
Map Nbr:		Point X:	-105.93004842
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	W	0.31	1,649.57	7,063.22	WATER WELLS

License Nb:	253	District Office S:	
POD No:	35549	Surv Map:	
POD Rec No:	11080	Other Loc:	540 Canyon Road, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/17/1981, 12:00 AM	Restrict :	0.0
Finish Date:	03/19/1981, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	03/25/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	160	UTM Zone:	13
Depth of Water:	34	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415836.6
Pcw Rcv Da:		Northing:	3949067.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/03/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415836.6
Static Lev:	0	Y:	3949067.2
Tract Nbr:		Point Y:	35.68191151
Map Nbr:		Point X:	-105.93009078
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		

Wells and Additional Sources Detail Report

Legal: Parcel Number 1054098504516000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
47	S	0.32	1,675.67	7,134.91	WATER WELLS

License Nb:	122	District Office S:	
POD No:	63354	Surv Map:	
POD Rec No:	334055	Other Loc:	503 Camino Del Monte Sol
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416355.5
Pcw Rcv Da:		Northing:	3948550.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/03/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596900.0
Static Lev:	0	Y:	1701900.0
Tract Nbr:		Point Y:	35.67729299
Map Nbr:		Point X:	-105.9243033
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
48	SSW	0.31	1,661.48	7,119.43	WATER WELLS

License Nb:	228	District Office S:	
POD No:	36889	Surv Map:	
POD Rec No:	28211	Other Loc:	831 El Caminito, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/16/1982, 12:00 AM	Restrict :	0.0
Finish Date:	01/18/1982, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	01/22/1982, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	220	UTM Zone:	13
Depth of Water:	40	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416153.0
Pcw Rcv Da:		Northing:	3948592.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/16/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416153.0
Static Lev:	0	Y:	3948592.6
Tract Nbr:		Point Y:	35.67765984
Map Nbr:		Point X:	-105.92654518
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal: Parcel Number 1055098089368000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
49	WNW	0.32	1,667.69	7,045.76	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91291	Surv Map:	
POD Rec No:	244529	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415869.3
Pcw Rcv Da:		Northing:	3949267.7
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	08/06/2009, 12:00 AM	Latitude Second:	1.4
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	55
Ditch Name:		Longitude Second:	47.1
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68372186
Map Nbr:		Point X:	-105.92975043
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
50	NW	0.32	1,699.88	7,069.83	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35901	Surv Map:	
POD Rec No:	26436	Other Loc:	535 E Palace Ave
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TC SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416004.2
Pcw Rcv Da:		Northing:	3949469.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/15/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735952.0
Static Lev:	0	Y:	1704963.0
Tract Nbr:		Point Y:	35.68554813
Map Nbr:		Point X:	-105.92828081

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
51	E	0.33	1,728.86	7,196.29	WATER WELLS

License Nb:	122	District Office S:	
POD No:	32089	Surv Map:	
POD Rec No:	325503	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	76	UTM Zone:	13
Depth of Water:	65	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	6	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416911.0
Pcw Rcv Da:		Northing:	3949091.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/04/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598700.0
Static Lev:	0	Y:	1703700.0
Tract Nbr:		Point Y:	35.68222172

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.91822146
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
52	WNW	0.33	1,748.85	7,047.61	WATER WELLS

License Nb:	0	District Office S:	
POD No:	83535	Surv Map:	
POD Rec No:	205389	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415833.1
Pcw Rcv Da:		Northing:	3949240.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/12/2025, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595157.0
Static Lev:	0	Y:	1704143.0

Wells and Additional Sources Detail Report

Tract Nbr:	C	Point Y:	35.68347085
Map Nbr:		Point X:	-105.93014756
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
53	NW	0.34	1,794.45	7,064.66	WATER WELLS

License Nb:	1310	District Office S:	
POD No:	71015	Surv Map:	
POD Rec No:	146760	Other Loc:	531 E Palace Ave
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA SF
Start Date:	08/15/1999, 12:00 AM	Restrict :	0.0
Finish Date:	08/19/1999, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	08/16/2000, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415965.9
Pcw Rcv Da:		Northing:	3949474.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/29/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415965.9

Wells and Additional Sources Detail Report

Static Lev:	0	Y:	3949474.0
Tract Nbr:		Point Y:	35.68558994
Map Nbr:		Point X:	-105.92870456
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number: 1055099024127000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
54	ESE	0.34	1,775.99	7,121.61	WATER WELLS

License Nb:	0	District Office S:	
POD No:	17579	Surv Map:	
POD Rec No:	9958	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416891.0
Pcw Rcv Da:		Northing:	3948887.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/18/2008, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68037641
Map Nbr:		Point X:	-105.91842132
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
55	SSE	0.35	1,859.42	7,146.93	WATER WELLS

License Nb:	622	District Office S:	
POD No:	71032	Surv Map:	
POD Rec No:	146889	Other Loc:	111 Victoria St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	29 10 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416682.2
Pcw Rcv Da:		Northing:	3948595.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/06/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416682.2
Static Lev:	0	Y:	3948595.5
Tract Nbr:		Point Y:	35.67773084
Map Nbr:		Point X:	-105.92069828
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:	Parcel Number: 1055098258377000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
56	SW	0.35	1,834.12	7,093.52	WATER WELLS

License Nb:	228	District Office S:	
POD No:	35391	Surv Map:	
POD Rec No:	22644	Other Loc:	459 Camino Manzano
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	Y SF
Start Date:	12/06/1980, 12:00 AM	Restrict :	0.0
Finish Date:	12/09/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	01/29/1981, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	80	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415960.9
Pcw Rcv Da:		Northing:	3948655.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/19/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735844.0
Static Lev:	0	Y:	1702292.0
Tract Nbr:		Point Y:	35.67821145
Map Nbr:		Point X:	-105.9286743
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
57	S	0.36	1,905.43	7,143.07	WATER WELLS

License Nb:	228	District Office S:	
POD No:	36880	Surv Map:	
POD Rec No:	60337	Other Loc:	587 Camino Del Monte Sol, Sf
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/14/1982, 12:00 AM	Restrict :	0.0
Finish Date:	08/15/1982, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	11/15/1982, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	175	UTM Zone:	13
Depth of Water:	90	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-36880-/	Easting:	416382.5
Pcw Rcv Da:		Northing:	3948480.1
Sched Date:		Latitude Degree:	0
Use of Wel:	1HH DOM	Latitude Minute:	0
Sys Date:	11/16/2021, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416382.5
Static Lev:	0	Y:	3948480.1
Tract Nbr:		Point Y:	35.67666511
Map Nbr:		Point X:	-105.92399771
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:	Parcel Number 1055098166315000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
58	SSE	0.37	1,929.68	7,154.98	WATER WELLS

License Nb:	214	District Office S:	
POD No:	09839	Surv Map:	
POD Rec No:	40319	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/24/1963, 12:00 AM	Restrict :	0.0
Finish Date:	10/07/1963, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	12/13/1963, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	255	UTM Zone:	13
Depth of Water:	37	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416485.0
Pcw Rcv Da:		Northing:	3948488.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	12/14/2005, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67674502
Map Nbr:		Point X:	-105.92286601
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
59	ESE	0.37	1,943.84	7,120.51	WATER WELLS

License Nb:	227	District Office S:	
POD No:	66701	Surv Map:	
POD Rec No:	42901	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA C SF
Start Date:	04/12/1998, 12:00 AM	Restrict :	0.0
Finish Date:	04/14/1998, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/15/1998, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	100	UTM Zone:	13
Depth of Water:	18	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	5	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416930.0
Pcw Rcv Da:		Northing:	3948845.6
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	05/19/2015, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1739016.0
Static Lev:	0	Y:	1702956.0
Tract Nbr:	C	Point Y:	35.68000647
Map Nbr:		Point X:	-105.91798612
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
60	ESE	0.38	1,988.83	7,120.47	WATER WELLS

License Nb:	0	District Office S:	
POD No:	74962	Surv Map:	
POD Rec No:	162543	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416953.9
Pcw Rcv Da:		Northing:	3948871.5

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/13/2000, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598850.0
Static Lev:	0	Y:	1702980.0
Tract Nbr:		Point Y:	35.68024198
Map Nbr:		Point X:	-105.91772471
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
61	SW	0.38	1,991.67	7,099.62	WATER WELLS

License Nb:	228	District Office S:	
POD No:	40770	Surv Map:	
POD Rec No:	58127	Other Loc:	465 Camino Manzano
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	14 3 T2 SF
Start Date:	06/12/1984, 12:00 AM	Restrict :	0.0
Finish Date:	06/15/1984, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	10/11/1984, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	75	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415956.5

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3948595.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/17/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735832.0
Static Lev:	0	Y:	1702096.0
Tract Nbr:		Point Y:	35.67767286
Map Nbr:		Point X:	-105.92871668
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
62	WSW	0.38	1,992.10	7,064.11	WATER WELLS

License Nb:	214	District Office S:	
POD No:	31840	Surv Map:	
POD Rec No:	21922	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/01/1979, 12:00 AM	Restrict :	0.0
Finish Date:	02/07/1979, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	02/13/1979, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	387	UTM Zone:	13
Depth of Water:	387	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	415750.7
Pcw Rcv Da:		Northing:	3948923.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/28/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594900.0
Static Lev:	0	Y:	1703100.0
Tract Nbr:		Point Y:	35.68060779
Map Nbr:		Point X:	-105.93102489
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
63	SW	0.38	2,004.37	7,094.49	WATER WELLS

License Nb:	228	District Office S:	
POD No:	35396	Surv Map:	
POD Rec No:	44008	Other Loc:	463 Camino Manzano
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	13 3 SF
Start Date:	12/09/1980, 12:00 AM	Restrict :	0.0
Finish Date:	12/11/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	01/29/1981, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	80	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415923.0
Pcw Rcv Da:		Northing:	3948620.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735721.0
Static Lev:	0	Y:	1702176.0
Tract Nbr:		Point Y:	35.67789358
Map Nbr:		Point X:	-105.92908942
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
64	SSW	0.39	2,048.40	7,144.62	WATER WELLS

License Nb:	228	District Office S:	
POD No:	19533	Surv Map:	
POD Rec No:	45725	Other Loc:	520 Camino Del Monte Sol
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1
Start Date:	03/29/1972, 12:00 AM	Restrict :	0.0
Finish Date:	05/06/1972, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	05/15/1972, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	265	UTM Zone:	13
Depth of Water:	100	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	5.0	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	416204.3
Pcw Rcv Da:		Northing:	3948452.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/13/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736651.0
Static Lev:	0	Y:	1701637.0
Tract Nbr:		Point Y:	35.67640477
Map Nbr:		Point X:	-105.92596381
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	516-520 Camino Del Monte Sol		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
65	ENE	0.39	2,039.85	7,203.29	WATER WELLS

License Nb:	0	District Office S:	
POD No:	66975	Surv Map:	
POD Rec No:	67600	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416974.2
Pcw Rcv Da:		Northing:	3949273.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/09/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598900.0
Static Lev:	0	Y:	1704300.0
Tract Nbr:		Point Y:	35.68386872
Map Nbr:		Point X:	-105.91754191
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Salvador Gonzales/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
66	WSW	0.39	2,042.24	7,071.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	65241	Surv Map:	
POD Rec No:	18737	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415779.7
Pcw Rcv Da:		Northing:	3948801.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/05/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595000.0
Static Lev:	0	Y:	1702700.0
Tract Nbr:		Point Y:	35.6795086
Map Nbr:		Point X:	-105.93069166
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
67	S	0.39	2,059.17	7,151.88	WATER WELLS

License Nb:	0	District Office S:	
POD No:	76563	Surv Map:	
POD Rec No:	173238	Other Loc:	535 Camino Del Monte Sol
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T1B SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416313.5
Pcw Rcv Da:		Northing:	3948433.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/27/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Land Of William/Linda Herrmann	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416313.5
Static Lev:	0	Y:	3948433.5
Tract Nbr:		Point Y:	35.67623915
Map Nbr:		Point X:	-105.92475525
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number: 1055098145279000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	NW	0.39	2,080.48	7,077.35	WATER WELLS

License Nb:	622	District Office S:	
POD No:	73263	Surv Map:	
POD Rec No:	154803	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10

Wells and Additional Sources Detail Report

Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415972.6
Pcw Rcv Da:		Northing:	3949591.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/14/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595600.0
Static Lev:	0	Y:	1705300.0
Tract Nbr:		Point Y:	35.68664619
Map Nbr:		Point X:	-105.92864276
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
69	SSW	0.39	2,060.85	7,119.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	71391	Surv Map:	
POD Rec No:	147896	Other Loc:	W/In City Limits Of Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416019.9
Pcw Rcv Da:		Northing:	3948523.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/21/2001, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595800.0
Static Lev:	0	Y:	1701800.0
Tract Nbr:		Point Y:	35.67702826
Map Nbr:		Point X:	-105.92800864
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
70	SE	0.40	2,101.92	7,175.38	WATER WELLS

License Nb:	0	District Office S:	
POD No:	65773	Surv Map:	
POD Rec No:	6748	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA

Wells and Additional Sources Detail Report

Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416782.5
Pcw Rcv Da:		Northing:	3948575.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/04/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598300.0
Static Lev:	0	Y:	1702000.0
Tract Nbr:		Point Y:	35.6775554
Map Nbr:		Point X:	-105.91958793
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	NW	0.40	2,111.80	7,052.69	WATER WELLS

License Nb:	0	District Office S:	
POD No:	32365	Surv Map:	
POD Rec No:	59116	Other Loc:	511 E Palace Ave
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 47 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	24
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415852.7
Pcw Rcv Da:		Northing:	3949494.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/14/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	King Map	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735454.0
Static Lev:	0	Y:	1705041.0
Tract Nbr:		Point Y:	35.6857669
Map Nbr:		Point X:	-105.92995761
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
72	NNW	0.41	2,155.84	7,102.51	WATER WELLS

License Nb:	49	District Office S:	
POD No:	56309	Surv Map:	
POD Rec No:	8592	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/14/1993, 12:00 AM	Restrict :	0.0
Finish Date:	02/04/1993, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	06/17/1993, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	300	UTM Zone:	13
Depth of Water:	240	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416156.9
Pcw Rcv Da:		Northing:	3949710.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/14/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596200.0
Static Lev:	0	Y:	1705700.0
Tract Nbr:		Point Y:	35.68773921
Map Nbr:		Point X:	-105.92661863
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
72	NNW	0.41	2,155.84	7,102.51	WATER WELLS

License Nb:	49	District Office S:	
POD No:	56310	Surv Map:	
POD Rec No:	26510	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	12/05/1992, 12:00 AM	Restrict :	0.0
Finish Date:	01/10/1993, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	01/27/1993, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	470	UTM Zone:	13
Depth of Water:	140	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416156.9
Pcw Rcv Da:		Northing:	3949710.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/19/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596200.0
Static Lev:	0	Y:	1705700.0
Tract Nbr:		Point Y:	35.68773921
Map Nbr:		Point X:	-105.92661863
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
72	NNW	0.41	2,155.84	7,102.51	WATER WELLS

License Nb:	49	District Office S:	
POD No:	69928	Surv Map:	
POD Rec No:	143661	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/14/1993, 12:00 AM	Restrict :	3.0
Finish Date:	01/14/1993, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	06/17/1993, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	240	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416156.9
Pcw Rcv Da:		Northing:	3949710.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/27/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596200.0
Static Lev:	0	Y:	1705700.0
Tract Nbr:		Point Y:	35.68773921
Map Nbr:		Point X:	-105.92661863
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
73	S	0.41	2,151.83	7,158.96	WATER WELLS

License Nb:	214	District Office S:	
POD No:	31512	Surv Map:	
POD Rec No:	25205	Other Loc:	535 Camino Del Monte Sol
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T2 SF
Start Date:	05/30/1979, 12:00 AM	Restrict :	0.0
Finish Date:	06/05/1979, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	06/06/1979, 12:00 AM	Range:	10E

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	285	UTM Zone:	13
Depth of Water:	240	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	18	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416345.7
Pcw Rcv Da:		Northing:	3948404.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/27/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416345.7
Static Lev:	0	Y:	3948404.7
Tract Nbr:		Point Y:	35.67598224
Map Nbr:		Point X:	-105.92439648
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number: 1055098147297000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
74	SW	0.40	2,136.83	7,101.68	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34900	Surv Map:	NA
POD Rec No:	16933	Other Loc:	Na
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	

Wells and Additional Sources Detail Report

Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-34900-/	Easting:	415898.8
Pcw Rcv Da:		Northing:	3948586.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/08/2017, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1735643.0
Static Lev:	0	Y:	1702064.0
Tract Nbr:	NA	Point Y:	35.6775868
Map Nbr:	NA	Point X:	-105.92935328
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
75	E	0.41	2,141.89	7,142.35	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34548	Surv Map:	
POD Rec No:	12381	Other Loc:	1176 Cerro Gordo Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	16 12 TA SF
Start Date:		Restrict :	0.0
Finish Date:	12/31/1925, 12:00 AM	Section:	19

Wells and Additional Sources Detail Report

Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	26	UTM Zone:	13
Depth of Water:	12	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	14	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417036.2
Pcw Rcv Da:		Northing:	3949048.1
Sched Date:		Latitude Degree:	0
Use of Wel:	IRR	Latitude Minute:	0
Sys Date:	10/05/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1739356.0
Static Lev:	0	Y:	1703625.0
Tract Nbr:		Point Y:	35.681841
Map Nbr:		Point X:	-105.91683355
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
76	E	0.41	2,144.65	7,161.90	WATER WELLS

License Nb:	228	District Office S:	
POD No:	35503	Surv Map:	
POD Rec No:	36099	Other Loc:	101 Rim Rd, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	107* 1 SF
Start Date:	01/29/1981, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	02/02/1981, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	02/18/1981, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	160	UTM Zone:	13
Depth of Water:	60	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417037.0
Pcw Rcv Da:		Northing:	3949112.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1739356.0
Static Lev:	0	Y:	1703835.0
Tract Nbr:		Point Y:	35.68241805
Map Nbr:		Point X:	-105.91683131
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098368521000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
78	ENE	0.41	2,151.97	7,206.94	WATER WELLS

License Nb:	1173	District Office S:	
POD No:	50645	Surv Map:	
POD Rec No:	3655	Other Loc:	200a Gonzales Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 SF

Wells and Additional Sources Detail Report

Start Date:	07/30/1991, 12:00 AM	Restrict :	0.0
Finish Date:	08/01/1991, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	10/28/1991, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	215	UTM Zone:	13
Depth of Water:	30	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	100	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416985.4
Pcw Rcv Da:		Northing:	3949341.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1739177.0
Static Lev:	0	Y:	1704584.0
Tract Nbr:		Point Y:	35.6844782
Map Nbr:		Point X:	-105.91742512
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
79	W	0.41	2,150.97	7,052.08	WATER WELLS

License Nb:	0	District Office S:	
POD No:	40581	Surv Map:	
POD Rec No:	170246	Other Loc:	318 Delgado St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	5&6 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	24
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415684.2
Pcw Rcv Da:		Northing:	3949086.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Delgado Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734918.0
Static Lev:	0	Y:	1703695.0
Tract Nbr:		Point Y:	35.68207429
Map Nbr:		Point X:	-105.9317768
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
80	N	0.42	2,200.22	7,148.87	WATER WELLS

License Nb:	622	District Office S:	
POD No:	62774	Surv Map:	
POD Rec No:	61887	Other Loc:	400 Kachina Ct, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	19 SF
Start Date:	05/10/1996, 12:00 AM	Restrict :	0.0
Finish Date:	05/13/1996, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	05/29/1996, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	360	UTM Zone:	13
Depth of Water:	120	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416354.6
Pcw Rcv Da:		Northing:	3949761.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/14/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Kachina Hills	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416354.6
Static Lev:	0	Y:	3949761.6
Tract Nbr:		Point Y:	35.68821578
Map Nbr:		Point X:	-105.92443925
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055099143210000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
82	NNW	0.43	2,248.32	7,100.73	WATER WELLS

License Nb:	606	District Office S:	
POD No:	29582	Surv Map:	
POD Rec No:	60616	Other Loc:	Usgs 7.5' Quad, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/01/1979, 12:00 AM	Restrict :	0.0
Finish Date:	07/01/1979, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/1979, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	162	UTM Zone:	13
Depth of Water:	40	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416157.3
Pcw Rcv Da:		Northing:	3949741.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/01/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596200.0
Static Lev:	0	Y:	1705800.0
Tract Nbr:		Point Y:	35.68801421
Map Nbr:		Point X:	-105.92661739
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
83	WNW	0.42	2,214.07	7,032.48	WATER WELLS

License Nb:	622	District Office S:	
POD No:	54536	Surv Map:	
POD Rec No:	51116	Other Loc:	208 Delgado St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/01/1991, 12:00 AM	Restrict :	0.0
Finish Date:	11/04/1991, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	11/19/1991, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	360	UTM Zone:	13
Depth of Water:	83	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415697.7
Pcw Rcv Da:		Northing:	3949281.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/17/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734954.0
Static Lev:	0	Y:	1704336.0
Tract Nbr:		Point Y:	35.68383522
Map Nbr:		Point X:	-105.93164809
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
84	SE	0.42	2,243.62	7,166.15	WATER WELLS

License Nb:	0	District Office S:	
POD No:	65777	Surv Map:	
POD Rec No:	10217	Other Loc:	
POD Basin:	RG	Zone :	C

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416905.1
Pcw Rcv Da:		Northing:	3948634.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/04/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598700.0
Static Lev:	0	Y:	1702200.0
Tract Nbr:		Point Y:	35.67810125
Map Nbr:		Point X:	-105.91823945
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
85	WSW	0.43	2,254.69	7,074.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	90264	Surv Map:	PLATT BOOK 552
POD Rec No:	236868	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415747.3
Pcw Rcv Da:		Northing:	3948724.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/10/2008, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1735140.0
Static Lev:	0	Y:	1702509.0
Tract Nbr:	B-1A	Point Y:	35.67881347
Map Nbr:		Point X:	-105.93104162
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
85	WSW	0.43	2,254.69	7,074.40	WATER WELLS

License Nb:	1616	District Office S:	
POD No:	90264	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	237237	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	05/19/2008, 12:00 AM	Restrict :	0.0
Finish Date:	05/28/2008, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	06/12/2008, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	240	UTM Zone:	13
Depth of Water:	84	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	12	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415747.3
Pcw Rcv Da:		Northing:	3948724.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/12/2008, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1735140.0
Static Lev:	0	Y:	1702509.0
Tract Nbr:	B 1A	Point Y:	35.67881347
Map Nbr:		Point X:	-105.93104162
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
86	S	0.43	2,290.44	7,168.54	WATER WELLS

License Nb:	622	District Office S:	

Wells and Additional Sources Detail Report

POD No:	68337	Surv Map:	
POD Rec No:	105580	Other Loc:	535 Camino Del Monte Sol
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T2 SF
Start Date:	10/04/1997, 12:00 AM	Restrict :	0.0
Finish Date:	10/08/1997, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	10/27/1997, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416299.2
Pcw Rcv Da:		Northing:	3948364.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/27/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416299.2
Static Lev:	0	Y:	3948364.1
Tract Nbr:		Point Y:	35.67561228
Map Nbr:		Point X:	-105.92490603
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number: 1055098147297000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
87	W	0.44	2,301.64	7,045.41	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	214	District Office S:	
POD No:	29621	Surv Map:	
POD Rec No:	44087	Other Loc:	414 Canyon Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/08/1978, 12:00 AM	Restrict :	0.0
Finish Date:	02/21/1978, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	03/02/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	303	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415641.7
Pcw Rcv Da:		Northing:	3949149.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/17/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734776.0
Static Lev:	0	Y:	1703900.0
Tract Nbr:		Point Y:	35.68263861
Map Nbr:		Point X:	-105.93225302
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
88	S	0.44	2,335.27	7,162.70	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	1281	District Office S:	
POD No:	57883	Surv Map:	
POD Rec No:	34861	Other Loc:	909 Camino Santander
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T2 SF
Start Date:	11/11/1993, 12:00 AM	Restrict :	0.0
Finish Date:	11/16/1993, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	04/13/1994, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	228	UTM Zone:	13
Depth of Water:	48	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	100	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416401.7
Pcw Rcv Da:		Northing:	3948350.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/06/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1737303.0
Static Lev:	0	Y:	1701309.0
Tract Nbr:	NA	Point Y:	35.67549746
Map Nbr:		Point X:	-105.9237721
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
89	S	0.44	2,341.01	7,169.04	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	30416	Surv Map:	
POD Rec No:	34267	Other Loc:	555 Camino Del Monte Sol, Sf
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416337.7
Pcw Rcv Da:		Northing:	3948346.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/19/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416337.7
Static Lev:	0	Y:	3948346.5
Tract Nbr:		Point Y:	35.67545687
Map Nbr:		Point X:	-105.92447882
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098144277000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

90	W	0.44	2,326.09	7,049.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	28882	Surv Map:	USGS 7.5 QUAD SANTA FE
POD Rec No:	55843	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415630.8
Pcw Rcv Da:		Northing:	3949077.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/08/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594500.0
Static Lev:	0	Y:	1703600.0
Tract Nbr:		Point Y:	35.68198498
Map Nbr:		Point X:	-105.93236587
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Usgs 7.5' Quad Of Santa Fe.		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

91	W	0.44	2,327.27	7,046.87	WATER WELLS

License Nb:	225	District Office S:	
POD No:	70612	Surv Map:	
POD Rec No:	145523	Other Loc:	334 Garcia St, Santa Fe, 87501
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/11/1998, 12:00 AM	Restrict :	0.0
Finish Date:	11/23/1998, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	01/05/2000, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	394	UTM Zone:	13
Depth of Water:	18	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415631.4
Pcw Rcv Da:		Northing:	3949123.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM SAN	Latitude Minute:	0
Sys Date:	10/12/2000, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594500.0
Static Lev:	0	Y:	1703750.0
Tract Nbr:		Point Y:	35.68239703
Map Nbr:		Point X:	-105.93236403
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
92	WNW	0.44	2,343.48	7,040.59	WATER WELLS

License Nb:	0	District Office S:	
POD No:	32540	Surv Map:	
POD Rec No:	47541	Other Loc:	124 Delgado, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415726.9
Pcw Rcv Da:		Northing:	3949441.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/14/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594800.0
Static Lev:	0	Y:	1704800.0
Tract Nbr:		Point Y:	35.68527925
Map Nbr:		Point X:	-105.93134218
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
93	WSW	0.45	2,351.37	7,066.42	WATER WELLS

License Nb:	228	District Office S:	
POD No:	07413	Surv Map:	
POD Rec No:	25978	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/28/1960, 12:00 AM	Restrict :	0.0
Finish Date:	06/28/1962, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	11/21/1962, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	115	UTM Zone:	13
Depth of Water:	20	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	415687.0
Pcw Rcv Da:		Northing:	3948777.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	10/09/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67928251
Map Nbr:		Point X:	-105.9317134
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
94	SSW	0.45	2,363.98	7,135.16	WATER WELLS

License Nb:	228	District Office S:	
POD No:	45875	Surv Map:	
POD Rec No:	33301	Other Loc:	858 Camino Ranchitos
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7A SF
Start Date:	07/18/1986, 12:00 AM	Restrict :	0.0
Finish Date:	07/22/1986, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/19/1986, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	340	UTM Zone:	13
Depth of Water:	70	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415992.2
Pcw Rcv Da:		Northing:	3948433.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/23/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Gault Comp	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735956.0
Static Lev:	0	Y:	1701564.0
Tract Nbr:		Point Y:	35.67621003
Map Nbr:		Point X:	-105.92830525
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
95	ESE	0.45	2,375.40	7,135.02	WATER WELLS

License Nb:	214	District Office S:	
POD No:	31705	Surv Map:	
POD Rec No:	36502	Other Loc:	1201 Canyon Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	A1 SF
Start Date:	12/18/1978, 12:00 AM	Restrict :	0.0
Finish Date:	12/22/1978, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	01/03/1979, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	159	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417083.8
Pcw Rcv Da:		Northing:	3948891.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/19/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417083.8
Static Lev:	0	Y:	3948891.3
Tract Nbr:		Point Y:	35.68043141
Map Nbr:		Point X:	-105.91629142
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal: Parcel Number 1-055-098-412-461

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
96	SW	0.45	2,382.98	7,080.54	WATER WELLS

License Nb:	228	District Office S:	
POD No:	37932	Surv Map:	
POD Rec No:	37913	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/12/1982, 12:00 AM	Restrict :	0.0
Finish Date:	05/14/1982, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	05/20/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	320	UTM Zone:	13
Depth of Water:	80	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415747.3
Pcw Rcv Da:		Northing:	3948649.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/29/2011, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594900.0
Static Lev:	0	Y:	1702200.0
Tract Nbr:		Point Y:	35.67813552
Map Nbr:		Point X:	-105.93103374
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
97	SSW	0.45	2,391.67	7,138.74	WATER WELLS

License Nb:	0	District Office S:	
POD No:	60365	Surv Map:	
POD Rec No:	2300	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416033.6
Pcw Rcv Da:		Northing:	3948401.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/26/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Galt Compound	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595850.0
Static Lev:	0	Y:	1701400.0
Tract Nbr:		Point Y:	35.67592867
Map Nbr:		Point X:	-105.92784453

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
98	SE	0.46	2,426.35	7,222.22	WATER WELLS

License Nb:	0	District Office S:	
POD No:	72757	Surv Map:	
POD Rec No:	152366	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416780.9
Pcw Rcv Da:		Northing:	3948453.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/04/1999, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598300.0
Static Lev:	0	Y:	1701600.0
Tract Nbr:		Point Y:	35.67645631

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.919593
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
99	ESE	0.45	2,396.46	7,134.25	WATER WELLS

License Nb:	0	District Office S:	
POD No:	04930	Surv Map:	
POD Rec No:	177236	Other Loc:	Point Of Div. Of Acequia Madre
POD Basin:	SD	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417097.7
Pcw Rcv Da:		Northing:	3948921.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/01/2002, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	599320.0
Static Lev:	0	Y:	1703150.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.68070484
Map Nbr:		Point X:	-105.91614094
Driller:			
POD Basin Desc:	Surface Declaration		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
99	ESE	0.45	2,396.46	7,134.25	WATER WELLS

License Nb:	0	District Office S:	
POD No:	04682	Surv Map:	SANTA FE (VOLUME II)
POD Rec No:	151588	Other Loc:	Acequia Madre
POD Basin:	SD	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417097.7
Pcw Rcv Da:		Northing:	3948921.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/09/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	599320.0

Wells and Additional Sources Detail Report

Static Lev:	0	Y:	1703150.0
Tract Nbr:		Point Y:	35.68070484
Map Nbr:	19	Point X:	-105.91614094
Driller:			
POD Basin Desc:	Surface Declaration		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
100	S	0.46	2,414.56	7,173.02	WATER WELLS

License Nb:	0	District Office S:	
POD No:	50460	Surv Map:	
POD Rec No:	27388	Other Loc:	555 Camino Del Monte Sol
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-50460-/	Easting:	416321.5
Pcw Rcv Da:		Northing:	3948324.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/31/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:	613E6	X:	416321.5
Static Lev:	0	Y:	3948324.8
Tract Nbr:		Point Y:	35.67525987
Map Nbr:		Point X:	-105.92465555
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
101	ESE	0.45	2,398.73	7,134.25	WATER WELLS

License Nb:	0	District Office S:	
POD No:	04899	Surv Map:	
POD Rec No:	295910	Other Loc:	
POD Basin:	SP	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417098.0
Pcw Rcv Da:		Northing:	3948918.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/20/2015, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1739564.0
Static Lev:	0	Y:	1703201.0
Tract Nbr:		Point Y:	35.68067422
Map Nbr:		Point X:	-105.91613728
Driller:			
POD Basin Desc:	Surface Permit		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
102	ESE	0.46	2,425.59	7,171.27	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35592	Surv Map:	
POD Rec No:	32100	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416996.9
Pcw Rcv Da:		Northing:	3948663.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/04/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	599000.0
Static Lev:	0	Y:	1702300.0
Tract Nbr:		Point Y:	35.67837313
Map Nbr:		Point X:	-105.91722815
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
103	SSE	0.47	2,462.82	7,197.59	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31909	Surv Map:	
POD Rec No:	14937	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416627.4
Pcw Rcv Da:		Northing:	3948363.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/07/2021, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597800.0
Static Lev:	0	Y:	1701300.0
Tract Nbr:		Point Y:	35.67563647
Map Nbr:		Point X:	-105.92127975
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
104	SW	0.46	2,437.25	7,126.56	WATER WELLS

License Nb:	0	District Office S:	
POD No:	81451	Surv Map:	
POD Rec No:	197078	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	17 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415896.1
Pcw Rcv Da:		Northing:	3948469.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	11/20/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co #1	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595396.0
Static Lev:	0	Y:	1701616.0
Tract Nbr:		Point Y:	35.67652638
Map Nbr:		Point X:	-105.92937082
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
105	SSW	0.46	2,448.29	7,158.97	WATER WELLS

License Nb:	547	District Office S:	
POD No:	66183	Surv Map:	
POD Rec No:	48425	Other Loc:	541 Camino Rancheros, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	M 5-7 SF
Start Date:	03/27/1997, 12:00 AM	Restrict :	0.0
Finish Date:	03/28/1997, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	04/04/1997, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	42	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416203.0
Pcw Rcv Da:		Northing:	3948328.4
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	02/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416203.0
Static Lev:	0	Y:	3948328.4
Tract Nbr:		Point Y:	35.67528226
Map Nbr:		Point X:	-105.92596521
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098102281000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
106	WSW	0.47	2,460.16	7,065.02	WATER WELLS

License Nb:	0	District Office S:	
POD No:	28796	Surv Map:	
POD Rec No:	282754	Other Loc:	433 Delgado Lane
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415657.5
Pcw Rcv Da:		Northing:	3948762.2

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734844.0
Static Lev:	0	Y:	1702629.0
Tract Nbr:		Point Y:	35.67914656
Map Nbr:		Point X:	-105.9320378
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
107	W	0.47	2,479.60	7,047.21	WATER WELLS

License Nb:	0	District Office S:	
POD No:	81449	Surv Map:	
POD Rec No:	197077	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415585.1

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3949032.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/20/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594352.0
Static Lev:	0	Y:	1703452.0
Tract Nbr:	1	Point Y:	35.68157989
Map Nbr:		Point X:	-105.93286617
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
108	SSW	0.47	2,487.64	7,143.70	WATER WELLS

License Nb:	0	District Office S:	
POD No:	81448	Surv Map:	
POD Rec No:	197079	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1-3 2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	415954.2
Pcw Rcv Da:		Northing:	3948411.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/20/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Galt Compound	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595589.0
Static Lev:	0	Y:	1701429.0
Tract Nbr:		Point Y:	35.67601116
Map Nbr:		Point X:	-105.92872284
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
109	NW	0.48	2,522.50	7,145.87	WATER WELLS

License Nb:	0	District Office S:	
POD No:	42150	Surv Map:	
POD Rec No:	24289	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415913.2
Pcw Rcv Da:		Northing:	3949713.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595400.0
Static Lev:	0	Y:	1705700.0
Tract Nbr:		Point Y:	35.6877464
Map Nbr:		Point X:	-105.92931197
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
110	SSW	0.47	2,500.66	7,143.94	WATER WELLS

License Nb:	1310	District Office S:	
POD No:	81673	Surv Map:	
POD Rec No:	197877	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7-A 1 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415992.6
Pcw Rcv Da:		Northing:	3948386.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/30/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Galt Compound	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595716.0
Static Lev:	0	Y:	1701347.0
Tract Nbr:		Point Y:	35.67578454
Map Nbr:		Point X:	-105.9282959
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
111	SW	0.48	2,509.77	7,132.94	WATER WELLS

License Nb:	1382	District Office S:	
POD No:	94187	Surv Map:	
POD Rec No:	285779	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	PLG	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:	05/09/2025, 12:00 AM	Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EG
Depth of Well:	135	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415906.2
Pcw Rcv Da:		Northing:	3948434.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/30/2025, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1735673.6
Static Lev:	0	Y:	1701565.7
Tract Nbr:		Point Y:	35.67621712
Map Nbr:		Point X:	-105.92925563
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
112	WNW	0.48	2,534.84	7,044.27	WATER WELLS

License Nb:	0	District Office S:	
POD No:	37628	Surv Map:	
POD Rec No:	334537	Other Loc:	511 East Palace Ave., Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415697.2
Pcw Rcv Da:		Northing:	3949503.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594700.0
Static Lev:	0	Y:	1705000.0
Tract Nbr:		Point Y:	35.68582934
Map Nbr:		Point X:	-105.9316768
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
112	WNW	0.48	2,534.84	7,044.27	WATER WELLS

License Nb:	253	District Office S:	
POD No:	37629	Surv Map:	
POD Rec No:	8784	Other Loc:	519 East Palace Ave., Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/22/1985, 12:00 AM	Restrict :	0.0
Finish Date:	02/23/1985, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	09/27/1985, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	80	UTM Zone:	13
Depth of Water:	28	UTM Accura:	10
Ground Water Src:	S	UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415697.2
Pcw Rcv Da:		Northing:	3949503.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594700.0
Static Lev:	0	Y:	1705000.0
Tract Nbr:		Point Y:	35.68582934
Map Nbr:		Point X:	-105.9316768
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
114	WSW	0.48	2,535.68	7,068.58	WATER WELLS

License Nb:	0	District Office S:	
POD No:	74064	Surv Map:	
POD Rec No:	157764	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10

Wells and Additional Sources Detail Report

Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415656.6
Pcw Rcv Da:		Northing:	3948711.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/12/2000, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594600.0
Static Lev:	0	Y:	1702400.0
Tract Nbr:		Point Y:	35.67868761
Map Nbr:		Point X:	-105.93204241
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
115	SW	0.48	2,545.54	7,135.57	WATER WELLS

License Nb:	72	District Office S:	
POD No:	94187	Surv Map:	
POD Rec No:	341180	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/30/2024, 12:00 AM	Restrict :	0.0
Finish Date:	10/02/2024, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	10/11/2024, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	360	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415899.1
Pcw Rcv Da:		Northing:	3948426.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/17/2024, 12:00 AM	Latitude Second:	34.1
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	55
Ditch Name:		Longitude Second:	45.6
Well Tag:	NA	X:	0.0
Static Lev:	116	Y:	0.0
Tract Nbr:		Point Y:	35.67613898
Map Nbr:		Point X:	-105.92933317
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
116	N	0.49	2,582.21	7,122.63	WATER WELLS

License Nb:	622	District Office S:	
POD No:	65227	Surv Map:	
POD Rec No:	25067	Other Loc:	412 Calle Kokopelli
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7 SF
Start Date:	01/09/2000, 12:00 AM	Restrict :	0.0
Finish Date:	01/14/2000, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	04/17/2000, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA

Wells and Additional Sources Detail Report

Depth of Well:	400	UTM Zone:	13
Depth of Water:	285	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416270.7
Pcw Rcv Da:		Northing:	3949871.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/04/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Kachina Hills	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416270.7
Static Lev:	0	Y:	3949871.9
Tract Nbr:		Point Y:	35.68920304
Map Nbr:		Point X:	-105.92537788
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055099113239000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
117	WSW	0.48	2,558.67	7,058.07	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31455	Surv Map:	
POD Rec No:	18083	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415597.2
Pcw Rcv Da:		Northing:	3948834.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/14/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594400.0
Static Lev:	0	Y:	1702800.0
Tract Nbr:		Point Y:	35.6797887
Map Nbr:		Point X:	-105.93271161
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
118	E	0.49	2,575.81	7,152.66	WATER WELLS

License Nb:	0	District Office S:	
POD No:	19196	Surv Map:	
POD Rec No:	21290	Other Loc:	4 Camino Pequeno
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	U1 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417162.1
Pcw Rcv Da:		Northing:	3948973.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Pequeno Compound	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1739772.0
Static Lev:	0	Y:	1703385.0
Tract Nbr:		Point Y:	35.68117815
Map Nbr:		Point X:	-105.91543469
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	4 Camino Pequeno, Santa Fe, N.M.		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
119	E	0.50	2,628.19	7,179.59	WATER WELLS

License Nb:	0	District Office S:	
POD No:	68085	Surv Map:	
POD Rec No:	104934	Other Loc:	1242 Cerro Cordo
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	340 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	22	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417185.2
Pcw Rcv Da:		Northing:	3949089.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/22/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	599600.0
Static Lev:	0	Y:	1703705.0
Tract Nbr:		Point Y:	35.68222766
Map Nbr:		Point X:	-105.91519141
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
119	E	0.50	2,628.19	7,179.59	WATER WELLS

License Nb:	0	District Office S:	
POD No:	67989	Surv Map:	
POD Rec No:	80815	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	X	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	22	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417185.2
Pcw Rcv Da:		Northing:	3949089.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/02/1997, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	599600.0
Static Lev:	0	Y:	1703705.0
Tract Nbr:		Point Y:	35.68222766
Map Nbr:		Point X:	-105.91519141
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
120	W	0.50	2,629.87	7,040.33	WATER WELLS

License Nb:	0	District Office S:	
POD No:	51376	Surv Map:	
POD Rec No:	24565	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415540.2
Pcw Rcv Da:		Northing:	3949139.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/18/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594200.0
Static Lev:	0	Y:	1703800.0
Tract Nbr:		Point Y:	35.68253707
Map Nbr:		Point X:	-105.93337349
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
121	WSW	0.51	2,680.53	7,062.80	WATER WELLS

License Nb:	0	District Office S:	
POD No:	58226	Surv Map:	
POD Rec No:	339881	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	

Wells and Additional Sources Detail Report

Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415593.0
Pcw Rcv Da:		Northing:	3948742.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/04/2024, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594390.0
Static Lev:	0	Y:	1702500.0
Tract Nbr:		Point Y:	35.67896435
Map Nbr:		Point X:	-105.93274843
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
122	WSW	0.52	2,732.51	7,062.80	WATER WELLS

License Nb:	0	District Office S:	
POD No:	58226	Surv Map:	
POD Rec No:	339880	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415577.7
Pcw Rcv Da:		Northing:	3948738.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/04/2024, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594340.0
Static Lev:	0	Y:	1702485.0
Tract Nbr:		Point Y:	35.67892337
Map Nbr:		Point X:	-105.93291702
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
123	E	0.52	2,730.49	7,191.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	67989	Surv Map:	
POD Rec No:	80814	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	25	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417215.9
Pcw Rcv Da:		Northing:	3949102.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/02/1997, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	599700.0
Static Lev:	0	Y:	1703750.0
Tract Nbr:		Point Y:	35.68235014
Map Nbr:		Point X:	-105.91485355
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
123	E	0.52	2,730.49	7,191.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	67898	Surv Map:	
POD Rec No:	338069	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417215.9
Pcw Rcv Da:		Northing:	3949102.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	599700.0
Static Lev:	0	Y:	1703750.0
Tract Nbr:		Point Y:	35.68235014
Map Nbr:		Point X:	-105.91485355
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
124	SW	0.52	2,745.88	7,081.27	WATER WELLS

License Nb:	622	District Office S:	
POD No:	65048	Surv Map:	
POD Rec No:	57818	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415655.1
Pcw Rcv Da:		Northing:	3948589.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594600.0
Static Lev:	0	Y:	1702000.0
Tract Nbr:		Point Y:	35.67758853
Map Nbr:		Point X:	-105.93204621
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
125	E	0.52	2,760.89	7,147.70	WATER WELLS

License Nb:	0	District Office S:	
POD No:	71076	Surv Map:	
POD Rec No:	146943	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417213.7
Pcw Rcv Da:		Northing:	3948935.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/13/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	599700.0
Static Lev:	0	Y:	1703200.0
Tract Nbr:		Point Y:	35.680839
Map Nbr:		Point X:	-105.91486061
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
126	WSW	0.52	2,761.83	7,062.35	WATER WELLS

License Nb:	0	District Office S:	
POD No:	58226	Surv Map:	
POD Rec No:	339879	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0

Wells and Additional Sources Detail Report

POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 8 39 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415565.6
Pcw Rcv Da:		Northing:	3948742.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/04/2024, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Kings Map	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594300.0
Static Lev:	0	Y:	1702500.0
Tract Nbr:		Point Y:	35.6789647
Map Nbr:		Point X:	-105.93305121
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
127	SSW	0.53	2,777.92	7,165.47	WATER WELLS

License Nb:	0	District Office S:	
POD No:	56393	Surv Map:	
POD Rec No:	51104	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416107.9
Pcw Rcv Da:		Northing:	3948248.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/14/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596100.0
Static Lev:	0	Y:	1700900.0
Tract Nbr:		Point Y:	35.67455296
Map Nbr:		Point X:	-105.92700761
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
128	SE	0.53	2,806.97	7,273.26	WATER WELLS

License Nb:	0	District Office S:	
POD No:	57536	Surv Map:	
POD Rec No:	44010	Other Loc:	
POD Basin:	RG	Zone :	C

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416932.9
Pcw Rcv Da:		Northing:	3948420.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/07/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598800.0
Static Lev:	0	Y:	1701500.0
Tract Nbr:		Point Y:	35.67617703
Map Nbr:		Point X:	-105.91791021
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
129	E	0.53	2,801.27	7,157.17	WATER WELLS

License Nb:	253	District Office S:	
POD No:	13892	Surv Map:	
POD Rec No:	25832	Other Loc:	5 Camino Pequeno

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	12 T11 SF
Start Date:	05/10/1966, 12:00 AM	Restrict :	0.0
Finish Date:	05/25/1966, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	12/28/1966, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	30	UTM Zone:	13
Depth of Water:	6	UTM Accura:	
Ground Water Src:	A	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417228.2
Pcw Rcv Da:		Northing:	3948948.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/19/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1739990.0
Static Lev:	0	Y:	1703307.0
Tract Nbr:		Point Y:	35.68096192
Map Nbr:		Point X:	-105.91470178
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
130	S	0.54	2,826.13	7,187.32	WATER WELLS

License Nb:	0	District Office S:	
POD No:	81586	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	197575	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416389.1
Pcw Rcv Da:		Northing:	3948199.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/12/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597025.0
Static Lev:	0	Y:	1700752.0
Tract Nbr:		Point Y:	35.67413779
Map Nbr:		Point X:	-105.92389565
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
131	E	0.53	2,802.84	7,209.12	WATER WELLS

License Nb:	214	District Office S:	

Wells and Additional Sources Detail Report

POD No:	35111	Surv Map:	
POD Rec No:	10548	Other Loc:	1241 Cerro Gordo Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1C SF
Start Date:	09/26/1980, 12:00 AM	Restrict :	0.0
Finish Date:	09/29/1980, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	10/28/1980, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	205	UTM Zone:	13
Depth of Water:	45	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	22	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417229.5
Pcw Rcv Da:		Northing:	3949199.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1739984.0
Static Lev:	0	Y:	1704131.0
Tract Nbr:		Point Y:	35.68322577
Map Nbr:		Point X:	-105.91471325
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Salvador Gonzales/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
132	SE	0.54	2,842.62	7,313.72	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	53900	Surv Map:	
POD Rec No:	52131	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416871.2
Pcw Rcv Da:		Northing:	3948360.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/23/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598600.0
Static Lev:	0	Y:	1701300.0
Tract Nbr:		Point Y:	35.67562911
Map Nbr:		Point X:	-105.91858571
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
132	SE	0.54	2,842.62	7,313.72	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	51374	Surv Map:	
POD Rec No:	17495	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416871.2
Pcw Rcv Da:		Northing:	3948360.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/18/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598600.0
Static Lev:	0	Y:	1701300.0
Tract Nbr:		Point Y:	35.67562911
Map Nbr:		Point X:	-105.91858571
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
133	W	0.53	2,817.45	7,035.69	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	225	District Office S:	
POD No:	08786	Surv Map:	
POD Rec No:	36762	Other Loc:	1011 Paseo De Peralta Sf 87501
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	PLG	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA1A SF
Start Date:	11/30/1998, 12:00 AM	Restrict :	0.0
Finish Date:	12/05/1998, 12:00 AM	Section:	25
Plug Date:	01/06/2001, 12:00 AM	Township:	17N
Log File D:	01/05/2000, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	293	UTM Zone:	13
Depth of Water:	25	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	55	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	415481.5
Pcw Rcv Da:		Northing:	3949110.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/07/2025, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734252.0
Static Lev:	0	Y:	1703765.0
Tract Nbr:		Point Y:	35.6822724
Map Nbr:		Point X:	-105.93401909
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

134	W	0.54	2,827.05	7,038.38	WATER WELLS

License Nb:	0	District Office S:	
POD No:	53901	Surv Map:	
POD Rec No:	36980	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415478.1
Pcw Rcv Da:		Northing:	3949048.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/23/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594000.0
Static Lev:	0	Y:	1703500.0
Tract Nbr:		Point Y:	35.68171496
Map Nbr:		Point X:	-105.93405017
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

135	SSW	0.54	2,845.49	7,168.75	WATER WELLS

License Nb:	622	District Office S:	
POD No:	69336	Surv Map:	
POD Rec No:	142014	Other Loc:	826 Camino Ranchitos, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 2 SF
Start Date:	12/16/1998, 12:00 AM	Restrict :	0.0
Finish Date:	12/17/1998, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	01/12/1999, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	340	UTM Zone:	13
Depth of Water:	108	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	6	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416141.2
Pcw Rcv Da:		Northing:	3948218.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Los Rancheros	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416141.2
Static Lev:	0	Y:	3948218.3
Tract Nbr:		Point Y:	35.67428443
Map Nbr:		Point X:	-105.92663655
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098082241000000		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
136	SSE	0.54	2,874.62	7,204.20	WATER WELLS

License Nb:	214	District Office S:	
POD No:	30590	Surv Map:	
POD Rec No:	23145	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/12/1978, 12:00 AM	Restrict :	0.0
Finish Date:	06/17/1978, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	06/21/1978, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	380	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	5	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416564.5
Pcw Rcv Da:		Northing:	3948212.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597600.0
Static Lev:	0	Y:	1700800.0
Tract Nbr:		Point Y:	35.67426444
Map Nbr:		Point X:	-105.921959
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
137	SW	0.54	2,850.50	7,089.39	WATER WELLS

License Nb:	0	District Office S:	
POD No:	44528	Surv Map:	
POD Rec No:	337651	Other Loc:	618 1/2 Garcia St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4B 134 SF
Start Date:		Restrict :	0.0
Finish Date:	12/31/1891, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	65	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415663.6
Pcw Rcv Da:		Northing:	3948523.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Kings Map	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734874.0
Static Lev:	0	Y:	1701846.0
Tract Nbr:		Point Y:	35.67699515
Map Nbr:		Point X:	-105.93194538
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
138	SW	0.54	2,874.67	7,080.98	WATER WELLS

License Nb:	547	District Office S:	
POD No:	68739	Surv Map:	
POD Rec No:	139929	Other Loc:	608 Garcia St, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	18 134 SF
Start Date:	01/05/1998, 12:00 AM	Restrict :	0.0
Finish Date:	01/06/1998, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	01/15/1998, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	72	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	33	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415618.2
Pcw Rcv Da:		Northing:	3948573.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/13/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415618.2
Static Lev:	0	Y:	3948573.7
Tract Nbr:		Point Y:	35.67744383
Map Nbr:		Point X:	-105.93245227
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal: Parcel Number 1054098430352000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
139	S	0.55	2,913.56	7,178.41	WATER WELLS

License Nb:	0	District Office S:	
POD No:	81392	Surv Map:	
POD Rec No:	196619	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416286.7
Pcw Rcv Da:		Northing:	3948173.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/06/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596690.0
Static Lev:	0	Y:	1700663.0
Tract Nbr:		Point Y:	35.67389651
Map Nbr:		Point X:	-105.92502435
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
140	NW	0.56	2,952.75	7,056.60	WATER WELLS

License Nb:	815	District Office S:	
POD No:	50828	Surv Map:	
POD Rec No:	49621	Other Loc:	347 Hillside, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	13 SF
Start Date:	07/23/1990, 12:00 AM	Restrict :	0.0
Finish Date:	07/27/1990, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	08/31/1990, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	80	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415693.5
Pcw Rcv Da:		Northing:	3949700.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/04/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415693.5
Static Lev:	0	Y:	3949700.5
Tract Nbr:		Point Y:	35.68760863
Map Nbr:		Point X:	-105.93173838
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc:	Rio Grande
POD Sub Basin Desc:	Santa Fe River
Grant :	Santa Fe
Legal:	Parcel Number 1054099457198000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
142	WSW	0.56	2,943.63	7,058.83	WATER WELLS

License Nb:	0	District Office S:	
POD No:	32201	Surv Map:	
POD Rec No:	333151	Other Loc:	488 Arroyo Tenorio
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415504.7
Pcw Rcv Da:		Northing:	3948743.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/09/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594100.0
Static Lev:	0	Y:	1702500.0
Tract Nbr:		Point Y:	35.6789667
Map Nbr:		Point X:	-105.9337242

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
143	ESE	0.56	2,968.22	7,165.31	WATER WELLS

License Nb:	622	District Office S:	
POD No:	59674	Surv Map:	
POD Rec No:	19910	Other Loc:	1239 Canyon Rd
POD Basin:	RG	Zone :	C
POD Suffix:	X	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:	07/10/1994, 12:00 AM	Restrict :	0.0
Finish Date:	07/10/1994, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/01/1994, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	220	UTM Zone:	13
Depth of Water:	30	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417254.8
Pcw Rcv Da:		Northing:	3948829.8
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	07/13/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417254.8
Static Lev:	0	Y:	3948829.8
Tract Nbr:		Point Y:	35.67989134

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.91439562
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098455453000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
144	SSW	0.57	2,994.63	7,128.23	WATER WELLS

License Nb:	0	District Office S:	
POD No:	33036	Surv Map:	
POD Rec No:	42534	Other Loc:	665 Garcia Street, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415925.0
Pcw Rcv Da:		Northing:	3948250.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/02/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595500.0
Static Lev:	0	Y:	1700900.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.67455811
Map Nbr:		Point X:	-105.92902866
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
145	SE	0.57	3,017.96	7,219.21	WATER WELLS

License Nb:	1382	District Office S:	
POD No:	40884	Surv Map:	
POD Rec No:	15825	Other Loc:	1156 Camino Delora
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	10/31/1983, 12:00 AM	Restrict :	0.0
Finish Date:	10/31/1983, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	361	UTM Zone:	13
Depth of Water:	144	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	23	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417072.7
Pcw Rcv Da:		Northing:	3948467.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/05/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1739500.0

Wells and Additional Sources Detail Report

Static Lev:	0	Y:	1701722.0
Tract Nbr:		Point Y:	35.67661161
Map Nbr:		Point X:	-105.9163704
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
146	NW	0.58	3,040.87	7,045.69	WATER WELLS

License Nb:	1173	District Office S:	
POD No:	81257	Surv Map:	
POD Rec No:	195967	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	EA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415660.4
Pcw Rcv Da:		Northing:	3949705.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/15/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:		X:	594571.0
Static Lev:	0	Y:	1705663.0
Tract Nbr:		Point Y:	35.68765268
Map Nbr:		Point X:	-105.9321047
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
147	W	0.57	3,023.20	7,026.37	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34783	Surv Map:	SANTA FE RIVER HYDRO SURVEY
POD Rec No:	27075	Other Loc:	**Tct 11.133
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	01/01/1915, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	ES
Depth of Well:	330	UTM Zone:	13
Depth of Water:	12	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415431.7
Pcw Rcv Da:		Northing:	3949233.8
Sched Date:		Latitude Degree:	0
Use of Wel:	COM, IRR.	Latitude Minute:	0
Sys Date:	07/11/2024, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593840.0
Static Lev:	0	Y:	1704105.0
Tract Nbr:	**	Point Y:	35.6833788
Map Nbr:	19	Point X:	-105.93458232
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
148	SW	0.57	3,028.86	7,107.32	WATER WELLS

License Nb:	253	District Office S:	
POD No:	37721	Surv Map:	
POD Rec No:	45295	Other Loc:	646 Garcia Street, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10E SF
Start Date:	06/14/1982, 12:00 AM	Restrict :	0.0
Finish Date:	06/17/1982, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	06/28/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	260	UTM Zone:	13
Depth of Water:	54	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	70	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415670.8
Pcw Rcv Da:		Northing:	3948431.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/28/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415670.8
Static Lev:	0	Y:	3948431.4
Tract Nbr:		Point Y:	35.67616546
Map Nbr:		Point X:	-105.93185617
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
149	WSW	0.57	3,032.81	7,052.57	WATER WELLS

License Nb:	214	District Office S:	
POD No:	28712	Surv Map:	
POD Rec No:	44800	Other Loc:	481 Arroyo Tenorio
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 SF
Start Date:	05/24/1977, 12:00 AM	Restrict :	0.0
Finish Date:	05/27/1977, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	06/08/1977, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	243	UTM Zone:	13
Depth of Water:	60	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415457.4
Pcw Rcv Da:		Northing:	3948796.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2021, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734186.0
Static Lev:	0	Y:	1702732.0
Tract Nbr:		Point Y:	35.67943504
Map Nbr:		Point X:	-105.93425234
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
150	ESE	0.58	3,037.00	7,169.13	WATER WELLS

License Nb:	622	District Office S:	
POD No:	59674	Surv Map:	
POD Rec No:	48012	Other Loc:	1239 Canyon Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:	07/12/1994, 12:00 AM	Restrict :	0.0
Finish Date:	07/12/1994, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/01/1994, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	220	UTM Zone:	13
Depth of Water:	60	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417274.6
Pcw Rcv Da:		Northing:	3948822.4
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	07/13/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417274.6
Static Lev:	0	Y:	3948822.4
Tract Nbr:		Point Y:	35.67982629
Map Nbr:		Point X:	-105.91417608
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:	Parcel Number 1055098455453000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
151	SSW	0.58	3,040.35	7,131.33	WATER WELLS

License Nb:	228	District Office S:	
POD No:	45498	Surv Map:	
POD Rec No:	15734	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/30/1986, 12:00 AM	Restrict :	0.0
Finish Date:	07/08/1986, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/19/1986, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	360	UTM Zone:	13
Depth of Water:	60	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415894.6
Pcw Rcv Da:		Northing:	3948251.1
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	10/09/2012, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595400.0
Static Lev:	0	Y:	1700900.0
Tract Nbr:		Point Y:	35.67455913
Map Nbr:		Point X:	-105.92936458
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
153	W	0.58	3,056.37	7,039.48	WATER WELLS

License Nb:	214	District Office S:	
POD No:	34694	Surv Map:	
POD Rec No:	58088	Other Loc:	1075 Paseo Del Peralta
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	19 126 SF
Start Date:	07/09/1980, 12:00 AM	Restrict :	0.0
Finish Date:	07/21/1980, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	07/25/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	390	UTM Zone:	13
Depth of Water:	35	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415415.8
Pcw Rcv Da:		Northing:	3948953.0

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/11/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734043.0
Static Lev:	0	Y:	1703245.0
Tract Nbr:		Point Y:	35.68084596
Map Nbr:		Point X:	-105.93472849
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
154	SSW	0.58	3,072.51	7,171.78	WATER WELLS

License Nb:	622	District Office S:	
POD No:	60399	Surv Map:	
POD Rec No:	42592	Other Loc:	540 Camino Rancheros
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 2 SF
Start Date:	10/17/1994, 12:00 AM	Restrict :	0.0
Finish Date:	10/18/1994, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	12/09/1994, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	370	UTM Zone:	13
Depth of Water:	99	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	5	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416151.3

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3948144.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/27/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416151.3
Static Lev:	0	Y:	3948144.6
Tract Nbr:		Point Y:	35.67362086
Map Nbr:		Point X:	-105.92651728
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098087223000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
155	S	0.58	3,077.38	7,182.65	WATER WELLS

License Nb:	225	District Office S:	
POD No:	44857	Surv Map:	
POD Rec No:	45114	Other Loc:	600 Camino Rancheros, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	26 4 SF
Start Date:	12/30/1985, 12:00 AM	Restrict :	0.0
Finish Date:	01/04/1986, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	02/21/1986, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	410	UTM Zone:	13
Depth of Water:	411	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	5	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	416192.0
Pcw Rcv Da:		Northing:	3948135.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/23/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	De Vargas	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416192.0
Static Lev:	0	Y:	3948135.6
Tract Nbr:		Point Y:	35.67354319
Map Nbr:		Point X:	-105.92606667
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098097215000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
156	WNW	0.58	3,083.47	7,017.93	WATER WELLS

License Nb:	622	District Office S:	
POD No:	71196	Surv Map:	
POD Rec No:	147430	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/05/1999, 12:00 AM	Restrict :	0.0
Finish Date:	04/07/1999, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/03/1999, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	408	UTM Zone:	13
Depth of Water:	8	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415451.9
Pcw Rcv Da:		Northing:	3949384.4
Sched Date:		Latitude Degree:	0
Use of Wel:	DRINK/SANITARY	Latitude Minute:	0
Sys Date:	05/07/1999, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593900.0
Static Lev:	0	Y:	1704600.0
Tract Nbr:		Point Y:	35.68473823
Map Nbr:		Point X:	-105.93437494
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
157	W	0.59	3,091.00	7,026.00	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34782	Surv Map:	SANTA FE RIVER HYDRO SURVEY
POD Rec No:	65820	Other Loc:	**Tct 11.133
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	01/01/1946, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	ES
Depth of Well:	60	UTM Zone:	13
Depth of Water:	12	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415407.0
Pcw Rcv Da:		Northing:	3949211.2
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	07/29/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593760.0
Static Lev:	0	Y:	1704030.0
Tract Nbr:	**	Point Y:	35.68317294
Map Nbr:	19	Point X:	-105.93485288
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
158	SW	0.60	3,144.97	7,093.91	WATER WELLS

License Nb:	0	District Office S:	
POD No:	29354	Surv Map:	USGS 7.5' QUAD SANTA FE
POD Rec No:	50582	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415592.6
Pcw Rcv Da:		Northing:	3948468.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/22/2015, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594400.0
Static Lev:	0	Y:	1701600.0
Tract Nbr:		Point Y:	35.67649143
Map Nbr:		Point X:	-105.93272407
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
159	S	0.60	3,169.45	7,207.15	WATER WELLS

License Nb:	227	District Office S:	
POD No:	34163	Surv Map:	
POD Rec No:	59540	Other Loc:	632 Camino Del Monte Sol, Sf
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 SF
Start Date:	04/25/1980, 12:00 AM	Restrict :	0.0
Finish Date:	04/28/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	05/05/1980, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	110	UTM Zone:	13
Depth of Water:	84	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	

Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416413.3
Pcw Rcv Da:		Northing:	3948096.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/30/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416413.3
Static Lev:	0	Y:	3948096.6
Tract Nbr:		Point Y:	35.67321037
Map Nbr:		Point X:	-105.92361757
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098168195000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
160	SW	0.60	3,149.06	7,088.95	WATER WELLS

License Nb:	1472	District Office S:	
POD No:	29354	Surv Map:	
POD Rec No:	296840	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	09/18/2015, 12:00 AM	Restrict :	0.0
Finish Date:	09/21/2015, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	09/30/2015, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	120	UTM Accura:	
Ground Water Src:	S	UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.32	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415576.6
Pcw Rcv Da:		Northing:	3948486.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/19/2015, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1734590.0
Static Lev:	0	Y:	1701722.0
Tract Nbr:		Point Y:	35.67665685
Map Nbr:		Point X:	-105.93290279
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
161	W	0.60	3,151.51	7,037.71	WATER WELLS

License Nb:	0	District Office S:	
POD No:	30918	Surv Map:	SANTA FE RIVER HYDROSURVEY
POD Rec No:	169331	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	12/31/1940, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	210	UTM Zone:	13
Depth of Water:	180	UTM Accura:	10

Wells and Additional Sources Detail Report

Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415385.5
Pcw Rcv Da:		Northing:	3948958.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/03/2001, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593700.0
Static Lev:	0	Y:	1703200.0
Tract Nbr:	8.14	Point Y:	35.68089295
Map Nbr:	2	Point X:	-105.93506387
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
162	WNW	0.60	3,188.30	7,023.59	WATER WELLS

License Nb:	1004	District Office S:	
POD No:	66323	Surv Map:	
POD Rec No:	32816	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415484.3
Pcw Rcv Da:		Northing:	3949536.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/16/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594000.0
Static Lev:	0	Y:	1705100.0
Tract Nbr:		Point Y:	35.68611041
Map Nbr:		Point X:	-105.93403289
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
163	S	0.61	3,197.31	7,186.94	WATER WELLS

License Nb:	1173	District Office S:	
POD No:	50629	Surv Map:	
POD Rec No:	69858	Other Loc:	623 Camino Rancheros
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	15 5 U1 SF
Start Date:	05/08/1989, 12:00 AM	Restrict :	0.0
Finish Date:	05/18/1989, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/07/1989, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA

Wells and Additional Sources Detail Report

Depth of Well:	236	UTM Zone:	13
Depth of Water:	120	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	12	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416311.5
Pcw Rcv Da:		Northing:	3948086.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1737018.0
Static Lev:	0	Y:	1700438.0
Tract Nbr:		Point Y:	35.67310708
Map Nbr:		Point X:	-105.92474121
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
164	W	0.60	3,192.63	7,022.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34781	Surv Map:	SANTA FE RIVER HYDRO SURVEY
POD Rec No:	67447	Other Loc:	**Tct 11.133
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	07/01/1946, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	21	UTM Source:	ES
Depth of Well:	50	UTM Zone:	13
Depth of Water:	8	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415379.8
Pcw Rcv Da:		Northing:	3949232.9
Sched Date:		Latitude Degree:	0
Use of Wel:	COM. IRR & DOM	Latitude Minute:	0
Sys Date:	07/29/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593670.0
Static Lev:	0	Y:	1704100.0
Tract Nbr:	**	Point Y:	35.68336623
Map Nbr:	19	Point X:	-105.93515572
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Tr. 11.133 Sheet 19		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
165	SW	0.61	3,196.44	7,133.60	WATER WELLS

License Nb:	214	District Office S:	
POD No:	34618	Surv Map:	
POD Rec No:	69509	Other Loc:	660 Garcia St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/26/1980, 12:00 AM	Restrict :	0.0
Finish Date:	06/27/1980, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	07/03/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	345	UTM Zone:	13
Depth of Water:	62	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	400	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415804.0
Pcw Rcv Da:		Northing:	3948251.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/06/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735346.0
Static Lev:	0	Y:	1700959.0
Tract Nbr:		Point Y:	35.6745532
Map Nbr:		Point X:	-105.93036561
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
165	SW	0.61	3,196.44	7,133.60	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31225	Surv Map:	
POD Rec No:	333099	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415803.2
Pcw Rcv Da:		Northing:	3948252.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595100.0
Static Lev:	0	Y:	1700900.0
Tract Nbr:		Point Y:	35.67456215
Map Nbr:		Point X:	-105.93037456
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
166	WSW	0.61	3,197.55	7,042.37	WATER WELLS

License Nb:	0	District Office S:	
POD No:	08786	Surv Map:	
POD Rec No:	275692	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	A	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.945
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415384.0
Pcw Rcv Da:		Northing:	3948880.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/08/2012, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68018512
Map Nbr:		Point X:	-105.93507218
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
166	WSW	0.61	3,197.55	7,042.37	WATER WELLS

License Nb:	622	District Office S:	
POD No:	40890	Surv Map:	
POD Rec No:	6700	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/26/1983, 12:00 AM	Restrict :	0.0
Finish Date:	10/26/1983, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	11/08/1983, 12:00 AM	Range:	09E

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	345	UTM Zone:	13
Depth of Water:	125	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415384.0
Pcw Rcv Da:		Northing:	3948880.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68018512
Map Nbr:		Point X:	-105.93507218
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
167	ENE	0.61	3,224.56	7,221.20	WATER WELLS

License Nb:	228	District Office S:	
POD No:	43193	Surv Map:	
POD Rec No:	22249	Other Loc:	1298 Lejano Ln, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	15 NA U5 SF
Start Date:	06/05/1985, 12:00 AM	Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:	07/17/1985, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	120	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417309.6
Pcw Rcv Da:		Northing:	3949409.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Valle Lejano	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417309.6
Static Lev:	0	Y:	3949409.7
Tract Nbr:		Point Y:	35.68512389
Map Nbr:		Point X:	-105.91384972
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Salvador Gonzales/Santa Fe		
Legal:	Parcel Number 1055099442074000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
168	NW	0.62	3,250.01	7,064.47	WATER WELLS

License Nb:	986	District Office S:	
POD No:	50497	Surv Map:	
POD Rec No:	11795	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:	04/12/1989, 12:00 AM	Restrict :	0.0
Finish Date:	04/22/1989, 12:00 AM	Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:	04/27/1989, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	206	UTM Zone:	13
Depth of Water:	60	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415644.3
Pcw Rcv Da:		Northing:	3949779.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/31/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415644.3
Static Lev:	0	Y:	3949779.4
Tract Nbr:		Point Y:	35.68831572
Map Nbr:		Point X:	-105.93229034
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1054099438216000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
169	NW	0.62	3,258.31	7,102.49	WATER WELLS

License Nb:	0	District Office S:	
POD No:	30796	Surv Map:	
POD Rec No:	29795	Other Loc:	321 Hillside Ave
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	9 40 SF
Start Date:		Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415670.5
Pcw Rcv Da:		Northing:	3949808.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/01/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1734843.0
Static Lev:	0	Y:	1706064.0
Tract Nbr:		Point Y:	35.68858301
Map Nbr:		Point X:	-105.9320039
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
170	E	0.62	3,296.36	7,230.01	WATER WELLS

License Nb:	0	District Office S:	
POD No:	69847	Surv Map:	
POD Rec No:	143277	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417370.3
Pcw Rcv Da:		Northing:	3949268.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	600200.0
Static Lev:	0	Y:	1704300.0
Tract Nbr:		Point Y:	35.68385603
Map Nbr:		Point X:	-105.91316447
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
171	WSW	0.63	3,300.34	7,055.77	WATER WELLS

License Nb:	0	District Office S:	
POD No:	65265	Surv Map:	
POD Rec No:	46176	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-65265-/	Easting:	415412.5
Pcw Rcv Da:		Northing:	3948683.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/11/2019, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593800.0
Static Lev:	0	Y:	1702300.0
Tract Nbr:		Point Y:	35.67841968
Map Nbr:		Point X:	-105.93473665
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
172	E	0.63	3,300.05	7,205.21	WATER WELLS

License Nb:	253	District Office S:	
POD No:	33106	Surv Map:	
POD Rec No:	36804	Other Loc:	107 South Armijo Ln, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	43
Start Date:	09/10/1979, 12:00 AM	Restrict :	0.0
Finish Date:	09/20/1979, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	09/25/1979, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	150	UTM Zone:	13
Depth of Water:	64	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417390.3
Pcw Rcv Da:		Northing:	3949100.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/07/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417390.3
Static Lev:	0	Y:	3949100.7
Tract Nbr:		Point Y:	35.68234494
Map Nbr:		Point X:	-105.91292623
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
173	ESE	0.63	3,335.36	7,157.72	WATER WELLS

License Nb:	214	District Office S:	
POD No:	33748	Surv Map:	
POD Rec No:	331148	Other Loc:	1242 Canyon Road, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TB
Start Date:	01/17/1980, 12:00 AM	Restrict :	0.0
Finish Date:	01/22/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	02/07/1980, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	98	UTM Zone:	13
Depth of Water:	22	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417378.9
Pcw Rcv Da:		Northing:	3948866.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/16/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417378.9
Static Lev:	0	Y:	3948866.2
Tract Nbr:		Point Y:	35.6802299
Map Nbr:		Point X:	-105.91302812
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:	Parcel Number 1055098493440000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
174	ESE	0.64	3,387.94	7,207.33	WATER WELLS

License Nb:	0	District Office S:	
POD No:	56223	Surv Map:	
POD Rec No:	2551	Other Loc:	1243 Canyon Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417369.4
Pcw Rcv Da:		Northing:	3948769.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/19/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417369.4
Static Lev:	0	Y:	3948769.2
Tract Nbr:		Point Y:	35.67935462
Map Nbr:		Point X:	-105.91312312
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number: 1055098489437000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
175	ESE	0.64	3,394.17	7,192.65	WATER WELLS

License Nb:	214	District Office S:	
POD No:	31318	Surv Map:	
POD Rec No:	46479	Other Loc:	1243 Canyon Road, Santa Fe
POD Basin:	RG	Zone :	C

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA
Start Date:	01/16/1980, 12:00 AM	Restrict :	0.0
Finish Date:	01/18/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	02/07/1980, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	136	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	200	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417379.0
Pcw Rcv Da:		Northing:	3948793.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417379.0
Static Lev:	0	Y:	3948793.0
Tract Nbr:		Point Y:	35.67956999
Map Nbr:		Point X:	-105.91301949
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:	Parcel Number 1055098489437000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
176	WSW	0.64	3,395.81	7,077.59	WATER WELLS

License Nb:	622	District Office S:	
POD No:	87703	Surv Map:	
POD Rec No:	221255	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/21/2006, 12:00 AM	Restrict :	0.0
Finish Date:	08/23/2006, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	09/13/2006, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	EA
Depth of Well:	360	UTM Zone:	13
Depth of Water:	70	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415479.2
Pcw Rcv Da:		Northing:	3948495.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/04/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594027.0
Static Lev:	0	Y:	1701684.0
Tract Nbr:		Point Y:	35.67672513
Map Nbr:		Point X:	-105.93397986
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
177	S	0.65	3,441.34	7,222.25	WATER WELLS

License Nb:	0	District Office S:	
POD No:	47857	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	62125	Other Loc:	644 Camino Del Monte Sol
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416458.4
Pcw Rcv Da:		Northing:	3948017.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/19/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1737503.0
Static Lev:	0	Y:	1700220.0
Tract Nbr:		Point Y:	35.67250379
Map Nbr:		Point X:	-105.9231111
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Lot 7 De Vargas Subdv		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
178	SW	0.65	3,436.12	7,084.12	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	19261	Surv Map:	
POD Rec No:	52631	Other Loc:	803 Camino Atalaya
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3G 134 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415499.9
Pcw Rcv Da:		Northing:	3948445.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734340.0
Static Lev:	0	Y:	1701582.0
Tract Nbr:		Point Y:	35.67627434
Map Nbr:		Point X:	-105.93374587
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
180	E	0.65	3,443.22	7,164.76	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	32171	Surv Map:	
POD Rec No:	9616	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417427.4
Pcw Rcv Da:		Northing:	3948963.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/08/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	600400.0
Static Lev:	0	Y:	1703300.0
Tract Nbr:		Point Y:	35.68110664
Map Nbr:		Point X:	-105.91250215
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
182	W	0.65	3,448.62	7,032.60	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	30918	Surv Map:	
POD Rec No:	63677	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	S	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	12/31/1919, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	40	UTM Zone:	13
Depth of Water:	35	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:	SUBMER	XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	36.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415294.1
Pcw Rcv Da:		Northing:	3948959.7
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	04/03/2001, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593400.0
Static Lev:	0	Y:	1703200.0
Tract Nbr:		Point Y:	35.68089592
Map Nbr:		Point X:	-105.93607392
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
183	W	0.65	3,456.88	7,015.98	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	40016	Surv Map:	
POD Rec No:	335283	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	24
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415297.6
Pcw Rcv Da:		Northing:	3949233.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/25/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593400.0
Static Lev:	0	Y:	1704100.0
Tract Nbr:		Point Y:	35.68336819
Map Nbr:		Point X:	-105.93606412
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

184	E	0.66	3,468.68	7,227.77	WATER WELLS

License Nb:	622	District Office S:	
POD No:	81437	Surv Map:	
POD Rec No:	196985	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417431.1
Pcw Rcv Da:		Northing:	3949227.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/09/2012, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	600401.0
Static Lev:	0	Y:	1704167.0
Tract Nbr:	1-B	Point Y:	35.68348879
Map Nbr:		Point X:	-105.91248839
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

185	E	0.66	3,470.67	7,195.53	WATER WELLS

License Nb:	622	District Office S:	
POD No:	41873	Surv Map:	
POD Rec No:	45459	Other Loc:	1330 Cerro Gordo Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TF SF
Start Date:	05/29/1984, 12:00 AM	Restrict :	0.0
Finish Date:	05/29/1984, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	06/04/1984, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	205	UTM Zone:	13
Depth of Water:	70	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417441.9
Pcw Rcv Da:		Northing:	3949074.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/21/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1740686.0
Static Lev:	0	Y:	1703728.0
Tract Nbr:		Point Y:	35.68211216
Map Nbr:		Point X:	-105.91235336
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
186	ESE	0.67	3,525.95	7,183.77	WATER WELLS

License Nb:	0	District Office S:	
POD No:	33318	Surv Map:	
POD Rec No:	62555	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Taos
Ref :	RG-33318-/	Easting:	417425.5
Pcw Rcv Da:		Northing:	3948810.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/18/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	600400.0
Static Lev:	0	Y:	1702800.0
Tract Nbr:		Point Y:	35.67973346
Map Nbr:		Point X:	-105.91250751
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
187	S	0.67	3,556.58	7,226.07	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31701	Surv Map:	
POD Rec No:	22175	Other Loc:	664 Camino Del Monte Sol
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	9 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416475.6
Pcw Rcv Da:		Northing:	3947983.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/19/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416475.6
Static Lev:	0	Y:	3947983.5
Tract Nbr:		Point Y:	35.67219602
Map Nbr:		Point X:	-105.9229175
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		

Wells and Additional Sources Detail Report

Legal: Parcel Number 1-055-098-185-166

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	WSW	0.67	3,535.86	7,065.94	WATER WELLS

License Nb:	228	District Office S:	
POD No:	42151	Surv Map:	NA
POD Rec No:	12660	Other Loc:	460 Camino De Las Animas
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	09/28/1984, 12:00 AM	Restrict :	0.0
Finish Date:	10/01/1984, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	10/18/1984, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	80	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415407.7
Pcw Rcv Da:		Northing:	3948531.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734034.0
Static Lev:	0	Y:	1701860.0
Tract Nbr:	NA	Point Y:	35.67704084
Map Nbr:	NA	Point X:	-105.93477361
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
189	ESE	0.67	3,555.87	7,231.89	WATER WELLS

License Nb:	1173	District Office S:	
POD No:	11665	Surv Map:	
POD Rec No:	3509	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/19/1964, 12:00 AM	Restrict :	0.0
Finish Date:	08/31/1964, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/20/1965, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	286	UTM Zone:	13
Depth of Water:	118	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417289.0
Pcw Rcv Da:		Northing:	3948481.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/24/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:	C4	Point Y:	35.67674968
Map Nbr:		Point X:	-105.91398187
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant :
Legal: Tract Tr C4

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
190	W	0.67	3,560.27	7,013.27	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94886	Surv Map:	
POD Rec No:	291975	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 52B NA
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EG
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415266.2
Pcw Rcv Da:		Northing:	3949235.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/28/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	415266.2
Static Lev:	0	Y:	3949235.4
Tract Nbr:	NA	Point Y:	35.68337901
Map Nbr:	NA	Point X:	-105.93641125
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
191	ESE	0.68	3,586.72	7,247.37	WATER WELLS

License Nb:	622	District Office S:	
POD No:	66994	Surv Map:	
POD Rec No:	21806	Other Loc:	126 Canyon Rd, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1&2 9 SF
Start Date:	06/19/1997, 12:00 AM	Restrict :	0.0
Finish Date:	06/19/1997, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	06/27/1997, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417405.3
Pcw Rcv Da:		Northing:	3948686.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/10/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417405.3
Static Lev:	0	Y:	3948686.4
Tract Nbr:		Point Y:	35.67861117
Map Nbr:		Point X:	-105.91271795

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Talaya Hill/Santa Fe
Legal: Parcel Number 1055098515393000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
192	W	0.68	3,579.55	7,026.01	WATER WELLS

License Nb:	0	District Office S:	
POD No:	30918	Surv Map:	
POD Rec No:	2688	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	S-2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	12/31/1919, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	40	UTM Zone:	13
Depth of Water:	35	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	36.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415249.3
Pcw Rcv Da:		Northing:	3949036.5
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	04/03/2001, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593250.0
Static Lev:	0	Y:	1703450.0
Tract Nbr:		Point Y:	35.68158444

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.93657703
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
193	S	0.68	3,614.94	7,228.46	WATER WELLS

License Nb:	547	District Office S:	
POD No:	68415	Surv Map:	
POD Rec No:	130574	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/15/1998, 12:00 AM	Restrict :	0.0
Finish Date:	06/15/1998, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	06/24/1998, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	260	UTM Zone:	13
Depth of Water:	175	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	11	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416500.5
Pcw Rcv Da:		Northing:	3947969.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/06/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597400.0
Static Lev:	0	Y:	1700000.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.67206831
Map Nbr:		Point X:	-105.9226409
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
193	S	0.68	3,614.94	7,228.46	WATER WELLS

License Nb:	1310	District Office S:	
POD No:	68415	Surv Map:	
POD Rec No:	148509	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	X	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/09/1999, 12:00 AM	Restrict :	0.0
Finish Date:	05/12/1999, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	06/01/1999, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	540	UTM Zone:	13
Depth of Water:	130	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416500.5
Pcw Rcv Da:		Northing:	3947969.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/06/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597400.0

Wells and Additional Sources Detail Report

Static Lev:	0	Y:	1700000.0
Tract Nbr:		Point Y:	35.67206831
Map Nbr:		Point X:	-105.9226409
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
194	WSW	0.68	3,606.58	7,058.00	WATER WELLS

License Nb:	228	District Office S:	
POD No:	51218	Surv Map:	
POD Rec No:	290334	Other Loc:	See Exhibit "A" For Location
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/31/1989, 12:00 AM	Restrict :	0.0
Finish Date:	10/31/1989, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	06/29/1990, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	400	UTM Zone:	13
Depth of Water:	80	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:	SUBMER	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415350.4
Pcw Rcv Da:	07/25/1990, 12:00 AM	Northing:	3948593.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/17/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:		X:	593600.0
Static Lev:	0	Y:	1702000.0
Tract Nbr:		Point Y:	35.67759758
Map Nbr:		Point X:	-105.93541328
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
194	WSW	0.68	3,606.58	7,058.00	WATER WELLS

License Nb:	0	District Office S:	
POD No:	50456	Surv Map:	
POD Rec No:	54561	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415350.4
Pcw Rcv Da:		Northing:	3948593.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/31/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593600.0
Static Lev:	0	Y:	1702000.0
Tract Nbr:		Point Y:	35.67759758
Map Nbr:		Point X:	-105.93541328
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
195	WSW	0.68	3,614.12	7,063.25	WATER WELLS

License Nb:	214	District Office S:	
POD No:	27838	Surv Map:	SANTA FE USGS QUAD SANTA FE
POD Rec No:	53638	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/15/1977, 12:00 AM	Restrict :	0.0
Finish Date:	02/21/1977, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	02/23/1977, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	109	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	38	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415380.1
Pcw Rcv Da:		Northing:	3948532.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/08/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593700.0
Static Lev:	0	Y:	1701800.0
Tract Nbr:		Point Y:	35.67704749
Map Nbr:		Point X:	-105.93507867
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
196	S	0.69	3,652.64	7,205.50	WATER WELLS

License Nb:	1195	District Office S:	
POD No:	82610	Surv Map:	
POD Rec No:	202114	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	33 U1 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	EA
Depth of Well:	500	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416244.1
Pcw Rcv Da:		Northing:	3947951.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	04/28/2004, 12:00 AM	Latitude Second:	18.8

Wells and Additional Sources Detail Report

Subdiv Nam:	De Vargas Development Co.	Longitude Degree:	105
Surface Co:	0	Longitude Minute:	55
Ditch Name:		Longitude Second:	31.7
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6718888
Map Nbr:		Point X:	-105.92547189
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
197	E	0.69	3,636.83	7,218.43	WATER WELLS

License Nb:	622	District Office S:	
POD No:	33218	Surv Map:	
POD Rec No:	16434	Other Loc:	1320 Cerro Gordo, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	46 4 SF
Start Date:	06/23/1982, 12:00 AM	Restrict :	0.0
Finish Date:	06/23/1982, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	07/07/1982, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	150	UTM Zone:	13
Depth of Water:	60	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	7	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417488.8
Pcw Rcv Da:		Northing:	3949176.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	06/16/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417488.8
Static Lev:	0	Y:	3949176.9
Tract Nbr:		Point Y:	35.68304015
Map Nbr:		Point X:	-105.91184564
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055099514003000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
198	S	0.70	3,714.09	7,223.83	WATER WELLS

License Nb:	253	District Office S:	
POD No:	38366	Surv Map:	
POD Rec No:	36178	Other Loc:	907 Garcia Street, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 SF
Start Date:	08/16/1982, 12:00 AM	Restrict :	0.0
Finish Date:	08/18/1982, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/26/1982, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	275	UTM Zone:	13
Depth of Water:	136	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	60	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-38366-/	Easting:	416412.2
Pcw Rcv Da:		Northing:	3947930.5
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	01/21/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416412.2
Static Lev:	0	Y:	3947930.5
Tract Nbr:		Point Y:	35.67171284
Map Nbr:		Point X:	-105.92361247
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098172153000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
199	SSW	0.70	3,711.42	7,140.66	WATER WELLS

License Nb:	214	District Office S:	
POD No:	16082	Surv Map:	
POD Rec No:	70020	Other Loc:	925 Old Santa Fe Trail
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T69A SF
Start Date:	09/10/1968, 12:00 AM	Restrict :	0.0
Finish Date:	09/10/1968, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	10/17/1968, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	85	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415748.2
Pcw Rcv Da:		Northing:	3948100.9

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/02/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	8	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735169.0
Static Lev:	0	Y:	1700463.0
Tract Nbr:		Point Y:	35.67319254
Map Nbr:		Point X:	-105.93096638
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
200	ESE	0.71	3,731.04	7,244.57	WATER WELLS

License Nb:	253	District Office S:	
POD No:	34855	Surv Map:	
POD Rec No:	50448	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	D 7 SF
Start Date:	06/17/1981, 12:00 AM	Restrict :	0.0
Finish Date:	06/20/1981, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	06/30/1981, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	236	UTM Zone:	13
Depth of Water:	134	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-34855-/	Easting:	417419.8

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3948606.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/24/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1740633.0
Static Lev:	0	Y:	1702193.0
Tract Nbr:		Point Y:	35.67789567
Map Nbr:		Point X:	-105.91254957
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
201	WSW	0.71	3,745.33	7,076.38	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A2193	Surv Map:	
POD Rec No:	355653	Other Loc:	449 Camino Monte Vista
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	415381.7
Pcw Rcv Da:		Northing:	3948450.0
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	09/15/2025, 12:00 AM	Latitude Second:	34.71
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	6.19
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67630838
Map Nbr:		Point X:	-105.93505237
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
202	NNE	0.71	3,754.34	7,224.72	WATER WELLS

License Nb:	0	District Office S:	
POD No:	69688	Surv Map:	
POD Rec No:	142917	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416923.8
Pcw Rcv Da:		Northing:	3950097.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/27/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598700.0
Static Lev:	0	Y:	1707000.0
Tract Nbr:		Point Y:	35.69128854
Map Nbr:		Point X:	-105.91818391
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
203	S	0.72	3,777.15	7,212.82	WATER WELLS

License Nb:	214	District Office S:	
POD No:	31224	Surv Map:	
POD Rec No:	333096	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/11/1979, 12:00 AM	Restrict :	0.0
Finish Date:	01/16/1979, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	01/17/1979, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	370	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	60	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416271.2
Pcw Rcv Da:		Northing:	3947911.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596650.0
Static Lev:	0	Y:	1699800.0
Tract Nbr:		Point Y:	35.67152599
Map Nbr:		Point X:	-105.92516826
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
204	E	0.71	3,766.17	7,246.08	WATER WELLS

License Nb:	622	District Office S:	
POD No:	71051	Surv Map:	
POD Rec No:	146884	Other Loc:	1317b Cerro Gordo Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T1 SF
Start Date:	01/27/1999, 12:00 AM	Restrict :	0.0
Finish Date:	02/03/1999, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	02/24/1999, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	340	UTM Zone:	13
Depth of Water:	67	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M

Wells and Additional Sources Detail Report

Estimate Yield:	25	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417511.1
Pcw Rcv Da:		Northing:	3949296.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/10/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417511.1
Static Lev:	0	Y:	3949296.2
Tract Nbr:		Point Y:	35.68411754
Map Nbr:		Point X:	-105.91161147
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Numbers: 1056099009109000000, 1056099003057000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
205	SW	0.71	3,769.97	7,122.07	WATER WELLS

License Nb:	0	District Office S:	
POD No:	90099	Surv Map:	
POD Rec No:	235372	Other Loc:	Nad 27
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415590.2
Pcw Rcv Da:		Northing:	3948195.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	11/30/2018, 12:00 AM	Latitude Second:	26.5
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	55
Ditch Name:		Longitude Second:	57.8
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67402827
Map Nbr:		Point X:	-105.93272193
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
206	E	0.72	3,776.25	7,217.78	WATER WELLS

License Nb:	253	District Office S:	
POD No:	28268	Surv Map:	
POD Rec No:	35290	Other Loc:	1330a Cerro Gordo Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA1 SF
Start Date:	03/05/1977, 12:00 AM	Restrict :	0.0
Finish Date:	03/08/1977, 12:00 AM	Section:	20
Plug Date:		Township:	17N
Log File D:	03/10/1977, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	50	UTM Accura:	
Ground Water Src:	S	UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417532.8
Pcw Rcv Da:		Northing:	3949157.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/02/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1740981.0
Static Lev:	0	Y:	1704005.0
Tract Nbr:		Point Y:	35.68286984
Map Nbr:		Point X:	-105.91135747
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
207	WSW	0.72	3,806.39	7,067.08	WATER WELLS

License Nb:	228	District Office S:	
POD No:	42587	Surv Map:	
POD Rec No:	63741	Other Loc:	444 Camino De Las Animas
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/04/1984, 12:00 AM	Restrict :	0.0
Finish Date:	10/08/1984, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	03/29/1999, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	40	UTM Accura:	10

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415329.9
Pcw Rcv Da:		Northing:	3948501.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/11/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1733780.0
Static Lev:	0	Y:	1701761.0
Tract Nbr:		Point Y:	35.67677092
Map Nbr:		Point X:	-105.93563015
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
208	WSW	0.73	3,828.25	7,031.31	WATER WELLS

License Nb:	1382	District Office S:	
POD No:	81376	Surv Map:	
POD Rec No:	196558	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415196.8
Pcw Rcv Da:		Northing:	3948839.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/04/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593086.0
Static Lev:	0	Y:	1702800.0
Tract Nbr:	1	Point Y:	35.67979942
Map Nbr:		Point X:	-105.93713632
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
209	SW	0.73	3,833.52	7,083.66	WATER WELLS

License Nb:	1768	District Office S:	
POD No:	04309	Surv Map:	
POD Rec No:	307222	Other Loc:	450 Camino Monte Vista
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 3 NA SF
Start Date:	04/16/2018, 12:00 AM	Restrict :	0.0
Finish Date:	04/17/2018, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	04/20/2018, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA

Wells and Additional Sources Detail Report

Depth of Well:	360	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	45	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415383.8
Pcw Rcv Da:		Northing:	3948398.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/05/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1733961.0
Static Lev:	96	Y:	1701423.0
Tract Nbr:		Point Y:	35.67584067
Map Nbr:		Point X:	-105.93502371
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
210	WSW	0.73	3,837.86	7,062.08	WATER WELLS

License Nb:	815	District Office S:	
POD No:	51434	Surv Map:	
POD Rec No:	339032	Other Loc:	428 Camino De Las Animas
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T2/1 SF
Start Date:	07/13/1990, 12:00 AM	Restrict :	0.0
Finish Date:	07/16/1990, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	08/30/1990, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	1	UTM Source:	EA
Depth of Well:	320	UTM Zone:	13
Depth of Water:	240	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415291.5
Pcw Rcv Da:		Northing:	3948554.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/29/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415291.5
Static Lev:	0	Y:	3948554.3
Tract Nbr:		Point Y:	35.67724092
Map Nbr:		Point X:	-105.93605996
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1054098329347000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	W	0.73	3,873.21	7,025.80	WATER WELLS

License Nb:	539	District Office S:	
POD No:	50779	Surv Map:	
POD Rec No:	338812	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/10/1989, 12:00 AM	Restrict :	0.0
Finish Date:	07/12/1989, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	12/29/1989, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	100	UTM Zone:	13
Depth of Water:	30	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415171.4
Pcw Rcv Da:		Northing:	3948900.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/10/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593000.0
Static Lev:	0	Y:	1703000.0
Tract Nbr:		Point Y:	35.68034986
Map Nbr:		Point X:	-105.93742344
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
214	WSW	0.74	3,892.69	7,044.82	WATER WELLS

License Nb:	0	District Office S:	
POD No:	28254	Surv Map:	
POD Rec No:	15951	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415229.3
Pcw Rcv Da:		Northing:	3948655.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/02/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593200.0
Static Lev:	0	Y:	1702200.0
Tract Nbr:		Point Y:	35.67815062
Map Nbr:		Point X:	-105.93675791
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
215	W	0.74	3,903.08	7,010.69	WATER WELLS

License Nb:	0	District Office S:	
POD No:	30341	Surv Map:	
POD Rec No:	40682	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	01/01/1959, 12:00 AM	Section:	
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	200	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415158.7
Pcw Rcv Da:		Northing:	3949217.4
Sched Date:		Latitude Degree:	0
Use of Wel:	IRR.	Latitude Minute:	0
Sys Date:	06/20/1991, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592945.0
Static Lev:	0	Y:	1704040.0
Tract Nbr:		Point Y:	35.68320749
Map Nbr:		Point X:	-105.93759721
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
216	WSW	0.74	3,919.09	7,060.63	WATER WELLS

License Nb:	122	District Office S:	
POD No:	51434	Surv Map:	
POD Rec No:	13668	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:	08/30/1990, 12:00 AM	Range:	09E

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	170	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415258.6
Pcw Rcv Da:		Northing:	3948564.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/29/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593300.0
Static Lev:	0	Y:	1701900.0
Tract Nbr:		Point Y:	35.67732554
Map Nbr:		Point X:	-105.9364245
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
217	E	0.74	3,919.79	7,214.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35749	Surv Map:	
POD Rec No:	351493	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD 2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2-A NA NA SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	20
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417579.0
Pcw Rcv Da:		Northing:	3949092.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/01/2025, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	61703	X:	1741135.2
Static Lev:	0	Y:	1703792.3
Tract Nbr:		Point Y:	35.6822841
Map Nbr:		Point X:	-105.91084026
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
218	NW	0.75	3,939.38	7,015.56	WATER WELLS

License Nb:	0	District Office S:	
POD No:	96123	Surv Map:	
POD Rec No:	301879	Other Loc:	Dsf-06
POD Basin:	RG	Zone :	
POD Suffix:	POD8	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415395.7
Pcw Rcv Da:		Northing:	3949816.7
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	06/17/2016, 12:00 AM	Latitude Second:	19.07
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	6.15
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68863068
Map Nbr:		Point X:	-105.93504144
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
219	SW	0.74	3,928.13	7,117.10	WATER WELLS

License Nb:	547	District Office S:	
POD No:	68665	Surv Map:	
POD Rec No:	131410	Other Loc:	909 Old Santa Fe Trail
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2&3 134 SF
Start Date:	10/28/1997, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	10/29/1997, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	11/10/1997, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	95	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	28	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415509.4
Pcw Rcv Da:		Northing:	3948205.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/07/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415509.4
Static Lev:	0	Y:	3948205.2
Tract Nbr:		Point Y:	35.6741124
Map Nbr:		Point X:	-105.93361572
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1054098405240000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
220	E	0.74	3,927.61	7,197.90	WATER WELLS

License Nb:	0	District Office S:	
POD No:	21187	Surv Map:	
POD Rec No:	21074	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417580.5
Pcw Rcv Da:		Northing:	3949022.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/09/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	600900.0
Static Lev:	0	Y:	1703500.0
Tract Nbr:		Point Y:	35.68165136
Map Nbr:		Point X:	-105.91081649
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
221	SW	0.75	3,960.39	7,096.28	WATER WELLS

License Nb:	214	District Office S:	
POD No:	67599	Surv Map:	
POD Rec No:	80129	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	7 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415373.7
Pcw Rcv Da:		Northing:	3948345.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/21/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	De Vargas Development Co.	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593687.0
Static Lev:	0	Y:	1701188.0
Tract Nbr:		Point Y:	35.6753656
Map Nbr:		Point X:	-105.93512977
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
222	E	0.75	3,961.15	7,239.50	WATER WELLS

License Nb:	815	District Office S:	
POD No:	50329	Surv Map:	
POD Rec No:	60584	Other Loc:	1402 Cerro Gordo, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	41 1 SF
Start Date:	01/07/1989, 12:00 AM	Restrict :	0.0
Finish Date:	02/14/1989, 12:00 AM	Section:	20
Plug Date:		Township:	17N
Log File D:	02/23/1989, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	217	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-50329-/	Easting:	417585.1
Pcw Rcv Da:		Northing:	3949200.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/31/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417585.1
Static Lev:	0	Y:	3949200.9
Tract Nbr:		Point Y:	35.68326457
Map Nbr:		Point X:	-105.91078399
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1056099027032000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
223	SE	0.75	3,981.78	7,230.10	WATER WELLS

License Nb:	622	District Office S:	
POD No:	71206	Surv Map:	
POD Rec No:	147367	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/16/1999, 12:00 AM	Restrict :	0.0
Finish Date:	11/19/1999, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	01/03/2000, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	240	UTM Zone:	13
Depth of Water:	126	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417358.7
Pcw Rcv Da:		Northing:	3948354.4
Sched Date:		Latitude Degree:	0
Use of Wel:	ONE HOUSEHOLD	Latitude Minute:	0
Sys Date:	01/04/2000, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	600200.0
Static Lev:	0	Y:	1701300.0
Tract Nbr:		Point Y:	35.67561419
Map Nbr:		Point X:	-105.91319874
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
224	WSW	0.75	3,973.64	7,072.26	WATER WELLS

License Nb:	253	District Office S:	
POD No:	38146	Surv Map:	
POD Rec No:	42191	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/31/1982, 12:00 AM	Restrict :	0.0
Finish Date:	09/01/1982, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	09/08/1982, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	125	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	60	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415287.9
Pcw Rcv Da:		Northing:	3948472.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/30/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593400.0
Static Lev:	0	Y:	1701600.0
Tract Nbr:		Point Y:	35.67650046
Map Nbr:		Point X:	-105.93609109
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
225	SSW	0.76	3,988.11	7,179.46	WATER WELLS

License Nb:	228	District Office S:	
POD No:	50246	Surv Map:	
POD Rec No:	64655	Other Loc:	
POD Basin:	RG	Zone :	C

Wells and Additional Sources Detail Report

POD Suffix:	1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/27/1989, 12:00 AM	Restrict :	0.0
Finish Date:	05/03/1989, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/26/1989, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	440	UTM Zone:	13
Depth of Water:	110	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416042.3
Pcw Rcv Da:		Northing:	3947883.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/30/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595900.0
Static Lev:	0	Y:	1699700.0
Tract Nbr:		Point Y:	35.6712577078761
Map Nbr:		Point X:	-105.927694335246
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	JUAN DE GABALDON		
Legal:	LOT NO. 64 OF SUBDIVISION 1 OF DEVARGAS DEVELOPMENT		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
226	ESE	0.76	3,991.12	7,255.23	WATER WELLS

License Nb:	253	District Office S:	
POD No:	29273	Surv Map:	USGS 7.5' QUAD SANTA FE
POD Rec No:	49702	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/01/1978, 12:00 AM	Restrict :	0.0
Finish Date:	09/05/1978, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	09/11/1978, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	182	UTM Zone:	13
Depth of Water:	85	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	12	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417514.5
Pcw Rcv Da:		Northing:	3948626.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/27/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	600700.0
Static Lev:	0	Y:	1702200.0
Tract Nbr:		Point Y:	35.6780821
Map Nbr:		Point X:	-105.91150524
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
228	WNW	0.76	3,996.61	7,002.15	WATER WELLS

License Nb:	228	District Office S:	
POD No:	44557	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	49303	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/29/1986, 12:00 AM	Restrict :	0.0
Finish Date:	05/15/1986, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	06/26/1986, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	230	UTM Zone:	13
Depth of Water:	40	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415272.5
Pcw Rcv Da:		Northing:	3949660.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593300.0
Static Lev:	0	Y:	1705500.0
Tract Nbr:		Point Y:	35.68721553
Map Nbr:		Point X:	-105.93638646
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
229	W	0.76	4,002.05	7,027.21	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	91533	Surv Map:	
POD Rec No:	246340	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415139.4
Pcw Rcv Da:		Northing:	3948853.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	06/25/2009, 12:00 AM	Latitude Second:	47.73
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	15.98
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6799252
Map Nbr:		Point X:	-105.93777208
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
230	NW	0.76	4,028.71	7,032.22	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	253	District Office S:	
POD No:	29042	Surv Map:	
POD Rec No:	21085	Other Loc:	235 Otero St, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	20 26
Start Date:	01/24/1978, 12:00 AM	Restrict :	0.0
Finish Date:	01/27/1978, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	02/01/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	165	UTM Zone:	13
Depth of Water:	37	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415446.6
Pcw Rcv Da:		Northing:	3949917.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/07/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415446.6
Static Lev:	0	Y:	3949917.4
Tract Nbr:		Point Y:	35.68954288
Map Nbr:		Point X:	-105.93448955
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1054099378248000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
231	SSW	0.76	4,019.41	7,178.51	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	214	District Office S:	
POD No:	28950	Surv Map:	
POD Rec No:	67173	Other Loc:	1011 Old Santa Fe Trail, Sf
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	65 3B SF
Start Date:	06/27/1977, 12:00 AM	Restrict :	0.0
Finish Date:	06/29/1977, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	07/07/1977, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	356	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415999.8
Pcw Rcv Da:		Northing:	3947885.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/05/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415999.8
Static Lev:	0	Y:	3947885.8
Tract Nbr:		Point Y:	35.67127482
Map Nbr:		Point X:	-105.92816413
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098033131000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
232	E	0.76	4,023.92	7,234.75	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	622	District Office S:	
POD No:	34699	Surv Map:	
POD Rec No:	15787	Other Loc:	1402 Cerro Gordo Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2B
Start Date:	02/10/1981, 12:00 AM	Restrict :	0.0
Finish Date:	02/10/1981, 12:00 AM	Section:	20
Plug Date:		Township:	17N
Log File D:	02/19/1981, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	260	UTM Zone:	13
Depth of Water:	130	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417607.9
Pcw Rcv Da:		Northing:	3949164.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/07/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1741227.0
Static Lev:	0	Y:	1704031.0
Tract Nbr:		Point Y:	35.68293923
Map Nbr:		Point X:	-105.91052834
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

233	W	0.77	4,049.84	7,027.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91534	Surv Map:	
POD Rec No:	246341	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415127.9
Pcw Rcv Da:		Northing:	3948839.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	06/25/2009, 12:00 AM	Latitude Second:	47.26
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	16.43
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67979439
Map Nbr:		Point X:	-105.93789763
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

234	SSW	0.77	4,060.01	7,172.42	WATER WELLS

License Nb:	547	District Office S:	
POD No:	66039	Surv Map:	
POD Rec No:	20920	Other Loc:	711 Camino Corrales, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	66 SF
Start Date:	08/22/1997, 12:00 AM	Restrict :	0.0
Finish Date:	08/26/1997, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	09/08/1997, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	126	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	27	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415894.4
Pcw Rcv Da:		Northing:	3947908.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/09/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415894.4
Static Lev:	0	Y:	3947908.0
Tract Nbr:		Point Y:	35.67146598
Map Nbr:		Point X:	-105.92933093
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098011154000000		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
235	W	0.77	4,054.08	7,026.27	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	343503	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD13	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415122.1
Pcw Rcv Da:		Northing:	3948859.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/26/2023, 12:00 AM	Latitude Second:	47.92
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	16.67
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6799778
Map Nbr:		Point X:	-105.93796387
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
236	S	0.77	4,087.06	7,227.32	WATER WELLS

License Nb:	1310	District Office S:	
POD No:	70505	Surv Map:	
POD Rec No:	145138	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/28/1998, 12:00 AM	Restrict :	0.0
Finish Date:	12/04/1998, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/27/1999, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	420	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416437.6
Pcw Rcv Da:		Northing:	3947817.6
Sched Date:		Latitude Degree:	0
Use of Wel:	COND 9	Latitude Minute:	0
Sys Date:	04/29/1999, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597200.0
Static Lev:	0	Y:	1699500.0
Tract Nbr:		Point Y:	35.67069717
Map Nbr:		Point X:	-105.92332012
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
237	WSW	0.77	4,071.35	7,033.50	WATER WELLS

License Nb:	0	District Office S:	
POD No:	99395	Surv Map:	
POD Rec No:	330690	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415142.3
Pcw Rcv Da:		Northing:	3948747.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/11/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1733154.0
Static Lev:	0	Y:	1702560.0
Tract Nbr:		Point Y:	35.67897164
Map Nbr:		Point X:	-105.93772888
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant :

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
238	W	0.77	4,070.68	7,025.94	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	343502	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD12	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415117.8
Pcw Rcv Da:		Northing:	3948856.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/26/2023, 12:00 AM	Latitude Second:	47.82
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	16.84
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67995038
Map Nbr:		Point X:	-105.93801107
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
239	E	0.77	4,073.49	7,213.20	WATER WELLS

License Nb:	622	District Office S:	
POD No:	35749	Surv Map:	
POD Rec No:	16232	Other Loc:	1400 Cerro Gordo Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2B NA NA SF
Start Date:	05/20/1981, 12:00 AM	Restrict :	0.0
Finish Date:	05/21/1981, 12:00 AM	Section:	20
Plug Date:		Township:	17N
Log File D:	05/23/1981, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	65	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417626.0
Pcw Rcv Da:		Northing:	3949054.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/01/2025, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Rio De Santa Fe	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1741291.0
Static Lev:	0	Y:	1703670.0
Tract Nbr:		Point Y:	35.68194725
Map Nbr:		Point X:	-105.91031705
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
240	W	0.77	4,073.53	7,025.94	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91532	Surv Map:	
POD Rec No:	246336	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415115.8
Pcw Rcv Da:		Northing:	3948861.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	06/25/2009, 12:00 AM	Latitude Second:	47.97
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	16.92
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67999168
Map Nbr:		Point X:	-105.93803365

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
240	W	0.77	4,073.53	7,025.29	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91532	Surv Map:	
POD Rec No:	271064	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415115.8
Pcw Rcv Da:		Northing:	3948861.7
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	03/29/2012, 12:00 AM	Latitude Second:	47.99
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	16.92
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67999709

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.93803371
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
241	W	0.78	4,096.95	7,025.19	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	343505	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD15	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415109.3
Pcw Rcv Da:		Northing:	3948856.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/26/2023, 12:00 AM	Latitude Second:	47.82
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.18
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.67994965
Map Nbr:		Point X:	-105.93810499
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
242	W	0.78	4,098.19	7,025.03	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	343504	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD14	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415108.3
Pcw Rcv Da:		Northing:	3948863.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/26/2023, 12:00 AM	Latitude Second:	48.06
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.22
Well Tag:	NA	X:	0.0

Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68001628
Map Nbr:		Point X:	-105.93811682
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
243	W	0.78	4,101.01	7,025.99	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	343506	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD16	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415109.7
Pcw Rcv Da:		Northing:	3948849.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/26/2023, 12:00 AM	Latitude Second:	47.59
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.16

Wells and Additional Sources Detail Report

Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67988658
Map Nbr:		Point X:	-105.93809983
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
244	WSW	0.78	4,110.11	7,075.26	WATER WELLS

License Nb:	214	District Office S:	
POD No:	27930	Surv Map:	USGS 7.5' QUAD SANTA FE
POD Rec No:	16097	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/23/1978, 12:00 AM	Restrict :	0.0
Finish Date:	02/06/1978, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	02/16/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	335	UTM Zone:	13
Depth of Water:	72	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415257.0
Pcw Rcv Da:		Northing:	3948442.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/28/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593300.0
Static Lev:	0	Y:	1701500.0
Tract Nbr:		Point Y:	35.67622645
Map Nbr:		Point X:	-105.93642934
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
245	W	0.78	4,109.52	7,026.16	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	343507	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD17	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415108.6
Pcw Rcv Da:		Northing:	3948841.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/26/2023, 12:00 AM	Latitude Second:	47.32
Subdiv Nam:		Longitude Degree:	105

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.2
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67981076
Map Nbr:		Point X:	-105.9381111
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
246	W	0.78	4,111.93	7,024.45	WATER WELLS

License Nb:	1522	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	327368	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD8	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/09/2020, 12:00 AM	Restrict :	0.0
Finish Date:	07/11/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/17/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	60	UTM Zone:	13
Depth of Water:	43	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415102.9
Pcw Rcv Da:		Northing:	3948871.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	04/27/2022, 12:00 AM	Latitude Second:	48.29

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.44
Well Tag:	NA	X:	0.0
Static Lev:	43	Y:	0.0
Tract Nbr:		Point Y:	35.68008072
Map Nbr:		Point X:	-105.93817724
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
247	SW	0.78	4,117.24	7,118.41	WATER WELLS

License Nb:	228	District Office S:	
POD No:	31517	Surv Map:	
POD Rec No:	29206	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7A SF
Start Date:	02/21/1979, 12:00 AM	Restrict :	0.0
Finish Date:	02/21/1979, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	03/02/1979, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	EA
Depth of Well:	140	UTM Zone:	13
Depth of Water:	15	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	22	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415466.8
Pcw Rcv Da:		Northing:	3948165.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	10/28/2019, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Heights	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	594000.0
Static Lev:	0	Y:	1700600.0
Tract Nbr:		Point Y:	35.67374724
Map Nbr:		Point X:	-105.93408217
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
248	W	0.78	4,117.37	7,024.45	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	291430	Other Loc:	Mw-7, 600 Old Santa Fe Trail
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	MW-7	Subdiv Loc:	
Start Date:	07/14/2014, 12:00 AM	Restrict :	0.0
Finish Date:	07/15/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/05/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	50	UTM Zone:	13
Depth of Water:	46	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415101.6
Pcw Rcv Da:		Northing:	3948866.2
Sched Date:		Latitude Degree:	35

Wells and Additional Sources Detail Report

Use of Wel:	MON	Latitude Minute:	40
Sys Date:	10/02/2018, 12:00 AM	Latitude Second:	48.13
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.49
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68003644
Map Nbr:		Point X:	-105.93819109
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
248	W	0.78	4,117.37	7,024.45	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	291429	Other Loc:	Mw-6
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	MW-6	Subdiv Loc:	
Start Date:	07/14/2014, 12:00 AM	Restrict :	0.0
Finish Date:	07/15/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/05/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	50	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415101.6
Pcw Rcv Da:		Northing:	3948866.2

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	35
Use of Wel:	MON	Latitude Minute:	40
Sys Date:	10/09/2019, 12:00 AM	Latitude Second:	48.13
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.49
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68003644
Map Nbr:		Point X:	-105.93819109
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
249	SW	0.78	4,120.96	7,109.24	WATER WELLS

License Nb:	0	District Office S:	
POD No:	33565	Surv Map:	
POD Rec No:	56428	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415406.6

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3948226.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593800.0
Static Lev:	0	Y:	1700800.0
Tract Nbr:		Point Y:	35.67429922
Map Nbr:		Point X:	-105.9347538
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
250	W	0.78	4,122.67	7,025.15	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	343501	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD11	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	415104.6
Pcw Rcv Da:		Northing:	3948843.0
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/26/2023, 12:00 AM	Latitude Second:	47.38
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.36
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67982754
Map Nbr:		Point X:	-105.93815549
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
251	W	0.78	4,128.40	7,024.39	WATER WELLS

License Nb:	1522	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	327367	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD7	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/07/2020, 12:00 AM	Restrict :	0.0
Finish Date:	07/08/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/17/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	50	UTM Zone:	13
Depth of Water:	43	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415100.2
Pcw Rcv Da:		Northing:	3948857.2
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	04/27/2022, 12:00 AM	Latitude Second:	47.84
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.54
Well Tag:	NA	X:	0.0
Static Lev:	43	Y:	0.0
Tract Nbr:		Point Y:	35.67995518
Map Nbr:		Point X:	-105.93820561
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
252	W	0.78	4,131.73	7,024.39	WATER WELLS

License Nb:	1522	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	327370	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD10	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/14/2020, 12:00 AM	Restrict :	0.0
Finish Date:	07/15/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/17/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	50	UTM Zone:	13
Depth of Water:	43	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415099.9
Pcw Rcv Da:		Northing:	3948852.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	04/27/2022, 12:00 AM	Latitude Second:	47.69
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.55
Well Tag:	NA	X:	0.0
Static Lev:	43	Y:	0.0
Tract Nbr:		Point Y:	35.67991368
Map Nbr:		Point X:	-105.93820844
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
253	W	0.78	4,133.77	7,025.15	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	291431	Other Loc:	Mw-8
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	MW-8	Subdiv Loc:	
Start Date:	07/14/2014, 12:00 AM	Restrict :	0.0
Finish Date:	07/15/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/05/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	50	UTM Zone:	13
Depth of Water:	40	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415099.6
Pcw Rcv Da:		Northing:	3948849.2
Sched Date:		Latitude Degree:	35
Use of Wel:	MON	Latitude Minute:	40
Sys Date:	10/09/2019, 12:00 AM	Latitude Second:	47.58
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.56
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67988301
Map Nbr:		Point X:	-105.9382114
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
253	W	0.78	4,133.77	7,025.15	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91532	Surv Map:	
POD Rec No:	271096	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415099.6
Pcw Rcv Da:		Northing:	3948849.2
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	03/30/2012, 12:00 AM	Latitude Second:	47.58
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.56
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67988301
Map Nbr:		Point X:	-105.9382114
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
254	W	0.79	4,155.20	7,023.53	WATER WELLS

License Nb:	1522	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	327369	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD9	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/12/2020, 12:00 AM	Restrict :	0.0
Finish Date:	07/13/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/17/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	50	UTM Zone:	13
Depth of Water:	43	UTM Accura:	
Ground Water Src:	S	UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415089.0
Pcw Rcv Da:		Northing:	3948872.8
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	04/27/2022, 12:00 AM	Latitude Second:	48.34
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.99
Well Tag:	NA	X:	0.0
Static Lev:	43	Y:	0.0
Tract Nbr:		Point Y:	35.68009485
Map Nbr:		Point X:	-105.93833101
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
255	W	0.79	4,159.17	7,022.71	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	305087	Other Loc:	Mw-11
POD Basin:	RG	Zone :	
POD Suffix:	POD6	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/03/2017, 12:00 AM	Restrict :	0.0
Finish Date:	02/04/2017, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	02/21/2017, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	50	UTM Zone:	13
Depth of Water:	35	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415086.9
Pcw Rcv Da:		Northing:	3948880.8
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/09/2019, 12:00 AM	Latitude Second:	48.6
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	18.08
Well Tag:		X:	0.0
Static Lev:	35	Y:	0.0
Tract Nbr:		Point Y:	35.68016679
Map Nbr:		Point X:	-105.93835506
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
256	SW	0.79	4,182.77	7,118.69	WATER WELLS

License Nb:	0	District Office S:	
POD No:	48630	Surv Map:	
POD Rec No:	163069	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	S	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	06
Plug Date:		Township:	16N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415454.4
Pcw Rcv Da:		Northing:	3948150.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/01/2000, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593960.0
Static Lev:	0	Y:	1700550.0
Tract Nbr:		Point Y:	35.67361095
Map Nbr:		Point X:	-105.9342176
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
257	WSW	0.79	4,190.09	7,085.71	WATER WELLS

License Nb:	547	District Office S:	
POD No:	68724	Surv Map:	
POD Rec No:	139844	Other Loc:	832 Old Pecos Trl, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:	10/25/1999, 12:00 AM	Restrict :	0.0
Finish Date:	10/27/1999, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	10/29/1999, 12:00 AM	Range:	04E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA

Wells and Additional Sources Detail Report

Depth of Well:	400	UTM Zone:	13
Depth of Water:	149	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	37	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415277.7
Pcw Rcv Da:		Northing:	3948361.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/12/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415277.7
Static Lev:	0	Y:	3948361.0
Tract Nbr:		Point Y:	35.6754971
Map Nbr:		Point X:	-105.93619209
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1054098322296000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
258	WNW	0.80	4,198.96	6,998.35	WATER WELLS

License Nb:	0	District Office S:	
POD No:	96123	Surv Map:	
POD Rec No:	301873	Other Loc:	Dsf-02a
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415204.7
Pcw Rcv Da:		Northing:	3949665.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	06/17/2016, 12:00 AM	Latitude Second:	14.09
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	13.69
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68724756
Map Nbr:		Point X:	-105.93713612
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
259	WSW	0.80	4,201.32	7,054.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	81960	Surv Map:	
POD Rec No:	199573	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415161.4
Pcw Rcv Da:		Northing:	3948572.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/13/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592981.0
Static Lev:	0	Y:	1701923.0
Tract Nbr:		Point Y:	35.67739111
Map Nbr:		Point X:	-105.93749933
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
260	SW	0.80	4,210.32	7,095.27	WATER WELLS

License Nb:	547	District Office S:	
POD No:	68359	Surv Map:	
POD Rec No:	105647	Other Loc:	844 Old Santa Fe Trail
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	5 128 SF
Start Date:	10/14/1997, 12:00 AM	Restrict :	0.0
Finish Date:	10/15/1997, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	10/27/1997, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	150	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415307.3
Pcw Rcv Da:		Northing:	3948307.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/05/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415307.3
Static Lev:	0	Y:	3948307.4
Tract Nbr:		Point Y:	35.67501642
Map Nbr:		Point X:	-105.9358594
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
261	E	0.80	4,229.55	7,204.51	WATER WELLS

License Nb:	672	District Office S:	
POD No:	81437	Surv Map:	
POD Rec No:	275742	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1B NA NA
Start Date:	04/01/2013, 12:00 AM	Restrict :	0.0
Finish Date:	04/05/2013, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/26/2013, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	140	UTM Zone:	13
Depth of Water:	48	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	205	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417672.6
Pcw Rcv Da:		Northing:	3949028.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/14/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1741445.0
Static Lev:	0	Y:	1703586.1
Tract Nbr:		Point Y:	35.68171495
Map Nbr:		Point X:	-105.90979945
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
262	ENE	0.81	4,252.56	7,315.96	WATER WELLS

License Nb:	0	District Office S:	
POD No:	50567	Surv Map:	
POD Rec No:	32449	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417616.8
Pcw Rcv Da:		Northing:	3949478.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/15/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	601000.0
Static Lev:	0	Y:	1705000.0
Tract Nbr:		Point Y:	35.68577167
Map Nbr:		Point X:	-105.91046217
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
263	SSW	0.81	4,264.60	7,189.20	WATER WELLS

License Nb:	228	District Office S:	
POD No:	50246	Surv Map:	
POD Rec No:	28075	Other Loc:	1021 Old Santa Fe Trail
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	64 3 U1 SF
Start Date:	04/27/1989, 12:00 AM	Restrict :	0.0
Finish Date:	05/03/1989, 12:00 AM	Section:	30
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:	05/09/1989, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	440	UTM Zone:	13
Depth of Water:	110	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416080.3
Pcw Rcv Da:		Northing:	3947788.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/07/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736272.0
Static Lev:	0	Y:	1699450.0
Tract Nbr:		Point Y:	35.67039999
Map Nbr:		Point X:	-105.92726454
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Lot No. 64 Of Subdivision Number One Of De Vargas Development Co.		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
264	NW	0.81	4,277.41	7,003.98	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	96123	Surv Map:	
POD Rec No:	301876	Other Loc:	Dsf-04
POD Basin:	RG	Zone :	
POD Suffix:	POD5	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/26/2016, 12:00 AM	Restrict :	0.0
Finish Date:	06/26/2016, 12:00 AM	Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:	05/07/2018, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	29	UTM Zone:	13
Depth of Water:	24	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415275.9
Pcw Rcv Da:		Northing:	3949828.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/19/2018, 12:00 AM	Latitude Second:	19.41
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	10.92
Well Tag:		X:	0.0
Static Lev:	19	Y:	0.0
Tract Nbr:		Point Y:	35.68872497
Map Nbr:		Point X:	-105.93636653
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
265	ESE	0.81	4,265.89	7,219.90	WATER WELLS

License Nb:	547	District Office S:	
POD No:	67227	Surv Map:	
POD Rec No:	8265	Other Loc:	1330 Canyon Rd, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TIIA SF
Start Date:	03/26/1997, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	03/26/1997, 12:00 AM	Section:	29
Plug Date:		Township:	17N
Log File D:	04/04/1997, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	140	UTM Zone:	13
Depth of Water:	32	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	14	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417647.3
Pcw Rcv Da:		Northing:	3948769.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/15/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417647.3
Static Lev:	0	Y:	3948769.5
Tract Nbr:		Point Y:	35.67938058
Map Nbr:		Point X:	-105.91005252
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:	Parcel Number 1056098060441000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
266	E	0.81	4,263.57	7,274.11	WATER WELLS

License Nb:	622	District Office S:	
POD No:	46187	Surv Map:	
POD Rec No:	8603	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:	08/07/1986, 12:00 AM	Restrict :	0.0
Finish Date:	08/08/1986, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/25/1986, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	280	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	38	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417674.7
Pcw Rcv Da:		Northing:	3949234.2
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	12/23/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	601200.0
Static Lev:	0	Y:	1704200.0
Tract Nbr:		Point Y:	35.68357227
Map Nbr:		Point X:	-105.90979733
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
267	SSW	0.81	4,294.35	7,182.94	WATER WELLS

License Nb:	547	District Office S:	
POD No:	90099	Surv Map:	
POD Rec No:	241491	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:	11/14/2013, 12:00 AM	Restrict :	0.0
Finish Date:	11/15/2013, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/30/2013, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	400	UTM Zone:	13
Depth of Water:	110	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	8	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415951.1
Pcw Rcv Da:		Northing:	3947812.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	02/04/2014, 12:00 AM	Latitude Second:	14.2
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	55
Ditch Name:		Longitude Second:	43.3
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67061076
Map Nbr:		Point X:	-105.92869453
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
268	WSW	0.82	4,325.12	7,056.83	WATER WELLS

License Nb:	622	District Office S:	
POD No:	71054	Surv Map:	
POD Rec No:	146887	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	280	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415136.3
Pcw Rcv Da:		Northing:	3948535.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/10/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592900.0
Static Lev:	0	Y:	1701800.0
Tract Nbr:		Point Y:	35.67705449
Map Nbr:		Point X:	-105.93777275
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
269	WNW	0.82	4,351.81	6,995.10	WATER WELLS

License Nb:	0	District Office S:	
POD No:	96123	Surv Map:	
POD Rec No:	301874	Other Loc:	Dsf-02b
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0

Wells and Additional Sources Detail Report

POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415105.1
Pcw Rcv Da:		Northing:	3949558.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	06/17/2016, 12:00 AM	Latitude Second:	10.6
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.61
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68627797
Map Nbr:		Point X:	-105.93822549
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
270	SE	0.83	4,387.36	7,291.09	WATER WELLS

License Nb:	0	District Office S:	
POD No:	44384	Surv Map:	
POD Rec No:	48299	Other Loc:	700 Camino Cabra
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417225.1
Pcw Rcv Da:		Northing:	3948038.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Armstrong	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1740018.0
Static Lev:	0	Y:	1700319.0
Tract Nbr:		Point Y:	35.67275235
Map Nbr:		Point X:	-105.91464235
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
271	WNW	0.83	4,400.84	6,996.12	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	96123	Surv Map:	
POD Rec No:	301872	Other Loc:	Dsf-01
POD Basin:	RG	Zone :	

Wells and Additional Sources Detail Report

POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/23/2016, 12:00 AM	Restrict :	0.0
Finish Date:	06/23/2016, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/07/2018, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	35	UTM Zone:	13
Depth of Water:	27	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415165.0
Pcw Rcv Da:		Northing:	3949722.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/19/2018, 12:00 AM	Latitude Second:	15.93
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	15.29
Well Tag:		X:	0.0
Static Lev:	20	Y:	0.0
Tract Nbr:		Point Y:	35.68775801
Map Nbr:		Point X:	-105.93758084
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
272	WNW	0.84	4,412.47	6,996.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	95469	Surv Map:	
POD Rec No:	297680	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:	POD4	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415180.2
Pcw Rcv Da:		Northing:	3949755.0
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	08/06/2015, 12:00 AM	Latitude Second:	17.0
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	14.7
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68805592
Map Nbr:		Point X:	-105.93741634
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
273	SE	0.85	4,471.05	7,262.53	WATER WELLS

License Nb:	0	District Office S:	
POD No:	44385	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	9399	Other Loc:	704 Camino Cabra
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2A SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417285.4
Pcw Rcv Da:		Northing:	3948055.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Armstrong	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1740215.0
Static Lev:	0	Y:	1700378.0
Tract Nbr:		Point Y:	35.67291247
Map Nbr:		Point X:	-105.91397789
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
274	SE	0.85	4,482.34	7,316.32	WATER WELLS

License Nb:	253	District Office S:	

Wells and Additional Sources Detail Report

POD No:	35536	Surv Map:	
POD Rec No:	24079	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/10/1981, 12:00 AM	Restrict :	0.0
Finish Date:	04/13/1981, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/24/1981, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	450	UTM Zone:	13
Depth of Water:	106	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	70	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417170.8
Pcw Rcv Da:		Northing:	3947960.6
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	06/18/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	599600.0
Static Lev:	0	Y:	1700000.0
Tract Nbr:		Point Y:	35.67204821
Map Nbr:		Point X:	-105.91523429
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
275	ESE	0.85	4,465.78	7,266.12	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	622	District Office S:	
POD No:	65480	Surv Map:	
POD Rec No:	30009	Other Loc:	535 Camino Militar, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T3 SF
Start Date:	08/16/1996, 12:00 AM	Restrict :	0.0
Finish Date:	08/16/1996, 12:00 AM	Section:	29
Plug Date:		Township:	17N
Log File D:	08/23/1996, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	320	UTM Zone:	13
Depth of Water:	150	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417612.9
Pcw Rcv Da:		Northing:	3948492.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Hedden	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417612.9
Static Lev:	0	Y:	3948492.1
Tract Nbr:		Point Y:	35.67687687
Map Nbr:		Point X:	-105.91040421
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:	Parcel Number 1056098033442000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
276	W	0.85	4,461.93	7,001.47	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	214	District Office S:	
POD No:	32605	Surv Map:	
POD Rec No:	31947	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/20/1979, 12:00 AM	Restrict :	0.0
Finish Date:	07/26/1979, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/06/1979, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	240	UTM Zone:	13
Depth of Water:	205	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	35	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414993.2
Pcw Rcv Da:		Northing:	3949268.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/14/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592400.0
Static Lev:	0	Y:	1704200.0
Tract Nbr:		Point Y:	35.68365211
Map Nbr:		Point X:	-105.93943134
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
277	ESE	0.85	4,471.49	7,262.37	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	228	District Office S:	
POD No:	23727	Surv Map:	
POD Rec No:	21964	Other Loc:	1300 Canyon Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	39 SF
Start Date:	07/24/1973, 12:00 AM	Restrict :	0.0
Finish Date:	08/20/1973, 12:00 AM	Section:	29
Plug Date:		Township:	17N
Log File D:	08/29/1973, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	560	UTM Zone:	13
Depth of Water:	45	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417658.2
Pcw Rcv Da:		Northing:	3948594.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/01/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1741416.0
Static Lev:	0	Y:	1702162.0
Tract Nbr:		Point Y:	35.67780291
Map Nbr:		Point X:	-105.90991416
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

278	ESE	0.85	4,476.22	7,258.73	WATER WELLS

License Nb:	1442	District Office S:	
POD No:	71197	Surv Map:	
POD Rec No:	158206	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	CLW180317	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	CLW	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	12/01/1999, 12:00 AM	Restrict :	0.0
Finish Date:	01/04/2000, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	01/12/2000, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	277	UTM Zone:	13
Depth of Water:	180	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	147427/RG-71197-/	Easting:	417635.3
Pcw Rcv Da:		Northing:	3948533.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/30/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	601100.0
Static Lev:	0	Y:	1701900.0
Tract Nbr:		Point Y:	35.67725377
Map Nbr:		Point X:	-105.91016097
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

278	ESE	0.85	4,476.22	7,258.73	WATER WELLS

License Nb:	1310	District Office S:	
POD No:	71197	Surv Map:	
POD Rec No:	147427	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/28/2003, 12:00 AM	Restrict :	0.0
Finish Date:	04/30/2003, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/01/2003, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	620	UTM Zone:	13
Depth of Water:	85	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417635.3
Pcw Rcv Da:		Northing:	3948533.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/30/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	601100.0
Static Lev:	0	Y:	1701900.0
Tract Nbr:		Point Y:	35.67725377
Map Nbr:		Point X:	-105.91016097
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
279	S	0.85	4,501.71	7,202.19	WATER WELLS

License Nb:	548	District Office S:	
POD No:	57886	Surv Map:	
POD Rec No:	61848	Other Loc:	1047 Old Santa Fe Trail
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	63 2 SF
Start Date:	03/23/1995, 12:00 AM	Restrict :	0.0
Finish Date:	03/26/1995, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	04/06/1995, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	380	UTM Zone:	13
Depth of Water:	105	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	35	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416108.6
Pcw Rcv Da:		Northing:	3947708.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/06/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736368.0
Static Lev:	0	Y:	1699191.0
Tract Nbr:		Point Y:	35.66968748
Map Nbr:		Point X:	-105.92694362
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
280	S	0.85	4,507.77	7,213.09	WATER WELLS

License Nb:	547	District Office S:	
POD No:	65135	Surv Map:	
POD Rec No:	37909	Other Loc:	1050 Camino Rancheros
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	64 2-4 SF
Start Date:	08/24/1998, 12:00 AM	Restrict :	0.0
Finish Date:	08/25/1998, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/31/1998, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	380	UTM Zone:	13
Depth of Water:	168	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	7	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416267.8
Pcw Rcv Da:		Northing:	3947688.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/22/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416267.8
Static Lev:	0	Y:	3947688.3
Tract Nbr:		Point Y:	35.6695171
Map Nbr:		Point X:	-105.92518265
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		

Wells and Additional Sources Detail Report

Legal: Parcel Number 1055098121066000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
281	WSW	0.86	4,531.51	7,054.96	WATER WELLS

License Nb:	622	District Office S:	
POD No:	34614	Surv Map:	
POD Rec No:	52864	Other Loc:	321 E Berger
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	11** 109 TB SF
Start Date:	07/15/1980, 12:00 AM	Restrict :	0.0
Finish Date:	07/15/1980, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	07/24/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	340	UTM Zone:	13
Depth of Water:	110	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415082.8
Pcw Rcv Da:		Northing:	3948501.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/06/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Buena Vista	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1732969.0
Static Lev:	0	Y:	1701748.0
Tract Nbr:		Point Y:	35.67674246
Map Nbr:		Point X:	-105.93836027
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
282	S	0.87	4,571.86	7,221.94	WATER WELLS

License Nb:	0	District Office S:	
POD No:	59723	Surv Map:	
POD Rec No:	57856	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416344.3
Pcw Rcv Da:		Northing:	3947666.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/07/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596900.0
Static Lev:	0	Y:	1699000.0
Tract Nbr:		Point Y:	35.66932616
Map Nbr:		Point X:	-105.9243352
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
283	SSW	0.87	4,571.00	7,169.49	WATER WELLS

License Nb:	622	District Office S:	
POD No:	33678	Surv Map:	
POD Rec No:	6470	Other Loc:	1006 Old Santa Fe Trail
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	82 SF
Start Date:	01/22/1980, 12:00 AM	Restrict :	0.0
Finish Date:	01/23/1980, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	01/30/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	460	UTM Zone:	13
Depth of Water:	70	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415811.7
Pcw Rcv Da:		Northing:	3947774.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/29/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	De Vargas Development Co.	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415811.7
Static Lev:	0	Y:	3947774.0
Tract Nbr:		Point Y:	35.67025088
Map Nbr:		Point X:	-105.93023061
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc:	Rio Grande
POD Sub Basin Desc:	Santa Fe River
Grant :	Santa Fe
Legal:	Parcel Number 1054098508109000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
284	NW	0.87	4,584.41	7,001.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	96123	Surv Map:	
POD Rec No:	301877	Other Loc:	Dsf-05a
POD Basin:	RG	Zone :	
POD Suffix:	POD6	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415217.3
Pcw Rcv Da:		Northing:	3949907.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	06/17/2016, 12:00 AM	Latitude Second:	21.95
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	13.28
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68943032
Map Nbr:		Point X:	-105.9370224

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
285	W	0.86	4,566.10	7,012.71	WATER WELLS

License Nb:	0	District Office S:	
POD No:	73396	Surv Map:	
POD Rec No:	155871	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	200	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.58	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414958.1
Pcw Rcv Da:		Northing:	3948903.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/23/2000, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592300.0
Static Lev:	0	Y:	1703000.0
Tract Nbr:		Point Y:	35.68035583

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.93978057
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
286	ESE	0.87	4,580.33	7,277.67	WATER WELLS

License Nb:	122	District Office S:	
POD No:	36585	Surv Map:	
POD Rec No:	24956	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	01/01/1960, 12:00 AM	Section:	29
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	125	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417591.0
Pcw Rcv Da:		Northing:	3948376.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/11/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.67582836
Map Nbr:		Point X:	-105.9106343
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
287	WNW	0.87	4,577.85	6,987.06	WATER WELLS

License Nb:	214	District Office S:	
POD No:	35065	Surv Map:	
POD Rec No:	58504	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/16/1980, 12:00 AM	Restrict :	0.0
Finish Date:	09/18/1980, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	09/29/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	243	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	23	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414995.6
Pcw Rcv Da:		Northing:	3949451.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/15/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592400.0

Wells and Additional Sources Detail Report

Static Lev:	0	Y:	1704800.0
Tract Nbr:		Point Y:	35.6853003
Map Nbr:		Point X:	-105.93942414
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
288	SW	0.87	4,581.57	7,105.63	WATER WELLS

License Nb:	0	District Office S:	
POD No:	32610	Surv Map:	
POD Rec No:	58529	Other Loc:	1001 Old Pecos Trail
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	500	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415309.6
Pcw Rcv Da:		Northing:	3948124.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/15/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:	NA	X:	1733729.0
Static Lev:	0	Y:	1700522.0
Tract Nbr:		Point Y:	35.67336773
Map Nbr:		Point X:	-105.93581474
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
289	SE	0.88	4,628.76	7,280.56	WATER WELLS

License Nb:	0	District Office S:	
POD No:	44386	Surv Map:	
POD Rec No:	70853	Other Loc:	720 Camino Cabra
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2B SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417289.2
Pcw Rcv Da:		Northing:	3947995.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Armstrong	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1740230.0
Static Lev:	0	Y:	1700180.0
Tract Nbr:		Point Y:	35.67236827
Map Nbr:		Point X:	-105.9139297
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
290	NW	0.87	4,619.08	6,998.95	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	96123	Surv Map:	
POD Rec No:	301878	Other Loc:	Dsf-05b
POD Basin:	RG	Zone :	
POD Suffix:	POD7	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/24/2016, 12:00 AM	Restrict :	0.0
Finish Date:	06/24/2016, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/17/2018, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	28	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415190.0
Pcw Rcv Da:		Northing:	3949887.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/19/2018, 12:00 AM	Latitude Second:	21.29
Subdiv Nam:		Longitude Degree:	105

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	14.36
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68924767
Map Nbr:		Point X:	-105.93732198
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
291	SE	0.88	4,644.68	7,328.23	WATER WELLS

License Nb:	253	District Office S:	
POD No:	40259	Surv Map:	
POD Rec No:	28562	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/09/1983, 12:00 AM	Restrict :	0.0
Finish Date:	09/10/1983, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	09/14/1983, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	137	UTM Zone:	13
Depth of Water:	35	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417170.1
Pcw Rcv Da:		Northing:	3947899.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/28/2022, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	599600.0
Static Lev:	0	Y:	1699800.0
Tract Nbr:		Point Y:	35.67149912
Map Nbr:		Point X:	-105.91523576
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Sebastian De Vargas		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
293	ESE	0.88	4,641.80	7,303.95	WATER WELLS

License Nb:	0	District Office S:	
POD No:	62631	Surv Map:	
POD Rec No:	66581	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417759.9
Pcw Rcv Da:		Northing:	3948745.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	09/27/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	601500.0
Static Lev:	0	Y:	1702600.0
Tract Nbr:		Point Y:	35.67917361
Map Nbr:		Point X:	-105.9088059
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
294	SSW	0.88	4,653.06	7,202.09	WATER WELLS

License Nb:	0	District Office S:	
POD No:	71142	Surv Map:	
POD Rec No:	147121	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416070.0
Pcw Rcv Da:		Northing:	3947669.9
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	12/28/1998, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596000.0
Static Lev:	0	Y:	1699000.0
Tract Nbr:		Point Y:	35.66933441
Map Nbr:		Point X:	-105.92736602
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
295	SW	0.88	4,650.53	7,136.35	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31143	Surv Map:	
POD Rec No:	324797	Other Loc:	620 Barcelona Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	29 A SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415559.0
Pcw Rcv Da:		Northing:	3947881.4

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/18/2019, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Galisteo	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415559.0
Static Lev:	0	Y:	3947881.4
Tract Nbr:		Point Y:	35.67119752
Map Nbr:		Point X:	-105.93303373
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
296	SW	0.88	4,667.39	7,136.35	WATER WELLS

License Nb:	228	District Office S:	
POD No:	35423	Surv Map:	
POD Rec No:	24157	Other Loc:	620 E. Barcelona Rd.
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	29 A SF
Start Date:	01/16/1981, 12:00 AM	Restrict :	0.0
Finish Date:	01/17/1981, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	01/29/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	260	UTM Zone:	13
Depth of Water:	160	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415558.5

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3947876.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Galisteo	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734556.0
Static Lev:	0	Y:	1699719.0
Tract Nbr:		Point Y:	35.6711542
Map Nbr:		Point X:	-105.93303875
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
297	E	0.88	4,665.78	7,254.91	WATER WELLS

License Nb:	72	District Office S:	
POD No:	30908	Surv Map:	
POD Rec No:	335808	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 1 NA SF
Start Date:	04/04/2023, 12:00 AM	Restrict :	0.0
Finish Date:	04/06/2023, 12:00 AM	Section:	20
Plug Date:		Township:	17N
Log File D:	04/12/2023, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PD
Depth of Well:	420	UTM Zone:	13
Depth of Water:	140	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	9	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	417802.6
Pcw Rcv Da:		Northing:	3949184.3
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	04/13/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Esperanza	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	623DD	X:	1741865.0
Static Lev:	80	Y:	1704103.8
Tract Nbr:		Point Y:	35.68313308
Map Nbr:		Point X:	-105.90837893
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
298	WNW	0.89	4,676.85	6,987.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35733	Surv Map:	
POD Rec No:	54636	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	24
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415032.4
Pcw Rcv Da:		Northing:	3949642.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/10/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1732756.0
Static Lev:	0	Y:	1705491.0
Tract Nbr:		Point Y:	35.68702718
Map Nbr:		Point X:	-105.9390377
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
299	SE	0.89	4,708.97	7,292.67	WATER WELLS

License Nb:	0	District Office S:	
POD No:	44387	Surv Map:	
POD Rec No:	26301	Other Loc:	730 Camino Cabra
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417254.9
Pcw Rcv Da:		Northing:	3947936.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Armstrong	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1740120.0
Static Lev:	0	Y:	1699986.0
Tract Nbr:		Point Y:	35.6718371
Map Nbr:		Point X:	-105.91430264
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
300	SE	0.89	4,714.72	7,292.67	WATER WELLS

License Nb:	547	District Office S:	
POD No:	50269	Surv Map:	
POD Rec No:	41448	Other Loc:	730 Camino Cabra
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3 SF
Start Date:	02/13/1989, 12:00 AM	Restrict :	0.0
Finish Date:	02/14/1989, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	02/23/1989, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	285	UTM Zone:	13
Depth of Water:	70	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	25	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417254.9
Pcw Rcv Da:		Northing:	3947934.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/07/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Armstrong	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1740120.0
Static Lev:	0	Y:	1699979.0
Tract Nbr:		Point Y:	35.67181726
Map Nbr:		Point X:	-105.91430241
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
301	SW	0.89	4,688.77	7,089.67	WATER WELLS

License Nb:	0	District Office S:	
POD No:	30514	Surv Map:	
POD Rec No:	8653	Other Loc:	1002 Old Pecos Trail
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415183.6
Pcw Rcv Da:		Northing:	3948230.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/23/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ramona	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1733311.0
Static Lev:	0	Y:	1700864.0
Tract Nbr:		Point Y:	35.67431072
Map Nbr:		Point X:	-105.937218
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
302	NNW	0.90	4,736.32	7,072.82	WATER WELLS

License Nb:	0	District Office S:	
POD No:	37084	Surv Map:	
POD Rec No:	19072	Other Loc:	205 Williams Street, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415738.9
Pcw Rcv Da:		Northing:	3950386.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/06/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594800.0
Static Lev:	0	Y:	1707900.0
Tract Nbr:		Point Y:	35.69379605
Map Nbr:		Point X:	-105.93130857
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
303	S	0.90	4,732.82	7,250.95	WATER WELLS

License Nb:	1310	District Office S:	
POD No:	68741	Surv Map:	
POD Rec No:	139928	Other Loc:	797 Camino Del Monte Sol
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TB SF
Start Date:	06/14/1998, 12:00 AM	Restrict :	0.0
Finish Date:	06/18/1998, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	10/28/1998, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	80	UTM Accura:	10

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416561.2
Pcw Rcv Da:		Northing:	3947633.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/13/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416561.2
Static Lev:	0	Y:	3947633.5
Tract Nbr:		Point Y:	35.66904793
Map Nbr:		Point X:	-105.92193547
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098217053000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
304	SW	0.89	4,710.99	7,089.20	WATER WELLS

License Nb:	622	District Office S:	
POD No:	40601	Surv Map:	
POD Rec No:	42452	Other Loc:	1002 Old Pecos Trail
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T2 SF
Start Date:	09/15/1983, 12:00 AM	Restrict :	0.0
Finish Date:	09/15/1983, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	09/26/1983, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	120	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415180.7
Pcw Rcv Da:		Northing:	3948222.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ramona	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1733302.0
Static Lev:	0	Y:	1700837.0
Tract Nbr:		Point Y:	35.67423654
Map Nbr:		Point X:	-105.93724918
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
305	ESE	0.89	4,717.23	7,294.26	WATER WELLS

License Nb:	1310	District Office S:	
POD No:	22690	Surv Map:	
POD Rec No:	185008	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/15/1996, 12:00 AM	Restrict :	3.0
Finish Date:	11/15/1996, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/03/1997, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA

Wells and Additional Sources Detail Report

Depth of Well:	200	UTM Zone:	13
Depth of Water:	130	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-22690-CLW228456/68780/RG-22	Easting:	417727.1
Pcw Rcv Da:		Northing:	3948563.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/03/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	601400.0
Static Lev:	0	Y:	1702000.0
Tract Nbr:		Point Y:	35.67752649
Map Nbr:		Point X:	-105.90914967
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
305	ESE	0.89	4,717.23	7,294.26	WATER WELLS

License Nb:	214	District Office S:	
POD No:	22690	Surv Map:	
POD Rec No:	68780	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	44 SF
Start Date:	06/25/1973, 12:00 AM	Restrict :	0.0
Finish Date:	06/27/1973, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/01/1973, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	21	UTM Source:	PD
Depth of Well:	150	UTM Zone:	13
Depth of Water:	25	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	22	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417727.1
Pcw Rcv Da:		Northing:	3948563.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/03/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	601400.0
Static Lev:	0	Y:	1702000.0
Tract Nbr:		Point Y:	35.67752649
Map Nbr:		Point X:	-105.90914967
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
306	ESE	0.90	4,727.76	7,273.60	WATER WELLS

License Nb:	790	District Office S:	
POD No:	44321	Surv Map:	
POD Rec No:	51211	Other Loc:	1300 Canyon Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T1A SF
Start Date:	03/21/1986, 12:00 AM	Restrict :	0.0
Finish Date:	03/22/1986, 12:00 AM	Section:	29
Plug Date:		Township:	17N
Log File D:	03/31/1986, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	209	UTM Zone:	13
Depth of Water:	148	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417755.4
Pcw Rcv Da:		Northing:	3948635.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1741733.0
Static Lev:	0	Y:	1702300.0
Tract Nbr:		Point Y:	35.67817885
Map Nbr:		Point X:	-105.90884435
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
307	E	0.90	4,729.90	7,236.23	WATER WELLS

License Nb:	214	District Office S:	
POD No:	30908	Surv Map:	
POD Rec No:	45421	Other Loc:	1404 Cerro Gordo Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 1 NA SF
Start Date:	09/20/1978, 12:00 AM	Restrict :	0.0
Finish Date:	10/02/1978, 12:00 AM	Section:	20
Plug Date:		Township:	17N
Log File D:	10/10/1978, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	95	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	12	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417823.6
Pcw Rcv Da:		Northing:	3949155.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Esperanza	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1741935.0
Static Lev:	0	Y:	1704009.0
Tract Nbr:		Point Y:	35.68287249
Map Nbr:		Point X:	-105.90814391
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
308	WNW	0.90	4,742.05	6,992.45	WATER WELLS

License Nb:	228	District Office S:	
POD No:	50580	Surv Map:	
POD Rec No:	338891	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T1 SF
Start Date:	05/24/1989, 12:00 AM	Restrict :	0.0
Finish Date:	05/26/1989, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	06/05/1989, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	160	UTM Zone:	13
Depth of Water:	80	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	12	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415086.0
Pcw Rcv Da:		Northing:	3949794.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/16/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Zens	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6883994
Map Nbr:		Point X:	-105.93846142
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
309	NNW	0.91	4,781.84	7,063.87	WATER WELLS

License Nb:	0	District Office S:	
POD No:	71157	Surv Map:	
POD Rec No:	147086	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415647.1
Pcw Rcv Da:		Northing:	3950357.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/24/1998, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594500.0
Static Lev:	0	Y:	1707800.0
Tract Nbr:		Point Y:	35.69352405
Map Nbr:		Point X:	-105.93232001
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
310	SSW	0.90	4,776.03	7,202.42	WATER WELLS

License Nb:	622	District Office S:	
POD No:	41134	Surv Map:	
POD Rec No:	17464	Other Loc:	1020 Old Santa Fe Trail
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	84 1 SF
Start Date:	08/23/1984, 12:00 AM	Restrict :	0.0
Finish Date:	08/24/1984, 12:00 AM	Section:	30
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:	08/29/1984, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	440	UTM Zone:	13
Depth of Water:	109	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416061.3
Pcw Rcv Da:		Northing:	3947633.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/06/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736216.0
Static Lev:	0	Y:	1698941.0
Tract Nbr:		Point Y:	35.66900191
Map Nbr:		Point X:	-105.9274583
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
311	ESE	0.91	4,788.48	7,321.40	WATER WELLS

License Nb:	253	District Office S:	
POD No:	20457	Surv Map:	
POD Rec No:	246270	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/14/1986, 12:00 AM	Restrict :	0.0
Finish Date:	08/24/1986, 12:00 AM	Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:	10/06/1986, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	84	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417789.6
Pcw Rcv Da:		Northing:	3948684.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/19/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	601600.0
Static Lev:	0	Y:	1702400.0
Tract Nbr:		Point Y:	35.67862345
Map Nbr:		Point X:	-105.90847147
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
311	ESE	0.91	4,788.48	7,321.40	WATER WELLS

License Nb:	214	District Office S:	
POD No:	20457	Surv Map:	
POD Rec No:	22216	Other Loc:	Off Canyon Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/29/1972, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	03/31/1972, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/06/1972, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	160	UTM Zone:	13
Depth of Water:	134	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417789.6
Pcw Rcv Da:		Northing:	3948684.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/19/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	601600.0
Static Lev:	0	Y:	1702400.0
Tract Nbr:		Point Y:	35.67862345
Map Nbr:		Point X:	-105.90847147
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Off Canyon Road		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
312	NW	0.91	4,828.67	7,023.42	WATER WELLS

License Nb:	228	District Office S:	
POD No:	29522	Surv Map:	
POD Rec No:	18487	Other Loc:	311 Bishop Lodge Rd, Sf
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:	11/17/1977, 12:00 AM	Restrict :	0.0
Finish Date:	11/18/1977, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	11/29/1977, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	240	UTM Zone:	13
Depth of Water:	75	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415301.2
Pcw Rcv Da:		Northing:	3950116.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/17/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593375.0
Static Lev:	0	Y:	1706997.0
Tract Nbr:		Point Y:	35.69132803
Map Nbr:		Point X:	-105.93611734
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
313	WNW	0.92	4,832.57	6,988.85	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	96123	Surv Map:	
POD Rec No:	301875	Other Loc:	Dsf-03
POD Basin:	RG	Zone :	
POD Suffix:	POD4	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:	06/25/2016, 12:00 AM	Restrict :	0.0
Finish Date:	06/26/2016, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/07/2018, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	36	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415023.6
Pcw Rcv Da:		Northing:	3949736.7
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/19/2018, 12:00 AM	Latitude Second:	16.36
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	20.92
Well Tag:		X:	0.0
Static Lev:	21	Y:	0.0
Tract Nbr:		Point Y:	35.68787745
Map Nbr:		Point X:	-105.93914492
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
314	ESE	0.92	4,835.73	7,312.36	WATER WELLS

License Nb:	622	District Office S:	
POD No:	47157	Surv Map:	
POD Rec No:	7604	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:	03/05/1987, 12:00 AM	Restrict :	0.0
Finish Date:	03/06/1987, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	03/16/1987, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	460	UTM Zone:	13
Depth of Water:	120	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	5	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417683.7
Pcw Rcv Da:		Northing:	3948381.7
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	10/27/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417683.7
Static Lev:	0	Y:	3948381.7
Tract Nbr:		Point Y:	35.67588749
Map Nbr:		Point X:	-105.90961064
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
315	S	0.92	4,840.76	7,217.21	WATER WELLS

License Nb:	214	District Office S:	
POD No:	34695	Surv Map:	
POD Rec No:	44043	Other Loc:	1110 Old Santa Fe Trail
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	102* U2 SF
Start Date:	07/28/1980, 12:00 AM	Restrict :	0.0
Finish Date:	07/31/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/13/1980, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	28	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416171.7
Pcw Rcv Da:		Northing:	3947595.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/07/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736580.0
Static Lev:	0	Y:	1698821.0
Tract Nbr:		Point Y:	35.66866871
Map Nbr:		Point X:	-105.92623465
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
316	SSW	0.92	4,839.59	7,185.95	WATER WELLS

License Nb:	228	District Office S:	
POD No:	29552	Surv Map:	
POD Rec No:	6899	Other Loc:	1014 Old Santa Fe Trail, Sf
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	85 T1 SF
Start Date:	01/09/1978, 12:00 AM	Restrict :	0.0
Finish Date:	01/14/1978, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	01/20/1978, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	500	UTM Zone:	13
Depth of Water:	200	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415946.3
Pcw Rcv Da:		Northing:	3947641.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	De Vargas Development Co.	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415946.3
Static Lev:	0	Y:	3947641.0
Tract Nbr:		Point Y:	35.66906333
Map Nbr:		Point X:	-105.92872964
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098027066000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
317	S	0.92	4,875.63	7,234.66	WATER WELLS

License Nb:	228	District Office S:	
POD No:	34938	Surv Map:	
POD Rec No:	18946	Other Loc:	1125 Old Santa Fe Trail, Sf
POD Basin:	RG	Zone :	C

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/18/1980, 12:00 AM	Restrict :	0.0
Finish Date:	11/25/1980, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/12/1980, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	90	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416373.6
Pcw Rcv Da:		Northing:	3947574.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/18/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597000.0
Static Lev:	0	Y:	1698700.0
Tract Nbr:		Point Y:	35.66850104
Map Nbr:		Point X:	-105.92400195
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
317	S	0.92	4,875.63	7,234.66	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35863	Surv Map:	
POD Rec No:	52541	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416373.6
Pcw Rcv Da:		Northing:	3947574.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/08/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597000.0
Static Lev:	0	Y:	1698700.0
Tract Nbr:		Point Y:	35.66850104
Map Nbr:		Point X:	-105.92400195
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
318	W	0.92	4,852.31	7,005.61	WATER WELLS

License Nb:	214	District Office S:	
POD No:	27732	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	3300	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/10/1975, 12:00 AM	Restrict :	0.0
Finish Date:	10/15/1976, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	10/19/1976, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	80	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	45	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414867.1
Pcw Rcv Da:		Northing:	3948934.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/26/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592000.0
Static Lev:	0	Y:	1703100.0
Tract Nbr:		Point Y:	35.68063376
Map Nbr:		Point X:	-105.94078943
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
319	NE	0.92	4,867.37	7,286.19	WATER WELLS

License Nb:	228	District Office S:	

Wells and Additional Sources Detail Report

POD No:	42157	Surv Map:	
POD Rec No:	43645	Other Loc:	2012 Calle Lejano
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	13 2 SF
Start Date:	10/29/1984, 12:00 AM	Restrict :	0.0
Finish Date:	10/31/1984, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	01/21/1985, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	440	UTM Zone:	13
Depth of Water:	140	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417490.6
Pcw Rcv Da:		Northing:	3950073.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Calle Lejano	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1740804.0
Static Lev:	0	Y:	1707008.0
Tract Nbr:		Point Y:	35.69112249
Map Nbr:		Point X:	-105.91191774
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
320	ESE	0.93	4,887.62	7,302.01	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	97421	Surv Map:	
POD Rec No:	313141	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA T1 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	29
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417660.3
Pcw Rcv Da:		Northing:	3948308.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/01/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1741434.8
Static Lev:	0	Y:	1701225.2
Tract Nbr:		Point Y:	35.67522922
Map Nbr:		Point X:	-105.90986174
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
321	NNW	0.93	4,925.65	7,062.59	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	228	District Office S:	
POD No:	41844	Surv Map:	
POD Rec No:	8445	Other Loc:	205 Williams St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	28 SF
Start Date:	07/28/1984, 12:00 AM	Restrict :	0.0
Finish Date:	07/30/1984, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	10/11/1984, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	225	UTM Zone:	13
Depth of Water:	60	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415740.0
Pcw Rcv Da:		Northing:	3950451.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/21/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735044.0
Static Lev:	0	Y:	1708176.0
Tract Nbr:		Point Y:	35.69438393
Map Nbr:		Point X:	-105.93130325
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
322	SSW	0.92	4,882.53	7,147.18	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	228	District Office S:	
POD No:	34909	Surv Map:	
POD Rec No:	54226	Other Loc:	635 Armenta St, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	34 SF
Start Date:	09/27/1980, 12:00 AM	Restrict :	0.0
Finish Date:	09/27/1980, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	10/15/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	80	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415621.1
Pcw Rcv Da:		Northing:	3947761.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/13/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415621.1
Static Lev:	0	Y:	3947761.1
Tract Nbr:		Point Y:	35.6701183
Map Nbr:		Point X:	-105.93233502
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1054098440098000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

323	ESE	0.93	4,897.17	7,296.76	WATER WELLS

License Nb:	622	District Office S:	
POD No:	64068	Surv Map:	
POD Rec No:	30152	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/22/1996, 12:00 AM	Restrict :	0.0
Finish Date:	02/23/1996, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/02/1996, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	265	UTM Zone:	13
Depth of Water:	15	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417734.5
Pcw Rcv Da:		Northing:	3948439.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	03/18/2015, 12:00 AM	Latitude Second:	35.1
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	54
Ditch Name:		Longitude Second:	32.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67641642
Map Nbr:		Point X:	-105.90905531
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

324	ESE	0.93	4,900.89	7,313.56	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31377	Surv Map:	
POD Rec No:	36763	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	29
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417791.0
Pcw Rcv Da:		Northing:	3948576.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/11/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67764811
Map Nbr:		Point X:	-105.90844495
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
325	SW	0.93	4,908.03	7,086.46	WATER WELLS

License Nb:	228	District Office S:	
POD No:	47702	Surv Map:	
POD Rec No:	338183	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	12/31/1950, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	160	UTM Zone:	13
Depth of Water:	135	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415160.9
Pcw Rcv Da:		Northing:	3948148.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/19/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1733240.0
Static Lev:	0	Y:	1700593.0
Tract Nbr:		Point Y:	35.67356681
Map Nbr:		Point X:	-105.93746013
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
326	E	0.93	4,916.06	7,233.55	WATER WELLS

License Nb:	228	District Office S:	
POD No:	36941	Surv Map:	
POD Rec No:	17420	Other Loc:	1384 Canyon Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	NRG	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:	04/16/1984, 12:00 AM	Restrict :	0.0
Finish Date:	04/26/1984, 12:00 AM	Section:	29
Plug Date:		Township:	17N
Log File D:	07/02/1984, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	240	UTM Zone:	13
Depth of Water:	20	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	12	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417874.2
Pcw Rcv Da:		Northing:	3948918.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/01/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1742111.0
Static Lev:	0	Y:	1703233.0
Tract Nbr:		Point Y:	35.68073828
Map Nbr:		Point X:	-105.90756057
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :	Talaya Hill/Santa Fe		

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
327	E	0.93	4,925.67	7,220.47	WATER WELLS

License Nb:	214	District Office S:	
POD No:	29588	Surv Map:	
POD Rec No:	2195	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	10/10/1978, 12:00 AM	Restrict :	0.0
Finish Date:	10/13/1978, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	11/15/1978, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	165	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417886.0
Pcw Rcv Da:		Northing:	3949079.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/18/2012, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	601900.0
Static Lev:	0	Y:	1703700.0
Tract Nbr:		Point Y:	35.68219162
Map Nbr:		Point X:	-105.90744663
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant :

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
328	SSW	0.93	4,933.08	7,154.65	WATER WELLS

License Nb:	228	District Office S:	
POD No:	37185	Surv Map:	
POD Rec No:	41531	Other Loc:	1303 Camino Corrales
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	91 3 U2 SF
Start Date:	05/15/1982, 12:00 AM	Restrict :	0.0
Finish Date:	05/17/1982, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	07/14/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	320	UTM Zone:	13
Depth of Water:	186	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415729.8
Pcw Rcv Da:		Northing:	3947688.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/08/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735126.0
Static Lev:	0	Y:	1699110.0
Tract Nbr:		Point Y:	35.66947579
Map Nbr:		Point X:	-105.93112652
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
329	E	0.93	4,931.70	7,193.14	WATER WELLS

License Nb:	0	District Office S:	
POD No:	49056	Surv Map:	
POD Rec No:	46802	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417884.8
Pcw Rcv Da:		Northing:	3948987.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/05/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	601900.0
Static Lev:	0	Y:	1703400.0
Tract Nbr:		Point Y:	35.68136752
Map Nbr:		Point X:	-105.90745056
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
330	E	0.94	4,937.89	7,210.37	WATER WELLS

License Nb:	0	District Office S:	
POD No:	72300	Surv Map:	
POD Rec No:	150306	Other Loc:	1401 Canyon Road, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	50 1 T1 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	29
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	15	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	24.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417884.5
Pcw Rcv Da:		Northing:	3948957.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/17/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417884.5
Static Lev:	0	Y:	3948957.1
Tract Nbr:		Point Y:	35.68109163
Map Nbr:		Point X:	-105.90745075

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Talaya Hill/Santa Fe
Legal: Parcel Number 1056098142502000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
331	SW	0.94	4,959.56	7,106.57	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31218	Surv Map:	
POD Rec No:	325652	Other Loc:	1211 Old Pecos Trail
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	25 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415351.4
Pcw Rcv Da:		Northing:	3947923.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/17/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ramona	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415351.4
Static Lev:	0	Y:	3947923.0
Tract Nbr:		Point Y:	35.67155475

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.93533171
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
332	SW	0.94	4,964.23	7,108.30	WATER WELLS

License Nb:	228	District Office S:	
POD No:	47331	Surv Map:	
POD Rec No:	30475	Other Loc:	1211 Old Pecos Trail
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	25 SF
Start Date:	05/06/1987, 12:00 AM	Restrict :	0.0
Finish Date:	05/10/1987, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	05/22/1987, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	320	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415362.0
Pcw Rcv Da:		Northing:	3947910.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/13/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ramona	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1733910.0
Static Lev:	0	Y:	1699823.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.67144568
Map Nbr:		Point X:	-105.93521332
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
333	SE	0.95	4,998.64	7,304.57	WATER WELLS

License Nb:	0	District Office S:	
POD No:	54310	Surv Map:	
POD Rec No:	61279	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	29
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417507.2
Pcw Rcv Da:		Northing:	3948047.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/06/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	600700.0

Wells and Additional Sources Detail Report

Static Lev:	0	Y:	1700300.0
Tract Nbr:		Point Y:	35.67286254
Map Nbr:		Point X:	-105.91152655
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
335	SSE	0.96	5,054.21	7,265.90	WATER WELLS

License Nb:	547	District Office S:	
POD No:	34709	Surv Map:	
POD Rec No:	53338	Other Loc:	49 & 50 Mount Carmel Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/06/1980, 12:00 AM	Restrict :	0.0
Finish Date:	08/07/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/09/1980, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	160	UTM Zone:	13
Depth of Water:	28	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416831.0
Pcw Rcv Da:		Northing:	3947597.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:	NA	X:	1738743.0
Static Lev:	0	Y:	1698857.0
Tract Nbr:		Point Y:	35.66874797
Map Nbr:		Point X:	-105.91895103
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
339	SW	0.96	5,048.71	7,121.11	WATER WELLS

License Nb:	1281	District Office S:	
POD No:	31271	Surv Map:	
POD Rec No:	15057	Other Loc:	555 Armenta St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	39 U2 SF
Start Date:	03/31/1995, 12:00 AM	Restrict :	0.0
Finish Date:	03/31/1995, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	07/19/1995, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	28	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415398.1
Pcw Rcv Da:		Northing:	3947848.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/01/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	De Vargas Development Co.	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734031.0
Static Lev:	0	Y:	1699620.0
Tract Nbr:		Point Y:	35.67088622
Map Nbr:		Point X:	-105.93480792
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
340	SW	0.96	5,052.55	7,129.31	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35302	Surv Map:	
POD Rec No:	54726	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415462.2
Pcw Rcv Da:		Northing:	3947799.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/27/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594000.0
Static Lev:	0	Y:	1699400.0
Tract Nbr:		Point Y:	35.67045088
Map Nbr:		Point X:	-105.93409459
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
341	W	0.96	5,052.93	6,988.38	WATER WELLS

License Nb:	0	District Office S:	
POD No:	95469	Surv Map:	
POD Rec No:	297677	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414819.1
Pcw Rcv Da:		Northing:	3949320.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	08/06/2015, 12:00 AM	Latitude Second:	2.8

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	28.9
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68411128
Map Nbr:		Point X:	-105.9413607
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
342	NNE	0.96	5,062.80	7,238.47	WATER WELLS

License Nb:	0	District Office S:	
POD No:	41006	Surv Map:	
POD Rec No:	63069	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416868.6
Pcw Rcv Da:		Northing:	3950554.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598500.0
Static Lev:	0	Y:	1708500.0
Tract Nbr:		Point Y:	35.69541106
Map Nbr:		Point X:	-105.91884126
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Salvador Gonzales/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
343	SSW	0.96	5,062.03	7,139.39	WATER WELLS

License Nb:	0	District Office S:	
POD No:	51490	Surv Map:	
POD Rec No:	28666	Other Loc:	662 Armenta St, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	92 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415552.8
Pcw Rcv Da:		Northing:	3947737.4
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	12/06/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Developement Co #2	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594300.0
Static Lev:	0	Y:	1699200.0
Tract Nbr:		Point Y:	35.66989879
Map Nbr:		Point X:	-105.93308712
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
345	W	0.96	5,066.72	6,987.64	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94330	Surv Map:	
POD Rec No:	287038	Other Loc:	Tbamw-06
POD Basin:	RG	Zone :	
POD Suffix:	POD6	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414817.7
Pcw Rcv Da:		Northing:	3949336.3

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	10/07/2013, 12:00 AM	Latitude Second:	3.3
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	28.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68425
Map Nbr:		Point X:	-105.9413778
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
346	SW	0.96	5,072.64	7,125.77	WATER WELLS

License Nb:	622	District Office S:	
POD No:	42637	Surv Map:	
POD Rec No:	13817	Other Loc:	575 Armenta St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	38 SF
Start Date:	10/04/1984, 12:00 AM	Restrict :	0.0
Finish Date:	10/05/1984, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	10/11/1984, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	360	UTM Zone:	13
Depth of Water:	120	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	35	Lat Lon SO:	
Casing Size:	5.6	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415435.1

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3947812.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/18/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734154.0
Static Lev:	0	Y:	1699502.0
Tract Nbr:		Point Y:	35.67056124
Map Nbr:		Point X:	-105.93439531
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
347	W	0.96	5,091.64	7,006.15	WATER WELLS

License Nb:	0	District Office S:	
POD No:	71348	Surv Map:	
POD Rec No:	147732	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	414805.0
Pcw Rcv Da:		Northing:	3948844.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/11/1999, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	591800.0
Static Lev:	0	Y:	1702800.0
Tract Nbr:		Point Y:	35.67981072
Map Nbr:		Point X:	-105.941466
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
348	WSW	0.97	5,101.92	7,075.52	WATER WELLS

License Nb:	228	District Office S:	
POD No:	38562	Surv Map:	
POD Rec No:	33152	Other Loc:	326 B E. Coronado, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 18 SF
Start Date:	08/30/1982, 12:00 AM	Restrict :	0.0
Finish Date:	09/03/1982, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	09/27/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415039.1
Pcw Rcv Da:		Northing:	3948218.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/26/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ferdinand	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415039.1
Static Lev:	0	Y:	3948218.1
Tract Nbr:		Point Y:	35.67418829
Map Nbr:		Point X:	-105.93881324
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1054098249246000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
349	E	0.97	5,105.78	7,270.73	WATER WELLS

License Nb:	622	District Office S:	
POD No:	43388	Surv Map:	
POD Rec No:	64469	Other Loc:	1446 Cerro Gordo Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TB1 SF
Start Date:	04/27/1985, 12:00 AM	Restrict :	0.0
Finish Date:	04/29/1985, 12:00 AM	Section:	20
Plug Date:		Township:	17N
Log File D:	06/03/1985, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	190	UTM Zone:	13
Depth of Water:	60	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	10	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417932.2
Pcw Rcv Da:		Northing:	3949237.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/18/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1742288.0
Static Lev:	0	Y:	1704284.0
Tract Nbr:		Point Y:	35.68362439
Map Nbr:		Point X:	-105.9069523
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
350	WSW	0.97	5,124.54	7,070.57	WATER WELLS

License Nb:	214	District Office S:	
POD No:	28575	Surv Map:	
POD Rec No:	65668	Other Loc:	318 East Coronado, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2A SF
Start Date:	05/16/1977, 12:00 AM	Restrict :	0.0
Finish Date:	05/17/1977, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	05/24/1977, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	224	UTM Zone:	13
Depth of Water:	130	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415006.6
Pcw Rcv Da:		Northing:	3948259.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/05/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ramona	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415006.6
Static Lev:	0	Y:	3948259.0
Tract Nbr:		Point Y:	35.67455421
Map Nbr:		Point X:	-105.93917664
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1054098237260000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
351	E	0.97	5,133.39	7,245.13	WATER WELLS

License Nb:	0	District Office S:	
POD No:	42781	Surv Map:	
POD Rec No:	63070	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417947.7
Pcw Rcv Da:		Northing:	3949139.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/19/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	602100.0
Static Lev:	0	Y:	1703900.0
Tract Nbr:		Point Y:	35.68273948
Map Nbr:		Point X:	-105.90677099
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
352	WSW	0.97	5,137.95	7,041.17	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34747	Surv Map:	
POD Rec No:	28625	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414891.7
Pcw Rcv Da:		Northing:	3948477.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592100.0
Static Lev:	0	Y:	1701600.0
Tract Nbr:		Point Y:	35.67651142
Map Nbr:		Point X:	-105.94046921
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
352	WSW	0.97	5,137.95	7,041.17	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34748	Surv Map:	
POD Rec No:	333618	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414891.7
Pcw Rcv Da:		Northing:	3948477.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592100.0
Static Lev:	0	Y:	1701600.0
Tract Nbr:		Point Y:	35.67651142
Map Nbr:		Point X:	-105.94046921
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
355	NNW	0.99	5,205.23	7,073.41	WATER WELLS

License Nb:	622	District Office S:	
POD No:	36890	Surv Map:	
POD Rec No:	47363	Other Loc:	119 Valley Drive, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 SF
Start Date:	10/14/1981, 12:00 AM	Restrict :	0.0
Finish Date:	10/14/1981, 12:00 AM	Section:	18
Plug Date:		Township:	17N
Log File D:	10/21/1981, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	215	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	110	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415978.6
Pcw Rcv Da:		Northing:	3950627.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/16/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Catron	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415978.6
Static Lev:	0	Y:	3950627.4
Tract Nbr:		Point Y:	35.69598918
Map Nbr:		Point X:	-105.92868475
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055099023489000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
356	SSW	0.99	5,209.33	7,145.91	WATER WELLS

License Nb:	228	District Office S:	
POD No:	41555	Surv Map:	
POD Rec No:	27335	Other Loc:	1313 Camino Corrales
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	90 U2 SF
Start Date:	06/04/1984, 12:00 AM	Restrict :	0.0
Finish Date:	06/07/1984, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	08/15/1984, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA

Wells and Additional Sources Detail Report

Depth of Well:	320	UTM Zone:	13
Depth of Water:	200	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415676.5
Pcw Rcv Da:		Northing:	3947621.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/13/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734954.0
Static Lev:	0	Y:	1698886.0
Tract Nbr:		Point Y:	35.6688618
Map Nbr:		Point X:	-105.9317083
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
357	SSW	0.99	5,220.85	7,185.90	WATER WELLS

License Nb:	253	District Office S:	
POD No:	37517	Surv Map:	
POD Rec No:	11048	Other Loc:	751 Camino Pinones
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	85 U2T2 SF
Start Date:	06/18/1982, 12:00 AM	Restrict :	0.0
Finish Date:	06/21/1982, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	07/23/1982, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	5	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	130	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415935.5
Pcw Rcv Da:		Northing:	3947523.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/04/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735808.0
Static Lev:	0	Y:	1698575.0
Tract Nbr:		Point Y:	35.66799951
Map Nbr:		Point X:	-105.92883664
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
358	WSW	0.99	5,215.79	7,053.28	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35676	Surv Map:	
POD Rec No:	31617	Other Loc:	210 E Houghton St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	11** 8 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414899.5
Pcw Rcv Da:		Northing:	3948399.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/09/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Buena Vista Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1732372.0
Static Lev:	0	Y:	1701408.0
Tract Nbr:		Point Y:	35.67581342
Map Nbr:		Point X:	-105.94037483
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
359	W	0.99	5,232.50	6,996.51	WATER WELLS

License Nb:	0	District Office S:	
POD No:	46827	Surv Map:	
POD Rec No:	43641	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414746.0
Pcw Rcv Da:		Northing:	3948997.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/26/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	591600.0
Static Lev:	0	Y:	1703300.0
Tract Nbr:		Point Y:	35.68118674
Map Nbr:		Point X:	-105.94213415
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
360	E	0.99	5,234.22	7,248.76	WATER WELLS

License Nb:	622	District Office S:	
POD No:	65238	Surv Map:	
POD Rec No:	46530	Other Loc:	1534 Cerro Gordo Rd.
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	STOCK WELL	Subdiv Loc:	
Start Date:	03/08/1999, 12:00 AM	Restrict :	0.0
Finish Date:	03/09/1999, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	03/19/1999, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	180	UTM Zone:	13
Depth of Water:	70	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	7	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417978.2
Pcw Rcv Da:		Northing:	3949138.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/05/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	602200.0
Static Lev:	0	Y:	1703900.0
Tract Nbr:		Point Y:	35.68273841
Map Nbr:		Point X:	-105.90643393
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
361	SW	0.99	5,237.03	7,085.47	WATER WELLS

License Nb:	641	District Office S:	
POD No:	35285	Surv Map:	
POD Rec No:	44048	Other Loc:	300 E Barcelona
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 NA U1TA SF
Start Date:	11/10/1980, 12:00 AM	Restrict :	0.0
Finish Date:	11/11/1980, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	03/24/1981, 12:00 AM	Range:	09E

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	280	UTM Zone:	13
Depth of Water:	90	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415165.2
Pcw Rcv Da:		Northing:	3947987.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/01/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Lovato Grant	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1733261.0
Static Lev:	0	Y:	1700065.0
Tract Nbr:		Point Y:	35.67211573
Map Nbr:		Point X:	-105.93739565
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
362	WSW	0.99	5,242.22	7,067.45	WATER WELLS

License Nb:	214	District Office S:	
POD No:	35870	Surv Map:	
POD Rec No:	5004	Other Loc:	302 E Coronado
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	F SF
Start Date:	03/25/1981, 12:00 AM	Restrict :	3.0
Finish Date:	03/27/1981, 12:00 AM	Section:	25
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:	04/01/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	316	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414948.7
Pcw Rcv Da:		Northing:	3948287.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/10/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ramona	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1732538.0
Static Lev:	0	Y:	1701041.0
Tract Nbr:		Point Y:	35.67480345
Map Nbr:		Point X:	-105.93981934
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
363	WNW	0.99	5,242.27	6,980.32	WATER WELLS

License Nb:	0	District Office S:	
POD No:	95469	Surv Map:	
POD Rec No:	297679	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414777.2
Pcw Rcv Da:		Northing:	3949410.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	08/06/2015, 12:00 AM	Latitude Second:	5.7
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	30.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68491633
Map Nbr:		Point X:	-105.9418332
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
364	E	1.00	5,256.91	7,268.27	WATER WELLS

License Nb:	622	District Office S:	
POD No:	70776	Surv Map:	
POD Rec No:	145898	Other Loc:	1494 Cerro Gordo Rd, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T3 SF
Start Date:	12/22/1998, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	12/22/1998, 12:00 AM	Section:	20
Plug Date:		Township:	17N
Log File D:	01/12/1999, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	220	UTM Zone:	13
Depth of Water:	60	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417979.1
Pcw Rcv Da:		Northing:	3949229.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/22/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417979.1
Static Lev:	0	Y:	3949229.8
Tract Nbr:		Point Y:	35.68355798
Map Nbr:		Point X:	-105.90643326
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1056099166044000000		

Radon Information

This section lists any relevant radon information found for the target property.

Federal EPA Radon Zone for *SANTA FE* County: **1**

Zone 1: Counties with predicted average indoor radon screening levels greater than 4 pCi/L
Zone 2: Counties with predicted average indoor radon screening levels from 2 to 4 pCi/L
Zone 3: Counties with predicted average indoor radon screening levels less than 2 pCi/L

Federal Area Radon Information for *SANTA FE* County

No Measures/Homes:	73
Geometric Mean:	3.2
Arithmetic Mean:	4.6
Median:	3.5
Standard Deviation:	3.8
Maximum:	21.6
% >4 pCi/L:	41
% >20 pCi/L:	1
Notes on Data Table:	TABLE 1. Screening indoor radon data from the EPA/State Residential Radon Survey of New Mexico conducted during 1988-89. Data represent 2-7 day charcoal canister measurements from the lowest level of each home tested.

Appendix

Federal Sources

FEMA National Flood Hazard Layer — **FEMA FLOOD**

The National Flood Hazard Layer (NFHL) data incorporates Flood Insurance Rate Map (FIRM) databases published by the Federal Emergency Management Agency (FEMA), and any Letters Of Map Revision (LOMRs) that have been issued against those databases since their publication date. The FIRM Database is the digital, geospatial version of the flood hazard information shown on the published paper FIRMs. The FIRM Database depicts flood risk information and supporting data used to develop the risk data. The FIRM Database is derived from Flood Insurance Studies (FISs), previously published FIRMs, flood hazard analyses performed in support of the FISs and FIRMs, and new mapping data, where available.

Indoor Radon Data — **INDOOR RADON**

Indoor radon measurements tracked by the Environmental Protection Agency(EPA) and the State Residential Radon Survey.

Public Water Systems Violations and Enforcement Data — **PWSV**

This list of drinking water violations and enforcement actions is sourced from the U.S Environmental Protection Agency's (EPA) Enforcement and Compliance History Online (ECHO) system that incorporates Public Water Systems data from EPA's Safe Drinking Water Information System (SDWIS) database, as part of the national download of Safe Drinking Water Act (SDWA) data. SDWIS contains information on public water systems from the Public Water System Supervision (PWSS) Program, including monitoring, enforcement, and violation data related to requirements established by the SWDA. Address information provided in SWDIS may correspond either with the physical location of the water system, or with a contact address.

Radon Zone Level — **RADON ZONE**

Areas showing the level of Radon Zones (level 1, 2 or 3) by county. This data is maintained by the Environmental Protection Agency (EPA).

Safe Drinking Water Information System (SDWIS) — **SDWIS**

This national download of Safe Drinking Water Act (SDWA) data is sourced from the U.S Environmental Protection Agency's (EPA) Enforcement and Compliance History Online (ECHO) system that incorporates Public Water Systems data from EPA's Safe Drinking Water Information System (SDWIS) database. SDWIS contains information on public water systems from the Public Water System Supervision (PWSS) Program related to requirements established by the Safe Drinking Water Act (SDWA). Address information provided in SWDIS may correspond either with the physical location of the water system, or with a contact address.

Soil Survey Geographic database — **SSURGO**

The Soil Survey Geographic database (SSURGO) contains information about soil as collected by the National Cooperative Soil Survey at the Natural Resources Conservation Service (NRCS). Soil maps outline areas called map units. The map units are linked to soil properties in a database. Each map unit may contain one to three major components and some minor components.

U.S. Fish & Wildlife Service Wetland Data — **US WETLAND**

The U.S. Fish & Wildlife Service Wetland layer represents the approximate location and type of wetlands and deepwater habitats in the United States.

USGS Current Topo — **US TOPO**

US Topo topographic maps are produced by the National Geospatial Program of the U.S. Geological Survey (USGS). The project was launched in late 2009, and the term "US Topo" refers specifically to quadrangle topographic maps published in 2009 and later.

USGS Geology — **US GEOLOGY**

Seamless maps depicting geological information provided by the United States Geological Survey (USGS).

USGS National Water Information System — **FED USGS**

The U.S. Geological Survey's (USGS) National Water Information System (NWIS) is the nation's principal repository of water resources data. The data includes comprehensive information of well-construction details, time-series data for gage height, streamflow, groundwater level, and precipitation and water use data. This NWIS database information is obtained through the Water Quality Data Portal (WQP). The WQP

is a cooperative service sponsored by the USGS, the Environmental Protection Agency (EPA), and the National Water Quality Monitoring Council (NWQMC).

State Sources

Oil and Gas Wells **OGW**

Oil and Gas Well Data collected by New Mexico Oil Conservation Division.

Point of Diversion Report **WATER WELLS**

Point of Diversion report provided by the New Mexico Office of the State Engineer (OSE). This data comes from the NM Water Rights Reporting System (NMWRRS). The report returns a summary of water rights use, owner, wells, point of diversion and location and other information. This list includes declared, complete, in-progress, and plugged wells.

Public Water Supply Wells **PWSW**

A list of public water supply systems maintained by the New Mexico Environment Department (NMED), Drinking Water Bureau (DWB). This database includes active and inactive public water systems.

Liability Notice

Reliance on information in Report: The Physical Setting Report (PSR) DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a review of environmental databases and physical characteristics for the site or adjacent properties.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS Information Inc. disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report(s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

APPENDIX E

User Provided Information

[RESERVED]

APPENDIX F

Historical Fire Insurance Maps

FIRE INSURANCE MAPS

Project Property: Lopez Cleaners
838 East Palace Avenue Santa Fe NM 87501
Project No: NMENV.M007.SF-WALDO
Requested By: INTERA Incorporated
Order No: 25121700727
Date Completed: December 17, 2025

Please note that no information was found for your site or adjacent properties.

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

APPENDIX G

Historical City Directories

CITY DIRECTORY

Project Property:	*Lopez Cleaners* *838 East Palace Avenue* *Santa Fe,NM 87501*
Project No:	*NMENV.M007.SF-WALDO*
Requested By:	*INTERA Incorporated*
Order No:	*25121700727*
Date Completed:	*December 22, 2025*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

December 22, 2025
RE: CITY DIRECTORY RESEARCH
838 East Palace Avenue
Santa Fe,NM 87501

Thank you for contacting ERIS for an City Directory Search for the site described above. Our staff has conducted a reverse listing City Directory search to determine prior occupants of the subject site and adjacent properties. We have provided the nearest addresses(s) when adjacent addresses are not listed. If we have searched a range of addresses, all addresses in that range found in the Directory are included.

Note: Reverse Listing Directories generally are focused on more highly developed areas. Newly developed areas may be covered in the more recent years, but the older directories will tend to cover only the "central" parts of the city. To complete the search, we have either utilized the ACPL, Library of Congress, State Archives, and/or a regional library or history center as well as multiple digitized directories. These do not claim to be a complete collection of all reverse listing city directories produced.

ERIS has made every effort to provide accurate and complete information but shall not be held liable for missing, incomplete or inaccurate information. To complete this search we used the general range(s) below to search for relevant findings. If you believe there are additional addresses or streets that require searching please contact us at 866-517-5204.

Search Criteria:
825-870 of E Alameda St
825-880 of E Palace Ave
Search Notes:

Search Results Summary

Date	Source	Comment
2024	DIGITAL BUSINESS DIRECTORY	
2023	DIGITAL BUSINESS DIRECTORY	
2020	DIGITAL BUSINESS DIRECTORY	
2016	DIGITAL BUSINESS DIRECTORY	
2012	DIGITAL BUSINESS DIRECTORY	
2007	DIGITAL BUSINESS DIRECTORY	
2003	DIGITAL BUSINESS DIRECTORY	
2000	DIGITAL BUSINESS DIRECTORY	
1996	POLKS	
1993	POLKS	
1988	POLKS	
1983	POLKS	
1978	POLKS	
1973	POLKS	
1968	HUDSPETHS	
1964	HUDSPETHS	
1960	HUDSPETHS	
1955	HUDSPETHS	
1949	HUDSPETHS	
1944	HUDSPETHS	
1940	HUDSPETHS	
1936-37	HUDSPETHS	
1930-31	HUDSPETHS	
1928-29	HUDSPETHS	

2024 E ALAMEDA ST

SOURCE: DIGITAL BUSINESS DIRECTORY

833 **BARBARA BANKS**...*RESIDENTIAL*
835 **LINDA SCHAEFER**...*RESIDENTIAL*
837 **MIGUEL GABALDON**...*RESIDENTIAL*
839 **MARY BAROS**...*RESIDENTIAL*
840 **DANIEL HOGAN**...*RESIDENTIAL*
841 **BLAINE YOUNG**...*RESIDENTIAL*
868 **LAURA BRINK**...*RESIDENTIAL*

2024 E PALACE AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

825 **PAMELA SEAWORTHY**...*RESIDENTIAL*
826 **ANTONIO GRIEGO**...*RESIDENTIAL*
828 **ELISSA HEYMAN**...*RESIDENTIAL*
828 **HEYMAN, ELISSA**...*PSYCHIC MEDIUMS*
833 **WILLIAM LAMBERT**...*RESIDENTIAL*
834 **MICHELE LOWRANCE**...*RESIDENTIAL*
838 **CLAY BURCHELL**...*RESIDENTIAL*
841 **GAIL EVANS**...*RESIDENTIAL*
841 **LUCY MODAHL**...*RESIDENTIAL*
843 **EVAN LYNCH**...*RESIDENTIAL*
843 **SUE BERRY**...*RESIDENTIAL*
843 **WILLIAM RANCK-JR**...*RESIDENTIAL*
845 **VIKKI YEARY**...*RESIDENTIAL*
847 **C SALEM**...*RESIDENTIAL*
847 **CHRISTOPHER NORRIS**...*RESIDENTIAL*
849 **TERRY BURT**...*RESIDENTIAL*
851 **DENNIS WRIGHT**...*RESIDENTIAL*
853 **HERMAN QUINTANA**...*RESIDENTIAL*
855 **MARIA KELIN**...*RESIDENTIAL*
855 **ZACKEREE KELIN**...*RESIDENTIAL*
856 **CHERYL FRY**...*RESIDENTIAL*
857 **MARY LACAFF**...*RESIDENTIAL*
859 **FUZZY WUZZY INTERIORS**...*INTERIOR DECORATORS DESIGN & CONSULTANTS*
864 **CARLINDA CASE**...*RESIDENTIAL*
864 **JOE SHEPARD**...*RESIDENTIAL*
864 **MARGARET BEACHAM**...*RESIDENTIAL*
868 **RDM ASSOCIATE**...*JEWELRY MANUFACTURER*
873 **STEPHANIE GALICHIA**...*RESIDENTIAL*
874 **MICHAEL POULSON**...*RESIDENTIAL*
878 **WARD HALLA**...*RESIDENTIAL*

2023 E ALAMEDA ST

SOURCE: DIGITAL BUSINESS DIRECTORY

829 **LUCY SAIZ**...*RESIDENTIAL*
833 **AARON BANKS**...*RESIDENTIAL*
833 **BARBARA BANKS**...*RESIDENTIAL*
835 **LINDA SCHAEFER**...*RESIDENTIAL*
837 **MIGUEL GABALDON**...*RESIDENTIAL*
839 **MARY BAROS**...*RESIDENTIAL*
841 **BLAINE YOUNG**...*RESIDENTIAL*
868 **LAURA BRINK**...*RESIDENTIAL*

2023 E PALACE AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

825 **PAMELA SEAWORTHY**...*RESIDENTIAL*
826 **ANTONIO GRIEGO**...*RESIDENTIAL*
831 **DONNA SALSICH**...*RESIDENTIAL*
833 **WILLIAM LAMBERT**...*RESIDENTIAL*
834 **MICHELE LOWRANCE**...*RESIDENTIAL*
836 **LAURA ELLERBY**...*RESIDENTIAL*
838 **CLAY BURCHELL**...*RESIDENTIAL*
841 **GAIL EVANS**...*RESIDENTIAL*
841 **LESLIE CARROLL**...*RESIDENTIAL*
841 **LUCY MODAHL**...*RESIDENTIAL*
843 **SUE BERRY**...*RESIDENTIAL*
843 **WILLIAM RANCK-JR**...*RESIDENTIAL*
847 **C SALEM**...*RESIDENTIAL*
847 **CHRISTOPHER NORRIS**...*RESIDENTIAL*
847 **KATHARINE YANDA**...*RESIDENTIAL*
849 **TERRY BURT**...*RESIDENTIAL*
853 **HERMAN QUINTANA**...*RESIDENTIAL*
857 **MARY LACAFF**...*RESIDENTIAL*
859 **JOEL STOCKER**...*RESIDENTIAL*
864 **JOE SHEPARD**...*RESIDENTIAL*
864 **MARGARET BEACHAM**...*RESIDENTIAL*
868 **RDM ASSOCIATE**...*JEWELRY-MANUFACTURERS*
868 **RDM ASSOCIATE**...*JEWELERS-RETAIL*
873 **STEPHANIE GALICHIA**...*RESIDENTIAL*
875 **BARBARA TEMPLEMAN**...*RESIDENTIAL*
878 **WARD HALLA**...*RESIDENTIAL*
880 **STEVEN BAKER**...*RESIDENTIAL*

2020 E ALAMEDA ST

SOURCE: DIGITAL BUSINESS DIRECTORY

829 **LUCY SAIZ**...*RESIDENTIAL*
833 **AARON BANKS**...*RESIDENTIAL*
835 **LINDA SCHAEFER**...*RESIDENTIAL*
837 **CHRISTINE GABALDON**...*RESIDENTIAL*
839 **MARY BAROS**...*RESIDENTIAL*
841 **BLAINE YOUNG**...*RESIDENTIAL*
868 **LAURA BRINK**...*RESIDENTIAL*

2020 E PALACE AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

825 **PAMELA SEAWORTHY**...*RESIDENTIAL*
826 **ANTONIO GRIEGO**...*RESIDENTIAL*
831 **DONNA SALSICH**...*RESIDENTIAL*
833 **WILLIAM LAMBERT**...*RESIDENTIAL*
834 **MICHELE LOWRANCE**...*RESIDENTIAL*
836 **LAURA ELLERBY**...*RESIDENTIAL*
838 **CLAY BURCHELL**...*RESIDENTIAL*
841 **GAIL EVANS**...*RESIDENTIAL*
841 **LUCY MODAHL**...*RESIDENTIAL*
843 **SUE BERRY**...*RESIDENTIAL*
843 **WILLIAM RANCK-JR**...*RESIDENTIAL*
847 **C SALEM**...*RESIDENTIAL*
847 **CHRISTOPHER NORRIS**...*RESIDENTIAL*
847 **KATHARINE YANDA**...*RESIDENTIAL*
849 **TERRY BURT**...*RESIDENTIAL*
853 **HERMAN QUINTANA**...*RESIDENTIAL*
857 **MARY LACAFF**...*RESIDENTIAL*
859 **JOEL STOCKER**...*RESIDENTIAL*
864 **JOE SHEPARD**...*RESIDENTIAL*
864 **MARGARET BEACHAM**...*RESIDENTIAL*
868 **RDM ASSOCIATE**...*JEWELERS-RETAIL*
868 **RDM ASSOCIATE**...*JEWELRY-MANUFACTURERS*
873 **STEPHANIE GALICHIA**...*RESIDENTIAL*
875 **BARBARA TEMPLEMAN**...*RESIDENTIAL*
878 **WARD HALLA**...*RESIDENTIAL*
880 **STEVEN BAKER**...*RESIDENTIAL*

2016 E ALAMEDA ST

SOURCE: DIGITAL BUSINESS DIRECTORY

829 **LUCY SAIZ**...*RESIDENTIAL*
829 **MAX SAIZ**...*RESIDENTIAL*
829 **PAUL SAIZ**...*RESIDENTIAL*
829 **ROSIE SAIZ**...*RESIDENTIAL*
833 **AARON BANKS**...*RESIDENTIAL*
833 **BARBARA BANKS**...*RESIDENTIAL*
835 **LINDA SCHAEFER**...*RESIDENTIAL*
837 **MIGUEL GABALDON**...*RESIDENTIAL*
839 **MARY BAROS**...*RESIDENTIAL*
839 **ROSINA BAROS**...*RESIDENTIAL*
841 **BLAINE YOUNG**...*RESIDENTIAL*
868 **JANE FENSKE**...*RESIDENTIAL*
868 **LAURA BRINK**...*RESIDENTIAL*

2016 E PALACE AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

825 **PAMELA SEAWORTHY**...*RESIDENTIAL*
826 **ANTONIO GRIEGO**...*RESIDENTIAL*
826 **CARMEN GRIEGO**...*RESIDENTIAL*
831 **DONNA SALSICH**...*RESIDENTIAL*
833 **WILLIAM LAMBERT**...*RESIDENTIAL*
834 **MICHELE LOWRANCE**...*RESIDENTIAL*
834 **RANDY LOWRANCE**...*RESIDENTIAL*
836 **LAURA ELLERBY**...*RESIDENTIAL*
838 **CLAY BURCHELL**...*RESIDENTIAL*
841 **GAIL EVANS**...*RESIDENTIAL*
847 **C SALEM**...*RESIDENTIAL*
847 **CHRISTOPHER NORRIS**...*RESIDENTIAL*
847 **KATHARINE YANDA**...*RESIDENTIAL*
847 **MARK YANDA**...*RESIDENTIAL*
847 **SUSAN YANDA**...*RESIDENTIAL*
849 **TERRY BURT**...*RESIDENTIAL*
853 **HERMAN QUINTANA**...*RESIDENTIAL*
857 **MARY LACAFF**...*RESIDENTIAL*
859 **JOEL STOCKER**...*RESIDENTIAL*
864 **JOE SHEPARD**...*RESIDENTIAL*
864 **MARGARET BEACHAM**...*RESIDENTIAL*
864 **SANDY SHEPARD**...*RESIDENTIAL*
868 **RDM ASSOCIATE**...*JEWELERS-RETAIL*
868 **RDM ASSOCIATE**...*JEWELRY-MANUFACTURERS*
873 **STEPHANIE GALICHIA**...*RESIDENTIAL*
875 **WILLIAM TEMPLEMAN**...*RESIDENTIAL*
878 **WARD HALLA**...*RESIDENTIAL*
880 **STEVEN BAKER**...*RESIDENTIAL*

2012 E ALAMEDA ST

SOURCE: DIGITAL BUSINESS DIRECTORY

827 **JOSIE GRIEGO**...*RESIDENTIAL*
829 **DOLORES SAIZ**...*RESIDENTIAL*
829 **JOE SAIZ**...*RESIDENTIAL*
829 **JOSEPH SAIZ**...*RESIDENTIAL*
829 **LUCY SAIZ**...*RESIDENTIAL*
829 **MARGARET SAIZ**...*RESIDENTIAL*
829 **MARIA SAIZ**...*RESIDENTIAL*
829 **MAX SAIZ**...*RESIDENTIAL*
829 **ROSIE SAIZ**...*RESIDENTIAL*
829 **TRACY SAIZ**...*RESIDENTIAL*
833 **AARON BANKS**...*RESIDENTIAL*
833 **FRANK JAMES**...*RESIDENTIAL*
833 **MICHAEL BANKS**...*RESIDENTIAL*
835 **LINDA SCHAEFER**...*RESIDENTIAL*
835 **MARK SCHAEFER**...*RESIDENTIAL*
837 **CHRISTINE GABALDON**...*RESIDENTIAL*
837 **FELIPE GABALDON**...*RESIDENTIAL*
837 **MIGUEL GABALDON**...*RESIDENTIAL*
837 **RICHARD GABALDON**...*RESIDENTIAL*
839 **GUS BAROS**...*RESIDENTIAL*
839 **MARY BAROS**...*RESIDENTIAL*
839 **THERESA BAROS**...*RESIDENTIAL*

2012 E PALACE AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

825 **PAMELA SEAWORTHY**...*RESIDENTIAL*
826 **ANDREW GRIEGO**...*RESIDENTIAL*
826 **ANTONIO GRIEGO**...*RESIDENTIAL*
826 **CARMEN GRIEGO**...*RESIDENTIAL*
831 **D SALSICH**...*RESIDENTIAL*
831 **DONNA SALSICH**...*RESIDENTIAL*
833 **CONSERVATION SOLUTIONS INC**...*MONUMENTS*
834 **MICHELE LOWRANCE**...*RESIDENTIAL*
838 **CLAY BURCHELL**...*RESIDENTIAL*
838 **SARA BURCHELL**...*RESIDENTIAL*
839 **VIRGINIA GALTNEY**...*RESIDENTIAL*
840 **JOANN STONE**...*RESIDENTIAL*
840 **M LITTLE**...*RESIDENTIAL*
841 **LESLIE MODAHL**...*RESIDENTIAL*
841 **LUCY MODAHL**...*RESIDENTIAL*
845 **CYNTHIA PURVIS**...*RESIDENTIAL*
847 **CHRIS NORRIS**...*RESIDENTIAL*
847 **SUSAN YANDA**...*RESIDENTIAL*
849 **JUANITA BURT**...*RESIDENTIAL*
849 **TERRY BURT**...*RESIDENTIAL*
849 **WARREN YOUNG**...*RESIDENTIAL*
851 **LAWRENCE LEAKE**...*RESIDENTIAL*
855 **STELLA ORTIZ**...*RESIDENTIAL*
857 **ADAM LOBATO**...*RESIDENTIAL*
857 **ANTONIO LOBATO**...*RESIDENTIAL*
857 **ELEANOR LOBATO**...*RESIDENTIAL*
857 **STEVEN LOBATO**...*RESIDENTIAL*
868 **RDM ASSOCIATE**...*JEWELERS-WHOLESALE*
875 **BARBARA TEMPLEMAN**...*RESIDENTIAL*
875 **WILLIAM TEMPLEMAN**...*RESIDENTIAL*
878 **JUDY HALLA**...*RESIDENTIAL*
878 **WARD HALLA**...*RESIDENTIAL*

2007 E ALAMEDA ST

SOURCE: DIGITAL BUSINESS DIRECTORY

827 **JOHN GRIEGO**...*RESIDENTIAL*
829 **AGUSTIN GRIEGO**...*RESIDENTIAL*
833 **BARBARA BANKS**...*RESIDENTIAL*
837 **MIGUEL GABALDON**...*RESIDENTIAL*
839 **GUS BAROS**...*RESIDENTIAL*
840 **JOANN G DURAN**...*RESIDENTIAL*
840 **LYNDEN BEAR**...*RESIDENTIAL*
841 **BLAINE YOUNG**...*RESIDENTIAL*
841 **RODNEY O & NANCY J CARLSON**...*RESIDENTIAL*
841 **RON STRONG**...*RESIDENTIAL*
868 **C CULVER**...*RESIDENTIAL*
868 **DONELIA TRUJILLO**...*RESIDENTIAL*
870 **J ABEL**...*RESIDENTIAL*

2007 E PALACE AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

826 **ANTONIO E GRIEGO**...*RESIDENTIAL*
831 **ART COLE**...*RESIDENTIAL*
831 **D B SALSICH**...*RESIDENTIAL*
832 **GWENDA ELIASON**...*RESIDENTIAL*
834 **CAROLE LAROCHE**...*RESIDENTIAL*
838 **CLAY BURCHELL**...*RESIDENTIAL*
840 **J A STONE**...*RESIDENTIAL*
840 **M J LITTLE**...*RESIDENTIAL*
841 **K C LARSON**...*RESIDENTIAL*
841 **WHITNEY CHASE**...*RESIDENTIAL*
845 **C SKEEN**...*RESIDENTIAL*
845 **RANDALL MERKER**...*RESIDENTIAL*
845 **SALOMON LOVATO**...*RESIDENTIAL*
845 **TED LOVATO**...*RESIDENTIAL*
847 **RACHEL YANDA**...*RESIDENTIAL*
847 **S B YANDA**...*RESIDENTIAL*
849 **WARREN YOUNG**...*RESIDENTIAL*
855 **DAVID LOVATO**...*RESIDENTIAL*
855 **LAWRENCE STANDISH**...*RESIDENTIAL*
855 **STELLA L ORTIZ**...*RESIDENTIAL*
857 **ELEANOR LOBATO**...*RESIDENTIAL*
857 **MARY & TED LACAFF**...*RESIDENTIAL*
857 **MARY R LOBATO**...*RESIDENTIAL*
860 **JOYCE PATRICK**...*RESIDENTIAL*
863 **TIMMY NOGER**...*RESIDENTIAL*
864 **KERMIT E LITTLE**...*RESIDENTIAL*
864 **MARK C LITTLE**...*RESIDENTIAL*
868 **RDM ASSOCIATE**...*JEWELRY-MANUFACTURERS*
874 **E TRUJILLO**...*RESIDENTIAL*
875 **BARBARA TEMPLEMAN INTERIOR**...*INTERIOR DECORATORS DESIGN & CONSULTANTS*
876 **JACK PROBST**...*RESIDENTIAL*
878 **JUDY HALLA**...*RESIDENTIAL*
878 **WARD HALLA**...*RESIDENTIAL*

2003 E ALAMEDA ST

SOURCE: DIGITAL BUSINESS DIRECTORY

827 **JOHN GRIEGO**...*RESIDENTIAL*
829 **AGUSTIN GRIEGO**...*RESIDENTIAL*
833 **BARBARA BANKS**...*RESIDENTIAL*
835 **HAROLD E BANKS**...*RESIDENTIAL*
839 **GUS BAROS**...*RESIDENTIAL*
840 **B SCHOLL**...*RESIDENTIAL*
840 **FRANK RIMBACH**...*RESIDENTIAL*
840 **LYNDEN BEAR**...*RESIDENTIAL*
840 **SUSAN E PACHECO**...*RESIDENTIAL*
841 **BLAINE YOUNG**...*RESIDENTIAL*
841 **PAUL W BOVE**...*RESIDENTIAL*
841 **RON STRONG**...*RESIDENTIAL*
868 **DONELIA TRUJILLO**...*RESIDENTIAL*
868 **NHEARIEB BUSTAMANTE**...*RESIDENTIAL*
870 **KELLY BAKER**...*RESIDENTIAL*
870 **REESE & ADRIENNE BAKER**...*RESIDENTIAL*
870 **WESTERN ECOLOGY**

2003 E PALACE AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

826 **ANTONIO E GRIEGO**...*RESIDENTIAL*
831 **ART COLE**...*RESIDENTIAL*
831 **D B SALSICH**...*RESIDENTIAL*
832 **MARIE JENKINS**...*RESIDENTIAL*
832 **PAUL DAVID FLETCHER**...*RESIDENTIAL*
833 **JAMES R DAUGHTRY**...*RESIDENTIAL*
833 **JOHN L STELLNER**...*RESIDENTIAL*
834 **CAROLE LAROCHE**...*RESIDENTIAL*
840 **J A STONE**...*RESIDENTIAL*
840 **M J LITTLE**...*RESIDENTIAL*
841 **WILLIAM YANDA**...*RESIDENTIAL*
845 **C SKEEN**...*RESIDENTIAL*
845 **M J MILLER**...*RESIDENTIAL*
845 **RANDALL MERKER**...*RESIDENTIAL*
845 **SALOMON LOVATO**...*RESIDENTIAL*
845 **TED LOVATO**...*RESIDENTIAL*
847 **MARK YANDA**...*RESIDENTIAL*
849 **RICHARD MONDIO**...*RESIDENTIAL*
849 **WARREN YOUNG**...*RESIDENTIAL*
853 **D S STREVER**...*RESIDENTIAL*
853 **PALACE GROCERY**
855 **DAVID LOVATO**...*RESIDENTIAL*
855 **PAUL SUNDOWN**...*RESIDENTIAL*
855 **STELLA L ORTIZ**...*RESIDENTIAL*
857 **ELEANOR LOBATO**...*RESIDENTIAL*
857 **MARY & TED LACAFF**...*RESIDENTIAL*
857 **MARY R LOBATO**...*RESIDENTIAL*
868 **PALACE LAUNDROMAT**
874 **E TRUJILLO**...*RESIDENTIAL*
876 **JACK PROBST**...*RESIDENTIAL*
878 **FRANK SR HALLA**...*RESIDENTIAL*

2000 E ALAMEDA ST

SOURCE: DIGITAL BUSINESS DIRECTORY

827 **JOHN GRIEGO**...*RESIDENTIAL*
829 **AGUSTIN GRIEGO**...*RESIDENTIAL*
833 **BARBARA BANKS**...*RESIDENTIAL*
835 **HAROLD E BANKS**...*RESIDENTIAL*
839 **GUS BAROS**...*RESIDENTIAL*
840 **B SCHOLL**...*RESIDENTIAL*
840 **FRANK RIMBACH**...*RESIDENTIAL*
840 **LYNDEN BEAR**...*RESIDENTIAL*
840 **SUSAN E PACHECO**...*RESIDENTIAL*
841 **BLAINE YOUNG**...*RESIDENTIAL*
841 **PAUL W BOVE**...*RESIDENTIAL*
841 **RON STRONG**...*RESIDENTIAL*
868 **DONELIA TRUJILLO**...*RESIDENTIAL*
868 **NHEARIEB BUSTAMANTE**...*RESIDENTIAL*
870 **KELLY BAKER**...*RESIDENTIAL*
870 **REESE & ADRIENNE BAKER**...*RESIDENTIAL*

2000 E PALACE AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

826 **ANTONIO E GRIEGO**...*RESIDENTIAL*
831 **ART COLE**...*RESIDENTIAL*
831 **D B SALSICH**...*RESIDENTIAL*
832 **MARIE JENKINS**...*RESIDENTIAL*
832 **PAUL DAVID FLETCHER**...*RESIDENTIAL*
833 **JAMES R DAUGHTRY**...*RESIDENTIAL*
833 **JOHN L STELLNER**...*RESIDENTIAL*
834 **CAROLE LAROCHE**...*RESIDENTIAL*
840 **J A STONE**...*RESIDENTIAL*
840 **M J LITTLE**...*RESIDENTIAL*
841 **WILLIAM YANDA**...*RESIDENTIAL*
845 **C SKEEN**...*RESIDENTIAL*
845 **M J MILLER**...*RESIDENTIAL*
845 **RANDALL MERKER**...*RESIDENTIAL*
845 **SALOMON LOVATO**...*RESIDENTIAL*
845 **TED LOVATO**...*RESIDENTIAL*
847 **MARK YANDA**...*RESIDENTIAL*
849 **RICHARD MONDIO**...*RESIDENTIAL*
849 **WARREN YOUNG**...*RESIDENTIAL*
853 **D S STREVER**...*RESIDENTIAL*
853 **PALACE GROCERY**
855 **DAVID LOVATO**...*RESIDENTIAL*
855 **PAUL SUNDOWN**...*RESIDENTIAL*
855 **STELLA L ORTIZ**...*RESIDENTIAL*
857 **ELEANOR LOBATO**...*RESIDENTIAL*
857 **MARY & TED LACAFF**...*RESIDENTIAL*
857 **MARY R LOBATO**...*RESIDENTIAL*
868 **PALACE LAUNDROMAT**
874 **E TRUJILLO**...*RESIDENTIAL*
876 **JACK PROBST**...*RESIDENTIAL*
878 **FRANK SR HALLA**...*RESIDENTIAL*

1996 E ALAMEDA ST

SOURCE: POLKS

E ALAMEDA ST cont'd

Address	Zip+4	CarrRte	Phone
275 ST FRANCIS CATHEDRAL SCHOOL			
	-2113	C040	982-0331
SUN WEST SVC	-2113	C040	989-1623
301 SHORT SET HAIR BOUTIQUE			
	-2289	C003	983-4406
303 INN ON THE ALAMEDA	-2229	C003	984-2121
324 Rabgay Pema	-2266	C003	820-0732
Thondup Paljor	-2266	C003	988-4142
331 Sanchez Mary I	-2229	C003	982-8025
335 Sandoval John R	-2229	C003	983-2430
337 Fogelman Cather	-2229	C003	986-1272
338 Alarid A	-2266	C003	988-2135
Alarid Brad	-2266	C003	986-9097
Alarid P	-2266	C003	988-2135
Alarid Pam J	-2266	C003	989-1742
Newman Todd	-2266	C003	984-8773
Oneill J	-2266	C003	986-8972
Ortiz K A	-2266	C003	988-2200
339 Ylm Leslie	-2229	C003	988-4597
341 Khalsa Kartar K	-2229	C003	984-2601
Kleinke Benjul	-2229	C003	986-1789
343 Duran Bernard A	-2229	C003	983-8896
351 Torres Gonzalo L	-2229	C003	820-6538
401 Viles L	-2202	C047	982-9917
403 Cantu Alfredo	-2202	C047	983-7644
Garcia L J	-2202	C047	982-1004
Willock Dolores	-2202	C047	982-2715
523 Scullin J S	-2203	C047	982-9955
Scullin Joseph	-2203	C047	982-9955
527 Scoggins T	-2201	C047	982-5607
528 Zarember Tami	-2231	C047	820-7719
540 Spiegel Austin	-2231	C047	988-3645
Spiegel Austin G	-2231	C047	983-0641
541 Funtanilla Victor	-2269	C047	984-1648
Hucko Bruce	-2269	C047	989-8562
Monette F	-2269	C047	984-1730
550 Weber Steven	-2231	C047	983-3832
564 ESTHER SUTIN STUDIO	-2231	C047	984-8716
605 Anderson Maria	-2204	C047	820-7816
607 Meyer Darrell	-2204	C047	820-7435
609 Darrington G	-2204	C047	820-6351
611 Burgess Helen	-2204	C047	983-1351
614 Treat J K	-2205	C047	986-9290
615 Schroeder Michael J	-2204	C047	988-9195
617 Johnson Jeff	-2204	C047	986-3467
618 Hayes M A	-2205	C047	989-1532
Herrera Patsy T	-2205	C047	983-3427
Katz Phillip	-2205	C047	982-8002
McCarthy Chelsea K	-2205	C047	820-1135
Stiles Barry E	-2205	C047	820-1135
624 Frissell Evelyn	-2237	C047	989-7844
Frissell William D	-2237	C047	989-7844
Gibson Charles A	-2237	C047	983-7786
Goldstein George	-2237	C047	986-8537
Hull Robert L	-2237	C047	988-3728
Lafarge Grant	-2237	C047	983-5104
Lafarge Grant	-2237	C047	988-5196
Lafarge Patric	-2237	C047	983-2358
Mason Gilbert A	-2237	C047	989-7395
McCune John R	-2237	C047	988-7425
Pence John	-2237	C047	982-1246
Salman David	-2237	C047	984-0781
Salman Marilyn	-2237	C047	984-0781
Sims Byron O Jr	-2237	C047	984-8158
Smith Layne	-2237	C047	983-7574
Smith Richard J	-2237	C047	983-7574
Smith Rick	-2237	C047	983-7574
Sullivan Lew	-2237	C047	983-1599
Sullivan Nancy	-2237	C047	983-1599
Wallace Edith	-2237	C047	984-3009
Williams Ralph	-2237	C047	988-9129
630 ERNESTO MAYANS GALLERY			
	-2205	C047	982-1999
Bobbs Howard	-2205	C047	983-5570
Castagnola Renee	-2205	C047	988-8974
Hlers Peter	-2205	C047	984-1421
Hurley Judith	-2205	C047	989-1935
Hurley Peter	-2205	C047	989-1935
Mayans Ernesto	-2205	C047	989-7312
Reed Elizab	-2205	C047	989-9620
Richardson Thadde	-2205	C047	989-8836
Thorndike John	-2205	C047	983-4073
Thurston Jeffrey A	-2205	C047	988-3905
633 Macneill Charles	-2204	C047	989-4587
Macneill Gale	-2204	C047	989-4587
637 Monahan T M	-2204	C047	983-3354
701 Mansell Gordon	-6418	C047	982-3603
705 Bloom David	-6426	C047	983-3294
Davis Paula	-6426	C047	983-2406
Jacobson David	-6426	C047	986-1579
Lasky Roeena	-6426	C047	983-7848
Meeker James W	-6426	C047	983-2853

E ALAMEDA ST cont'd

Address	Zip+4	CarrRte	Phone
Meeker James W	-6426	C047	984-8926
Morgan C	-6426	C047	988-9255
Omalley Brian P	-6426	C047	983-6834
Sanborn Matthew	-6426	C047	984-1557
803 Smith Alan	-2207	C047	983-9116
815 Fleck L	-2207	C047	984-0623
Huser Channi	-2207	C047	983-7851
Johnston Stewart	-2207	C047	983-7851
Muhs Chloe	-2207	C047	983-5780
817 McKenna Philip	-2207	C047	982-2763
Urffer Sallie	-2207	C047	986-1627
Valenzuela Gilber	-2207	C047	983-6278
827 Griego John	-2207	C047	983-3553
829 Griego Agustin	-2207	C047	983-7536
833 Banks Barbara	-2207	C047	982-1202
835 Banks Harold E	-2207	C047	982-2341
837 Gabaldon Miguel	-2207	C047	982-0296
839 Baros Gus	-2207	C047	982-0392
840 Bear Lynden	-2208	C047	982-9406
Pacheco Susan E	-2208	C047	988-1376
Rimbach Frank	-2208	C047	989-9031
Scholl B	-2208	C047	986-1213
841 Bove Paul W	-2207	C047	986-8576
Strong Ron	-2207	C047	988-2095
Young Blaine	-2207	C047	988-5105
868 Bustamante Nheari	-2208	C047	982-7792
Trujillo Donelia	-2208	C047	983-3004
870 Baker Adrien	-2208	C047	989-7248
Baker Kelly	-2208	C047	989-7248
Baker Reese	-2208	C047	989-7248
874 Thompson Jonath P	-2208	C047	982-7437
1001 JAMES JEREB DESIGN	-2284	C047	989-8765
Jereb James F	-2284	C047	989-8765
Mullen Jennif	-2284	C047	982-7285
Mullen Richard	-2284	C047	982-7285
1005 THEODORE WADDELL ASSOC			
	-2284	C047	983-1252
Macclellan B L	-2284	C047	982-0280
McMahan Jamie L	-2284	C047	982-0280
Summers A	-2284	C047	986-9745
Waddell Theodo	-2284	C047	988-2686
1115 Stuart Paul S	-2286	C047	988-5961
1117 Anaya Joseph E Jr	-2286	C047	982-3907
1122 Lindfors M	-2285	C047	983-7824
1131 Messick R	-2286	C047	983-9533
1145 Nakk Marrika A	-2286	C047	982-7555
1149 Shapiro Jay J	-2286	C047	982-4255
Shapiro Leigh	-2286	C047	982-1003
1169 Ohlsen Gerald G	-2286	C047	982-0310
Ohlsen Linnea D	-2286	C047	982-0310

BUSINESSES 13 HOUSEHOLDS 231

W ALAMEDA ST *(SF)* 87501

DOC'S SPEED ACRES	474-0253
SOUTHWEST SATELLITE	471-8831
TOP PLUMBING & HEATING	
	471-8192
Althouse Robert C	471-3900
Arguello Gloria	471-3044
Baldinger Louise	471-9070
Baucom Clifton D	473-2916
Beckman Frank	471-7961
Binette Margar J	473-9767
Borrego Placido	471-7712
Boylan Ed	473-5602
Burgel J A	471-4075
Caputo David	473-9294
Carnes Carol	438-6131
Catanach Patty	438-0063
Claggett Caroli	473-2621
Conway Jim J	471-5122
Cornett L L	471-3774
Cowell Raymond C	471-7716
Davis Blake	474-2877
Davis Dovie M	473-2243
Drake James R	471-3360
Elliott Alvin R	473-3658
Erdoes Eric P	438-8511
Farella A	471-1203
Forkin James	438-3066
Forkin Kris	438-3066
Gonzales David A	473-0449
Hansen R W	471-8090
Hartse Hans	473-9366
Head Ivan R Jr	471-8345
Head Patrick	438-0771
Hill Stanley	471-7693
Kenney Nancy	471-3900
Kesler Charles	471-1321
Koska David S	474-0813
Kruger Wolfga	471-8731
Lopez Garrett	473-0431

1996 E PALACE AVE

SOURCE: POLKS

E PALACE AVE

Address	Zip+4	CarrRte	Phone
LAND DESIGN SOUTHWEST	-2223	C019	982-0736
REGISTER & BACLAWSKI	-2223	C019	983-5566
Lovro David A	-2223	C019	982-0736
Rousselot Tina L	-2223	C019	982-0736
419 ANCIENT CITY ART CRATING			
	-2223	C019	984-3002
DAYLIGHT CHEMICAL INFORMATION			
	-2223	C019	989-1000
504 ACTION & LIFE PUBLICATIONS			
	-2226	C047	983-1960
508 Hensel Giselle	-2226	C047	989-4424
512 Goldstein John C	-2226	C047	988-1518
Paradise Susan	-2226	C047	983-2419
514 Lindsey Beth	-2226	C047	986-0601
529 ALEXANDER'S INN	-2200	C047	986-1431
531 Carpenter Laura L	-2200	C047	983-1925
McIngvale Dallas	-2200	C047	983-4869
McIngvale Diane	-2200	C047	983-1925
535 Kelly D T Jr	-2200	C047	983-9796
540 Mazurek Jeanma	-2226	C047	989-1976
542 Brodkey Benn D	-2226	C047	982-8670
Brodkey Karen	-2226	C047	982-8670
606 Gilman Chandl R	-2228	C047	983-5544
607 Follingstad Jim	-2227	C047	986-9263
608 Mui K C	-2228	C047	986-8388
610 Elling John	-2228	C047	820-1855
Farr M W	-2228	C047	983-3619
614 Bjorklund Alix	-2228	C047	986-9397
617 Barker Laughl	-2227	C047	982-4209
628 Romero Arthur R	-2228	C047	982-0127
629 Montoya Juan P	-2227	C047	983-7420
Montoya N	-2227	C047	982-5322
Zuniga Ricardo	-2227	C047	986-6092
632 Wagner G R	-2228	C047	984-1174
636 Boren Patric	-2228	C047	982-9349
640 Castner Olinda R	-2228	C047	982-5427
644 Hill J P	-2228	C047	986-8445
Notte Guerry	-2228	C047	986-8445
645 Camp Patric	-6410	C047	983-4961
Kaufman M	-6410	C047	989-9129
Moyano Sergio	-6410	C047	988-1952
Porter Doug	-6410	C047	984-0335
Sandoval Mike R	-6410	C047	982-8049
Vigil Melton Jr	-6410	C047	983-8768
651 Park Nancy	-2274	C047	984-1656
700 Northrup Charles	-2255	C047	983-5810
702 Gillespie Mary	-2255	C047	982-9628
704 Jackson C E	-2255	C047	983-2593
Jakobs Erwin	-2255	C047	982-2108
707 SITE SANTA FE	-2288	C047	989-1199
Andrews Alexan	-2288	C047	989-8168
Andrews Lynne	-2288	C047	989-8168
Anthony Richard	-2288	C047	986-6181
Anthony Toby	-2288	C047	986-6181
Ashbey William N	-2288	C047	984-8144
Barrow John M	-2288	C047	989-7991
Bevis M	-2288	C047	989-8168
Burnett Barbara	-2288	C047	989-9297
Burnett Donald	-2288	C047	989-9297
Cappuccio Angelo	-2288	C047	986-3435
Cappuccio Ginger	-2288	C047	986-3435
Cirino A L	-2288	C047	983-2432
Cole Eric	-2288	C047	982-9474
Collins John	-2288	C047	982-9251
Freeman E W III	-2288	C047	984-8134
Hall Edward T	-2288	C047	982-3203
Haynes Frank M	-2288	C047	989-9112
Josserand Robert D	-2288	C047	982-1426
Klauck J A	-2288	C047	988-8908
Kool Peter	-2288	C047	989-7894
Lowe Charles E	-2288	C047	982-5052
Martinez Richard L	-2288	C047	986-1846
Miller Brad	-2288	C047	989-9027
Miller Carol	-2288	C047	989-9027
Pilat Joseph F	-2288	C047	820-6839
Schreider H	-2288	C047	986-8453
Shick C J	-2288	C047	986-8937
Springsted Eric O	-2288	C047	986-8110
Zibart Rosema	-2288	C047	989-7991
708 Heyman Elissa	-2255	C047	982-3294
Lorton Julie C	-2255	C047	989-1536
716 Glassmire S H	-2255	C047	982-0270
720 Calles Eloy	-2255	C047	982-5643
729 Hoffberg Doral	-2254	C047	986-5377
Hoffberg Larry	-2254	C047	986-8548
Hoffberg Larry	-2254	C047	988-5377
Lord Patrick	-2254	C047	986-8519
802 Gordon Mark	-2257	C047	986-1257
Johnson Peter L	-2257	C047	986-1257
Schiff Kathryn L	-2257	C047	820-1122
806 Allen Jay	-2257	C047	982-1122

E PALACE AVE cont'd

Address	Zip+4	CarrRte	Phone
Allen Julie	-2257	C047	820-1122
810 Wegrostek Monica	-2257	C047	820-1361
Wegrostek Peter	-2257	C047	820-1361
Wilson Scott	-2257	C047	988-4866
815 Amirmoez Yassam	-2239	C047	982-5096
Austin Reid S	-2239	C047	983-7277
Bromberg Stephen	-2239	C047	983-1726
Counselman O L	-2239	C047	986-3480
Duval Leo A	-2239	C047	988-1002
Foote Merrill J	-2239	C047	988-3726
Frankenheim Nina	-2239	C047	984-2296
Frankenheim Samuel	-2239	C047	984-2296
Hilliard B P	-2239	C047	983-7896
Hoitsma Cather	-2239	C047	989-8956
Janis Eugenia	-2239	C047	983-9539
Jenkins N N	-2239	C047	983-3504
Kadis Rosanne	-2239	C047	984-0304
Mason Lara B	-2239	C047	989-1939
Mojarrabian V	-2239	C047	986-0545
Myers Juliet	-2239	C047	984-0304
Otopalik Brown H	-2239	C047	988-4832
Patton John	-2239	C047	988-1002
Sheedy David	-2239	C047	983-4750
Stine William	-2239	C047	982-8370
Ware C	-2239	C047	986-0545
823 Padilla Albert	-2256	C047	988-2250
Padilla Debra	-2256	C047	988-2250
826 Griego Antonio E	-2257	C047	983-7198
831 Cole Art	-2256	C047	988-4273
Salsich D B	-2256	C047	988-4273
832 Fletcher Paul D	-2257	C047	982-2015
Jenkins Marie	-2257	C047	982-5150
Sosa Maritza	-2257	C047	984-8751
833 Daughtry James R	-2256	C047	988-4216
Stellner John L	-2256	C047	988-4216
834 Laroche Carole	-2257	C047	986-1436
840 Little M J	-2257	C047	983-5473
Stone J A	-2257	C047	983-5473
841 Yanda Susan	-2256	C047	984-0098
Yanda William	-2256	C047	984-0098
845 Lovato Salomon	-2256	C047	982-0614
Lovato Ted	-2256	C047	988-4507
Merker Randall	-2256	C047	989-7192
Miller M J	-2256	C047	982-8958
Skeen C	-2256	C047	988-2251
847 ADOBE-SOLAR ASSOC	-2256	C047	984-0077
Yanda Mark	-2256	C047	984-8219
849 Mondio Richard	-2256	C047	983-2998
Mondio Richard	-2256	C047	988-4707
Young Warren	-2256	C047	983-2998
853 PALACE GROCERY	-2256	C047	983-9573
Strever D S	-2256	C047	983-9354
855 Lovato David	-2256	C047	983-8155
Ortiz Stella L	-2256	C047	982-0488
Sundown Nadina	-2256	C047	988-5716
Sundown Paul	-2256	C047	988-5716
857 Lacaff Mary	-2256	C047	986-8198
Lacaff Ted	-2256	C047	986-8198
Lobato Eleanor	-2256	C047	983-8633
Lobato Mary R	-2256	C047	983-7552
868 PALACE LAUNDROMAT	-2257	C047	984-0109
874 Trujillo E	-2257	C047	988-5064
876 Probst Jack	-2257	C047	983-3084
878 Halla Frank Sr	-2257	C047	983-8041
940 WISEMAN & GALE & DUNCAN			
	-2259	C047	984-8544
Hooker Richard T	-2259	C047	982-6776
Parsons David J	-2259	C047	982-6776
Shugard Leslee	-2259	C047	820-0339
Shugard Owen S	-2259	C047	820-0339
941 Welsh Daniel J	-2267	C047	982-2152
944 Vigil John L	-2259	C047	983-4210

BUSINESSES 117 HOUSEHOLDS 206

W PALACE AVE *(SF)* 87501

123 CONTEMPORARY SOUTHWEST GALLERY	
	-2045 C001 986-0440
124 CUSTOM BANKING OFFICE	
	-2015 C001 984-7732
FIRST NATIONAL BANK	-2015 C001 984-7734
128 WADLE GALLERIES LTD	-2015 C001 983-9219
129 ELAINE HORWITCH GALLERIES	
	-2045 C001 988-8997
130 MOUNTAIN TRAILS GALLERY	
	-2051 C001 983-2332
SHANNON'S	-2051 C001 982-9757
132 STAN BERNING GALLERY-STUDIOS	
	-2056 C001 988-7274
135 CHICO'S	-2072 C001 984-3134
CHICO'S INC	-2072 C001 984-3134
CHUCK JONES SHOWROOM	
	-2072 C001 983-5999

1993 E ALAMEDA ST

SOURCE: POLKS

11 Wallace Edith [2] 984-3009
12 Freeman Jas L [2] 984-0835
13 Williams [2]
14 Stevens John [4] ◎ 988-7424
14 Story Ron 988-7424
16 La Farge C G [3] 983-2358
16 La Farge D [8] 983-5104
17 Mason [2]
18 Sims [2]
630 Bobbs Elspeth [9]+ ◎ 983-5570
Apartments
A Reed Betsy L [2] 989-9620
B Thurston Jeffery A [9]+ 988-3905
C Richardson Thaddeus [2] 989-8836
D Not Verified
E Ingle Jon [5] 983-5786
F Castaqwola Renee [2] 988-8974
H-630 Not Verified (3 Apts)
K Myans Ernesto [2]
633 Not Verified
635 Harrick Lee [3]
635½ Ellis Oren [3] 984-2671
637 Byrne Kirsten A [2] 983-9150
701 Apartments
1 Not Verified
2 England Nancy T [2]
3★Goler Raul
4★Unger Jas L & Solveiga ◎ 983-6994
703 Not Verified
705 RIVER OAKS THE custom apts 983-2853
1★Fallon Joanne 932-0427
2★Davis Paula 983-2406
3 Lasky Roeena [2] 983-7848
4 Meeker Jas N [2] 983-2853
5 Momaday Brit [2] 986-2017
6★Cushman David W 988-5714
7-705 Not Verified (2 Apts)
9 Hagler Barbara J [3] 984-0781
10 Berry Raymond R [2] 986-5845
• EL ALAMO ST INTERSECTS
801★Moya Don D Jr 986-9865
Padilla Carmella 986-9865
803 Scott Michl [2] 986-9705
805 Not Verified
816 Apartments
1 Muhs Chloe D [4] 983-5780
2 Adams Jack [5] 984-1776
3 Gould Wm R [2] 986-8701
4 Vacant
5 Rostro Rudy [8] 988-2556
817 Apartments
1 Not Verified
2 Urffer Sally S [4] 986-1627
3 Not Verified
4 Thompson Jas [2]
5 Mc Kenna Philip [3] 982-2763
827 Griego John & Josefita B [9]+ ◎ 983-3553
829 Griego Augustine [9]+ ◎ 983-7536
Saiz Lucy C 983-7536
Saiz Rosarita 983-7536
Slaz Delores A 983-7536
833 Banks Barbara J [9]+ 982-1202
835 Banks Harold E [9]+ 982-2341
837 Gabaldon Miguel B [9]+ 982-0296
839 Baros Augustin B & Mary R [9]+ ◎ 982-0392
840 Apartments
1 Bear Lynden [2] 982-9406
2 Carter Jo [3] 988-9542
3 Rimbach Frank [2] 989-9031
4 Not Verified
5 Stevens Walt E [5] 988-2659
841a Young Blaine [5] ◎ 988-5105
Rfasoner Jennifer 988-5105
841b-841d Vacant (3 Hses)
868a Robrin Jan [2] 988-9749
868b Conner Thos [2] 988-9749
868½ Trujillo Donella [4] 983-3004
870 Anderson Stevan T [2] 988-7033
Haygood Bill C [2] 984-1469
874 Adams J [3] 988-3018

• E PALACE AV INTERSECTS
1001 Jereb James [2] ◎ 989-8765
1005 WADELL THEODORE & ASSOCIATES archts 983-1252
ALMEDA HILL CONDO ASSOCIATES 983-1252
Waddell Theo H & Eleanor H [2] ◎ 988-2686
1005b Vacant
1005 Summers Ann [2] ◎ 986-9745
1005n Vacant
1009 Not Verified
1010 Vacant
1115 Sena-Stuart Edielinda T [5] ◎ 988-5961
Diego Micheal 988-5961
Sena-Stuart Paul 988-5961
1117 Anaya Jos E Jr [9]+ ◎ 982-3907
1120 Not Verified
1122 Lindfor S M [2] ◎ 983-7824
Rear★Crowley M 984-0639
1127 Levine [2]
1131★Lehman Max 984-1573
1133 Ruiz Carlos [2] 982-4897
236 HOUSEHOLDS
12 BUSINESSES

ALAMEDA ST WEST –FROM 100 DON GASPAR AV WEST TO CITY LIMITS

• ORTIZ ST INTERSECTS
• ZIP CODE 87501
• GALISTEO INTERSECTS
100 SANTA FE RIVER PARK city ofc
213 CHEZ WHAT night club 982-0099
• SANDOVAL INTERSECTS
• GUADALUPE INTERSECTS
425-427 Vacant (2 Businesses)
451 NOON WHISTLE THE restr 988-2636
• WATER ST INTERSECTS

• DEFOURI INTERSECTS
• CAMINO DEL CAMPO INTERSECTS
500 City Public Housing Site A
501 Salazar Willie S & Kathy [2] 984-0709
502 Chavez Jose [2]
503 Not Verified
504 Labar Pat [2]
505★Rivera Jerry
506★Roybal Audelia
507 Wheeler Flora C [9]+ 982-4951
Wheeler Paul [2]
509★Maes Amado A
511★Molosky Bertha 982-3180
513 Aragon Cipriano [2]
• CANDELARIO INTERSECTS
525 SALVATION ARMY THE church 988-8054
530 Apartments
A Moore Deborah L [2] 989-7491
B Dearth Jayne A [3] 984-0796
C Englander Ron [2] 983-4125
D Penn Joyce [2]
E★Williams John
3 Williams Cynthia
532 Salemi Steph [2] 982-6101
532b-532½ Not Verified (2 Hses)
534 Montoya Ramon [9]+ ◎ 982-1259
Montoya Elmer T 982-1259
Montoya Diane M [2]
534½ Shook James & Jovita [9]+ ◎ 983-8661
536★Lozoya Rosa
536½ Not Verified
538 Ponce Emily [2] ◎ 982-1217
538½ Quintana Jean [2]
• CANDELARIO ST INTERSECTS
600a-600b Not Verified (2 Hses)
604 Marroquin Gladys [2] 988-7052
Leonardo Samara 988-7052
613 Oroszco Stella [2] ◎ 986-8101
615★Creelman Peggy ◎ 989-8652
615½ EL BIENESTAR accupunture
★Walker Steven
617 Vasquez Angel J & Elvia G [7] 983-7958
619★Rael Betrocina ◎ 982-8876
619½ Montano Bonifacio & Reyes plaster contr ◎ 988-5266
627½ Carrillo Carmen [2]
627 MARKET PLACE THE natural foods 984-2852
701 Waterman Charles E [8]
703 Gutierrez Frank [2]
705 Romero Marty & Teresa [2]
707 Roybal Stella [2]
709 Duran Manuel J & Gloria P [9]+
711 Trujillo Patricia I [7]
713 Roybal Juan & Grace [8]
715 Erwin Ralph [9]+
716 Chavez Frances [8] 986-1607
Chavez Ines 986-1607
717 Boydston Joyce P [2]
718 Vigil Francis [3] 988-2297
Vigil Dale 988-2297
719 Jaramillo Joe & Connie [2]
Jarmillo Patsy
720★Segura Ramon & Luces 983-2189
Segura Luces 983-2189
Segura Johnny 983-2189
721 Gutieriez Nicholas J & Patty A [2]
722 Not Verified
723★Noriega Julieniana 984-0630

1993 E PALACE AVE

SOURCE: POLKS

4 Freeman E W III & June [2] 984-8134
5 Not Verified
6 Eber Marilyn [4] 988-1746
7-707 Not Verified (2 Apts)
9 Martinez Richd L & Michele [4] ◎ 986-1846
10★Summers Tom B & Carolyn G 986-8694
11 Not Verified
13 Hall Edw T & Mildred [4] 982-3203
14 Not Verified
15★Schreider H 986-8453
16-707 Not Verified (3 Apts)
19 Wester [2]
20 Barrow John M [4] ◎ 989-7991
20 Zibart Rosemary 989-7991
21 Padwa David [2] ◎
23 Holliday Philip J [2] ◎ 988-9736
24 Vacant
25 Andrews Alexander S & Lynne B wrtr 989-8168
26 Cappuccio Angelo & Ginger [2] ◎ 988-3435
27 Josserand Robt D [4] 982-1420
28 Klauck J A [4] 988-8908
29 Not Verified
30 Schoenke Ray [3] 983-9296
31-707 Not Verified (3 Apts)
34★Minkin Richd D & Bobbie 983-0543
35 Lowe Chas E [2] 982-5052
708a Corbus Barbara [2]
708b Wilkinson Dell A [2] 989-8157
• EL ALAMO INTERSECTS
716 Glassmire Saml H Jr & Norma E [9]+ ◎ 982-0270
720 Calles Eloy [9]+ ◎ 982-5643
729 Lord Patk [2] ◎ 986-8319
• LA VEREDA INTERSECTS
802 Griffin Robt R [2] 986-1807
Siddall Gina 986-1807
Yelder Sharon 986-1807
806 Sherwood Cecil D & Fae [9]+ ◎ 983-9647
810a Not Verified
810b★Marchesi Donna
810c Not Verified
810d Baumon Mark [2]
815 LLANO COMPOUND apts & townhouses Units
1 Silverman Jack [9]+ ◎ 982-6722
2 Kleeb Robt H [2] ◎ 989-8535
3 Not Verified
4★Kaplan Jim & Tini ◎
5-815 Not Verified (3 Apts)
10★Denton-Davis Bromven authors & composers ◎
8★Mojarrabian Vahid 988-0545
9 Hoitsma Cath M [4] ◎ 989-8956
10★Davis Jefferson ◎ 986-0890
11 Not Verified
12 Duval Leo A [9]+ ◎ 988-1002
13 Not Verified
14 Parker Mark [2] 983-9687
15★Ging Robt C & Linda ◎ 989-8672
16 Not Verified
17★Mason Laura B ◎ 989-1939
18 Handey Jack W [5] ◎
19 Kincaid Pat [2]
20 Jenkins Newell N [9]+ ◎ 983-3504
21 Janis Eug [2] 983-9539
22 Not Verified
23 Mc Cormick Melissa [4]
25-815 Not Verified (2 Apts)
27 Otopalik Brown H [9]+ ◎ 988-4832
28 Bonaguidi Lawrence P [5] ◎
30 Not Verified
31 Vacant
Foote Merrill [2] 988-3726
823 Vacant
825 Not Verified
825½ Ringham Kristen [2] ◎ 983-3936
826 Griego Antonio E & Carmen A [9]+ ◎ 983-7198
Griego Andrew 983-7198
Griego Veronica 983-7198
Griego Vincent 983-7198
829 PALACE YOUTH CENTER 984-6771
831-831 Not Verified (2 Hses)
832 Not Verified
A-832 Not Verified (3 Apts)
833★Daughtry Jas R 988-4216
Stellner John L 988-4216
834★La Roche Carol ◎ 986-1436
836a Not Verified
836b Peterson [2]
838 Vacant
838½-839 Not Verified (2 Hses)
839½ Mc Math Jim [2] 982-9185
840 Little M J [2] 983-5473
841 Yanda Wm & Susan [4] ◎ 984-0098
841½b Miller [2]
A★Lovato Tony
845 Mc Kinney [2]
841b Miller Margt T [2] ◎ 983-3837
845c Lovato Ted [2] 988-4507
845½ Merker [2]
Lovato Salomon & Elviera F [4] 982-0614
849½ Not Verified
A★Risbourg
853 PALACE GROCERY 983-9573
B★Strever Sage
B Vigil Jos
855 Lovato David & Mary [9]+ 983-8155
855a Sundown Paul & Nadina B artist 988-5716
855b Ortiz Stella L [2] 982-0488
857 Canuto Mary R [2] ◎ 983-7552
857b Lobato Eleanor elderly care 983-8633
857c Lobato Mary [2]
859 Foyt Otto [2] ◎ 982-5628
863a Deyo Janet E [4] 983-1939
863d Vacant
868 Vacant
• CERRO GORDO RD INTERSECTS
873 Not Verified
874-875 Vacant (2 Hses)
876 Probst Jack S & Marlene C [9]+ ◎ 983-3084
877 Vacant
878 Halla Frank S [7] 983-8041
880 Gray Barbara H [4] 988-7582
883 Mead D G [2] ◎ 988-2981
885 Vacant

10
• ALAMEDA INTERSECTS
940 Vacant
940½ Parson David J artist ◎ 982-6776
Hooker Richd T artist 982-6776
941 Vacant
944 Vigil John L [9]+ ◎ 983-4210
Vigil David D 983-4210
• CANYON RD INTERSECTS
150 HOUSEHOLDS
103 BUSINESSES

3
PALACE AV WEST –FROM 100 WASHINGTON AV WEST TO GRANT AV

• ZIP CODE 87501
105 PALACE OF THE GOVERNORS 827-6483
• LINCOLN AV INTERSECTS
107 MUSEUM OF NEW MEXICO museum 827-4470
• SHERIDAN AV BEGINS
123 CONTEMPORARY SOUTHWEST GALLERIES art 986-0440
124 FIRST NATIONAL BANK custom ofc 984-7734
125 HORWITCH ELAINE GALLERIES overflow
128 WADLE GALLERIES LTD 983-9219
129 HORWITCH ELAINE GALLERIES art 988-8997
130 ANDREW SMITH SHIPPING DEPARTMENT
130c SUSIE'S PATIO RESTAURANT 983-3245
131 HORWITCH ELAINE GALLERIES overflow
132 STAN BERNING STUDIOS art gallery
SUSIE'S PATIO CAFE restaurant 983-3245
ROSS DAVID STUDIO art mfg & sls 988-4017
135 PALACE COURT BUILDING
Suites
100 CHICO'S INCORPORATED casual cloret 984-3134
101 MONTEZ GOLD jwlry 983-9449
102-135 Vacant (4 Businesses)
200 MUCHO THE GOURMET SANDWICH SHOPPE 988-2223
210 COLLECTIONS GALLERY art gallery
212 COLLECTIONS GALLERY addl sp
300 EDGE restaurant discotheque 986-1700
STREET CONTINUED
142 BOKUM BUILDING 983-9265
PALACE RESTAURANT 982-9891
Suites
100 Vacant
101 PARKER BOOKS OF THE WEST books retail 988-1076
102 PALACE RESTAURANT ofc 982-9891
103 STORAGE
200 FIRE MARSHAL ofc
300 GREAT WESTERN DEVELOPMENT CO real est 982-1816
• GRANT AV INTERSECTS
• BURRO ALLEY INTERSECTS
18 BUSINESSES

19
PALOMINO ST –FROM 1513 AGUA FRIA SOUTH TO DEAD END

• ZIP CODE 87501
301 Not Verified
303 Sondheimer Joshua [2] 988-5177
Oakley Kelly J 988-5177
306 Ortiz Geo R & Anita [9]+ ◎ 982-3206
307 Gonzales Charles L & Ruperta [9]+ ◎ 983-5255
309 Salazar Bernie [2]

1988 E ALAMEDA ST

SOURCE: POLKS

10★Huel Robt @ 988-3728
11 Vacant
12★Whittenburg Eug 988-8010
13 Williams
14★Stevens Story
16 La Farge G
17★Mason Gilbert A 989-7396
18★Sims Byron O Jr 984-8158
19 No Return
630 Bobbs W Howard 983-5570
Apartments
A★O'Neill Jas 984-0378
B Thurston Jeffery A 988-3905
C Swarth Judith 982-8640
D Burt Kim 988-4497
E Ingle Jon 983-5786
F Olmstead Chas
G★Kinslow Paul 989-8050
H Kirtley Hazel
I No Return
633★Yeager Fredk @ 986-0611
635 Simkins A C 984-3116
637 Barber Mary W Mrs @ 983-9150
CAMINO ESCONDIDO INTERSECTS
701 Apartments
1★Rogers Gail 988-1315
2 Topia Jos 983-7369
3★Dimeff Carol S 984-0750
4 Aranda Patrick
705 River Oaks The custom apts 983-2853
1 Tsukahara Masaru
2★Fisher Jean A
3★Gross Ann E 988-7134
4★Reed Hope
5★Lujan Cynthia M 986-0936
6★Lowe Constance 986-1413
7★Fugiwara Toshihisa 988-2038
8★Augustine Judith 984-2723
9★Garnett D
10★Jenkins M G 982-4308
801★Lubet Lloyd 989-9239
803★Duffy Terry 988-1034
805★Bennett John S 989-9044
815 Apartments
1★Muhs Chloe 983-5780
2 Adams Jack
3★Digneo Bernadette 988-5303
4 Wagner Patti L 982-1609
5 Rostro Rudy 988-2556
817 Apartments
1★Reichstein Gail
2★Urffer Sally 986-1627
3 Vacant
4 Mc Kenna Philip 982-2763
5 Vacant
827 Griego John @ 983-3553
829 Griego Augustine @ 983-7536
833 Banks Michl @ 982-1202
835 Banks Harold E @ 982-2341
837 Gabaldon Miguel B @ 982-0296
839 Baros Augustin B @ 982-0392
840 Apartments
1 No Return
2★Corter Joe 988-9542
3★Hafer Mariannn 989-7495
4★Collins Wm M 988-4918
5 Stevens Walt E 988-2659
841a Young Blaine @ 983-3791
841c★Kanter Joel E 989-7846
841b Strong Ron W 988-2095
868a Stark Thekla @ 988-1573

E ALAMEDA ST–Contd

868b Pilgrim Wesley @ 988-4206
868½★Trujillo Donelia 983-3004
870 Montoya Joe S @ 983-4436
874 Vacant

10

E PALACE AV INTERSECTS
1001 Smith Kip F @ 983-3825
1005 Zedderlen Roger
Waddell Theodore Guest Houses 988-2686
★Brecher Jas 982-4660
Stanley Sara W 984-1838
1010 No Return
1115 Sena-Stuart Paul @ 988-5961
1117 Anaya Jos E Jr @ 982-3907
1120 Wright Gorden 988-5049
1122 Linfors M @ 983-7824
Rear★Casey Wm
1127 No Return
1131 Pecos Veronica
Mireles Angie S 988-8957
1133 Corliss S 988-7147
1135 Vacant

1

ALAMEDA ST WEST –FROM 234 DON GASPAR AV WEST TO CITY LIMITS

ZIP CODE 87501
GALISTCO INTERSECTS
100 Santa Fe River Park city ofc
N JEFFERSON INTERSECTS
HANCOCK ST INTERSECTS
213 Club West night club 982-4523
425 Vacant
427 Vacant
451 Noon Whistle The restr 988-2636

7

DEFOURI BEGINS
CAMINO DEL CAMPO BEGINS
500 Public Housing Site A (Ofc)
501 Duran Willie G 982-8702
502 No Return
503★Barela Roman
505 Encinas Connie 982-2750
507 Wheeler Flora C 982-4951
509 Maes Amado 983-1923
511 Sanchez Clara
513★Valdez Emado
CANDELARIO BEGINS
524 Cordova Kathrin
525 Salvation Army The church 988-8054
530 Apartments
Goodman G C 983-3462
B No Return
C★Harris M 983-2270
D★Donahue Peter 984-8532
E★Roybal M R 982-2134
532★Thomas Sandra J 982-6151
532b Marion John B 988-1860
532½ Copley Michl @ 983-5438
534 Montoya Ramon @ 982-1259
Rear★Montoya Rick 982-9750
534½ Shook Jim @ 983-8661
536 Silva Jake @ 983-3113
Losoya Carlota
538 Ortiz Emily @
538½ Quintana Jean G

1988 E PALACE AVE

SOURCE: POLKS

E PALACE AV–Contd

7 Herter Susan 455-7852
8 Day Sally 984-1390
9★Holtsma Cath M
10 Schultz Miriam 983-3990
11 Vacant
12 Duval Leo A 988-1002
13 Stevens Riki 988-2558
14★Bomberg Steph 983-1726
15 Vacant
16 Vacant
17 Hull Brandon @ 983-2337
9 Handey Jack W writer 989-8685
20 Jenkins Newell N 983-3504
21 Vacant
22★Hilliard B P 983-5060
23★Mc Cormick Melissa 982-9453
25 No Return
26 Baten Michl @ 988-1223
27 Otopalik Brown H @ 988-4832
28 Bonaguidi Lawrence 982-9337
30 Vacant
31 Vacant
823 Emerson Joan investor @
825 Vacant
825½ Garcia Thos G @ 982-8729
826 Griego Antonio E @ 983-7198
828 Palace Youth Center 984-6771
831 Morgan Eva P 983-1276
Stevens Jos E 982-8033
832a★Holt Robt
832b Jenkins TV & Radio Sales & Service 983-9146
832c★Sanchez Larry
833 Vacant
834 Vacant
836a Humco Incorporated 982-0400
836b Vacant
838 Lopez Max Mrs @ 982-2321
838½ Vacant
839★Mc Phern Robt
839½ Rael Frances M @ 983-9252
840★Betts S L 982-4239
841★Yanda Wm 984-0098
841½★Yanda K S 989-7607
845★Baker Joan 983-8067
845½ Miller Geo L @ 983-3837
★Clark Geo L 988-5926
★Crimmel C 982-6810
★Lovato Salomon 982-0614
★Lovato Ted 988-4507
845½c★Stone Warner 988-1322
853 Palace Grocery 983-9573
855 Lovato David 983-8155
855a Sundown Paul 988-5716
855b Oritz Stella L 982-0488
855c Lovato Teodoro @ 988-4547
857 Lobato Mary R @ 983-7552
857½★Bird Pauline
Rear Lovato Bernie
859 Metcalf Sheila T 982-5058
863a Deyo Janet E 983-1939
863b Bloom David 983-3294
864 Vacant
868 Palace Laundromat 984-0109
CERRO GORDO RD BEGINS
873 No Return
874 Trujillo Plumbing & Heating 983-1468
Trujillo Max @ 983-1468
875 Dealey Kenneth Mrs
876 Probst Jack @ 983-3084
877★Dealey Trigg 982-2247
878 Halla Frank S 983-8041
878½ No Return
880★Gray Barbara H 988-7258
883 Redding Bud @ 982-3589
885★Westergren Susan

10

ALAMEDA INTERSECTS
940★Romero Mary Z @ 982-4097
940½★Hooker Richd T 982-6776
944 Vigil John L @ 983-4210
CANYON RD INTERSECTS

3

PALACE AV WEST –FROM 100 WASHINGTON AV WEST TO BURRO AL

ZIP CODE 87501
1 State Office Of Cultural Affairs palace of the governors 827-6483
LINCOLN AV INTERSECTS
107 State Office Of Cultural Affairs 827-4468
SHERIDAN AV BEGINS
123 New Mexico Banquest Corporation chairman's ofc & loan dept 984-7592
New Mexico Banquest Corporation 984-7422
New Mexico Banquest Corp custom banking ofc 984-7734
124 Delgado Building
124 New Mexico Banquest (Addl Sp)
125 New Mexico Banquest (Addl Sp)
128 Wadle Galleries Ltd 983-9219
129 Horwitch Elaine Galleries art 988-8997
130 Anasazi Arran 983-4653
Downtown Subscription news dlrs 983-3085
131 American Parking Inc lot
132 Discover Santa Fe Inc jewelery & gifts 984-8484
Shannon's Of Santa Fe women's clo 982-9757
Ross David Studio art mfg & sls 988-4017
135 Club Cielo cocktail lounge 986-0566
142 Bokum Building
Palace Restaurant 982-9891
Suites
100 Vacant
101 Parker Books Of The West books retail 983-1076
102 Vacant
103 Vacant
200 Schutz & Co
300 Great Western Dev real est 984-0818
GRANT AV INTERSECTS
BURRO ALLEY INTERSECTS

19

PALOMINO ST –FROM 1513 AGUA FRIA SOUTH TO DEAD END

ZIP CODE 87501
301 Gurule Rick
303★Fresquez Leo 983-3457
306 Ortiz Geo R @ 982-3206
307 Gonzales Charles L @ 983-5255
309★Salazar J @
311 Romero Florentina Mrs @ 983-2638

1983 E ALAMEDA ST

SOURCE: POLKS

10★Weeks Danl
11★Idar Ed
12★Bickley Nancy 982-6795
540 Espejo Juan ◎
541 Apartments
A★Delgado Fred
B No Return
C★Lovald Ruth
D Kenrr Tod
550 Crumm John C 982-1473
564★Daly Richd M ◎
CAMINO ESCONDIDO BEGINS SS
609 Vacant
611 Secretary Bird The 988-9180
614 Reynolds Stephen E ◎ 982-5140
615 Markin Meade 982-5647
616 Rodriguez Felix ◎
616½a Wysong Wiona E
617 Vacant
618★Kirby Ken 982-6163
★Matson Pamela H
Rear Herrera Patsy Mrs 983-3427
Apartments
1 Croy Donald D ◎
2★Klotsche Charles 988-1700
3★Dant J R 983-8372
4 Vacant
5★Fries John G
6 Vacant
7 No Return
8★Treisman Eric 983-3033
9 Vacant
11 Vacant
12 Vacant
13★Edmundson J
14 No Return (apts 14-16)
17 Vacant
18 No Return
10★Charnas Juliet 983-1754
630 Apartments
Bobbs W Howard 983-5570
A★Reed Eliz 983-5091
B Thurston Jeff 988-3905
C★Lancaster J M 988-1801
D★Redding Geo H III 983-6076
E★Moore Jane
F Armstrong Michl 983-6680
G★Dillon Nancy P
H★Kimball Tracey
I Vacant
633 Vacant
637 Barber Mary W Mrs ◎ 983-9150
CAMINO ESCONDIDO INTERSECTS
705 Villa Alameda Apartments
1★Fox Elliot 984-1610
2★Weiland W C 988-3465
3 De Vito Janis
4★Bonifer Steven
5 Maremont Steve
6★Good Jack
7★Stebbins Don 983-1720
8★Young Richd L 982-8900
9 Sigunak Sally

E ALAMEDA ST—Contd
10 Gurdo Wally
801★Hunter Tim 982-3084
803 Vacant
805 Golaria Arguero
815 Apartments
1 Baker Greg 988-1825
2 Vacant
3★Bond Gordon
4 Vacant
5 Rostro Rudy 988-2556
817 Apartments
1★Garcia Joe
2★Segura Victor 988-6110
3 Mc Intee Tim
4★Mc Kenna Philip 982-2763
5 O'Schaughnessy Gary 982-0519
827 Griego John ◎ 983-3553
829★Griego Augustine ◎ 983-7536
833 Banks Michl ◎ 982-1202
835 Banks Harold E ◎ 982-2341
837 Gabaldon Miguel B ◎ 982-0296
839 Baros Augustin B ◎ 982-0392
840 Apartments
1 Stevens Walt 988-2659
2★Wynn Meridee
3★Lee Jack
4★Wood Clayton 983-7781
5 Browne Elizabeth T 983-1070
868 Whiteridge Jackie ◎ 988-9252
A Dorman
B Hernandez
868½ Trujillo Donelia ◎ 983-3004
870 Montoya Joe S ◎ 983-4436
874 Phillips Steph B 982-1080

10

E PALACE AV INTERSECTS
1001 Smith Kip F 983-3825
1005 Waddell Theo H ◎ 988-2686
Apartments
1★Underwood Betty
2 Vacant
3 Halla Frank Z 983-8041
1010 Abeyta Tony ◎ 983-8665
1115 Sena Louis A ◎
1117 Anaya Joseph E ◎ 982-3907
1120 Morris Robert E ◎
1122 Bell David ◎ 982-8715
1127 Vacant
1131 Mireles Angie S 983-6243
1133 Shirley Wayne 982-3825
1135 Abeyta Gilbert R

1

ALAMEDA ST WEST —FROM 234 DON GASPAR AV WEST TO CITY LIMITS

ZIP CODE 87501
GALISTCO INTERSECTS
100 Santa Fe River Park
N JEFFERSON INTERSECTS
HANCOCK ST INTERSECTS

1983 E PALACE AVE

SOURCE: POLKS

E PALACE AV—Contd
533 Dockweiller Marian 982-0007
535 Kelly Daniel T Jr ◎ 983-9796
606 Gilman Chandler R ◎ 983-5544
607 Streeper Richd B ◎
608 Vacant
610a Vacant
610 Vacant
614 Barrow Lynda 983-4516
616 Hammond Katherine Mrs 983-4076
617 Barker Laughlin ◎ 982-4030
628 Romero Arthur R ◎ 982-0127
629 Apartments
1 Montoya Johnny M ◎ 982-5332
2 Sisneros Stella
3★Kuren Steve
4★Schiels Patk
5★Scharse Eliz 983-9707
6★Baca Phillip
RODRIQUEZ ST INTERSECTS
636 Vacant
638 Vacant
639 Gilliam Julian 988-4352
640 Castner Olinda R Mrs ◎ 982-5427
644 Vacant
645 Vigil Milton Jr ◎ 983-8768
Sandoval Michl 982-8049
645a Romero Victor G ◎ 983-1884
645b Spears Beverly 982-4926
645c Rael Andres S
D★Summers Marsha
645e Bibo B A 983-7793
645½ Saenz Severiana 982-8720
651 Mc Convery Electa P Mrs ◎ 983-4528
700 Reust Josephine P ◎
702 Potts Marianne ◎ 988-5632
★Gorhan Danl
704 Pollack Lewis 982-0824
705 Schleider Anne
LA VEREDA BEGINS
706a Halstead Mike 983-7938
706b Grant Gerald M 988-2585
707 Under Constn
708 Jacobs James 988-1385
EL ALAMO BEGINS
716 Glassmire Saml H Jr ◎ 982-0270
720 Calles Eloy 982-5643
729★Wilson Warren ◎ 988-4368
729½ Vacant
LA VEREDA ENDS NS
802 Tapia Annie Mrs ◎ 983-6715
806 Sherwood Cecil ◎ 983-9647
A No Return
D★Berry Debra
810d★Sherrard Robt
815 Apartments
1 Silverman Jack 982-6722
2 Mc Culloch Scott P 983-9596
3 Boswell William
4 Vacant
5 Vacant
6 No Return
7 Miller M Laurence 982-0327
8 Slaughter Glenn
9 Bragdon Allen
10 Vacant
11 Councilman Orville
12 Duval Leo 988-1002
13 Stevens Riki 988-2558
14 Conley Zeb B Jr 988-2500
15 Ging Robert C 983-2983
16★Wood Michael W 982-5090
17 Hull Branden ◎ 983-2337
19 Mitchell Kelvin L
20 Jenkins N N
21★Bussell Joe 988-3377
22 Hilliard B P 983-5060
23 Vacant
25 No Return
26 Baten Michael 988-1223
27 Otopalik Brown H ◎
28 Shupp Donald W
31 Galen Nina 988-3008
823 Daly M Kathrine ◎ 983-7135
825 Vacant
825½ Garcia Thos 982-8729
826 Griego Antonio E ◎ 983-7198
828 Palace Youth Center 982-0114
831★Dealey Kenneth T 982-1772
832a★Williams Karen
832b Jenkins TV & Radio Sales & Service 983-9146
832c Diehl Larry
833 Alderete Alphonso N ◎ 983-5613
834★Grey J 988-2675
836★Haney Wm T 988-7145
838 Lopez Max L ◎ 982-2321
838½ Callarman Lesley
839 Rossiter Robt Jr
Rear Rossiter Robt 983-9252
840 Vacant
841 Vacant
845 Vacant
845½a Miller Margaret
845½b Lavoto Salomon 982-0614
853 Palace Grocery 983-9573
855 Lovato David
Thomas Arth 983-2398
855a Oritz Stella 982-0488
857 Lovato Mary R ◎ 983-7552
857½ Vacant
Rear★Campbell Jamie 984-0154
859 Vacant
A Deyo Janet 983-1939
B Vacant
864★Hernandez M D ◎ 988-1114
868 Palace Laundromat
CERRO GORDO RD BEGINS
874 Trujillo Plumbing & Heating 983-1468
Trujillo Max ◎ 983-1468
876 Probst Jack ◎ 983-3084
880 Powell Esther 983-1659
883 Swanson Lois ◎ 982-3589
885 Vacant

10

1978 E ALAMEDA ST

SOURCE: POLKS

E ALAMEDA ST—Contd
630 Apartments
A Bobbs W Howard 983-5570
A Moore Jane
B Johnstone James C
C Johnson David
D Kelly Maria
E Leonard Jeanne 983-1327
F Bobbs Sheila 983-6680
633 Blythe School 983-1034
637 Barber Mary W Mrs © 983-9150
CAMINO ESCONDIDO INTERSECTS
705 Villa Alameda Apartments
1★Norman Rae 988-1011
2 King Herbert A 983-1049
3 De Vito Janis
4 Bodenhamer Jerry L
5★Fisher Thellan
6★Forrer K 982-0744
7 Vacant
8 Stokie Glen
9★Velasquez Robt
★Lujan P J 983-2630
801★Koch Karen
803 No Return
805 Vacant
815 Apartments
1★O'Shaughnessy Gary
2★Alcott Margt 983-2996
3★Lujan Sostella
4★Vigil Joanne 983-5096
5★Moreno Al 983-5235
817 Apartments
1★Weber Kurt 988-1795
2 Painter Ernest
3a Murphy Dennis P © 988-2383
3b Vacant
4 Coy Lillian B
5★Kellogg Kara 983-3135
827 Griego John © 983-3553
829 Saiz Narciso © 983-7536
835 Banks Harold E © 982-2341
837 Gabaldon Michl B © 982-0296
837½ Berthrong Sonja 983-4867
839 Baros Augustin © 982-0392
840 Apartments
1 No Return
868★Ambrose C 983-2286
868½ Ortiz Donelia ©
870 Montoya Joe S © 983-4436
874 Phillips Steph B 982-1080

10

E PALACE AV INTERSECTS
1005 Griffith J W © 983-8204
1115 Sena Louis A © 988-5961
1117 Anaya Joseph E Jr
1120 Gross Mari © 983-5184
1122 Buffington Robt O ©
1127★Sloan Jeff
1131 Roybal Lorenzo © 983-6243
1133 Hubbard Karen

1

ALAMEDA ST WEST —FROM 234 DON GASPAR AV WEST TO CITY LIMITS

ZIP CODE 87501
GALISTCO INTERSECTS
100 Santa Fe River Park
N JEFFERSON INTERSECTS
HANCOCK ST INTERSECTS
425 Sebastian's Firestone tires & appliances 983-7303
427 Hunton's Pharmacy 983-6303
451 New Life Co-Op health foods 988-2443

7

DEFOURI BEGINS
CAMINO DEL CAMPO BEGINS
500 Public Housing Site A
501 Lujan Joe E 983-1749
503 Baca Mary I
505 Martinez Natividad
507★Wheeler Flora C
509 Lovato Rafailita
511 Leyba Thos 982-3010
513 No Return
514 Ortega Eug
CANDELARIO BEGINS
525 Salvation Army The 988-8054
530 Rivera Alfredo R © 983-9358
532 Serrano Mary
532½ Trujillo Angela
534 Montoya Ramon © 982-1259
534½★Shook Jim © 983-8861
536★Lane Michl ©
536½★Silva Jake © 983-3113
538 Ponce Emilia Mrs ©
538½ Vacant
600 Quintana Lucieta Mrs © 982-4032
604★Lujan John C ©
613 Roybal Stella Mrs © 988-2577
615 Vigil Leo A © 982-3352
617 No Return
619 Rael Patrocinia Mrs ©
621 Garcia Ben J ©
623★Sanchez Delfin 982-5212
701 Brassfield Opal Mrs
703 Brandall Lily
705 Rivera Philip
707 Gallegos Danl
709 Padilla Ophelia Mrs 983-5510
711 Martinez Susanna Mrs
713 Lujan Joe B 983-8052
715 Serrano Filimon 988-2154
716 Chavez Henry R 988-3498
717 Vacant
718★Archuleta Ray 983-3804
719 Payne Leroy 983-1814
720 Gonzales Mary A 988-1059
721 Chavez Joe P 982-0652
723 Delgado Mela 983-3995
725 Chavez
727 No Return
729★Archuleta Cora 983-1826

1978 E PALACE AVE

SOURCE: POLKS

E PALACE AV—Contd
806 Sherwood Cecil © 983-3427
810a No Return
810b Coleman C 983-3705
810c No Return
810d Moreno Robt G
815 Briggs Lenard
817 Vacant
823 Daly Mary E Mrs © 983-7135
825 Vacant
825½★Garcia Clarita 982-8729
826 Griego Antonio E © 983-7198
828 Palace Youth Center 982-0114
831 Clark Ann D Mrs © 983-9128
832a Newby Alice Mrs 983-8279
832b Jenkins TV & Radio Sales & Service 983-9146
832c Thompson Scott
833 Alderete Alphonso N © 983-5613
834 Sanders Troy P © 983-3753
836 Martinez Manuel D © 983-7564
836a Lujan Luciano © 983-7174
838 Lopez Dry Cleaners 983-6712
Lopez Max L © 983-6712
839 Rossiter Robt
Rear Rossiter Francis 983-9252
841 Rael Clara 983-3163
845 Ross Annella E Mrs 983-3642
845½a Miller Geo L © 983-3837
845½b Miller Feliberto ©
845½c Lovato Stella 982-0614
845½d Lovato David 983-8155
845½e Lovato Frank R
845½f★Stevens J R
845½g Gomez Geo © 983-5638
845½h Lovato Salomon ©
853 Palace Grocery gro 982-9069
855 Ortiz Eddie J 982-0488
857 Lobato Canuto G © 983-7552
857½ Gorman Josefita L Mrs © 982-2124
Rear Vacant
864 Garcia Antonio ©
CERRO GORDO RD BEGINS
874 Trujillo Plumbing & Heating 983-5745
Trujillo Max © 983-5745
876 Casados Cayetano © 983-6615
878 Vacant
880 Wright Sandi 982-9206
883 Woods Harry L 988-2460

10

ALAMEDA INTERSECTS
940 Gonzalez Dolores Mrs © 982-2156
940½ Gonzales Jerry 982-3261
944 Vigil John L © 983-4210
CANYON RD INTERSECTS

3

PALACE AV WEST —FROM 100 WASHINGTON AV WEST TO BURRO AL

ZIP CODE 87501
1 Palace Of The Governors 827-2437
LINCOLN AV INTERSECTS
107 Museum Of New Mexico Hall Of Fine Arts 827-2351
SHERIDAN AV BEGINS
123 Bishop Building
Rooms
1 Under Constn
5 Vacant
6 Pattison H H real est 983-9181
6 Equitable Life Assurance Society Of The U S 983-9181
7 Under Constn
17 Lieber & Company stock exch 982-1848
18 Indian Cultural Services 982-4377
Neff & Co accts
19 Santa Fe Chamber Music Festival 983-2075
STREET CONTINUED
124 Delgado Building
Reynolds Agency Inc The ins agency 983-4353
STREET CONTINUED
125 Artist Co-Op Gallery 988-2582
127 Polka Dot womens clo 982-1348
128 Broome's Of Santa Fe furn 982-5554
129 Horwitch Elaine Gallery 988-8997
130 Kachina Gallery 982-2997
131 Las Cosas De Santa Fe 988-3344
135 Sherwood Cecil Chevron Station 983-9035
136 Palace Restaurant 982-9891
142 Bokum Building
Rooms
101 Prince & Schmidt 982-3836
102 Vacant
200 Bigbee Byrd Carpenter & Crout lwyrs 982-4611
205 Peat Marwick Mitchell & Co accts 982-4326
300 Bokum Resources Corp mining 982-1824
STREET CONTINUED
GRANT AV INTERSECTS
BURRO ALLEY INTERSECTS

19

PALOMINO ST —FROM 1513 AGUA FRIA SOUTH TO DEAD END

ZIP CODE 87501
303★Sandoval Remigio ©
306 Ortiz Geo R © 982-3206
307 Gonzales Charles L © 983-5255
309★Lujan Frank ©
311 Romero Faustin © 983-2638
313 Larranaga Eloy © 983-6739
315 Lopez Jake © 982-1152
317 Gonzales David © 982-5316
319 Trujillo Larry M © 988-5647
321 Lopez Michl © 982-8262
401 Griego Pablo F Jr © 983-7273

E ALAMEDA ST—Contd
1 ★ Lujuane W E
2 Vacant
3 Matson Joseph T 982-9459
4 Dodds Gertrude G Mrs 982-5740
5 Trujillo Edw A 983-2888
528 Stevenson Dorothy R author
529 Apartments
1 Vacant
2 ★ Mc Dermott Wm J
3 Vacant
4 ★ Lopez Dorothy
5 ★ Roberts Willie
6 ★ Porter Even
7 No Return
8 ★ Wright Billy
9 Meals Katy 982-8049
540 Spiegel Zane ◎ 982-8658
541 Apartments
1 Chegaras Antonios D
2 Vacant
3 Vacant
4 Wallis Janice M Mrs
550 Scott Eleanor M Mrs ◎ 982-5653
564 Otero Ted M real est ◎ 982-0493
CAMINO ESCONDIDO BEGINS SS
614 Reynolds Stephen E ◎ 982-5140
615 Vacant
616 Overman Dennis 983-1128
616½ Saiz Joe I ◎
Lanes Jim
617 Berry Weldon 983-5408
618 Sundown Paul
Herrera Gilbert E ◎
Rear Vacant
630 Bobbs Howard 983-5570
Rear Vacant
633 Blythe School 982-5912
637 Barber Mary W Mrs ◎ 983-9150
650 Compound The apts
Apartments
1 Under Constn (17 Apts)
CAMINO ESCONDIDO INTERSECTS
705 Zamora Patricia
711 Under Constn
803 Vacant
805 Vacant
815 Apartments
1 Evans Ernestine D Mrs
2 Fleming Janet I 983-1340
3 ★ Goodwin Lorin Mrs
4 Batista Mario 982-9273
5 Vacant
817 Apartments
1 King Marjorie F Mrs 983-4938
2 Vacant
3 Hickey Thos E 982-0611
4 Vacant
5 ★ Sorensen Nielson
827 Griego John ◎ 983-3553
829 Saiz Narciso ◎ 983-7536
835 Banks Harold E ◎ 982-2341
837 Gabaldon Michl ◎ 982-0296
837½ Vacant
839 Baros Augustine ◎ 982-0392
840 Apartments
1 ★ Sandoval L
2 No Return
3 No Return
4 Sisneros Rose Mrs
868 Vacant
868½ Trujillo Donelia Mrs 983-9657
870 Montoya Joe S ◎ 983-4436
874 ★ Montoya Pete

10

E PALACE AV INTERSECTS
1005 Vacant
1115 Sena Louis A ◎
1117 Anaya Joe 982-3907
1120 Durham Lee ◎
1122 Buffington Robt O ◎ 983-2373
1127 Holmes Leroy P ◎
1131 Roybal Lorenzo ◎ 983-6243
1133 Vacant

E PALACE AV—Contd
700 Reust Josephine P Mrs ◎ 983-3628
702 Fullerton Marie Mrs ◎ 983-8116
704 ★ Wallace Gertrude 982-1028
705 Coca Michl A 983-2558
LA VEREDA BEGINS
706a ★ Nolan Dan J 982-0921
706b Ulibarri Roberta Mrs
708a ★ Garcia Lucille
708b ★ Vigil Joe L
EL ALAMO BEGINS
716 Glassmire Saml H Jr ◎ 982-0270
720 ★ Calles Eloy 982-5643
729 ★ Richards Cletus
729½ Vacant
LA VEREDA ENDS NS
802 Tapia Joseph M ◎ 983-6715
806 Sherwood Cecil ◎ 983-3427
810a No Return
810b ★ Lehmann Freida
810c ★ Dunnigan Tom
810d Griego Gil R 983-4728
815 ★ Moyers Portia T 983-2666
815½ ★ Phieffer Craig
817 ★ Yurcik Toni Mrs
817½ Lopez Manuel
823 Daly Mary E Mrs 983-7135
825 Roe Evelyn Mrs
825½ Gonzales Guadalupe G Mrs
826 Griego Antonio E ◎ 983-7198
828 Palace Youth Center 982-0114
831 Clark Ann D Mrs ◎ 983-9128
832 Jenkins George F ◎ 983-9146
832a Newby Alice Mrs 983-8279
832b Jenkins TV & Radio Sales & Service 983-9146
832c ★ Barbero Eloy
833 Alderete Alphonso N ◎ 983-5613
834 Sanders Troy P ◎ 983-3753
836 Martinez Manuel D ◎ 983-7564
836a Lujan Luciano ◎ 983-7174
838 Lopez Dry Cleaners 983-6712
Lopez Max L ◎ 983-6712
839 Vacant
Rear Rael Arthur
840 Vacant
841 Rael Clara 983-3153
845 Ross Annella E Mrs 983-3642
845½a Miller Geo L ◎ 983-3837
845½b Miller Feliberto ◎
845½c Vacant
845½d ★ Lonato David
845½e Lovato Frank R
845½f Vacant
845½g Gomez Geo ◎
845½h Lovato Salomon ◎
853 Palace Grocery gro 982-9069
855 Vacant
857 Lobato Canuto G ◎ 983-7552
Rear Lovato P Bernadette Mrs
857½ Gorman Josefita L Mrs ◎ 982-2124
864 Garcia Antonio ◎ 983-3819
CERRO GORDO RD BEGINS
868 Vacant
Rear Vacant
874 Trujillo Max ◎ 983-5745
876 Casados Cayetano ◎ 983-6615
878 ★ Maes Gilbert
880 Baker Evelyn Mrs
883 Vacant
885 Vacant

10

ALAMEDA INTERSECTS
940 Gonzales Rupertita Mrs ◎ 982-2156
940½ Gonzales Jerry 982-3261
944 Vigil John L ◎ 983-4210
985 Under Constn
CANYON RD INTERSECTS

3

PALACE AV WEST —FROM 100 WASHINGTON AV WEST TO BURRO AL

ZIP CODE 87501
1 Palace Of The Governors 827-2437
107 Museum Of New Mexico Hall Of Ethnology 827-2834
LINCOLN INTERSECTS

1968 E ALAMEDA ST

SOURCE: HUDSPETHS

ALAMEDA ST EAST--CONTD

615 BUCKLEY KATHRYN MRS
982-5193
616 GALLEGOS DANL
616½ SAIZ JOE I •
FICK CYNTHIA STUDIO
ARTIST
617 WESCHE ALICE 982-8659
618 GARCIA FLORIAN
982-9680
HERRERA GILBERT •
REAR VACANT
630 BABBS HOWARD 983-5672
REAR VACANT
633 BLYTHE SCHOOL
982-5912
637 BARBER MARY W MRS •
983-9150
650 COMPOUND THE RESTR
982-4353
APARTMENTS
1 KINNEY MARIAN C MRS
982-5838
2 MC CHESNEY EVA J
MRS 983-4842
3 HOOTON WM 982-5097
4 DUHOYS ALEX
5 STETSON HAFFORD MRS
983-8778
6 VACANT
7 BIEBER C FRANCES
982-1038
8 SCOTT MARY 982-9760
---CAMINO ESCONDIDO
INTERSECTS
803 DURAN ROBT J
805 GABALDON BEN A
983-6787
815 APARTMENTS
1 NO RETURN
2 CALDWELL MARJORIE
983-6818
3 JOHNSON JAMES R
AUTHOR 982-4186
4 BULLARD DEWEY
5 SULLIVAN WM
817 APARTMENTS
1 KING MARJORIE F
983-4938
2 COLLEY EDWIN
3 JOE J R MRS
4 COY LILLIAN B
982-4167
827 GRIEGO JOHN •
983-3553
829 SAIZ NARCISO •
983-7536
835 BANKS HAROLD E •
982-2341
837 VACANT
837½ COHN ROLF
839 BAROS AGUSTIN •
982-8312
840 APARTMENTS
1 MILLER MARILLITA
MRS • 983-9536
2 MADRID JOE M
3 GONZALES REYNALDO L
4 ORTIZ SOTERO
868 MARQUEZ MARY MRS
MONTOYA TESSIE MRS
868½ TRUJILLO JAKE R
983-9657
870 MONTOYA JOE S •
983-4436

10

---E PALACE AV INTERSECTS
1115 SENA LOUIS A •
1117 ANAYA JOSEPH E JR •
982-3907
1120 GROSS MARIE DE VILLE
MRS • 982-0536
1122 CARTER MERLE W MRS
983-7888
1127 HOLMES OLIVER •
983-6465
1131 ROYBAL LORENZO •
983-6243
1133 SCHOENFELD PETER

1

ALAMEDA ST WEST -FROM 234
DON GASPAR AV WEST TO
CITY LIMITS

---ZIP CODE 87501
---GALISTCO INTERSECTS
100 SANTA FE RIVER PARK
213 SCHIFANI BROS
PRINTING CO INC
982-2489
235 HOLMAN APARTMENTS
1 LEYBA TONY
2 VACANT
3 VACANT
4 CHAVEZ RAMON
5 SWEENEY SARAH MRS
6 PALOMINO MARCELLA
MRS
7 CHAVEZ JERRY
8 ANAYA HELEN
9 PADILLA MARY
10 RIVERA NACRIO
237 VACANT
239 CAPITOL OFFICE
MACHINES 982-9691
241 FIRST NORTHERN SAVING
& LOAN ASSN 983-4314
---N JEFFERSON INTERSECTS
---HANCOCK ST INTERSECTS
425 FOODWAY MARKETS
982-0741
451 INDEPENDENT GROCERY
982-1011
459 VACANT
---DE FOURI BEGINS
461 MOYA ENRIQUE
463 TRUITT ANTONIO
465 CRESPIN ABEL
467 SALAZAR FRANCISCO
469 MARTINEZ VICTORIA MRS
471 GALLEGOS SOLEDAD
473 RIVERA RUFINA M
982-0333

1968 E PALACE AVE

SOURCE: HUDSPETHS

PALACE AV EAST--CONTD

810D NO RETURN
815 SAFFORD EDW L •
983-9229
815½ LASSETTER GERALD C
983-8003
817 BROOKS E 983-5752
817½ HOFFMAN JERRY
982-5632
823 DALY MARY E MRS •
983-7135
825 STOLBERG LAWRENCE G
825½ GARCIA CLARA S MRS
982-8729
826 GRIEGO ANTONIO E •
983-7198
828 PALACE YOUTH CENTER
831 CLARK ANNE D MRS •
983-9128
832 JENKINS GEORGE F •
983-9146
832A NEWBY ALICE MRS
983-8279
832B JENKINS TV & RADIO
SALES & SERVICE
983-9146
832C GAINES CHARLES H
833 ALDERETE ALPHONSO N •
982-0554
834 SANDERS TROY P •
983-3753
836 MARTINEZ MANUEL D •
983-7564
836A LUJAN LUCIANO •
983-7174
838 LOPEZ DRY CLEANERS
983-6712
LOPEZ MAX L •
983-6712
839 ROSSITER ROBT D •
REAR RAEL GENEVIEVE •
983-9252
840 RIVERA AUGUSTIN D •
841 RAEL CLARABELLE MRS
845 ROSS ANNELLA E MRS
983-3642
845½ MILLER GEO L •
983-3837
LYNN RAMONA
ROMERO ULBALITA MRS
•
LOVATO JOYCE MRS
RAEL CLORA MRS
983-3153
LOVATO FRANK
MILLER FILIBERTO •
DURAN RAMONA MRS •
983-6254
LOVATO SALOMON •
853 PALACE GROCERY GRO
982-9316
855 SAIZ RUTH L MRS
983-4413
857 LOBATO CANUTO G •
983-7552
REAR LOVATO P BERNADETTE
MRS
857½ GORMAN JOSEFITA L
MRS • 982-2124
859 YOUNG ROBT
864 GARCIA ANTONIO •
983-3819
---CERRO GORDO RD BEGINS
868 VACANT
REAR VACANT
874 TRUJILLO MAX •
983-5745
876 CASADOS CAYETANO •
983-6615
878 SPARR LUGARDA MRS •
982-0057
880 CLAY ROBT
883 WOLVERTON RICHD
982-9977
885 VACANT

10

---ALAMEDA INTERSECTS
940 GONZALES RUPERTITA
MRS • 982-2156
940½ GONZALES JERRY
944 VIGIL JOHN L •
983-4210
---CANYON RD INTERSECTS

3

PALACE AV WEST -FROM 100
WASHINGTON AV WEST TO
BURRO AL

---ZIP CODE 87501
1 PALACE OF THE GOVERNORS
827-2437
107 MUSEUM OF NEW MEXICO
HALL OF ETHNOLOGY
827-2834
---LINCOLN INTERSECTS
MUSEUM OF NEW MEXICO
(FINE ARTS)
827-2351
107½ WINGO ROLAND
983-6112
---SHERIDAN AV BEGINS
123 BISHOP BUILDING
ROOMS
1 PREVIEWS INC (BR
OFC) NATL REAL EST
LISTINGS 983-4354
1 BISHOP MANUEL &
HUNKER INC (BR)
INS 983-4354

1964 E ALAMEDA ST

SOURCE: HUDSPETHS

ALAMEDA ST E--CONTD
528 STEVENSON FREDK R •
983-7936
STEVENSON DOROTHY R
AUTHOR
528½ VACANT
6 BOWERSOCK DALE D
982-0878
7 COLLINS TERRENCE
983-4295
8 CALDWELL MARJORIE
983-6818
9 HAEGBERG R J
540 VACANT
550 SCOTT WINFIELD T
AUTHOR • 982-5653
564 OTERO TED M REAL EST
• 982-0493
---CAMINO ESCONDIDO
BEGINS SS
610 NO RETURN
613 UNDER CONSTN
614 REYNOLDS STEPHEN E
982-5140
615 BUCKLEY GEO H
982-5193
616 RODRIGUEZ FRANCES V
MRS • 983-4246
616½ SAIZ JOE V •
617 WESCHE ALICE MRS
982-8659
618 SISNEROS JULIO •
983-7545
GARCIA FLORIAN
982-9680
SAIZ ROBERT
HERRERA GILBERT •
982-2934
REAR ORTIZ MARIE MRS
630 ANDERSON HORACE
PRINTER • 983-4437
REAR VACANT
633 BLYTHE SCHOOL
982-5912
637 BARBER MARY W MRS •
983-9150
650 RUTHERFORD J C
A EHRICH JUDITH
B CLAPPER CHARLES
982-3982
1 KINNEY MARIAN C MRS
982-5838
2 MC CHESNEY EVA J
983-4842
3 SHAPARIO JOSEPH
4 WORK ALLENE
983-3830
5 STETSON HAFFORD MRS
983-8778
6 DU HAYES ALEXANDER
983-6368
7 BIEBER C FRANCES
982-1038
8 SIMPSON JAMES C
983-4630
---CAMINO ESCONDIDO
INTERSECTS
801 LESTER HARRY L
982-9284
803 VACANT
805 VACANT
1 JOHNSON JAMES R
AUTHOR 982-4186
2 CAMPBELL CHARLES
3 DALLAS GENE MRS
982-9385
4 CURRIE ELEANOR
982-9264
1 VACANT
2 CHANDLER EDWARD S
983-7463
3 BRANNAN DAVID M
982-5774
4 COY LILLIAN B
982-4167
827 GRIEGO JOHN •
983-3553
829 SAIZ NARCIO •
983-7536
835 BANKS HAROLD E •
983-4834
837 CDE BACA FRANK
837½ VIALPONDO IKE J
839 BAROS AGUSTIN •
1 MILLER MARILLITO R
MRS • 983-9536
2 MADRID JOE
3 VACANT
4 BAROS AGUSTIN B JR
7 VACANT
10 VACANT
11 VACANT
868 LOVATO DAN
MONTOYA TESSIE MRS
868½ TRUJILLO JAKE R •
983-9657
870 MONTOYA JOE S •
983-9436
8 CALDWELL MARJORIE
MRS • 983-6818

10

---E PALACE AV INTERSECTS
1115 SANA LOUIE •
1117 ANOYA JOSEPH E •
982-3907
1120 GROSS MARK •
982-2207
1122 CARTER MERLE W MRS
983-7888
1127 HOLMES OLIVER •
983-6465

1964 E PALACE AVE

SOURCE: HUDSPETHS

PALACE AV E--CONTD
705 SULLIVAN JAMES B
982-0489
706A WILLIAMS EVA W MRS
982-9475
706B VACANT
708A SMITH ESTHER MRS
708B QUINTANA FRANK M JR
716 GLASSMIRE SAML H JR
982-0270
720 CALLES ELOY •
982-5643
729 LORD DE FOREST D •
983-4831
729½ RIGGS ADRIENNE MRS
983-4831
---LA VEREDA ENDS NS
802 TAPIA JOE M •
983-6715
806 SHERWOOD D CECIL •
983-3427
810A FULLERTON FREIDA MRS
• 983-8116
810B MILLIGAN JIM A
983-3881
815 SAFFORD EDW L •
983-9229
815½ LASSETTER GERALD C
983-8003
817 LAWLESS ROBT J JR
983-4239
817½ MONTOYA TED 983-3678
823 DALY MARY E MRS •
983-7135
825 MODRALL G C 983-6151
825½ GARCIA CLARA S MRS
982-8729
826 GRIEGO ANTONIO E •
983-7198
828 PALACE YOUTH CENTER
982-0114
831 CLARK JOSEPH M •
983-9128
832 JENKINS GEORGE F •
983-9146
832A NEWBY ALICE MRS
983-8279
832B JENKINS TV & RADIO
REPAIR 983-9146
832C GAINES CHARLES H
833 ALDERETE ALPHONSO •
982-0554
834 SANDERS TROY P •
983-3753
836A LUJAN LUCIANO •
983-7174
838 LOPEZ DRY CLEANERS
983-6712
LOPEZ MAX L •
983-6712
839 ROSSITER ROBT D PLMB
CONTR •
REAR RAEL GENEVIEVE •
983-9252
840 RIVERA AUGUSTIN C •
841 HOLMES GILBERT •
983-3153
845 ROSS ANNELLA E MRS
983-3642
845½ GALLEGOS JOE S
982-8493
ROMERO WM W •
982-1109
MILLER GEO L •
983-3837
MILLER MICHAEL
LOVATO FRANK
LOVATO LEANDRO
LOVATO TOMASITA MRS
MRS
MILLER FILIBERTO •
983-4237
DURAN RAMONA MRS •
983-6254
LOVATO SALOMON •
982-0614
853 PALACE GROCERY GRO
982-9316
855 SAIZ RUTH L MRS
983-4413
SALAZAR MARY L MRS
857 LOVATO CANUTO G •
983-7552
REAR LOVATO P BERNADETTE
857½ GORMAN JOSEFITA L
MRS • 982-2124
859 ROMERO GUADALUPE
864 RIVERA FRANK •
LOVATO EDWARD
868 LOPEZ JOHN
REAR ORTEGA PERFITITA MRS
REAR VACANT
874 TRUJILLO ROSINA •
982-1418
876 CASADOS CAYETANO •
983-6615
878 SPARR LUGARDA MRS •
982-0057
880 CORNER GROCERY &
MARKET 982-0353
883 UNDER CONSTN
883½ ROSEN NORMAN
---CERRO GORDO RD BEGINS
NS

10

---ALAMEDA INTERSECTS
940 GONZALES RUPERTA MRS
•
940½ GONZALES JERRY •

10

522 Robinson Richd H ◎ ΔYU3-7195
523 Magers H Brady ◎ ΔYU3-8736
525 Ortiz Arth ◎ ΔYU3-9377
527-29 **Apartments**
1 Bankson Lewis M
2 Thompson Van
3 Matson Jos T ΔYU2-9459
4 Marler Joe ΔYU2-2880
5 Vacant
6 Scott Robt W
7 Vigil Ray J ΔYU2-1659
8 Coldwell Marjorie Mrs
9 Bushnell David L ΔYU2-2896
528 StevensonF Robt ◎ ΔYU3-7936
540 Proebstel Edith W Mrs ◎ ΔYU3-4249
550 Scott W T ◎ ΔYU2-5653
564 Wangerien Harry A ◎ ΔYU3-3638
Camino Escondido begins ss
614 Reynolds Steven E ◎ ΔYU2-5140
615 Buckley Geo H ΔYU2-5193
616 Rodriguez Frances V Mrs ◎ ΔYU3-4246
Romero Antonio ΔYU2-2209
Trujillo Louis ΔYU2-5281
616½ Manzanares Julia Mrs ◎
Salz Joe V ◎ ΔYU2-1670
617 Wesche Alice Mrs
618 Sisneros Julio ◎ ΔYU3-7545
Garcia Florian
630 Anderson Horace ◎ prntr ΔYU3-4437
Ilfeld Wm C ΔYU3-4023
633 Blythe Sch ΔYU2-5912
637 Barber Mary Mrs ◎ nurse ΔYU3-9150
Davis Almeta M ◎ ΔYU3-9150
650 **Apartments**
Beckman Edgar ΔYU2-9485
A Gates Marie E ΔYU3-4638
B Hughes Rowena Mrs ΔYU3-7923
1 Kinney Marian C Mrs ΔYU2-5838

ALAMEDA E—Contd
650—Contd
2 Charles Rose E Mrs ΔYU3-8337
3 Crosby Edith A Mrs ΔYU3-6935
4 Work Allene ΔYU3-3830
5 Stetson Hafford Mrs ΔYU3-8778
6 Knopp Geo ΔYU3-7731
7 Bieber C Frances ΔYU2-1038
8 McComb Sara W Mrs ◎ ΔYU2-0839
Camino Escondido intersects
801 Weltman Moe ΔYU2-8154
815 **Apartments**
1 Lusk Alice M
2 VanCourt Frances A ΔYU3-8164
3 Dallas Gene Mrs
Street continued
827 Griego John ◎ ΔYU3-3553
829 Saiz Narcio ◎ ΔYU3-7536
835 Banks Harold ◎ ΔYU3-4834
837 C de Baca Frank
837½ Vialpando Ike
839 Baros Agustin ◎
840 **Apartments**
1 Miller Marillta R Mrs ◎ ΔYU3-9536
3 Stone Codell ΔYU2-2234
7 McGill Ernest
10 Wright Bennie C ΔYU2-5637
11 Vacant
Street continued
868½ Trujillo Jake R ◎
870 Montoya Jos S ◎ ΔYU3-4436

10

E Palace av intersects

1115 Sena Louis ◎ ΔYU3-9326
1117 Maes Cabinet Shop
Maes Miguel ◎ ΔYU3-8848
1120 Gross Mark ◎ ΔYU3-7980
1122 Carter Merle W Mrs ΔYU3-7888
1127 Holmes Oliver ◎ ΔYU3-6465
1131 Roybal Lorenzo ◎ ΔYU3-6243

1

ALAMEDA W—From 234 Don Gaspar av west to city limits (Right Odd)

815½ Lassetter Gerald C ΔYU3-8003
817 Mayne Phyllis ΔYU3-8547
817½ Jarman Alf J ΔYU2-1024
823 Daly Mary E Mrs ◎ ΔYU3-7135
825 Freeman Jas W ◎ ΔYU3-8910
825½ Garcia Clarita Mrs
826 Griego Antonio E ◎ ΔYU3-7198
828 Palace Youth Center
831 Clark Jos M ◎ ΔYU3-9128
832 Dillard Thurman W
Dillard Studio of Creative Art
833 Bishop Raymond C ΔYU2-2224
833½ Real Joe
834 Sanders Troy P ◎ ΔYU3-3753
836 Martinez Manuel D ◎ ΔYU3-7564
836a Lujan Luciano ◎ ΔYU3-7174
838 Lopez Max L ◎ ΔYU3-6712
Lopez Dry Clns ΔYU3-6712
Madrid Joe
839 Rossiter Robt D plmb ◎
rear Real Genevieve ◎ ΔYU3-9252
840 Rivera Agustin O ◎
841 Holmes Andreita Mrs ◎ ΔYU3-3153
rear Miller Geo L ◎ ΔYU3-3837
845 Ross Annella Mrs ΔYU3-3642
rear Romero Willie ◎
845½ Shirley Joe A ◎ ΔYU2-0663
Romero Wm A ΔYU2-1109
Miller Filiberto ◎ ΔYU3-4237
Lovato Moises ◎
Lovato Edw ◎
Duran Ramona ◎ ΔYU3-6254
Lovato Salomon ◎ ΔYU2-0614
Lovato Frank ◎
Lovato Leandro
855 Palace Grocery ΔYU2-9316

PALACE AV E—Contd
855—Contd
Elliott Herman ΔYU3-3458
rear Archuleta David
857 Lovato Canuto G ◎
rear Lovato Bernie
857½ Gorman Josie M Mrs ◎ ΔYU2-2124
859 Vacant
864 Rivera Frank ◎
Gonzales Nick
868 Lopez John
rear Ortega Perfitita Mrs
874 Trujillo Rosina ◎ ΔYU2-1418
876 Cassados Cayetano ◎ ΔYU3-6615
878 Sparr Lugarda Mrs ◎ ΔYU2-0057
880 Corner Grocery & Mkt ΔYU2-0353
Rivera Alfonso J ΔYU2-0353
Cerro Gordo rd begins ns

10

Alameda intersects

940 Sandoval Santiago ◎ ΔYU3-8438
Gonzales Ruperta Mrs ◎
940½ Gonzales Julio jr ◎
941 Vigil Eloisa V Mrs
Gomez Pat
944 Vigil John L ◎ ΔYU3-4210
Canyon rd intersects

3

PALACE AV W—From 100 Washington av west to Grant av (Right Odd)

ns Palace of the Governors Museum of NM ΔYU2-5584
School of American Research
Historical Society of NM
Lincoln intersects
107 Museum of NM (Art Gallery) ΔYU2-5611
107½ Wingo Rolan ΔYU3-6112

BILL CAMPBELL
Kelly Springfield Tires — Pres
College at Manhattan

1955 E ALAMEDA ST

SOURCE: HUDSPETHS

ALAMEDA E—Contd
301-05 **Casitas Del Rio Apts**
1 Kimbrell Anna
2 O'Brien Mary A Mrs 3-8788
3 Roberts Rose Mrs
4 Brown Richmond P 3-4981
5 Oldham Florence I 3-6208
6 Stephens Danl B 3-6693
Street continued

311 Harvey Jas C 3-4987
328 Wheeler Edgar L 3-4138
329 Lindgren Roy P 3-9590
331 Castillo Margarita
331½ Wheeler Geo 2-0955
335 Jimenez Juan B 3-6954
337 Jimenez Juan M
339 Gonzales Jose V 3-9577
Garcia Arth A 3-8947
341 Slater Arth 3-8306
343 Gonzales Ismael 3-8896
345 Medrano Tom
Apartments
1 Medrano Tom jr
2 Archuleta Delfina 3-3268
3 Ortega Laurencita
4 Martinez Cipriano
Street continued
349 Wheeler John 3-9495
351 Roybal Enrique
353 Dohrer John V 3-4888
Delgado intersects

401 Goxem Gunhild 3-8038
403 Garcia Lsabelle Mrs
403½ Cantu Alfredo M 3-7644
411 Howland Lourdes Mrs 2-0137
520 Pearson Harry W 2-0915
523 Magers H Brady 3-8736
528 Stevenson F Robt 3-7936
540 Proebstel Edith Mrs 3-4249
550 Hapgood Eleanor Mrs 3-9366
564 Wangerien Harry A 3-3638
Camino Escondido begins ss

614 Funk Ilo C 3-5337
615 O'Neil Floyd B
616 Montoya Narciso
616½ Romero Antonio J
Saiz Jose V
617 Overton Veda 3-8264
618 Sisneros Julio 3-7545
630 Anderson Horace 3-4437
633 Blythe School 3-5912
637 Barber Mary Mrs nurse 3-9150
Davis Almeta nurse

650 **Apartments**
Russell John D 4-5359
A Gates Maire E 3-4638
B Hill Gertrude F 3-6643
1 Kinney Marian C Mrs 3-5838
2 Charles Rose E Mrs 3-8337
3 Crosby Edith A Mrs 3-6935
4 Work Allene 3-3834
5 Stetson Hafford Mrs 3-8778
6 Alfau Rafael Mrs 2-1138
7 Bieber C Frances 2-1038
8 McComb Sara WMrs 2-0839
Camino Escondido intersects

815 **Apartments**
1 Janssen Geo
2 Groh Lee D 3-3695
3 Kubotso Teruko
Street continued
827 Kriego John 3-3553
829 Griego Pablo S 3-7536
835 Banks Harold 3-4834
837 Sheppard Eug 3-8313
837½ Vacant
839 Baros Agustin
840 Miller May R Mrs 3-9536
Wright Venesee 3-5637
E Palace av intersects

870 Montoya Joe S 3-4436
1001 Morrow Mable 3-8874

1

ALAMEDA W—From 234 Don Gaspar av west to city limits (Right Odd)
Agua Fria intersects
211 Vacant
237 Emble mSheet Mtl Wks 3-8812
N Jefferson intersects
425 Farmway Feed & Equip Co 2-0911
468 Independent Gro 2-1011

7

Park av intersects
530 Rivera Alfred oR 2-0016
532 Vigil Ramon 2-1124
532½ Roybal Juan
534 Montoya Castelita Mrs 3-7919
534½ Gonazles Balvinita Mrs
536 Jaramillo Anastacia Mrs
536½ Silva Adela O Mrs 3-3113
538 Ponce Albert L 3-3515
Duran begins ns

600 Vieira Francisco
604 Ortiz Robt C 3-8064
605 Orozco John N
Roybal Bennie D
606 Roybal Abedon
606½ Under constn
608 Rael Albert
Garcia Benny J
Candelario intersects
700 Rocky's Mkt gro
Apartments
1 Montoya Joe
2 Pena Pete 3-3549
3 Ortiz Pete
4 Vacant
5 Vacant
6 Padilla Tomacita Mrs
7 Barela Antonio T 3-3794
8 Vacant
9 Vacant
10 Valdez Reyes Mrs
11 Rico Ernest
12 Chavez Apolinio
13 Chavez Remijio 3-8912
Street continued
710 Silva Luis
720 Rodriguez Josefita Mrs
730 Barela Anastacio 3-7614
Walton Victoria Mrs 3-7614
Mares Juan
Barela Ramon
734 Barela Willie 3-5414
758 Gonzales Joe A
760 Sena Alfredo R
762 Ortiz Julio
764 Conway Clara Mrs
Muniz Pablita Mrs
766 Benavides Edw 3-4958
768 Garcia Eladio S 3-4444
770 Garcia Hilario S
784 Watson Noah 2-0415
790 Fresquez Nestor 3-8110
792 Benavides Atanacio
Sandoval Adolfo
W San Francisco ends ns
nw cor Gonzales Elem Sch 3-6711
800 Quintana Joe H
804 Espinoza Gilbert
1221 Serano Press 3-8332
1405 Thompson Frank N 3-7516
Following are Rural Delivery and Showing Box Numbers
126 Darras Julia Mrs
130 Popez Eduardo
Dooley Geo S 2-1016
Rank Tessie

9

ALARID—From 800 W Manhattan south (Right Even)
510 Romero Ramon 3-9643
510½ Vacant
511 Dagh Gust O 3-8152
513 Roybal Joe L 3-8682
513½ Weizer Dale

1955 E PALACE AVE

SOURCE: HUDSPETHS

PALACE AV EAST—Contd
518 Rolls Kate G Mrs 3-9629
519 Trussel Fredk D 3-4907
525 Mahoney Donald H 2-0058
529 Castle H Stuart 3-4837
531 Kelly Danl T 3-6229
533 Mervis J M 3-9341
535 Vacant
542 Montgomery Andrew K 3-9328
606 Miller Kenneth K 3-5429
607 Cooper Wm M contr 3-6422
608 Stauffer Virginia H Mrs 3-5829
610 Beatman Lawrence C 3-3926
614 Greer Chas R 3-4489
616 Ellis Dorothy S Mrs 3-6178
617 Kiker Henry A 3-5728
628 Romero Arth R 2-0127
629 Montoya Johnny M 3-4127
636 Wynkoop Harman H 3-5729
638 Updike John T 3-9426
Rodriguez begins ss

639 Walter Paul A F 3-4128
640 Castner Robt D 2-0234
642 Vacant
644 Leverton Chas W 3-7424
645 Rael Adelaida G Mrs 2-0124
Vigil Guadalupita Mrs 3-1439
645½ Saenz Leo T 3-9143
651 McConvery Electa Mrs 3-4528

700 Reust Arth J 3-3628
702 Bencoe Paul 3-3691
704 Breshears Furmon 3-3294
705 Dunbar C W 3-8036
706 Elkine Claude L 3-9244
708a Chrisler Charlotte Mrs 3-8451
708b Boughner Rhea V 3-6593
Rodriguez begins es

729 Lord DeForest D 3-4831
729½ Brosseau Roberta Mrs
LaVerda begins ns

815 Safford Edw L 3-9229
815½ Lassetter Gerald C 3-8003
817 Armentrout Donald E 3-8887
817½ Neeley O Nelson 3-8453
823 Daly Mary E Mrs 3-7135
825 Freeman J W
825½ Garcia Rafael B 3-6927
826 Griego Antonio E 3-7198
828 Palace Youth Center
831 Clark Jos M 3-9128
832 Dillard Thurman W
833 Martinez J P 2-0542
833½ Vasquez Andy Mrs
834 Sanders Troy P 3-3753
836 Martinez Manuel D 3-7564
836a Lujian Luciano
838 Lopez Max L 3-6712
Lopez Clns 3-6712
839 Rossiter Robt D
840 Rivera Agustin O
841 Holmes Andreita Mrs
845 Ross Malcom A Mrs 3-3642
845½ Shirley Joe A 3-5996
Romero Wm
Miller Filiberto 3-4237
Lovato Moises
Lovato Edw
855 Palace Grocery 3-9956
Saiz Ricardo 3-9956
857 Lovato Canuto G
857½ Lovato Gregorio
864 Rivera Frank
868 Lopez John
Ortega Santos A
874 Trujillo Ramoncita R Mrs
876 Montoya David S jr 3-3615
878 Sparr Lugarda Mrs
880 Corner Grocery 2-0353
Rivera Alfonso J
Cerro Gordo rd begins ns
Alameda intersects

940 Sandoval Santiago 3-8438
940½ Hermes Harry G
941 Cristo Rey Credit Union 3-3136
Vigil Eloisa V Mrs 3-3136
944 Vigil John L 3-4210
Canyon rd intersects

1

PALACE AV W — From 100 Washington av west to Grant av (Right Odd)
ns Palace of the Governors
Museum of NM 3-7812
School of American Research
Historical Society of NM
Lincoln intersects
107 Museum of NM (Art Gallery) 3-5611 and 3-5711
107½ Wingo Roland
Sheridan av begins ns
122-24 Senutovich Andre Uranium mining 3-6115 and 3-7898
US Uranium Corp mining
Trigon Co real est
123 **Bishop Building**
Rooms:
1-2 Bisnop Manuel & Hunker Inc eral est 3-4354
4-5 Avery-Bowman Extract Co 3-7681
7 Avery-Bowman Co 3-8681
7 Avery-Bowman Real Est Co 3-8581
8 Neal W C acct 3-9281
9 Avery-Bowman Ins Agcy 3-9181
Equitable Life Assurance Soc of the US 3-9181
10-11 Commercial Standard Ins Co of Ft Worth
Hutchison Abstract Co 3-7881
12-14 Santa Fe Abstract & Title Co 3-8491
15 Vacant
18-20 Andrews & Montoya lwyrs 3-6339
21-24 Gilbert White & Gilbert lwyrs 3-4324
Santa Fe Holding Co real est
Koch Sumner S lwyr 3-4324
Street continued
125 Vic's Dispensary liquors 3-9381
127 Unique Beauty Serv 3-9481
128 Broome's of Santa Fe furn 3-5554
129-31 Southwest Arts & Crafts whol curios 2-0771
135 Sherwood Cecil Chevron Serv Sta 3-9035
136 Pueblo Southern Corp mining 3-7213
Candelario's Enterprises real est 2-1391
138 Frank's liquors 3-9949
Grant av intersects

4

PALOMA—From 201 E Manhattan south, 1 north
400 Mares Victor 3-7497
402 Sager Lorena mus tchr 3-8385
403 Imgainga Tolden 3-9339
405 Abramson Elma
407 Tyler Wm C 3-7853
408 Yountz Grace Mrs 3-8177
411 Fraser Freeman D 3-5167
412 Kennedy Kirby K 3-7777
415 Hammond Herbert J jr 3-7477
416 Stephenson Annabelle 3-8185
419 Vacant
420 Buvinghausen Karl 3-5627
E Manhattan intersects

3

PARK AV—From 501 W San Francisco north (Right Odd)
110 Tinkham David W 3-4823
112 Dona David J 3-8616
114 Anderson O L 3-8916
118 Seligman Jake 2-0618
119 Pacheco Elena S Mrs 2-0619

AGUA FRIA ROAD—Contd
33A◊Tafoya Juan D ⓪
36 Garcia Florentino ⓪
36½ Velarde Alejandro ⓪
37 Romero Josephine
38 Pino Nicolas ⓪
40 Baca Ramon J ⓪
41 Tapia Amarante ⓪
42 Rodrigvez Manuel V ⓪
42A Montano Gabriel ⓪
42B Gonzalez Jose B
43◊Castellano Monico ⓪
43A Sandoval Fermin ⓪
44 Encinias Felipe ⓪
46 Barela Rafael

1

ALAMEDA E — Begins 300 Don Gaspar av ext east (Right Even)
113◊Original Mex Cafe
Lawrence Wm J ⓪
121◊Mountain States T & T Co
129◊Memorial Chapel
College intersects
nw cor◊StFrancis Cath Sch
StFrancis Cath Center
Shelby ends ns
137◊Potter G R
◊Craik Elsa Mrs
Scheid Gerda Mrs
137½ Jones Maude Mrs
138◊State Park Comnr
◊State Bank Examnr
141◊Nohl A K
143◊Vohs Wm
145◊Sippel Mathias A
College intersects
Cathedral pl ends ns

6

S Castillo intersects
301-05 **Casitas Del Rio** Apartments:
1◊Moranetz Walter P
2◊Quigley Alice R
3 Anderson Betty
4◊Drew Cullen O
5◊Morrison Earl L
6◊Haynes Hazel Mrs
Street continued
311◊Harvey John C ⓪
328◊Wheeler Edgar L ⓪
Chastain Thos M
329 Jorgenson Lewis V
331 Archuleta Mary S Mrs
335◊Jimenez Juan B ⓪
337 Jimenez Juan M ⓪
339◊Gonzalez Jose V ⓪
341 Burlington Mary Mrs nurse
◊Dunn Marcella
343◊Gonzales Ismael ⓪
345◊Medrano Tom ⓪
Apartments:
1 Springer Lloyd
2 Gonzales Frank
3 Moyo Luis jr
4 Garcia Silas
Street continued
349◊Wheeler John jr ⓪
rear◊Benavides Gregorio
◊Martinez Carlos ⓪
353◊Dohrer John V ⓪
Delgado intersects
401◊Goxem Gunhild ⓪
403◊McGrath Arth
403½◊Cantu Alfredo M
411◊Trujillo Max ⓪
Frost Chas J
523◊Magers H Brady ⓪
528◊Stevenson F Robt ⓪
528½ Ringer Anna H Mrs
540◊Proebstel Edith Mrs ⓪
rear Eppler Barbara J
550◊Hapgood H Prentice ⓪
564◊Wagerien Harry A ⓪
Camino Escondido begins ss
614◊Bainbridge Alex G
◊Broadhead Edith Mrs
615◊Summers Consuelo Mrs ⓪
Hostess Club adv
616◊Rodriguez Benidictio ⓪
Garcia Maria Mrs
616½ Romero Antonio
Saiz Jose V ⓪
617◊McMahon Geo H
618◊Pacheco Louise ⓪
◊Sisneros Julio ⓪
630◊Anderson Horace ⓪
633◊Blythe School
637◊Romero Juan J jr ⓪
650◊Cole Jas R
Apartments:
A Gates Marie E
B◊Andrews Marion
1◊Kinney Marian Mrs
2◊Charles H H
3◊Crosby Edith Mrs
4◊Tichy Marjorie Mrs
5◊Bond Marion
6◊Alfau Rafael
7◊Bieber C Frances
8◊McComb Sara W Mrs ⓪
Street continued
Camino Escondido intersects
815 **Apartments**
1◊Gulesserian Mary
2◊Grandstaff Ruth ⓪
3◊Allison Beatrice
Street continued
827◊Griego John ⓪
829◊Griego Carlo S ⓪
831 Lynch Dorothy
835 Vacant
837◊Galvan Catalino ⓪
837½◊Banks Robt T
839 Baros Augustin ⓪
840◊Miller Chas A ⓪
E Palace av intersects
870◊Montoya Joe
870½ Vacant

1

ALAMEDA W — Begins 234 Don Gaspar av ext west (Right Odd)
209-13◊White Swan Lndry
Agua Fria intersects

3

425◊Santa Fe Hay & G Co
468 Independent Gro
530◊Revera Alf ⓪
532◊Vigil Ramon
534 Montoya Ramon ⓪
Roybal Juan
534½ Gonzalez Balvinia Mrs ⓪

PALACE AV E—Contd
409◊Harkins Peter M ⓪ contr
412◊DeBolt Russell E ⓪
417 Catholic Maternity Institute Inc
◊Medical Mission Sisters
Armijo begins ns
Delgado begins ss
504◊Gonzalez Guadalupe L Mrs ⓪
508◊O'Hara C M Mrs
510 Vacant
511◊Woolf J D ⓪
512◊Hendricks Saml D
512½◊Ferrick Marie M Mrs
514◊Hamilton Jas B
518◊Rolls Kate Mrs ⓪
519◊Orvedahl Walter eng
◊Control Devices Corp oil burners
525◊Henry Thomp J ⓪
529◊Castle H Stuart ⓪
531◊Kelly Danl T ⓪
535◊Kelly Ellis T Mrs ⓪
542◊Montgomery Andrew K ⓪
606◊Miller Kenneth K ⓪
607◊Cooper Wm M ⓪ contr
608◊Stauffer Virginia Mrs ⓪
610◊Scott Doris S Mrs ⓪
614◊Sullivan Melvin C
616 Cannon Monna M Mrs
617◊Kiker Henry A ⓪
628◊Romero Arth R ⓪
629◊Ryan John G ⓪
636◊Trussell Fredk D
638◊Updike John T ⓪
Rodriguez begins ss
639◊Walter Paul A F ⓪
640◊Castner Robt D ⓪
642◊Delaney Douglas
644◊Gillard Wm H
645 **Apartments**
1 Romero Alejandro ⓪
2 Rael Adelaida G Mrs ⓪
3◊Vigil Guadalupita ⓪
4 Romero Victor ⓪
Street continued
645½ Herrera Antonio ⓪
651◊McConvery John C ⓪
700◊Reust Arth J ⓪
702 Crabb R C
704◊Krause Kathryn B Mrs baby furn
705◊Ellis Herbert ⓪
Ellis Herbert B jr
706◊Rowley Martin H
Roeder Henry D
708◊Paul Geo C
Rodriguez begins es
729◊Lord DeForest D
LaVereda begins ns
815◊Safford Edw L ⓪
817◊Lucero Luis ⓪
817½◊Robertson Lyman G
823◊Daly Mary E Mrs
825 Lemke Jas W
825½◊Garcia Rafael ⓪
826 Griego Antonio E ⓪
828 Pullen Eug H
◊Gentry Paul V
831◊Clark Jos M ⓪
832 Lynch Geo
833◊Gore Herschel H
Hallock Tracy D
834◊Sanders Troy ⓪
836 Lujan Luciano ⓪
838 Lopez Max L ⓪
◊Lopez Cleaners
839◊Rael Ramon ⓪
840 Rivera Agustin O ⓪
845◊Ross Malcolm A
845½◊Miller G L ⓪
◊Miller Filiberto ⓪
Lovato Frank ⓪
Lovato Moises ⓪
Romero Wm ⓪
◊Duran Ramona Mrs ⓪
◊Lucero Jose A
◊Padilla Lucy
◊Lovato Salomon ⓪
◊Holmes Andreita Mrs ⓪
◊Salazar Antonio ⓪
855◊Palace Grocery
◊Saiz Ricardo ⓪
857 Lovato Canuto G ⓪
857½◊Lovato Apolonio ⓪
Davis John
864 Douglas Oscar
Rivera Frank ⓪
868 Duran Arth A mech
874◊Trujillo Ramoncita R Mrs ⓪
876◊Montoya David S ⓪
878◊Sparr Lugarda Mrs ⓪
880 Corner Grocery
Rivera Alfonso ⓪
Cerro Gordo rd begins ns
Alameda intersects
940◊Sandoval Santiago ⓪
941 Vigil Eloisa Mrs ⓪
944◊Vigil Juan S ⓪
Canon rd intersects

1

PALACE AV WEST — Begins 100 Washington av extends west to Grant av (Right Odd)
ns◊Palace of the Governors
◊Archaeological Society of N M
◊Museum of N M-Sch of Am Research
Historical Society of N M
Internatl Museum of Folklore Art
Lincoln intersects
100◊Hudson Dealer autos
ns◊Museum of N M Art Gallery
108 Vacant
110◊J & M Radio Sales & Serv Co
114 Plaza Service Shop appliance reprs
Niles Safe & Lock Service
Clark Leslie M
116◊Gallette Automotive Serv
Sheridan begins ns
122◊Niles Safe & Lock Co
123 **Bishop Building** Rooms:
1-2◊Bishop C A & Co ins
4-5◊Avery-Bowman Co real est
◊Avery-Bowman Abstract Co
◊Avery-Bowman Real Est Co
6-7◊Mutual Bldg & Loan Assn

Report ID: 25121700727 - 12/22/2025
www.erisinfo.com

AGUA FRIA—Contd
927 Romero Luis ⓪
928◊H & H Grocery
Herrington R L
Urioste intersects
Franklin pl bg ss
937 Chavez Pedro ⓪
941 Sanchez Jose
943◊Lyons Frank
Lyons Alma midwife
1 rear Hurtado Juanita Mrs
2 rear Lopez Eliseo ⓪
3 rear Vallegos Florinda Mrs
4 rear Anaya T C Mrs ⓪
5 rear Anaya Vicenta ⓪
950 Pentecostal Mission
◊Benavides Rubel ⓪
952 Lawrence Ellen Mrs
954 Gutierrez C N ⓪
985◊Smith R D ⓪ contr
Kathryn bg es
1201◊Settys Body Shop auto repr
rear◊Brown H E
1205 Nelson Wesley
1207◊Hansen Lbr Co
◊Hansen J O ⓪
1243 Alire Miguel ⓪
1247◊Lamoreaux H O ⓪
1251 Padilla Albino ⓪
1252 Romero Celestino ⓪
1253 Rodriguez Luis ⓪
1255 Garcia A R ⓪
1257 Alire Nicolas ⓪
Cortez bg ss
Salazar bg ss

AGUA FRIA ROAD — Continuation of Agua Fria bey city
◊Larragoite School

ALAMEDA EAST—Begins 300 Don Gaspar av ext east (Right Even)
113◊Original Mex Cafe
Lawrence W J ⓪
121◊Mountain States T & T Co
129◊Memorial Chapel
Shelby ends ns
137◊White L E
138◊State Planning Bd
State Park Comnr
Apartments
*1 Cassell Ruth Mrs
*2◊Arias Raymond
*4 Ward Florence
*8 Scheid Gerda
141◊Shankweiler L S Mrs
143◊Vohs Wm
145 Gairey J W
College intersects
Cathedral pl ends ss
S Castillo intersects
301-5 Casitas Del Rio
*1 Sadler W C
*2◊Lutzow M B
*3 Emantian Richd
*4◊Drew Cullen
311◊Harvey J C ⓪
328◊Wheeler E L ⓪ contr
331 Castillo Margarita ⓪
337 Jimenez J M ⓪
339 Roybal Eugenio
rear Gonzalez J B ⓪
341 Burlington Mary Mrs
343 Landwehr R J
345 Marales Anita Mrs
rear Gonzales Ismael ⓪
Medrano Andres Mrs ⓪
Chavez M R
349 Johnson Ramona
rear Vacant
353 Ratliff R W
Delgado intersects
401◊Goxem G G
403◊Lucero Wm ⓪
rear Lucero P F
407 Vacant
411 Howland Lourdes Mrs ⓪
523◊Magers H B ⓪
528◊Stevenson F R ⓪
540◊Proebstel Chas ⓪
550◊Hapgood T E ⓪
564◊Wangerien H A ⓪
Camino Escondido bg ss
614◊Zahn Geo
615 Tandy Helen
616 Saiz Jose ⓪
616½ Romero Antonio
617◊Summers Consuelo Mrs ⓪
618◊Werther Wm ⓪
rear Herrera Jose ⓪
◊Sisneros Julio ⓪
637 Romero J J jr ⓪
Camino Escondido intersects
829 Griego Pablo
831 Sesneros Andres
835 Vacant
837 Galvan Catarino ⓪
Rodriguez Petrita
837½ Lynch Curtis
840◊Miller C A ⓪
rear Lobato Marcial
E Palace av intersects
868 Vacant
870 Taylor W E
rear Montoya Jose

ALAMEDA WEST — Begins 234 Don Gaspar av ext west (Right Odd)
209-13◊White Swan Lndry
Agua Fria intersects
425◊Santa Fe Hay & G Co
530 Lopez Theo
532 Vacant
rear Vacant
534◊Flores Alexandro
536 Jaramillo J E
rear Vacant
538◊Ponce Albert
600 Quintana Antonio
604 Romero Frances Mrs
606 Vacant
698 Jaramillo Porfirio
Candelario intersects
710 Barela Roque

PALACE AV E—Contd
309◊Kinsolving C J Rev
311 Holy Faith Church
315 Holy Faith Parish Hall
323◊Goodman Morey
323½◊Polhemus L E ⓪
325◊Dove F A ⓪
329 Vacant
330◊La Posada Inn hotel
Cactus Tea Room
◊Mason R H ⓪
333◊Berry F A ⓪
342◊Jopling Carl
343◊Barker E S ⓪
347◊Bryars W D
350◊March J W ⓪
354◊Otero Maud Mrs ⓪
355 Hinojos R O Mrs ⓪ translater
356 Quintana Frances Mrs
358 Vacant
358½ Romero Henry
Martinez bg ns
401◊White T J ⓪
406◊Green Mary
409◊Harkins P M ⓪ contr
412 DeBolt R E
417 **Palomar Apartments**
◊I Am DeCree
◊Lucas Donna
◊Santa Fe Catholic Maternity Institute
Armijo bg ns
Delgado bg ss
504 Gonzalez G L Mrs ⓪
508 Seifert C H
510◊Thomas F T
511◊Shannon M J Mrs ⓪
512◊Dring Ruth
512½ Ferrich Marie Mrs nurse
514◊Hamilton J B
518◊Rolls Kate Mrs ⓪
519 Vacant
525◊Coombs R B
529 Castle H S
531◊Kelly D T ⓪
535◊Kelly E T Mrs ⓪
542◊Montgomery A K ⓪
◊Manuel LeRoy
606◊Walter J K S
◊Cobb Elmer ⓪
607◊Davenport LaMar
608◊Stauffer Virginia Mrs ⓪
610◊Scott L B
614◊Foster R T
616◊Harris Wm
616½ Thompson R E
617◊Kiker H A ⓪
628 Watson Noble
629◊Corrigan G J Mrs
636◊Brown Bernard Mrs
638◊Updike J T
Blythe School
Rodriguez bg ss
639◊Walter P A F ⓪
640 McKain Edna Mrs
642 Street Ralph
644◊Martinez U J Rev
645 **Apartments**
*1 Romero Alejandro ⓪
*2 Rael A G Mrs ⓪
*3◊Vigil Guadalupita
*4 Romero Victor ⓪
645½ Herrera Isabel ⓪
651◊McConvery J C ⓪
705◊Hohmann F J
Rodriguez bg es
729◊Lord D D ⓪
730 Vacant
LaVereda bg ns
815◊Safford E L ⓪
Baker J E
817◊Pierre Woodman
817½◊Cuicci Danl
823◊Daly M E Mrs
825◊Quintana J A ⓪
825½ Garcia Rafael ⓪
826 Vacant
827 Salazar Adela Mrs
828◊Byers Wm E
831 Holmes Andreita Mrs ⓪
832 Griego Frank ⓪
833 Meza F O
834◊Uphaw Mae ⓪
836 Cisneros Paulita Mrs ⓪
838 Lopez M L ⓪
839 Rael Ramon ⓪
840 Rivera A O ⓪
845◊Ross M A
845½◊Miller G L ⓪
rear Lovato Leandro ⓪
Lovato Apolonio
Lovato Frank ⓪
Lovato Moises
Lovato Salomon
Holmes Andrieta Mrs
Rodriguez Eduardo
Miller Filiberto
Montoya David ⓪
851 Vacant
855◊Palace Gro
◊Saiz Ricardo ⓪
857 Lovato C G ⓪
rear Muniz Onofre Mrs
864 Rivera Frank ⓪
868 Trujillo y Lopez Ramon gro
874 Trujillo Romancita Mrs ⓪
876◊Counts V D
878 Sparr Lugarda Mrs
880 Scott Harvey
Cerro Gordo rd bg ns
Alameda ends ss
940◊Sandoval Santiago
941 Vigil Eloisa Mrs
944◊Latimer R L
Canon rd intersects

PALACE AV WEST—Begins 100 Washington av extends west to Grant av (Right Odd)
ns◊Palace of the Governors
Museum of N M

ss Byres P E ◎
ss Cruz Aniceto ◎

ALAMEDA EAST
Begins 300 Don Gaspar av ext east (Right Even)
113 Original Mex Cafe
121 Mountain States T & T Co
129 Sayre-Andrew Funeral Home
Shelby ends ns
137 White L E
138 Williams Melba Mrs
Mahboub F W
138 State Emp Serv
State Park Comnr
141 Borders Olive Mrs
143 Vohs Wm
145 Meffert Lydia Mrs
College intersects
Cathedral pl ends ss
S Castillo intersects
301-5 **Casitas Del Rio**
*1 Wallis W R
*2 Ashmore R L
*3 Bayne C W
*4 Shamhart C A
*5 McVey V L
*6 Allen K E
311 Harvey J C ◎
328 Wheeler E L ◎ contr
331 Castillo Margarita ◎
337 Jimenez J M ◎
339 Roybal Eugenio
rear Gonzalez J B ◎
341 Payne H R
343 Trujillo J F
343½ Medrano Tomas ◎
345 Medrano Andres ◎
349 Labadie Jose ◎
353 Ratliff R W
Delgado intersects
401 Bakke M A
407 Callahan Tonita Mrs
528 Stevenson F R ◎
528½ Murphy C J
540 Proebstel Chas ◎
550 Rose A D Mrs ◎
564 Wangerien H A ◎
Camino Escondido bg ss
614 Finney R G
615 Bliss J H
616 Saiz Jose ◎
1 rear Saiz Frank ◎
2 rear Rodriguez Benedicto ◎
3 rear Ortega Manuel ◎
4 rear Armijo Adolph
617 Watson W A
618 Pacheco Ramon ◎
Sandoval Santiago ◎
637 Rodriguez D M
Camino Escondido intersects
835 Terrell G R ◎
837 Sanders Troy

ALAMEDA E (Cont'd)
840 Miller M R Mrs ◎
Martinez Eliseo
Sherman L W
E Palace av intersects
863 Pope David
870 Puckett R E

ALAMEDA WEST
Begins 234 Don Gaspar av ext west (Right Odd)
209-13 White Swan Lndry
Agua Fria intersects
451-53 Santa Fe Hay & G Co
500 Gilcrease M A Jr
508 Sanchez Lee
530 Arrey Frank ◎
600 Vigil Ray
620 Jaramillo J E ◎
Candelario intersects
710 Romero Frances Mrs
730 Montoya F B
Varela Anastacio ◎
736 Moreno Saml
738 Varela Wm
766 Benavides Pablo ◎
770 Mora Iosefita Mrs ◎
784 Watson Noah
790 Arellano Federico ◎

ALARID
Bg 800 W Manhattan ext south (Right Even)
513 Griffin B N
515 Sandoval J B ◎
517 Vacant
520 Gonzalez Cesaria Mrs ◎
527 Baca C L ◎
534 Alarid Socorro Mrs ◎
538 Miller O A
546 McNatt W C
548 Help Yourself Lndry
Hickox intersects
603 Henson French
607 Kilmer M L
609 Ackerman L A
611 Grubbs L F
rear Stephenson W C
611½ Weirich S E
617 Yates T E ◎
618 Narvaez Adolfo ◎
621 Irby C H ◎
626 Mercer D H
628 Martinez Emilia Mrs
630 Longacre Rube
Ninita intersects
701 Gonzalez Faustin ◎
703 Gonzalez Onecimo ◎

ALLENDALE
Begins ½ blk north of 224 Sena ext south (Right Even)
723 Conway T W
725 Root L F
W Buena Vista av intersects

PALACE AV E (Cont'd)
644 Rodriguez S M Mrs ◎
645 **Apartments**
*1 Romero Alejandro ◎
*2 Rael A G Mrs ◎
*3 Vigil Meliton ◎
*4 Romero Victor ◎
645½ Herrera Antonio ◎
651 McConvery J C ◎
705 Fisher R G
Rodriguez bg es
729 Lord D D
La Vereda bg ns
815 Fish J C
Baker J E
817 Milford S J
817½ Safford E L ◎
823 Daly M E Mrs
825 Roberts E W
825½ Ross M A Jr
826 Griego Juan ◎
827 Salazar Adela Mrs
828 Ross M A
831 Kirkpatrick R L
832 Griego Frank ◎
833 Robertson G R
833½ James Agnes Mrs
834 Harrison M J
836 Cisneros Paulita Mrs ◎
838 Lopez Max ◎
839 Rael Ramon ◎
840 Rivera A O ◎
845 Palace Gro
1rear Lovato Salomon
2rear Miller Filiberto
4rear Romero Bernardo ◎
5rear Montoya Abenicio
6rear Bustos Benj
845½ Miller G L ◎
1rear Lovato Leandro ◎
2rear Miller Filiebrto
3rear Montoya David ◎
851 Byers W E ◎
855 Morriss D H
1rear Lovato Apolonio
2rear Miller Mariana ◎
857 Lovato C G ◎
rear Muniz Rafael
864 Rivera L O Mrs ◎
868 Trujillo y Lopez Ramon gro
874 Trujillo Pilar ◎
876 Kennedy J L
878 Vacant
880 Montoya Francisco ◎
Cerro Gordo rd bg ns
Alameda ends ss
940 Jeffus Hubert
941 Vigil Eloisa Mrs
944 Clodfelter M L
Canon rd intersects

PALACE AV WEST
Begins 100 Washington av extends west to Grant av (Right Odd)
ns Palace of the Governors
Museum of N M
N M Historical Soc
N M Historical Review
El Palacio
Sch of Amer Research
N M Library Ext Serv
Museum of N M Library
N M Archeological Soc
Lincoln intersects
sw cor Beers Don Motor Co
ns Museum of N M Art Gallery
108 **Cassell Building**
Avery-Bowman Co ins
114-16 S W Master Craftsmen
Sheridan bg ns
123 New Mexican Pub Co
Santa Fe New Mexican
Capital Examiner
124 Delgado Miguel ◎
126-30 Dendahl Building
128 Broome Furn Co
129-31 Broome Furn Co
130 Safeway Stores
135 Standard Stas Inc
136 Dodds I C
138 Candelario Fin Co
Candelario Purch Agcy
Cunningham R lawyer
140 Emblem & Lawrence autos
Grant av intersects

PALOMA
Begins 1 blk north of 201 E Manhattan ext south
402 Charles Perl
403 Joiner Stanley
405 Kerr Earl
407 Williams D B ◎
408 Yontz H B ◎
411 Fraser F D ◎
412 Harris P B
415 Harding J J
416 Stephenson Florence ◎
419 Ormsbee R L ◎
420 Kaufman Emil
E Manhattan intersects

PARK AV
Begins 501 W San Francisco ext north (Right Odd)
110 Federici F J
112 Srok Tony
114 Anderson O L
117 Sanchez Eufemia Mrs ◎
118 Seligman Jacob ◎
119 Pacheco Jose ◎
119½ Kopanos Peter
122 Ortega Marcial ◎
123 Rodriguez J L ◎

ALAMEDA E—Cont'd
540 Proebstel Chas ◎
550 Rose A D Mrs ◎
564 Wangerien H A ◎
Rose av begins ss
614 Vacant
616 Romero Daniel
(1) rear Saiz Frank ◎
(2) rear Rodrizuez Benedicto ◎
(3) rear Ortega Manuel
618 Sandoval Santiago ◎
rear Pacheco Ramon
E Palace av intersects

ALAMEDA WEST
Begins 234 Don Gaspar av extends west to Hancock
211-13 White Swan Lndry Co

ALARID
Begins 800 W Manhattan extends south to Ninita
515 Sandoval B H ◎
520 Alarid J D ◎
534 Alarid Ricardo ◎
536 Miller O A
564 Haun L M ◎
Hickox intersects
603 Wrinkle J R
607 Smith V E
609 Baca C L
611 Ortiz Florentino ◎
rear Morris M L
617 Yates T E ◎
rear Thompson J E
618 Narvaez Adolfo ◎
621 Irby C H ◎
626 Haynes W L ◎
628 Martinez E G Mrs ◎
630 Vigil J E ◎
632 de Baca L C ◎
Ninita intersects
701 Gonzalez Faustin ◎

ALLENDALE
Begins ½ blk north of 224 W Buena Vista av extends south 2 blks
723 Cooper W M
725 Burleson F E
W Buena Vista av intersects
805 Street G F ◎
808 Lopez Alfonso ◎
811 Williamson Al
812 Vacant
813 Reynolds M B
814 Nix M L
815 Cornelson F E
818 O'Hara J S ◎
819 Smith O W ◎
822 Shimp Mildred Mrs ◎
823 Sadler D K
828 Tyner C D ◎
829 Hammond H J
831 Anderson W R
832 Ashley A J

ALTO
Begins 200 De Fouri extend west beyond city limits
508 Campbell C M ◎
510 Garcia Adelaida Mrs
514 Chavez Romualdo ◎
516 Garcia Martha Mrs ◎
518 Garcia Vicente ◎
522 Espino Candelario ◎
524 Rivera Telesforo
525 Armijo Isabelita Mrs ◎
rear Armijo Pablo
526 Gonzalez Benj
527 Garcia Jose
528 Chavez Eufemia Mrs
529 Armijo Adolfo ◎
531 Garcia Francisquita
532-34 Ortiz J M ◎
536 Cisneros Benj
540 Roybal Genoveva Mrs ◎
Polaco bg ss
542 Armijo M V Mrs ◎
rear Maes Antonio
548 Sandoval Bonifacia ◎
550 Ortega J A ◎
Closson intersects
604 Vacant
605 Sena Mariano ◎
606 Sena J G ◎
608 Moya Antonio
610 Cordova Margarita
618 Montoya Miguel ◎
620 Lucero P G ◎
622 Cisneros Juan
Barela bg ss
636 Ortiz W J ◎
648 Ortiz Candido ◎
Young bg ss
724 Rivera Placida Mrs
728 Ellison Maria ◎
736 Roybal Luciano ◎
(1) rear Rivera Placida
(2) rear Roybal Jose ◎
(3) rear Romero Alejandrino ◎
(4) rear Coriz Tranquilino ◎
(5) rear Montoya Lillie Mrs
(7) rear Velarde Pomposo ◎
737 Roybal Pedro ◎
rear Salazar Jose
741 Vacant
Irvine bg ss
Ambrosio bg ss
821 Arrey Jesus
831 Valdez Otto ◎
837-39 Rougemont Marcelino
845 Montoya Albino ◎
847 Montoya Guadalupe ◎
851 Roman Urbano ◎
853 Montoya J L ◎
Montoya intersect
903 Montoya Manuel ◎

ALACE AV E—Cont'd
18 Rolls J A ◎
19 State Pub Health Dept
25 Thomas C C
29 Webster F A
31 Kelly D T
35 Kelly H W Mrs ◎
42 Pond Hazel Mrs ◎
106 Reed E C Mrs ◎
107 Donnell F S ◎
108 Stauffer J K ◎
610 Seligman O P ◎
614 Vacant
616 Miller Prager
617 Summers O B ◎
628 Rodriguez R A ◎
629 Vacant
638 Rodriguez D M ◎
Rodriguez bg es
639 Walter P A F ◎
(1) rear Romero Alejandro ◎
(2) rear Vigil Meliton ◎
640 Lelekas Peter
642 Simmons E H
644 Rodriguez S M Mrs ◎
645 Rael Marcos ◎
645½ Herrera Antonio ◎
651 McConvery J C ◎
705 Fisher R G
La Vereda bg ns
729 Wait F L Mrs
Southwest Sch
730 La Vereda Stables
815 Safford E L ◎
817 Gross R H Jr
817½ Madsen R W
823 Perry E M
825 Norvell C B
Santa Fe Eng Co
826 Griego Juan ◎
827 Salazar Adela Mrs
828 Griego Pablo ◎
831 Martinez Ezequiel
832 Griego Placida Mrs ◎
833 Ragle P H ◎
834 Ferran Leo
834½ Dozier J P
836 Cisneros Anastacio ◎
838 Lopez Max ◎
839 Rael Ramon ◎
840 Rivera Agustin
845 Saiz Rebeca Mrs
(1) rear Lovato Salomon
(2) rear Sandoval Guillermo
845½ Speer Chas
(1) rear Lovato Leandro
(2) rear Montoyo David ◎
(3) rear Romero Bernardo ◎
851 Byers W E
855 Holmes Oliver ◎
(2) rear Miller Mariana ◎
857 Lovato C G
rear Lopez Concha Mrs ◎
864 Rivera L O Mrs ◎
868 Trujillo y Lopez Ramon ◎
874 Trujillo Pilar ◎
876 Caldwell R H
878 Murray J P
880 Qualls J D
Alameda ends ss
915 Parsons Sheldon ◎
Cerro Gordo rd bg ns
940 Russell F L
941 Garcia Antonio ◎
Martin Orville
944 Brown R E
Canon rd intersects

PALACE AV WEST
Begins 100 Washington av extends west to Grant av
ns Palace of the Governors
Museum of N M
N M Historical Soc
N M Historical Review
El Palacio
Sch of Amer Research
Museum of N M Library
N M Archeological Soc
Lincoln intersects
sw cor Cassell Motor Co
Rent A Car Co
ns Museum of N M Art Gallery
108 Cassell Building
Avery-Bowman Co
Mutual Bldg & Loan Assn
Santa Fe Abst Realty & Ins Agcy
114-16 S W Master Craftsmen
Sheridan bg ns
123 Santa Fe New Mexican Pub Corp
Santa Fe New Mexican
El Nuevo Mexicano
Associated Press
124 Delgado Miguel ◎
126-30 Dendahl Building
128 Broome Furn Co
129 Native Market
130 Mac Marr Stores
131 Broome Furn Co 2d hnd dept
136 Candelario J S ◎
138 Montgomery Ward & Co
140 Emblem & Sauer
Packard Serv Sta
ne cor Standard Stations
Grant av intersects

PALOMA
Begins 1 blk north of 201 E Manthattan extends south
402 Shuart H E
407 Williams D B ◎
408 Yontz H B ◎
411 Fraser F D ◎
412 Zinn A L
415 Walker R S ◎

www.erisinfo.com

1930-31 E ALAMEDA ST

SOURCE: HUDSPETHS

RANGE NOT LISTED

1930-31 E PALACE AVE

SOURCE: HUDSPETHS

PALACE AV E—Cont'd
350 Seligman Arthur ◎
354 Otero M A ◎
355 Hinojos Alfredo ◎
356 Garcia D B Mrs ◎
Quintana Frank
358 Salazar William ◎
358½ Fayette Joseph ◎
Martinez bg ns
406 Holderman T J
409 Vacant
412 Hamilton M W
417 **Palomar Apts**
Tipton J E
Jenkyns Gladys Mrs
Manuel L R
Armijo bg ns
Delgado bg ss
502-4 Gonzalez G L Mrs ◎
508 Delgado M T Mrs ◎
511 Agens Donia Mrs
512 Smith T A
514 Collins J F
518 Rolls J A ◎
519 Vacant
525 Brown Burton
529 Vacant
531 Kelly D T ◎
535 Pond Ashley ◎
606 Reed E C Mrs ◎
607 Donnell F S ◎
608 Stauffer J K ◎
610 Seligman O P ◎
617 Chavez Amado ◎
628 Rodriguez R A ◎
629 Kenney J J ◎
Rodriguez bg es
635 Walter P A F ◎
(1) rear Romero Alejandro ◎
(2) rear Vigil Meliton ◎
(3) rear Padilla Luis
642 Roberts W A
644 Rodriguez S M Mrs ◎
645 Rael Marcos ◎
645½ Herrera Antonio ◎
651 McConvery J C ◎
705 Nielsen W W
La Bareda bg ns
729 McNary J G
815 Safford E L ◎
819 Greer H K
823 Daly R M ◎
825 Gonzalez M E Mrs ◎
826 Griego Juan ◎
827 Osborne H R
828 Griego Pablo ◎
831 Vacant
833 Griego Vivian ◎
833 Bratschi W G
834 Weed R S
rear Reynolds C C
836 Cisneros Anastacio ◎
838 Miller Chas ◎
839 Rael Ramon ◎
843 Miller G L
845 Miller Raymond
(1) rear Lovato Lorenza
(2) rear Miller Mariana ◎
851 Beyers F W
(1) rear Lovato Leandro
(2) rear Montoyo David ◎
(3) rear Zamora Juan
(4) rear Valdez Joseph ◎
(5) rear Garcia Anastacio ◎
855 Holmes Oliver ◎
(1) rear Lovato Apolonio ◎
(2) rear Sandoval William ◎
(3) rear Romero Bernardo ◎
(4) rear Rivera William ◎
857 Lovato Canuto ◎
rear Montano Sotero ◎
861 Vacant
864 Rivera L O Mrs ◎
865 Vacant
868 Trujillo y Lopez Ramon ◎
874 Trujillo Pilar ◎
876 Vacant
878 Wiley J W
880 Myers L F
Alameda ends ss
915 Parsons Sheldon ◎
Cerro Gordo rd bg ns
925 Field W M ◎
940 Sandoval Santiago
941 Garcia Antonio ◎
944 Dozier Paul
Canon rd intersects

PALACE AV W
Begins 100 Lincoln extends w to Grant av
sw cor Cassell Motor Co
ns Museum of N M Art Gallery
School of American Research
N M State Library
108 **Cassell Building**
Avery-Bowman Co

1928-29 E ALAMEDA ST

SOURCE: HUDSPETHS

RANGE NOT LISTED

1928-29 E PALACE AVE-A

SOURCE: HUDSPETHS

129-29½ Romero F B
131 Vacant
133 Vacant
133½ Standish Annie Mrs
135 Abreu Marcos
141 County Court House
Cathedral pl bg ss
Otero bg ns
210 St Vicent Sanatorium
St Vicent Orphanage
St Vicent Sanatorium & Hosp Training School for Nurses
Brown R O
Alexander H S A
McIntyre E F
211 Flynn R F (o)
223 Lutes O A Mrs (o)
229 Riddle Geo Mrs (o)
237 Spitz B W (o)
Castillo intersects
301 Morrison A L (o)
307 Zook J N (o)
308 Baca R L (o)
309 Trowbridge W S
311 Holy Faith Church
315 Holy Faith Parish Hall
324 Munchoff W C
324½ Slaughter W D
329 Neblett Colin (o)
330 Elliott L E (o)
333 Wood D P
342 Davies E P (o)
343 White T J (o)
347 Murphy J T (o)
350 Seligman Arthur (o)
354 Otero M A (o)
355 Hinojos Alfreda (o)
356 Garcia D B Mrs (o)
Quintana Frank
358 Salazar William (o)
Martinez bg ns
406 Shafer L D Miss (o)
409 Martinez J R (o)
412 Thompson F K
417 Manuel Le Roy
Thompson Burton
Delgado bg ss
502-4 Gonzalez G L Mrs (o)
508 Delgado Margaret (o)
510 Turney L E
511 Gallegos J C
512 Simmons C W
514 Collins J F
518 Rolls J A (o)
519 Vacant
525 Taichert D H
529 Wheelon C A
531 Kelly D T (o)
535 Pond Ashley (o)
606 Reed E C Mrs (o)
607 Donnell F S (o)
608 Hunsaker Mabel Mrs
610 Seligman O P (o)
617 Chavez Amado (o)
628 Rodriguez R A (o)
629 Kenney J J (o)
Rodriguez bg es
635 Walter P A F (o)
(1) rear Romero Aljandro (o)
(2) rear Vigil Meliton (o)
(3) rear Brito Juan
642 Sandoval A G
644 Rodriguez S M Mrs (o)
645 Rael Marcos (o)
651 McConvery J C (o)
Herrera Antonio (o)
705 Gibbons G R
LaBareda bg ns
729 Renehan Marietta (o)
815 Safford E L (o)
819 Broaddus W H
821 Lucero Nazario
823 Daly R M (o)
825 Gonzalez M E Mrs (o)
826 Griego Juan (o)
827 Johnson M M (o)
828 Griego Pablo (o)
831 Fagan Bess Miss
832 Griego Vivian (o)
833 Southgate Howard
834 Miller Charles (o)
rear Shannon Guy
836 Cisneros Anastacio (o)
838 Lopez Max (o)
839 Rael Ramon (o)
845 Garren J R
(1) rear Lovato Lorenzo
(2) rear Miller Mariana (o)
851 Holmes Apolonia Mrs (o)
(1) rear Duran Alfonso
(2) rear Montoyo David (o)
(3) rear Ortiz Rafael (o)
(4) rear Valdez Joseph (o)
(5) rear Garcia Anastacio (o)
855 Holmes Oliver (o)

(1)rear Lovato Apolonio(o)
(2)rear Sandoval William (o)
(3)rear Romero Bernardo (o)
(4)rear Rivera William (o)
857 Lovato Canuto (o)
rear Montano Sotero (o)
861 Vacant
864 Rivera L O Mrs (o)
865 Vacant
868 Trujillo y Lopez Ramon (o)
874 Trujillo Pilar (o)
880 Howland Frank

Alameda ends ss

915 Parsons Sheldon (o)

Cerro Gorda rd bg ns

925(926)Nielsen W W (o)
941 Garcia Antonio (o)
944 Crawford F L

Canyon rd intersects

PALACE W

Begins 100 Lincoln av extends w to Grant av

sw cor Cassell Motor Co
ns Museum of N M Art Gallery
108 Cassell Building Avery-Bowman Co Mutual Bldg & Loan Assn

Sheridan bg ns

123 Santa Fe New Mexican Pub Corp
124 Delgado Lucy Mrs (o)
132 Jackson R D
136 Candelario J S (o)
127-29 Vacant

Grant av intersects

PALOMA

Begins 1 blk north of 201 E Manhattan extends south

406 Vacant
407 Williams D B (o)
408 Yontz H B (o)
419 Ormsbee R L (o)
420 Moore G E

E Manhattan intersects

PARK AV

Begins 501 W San Francisco extends north 1 blk

110 McIntosh C R
112 Thompson Louise Mrs
114 Kaune G J
119 Sanchez Elena Mrs (o)
119½ Valdez Eduviges Mrs
122 Seward L B
123 Rodriguez J L (o)
124 Hamill H A
134 Vacant
138 Duran Emilio (o)

Rosario intersects

PECOS ROAD

Begins 801 College extends southeast

es Urioste Teodora Mrs (o)

Coronado rd ends es

ws Cutting B M (o)
es Meem & McCormick Summount San

PINO

Begins 529 College extends west

307 Cortinas Catalino
311 Sandoval Frank
313 Griego Nicolas
316 Sena Andres (o)
318 Vigil Nicolita Mrs (o)
319 Esquivera Frank (o)
321 Esquivera Francisco
323 Esquivera Ramon
325 Gonzalez Florencio
327 Garcia Francisca (o)
327½ Garcia Juan
329 Garcia Juan
333 Chavez Juan (o)
rear Gallegos Teresa Mrs(o)
335 Gutierrez Dionicia Mrs

PLAZA BALENTIN

Begins 617 E Manhattan extends north ½ blk

QUINTANA

Begins 600 Alto extends south 1 blk

es Maes Nicolas
es Maes Fred (o)
es Lujan Alfonso (o)
es Roybal Juan (o)
ws Archuleta Abel (o)
ws Archuleta Paul (o)
ws Gabaldon Silverio (o)
ws Gabaldon Hilario (o)
ws Rivera Isidro (o)
ws Vacant

APPENDIX H

Database Report

DATABASE REPORT

Project Property:	*Lopez Cleaners* *838 East Palace Avenue* *Santa Fe NM 87501*
Project No:	*NMENV.M007.SF-WALDO*
Report Type:	*Database Report*
Order No:	*25121700727*
Requested by:	*INTERA Incorporated*
Date Completed:	*December 18, 2025*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....8
Executive Summary: Site Report Summary - Surrounding Properties.....9
Executive Summary: Summary by Data Source.....10
Map.....12
Aerial.....15
Topographic Map.....16
Detail Report.....17
Unplottable Summary.....22
Unplottable Report.....23
Appendix: Database Descriptions.....24
Definitions.....39

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:		*Lopez Cleaners* *838 East Palace Avenue Santa Fe NM 87501*
Project No:		*NMENV.M007.SF-WALDO*
Coordinates:		
	Latitude:	*35.68203566*
	Longitude:	*-105.9242855*
	UTM Northing:	*3,949,076.01*
	UTM Easting:	*416,362.06*
	UTM Zone:	*13S*
Elevation:		*7,083 FT*

Order Information:

Order No:	*25121700727*
Date Requested:	*December 17, 2025*
Requested by:	*INTERA Incorporated*
Report Type:	*Database Report*

Historicals/Products:

Aerial Photographs	*Historical Aerials (with Project Boundaries)*
Chain of Title & Lien Searches	*ASTM E1527-21 Compliant Environmental Lien Search (back to 1980) with Historic Chain of Title (back to 1932)*
City Directory Search	*CD - 2 Street Search*
ERIS Xplorer	*ERIS Xplorer*
Excel Add-On	*Excel Add-On*
Fire Insurance Maps	*US Fire Insurance Maps*
Physical Setting Report (PSR)	*Physical Setting Report (PSR)*
Topographic Map	*Topographic Maps*

Executive Summary: Report Summary

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
Standard Environmental Records								
Federal								
NPL	Y	1	0	0	0	0	0	0
PROPOSED NPL	Y	1	0	0	0	0	0	0
DELETED NPL	Y	0.5	0	0	0	0	-	0
SEMS	Y	0.5	0	0	0	0	-	0
SEMS ARCHIVE	Y	0.5	0	0	0	0	-	0
ODI	Y	0.5	0	0	0	0	-	0
IODI	Y	0.5	0	0	0	0	-	0
CERCLIS	Y	0.5	0	0	0	0	-	0
CERCLIS NFRAP	Y	0.5	0	0	0	0	-	0
CERCLIS LIENS	Y	PO	0	-	-	-	-	0
RCRA CORRACTS	Y	1	0	0	0	0	0	0
RCRA TSD	Y	0.5	0	0	0	0	-	0
RCRA LQG	Y	0.25	0	0	0	-	-	0
RCRA SQG	Y	0.25	0	0	0	-	-	0
RCRA VSQG	Y	0.25	0	0	0	-	-	0
RCRA NON GEN	Y	0.25	0	0	***1***	-	-	***1***
RCRA CONTROLS	Y	0.5	0	0	0	0	-	0
FED ENG	Y	0.5	0	0	0	0	-	0
FED INST	Y	0.5	0	0	0	0	-	0
LUCIS	Y	0.5	0	0	0	0	-	0
NPL IC	Y	0.5	0	0	0	0	-	0
ERNS 1982 TO 1986	Y	PO	0	-	-	-	-	0
ERNS 1987 TO 1989	Y	PO	0	-	-	-	-	0
ERNS	Y	PO	0	-	-	-	-	0
FED BROWNFIELDS	Y	0.5	0	0	0	0	-	0
FEMA UST	Y	0.25	0	0	0	-	-	0
FRP	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
DELISTED FRP	Y	0.25	0	0	0	-	-	0
HIST GAS STATIONS	Y	0.25	0	0	0	-	-	0
REFN	Y	0.25	0	0	0	-	-	0
BULK TERMINAL	Y	0.25	0	0	0	-	-	0
SEMS LIEN	Y	PO	0	-	-	-	-	0
SUPERFUND ROD	Y	1	0	0	0	0	0	0
State								
SCS	Y	1	0	0	0	**1**	**1**	**2**
DELISTED SCS	Y	1	0	0	0	0	0	0
SWF/LF	Y	0.5	0	0	0	0	-	0
HIST LF	Y	0.5	0	0	0	0	-	0
RECYCLING	Y	0.5	0	0	0	0	-	0
LST	Y	0.5	0	0	0	0	-	0
DELISTED LST	Y	0.5	0	0	0	0	-	0
LUST HIST	Y	0.5	0	0	0	0	-	0
UST	Y	0.25	0	0	0	-	-	0
AST	Y	0.25	0	0	0	-	-	0
TANKS	Y	0.25	0	0	0	-	-	0
UST HIST	Y	0.25	0	0	0	-	-	0
AST HIST	Y	0.25	0	0	0	-	-	0
DELISTED TANK	Y	0.25	0	0	0	-	-	0
INST	Y	0.5	0	0	0	0	-	0
VCP	Y	0.5	0	0	0	0	-	0
BROWNFIELDS	Y	0.5	0	0	0	0	-	0
Tribal								
INDIAN LUST	Y	0.5	0	0	0	0	-	0
INDIAN UST	Y	0.25	0	0	0	-	-	0
DELISTED INDIAN LST	Y	0.5	0	0	0	0	-	0
DELISTED INDIAN UST	Y	0.25	0	0	0	-	-	0
County	***No County databases were selected to be included in the search.***							

Additional Environmental Records

Federal

PFAS GHG	Y	0.5	0	0	0	0	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
OSC RESPONSE	Y	0.125	0	0	-	-	-	0
FINDS/FRS	Y	PO	0	-	-	-	-	0
TRIS	Y	PO	0	-	-	-	-	0
PFAS NPL	Y	0.5	0	0	0	0	-	0
PFAS FED SITES	Y	0.5	0	0	0	0	-	0
PFAS SSEHRI	Y	0.5	0	0	0	0	-	0
PFAS ERNS	Y	0.5	0	0	0	0	-	0
PFAS NPDES	Y	0.5	0	0	0	0	-	0
PFAS TRI	Y	0.5	0	0	0	0	-	0
PFAS WATER	Y	0.5	0	0	0	0	-	0
PFAS TSCA	Y	0.5	0	0	0	0	-	0
PFAS E-MANIFEST	Y	0.5	0	0	0	0	-	0
PFAS IND	Y	0.5	0	0	0	0	-	0
HMIRS	Y	0.125	0	0	-	-	-	0
NCDL	Y	0.125	0	0	-	-	-	0
TSCA	Y	0.125	0	0	-	-	-	0
HIST TSCA	Y	0.125	0	0	-	-	-	0
FTTS ADMIN	Y	PO	0	-	-	-	-	0
FTTS INSP	Y	PO	0	-	-	-	-	0
PRP	Y	PO	0	-	-	-	-	0
SCRD DRYCLEANER	Y	0.5	0	0	0	0	-	0
ICIS	Y	PO	0	-	-	-	-	0
FED DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DELISTED FED DRY	Y	0.25	0	0	0	-	-	0
FUDS	Y	1	0	0	0	**1**	0	**1**
FUDS MRS	Y	1	0	0	0	0	0	0
FORMER NIKE	Y	1	0	0	0	0	0	0
PIPELINE INCIDENT	Y	PO	0	-	-	-	-	0
MLTS	Y	PO	0	-	-	-	-	0
HIST MLTS	Y	PO	0	-	-	-	-	0
MINES	Y	0.25	0	0	0	-	-	0
SMCRA	Y	1	0	0	0	0	0	0
MRDS	Y	1	0	0	0	0	0	0
LM SITES	Y	1	0	0	0	0	0	0
ALT FUELS	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
CONSENT DECREES	Y	0.25	0	0	0	-	-	0
AFS	Y	PO	0	-	-	-	-	0
SSTS	Y	0.25	0	0	0	-	-	0
PCBT	Y	0.5	0	0	0	0	-	0
PCB	Y	0.5	0	0	0	0	-	0
POWER PLANTS	Y	0.125	0	0	-	-	-	0
HIST RISK	Y	0.125	**2**	**1**	-	-	-	**3**
State								
HAZ	Y	0.5	0	0	0	0	-	0
SPILLS	Y	0.125	0	**1**	-	-	-	**1**
SPILLS OIL	Y	0.125	0	0	-	-	-	0
CDL	Y	0.125	0	0	-	-	-	0
PFAS	Y	0.5	0	0	0	0	-	0
GW DISCHARGE	Y	PO	0	-	-	-	-	0
URANIUM	Y	0.5	0	0	0	0	-	0
Tribal	***No Tribal additional environmental record sources available for this State.***							
County	***No County additional environmental record sources available for this State.***							
Total:			**2**	**2**	**1**	**2**	**1**	**8**

**** PO – Property Only***
**** 'Property and adjoining properties' database search radii are set at 0.25 miles.***

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	HIST RISK	Lopez Cleaners	838 E Palace Santa FE NM	SE	0.00 / 0.00	0	17
1	HIST RISK	Lopez Cleaners	838 E Palace av Santa FE NM	SE	0.00 / 0.00	0	17

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
2	HIST RISK	Martinez Bros	725 Canyon rd Santa FE NM	SW	0.09 / 475.82	2	17
3	SPILLS		502 N MAIN MN Santa Fe NM ***Notification ID*	*Status:*** 15783 | Forward Within NMED	S	0.12 / 641.91	7	18
4	RCRA NON GEN	PARROTT FABRICS INC	634 CANYON RD SANTA FE NM 87501 ***Handler ID*	*Recycler Activity?:*** NMD035792506 | NO	WSW	0.20 / 1,055.25	-6	18
5	SCS	Ruben Well	Camino Sin Nombre and Camino San Acacio, 623 Camino Rancheros Santa Fe NM	SSE	0.44 / 2,334.54	107	20
6	FUDS	FORT MARCY	SANTA FE NM ***FUDS Property No:*** K06NM0417	NNE	0.47 / 2,505.29	88	20
7	SCS	913 Old Pecos Trial	913 Old Pecos Trial Santa Fe NM	WSW	0.84 / 4,434.85	0	21

Executive Summary: Summary by Data Source

Standard

Federal

RCRA NON GEN - RCRA Non-Generators

A search of the RCRA NON GEN database, dated Sep 1, 2025 has found that there are 1 RCRA NON GEN site(s) within approximately 0.25miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
PARROTT FABRICS INC	634 CANYON RD SANTA FE NM 87501	WSW	0.20 / 1,055.25	4
	Handler ID* | *Recycler Activity?: *NMD035792506* | *NO*			

State

SCS - State Cleanup Sites Listing

A search of the SCS database, dated Feb 4, 2025 has found that there are 2 SCS site(s) within approximately 1.00miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Ruben Well	Camino Sin Nombre and Camino San Acacio, 623 Camino Rancheros Santa Fe NM	SSE	0.44 / 2,334.54	5
913 Old Pecos Trial	913 Old Pecos Trial Santa Fe NM	WSW	0.84 / 4,434.85	7

Non Standard

Federal

FUDS - Formerly Used Defense Sites

A search of the FUDS database, dated May 15, 2023 has found that there are 1 FUDS site(s) within approximately 1.00miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
FORT MARCY	SANTA FE NM	NNE	0.47 / 2,505.29	6
	FUDS Property No: *K06NM0417*			

HIST RISK - Historical Business Activity Risk

A search of the HIST RISK database, dated Jan 1, 1960 has found that there are 3 HIST RISK site(s) within approximately 0.12miles of the project property.


Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Lopez Cleaners	838 E Palace Santa FE NM	SE	0.00 / 0.00	1
Lopez Cleaners	838 E Palace av Santa FE NM	SE	0.00 / 0.00	1
Martinez Bros	725 Canyon rd Santa FE NM	SW	0.09 / 475.82	2

State

SPILLS - Spills

A search of the SPILLS database, dated May 31, 2025 has found that there are 1 SPILLS site(s) within approximately 0.12miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	502 N MAIN MN Santa Fe NM	S	0.12 / 641.91	3
	***Notification ID | Status**: 15783 | Forward Within NMED*			



Map: 1.0 Mile Radius


Order Number: 25121700727

Address: 838 East Palace Avenue, Santa Fe, NM

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.5 Mile Radius


Order Number: 25121700727

Address: 838 East Palace Avenue, Santa Fe, NM

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.25 Mile Radius


Order Number: 25121700727

Address: 838 East Palace Avenue, Santa Fe, NM

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Aerial


Year: 2024

Order Number: 25121700727

Address: 838 East Palace Avenue, Santa Fe, NM

Source: ESRI World Imagery

© ERIS Information Limited Partnership



Topographic Map

Year: 2023

Order Number: 25121700727

Address: 838 East Palace Avenue, NM

Quadrangle(s): Santa Fe NM

Source: USGS Topographic Map

© ERIS Information Inc.

Detail Report

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	1 of 2	SE	0.00 / 0.00	7,083.40 / 0	Lopez Cleaners 838 E Palace Santa FE NM	HIST RISK

Historic Potential Business Activity Risk

Year:	1953
Directory Publisher:	HUDSPETHS
Broad Term:	Potential Hazardous Chemical User
Directory Heading:	1953
Listing:	Lopez Cleaners
Address:	838 E Palace
Address2:	
City:	Santa FE
State:	NM
Zip:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	2 of 2	SE	0.00 / 0.00	7,083.40 / 0	Lopez Cleaners 838 E Palace av Santa FE NM	HIST RISK

Historic Potential Business Activity Risk

Year:	1949
Directory Publisher:	HUDSPETHS
Broad Term:	Potential Hazardous Chemical User
Directory Heading:	1949
Listing:	Lopez Cleaners
Address:	838 E Palace av
Address2:	
City:	Santa FE
State:	NM
Zip:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	1 of1	SW	0.09 / 475.82	7,084.96 / 2	Martinez Bros 725 Canyon rd Santa FE NM	HIST RISK

Historic Potential Business Activity Risk

Year:	1928-29
Directory Publisher:	HUDSPETHS
Broad Term:	Fuel and Automotive
Directory Heading:	1928-29
Listing:	Martinez Bros
Address:	725 Canyon rd
Address2:	
City:	Santa FE
State:	NM
Zip:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
3	1 of1	S	0.12 / 641.91	7,089.99 / 7	502 N MAIN MN Santa Fe NM	SPILLS

Notification ID:	15783	**Nearest City:**	Santa Fe
Notification Type:	Spills	**County:**	Santa Fe
Notification Date:	3/8/2022 3:44:00 PM	**Incident District:**	
Notificat Priority:		**Field Office:**	
EJ Issue:		**Created by:**	
Assigned Bureau:	Surface Water Quality Bureau	**Date Created:**	
Assigned Staff:	levi.dean	**Entered Sep ID:**	
Status Date:	3/8/2022 4:51:46 PM		
Status:	Forward Within NMED		
Suspect Resp Party:	GM EMULSION		
Resp Party Address1:	5935 AGUA FRIA ROAD		
Resp Party Address2:			
Resp Party City:	Santa Fe		
Resp Party State:	NM		
Resp Party Zip:	87501		
Resp Party Phone:			
Reporter Name:	JAMIE WROBEL		
Reporter Address 1:			
Reporter Address 2:			
Reporter City:	Santa Fe		
Reporter State:	New Mexico		
Reporter Zip:			
Reporter Phone:	505-577-3287		
Reporter Email:	jamie.wrobel@gmail.com		
Description:	Incident Report # 1330491 CALLER REPORTS A NEWLY INSTALLED CONCRETE PARKING LOT HAS BEEN COVERED WITH AN UNKNOWN FUEL, PRESUMABLY AS A TEMPORARY PROTECTANT. CALLER STATES THEY BELIEVE THIS IS EITHER KEROSENE OR DIESEL FUEL. CALLER REPORTS A STRONG SMELL OF FUEL IN THE AIR. CALLER STATES THIS LOCATION IS 250FT FROM THE SANTA FE RIVER AND EXPRESSES CONCERN ABOUT IMPACT TO THE WATER WAY. IT IS CURRENTLY RAINING AT THE INCIDENT LOCATION. NO KNOWN WATER IMPACT/SHEEN IS REPORTED AT THIS TIME.		
Location:	809 CANYON ROAD County: SANTA FE City: SANTA FE State: NM Zip: 87501 On Canyon across from El Farol.		
Data Source:	Environmental Notification Reporting - Spills Reported From 2020 to Dec 2022 (as of 31 Dec 2022)		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
4	1 of1	WSW	0.20 / 1,055.25	7,077.71 / -6	PARROTT FABRICS INC 634 CANYON RD SANTA FE NM 87501	RCRA NON GEN

Handler ID:	NMD035792506
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Sep 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	N	***NAIC 1:***	315191
Seq No:	1	***NAIC 2:***	
Non Notifier:		***NAIC 3:***	
Receive Date:	19800721	***NAIC 4:***	
Active Site:	-----	***State:***	NM
Land Type:		***Location Latitude:***	35.681427
In Handler Univ:	N	***Location Longitude:***	-105.927755
In A Universe:	N	***Loc GIS Primary:***	N
Gen Status:	N	***Loc GIS Origin:***	AG
Report Cycle:		***State District Owner:***	NM
Accessibility:		***State District:***	02
Region:	06		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	NM
State Waste Generator:	N
Short Term Generator:	N
Uni Waste:	N
Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20150414
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	PARROTT FABRICS INC
Location Street No:	634
Location Street1:	CANYON RD
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87501
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Name: ALICE PARROTT
Contact Street No:
Contact Street1: 634 CANYON RD
Contact Street2:
Contact City: SANTA FE
Contact State: NM
Contact Zip: 87501
Contact Country: US
Contact Phone & Ext: 505-982-0794
Contact Fax:
Contact Email Address:
Contact Title:
Owner Name: PARROTT ALICE
Owner Type: P
Owner Seq: 1
Operator Name:
Operator Type:
Operator Seq:
Public Notes:

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 19800721
Handler Name: PARROTT FABRICS INC
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Notification
TSD Activity: N

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: PARROTT ALICE
Dt Became Current:
Dt Ended Current:
Phone: 000-000-0000
Source Type: Notification
Street No:
Street1: UNKNOWN
Street2:
City: UNKNOWN
State: NM
Country:
Zip: 00000-0000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
5	1 of1	SSE	0.44 / 2,334.54	7,190.56 / 107	Ruben Well Camino Sin Nombre and Camino San Acacio, 623 Camino Rancheros Santa Fe NM	SCS

County: Santa Fe
Latitude:
Longitude:
Data source(s): Closed/Inactive State Cleanup Sites(Closed)

Closed Detail

Status: referred to SOS
Date :
Discharge Dt: pre1997
Event: PCE discovered in domestic well
Action Taken: CERCLA conducting an investigation to discover sources sampling of domestic wells in area. No source or RP identified.
Concentrations have decreased over time.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
6	1 of1	NNE	0.47 / 2,505.29	7,171.14 / 88	FORT MARCY	FUDS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					SANTA FE NM	

FUDS Property No: K06NM0417
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map?id=61502
FUDS INST ID: NM69799F621400
Status: Properties without projects
SDS ID:
NPL Status Code:
Eligibility: Eligible
Site Eligib:
Current Owner: PRIV: PRIVATE UNKNOWN ; STATE: STATE UNKNOWN
Has Project: No
DOD FUDS Pro: K06NM0417
Project Required: No
No Further Action:
Congressional District: 03
Congressional Dist 117: 03
Media ID:
Metadata ID:
Feature Desc:
EPA Region: 06
County: SANTA FE
Latitude: 35.68888889
Longitude: -105.92222222
Fiscal year: 2021
USACE Division: SPD
USACE District: Los Angeles District (SPL)
Centroid Lat:
Centroid Long:
Se Anno Cad Data:
Shape Length:
Shape Area:
Shape Len:
X: -105.922180176
Y: 35.689025879
Data Source: U.S. Army Corps of Engineers Geospatial Open Data
Property History:

Feature Description:

The DOD began use of the site in 1846 when U.S. troops under General Stephen Watts Kearney occupied the area. The military post was intended as a citadel to which troops could retreat and hold out until help arrived. The site was abandoned in 1894 as a military post and transferred to the city of Santa Fe in 1904.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
7	1 of1	WSW	0.84 / 4,434.85	7,083.77 / 0	913 Old Pecos Trial 913 Old Pecos Trial Santa Fe NM	SCS

County: Santa Fe
Latitude: 35.675081
Longitude: -105.936761
Data source(s): Active State Cleanup Sites

Active Detail

Project Manager: Kate
Depth To Water (Ft): unknown
Flow Direction: unknown
Media Impacted: Soil Vapor
Regulatory Status: CAR 1203.A
Size Acres: <1
Contam of Concern: PCE, TCE, VOCs
Assmnt/Abatement: Assessment in progress

Unplottable Summary

Total: 0 Unplottable sites

DB	Company Name/Site Name	Address	City	Zip	ERIS ID

No unplottable records were found that may be relevant for the search criteria.

Unplottable Report

No unplottable records were found that may be relevant for the search criteria.

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ERIS updates databases as set out in ASTM Standard E1527-13 and E1527-21, Section 8.1.8 Sources of Standard Source Information:

"Government information from nongovernmental sources may be considered current if the source updates the information at least every 90 days, or, for information that is updated less frequently than quarterly by the government agency, within 90 days of the date the government agency makes the information available to the public."

Standard Environmental Record Sources

Federal

National Priority List: NPL

The U.S. Environmental Protection Agency (EPA)'s National Priorities List (NPL) includes the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program, based primarily on the score a site receives from EPA's Hazard Ranking System. A site must be on the NPL to receive money from the Superfund Trust Fund for remedial action. This data includes NPL sites represented as polygons, where available, that can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS), and is limited to those sites where the NPL Status reflects the site is 'Currently on the Final NPL (F)' and/or the 'Site is Part of NPL Site (A)'. These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. As site investigation and remediation progress, OUs may be added, modified or refined. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Sep 6, 2025

National Priority List - Proposed: PROPOSED NPL

Sites proposed by the U.S. Environmental Protection Agency (EPA), the state agency, or concerned citizens for addition to the National Priorities List (NPL) due to contamination by hazardous waste and identified by the EPA as a candidate for cleanup because it poses a risk to human health and/or the environment. Sites represented as polygons, where available, can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Sep 6, 2025

Deleted NPL: DELETED NPL

Sites deleted from the U.S. Environmental Protection Agency (EPA)'s National Priorities List (NPL). The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate. Sites represented as polygons, where available, can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Sep 6, 2025

SEMS List 8R Active Site Inventory: SEMS

The U.S. Environmental Protection Agency's (EPA) Superfund Program has deployed the Superfund Enterprise Management System (SEMS), which integrates multiple legacy systems into a comprehensive tracking and reporting tool. This inventory contains active sites evaluated by the Superfund program that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The Active Site Inventory Report displays site and location information at active SEMS sites. An active site is one at which site assessment, removal, remedial, enforcement, cost recovery, or oversight activities are being planned or conducted. This data includes SEMS sites from the List 8R Active file as well as applicable sites from the EPA's Facility Registry Service map tool. This data may also include applicable sites represented as polygons sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS), and is limited to those sites where the NPL Status reflects the site is 'Not on the NPL (N)' , 'Removed from Proposed (R)', and/or 'Pre-Proposal Site (S)'. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Aug 27, 2025

SEMS List 8R Archive Sites: SEMS ARCHIVE

The U.S. Environmental Protection Agency's (EPA) Superfund Enterprise Management System (SEMS) Archived Site Inventory displays site and location information at sites archived from SEMS. An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. This data includes sites from the List 8R Archived site file. This data may also include applicable sites represented as polygons sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS), and is limited to those sites where the NPL Status reflects the site is 'Not on the NPL (N)' , 'Removed from Proposed (R)', and/or 'Pre-Proposal Site (S)'. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Aug 27, 2025

Inventory of Open Dumps, June 1985: ODI

The Resource Conservation and Recovery Act (RCRA) provides for publication of an inventory of open dumps. The Act defines "open dumps" as facilities which do not comply with EPA's "Criteria for Classification of Solid Waste Disposal Facilities and Practices" (40 CFR 257).

Government Publication Date: Jun 1985

EPA Report on the Status of Open Dumps on Indian Lands: IODI

Public Law 103-399, The Indian Lands Open Dump Cleanup Act of 1994, enacted October 22, 1994, identified congressional concerns that solid waste open dump sites located on American Indian or Alaska Native (AI/AN) lands threaten the health and safety of residents of those lands and contiguous areas. The purpose of the Act is to identify the location of open dumps on Indian lands, assess the relative health and environment hazards posed by those sites, and provide financial and technical assistance to Indian tribal governments to close such dumps in compliance with Federal standards and regulations or standards promulgated by Indian Tribal governments or Alaska Native entities.

Government Publication Date: Dec 31, 1998

Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS: CERCLIS

Superfund is a program administered by the United States Environmental Protection Agency (EPA) to locate, investigate, and clean up the worst hazardous waste sites throughout the United States. CERCLIS is a database of potential and confirmed hazardous waste sites at which the EPA Superfund program has some involvement. It contains sites that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The EPA administers the Superfund program in cooperation with individual states and tribal governments; this database is made available by the EPA.

Government Publication Date: Oct 25, 2013

CERCLIS - No Further Remedial Action Planned: CERCLIS NFRAP

An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. The Archive designation means that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL). This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Government Publication Date: Oct 25, 2013

CERCLIS Liens: CERCLIS LIENS

A Federal Superfund lien exists at any property where EPA has incurred Superfund costs to address contamination ("Superfund site") and has provided notice of liability to the property owner. A Federal CERCLA ("Superfund") lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. This database is made available by the United States Environmental Protection Agency (EPA). This database was provided by the United States Environmental Protection Agency (EPA). Refer to SEMS LIEN as the current data source for Superfund Liens.

Government Publication Date: Jan 30, 2014

RCRA CORRACTS-Corrective Action: RCRA CORRACTS

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. At these sites, the Corrective Action Program ensures that cleanups occur. EPA and state regulators work with facilities and communities to design remedies based on the contamination, geology, and anticipated use unique to each site.

Government Publication Date: Sep 1, 2025

RCRA non-CORRACTS TSD Facilities: RCRA TSD

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. This database includes Non-Corrective Action sites that have indicated engagement in the treatment, storage, or disposal of hazardous waste which requires a RCRA hazardous waste permit.

Government Publication Date: Sep 1, 2025

RCRA Generator List: RCRA LQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Large Quantity Generators (LQGs) generate 1,000 kilograms per month or more of hazardous waste or more than one kilogram per month of acutely hazardous waste. This list also includes RCRAInfo sites that have notified as LQGs that do not have a registered Site Manager or Certifier in RCRAInfo.

Government Publication Date: Sep 1, 2025

RCRA Small Quantity Generators List: RCRA SQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Small Quantity Generators (SQGs) generate more than 100 kilograms, but less than 1,000 kilograms, of hazardous waste per month. This list also includes RCRAInfo sites that have notified as SQGs that do not have a registered Site Manager or Certifier in RCRAInfo.

Government Publication Date: Sep 1, 2025

RCRA Very Small Quantity Generators List: RCRA VSQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Very Small Quantity Generators (VSQG) generate 100 kilograms or less per month of hazardous waste, or one kilogram or less per month of acutely hazardous waste. Additionally, VSQG may not accumulate more than 1,000 kilograms of hazardous waste at any time.

Government Publication Date: Sep 1, 2025

RCRA Non-Generators: RCRA NON GEN

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Non-Generators do not presently generate hazardous waste.

Government Publication Date: Sep 1, 2025

RCRA Sites with Controls: RCRA CONTROLS

List of Resource Conservation and Recovery Act (RCRA) facilities with institutional controls in place. RCRA gives the U.S. Environmental Protection Agency (EPA) the authority to control hazardous waste from the "cradle-to-grave." This includes the generation, transportation, treatment, storage, and disposal of hazardous waste. RCRA also set forth a framework for the management of non-hazardous solid wastes. The 1986 amendments to RCRA enabled EPA to address environmental problems that could result from underground tanks storing petroleum and other hazardous substances.

Government Publication Date: Sep 1, 2025

Federal Engineering Controls-ECs: FED ENG

List of Engineering controls (ECs) made availabe by the United States Environmental Protection Agency (EPA). ECs encompass a variety of engineered and constructed physical barriers (e.g., soil capping, sub-surface venting systems, mitigation barriers, fences) to contain and/or prevent exposure to contamination on a property. The EC listing includes remedy component data from Superfund decision documents for applicable sites on the final or deleted on the National Priorities List (NPL); and sites with a Superfund Alternative Approach (SAA) Agreement in place. The only sites included that are not on the NPL; proposed for NPL; or removed from proposed NPL, are those with an SAA Agreement in place.

Government Publication Date: Sep 29, 2025

Federal Institutional Controls- ICs: FED INST

List of Institutional controls (ICs) made available by the United States Environmental Protection Agency (EPA). ICs are non-engineered instruments, such as administrative and legal controls, that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Although it is EPA's expectation that treatment or engineering controls will be used to address principal threat wastes and that groundwater will be returned to its beneficial use whenever practicable, ICs play an important role in site remedies because they reduce exposure to contamination by limiting land or resource use and guide human behavior at a site. The IC listing includes remedy component data from Superfund decision documents for applicable sites on the final or deleted on the National Priorities List (NPL); and sites with a Superfund Alternative Approach (SAA) Agreement in place. The only sites included that are not on the NPL; proposed for NPL; or removed from proposed NPL, are those with an SAA Agreement in place.

Government Publication Date: Sep 29, 2025

Land Use Controls Information System: LUCIS

The Land Use Controls Information System (LUCIS) database is sourced from the U.S. Department of the Navy (DON). This data contains information for former Base Realignment and Closure (BRAC) properties across the United States. DON's BRAC office was tasked with tracking certain base closures while requiring the prevention of risks to human health and the environment of those properties with LUCs in place. Regarding currently available LUC Sites data, the sites listing is limited to centroid point locations for the overall installation property boundaries. Formerly obtained LUC Sites data may reflect site details that applied previously for a BRAC property.

Government Publication Date: Jun 13, 2024

Institutional Control Boundaries at NPL sites: NPL IC

These boundaries of Institutional Control areas at sites on the U.S. Environmental Protection Agency's (EPA) National Priorities List (NPL), or as Proposed or Deleted, are sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). The EPA's NPL includes the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. Institutional controls are non-engineered instruments such as administrative and legal controls that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes.

Government Publication Date: Sep 6, 2025

Emergency Response Notification System: ERNS 1982 TO 1986

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1982-1986

Emergency Response Notification System: ERNS 1987 TO 1989

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1987-1989

Emergency Response Notification System: ERNS

Database of oil and hazardous substances spill reports made available by the United States Coast Guard National Response Center (NRC). The NRC fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. These data contain initial incident data that has not been validated or investigated by a federal/state response agency.

Government Publication Date: Sep 7, 2025

The Assessment, Cleanup and Redevelopment Exchange System (ACRES) Brownfield Database: FED BROWNFIELDS

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties protects the environment, reduces blight, and takes development pressures off greenspaces and working lands. This data is provided by the United States Environmental Protection Agency (EPA) and includes Brownfield sites from the Cleanups in My Community (CIMC) web application.

Government Publication Date: Sep 8, 2025

FEMA Underground Storage Tank Listing: FEMA UST

The Federal Emergency Management Agency (FEMA) of the Department of Homeland Security maintains a list of FEMA owned underground storage tanks.

Government Publication Date: Dec 31, 2017

Facility Response Plan: FRP

This listing contains facilities that have submitted Facility Response Plans (FRPs) to the U.S. Environmental Protection Agency (EPA). Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit FRPs. Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments. The list includes FRP facilities sourced from the EPA FOIA office and from previously available Homeland Infrastructure Foundation-Level Data (HIFLD) file/s. Disclaimer: Per the EPA FOIA Office, the verification process for current requested FRP data is undergoing review and revision, and any similar reporting will be made public in Fiscal Year 2026. For this reason, the latest available FOIA file may be incomplete.

Government Publication Date: Jun 1, 2025

Delisted Facility Response Plans: DELISTED FRP

Facilities that once appeared in - and have since been removed from - the list of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Jun 1, 2025

Historical Gas Stations: HIST GAS STATIONS

This historic directory of service stations is provided by the Cities Service Company. The directory includes Cities Service filling stations that were located throughout the United States in 1930.

Government Publication Date: Jul 1, 1930

Petroleum Refineries: REFN

This list of petroleum refineries is sourced from the U.S. Energy Information Administration (EIA), Refinery Capacity Report. The listing includes operating and idle petroleum refineries (including new refineries under construction) and refineries shut down during the previous year. The geographic area the report covers is the 50 States, the District of Columbia, Puerto Rico, the U.S. Virgin Islands, Guam, and other U.S. possessions. Per the EIA, the facility location data represents the approximate location based on research of publicly available information from sources such as Federal agencies, company websites, and satellite images on public websites.

Government Publication Date: Oct 31, 2024

Petroleum Product and Crude Oil Rail Terminals: BULK TERMINAL

A list of petroleum product and crude oil rail terminals from the U.S. Energy Information Administration (EIA), as well as petroleum terminals sourced from Oak Ridge National Laboratory hosted by the Homeland Infrastructure Foundation-Level Database. Data includes operable bulk petroleum product terminals with a total bulk shell storage capacity of 50,000 barrels or more, and/or the ability to receive volumes from tanker, barge, or pipeline; also rail terminals handling the loading and unloading of crude oil with activity between 2017 and 2018. EIA petroleum product terminal data comes from the EIA-815 Bulk Terminal and Blender Report, which includes working, shell in operation, and shell idle for several major product groupings.

Government Publication Date: Jun 5, 2025

LIEN on Property: SEMS LIEN

The U.S. Environmental Protection Agency's (EPA) Superfund Enterprise Management System (SEMS) provides Lien details on applicable properties, such as the Superfund lien on property activity, the lien property information, and the parties associated with the lien.

Government Publication Date: Aug 27, 2025

Superfund Decision Documents: SUPERFUND ROD

This database contains a list of decision documents for Superfund sites. Decision documents serve to provide the reasoning for the choice of (or) changes to a Superfund Site cleanup plan. The decision documents include completed Records of Decision (ROD), ROD Amendments, Explanations of Significant Differences (ESD) for active and archived sites stored in the Superfund Enterprise Management System (SEMS), along with other associated memos and files. This information is maintained and made available by the U.S. Environmental Protection Agency.

Government Publication Date: Oct 30, 2025

State

State Cleanup Sites Listing: SCS

List of active and closed State Clean Up Sites made available by the Ground Water Quality Bureau's Remediation Oversight Section of the New Mexico Environment Department (NMED). The Remediation Oversight Section encourages and oversees voluntary efforts to clean up contaminated sites, and administers the Water Quality Control Commission Regulations that require responsible parties to clean up contaminated soil and ground water. This database serves a purpose similar to that of the federal Superfund Enterprise Management System (SEMS), functioning as a state-level counterpart for tracking potential hazardous substance release sites.

Government Publication Date: Feb 4, 2025

Delisted State Cleanup Sites: DELISTED SCS

List of sites removed from State Clean Up Sites made available by the Ground Water Quality Bureau's Remediation Oversight Section of the New Mexico Environment Department (NMED).

Government Publication Date: Feb 4, 2025

Solid Waste Facilities: SWF/LF

List of currently or formerly permitted/registered facilities in New Mexico, including haulers, landfills, transfer stations, collection centers, generators, recycling facilities, and composting facilities. This list includes facilities that are currently open and reporting as well as facilities that are closed but previously held a permit. This list is made available by the New Mexico Environment Department (NMED)'s Solid Waste Bureau.

Government Publication Date: Oct 23, 2025

Historical Solid Waste Landfills: HIST LF

List of historical landfill sites provided by the New Mexico Environment Department (NMED) Solid Waste Bureau, and sites from the Bureau of Land Management which were closed prior to 1984. Public Land Survey System (PLSS) locations provided by the source are subject to accuracy limitations inherent to the PLSS system.

Government Publication Date: Aug 21, 2014

Recycling Centers: RECYCLING

List of registered recycling centers made available by the New Mexico Environment Department's (NMED) Solid Waste Bureau.

Government Publication Date: Jul 7, 2025

Leaking Petroleum Storage Tanks: LST

This list of Leaking Petroleum Storage Tank sites is made available by the New Mexico Environment Department's (NMED) Petroleum Storage Tank Bureau (PSTB). Includes records from PSTB listings, and records from the NMED Open Map Portal.

Government Publication Date: Sep 16, 2025

Delisted Active and No Further Action Leaking Tanks: DELISTED LST

This database contains a list of leaking storage tank sites that were removed from the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau.

Government Publication Date: Sep 16, 2025

Leaking Underground Storage Tanks: LUST HIST

Historical list of leaking underground leaking tanks provided by the New Mexico Environment Department (NMED). This list was last updated in August of 2006.

Government Publication Date: Aug 1, 2006

Underground Storage Tanks: UST

List of Underground Storage Tank sites made available by the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau (PSTB). Includes Underground Storage Tank Facilities from the NMED Open Data Portal.

Government Publication Date: Nov 3, 2025

Aboveground Storage Tanks: AST

List of Aboveground Storage Tank sites made available by the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau (PSTB). Includes Aboveground Storage Tank Facilities from the NMED Open Data Portal.

Government Publication Date: Nov 3, 2025

Petroleum Storage Tanks: TANKS

List of Storage Tank Sites made available by the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau. Includes sites with underground and aboveground tanks.

Government Publication Date: Jul 9, 2019

Underground Storage Tanks - Historical: UST HIST

Historical listing of underground storage tanks registered with the New Mexico Environment Department (NMED). This data was last updated in August 2006.

Government Publication Date: Aug 1, 2006

Aboveground Storage Tanks - Historical: AST HIST

Historical listing of aboveground storage tank facilities registered with the New Mexico Environment Department (NMED. This data was last updated in August 2006.

Government Publication Date: Aug 4, 2006

Delisted Tanks: DELISTED TANK

List of Storage Tank Sites removed from the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau's list of underground and aboveground tanks.

Government Publication Date: Nov 3, 2025

Sites with Institutional and Engineering Controls: INST

List of sites in the New Mexico Environment Department (NMED)'s Public Record of Voluntary Remediation Program (VRP) Sites with institutional and/or engineering controls.

Government Publication Date: Sep 30, 2025

Voluntary Remediation Program Sites: VCP

Public Record of Voluntary Remediation Program (VRP) Sites made available by the New Mexico Environment Department (NMED). New Mexico's Voluntary Remediation Program (VRP) provides incentives for the voluntary cleanup of contaminated properties and encourages their redevelopment. VRP participants that complete the program successfully will receive site closure documentation from the NMED including a Certificate of Completion or Conditional Certificate of Completion.

Government Publication Date: Sep 30, 2025

Targeted Brownfields Assessment Sites: BROWNFIELDS

List of Targeted Brownfields Assessment Sites made available by the New Mexico Environment Department (NMED). Brownfields are properties whose redevelopment is complicated by the presence or potential presence of hazardous substances or petroleum products. NMED provides no-cost environmental assessments of brownfield sites to local or tribal governments. NMED also manages a Brownfields Revolving Loan Fund providing low-interest loans for brownfield cleanups where redevelopment is planned.

Government Publication Date: Sep 30, 2025

Tribal

Leaking Underground Storage Tanks on Tribal/Indian Lands: INDIAN LUST

This list of leaking underground storage tanks (LUSTs) on Tribal/Indian Lands in Region 6, which includes New Mexico, is provided by the United States Environmental Protection Agency (EPA).

Government Publication Date: Apr 21, 2025

Underground Storage Tanks on Tribal/Indian Lands: INDIAN UST

This list of underground storage tanks (USTs) on Tribal/Indian Lands in Region 6, which includes New Mexico, is provided by the United States Environmental Protection Agency (EPA).

Government Publication Date: Apr 21, 2025

Delisted Tribal Leaking Storage Tanks: DELISTED INDIAN LST

Leaking Underground Storage Tank (LUST) facilities which once appeared on - and have since been removed from - the Regional Tribal/Indian LUST lists made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: May 22, 2025

Delisted Tribal Underground Storage Tanks: DELISTED INDIAN UST

Underground Storage Tank (UST) facilities which once appeared on - and have since been removed from - the Regional Tribal/Indian UST lists made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: May 22, 2025

County

No County databases were selected to be included in the search.

Additional Environmental Record Sources

Federal

PFAS Greenhouse Gas Emissions Data: PFAS GHG

The U.S. Environmental Protection Agency's (EPA) Greenhouse Gas Reporting Program (GHGRP) collects Greenhouse Gas (GHG) data from large emitting facilities (25,000 metric tons of carbon dioxide equivalent (CO2e) per year), and suppliers of fossil fuels and industrial gases that results in GHG emissions when used. This dataset is sourced from the EPA's PFAS Analytic Tools, and it includes GHG emissions data for facilities that emit or have emitted since 2010 chemicals identified as PFAS based on EPA's CompTox Chemicals Dashboard lists of PFAS with defined and undefined structures. PFAS emissions data has been identified for facilities engaged in the following industrial processes: Aluminum Production (GHGRP Subpart F), HCFC-22 Production and HFC-23 Destruction (Subpart O), Electronics Manufacturing (Subpart I), Fluorinated Gas Production (Subpart L), Magnesium Production (Subpart T), Electrical Transmission and Distribution Equipment Use (Subpart DD), and Manufacture of Electric Transmission and Distribution Equipment (Subpart SS). Over time, other industrial processes with required GHGRP reporting may include PFAS emissions data and the list of reportable gases may change over time. Note that some regulatory programs have specified chemical structure requirements that define PFAS differently than the lists in EPA's CompTox Chemicals Dashboard.

Government Publication Date: Oct 7, 2025

On-Scene Coordinator Response Sites: OSC RESPONSE

This list of On-Scene Coordinator (OSC) Response Sites is provided by the U.S. Environmental Protection Agency (EPA). OSCs are the federal officials responsible for monitoring or directing responses to all oil spills and hazardous substance releases reported to the federal government. OSCs coordinate all federal efforts with, and provide support and information to local, state, and regional response communities. An OSC is an agent of either EPA or the U.S. Coast Guard (USCG), depending on where the incident occurs. EPA's OSCs have primary responsibility for spills and releases to inland areas and waters. USCG OSCs have responsibility for coastal waters and the Great Lakes. In general, an OSC has the following key responsibilities during and after a response: Assessment, Monitoring, Response Assistance, and Evaluation.

Government Publication Date: Oct 8, 2025

Facility Registry Service/Facility Index: FINDS/FRS

The Facility Registry Service (FRS) is a centrally managed database that identifies facilities, sites, or places subject to environmental regulations or of environmental interest. FRS creates high-quality, accurate, and authoritative facility identification records through rigorous verification and management procedures that incorporate information from program national systems, state master facility records, and data collected from EPA's Central Data Exchange registrations and data management personnel. This list is made available by the U.S. Environmental Protection Agency (EPA).

Government Publication Date: Oct 10, 2025

Toxics Release Inventory (TRI) Program: TRIS

The U.S. Environmental Protection Agency's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of toxic chemicals from U.S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment. There are currently 770 individually listed chemicals and 33 chemical categories covered by the TRI Program. Facilities that manufacture, process or otherwise use these chemicals in amounts above established levels must submit annual reporting forms for each chemical. Note that the TRI chemical list does not include all toxic chemicals used in the U.S. One of TRI's primary purposes is to inform communities about toxic chemical releases to the environment. This database includes TRI Reporting Data for calendar years 1987 through 2021 and Preliminary Data for 2022.

Government Publication Date: Sep 20, 2023

PFOA/PFOS Contaminated Sites: PFAS NPL

This list of Superfund Sites with Per- and Polyfluoroalkyl Substances (PFAS) detections is made available by the U.S. Environmental Protection Agency (EPA) in their PFAS Analytic Tools data, previously the list was obtained by EPA FOIA requests. EPA's Office of Land and Emergency Management and EPA Regional Offices maintain what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment. Limitations: Detections of PFAS at National Priorities List (NPL) sites do not mean that people are at risk from PFAS, are exposed to PFAS, or that the site is the source of the PFAS. The information in the Superfund NPL and Superfund Alternative Agreement (SAA) PFAS detection site list is years old and may not be accurate today. Site information such as site name, site ID, and location has been confirmed for accuracy; however, PFAS-related information such as media sampled, drinking water being above the health advisory, or mitigation efforts has not been verified. For Federal Facilities data, the other Federal agencies (OFA) are the lead agency for their data and provided them to EPA.

Government Publication Date: Sep 26, 2025

Federal Agency Locations with Known or Suspected PFAS Detections: PFAS FED SITES

This list of federal agency locations with known or suspected detections of Per- and Polyfluoroalkyl Substances (PFAS) is made available by the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools data. The EPA outlines that these data are gathered from several federal entities, such as the federal Superfund program, Department of Defense (DOD), National Aeronautics and Space Administration (NASA), Department of Transportation (DOT), and Department of Energy (DOE). The dates this data was extracted for the PFAS Analytic Tools range from 2022 to 2025 per agency entity dataset. Sites on this list do not necessarily reflect the source/s of PFAS contamination and detections do not indicate level of risk or human exposure at the site. Agricultural notifications in this data are limited to DOD sites only. At this time, the EPA is aware that this list is not comprehensive of all Federal agencies.

Government Publication Date: May 30, 2025

SSEHRI PFAS Contamination Sites: PFAS SSEHRI

This PFAS Contamination Site Tracker database is compiled by the PFAS Project Lab, part of the Social Science Environmental Health Research Institute (SSEHRI) at Northeastern University. According to the SSEHRI, the database records qualitative and quantitative data from each known site of PFAS contamination, including timeline of discovery, sources, levels, health impacts, community response, and government response. The goal of this database is to compile information and support public understanding of the rapidly unfolding issue of PFAS contamination. All data presented was extracted from government websites, news articles, or publicly available documents. Locations for the Known PFAS Contamination Sites are sourced from the PFAS Sites and Community Resources Map by the PFAS-REACH team, credited to PFAS Project Lab, Silent Spring Institute, and PFAS Exchange. Disclaimer: The source conveys the data undergoes regular updates as new information becomes available, some sites may be missing and/or contain information that is incorrect or outdated, as well as their information represents all contamination sites SSEHRI is aware of, not all possible contamination sites. This data is not intended to be used for legal purposes. Access the following source link for the most current information: https://pfasproject.com/pfas-sites-and-community-resources/

Government Publication Date: Aug 1, 2025

National Response Center PFAS Spills: PFAS ERNS

This Per- and Poly-Fluoroalkyl Substances (PFAS) Spills dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The National Response Center (NRC), operated by the U.S. Coast Guard, is the designated federal point of contact for reporting all oil, chemical, and other discharges into the environment, for the United States and its territories. This dataset contains NRC spill information from 1990 to the present that is restricted to records associated with PFAS and PFAS-containing materials. Incidents are filtered to include only records with a "Material Involved" or "Incident Description" related to Aqueous Film Forming Foam (AFFF). The keywords used to filter the data included "AFFF," "Fire Fighting Foam," "Aqueous Film Forming Foam," "Fire Suppressant Foam, "PFAS," "PERFL," "PFOA," "PFOS," and "Genx." Limitations: The data from the NRC website contains initial incident data that has not been validated or investigated by a federal/state response agency. Keyword searches may misidentify some incident reports that do not contain PFAS. This dataset should also not be considered to be exhaustive of all PFAS spills/release incidents.

Government Publication Date: Dec 1, 2025

PFAS NPDES Discharge Monitoring: PFAS NPDES

This list of National Pollutant Discharge Elimination System (NPDES) permitted facilities with required monitoring for Per- and Polyfluoroalkyl (PFAS) Substances is made available via the U.S. Environmental Protection Agency (EPA)'s PFAS Analytic Tools. Any point-source wastewater discharger to waters of the United States must have a NPDES permit, which defines a set of parameters for pollutants and monitoring to ensure that the discharge does not degrade water quality or impair human health. This list includes NPDES permitted facilities associated with permits that monitor for Per- and Polyfluoroalkyl Substances (PFAS), limited to the years 2007 - present. EPA further advises the following regarding these data: currently, fewer than half of states have required PFAS monitoring for at least one of their permittees, and fewer states have established PFAS effluent limits for permittees. For states that may have required monitoring, some reporting and data transfer issues may exist on a state-by-state basis.

Government Publication Date: Dec 16, 2024

Perfluorinated Alkyl Substances (PFAS) from Toxic Release Inventory: PFAS TRI

List of Toxics Release Inventory (TRI) facilities at which the reported chemical is a per- or polyfluoroalkyl (PFAS) substance included in the U.S. Environmental Protection Agency's (EPA) consolidated PFAS Master List of PFAS Substances. Encompasses Toxics Release Inventory records included in the EPA PFAS Analytic Tools. The EPA's TRI database currently tracks information on disposal or releases of 770 individually listed toxic chemicals and 33 chemical categories from thousands of U.S. facilities and details about how facilities manage those chemicals through recycling, energy recovery, and treatment. This listing includes TRI Reporting Data for calendar years 1987 through 2021 and Preliminary Data for 2022.

Government Publication Date: Sep 20, 2023

PFAS Water Quality Portal Sampling Data: PFAS WATER

This Per- and Poly-Fluoroalkyl Substances (PFAS) Environmental Media Sampling Data is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The Water Quality Portal (WQP), as a cooperative service sponsored by the United States Geological Survey, the EPA, and the National Water Quality Monitoring Council, is part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations, and individuals submit project details and sampling results to this public repository. Limitations: EPA did not carry out the sampling or testing of a majority of the data in the WQP PFAS dataset. EPA can only speak to the accuracy and completeness of the data from projects like the National Aquatic Resource Surveys for which EPA is the data owner/organization. Data may exist within the file on Quality Assurance Project Plans (QAPPs) and the approving agency of the QAPP, if a QAPP is entered.

Government Publication Date: Jul 21, 2025

PFAS TSCA Manufacture and Import Facilities: PFAS TSCA

The U.S. Environmental Protection Agency (EPA) issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. This list is specific only to TSCA Manufacture and Import Facilities with reported per- and poly-fluoroalkyl (PFAS) substances. Data file is sourced from EPA's PFAS Analytic Tools TSCA dataset which includes CDR/Inventory Update Reporting data from 1998 up to 2020. Disclaimer: This data file includes production and importation data for chemicals identified in EPA's CompTox Chemicals Dashboard list of PFAS without explicit structures and list of PFAS structures in DSSTox. Note that some regulations have specific chemical structure requirements that define PFAS differently than the lists in EPA's CompTox Chemicals Dashboard. Reporting information on manufactured or imported chemical substance amounts should not be compared between facilities, as some companies claim Chemical Data Reporting Rule data fields for PFAS information as Confidential Business Information.

Government Publication Date: Jan 5, 2023

PFAS Waste Transfers from RCRA e-Manifest: PFAS E-MANIFEST

This Per- and Poly-Fluoroalkyl Substances (PFAS) Waste Transfers dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. Every shipment of hazardous waste in the U.S. must be accompanied by a shipment manifest, which is a critical component of the cradle-to-grave tracking of wastes mandated by the Resource Conservation and Recovery Act (RCRA). According to the EPA, currently no Federal Waste Code exists for any PFAS compounds. To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: • PFAS • PFOA • PFOS • PERFL • AFFF • GENX • GEN-X (plus the Vermont state-specific waste codes). Limitations: Amount or concentration of PFAS being transferred cannot be determined from the manifest information. Keyword searches may misidentify some manifest records that do not contain PFAS. This dataset should also not be considered to be exhaustive of all PFAS waste transfers.

Government Publication Date: Oct 4, 2025

PFAS Industry Sectors: PFAS IND

This Per- and Poly-Fluoroalkyl Substances (PFAS) Industry Sectors dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The EPA developed the dataset from various sources that show which industries may be handling PFAS including: EPA's Enforcement and Compliance History Online (ECHO) records restricted to potential PFAS-handling industry sectors; ECHO records for Fire Training Sites identified where fire-fighting foam may have been used in training exercises; and 14 CFR Part 139 Airports compiled from historic and current records from the FAA Airport Data and Information Portal. Since July 2006, all certificated Part 139 Airports are required to have fire-fighting foam onsite that meet certain military specifications, which to date have been fluorinated (Aqueous Film Forming Foam). Limitations: Inclusion in this dataset does not indicate that PFAS are being manufactured, processed, used, or released by the facility. Listed facilities potentially handle PFAS based on their industrial profile, but are unconfirmed by the EPA. Keyword searches in ECHO for Fire Training sites may misidentify some facilities and should not be considered to be an exhaustive list of fire training facilities in the U.S.

Government Publication Date: Sep 1, 2025

Hazardous Materials Information Reporting System: HMIRS

The Hazardous Materials Incident Reporting System (HMIRS) database contains unintentional hazardous materials release information reported to the U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration.

Government Publication Date: May 28, 2025

National Clandestine Drug Labs: NCDL

The U.S. Department of Justice ("the Department"), Drug Enforcement Administration (DEA), provides this data as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy.

Government Publication Date: Nov 30, 2023

Toxic Substances Control Act: TSCA

The U.S. Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule. The CDR enables EPA to collect and publish information on the manufacturing, processing, and use of commercial chemical substances and mixtures (referred to hereafter as chemical substances) on the TSCA Chemical Substance Inventory (TSCA Inventory). This includes current information on chemical substance production volumes, manufacturing sites, and how the chemical substances are used. This information helps the Agency determine whether people or the environment are potentially exposed to reported chemical substances. EPA publishes submitted CDR data that is not Confidential Business Information (CBI). EPA CDR collections occur approximately every four years and reporting requirements change per collection.

Government Publication Date: May 12, 2022

Hist TSCA: HIST TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.
The 2006 IUR data summary report includes information about chemicals manufactured or imported in quantities of 25,000 pounds or more at a single site during calendar year 2005. In addition to the basic manufacturing information collected in previous reporting cycles, the 2006 cycle is the first time EPA collected information to characterize exposure during manufacturing, processing and use of organic chemicals. The 2006 cycle also is the first time manufacturers of inorganic chemicals were required to report basic manufacturing information.

Government Publication Date: Dec 31, 2006

FTTS Administrative Case Listing: FTTS ADMIN

An administrative case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

FTTS Inspection Case Listing: FTTS INSP

An inspection case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

Potentially Responsible Parties List: PRP

Early in the site cleanup process, the U.S. Environmental Protection Agency (EPA) conducts a search to find the Potentially Responsible Parties (PRPs). The EPA looks for evidence to determine liability by matching wastes found at the site with parties that may have contributed wastes to the site. This listing contains PRPs, Noticed Parties, at sites in the EPA's Superfund Enterprise Management System (SEMS).

Government Publication Date: Sep 29, 2025

State Coalition for Remediation of Drycleaners Listing: SCRD DRYCLEANER

The State Coalition for Remediation of Drycleaners (SCRD) was established in 1998, with support from the U.S. Environmental Protection Agency (EPA) Office of Superfund Remediation and Technology Innovation. Coalition members are states with mandated programs and funding for drycleaner site remediation. Current members are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin. Since 2017, the SCRD no longer maintains this data, refer to applicable state source data where available.

Government Publication Date: Nov 08, 2017

Integrated Compliance Information System (ICIS): ICIS

The Integrated Compliance Information System (ICIS) database contains integrated enforcement and compliance information across most of U.S. Environmental Protection Agency's (EPA) programs. The vision for ICIS is to replace EPA's independent databases that contain enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions and a subset of the Permit Compliance System (PCS), which supports the National Pollutant Discharge Elimination System (NPDES). This information is maintained by the EPA Headquarters and at the Regional offices. A future release of ICIS will completely replace PCS and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities that support compliance and enforcement programs, including incident tracking, compliance assistance, and compliance monitoring.

Government Publication Date: May 3, 2025

Drycleaner Facilities: FED DRYCLEANERS

A list of drycleaner facilities from Enforcement and Compliance History Online (ECHO) data as made available by the U.S. Environmental Protection Agency (EPA), sourced from the ECHO Exporter file. This EPA source file tracks facilities that possess NAICS and SIC codes that classify businesses as drycleaner establishments.

Government Publication Date: Jul 19, 2025

Delisted Drycleaner Facilities: DELISTED FED DRY

List of sites which once appeared on - and have since been removed from - the list of drycleaner facilities included in Enforcement and Compliance History Online (ECHO) data as made available by the U.S. Environmental Protection Agency (EPA), sourced from the ECHO Exporter file. This EPA source file tracks facilities that possess NAICS and SIC codes that classify businesses as drycleaner establishments.

Government Publication Date: Jul 19, 2025

Formerly Used Defense Sites: FUDS

Formerly Used Defense Sites (FUDS) are properties that were formerly owned by, leased to, or otherwise possessed by and under the jurisdiction of the Secretary of Defense prior to October 1986, where the Department of Defense (DOD) is responsible for an environmental restoration. The FUDS Annual Report to Congress (ARC) is published by the U.S. Army Corps of Engineers (USACE). This data is compiled from the USACE's Geospatial FUDS data layers and Homeland Infrastructure Foundation-Level Data (HIFLD) FUDS dataset which applies to the Fiscal Year 2021 FUDS Inventory.

Government Publication Date: May 15, 2023

FUDS Munitions Response Sites: FUDS MRS

Boundaries of Munitions Response Sites (MRS), published with the Formerly Used Defense Sites (FUDS) Annual Report to Congress (ARC) by the U.S. Army Corps of Engineers (USACE). An MRS is a discrete location within a Munitions response area (MRA) that is known to require a munitions response. An MRA means any area on a defense site that is known or suspected to contain unexploded ordnance (UXO), discarded military munitions (DMM), or munitions constituents (MC). This data is compiled from the USACE's Geospatial MRS data layers and Homeland Infrastructure Foundation-Level Data (HIFLD) MRS dataset.

Government Publication Date: May 15, 2023

Former Military Nike Missile Sites: FORMER NIKE

This information was taken from report DRXTH-AS-IA-83A016 (Historical Overview of the Nike Missile System, 12/1984) which was performed by Environmental Science and Engineering, Inc. for the U.S. Army Toxic and Hazardous Materials Agency Assessment Division. The Nike system was deployed between 1954 and the mid-1970's. Among the substances used or stored on Nike sites were liquid missile fuel (JP-4); starter fluids (UDKH, aniline, and furfuryl alcohol); oxidizer (IRFNA); hydrocarbons (motor oil, hydraulic fluid, diesel fuel, gasoline, heating oil); solvents (carbon tetrachloride, trichloroethylene, trichloroethane, stoddard solvent); and battery electrolyte. The quantities of material a disposed of and procedures for disposal are not documented in published reports. Virtually all information concerning the potential for contamination at Nike sites is confined to personnel who were assigned to Nike sites. During deactivation most hardware was shipped to depot-level supply points. There were reportedly instances where excess materials were disposed of on or near the site itself at closure. There was reportedly no routine site decontamination.

Government Publication Date: Dec 2, 1984

PHMSA Pipeline Safety Flagged Incidents: PIPELINE INCIDENT

This list of flagged pipeline incidents is made available by the U.S. Department of Transportation (US DOT) Pipeline and Hazardous Materials Safety Administration (PHMSA). PHMSA regulations require incident and accident reports for five different pipeline system types. Accidents reported on hazardous liquid gravity lines (§195.13) and reporting-regulated-only hazardous liquid gathering lines (§195.15) and incidents reported on Type R gas gathering (§192.8(c)) are not included in the flagged incident file data.

Government Publication Date: Jul 10, 2025

Material Licensing Tracking System (MLTS): MLTS

A list of sites that store radioactive material subject to the Nuclear Regulatory Commission (NRC) licensing requirements. This list is maintained by the NRC. As of September 2016, the NRC no longer releases location information for sites. Site locations were last received in July 2016.

Government Publication Date: May 11, 2021

Historic Material Licensing Tracking System (MLTS) sites: HIST MLTS

A historic list of sites that have inactive licenses and/or removed from the Material Licensing Tracking System (MLTS). In some cases, a site is removed from the MLTS when the state becomes an "Agreement State". An Agreement State is a State that has signed an agreement with the Nuclear Regulatory Commission (NRC) authorizing the State to regulate certain uses of radioactive materials within the State.

Government Publication Date: Jan 31, 2010

Mines Master Index File: MINES

The Master Index File (MIF) is provided by the United States Department of Labor, Mine Safety and Health Administration (MSHA). This file, which was originally created in the 1970's, contained many Mine-IDs that were invalid. MSHA removes invalid IDs from the MIF upon discovery. MSHA applicable data includes the following: all Coal and Metal/Non-Metal mines under MSHA's jurisdiction since 1/1/1970; mine addresses for all mines in the database except for Abandoned mines prior to 1998 from MSHA's legacy system (addresses may or may not correspond with the physical location of the mine itself); violations that have been assessed penalties as a result of MSHA inspections beginning on 1/1/2000; and violations issued as a result of MSHA inspections conducted beginning on 1/1/2000.

Government Publication Date: Aug 8, 2025

Surface Mining Control and Reclamation Act Sites: SMCRA

This inventory of land and water impacted by past mining (primarily legacy coal mining operations) is maintained by the U.S. Department of the Interior's Office of Surface Mining Reclamation and Enforcement (OSMRE), as it provides information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). This inventory contains information on the type and extent of Abandoned Mine Land (AML) Problems, as well as information on the cost associated with the reclamation of those problems. The data is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed. Disclaimer: Per the OSMRE, States and tribes who enter their data into e-AMLIS (AML Inventory System) may truncate their latitude and longitude so the precise location of usually dangerous AMLs is not revealed in an effort to protect the public from searching for these AMLs, most of which are on private property. If more precise location information is needed, please contact the applicable state/tribe of interest.

Government Publication Date: Oct 30, 2025

Mineral Resource Data System: MRDS

The Mineral Resource Data System (MRDS) is a collection of reports describing metallic and nonmetallic mineral resources throughout the world. Included are deposit name, location, commodity, deposit description, geologic characteristics, production, reserves, resources, and references. This database contains the records previously provided in the Mineral Resource Data System (MRDS) of USGS and the Mineral Availability System/Mineral Industry Locator System (MAS/MILS) originated in the U.S. Bureau of Mines, which is now part of USGS. The USGS has ceased systematic updates of the MRDS database with their focus more recently on deposits of critical minerals while providing a well-documented baseline of historical mine locations from USGS topographic maps.

Government Publication Date: Mar 15, 2016

DOE Legacy Management Sites: LM SITES

The U.S. Department of Energy (DOE) Office of Legacy Management (LM) currently manages radioactive and chemical waste, environmental contamination, and hazardous material at over 100 sites across the U.S. The LM manages sites with diverse regulatory drivers (statutes or programs that direct cleanup and management requirements at DOE sites) or as part of internal DOE or congressionally-recognized programs, such as but not limited to: Formerly Utilized Sites Remedial Action Program (FUSRAP), Uranium Mill Tailings Radiation Control Act (UMTRCA Title I, Tile II), Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), Resource Conservation and Recovery Act (RCRA), Decontamination and Decommissioning (D&D), Nuclear Waste Policy Act (NWPA). The intent of the site location is to provide a general reference point to the site on a national scale. The coordinates of each site point can be the location of a site monument, the centroid of the site boundary, or a general location of the site. This site listing includes data exported from the DOE Office of LM's Geospatial Environmental Mapping System (GEMS). GEMS Data disclaimer: The DOE Office of LM makes no representation or warranty, expressed or implied, regarding the use, accuracy, availability, or completeness of the data presented herein.

Government Publication Date: Nov 6, 2025

Alternative Fueling Stations: ALT FUELS

This list of alternative fueling stations is sourced from the Alternative Fuels Data Center (AFDC). The U.S. Department of Energy's Office of Energy Efficiency & Renewable Energy launched the AFDC in 1991 as a repository for alternative fuel vehicle performance data, which provides a wealth of information and data on alternative and renewable fuels, advanced vehicles, fuel-saving strategies, and emerging transportation technologies. The data includes Biodiesel (B20 and above), Compressed Natural Gas (CNG), Electric, Ethanol (E85), Hydrogen, Liquefied Natural Gas (LNG), Propane (LPG), and Renewable Diesel (R20 and above) fuel type locations.

Government Publication Date: Aug 1, 2025

Superfunds Consent Decrees: CONSENT DECREES

This list of Superfund consent decrees is provided by the Department of Justice, Environment & Natural Resources Division (ENRD) through a Freedom of Information Act (FOIA) applicable file. This listing includes Cases filed since 2010 limited to the following: Consent Decrees for CERCLA or Superfund Sites filed and/or as proposed within the ENRD's Case Management System (CMS); and applicable ENRD's Environmental Defense Section (EDS) CERCLA Cases with "Consent" in History Note. CMS may not reflect the latest developments in a case, nor can the agency guarantee the accuracy of the data. ENRD Disclaimer: Congress excluded three discrete categories of law enforcement and national security records from the requirements of the FOIA; response is limited to those records that are subject to the requirements of the FOIA; however, this should not be taken as an indication that excluded records do, or do not, exist.

Government Publication Date: Jun 26, 2024

Air Facility System: AFS

This EPA retired Air Facility System (AFS) dataset contains emissions, compliance, and enforcement data on stationary sources of air pollution. Regulated sources cover a wide spectrum; from large industrial facilities to relatively small operations such as dry cleaners. AFS does not contain data on facilities that are solely asbestos demolition and/or renovation contractors, or landfills. ECHO Clean Air Act data from AFS are frozen and reflect data as of October 17, 2014; the EPA retired this system for Clean Air Act stationary sources and transitioned to ICIS-Air.

Government Publication Date: Oct 17, 2014

Registered Pesticide Establishments: SSTS

This national list of active EPA-registered foreign and domestic pesticide and/or device-producing establishments is based on data from the Section Seven Tracking System (SSTS). The Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) Section 7 requires that each producing establishment must place its EPA establishment number on the label or immediate container of each pesticide, active ingredient or device produced. An EPA establishment number on a pesticide product label identifies the EPA registered location where the product was produced. The list of establishments is made available by the U.S. Environmental Protection Agency (EPA).

Government Publication Date: Sep 26, 2025

Polychlorinated Biphenyl (PCB) Transformers: PCBT

Locations of Transformers Containing Polychlorinated Biphenyls (PCBs) registered with the United States Environmental Protection Agency. PCB transformer owners must register their transformer(s) with EPA. Although not required, PCB transformer owners who have removed and properly disposed of a registered PCB transformer may notify EPA to have their PCB transformer de-registered. Data made available by EPA.

Government Publication Date: Oct 15, 2019

Polychlorinated Biphenyl (PCB) Notifiers: PCB

Facilities included in the national list of facilities that have notified the United States Environmental Protection Agency (EPA) of Polychlorinated Biphenyl (PCB) activities. Any company or person storing, transporting or disposing of PCBs or conducting PCB research and development must notify the EPA and receive an identification number.

Government Publication Date: May 23, 2024

Power Plants: POWER PLANTS

This list of power plants is provided by the U.S. Energy Information Administration (EIA). The listing includes operable electric generating plants in the United States by energy source, originating from the EIA-860, Annual Electric Generator Report; EIA-860M, Monthly Update to the Annual Electric Generator Report; and EIA-923, Power Plant Operations Report. It includes all operable plants by energy source with a combined nameplate capacity of 1 megawatt or more that are operating, are on standby, or out of service for short- or long-term.

Government Publication Date: Jun 5, 2025

Historical Business Activity Risk: HIST RISK

Proprietary list of sites identified as potentially having engaged in business activity that poses a higher-than-normal risk of contamination. Records originate from historical city directories, and are included in this list based on broad business categories Potentially Hazardous Chemical Users and Fuel and Automotive, including but not limited to Dry Cleaners and Fuel Stations, Garages, etc. Inclusion in this listing does not indicate that there is or ever has been contamination; rather, sites are included in this list due to their potential for having engaged in a business activity presenting an elevated risk of contamination. The list was compiled from various city directories including Polks, Millers, Mullin Kille, Interstate Directory, and State Directory Co; spanning roughly 1920s through 1960 depending on information available by city.

Government Publication Date: Jan 1, 1960

State

Hazardous Waste Facilities: HAZ

List of hazardous waste generators and treatment, storage, and disposal facilities overseen by the Hazardous Waste Bureau (HWB), New Mexico Environment Department (NMED).

Government Publication Date: Apr 24, 2018

Spills: SPILLS

A listing of spills included in the New Mexico Environment Department's Environmental Notification Tracking System.

Government Publication Date: May 31, 2025

Spills and Incidents - Oil Conservation Division: SPILLS OIL

List of Spills and Incidents made available by the State of New Mexico Oil Conservation Division.

Government Publication Date: Oct 23, 2025

Clandestine Drug Lab Discoveries: CDL

List of addresses of locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. The sources of the entries are law enforcement agencies, and although the list is made available by the New Mexico Environment Department (NMED), NMED has not verified the data and does not guarantee its accuracy. Sites listed were seized prior to January 1, 2008, were not subject to the New Mexico Clandestine Drug Lab Cleanup Rule.

Government Publication Date: May 17, 2018

Per- and Polyfluoroalkyl Substances (PFAS): PFAS

List of PFAS/PFOS sites of concern and sampling locations made available by the New Mexico Environment Department (NMED). Includes sites known to the NMED where PFAS/PFOS containing material may be of concern, as well as USGS PFAS groundwater sampling locations.

Government Publication Date: Feb 4, 2025

Ground Water Discharge Permits: GW DISCHARGE

The Ground Water Pollution Prevention Section of the New Mexico Environment Department reviews and approves discharges that have the potential to impact ground water quality pursuant to Subparts III and V of the Water Quality Control Commission (WQCC) regulations (20.6.2 NMAC). Ground water discharge permits address a wide variety of discharges including domestic wastewater treatment plants, commercial septic tank leach fields, power generating plants, commercial laundries not served by sanitary sewers, dairies, food processing plants, commercial land farms for treatment of contaminated soil, industrial discharges, injection wells and ground water remediation systems. This list does not include permits for mines or agricultural facilities.

Government Publication Date: Dec 20, 2024

Southwest Research and Information Center Uranium Sites: URANIUM

This database contains information on Northwestern New Mexico uranium projects located in Navajo Country and is maintained by the Southwest Research and Information Center. This organization was founded in 1971 for the purpose of providing information to the public on the effects of energy development and resource exploitation on the people and their cultures, lands, water, and air of New Mexico and the Southwest.

Government Publication Date: Oct 18, 2006

Tribal

No Tribal additional environmental record sources available for this State.

County

No County additional environmental record sources available for this State.

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

APPENDIX I

Supplemental Records

[RESERVED]

APPENDIX J

Photographic Log



Photograph 1. View of the Subject Property's eastern frontage along East Palace Avenue. Photograph taken from east of the Subject Property boundary facing west.



Photograph 2. View of the Subject Property interior along the northern boundary taken from the sidewalk forming the eastern boundary.



Photograph 3. Gas and water meters located along the southeastern Subject Property boundary.



Photograph 4. View of overhead electrical service lines with utility pole located on the northeastern Subject Property's boundary with East Palace Avenue visible in the center-right of the photograph.



Photograph 5. View from the southeastern corner of the Subject Property facing northwest.



Photograph 6. View from the southeastern corner of the Subject Property facing northeast.



Photograph 7. View from the southeastern corner of the Subject Property facing southeast.



Photograph 8. View from the southeastern corner of the Subject Property facing southwest.



Photograph 9. View from the northeastern corner of the Subject Property facing northwest.



Photograph 10. View from the northeastern corner of the Subject Property facing northeast.



Photograph 11. View from the northeastern corner of the Subject Property facing southeast.



Photograph 12. View from the northeastern corner of the Subject Property facing southwest.



Photograph 13. The north adjoining property, 836 East Palace Avenue A and B.



Photograph 14. The south adjoining property, associated addresses include 840 5 East Palace Avenue, 841 East Palace Avenue A, B, C, and D, and 856 East Palace Avenue.



Photograph 15. The east adjoining property, 853-A East Palace Avenue with Palace Grocery sign visible on the western building exterior. Building appeared vacant during visual reconnaissance.



Photograph 16. View of the west adjoining property, 839 East Alameda Street.



Photograph 17. View of storm drain grates along the eastern edge of East Palace Avenue with sewer manhole lid visible along the center line of East Palace Avenue. Photograph taken northeast of the Subject Property facing southwest with the Subject Property visible in the background of the photograph.



Photograph 18. View of The Santa Fe River west of the Subject Property and west of East Alameda Street.



Photograph 19. View of East Palace Avenue taken south of the Subject Property facing north.



Photograph 20. View of East Palace Avenue north of the Subject Property facing south with sewer manhole visible in the foreground of the photograph.

APPENDIX K

Interviews

[RESERVED]

APPENDIX L

Qualifications of Environmental Professionals



Matt Hubbard
Senior Environmental Scientist

Years of Experience: 14

Education:

- BS, Environmental Science, University of Texas at Austin

Professional Registrations/Affiliations:

- TCEQ Leaking Petroleum Storage Tank (LPST) Project Manager, License No. PM0000720, 2022

Professional History:

2026 – Present	Senior Environmental Scientist – INTERA Incorporated, Austin, TX
2018 – 2025	Environmental Scientist – INTERA Incorporated, Austin, TX
2017 – 2018	Environmental Specialist – City of Austin, Development Services Department, Austin, TX
2013 – 2017	Project Manager / Engineering and Corrective Action Specialist – Texas Commission on Environmental Quality, Remediation Division, Superfund Section, Austin, TX
2012 – 2013	Work Lead / Licensed Electrician – Wells Solar and Electrical Services, Austin, TX
2012	Field Research Assistant – University of Texas, Austin, TX

Training:

- MSHA Part 48 Surface New Miner Training, 2019-2023
- 40-Hour General Site Workers Training, OSHA 29 CFR 1910.120(e)(3), 2013
- 8-Hour Refresher, OSHA 29 CFR 1910.120, 2013 – 2025
- Hydrogen Sulfide (H2S) Training, 2018
- CPR, First Aid, and Bloodborne Pathogens Training, 29 CFR 1910.1030, 2024
- ArcGIS Pro, WinSitu, Strater®, Grapher™, Surfer®, PLog, LogPlot
- Land Science® Certified Vapor Barrier Inspector, 2020

Matt Hubbard is a Senior Environmental Scientist at INTERA with a BS degree in environmental science and 14 years of experience investigating and remediating contaminated sites. He serves in several capacities including Project Manager, Technical Lead, Field Lead, and Health and Safety Lead. Matt develops and implements highly technical work plans for complex technical projects and provides subject matter expertise to clients and senior leadership. His project experience includes state and federal Superfund, Brownfields, voluntary cleanup program (VCP), petroleum storage tank (PST), Phase I and Phase II Environmental Site Assessment (ESA), and imminent threat/removal assessments. Matt is an expert in field methods including sampling of surface and subsurface environmental media, field screening techniques, environmental drilling, and well construction. He has worked on contaminated sites associated with metals including hexavalent chromium, petroleum hydrocarbons, chlorinated solvents, polychlorinated biphenyls (PCBs), organochlorine and organophosphorus compounds (pesticides and herbicides), dioxins/furans, and per- and polyfluoroalkyl substances (PFAS). Matt has significant experience designing assessments and implementing innovative methods, including incremental sampling methodology (ISM), field portable x-ray fluorescence (XRF), passive soil gas (PSG), ground-penetrating radar (GPR), and electromagnetic mapping. He is also experienced in water resources development, including oversight and support of production well drilling and installation, aquifer performance analysis, dynamic flow profiling, and mass balance chemical analysis.

Project Experience – Environmental

ChemFab Phase I Environmental Site Assessment, ChemFab, LLC., Clute, TX. 2026. *Project Manager.* Conducted a Phase I ESA for a fabrication facility and an adjoining property in accordance with ASTM Standard Practice E1527-21.

Southside Storage Phase I Environmental Site Assessments, Southside Wrecker, Inc., Austin, TX. 2025 – 2026. *Project Manager.* Conducted two Phase I ESAs: one at a vacant property that was previously a sand and gravel mine and subsequently filled via unpermitted landfilling operations and another at an automotive repair and maintenance facility. The Phase I ESAs were conducted in accordance with ASTM Standard Practice E1527-21.

Hornsby Bend Biosolids Management Plant, City of Austin Water, TX. 2023 – 2026. *Project Manager.* Coordinated and led quarterly groundwater monitoring and annual soil sampling in support of the requirements of the Texas Commission on Environmental Quality (TCEQ) permit to process wastewater treatment plant sewer sludge, land apply wastewater treatment plant sewage sludge, and irrigate lagoon supernatant under provisions of Chapter 26 of the Texas Water Code, Chapter 361.121 of the Texas Health and Safety Code, and Chapter 312 of the Texas Administrative Code. Conducted independent data usability review for each quarterly groundwater event. Prepared quarterly updates to groundwater potentiometric elevation maps.

Prepared annual report for submittal to the TCEQ. Performed supplemental historical data review and assessment in support of additional reporting requested by special provision of the 2025 permit renewal and was the primary author of the supplemental report.

Jensen Drive Scrap State Superfund Site, 3603 Jensen Drive LLC, Harris County, TX. 2018 – 2026. *Environmental Scientist and Field Lead.* Drafted Annual Post Closure Care Report and Data Usability Summary for annual 2018, 2019, 2020, and 2025 site activities, which included groundwater monitoring, potentiometric mapping, and engineer's inspection of the site waste containment unit. Coordinated and conducted 2019, 2020, and 2025 groundwater monitoring events, including low-flow sampling for PCBs.

BAE TRACOR Phase I and Phase II Environmental Site Assessment, City of Austin Brownfields, TX. 2025. *Project Manager.* Conducted a Phase I ESA for the City of Austin (COA) Brownfields Program in accordance with ASTM Standard Practice E1527-21. The approximately 140-acre facility had 12 permanent structures and was formerly used for military research and development. Coordinated all aspects of project work to meet the City's expedited timeline within the 120-day due diligence period. Developed the rationale and scope of the Phase II ESA and designed the sampling plan. Soil and groundwater investigation included the installation of soil borings and monitor wells for sampling and analysis of soil and groundwater for contaminants including PFAS and nitroaromatics and nitramines. Directed the INTERA team and subcontractors for the multi-phased progressive tasks in support of the overall objective and made necessary and defensible modifications to the plan, as needed, to meet budget and scheduling restraints. Authored the Phase II ESA and provided support to the COA during negotiations leading up to and culminating with the acquisition of the property.

411 Chicon, City of Austin Brownfields, TX. 2024 – 2025. *Project Manager.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice E1527-21. Oversaw a geophysical survey of the subsurface and an exploratory investigation to determine the presence or absence of underground storage tanks.

Former Travis County Landfill, Moo Moo Meadows, LLC., Austin, TX. 2024 – 2025. *Project Manager.* Reviewed available data to determine groundwater conditions and assess landfill permittee's responsibilities for management. Provided expert environmental support in a contested dispute for site development under 30 Texas Administrative Code (TAC) 330 Subchapter T – Use of Land Over Closed Municipal Solid Waste Landfills.

Austin Bergstrom International Airport Augmented Staff, City of Austin Aviation Department, TX. 2023 – 2025. *Environmental Scientist and Field Lead.* Provided as-needed consulting and field assistance in support of ongoing development at Austin Bergstrom International Airport. Conducted liquid and solid waste sampling for disposal and consulting for the remediation of bulk PFAS chemical and PFAS-containing water in emergency response vehicles. Provided oversight and project coordination for PFAS-contaminated stockpile relocation, monitor well drilling and installation, and soil and groundwater sampling for PFAS.

In-Situ Anaerobic Bioremediation Pilot Study, Chemical Waste Management, Corpus Christi, TX. 2024. *Environmental Scientist.* Conducted baseline groundwater monitoring in support of the pilot study that was performed to evaluate in-situ anaerobic bioremediation as a remedial method groundwater contamination.

Pollution Prevention Plan, Precise Hard Chrome, LLC., Waco, TX. 2024. *Environmental Scientist.* Authored the five-year Pollution Prevention Plan for the Precise Hard Chrome facility in Waco, Texas in accordance with 30 TAC Chapter 335, Subchapter Q (*Pollution Prevention: Source Reduction and Waste Management*). The plan identified all activities that generated hazardous waste or resulted in a release of Toxic Release Inventory reportable chemicals and a prioritized list of economically and technologically feasible source reduction and waste minimization projects.

Peaceful Hill, Graham Development, Austin, TX. 2024. *Project Manager.* Assessed the regulatory framework for proposed stormwater injection to aquifer recharge wells on a commercial development (Class V Injection Well). The assessment included siting and hydrogeologic analysis and provided recommendations for additional investigation in support of implementation.

Rio Grande Coop Phase I Environmental Site Assessment, City of Austin Brownfields, TX. 2024. *Project Manager.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice E1527-21.

Anita Ferrales Coy Phase I Environmental Site Assessment and Asbestos/Lead Survey, City of Austin Brownfields, TX. 2024. *Project Manager.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice

E1527-21. Facilitated asbestos containing material and lead-containing paint survey and preparation of project remediation specifications.

McAlpine Lease Third Party Release Assessment Review, E&W Law, Stanton, TX. 2024. *Environmental Scientist and Data Reviewer.* Conducted data usability review of laboratory analytical results and senior review of the assessment review report for a crude oil and produced water release. Evaluated data relative to Railroad Commission of Texas (RRC) guidance.

Town Lake Metro Park Youth Hostel Phase I Environmental Site Assessment, City of Austin Parks and Recreation Department, TX. 2024. *Environmental Scientist.* Conducted a Phase I ESA in accordance with ASTM Standard Practice E1527-21 in support of planned redevelopment.

Environmental Impacts Assessment, Cooks Branch Conservancy, Montgomery, TX. 2024. *Environmental Scientist.* Oversaw drilling and installation of three monitoring wells. Lithologically logged each well in accordance with ASTM D2488-17e1 and Unified Soil Classification System (USCS). Conducted groundwater and surface water sampling and assessment for a range of analytes to determine impacts from a nearby mining operation. Provided technical support and senior review of data and deliverables.

Geotechnical Investigation for a Potential Compost Facility, Confidential Client, TX. 2024. *Environmental Scientist.* To determine a proposed site's suitability for TCEQ permitting of a compost facility, conducted a subsurface investigation focused on identifying shallow, low permeability clays suitable for use as an in-situ clay liner. Installed and lithologically logged 12 soil borings using the USCS. Collected soil samples from each boring at low permeability clay intervals based on field observations. Sent select samples to a geotechnical laboratory for analysis.

North Railroad Avenue Plume Superfund Site, New Mexico Environment Department, Española, NM. 2024. *Environmental Scientist and Field Lead.* Served as field lead for roto-sonic drilling and installation of a monitoring well in support of an New Mexico Environmental Department (NMED)-led cleanup at a former drycleaner site contaminated with tetrachloroethene (PCE) and its degradation products. Logged continuous core (ASTM D2488-17e1 / USCS) to 257 feet below ground surface (bgs), screened heated headspace soil samples with a photoionization detector, collected push-ahead groundwater samples at discrete depth intervals during drilling, and oversaw analysis of push-ahead groundwater samples via a FROG-5000 portable gas chromatograph. Identified the target hydrostratigraphic unit and informed the selection of the well screen interval. Assisted in work plan creation and annual reporting including software-based boring logs and potentiometric surface elevation mapping.

Per- and Polyfluorinated Substances Risk Assessment, California American Water, Duarte, CA. 2023 – 2024. *Environmental Scientist.* Assisted in the development of custom-built vadose-zone PFAS analytical solution tool to assess the vulnerability of existing and potential well sites to contamination. Identified potential contamination sources by evaluating records on former and current regulated facilities with current or former operations known to be or commonly associated with the use of PFAS. This information was used together with the spatial vulnerability analysis to assess the relative risk of PFAS contamination to existing and potential well sites. The analysis was used to develop recommendations for engineering and operational measures to mitigate the risk and impacts of future contamination. Measures could include changes in operation of existing wells, treatment, or replacement of wells that have reached the end of their service life. Prioritized recommendations for investigation and test drilling at new well sites based on operational benefits, cost, and risk of current or future contamination. The environmental data gathered for the study was provided for future use in permitting selected well sites.

JV DIRT, American AllWaste, Austin, TX. 2023 – 2024. *Environmental Scientist.* Conducted video well survey with a downhole camera. Conducted groundwater sampling. Prepared an update and revision to the site geologic/hydrogeologic report and groundwater protection plan in support of a permit renewal application for composting activities.

Remedial Investigation at Scrub-A-Dubb Barrel Company Site, Texas Commission on Environmental Quality, Lubbock, TX. 2020 – 2024. *Environmental Scientist.* Designed and conducted a remedial investigation, which was a targeted surface soil assessment in compliance with the site-specific field sampling plan (FSP) and the quality assurance program plan developed for the former drum recycling site utilizing ISM for the TCEQ Superfund Section. The primary contaminants of concern included volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), and metals. Used direct-push methodology to collect over 700 soil increments (aliquots) to generate data to assess soils down to five feet bgs for the entirety of the five-acre site during one field mobilization. Collected replicate data to determine statistically if data generated for each ISM decision unit (DU) were representative and defensible. The field activity report was finalized and approved by the TCEQ in March 2022.

Data evaluation confirmed the success of the ISM approach. Authored an affected property assessment report for the TCEQ Remediation Division, compiling data from assessment over an approximately five-year span including soil, sediment, and groundwater.

Voluntary Cleanup Program Post-Response Assistance, Ice Man, Inc., Belton, TX. 2023. *Environmental Scientist.* Conducted on-site review and documentation of the condition of the side slope of an engineering control cap constructed and the adjacent creek bank at a TCEQ VCP site as part of the required post-response care actions. Prepared a memorandum describing the observations made and recommended future actions.

St. Johns Redevelopment Site, City of Austin Economic Development Department via the Austin Brownfield Revitalization Office, TX. 2023. *Project Manager.* Designed and implemented a Limited Phase II ESA for the assessment of a former industrial facility and TCEQ Leaking Petroleum Storage Tank site for planned redevelopment as residential multifamily affordable housing. The assessment included (1) third-party review and assessment of previous site investigation data to identify potential data gaps and areas of concern relative to potential contaminant impacts and (2) soil gas sampling and assessment to assess the potential vapor exposure risk to occupants of future site buildings. Installed a grid of 31 passive soil gas sampling devices over the former site operations area and assessed the laboratory analytical results after a 14-day uptake period, compared to United States Environmental Protection Agency (EPA) Vapor Intrusion Screening Levels. Prepared report documenting the assessment and recommended future actions and guidelines for the Austin Economic Development Department's agreement with the site developer.

Fairfield Lake State Park Environmental Assessment, Texas Parks and Wildlife Department, Freestone County, TX. 2023. *Environmental Scientist.* Provided technical support in discussions with client regarding conduct of Phase I and Phase II ESAs in aid of State of Texas eminent domain condemnation procedures for approximately 5,000 acres, including Fairfield Lake and the immediate surrounding property that was formerly designated as Fairfield Lake State Park. Of specific concern was possible impacts to surface water, sediments, and aquatic life from heavy metals and PCBs related to a former coal-fired power plant located along the northern end of the property. Conducted the site reconnaissance and prepared the Phase I ESA (ASTM Standard E1527-21), which identified several Recognized Environmental Conditions (RECs); however, additional work to address the RECs was halted when Texas Parks and Wildlife Department decided to end condemnation procedures.

Langford Elementary Phase I Environmental Site Assessment, City of Ausitn Brownfields Program, TX. 2023. *Environmental Scientist.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice E1527-21.

Whisper Valley, City of Austin Brownfields Program, TX. 2023. *Environmental Scientist.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice E1527-21.

Emergency Response Waste Sampling at the Mexican American Cultural Center, City of Austin, TX. 2023. *Environmental Scientist.* Conducted emergency sampling of uncovered landfill waste material during the redevelopment of the Mexican American Cultural Center in downtown Austin, Texas.

Limited Phase II Environmental Site Assessment, American AllWaste, Lake Charles, LA. 2023. *Environmental Scientist.* Developed and sampled groundwater for VOCs, SVOCs, metals, petroleum hydrocarbons, pesticides, herbicides, PCBs, and PFAS. Prepared the report documenting the analytical results including a data usability summary. Provided recommendations for additional assessment based on the client's proposed property transaction.

Austin Nature Science Center Outpost, Soil Assessment, City of Austin Parks Department, TX. 2022 – 2023. *Environmental Scientist.* Performed soil assessment to delineate polycyclic aromatic hydrocarbons and heavy metals to Texas Risk Reduction Program (TRRP) Tier 1 Residential Total-soil-combined protective concentrations levels (PCLs) related to former skeet and firing range operations. This work was conducted in support of the implementation of a forthcoming removal action to restore the site to residential standards. Sampling approaches included ISM and ex-situ XRF methods. Authored the work plan and assessment report for this project.

Limited Phase II Environmental Site Assessment for Shield Park, Texas Commission on Environmental Quality Brownfields Program, Galveston, TX. 2022 – 2023. *Project Manager*. Oversaw completion of a geophysical survey implementing GPR and electromagnetic mapping to assess the presence of suspected underground storage tanks (USTs). Provided technical review and implemented TCEQ's soil assessment strategy including installing, screening, and sampling 20 soil borings. Logged each

boring according to the USCS. Prepared the Limited Phase II ESA report documenting site activities and analytical results for VOCs, SVOCs, metals, PCBs, and total petroleum hydrocarbons (TPH). Conducted technical data review and usability assessment and prepared a memorandum in accordance with the TCEQ Quality Assurance Project Plan and applicable EPA guidance.

Limited Phase II Environmental Site Assessment for Hargrave Fleet Services Property, City of Austin Brownfields Program, TX. 2022 – 2023. *Environmental Scientist.* The scope of the Phase II ESA included a full asbestos and lead-containing paint inspection survey, soil gas, surface soil, and groundwater assessment. Contaminants of concern included heavy metals, VOCs, SVOCs, dioxins/furans, and PFAS. Authored the work plan and led the field event to install passive soil gas sampling devices, groundwater monitoring wells, and soil borings. Categorized the groundwater in the shallow groundwater bearing in accordance with TRRP guidelines.

Phase I and II Environmental Site Assessment, Foundation Communities Brownfields Redevelopment Project - Airport Boulevard, Austin, TX. 2022. *Environmental Scientist.* Performed Phase II ESA in preparation for the development of an affordable housing apartment complex by Foundation Communities. Activities assessed two vapor encroachment conditions and two RECs. Deployed a total of 20 PSGs to assess soil gas. Installed four soil borings to assess site soils and the shallow groundwater-bearing unit.

Phase I Environmental Site Assessment, Tract 1-B: Paseo del Pueblo Sur and Los Pandos Road, Taos Hotel Associates, LLC., Taos, NM. 2022. *Environmental Scientist.* Conducted and prepared a Phase I ESA report in accordance with ASTM Standard E1527-21 and resultant volume estimate for a proposed removal of identified petroleum-contaminated soil more than the NMED action level of 100 parts per million by volume.

Scrub-A-Dubb Barrell Company Proposed State Superfund Site, Texas Commission on Environmental Quality, Lubbock County, TX. 2019 – 2023. *Environmental Scientist.* Drafted the TCEQ State Superfund FSP to implement assessment of on- and off-site soils for metals and VOCs referencing Interstate Technology Regulatory Council ISM. The ISM protocol would be used to assess risk to nearby human health and sensitive environmental receptors and to support a potential removal action. Results were compared to TRRP action levels.

Groundwater Sampling & Reporting, Chemical Waste Management, Port Arthur, Texas. 2022. *Environmental Scientist*. Conducted quarterly groundwater monitoring activities for a closed hazardous waste landfill facility. Sampling included groundwater collection at approximately 30 site monitoring wells for VOCs and arsenic.

Gem Dandy 14 Phase I Environmental Site Assessment, Texas Commission on Environmental Quality Brownfields Program, Hamilton, TX. 2022 – 2023. *Project Manager.* Conducted a Phase I ESA for the TCEQ Brownfields Program in accordance with ASTM Standard Practice E1527-21. Oversaw completion of a geophysical survey implementing GPR and electromagnetic mapping to confirm the presence of a UST. Conducted removal of one 12,000-gallon UST and associated infrastructure. Prepared and submitted a report in accordance with TCEQ Regulatory Guidance (RG) 411 documenting removal and restoration activities.

IWC Winters Landfill, Texas Commission on Environmental Quality Superfund Site Discovery and Assessment Program, Orange, TX. 2022 – 2023. *Project Manager.* Designed and conducted initial assessment of this former industrial waste landfill that had become partially submerged and had a history of fires near Adams Bayou in Orange, TX. Sampling of soil, sediment, groundwater, and surface water was conducted for VOCs, SVOCs, organochlorine and organophosphorus pesticides, metals, PCBs, dioxins/furans, and PFAS. Prepared the assessment report including technical data review in accordance with the TCEQ Quality Assurance Project Plan and applicable EPA guidance for all media and analytes.

Former Frank Ortiz Landfill, City of Santa Fe Environmental Services Division, NM. 2021 – 2023. *Environmental Scientist*. Prepared Stage 1 Abatement Plan Quarterly Monitoring Reports detailing ongoing monitoring efforts at the site including soil vapor sampling, groundwater monitoring, and landfill gas monitoring.

Rockwool Industries Federal Superfund Site, Texas Commission on Environmental Quality, Bell County, TX. 2018 – 2023. *Project Manager.* Conducted annual groundwater monitoring and semi-annual site inspections, provided oversight for site maintenance, and drafted the annual reports including potentiometric surface and isoconcentration maps, documenting all site activities, and providing conclusions and recommendations for future site activities.

Calhoun and Griggs Soil Assessment, Texas Commission on Environmental Quality, Houston, TX. 2022. *Project Manager.* Designed and conducted a soils assessment for metals and prepared a report documenting the findings.

Magic Tunnel Geophysical Survey, Texas Commission on Environmental Quality Brownfields Program, Texarkana, TX. 2022. *Project Manager*. Oversaw the completion of a geophysical survey implementing GPR and electromagnetic mapping to determine the presence of suspected USTs.

Former Nursing Home Phase I Environmental Site Assessment, Texas Commission on Environmental Quality Brownfields Program, Hamilton, TX. 2022. *Project Manager.* Conducted a Phase I ESAs for the TCEQ Brownfields Program in accordance with ASTM Standard Practice E1527-21.

Kirtland Air Force Base Environmental Baseline Surveys, Albuquerque Bernalillo County Water Utility Authority, NM. 2020 – 2022. *Environmental Scientist.* Authored and certified two Environmental Baseline Survey (EBS) Reports to meet appropriate property due diligence practices for the easement between Albuquerque Bernalillo County Water Utility Authority (ABCWUA) and Kirtland Air Force Base (KAFB), in accordance with Air Force Instruction 32-7066. The property locations included a 5.29-mile-long easement and a 24-acre parcel, all located on KAFB and Department of Energy property. The project included installing an interceptor pipeline and booster station by ABCWUA, with INTERA responsible for all federal due diligence requirements associated with construction projects occurring on federal facilities. Air Force EBS reports are generally comparable to an environmental due diligence report (Phase I ESA) but also include National Environmental Policy Act review, including cultural natural/biological resource review. Updated the sewer interceptor line easement in February 2022. The EBS reports were approved by the ABCWUA and KAFB in 2022.

Former Santa Fe Generating Station, Public Service Company of New Mexico, Santa Fe County, NM. 2018 – 2022. *Environmental Scientist*. Provided data review services of laboratory analytical and field and laboratory quality assurance/quality control for periodic groundwater monitoring. Reviewed figures and tables and created contaminant trends time series data visualizations with Grapher™ software for quarterly progress reporting (2019-2022). Conducted groundwater monitoring (2021) for VOCs and nitrate/nitrite utilizing piston driven Bennett Pump. Conducted a detailed review of historical aerial photographs for evidence of potential sources to petroleum contamination at the site. Drafted a report including a detailed spatiotemporal summary of findings with correlation to historical documentation.

South State Highway 16, Texas Commission on Environmental Quality Superfund Site Discovery and Assessment Program, San Antonio, TX. 2021. *Project Manager.* Designed and conducted a Superfund Site Discovery and Assessment Program (SSDAP) Eligibility Sampling groundwater assessment in the vicinity of a former illegal dump site used by a pesticide applicator to assess impacts to nearby human health receptors at target sole source water wells.

Airline & Aldine, Texas Commission on Environmental Quality Superfund Site Discovery and Assessment Program, Houston, TX. 2021. *Project Manager.* Designed and conducted a State Screening groundwater assessment in the vicinity of a former public water supply well with chlorinated solvent contamination to assess impacts to human health receptors at target sole source water wells.

Elm Street Phase I Environmental Site Assessments, Texas Commission on Environmental Quality Brownfields Program, Texarkana, TX. 2021. *Environmental Scientist.* Conducted two Phase I ESAs for the TCEQ Brownfields Program in accordance with ASTM Standard Practice E1527-13.

Site Investigation of Former Drilling Fluids Disposal Pit, Mo-Vac Service Company, Alice, TX. 2021. *Environmental Scientist.* Conducted a site investigation of a former drilling fluids disposal pit pursuant to an RRC letter to INTERA's client. Conducted a pump test to properly classify the groundwater and conducted groundwater sampling.

Covenant Testing Technologies Railroad Commission of Texas Pit Closure, Covenant Testing Technologies, Midland, TX. 2021. *Environmental Scientist*. Conducted sampling event to close an in-ground steel tank and wash pads that were used to collect hydrocarbon contaminated equipment wash water. Assisted in preparing submittal to the RRC documenting that the site met RRC closure criteria.

Wally's Flying Service Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Uvalde County, TX. 2020. *Environmental Scientist.* Prepared the site-specific health and safety plan (SSHASP) and FSP. Conducted field event including groundwater sampling for SVOCs by method 8270E, organochlorine pesticides by method 8081B, and organophosphorus pesticides by method 8141B. Target contaminants of concerns, glyphosate and endothall, were also sampled and analyzed via EPA drinking water methods 547 and 548.1, respectively. Prepared the final SSDAP Letter Report documenting sampling and comparing analytical results to TRRP PCLs.

G&L Spraying Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Tom Green County, TX. 2020 – 2021. *Project Manager.* Designed and conducted a State Screening groundwater assessment in the vicinity of a former pesticide applicator with a history of releases to the ground surface to assess impacts to human health receptors at target sole source water wells. Conducted groundwater sampling for metals (primarily arsenic) and SVOC pesticides pendimethalin and trifluralin.

Jain Lane / Govalle Soil Vapor Assessment and Vapor Intrusion Mitigation Assistance, Cesar Chavez Foundation, Austin, TX. 2019 – 2021. *Environmental Scientist.* Prepared an updated FSP to conduct soil vapor assessment for a proposed multi-unit residential development. Conducted soil vapor sampling to assess soil vapor impacts from hydrocarbon-affected groundwater from an adjoining, upgradient site. Prepared a Limited Phase II Report for soil vapor assessment concluding potential risk of vapor intrusion to the proposed development and provided recommendations for a vapor barrier system to mitigate potential impacts. Provided mitigation design assistance during the planning stages for construction. Provided certified third party inspection during vapor barrier and venting system installation for a multi-tenant residential complex. Provided final report documenting mitigation effort to satisfy requirements to obtain financial assistance.

Former First Baptist Church, University of New Mexico, Albuquerque, NM. 2020. *Environmental Scientist.* Prepared and submitted a Phase I ESA Report in accordance with ASTM Standard Practice E1527-13. Reviewed available historical records evaluated site visit findings to identify, to the extent possible, any RECs, as defined by ASTM. The Subject Property consisted of mixed use educational, residential, and creative space development. The development is in a highly developed area of Albuquerque and is also immediately south of a chlorinated solvent groundwater plume that is part of a federal superfund site on the national priority list.

Hospital Drive, Anchorum St. Vincent c/o Colliers International, Santa Fe, NM. 2020. *Environmental Scientist.* Prepared and submitted a Phase I ESA Report in accordance with ASTM Standard Practice E1527-13. Reviewed available historical records evaluated site visit findings to identify, to the extent possible, any RECs, as defined by ASTM. The Subject Property consisted of an outpatient medical facility in a mixed commercial and residential area.

Oltorf Street Phase I Environmental Site Assessment, City of Austin, TX. 2020. *Environmental Scientist*. Prepared and submitted a Phase I ESA Report in accordance with ASTM Standard Practice E1527-13. Reviewed available historical records conducted site visit to identify, to the extent possible, any RECs, as defined by ASTM. The Subject Property consisted of a 2.57-mile corridor through commercial and residential areas for a proposed reclaimed water main project.

Loco Ocho Hydrogeologic Assessment, Confidential Client, Wimberly, TX. 2020. *Environmental Scientist*. Conducted groundwater sampling at a private water supply well to establish baseline water quality.

Frank's Conoco, New Mexico Environmental Department Petroleum Storage Tank Bureau, Las Cruces, NM. 2020.
Environmental Scientist. Prepared Groundwater Monitoring Report for a petroleum hydrocarbons release site where INTERA gauged depth to water/light non-aqueous phase liquid (LNAPL) collected groundwater samples. Groundwater was analyzed for VOCs. Reporting included calculating and graphically depicting the groundwater gradient and potentiometric surface. Analytical results were compared to New Mexico Water Quality Control Commission (NMWQCC) standards.

Highway Texaco, New Mexico Environmental Department Petroleum Storage Tank Bureau, Las Cruces, NM. 2020.
Environmental Scientist. Prepared a work plan and cost estimate to conduct a single groundwater monitoring event including monitoring well gauging, sampling, and analysis for dissolved iron and manganese, and VOCs. Analytical results were compared to NMWQCC standards. The sampling monitored petroleum hydrocarbon contaminants in groundwater associated with releases from a former gasoline service station.

Corrales Chevron, New Mexico Environmental Department Petroleum Storage Tank Bureau, Corrales, NM. 2020.
Environmental Scientist. Prepared a work plan and cost estimate to conduct a semi-annual groundwater monitoring at an active gasoline service station with historical releases from the former operations of a preceding service station. The scope of work for this project included monitoring petroleum hydrocarbon contamination in groundwater from a series of 10 monitoring wells and from six nearby water supply wells (i.e., wells with a sealed wellhead). Analytical results of sampling conducted for VOCs were compared to NMWQCC standards.

Caldwell Motor Company, New Mexico Environmental Department Petroleum Storage Tank Bureau, Belen, NM. 2020.
Environmental Scientist. Prepared a work plan and cost estimate to conduct a semi-annual groundwater monitoring at a

former gasoline service station with a historical presence of LNAPL and an undefined dissolved phase contaminant plume. The sampling monitored the contaminant plume from the existing four monitoring wells and compared analytical results to NMWQCC standards.

Old Exxon Jobber Site, Texas Commission on Environmental Quality, San Patricio County, TX. 2019 – 2020. *Environmental Scientist.* Conducted site reconnaissance and scoping meeting with TCEQ to facilitate preparation of the FSP for tank removal activities and release determination sampling. Prepared FSP in accordance with TCEQ Regulatory Guidance 411 (RG-411) to conduct permanent tank removal activities for two registered 22,000-gallon USTs, and all associated components, and to conduct confirmation and surface release assessment. Conducted field oversight for removal of the tanks and collected confirmation samples for petroleum hydrocarbon contaminants including benzene, toluene, ethylbenzene, xylenes (BTEX), methyl-tert butyl ether (MTBE) via EPA Method 8260/5035, polycyclic aromatic hydrocarbons (PAHs) via EPA Method 8270D, and TPH via TCEQ Method 1005. Prepared and submitted a Release Determination Report in accordance with applicable standard (TCEQ-00621)

Union Pacific Rail Yard, Texas Commission on Environmental Quality, Cameron County, TX. 2019. *Environmental Scientist*. Conducted a Phase I ESA and prepared and submitted a Phase I ESA Report in accordance with ASTM Standard Practice E1527-13. Reviewed available historical records and conducted a site visit to identify, to the extent possible, any RECs, as defined by ASTM. The Subject Property consisted of approximately 25.5 acres of land within an urban mixed residential and commercial industrial area that was formerly a train depot and railway switchyard.

Texaco Building, Texas Commission on Environmental Quality, Cameron County, TX. 2019. *Environmental Scientist.* Conducted a Limited Phase II ESA in which 8,000-gallon steel tank and one 12,000-gallon steel tank and associated piping and conducted sampling and analysis in accordance with TCEQ RG-411. Collected confirmation samples for petroleum hydrocarbon contaminants including BTEX, MTBE via EPA Method 8260/5035, PAHs via EPA Method 8270D, and TPH via TCEQ Method 1005. Prepared and submitted an Release Determination Report in accordance with applicable standard (TCEQ-00621).

City of Hondo Landfill Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Medina County, TX. 2019. *Environmental Scientist.* Prepared the SSHASP and FSP. Conducted field event including groundwater sampling for metals, VOCs, SVOCs, and PCBs. Prepared the final SSDAP Letter Report documenting sampling and comparing analytical results to TRRP PCLs.

Russell Flying Service Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Medina County, TX. 2019. *Environmental Scientist.* Prepared the SSHASP and FSP. Conducted field event including groundwater sampling for metals including hexavalent chromium, SVOCs, VOCs, pesticides, and herbicides. Prepared the final SSDAP Letter Report documenting sampling and comparing analytical results to TRRP PCLs.

The Word Church Phase II Environmental Site Assessment, Texas Commission on Environmental Quality, Bexar County, TX. 2019. *Environmental Scientist.* Provided oversight of drilling via solid stem auger and installation of a monitoring well. Conducted well development and collected a representative groundwater sample via low-flow technique.

Sand Hill Energy Center Release Assessment in Support of Affected Property Assessment Report, City of Austin, TX. 2019. *Environmental Scientist.* Provided oversight for hydro-vac to clear utilities down to six feet at the facility, drilling via hollow-stem auger, and installing and developing three monitoring wells. Collected soil and groundwater samples for analysis of TPH and PAHs. Assisted in preparing an affected property assessment report for submission to TCEQ.

Mineral Wool Insulation Manufacturing Company Proposed State Superfund Site Additional Offsite Evaluation in Support of Remediation, Texas Commission on Environmental Quality, Bell County, TX. 2018 – 2019. *Environmental Scientist.* Conducted detailed overland migration characterization and subsurface sediment sampling using a gravity core sampling device deployed from a boat. Drafted report documenting field activities and providing comprehensive descriptions of the migration pathway with estimation of anticipated volumes for removal based on impacted soils above site specific ecological PCLs. Also collected agricultural samples for nutrient analysis to determine the viability and practicality of repurposing on and offsite soils in the design of a containment cell cap with effective vegetative growth.

Schumann Property Petroleum Storage Tank Removal and Brownfields Site Assessment, Texas Commission on Environmental Quality, Concho County, TX. 2018. *Environmental Scientist.* Prepared the FSP based on TCEQ Regulatory Guidance RG-411. Implemented the FSP including oversight of PST removal (550-gallon "ghost tank"), conducted field screening and

confirmation sampling. Prepared the Release Determination Report documenting removal activities and analytical results with respect to PST Action Levels.

Hamlin Municipal Development District Phase I Environmental Site Assessment, Texas Commission on Environmental Quality, Jones County, TX. 2018. *Environmental Scientist.* Conducted the Phase I ESA site reconnaissance to identify and document RECs.

West Texas Phase I Environmental Site Assessment, Confidential Client, Loving County, TX. 2018. *Environmental Scientist.* Provided historical document review and drafted the historical portion of the Phase I ESA Report for approximately 50 square miles of property in accordance with Standard Practice E2247-16 of ASTM International.

Medical Drive Groundwater Plume Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Bexar County, TX. 2018. *Environmental Scientist.* Conducted groundwater sampling at public and domestic drinking water wells for PCE on rapid 24-hour turnaround time (EPA Drinking Water Method 524.2) and drafted the report to document the release and impacts to receptors in the critical pathway of exposure to facilitate Hazard Ranking System scoring.

South Austin Regional Wastewater Treatment Plant Phase I Environmental Site Assessment, City of Austin Public Works, TX. 2018. *Environmental Scientist*. Conducted the Phase I ESA historical document review and site reconnaissance to identify and document RECs.

The Word Church Phase II Environmental Site Assessment, Texas Commission on Environmental Quality, Bexar County, TX. 2018. *Environmental Scientist*. Provided oversight of environmental borehole drilling with direct push technology for the collection of soil samples to a depth of 15 feet. Assisted in lithological logging, field screened and sampled for VOCs or petroleum products. Drafted the Phase II ESA Report. Work was conducted in accordance with Standard Practice E1903-11 of ASTM International. Provided oversight of drilling via solid stem auger and installation of a monitoring well. Conducted well development and collected a representative groundwater sample via low-flow technique.

Cass County Treating Company State Superfund Site Immediate Removal Action, Texas Commission on Environmental Quality, Cass County, TX. 2016 – 2017. *Project Manager*. Coordinated and provided oversight for removal of soils affected with pentachlorophenol and dioxins/furans at a residential property. The scope of the project included air sampling for the development of protective particulate monitoring action levels, confirmation sampling via ISM including development of a pentachlorophenol screening level concentration indicative of dioxins/furans concentrations as a screening tool, and site restoration.

North Andrews Highway Health and Safety Plan and Preliminary Assessment, U.S. Environmental Protection Agency, Ector County, TX. 2016 – 2017. *Project Manager*. Developed the site health and safety plan. Authored the preliminary assessment report based on research and available site information, including consolidating and analyzing historical site knowledge and analytical data, describing the geologic setting and aquifer characteristics, evaluating major migration and exposure pathways, and producing figures and tables.

Harvey Industries State Superfund Site, Texas Commission on Environmental Quality, Henderson County, TX. 2016 – 2017. *Project Manager*. Coordinated and oversaw operations and maintenance activities at the site including soil gas monitoring and cap inspection/maintenance.

First Quality Cylinders State Superfund Site, Texas Commission on Environmental Quality, Bexar County, TX. 2014 – 2017. *Assistant Project Manager and Project Manager.* Coordinated and provided oversight for the continuous removal of affected groundwater contained behind a slurry wall from on-site extraction wells. Reviewed engineering documents and assisted in project management for the implementation of the final remedy which included groundwater remediation via direct push in-situ chemical reduction of hexavalent chromium in the shallow groundwater bearing unit and the installation of a continuous onsite pump and treat system. Managed operations and maintenance activities for the on-site treatment system.

Jerrell B Thompson Battery State Superfund Site, Texas Commission on Environmental Quality, Van Zandt County, TX. 2013 – 2017. *Project Manager.* Conducted annual inspection to ensure site controls for waste remained undisturbed and in good condition as part of operations and maintenance activities.

JCS Company State Superfund Site, Texas Commission on Environmental Quality, Van Zandt County, TX. 2013 – 2017. *Project Manager.* Coordinated and provided oversight for annual operations and maintenance activities at the site including cap inspection and maintenance as well as groundwater monitoring activities.

Deepwater Horizon RESTORE Act Proposal Evaluations, Texas Commission on Environmental Quality Natural Resource Damage Assessment, Austin, TX. 2016. *Evaluator.* Was selected to be part of a six-member interdisciplinary committee that evaluated more than 200 proposals requesting funds allocated to the state by the RESTORE Act for the Deepwater Horizon oil spill.

Schaefer Road Drum Immediate Removal Action, Texas Commission on Environmental Quality, Bexar County, TX. 2016. *Project Manager.* Coordinated and provided oversight for HAZCAT classification, removal, and proper disposal of abandoned bulk and containerized wastes, and affected site soils. Authored legal documents for cost recovery.

Methodist Hospital Health and Safety Plan and Preliminary Assessment, U.S. Environmental Protection Agency, Bexar County, TX. 2016. *Project Manager*. Developed the site health and safety plan. Authored the preliminary assessment report based on site reconnaissance, research, and available site information including consolidating and analyzing historical site knowledge and analytical data, describing the geologic setting and aquifer characteristics, evaluating major migration/exposure pathways, and producing figures and tables.

Highway 18 Groundwater Plume Expanded Site Investigation, U.S. Environmental Protection Agency, Winkler County, TX. 2016. *Field Project Manager.* Responsible for the field event, which included coordination and sampling of soils at potential source locations and sampling sole source water wells for evaluation of impact to human health receptors in the groundwater migration pathway.

Lane Plating Works Site Investigation, U.S. Environmental Protection Agency, Dallas County, TX. 2016. *Field Project Manager*. Acted as Project Manager for the field event, which included identifying representative sampling locations in the field and sampling of soils, sediments, and surface water.

Southwestern Plating Works Immediate Removal 2015, Texas Commission on Environmental Quality, Lubbock County, TX. 2015 – 2016. *Project Manager*. Coordinated and provided oversight for the classification, removal, and proper disposal of abandoned plating vats and containerized wastes. Conducted SSDAP state screening activities, including soil and groundwater sampling and analysis and authored legal documents for cost recovery.

Ector Drum Site Investigation, U.S. Environmental Protection Agency, Ector County, TX. 2015 – 2016. *Project Manager*. Conducted the field effort, including sampling of residential and commercial sole source groundwater wells. Analyzed the collected groundwater data, compared data to EPA Maximum Concentration Levels, and authored the final technical report.

Absolute Fuels Superfund Site, Texas Commission on Environmental Quality, Lamb County, TX. 2015. *Project Manager*. Coordinated and provided oversight for the assessment and investigation of impact to human health receptors via the groundwater pathway and the completion of the final Removal Action Report. Authored legal documents, including a property lien for cost recovery.

Industrial Waste Control Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Orange County, TX. 2015. *Project Manager*. Coordinated and provided oversight for the assessment and investigation of impact to human health receptors in the groundwater migration pathway. Analyzed and compared data to TRRP PCLs to provide conclusions and site recommendations.

Browning Ferris Industries Landfill Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Orange County, TX. 2015. *Project Manager.* Coordinated and provided oversight for the assessment and investigation of impact to human health receptors in the groundwater migration pathway. Analyzed data, compared data to TRRP PCLs, and provided conclusions and site recommendations.

Lonesome Trail Site Investigation, U.S. Environmental Protection Agency, Bexar County, TX. 2014. *SI Team Member*. Conducted soil and groundwater sampling to assist in the completion of the Site Investigation.

River City Metal Finishing Superfund Site, Texas Commission on Environmental Quality, Bexar County, TX. 2014. *Project Manager.* Conducted closeout activities, including authoring legal documents and notices including a restrictive covenant and property lien.

Battery Recyclers of Houston Superfund Site, Texas Commission on Environmental Quality, Brazoria County, TX. 2014. *Project Manager.* Coordinated and provided oversight for the assessment and investigation of impact to human health receptors in the groundwater and soils migration pathways. Analyzed data, compared data to TRRP protective concentration levels, and provided conclusions and site recommendations.

Sampling of Vegetation Transects in the Okavango Delta, Dr. Kelley Crews and Dr. Thoralf Meyer, Undergraduate Research, Botswana, Africa. 2012. *Field Research Assistant.* Conducted sampling in remote parts of Botswana, Africa as part of a ground truthing effort for remotely sensed data. Responsibilities included gathering data using high resolution spectral imagery as well as identifying and measuring woody vegetation across ecological regimes. Applied data gathered for analyzing carbon sequestration in above ground woody biomass using the allometric relation of basal area to biomass.

Project Experience – Water Resources

Vertical Flow Profiling for Production Well, Porter Special Utility District, TX. 2021. *Environmental Scientist.* Provided oversight for "lift and shift" and ultimately the complete removal and reinstallation of a 560 ft, 10-inch pump column. Conducted vertical flow profiling utilizing BESST's upgraded and proprietary version of the U.S. Geological Survey tracer flowmeter and targeted depth interval groundwater sampling using the BESST HydroBooster sampling pump. Analytes included hydrogen sulfide (H2S), adenosine triphosphate (ATP), sulfate reducing bacteria (SRBs), iron reducing bacteria (IRBs), dissolved sulfide, total sulfides, total iron, total organic carbon, methane, chloride, sodium, oxidation/reduction potential (ORP), and specific conductivity. Field testing was also performed including H2S, ORP, dissolved oxygen (DO), pH, temperature, turbidity, and specific conductivity. Wellhead samples were also collected, representing blended composites of zonal chemical mass contribution from each contributing flow interval.

Evangeline Laguna Borehole Surveys and Pump Testing, Confidential Client, San Patricio County, TX. 2020. *Environmental Scientist*. Performed video surveys of wells to determine conditions and screened intervals. Conducted oversight of pump removal and installation and 36-hour pump tests in three wells with In-Situ Trolls and WinSitu software while obtaining manual water level and flow measurements. Collected water samples to analyze water chemistry before, during, and after pump tests.

Dynamic Flow and Water Chemistry Profiling, West Harris County Municipal Utility District, Houston and Katy, TX. 2020. *Environmental Scientist.* Conducted downhole investigation at two public water supply wells to: (1) measure zonal flow contribution within the well under steady-state pumping conditions; (2) characterize zonal chemical contribution of arsenic, iron, and exsolved methane; and (3) determine viable economical options to physically modify the well screen to reduce or eliminate treatment for arsenic and iron and to mitigate methane influx. Conducted dynamic flow profiling to calculate zonal flow contributions over hundreds of feet of intermittently perforated well screen by injecting rhodamine dye at discrete depth intervals and measuring peak return rates at the surface via fluorometer. Conducted depth-dependent groundwater sampling to characterize zonal chemical contribution.

New Braunfels Utilities Aquifer Storage and Recovery Monitoring, ARCADIS, New Braunfels, TX. 2020. *Environmental Scientist.* Provided oversight for drop pipe and transducer installation at monitoring wells supporting aquifer storage and recovery monitoring.

Constant Rate Test for Turtle Creek No. 3 Pump Station, San Antonio Water System, Bexar County, TX. 2019. *Environmental Scientist.* Provided oversight for the constant rate test at 7,000 gallons per minute.

El Dorado Sand Mine Water Supply Wells Development and Performance Analysis, Black Mountain Sand, Winkler County, TX. 2019. *Environmental Scientist.* Provided well development (bailing and airlifting) and pump installation oversight, including water quality monitoring; conducted step drawdown tests to assess supply well performance; and collected aquifer test data for four wells using water level meters and multiple transducers. Collected data using In-Situ Trolls and WinSitu software.

Observation Well Drilling Oversight and Sampling - Oversight for Vertical Flow Profiling for Production Well, Confidential Client, San Patricio County, TX. 2018 – 2019. *Environmental Scientist.* Provided oversight for well drilling activities of observation well to depth greater than 1,000 feet bgs and collected mud rotary cuttings samples for sieve analysis. Provided oversight for BESST, Inc. implementing their ambient flow profiling service using the DyeTracer system developed by the U.S. Geological Survey.

Bigfoot Sand Mine Water Supply Well Installation, Turnkey Processing Solutions, Atascosa County, TX. 2018. *Environmental Scientist.* Provided well drilling and installation oversight. Logged drilling cuttings, conducted step drawdown tests, and collected aquifer test data using water level meters and multiple transducers.



Joseph Tracy, PG

Principal Geologist | Senior Vice President

Years of Experience: 31

Education:

- BS, 1993, Environmental Geology, Ohio University

Professional Registrations/Affiliations:

- Professional Geologist, AZ, 2003, No. 38741
- Professional Geologist, TN, 1999, No. TN4417
- Professional Geologist, TX, 2013, No. 11588

Professional History:

2000 – Present	Senior Vice President, Principal Geologist – INTERA Incorporated, Albuquerque, NM
1999 – 2000	Environmental Specialist – GeoTek Insite, Albuquerque, NM
1997 – 1999	Staff Geologist – Professional Services Industries, Inc. (PSI), Cleveland, OH
1994 – 1997	Staff Geologist – Terranext, Inc., Denver, CO

Training:

- OSHA Health and Safety Training, 29 CFR 1910.120, (40-Hour), 1994
- OSHA Health and Safety Training, Annual Refresher, (8-Hour), current
- DOT HM 126 Hazardous Material Transportation Training, 49 CFR 172.700, 1996
- Confined Space Entry Training, 29 CFR 1910.140, 1995
- National Ground Water Association – Fate and Transport of Light Non-Aqueous Phase Liquids/Dense Non-Aqueous Phase Liquids (LNAPLs/DNAPLs) Training, 1995
- Asbestos Inspector and Management Planner (Toxic Substance Control Act Sec. 206, Title II) Training, 1997
- Asbestos Contractor Supervisor (Toxic Substance Control Act Title II and AHERA) Training, 2000
- Vapor Intrusion Training, 2011
- Red Cross First Aid/CPR Training, current
- Sulfuric Acid Handling Training, 2013
- Interstate Technology Regulatory Council (ITRC) Training – Vapor Intrusion Pathway: Investigative Approaches for Typical Scenarios (2008)

Joseph "Joe" Tracy is a Principal Geologist and Senior Vice President at INTERA with a BS degree in environmental geology and over three decades of consulting experience focused on environmental assessments, site investigations, remedial planning, and site remediation. He has evaluated the environmental impacts to soil and groundwater at leaking petroleum storage tank (PST) sites, Superfund sites, Brownfield sites, and a variety of operational and former industrial properties and facilities. Mr. Tracy leads multidisciplinary teams of scientists and engineers to complete investigations and remediation of contaminants that include petroleum hydrocarbons, heavy metals, chlorinated solvents, polychlorinated biphenyls (PCBs), per- and polyfluoroalkyl substance (PFAS), and asbestos. He develops remedial plans under voluntary remediation and Superfund programs and prepares and implements work plans, quality assurance project plans, and remedial action plans for Brownfields and other redevelopment projects. Mr. Tracy's experience also includes performing investigations and related work at municipal landfills where activities have included the installation and monitoring of landfill gas (LFG) probes, preparing landfill management plans, operation and maintenance of LFG extraction/destruction systems, developing and implementing grading and drainage plans, and profiling the nature and extent of landfill wastes. Mr. Tracy is a Senior Vice President within INTERA's Southwest Region, where he oversees multi-site contracts with state, county, and municipal agencies, and is responsible for directing all environmental services marketing efforts within the INTERA Mining and Environmental Line of Business Unit.

Project Experience – Environmental

Santa Fe County Investigation of Per- and Polyfluoroalkyl Substance Contaminants in Domestic Wells, Santa Fe County, NM. 2024 – Present.

Project Manager. Santa Fe County The sampling and analysis of drinking water in October 2023 from six domestic wells within the communities of La Cienega and La Cieneguilla, Santa Fe County discovered PFAS at concentrations above the safe drinking water standards recently established by the USEPA. Driven by the health concerns related to this discovery, the County, in collaboration with the New Mexico Environment Department (NMED) Construction Programs Bureau (CPB) and the City of Santa Fe, successfully acted to obtain a USEPA grant to help fund the assessment of the potential PFAS impacts to area groundwater. Mr. Tracy is leading the INTERA Team to achieve the overarching project goals of determining the extent of the PFAS contamination in groundwater and developing alternatives for mitigation and/or remediation of the contamination. Mr. Tracy is currently assisting the County with the initial project activities including the development of a conceptual site model (CSM) and selecting additional domestic wells for PFAS sampling. In addition, Mr. Tracy is working with INTERA subcontractor, John Shomaker and Associates, Inc. (JSAI), in the development of a groundwater flow model, in an effort to determine preferential flow paths for underlying PFAS contamination in ground water.

Environmental Investigations, City of Albuquerque – Department of Municipal Development, Albuquerque, NM. 2005 – 2018 and 2023 – Present. *Contract Manager and Project Manager.* Contract Manager City of Albuquerque Department of Municipal Development Environmental On-Call Services contract. Performed Phase I and Phase II Environmental Site Assessments (ESAs) for the City of Albuquerque (COA) as part of this contract. In addition, provided environmental assistance to the COA Department of Municipal Development on an as-needed basis as project environmental issues develop. Environmental issues included extraction well evaluation at the former Los Angeles Landfill, maintenance and monitoring services at the former Los Angeles Landfill, geophysical investigations in the downtown Albuquerque area, micro-turbine analysis at the former Los Angeles Landfill, engineering evaluation/cost analysis (EE/CA) for the Hotel La Posada del Albuquerque, conducting a soil vapor survey at the City of Albuquerque 1st and Central Site which is located adjacent to the former BNSF East Bound Fueling Facility, ambient air monitoring within residential houses in the Albuquerque area, and asbestos and lead-based paint surveys at several city facilities (i.e., Los Duranes Community Center, Jeanne Bellamah Community Center, Holiday Park Community Center, Barelas Community Center, Mesa Verde Community Center, APD Education Building, Dennis Chavez Community Center, Rio Grande Fire House, Pino Yard Senior Games Building, North Valley Senior Center, Palo Duro Senior Center, Environmental Health Department offices), city-owned former historic hotels (El Vado and De Anza), and city-acquired properties (Brown Property, Caravan Building, Loan Pawn Shop). Facilitated on-call projects such as the development of a CSM for the Kirtland Air Force Base Fuel Spill, development of a voluntary remediation approach for at the Marble-Arno Property and the downtown Railyard, locating a new COA storm water facility, conducting an archaeological survey at the Singing Arrow Community Center, and several landfill maintenance projects for the COA Solid Waste Division Cerro Colorado landfill. Currently projects for the COA include the assessment of asbestos and lead-based paint in several buildings at the COA BioPark (Zoo), which is undergoing a full-scale remodeling and renovation, as well as continuing groundwater monitoring activities at the Marble-Arno Property under the Voluntary Remediation Program (VRP). Secured an additional environmental services on-call contract with the COA in late 2023 and work began in 2024. Mr. Tracy is currently leading the environmental surveys associated with the renovation of the COA Gibson Health Hub (GHH) and several COA community centers and libraries.

Santa Fe Well-S (Santa Fe Generating Station) Petroleum Storage Tank Investigation, Public Service Company of New Mexico, Santa Fe, NM. 2018 – Present. *Project Principal.* Providing contract support for the investigation of fuel and chlorinated solvent release at a former power generating station and other, off-site sources. The release(s) have impacted a City of Santa Fe municipal supply well, causing production of drinking water from this well to be discontinued. The investigation includes the installation of 25 monitoring wells to depths ranging from approximately 300 to over 400 feet using roto-sonic drilling and sampling techniques. Portable gas chromatography and a photoionization detector are being used to analyze soil and groundwater samples in the field so that contaminated zones can be identified, and real-time, informed decisions can be made concerning screen intervals. The results of the in-field screening have identified zones, some as thin as three feet, containing mobile light non-aqueous phase liquid (LNAPL) and conveying highly contaminated groundwater. Responsibilities have included contract and technical discussions with the client and project team as well as attending several scoping and status meetings with Public Service Company of New Mexico, the City, and NMED representatives. In addition to providing support of environmental services associated with the fuel plume, also reviewing efforts associated with State 1 abatement plan (S1AP) investigations regarding chlorinated solvents and nitrates contamination present in ground water at the site.

Hop Canyon/Waldo Mill Site Phase II Site Investigation and Voluntary Remediation Program Activities, ASARCO, Magdalena, NM. 2000 – 2002 and 2018 – Present. *Project Principal, Project Manager, and Staff Geologist.* Implemented a Work Plan to characterize an American former Smelting and Refining Company (ASARCO) mining mill tailings site in Magdalena, New Mexico. The voluntary remediation activities included characterization and removal of affected soil and construction of an onsite tailings impoundment capped with clean soil. Surface drainage issues included interfacing with the U.S. Army Corps of Engineers to present erosion of the impoundment cap and surrounding soils. Initiated additional work at this site on behalf of the ASARCO Trust in 2018. INTERA is currently responsible for Site Caretaker Operations, which are essentially weekly Site visits to make certain the tailings impoundment cover remains in good condition. INTERA will prepare a VRP Work Plan to guide the repair work of the tailing impoundment cover. NMED and/or the ASARCO Trust identified several areas of the tailings impoundment cover in 2017 that are recommended for repair. The remainder of the ASARCO property at the site was legally transferred into ASARCO Trust ownership in late 2023. Currently working with ASARCO Trust representatives and the INTERA Project Team to design and conduct cap repair activities and secure a VRP Conditional Certificate of Completion (CCOC).

Las Vegas Patrol Yard Groundwater Remediation System Operation and Maintenance, New Mexico Department of Transportation, Las Vegas, NM. 2017 – Present. *Project Principal.* Began operation and maintenance (O&M) activities of a groundwater remediation system associated with the two contaminant plumes: an inorganic (chloride and total dissolved solids [TDS]) plume and organic (petroleum and chlorinated compound) plume located at the New Mexico Department of Transportation (NMDOT) Las Vegas Patrol Yard. The groundwater remediation system was originally operated by another firm but due to performance issues INTERA was asked to conduct O&M activities at the site. The groundwater remediation system consists of five interceptor trenches (four of the trenches focus on capturing the inorganic and petroleum plume and one focuses on capturing the chlorinated solvent plume) which capture contaminated groundwater and convey the water to two treatment containers. The treatment system consists of a filter media capable of removing iron and manganese, an air stripper which targets volatile organic compounds (VOCs), and reverse osmosis (RO) membranes which removes TDS and chlorides. The treated groundwater is reinjected into the subsurface via three infiltration trenches. Monthly influent and effluent samples are collected from the groundwater remediation system to ensure the system is operating effectively and that the effluent water quality meets the approved discharge permit requirements. O&M activities include maintaining all parts (pumps, inline sensors, filters) of the system, monitoring the dosing rate of the system additives (sodium hypochlorite, sodium metabisulfite, caustic soda, and anti-scaling agent), analyzing field water quality parameters/compounds (pH, TDS, free chlorine, total iron, total manganese) using handheld meters or Hach kits, replacing filters, monitoring system pressures, maintaining adequate additive volumes in vessels, and performing high- and low-pH cleaning of the RO membranes when necessary. The data collected during O&M activities and recorded remotely using a programmable logic controller is tracked and analyzed on a weekly basis to make sure the system is operating as designed. Treatment system operation has been suspended in recent years due to a discharge permit issue, but are estimated to be re-started in 2024.

Investigation of the Former Frank Ortiz Landfill, City of Santa Fe, NM. 2016 – Present. *Project Manager.* The Frank Ortiz Landfill operated as a City of Santa Fe municipal landfill between 1954 to 1968. Since no solid waste management regulations were in place during this period of operation, the landfill is not regulated by the NMED Solid Waste Bureau. The landfill site was re-developed by the city with soccer fields from 1987 to 1993 and currently serves as a dog park. In April 1993, soil vapor samples were collected from the fill and soil cover areas. Laboratory analysis of the samples showed that they contained hydrocarbons, chlorinated solvents, and chlorinated solvent degradation products. Concentrations of some of the contaminants exceeded 1,000 parts per billion. A single groundwater monitoring well (Ortiz Park No. 1) was installed approximately 500 feet southwest of the landfill in 2004. A groundwater sample collected from the well indicated that groundwater had been impacted from VOCs, hydrocarbons, metals, and nitrogen believed to have originated at the landfill site. Periodic groundwater and soil vapor sampling have continued at the site since 2004. An S1AP was developed for the Site in 2010 and submitted to NMED for review and approval. In 2013, NMED issued a letter noting several deficiencies in the S1AP including: the lack of a plan for maintenance of a two-foot cap over the former landfill; inadequate definition of the nature and extent of the landfill waste; inadequate definition of contaminant concentrations in the vadose zone below the waste; inadequate definition of the potential contaminant impacts to groundwater; the lack of a long-term monitoring program; and the need for a quality assurance project plan, health and safety plan, and a schedule for implementing the additional investigation activities and analyses necessary to address the identified deficiencies.

In 2015, at the request of NMED, the City conducted a geophysical investigation to define the areal extent of buried waste at the landfill. INTERA was awarded a contract from the City in September 2016 to help address the remaining S1AP deficiencies. Helped develop and reviewed an integrated Sampling and Analysis Plan (SAP)/Quality Assurance Project Plan (QAPP) for the former landfill that was submitted to and approved by NMED. The SAP outlined several steps for the City to address the noted NMED concerns, including: installation of test pits to determine type and extent of waste; the collection of soil samples to determine the impact to soil immediately below the buried waste (extent of contamination in the vadose zone); installation of groundwater monitoring wells; groundwater sample collection; and an approach for a long-term groundwater monitoring program. Field sampling activities associated with the SAP/QAPP were completed in July 2017. Met with the NMED to go over the report findings and discuss recommendations for next steps. The investigation revealed the approximate extent and depth of buried waste, determined the extent of the vapor plume, and provided information on the landfill cover content and thickness. To address NMED's final concern, additional groundwater monitoring wells co-located with three soil vapor monitoring wells and an additional soil vapor monitoring well were recommended and the approximate locations were determined.

The additional wells were installed at the Ortiz Landfill in late 2019 and early 2020 and a final report was submitted to by INTERA to NMED in May 2020. The report findings indicated a direct impact to Site soil vapor likely from the presence of the buried waste, but it appears that Site groundwater is largely unimpacted. INTERA has successfully negotiated with NMED a period of monitoring work for the three years and includes the addition of Surface Emission Monitoring (SEM) on a quarterly basis of the entire Ortiz Landfill property (historic fill area and adjacent land within the property boundary). Once this period has expired, Mr. Tracy will work with City and NMED representatives to determine the need and location(s) for any future additional groundwater and soil vapor monitoring well installations.

The INTERA former Frank Ortiz Landfill work is being conducted in concert with additional investigation and monitoring activities at the adjacent Paseo de Vista (PDV) Landfill. The monitoring and maintenance of the PDV Landfill was added to the INTERA Ortiz Landfill contract by the City in 2019. The work at PDV has largely been conducted by personnel from INTERA's partner, Parkhill, under INTERA oversight. All PDV deliverables are prepared by Parkhill and reviewed by Mr. Tracy prior to submittal to the City and NMED. Mr. Tracy currently leads the long-term monitoring (LTM) activities at both landfills on behalf of the City and manages subcontractor Parkhill. The City of Santa Fe has requested that INTERA assist with NMED updated S1AP activities which are scheduled to begin in July 2025. This will consist of the installation of an additional ground water monitoring well, several LFG monitoring wells, and sampling ground water for PFAS in addition to the required analysis suite.

North Railroad Avenue Plume Superfund Project, New Mexico Environment Department - Groundwater Quality Bureau, Española, NM. 2016 – Present. *Project Principal*. A bio-amendment injection event was performed to remediate residual contamination (tetrachloroethene [PCE] and daughter products) in discrete intervals of fine-grained material identified in the source area (SA) and hot spot (HS) of the site. INTERA evaluated available data, identified six treatment areas, determined targeted treatment intervals, selected emulsified soybean oil as the carbon substrate, and devised an injection method to ensure that the substrate is delivered precisely. INTERA oversaw the bio-amendment substrate injection event which was conducted in two separate events: the first was completed in April 2017 via a direct-push injection tool within sonic casing and the second event was conducted with direct sonic injection in September 2017. INTERA conducted follow-up performance groundwater monitoring. Results of the performance monitoring events confirmed the successful distribution of the carbon substrate through the presence of the dye tracer (Rhodamine WT) and elevated total organic carbon (TOC) in monitoring wells within the anticipated radius of influence (ROI). Additionally, the groundwater analytical results from the first performance monitoring event provided evidence that in-situ reductive dichlorination was enhanced through the injection of the carbon substrate. Performance monitoring is currently ongoing. Serves as a Project Principal for INTERA's NMED contract, which includes INTERA's work at the NRAP site as well as INTERA's work at the Eagle Picher site in Socorro, New Mexico.

Former Central Works Equipment Facility Remediation Activities "COA Rail Yards," City of Albuquerque, NM. 2006 – Present. *Project Manager.* Managed the removal of contaminated soil at the former Central Works Equipment (CWE) facility in Albuquerque, New Mexico. The project included the removal of approximately 600 cubic yards of lead-contaminated soil previously stockpiled at the site. Developed a Work Plan to investigate petroleum-hydrocarbon and metals contamination at this site using Targeted Brownfields Assessment (TBA) funding. Led an additional Phase II investigation at the site in 2012. The Phase II investigation consisted of surface and subsurface soil sampling, building sub-slab vapor sampling, and groundwater sampling. This effort was conducted to determine what impacts (if any) the historical operations of the site as a railyard would have on future redevelopment. It was determined that a petroleum-hydrocarbon plume was present at the southwest corner of the site. Limited impacts were present in surface and subsurface soils. Developed several cost estimates for the remediation of soil and groundwater at the site for the city to use depending on the redevelopment scenario they selected. Further site investigation work was completed in 2012 as the city moved toward redevelopment of the site. Served as Project Manager for an Additional Site Investigation (ASI) that included completing a data evaluation/remediation options document to compile and analyze all existing contaminant data for the entire city railyard, which included former tank areas, oil/water separator, and a former locomotive roundhouse, among others. The evaluation resulted in identifying several data gaps which were investigated during the ASI. Contaminants of concern for this site included VOCs, TPH, PAHs, lead, and arsenic. The site investigation included (1) collecting surface soil samples from thirteen locations, (2) drilling oversight of 18 soil borings using direct push technology methods, (3) collection and screening of soils samples using a photoionization detector (PID) and Dexsil PetroFLAG field test kit to aid in selection of samples for laboratory analysis, (4) collection of eleven groundwater samples with the SP-16 sampler, temporary monitoring wells, and

existing monitoring wells, (5) installation of a soil vapor sample point, and (6) collection of a soil vapor sample using a Vapor PinTM. INTERA provided the client with a completed report, which included several remediation scenarios based on various redevelopment options.

Oversaw the remediation of the Blacksmith Shop building at the CWE facility in 2013. The remediation work consisted of the abatement of asbestos as well as the encapsulation of lead-based paint on the ceiling of the Blacksmith Shop. The Blacksmith Shop was redeveloped by COA into an open-air market following remediation activities. The redeveloped Blacksmith Shop opened in June 2013.

Worked with the COA selected developer, Samitaur, on a VRP approach for all portions of the Railyard property. This included a multi-option remediation approach as several redevelopment options (residential, commercial, open space) will be implemented at the site. Oversaw the development of a CSM for the site. INTERA compiled all available information related to environmental site conditions such as historical soil and groundwater data to help determine the nature and extent of the contamination across the site with regard to depth and COCs in the CSM to provide a foundation for remedial action decisions. Activities completed as part of the CSM included developing a database in Microsoft Access, connecting the database to ArcGIS to allow for visual data analysis, and identifying key data gaps. The CSM was also used as a foundation for development of a remediation work plan required to address data gaps at the site. The remediation work plan was developed in conjunction with potential redevelopment scenarios identified for the site. Implementation of the remediation work plan was completed early 2017 and included the collection of soil samples, soil vapor samples, groundwater samples, sub-slab soil vapor samples, and the completion of asbestos and lead-based paint surveys on all site buildings. The results of the data collection were compiled into ten different reports, one for each of the 10 railyard parcels. The intent of separate reporting for each of the 10 parcels was to allow phased development of the site over a lengthier time period than is customary under the VRP.

Contracted in late 2018 to develop a revised VRP Application and Preliminary Work Plan for the COA Rail Yards, splitting the COA Rail Yards into two VRP sites (COA Rail Yards North and COA Rail Yards South). Currently, the COA Rail Yards North has received conditional eligibility to enter the VRP and Public Notice and a Public Meeting was held in April 2019 to outline for the public the proposed remedial actions. Assisted with the Public Notice requirements for the COA Environmental Health Department personnel. The COA implemented soil removal activities within the COA Rail Yards North in May and June 2019.

Contracted in early 2020 to help the COA develop a VRCR for the COA Rail Yards North and to implement an off-Site groundwater monitoring well installation Preliminary Work Plan for the COA Rail Yards South. INTERA developed a VRCR for the COA Rail Yards North and submitted it to NMED in September 2020. INTERA also, as requested by the COA, developed, submitted to NMED, and received NMED approval for a Contaminated Soil Management Plan (SMP) in July 2020. This SMP will be followed as additional impacted soil is excavated at the COA Rail Yards. Either developed or provided final review of this documents. INTERA installed 5 ground water monitoring wells at off-site locations surrounding the COA Rail Yards South. These monitoring wells were installed in February 2021. Provided interface with the client during the field work and also provided daily direction to the INTERA field team. Finally, INTERA will work with the COA's Rail Yards management team to develop the remediation approaches for the COA Rail Yards South depending on the selected future development. Secured a VRP CCOC for the Rail Yards North in 2021. Currently leading the LTM activities associated with ground water and soil vapor at the Site and leading efforts to secure a CCOC for the Rail Yards South. In addition to LTM activities, currently providing quality assurance inspections for the installation of a soil vapor mitigation system in the Boiler Shop, prior to it's redevelopment as a movie studio for CNM (abqrailyards.com).

Technical Support Services for the Red Hill Bulk Fuel Storage Facility, Honolulu Board of Water Supply, Honolulu, HI. 2015 – Present.
Project Manager. Providing third-party technical review of technical documents and data produced and collected by the U.S. Navy and its contractors at the Red Hill Bulk Fuel Storage Facility (RHBFSF). The RHBFSF contains 20 large field-constructed underground storage tanks, each containing approximately 12.5 million gallons of fuel. These tanks are located at depths ranging from 120 to 175 feet below ground surface within the Koolau Basalt and lie 100 feet above the aquifer. Fuel leaks from the facility both historic and recent (January 2014 – 27,000-gallon release) have impacted the underlying EPA-designated Sole Source Southern Oahu Basal Aquifer and are potentially threatening the Honolulu Board of Water Supply (BWS) water supply wells and production shaft. The 2014 release resulted in the Navy, the EPA, and the Hawaii Department of Health (DOH) signing an Administrative Order on Consent (AOC) to assess the RHBFSF and determine what impact this release and previous releases have had on the environment and to determine what the appropriate tank

upgrade solution may be. Activities included reviewing technical reports and extracting and compiling data collected at the RHBFSF from these reports. Reviewed and provided over 135 comment letters to date to the DOH and the EPA on various Navy work plans and reports. Led the INTERA Team's development of a CSM that describes the processes and features controlling the migration of fuel contamination and identifies potential exposure pathways and receptors. Additionally, supported the development of a Monitoring Well Construction and Installation Plan, sampling plan, and quality assurance plan for several sentinel wells installed by INTERA for the BWS. The first monitoring well was completed in 2017, and quarterly groundwater monitoring was in 2017 and 2018. Semi-annual sampling of this monitoring well began in 2019 and continues in 2021. Hired Exponent as a subcontractor and oversee their technical work associated with tank infrastructure, release detection, corrosion and metal fatigue, risk assessment, and toxicology services. This expertise has been needed on various comment letters developed by INTERA for the BWS since the initiation of the contract. Representing BWS interest in numerous technical working meetings associated with the Red Hill AOC and the AOC Statement of Work (SOW) since contract initiation in 2015. Participates in Groundwater Modeling Working Group meetings to review the progress of the Navy's flow and transport groundwater model. Assists the BWS with the development of community meeting and BWS Board presentations and regularly attends all public meetings in California and/or Hawaii held by the EPA, DOH, and the Navy on the Red Hill matter. Negotiated a 2020 contract renewal with BWS that extended INTERA's work on this project for the next several years.

Led INTERA's efforts in 2021 and 2022 to support the BWS in response to the Red Hill Hawaii Department of Health (DOH) Emergency Order which requires the complete defueling of the facility by June 2024 (defueling was completed by the Navy in March 2024). These efforts have included reviewing and commenting on Navy deliverables (Defueling Plan, Closure Plan, Notice of Intent [NOI] data reports, groundwater flow model reports, etc.) and providing this information to BWS. In addition, because of the May and November 2021 fuel releases at Red Hill, the BWS has been forced to shut down several drinking water sources in the area. Mr. Tracy is currently focused on supporting the BWS with the identification of monitoring well and exploratory production well sites and working with the INTERA Project Team to design each monitoring and exploratory well and exploratory well pumping tests. INTERA has developed well designs for over ten monitoring wells and four exploratory well locations and is currently developing the drilling plans and testing plans associated with these wells. Assisting the BWS with the development of bid documents to procure drilling services for monitoring and exploratory well installations. Providing management and scheduling assistance for INTERA field teams overseeing well installation activities by BWS general and drilling contractors.

Sites Assessments, New Mexico Department of Transportation, Various Locations, NM. 2015 – Present. *Principal in Charge.* Provides senior technical review of Initial Site Assessments (ISAs), preliminary site investigations (PSIs) and Detailed Site Investigations (DSI) at several NMDOT construction project sites in New Mexico. These NMDOT projects involve the evaluation of properties either NMDOT-owned or NMDOT right-of-way (ROW) acquisitions as part of highway improvement projects. The ISAs completed generally follow the ASTM Standard E1527-13 and the NMDOT Handbook for site assessments. The PSIs and DSI include Phase II activities (investigative excavations, soil boring drilling, soil sampling, and geophysical surveys) for further evaluation of NMDOT property. Supervises the field teams conducting this work and provides senior technical review of all project deliverables. Manages overall contract issues and interfaces directly with the INTERA Project Manager and NMDOT management. Most of these assessments are completed in areas where NMDOT is going to expand their infrastructure with either additional traffic lanes or an upgrading of their maintenance yards.

Site Monitoring and Emergency Response Contract, New Mexico Environment Department - Petroleum Storage Tank Bureau, Various Locations, NM. 2014 – Present. *Project Principal.* Providing administrative and technical review of work conducted for contaminant characterization investigations and groundwater monitoring activities. These activities seek to determine the nature and extent of subsurface petroleum hydrocarbon contamination originating from above ground and underground storage tank sites. Investigations include the analysis of soil, groundwater, and soil vapor impacts to these various sites across New Mexico. Work includes the following partial listing of INTERA Petroleum Storage Tank Bureau (PSTB) state-led sites: Barelas Bridge Site in Albuquerque, New Mexico; Bell Gas Site in Truth or Consequences, New Mexico; Brewer Self-Serve Site in Roswell, New Mexico; City Market Site in San Miquel, New Mexico; Frank's Conoco Site in Bernalillo, New Mexico; Corrales Chevron in Corrales, New Mexico; Robinson Texaco in Taos, New Mexico; Rodgers Drilling Site in Albuquerque, New Mexico; Village Market and the Former Caldwell Motors sites in Belen, New Mexico; and the Montoya Well Site in El Prado, New Mexico.

Dry Cleaning Site Investigation and Remediation of Tetrachloroethene Contamination, Elite Laundry and Cleaning, Gallup, NM. 2013 – Present. *Project Manager.* Leading efforts to investigate and remediate groundwater impacted by PCE as a result of previous releases from this operating dry-cleaning facility. The impacted groundwater was discovered during a Phase II ESA conducted on an adjacent property. In response to a letter from NMED to address the contamination, efforts have included providing technical support and advice to Elite Laundry and Cleaners representatives to determine the most appropriate path forward. This included addressing the identified contamination under the NMED VRP. Prepared and submitted a VRP work plan and VRP application to NMED. The proposed VRP investigation activities include the installation of monitoring well on- and offsite to characterize and delineate the PCE in groundwater contamination. The field activities identified in the VRP Work Plan were initiated in late 2018 and early 2019, which included the installation of additional monitoring wells as well as subsurface soil and indoor air vapor sampling activities. Off-site passive vapor sampling activities were completed by INTERA under Mr. Tracy's oversight at the Site and within the area in 2020. Additional site characterization activities and preliminary design for a remediation system to prevent the off-site migration of contaminants in soil vapor and ground water are planned for 2025, including the installation of a soil vapor extraction system for the removal of VOCs in soil gas to prevent the potential for offsite migration.

Judge Steve Herrera Judicial Complex Site Investigation, Remediation, and Monitoring, Santa Fe County, NM. 2009 – Present. *Contract Manager and Project Manager.* Leads INTERA's efforts to develop a remedial solution for the Santa Fe County Judicial Complex which involves interfacing with both the NMED VRP and PSTB. INTERA was contracted by Santa Fe County in March 2009 to support their efforts to re-develop a Brownfields property comprising a three-story judicial complex and associated plaza and subsurface parking garage in downtown Santa Fe, New Mexico. A large excavation and steel/wood shoring system was constructed beginning in the fall of 2008. During shoring activities, a two-foot layer of LNAPL was discovered near the water table. INTERA performed additional site investigation activities and determined that the LNAPL plume was predominately present in the proposed location of a subsurface two-story parking garage. Construction of the garage and associated judicial complex was delayed, enabling the county and NMED's PSTB to develop an appropriate response action. PSTB subsequently designed and is operating a soil vapor extraction system for the areas outside of the judicial complex excavation to remediate the historic contamination. The county was responsible for the remediation of their property even though they were not a responsible party. Led the development of a petroleum contaminated soil (PCS) work plan including development of a dewatering plan, excavation and removal of over 20,000 tons of PCS, installation of a vapor intrusion/ground water barrier (liner) on all parts of the development located below grade, and development of a vapor monitoring system for the final development of the site. The Work Plan was approved by VRP and PSTB. The excavation work is complicated because of two primary factors: (1) soil must be excavated below the water table requiring dewatering for safe removal; and (2) construction activities are scheduled to take place immediately following soil remediation efforts, requiring that dewatering continue for several months until construction infrastructure can be put in place below the water table for the two-story parking garage. Helped initiate the development of a soil gas passive venting system around the subsurface parking garage and initiated the installation of this system in January 2012.

Additionally, prepared and submitted a VRP application to secure a certificate of completion for the remediation work; supervised risk assessors in the development of a document pertaining to future building occupancy and currently participates in numerous stakeholder meetings with the county and PSTB representatives. Either conducted or supervised INTERA staff employees or subcontractors in assessing, reviewing, and selecting mitigation measures for the complex; identifying and developing measures to isolate the proposed infrastructure from contacting LNAPL remaining in the plume around the building (i.e. liner selection process); LNAPL sampling and characterization; air emissions testing and permitting; waste profiling; preparation and submittal of a groundwater discharge permit application; LNAPL removal and disposal; LNAPL bail-down testing; a Phase I ESA of the site; slug testing to determine aquifer properties; weekly VRP update reporting, and subcontractor oversight of remediation activities. The PCS removal activities were completed at the site in February 2011. Continues to work with the county to develop a VRP Completion Report and secure a CCOC for the site. The judicial complex was completed in February 2013 and began operating in June 2013. Continues to oversee quarterly groundwater monitoring activities at the site as part of the county's VRP Work Plan. Secured a Voluntary Remediation Agreement (VRA) for the site on July 9, 2015. Completed the Voluntary Remediation Completion Report (VRCR) for the site in February 2016 and assisted the county in obtaining a VRP CCOC from NMED also in February 2016. Groundwater monitoring activities were completed by INTERA at the site in October 2016. Currently assisting the county by reviewing the work conducted by the PSTB at the site and providing status reports to the county. For example, observed multi-dual phase extraction activities conducted by PSTB and their contractor at the site in 2017. The final goal is to assist the county in

securing a VRP CCOC with only a land use restriction in 2024. Helped the County discontinue the NMED judicial complex discharge permit (NMED DP-1747) in late 2023 and currently negotiating on the County's behalf with NMED to modify the VRP CCOC in 2025.

SunZia Transmission Line Phase I Environmental Site Assessment, New Mexico and Arizona Approximate 550-Mile Corridor. 2021 – 2024. *Project Principal*. INTERA was retained by SunZia Transmission, LLC located in Albuquerque, New Mexico to perform a Phase I ESA for a 550-mile corridor starting southeast of Phoenix, Arizona and terminating in Corona, New Mexico. The proposed transmission line would ultimately aid in the transportation of wind farm produced electricity across New Mexico and into the Tucson area of Arizona. Provided Project Principal review and contract management duties for the project. Worked with the Project Team to develop Phase II site characterization goals for the recognized environmental conditions (RECs) identified during the Phase I ESA work. The Phase II recommendations included geophysical surveys for two former bombing ranges that the Project Corridor intersects in New Mexico and for soil cleanup of an above-ground storage tank release at a commercial agriculture operation at a property in Arizona. The geophysical investigations for the two former bombing ranges were completed in 2023 (no mitigation needed) and the soil cleanup for the Arizona commercial agriculture operation is scheduled to be conducted in 2024.

Data Gap Monitoring Well for the Albuquerque Bernalillo County Water Utility Authority, Albuquerque, NM. 2022 – 2023. *Project Manager.* The Albuquerque Bernalillo County Water Utility Authority (ABCWUA) received funding from the State of New Mexico CPB in 2021 to drill, install, and sample a monitoring well downgradient of the ethylene dibromide (EDB) and petroleum hydrocarbon plumes in groundwater migrating offsite from Kirtland Air Force Base (KAFB). Provided technical input on recommended location and design of a >500-ft deep monitoring well to address a potential data gap toward the distal end of the known EDB plume. Led the installation of the monitoring well (sonic drilling methods) and initial well development which was completed in April 2022. Led initial one-year long-term monitoring activities of the data gap monitoring well in late 2022 and early 2023 until the LTM duties were shifted from INTERA to an ABCWUA on-call contractor.

Kirtland Air Force Base Environmental Baseline Surveys, Albuquerque Bernalillo County Water Utility Authority, NM. 2018 – 2022. *Project Principal.* Provided technical oversight and review of final deliverables for the INTERA effort to conduct two Environmental Baseline Surveys (EBS) for the ABCWUA to meet appropriate property due diligence practices for the easement agreement between ABCWUA and KAFB. The property locations included a 5.29-mile-long easement and a 24-acre parcel, all located on KAFB and Department of Energy (DOE) property. The project includes the ABCWUA installing an interceptor pipeline and booster station and INTERA is responsible for all federal due diligence requirements associated with construction projects occurring on federal facilities. Responsible for internal team communications, client meetings, and final review of the two EBS reports. The EBS reports were completed and approved by the ABCWUA and KAFB in 2022.

Phase I Environmental Site Assessment of Mt. Chalchihuitl and Cerrillos Gravel Products Properties, Santa Fe County, Cerrillos, NM. 2004 – 2022. *Project Manager.* Project Manager for the Phase I ESA of the combined 745-acre Mt. Chalchihuitl and Cerrillos Gravel Products properties. Assessment activities are being conducted using the EPA's All Appropriate Inquiry (AAI) and ASTM Standard E1527-05 as guidance. Performed risk assessment and remediation alternative analysis activities at the Mt. Chalchihuitl portion of the site (545 acres) in 2004. The entire site was historically used for mining activities, located at the center of the Cerrillos Mining District South area. Santa Fe County plans to re-develop the site as open space by incorporating it into the Cerrillos Hills Historic Park, and INTERA continues to work with Santa Fe County to determine remediation options for the site. The development objective is to include these properties in the Cerrillos Hills Mining District Open Space Park.

Developed a VRP Work Plan for the site in 2012, which selected a previously determined remedial option and submitted the Work Plan to Santa Fe County for review. The selected remediation includes the construction of tailings impoundment and cap in a former gravel pit and long-term monitoring to make certain the cap integrity is secured. The remainder of the site will be used as a public open space, allowing the public to observe some of the oldest mines in North America. Completed and submitted the VRP Application and Preliminary VRP Work Plan for this Site in September 2017. The county would like to acquire the properties in 2018 and begin soil remediation as soon as possible after property acquisition. Currently assisting the county legal team with the development of a VRA between the county and NMED. Also, were recently awarded a contract to sample soils in the arroyo to the south of the Cerrillos Gravel Products property and to sample three area drinking water wells to determine any potential water quality impacts.

Responded to a Letter of Interest (LOI) released by the County in 2019 to assess ground water conditions at the Mt. Chal site. After selection by the County in response to the LOI, led the INTERA Team in sampling an upgradient private water well and a monitoring well at the Cerrillos Gravel Products property. Determined elevated metals concentrations are present in site groundwater and offered recommendation to the County for addition work at the site and the potential installation of a new monitoring well in a down gradient location. Due to a disagreement on overall value with the landowner (both property and mineral rights), the County passed a resolution and discontinued their Mt. Chalchihuitl acquisition initiatives in 2022.

Redevelopment of the Former First Baptist Church Site, Lobo Development, Albuquerque, NM. 2013 – 2021. *Project Manager.* Provided oversight for voluntary remediation activities associated with redevelopment of this property in downtown Albuquerque. Previously conducted Phase I and II ESAs and identified subsurface soil and groundwater contamination that was believed to be the result of a diesel fuel release at the adjacent Burlington Northern Santa Fe (BNSF) Railway Railyard. Evaluated site investigation data and determined that the property had been impacted by both off-site sources and historic site uses that required limited remediation prior to site redevelopment. The site was entered in the NMED VRP to secure a Certification of Completion (COC) to facilitate redevelopment. Activities included interaction with NMED to ensure the COC was issued in a timely manner and assisting in obtaining a Covenant Not to Sue (CNS). After receiving the COC and CNS, Lobo Development acquired the property in 2014 and the site was re-developed as part of the City of Albuquerque's "Innovate ABQ" development initiative. Worked with the Innovate ABQ development team to manage the environmental risks associated with the planned redevelopment of the Site. Assisted the Site developer (Signet) with renovation and demolition activities completed within the former First Baptist Church in 2016. Assisted the developer with VRP reporting activities in 2016, 2017, and 2018 associated with the construction of a three-story building at the site. VRP reporting activities are required in order to maintain the COC by guiding the developer to implement the proper engineering controls. The newly constructed three-story commercial building is known as the "Lobo Rainforest" and serves as an entrepreneur center for business associated with "Innovate ABQ," a downtown Albuquerque technology park. Led a team that updated the Phase I ESA in 2020 on behalf of the University of New Mexico (UNM). Also helped secure a U.S. Environmental Protection Agency (EPA) "Comfort Letter" for UNM and a CNS prior to the property transfer. UNM assumed ownership of the site in late December 2020.

Redevelopment of the Former Galles Chevrolet Automobile Dealership Property, University of New Mexico, Albuquerque, NM. 2018 – 2020. *Project Manager.* Provided oversight for voluntary remediation activities associated with redevelopment of this property in the UNM area of Albuquerque. Previously conducted Phase I and II ESAs identified subsurface soil and groundwater contamination that was believed to be the result of gasoline and diesel fuel releases from former underground storage tanks (USTs) located at the property. Additional environmental contamination was also identified by the operation of over 70 underground hydraulic lifts as well as five former oil/water separators (OWS) in use at the property. Evaluated site investigation data and determined that the property has been impacted by historic site uses that required limited remediation prior to site redevelopment. The site was entered in the NMED VRP to secure a COC to facilitate redevelopment. Activities included interaction with the NMED to ensure the COC was issued in a timely manner and assisting in obtaining a CNS. The issuance of the COC and CNS are still pending. Conducted an on-site soil vapor survey to determine areas of elevated soil vapor concentrations and developed a plan for the construction and use of vapor intrusion barriers for any newly constructed buildings at the Site. Evaluated the remediation activities conducted by the landowner (Sandia Corporation) to determine what impact, if any, the remedial work may have on future UNM activities at the site. Worked with subcontractor DC Environmental to prepare a cost estimate associated with the asbestos and lead-based paint abatement at current Site buildings prior to demolition and/or renovation. UNM leased the property in late 2019. Worked with UNM Medical Center personnel to assist with the development of short-term uses for the site prior to full-scale redevelopment.

Investigation of the Santa Fe River Targeted Brownfields Assessment Area, City of Santa Fe, NM. 2010 – 2019. *Project Manager.* Led an investigation in the downtown Santa Fe area to (1) develop a better understanding of groundwater flow within the area so that appropriate decisions can be made about remediation of petroleum hydrocarbons and other groundwater contaminants, (2) determine what impact, if any, will occur within the shallow groundwater aquifer if stream flow in the Santa Fe River is increased, and (3) determine the nature and extent of petroleum hydrocarbon contamination so engineering controls can be evaluated for future development within the TBA area. Activities included developing a geologic model and implementing a drilling program to confirm model accuracy. Field investigations showed that the

geologic model is accurate, and the City of Santa Fe and NMED used the geologic model to guide additional investigations being conducted by NMED and EPA in the downtown Santa Fe area. These investigations were completed to identify sources of petroleum hydrocarbon as well as chlorinated hydrocarbon contamination in ground water in the downtown Santa Fe area. Activities in 2016 and 2017 included the installation of additional groundwater monitoring wells, groundwater sampling, installation of soil vapor monitoring wells, soil vapor sampling, indoor air sampling, and groundwater sampling of additional monitoring wells owned by several different entities in the downtown Santa Fe area to determine groundwater characteristics and the potential sources of identified contamination. Subsurface soil gas sampling was conducted at this Site in June 2019 using "Waterloo Membrane Samplers" placed at several facilities within the TBA area that may have been sources of the underlying ground water contamination. Helped NMED develop a report for the 2019 sampling event and discussed the findings with NMED.

Proposed Belen Fire Station Property Investigation and Remediation, Molzen Corbin, Belen, NM. 2017 – 2018. *Project Manager.* Supervised Site investigation and remediation services at the proposed new Belen Fire Station property located in Belen, New Mexico. Prior to site redevelopment activities, Molzen Corbin Engineers contracted INTERA to conduct site investigation activities to determine if any impact from petroleum hydrocarbons occurred at the Site during historical activities (automobile repair activities) and to conduct geophysical investigation work to determine if any relic USTs were present at the site. INTERA advanced 15 soil borings at the site using geoprobe investigation methods to collect soil and groundwater samples. Investigation results determined that approximately 2,800 cubic yards of PCS were present at the site and one UST was in the northwest corner of the property. INTERA provided a map of the locations of the PCS and the UST. The PCS and UST were removed by City of Belen contractors in 2017. In addition, groundwater impacts by petroleum hydrocarbons were also verified, but no concentrations identified were above New Mexico Water Quality Control Commission (NMWQCC) standards or PSTB action levels. Continued to provide consulting services to Molzen Corbin at the Site as Fire Station building construction was initiated in 2017. INTERA recommended removal of the PCS and installation of a vapor intrusion barrier and sub-slab venting system to protect future building occupants and Site users. INTERA developed specification documents for both PCS removal and vapor intrusion barrier installation and provided to Molzen Corbin Engineers to include in the general contractor bid package. Construction of the Belen Fire Station was completed in 2018. The Belen Fire Station redevelopment project received the "Environmental" award from the New Mexico Chapter of the American Council of Engineering Companies in September 2020.

Investigation of Perchloroethylene Contamination at the Griggs and Walnut Superfund Site, Confidential Client, Las Cruces, NM. 2015 – 2018. *Senior Scientist.* Assisted the technical team evaluating the release timing and locations of PCE contamination in the area of the Griggs Street and Walnut Avenue intersection in the northern section of the City of Las Cruces. The timing information was critical in demonstrating occurrences for insurance reimbursement purposes. Assisted in the development of the CSM for the potential release sites in the area. The CSM would be used by Dona Ana County and the City to help further their understanding of the Superfund site.

Facility Environmental Audits and Stormwater Management Plans, Wood Group/TurboCare Generator Services/Ethos Energy, Farmington, NM. 2010 – 2018. *Project Manager.* Performed environmental audits of three electric generator parts manufacturing facilities, focused on determining volumes of hazardous waste generated at each facility. Reviewed information to calculate volumes to determine the correct generator status (conditionally exempt, small or large), obtain a correct hazardous waste generator identification number, and calculate and pay the associated hazardous waste fees to the NMED Hazardous Waste Bureau for each facility. After calculating these volumes, the Wood Group reported previous quantities of generated waste and paid current and past hazardous waste-generation fees, bringing the facilities back into regulatory compliance. Prepared stormwater pollution protection plans (SWPPPs) for each facility and provided ongoing support with stormwater issues. Due to facility operator transfer and the closing of the two of the facilities, worked with INTERA staff in 2017 and 2018 to update the SWPPP and file Notice of Termination of discharge and NOI to discharge for the new ownership group (Ethos Energy).

Reclamation of the San Vicente Mill Site, New Mexico Environment Department, Silver City, NM. 2013 – 2016. *Project Manager.* Led environmental investigation and remediation/reclamation activities to address an above-grade tailings pile, resulting from former milling and smelting operations for lead, silver, copper, and gold that operated from the 1880s to the 1940s. The tailings pile contained metals (e.g., arsenic and lead) at levels exceeding established human health standards. Water quality had been impacted by the erosion of the tailings pile and the subsequent transport of contaminated material to an adjacent creek. Groundwater also contains elevated concentrations of metals. Project activities included negotiating access

agreements, as portions of the site were on private property; determining the extent of tailings and contaminated soils on-site and offsite; organizing and holding a community meeting to inform property owners as well as Town of Silver City representatives and citizens of potential community impacts; providing contractor oversight for removal of contaminated materials (approximately 50,000 cubic yards); transporting and disposing of contaminated materials at a nearby operational mine site; restoring disturbed areas with placement of soil cover; and reseeding with a native seed mixture. Implemented a reclamation approach that included performing additional characterization efforts while removal of the main tailings area material was being conducted. The single mobilization resulted in cost savings and a project that was completed ahead of schedule. Responsible for developing the Final Removal Assessment Report which documented the quantity of tailings removed and the restoration activities including clean fill placement, grading, and institution of property engineering controls.

Environmental Site Assessments, Los Alamos County, NM. 2005 – 2016. *Contract Manager and Project Manager.* Served as Contract Manager for Los Alamos On-Call Services contract. Investigated and characterized the environmental conditions at several Los Alamos County and Los Alamos School District properties. These properties were formerly operated by Los Alamos National Laboratory. Currently managing this work, which includes Phase I and Phase II ESAs, asbestos and lead-based paint surveys, archaeological investigations, archaeological stabilization activities, surface water sampling, and other general environmental consulting activities. Special projects have included a hazardous materials survey at the Los Alamos County Golf Course, an Environmental Assessment (EA) of the Los Alamos County Canyon Dam site, and a NMED VRP application for the Los Alamos County Trinity Redevelopment site.

Designed and constructed a stormwater detention pond engineering controls at the Trinity Redevelopment site in 2012. The pond was constructed as a solution to an NMED action that required the county to control stormwater runoff into the canyon to the south of the site. Managed the project that included engineering design, construction, and reporting to NMED. Following the construction of the drainage improvement, Los Alamos County began redeveloping the site with a shopping center to include a grocery store, small businesses, and restaurants.

Provided oversight of the removal of a historic OWS from the Trinity Redevelopment Site in 2013. The OWS was discovered during redevelopment construction activities. Secured a subcontractor and provided the county with expedited services during the OWS removal and subsequent sampling so that the construction activities scheduled for the site were not compromised.

Former Eubank Landfill Assessment of Remediation Alternatives, City of Albuquerque/New Mexico Environment Department, NM. 2003 – 2016. *Project Manager.* Led an effort on behalf of the COA and NMED to characterize the nature and extent of landfill gas contamination at the former Eubank Landfill (northeast fill area). Also worked at this site on behalf of Albuquerque Public Schools, an owner of an adjacent property; Bernalillo County, a stakeholder related to the Eubank Landfill; the U.S. Army Corps of Engineers; and the New Mexico State Land Office. The northeast fill area of the former COA Eubank Landfill was operated between 1963 and 1973 on property leased from the New Mexico State Land Office. The Eubank Landfill northeast fill area was unlined and covered approximately 21 acres, with a waste depth in the range of approximately 30 to 40 feet. Material placed at the Eubank Landfill was reported to be mainly residential and commercial waste.

Conducted an assessment of the former Eubank Landfill southwest fill area in 2011 for the proposed future development as a solar panel system field. Worked for a private solar development company along with the COA to evaluate this use of the site and how this use may be impacted by the potential migration of landfill gas. Also worked with INTERA engineers in the development of a final landfill gas management plan as well as a surface grading and drainage plan. In 2012, managed the project, which included additional grading plans for several types of solar panel designs selected for the site. This included the development of a Waste Excavation Plan (WEP). The WEP included the use of waste as fill material, the first of its kind in the State of New Mexico.

Developed an approach for Emcore Solar Power to install and operate a solar panel field at the surface of the former Eubank Landfill southwest fill area. This included LFG investigation activities as well as a geotechnical investigation conducted in order to develop recommendations for landfill gas control measures as well as geotechnical foundation of the solar panel trackers. This work included communicating with civil engineers, architects, electricians, and others to facilitate the successful project. The solar field is currently online and provides power to the Emcore manufacturing facility located

adjacent to the former landfill. Responsible for final reporting and periodic site inspections concerning the condition of the landfill surface.

Hyder Property Site Investigation, City of Albuquerque, NM. 2003 – 2016. *Project Manager.* Developed the investigation work plan at this Brownfield redevelopment property which was the site of a former dry-cleaning facility. The work plan included the execution of a geophysical survey as well as investigative digging to find historic underground solvent storage tanks. Investigative excavations were constructed at the Hyder property, and six USTs were discovered. Conducted a Phase II site investigation at the Hyder property, which included the collection of surface soil, subsurface soil, soil gas, and groundwater samples. Wrote the VRP Completion Report for this site; property received a Certificate of Completion from the NMED VRP. Worked with the site developer, YES Housing, to oversee excavation of soils to determine if contamination was present during construction in late 2014. Site redevelopment as the Imperial Building began in early 2015. Worked with the construction contractor to address environmental contamination (removal of petroleum-contaminated soils and two underground storage tanks) during building excavation and construction work. Submitted the VRCR for the site to NMED in December 2015. Assisted the site developer in securing a CNS from the NMED VRP in early 2016. The Imperial Building includes residential housing on the two upper floors and a community garden on the roof, with commercial spaces (including a grocery store) on the first floor. One level of parking is included in a subsurface parking lot located below the building. The Imperial Building officially opened in September 2016.

500 Copper Square Property Soil Vapor Investigation, First Financial, Albuquerque, NM. 2014 – 2015. *Project Manager.* Led efforts to determine presence of VOCs in site soil vapor. Collected sub-slab soil gas samples at locations within the building basement and compared analytical results to EPA's recommended commercial and residential vapor intrusion screening levels (VISLs) to determine whether VOC contaminants were impacting air quality in the building. Tetrachloroethene (PERC)—a dry cleaning solvent—was present in several of the soil vapor samples, but concentrations did not exceed applicable VISLs for PERC. Entered site into the state VRP in order to obtain a COC to document that current conditions meet applicable environmental quality standards and provide liability protection for lenders. NMED issued at COC in 2015, and a CNS can be transferred to any lender or future owner of the property.

Former Sterling Manufactured Gas Plant Voluntary Cleanup Program Site, Centennial Mental Health Center, Sterling, CO. 2014 – 2015. *Senior Technical Advisor.* Assisted with additional site investigation activities within the VCP investigation and remediation activities at the former Sterling Manufactured Gas Plant site. This site was remediated through the Colorado Department of Public Health and the Environment (CDPHE) VCP for future development into a parking lot for use by the future landowner and neighboring facility, Centennial Mental Health Center. The initial site investigation and targeted brownfields assessment were completed by CDPHE and identified polyaromatic hydrocarbons (PAH) organics and metals contamination above the regulatory limits in the site soils. Project tasks have included potholing of site soils to define further the extent of soil contamination, sampling of an upgradient groundwater monitoring well to determine if metals contamination can be attributed to an off-site source, determination of the most cost-effective method to sample near and around a transformer on site, and completion of the work plan, cost estimate, and health and safety plan for the excavation of site contaminated soils. To accommodate funding schedules, the remediation activities, which consisted of excavation, hauling, and off-site disposal of 814.5 cubic yards of soils contaminated with PAHs, were performed using a phased approach and were completed in 2015. A No Action Determination (NAD) was submitted and formal acceptance of the NAD by CDPHE was received in December 2015.

Characterization and Remediation of the Former Bell Trading Post Property, City of Albuquerque, NM. 2001 – 2005 and 2015. *Project Manager.* Developed a Work Plan to characterize this facility adequately for ultimate inclusion into the VRP. The Bell Trading Post building was formerly a jewelry manufacturing facility as well as a photograph development facility. Heavy metals and solvents were in use at this historic facility. The Work Plan included Geoprobe soil boring installations, subsurface soil sampling, and groundwater sample collection. In addition, on behalf of the COA, supervised a subcontractor conducting a limited asbestos survey at the Bell Trading Post facility building. Completed the VRP Application for this site and developed a VRP Work Plan for the remedial work, which included an integrated QAPP. The remediation consisted of contaminated soil removal as well as the remediation of asbestos and lead-based paint. This was the first Work Plan/QAPP developed for asbestos/lead-based paint remediation in EPA Region VI. Provided oversight of the remediation work and documented the progress on behalf of the COA and its developer, Family Housing Development Corporation. Remediation work completed included the cleaning of a substantial amount of pigeon droppings, asbestos and lead-based paint abatement, lead-in-soil removal, and the removal of all light ballasts from the building. Wrote the VRCR for this facility and

helped the COA obtain a Certificate of Completion from the NMED VRP. This facility was later renovated and developed with residential housing units and commercial office space. Lead a soil vapor intrusion assessment of the renovated building on behalf of the NMED in 2015.

Municipal Separate Storm Sewer System Audit and Application, Santa Fe County, NM. 2012 – 2013. *Project Manager.* Led efforts to assist the county in submitting a municipal separate storm sewer system (MS4) application to the EPA. Reviewed and evaluated documents regarding the history of the MS4 and the NOI Plan; prepared summary report for the county to document current status of the EPA requirements for the MS4 Plan and NOI and define options, deliverables, action items, and schedules/timelines; and helped the county resubmit the MS4 Application to EPA. By working cooperatively with both the county and EPA, helped avoid financial penalties for the county.

Phase I and Phase II Assessments, Northwest New Mexico Council of Governments, Gallup, NM. 2010 – 2013. *Contract Manager and Project Manager.* Contract Manager for Northwest New Mexico Council of Governments (NWNMCOG) On-Call Services contract. This contract was established by the NWNMCOG to evaluate potential Brownfields within the NWNMCOG area (Gallup, San Juan, and Cibola counties). Performed Phase I and Phase II Assessments for the NWNMCOG as part of this contract. Brownfield site characterization activities are the general focus of the contract for those sites located within the NWNMCOG area. Phase II activities conducted under this contract included hollow-stem and air rotary drilling, geophysical survey using electromagnetic (EM) and ground-penetrating radar (GPR) equipment, surface and subsurface soil sampling, groundwater sampling, and investigative excavations using a backhoe.

An example of a NWNMCOG project is the Coal & Puerco Site in Gallup, New Mexico. This site is proposed to be redeveloped with a live/work facility by Community Area Resource Enterprise 66. A dry-cleaning facility is located immediately north of the site. Led INTERA's efforts to investigate the redevelopment site and determine what remedial actions or engineering controls would need to be implemented at the site to although for safe and cost-effective redevelopment. INTERA conducted surface and subsurface soil sampling, soil vapor sampling, and groundwater sampling at the site. PERC was identified in site groundwater and soil vapor. Based on findings of the investigation, recommended that a vapor intrusion barrier be placed below the proposed site building to prevent impacted soil vapor from entering building indoor air. Additionally, worked with the NWNMCOG and NMED to investigate impacts to groundwater in the immediate area surrounding the site and determined that PERC was present in several off-site areas. INTERA is currently working with NMED and the responsible party to determine the vertical and lateral extent of the PCE groundwater plume and determine remedial options.

4407 Lomas Boulevard Site Investigation, Parnell Lomas, Albuquerque, NM. 2012. *Project Manager.* Led a Phase II Site Investigation at this site to determine if former operations as a gasoline service station had negatively impacted soil, soil vapor, or groundwater. The site included an office building and the client was trying to decide whether to purchase the property. After the investigation, it was determined that the site had not been negatively impacted by former operation as a gasoline service station, but that soil vapor was impacted with PCE, most likely from off-site historical dry cleaners. It was concluded that PCE could enter the current office building at levels above EPA screening levels. A proposal was prepared for a vapor mitigation system. Client decided not to purchase the property due to the cost of implementing the vapor mitigation system and associated ongoing monitoring.

Former Tulip Drive Landfill Phase I ESA and Phase II Site Investigation Activities, Luna County, Deming, NM. 2010 – 2012. *Project Manager.* Served as INTERA's Project Manager for the performance of a Phase II ESA performed at the 75-acre tract of land, including the Former Tulip Drive Landfill, located in Deming, Luna County, New Mexico. The Phase II ESA was performed for the county and city using funds provided by the EPA Brownfields Assessment Grant Program. Responsible for the development of a site-specific SAP, which guided field activities. The site was a vacant tract of land owned by the city located southeast of the intersection of New Mexico Highway 26 and U.S. Highway 180, along the Mimbres River. It was the city's and county's intent to redevelop the site as recreational open space; therefore, the objective of the Phase II ESA was twofold: (1) obtain additional information regarding the character of the former Tulip Landfill, such as cover thickness, depths and types of waste, and the extent of the former Tulip Landfill area, and (2) determine if soil and/or groundwater impacts exist from the recognized environmental concerns identified as part of the Phase I ESA completed by INTERA in 2011. INTERA conducted the following Phase II ESA field activities in 2012: (1) investigative excavation of 15 test pits located within the footprint of the former Tulip Drive Landfill, (2) hollow-stem auger (HSA) drilling and sampling of eight shallow exploratory soil borings, (3) HSA drilling and sampling of three deep soil borings, (4) installation and development of three

groundwater monitoring wells (within the deep soil borings), and (5) a single groundwater sampling event. Due to only minimal exceedances of applicable standards in site soil and no exceedances in site groundwater, recommended proceeding with site development upon completion of the following additional remediation/characterization activities:

- Consolidation of the numerous surface litter and debris piles scattered through the vacant lot to within the confines of the former Tulip Drive Landfill
- Preparation of preliminary design and installation of an evapotranspirative cap over the consolidation area to (a) minimize exposure to potentially harmful waste and (b) stabilize waste to deter further offsite transport of site contaminants via surficial processes (i.e., storm water, wind)
- Provision of bank stabilization and erosion control of property land located along the Mimbres River to mitigate the negative effects of progressive undercutting by seasonal surficial processes and help minimize future transport of site contaminants off-site
- Securing the site to prevent future indiscriminate dumping
- Installation of at least one additional ground water monitoring well in the northeast corner of the site to confirm groundwater remained unimpacted by the presence of the landfill
- Completion of one or more additional groundwater sampling events to further assess and monitor groundwater site conditions
- Completion of all additional site remediation/characterization efforts through participation in the NMED VRP.

Hotel La Posada de Albuquerque Redevelopment, City of Albuquerque, NM. 2007 – 2011. *Project Manager.* Developed a QAPP and asbestos specifications for the removal of asbestos from the Hotel La Posada de Albuquerque. Also developed an EE/CA that evaluated the remediation options for the renovation of this historic hotel. Significant quantities of asbestos and lead-based paint were present within La Posada. The EE/CA was used to support the use of the COA Brownfields Cleanup Revolving Loan Fund for a portion of the remediation. Through the EE/CA report, documented the alternative selection process for a non-time-critical removal action that was completed in accordance with 40 CFR 300.415 of the National Oil and Hazardous Substances Pollution Contingency Plan. The Hotel La Posada de Albuquerque was successfully remediated, renovated, and reopened as the Andaluz Hotel in October 2009. Prepared a self-certification document in 2011 that was submitted to the EPA for the voluntary remediation conducted at this building. Site was renamed the "Hotel Andaluz."

Casa Grande Property/El Vado Hotel Phase I Environmental Site Assessment, and Phase II Site Investigation, City of Albuquerque, NM. 2009 – 2010. *Project Manager.* Led an environmental evaluation of the Casa Grande Property on behalf of the COA. The COA proposed redeveloping the Casa Grande Property/El Vado Hotel located at 2500 Central Avenue with mixed use development (residential/commercial) and contracted INTERA to perform a National Environmental Policy Act (NEPA) Environmental Assessment, a Phase I ESA, and a Phase II Site Investigation at the site. The Phase I ESA and Phase II Site Investigation were performed with support from other key INTERA staff members. The Phase I ESA identified a historical property use (gasoline pumps at the El Vado Hotel) and a historic gasoline release at the Casa Grande Chevron located across the street as potential recognized environmental conditions and recommended subsurface soil borings as well as a geophysical investigation be completed at the property. Eight subsurface soil borings were completed at the site in areas believed to have been potentially impacted by historical property and area uses. No impact from petroleum hydrocarbons in soils and/or groundwater was identified. In addition, the geophysical investigation, conducted by Sunbelt Geophysics, did not identify any evidence of abandoned USTs at the site.

Managed the completion of a NEPA Environmental Assessment at the site as prescribed by the lead federal agency, which in this case was the Department of Housing and Urban Development. The EA was completed with support from Parametrix (cultural and biological surveys). The ESA was required to release Community Development Block Grant funds for the property purchase and additional property redevelopment work.

New Mexico Rail Runner Site Assessments, Parsons Brinckerhoff Quade & Douglas, Santa Fe, NM. 2006 – 2009. *Project Manager.* INTERA was retained by Parsons Brinckerhoff Quade & Douglas (PB) in 2006 to perform ISAs for Phase 2 of the Mid-Region Council of Governments/ NMDOT Belen to Santa Fe New Mexico Rail Runner Express Commuter Rail Project. Performed an ISA for the existing BNSF railroad line from Bernalillo to Lamy, New Mexico, and an ISA for the proposed commuter rail line from La Bajada Hill to downtown Santa Fe, New Mexico. Acted as the designated INTERA Project Manager for each ISA

project. The ISA included the assessment of existing railroad lines and facilities (BNSF and Santa Fe Southern), as well as several miles of railroad tracks constructed on undeveloped ranch land to facilitate commuter rail service between Albuquerque and Santa Fe. Project management duties included developing and implementing the schedule for the records reviews, field reconnaissance, and report development. Led field activities for each ISA (the combined assessment length of the two ISA totals over 70 miles) and coordinated with the PB Project Manager, the NMDOT Environmental Geology Section representatives, and NMDOT legal counsel with the finals of each ISA Report. The New Mexico Rail Runner Express began operations in 2009.

Landfill Gas Assessment of Five Formerly City-Owned and/or Operated Landfills, New Mexico Environmental Health Department, Albuquerque, NM. 2003 – 2009. *Contract Manager and Project Manager.* Contract Manager for INTERA's COA landfill gas assessment project. Over 100 landfill gas monitoring wells have been installed to monitor landfill gas migration at five of the COA formerly owned and/or operated solid waste landfills under direction. Managed the landfill gas monitoring well installation and supervised landfill gas sample collection. Other duties conducted include contract budget tracking, future landfill gas monitoring well locating, and landfill gas sample results interpretation. Developed the current COA landfill gas well installation report format as well as the format used for the landfill gas monitoring reports. Also developed landfill management plans to guide development on and adjacent to the former Eubank and San Antonio landfills.

Former Peru Hill Mill Site Phase I Environmental Site Assessment and Phase II Site Investigation and Remediation, New Mexico Environment Department, Deming, NM. 2001 – 2008. *Project Manager.* Performed a Phase I ESA and Phase II Site Investigation of the former Peru Hill Mill mining mill facility in Deming, New Mexico. The Peru Hill Mill primarily processed zinc sulfide ore. Peru Mining Company, a subsidiary of Illinois Zinc Company, constructed the Peru Hill Mill and operated it from 1928 to 1967. Barite of America acquired the facility in 1979 and operated it intermittently until 1985, when the company filed for bankruptcy. Luna County acquired the property in 2001 and deeded it to the City of Deming. The major environmental concerns at the site were uncontained tailings in a 104-acre impoundment and redistributed tailings transported from the impoundment by wind erosion and surface water runoff. The tailings formed dunes around the impoundment that blanketed an area of approximately 161 acres. The total area of the tailings impoundment and redistributed tailings was approximately 265 acres.

Prior to initiating the site investigation, a Phase I ESA was completed at the site. Used the results of the Phase I efforts to complete a work plan and QAPP for the Phase II Site Investigation. Soil sampling results indicated lead, arsenic, and zinc concentrations in surficial soils were in excess of NMED soil screening levels (SSLs). Recommended that surficial soils containing metals concentrations above SSLs be placed within a site tailings impoundment area and that the tailings be capped with soil to prevent further migration by wind and/or water erosion. Secured an engineering firm to design the tailings impoundment cap and a soil consolidation plan. Prior to implementation, the City ultimately used the Phase I ESA report and the information in the site investigation report to submit a VRP application to NMED.

Excavation activities were completed by the City and the tailings were excavated and redistributed to the designated tailings impoundment area. Helped develop a confirmation soil sampling plan to assure that the tailings removal effort was successful. Directed Neptune and Company (subcontractor) in the development of a site-specific remedial action goal for arsenic at the site. Remediation efforts were completed according to plan at Peru Hill Mill and a VRP Completion Report was developed for this facility in 2008. The site received a Conditional Certificate of Completion from VRP in 2009.

Plaza Del Sol Property Site Investigation, City of Albuquerque, NM. 2001 – 2008. *Project Manager.* Led the investigation of this Brownfields redevelopment site, which was believed to be impacted by a historic petroleum hydrocarbon release in the local area. Investigation activities included the preparation of a Phase I ESA, installation of monitoring wells, and groundwater sample collection. Completed additional work at this site on behalf of the COA and private developers in 2008 and developed a VRP Completion Report for the site. The site received a Certificate of Completion from the NMED VRP in 2008 and has since been developed with residential housing.

City of Santa Fe Railyard (including Phillips Petroleum) Brownfields Investigation, City of Santa Fe/New Mexico Environment Department, NM. 2000 – 2008. *Project Manager.* Led several stages of work completed at the City of Santa Fe Railyard for either the City of Santa Fe or the NMED. The work included the development of a Phase I ESA for a 33-acre portion of the site, a preliminary evaluation of groundwater impacts, a subsurface soil clean-up of tar, and the development of a VRP Completion Report. The Phase I ESA focused on identifying more fully potential responsible parties so that the City could consider this information in its Brownfields redevelopment strategies. The City development plan was to redevelop the underutilized

railyard with a railyard park to include open space and trails, green space, and a farmer's market area. A VRP Application and Work Plan were developed by the City and the site was accepted into the VRP.

Construction at the site began in 2006, and tar was discovered in subsurface soils during archaeological excavation work being conducted at the site. Provided the planning and oversight of the removal of subsurface soil containing tar at the site in 2006 and 2007. Developed a report which was submitted to NMED documenting the tar removal activities completed on behalf of the City.

Performed a Phase I ESA at the Phillips Petroleum site, which is located within the Santa Fe Railyard. Completed a VRP application and developed a work plan to address petroleum hydrocarbon contamination in surface soils located at the Phillips Petroleum site. The work plan included additional groundwater monitoring, but no other work was recommended. The Phillips Petroleum site was incorporated into the Santa Fe Railyard Certificate of Completion once the VRP Completion Report was developed and submitted. After receiving a NMED VRP Certificate of Completion and Covenant Not to Sue, this site is now completely redeveloped.

Tender Loving Care Cleaners Phase I Environmental Site Assessment, New Mexico Department of Transportation, Belen, NM. 2006. *Project Manager.* Conducted a Phase I ESA at the former Tender Loving Care (TLC) Dry Cleaning facility located in Belen, New Mexico. Conducted the Phase I ESA to meet the assessment and EPA AAI requirements of the ASTM Standard E1527-05, "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process" and the reporting requirements of the NMDOT 1999 Hazardous Waste Assessment Handbook. The site operated as a dry cleaner under the name "Sunshine Cleaners" from 1987 to 1990 and as TLC Cleaners from approximately 1990 to 1997. NMED conducted a Phase II Site Investigation at the facility and determined that chlorinated solvent contamination was present in subsurface soils and groundwater. The Phase I ESA developed recommended additional sampling to delineate the extent of soil and groundwater contamination. NMDOT ultimately decided not to acquire the property for use as a New Mexico Rail Runner stop.

Former Hillcrest Hospital Facility Site Characterization, New Mexico Environment Department, Silver City, NM. 2004 – 2006. *Project Manager.* Managed the characterization of an abandoned hospital building proposed to be redeveloped as a library. The site characterization included the evaluation of the building for the presence of asbestos and lead-based paint. Additional work included the characterization of site soils for asbestos contamination as well as excavations completed to find an abandoned petroleum storage tank. Developed the QAPP to guide sampling to adequately characterize the facility. Prepared the integrated work plan for the remedial efforts and assisted the Town of Silver City in the selection of a remediation contractor. Managed the remediation work which included asbestos and lead-based paint abatement, as well as a clean-up for pigeon droppings. After successful remediation, the building was demolished and the site was considered ready for redevelopment.

Proposed Rio Grande Silvery Minnow Sanctuary, U.S. Department of Interior - Bureau of Reclamation, Albuquerque, NM. 2005. *Project Manager.* Served as the project manager for a Phase II site investigation evaluating a proposed site for use as a minnow sanctuary. Developed the work plan and provided oversight for the field work consisting of soil, subsurface soil, surface water, and groundwater sampling. Performed an additional site investigation using biological testing of fish to further evaluate the site for suitability as a minnow sanctuary. The site was ultimately selected by the Bureau of Reclamation for the location of the Rio Grande Silvery Minnow Sanctuary.

Phase II Site Investigation and Soil Remediation Activities at Former Araho Well Injection Disposal Facility, New Mexico Oil Conservation Division, Lovington, NM. 2003 – 2005. *Project Manager.* Managed a Phase II site investigation and subsequent soil remediation activities at a former well injection facility. Evaluated the site for the presence of petroleum hydrocarbons and chloride content in soil and then developed a work plan for remediation. Supervised the soil remediation efforts including soil excavation, transportation, and disposal and the subsequent placement of clean fill. Assisted engineers in the development of a cap for the site and provided oversight for the cap construction.

Former San Antonio Landfill Phase II Site Investigation, City of Albuquerque, NM. 2002 – 2003. *Project Manager.* Led a geophysical investigation at the former San Antonio Landfill on behalf of the COA and NMED to determine the volume of waste and thickness of cover at the site. The landfill consisted of approximately 42.5 acres in northeast Albuquerque in an area that was once on the outskirts of town but later became a residential and commercial area. Owned partially by the COA and partially by private landowners, the landfill reportedly accepted municipal waste from 1968 until 1970, at which time it was

capped and informally closed. Data from the geophysical survey provided enough evidence to conclude that the depth of soil cover across the San Antonio Landfill ranged from 2 to 6 feet. Based on the geophysical evidence of the thickness of the soil cover, it was determined it was very unlikely that landfill-related waste was present in surface soils at the site. The results of this investigation were subsequently used several times to help the COA guide development work on and near the former landfill.

Voluntary Remediation Program Assistance (Brownfields Awareness), New Mexico Environment Department, Santa Fe, NM. 2002. *Project Manager.* Managed a NMED project to increase awareness of the number of brownfields sites within New Mexico and the funding assistance available to New Mexico municipalities for brownfields site investigation and remediation. Project included extensive file review, database management, and coordination of a conference for public and private sector representatives. Consistent interaction with the VRP manager and VRP staff was essential to complete this task.

Historic Waterworks Property Site Investigation, New Mexico Environment Department, Silver City, NM. 2002. *Project Manager.* Led investigation to characterize site for inclusion in the state VRP. Site characterization activities included surface soil sampling, soil boring installation, subsurface soil sampling, and groundwater sample collection. In addition, asbestos and lead-based paint sampling were conducted in the historic building located on the site. Site characterization activities required interaction with NMED and the State Historic Preservation Officer.

Old Silver City Landfill Site Investigation, Town of Silver City, NM. 2000 – 2002. *Project Manager.* Led a Phase II Site Investigation of the closed municipal waste landfill known as the Old Silver City Landfill on behalf of the Town of Silver City and the NMED in 2000. The landfill operated from 1968 to 1993 and was historically used by the Town of Silver City and Grant County residents and businesses. The landfill was unlined and placed over arroyos and suspected to be serving as a source for methane gas and groundwater contaminants. Performed an evaluation of potential sources for chlorinated solvents in the vicinity of the landfill that might have been related to groundwater contamination in the area. This task was completed by collecting surface soil samples at an onsite machine shop; subsequent analysis of these samples showed the machine shop was not a source of the contamination.

In addition, the Town of Silver City and NMED asked for an evaluation of viability of harnessing the methane gas from the landfill for energy purposes to be conducted. As a first stage of this work, performed a site reconnaissance of the landfill with landfill engineers, collected landfill gas samples, and reviewed all the available existing records on disposal history and methane gas detection. This information was used to estimate the landfill gas volume and methane concentration using industry-accepted methods. It was determined that there was not enough landfill gas available to provide a viable energy source.