Phase I Environmental Site Assessment

New Method Cleaners

1911 St. Michaels Drive

Santa Fe, New Mexico

Prepared for:

New Mexico Environment Department
Groundwater Quality Bureau
1190 S. St. Francis Drive
Santa Fe, NM 87505

Prepared by:

INTERA Incorporated
2440 Louisiana Boulevard SE, Suite 700
Albuquerque, NM 87110
505.246.1600

JUNE 5, 2026

Executive Summary

This report documents the methods, findings, opinions, and conclusions of a Phase I Environmental Site Assessment (ESA) performed by INTERA Incorporated (INTERA) for New Method Cleaners, 1911 St. Michaels Drive in Santa Fe, New Mexico (Site/Subject Property) (**Figure 1**). The New Mexico Environment Department (NMED) Ground Water Quality Bureau (GWQB) (User) is using its Professional Services Contract #24-667-2030-27724, Work Order Number INTE08-ROS-21, to contract the performance of a due diligence assessment of the Subject Property. The Phase I ESA was conducted to document current and former conditions relative to historical operations at the Site.

INTERA performed this Phase I ESA following the procedures of Standard Practice E1527-21 of ASTM International (ASTM), entitled *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process* (ASTM, 2021). The objective of the Phase I ESA was (1) to identify, to the extent possible, any *recognized environmental conditions* (RECs) as defined by the ASTM and (2) to collect reasonably ascertainable information about the environmental condition of the Subject Property. Additionally, based on reviews of Subject Property, adjoining properties, and vicinity properties' findings within the default *area of concern* (AOC) as defined by ASTM Standard E2600-22, *Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions* (ASTM, 2022), *vapor encroachment conditions* (VECs) were also assessed for the migration potential of hazardous substances and/or petroleum products within or near the Subject Property.

The Subject Property is located in a multi-unit development made up of five land parcels with the same address totaling 0.27 acres. The Subject Property parcel (Suite A) is approximately 0.11 acres located on the southeast corner of the multi-unit development. The Subject Property is located in a commercial area, with a residential area to the north. Based on review of historical records, the Subject Property has been operated as a dry cleaning facility since approximately 1988. The current owner indicated that the halogenated solvent equipment was replaced with non-halogenated solvent equipment in 2000, when the current ownership began. The immediate vicinity of the Subject Property is depicted in **Figure 2**.

The Phase I ESA included:

- a review of the Subject Property and adjoining properties' historical and current land use records,
- review of standard environmental regulatory agency records,
- a site reconnaissance, and
- interviews with individual(s) having knowledge of past and/or present uses of the Subject Property.

These activities were performed to assess sources of surface and subsurface contamination that potentially exist at the Subject Property and within ASTM-specified distances from the Subject Property. This information was integrated with the physical setting data and future occupancy or development plans for the Subject Property to form an opinion concerning whether properties found to be a potential source of contamination may, in fact, be a REC with regard to the Subject Property, as defined by ASTM.

The Phase I ESA was performed by environmental professional(s) as defined in 40 Code of Federal Regulations (CFR) §312.10 and as identified in this report.

INTERA has performed a Phase I ESA in conformance with the scope and limitations of ASTM Standard E1527-21 for the Subject Property. Based on the completion of the scope of services provided in support of this Phase I ESA, one REC/VEC was identified in connection with the Subject Property, and one REC associated with an adjoining property as follows:

- Approximately 12 years (1988-2000) of dry cleaning operations conducted at the Subject Property using tetrachloroethylene (PCE)-based solvents is considered a **REC/VEC** in connection with the Subject Property.
- Potential contaminant impacts due to vehicle maintenance/repair activities on the adjoining car dealership property, and a potential historical environmental investigation/sampling effort, as indicated by the New Method Cleaners owner, is considered a **REC/VEC** in connection with the Subject Property.

Based on the conclusions of this Phase I ESA, INTERA recommends the following:

- Perform a Phase II investigation to assess the potential impacts to environmental media from the RECs identified in connection with the Subject Property.

Table of Contents

1.0 Introduction 1
1.1 Purpose 1
1.2 Detailed Scope of Services 1
1.2.1 Vapor Encroachment Considerations 2
1.2.2 Non-Scope Environmental Considerations 3
1.3 Significant Assumptions 3
1.4 Limitations and Exceptions 4
1.5 Special Terms and Conditions 4
1.6 User Reliance 4
2.0 Site Description 6
2.1 Location and Legal Description 6
2.2 Site Vicinity and General Characteristics 6
2.3 Physical Setting 7
2.3.1 Topography and Watershed 7
2.3.2 Average Precipitation and Temperature 7
2.3.3 Flood Plain 7
2.3.4 Soil Characterization 7
2.3.5 Geology and Hydrogeology 7
2.4 Descriptions and Current Uses of Adjoining Properties 8
3.0 User-Provided Information 9
4.0 Records Review 10
4.1 Historical Use of the Site and Adjoining Properties 10
4.1.1 Chain of Title and Environmental Lien Search 10
4.1.2 Historical Topographic Maps 10
4.1.3 Historical Aerial Photographs 11
4.1.4 Fire Insurance Maps 13
4.1.5 Historical City Directories 13
4.2 Environmental Database Records Review 14
4.2.1 Mapped Locations 14
4.3 Regulatory Agency and Supplemental Records Review 15
5.0 Site Reconnaissance 16
5.1 Methodology and Limiting Conditions 16

5.2 Subject Property 16
5.3 Adjoining Properties 17
5.4 Surrounding Properties 17
6.0 Interviews 18
6.1 Key Site Manager 18
6.2 Local Government Officials 18
7.0 Findings and Opinions 19
7.1 Subject Property Findings and Opinions 19
7.2 Adjoining Property Findings and Opinions 19
7.3 Vicinity Findings and Opinions 20
7.4 Tier 1 Vapor Encroachment Screening 21
7.5 Data Gaps 21
8.0 Conclusions 22
9.0 Recommendations 22
10.0 References 23
11.0 Disclaimer 24
12.0 Qualifications and Signatures of Environmental Professionals 25

List of Appendices

Appendix A Chain of Title and Environmental Lien and Activity and Use Limitation Search
Appendix B Historical Topographic Maps
Appendix C Historical Aerial Photographs
Appendix D Physical Setting Documentation
Appendix E User Provided Information [RESERVED]
Appendix F Historical Fire Insurance Maps
Appendix G Historical City Directories
Appendix H Database Report
Appendix I Supplemental Records
Appendix J Photograph Log
Appendix K Interviews
Appendix L Qualifications of Environmental Professionals

List of Figures

Figure 1 Site Location
Figure 2 Site Plan

List of Tables

Table 1. Summary of Subject Property Tax Parcel(s) Information 6
Table 2. User-Provided Information 9
Table 3. City Directory Listings 13
Table 4. File Review Information 14

Acronyms and Abbreviations

AAI	All Appropriate Inquiry
AMSD	approximate minimum search distance
AOC	area of concern
ASTM	American Society for Testing and Materials International
AUL	Activity and Use Limitation
bgs	below ground surface
CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act
CFR	Code of Federal Regulations
COC	chemical of concern
EPA	United States Environmental Protection Agency
ERIS	Environmental Risk Information Services
ESA	Environmental Site Assessment
GWQB	Ground Water Quality Bureau
°F	degree(s) Fahrenheit
FIM	fire insurance map
ft	foot or feet
INTERA	INTERA Incorporated
LST	leaking storage tank
msl	mean sea level
NFA	no further action
NMED	New Mexico Environment Department
NMOSE	New Mexico Office of the State Engineer
NOAA	National Oceanic and Atmospheric Administration
PCB	polychlorinated biphenyl
PCE	tetrachloroethylene
POD	Point of Diversion
RCRA	Resource Conservation and Recovery Act
REC	Recognized Environmental Condition
SFCA	Santa Fe County Assessor
Site or Subject Property	New Method Cleaners,1911 St. Michaels Drive, Santa Fe, NM

User	NMED Ground Water Quality Bureau
USGS	United States Geological Survey
UST	underground storage tank
VEC	Vapor Encroachment Condition
VES	Vapor Encroachment Screening
VRP	Voluntary Remediation Program

1.0 Introduction

INTERA Incorporated (INTERA) under contract with the New Mexico Environment Department (NMED) Ground Water Quality Bureau (GWQB) (User), was tasked to perform a Phase I Environmental Site Assessment (ESA) of the property located at 1911 St. Michaels Drive, Santa Fe, New Mexico 87505 (New Method Cleaners), hereafter referred to as the Site or Subject Property (Santa Fe County Assessor [SFCA], 2026). The location of the Subject Property is illustrated in **Figure 1**.

The User is funding consultant resources from its Professional Services Contract #24-667-2030-27724, Work Order Number INTE08-ROS-21, to document current and historical conditions relative to historical operations at the Site.

1.1 Purpose

This Phase I ESA was performed (1) to identify, to the extent possible, any recognized environmental conditions (RECs), defined below in **Section 1.2**, and (2) to collect all reasonably ascertainable information about the environmental condition of the Subject Property. This was performed, consistent with good commercial and customary practice, to allow potential future redevelopment of the Subject Property and to qualify the User for statutory limitations of potential liability under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), a.k.a. Superfund.

This Phase I ESA was performed to meet the assessment and all appropriate inquiries (AAIs) requirements of American Society for Testing and Materials International (ASTM) Standard E1527-21, *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process* (ASTM, 2021). In 2005, the United States Environmental Protection Agency (EPA) issued *Standards and Practices for All Appropriate Inquiries, Final Rule* (EPA final rule; EPA, 2005), and in 2021 ASTM issued ASTM Standard E1527-21 (ASTM, 2021). Both the EPA final rule and the 2021 ASTM Standard E1527-21 implement the CERCLA as amended by the Small Business Liability Relief and Brownfields Revitalization Act of 2002. Under the EPA final rule, effective November 1, 2006, satisfaction of the CERCLA AAI requirement for liability protection as an innocent landowner, a bona fide prospective purchaser, or a contiguous landowner is met by an assessment conducted in accordance with ASTM Standard E1527-21.

1.2 Detailed Scope of Services

In general, the Phase I ESA scope of services included the following four components:

- Records review;
- Site reconnaissance;
- Interviews; and
- Report.

INTERA has completed a Phase I ESA for the Subject Property in accordance with ASTM Standard E1527-21, with the exception of any deviations listed in **Section 1.4** or data gaps listed in **Section 7.5**.

For the purposes of this Phase I ESA report, the definition of the term "*Recognized Environmental Condition*" is as outlined in Section 3.2.73 of ASTM Standard E1527-21:

> "(1) the presence of *hazardous substances* or *petroleum products* in, on, or at the *subject property* due to *release or likely release* to the *environment*; (2) the likely presence of *hazardous substances* or *petroleum products* in, on, or at the *subject property* due to a *release* to the *environment*; or (3) the presence of *hazardous substances* or *petroleum products* in, on, or at the *subject property* under conditions that pose a *material threat* of a future *release* to the *environment.*" (ASTM, 2021, p. 8)

For the purposes of this Phase I ESA report, the definition of the term "*Historical Recognized Environmental Condition*" is as outlined in Section 3.2.39 of ASTM Standard E1527-21:

> "A previous *release* of any *hazardous substances* or *petroleum products* affecting the *subject property* that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the *subject property* to any controls (for example, *activity and use limitations* or other *property use limitations*). A *historical recognized environmental condition* is not a *recognized environmental condition*." (ASTM, 2021, p. 6)

For the purposes of this Phase I ESA report, the definition of the term "*Controlled Recognized Environmental Condition*" is as outlined in Section 3.2.17 of ASTM Standard E1527-21:

> "*A recognized environmental condition* affecting the *subject property* that has been addressed to the satisfaction of the applicable regulatory authority or authorities with *hazardous substances* or *petroleum products* allowed to remain in place subject to the implementation of required controls (for example, activity and use limitations or other property use limitations)." (ASTM, 2021, p. 4)

An additional term related to this Phase I ESA report is "*de minimis condition.*" It is defined by Section 3.2.20 of ASTM Standard E1527-21 as:

> "a condition related to a *release* that generally does not present a threat to human health or the *environment* and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. A condition determined to be a *de minimis condition* is not a *recognized environmental condition* nor a *controlled recognized environmental condition.*" (ASTM, 2021, p. 4-5)

1.2.1 Vapor Encroachment Considerations

ASTM Standard E1527-21 requires the assessment of the migration potential of hazardous substances and/or petroleum products within or near the Subject Property.

The definition of the term "*migrate/migration*" is outlined in Section 3.2.53 of ASTM Standard E1527-21:

> "…the movement of *hazardous substances* or *petroleum products* in any form, including, for example, solid and liquid at the surface or subsurface, and vapor in the subsurface." (ASTM, 2021, p. 7)

Vapor migration in the subsurface is described in ASTM Standard E2600-22, *Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions* (ASTM, 2022); however, ASTM Standard E1527-21 does not require its application to achieve compliance with AAI (ASTM, 2021, p. 7).

In order to assess potential migration of hazardous substances and/or petroleum products that may migrate as vapors into the vadose zone as a result of contaminated soil and/or groundwater on or near the Subject Property, INTERA has completed a Tier 1 Vapor Encroachment Screening (VES) in accordance with ASTM Standard E2600-22 for the Subject Property. The objective of the VES is to determine if a vapor encroachment condition (VEC) exists at the Subject Property. For the purposes of this Phase I ESA report, the definition of the term "*Vapor Encroachment Condition*" is as outlined in Section 3.2.37 of ASTM Standard E2600-22:

> "[The] presence or likely presence of [chemical of concern (COC)] vapors in the vadose zone of the [Subject Property] caused by the release of vapors from contaminated soil and/or groundwater either on or near the [Subject Property]…" (ASTM, 2022, p. 4)

The results of the Tier 1 VES are presented in **Section 7.4.**

1.2.2 Non-Scope Environmental Considerations

Non-scope environmental considerations such as those identified in Section 13.1.5 of ASTM E1527-21 were not evaluated as part of this ESA. Non-scope considerations may include, but are not limited to: presence of potential asbestos-containing building materials unrelated to releases into the environment; biological agents; cultural and historic resources, ecological resources; endangered species; health and safety; indoor air quality unrelated to releases of hazardous substances or petroleum products into the environment; industrial hygiene; presence of potential lead-based paint unrelated to releases into the environment; lead in drinking water; mold or microbial growth conditions; polychlorinated biphenyl (PCB)-containing building materials; naturally-occurring radon; regulatory compliance; substances not defined as hazardous substances (including some substances sometimes generally referred to as emerging contaminants) unless or until such substances are classified as a CERCLA hazardous substance; and wetlands (ASTM, 2021, p. 25).

1.3 Significant Assumptions

Significant assumptions pertaining to this Phase I ESA are briefly summarized as follows:

- Environmental database information (and facility locations) generated by Environmental Risk Information Services (ERIS) is accurate and complete;
- The User has provided INTERA with all the information in its possession that would help determine the presence of RECs;
- Interview information provided to INTERA by various parties and individuals is accurate and was provided without bias; and
- Publicly available reasonably ascertainable information accessed by INTERA is accurate and complete.

The significant assumptions underlying the preparation of any Phase I ESA are specified in the principles set forth by ASTM Standard E1527-21. The principles are presented in their entirety in Section 4.5 of ASTM Standard E1527-21 (ASTM, 2021, p. 10).

1.4 Limitations and Exceptions

Any Phase I ESA is by nature limited and qualitative in scope, being based predominantly on the examination of selected maps, agency records, interviews, and visual and/or physical observations made during the site reconnaissance. As such, this Phase I ESA should not be construed to be a complete characterization of environmental regulatory compliance of conditions above or below ground surface (bgs) at the Subject Property. Instead, the ESA process is designed to provide information regarding apparent existing or potential adverse environmental conditions related to the Subject Property in accordance with good commercial and customary practice. Any significant data gaps that would further limit the scope of the Phase I ESA are identified in **Section 7.5**.

This Phase I ESA is limited to the reasonably ascertainable information available or known to INTERA as of the date of this report. Consistent with ASTM Standard E1527-21, no intrusive testing or sampling of concealed or subsurface conditions was performed at the Subject Property as part of this Phase I ESA. The findings, opinions, and conclusions contained in this report are limited to those that could be identified during the Phase I ESA performed in accordance with ASTM Standard E1527-21. INTERA has accepted as true the information provided by interviewees on current and historical uses of the Subject Property and surrounding area. INTERA does not warrant or guarantee the accuracy or completeness of information provided by other sources.

INTERA represents that the Phase I ESA was performed in a competent manner by environmental professionals, consistent with the practices and procedures contemplated under ASTM E1527-21. However, even with proper application of the ASTM methodology, environmental conditions may be present that cannot be identified within the scope of the Phase I ESA or that may not be reasonably identifiable from the available information. As such, no warranty is expressed or implied as to the findings, conclusions, and/or recommendations presented in this Phase I ESA report beyond matters amenable to empirical review and visual confirmation within the limits under ASTM E1527-21 and/or the specified scope of work.

1.5 Special Terms and Conditions

Since a property transaction was not part of the rationale for conducting the Phase I ESA, some of the discussion related to purpose, liability protection, and User reliance herein may not be relevant. This language is included for consistency and transparency of describing the intention of the Phase I ESA to meet the ASTM Standard.

1.6 User Reliance

This Phase I ESA has been prepared for the use of the User. There are no third-party rights or benefits conferred under this report. Use of or reliance on this Phase I ESA report by any third party is at the sole risk of that party.

This Phase I ESA is valid for 180 days prior to acquisition of the Site and/or transactions not involving acquisition of the Site. In accordance with the ASTM Standard, if the Phase I ESA is to be used by a different user other than the intended user within the 180 days, then the new user must satisfy the requirements in Section 6 of ASTM E1527-21. The Phase I ESA can be valid for longer if the Phase I ESA has been updated within one year of the date of acquisition or intended transaction, provided that the following components have been completed within 180 days of the acquisition or transaction: interviews; searches for recorded environmental cleanup liens; review of federal, tribal, state, and local government records; visual inspection of the property and of adjoining properties; and the declaration by the environmental professional responsible for the assessment or update (ASTM, 2021, p. 11).

2.0 Site Description

As required by ASTM Standard E1527-21, INTERA gathered information concerning the location, characteristics, current land uses, and physical improvements of the Subject Property, adjoining properties, and vicinity properties. Sources for this information were United States Geological Survey (USGS) 7.5-minute historical topographic maps, geologic and hydrologic publications, aerial photographs, observations made during the site reconnaissance, interviews, and consulting other publicly available information.

The Subject Property is located in a multi-unit development made up of five land parcels with the same address totaling 0.27 acres. The subject Property parcel (Suite A) is approximately 0.11 acres located on the southeast corner of the multi-unit development. The Subject Property is located in a predominantly commercial area. Adjoining properties are described in **Section 2.4**. The Site and immediate vicinity thereof are depicted in **Figure 2**.

2.1 Location and Legal Description

The Subject Property is composed of five Santa Fe County land parcels totaling 0.11-acres in Santa Fe, New Mexico. General real estate property tax information was gathered from the SFCA Department website for the Subject Property, summarized below in **Table 1** (SFCA, 2026).

Table 1. Summary of Subject Property Tax Parcel(s) Information

Address	1911 St. Michaels Dr. A, Santa Fe, NM 87505
Owner Name	Ortega, Ben & Helen Revoc Trust
Parcel No.	19102704
Legal Description	1: UNIT A LOS ORTEGAS CONDOS T17N R 9E S34
Size (acres)	0.1057
Deed Date	12/31/2018
Instrument	1875968

An Environmental Lien and Activity and Use Limitation (AUL) search was performed for the Subject Property parcel for the current owner. No environmental liens or AULs were identified for the Subject Property in the Lien Search Report (ERIS, 2026a – **Appendix A**).

2.2 Site Vicinity and General Characteristics

ASTM Standard E1527-21 specifies that the only standard physical setting source that must be checked during the Phase I ESA is the current USGS 7.5-minute topographic map (or equivalent). Other physical setting sources used for this Phase I ESA were historical topographic maps (ERIS, 2025b – **Appendix B**) and historical aerial photographs (ERIS, 2025c – **Appendix C**), discussed in **Section 4**.

2.3 Physical Setting

Several sources were reviewed to determine the physical setting of the Subject Property. Information from published physical settings maps (ERIS, 2024d – **Appendix D**) are discussed in the following subsections.

2.3.1 Topography and Watershed

The most recent (2022) USGS 7.5-minute topographic map of the site area was obtained and reviewed as specified in ASTM Standard E1527-21 Section 8.2.1 (ASTM, 2021). The USGS Santa Fe, NM quadrangle provides coverage of the Subject Property and vicinity (USGS, 2022). Historical topographic maps were reviewed for surface topography and drainage information in the vicinity of the Subject Property, and are provided in **Appendix B**.

According to the topographic maps, the Subject Property is relatively flat, with a surface elevation of approximately 6845 feet (ft) mean seal level (msl). The topography in the area slopes gently to the west, towards an ephemeral channel called Acequia de los Pinos. This acequia continues to the southwest and eventually joins the Santa Fe River, which is also ephemeral in this section. The Santa Fe River drains into the Rio Grande approximately 25 miles downstream to the southwest. The site topography was confirmed during the site reconnaissance (**Section 5**). Surface drainage at the Subject Property follows the surface topography (**Figure 1**).

2.3.2 Average Precipitation and Temperature

The average annual precipitation in Santa Fe, New Mexico is approximately 13.69 inches per year. Most of the precipitation historically occurs in July. The greatest average temperature historically is in July at 72.2 degrees Fahrenheit (°F), the lowest average temperature historically is in January at 31.6 °F (National Oceanic and Atmospheric Administration [NOAA], 2026).

2.3.3 Flood Plain

The Subject Property is outside of the FEMA 100- and 500-year floodplains (ERIS, 2025d – **Appendix D**).

2.3.4 Soil Characterization

The soil map provided by ERIS was reviewed to identify local surface soils underlying the Site. Soils underlying the Subject Property are solely composed of urban land, a miscellaneous categorization for highly developed areas. Several other minor soil components make up roughly 15% of the composition of the underlying soil, but the aggregate soil characteristic is not discernable from the available information (ERIS, 2025d).

2.3.5 Geology and Hydrogeology

The Subject Property is located near the base of the Sangre de Cristo Mountains, the southernmost subrange of the Rocky Mountains. Santa Fe is located on a large system of dissected alluvial fans stretching from the base of the Sangre de Cristos to the bottom of the Rio Grande rift valley. The geologic map provided by ERIS (ERIS 2025d – **Appendix D**) to determine the general geologic setting at

the Subject Property. The geologic maps show that the Subject Property is underlain by the Quaternary upper Santa Fe Group (QTs). Nearby, there are also areas underlain by alluvial fan-type deposits of piedmont alluvial deposits, which are also Quaternary in age. The source of the sediment that makes up this alluvial fan system is primarily the Mesoproterozoic and Paleoproterozoic plutonic bedrock that makes up the Sangre de Cristo Mountains to the east.

The primary source of groundwater in the area of the Subject Property is the series of aquifers within the Santa Fe Group, which is primarily unconsolidated silts, sands, and gravels. ERIS reports a total of 223 water wells within a one-mile radius of the Subject Property. Sources queried included:

- Public Water Systems Violations and Enforcement Data,
- Safe Drinking Water Information System,
- USGS National Water Information System,
- The New Mexico Office of the State Engineer (NMOSE) Point of Diversion (POD) Database.

Of the four wells listed within 1000 ft of the Subject Property, only one lists a depth to water measurement, which is 282 ft bgs (ERIS, 2025d). Although the local shallow groundwater gradient is unknown, groundwater likely flows to the west in this area, following the surface gradient down towards the Santa Fe River.

2.4 Descriptions and Current Uses of Adjoining Properties

The Subject Property is bound by the following properties and rights-of-way:

- A single commercial property across St. Michaels Drive to the south, SFCA parcel No. 10371461, 1234 St. Michaels Drive, occupied by a bank.
- A single commercial property west of the Subject Property, SFCA Parcel No. 19102701, 1911 St. Michaels Drive (Suite B), currently occupied by a Subway sandwich shop.
- A single commercial property to the north, SFCA Parcel No. 19102702, 1911 St. Michaels Drive (Suite C), currently occupied by a church.
- A single commercial property to the east, SFCA parcel No. 12620928, 1955 St. Michaels Drive, currently occupied by a car dealership with potential onsite automotive repair/service.

The Site and immediate vicinity thereof are depicted in **Figure 2**.

3.0 User-Provided Information

During project initiation, the User provided a summary of their knowledge of the Subject Property, summarized below in **Table 2**.

Table 2. User-Provided Information

Site Type	Dry Cleaner
Site Name	New Method Dry Cleaner
Location	1911 St. Michaels Drive
Source of Identification	Historical City Directories for years 1989, 1992, and 2002
Previous Investigations	None
Major Contaminant Concern	Tetrachloroethylene (PCE), trichloroethylene (TCE)

Other than the information provided in **Table 2**, it is INTERA's understanding that the User has no additional knowledge of the Subject Property including those topics outlined in Section 6 of ASTM Standard E1527-21 as the User's responsibilities, summarized as follows:

- The User has no knowledge of any environmental liens or AULs for the Subject Property. However, INTERA has performed a review of land title records and performed a search for environmental liens and AULs on behalf of the User (**Section 4.1.1**).
- The User had no specialized knowledge or experience related to the Subject Property beyond the standard knowledge of an environmental regulatory agency relative to common contaminants associated with dry cleaning operations in general.
- Since a property transaction is not part of the rationale for this Phase I ESA, INTERA did not inquire about the purchase price or fair market value of the Subject Property.
- The User was unaware of any commonly known or reasonably ascertainable information other than what is summarized in **Table 2**, including knowledge of any contamination, spills/releases, or cleanups that have taken place at the Subject Property.
- The User was unaware of any obvious indicators of the presence or likely presence of releases at the Subject Property.
- Any supplemental information relative to the User's responsibilities as defined in Section 6 of ASTM Standard E1521-21 is provided in **Appendix E**.

4.0 Records Review

In accordance with ASTM requirements, INTERA reviewed historical topographic maps and aerial imagery, and standard federal, state, local, and tribal environmental regulatory agency documents. A discussion of records reviewed is provided in the following subsections.

4.1 Historical Use of the Site and Adjoining Properties

INTERA contracted ERIS to search for and provide historical topographic maps, historical aerial photographs, historical city directories, and historical fire insurance maps (FIMs) for the Subject Property and surrounding properties. ERIS also provided environmental lien and AUL search services. INTERA reviewed the historical sources of information to investigate the history of development and prior land uses associated with the Subject Property, adjoining properties, and surrounding area, and to identify past land uses that may indicate that hazardous substances or petroleum products were used. A summary of the historical records reviewed is provided below.

4.1.1 Chain of Title and Environmental Lien Search

INTERA contracted ERIS to perform historical chain of title and environmental lien and AUL search for the Subject Property. ERIS searched county, state, and federal records associated with the Subject Property addresses and parcel identifiers dating back to 1932 for the chain of title and to 1980 for the lien and AUL search.

The Chain of Title Report identified 15 deed conveyances, with the earliest recorded being in 1956. The conveyance details indicated ownership by a tire and supply company between 1969 and 1984, but did not indicate any other new information relative to the use or activities conducted at the Subject Property, including dry cleaning operations. No environmental liens and/or AULs were found (ERIS, 2025a). A copy of the Chain of Title Report and Environmental Lien Report is included in **Appendix A**.

4.1.2 Historical Topographic Maps

INTERA reviewed historical topographic maps provided by ERIS dated 1952, 1961, 1977, 1993, 2002, 2013, 2017, 2020, and 2023 (ERIS, 2025b), which are provided in **Appendix B**. A brief description of the Subject Property and the surrounding area derived from the review of historical and recent topographic maps is provided below.

- 1952:
  - There are no structures on the Subject Property. An unpaved road follows the eastern side of the Site. There is light residential development in the neighborhood to the north.
- 1961:
  - Development surrounding the Subject Property has expanded with more surrounding streets, but there are still no structures onsite. St. Michaels Drive is indicated for the first time, south of the Subject Property.
- 1977:

  - Development of the surrounding area has increased since the previous map, and St. Francis Drive is indicated for the first time, east of the Subject Property. There are still no structures on the Subject Property.
- 1993:
  - A structure is depicted on the Subject Property. Development of the surrounding area continues to increase. Dense development is depicted within the surrounding area.
- 2002:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.
- 2013:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.
- 2017:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.
- 2020:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.
- 2023:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.

4.1.3 Historical Aerial Photographs

INTERA reviewed historical aerial photographs provided by ERIS dated 1935, 1948, 1951, 1960, 1968, 1975, 1981, 1991, 1996, 2005, 2009, 2011, 2014, 2016, 2018, 2020, and 2022 (ERIS, 2025c – **Appendix C**). A brief description of each historical aerial photograph reviewed is provided below**.**

- 1935: Image Resolution – Poor
  - The Subject Property and surrounding area are undeveloped. Cerrillos Road is visible to the northwest, and a railroad is visible to the east.
- 1948: Image Resolution – Poor
  - The Subject Property is still undeveloped. Structures and new arterial streets are now visible north of the Site.
- 1951: Image Resolution – Fair
  - The Subject Property is still undeveloped. More streets have been built, and the streets immediately north of the Subject Property have been laid out, although there is no development observed along them. There is an unimproved dirt road on the west side of the Site.
- 1960: Image Resolution – Good
  - The Subject Property is still undeveloped. The neighborhood directly northwest of the Subject Property is now developed with residences. St. Michaels Drive now appears in the image, south of the Site.

- 1967: Image Resolution – Good
  - The Subject Property is still undeveloped. Development around the Subject Property is denser, mostly to the northwest.
- 1975: Image Resolution – Fair
  - A structure is visible on the Subject Property. St. Michaels Drive appears to be widened. Development surrounding the Subject Property has increased in all directions.
- 1981: Image Resolution – Poor
  - The Subject Property appears unchanged from the previous image. Development in the vicinity continues to fill previously vacant areas.
- 1991: Image Resolution – Fair
  - The Subject Property appears unchanged from the previous image. Development in the vicinity continues to fill previously vacant areas.
- 1996: Image Resolution – Good
  - The Subject Property appears unchanged from the previous image. Development in the vicinity continues to fill previously vacant areas.
- 2005: Image Resolution – Good
  - This is the first full-color image. The Subject Property and vicinity appear relatively unchanged since the previous image, and the entire area covered by the image is now infilled with development.
- 2009: Image Resolution – Good
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2011: Image Resolution – Good
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2014: Image Resolution – Good
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2016: Image Resolution – Excellent
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2018: Image Resolution – Excellent
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2020: Image Resolution –Excellent
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2022: Image Resolution – Excellent
  - The Subject Property and vicinity appear relatively unchanged since the previous image.

4.1.4 Fire Insurance Maps

Historical FIMs can be used to identify historical uses of a property including the presence of hazardous substances and petroleum products. However, no information was found for the Subject Property or adjacent properties (ERIS, 2025e – **Appendix F**).

4.1.5 Historical City Directories

Historical city directories provide a method for researching historical uses of property. INTERA reviewed historical city directories obtained from ERIS to determine current and historical uses of the Subject Property and adjoining properties (ERIS, 2025f – **Appendix G**). ERIS provided historical City Directory Reports for 1700-1925 5th Street and 1700-end of St. Michaels Drive. Additional results may be provided if included on the historical directory pages for the ranges provided by ERIS. ERIS provided results for the years 1928-29, 1930-31, 1936-37, 1940, 1944, 1949, 1955, 1960, 1964, 1968, 1973, 1978, 1983, 1988, 1993, 1996, 2000, 2003, 2008, 2011, 2016, 2020, and 2024. However, 5th Street listings only go as far back as 1955, and St. Michaels Drive listings begin in 1964. The city directory listings that could be reasonably presumed to be commercial or retail properties that may be associated with historical operations utilizing petroleum products (e.g., gas stations) or other hazardous substances (e.g., dry cleaners or manufacturing facilities) are as follows:

Table 3. City Directory Listings

Address	Property Listing(s) (Year(s))
1700 St. Michaels Drive	Llano/St. Michaels/Brewer/Graham's Chevron (2024, 2020, 2016, 2011, 2008, 2003, 2000, 1996, 1993, 1988, 1983, 1978); Royal City Motors (1973)
1701 St. Michaels Drive	Zia Kia (2024, 2020, 2016); Car World Kia / Santa Fe Chrysler Jeep (2011, 2008, 2003, 2000, 1993, 1988); Horace Automotive (2003); Garcia's Julian Plaza Motors (1983, 1978)
1899 St. Michaels Drive	Phillips 66 (2024, 2020); Allsups 344 (2008, 2003, 2000, 1996, 1993); SF Car Company (Jeep) retail auto (1988)
1911 St. Michaels Drive	New Method Cleaners (2024, 2020, 2016, 2011, 2008, 2003, 2000, 1996, 1993, 1988); Santa Fe Tire and Supply Co. (1973)
2005 St. Michaels Drive	Garcia Nissan (2024, 2020, 2016); Hyundai of Santa Fe (2008); Santa Fe Nissan (2003, 2000, 1996, 1993, 1988); Auto Trading Post (1983, 1978)
1955 St. Michaels Drive	Santa Fe Mitsubishi and Hyundai (2003, 1996); Ken John's Auto Mart (1988)
1520 5th Street	Ben's Automotive (1996, 1993, 1988, 1983, 1978, 1973)
1698 St. Michaels Drive	Exxon Service Station (1993, 1988)
711 St. Michaels Drive	Shell Service Station (1988, 1978)
1500 St. Michaels Drive	Sauter Lincoln-Mercury-Toyota (1988, 1983, 1978, 1973, 1968)
854 St. Michaels Drive	Paul's Transmission Specialist (1983)

1704 St. Michaels Drive	Saint Michael's Village Service Station (1983, 1978)
1203 St. Michaels Drive	Hadley JH Oil Station (1978, 1973)

4.2 Environmental Database Records Review

ERIS was contracted to provide a listing of standard environmental records within the ASTM-specified approximate minimum search distance (AMSD) from the Subject Property. ERIS also provides results from non-standard databases that may be relevant with respect to the objective of a Phase I ESA (i.e., without a specified AMSD). ERIS provided results from 104 unique federal, state, and tribal databases using the ASTM-specified AMSD or otherwise relevant search distance for each database. The ASTM-compliant regulatory database report is included as **Appendix H**.

4.2.1 Mapped Locations

Based on 90 total results of the database search, ERIS identified 33 sites (mapped locations) within 1-mile of the Subject Property. Eight of these results were identified for the Subject Property. Many of the sites are identified in multiple databases, some may be identified in the same database more than once, and some may be for former and/or current operations. Findings based on results of select databases that returned significant results that support the objective of the Phase I ESA and opinions of those findings are discussed in **Section 7**. The mapped locations are summarized in **Table 4**. The ERIS Database Report, which describes and shows these facility locations, is included in **Appendix H** (ERIS, 2025g).

Table 4. File Review Information

Database Record[1]	AMSD (miles)	Total Sites Identified	Within AMSD	On Site Property	Data Source
Standard ASTM Environmental Record Resources					
Federal – RCRA VSQG	Subject Property and Adjoining Properties	7	0	0	ERIS
Federal – RCRA Non-Generators	Subject Property and Adjoining Properties	10	2	2	ERIS
State – SCS	1.0	5	5	0	ERIS
State – Delisted SCS	1.0	1	1	0	ERIS
State – SWF/LF	0.5	3	3	0	ERIS
State – LST	0.5	11	11	0	ERIS
State – LUST HIST	0.5	10	10	0	ERIS
State – UST	Subject Property and Adjoining Properties	9	0	0	ERIS
State – UST HIST	Subject Property and Adjoining Properties	10	0	0	ERIS
State – TANKS	Subject Property and Adjoining Properties	9	9	0	ERIS
State – VRP	0.5	4	4	0	ERIS

Database Record[1]	AMSD (miles)	Total Sites Identified	Within AMSD	On Site Property	Data Source
Tribal – INDIAN UST	Subject Property and Adjoining Properties	1	0	0	ERIS
Non-Standard Environmental Records Resources					
Federal – FINDS/FRS	NA	3	NA	3	ERIS
Federal – ICIS	NA	1	NA	1	ERIS
Federal – FED DRYCLEANERS	NA	1	NA	1	ERIS
Federal – ALT FUELS	NA	3	NA	0	ERIS
Federal – AFS	NA	1	NA	1	ERIS
State – SPILLS	NA	1	NA	0	ERIS

Notes:
[1] Full descriptions of the database sources of information can be found in the ERIS Database Report (Appendix H)
[2] One or more mapped locations are listed more than one time

4.3 Regulatory Agency and Supplemental Records Review

If the Subject Property or a property adjoining the Subject Property is identified in a review of standard ASTM environmental records resources, supplemental records review must be conducted (Section 8.2.3.1 of ASTM E1527-21). Unless otherwise specified in **Section 7**, INTERA reviewed supplemental records for the Subject Property and the following adjoining properties:

- New Method Cleaners (1911 St. Michaels Drive, Suite A) identified in the federal Resource Conservation and Recovery Act (RCRA) Non-Generators (NON-GEN) database.

Relevant supplemental records obtained are presented in **Appendix I**. Pertinent references to individual documents are associated with specific findings in **Section 7**.

5.0 Site Reconnaissance

In general, the following was observed during the site reconnaissance to obtain information for the evaluation of RECs in connection with the Subject Property:

- The Subject Property.
- Adjoining properties from the Subject Property boundary and/or the public right-of-way.
- General topography and surface drainage in the vicinity of the Subject Property.

INTERA personnel conducted the site reconnaissance on February 12, 2026. Photographic documentation of the site visit is included in **Appendix J.** Findings documented during the site reconnaissance are summarized in **Section 7** of this report.

Conditions observed are presented below; a check mark in any box indicates that INTERA observed evidence of the item during the Site reconnaissance.

☒ Hazardous substances and/ or petroleum products	☐ Unidentified substance containers	☐ Stressed vegetation
☐ Storage tanks	☐ PCBs	☐ Solid waste
☐ Odors	☒ Drains and Sumps	☒ Utilities/Pipelines
☒ Pools of liquid	☐ Pits, ponds, or lagoons	☐ Wastewater
☒ Drums/Containers	☐ Stained soil or pavement	☐ Wells
☒ Hazardous substance and/or petroleum product containers	☐ Stains or Corrosion	☐ Septic systems

Relevant discussion of the conditions observed, including but not limited to the items identified above, is discussed in the following subsections.

5.1 Methodology and Limiting Conditions

The methodology for the site reconnaissance was based on ASTM Standard E1527-21 (ASTM, 2021). INTERA physically inspected the Subject Property, the adjoining properties to the extent possible from the right-of-way, and the general site vicinity to identify RECs or evidence of RECs as specified in Section 9 of ASTM Standard E1527-21 (ASTM, 2021).

5.2 Subject Property

The Subject Property is located in a multi-unit development made up of five land parcels with the same address totaling 0.27 acres. The subject Property parcel (Suite A) is approximately 0.11 acres located on the southeast corner of the multi-unit development. The Subject Property is located in a predominantly commercial area. The Site and immediate vicinity are depicted in **Figure 2**.

Generally, the Site reconnaissance did not identify any obvious signs of contamination or releases of hazardous substances or petroleum products. The facility appeared clean, and no odors were noted.

Hazardous materials were observed at the Subject Property, stored appropriately in the proper containers and in quantities applicable to their intended and continued use (e.g., chemicals for dry cleaning or general custodial/maintenance purposes). Piping, venting, and other equipment infrastructure associated with the active dry cleaning facility was observed during the reconnaissance and appeared to be maintained in good condition for use. A puddle of water was observed underneath the boiler. Chemical waste from dry cleaning activities is stored outside, in a drum with a locking lid on a concrete pad. The chemical waste drum is transported to an approved disposal facility twice per month, according to the owner (**Section 6.1**).

Photographs taken during the Site reconnaissance are included in **Appendix J**.

5.3 Adjoining Properties

INTERA observed properties from the boundary of the Subject Property and from public rights-of-way to the extent possible. Evidence of petroleum products or hazardous substances was not directly observed. The car dealership to the east of the Subject Property does appear to conduct vehicle repair/servicing, based on observed signage. Descriptions of adjoining properties are provided in **Section 2.4**.

5.4 Surrounding Properties

Surrounding properties were generally commercial, with a residential neighborhood to the north of the Subject Property.

6.0 Interviews

In accordance with requirements of Sections 10 and 11 of ASTM Standard E1527-21 (ASTM, 2021, pp. 21-23), INTERA interviewed the *key site manager* and *local government officials* for knowledge of any past or present RECs in connection with the Subject Property.

Any findings associated with these interviews are indicated in **Section 7**.

6.1 Key Site Manager

Mr. Andrew Murphy of INTERA interviewed Mr. Lawrence Romero, business owner and Key Site Manager for the Subject Property, on February 12, 2026. Mr. Romero indicated that he has operated the dry cleaning business at this location since approximately the year 2000. Mr. Romero stated that the dry cleaning facility is on its third set of machinery and currently uses "Seitz Intense" solvent, which is free of halogenated solvents (e.g., PCE). He reportedly removed the chlorinated solvent machine when he took over the business in 2000.

During the Site reconnaissance, Mr. Romero indicated that he believes that there was an environmental sampling or investigation conducted near the Subject Property boundary within the car dealership to the east, on the other side of the stormwater drainage, completed approximately eight years ago.

Documentation of the interview with the Key Site Manager is provided in **Appendix K**.

6.2 Local Government Officials

NMED provided available information for the Subject Property during project initiation as described in **Section 3**. The information provided is considered satisfactory to meet the requirements of the Standard. No additional information from local government officials was obtained.

Records received from NMED are included in **Appendix K**.

7.0 Findings and Opinions

This section presents the findings of the Phase I ESA Report for the Subject Property and summarizes the results of the Phase I ESA records review, site reconnaissance, and interviews as they relate to the potential presence of RECs. A discussion of Subject Property findings related to the use, storage, and disposal of hazardous substances and petroleum products is presented in **Section 7.1.** A discussion of the findings for adjoining and surrounding vicinity properties is included in **Sections 7.2** and **7.3**, respectively. **Section 7.4** discusses the results of the Tier 1 VES. This section also presents INTERA's opinions concerning the potential of the findings to contaminate Subject Property environmental media and whether the finding is considered a REC. The findings presented in this section are the basis for the Phase I ESA conclusions presented by INTERA in **Section 8** of this Phase I ESA Report.

7.1 Subject Property Findings and Opinions

The Subject Property is located in a multi-unit development made up of five land parcels with the same address totaling 0.27 acres. The subject Property parcel (Suite A) is approximately 0.11 acres located on the southeast corner of the multi-unit development. The Subject Property is located in a commercial area, with a residential area to the north. Based on review of historical records the Subject Property has been operated as a dry cleaning facility since approximately 1988. The current owner indicated that the halogenated solvent equipment was replaced with non-halogenated solvent equipment in 2000 when the current ownership began.

Based on the information available, a **REC** exists in connection with the Subject Property due to the approximate 12 years of operations using halogenated solvents.

7.2 Adjoining Property Findings and Opinions

No relevant findings were identified associated with adjoining properties. During the interview with the Site Manager, Mr. Romero recalled an environmental investigation being conducted at the adjoining car dealership to the east. However, no corroborating evidence of an environmental investigation was identified in historical records. During the Site reconnaissance, the car dealership was observed to offer vehicle service/repair. Due to the proximity of the car dealership and vehicle maintenance/repair facility, and the unknown circumstances surrounding a potentially previous environmental investigation, a **REC** exists in connection with the Subject Property.

No other evidence of releases of hazardous substances or petroleum products was identified associated with any of the other adjoining properties. Based on the information available at this time, no other RECs were identified on adjoining properties.

7.3 Vicinity Findings and Opinions

Select findings in the vicinity of the Subject Property within the respective AMSD for the databases they are listed in are discussed in this section. Other findings from non-standard environmental records (**Table 3**) are discussed here, where relevant, as well.

ATEX Allsups #327 (1899/2000 St. Michaels Drive), approximately 450 ft west of the Subject Property, hydraulically downgradient

This property is listed as a former leaking storage tank site (LST) site. A hydrocarbon release was reported on April 29, 1993. On October 25, 1993, the site was granted no further action (NFA) status because contamination was confined to the site and did not reach the groundwater table (NMED, 1993). The facility is still an active gas station with registered underground storage tanks (USTs). Based on the information available at this time, this facility is not considered a REC in connection with the Subject Property.

Premier Nissan/ Santa Fe Partners (2005 St. Michaels Drive), approximately 711 ft east of the Subject Property, hydraulically upgradient

This facility was identified as a former UST and a former NMED Voluntary Remediation Program (VRP) site. A 560-gallon waste oil tank was removed in 1994; no impacts to environmental media were documented (NMED, 1994). The property was entered into the VRP because of contamination associated with hydraulic lifts and sump on-site. A certificate of completion was issued in 2006. Based on the information available at this time, this facility is not considered a REC in connection with the Subject Property.

Allsups 252 (2007 Calle Lorca), approximately 0.25-mile east-southeast of the Subject Property, hydraulically upgradient

This facility is a former LST site that was granted NFA status in 2003. Soil contamination was identified to a depth of 105 ft bgs, but groundwater was not encountered at 220 ft bgs. The NFA letter indicates a public water supply well approximately 100 yards west of this location is completed at approximately 400 ft bgs. (NMED, 2003). Based on the information available at this time, this facility is not considered a REC in connection with the Subject Property.

Smith's #491 Fuel Center (800 St. Michaels Drive), approximately 0.29-mile east of the Subject Property, hydraulically upgradient.

This facility is a former VRP site with petroleum contamination in soil. A certificate of completion was issued on May 5, 2015, and no institutional controls or land use restrictions are indicated. Based on the information available at this time, this facility is not considered a REC in connection with the Subject Property.

Park Avenue Cleaners (720 St. Michaels Drive), approximately 0.4-mile east of the Subject Property, hydraulically upgradient.

This facility is a former dry cleaner and active VRP with a conditional certificate of completion issued by NMED in 2021. The VRP database information indicates that sub-slab soil at the site was contaminated

with PCE. There is no indication that groundwater was impacted. Based on the information available at this time, this facility is not considered a REC in connection with the Subject Property.

St. Michaels Shell (711 St. Michaels Drive), approximately 0.49-mile east of the Subject Property, hydraulically upgradient.

This facility is a former LST site that was granted NFA status in 1994 after vertical and horizontal delineation of impacted soil above the water table and removal of soil above the state action levels (NMED, 1994). Based on the information available at this time, this facility is not considered a REC in connection with the Subject Property.

7.4 Tier 1 Vapor Encroachment Screening

ASTM Standard E2600-22 defines the default area of concern (AOC) based on $^{1}/_{3}$-mile for hazardous substances and $^{1}/_{10}$-mile for petroleum hydrocarbon contaminants. The AOC is measured from the Subject Property boundary to a contaminated property with known or suspected contamination of soil and/or groundwater (ASTM, 2022).

Based on review of Subject Property, adjoining property, and vicinity property findings within the default AOC, the dry-cleaning activities using a PCE-based solvent until 2000 that occurred at the Subject Property are considered a **VEC**. Potential contaminant impacts due to vehicle maintenance/repair activities on the adjoining car dealership property, as indicated by the account of the New Method Cleaners owner, are also considered a **VEC**.

7.5 Data Gaps

No data gaps were identified in connection with the Subject Property.

8.0 Conclusions

INTERA has performed a Phase I ESA in conformance with the scope and limitations of ASTM Standard E1527-21 for the Subject Property. Any exceptions to or deletions from this practice are described in **Section 7.5**. Based on the completion of the scope of services provided in support of this Phase I ESA, one REC/VEC was identified in connection with the Subject Property and one REC associated with an adjoining property, as follows:

- Approximately 12 years (1988-2000) of dry cleaning operations conducted at the Subject Property using PCE-based solvents is considered a **REC/VEC** in connection with the Subject Property.
- Potential contaminant impacts due to vehicle maintenance/repair activities on the adjoining car dealership property, and a potential historical environmental investigation/sampling effort, as indicated by the New Method Cleaners owner, is considered a **REC/VEC** in connection with the Subject Property.

9.0 Recommendations

Based on the AAIs performed by the environmental professional in conformance with 40 Code of Federal Regulations (CFR) 312.31(a) and (b), this Phase I ESA has revealed evidence of one or more RECs/VECs or *significant data gaps* in connection with the Subject Property. Based on the conclusions of this Phase I ESA, INTERA recommends the following:

- Perform a Phase II investigation to assess the potential impacts to environmental media from the RECs identified in connection with the Subject Property.

10.0 References

ASTM International (ASTM). 2021. *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process.* Standard E1527-21. West Conshohocken, Pennsylvania: ASTM International.

———. 2022. *Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions*. Standard E2600-22. West Conshohocken, Pennsylvania. May 18, 2022.

Environmental Risk Information Services (ERIS). 2025a. Environmental Lien Search.

———. 2025b. Topographic Maps.

———. 2025c. Historical Aerials.

———. 2025d. Physical Setting Report.

———. 2025e. Fire Insurance Maps.

———. 2025f. City Directory.

———. 2025g. Database Report.

National Oceanic and Atmospheric Administration (NOAA), 2026. National Weather Service Climate Data. https://www.weather.gov/wrh/Climate?wfo=hgx. Accessed March 31, 2026.

New Mexico Environment Department (NMED). 1993. Letter from Phillis Stevens, Geological Engineer, Remedial Action Program, Underground Storage Tank Bureau, to J.R. Jacobs (Allsups Representative). *RE: Allsups #327 UST Contamination Site, 2000 St. Michael's, Santa Fe.* October 25, 1993.

———. 1994. Letter from Bill Skinner, Water Resource Specialist, Underground Storage Tank Bureau, to Mr. Alfred East, Brewer Oil Company. *RE: No Further Action Required at St. Mike's Shell, 711 Saint Michael's Drive, Santa Fe, New Mexico*. October 24, 1994.

———. 2003. Letter from Lorena Goerger, Geologist, Petroleum Storage Tank Bureau, to Mr. Jeff Scarbrough (Allsups Representative). *RE: No Further Action Status at Allsups #252, 2007 Calle Lorca, Santa Fe, New Mexico.* June 16, 2003.

Santa Fe County Assessor (SFCA) Parcel Viewer. 2025. https://www.santafecountynm.gov/assessor/tools. Accessed January 13, 2026.

United States Geological Survey (USGS). 2023. *Santa Fe, New Mexico 7.5-Minute Series*. U.S. Department of the Interior, U.S. Geological Survey.

11.0 Disclaimer

The findings and conclusions contained in this report were derived using the methodologies provided in ASTM Standard E1527-21 (ASTM, 2021). The findings and conclusions contain all limitations inherent in these methodologies. There is the possibility that even with proper application of these methodologies, conditions may exist at the Subject Property that could not be identified within the scope of the Phase I ESA or that were not reasonably identifiable from the available information.

INTERA has prepared this report in accordance with the generally accepted environmental professional practices in use at the time of our study. This report may be used only by the User(s) and only for the purposes stated within a reasonable time from its issuance as outlined in ASTM Standard E1527-21 (ASTM, 2021). Land use, Site conditions (both onsite and offsite), or other factors may change over time, and additional work may be required with the passage of time. Any party other than the User(s) who wishes to use this report shall notify the User(s) of the intended use. Non-compliance with any of these requirements will release INTERA from any liability resulting from the use of this report.

INTERA does not warrant or guarantee in any manner, expressed or implied, that the conclusions and findings reported in this Phase I ESA, or the information obtained for this Phase I ESA from the records review or from other sources, including site reconnaissance observations, personal interviews, and correspondence, are accurate or complete beyond the limits of the methods applied. The methodologies of this Phase I ESA assessment are intended to meet the scope of a Phase I ESA in accordance with ASTM Standard E1527-21 (ASTM, 2021).

INTERA conducted this Phase I ESA and AAI into previous property ownership and uses in a manner consistent with ASTM Standard E1527-21 and the EPA AAI Final Rule (EPA, 2005) definitions of good commercial and customary ESA and AAI practices in the United States of America.

This Phase I ESA report is intended for use solely by the User(s). Any party other than the User(s) is explicitly denied any rights to rely on the findings, opinions, and conclusions of this Phase I ESA report.

12.0 Qualifications and Signatures of Environmental Professionals


Complete copies of resumes outlining the qualifications of the individuals completing this Phase I ESA report are included as **Appendix L**.

"I declare that, to the best of my professional knowledge and belief, I meet the definition of environmental professional as defined in Section 312.10 of 40 CFR 312. I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the Subject Property. I have developed and performed all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR part 312."

Matt Hubbard, Senior Environmental Scientist/Environmental Professional

Signature: 

Joeseph Tracy, P.G., Principal Geologist/Environmental Professional

Signature: 

FIGURES





Figure 1
Site Location
New Method Cleaners
1911 St. Michaels Drive, Santa Fe, New Mexico

Exported: 6/3/2026 10:19 AM
S:\ABQ\NMENV.M007.SF-WALDO\Graphics\SantaFe_Waldo_P1P2_Proposal\SantaFe_Waldo_P1P2_Proposal.aprx
User: mhubbard
Layout: Figure 1 - 1911 St Mikes

INTERA



Legend

- Subject Property
- Hyundai Dealership/ Service Center (Adjoining)
- VRP Sites
- LST Sites

0 500 1,000
US Feet

N

Figure 2
Site Plan
New Method Cleaners
1911 St. Michaels Drive, Santa Fe, New Mexico

Exported: 6/5/2026 10:32 AM
S:\ABQ\NMENV.M007.SF-WALDO\Graphics\SantaFe_Waldo_P1P2_Proposal\SantaFe_Waldo_P1P2_Proposal.aprx
User: mhubbard
Layout: Figure 2 - Site Plan St Mikes

INTERA

APPENDIX A

Chain of Title Report and Environmental Lien and Activity and Use Limitation Search

CHAIN OF TITLE

Project Property: *1911 ST MICHAELS DR*
SANTA FE, NM 87505
Order No: *25121700734-COT1*
Date Completed: *01/05/2026*

ERIS – Environmental Risk Information Services hereby submits the following historical chain-of-title to the land described below.

Title to the estate or interest covered by this report appears to be vested in:

HELEN ORTEGA AS TRUSTEE OF THE BEN AND HELEN ORTEGA REVOCABLE TRUST U/T/A/D SEPTEMBER 12, 1991

The following is the current property legal description (See deed for full legal description):

UNIT A LOS ORTEGAS CONDOS T17N R 9E S34

Assessor's Parcel Number(s): 019102704 AND 1-052-097-432-244

CHAIN OF TITLE REPORT

Order No: *25121700734-COT1*

HISTORICAL CHAIN OF TITLE

Public Records were searched at the SANTA FE COUNTY Assessor's office and the SANTA FE COUNTY Clerk's office back to 1932. The following conveyances were found of record.

1.	Deed Type:	QUIT CLAIM DEED
	Deed Date:	12/31/2018
	Recorded:	12/31/2018
	Grantor:	ORTEGA FAMILY LIMITED PARTNERSHIP
	Grantee:	HELEN ORTEGA AS TRUSTEE OF THE BEN AND HELEN ORTEGA REVOCABLE TRUST U/T/A/D SEPTEMBER 12, 1991
	Instrument:	1875968
	Notes:	NA
2.	Deed Type:	DEED
	Deed Date:	07/12/1993
	Recorded:	07/12/1993
	Grantor:	BEN N. ORTEGA AND HELEN A ORTEGA, THE ORTEGA FAMILY LP
	Grantee:	ORTEGA FAMILY LIMITED PARTNERSHIP
	Instrument:	BOOK 944 / PAGE 603
	Notes:	NA
3.	Deed Type:	DEED
	Deed Date:	12/31/1991
	Recorded:	12/31/1991
	Grantor:	BEN ORTEGA AND HELEN ORTEGA, THE ORTEGA FAMILY LP
	Grantee:	BEN N. ORTEGA AND HELEN A ORTEGA, THE ORTEGA FAMILY PARTNERSHIP
	Instrument:	BOOK 779 / PAGE 517
	Notes:	NO DEED OF RECORD FOUND INTO BEN AND HELEN ORTEGA REVOCABLE TRUST.

4. Deed Type: DEED
   Deed Date: 04/05/1984
   Recorded: 04/05/1984
   Grantor: ANNE L NOONAN AND MILTON L NOONAN, CONNIE MARIE PATERSON AND GEORGE H. PATTERSON, BEN N. ORTEGA AND HELEN A ORTEGA
   Grantee: BEN ORTEGA AND HELEN ORTEGA, THE ORTEGA FAMILY LP
   Instrument: BOOK 487 / PAGE 597
   Notes: NA

5. Deed Type: DEED
   Deed Date: 04/05/1984
   Recorded: 04/05/1984
   Grantor: SANTA FE TIRE INC., ANNE L NOONAN AND MILTON L NOONAN, CONNIE MARIE PATTERSON AND GEORGE H. PATTTERSON
   Grantee: ANNE L NOONAN AND MILTON L NOONAN, CONNIE MARIE PATERSON AND GEORGE H. PATTERSON, BEN N. ORTEGA AND HELEN A ORTEGA
   Instrument: BOOK 487 / PAGE 595
   Notes: NA

6. Deed Type: DEED
   Deed Date: 08/19/1982
   Recorded: 08/19/1982
   Grantor: SANTA FE TIRE INC., CONNIE MARIE PATTERSON AND GEORGE H. PATTERSON
   Grantee: SANTA FE TIRE INC., ANNE L NOONAN AND MILTON L NOONAN, CONNIE MARIE PATTERSON AND GEORGE H. PATTTERSON
   Instrument: BOOK 446 / PAGE 442
   Notes: NA

7. Deed Type: DEED
   Deed Date: 08/19/1982
   Recorded: 08/19/1982
   Grantor: SANTA FE TIRE INC., ANNE L NOONAN AND MILTON L. NOONAN
   Grantee: SANTA FE TIRE INC., CONNIE MARIE PATTERSON AND GEORGE H. PATTERSON
   Instrument: BOOK 446 / PAGE 441
   Notes: NA

8. Deed Type: DEED
   Deed Date: 08/19/1982
   Recorded: 08/19/1982
   Grantor: SANTA FE TIRE AND SUPPLY COMPANY INC., SANTA FE TIRE INC.
   Grantee: SANTA FE TIRE INC., ANNE L NOONAN AND MILTON L. NOONAN
   Instrument: BOOK 446 / PAGE 440
   Notes: NA

9. Deed Type: DEED
   Deed Date: 02/15/1973
   Recorded: 02/15/1973
   Grantor: B & R SALES COMPANY INC., SANTA FE TIRE AND SUPPLY COMPANY INC.
   Grantee: SANTA FE TIRE AND SUPPLY COMPANY INC., SANTA FE TIRE INC.
   Instrument: BOOK 298 / PAGE 323
   Notes: NA

10. Deed Type: DEED
    Deed Date: 12/16/1969
    Recorded: 12/16/1969
    Grantor: BUENO INC., B & R SALES COMPANY INC.
    Grantee: B & R SALES COMPANY INC., SANTA FE TIRE AND SUPPLY COMPANY INC.
    Instrument: BOOK 269 / PAGE 643
    Notes: NA

11.	Deed Type:	DEED
	Deed Date:	12/10/1969
	Recorded:	12/10/1969
	Grantor:	BESS G THOMAS AND BUENO INC.
	Grantee:	BUENO INC., B & R SALES COMPANY INC.
	Instrument:	BOOK 269 / PAGE 542
	Notes:	NA
12.	Deed Type:	DEED
	Deed Date:	02/15/1965
	Recorded:	02/15/1965
	Grantor:	LEAGUE OF UNITED LATIN AMERICAN CITIZENS, BUENO INC.
	Grantee:	BESS G THOMAS AND BUENO INC.
	Instrument:	BOOK 222 / PAGE 18
	Notes:	NA
13.	Deed Type:	DEED
	Deed Date:	09/23/1963
	Recorded:	09/23/1963
	Grantor:	BESS G. THOMAS, LEAGUE OF UNITED LATIN AMERICAN CITIZENS
	Grantee:	LEAGUE OF UNITED LATIN AMERICAN CITIZENS, BUENO INC.
	Instrument:	BOOK 205 / PAGE 344
	Notes:	NA
14.	Deed Type:	DEED
	Deed Date:	08/12/1963
	Recorded:	08/12/1963
	Grantor:	LEAGUE OF UNITED LATIN AMERIAN CITIZENS, BESS G. THOMAS
	Grantee:	BESS G. THOMAS, LEAGUE OF UNITED LATIN AMERICAN CITIZENS
	Instrument:	BOOK 204 / PAGE 101
	Notes:	NA

15.	Deed Type:	DEED
	Deed Date:	09/04/1956
	Recorded:	09/07/1956
	Grantor:	KATE R SENA, LEAGUE OF UNITED LATIN AMERICAN CITIZENS
	Grantee:	LEAGUE OF UNITED LATIN AMERIAN CITIZENS, BESS G. THOMAS
	Instrument:	BOOK 123 / PAGE 4
	Notes:	SEARCHED BACK TO 1932, PRIOR DEED WAS RECORDED BEFORE 1932.

LEASES AND MISCELLANEOUS

Comments: NONE IDENTIFIED.

CHAIN OF TITLE REPORT

Order No: *25121700734-COT1*

Thank You for Your Business
Please contact ERIS at **416-510-5204** or **info@erisinfo.com**
with any questions or comments

LIMITATION

This report is neither a guarantee of title, a commitment to insure, or a policy of title insurance. ERIS – Environmental Risk Information Services does not guarantee nor include any warranty of any kind whether expressed or implied, about the validity of all information included in this report since this information is retrieved as it is recorded from various agencies that make it available. The total liability is limited to the fee paid for this report.

QUITCLAIM DEED

The **Ortega Family Limited Partnership**, a New Mexico limited partnership, for no consideration, hereby quitclaims to **Helen Ortega** as Trustee of the **Ben and Helen Ortega Revocable Trust u/t/a/d September 12, 1991,** whose address is P.O. Box 4576, Santa Fe, NM 87502, the real property situated in Santa Fe County, State of New Mexico, more particularly described as:

See **Exhibit A** attached hereto and made a part hereof

Subject to: Restrictions, reservations, easements and encumbrances or record, if any.

WITNESS our hands and seals this 31st day of December, 2018.

Ben and Helen Ortega Revocable Trust,
u/t/a/d September 12, 1991
General Partner

By: Helen Ortega
Helen Ortega, Trustee

SFC CLERK RECORDED 12/31/2018

ACKNOWLEDGMENT

STATE OF NEW MEXICO)
)ss.
COUNTY OF SANTA FE)

The foregoing Quitclaim Deed was acknowledged before me this 31st day of December, 2018 by **Helen Ortega**, Trustee of the **Ben and Helen Ortega Revocable Trust, u/t/a/d September 12, 1991**, General Partner of the **Ortega Family Limited Partnership**.

JENNIFER VAN WIEL NOTARY PUBLIC STATE OF NEW MEXICO

Notary Public
My Commission expires: March 20, 2019

COUNTY CLERK GERALDINE SALAZAR SANTA FE COUNTY NEW MEXICO

QUITCLAIM DEED
COUNTY OF SANTA FE) PAGES: 2
STATE OF NEW MEXICO) ss
I Hereby Certify That This Instrument Was Filed for Record On The 31ST Day Of December, 2018 at 10:23:37 AM
And Was Duly Recorded as Instrument # 1875968
Of The Records Of Santa Fe County

Witness My Hand And Seal Of Office
Geraldine Salazar
Deputy Veronica Duran County Clerk, Santa Fe, NM

Exhibit A

Units A, B, C and D of the Los Ortega's Condominium Plaza, Santa Fe, New Mexico, as created by the Declaration of Condominiums and of Easements, Restrictions and Covenants for Los Ortegas Condominium Plaza, recorded in the Office of the County Clerk, Santa Fe County, New Mexico on March 18, 1985, in Book 516, Pages 126-134, and as shown on that certain plat entitled "LOS ORTEGA'S CONDOMINIUM PLAZA, 1911 St. Michael's Drive, within the City of Santa Fe, Santa Fe County, New Mexico," filed in the Office of the County Clerk, Santa Fe County, New Mexico, on March 18, 1985, in Plat Book 150, Page 27, as Document No. 563,286, together with an undivided 57.2% interest in all common areas associated with Units A, B, C and D.

SFC CLERK RECORDED 12/31/2018

CHAIN OF TITLE & LIEN SEARCHES

Project Property: *1911 ST MICHAELS DR*
SANTA FE, NM 87505
Order No: *25121700734-COTEL1*
Date Completed: *01/05/2026*

Title to the estate or interest covered by this report appears to be vested in:
HELEN ORTEGA AS TRUSTEE OF THE BEN AND HELEN ORTEGA REVOCABLE TRUST U/T/A/D SEPTEMBER 12, 1991

The following is the current property legal description (See deed for full legal description):
UNIT A LOS ORTEGAS CONDOS T17N R 9E S34

Assessor's Parcel Number(s):
019102704 AND 1-052-097-432-244

ENVIRONMENTAL LIEN TO 1980 REPORT

Order No: *25121700734-COTEL1*

TARGET PROPERTY INFORMATION

ADDRESS

1911 ST MICHAELS DR
SANTA FE, NM 87505

RESEARCH SOURCES

RECORDER:	SANTA FE COUNTY RECORDER'S OFFICE
ASSESSOR:	SANTA FE COUNTY ASSESSOR'S OFFICE
STATE:	NEW MEXICO ENVIRONMENT DEPARTMENT
FEDERAL:	UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
OTHER:	JUDICIAL RECORDS NOT SEARCHED. BASED ON AVAILABLE INFORMATION EVALUATED BY THE TITLE SEARCH PROFESSIONAL, THE JURISDICTION DOES NOT REQUIRE A SEARCH OF JUDICIAL RECORDS IN ORDER TO IDENTIFY ENVIRONMENTAL LIENS.
NOTES:	PUBLIC RECORDS OF SANTA FE COUNTY, NM WERE SEARCHED FROM JANUARY 1, 1980 TO DECEMBER 29, 2025, AND NO OTHER DEEDS VESTING TITLE IN THE SUBJECT PROPERTY WERE FOUND OF RECORD DURING THE PERIOD SEARCHED.

ENVIRONMENTAL LIENS

Environmental Lien: [X] NOT FOUND

ACTIVITY AND USE LIMITATIONS (AULs)

AULs: [X] NOT FOUND

CHAIN OF TITLE TO 1980

1. Deed Type: QUIT CLAIM DEED
   Deed Date: 12/31/2018
   Recorded: 12/31/2018
   Grantor: THE ORTEGA FAMILY LIMITED PARTNERSHIP
   Grantee: HELEN ORTEGA AS TRUSTEE OF THE BEN AND HELEN ORTEGA REVOCABLE TRUST U/T/A/D SEPTEMBER 12, 1991
   Instrument: NA
   Notes: NO DEED TO REVOCABLE TRUST FOUND

2. Deed Type: DEED
   Deed Date: 07/12/1993
   Recorded: 07/12/1993
   Grantor: BEN N. ORTEGA AND HELEN A. ORTEGA
   Grantee: THE ORTEGA FAMILY LIMITED PARTNERSHIP
   Instrument: BOOK 944 / PAGE 603
   Notes:

3. Deed Type: DEED
   Deed Date: 12/31/1991
   Recorded: 12/31/1991
   Grantor: BEN N. ORTEGA AND HELEN A. ORTEGA
   Grantee: THE ORTEGA FAMILY LIMITED PARTNERSHIP
   Instrument: BOOK 779 / PAGE 517
   Notes:

4. Deed Type: DEED
   Deed Date: 04/05/1984
   Recorded: 04/05/1984
   Grantor: ANNE L. NOONAN AND MILTON L. NOONAN, CONNIE MARIE PATTERSON AND GEORGE H. PATTERSON
   Grantee: BEN N. ORTEGA AND HELEN A. ORTEGA
   Instrument: BOOK 487 / PAGE 597
   Notes:

5. Deed Type: DEED
   Deed Date: 04/05/1984
   Recorded: 04/05/1984
   Grantor: SANTA FE TIRE, INC
   Grantee: ANNE L. NOONAN AND MILTON L. NOONAN, CONNIE MARIE PATTERSON AND GEORGE H. PATTERSON
   Instrument: BOOK 487 / PAGE 595
   Notes:

6. Deed Type: DEED
   Deed Date: 08/19/1982
   Recorded: 08/19/1982
   Grantor: SANTA FE TIRE, INC
   Grantee: CONNIE MARIE PATTERSON AND GEORGE H. PATTERSON
   Instrument: BOOK 446 / PAGE 442
   Notes:

7. Deed Type: DEED
   Deed Date: 08/19/1982
   Recorded: 08/19/1982
   Grantor: SANTA FE TIRE, INC
   Grantee: ANNE L. NOONAN AND MILTON L. NOONAN
   Instrument: BOOK 446 / PAGE 441
   Notes:

8. Deed Type: DEED
   Deed Date: 08/19/1982
   Recorded: 08/19/1982
   Grantor: SANTA FE TIRE AND SUPPLY COMPANY, INC
   Grantee: SANTA FE TIRE, INC
   Instrument: BOOK 446 / PAGE 440
   Notes: GRANTOR TOOK TITLE PRIOR TO 1980
   RESEARCH CONDUCTED BACK TO 1980. THIS IS THE OLDEST DEED OF RECORD FOUND POST DECEMBER 31, 1979 (BETWEEN 01/01/1980 AND 08/19/1982).

MISCELLANEOUS

1. 1st Party: NEW METHOD DRY CLEANERS/ST. MICHAELS DR.
   2nd Party: UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
   Dated: NA
   Recorded Date: NA
   Instrument #: NA
   Instrument Type: DETAILED FACILITY REPORT
   Comments: FRS ID110004274151

The ERIS Environmental Lien Search Report to 1980 provides results from a search of available current land title records for environmental cleanup liens and other activity and use limitations, such as engineering and institutional controls.

A network of professional, trained researchers, following established procedures, uses client supplied property information to:

- Search for parcel information and / or legal description
- Search for ownership information
- Research official land title documents recorded at jurisdictional agencies such as recorder's' office, registries of deeds, county clerks' offices, etc.
- Access copies of deeds to 1980
- Search for environmental encumbrance(s) associated with the deeds
- Provide a copy of any environmental encumbrance(s) based upon a review of keywords in the instrument(s) (title, parties involved and description)
- Provide a copy of the deeds or cite documents reviewed

Thank You for Your Business
Please contact ERIS at **416-510-5204** or **info@erisinfo.com**
with any questions or comments

LIMITATION

This report is neither a guarantee of title, a commitment to insure, or a policy of title insurance. ERIS – Environmental Risk Information Services does not guarantee nor include any warranty of any kind whether expressed or implied, about the validity of all information included in this report since this information is retrieved as it is recorded from various agencies that make it available. The total liability is limited to the fee paid for this report.

DEED EXHIBIT

QUITCLAIM DEED

The **Ortega Family Limited Partnership**, a New Mexico limited partnership, for no consideration, hereby quitclaims to **Helen Ortega** as Trustee of the **Ben and Helen Ortega Revocable Trust u/t/a/d September 12, 1991,** whose address is P.O. Box 4576, Santa Fe, NM 87502, the real property situated in Santa Fe County, State of New Mexico, more particularly described as:

See **Exhibit A** attached hereto and made a part hereof

Subject to: Restrictions, reservations, easements and encumbrances or record, if any.

WITNESS our hands and seals this 31st day of December, 2018.

Ben and Helen Ortega Revocable Trust,
u/t/a/d September 12, 1991
General Partner

By: Helen Ortega
Helen Ortega, Trustee

SFC CLERK RECORDED 12/31/2018

ACKNOWLEDGMENT

STATE OF NEW MEXICO)
)ss.
COUNTY OF SANTA FE)

The foregoing Quitclaim Deed was acknowledged before me this 31st day of December, 2018 by **Helen Ortega**, Trustee of the **Ben and Helen Ortega Revocable Trust, u/t/a/d September 12, 1991**, General Partner of the **Ortega Family Limited Partnership**.

JENNIFER VAN WIEL NOTARY PUBLIC STATE OF NEW MEXICO

Notary Public
My Commission expires: March 20, 2019

COUNTY CLERK GERALDINE SALAZAR SANTA FE COUNTY NEW MEXICO

QUITCLAIM DEED
COUNTY OF SANTA FE) PAGES: 2
STATE OF NEW MEXICO) ss
I Hereby Certify That This Instrument Was Filed for Record On The 31ST Day Of December, 2018 at 10:23:37 AM
And Was Duly Recorded as Instrument # 1875968
Of The Records Of Santa Fe County

Witness My Hand And Seal Of Office
Geraldine Salazar
Deputy Veronica Duran County Clerk, Santa Fe, NM

Exhibit A

Units A, B, C and D of the Los Ortega's Condominium Plaza, Santa Fe, New Mexico, as created by the Declaration of Condominiums and of Easements, Restrictions and Covenants for Los Ortegas Condominium Plaza, recorded in the Office of the County Clerk, Santa Fe County, New Mexico on March 18, 1985, in Book 516, Pages 126-134, and as shown on that certain plat entitled "LOS ORTEGA'S CONDOMINIUM PLAZA, 1911 St. Michael's Drive, within the City of Santa Fe, Santa Fe County, New Mexico," filed in the Office of the County Clerk, Santa Fe County, New Mexico, on March 18, 1985, in Plat Book 150, Page 27, as Document No. 563,286, together with an undivided 57.2% interest in all common areas associated with Units A, B, C and D.

SFC CLERK RECORDED 12/31/2018

MISCELLANEOUS EXHIBIT

Detailed Facility Report

Facility Summary

NEW METHOD DRY CLEANERS/ST. MICHAELS DR.

1911A SAINT MICHAELS DRIVE, SANTA FE, NM 87505

FRS (Facility Registry Service) ID: 110004274151

EPA Region: 06

Latitude: 35.65913

Longitude: -105.969238

Locational Data Source: --

Industries: Personal and Laundry Services

Indian Country: N

Enforcement and Compliance Summary

Statute	CAA
Compliance Monitoring Activities (5 years)	--
Date of Last Compliance Monitoring Activity	01/08/1999
Compliance Status	No Violation Identified
Qtrs in Noncompliance (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	--
Formal Enforcement Actions (5 years)	--
Penalties from Formal Enforcement Actions (5 years)	--
EPA Cases (5 years)	--
Penalties from EPA Cases (5 years)	--
Statute	**RCRA**
Compliance Monitoring Activities (5 years)	--
Date of Last Compliance Monitoring Activity	--
Compliance Status	No Violation Identified
Qtrs in Noncompliance (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	--
Formal Enforcement Actions (5 years)	--
Penalties from Formal Enforcement Actions (5 years)	--
EPA Cases (5 years)	--
Penalties from EPA Cases (5 years)	--

Regulatory Information

Clean Air Act (CAA): Operating Minor (NM0000003504978036)

Clean Water Act (CWA): No Information

Resource Conservation and Recovery Act (RCRA): Inactive Other, (NMD981512999)

Safe Drinking Water Act (SDWA): No Information

Other Regulatory Reports

Air Emissions Inventory (EIS): No Information

Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): No Information

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

Go To Enforcement/Compliance Details
Known Data Problems <https://epa.gov/resources/echo-data/known-data-problems>

Facility/System Characteristics

Facility/System Characteristics

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110004274151					N	35.65913	-105.969238
ICIS-Air	CAA	NM0000003504978036	Minor Emissions	Operating	CAAMACT		N	35.659417	-105.969356
RCRAInfo	RCRA	NMD981512999	Other	Inactive ( )			N	35.659469	-105.968544

Facility Address

System	Statute	Identifier	Facility Name	Facility Address	Facility County
FRS		110004274151	NEW METHOD DRY CLEANERS/ST. MICHAELS DR.	1911A SAINT MICHAELS DRIVE, SANTA FE, NM 87505	Santa Fe County
ICIS-Air	CAA	NM0000003504978036	NEW METHOD DRY CLEANERS/ST. MICHAELS DR.	1911 ST. MICHAELS DR., SANTA FE, NM 87505	Santa Fe County
RCRAInfo	RCRA	NMD981512999	NEW METHOD CLNRS	1911-A ST MICHAELS DR, SANTA FE, NM 87505	Santa Fe County

Facility SIC (Standard Industrial Classification) Codes

System	Identifier	SIC Code	SIC Description
ICIS-Air	NM0000003504978036	7216	Drycleaning Plants, Except Rug

Facility NAICS (North American Industry Classification System) Codes

System	Identifier	NAICS Code	NAICS Description
ICIS-Air	NM0000003504978036	812320	Drycleaning and Laundry Services (except Coin-Operated)

Facility Tribe Information

Reservation Name	Tribe Name	EPA Tribal ID	Distance to Tribe (miles)
Ohkay Owingeh	Ohkay Owingeh, New Mexico	100000180	25
Pueblo de Cochiti	Pueblo of Cochiti, New Mexico	100000213	15
Nambe Pueblo	Pueblo of Nambe, New Mexico	100000217	12
Pueblo of Pojoaque	Pueblo of Pojoaque, New Mexico	100000219	8
San Felipe Pueblo/Santo Domingo Pueblo joint-use area	Pueblo of San Felipe, New Mexico	100000220	25
San Ildefonso Pueblo	Pueblo of San Ildefonso, New Mexico	100000221	15
Santa Clara Pueblo	Pueblo of Santa Clara, New Mexico	100000224	20
Tesuque Pueblo	Pueblo of Tesuque, New Mexico	100000226	8
Santo Domingo Pueblo	Santo Domingo Pueblo	100000123	18

Enforcement and Compliance

Compliance Monitoring History

Last 5 Years

Statute	Source ID	System	Activity Type	Compliance Monitoring Type	Lead Agency	Date	Finding (if applicable)

No data records returned

Entries in italics are not included in ECHO's Compliance Monitoring Activity counts because they are not compliance monitoring strategy <https://www.epa.gov/compliance/compliance-monitoring-programs> *activities or because they are not counted as inspections within EPA's Annual Results* <https://www.epa.gov/enforcement/enforcement-data-and-results>.

Compliance Summary Data

Statute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
CAA	NM0000003504978036	No	01/03/2026	0	01/02/2026
RCRA	NMD981512999	No	01/03/2026	0	01/02/2026

Three-Year Compliance History by Quarter

Statute	Program/Pollutant/Violation Type	QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	
CAA (Source ID: NM0000003504978036)		01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/0
	Facility-Level Status	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No
	HPV History											

	Violation Type	Agency	Programs	Pollutants

Statute	Program/Pollutant/Violation Type	QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11
RCRA (Source ID: NMD981512999)		01/01-03/31/23	04/01-06/30/23	07/01-09/30/23	10/01-12/31/23	01/01-03/31/24	04/01-06/30/24	07/01-09/30/24	10/01-12/31/24	01/01-03/31/25	04/01-06/30/25	07/01-09/30/25
	Facility-Level Status	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified	No Violation Identified

	Violation	Agency

Informal Enforcement Actions

Last 5 Years

Statute	System	Source ID	Type of Action	Lead Agency	Date

No data records returned

Entries in italics are not counted as "informal enforcement actions" in EPA policies pertaining to enforcement response tools.

Formal Enforcement Actions

Last 5 Years

Statute	System	Law/ Section	Source ID	Type of Action	Case No.	Lead Agency	Case Name	Issued/ Filed Date	Settlements/ Actions	Settlement/ Action Date	Federal Penalty Assessed	State/ Local Penalty Assessed	Penalty Amount Collected	SEP Value	Comp Action Cost

No data records returned

Environmental Conditions

Watersheds

12-Digit WBD (Watershed Boundary Dataset) HUC (RAD (Reach Address Database))	WBD (Watershed Boundary Dataset) Subwatershed Name (RAD (Reach Address Database))	State Water Body Name (ICIS (Integrated Compliance Information System))	Beach Closures Within Last Year	Beach Closures Within Last Two Years	Pollutants Potentially Related to Impairment	Watershed with ESA (Endangered Species Act)-listed Aquatic Species?

No data records returned

Assessed Waters From Latest State Submission (ATTAINS)

State	Report Cycle	Assessment Unit ID	Assessment Unit Name	Water Condition	Cause Groups Impaired	Drinking Water Use	Ecological Use	Fish Consumption Use	Recreation Use	Other Use

No data records returned

Air Quality Nonattainment Areas

Pollutant	Within Nonattainment Status Area?	Nonattainment Status Applicable Standard(s)	Within Maintenance Status Area?	Maintenance Status Applicable Standard(s)

No data records returned

Pollutants

Toxics Release Inventory History of Reported Chemicals Released or Transferred in Pounds per Year at Site

TRI Facility ID	Year	Air Emissions	Surface Water Discharges	Off-Site Transfers to POTWs (Publicly Owned Treatment Works)	Underground Injections	Disposal to Land	Total On-Site Releases	Total Off-Site Transfers

No data records returned

Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Chemical Name

No data records returned

Community

Demographic Profile of Surrounding Area (1-Mile Radius)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2023 American Community Survey (ACS) 5-year Summary and are accurate to the extent that the facility latitude and longitude listed below are correct. Census boundaries and demographic data for U.S. Territories are based on the "2020 Island Areas Demographic Profiles" from the U.S. Census Bureau. EPA's spatial processing methodology considers the overlap between the selected radii and ACS census block groups in determining the demographics surrounding the facility. For more detail about this methodology, see the DFR Data Dictionary <https://epa.gov/help/reports/dfr-data-dictionary#demographic>.

General Statistics (ACS (American Community Survey))	
Total Persons	9,515
Population Density	3,030/sq.mi.
Housing Units in Area	5,336
Percent People of Color	57%
Households in Area	4,955
Households on Public Assistance	141
Persons With Low Income	3,525
Percent With Low Income	37%

Geography	
Radius of Selected Area	1 mi.
Center Latitude	35.65913
Center Longitude	-105.969238
Total Area	3.14 sq.mi.
Land Area	100%
Water Area	0%

Income Breakdown (ACS (American Community Survey)) - Households (%)	
Less than $15,000	587 (11.84%)
$15,000 - $25,000	481 (9.7%)
$25,000 - $50,000	1,327 (26.76%)
$50,000 - $75,000	811 (16.36%)
Greater than $75,000	1,752 (35.34%)

Age Breakdown (ACS (American Community Survey)) - Persons (%)	
Children 5 years and younger	309 (3%)
Minors 17 years and younger	1,307 (14%)
Adults 18 years and older	8,206 (86%)
Seniors 65 years and older	2,612 (27%)

Race Breakdown (ACS (American Community Survey)) - Persons (%)	
White	5,812 (61%)
African-American	399 (4%)
Hispanic-Origin	4,481 (47%)
Asian	134 (1%)
Hawaiian/Pacific Islander	0 (0%)
American Indian	133 (1%)
Other/Multiracial	959 (10%)

Education Level (Persons 25 & older) (ACS (American Community Survey)) - Persons (%)	
Less than 9th Grade	318 (4.43%)
9th through 12th Grade	511 (7.11%)
High School Diploma	1,202 (16.73%)
Some College/2-year	1,574 (21.91%)
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	3,109 (43.28%)

APPENDIX B

Historical Topographic Maps

TOPOGRAPHIC MAPS

Project Property:	New Method Cleaners
	1911 St Michaels Dr
	Santa Fe NM 87505
Project No:	NMENV.M007.SF-WALDO
Requested By:	INTERA Incorporated
Order No:	25121700734
Date Completed:	December 17, 2025

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

We have searched USGS collections of current topographic maps and historical topographic maps for the project property. Below is a list of maps found for the project property and adjacent area. Maps are from 7.5 and 15 minute topographic map series, if available.

Year	Map Series
2023	7.5
2020	7.5
2017	7.5
2013	7.5
2002	7.5
1993	7.5
1977	7.5
1961	7.5
1952	7.5

Topographic Map Symbology for the maps may be available in the following documents:

Pre-1947

Page 223 of 1918 Topographic Instructions

Page 130 of 1928 Topographic Instructions


1947-2009

Topographic Map Symbols

2009-present

US Topo Map Symbols

Topographic Maps included in this report are produced by the USGS and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property.
No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc.(in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS', using Topographic Maps produced by the USGS. This maps contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.



2023


Order No. 25121700734

Available Quadrangle(s): Santa Fe, NM



Source: USGS 7.5 Minute Topographic Map

ERIS



2020


Order No. 25121700734

Available Quadrangle(s): Santa Fe, NM



Source: USGS 7.5 Minute Topographic Map

ERIS




2017

Order No. 25121700734



Available Quadrangle(s): Santa Fe, NM

Source: USGS 7.5 Minute Topographic Map



2013


Order No. 25121700734



Available Quadrangle(s): Santa Fe, NM

Source: USGS 7.5 Minute Topographic Map

ERIS



2002 (1-2002)

Aerial Photo Year: 1996


Order No. 25121700734

Available Quadrangle(s): Santa Fe, NM(1-2002)



Source: USGS 7.5 Minute Topographic Map

ERIS



1993 (1-1993)

Aerial Photo Year: 1990


Order No. 25121700734

Available Quadrangle(s): Santa Fe, NM(1-1993)



Source: USGS 7.5 Minute Topographic Map

ERIS



1977 (1-1977)


Aerial Photo Year: 1976
Photo Revision Year: 1977

Order No. 25121700734

Available Quadrangle(s): Santa Fe, NM(1-1977)



Source: USGS 7.5 Minute Topographic Map



1961 (1-1961)


Aerial Photo Year: 1960

Order No. 25121700734



Available Quadrangle(s): Santa Fe, NM(1-1961)

Source: USGS 7.5 Minute Topographic Map



1952 (1-1952)

Aerial Photo Year: 1951

Order No. 25121700734

Available Quadrangle(s): Santa Fe, NM(1-1952)



Source: USGS 7.5 Minute Topographic Map

APPENDIX C

Historical Aerial Photographs

HISTORICAL AERIALS

Project Property: New Method Cleaners
1911 St Michaels Dr
Santa Fe NM 87505

Project No: NMENV.M007.SF-WALDO

Requested By: INTERA Incorporated

Order No: 25121700734

Date Completed: December 19,2025

Aerial Maps included in this report are produced by the sources listed above and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property. ERIS provides no warranty of accuracy or liability. The information contained in this report has been produced using aerial photos listed in above sources by ERIS Information Inc. (in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS'. The maps contained in this report do not purport to be and do not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Date	Source	Scale	Comments
2022	United States Department of Agriculture	1" = 500'	
2020	United States Department of Agriculture	1" = 500'	
2018	United States Department of Agriculture	1" = 500'	
2016	United States Department of Agriculture	1" = 500'	
2014	United States Department of Agriculture	1" = 500'	
2011	United States Department of Agriculture	1" = 500'	
2009	United States Department of Agriculture	1" = 500'	
2005	United States Geological Survey	1" = 500'	
1996	United States Geological Survey	1" = 500'	
1991	United States Geological Survey	1" = 500'	
1981	United States Geological Survey	1" = 500'	
1975	United States Forest Service	1" = 500'	Adjacent Frame Unavailable
1968	Pacific Western Techonolgies	1" = 500'	
1960	United States Geological Survey	1" = 500'	
1951	United States Geological Survey	1" = 500'	
1948	United States Geological Survey	1" = 500'	
1935	Agricultural Stabilization & Conserv. Service	1" = 500'	




Year: 2022
Source: USDA
Scale: 1" = 500'
Comment:

Address: 1911 St Michaels Dr, Santa Fe, NM
Approx Center: -105.96852438,35.6599385

Order No: 25121700734

ERIS




Year: 2020
Source: USDA
Scale: 1" = 500'
Comment:

Address: 1911 St Michaels Dr, Santa Fe, NM
Approx Center: -105.96852438,35.6599385

Order No: 25121700734

ERIS




Year: 2018
Source: USDA
Scale: 1" = 500'
Comment:

Address: 1911 St Michaels Dr, Santa Fe, NM
Approx Center: -105.96852438,35.6599385

Order No: 25121700734

ERIS




Year: 2016
Source: USDA
Scale: 1" = 500'
Comment:

Address: 1911 St Michaels Dr, Santa Fe, NM
Approx Center: -105.96852438,35.6599385

Order No: 25121700734

ERIS




Year: 2014
Source: USDA
Scale: 1" = 500'
Comment:

Address: 1911 St Michaels Dr, Santa Fe, NM
Approx Center: -105.96852438,35.6599385

Order No: 25121700734

ERIS




Year: 2011
Source: USDA
Scale: 1" = 500'
Comment:

Address: 1911 St Michaels Dr, Santa Fe, NM
Approx Center: -105.96852438,35.6599385

Order No: 25121700734

ERIS




Year: 2009
Source: USDA
Scale: 1" = 500'
Comment:

Address: 1911 St Michaels Dr, Santa Fe, NM
Approx Center: -105.96852438,35.6599385

Order No: 25121700734

ERIS



Year: 2005
Source: USGS
Scale: 1" = 500'
Comment:

Address: 1911 St Michaels Dr, Santa Fe, NM
Approx Center: -105.96852438,35.6599385

Order No: 25121700734

ERIS




Year: 1996
Source: USGS
Scale: 1" = 500'
Comment:

Address: 1911 St Michaels Dr, Santa Fe, NM
Approx Center: -105.96852438,35.6599385

Order No: 25121700734

ERIS



Year: 1991
Source: USGS
Scale: 1" = 500'
Comment:

Address: 1911 St Michaels Dr, Santa Fe, NM
Approx Center: -105.96852438,35.6599385

Order No: 25121700734

ERIS



Year: 1981
Source: USGS
Scale: 1" = 500'
Comment:

Address: 1911 St Michaels Dr, Santa Fe, NM
Approx Center: -105.96852438,35.6599385

Order No: 25121700734

ERIS



Year: 1975
Source: USFS
Scale: 1" = 500'
Comment: Adjacent Frame Unavailable

Address: 1911 St Michaels Dr, Santa Fe, NM
Approx Center: -105.96852438,35.6599385

Order No: 25121700734

ERIS



Year: 1968
Source: PWT
Scale: 1" = 500'
Comment:

Address: 1911 St Michaels Dr, Santa Fe, NM
Approx Center: -105.96852438,35.6599385

Order No: 25121700734

ERIS



Year: 1960
Source: USGS
Scale: 1" = 500'
Comment:

Address: 1911 St Michaels Dr, Santa Fe, NM
Approx Center: -105.96852438,35.6599385

Order No: 25121700734

ERIS



Year: 1951
Source: USGS
Scale: 1" = 500'
Comment:

Address: 1911 St Michaels Dr, Santa Fe, NM
Approx Center: -105.96852438,35.6599385

Order No: 25121700734

ERIS



Year: 1948
Source: USGS
Scale: 1" = 500'
Comment:

Address: 1911 St Michaels Dr, Santa Fe, NM
Approx Center: -105.96852438,35.6599385

Order No: 25121700734

ERIS



Year: 1935
Source: ASCS
Scale: 1" = 500'
Comment:

Address: 1911 St Michaels Dr, Santa Fe, NM
Approx Center: -105.96852438,35.6599385

Order No: 25121700734

ERIS

APPENDIX D

Physical Setting Documentation

PSR
PHYSICAL SETTING REPORT

Property Information

Order Number:	25121700734p
Date Completed:	December 17, 2025
Project Number:	NMENV.M007.SF-WALDO
Project Property:	New Method Cleaners 1911 St Michaels Dr Santa Fe NM 87505
Coordinates:	
Latitude:	35.6599385
Longitude:	-105.96852438
UTM Northing:	3946663.70738 Meters
UTM Easting:	412334.635183 Meters
UTM Zone:	UTM Zone 13S
Elevation:	6,845.34 ft
Slope Direction:	W

Topographic Information....2
Hydrologic Information....4
Geologic Information....9
Soil Information....11
Wells and Additional Sources....20
Summary....21
Detail Report....27
Radon Information....356
Appendix....357
Liability Notice....359

The ERIS ***Physical Setting Report - PSR*** provides comprehensive information about the physical setting around a site and includes a complete overview of topography and surface topology, in addition to hydrologic, geologic and soil characteristics. The location and detailed attributes of oil and gas wells, water wells, public water systems and radon are also included for review.

The compilation of both physical characteristics of a site and additional attribute data is useful in assessing the impact of migration of contaminants and subsequent impact on soils and groundwater.

Disclaimer

This Report does not provide a full environmental evaluation for the site or adjacent properties. Please see the terms and disclaimer at the end of the Report for greater detail.

Topographic Information



Current USGS Topo (2023)

0 0.2 0.4 0.8 Miles

N

Quadrangle(s): Santa Fe,NM


Source: USGS 7.5 Minute Topographic Map

Topographic Information


The previous topographic map(s) are created by seamlessly merging and cutting current USGS topographic data. Below are shaded relief map(s), derived from USGS elevation data to show surrounding topography in further detail.

Topographic information at project property:

Elevation:	6,845.34 ft
Slope Direction:	W



Hydrologic Information



Wetland

0 0.075 0.15 0.3 Miles

N

This map shows wetland existence using data from US Fish & Wildlife.
Data coverage is shown to the right. Gray indicates no data available in the area.

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland
- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond
- Lake
- Other
- Riverine

ERIS

Hydrologic Information



Flood Hazard Zones

This map shows FEMA flood hazard zones based on FEMA's National Flood Hazard Layer. FIRM Panels are overlayed. An absent FIRM panel represents no data available.

Miles
0 0.05 0.1

N

- 1% Annual Chance Flood Hazard
- Regulatory Floodway
- Special Floodway
- Area of Undetermined Flood Hazard
- 0.2% Annual Chance Flood Hazard
- Future Conditions 1% Annual Chance Flood Hazard
- Area with Reduced Risk Due to Levee
- Area with Risk Due to Levee
- Open Water

Quadrangle(s): Santa Fe,NM

ERIS

Hydrologic Information

The Wetland Type map shows wetland existence overlaid on an aerial imagery. The Flood Hazard Zones map shows FEMA flood hazard zones overlaid on an aerial imagery. Relevant FIRM panels and detailed zone information is provided below.
For detailed Zone descriptions please click the link: https://floodadvocate.com/fema-zone-definitions

Available FIRM Panels in area:	35049C0413E(effective:2012-12-04) 35049C0411E(effective:2012-12-04) 35049C0414E(effective:2012-12-04) 35049C0412E(effective:2012-12-04)

Flood Zone AE-01

Zone:	AE
Zone subtype:	

Flood Zone X-01

Zone:	X
Zone subtype:	0.2 PCT ANNUAL CHANCE FLOOD HAZARD

Flood Zone X-12

Zone:	X
Zone subtype:	AREA OF MINIMAL FLOOD HAZARD

Hydrologic Information

FEMA Flood Zone Definitions

Special Flood Hazard Areas – High Risk

Special Flood Hazard Areas represent the area subject to inundation by 1-percent-annual chance flood. Structures located within the SFHA have a 26-percent chance of flooding during the life of a standard 30-year mortgage. Federal floodplain management regulations and mandatory flood insurance purchase requirements apply in these zones.

ZONE	DESCRIPTION
A	Areas subject to inundation by the 1-percent-annual-chance flood event. Because detailed hydraulic analyses have not been performed, no Base Flood Elevations (BFEs) or flood depths are shown.
AE, A1-A30	Areas subject to inundation by the 1-percent-annual-chance flood event determined by detailed methods. BFEs are shown within these zones. (Zone AE is used on new and revised maps in place of Zones A1–A30.)
AH	Areas subject to inundation by 1-percent-annual-chance shallow flooding (usually areas of ponding) where average depths are 1–3 feet. BFEs derived from detailed hydraulic analyses are shown in this zone.
AO	Areas subject to inundation by 1-percent-annual-chance shallow flooding (usually sheet flow on sloping terrain) where average depths are 1–3 feet. Average flood depths derived from detailed hydraulic analyses are shown within this zone.
AR	Areas that result from the decertification of a previously accredited flood protection system that is determined to be in the process of being restored to provide base flood protection.
A99	Areas subject to inundation by the 1-percent-annual-chance flood event, but which will ultimately be protected upon completion of an under-construction Federal flood protection system. These are areas of special flood hazard where enough progress has been made on the construction of a protection system, such as dikes, dams, and levees, to consider it complete for insurance rating purposes. Zone A99 may be used only when the flood protection system has reached specified statutory progress toward completion. No BFEs or flood depths are shown.

Coastal High Hazard Areas – High Risk

Coastal High Hazard Areas (CHHA) represent the area subject to inundation by 1-percent-annual chance flood, extending from offshore to the inland limit of a primary front al dune along an open coast and any other area subject to high velocity wave action from storms or seismic sources. Structures located within the CHHA have a 26-percent chance of flooding during the life of a standard 30-year mortgage. Federal floodplain management regulations and mandatory purchase requirements apply in these zones.

ZONE	DESCRIPTION
V	Areas along coasts subject to inundation by the 1-percent-annual-chance flood event with additional hazards associated with storm-induced waves. Because detailed coastal analyses have not been performed, no BFEs or flood depths are shown.
VE, V1-V30	Areas along coasts subject to inundation by the 1-percent-annual-chance flood event with additional hazards due to storm-induced velocity wave action. BFEs derived from detailed hydraulic coastal analyses are shown within these zones. (Zone VE is used on new and revised maps in place of Zones V1–V30.)

Hydrologic Information

Moderate and Minimal Risk Areas


Areas of moderate or minimal hazard are studied based upon the principal source of flood in the area. However, buildings in these zones could be flooded by severe, concentrated rainfall coupled with inadequate local drainage systems. Local stormwater drainage systems are not normally considered in a community's flood insurance study. The failure of a local drainage system can create areas of high flood risk within these zones. Flood insurance is available in participating communities, but is not required by regulation in these zones. Nearly 25-percent of all flood claims filed are for structures located within these zones.

ZONE	DESCRIPTION
B, X (shaded)	Moderate risk areas within the 0.2-percent-annual-chance floodplain, areas of 1-percent-annual-chance flooding where average depths are less than 1 foot, areas of 1-percent-annual-chance flooding where the contributing drainage area is less than 1 square mile, and areas protected from the 1-percent-annual-chance flood by a levee. No BFEs or base flood depths are shown within these zones. (Zone X (shaded) is used on new and revised maps in place of Zone B.)
C, X (unshaded)	Minimal risk areas outside the 1-percent and .2-percent-annual-chance floodplains. No BFEs or base flood depths are shown within these zones. (Zone X (unshaded) is used on new and revised maps in place of Zone C.)

Undetermined Risk Areas

ZONE	DESCRIPTION
D	Unstudied areas where flood hazards are undetermined, but flooding is possible. No mandatory flood insurance purchase requirements apply, but coverage is available in participating communities.

Geologic Information



Geologic Units

This maps shows geologic units in the area. Please refer to the report for detailed descriptions.

N

0 0.125 0.25 Miles

ERIS

Geologic Information

The previous page shows USGS geology information. Detailed information about each unit is provided below.


Geologic Unit Qp

Unit Name:	Piedmont alluvial deposits
Unit Age:	Holocene to lower Pleistocene
Primary Rock Type:	Unconsolidated
Secondary Rock Type:	
Unit Description:	Includes deposits of higher gradient tributaries bordering major stream valleys, alluvial veneers of the piedmont slope, and alluvial fans. May locally include uppermost Pliocene deposits.

Geologic Unit QTs

Unit Name:	Upper Santa Fe Group
Unit Age:	Middle Pleistocene to uppermost Miocene
Primary Rock Type:	Conglomerate-sandstone
Secondary Rock Type:	Coarse-detrital
Unit Description:	Includes Camp Rice, Fort Hancock, Palomas, Sierra Ladrones, Arroyo Ojito, Ancha, Puye, and Alamosa Formations.

Soil Information



SSURGO Soils

N

0 0.125 0.25 Miles

This maps shows SSURGO soil units around the target property. Please refer to the report for detailed soil descriptions.

ERIS

Soil Information

The previous page shows a soil map using SSURGO data from USDA Natural Resources Conservation Service. Detailed information about each unit is provided below.

Map Unit 103 (0.1%)

Map Unit Name:	Zepol silt loam, 0 to 2 percent slopes, flooded
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	B - Soils in this group have moderately low runoff potential when thoroughly wet. Water transmission through the soil is unimpeded.

Major components are printed below

Zepol(85%)

horizon AC1(0cm to 8cm)	Silt loam
horizon AC2(8cm to 15cm)	Silt loam
horizon Bt1(15cm to 30cm)	Silt loam
horizon Bt2(30cm to 56cm)	Silty clay loam
horizon Bt3(56cm to 69cm)	Silt loam
horizon Btk1(69cm to 89cm)	Silt loam
horizon Btk2(89cm to 117cm)	Silt loam
horizon Bk1(117cm to 190cm)	Silt loam
horizon Bk2(190cm to 226cm)	Silt loam
horizon BCk(226cm to 290cm)	Loam

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 103 - Zepol silt loam, 0 to 2 percent slopes, flooded

Component: Zepol (85%)
The Zepol component makes up 85 percent of the map unit. Slopes are 0 to 2 percent. This component is on narrow flood plains on eroded fan remnants, fan piedmonts. The parent material consists of alluvium derived from loess, volcanic ash, pumice, basalt lapilli, granite, and schist. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is high. Shrink-swell potential is moderate. This soil is occasionally flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 3 percent. This component is in the R035XA112NM Loamy ecological site. Nonirrigated land capability classification is 6c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 4 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Zia (6%)
Generated brief soil descriptions are created for major soil components. The Zia soil is a minor component.

Component: Chupe (5%)
Generated brief soil descriptions are created for major soil components. The Chupe soil is a minor component.

Component: Khapo (4%)
Generated brief soil descriptions are created for major soil components. The Khapo soil is a minor component.

Map Unit 114 (24.26%)

Map Unit Name:	Devargas-Urban land complex, 1 to 3 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained

Soil Information

Hydrologic Group - Dominant:	C - Soils in this group have moderately high runoff potential when thoroughly wet. Water transmission through the soil is somewhat restricted.

Major components are printed below

Devargas(50%)

horizon A(0cm to 5cm)	Loam
horizon Bt1(5cm to 23cm)	Loam
horizon Bt2(23cm to 43cm)	Clay loam
horizon Btk1(43cm to 63cm)	Clay loam
horizon Btk2(63cm to 76cm)	Loam
horizon Bk(76cm to 84cm)	Very gravelly coarse sandy loam
horizon 2BCk(84cm to 107cm)	Extremely gravelly loamy coarse sand
horizon 2C1(107cm to 170cm)	Extremely cobbly coarse sand
horizon 2C2(170cm to 216cm)	Extremely gravelly loamy coarse sand
horizon 2C3(216cm to 239cm)	Very gravelly coarse sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 114 - Devargas-Urban land complex, 1 to 3 percent slopes

Component: Devargas (50%)
The Devargas component makes up 50 percent of the map unit. Slopes are 1 to 3 percent. This component is on high stream terraces, valleys. The parent material consists of alluvium derived from sandstone over alluvium derived from granite, gneiss, and schist. Depth to a root restrictive layer, strongly contrasting textural stratification, is 28 to 31 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the R035XA112NM Loamy ecological site. Nonirrigated land capability classification is 6c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 4 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Urban land (45%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Delvalle (3%)
Generated brief soil descriptions are created for major soil components. The Delvalle soil is a minor component.

Component: Panky (1%)
Generated brief soil descriptions are created for major soil components. The Panky soil is a minor component.

Component: Dumps (1%)
Generated brief soil descriptions are created for major soil components. The Dumps soil is a minor component.

Map Unit 200 (5.45%)

Map Unit Name:	Predawn loam, 1 to 4 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	C - Soils in this group have moderately high runoff potential when thoroughly wet. Water transmission through the soil is somewhat restricted.

Major components are printed below

Predawn(90%)

horizon A(0cm to 5cm)	Loam
horizon BA(5cm to 10cm)	Loam
horizon Bt(10cm to 23cm)	Clay loam
horizon Btk1(23cm to 36cm)	Clay loam
horizon Btk2(36cm to 48cm)	Clay loam

horizon Bk1(48cm to 69cm)	Loam
horizon Bk2(69cm to 91cm)	Loam
horizon BCk1(91cm to 132cm)	Gravelly sandy loam
horizon BCk2(132cm to 196cm)	Very gravelly coarse sand
horizon C(196cm to 218cm)	Gravelly loamy sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 200 - Predawn loam, 1 to 4 percent slopes

Component: Predawn (90%)
The Predawn component makes up 90 percent of the map unit. Slopes are 1 to 4 percent. This component is on eroded fan remnants, fan piedmonts. The parent material consists of alluvium derived from granite, gneiss, schist, loess, and volcanic ash. Depth to a root restrictive layer, abrupt textural change, is 2 to 6 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately low. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the R035XA112NM Loamy ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 33 percent. The soil has a slightly saline horizon within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 9 within 30 inches of the soil surface.

Component: Alire (6%)
Generated brief soil descriptions are created for major soil components. The Alire soil is a minor component.

Component: Encantado (3%)
Generated brief soil descriptions are created for major soil components. The Encantado soil is a minor component.

Component: Urban land (1%)
Generated brief soil descriptions are created for major soil components. The Urban land soil is a minor component.

Map Unit 203 (0.47%)

Map Unit Name:	Buckhorse-Altazano complex, 2 to 8 percent slopes, flooded
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	B - Soils in this group have moderately low runoff potential when thoroughly wet. Water transmission through the soil is unimpeded.

Major components are printed below

Buckhorse(55%)

horizon A(0cm to 10cm)	Coarse sandy loam
horizon Bt(10cm to 28cm)	Coarse sandy loam
horizon Btk1(28cm to 56cm)	Loam
horizon Btk2(56cm to 94cm)	Loam
horizon Bk(94cm to 124cm)	Fine sandy loam
horizon BCk(124cm to 155cm)	Sandy loam
horizon C(155cm to 211cm)	Gravelly coarse sand

Altazano(35%)

horizon AC(0cm to 5cm)	Gravelly sandy loam
horizon C1(5cm to 20cm)	Gravelly coarse sandy loam
horizon C2(20cm to 48cm)	Very gravelly loamy coarse sand
horizon C3(48cm to 74cm)	Gravelly sandy loam
horizon Btkb1(74cm to 117cm)	Loam
horizon Btkb2(117cm to 165cm)	Loam
horizon BCkb(165cm to 188cm)	Gravelly coarse sandy loam
horizon Ckb(188cm to 229cm)	Gravelly loamy coarse sand

Soil Information

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 203 - Buckhorse-Altazano complex, 2 to 8 percent slopes, flooded

Component: Buckhorse (55%)
The Buckhorse component makes up 55 percent of the map unit. Slopes are 2 to 8 percent. This component is on eroded fan remnants, fan piedmonts. The parent material consists of slope alluvium derived from granite, gneiss, schist, granitic sandstone, fanglomerate, and mudstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the R035XA112NM Loamy ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 10 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Altazano (35%)
The Altazano component makes up 35 percent of the map unit. Slopes are 2 to 8 percent. This component is on eroded fan remnants, fan piedmonts. The parent material consists of slope alluvium derived from granite, gneiss, schist, granitic sandstone, fanglomerate, and mudstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is frequently flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the R035XG114NM Gravelly ecological site. Nonirrigated land capability classification is 4w. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 13 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Junebee (4%)
Generated brief soil descriptions are created for major soil components. The Junebee soil is a minor component.

Component: Tanoan (3%)
Generated brief soil descriptions are created for major soil components. The Tanoan soil is a minor component.

Component: Riverwash (2%)
Generated brief soil descriptions are created for major soil components. The Riverwash soil is a minor component.

Component: Urban land (1%)
Generated brief soil descriptions are created for major soil components. The Urban land soil is a minor component.

Map Unit 204 (0.16%)

Map Unit Name:	Altazano loamy sand, 0 to 2 percent slopes, flooded
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Somewhat excessively drained
Hydrologic Group - Dominant:	B - Soils in this group have moderately low runoff potential when thoroughly wet. Water transmission through the soil is unimpeded.
Major components are printed below	
Altazano(85%)	
horizon AC(0cm to 8cm)	Loamy sand
horizon C1(8cm to 20cm)	Fine sandy loam
horizon C2(20cm to 30cm)	Loamy sand
horizon C3(30cm to 46cm)	Stratified sandy loam to loam
horizon C4(46cm to 66cm)	Gravelly loamy coarse sand
horizon Btkb1(66cm to 74cm)	Loam
horizon Btkb2(74cm to 91cm)	Loam
horizon Bkb(91cm to 147cm)	Loam
horizon BCkb1(147cm to 193cm)	Gravelly coarse sandy loam
horizon BCkb2(193cm to 234cm)	Gravelly coarse sand

Soil Information

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 204 - Altazano loamy sand, 0 to 2 percent slopes, flooded

Component: Altazano (85%)
The Altazano component makes up 85 percent of the map unit. Slopes are 0 to 2 percent. This component is on flood plains on valley floors, valleys. The parent material consists of alluvium derived from granite, gneiss, schist, granitic sandstone, fanglomerate, and mudstone. Depth to a root restrictive layer, strongly contrasting textural stratification, is 22 to 30 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is low. This soil is occasionally flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the R035XG114NM Gravelly ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 4 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Buckhorse (5%)
Generated brief soil descriptions are created for major soil components. The Buckhorse soil is a minor component.

Component: Levante (3%)
Generated brief soil descriptions are created for major soil components. The Levante soil is a minor component.

Component: Tanoan (3%)
Generated brief soil descriptions are created for major soil components. The Tanoan soil is a minor component.

Component: Riverwash (2%)
Generated brief soil descriptions are created for major soil components. The Riverwash soil is a minor component.

Component: Urban land (2%)
Generated brief soil descriptions are created for major soil components. The Urban land soil is a minor component.

Map Unit 207 (41.98%)

Map Unit Name: Urban land

No more attributes available for this map unit

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 207 - Urban land

Component: Urban land (85%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Alire (4%)
Generated brief soil descriptions are created for major soil components. The Alire soil is a minor component.

Component: Panky (3%)
Generated brief soil descriptions are created for major soil components. The Panky soil is a minor component.

Component: Altazano (2%)
Generated brief soil descriptions are created for major soil components. The Altazano soil is a minor component.

Component: Buckhorse (2%)
Generated brief soil descriptions are created for major soil components. The Buckhorse soil is a minor component.

Component: Predawn (2%)
Generated brief soil descriptions are created for major soil components. The Predawn soil is a minor component.

Component: Delvalle (1%)
Generated brief soil descriptions are created for major soil components. The Delvalle soil is a minor component.

Component: Tanoan (1%)
Generated brief soil descriptions are created for major soil components. The Tanoan soil is a minor component.

Map Unit 208 (26.01%)

Map Unit Name:	Alire-Urban land complex, 2 to 8 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	C - Soils in this group have moderately high runoff potential when thoroughly wet. Water transmission through the soil is somewhat restricted.

Major components are printed below

Alire(50%)

horizon A(0cm to 10cm)	Loam
horizon Bt(10cm to 28cm)	Clay loam
horizon Btk1(28cm to 51cm)	Clay loam
horizon Btk2(51cm to 69cm)	Loam
horizon Bk1(69cm to 107cm)	Loam
horizon Bk2(107cm to 130cm)	Gravelly loam
horizon Bkq1(130cm to 175cm)	Gravelly loam
horizon Bkq2(175cm to 241cm)	Gravelly loam
horizon C(241cm to 251cm)	Gravelly sandy loam

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 208 - Alire-Urban land complex, 2 to 8 percent slopes

Component: Alire (50%)
The Alire component makes up 50 percent of the map unit. Slopes are 2 to 8 percent. This component is on beveled eroded fan remnants, fan piedmonts. The parent material consists of alluvium derived from granite, gneiss, schist, and loess. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is high. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the R035XA112NM Loamy ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 23 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 9 within 30 inches of the soil surface.

Component: Urban land (40%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Predawn (4%)
Generated brief soil descriptions are created for major soil components. The Predawn soil is a minor component.

Component: Tanoan (3%)
Generated brief soil descriptions are created for major soil components. The Tanoan soil is a minor component.

Component: Altazano (2%)
Generated brief soil descriptions are created for major soil components. The Altazano soil is a minor component.

Component: Encantado (1%)
Generated brief soil descriptions are created for major soil components. The Encantado soil is a minor component.

Map Unit 211 (1.58%)

Map Unit Name:	Tanoan-Encantado-Urban land complex, 5 to 25 percent slopes
Bedrock Depth - Min:	

Soil Information

Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Somewhat excessively drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.

Major components are printed below

Tanoan(35%)

horizon A(0cm to 8cm)	Gravelly sandy loam
horizon Bk1(8cm to 18cm)	Loam
horizon Bk2(18cm to 61cm)	Loam
horizon Bk3(61cm to 81cm)	Sandy loam
horizon Bkq(81cm to 145cm)	Loam
horizon BCk1(145cm to 178cm)	Gravelly loamy coarse sand
horizon BCk2(178cm to 213cm)	Gravelly coarse sandy loam

Encantado(30%)

horizon ABk(0cm to 8cm)	Very gravelly sandy loam
horizon Bk1(8cm to 23cm)	Very gravelly loam
horizon Bk2(23cm to 56cm)	Very gravelly coarse sandy loam
horizon BCk1(56cm to 84cm)	Gravelly loamy coarse sand
horizon BCk2(84cm to 114cm)	Very gravelly loamy coarse sand
horizon BCk3(114cm to 137cm)	Very gravelly loamy coarse sand
horizon C1(137cm to 160cm)	Gravelly loamy sand
horizon C2(160cm to 216cm)	Very gravelly loamy sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 211 - Tanoan-Encantado-Urban land complex, 5 to 25 percent slopes

Component: Tanoan (35%)
The Tanoan component makes up 35 percent of the map unit. Slopes are 5 to 15 percent. This component is on eroded fan remnants, fan piedmonts. The parent material consists of alluvium derived from granite, gneiss, schist, and loess over residuum weathered from basaltic tuff or granitic sandstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the F036XA136NM Pinyon-juniper-apache Plume ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 15 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Encantado (30%)
The Encantado component makes up 30 percent of the map unit. Slopes are 10 to 25 percent. This component is on eroded fan remnants, fan piedmonts. The parent material consists of colluvium and slope alluvium derived from granite, gneiss, and schist over residuum weathered from granitic fanglomerate and sandstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the F036XA136NM Pinyon-juniper-apache Plume ecological site. Nonirrigated land capability classification is 4s. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 27 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Urban land (25%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Altazano (4%)
Generated brief soil descriptions are created for major soil components. The Altazano soil is a minor component.


Component: Junebee (3%)
Generated brief soil descriptions are created for major soil components. The Junebee soil is a minor component.

Component: Nazario (2%)
Generated brief soil descriptions are created for major soil components. The Nazario soil is a minor component.

Soil Information

Component: Alire (1%)
Generated brief soil descriptions are created for major soil components. The Alire soil is a minor component.

Wells and Additional Sources



Wells & Additional Sources

N

0 0.15 0.3 0.6 Miles

- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- OGW Sites with Higher Elevation
- OGW Sites with Same Elevation
- OGW Sites with Lower Elevation
- OGW Sites with Unknown Elevation

ERIS

Wells and Additional Sources Summary

Federal Sources

Public Water Systems Violations and Enforcement Data

Map Key	PWS ID	Distance (ft)	Direction
157	NM3593519	4675.76	NE
157	NM3590218	4675.76	NE
157	NM3590231	4675.76	NE
196	NM3510225	5057.78	E
202	NM3581326	5104.47	S

Safe Drinking Water Information System (SDWIS)

Map Key	PWS ID	Distance (ft)	Direction
157	NM3590218	4675.76	NE
157	NM3593519	4675.76	NE
157	NM3590231	4675.76	NE
196	NM3510225	5057.78	E
202	NM3581326	5104.47	S

USGS National Water Information System

Map Key	Site No	Distance (ft)	Direction
2	USGS-353933105575601	681.08	ESE
7	USGS-353925105575201	1404.92	SE
12	USGS-353945105574501	1822.45	ENE
12	USGS-353945105574503	1822.45	ENE
12	USGS-353945105574502	1822.45	ENE
42	USGS-353948105573201	2921.80	ENE
47	USGS-353916105573201	3254.72	SE
66	USGS-353900105580001	3531.81	S
75	USGS-354013105580601	3652.37	N
79	USGS-353933105585101	3784.76	W
83	USGS-353908105573201	3787.21	SE
88	USGS-353907105583701	3869.15	SW
97	USGS-353906105583801	3999.28	SW
167	USGS-353922105570801	4794.16	ESE
223	USGS-354006105585801	5276.52	NW

State Sources

Oil and Gas Wells

Map Key	ID	Distance (ft)	Direction
	No records found		

Point of Diversion Report

Map Key	POD Rec No	Distance (ft)	Direction
1	174796	218.98	NE
1	174796	218.98	NE

Wells and Additional Sources Summary

4	264936	1384.54	WSW
5	20878	1342.59	NNW
6	35998	1374.56	N
8	264937	1491.51	WNW
9	18815	1536.09	SSE
10	264938	1558.13	WNW
11	40912	1674.19	SSE
13	304918	1797.18	SW
14	9001	1872.75	ENE
15	64008	1931.44	SW
16	53640	1985.77	NW
17	13204	1993.66	SSE
18	47567	2058.15	NW
19	12254	2203.54	NNE
20	26352	2220.44	N
21	50778	2276.02	NNE
22	289866	2318.45	SW
23	193400	2360.30	NE
24	289817	2363.07	SW
24	289816	2363.07	SW
24	289832	2363.07	SW
24	289830	2363.07	SW
24	289815	2363.07	SW
24	289822	2363.07	SW
24	289837	2363.07	SW
24	289833	2363.07	SW
24	289824	2363.07	SW
24	289823	2363.07	SW
24	289829	2363.07	SW
24	289827	2363.07	SW
24	289831	2363.07	SW
24	289835	2363.07	SW
24	289818	2363.07	SW
24	289821	2363.07	SW
24	289814	2363.07	SW
24	289826	2363.07	SW
24	289828	2363.07	SW
24	289836	2363.07	SW
24	289820	2363.07	SW
24	289838	2363.07	SW
24	289825	2363.07	SW
24	289819	2363.07	SW
25	289862	2434.94	SW
26	35556	2468.63	NE
27	177055	2461.09	N
28	18058	2470.69	SSE
29	289810	2493.81	SSW
29	289811	2493.81	SSW
29	289809	2493.81	SSW
29	289808	2493.81	SSW
29	289813	2493.81	SSW
29	289812	2493.81	SSW
30	289863	2538.59	SW
30	289864	2538.59	SW
30	289865	2538.59	SW
30	289867	2538.59	SW
31	25717	2584.63	ENE
32	48042	2659.69	ENE
33	289871	2628.98	SW
33	289869	2628.98	SW
33	289872	2628.98	SW
33	289868	2628.98	SW
33	289870	2628.98	SW
33	289873	2628.98	SW
34	289853	2643.93	SW
34	289846	2643.93	SW

34	289842	2643.93	SW
34	289852	2643.93	SW
34	289859	2643.93	SW
34	289860	2643.93	SW
34	289854	2643.93	SW
34	289858	2643.93	SW
34	289845	2643.93	SW
34	289848	2643.93	SW
34	289861	2643.93	SW
34	289857	2643.93	SW
34	289841	2643.93	SW
34	289843	2643.93	SW
34	289844	2643.93	SW
34	289850	2643.93	SW
34	289849	2643.93	SW
34	289856	2643.93	SW
34	289847	2643.93	SW
34	289840	2643.93	SW
34	289851	2643.93	SW
34	289839	2643.93	SW
34	289855	2643.93	SW
35	146964	2655.74	NNE
36	339403	2666.60	WNW
37	283516	2695.82	SW
38	4922	2754.14	ENE
39	10205	2763.96	NW
40	10092	2790.23	NE
41	42763	2843.67	NE
43	54438	3022.42	NE
43	59990	3022.42	NE
44	49038	3014.27	NW
45	291265	3071.55	NW
46	8325	3216.31	NW
48	6730	3288.94	NE
49	51436	3305.34	N
50	40391	3399.75	NW
51	291277	3422.04	NW
52	305038	3475.63	W
53	343038	3488.27	W
54	343041	3499.83	W
55	343037	3509.84	W
56	305037	3513.65	W
57	325609	3489.54	WNW
58	304643	3522.95	W
59	343040	3525.77	W
60	305036	3531.25	W
61	27181	3502.09	NNW
62	343039	3550.46	W
63	343042	3553.66	W
64	27748	3526.51	SSW
65	30276	3539.01	WNW
67	13282	3537.95	SSE
67	161567	3537.95	SSE
68	343043	3613.50	W
69	19752	3586.14	SW
70	304644	3641.29	W
71	67648	3600.15	SE
72	305035	3647.19	W
73	3923	3641.73	SW
74	15389	3660.81	W
76	33899	3703.41	NNE
77	325604	3721.16	NW
78	60802	3742.94	NW
80	28861	3744.00	NW
81	33631	3756.10	NW
82	189490	3775.92	NNW

84	23926	3820.99	W
85	24662	3805.44	WNW
86	64690	3821.07	WNW
87	291276	3827.68	NW
89	4330	3919.72	SW
89	10563	3919.72	SW
89	65894	3919.72	SW
89	15437	3919.72	SW
89	190415	3919.72	SW
89	59549	3919.72	SW
90	339114	3909.43	NNE
91	54566	3908.09	NW
92	17094	3927.89	SSW
93	49565	3927.53	NNW
94	37998	3984.14	WNW
95	21326	3976.29	SW
95	30686	3976.29	SW
95	192804	3976.29	SW
95	328083	3976.29	SW
95	6904	3976.29	SW
96	13190	3975.62	SSW
98	340741	4055.33	SSW
99	340738	4062.35	SSW
100	325646	4076.39	NNW
101	340740	4085.77	SSW
102	57940	4087.00	NNW
103	340739	4088.68	SSW
104	340737	4092.76	SSW
105	44289	4097.62	SE
106	340736	4096.51	SSW
107	5367	4161.72	SSE
108	8941	4228.62	NW
109	52363	4229.48	NW
109	287003	4229.48	NW
110	35609	4231.49	NNW
111	337726	4235.46	NNW
111	37406	4235.46	NNW
112	5411	4266.20	SSW
113	61378	4290.99	SSE
114	67631	4307.66	WNW
115	49375	4320.19	WNW
116	55508	4343.06	ESE
117	325634	4355.96	NNW
118	69585	4367.77	SSW
119	32953	4372.56	WNW
120	32346	4376.02	SE
120	18445	4376.02	SE
120	3704	4376.02	SE
121	49938	4384.12	NW
121	333202	4384.12	NW
122	52939	4407.88	NW
123	50209	4452.74	ENE
123	7104	4452.74	ENE
124	42431	4413.76	NNW
125	41159	4437.20	SW
125	51197	4437.20	SW
125	58616	4437.20	SW
126	59389	4431.64	NW
127	40996	4435.51	SSW
128	61486	4448.47	NNE
129	282443	4441.51	SSE
130	23581	4450.71	WNW
131	44430	4454.49	NNE
131	31584	4454.49	NNE
132	181277	4500.84	W
133	39428	4455.62	NW

134	54256	4470.46	ESE
135	46643	4467.25	SSW
136	16666	4515.12	ENE
137	62930	4480.58	NW
138	7016	4480.75	NW
139	33563	4499.79	WNW
140	334340	4496.82	SE
141	36482	4574.81	W
141	29277	4574.81	W
142	8591	4583.13	ENE
143	26603	4556.85	SSW
143	65129	4556.85	SSW
144	51419	4572.56	SSW
145	68392	4571.18	NW
146	230372	4593.87	SSW
147	291256	4596.47	NW
148	334455	4606.80	WNW
149	52690	4630.19	NW
150	199128	4646.84	ESE
151	8067	4633.66	NNW
152	44856	4640.92	SSW
153	61622	4636.53	NW
154	46210	4649.61	SSW
155	3857	4704.32	WSW
156	3071	4650.80	NW
158	242466	4660.14	SSW
159	62757	4670.52	SSW
160	165194	4688.97	SSE
161	17131	4729.39	SSW
162	51536	4730.27	NNW
163	60902	4800.39	ENE
164	202403	4747.96	SSW
165	335262	4777.72	WNW
166	40390	4773.34	ESE
168	70667	4833.64	ENE
169	9522	4827.09	W
170	179805	4807.29	SSW
171	9856	4832.66	SSW
172	60094	4863.67	W
172	6722	4863.67	W
173	4327	4843.09	SE
174	51067	4854.92	SE
175	49312	4859.33	SSW
176	59563	4890.61	E
177	10125	4901.77	SSW
178	51166	4896.90	NW
179	19821	4943.29	W
180	328923	4910.35	SSW
181	198001	4928.25	ESE
182	284474	4909.47	N
183	63913	4915.26	NNW
184	17739	4956.53	E
185	51857	4936.26	SW
186	68364	4957.00	WNW
187	22801	4966.12	NW
188	58191	4970.86	SSW
188	69486	4970.86	SSW
188	8137	4970.86	SSW
189	52095	4990.51	SSW
189	21000	4990.51	SSW
189	12732	4990.51	SSW
190	192850	5001.84	SSW
191	36673	5017.67	ESE
192	16648	5010.85	NW
193	7850	5024.43	WNW
194	18588	5028.29	SSW

195	50390	5032.21	NW
197	15451	5035.25	NW
198	331159	5045.92	ESE
199	39891	5055.72	SSW
200	15632	5108.63	SW
201	44581	5119.20	SW
203	36563	5115.53	NW
204	58891	5119.91	NW
205	42505	5133.74	WNW
205	60986	5133.74	WNW
206	186588	5133.23	WNW
207	51486	5179.63	W
208	26402	5204.52	WSW
208	20514	5204.52	WSW
208	63762	5204.52	WSW
209	14615	5163.24	SSW
210	54089	5157.62	SSW
211	51242	5206.03	W
212	61976	5186.70	SW
213	16176	5214.80	SW
214	62730	5227.66	E
215	70300	5230.69	W
215	46452	5230.69	W
215	47640	5230.69	W
216	54204	5211.27	WNW
217	325631	5223.02	SW
218	223314	5247.05	NE
218	223401	5247.05	NE
219	7550	5243.55	NNW
219	67083	5243.55	NNW
219	42626	5243.55	NNW
220	327476	5266.77	ESE
221	67733	5255.98	WNW
221	21794	5255.98	WNW
221	39933	5255.98	WNW
221	328592	5255.98	WNW
222	339490	5266.71	NNW

Public Water Supply Wells

Map Key	TINWSF Is No	Distance (ft)	Direction
3	1948	817.90	ESE

Public Water Systems Violations and Enforcement Data

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
157	NE	0.89	4,675.76	6,935.82	PWSV

PWS ID:	NM3593519
PWS Type Code:	TNCWS
PWS Type Description:	Transient non-community system
Primary Source Code:	GW
Primary Source Desc:	Ground water
PWS Activity Code:	A
PWS Activity Description:	Active
PWS Deactivation Date:	
Zip Code:	87505
Phone No:	505-699-4669
Phone Ext No:	
Admin Name:	BAKER, COLLEEN
Alt Phone No:	
Email Addr:	colleen.baker@emnrd.nm.gov
Fax No:	
Cds ID:	
Population Served Count:	150
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	01/10/1981
Gw or Sw:	Groundwater
Gw Sw Code:	GW
Is Grant Eligible Ind:	Yes
Outstanding Performer:	
Is School or Daycare Ind:	No
Is Source Water Protection:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Lt2 Schedule Cat Code:	
Last Reported Date:	06/25/2025
Org Name:	BAKER, COLLEEN
Outstanding Perform Begin Date:	
Owner Type:	State government
Pop Cat 11:	101-500
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Season Begin Date:	01-01

Wells and Additional Sources Detail Report

Season End Date:	12-31
Service Connections Count:	29
Submission Status Code:	Y
Submissionyearquarter:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin Date:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	ALAMOGORDO
County Served:	Otero
Source Water Protection Code:	N

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
157	NE	0.89	4,675.76	6,935.82	PWSV

PWS ID:	NM3590218
PWS Type Code:	TNCWS
PWS Type Description:	Transient non-community system
Primary Source Code:	GW
Primary Source Desc:	Ground water
PWS Activity Code:	A
PWS Activity Description:	Active
PWS Deactivation Date:	
Zip Code:	87505
Phone No:	505-699-4669
Phone Ext No:	
Admin Name:	BAKER, COLLEEN
Alt Phone No:	
Email Addr:	colleen.baker@emnrd.nm.gov
Fax No:	
Cds ID:	
Population Served Count:	50
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	03/12/1980
Gw or Sw:	Groundwater
Gw Sw Code:	GW
Is Grant Eligible Ind:	Yes
Outstanding Performer:	
Is School or Daycare Ind:	No

Is Source Water Protection:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Lt2 Schedule Cat Code:	
Last Reported Date:	06/25/2025
Org Name:	BAKER, COLLEEN
Outstanding Perform Begin Date:	
Owner Type:	State government
Pop Cat 11:	<=100
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	23
Submission Status Code:	Y
Submissionyearquarter:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin Date:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	GUADALUPITA
County Served:	Mora
Source Water Protection Code:	N

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
157	NE	0.89	4,675.76	6,935.82	PWSV

PWS ID:	NM3590231
PWS Type Code:	TNCWS
PWS Type Description:	Transient non-community system
Primary Source Code:	GW
Primary Source Desc:	Ground water
PWS Activity Code:	A
PWS Activity Description:	Active
PWS Deactivation Date:	
Zip Code:	87505

Wells and Additional Sources Detail Report

Phone No:	505-699-4669
Phone Ext No:	
Admin Name:	BAKER, COLLEEN
Alt Phone No:	
Email Addr:	colleen.baker@emnrd.nm.gov
Fax No:	
Cds ID:	
Population Served Count:	178
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	03/12/1980
Gw or Sw:	Groundwater
Gw Sw Code:	GW
Is Grant Eligible Ind:	Yes
Outstanding Performer:	
Is School or Daycare Ind:	No
Is Source Water Protection:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Lt2 Schedule Cat Code:	
Last Reported Date:	06/25/2025
Org Name:	BAKER, COLLEEN
Outstanding Perform Begin Date:	
Owner Type:	State government
Pop Cat 11:	101-500
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	1
Submission Status Code:	Y
Submissionyearquarter:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin Date:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	CLAYTON
County Served:	Union

Wells and Additional Sources Detail Report

Source Water Protection Code: N

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
196	E	0.96	5,057.78	6,963.35	PWSV

PWS ID: NM3510225
PWS Type Code: CWS
PWS Type Description: Community water system
Primary Source Code: GW
Primary Source Desc: Ground water
PWS Activity Code: I
PWS Activity Description: Inactive
PWS Deactivation Date: 08/01/2002
Zip Code: 87505
Phone No: 505-421-2270
Phone Ext No:
Admin Name: AMADEO ARAGON
Alt Phone No:
Email Addr:
Fax No:
Cds ID:
Population Served Count: 60
Epa Region Desc: Region 6
Epa Region: 06
First Reported Date: 07/01/1987
Gw or Sw: Groundwater
Gw Sw Code: GW
Is Grant Eligible Ind: No
Outstanding Performer:
Is School or Daycare Ind: No
Is Source Water Protection:
Is Wholesaler Ind: No
Lt2 Schedule Cat:
Lt2 Schedule Cat Code:
Last Reported Date: 07/11/2005
Org Name:
Outstanding Perform Begin Date:
Owner Type: Private
Pop Cat 11: <=100
Pop Cat 2: <10,000
Pop Cat 3: <=3300
Pop Cat 4: <10K
Pop Cat 5: <=500
Primacy Agency: New Mexico
Season Begin Date: 01-01

Wells and Additional Sources Detail Report

Season End Date:	12-31
Service Connections Count:	12
Submission Status Code:	Y
Submissionyearquarter:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin Date:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	
County Served:	San Miguel
Source Water Protection Code:	

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
202	S	0.97	5,104.47	6,817.64	PWSV

PWS ID:	NM3581326
PWS Type Code:	NTNCWS
PWS Type Description:	Non-Transient non-community system
Primary Source Code:	GW
Primary Source Desc:	Ground water
PWS Activity Code:	N
PWS Activity Description:	Changed from public to non-public
PWS Deactivation Date:	01/25/2012
Zip Code:	87507
Phone No:	505-470-6351
Phone Ext No:	
Admin Name:	BUTLER, JIM
Alt Phone No:	
Email Addr:	
Fax No:	
Cds ID:	
Population Served Count:	441
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	11/25/1992
Gw or Sw:	Groundwater
Gw Sw Code:	GW
Is Grant Eligible Ind:	No
Outstanding Performer:	
Is School or Daycare Ind:	Yes

Is Source Water Protection:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Lt2 Schedule Cat Code:	
Last Reported Date:	06/25/2025
Org Name:	BUTLER, JIM
Outstanding Perform Begin Date:	
Owner Type:	Local government
Pop Cat 11:	101-500
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	1
Submission Status Code:	Y
Submissionyearquarter:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin Date:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	SANTA FE
County Served:	Santa Fe
Source Water Protection Code:	N

Safe Drinking Water Information System (SDWIS)

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
157	NE	0.89	4,675.76	6,935.82	SDWIS

PWS ID:	NM3590218
PWS Type Code:	TNCWS
PSW Type:	Transient non-community system
Primary Source Code:	GW
Primary Source:	Ground water
Pws Activity Code:	A
Activity:	Active
PWS Deactivation Dt:	

Wells and Additional Sources Detail Report

Phone No:	505-699-4669
Phone Ext No:	
Admin Name:	BAKER, COLLEEN
Alt Phone No:	
Email Addr:	colleen.baker@emnrd.nm.gov
Fax No:	
Cds ID:	
Population Served Count:	50
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	03/12/1980
Gw or Sw:	Groundwater
Is Grant Eligible Ind:	Yes
Outstanding Performer:	
Is School or Daycare Ind:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Last Reported Date:	06/25/2025
Org Name:	BAKER, COLLEEN
Outstanding Perform Begin Date:	
Owner Type:	State government
Pop Cat 11:	<=100
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Primacy Agency Code:	NM
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	23
Submission Yr Qtr:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	GUADALUPITA
County Served:	Mora

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
157	NE	0.89	4,675.76	6,935.82	SDWIS

Wells and Additional Sources Detail Report

PWS ID:	NM3593519
PWS Type Code:	TNCWS
PSW Type:	Transient non-community system
Primary Source Code:	GW
Primary Source:	Ground water
Pws Activity Code:	A
Activity:	Active
PWS Deactivation Dt:	
Phone No:	505-699-4669
Phone Ext No:	
Admin Name:	BAKER, COLLEEN
Alt Phone No:	
Email Addr:	colleen.baker@emnrd.nm.gov
Fax No:	
Cds ID:	
Population Served Count:	150
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	01/10/1981
Gw or Sw:	Groundwater
Is Grant Eligible Ind:	Yes
Outstanding Performer:	
Is School or Daycare Ind:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Last Reported Date:	06/25/2025
Org Name:	BAKER, COLLEEN
Outstanding Perform Begin Date:	
Owner Type:	State government
Pop Cat 11:	101-500
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Primacy Agency Code:	NM
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	29
Submission Yr Qtr:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin:	

Reduced Monitoring End Date:
Reduced Rtcr Monitoring:
Seasonal Startup System:
Source Protection Begin Date:
City Served: ALAMOGORDO
County Served: Otero

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
157	NE	0.89	4,675.76	6,935.82	SDWIS

PWS ID: NM3590231
PWS Type Code: TNCWS
PSW Type: Transient non-community system
Primary Source Code: GW
Primary Source: Ground water
Pws Activity Code: A
Activity: Active
PWS Deactivation Dt:
Phone No: 505-699-4669
Phone Ext No:
Admin Name: BAKER, COLLEEN
Alt Phone No:
Email Addr: colleen.baker@emnrd.nm.gov
Fax No:
Cds ID:
Population Served Count: 178
Epa Region Desc: Region 6
Epa Region: 06
First Reported Date: 03/12/1980
Gw or Sw: Groundwater
Is Grant Eligible Ind: Yes
Outstanding Performer:
Is School or Daycare Ind: No
Is Wholesaler Ind: No
Lt2 Schedule Cat:
Last Reported Date: 06/25/2025
Org Name: BAKER, COLLEEN
Outstanding Perform Begin Date:
Owner Type: State government
Pop Cat 11: 101-500
Pop Cat 2: <10,000
Pop Cat 3: <=3300
Pop Cat 4: <10K
Pop Cat 5: <=500
Primacy Agency: New Mexico

Wells and Additional Sources Detail Report

Primacy Agency Code:	NM
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	1
Submission Yr Qtr:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	CLAYTON
County Served:	Union

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
196	E	0.96	5,057.78	6,963.35	SDWIS

PWS ID:	NM3510225
PWS Type Code:	CWS
PSW Type:	Community water system
Primary Source Code:	GW
Primary Source:	Ground water
Pws Activity Code:	I
Activity:	Inactive
PWS Deactivation Dt:	08/01/2002
Phone No:	505-421-2270
Phone Ext No:	
Admin Name:	AMADEO ARAGON
Alt Phone No:	
Email Addr:	
Fax No:	
Cds ID:	
Population Served Count:	60
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	07/01/1987
Gw or Sw:	Groundwater
Is Grant Eligible Ind:	No
Outstanding Performer:	
Is School or Daycare Ind:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Last Reported Date:	07/11/2005

Wells and Additional Sources Detail Report

Org Name:	
Outstanding Perform Begin Date:	
Owner Type:	Private
Pop Cat 11:	<=100
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Primacy Agency Code:	NM
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	12
Submission Yr Qtr:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	
County Served:	San Miguel

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
202	S	0.97	5,104.47	6,817.64	SDWIS

PWS ID:	NM3581326
PWS Type Code:	NTNCWS
PSW Type:	Non-Transient non-community system
Primary Source Code:	GW
Primary Source:	Ground water
Pws Activity Code:	N
Activity:	Changed from public to non-public
PWS Deactivation Dt:	01/25/2012
Phone No:	505-470-6351
Phone Ext No:	
Admin Name:	BUTLER, JIM
Alt Phone No:	
Email Addr:	
Fax No:	
Cds ID:	
Population Served Count:	441

Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	11/25/1992
Gw or Sw:	Groundwater
Is Grant Eligible Ind:	No
Outstanding Performer:	
Is School or Daycare Ind:	Yes
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Last Reported Date:	06/25/2025
Org Name:	BUTLER, JIM
Outstanding Perform Begin Date:	
Owner Type:	Local government
Pop Cat 11:	101-500
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Primacy Agency Code:	NM
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	1
Submission Yr Qtr:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	SANTA FE
County Served:	Santa Fe

USGS National Water Information System

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
2	ESE	0.13	681.08	6,868.18	FED USGS

Site No:	USGS-353933105575601
Site Type:	Well
Formation Type:	Tesuque Formation, Undifferentiated Unit
Date Drilled:	19570304
Well Depth:	820

Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.34.422
Latitude: 35.65919797000000
Longitude: -105.9661327000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
7	SE	0.27	1,404.92	6,835.33	FED USGS

Site No: USGS-353925105575201
Site Type: Well
Formation Type:
Date Drilled:
Well Depth: 820
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.34.4224
Latitude: 35.65697580000000
Longitude: -105.9650215000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
12	ENE	0.35	1,822.45	6,885.14	FED USGS

Site No: USGS-353945105574501
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19860916
Well Depth: 1952
Well Depth Unit: ft
Well Hole Depth: 2020
Well Hole Depth Unit: ft
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.35.1314A SANTA FE 1 DEEP PIEZO.
Latitude: 35.66253120000000
Longitude: -105.9630770000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
12	ENE	0.35	1,822.45	6,885.14	FED USGS

Site No: USGS-353945105574503
Site Type: Well

Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19860916
Well Depth: 780
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.35.1314C SANTA FE 1 SHALLOW PIEZO.
Latitude: 35.66253120000000
Longitude: -105.9630770000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
12	ENE	0.35	1,822.45	6,885.14	FED USGS

Site No: USGS-353945105574502
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19860916
Well Depth: 1060
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.35.1314B SANTA FE 1 MIDDLE PIEZO.
Latitude: 35.66253120000000
Longitude: -105.9630770000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
42	ENE	0.55	2,921.80	6,904.82	FED USGS

Site No: USGS-353948105573201
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19780601
Well Depth: 356
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.35.141
Latitude: 35.66336457000000
Longitude: -105.9594659000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
47	SE	0.62	3,254.72	6,907.94	FED USGS

Site No:	USGS-353916105573201
Site Type:	Well
Formation Type:	Tesuque Formation, Undifferentiated Unit
Date Drilled:	19570501
Well Depth:	275
Well Depth Unit:	ft
Well Hole Depth:	275
Well Hole Depth Unit:	ft
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	17N.09E.35.343
Latitude:	35.65447590000000
Longitude:	-105.9594659000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
66	S	0.67	3,531.81	6,822.37	FED USGS

Site No:	USGS-353900105580001
Site Type:	Atmosphere
Formation Type:	
Date Drilled:	
Well Depth:	
Well Depth Unit:	
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	SANTA FE, NM W23049
Latitude:	35.65003155000000
Longitude:	-105.9672438000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
75	N	0.69	3,652.37	6,851.42	FED USGS

Site No:	USGS-354013105580601
Site Type:	Well
Formation Type:	Santa Fe Group
Date Drilled:	19050101
Well Depth:	989
Well Depth Unit:	ft
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	17N.09E.27.441
Latitude:	35.67022220000000
Longitude:	-105.9679167000000

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
79	W	0.72	3,784.76	6,768.47	FED USGS

Site No:	USGS-353933105585101
Site Type:	Well
Formation Type:	
Date Drilled:	
Well Depth:	61.3
Well Depth Unit:	ft
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	17N.09E.34.311
Latitude:	35.65919785000000
Longitude:	-105.9814108000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
83	SE	0.72	3,787.21	6,894.75	FED USGS

Site No:	USGS-353908105573201
Site Type:	Well
Formation Type:	
Date Drilled:	
Well Depth:	291
Well Depth Unit:	ft
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	16N.09E.02.121
Latitude:	35.65225377000000
Longitude:	-105.9594659000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
88	SW	0.73	3,869.15	6,752.64	FED USGS

Site No:	USGS-353907105583701
Site Type:	Well
Formation Type:	
Date Drilled:	19470101
Well Depth:	60.0
Well Depth Unit:	ft
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	16N.09E.03.1213 B

Latitude: 35.65197586000000
Longitude: -105.9775217000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
97	SW	0.76	3,999.28	6,746.77	FED USGS

Site No: USGS-353906105583801
Site Type: Well
Formation Type: Ancha Formation, Upper Part of Santa Fe Group
Date Drilled: 19770418
Well Depth: 130
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 16N.09E.03.1213 A
Latitude: 35.65169808000000
Longitude: -105.9777995000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
167	ESE	0.91	4,794.16	6,949.13	FED USGS

Site No: USGS-353922105570801
Site Type: Well
Formation Type:
Date Drilled: 19430101
Well Depth: 230
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.35.432
Latitude: 35.65614260000000
Longitude: -105.9527990000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
223	NW	1.00	5,276.52	6,755.21	FED USGS

Site No: USGS-354006105585801
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19640710
Well Depth: 67.0
Well Depth Unit: ft
Well Hole Depth:

Wells and Additional Sources Detail Report

Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.28.444
Latitude: 35.66836424000000
Longitude: -105.9833553000000

Point of Diversion Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	NE	0.04	218.98	6,856.70	WATER WELLS

License Nb:	0	District Office S:	
POD No:	00304	Surv Map:	
POD Rec No:	174796	Other Loc:	St. Michael'S Well
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	1613.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412400.7
Pcw Rcv Da:		Northing:	3946710.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/18/2001, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	584000.0
Static Lev:	0	Y:	1695700.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.66036892
Map Nbr:		Point X:	-105.96779971
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	NE	0.04	218.98	6,856.70	WATER WELLS

License Nb:		District Office S:	1 thru 7
POD No:	00304	Surv Map:	
POD Rec No:	174796	Other Loc:	
POD Basin:	SP	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	RG	Percent Sh:	
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:		Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:		Datum:	NAD83
CS Code:		UTM Source:	UN
Depth of Well:	0	UTM Zone:	
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0	Lat Lon AC:	
Elevation:		County:	Santa Fe
Ref :		Easting:	412400.7
Pcw Rcv Da:		Northing:	3946710.8
Sched Date:		Latitude Degree:	
Use of Wel:		Latitude Minute:	
Sys Date:		Latitude Second:	
Subdiv Nam:		Longitude Degree:	
Surface Co:		Longitude Minute:	
Ditch Name:		Longitude Second:	
Well Tag:		X:	584000

Wells and Additional Sources Detail Report

Static Lev:		Y:	1695700
Tract Nbr:		Point Y:	
Map Nbr:		Point X:	01677
Driller:			
POD Basin Desc:	Surface Permit		
POD Sub Basin Desc:			
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	WSW	0.26	1,384.54	6,820.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	93057	Surv Map:	
POD Rec No:	264936	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411910.0
Pcw Rcv Da:		Northing:	3946577.4
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	10/06/2011, 12:00 AM	Latitude Second:	32.84
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	23.54

Wells and Additional Sources Detail Report

Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65912261
Map Nbr:		Point X:	-105.97320569
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
5	NNW	0.25	1,342.59	6,844.24	WATER WELLS

License Nb:	0	District Office S:	
POD No:	37924	Surv Map:	
POD Rec No:	20878	Other Loc:	1608 Fourth St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	23 13 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412156.5
Pcw Rcv Da:		Northing:	3947062.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/11/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1723427.0
Static Lev:	0	Y:	1696905.0
Tract Nbr:		Point Y:	35.66351603
Map Nbr:		Point X:	-105.97053564
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
6	N	0.26	1,374.56	6,850.18	WATER WELLS

License Nb:	0	District Office S:	
POD No:	30681	Surv Map:	
POD Rec No:	35998	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412283.9
Pcw Rcv Da:		Northing:	3947108.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/27/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	583600.0
Static Lev:	0	Y:	1697000.0
Tract Nbr:		Point Y:	35.66394387
Map Nbr:		Point X:	-105.96913328
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	WNW	0.28	1,491.51	6,821.39	WATER WELLS

License Nb:	0	District Office S:	
POD No:	93057	Surv Map:	
POD Rec No:	264937	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411871.0
Pcw Rcv Da:		Northing:	3946772.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	10/06/2011, 12:00 AM	Latitude Second:	39.16

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	25.17
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66087798
Map Nbr:		Point X:	-105.97365785
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
9	SSE	0.29	1,536.09	6,819.60	WATER WELLS

License Nb:	0	District Office S:	
POD No:	39921	Surv Map:	
POD Rec No:	18815	Other Loc:	2055 Camino Lado, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412485.6
Pcw Rcv Da:		Northing:	3946191.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	02/23/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	584300.0
Static Lev:	0	Y:	1694000.0
Tract Nbr:		Point Y:	35.65569667
Map Nbr:		Point X:	-105.96680544
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
10	WNW	0.30	1,558.13	6,819.96	WATER WELLS

License Nb:	0	District Office S:	
POD No:	93057	Surv Map:	
POD Rec No:	264938	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411849.8
Pcw Rcv Da:		Northing:	3946771.8
Sched Date:		Latitude Degree:	35

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	39
Sys Date:	10/06/2011, 12:00 AM	Latitude Second:	39.13
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	26.01
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66086977
Map Nbr:		Point X:	-105.97389196
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
11	SSE	0.32	1,674.19	6,839.21	WATER WELLS

License Nb:	253	District Office S:	
POD No:	38596	Surv Map:	
POD Rec No:	40912	Other Loc:	2067 Calle Sombra, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	21 2 U3 SF
Start Date:	05/18/1983, 12:00 AM	Restrict :	0.0
Finish Date:	05/19/1983, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	06/06/1983, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	330	UTM Zone:	13
Depth of Water:	205	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	8.75	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412613.7
Pcw Rcv Da:		Northing:	3946202.5

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/26/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Del Cerro	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	412613.7
Static Lev:	0	Y:	3946202.5
Tract Nbr:		Point Y:	35.65580539
Map Nbr:		Point X:	-105.96539162
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052097520103000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	SW	0.34	1,797.18	6,805.16	WATER WELLS

License Nb:	0	District Office S:	
POD No:	96479	Surv Map:	
POD Rec No:	304918	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412005.0

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3946196.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/05/2017, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	412005.0
Static Lev:	0	Y:	3946196.0
Tract Nbr:		Point Y:	35.6556927
Map Nbr:		Point X:	-105.9721146
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
14	ENE	0.35	1,872.75	6,887.45	WATER WELLS

License Nb:	331	District Office S:	
POD No:	42755	Surv Map:	
POD Rec No:	9001	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/25/1984, 12:00 AM	Restrict :	0.0
Finish Date:	11/09/1984, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	11/30/1984, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	2020	UTM Zone:	13
Depth of Water:	179	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	6880.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :	RG-42755-EXPL/	Easting:	412860.5
Pcw Rcv Da:		Northing:	3946918.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/19/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	585500.0
Static Lev:	0	Y:	1696400.0
Tract Nbr:		Point Y:	35.66228028
Map Nbr:		Point X:	-105.96274293
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	SW	0.37	1,931.44	6,798.44	WATER WELLS

License Nb:	1004	District Office S:	
POD No:	62759	Surv Map:	
POD Rec No:	64008	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/25/1995, 12:00 AM	Restrict :	3.0
Finish Date:	07/26/1995, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	07/31/1995, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	304	UTM Zone:	13
Depth of Water:	163	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411937.1
Pcw Rcv Da:		Northing:	3946198.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/06/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	582500.0
Static Lev:	0	Y:	1694000.0
Tract Nbr:		Point Y:	35.65571008
Map Nbr:		Point X:	-105.97286491
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NW	0.38	1,985.77	6,821.65	WATER WELLS

License Nb:	622	District Office S:	
POD No:	60866	Surv Map:	
POD Rec No:	53640	Other Loc:	1862 Cerrillos Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA SF
Start Date:	01/12/1995, 12:00 AM	Restrict :	3.0
Finish Date:	01/13/1995, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	02/14/1995, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	320	UTM Zone:	13
Depth of Water:	169	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	3.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411887.8
Pcw Rcv Da:		Northing:	3947113.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/05/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	582300.0
Static Lev:	0	Y:	1697000.0
Tract Nbr:		Point Y:	35.66395364
Map Nbr:		Point X:	-105.97350959
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
17	SSE	0.38	1,993.66	6,841.44	WATER WELLS

License Nb:	253	District Office S:	
POD No:	38598	Surv Map:	
POD Rec No:	13204	Other Loc:	2069 Camino Lado, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	15 2 U3 SF
Start Date:	05/20/1983, 12:00 AM	Restrict :	0.0
Finish Date:	05/21/1983, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	05/31/1983, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	325	UTM Zone:	13
Depth of Water:	200	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412644.9
Pcw Rcv Da:		Northing:	3946108.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/26/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Del Cerro	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	412644.9
Static Lev:	0	Y:	3946108.9
Tract Nbr:		Point Y:	35.65496433
Map Nbr:		Point X:	-105.96503684
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1053097005075000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
18	NW	0.39	2,058.15	6,821.41	WATER WELLS

License Nb:	622	District Office S:	
POD No:	35311	Surv Map:	
POD Rec No:	47567	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/17/1980, 12:00 AM	Restrict :	0.0
Finish Date:	11/18/1980, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/01/1980, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	137	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	

Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411888.2
Pcw Rcv Da:		Northing:	3947144.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/15/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	582300.0
Static Lev:	0	Y:	1697100.0
Tract Nbr:		Point Y:	35.66422864
Map Nbr:		Point X:	-105.97350851
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
19	NNE	0.42	2,203.54	6,873.42	WATER WELLS

License Nb:	0	District Office S:	
POD No:	38027	Surv Map:	
POD Rec No:	12254	Other Loc:	1630 Jay St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	5 6 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412634.8
Pcw Rcv Da:		Northing:	3947294.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/18/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Young'S Mountain View Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1724987.0
Static Lev:	0	Y:	1697686.0
Tract Nbr:		Point Y:	35.66564912
Map Nbr:		Point X:	-105.965277
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
20	N	0.42	2,220.44	6,859.80	WATER WELLS

License Nb:	1004	District Office S:	
POD No:	42336	Surv Map:	
POD Rec No:	26352	Other Loc:	1522 Cochiti St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	8/9 4 SF
Start Date:	12/04/1984, 12:00 AM	Restrict :	0.0
Finish Date:	12/07/1984, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	12/17/1984, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	240	UTM Zone:	13
Depth of Water:	190	UTM Accura:	10

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412408.7
Pcw Rcv Da:		Northing:	3947365.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/05/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Indian School Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1724242.0
Static Lev:	0	Y:	1697911.0
Tract Nbr:		Point Y:	35.66627275
Map Nbr:		Point X:	-105.96778258
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
21	NNE	0.43	2,276.02	6,877.62	WATER WELLS

License Nb:	0	District Office S:	
POD No:	42118	Surv Map:	
POD Rec No:	50778	Other Loc:	1710 Lena St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	A
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412723.8
Pcw Rcv Da:		Northing:	3947268.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1725280.0
Static Lev:	0	Y:	1697605.0
Tract Nbr:		Point Y:	35.66542441
Map Nbr:		Point X:	-105.96429099
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
22	SW	0.44	2,318.45	6,782.58	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289866	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD65	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA

Wells and Additional Sources Detail Report

Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411821.8
Pcw Rcv Da:		Northing:	3946146.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	18.84
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	26.88
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6552337
Map Nbr:		Point X:	-105.97413285
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
23	NE	0.45	2,360.30	6,882.42	WATER WELLS

License Nb:	0	District Office S:	
POD No:	05264	Surv Map:	
POD Rec No:	193400	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412852.0
Pcw Rcv Da:		Northing:	3947195.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/17/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66477403
Map Nbr:		Point X:	-105.96286678
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289817	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD16	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289816	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD15	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289832	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD31	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289830	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD29	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289815	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD14	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	

Wells and Additional Sources Detail Report

Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289822	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD21	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289837	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD36	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289833	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD32	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289824	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD23	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289823	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD22	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289829	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD28	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0

Wells and Additional Sources Detail Report

POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289827	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD26	BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289831	Other Loc:	
POD Basin:	RG	Zone :	

Wells and Additional Sources Detail Report

POD Suffix:	POD30	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289835	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:	POD34	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	289818	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD17	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	94602	Surv Map:	
POD Rec No:	289821	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD20	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289814	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD13	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289826	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD25	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289828	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD27	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289836	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD35	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289820	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD19	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289838	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD37	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289825	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD24	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	SW	0.45	2,363.07	6,789.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289819	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD18	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant :

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
25	SW	0.46	2,434.94	6,788.56	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289862	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD61	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411871.1
Pcw Rcv Da:		Northing:	3946053.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	15.84
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.88
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6543997
Map Nbr:		Point X:	-105.97357811
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
26	NE	0.47	2,468.63	6,884.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	66307	Surv Map:	
POD Rec No:	35556	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412924.6
Pcw Rcv Da:		Northing:	3947161.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/16/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	585700.0
Static Lev:	0	Y:	1697200.0
Tract Nbr:		Point Y:	35.66447663
Map Nbr:		Point X:	-105.9620611
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
27	N	0.47	2,461.09	6,855.01	WATER WELLS

License Nb:	0	District Office S:	
POD No:	42336	Surv Map:	
POD Rec No:	177055	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-42336-CLW225828/26352/RG-42	Easting:	412349.1
Pcw Rcv Da:		Northing:	3947442.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/01/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	583800.0
Static Lev:	0	Y:	1698100.0
Tract Nbr:		Point Y:	35.66696433
Map Nbr:		Point X:	-105.96844942

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
28	SSE	0.47	2,470.69	6,851.33	WATER WELLS

License Nb:	228	District Office S:	
POD No:	40807	Surv Map:	
POD Rec No:	18058	Other Loc:	2077 Camino Lado, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/11/1984, 12:00 AM	Restrict :	0.0
Finish Date:	10/17/1984, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	11/26/1984, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	360	UTM Zone:	13
Depth of Water:	260	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412604.2
Pcw Rcv Da:		Northing:	3945931.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/06/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	584700.0
Static Lev:	0	Y:	1693150.0
Tract Nbr:		Point Y:	35.65335783

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.96546711
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
29	SSW	0.47	2,493.81	6,789.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289810	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD9	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411909.4
Pcw Rcv Da:		Northing:	3946003.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	14.22
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	23.34
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.65394966
Map Nbr:		Point X:	-105.97314955
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
29	SSW	0.47	2,493.81	6,789.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289811	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD10	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411909.4
Pcw Rcv Da:		Northing:	3946003.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	14.22
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	23.34
Well Tag:		X:	0.0

Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65394966
Map Nbr:		Point X:	-105.97314955
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
29	SSW	0.47	2,493.81	6,789.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289809	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD8	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411909.4
Pcw Rcv Da:		Northing:	3946003.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	14.22
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	23.34

Wells and Additional Sources Detail Report

Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65394966
Map Nbr:		Point X:	-105.97314955
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
29	SSW	0.47	2,493.81	6,789.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289808	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD7	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411909.4
Pcw Rcv Da:		Northing:	3946003.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	14.22
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	23.34
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65394966
Map Nbr:		Point X:	-105.97314955
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
29	SSW	0.47	2,493.81	6,789.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289813	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD12	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411909.4
Pcw Rcv Da:		Northing:	3946003.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	14.22
Subdiv Nam:		Longitude Degree:	105

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	23.34
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65394966
Map Nbr:		Point X:	-105.97314955
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
29	SSW	0.47	2,493.81	6,789.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289812	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD11	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411909.4
Pcw Rcv Da:		Northing:	3946003.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	14.22

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	23.34
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65394966
Map Nbr:		Point X:	-105.97314955
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
30	SW	0.48	2,538.59	6,783.49	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289863	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD62	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411820.8
Pcw Rcv Da:		Northing:	3946054.4
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39

Wells and Additional Sources Detail Report

Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	15.84
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	26.88
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65439971
Map Nbr:		Point X:	-105.97413377
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
30	SW	0.48	2,538.59	6,783.49	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289864	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD63	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411820.8
Pcw Rcv Da:		Northing:	3946054.4
Sched Date:		Latitude Degree:	35

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	15.84
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	26.88
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65439971
Map Nbr:		Point X:	-105.97413377
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
30	SW	0.48	2,538.59	6,783.49	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289865	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD64	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411820.8
Pcw Rcv Da:		Northing:	3946054.4

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	15.84
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	26.88
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65439971
Map Nbr:		Point X:	-105.97413377
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
30	SW	0.48	2,538.59	6,783.49	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289867	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD66	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411820.8

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3946054.4
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	15.84
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	26.88
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65439971
Map Nbr:		Point X:	-105.97413377
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
31	ENE	0.49	2,584.63	6,895.77	WATER WELLS

License Nb:	227	District Office S:	
POD No:	30564	Surv Map:	
POD Rec No:	25717	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/01/1978, 12:00 AM	Restrict :	0.0
Finish Date:	06/22/1978, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	06/28/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	356	UTM Zone:	13
Depth of Water:	261	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	413044.9
Pcw Rcv Da:		Northing:	3947037.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/01/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	586100.0
Static Lev:	0	Y:	1696800.0
Tract Nbr:		Point Y:	35.66337477
Map Nbr:		Point X:	-105.9607188
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
32	ENE	0.50	2,659.69	6,896.39	WATER WELLS

License Nb:	0	District Office S:	
POD No:	43195	Surv Map:	
POD Rec No:	48042	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413134.0
Pcw Rcv Da:		Northing:	3946853.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	586400.0
Static Lev:	0	Y:	1696200.0
Tract Nbr:		Point Y:	35.66172382
Map Nbr:		Point X:	-105.95971465
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
33	SW	0.50	2,628.98	6,787.48	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289871	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD70	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945981.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.5
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65375037
Map Nbr:		Point X:	-105.97360005
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
33	SW	0.50	2,628.98	6,787.48	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289869	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD68	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945982.2
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.51
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65375307
Map Nbr:		Point X:	-105.97360009
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
33	SW	0.50	2,628.98	6,787.48	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289872	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD71	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945981.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.5
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65375037
Map Nbr:		Point X:	-105.97360005
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
33	SW	0.50	2,628.98	6,787.48	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289868	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD67	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945982.2
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.51
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65375307
Map Nbr:		Point X:	-105.97360009
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
33	SW	0.50	2,628.98	6,787.48	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289870	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD69	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945981.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.5
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65375037
Map Nbr:		Point X:	-105.97360005
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
33	SW	0.50	2,628.98	6,787.48	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289873	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD72	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945981.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.5
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65375037
Map Nbr:		Point X:	-105.97360005
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289853	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD52	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA

Wells and Additional Sources Detail Report

Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289846	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD45	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289842	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD41	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289852	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD51	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289859	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD58	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289860	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD59	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289854	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD53	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	

Wells and Additional Sources Detail Report

Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289858	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD57	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289845	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD44	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289848	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD47	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289861	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD60	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289857	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD56	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289841	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD40	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0

Wells and Additional Sources Detail Report

POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289843	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD42	BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289844	Other Loc:	
POD Basin:	RG	Zone :	

Wells and Additional Sources Detail Report

POD Suffix:	POD43	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289850	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:	POD49	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	289849	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD48	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	94602	Surv Map:	
POD Rec No:	289856	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD55	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289847	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD46	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289840	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD39	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289851	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD50	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289839	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD38	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

34	SW	0.50	2,643.93	6,787.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289855	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD54	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
35	NNE	0.50	2,655.74	6,879.53	WATER WELLS

License Nb:	622	District Office S:	
POD No:	71072	Surv Map:	
POD Rec No:	146964	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412684.1
Pcw Rcv Da:		Northing:	3947423.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/12/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	584900.0
Static Lev:	0	Y:	1698050.0
Tract Nbr:		Point Y:	35.66681824
Map Nbr:		Point X:	-105.96474638
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
36	WNW	0.51	2,666.60	6,798.33	WATER WELLS

License Nb:	0	District Office S:	
POD No:	53590	Surv Map:	
POD Rec No:	339403	Other Loc:	1975 Cerrillos Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	12/31/1950, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	13	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411581.9
Pcw Rcv Da:		Northing:	3947033.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/27/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721543.0
Static Lev:	0	Y:	1696785.0
Tract Nbr:		Point Y:	35.66320056
Map Nbr:		Point X:	-105.97688005
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
37	SW	0.51	2,695.82	6,782.44	WATER WELLS

License Nb:	0	District Office S:	
POD No:	93961	Surv Map:	
POD Rec No:	283516	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	UA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411787.3
Pcw Rcv Da:		Northing:	3946020.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	04/17/2013, 12:00 AM	Latitude Second:	14.74
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	28.2
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65409471
Map Nbr:		Point X:	-105.97450013
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant :

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
38	ENE	0.52	2,754.14	6,898.37	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35697	Surv Map:	
POD Rec No:	4922	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413164.4
Pcw Rcv Da:		Northing:	3946853.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/09/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	586500.0
Static Lev:	0	Y:	1696200.0
Tract Nbr:		Point Y:	35.66172289
Map Nbr:		Point X:	-105.95937878
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
39	NW	0.52	2,763.96	6,812.00	WATER WELLS

License Nb:	790	District Office S:	
POD No:	31371	Surv Map:	
POD Rec No:	10205	Other Loc:	1844 Hopi Road, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	NRG	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	9 2 SF
Start Date:	11/26/1979, 12:00 AM	Restrict :	0.0
Finish Date:	12/03/1979, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	12/12/1979, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	160	UTM Zone:	13
Depth of Water:	117	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411794.4
Pcw Rcv Da:		Northing:	3947346.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411794.4
Static Lev:	0	Y:	3947346.8
Tract Nbr:		Point Y:	35.66604853
Map Nbr:		Point X:	-105.97456695
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc:	Rio Grande
POD Sub Basin Desc:	Northern Rio Grande
Grant :	Santa Fe
Legal:	Parcel Number 1052097243469000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
40	NE	0.53	2,790.23	6,887.79	WATER WELLS

License Nb:	0	District Office S:	
POD No:	44039	Surv Map:	
POD Rec No:	10092	Other Loc:	1451 Santa Cruz Dr
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 5 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412851.0
Pcw Rcv Da:		Northing:	3947370.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/26/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Linda Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1725693.0
Static Lev:	0	Y:	1697944.0
Tract Nbr:		Point Y:	35.6663525
Map Nbr:		Point X:	-105.96289678

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
41	NE	0.54	2,843.67	6,890.74	WATER WELLS

License Nb:	0	District Office S:	
POD No:	61687	Surv Map:	
POD Rec No:	42763	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412956.8
Pcw Rcv Da:		Northing:	3947298.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/26/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	585800.0
Static Lev:	0	Y:	1697650.0
Tract Nbr:		Point Y:	35.66571184

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.96172016
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
43	NE	0.57	3,022.42	6,897.14	WATER WELLS

License Nb:	0	District Office S:	
POD No:	43115	Surv Map:	
POD Rec No:	54438	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413017.9
Pcw Rcv Da:		Northing:	3947312.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/02/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	586000.0
Static Lev:	0	Y:	1697700.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.66584795
Map Nbr:		Point X:	-105.96104674
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
43	NE	0.57	3,022.42	6,897.14	WATER WELLS

License Nb:	0	District Office S:	
POD No:	43116	Surv Map:	
POD Rec No:	59990	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413017.9
Pcw Rcv Da:		Northing:	3947312.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/02/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	586000.0

Wells and Additional Sources Detail Report

Static Lev:	0	Y:	1697700.0
Tract Nbr:		Point Y:	35.66584795
Map Nbr:		Point X:	-105.96104674
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
44	NW	0.57	3,014.27	6,804.37	WATER WELLS

License Nb:	228	District Office S:	
POD No:	49459	Surv Map:	
POD Rec No:	49038	Other Loc:	1913 Hopi Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3 14 SF
Start Date:	08/25/1988, 12:00 AM	Restrict :	0.0
Finish Date:	09/02/1988, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	09/09/1988, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	290	UTM Zone:	13
Depth of Water:	160	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411701.7
Pcw Rcv Da:		Northing:	3947369.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/17/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:	NA	X:	1721922.0
Static Lev:	0	Y:	1697893.0
Tract Nbr:		Point Y:	35.66624218
Map Nbr:		Point X:	-105.9755935
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
45	NW	0.58	3,071.55	6,798.06	WATER WELLS

License Nb:	214	District Office S:	
POD No:	31329	Surv Map:	
POD Rec No:	291265	Other Loc:	1944 Hopi Road, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	9 11 SF
Start Date:	05/15/1980, 12:00 AM	Restrict :	0.0
Finish Date:	05/15/1980, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	05/22/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	137	UTM Zone:	13
Depth of Water:	109	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	12	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411608.8
Pcw Rcv Da:		Northing:	3947299.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411608.8
Static Lev:	0	Y:	3947299.1
Tract Nbr:		Point Y:	35.6656019
Map Nbr:		Point X:	-105.9766121
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052097183449000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	NW	0.61	3,216.31	6,794.94	WATER WELLS

License Nb:	253	District Office S:	
POD No:	30882	Surv Map:	
POD Rec No:	8325	Other Loc:	1949 Hopi Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 14 SF
Start Date:	07/20/1979, 12:00 AM	Restrict :	0.0
Finish Date:	07/21/1979, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	08/28/1979, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	155	UTM Zone:	13
Depth of Water:	98	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411573.1
Pcw Rcv Da:		Northing:	3947324.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/30/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre Addition	Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721502.0
Static Lev:	0	Y:	1697741.0
Tract Nbr:		Point Y:	35.66582768
Map Nbr:		Point X:	-105.97700928
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
48	NE	0.62	3,288.94	6,906.52	WATER WELLS

License Nb:	790	District Office S:	
POD No:	52957	Surv Map:	
POD Rec No:	6730	Other Loc:	1516 Pacheco St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA T4A SF
Start Date:	09/04/1991, 12:00 AM	Restrict :	0.0
Finish Date:	09/04/1991, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	09/18/1991, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	390	UTM Zone:	13
Depth of Water:	201	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413089.1
Pcw Rcv Da:		Northing:	3947353.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/13/2022, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1726475.0
Static Lev:	0	Y:	1697901.0
Tract Nbr:		Point Y:	35.66622746
Map Nbr:		Point X:	-105.96026463
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
49	N	0.63	3,305.34	6,852.27	WATER WELLS

License Nb:	228	District Office S:	
POD No:	14882	Surv Map:	
POD Rec No:	51436	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/09/1967, 12:00 AM	Restrict :	0.0
Finish Date:	05/10/1967, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	09/18/1967, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	100	UTM Zone:	13
Depth of Water:	55	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	412352.0
Pcw Rcv Da:		Northing:	3947700.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	10/29/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66928238
Map Nbr:		Point X:	-105.96844538
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	One Block West Osage On Agua Fria.		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
50	NW	0.64	3,399.75	6,804.92	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35520	Surv Map:	
POD Rec No:	40391	Other Loc:	1223 San Felipe Ave, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	12 2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-35520-/	Easting:	411740.3
Pcw Rcv Da:		Northing:	3947546.7
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	11/03/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411740.3
Static Lev:	0	Y:	3947546.7
Tract Nbr:		Point Y:	35.66784582
Map Nbr:		Point X:	-105.97518653
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052098225005000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
51	NW	0.65	3,422.04	6,801.98	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31368	Surv Map:	
POD Rec No:	291277	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411679.5
Pcw Rcv Da:		Northing:	3947512.4

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/11/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581600.0
Static Lev:	0	Y:	1698300.0
Tract Nbr:		Point Y:	35.66753116
Map Nbr:		Point X:	-105.97585446
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
52	W	0.66	3,475.63	6,773.91	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	305038	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD6	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/20/2017, 12:00 AM	Restrict :	0.0
Finish Date:	02/24/2017, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	03/16/2017, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	115	UTM Zone:	13
Depth of Water:	105	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411264.2

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3946570.8
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	09/21/2018, 12:00 AM	Latitude Second:	32.42
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	49.22
Well Tag:		X:	0.0
Static Lev:	104	Y:	0.0
Tract Nbr:		Point Y:	35.65900524
Map Nbr:		Point X:	-105.98033874
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
53	W	0.66	3,488.27	6,773.02	WATER WELLS

License Nb:	1848	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	343038	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD8	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	IW-2	Subdiv Loc:	
Start Date:	10/23/2023, 12:00 AM	Restrict :	0.0
Finish Date:	11/06/2023, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/14/2023, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	117	UTM Zone:	13
Depth of Water:	102	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	411259.5
Pcw Rcv Da:		Northing:	3946577.4
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	01/02/2024, 12:00 AM	Latitude Second:	32.63
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	49.41
Well Tag:	NA	X:	0.0
Static Lev:	102	Y:	0.0
Tract Nbr:		Point Y:	35.65906432
Map Nbr:		Point X:	-105.98039138
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
54	W	0.66	3,499.83	6,773.06	WATER WELLS

License Nb:	1848	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	343041	Other Loc:	Iw-5
POD Basin:	RG	Zone :	
POD Suffix:	POD11	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	IW-5	Subdiv Loc:	
Start Date:	10/23/2023, 12:00 AM	Restrict :	0.0
Finish Date:	11/06/2023, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/14/2023, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	118	UTM Zone:	13
Depth of Water:	102	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411257.8
Pcw Rcv Da:		Northing:	3946562.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	01/02/2024, 12:00 AM	Latitude Second:	32.15
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	49.47
Well Tag:	NA	X:	0.0
Static Lev:	102	Y:	0.0
Tract Nbr:		Point Y:	35.65893074
Map Nbr:		Point X:	-105.98040853
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
55	W	0.66	3,509.84	6,773.28	WATER WELLS

License Nb:	1848	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	343037	Other Loc:	Iw-1
POD Basin:	RG	Zone :	
POD Suffix:	POD7	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	IW-1	Subdiv Loc:	
Start Date:	10/23/2023, 12:00 AM	Restrict :	0.0
Finish Date:	11/06/2023, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/14/2023, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	117	UTM Zone:	13
Depth of Water:	102	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411251.6
Pcw Rcv Da:		Northing:	3946591.0
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	01/02/2024, 12:00 AM	Latitude Second:	33.07
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	49.73
Well Tag:	NA	X:	0.0
Static Lev:	102	Y:	0.0
Tract Nbr:		Point Y:	35.65918621
Map Nbr:		Point X:	-105.98048015
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
56	W	0.67	3,513.65	6,773.06	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	305037	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD5	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/20/2017, 12:00 AM	Restrict :	0.0
Finish Date:	02/24/2017, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	03/21/2017, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	114	UTM Zone:	13
Depth of Water:	108	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411253.3
Pcw Rcv Da:		Northing:	3946564.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	32.21
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	49.65
Well Tag:		X:	0.0
Static Lev:	108	Y:	0.0
Tract Nbr:		Point Y:	35.65894746
Map Nbr:		Point X:	-105.98045845
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
57	WNW	0.66	3,489.54	6,775.97	WATER WELLS

License Nb:	253	District Office S:	
POD No:	31193	Surv Map:	
POD Rec No:	325609	Other Loc:	1319 Vitalia St.
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 1 SF
Start Date:	09/25/1978, 12:00 AM	Restrict :	0.0
Finish Date:	09/25/1978, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	10/02/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	120	UTM Zone:	13
Depth of Water:	77	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	28	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411284.2
Pcw Rcv Da:		Northing:	3946939.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/13/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Domingo #2	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411284.2
Static Lev:	0	Y:	3946939.8
Tract Nbr:		Point Y:	35.66233362
Map Nbr:		Point X:	-105.98015846
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
58	W	0.67	3,522.95	6,772.17	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	304643	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	1	Subdiv Loc:	
Start Date:	10/10/2016, 12:00 AM	Restrict :	0.0
Finish Date:	10/14/2016, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	10/19/2016, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	120	UTM Zone:	13
Depth of Water:	105	UTM Accura:	
Ground Water Src:	S	UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411250.3
Pcw Rcv Da:		Northing:	3946564.2
Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	39
Sys Date:	11/21/2016, 12:00 AM	Latitude Second:	32.2
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	49.77
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65894449
Map Nbr:		Point X:	-105.98049155
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
59	W	0.67	3,525.77	6,772.18	WATER WELLS

License Nb:	1848	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	343040	Other Loc:	Iw-4
POD Basin:	RG	Zone :	
POD Suffix:	POD10	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	IW-4	Subdiv Loc:	
Start Date:	10/23/2023, 12:00 AM	Restrict :	0.0
Finish Date:	11/06/2023, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/14/2023, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	117	UTM Zone:	13
Depth of Water:	102	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411249.1
Pcw Rcv Da:		Northing:	3946571.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	01/02/2024, 12:00 AM	Latitude Second:	32.44
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	49.82
Well Tag:	NA	X:	0.0
Static Lev:	102	Y:	0.0
Tract Nbr:		Point Y:	35.65901109
Map Nbr:		Point X:	-105.98050562
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
60	W	0.67	3,531.25	6,773.28	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	305036	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD4	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/20/2017, 12:00 AM	Restrict :	0.0
Finish Date:	02/24/2017, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	03/16/2017, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	115	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	108	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411245.0
Pcw Rcv Da:		Northing:	3946589.8
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	09/21/2018, 12:00 AM	Latitude Second:	33.03
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	49.99
Well Tag:		X:	0.0
Static Lev:	108	Y:	0.0
Tract Nbr:		Point Y:	35.6591748
Map Nbr:		Point X:	-105.98055292
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
61	NNW	0.66	3,502.09	6,808.88	WATER WELLS

License Nb:	228	District Office S:	
POD No:	42471	Surv Map:	
POD Rec No:	27181	Other Loc:	1834 Hano Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	5 3 U4 SF
Start Date:	11/28/1984, 12:00 AM	Restrict :	0.0
Finish Date:	11/30/1984, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	01/25/1985, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA

Wells and Additional Sources Detail Report

Depth of Well:	250	UTM Zone:	13
Depth of Water:	140	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411792.9
Pcw Rcv Da:		Northing:	3947617.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/07/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1722211.0
Static Lev:	0	Y:	1698710.0
Tract Nbr:		Point Y:	35.66848429
Map Nbr:		Point X:	-105.97461313
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
62	W	0.67	3,550.46	6,771.49	WATER WELLS

License Nb:	1848	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	343039	Other Loc:	Iw-3
POD Basin:	RG	Zone :	
POD Suffix:	POD9	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	IW-3	Subdiv Loc:	
Start Date:	10/23/2023, 12:00 AM	Restrict :	0.0
Finish Date:	11/06/2023, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/14/2023, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	0	UTM Source:	PA
Depth of Well:	117	UTM Zone:	13
Depth of Water:	102	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411240.2
Pcw Rcv Da:		Northing:	3946585.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	01/02/2024, 12:00 AM	Latitude Second:	32.88
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	50.18
Well Tag:	NA	X:	0.0
Static Lev:	102	Y:	0.0
Tract Nbr:		Point Y:	35.6591338
Map Nbr:		Point X:	-105.98060545
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
63	W	0.67	3,553.66	6,771.33	WATER WELLS

License Nb:	1848	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	343042	Other Loc:	Iw-6
POD Basin:	RG	Zone :	
POD Suffix:	POD12	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	IW-6	Subdiv Loc:	
Start Date:	10/23/2023, 12:00 AM	Restrict :	0.0
Finish Date:	11/06/2023, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/14/2023, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	116	UTM Zone:	13
Depth of Water:	102	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411242.4
Pcw Rcv Da:		Northing:	3946554.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	01/02/2024, 12:00 AM	Latitude Second:	31.87
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	50.08
Well Tag:	NA	X:	0.0
Static Lev:	102	Y:	0.0
Tract Nbr:		Point Y:	35.65885273
Map Nbr:		Point X:	-105.98057771
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
64	SSW	0.67	3,526.51	6,765.11	WATER WELLS

License Nb:	228	District Office S:	
POD No:	02798	Surv Map:	
POD Rec No:	27748	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/25/1959, 12:00 AM	Restrict :	0.0
Finish Date:	11/05/1959, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	12/08/1959, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2

CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	127	UTM Zone:	13
Depth of Water:	85	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7500.0	County:	Santa Fe
Ref :		Easting:	411746.0
Pcw Rcv Da:		Northing:	3945735.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	06/02/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65151359
Map Nbr:		Point X:	-105.974925
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
65	WNW	0.67	3,539.01	6,775.09	WATER WELLS

License Nb:	0	District Office S:	
POD No:	41631	Surv Map:	
POD Rec No:	30276	Other Loc:	1315 Vitalia St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 1 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411277.0
Pcw Rcv Da:		Northing:	3946972.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/13/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Domingo	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720545.0
Static Lev:	0	Y:	1696573.0
Tract Nbr:		Point Y:	35.66262597
Map Nbr:		Point X:	-105.98024158
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
67	SSE	0.67	3,537.95	6,879.92	WATER WELLS

License Nb:	0	District Office S:	
POD No:	63901	Surv Map:	
POD Rec No:	13282	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	02
Plug Date:		Township:	16N
Log File D:		Range:	09E

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412920.0
Pcw Rcv Da:		Northing:	3945724.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/24/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6515187
Map Nbr:		Point X:	-105.9619565
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
67	SSE	0.67	3,537.95	6,879.92	WATER WELLS

License Nb:	790	District Office S:	
POD No:	74744	Surv Map:	
POD Rec No:	161567	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	02
Plug Date:		Township:	16N

Wells and Additional Sources Detail Report

Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	250	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412920.0
Pcw Rcv Da:		Northing:	3945724.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/10/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6515187
Map Nbr:		Point X:	-105.9619565
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	W	0.68	3,613.50	6,769.65	WATER WELLS

License Nb:	1848	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	343043	Other Loc:	Iw-7
POD Basin:	RG	Zone :	
POD Suffix:	POD13	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	IW-7	Subdiv Loc:	
Start Date:	10/23/2023, 12:00 AM	Restrict :	0.0
Finish Date:	11/06/2023, 12:00 AM	Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:	12/14/2023, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	115	UTM Zone:	13
Depth of Water:	102	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411223.8
Pcw Rcv Da:		Northing:	3946552.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	01/02/2024, 12:00 AM	Latitude Second:	31.8
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	50.82
Well Tag:	NA	X:	0.0
Static Lev:	102	Y:	0.0
Tract Nbr:		Point Y:	35.65883302
Map Nbr:		Point X:	-105.98078295
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
69	SW	0.68	3,586.14	6,762.92	WATER WELLS

License Nb:	228	District Office S:	
POD No:	08166	Surv Map:	
POD Rec No:	19752	Other Loc:	2503 Rancho Siringo Dr
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	C SF
Start Date:	06/25/1977, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	06/28/1977, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	07/11/1977, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	90	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-08166-2/	Easting:	411707.9
Pcw Rcv Da:		Northing:	3945738.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/21/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Lands Of Evelyn H. Lischke	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411707.9
Static Lev:	0	Y:	3945738.5
Tract Nbr:		Point Y:	35.65154173
Map Nbr:		Point X:	-105.97534621
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Parcel Number 1-052-096-224-456		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
70	W	0.69	3,641.29	6,768.75	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	304644	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	POD2	Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:	10/10/2016, 12:00 AM	Restrict :	0.0
Finish Date:	10/14/2016, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	10/19/2016, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	123	UTM Zone:	13
Depth of Water:	103	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411213.8
Pcw Rcv Da:		Northing:	3946563.0
Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	39
Sys Date:	11/21/2016, 12:00 AM	Latitude Second:	32.15
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	51.22
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65893039
Map Nbr:		Point X:	-105.98089461
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	SE	0.68	3,600.15	6,902.91	WATER WELLS

License Nb:	214	District Office S:	
POD No:	00804	Surv Map:	
POD Rec No:	67648	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:	05/01/1957, 12:00 AM	Restrict :	0.0
Finish Date:	05/01/1957, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	06/27/1957, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	275	UTM Zone:	13
Depth of Water:	205	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413142.0
Pcw Rcv Da:		Northing:	3945880.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/30/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65294463
Map Nbr:		Point X:	-105.95952124
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
72	W	0.69	3,647.19	6,768.75	WATER WELLS

License Nb:	0	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	305035	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411212.1
Pcw Rcv Da:		Northing:	3946562.7
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	01/10/2017, 12:00 AM	Latitude Second:	32.14
Subdiv Nam:	College Plaza	Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	51.29
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65892753
Map Nbr:		Point X:	-105.98091336
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
73	SW	0.69	3,641.73	6,762.50	WATER WELLS

License Nb:	228	District Office S:	
POD No:	08166	Surv Map:	
POD Rec No:	3923	Other Loc:	2503 Rancho Siringo Dr
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	C SF
Start Date:	02/01/1962, 12:00 AM	Restrict :	0.0
Finish Date:	02/08/1963, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	04/30/1963, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	92	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	411691.8
Pcw Rcv Da:		Northing:	3945729.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	09/21/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Lands Of Evelyn H. Lischke	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411691.8
Static Lev:	0	Y:	3945729.0
Tract Nbr:		Point Y:	35.65145465
Map Nbr:		Point X:	-105.975523
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Parcel Number 1-052-096-224-456		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
74	W	0.69	3,660.81	6,772.23	WATER WELLS

License Nb:	253	District Office S:	
POD No:	31384	Surv Map:	
POD Rec No:	15389	Other Loc:	2217 Cerrillos Road, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1B NA NA SF
Start Date:	09/26/1978, 12:00 AM	Restrict :	0.0
Finish Date:	09/26/1978, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	10/02/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	127	UTM Zone:	13
Depth of Water:	75	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411218.2
Pcw Rcv Da:		Northing:	3946880.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	El Pollo Asado	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411218.2
Static Lev:	0	Y:	3946880.5
Tract Nbr:		Point Y:	35.66179309
Map Nbr:		Point X:	-105.98088102
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052097059308000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
76	NNE	0.70	3,703.41	6,871.47	WATER WELLS

License Nb:	228	District Office S:	
POD No:	50802	Surv Map:	
POD Rec No:	33899	Other Loc:	1303 Camino Corrales
POD Basin:	RG	Zone :	C

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/01/1991, 12:00 AM	Restrict :	0.0
Finish Date:	06/05/1991, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	06/24/1991, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	560	UTM Zone:	13
Depth of Water:	90	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412658.1
Pcw Rcv Da:		Northing:	3947774.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/20/2016, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	584800.0
Static Lev:	0	Y:	1699200.0
Tract Nbr:		Point Y:	35.66997846
Map Nbr:		Point X:	-105.96507168
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
77	NW	0.70	3,721.16	6,785.54	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31188	Surv Map:	
POD Rec No:	325604	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411496.1
Pcw Rcv Da:		Northing:	3947469.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/13/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581000.0
Static Lev:	0	Y:	1698150.0
Tract Nbr:		Point Y:	35.66712346
Map Nbr:		Point X:	-105.97787581
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
78	NW	0.71	3,742.94	6,782.37	WATER WELLS

License Nb:	790	District Office S:	
POD No:	35792	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	60802	Other Loc:	1231 Osage Ave
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	16 23 SF
Start Date:	03/28/1981, 12:00 AM	Restrict :	0.0
Finish Date:	03/31/1981, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	04/06/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	138	UTM Zone:	13
Depth of Water:	98	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411445.5
Pcw Rcv Da:		Northing:	3947422.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721079.0
Static Lev:	0	Y:	1698058.0
Tract Nbr:		Point Y:	35.66670152
Map Nbr:		Point X:	-105.97842972
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
80	NW	0.71	3,744.00	6,798.08	WATER WELLS

License Nb:	228	District Office S:	

Wells and Additional Sources Detail Report

POD No:	40698	Surv Map:	
POD Rec No:	28861	Other Loc:	1208 San Felipe Ave
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 2 U2 SF
Start Date:	03/19/1984, 12:00 AM	Restrict :	0.0
Finish Date:	03/21/1984, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	06/15/1984, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411659.2
Pcw Rcv Da:		Northing:	3947618.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/15/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre No. 5	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721772.0
Static Lev:	0	Y:	1698710.0
Tract Nbr:		Point Y:	35.66848765
Map Nbr:		Point X:	-105.97609039
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	NW	0.71	3,756.10	6,785.56	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	40295	Surv Map:	
POD Rec No:	33631	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	125	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411496.3
Pcw Rcv Da:		Northing:	3947484.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/22/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581000.0
Static Lev:	0	Y:	1698200.0
Tract Nbr:		Point Y:	35.66726051
Map Nbr:		Point X:	-105.97787527
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
82	NNW	0.72	3,775.92	6,807.91	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	36626	Surv Map:	
POD Rec No:	189490	Other Loc:	1808 Otowi Dr.
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3 1 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411827.6
Pcw Rcv Da:		Northing:	3947728.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/22/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1722320.0
Static Lev:	0	Y:	1699076.0
Tract Nbr:		Point Y:	35.66948897
Map Nbr:		Point X:	-105.97424194
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
84	W	0.72	3,820.99	6,770.46	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	40727	Surv Map:	
POD Rec No:	23926	Other Loc:	1326 Lujan St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411160.8
Pcw Rcv Da:		Northing:	3946824.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/17/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Domingo	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720170.0
Static Lev:	0	Y:	1696084.0
Tract Nbr:		Point Y:	35.66128488
Map Nbr:		Point X:	-105.98150894
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

85	WNW	0.72	3,805.44	6,773.61	WATER WELLS

License Nb:	653	District Office S:	
POD No:	31116	Surv Map:	
POD Rec No:	24662	Other Loc:	1228 Apache Ave
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3 2 SF
Start Date:	09/01/1978, 12:00 AM	Restrict :	0.0
Finish Date:	09/22/1978, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	09/29/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	100	UTM Zone:	13
Depth of Water:	64	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411260.9
Pcw Rcv Da:		Northing:	3947166.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/27/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720484.0
Static Lev:	0	Y:	1697208.0
Tract Nbr:		Point Y:	35.66437075
Map Nbr:		Point X:	-105.98044079
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

86	WNW	0.72	3,821.07	6,775.34	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31273	Surv Map:	
POD Rec No:	64690	Other Loc:	2050 Hopi Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 12 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411284.1
Pcw Rcv Da:		Northing:	3947224.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/09/2019, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411284.1
Static Lev:	0	Y:	3947224.7
Tract Nbr:		Point Y:	35.66490202
Map Nbr:		Point X:	-105.98019096
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Parcel Number 11041920		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
87	NW	0.72	3,827.68	6,782.97	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31367	Surv Map:	
POD Rec No:	291276	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411465.8
Pcw Rcv Da:		Northing:	3947484.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/11/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	580900.0
Static Lev:	0	Y:	1698200.0
Tract Nbr:		Point Y:	35.66726138
Map Nbr:		Point X:	-105.97821227
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
89	SW	0.74	3,919.72	6,744.41	WATER WELLS

License Nb:	0	District Office S:	
POD No:	00655	Surv Map:	
POD Rec No:	4330	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	03
Plug Date:		Township:	16N
Log File D:	04/01/1957, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	37	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	8.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411546.0
Pcw Rcv Da:		Northing:	3945735.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/29/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65149568
Map Nbr:		Point X:	-105.97713407
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
89	SW	0.74	3,919.72	6,744.41	WATER WELLS

License Nb:	0	District Office S:	
POD No:	00643	Surv Map:	
POD Rec No:	10563	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/01/1947, 12:00 AM	Restrict :	0.0
Finish Date:	12/31/1947, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	04/01/1957, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	63	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411546.0
Pcw Rcv Da:		Northing:	3945735.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/28/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65149568
Map Nbr:		Point X:	-105.97713407
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant :

Legal: A Portion Of Lot 3

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
89	SW	0.74	3,919.72	6,744.41	WATER WELLS

License Nb:	0	District Office S:	
POD No:	50525	Surv Map:	
POD Rec No:	65894	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	03
Plug Date:		Township:	16N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411546.0
Pcw Rcv Da:		Northing:	3945735.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/02/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65149568
Map Nbr:		Point X:	-105.97713407
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
89	SW	0.74	3,919.72	6,744.41	WATER WELLS

License Nb:	0	District Office S:	
POD No:	00631	Surv Map:	
POD Rec No:	15437	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/01/1956, 12:00 AM	Restrict :	0.0
Finish Date:	12/31/1956, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	04/01/1957, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	64	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411546.0
Pcw Rcv Da:		Northing:	3945735.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/25/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65149568
Map Nbr:		Point X:	-105.97713407
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal: Portion Of Lot 3

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
89	SW	0.74	3,919.72	6,744.41	WATER WELLS

License Nb:	0	District Office S:	
POD No:	00630	Surv Map:	
POD Rec No:	190415	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	03
Plug Date:		Township:	16N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	84	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411546.0
Pcw Rcv Da:		Northing:	3945735.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/25/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65149568
Map Nbr:		Point X:	-105.97713407

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
89	SW	0.74	3,919.72	6,744.41	WATER WELLS

License Nb:	0	District Office S:	
POD No:	00656	Surv Map:	
POD Rec No:	59549	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/01/1947, 12:00 AM	Restrict :	0.0
Finish Date:	12/31/1947, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	04/01/1957, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	60	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	8.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411546.0
Pcw Rcv Da:		Northing:	3945735.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/29/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65149568

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.97713407
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
90	NNE	0.74	3,909.43	6,882.60	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0942	Surv Map:	
POD Rec No:	339114	Other Loc:	Vw-1
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	26
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412752.9
Pcw Rcv Da:		Northing:	3947809.2
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	12/05/2022, 12:00 AM	Latitude Second:	13.09
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	50.5
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.67030238
Map Nbr:		Point X:	-105.96402813
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
91	NW	0.74	3,908.09	6,783.19	WATER WELLS

License Nb:	227	District Office S:	
POD No:	41936	Surv Map:	
POD Rec No:	54566	Other Loc:	1968 Hano Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	11 3 U5 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:	07/16/1984, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	189	UTM Zone:	13
Depth of Water:	96	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411461.9
Pcw Rcv Da:		Northing:	3947515.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/21/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721129.0

Wells and Additional Sources Detail Report

Static Lev:	0	Y:	1698362.0
Tract Nbr:		Point Y:	35.66753599
Map Nbr:		Point X:	-105.97825871
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
92	SSW	0.74	3,927.89	6,768.50	WATER WELLS

License Nb:	228	District Office S:	
POD No:	04151	Surv Map:	
POD Rec No:	17094	Other Loc:	2504 Rancho Siringo/*Unit A
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TH3* SF
Start Date:	05/02/1960, 12:00 AM	Restrict :	0.0
Finish Date:	05/08/1960, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	08/17/1960, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	90	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411689.6
Pcw Rcv Da:		Northing:	3945625.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/11/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:	NA	X:	1721955.2
Static Lev:	0	Y:	1692171.1
Tract Nbr:		Point Y:	35.65052138
Map Nbr:		Point X:	-105.97553595
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Parcel Number 1-052-096-210-420		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
93	NNW	0.74	3,927.53	6,806.26	WATER WELLS

License Nb:	622	District Office S:	
POD No:	31385	Surv Map:	
POD Rec No:	49565	Other Loc:	1201 San Jose Avenue, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 2 SF
Start Date:	01/30/1979, 12:00 AM	Restrict :	0.0
Finish Date:	02/01/1979, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	02/14/1979, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	140	UTM Zone:	13
Depth of Water:	117	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411891.0
Pcw Rcv Da:		Northing:	3947804.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411891.0
Static Lev:	0	Y:	3947804.9
Tract Nbr:		Point Y:	35.670187
Map Nbr:		Point X:	-105.97354992
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052098274080000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
94	WNW	0.75	3,984.14	6,765.94	WATER WELLS

License Nb:	0	District Office S:	
POD No:	42737	Surv Map:	
POD Rec No:	37998	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411123.3
Pcw Rcv Da:		Northing:	3946909.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579800.0
Static Lev:	0	Y:	1696300.0
Tract Nbr:		Point Y:	35.66204959
Map Nbr:		Point X:	-105.9819326
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
95	SW	0.75	3,976.29	6,762.26	WATER WELLS

License Nb:	228	District Office S:	
POD No:	04622	Surv Map:	
POD Rec No:	21326	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/28/1960, 12:00 AM	Restrict :	0.0
Finish Date:	06/04/1960, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	08/16/1960, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	90	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411647.0
Pcw Rcv Da:		Northing:	3945636.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	07/07/2003, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65061223
Map Nbr:		Point X:	-105.97600763
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
95	SW	0.75	3,976.29	6,762.26	WATER WELLS

License Nb:	214	District Office S:	
POD No:	08010	Surv Map:	
POD Rec No:	30686	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/18/1962, 12:00 AM	Restrict :	0.0
Finish Date:	09/18/1962, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	12/14/1962, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	71	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411647.0
Pcw Rcv Da:		Northing:	3945636.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	05/17/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65061223
Map Nbr:		Point X:	-105.97600763
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
95	SW	0.75	3,976.29	6,762.26	WATER WELLS

License Nb:	0	District Office S:	
POD No:	04453	Surv Map:	LANDS OF EVELYN H. LISCHKE
POD Rec No:	192804	Other Loc:	Street Rancho Siringo, Sf
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	03
Plug Date:		Township:	16N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411647.0
Pcw Rcv Da:		Northing:	3945636.0
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	06/30/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:	F	Point Y:	35.65061223
Map Nbr:		Point X:	-105.97600763
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
95	SW	0.75	3,976.29	6,762.26	WATER WELLS

License Nb:	228	District Office S:	
POD No:	05303	Surv Map:	
POD Rec No:	328083	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	03
Plug Date:		Township:	16N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411647.0
Pcw Rcv Da:		Northing:	3945636.0

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/18/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65061223
Map Nbr:		Point X:	-105.97600763
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
95	SW	0.75	3,976.29	6,762.26	WATER WELLS

License Nb:	228	District Office S:	
POD No:	04472	Surv Map:	
POD Rec No:	6904	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/18/1960, 12:00 AM	Restrict :	0.0
Finish Date:	05/26/1960, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	01/29/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	100	UTM Zone:	13
Depth of Water:	60	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411647.0

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3945636.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	08/13/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65061223
Map Nbr:		Point X:	-105.97600763
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
96	SSW	0.75	3,975.62	6,774.54	WATER WELLS

License Nb:	0	District Office S:	
POD No:	36994	Surv Map:	
POD Rec No:	13190	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	12/01/1981, 12:00 AM	Restrict :	0.0
Finish Date:	12/03/1981, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	12/07/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	90	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	411716.0
Pcw Rcv Da:		Northing:	3945591.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/02/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581800.0
Static Lev:	0	Y:	1692000.0
Tract Nbr:		Point Y:	35.65022083
Map Nbr:		Point X:	-105.97524068
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
98	SSW	0.77	4,055.33	6,793.87	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A1178	Surv Map:	
POD Rec No:	340741	Other Loc:	Sb-6
POD Basin:	RG	Zone :	
POD Suffix:	POD6	BLK:	
Pod Sub Ba:	NRG	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411990.9
Pcw Rcv Da:		Northing:	3945446.7
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	38
Sys Date:	04/13/2023, 12:00 AM	Latitude Second:	56.17
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	19.88
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64893638
Map Nbr:		Point X:	-105.97218849
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
99	SSW	0.77	4,062.35	6,793.87	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A1178	Surv Map:	
POD Rec No:	340738	Other Loc:	Sb-3
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	NRG	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411990.8
Pcw Rcv Da:		Northing:	3945444.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	38
Sys Date:	04/13/2023, 12:00 AM	Latitude Second:	56.1
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	19.88
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64891654
Map Nbr:		Point X:	-105.97218935
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
100	NNW	0.77	4,076.39	6,799.59	WATER WELLS

License Nb:	214	District Office S:	
POD No:	31217	Surv Map:	
POD Rec No:	325646	Other Loc:	1804 San Felipe Circle, Sf
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 2 SF
Start Date:	05/17/1980, 12:00 AM	Restrict :	0.0
Finish Date:	05/17/1980, 12:00 AM	Section:	27
Plug Date:		Township:	12N
Log File D:	05/28/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	211	UTM Zone:	13
Depth of Water:	105	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	24	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411707.6
Pcw Rcv Da:		Northing:	3947769.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/17/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411707.6
Static Lev:	0	Y:	3947769.3
Tract Nbr:		Point Y:	35.66984966
Map Nbr:		Point X:	-105.9755722
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052098211077000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
101	SSW	0.77	4,085.77	6,792.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A1178	Surv Map:	
POD Rec No:	340740	Other Loc:	Sb-5
POD Basin:	RG	Zone :	
POD Suffix:	POD5	BLK:	
Pod Sub Ba:	NRG	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411976.2
Pcw Rcv Da:		Northing:	3945441.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	38
Sys Date:	04/13/2023, 12:00 AM	Latitude Second:	56.01
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	20.46
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6488918
Map Nbr:		Point X:	-105.97235032
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
102	NNW	0.77	4,087.00	6,800.71	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31501	Surv Map:	
POD Rec No:	57940	Other Loc:	1800 San Felipe Circle
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411726.7
Pcw Rcv Da:		Northing:	3947783.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/10/2019, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411726.7
Static Lev:	0	Y:	3947783.1
Tract Nbr:		Point Y:	35.66997578
Map Nbr:		Point X:	-105.9753627
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 11647104		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
103	SSW	0.77	4,088.68	6,792.16	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A1178	Surv Map:	
POD Rec No:	340739	Other Loc:	Sb-4
POD Basin:	RG	Zone :	
POD Suffix:	POD4	BLK:	
Pod Sub Ba:	NRG	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411958.4
Pcw Rcv Da:		Northing:	3945445.8
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	38
Sys Date:	04/13/2023, 12:00 AM	Latitude Second:	56.13
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	21.17
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64892537
Map Nbr:		Point X:	-105.97254735
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
104	SSW	0.78	4,092.76	6,790.89	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A1178	Surv Map:	
POD Rec No:	340737	Other Loc:	Sb-2
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	NRG	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411976.5
Pcw Rcv Da:		Northing:	3945439.7
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	38
Sys Date:	04/13/2023, 12:00 AM	Latitude Second:	55.94
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	20.45
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64887199
Map Nbr:		Point X:	-105.97234677
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
105	SE	0.78	4,097.62	6,905.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	09166	Surv Map:	
POD Rec No:	44289	Other Loc:	See Comments
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G

Wells and Additional Sources Detail Report

Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413342.0
Pcw Rcv Da:		Northing:	3945880.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/21/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65296221
Map Nbr:		Point X:	-105.95731211
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
106	SSW	0.78	4,096.51	6,792.16	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A1178	Surv Map:	
POD Rec No:	340736	Other Loc:	Sb-1
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	NRG	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411956.9
Pcw Rcv Da:		Northing:	3945444.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	38
Sys Date:	04/13/2023, 12:00 AM	Latitude Second:	56.09
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	21.23
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64891352
Map Nbr:		Point X:	-105.97256378
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
107	SSE	0.79	4,161.72	6,824.95	WATER WELLS

License Nb:	0	District Office S:	
POD No:	42189	Surv Map:	
POD Rec No:	5367	Other Loc:	2154 Candelero St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	23 3 U2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	02
Plug Date:		Township:	16N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412876.7
Pcw Rcv Da:		Northing:	3945485.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/27/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Candelero De Santa Fe	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1725856.0
Static Lev:	0	Y:	1691762.0
Tract Nbr:		Point Y:	35.64936656
Map Nbr:		Point X:	-105.962409
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
108	NW	0.80	4,228.62	6,772.06	WATER WELLS

License Nb:	653	District Office S:	
POD No:	31237	Surv Map:	
POD Rec No:	8941	Other Loc:	2019 Otowi Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	5 1 SF
Start Date:	09/26/1978, 12:00 AM	Restrict :	0.0
Finish Date:	10/04/1978, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	10/16/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	105	UTM Zone:	13
Depth of Water:	68	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	18	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411298.1
Pcw Rcv Da:		Northing:	3947476.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/18/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411298.1
Static Lev:	0	Y:	3947476.3
Tract Nbr:		Point Y:	35.66717149
Map Nbr:		Point X:	-105.98006402
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1-052-097-083-505		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
109	NW	0.80	4,229.48	6,776.18	WATER WELLS

License Nb:	253	District Office S:	
POD No:	31598	Surv Map:	
POD Rec No:	52363	Other Loc:	1105 Osage Ave
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	19 1 NA SF
Start Date:	05/29/1981, 12:00 AM	Restrict :	0.0
Finish Date:	05/30/1981, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	06/08/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	114	UTM Zone:	13
Depth of Water:	74	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411360.7
Pcw Rcv Da:		Northing:	3947551.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/23/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411360.7
Static Lev:	0	Y:	3947551.3
Tract Nbr:		Point Y:	35.66785325
Map Nbr:		Point X:	-105.97938071
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1-052-098-102-007		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
109	NW	0.80	4,229.48	6,776.18	WATER WELLS

License Nb:	1472	District Office S:	
POD No:	31598	Surv Map:	
POD Rec No:	287003	Other Loc:	1105 Osage Ave
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	POD2	Subdiv Loc:	19 1 NA SF
Start Date:	10/04/2013, 12:00 AM	Restrict :	0.0
Finish Date:	10/07/2013, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	11/18/2013, 12:00 AM	Range:	09E

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	260	UTM Zone:	13
Depth of Water:	125	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.36	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411360.7
Pcw Rcv Da:		Northing:	3947551.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/23/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411360.7
Static Lev:	0	Y:	3947551.3
Tract Nbr:		Point Y:	35.66785325
Map Nbr:		Point X:	-105.97938071
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1-052-098-102-007		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
110	NNW	0.80	4,231.49	6,798.69	WATER WELLS

License Nb:	0	District Office S:	
POD No:	29384	Surv Map:	
POD Rec No:	35609	Other Loc:	1803 San Felipe Circle
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3 2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411714.5
Pcw Rcv Da:		Northing:	3947826.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/11/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721945.0
Static Lev:	0	Y:	1699394.0
Tract Nbr:		Point Y:	35.67036504
Map Nbr:		Point X:	-105.97550224
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
111	NNW	0.80	4,235.46	6,792.51	WATER WELLS

License Nb:	0	District Office S:	
POD No:	44661	Surv Map:	
POD Rec No:	337726	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/21/1986, 12:00 AM	Restrict :	0.0
Finish Date:	04/27/1986, 12:00 AM	Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:	05/16/1986, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	PA
Depth of Well:	195	UTM Zone:	13
Depth of Water:	95	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	4	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	8000.0	County:	Santa Fe
Ref :		Easting:	411616.9
Pcw Rcv Da:		Northing:	3947770.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411616.9
Static Lev:	0	Y:	3947770.8
Tract Nbr:		Point Y:	35.66985506
Map Nbr:		Point X:	-105.97657441
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
111	NNW	0.80	4,235.46	6,792.51	WATER WELLS

License Nb:	622	District Office S:	
POD No:	44659	Surv Map:	
POD Rec No:	37406	Other Loc:	Ramanda Ridge
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 3 SF
Start Date:	10/14/1985, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	10/15/1985, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	10/21/1985, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	290	UTM Zone:	13
Depth of Water:	180	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411616.9
Pcw Rcv Da:		Northing:	3947770.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ramanda Ridge	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	411616.9
Static Lev:	0	Y:	3947770.8
Tract Nbr:		Point Y:	35.66985506
Map Nbr:		Point X:	-105.97657441
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Lot No. 1 Of Blk 3 Of Ramanda Ridge		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
112	SSW	0.81	4,266.20	6,764.55	WATER WELLS

License Nb:	641	District Office S:	
POD No:	43092	Surv Map:	
POD Rec No:	5411	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	8 5 SF

Wells and Additional Sources Detail Report

Start Date:	02/14/1985, 12:00 AM	Restrict :	0.0
Finish Date:	02/15/1985, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	03/21/1985, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	30	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	3	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411632.3
Pcw Rcv Da:		Northing:	3945538.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/28/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ranchos Encondidos	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721770.8
Static Lev:	0	Y:	1691884.6
Tract Nbr:		Point Y:	35.64973554
Map Nbr:		Point X:	-105.97615934
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Parcel Number 1052096195392000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
113	SSE	0.81	4,290.99	6,818.19	WATER WELLS

License Nb:	0	District Office S:	
POD No:	42229	Surv Map:	
POD Rec No:	61378	Other Loc:	2163 Candelero St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	22 5 U2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	02
Plug Date:		Township:	16N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412783.0
Pcw Rcv Da:		Northing:	3945406.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/28/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Candelero De Santa Fe	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1725552.0
Static Lev:	0	Y:	1691498.0
Tract Nbr:		Point Y:	35.64864428
Map Nbr:		Point X:	-105.96343535
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
114	WNW	0.82	4,307.66	6,767.42	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34773	Surv Map:	
POD Rec No:	67631	Other Loc:	1207 Vitalia St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411177.4
Pcw Rcv Da:		Northing:	3947338.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720203.0
Static Lev:	0	Y:	1697771.0
Tract Nbr:		Point Y:	35.66591924
Map Nbr:		Point X:	-105.98138227
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
115	WNW	0.82	4,320.19	6,765.95	WATER WELLS

License Nb:	653	District Office S:	
POD No:	31073	Surv Map:	
POD Rec No:	49375	Other Loc:	1204 Apache Avenue, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 1 SF
Start Date:	08/08/1978, 12:00 AM	Restrict :	0.0
Finish Date:	09/06/1978, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	09/14/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	100	UTM Zone:	13
Depth of Water:	66	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	16	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411204.2
Pcw Rcv Da:		Northing:	3947390.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/30/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411204.2
Static Lev:	0	Y:	3947390.8
Tract Nbr:		Point Y:	35.66639225
Map Nbr:		Point X:	-105.98109195
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052097045481000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
116	ESE	0.82	4,343.06	6,961.61	WATER WELLS

License Nb:	49	District Office S:	
POD No:	16897	Surv Map:	
POD Rec No:	55508	Other Loc:	See Comment For Loc:
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/07/1970, 12:00 AM	Restrict :	0.0
Finish Date:	01/17/1970, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	01/30/1970, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	310	UTM Zone:	13
Depth of Water:	305	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413650.0
Pcw Rcv Da:		Northing:	3946383.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/24/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65752386
Map Nbr:		Point X:	-105.95396398
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	North St Michael'S Dr & East Of Galisteo St W/I City Of Santa Fe Land Grant		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
117	NNW	0.82	4,355.96	6,791.47	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31202	Surv Map:	
POD Rec No:	325634	Other Loc:	1828 San Felipe, Santa Fe
POD Basin:	RG	Zone :	

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411622.4
Pcw Rcv Da:		Northing:	3947817.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/17/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581400.0
Static Lev:	0	Y:	1699300.0
Tract Nbr:		Point Y:	35.67028016
Map Nbr:		Point X:	-105.97651882
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
118	SSW	0.83	4,367.77	6,779.13	WATER WELLS

License Nb:	253	District Office S:	
POD No:	29101	Surv Map:	
POD Rec No:	69585	Other Loc:	2520 Cactus Lane, Santa Fe

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 TA SF
Start Date:	08/09/1977, 12:00 AM	Restrict :	0.0
Finish Date:	08/10/1977, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	08/12/1977, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	135	UTM Zone:	13
Depth of Water:	76	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411822.1
Pcw Rcv Da:		Northing:	3945405.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/08/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Lischke	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411822.1
Static Lev:	0	Y:	3945405.0
Tract Nbr:		Point Y:	35.64854538
Map Nbr:		Point X:	-105.97404832
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Parcel Number 1052096252357000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
119	WNW	0.83	4,372.56	6,765.06	WATER WELLS

License Nb:	653	District Office S:	
POD No:	30992	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	32953	Other Loc:	1202 Apache Ave
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 1 SF
Start Date:	08/09/1978, 12:00 AM	Restrict :	0.0
Finish Date:	08/18/1978, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	08/29/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	100	UTM Zone:	13
Depth of Water:	58	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411198.5
Pcw Rcv Da:		Northing:	3947410.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720269.0
Static Lev:	0	Y:	1698008.0
Tract Nbr:		Point Y:	35.66657023
Map Nbr:		Point X:	-105.98115711
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
120	SE	0.83	4,376.02	6,867.88	WATER WELLS

License Nb:	253	District Office S:	

Wells and Additional Sources Detail Report

POD No:	08710	Surv Map:	
POD Rec No:	32346	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	REPAR	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/04/1967, 12:00 AM	Restrict :	0.0
Finish Date:	10/07/1967, 12:00 AM	Section:	02
Plug Date:		Township:	16N
Log File D:	01/08/1968, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	448	UTM Zone:	13
Depth of Water:	213	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413212.0
Pcw Rcv Da:		Northing:	3945621.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	04/12/2006, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65061585
Map Nbr:		Point X:	-105.95872014
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
120	SE	0.83	4,376.02	6,867.88	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	253	District Office S:	
POD No:	08710	Surv Map:	
POD Rec No:	18445	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/03/1963, 12:00 AM	Restrict :	0.0
Finish Date:	05/08/1963, 12:00 AM	Section:	02
Plug Date:		Township:	16N
Log File D:	07/16/1963, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	233	UTM Zone:	13
Depth of Water:	195	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413212.0
Pcw Rcv Da:		Northing:	3945621.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/05/1989, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65061585
Map Nbr:		Point X:	-105.95872014
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
120	SE	0.83	4,376.02	6,867.88	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	253	District Office S:	
POD No:	08710	Surv Map:	
POD Rec No:	3704	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	REPAR 1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/22/1974, 12:00 AM	Restrict :	0.0
Finish Date:	10/29/1974, 12:00 AM	Section:	02
Plug Date:		Township:	16N
Log File D:	10/31/1974, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	291	UTM Zone:	13
Depth of Water:	243	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413212.0
Pcw Rcv Da:		Northing:	3945621.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	04/12/2006, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65061585
Map Nbr:		Point X:	-105.95872014
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
121	NW	0.83	4,384.12	6,786.64	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	622	District Office S:	
POD No:	32529	Surv Map:	
POD Rec No:	49938	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/10/1984, 12:00 AM	Restrict :	0.0
Finish Date:	04/11/1984, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/16/1984, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	210	UTM Zone:	13
Depth of Water:	90	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411561.1
Pcw Rcv Da:		Northing:	3947788.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/14/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581200.0
Static Lev:	0	Y:	1699200.0
Tract Nbr:		Point Y:	35.67000692
Map Nbr:		Point X:	-105.9771928
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

121	NW	0.83	4,384.12	6,786.64	WATER WELLS

License Nb:	0	District Office S:	
POD No:	32529	Surv Map:	
POD Rec No:	333202	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411561.1
Pcw Rcv Da:		Northing:	3947788.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/14/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581200.0
Static Lev:	0	Y:	1699200.0
Tract Nbr:		Point Y:	35.67000692
Map Nbr:		Point X:	-105.9771928
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

122	NW	0.83	4,407.88	6,767.90	WATER WELLS

License Nb:	214	District Office S:	
POD No:	33690	Surv Map:	
POD Rec No:	52939	Other Loc:	1066 Osage Circle, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	18 1 SF
Start Date:	09/24/1980, 12:00 AM	Restrict :	0.0
Finish Date:	09/24/1980, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	09/26/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	116	UTM Zone:	13
Depth of Water:	70	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	18	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411246.2
Pcw Rcv Da:		Northing:	3947498.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/15/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411246.2
Static Lev:	0	Y:	3947498.1
Tract Nbr:		Point Y:	35.66736335
Map Nbr:		Point X:	-105.98063979
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052097064514000000		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
123	ENE	0.84	4,452.74	6,944.07	WATER WELLS

License Nb:	253	District Office S:	
POD No:	09030	Surv Map:	
POD Rec No:	50209	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/17/1963, 12:00 AM	Restrict :	0.0
Finish Date:	05/29/1963, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	07/16/1963, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	220	UTM Zone:	13
Depth of Water:	153	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413557.0
Pcw Rcv Da:		Northing:	3947286.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	04/28/2006, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66565644
Map Nbr:		Point X:	-105.95508823
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
123	ENE	0.84	4,452.74	6,944.07	WATER WELLS

License Nb:	253	District Office S:	
POD No:	09030	Surv Map:	
POD Rec No:	7104	Other Loc:	Qtrs Are Projected
POD Basin:	RG	Zone :	
POD Suffix:	REPAR	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/09/1982, 12:00 AM	Restrict :	0.0
Finish Date:	11/24/1982, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	11/30/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	238	UTM Zone:	13
Depth of Water:	189	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413557.0
Pcw Rcv Da:		Northing:	3947286.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	05/17/2006, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66565644
Map Nbr:		Point X:	-105.95508823
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
124	NNW	0.84	4,413.76	6,818.44	WATER WELLS

License Nb:	228	District Office S:	
POD No:	12441	Surv Map:	
POD Rec No:	42431	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/01/1965, 12:00 AM	Restrict :	0.0
Finish Date:	04/04/1965, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	08/12/1965, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	150	UTM Zone:	13
Depth of Water:	110	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	412054.0
Pcw Rcv Da:		Northing:	3948008.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	10/03/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67203252
Map Nbr:		Point X:	-105.97177129
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant :

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
125	SW	0.84	4,437.20	6,755.18	WATER WELLS

License Nb:	253	District Office S:	
POD No:	31150	Surv Map:	
POD Rec No:	41159	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/04/1983, 12:00 AM	Restrict :	0.0
Finish Date:	11/05/1983, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	11/14/1983, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	117	UTM Zone:	13
Depth of Water:	54	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411546.0
Pcw Rcv Da:		Northing:	3945535.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/30/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64969265
Map Nbr:		Point X:	-105.97711211
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
125	SW	0.84	4,437.20	6,755.18	WATER WELLS

License Nb:	253	District Office S:	
POD No:	40551	Surv Map:	
POD Rec No:	51197	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/28/1983, 12:00 AM	Restrict :	0.0
Finish Date:	11/19/1983, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	12/05/1983, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	118	UTM Zone:	13
Depth of Water:	52	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411546.0
Pcw Rcv Da:		Northing:	3945535.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/04/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64969265
Map Nbr:		Point X:	-105.97711211
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
125	SW	0.84	4,437.20	6,755.18	WATER WELLS

License Nb:	228	District Office S:	
POD No:	09844	Surv Map:	
POD Rec No:	58616	Other Loc:	Santa Fe Quad. Map
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/02/1963, 12:00 AM	Restrict :	0.0
Finish Date:	10/18/1963, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	12/23/1963, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	411546.0
Pcw Rcv Da:		Northing:	3945535.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	12/15/2005, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:	I	Point Y:	35.64969265
Map Nbr:		Point X:	-105.97711211

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal: South Of Siringo Road.

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
126	NW	0.84	4,431.64	6,765.88	WATER WELLS

License Nb:	253	District Office S:	
POD No:	29496	Surv Map:	
POD Rec No:	59389	Other Loc:	1062 Osage Circle
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	17 1 SF
Start Date:	10/15/1977, 12:00 AM	Restrict :	0.0
Finish Date:	10/17/1977, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	11/22/1977, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	102	UTM Zone:	13
Depth of Water:	62	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	28	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411223.1
Pcw Rcv Da:		Northing:	3947478.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720347.0
Static Lev:	0	Y:	1698233.0
Tract Nbr:		Point Y:	35.66718818

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.98089288
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
127	SSW	0.84	4,435.51	6,776.37	WATER WELLS

License Nb:	1035	District Office S:	
POD No:	52755	Surv Map:	
POD Rec No:	40996	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/17/1990, 12:00 AM	Restrict :	0.0
Finish Date:	08/19/1990, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	11/25/1991, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	150	UTM Zone:	13
Depth of Water:	70	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412047.7
Pcw Rcv Da:		Northing:	3945313.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/09/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	582900.0
Static Lev:	0	Y:	1691100.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.64773972
Map Nbr:		Point X:	-105.97154658
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
128	NNE	0.84	4,448.47	6,900.48	WATER WELLS

License Nb:	0	District Office S:	
POD No:	65338	Surv Map:	
POD Rec No:	61486	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413024.9
Pcw Rcv Da:		Northing:	3947861.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/11/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	586000.0

Wells and Additional Sources Detail Report

Static Lev:	0	Y:	1699500.0
Tract Nbr:		Point Y:	35.67079339
Map Nbr:		Point X:	-105.96102867
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
129	SSE	0.84	4,441.51	6,830.08	WATER WELLS

License Nb:	0	District Office S:	
POD No:	28920	Surv Map:	
POD Rec No:	282443	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2
Start Date:		Restrict :	0.0
Finish Date:		Section:	02
Plug Date:		Township:	16N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413024.0
Pcw Rcv Da:		Northing:	3945466.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/25/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64920195
Map Nbr:		Point X:	-105.96077992
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
130	WNW	0.84	4,450.71	6,763.28	WATER WELLS

License Nb:	253	District Office S:	
POD No:	30880	Surv Map:	
POD Rec No:	23581	Other Loc:	1201 Vitalia St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 2 SF
Start Date:	09/19/1978, 12:00 AM	Restrict :	0.0
Finish Date:	09/19/1978, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	09/22/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	100	UTM Zone:	13
Depth of Water:	63	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	24	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411162.3
Pcw Rcv Da:		Northing:	3947397.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/30/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Domingo Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720151.0
Static Lev:	0	Y:	1697964.0
Tract Nbr:		Point Y:	35.66644978
Map Nbr:		Point X:	-105.98155559
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
131	NNE	0.84	4,454.49	6,895.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	19584	Surv Map:	
POD Rec No:	44430	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	01/01/1955, 12:00 AM	Section:	26
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	260	UTM Zone:	13
Depth of Water:	248	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:	SUBMER	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412959.0
Pcw Rcv Da:		Northing:	3947899.0
Sched Date:		Latitude Degree:	0
Use of Wel:	COM,DOM,IND	Latitude Minute:	0
Sys Date:	08/22/1991, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67113015
Map Nbr:		Point X:	-105.96176085
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
131	NNE	0.84	4,454.49	6,895.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	41309	Surv Map:	
POD Rec No:	31584	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	26
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412959.0
Pcw Rcv Da:		Northing:	3947899.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/02/2022, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67113015
Map Nbr:		Point X:	-105.96176085
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
132	W	0.85	4,500.84	6,749.49	WATER WELLS

License Nb:	0	District Office S:	
POD No:	78600	Surv Map:	
POD Rec No:	181277	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410965.1
Pcw Rcv Da:		Northing:	3946454.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	08/02/2002, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579300.0
Static Lev:	0	Y:	1694800.0
Tract Nbr:		Point Y:	35.65793254
Map Nbr:		Point X:	-105.98362988
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
133	NW	0.84	4,455.62	6,781.41	WATER WELLS

License Nb:	790	District Office S:	
POD No:	34568	Surv Map:	
POD Rec No:	39428	Other Loc:	1919 Sanidlefonso Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1B 3 TB SF
Start Date:	10/06/1980, 12:00 AM	Restrict :	0.0
Finish Date:	10/10/1980, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	10/14/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	136	UTM Zone:	13
Depth of Water:	92	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411488.8
Pcw Rcv Da:		Northing:	3947762.3
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	10/05/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721207.0
Static Lev:	0	Y:	1699174.0
Tract Nbr:		Point Y:	35.66976694
Map Nbr:		Point X:	-105.97798871
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
134	ESE	0.85	4,470.46	6,923.86	WATER WELLS

License Nb:	227	District Office S:	
POD No:	35346	Surv Map:	
POD Rec No:	54256	Other Loc:	2075 Galisteo Street, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	5 SF
Start Date:	11/17/1980, 12:00 AM	Restrict :	0.0
Finish Date:	12/04/1980, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	12/11/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	240	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413577.3
Pcw Rcv Da:		Northing:	3946045.3

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/29/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	413577.3
Static Lev:	0	Y:	3946045.3
Tract Nbr:		Point Y:	35.65447306
Map Nbr:		Point X:	-105.95473081
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1053097302060000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
135	SSW	0.85	4,467.25	6,772.11	WATER WELLS

License Nb:	228	District Office S:	
POD No:	52364	Surv Map:	
POD Rec No:	46643	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:	07/25/1990, 12:00 AM	Restrict :	0.0
Finish Date:	07/27/1990, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	08/10/1990, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	180	UTM Zone:	13
Depth of Water:	105	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411759.9

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3945399.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/06/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411759.9
Static Lev:	0	Y:	3945399.4
Tract Nbr:		Point Y:	35.64848934
Map Nbr:		Point X:	-105.97473471
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
136	ENE	0.86	4,515.12	6,946.70	WATER WELLS

License Nb:	0	District Office S:	
POD No:	53353	Surv Map:	
POD Rec No:	16666	Other Loc:	1435 S St Francis Dr
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	6 10 U2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	413501.4
Pcw Rcv Da:		Northing:	3947425.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Pacheco Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1727825.0
Static Lev:	0	Y:	1698153.0
Tract Nbr:		Point Y:	35.66690918
Map Nbr:		Point X:	-105.95571746
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
137	NW	0.85	4,480.58	6,771.57	WATER WELLS

License Nb:	253	District Office S:	
POD No:	29321	Surv Map:	
POD Rec No:	62930	Other Loc:	1012 Osage Ave
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	8 2 SF
Start Date:	09/21/1977, 12:00 AM	Restrict :	0.0
Finish Date:	09/22/1977, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	09/27/1977, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	146	UTM Zone:	13
Depth of Water:	83	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411290.6
Pcw Rcv Da:		Northing:	3947587.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/10/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegra #10	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720564.0
Static Lev:	0	Y:	1698592.0
Tract Nbr:		Point Y:	35.66817239
Map Nbr:		Point X:	-105.98015913
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
138	NW	0.85	4,480.75	6,778.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31500	Surv Map:	
POD Rec No:	7016	Other Loc:	1944 San Ildefonso Rd.
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411413.0
Pcw Rcv Da:		Northing:	3947710.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/10/2019, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411413.0
Static Lev:	0	Y:	3947710.1
Tract Nbr:		Point Y:	35.66928955
Map Nbr:		Point X:	-105.9788204
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 10520981190530		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
139	WNW	0.85	4,499.79	6,763.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	38282	Surv Map:	
POD Rec No:	33563	Other Loc:	1207 Lujan St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	20 13 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411087.3
Pcw Rcv Da:		Northing:	3947293.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/26/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Domingo	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1719909.0
Static Lev:	0	Y:	1697620.0
Tract Nbr:		Point Y:	35.66550725
Map Nbr:		Point X:	-105.98237268
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
140	SE	0.85	4,496.82	6,885.69	WATER WELLS

License Nb:	0	District Office S:	
POD No:	36449	Surv Map:	
POD Rec No:	334340	Other Loc:	2099 Galisteo St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1A SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413479.7
Pcw Rcv Da:		Northing:	3945861.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/29/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1727819.0
Static Lev:	0	Y:	1693020.0
Tract Nbr:		Point Y:	35.65280661
Map Nbr:		Point X:	-105.95578913
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
141	W	0.87	4,574.81	6,754.27	WATER WELLS

License Nb:	228	District Office S:	
POD No:	02382	Surv Map:	
POD Rec No:	36482	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/12/1958, 12:00 AM	Restrict :	0.0
Finish Date:	08/25/1958, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	11/21/1958, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	267	UTM Zone:	13
Depth of Water:	211	UTM Accura:	
Ground Water Src:	S	UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410934.0
Pcw Rcv Da:		Northing:	3946510.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	05/22/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65842737
Map Nbr:		Point X:	-105.98397953
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
141	W	0.87	4,574.81	6,754.27	WATER WELLS

License Nb:	0	District Office S:	
POD No:	01394	Surv Map:	
POD Rec No:	29277	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/01/1953, 12:00 AM	Restrict :	0.0
Finish Date:	07/31/1953, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	09/16/1957, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	240	UTM Zone:	13
Depth of Water:	0	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	32	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410934.0
Pcw Rcv Da:		Northing:	3946510.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/12/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65842737
Map Nbr:		Point X:	-105.98397953
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
142	ENE	0.87	4,583.13	6,939.11	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31248	Surv Map:	
POD Rec No:	8591	Other Loc:	102 La Placita Cir.
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 4 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413632.9
Pcw Rcv Da:		Northing:	3947213.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/18/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Mateo Heights	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	413632.9
Static Lev:	0	Y:	3947213.0
Tract Nbr:		Point Y:	35.66500498
Map Nbr:		Point X:	-105.9542419
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1-053-097-315-437		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
143	SSW	0.86	4,556.85	6,769.35	WATER WELLS

License Nb:	214	District Office S:	
POD No:	07082	Surv Map:	
POD Rec No:	26603	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	PLG	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/19/1962, 12:00 AM	Restrict :	0.0
Finish Date:	03/23/1962, 12:00 AM	Section:	03
Plug Date:	08/24/2002, 12:00 AM	Township:	16N
Log File D:	03/27/1962, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G

Wells and Additional Sources Detail Report

Depth of Well:	111	UTM Zone:	13
Depth of Water:	56	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411743.0
Pcw Rcv Da:		Northing:	3945378.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/08/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64829491
Map Nbr:		Point X:	-105.97491902
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
143	SSW	0.86	4,556.85	6,769.35	WATER WELLS

License Nb:	622	District Office S:	
POD No:	37109	Surv Map:	
POD Rec No:	65129	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/23/1981, 12:00 AM	Restrict :	0.0
Finish Date:	11/24/1981, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	12/04/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	0	UTM Source:	G
Depth of Well:	120	UTM Zone:	13
Depth of Water:	55	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411743.0
Pcw Rcv Da:		Northing:	3945378.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/15/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64829491
Map Nbr:		Point X:	-105.97491902
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
144	SSW	0.87	4,572.56	6,764.09	WATER WELLS

License Nb:	606	District Office S:	
POD No:	32336	Surv Map:	
POD Rec No:	51419	Other Loc:	2505 Cactus Lane
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TQ SF
Start Date:	04/01/1979, 12:00 AM	Restrict :	0.0
Finish Date:	05/01/1979, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	05/08/1979, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	130	UTM Zone:	13
Depth of Water:	60	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	35	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411673.1
Pcw Rcv Da:		Northing:	3945407.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/14/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Land Of Evelyn H Lischke	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721910.0
Static Lev:	0	Y:	1691455.0
Tract Nbr:		Point Y:	35.6485546
Map Nbr:		Point X:	-105.9756943
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
145	NW	0.87	4,571.18	6,769.56	WATER WELLS

License Nb:	253	District Office S:	
POD No:	36644	Surv Map:	
POD Rec No:	68392	Other Loc:	1027 Osage Circle
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	6 2 SF
Start Date:	04/17/1982, 12:00 AM	Restrict :	0.0
Finish Date:	05/17/1982, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	05/24/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3

CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	127	UTM Zone:	13
Depth of Water:	73	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	31	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411242.6
Pcw Rcv Da:		Northing:	3947573.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/22/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre #10	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720407.0
Static Lev:	0	Y:	1698543.0
Tract Nbr:		Point Y:	35.66803916
Map Nbr:		Point X:	-105.98068784
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
146	SSW	0.87	4,593.87	6,759.82	WATER WELLS

License Nb:	1616	District Office S:	
POD No:	12383	Surv Map:	
POD Rec No:	230372	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	07/23/2007, 12:00 AM	Restrict :	0.0
Finish Date:	07/24/2007, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/01/2007, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	UN
Depth of Well:	250	UTM Zone:	13
Depth of Water:	94	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411606.4
Pcw Rcv Da:		Northing:	3945437.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/30/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1721690.0
Static Lev:	0	Y:	1691552.0
Tract Nbr:	3	Point Y:	35.64882269
Map Nbr:		Point X:	-105.97643433
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
147	NW	0.87	4,596.47	6,766.41	WATER WELLS

License Nb:	214	District Office S:	
POD No:	31305	Surv Map:	
POD Rec No:	291256	Other Loc:	1052 Osage Circle, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	15 1 SF
Start Date:	03/13/1979, 12:00 AM	Restrict :	0.0
Finish Date:	03/20/1979, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	03/30/1979, 12:00 AM	Range:	09E

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	125	UTM Zone:	13
Depth of Water:	80	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411192.6
Pcw Rcv Da:		Northing:	3947522.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411192.6
Static Lev:	0	Y:	3947522.2
Tract Nbr:		Point Y:	35.66757579
Map Nbr:		Point X:	-105.9812346
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052097048527000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
148	WNW	0.87	4,606.80	6,756.39	WATER WELLS

License Nb:	0	District Office S:	
POD No:	37349	Surv Map:	
POD Rec No:	334455	Other Loc:	1209 Declovina St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 3 U3 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411024.3
Pcw Rcv Da:		Northing:	3947234.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/29/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Domingo	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1719705.0
Static Lev:	0	Y:	1697424.0
Tract Nbr:		Point Y:	35.66496968
Map Nbr:		Point X:	-105.98306214
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
149	NW	0.88	4,630.19	6,767.30	WATER WELLS

License Nb:	253	District Office S:	
POD No:	37718	Surv Map:	
POD Rec No:	52690	Other Loc:	1046 Osage Circle, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	14 1 U10 SF
Start Date:	06/03/1982, 12:00 AM	Restrict :	0.0
Finish Date:	06/29/1982, 12:00 AM	Section:	27

Wells and Additional Sources Detail Report

Plug Date:		Township:	17N
Log File D:	07/07/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	133	UTM Zone:	13
Depth of Water:	69	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	42	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411197.0
Pcw Rcv Da:		Northing:	3947545.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/28/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411197.0
Static Lev:	0	Y:	3947545.2
Tract Nbr:		Point Y:	35.66778353
Map Nbr:		Point X:	-105.98118853
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052098046004000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
150	ESE	0.88	4,646.84	6,955.22	WATER WELLS

License Nb:	547	District Office S:	
POD No:	81912	Surv Map:	
POD Rec No:	199128	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2
Start Date:	03/23/2004, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	03/24/2004, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	04/01/2004, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	EA
Depth of Well:	500	UTM Zone:	13
Depth of Water:	250	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	70	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413712.3
Pcw Rcv Da:		Northing:	3946247.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/26/2024, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Leggits	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	588323.0
Static Lev:	0	Y:	1694233.0
Tract Nbr:		Point Y:	35.65630414
Map Nbr:		Point X:	-105.95326124
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
151	NNW	0.88	4,633.66	6,803.44	WATER WELLS

License Nb:	228	District Office S:	
POD No:	39994	Surv Map:	
POD Rec No:	8067	Other Loc:	1715 Artistic Lane, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1

Wells and Additional Sources Detail Report

Start Date:	07/14/1983, 12:00 AM	Restrict :	0.0
Finish Date:	07/15/1983, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	10/24/1983, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	200	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411725.5
Pcw Rcv Da:		Northing:	3947969.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411725.5
Static Lev:	0	Y:	3947969.1
Tract Nbr:		Point Y:	35.67165248
Map Nbr:		Point X:	-105.97539636
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052098216140000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
152	SSW	0.88	4,640.92	6,760.62	WATER WELLS

License Nb:	228	District Office S:	
POD No:	12110	Surv Map:	
POD Rec No:	44856	Other Loc:	2507 Cactus Lane
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	TP SF
Start Date:	03/22/1965, 12:00 AM	Restrict :	0.0
Finish Date:	03/23/1965, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	08/12/1965, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	102	UTM Zone:	13
Depth of Water:	35	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :	RG-12110-/	Easting:	411622.0
Pcw Rcv Da:		Northing:	3945412.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/30/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721742.0
Static Lev:	0	Y:	1691469.0
Tract Nbr:		Point Y:	35.6485942
Map Nbr:		Point X:	-105.97625923
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Lot P Of The Evelyn H. Lischke, Santa Fe		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
153	NW	0.88	4,636.53	6,770.37	WATER WELLS

License Nb:	1035	District Office S:	
POD No:	52767	Surv Map:	
POD Rec No:	61622	Other Loc:	Ward 4
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA SF
Start Date:	08/13/1990, 12:00 AM	Restrict :	0.0
Finish Date:	08/15/1990, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	06/11/1991, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	150	UTM Zone:	13
Depth of Water:	70	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411250.0
Pcw Rcv Da:		Northing:	3947613.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/09/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Haven Terrell	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66839953
Map Nbr:		Point X:	-105.98061048
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
154	SSW	0.88	4,649.61	6,769.47	WATER WELLS

License Nb:	606	District Office S:	
POD No:	30831	Surv Map:	
POD Rec No:	46210	Other Loc:	2204 Yucca St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/30/1978, 12:00 AM	Restrict :	0.0
Finish Date:	12/06/1978, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	12/06/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	176	UTM Zone:	13
Depth of Water:	60	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	60	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411781.8
Pcw Rcv Da:		Northing:	3945329.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/30/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1722270.0
Static Lev:	0	Y:	1691203.0
Tract Nbr:		Point Y:	35.64785934
Map Nbr:		Point X:	-105.97448515
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
155	WSW	0.89	4,704.32	6,743.81	WATER WELLS

License Nb:	239	District Office S:	
POD No:	02672	Surv Map:	
POD Rec No:	3857	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/17/1958, 12:00 AM	Restrict :	0.0
Finish Date:	11/29/1958, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	12/09/1958, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	242	UTM Zone:	13
Depth of Water:	206	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.25	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410934.0
Pcw Rcv Da:		Northing:	3946310.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	07/07/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65662435
Map Nbr:		Point X:	-105.98395741
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
156	NW	0.88	4,650.80	6,766.44	WATER WELLS

License Nb:	0	District Office S:	
POD No:	37923	Surv Map:	
POD Rec No:	3071	Other Loc:	
POD Basin:	RG	Zone :	C

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411192.4
Pcw Rcv Da:		Northing:	3947549.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/07/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	580000.0
Static Lev:	0	Y:	1698400.0
Tract Nbr:		Point Y:	35.66781738
Map Nbr:		Point X:	-105.98123977
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
158	SSW	0.88	4,660.14	6,763.44	WATER WELLS

License Nb:	253	District Office S:	
POD No:	14694	Surv Map:	
POD Rec No:	242466	Other Loc:	2209 Yucca St

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 SF
Start Date:	03/14/1967, 12:00 AM	Restrict :	0.0
Finish Date:	03/31/1967, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	12/01/1967, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	122	UTM Zone:	13
Depth of Water:	60	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411867.3
Pcw Rcv Da:		Northing:	3945293.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/21/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	High School	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1722552.0
Static Lev:	0	Y:	1691088.0
Tract Nbr:		Point Y:	35.64754062
Map Nbr:		Point X:	-105.97353685
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
159	SSW	0.88	4,670.52	6,766.45	WATER WELLS

License Nb:	228	District Office S:	
POD No:	15214	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	62757	Other Loc:	2502 Cactus Ln., Santa Fe, Nm
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	03
Plug Date:		Township:	16N
Log File D:	12/12/1967, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	130	UTM Zone:	13
Depth of Water:	60	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	411727.3
Pcw Rcv Da:		Northing:	3945347.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/12/2024, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1722090.4
Static Lev:	0	Y:	1691259.3
Tract Nbr:		Point Y:	35.64801493
Map Nbr:		Point X:	-105.97508904
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
160	SSE	0.89	4,688.97	6,843.71	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	75298	Surv Map:	
POD Rec No:	165194	Other Loc:	2129 Candelero St, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	37 5 U2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	02
Plug Date:		Township:	16N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413095.6
Pcw Rcv Da:		Northing:	3945420.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/25/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Candelero De Santa Fe	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	413095.6
Static Lev:	0	Y:	3945420.8
Tract Nbr:		Point Y:	35.64880077
Map Nbr:		Point X:	-105.95998422
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Parcel Number 1053096140367000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
161	SSW	0.90	4,729.39	6,755.22	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	228	District Office S:	
POD No:	12383	Surv Map:	
POD Rec No:	17131	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/22/1965, 12:00 AM	Restrict :	0.0
Finish Date:	03/28/1965, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	08/12/1965, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	100	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	411542.1
Pcw Rcv Da:		Northing:	3945429.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/30/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581236.0
Static Lev:	0	Y:	1691460.0
Tract Nbr:	3	Point Y:	35.6487421
Map Nbr:		Point X:	-105.97714361
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Tract 3 Compisite Plate Showing Lands Of Evelyn H. Liechke		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
162	NNW	0.90	4,730.27	6,789.45	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	228	District Office S:	
POD No:	02849	Surv Map:	
POD Rec No:	51536	Other Loc:	Barela Street-Not Numbered Yet
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/10/1959, 12:00 AM	Restrict :	0.0
Finish Date:	02/20/1959, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	02/24/1959, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	87	UTM Zone:	13
Depth of Water:	60	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7500.0	County:	Santa Fe
Ref :		Easting:	411555.0
Pcw Rcv Da:		Northing:	3947911.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	05/29/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67111343
Map Nbr:		Point X:	-105.97727368
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
163	ENE	0.91	4,800.39	6,954.08	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	214	District Office S:	
POD No:	35407	Surv Map:	
POD Rec No:	60902	Other Loc:	129 Mateo Circle, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 1 SF
Start Date:	12/09/1980, 12:00 AM	Restrict :	0.0
Finish Date:	12/11/1980, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	01/07/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	336	UTM Zone:	13
Depth of Water:	240	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413764.5
Pcw Rcv Da:		Northing:	3947023.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/05/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Mateo Heights	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	413764.5
Static Lev:	0	Y:	3947023.5
Tract Nbr:		Point Y:	35.66330811
Map Nbr:		Point X:	-105.95276778
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1053097360371000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

164	SSW	0.90	4,747.96	6,768.18	WATER WELLS

License Nb:	547	District Office S:	
POD No:	82698	Surv Map:	
POD Rec No:	202403	Other Loc:	Well @ 2501 Ponderosa Lane
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/26/2004, 12:00 AM	Restrict :	0.0
Finish Date:	05/26/2004, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	06/07/2004, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	EA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	79	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	65	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411794.7
Pcw Rcv Da:		Northing:	3945291.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	38
Sys Date:	09/04/2024, 12:00 AM	Latitude Second:	51.07
Subdiv Nam:	Na	Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	27.62
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64751971
Map Nbr:		Point X:	-105.97433853
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Parcel Number:1052096252309000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

165	WNW	0.90	4,777.72	6,749.49	WATER WELLS

License Nb:	0	District Office S:	
POD No:	39859	Surv Map:	
POD Rec No:	335262	Other Loc:	2405 Maclovia Lane
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	6 3 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410947.5
Pcw Rcv Da:		Northing:	3947182.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/23/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1719455.0
Static Lev:	0	Y:	1697248.0
Tract Nbr:		Point Y:	35.66448855
Map Nbr:		Point X:	-105.98390475
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
166	ESE	0.90	4,773.34	6,918.38	WATER WELLS

License Nb:	228	District Office S:	
POD No:	17863	Surv Map:	
POD Rec No:	40390	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/15/1970, 12:00 AM	Restrict :	0.0
Finish Date:	01/04/1971, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	01/25/1971, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	350	UTM Zone:	13
Depth of Water:	220	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	413646.0
Pcw Rcv Da:		Northing:	3945977.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/15/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65386333
Map Nbr:		Point X:	-105.95396464
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
168	ENE	0.92	4,833.64	6,954.92	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34375	Surv Map:	
POD Rec No:	70667	Other Loc:	129 Mateo Circle N
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 1 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413777.2
Pcw Rcv Da:		Northing:	3947015.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/29/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Mateo Heights	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1728747.0
Static Lev:	0	Y:	1696820.0
Tract Nbr:		Point Y:	35.6632389
Map Nbr:		Point X:	-105.95262665
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
169	W	0.91	4,827.09	6,752.09	WATER WELLS

License Nb:	0	District Office S:	
POD No:	41552	Surv Map:	
POD Rec No:	9522	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	12/31/1954, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410846.7
Pcw Rcv Da:		Northing:	3946730.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	578900.0
Static Lev:	0	Y:	1695700.0
Tract Nbr:		Point Y:	35.66040822
Map Nbr:		Point X:	-105.98496829
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
170	SSW	0.91	4,807.29	6,765.17	WATER WELLS

License Nb:	1316	District Office S:	
POD No:	07082	Surv Map:	
POD Rec No:	179805	Other Loc:	2501 C Ponderosa Lane
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 SF
Start Date:	08/20/2002, 12:00 AM	Restrict :	0.0
Finish Date:	08/24/2002, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	08/27/2002, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	140	UTM Zone:	13
Depth of Water:	70	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-07082-CLW233172/26603/RG-07	Easting:	411746.9
Pcw Rcv Da:		Northing:	3945292.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/08/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1722157.0
Static Lev:	0	Y:	1691080.0
Tract Nbr:		Point Y:	35.64752175
Map Nbr:		Point X:	-105.97486655
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
171	SSW	0.92	4,832.66	6,764.83	WATER WELLS

License Nb:	253	District Office S:	
POD No:	03440	Surv Map:	
POD Rec No:	9856	Other Loc:	2501c Ponderosa Lane
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 SF
Start Date:	06/22/1959, 12:00 AM	Restrict :	0.0
Finish Date:	06/24/1959, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	07/21/1959, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	107	UTM Zone:	13
Depth of Water:	53	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411761.0
Pcw Rcv Da:		Northing:	3945277.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1722204.0
Static Lev:	0	Y:	1691033.0
Tract Nbr:		Point Y:	35.64739229
Map Nbr:		Point X:	-105.97470923
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
172	W	0.92	4,863.67	6,748.33	WATER WELLS

License Nb:	228	District Office S:	
POD No:	03397	Surv Map:	
POD Rec No:	60094	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/08/1959, 12:00 AM	Restrict :	0.0
Finish Date:	06/22/1959, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	07/07/1959, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	223	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	410840.0
Pcw Rcv Da:		Northing:	3946813.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/03/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66115046
Map Nbr:		Point X:	-105.98505143

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
172	W	0.92	4,863.67	6,748.33	WATER WELLS

License Nb:	253	District Office S:	
POD No:	07200	Surv Map:	
POD Rec No:	6722	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/16/1962, 12:00 AM	Restrict :	0.0
Finish Date:	04/17/1962, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	02/19/1963, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	235	UTM Zone:	13
Depth of Water:	218	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410840.0
Pcw Rcv Da:		Northing:	3946813.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	09/24/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66115046

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.98505143
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
173	SE	0.92	4,843.09	6,915.36	WATER WELLS

License Nb:	228	District Office S:	
POD No:	51026	Surv Map:	
POD Rec No:	4327	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	06/26/1989, 12:00 AM	Restrict :	0.0
Finish Date:	06/29/1989, 12:00 AM	Section:	02
Plug Date:		Township:	16N
Log File D:	06/30/1989, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	220	UTM Zone:	13
Depth of Water:	80	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413503.0
Pcw Rcv Da:		Northing:	3945716.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/19/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.65149784
Map Nbr:		Point X:	-105.95551615
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
174	SE	0.92	4,854.92	6,876.08	WATER WELLS

License Nb:	622	District Office S:	
POD No:	37334	Surv Map:	
POD Rec No:	51067	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/01/1982, 12:00 AM	Restrict :	0.0
Finish Date:	07/02/1982, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	07/07/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	360	UTM Zone:	13
Depth of Water:	240	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413577.9
Pcw Rcv Da:		Northing:	3945812.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/10/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	587900.0

Static Lev:	0	Y:	1692800.0
Tract Nbr:		Point Y:	35.65237076
Map Nbr:		Point X:	-105.95469916
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
175	SSW	0.92	4,859.33	6,759.22	WATER WELLS

License Nb:	228	District Office S:	
POD No:	21472	Surv Map:	
POD Rec No:	49312	Other Loc:	2508 Cactus Ln, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 SF
Start Date:	10/05/1972, 12:00 AM	Restrict :	0.0
Finish Date:	10/05/1972, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	10/10/1972, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	140	UTM Zone:	13
Depth of Water:	75	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.5	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	411634.5
Pcw Rcv Da:		Northing:	3945328.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/26/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Lischke	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:	NA	X:	411634.5
Static Lev:	0	Y:	3945328.7
Tract Nbr:		Point Y:	35.64784075
Map Nbr:		Point X:	-105.97611199
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Parcel Number 1052096192316000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
176	E	0.93	4,890.61	6,969.65	WATER WELLS

License Nb:	585	District Office S:	
POD No:	26655	Surv Map:	
POD Rec No:	59563	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	12/06/1975, 12:00 AM	Restrict :	0.0
Finish Date:	12/28/1975, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	01/13/1976, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	332	UTM Zone:	13
Depth of Water:	262	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.13	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413829.8
Pcw Rcv Da:		Northing:	3946448.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/21/2010, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	588700.0
Static Lev:	0	Y:	1694900.0
Tract Nbr:		Point Y:	35.65813278
Map Nbr:		Point X:	-105.9519849
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
177	SSW	0.93	4,901.77	6,760.52	WATER WELLS

License Nb:	547	District Office S:	
POD No:	03472	Surv Map:	
POD Rec No:	10125	Other Loc:	2503 Ponderosa Lane
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/28/2004, 12:00 AM	Restrict :	0.0
Finish Date:	08/28/2004, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	09/07/2004, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	80	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411707.4
Pcw Rcv Da:		Northing:	3945277.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1722028.0
Static Lev:	0	Y:	1691030.0
Tract Nbr:		Point Y:	35.6473857
Map Nbr:		Point X:	-105.97530121
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
178	NW	0.93	4,896.90	6,776.08	WATER WELLS

License Nb:	253	District Office S:	
POD No:	23084	Surv Map:	
POD Rec No:	51166	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/23/1973, 12:00 AM	Restrict :	0.0
Finish Date:	04/26/1973, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	05/07/1973, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	52	UTM Zone:	13
Depth of Water:	17	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411348.2
Pcw Rcv Da:		Northing:	3947821.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/25/2009, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	580500.0
Static Lev:	0	Y:	1699300.0
Tract Nbr:		Point Y:	35.67028621
Map Nbr:		Point X:	-105.97954854
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
179	W	0.94	4,943.29	6,749.49	WATER WELLS

License Nb:	253	District Office S:	
POD No:	03889	Surv Map:	
POD Rec No:	19821	Other Loc:	2641 Cerrillos Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/03/1959, 12:00 AM	Restrict :	0.0
Finish Date:	10/08/1959, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	10/19/1959, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	284	UTM Zone:	13
Depth of Water:	226	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410815.5
Pcw Rcv Da:		Northing:	3946559.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	08/06/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1719048.0
Static Lev:	0	Y:	1695199.0
Tract Nbr:		Point Y:	35.65886201
Map Nbr:		Point X:	-105.98529398
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
180	SSW	0.93	4,910.35	6,759.62	WATER WELLS

License Nb:	622	District Office S:	
POD No:	14048	Surv Map:	
POD Rec No:	328923	Other Loc:	2505 Ponderosa Ln
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3 5 SF
Start Date:	08/12/2005, 12:00 AM	Restrict :	0.0
Finish Date:	08/12/2005, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	08/12/2005, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	200	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	12	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411675.3
Pcw Rcv Da:		Northing:	3945290.9
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	10/19/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Los Cedros	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411675.3
Static Lev:	95	Y:	3945290.9
Tract Nbr:		Point Y:	35.64750363
Map Nbr:		Point X:	-105.97565722
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Parcel Number 1052096207316000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
181	ESE	0.93	4,928.25	6,950.08	WATER WELLS

License Nb:	0	District Office S:	
POD No:	81672	Surv Map:	
POD Rec No:	198001	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413815.4
Pcw Rcv Da:		Northing:	3946300.6

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/06/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	588659.0
Static Lev:	0	Y:	1694413.0
Tract Nbr:		Point Y:	35.65679546
Map Nbr:		Point X:	-105.95212811
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
182	N	0.93	4,909.47	6,828.51	WATER WELLS

License Nb:	0	District Office S:	
POD No:	29514	Surv Map:	
POD Rec No:	284474	Other Loc:	Usgs 7.5' Quad "Santa Fe"
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412145.0

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3948177.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/17/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	412145.0
Static Lev:	0	Y:	3948177.0
Tract Nbr:		Point Y:	35.67356419
Map Nbr:		Point X:	-105.97078436
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
183	NNW	0.93	4,915.26	6,798.11	WATER WELLS

License Nb:	1004	District Office S:	
POD No:	55005	Surv Map:	
POD Rec No:	63913	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/30/1993, 12:00 AM	Restrict :	0.0
Finish Date:	05/01/1993, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	05/03/1993, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	240	UTM Zone:	13
Depth of Water:	133	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	411655.6
Pcw Rcv Da:		Northing:	3948030.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/09/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581500.0
Static Lev:	0	Y:	1700000.0
Tract Nbr:		Point Y:	35.67220246
Map Nbr:		Point X:	-105.9761754
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
184	E	0.94	4,956.53	6,971.27	WATER WELLS

License Nb:	228	District Office S:	
POD No:	45507	Surv Map:	
POD Rec No:	17739	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/21/1986, 12:00 AM	Restrict :	0.0
Finish Date:	04/25/1986, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	05/26/1986, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	500	UTM Zone:	13
Depth of Water:	240	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	80	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413862.6
Pcw Rcv Da:		Northing:	3946631.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/18/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	588800.0
Static Lev:	0	Y:	1695500.0
Tract Nbr:		Point Y:	35.65978092
Map Nbr:		Point X:	-105.9516421
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
185	SW	0.93	4,936.26	6,751.33	WATER WELLS

License Nb:	0	District Office S:	
POD No:	32413	Surv Map:	
POD Rec No:	51857	Other Loc:	2203 Rancho Sirango Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 SF
Start Date:	05/01/1979, 12:00 AM	Restrict :	0.0
Finish Date:	05/01/1979, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	06/12/1979, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	140	UTM Zone:	13
Depth of Water:	60	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411480.0
Pcw Rcv Da:		Northing:	3945395.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/14/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721277.0
Static Lev:	0	Y:	1691409.0
Tract Nbr:		Point Y:	35.64843273
Map Nbr:		Point X:	-105.97782581
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
186	WNW	0.94	4,957.00	6,743.62	WATER WELLS

License Nb:	227	District Office S:	
POD No:	36500	Surv Map:	
POD Rec No:	68364	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/03/1981, 12:00 AM	Restrict :	0.0
Finish Date:	07/06/1981, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	07/14/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	96	UTM Zone:	13
Depth of Water:	46	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410943.0
Pcw Rcv Da:		Northing:	3947314.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/24/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66567634
Map Nbr:		Point X:	-105.98396904
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
187	NW	0.94	4,966.12	6,781.99	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34886	Surv Map:	
POD Rec No:	22801	Other Loc:	522 Solano
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	A SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411397.8
Pcw Rcv Da:		Northing:	3947888.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/14/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Cienegitas	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720903.0
Static Lev:	0	Y:	1699584.0
Tract Nbr:		Point Y:	35.67089558
Map Nbr:		Point X:	-105.97900795
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.94	4,970.86	6,760.31	WATER WELLS

License Nb:	0	District Office S:	
POD No:	00666	Surv Map:	
POD Rec No:	58191	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	03
Plug Date:		Township:	16N
Log File D:	04/01/1957, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	68	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411936.0
Pcw Rcv Da:		Northing:	3945173.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/06/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64646403
Map Nbr:		Point X:	-105.97276494
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.94	4,970.86	6,760.31	WATER WELLS

License Nb:	239	District Office S:	
POD No:	05242	Surv Map:	
POD Rec No:	69486	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/12/1960, 12:00 AM	Restrict :	0.0
Finish Date:	10/20/1960, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	11/07/1960, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	72	UTM Zone:	13
Depth of Water:	35	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411936.0
Pcw Rcv Da:		Northing:	3945173.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/14/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64646403
Map Nbr:		Point X:	-105.97276494
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.94	4,970.86	6,760.31	WATER WELLS

License Nb:	0	District Office S:	
POD No:	14694	Surv Map:	
POD Rec No:	8137	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	03
Plug Date:		Township:	16N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411936.0
Pcw Rcv Da:		Northing:	3945173.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/21/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64646403
Map Nbr:		Point X:	-105.97276494
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
189	SSW	0.95	4,990.51	6,757.17	WATER WELLS

License Nb:	228	District Office S:	
POD No:	07636	Surv Map:	
POD Rec No:	52095	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/10/1962, 12:00 AM	Restrict :	0.0
Finish Date:	07/18/1962, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	07/09/1963, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G

Wells and Additional Sources Detail Report

Depth of Well:	105	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	411644.0
Pcw Rcv Da:		Northing:	3945279.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	03/30/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64739355
Map Nbr:		Point X:	-105.97600161
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
189	SSW	0.95	4,990.51	6,757.17	WATER WELLS

License Nb:	228	District Office S:	
POD No:	03542	Surv Map:	
POD Rec No:	21000	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/06/1959, 12:00 AM	Restrict :	0.0
Finish Date:	07/12/1959, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	12/08/1959, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	0	UTM Source:	G
Depth of Well:	75	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	411644.0
Pcw Rcv Da:		Northing:	3945279.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	06/12/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64739355
Map Nbr:		Point X:	-105.97600161
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
189	SSW	0.95	4,990.51	6,757.17	WATER WELLS

License Nb:	0	District Office S:	
POD No:	14048	Surv Map:	
POD Rec No:	12732	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	03
Plug Date:		Township:	16N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	95	UTM Accura:	
Ground Water Src:	A	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411644.0
Pcw Rcv Da:		Northing:	3945279.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/19/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64739355
Map Nbr:		Point X:	-105.97600161
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
190	SSW	0.95	5,001.84	6,757.99	WATER WELLS

License Nb:	253	District Office S:	
POD No:	04472	Surv Map:	
POD Rec No:	192850	Other Loc:	2500 Ponderosa Lane
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 T9 SF
Start Date:	01/23/1981, 12:00 AM	Restrict :	0.0
Finish Date:	01/24/1981, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	01/29/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	160	UTM Zone:	13
Depth of Water:	74	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-04472-CLW276157/6904/RG-044	Easting:	411807.7
Pcw Rcv Da:		Northing:	3945204.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/13/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1722360.0
Static Lev:	0	Y:	1690794.0
Tract Nbr:		Point Y:	35.64673475
Map Nbr:		Point X:	-105.9741854
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
191	ESE	0.95	5,017.67	6,920.80	WATER WELLS

License Nb:	0	District Office S:	
POD No:	39248	Surv Map:	
POD Rec No:	36673	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413763.8
Pcw Rcv Da:		Northing:	3946053.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	588500.0
Static Lev:	0	Y:	1693600.0
Tract Nbr:		Point Y:	35.6545633
Map Nbr:		Point X:	-105.95267164
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
192	NW	0.95	5,010.85	6,763.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	37922	Surv Map:	
POD Rec No:	16648	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411101.7
Pcw Rcv Da:		Northing:	3947611.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/07/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579700.0
Static Lev:	0	Y:	1698600.0
Tract Nbr:		Point Y:	35.66836904
Map Nbr:		Point X:	-105.98224864
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
193	WNW	0.95	5,024.43	6,751.58	WATER WELLS

License Nb:	1004	District Office S:	
POD No:	46868	Surv Map:	
POD Rec No:	7850	Other Loc:	2372 Camino Hualapai, Unit A
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	UA SF
Start Date:	03/17/1987, 12:00 AM	Restrict :	0.0
Finish Date:	03/18/1987, 12:00 AM	Section:	34
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:	03/07/2005, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	138	UTM Zone:	13
Depth of Water:	65	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410961.8
Pcw Rcv Da:		Northing:	3947399.6
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	08/02/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Hualapai	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1719493.0
Static Lev:	0	Y:	1697962.0
Tract Nbr:		Point Y:	35.66644973
Map Nbr:		Point X:	-105.98377082
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
194	SSW	0.95	5,028.29	6,755.46	WATER WELLS

License Nb:	253	District Office S:	
POD No:	24853	Surv Map:	
POD Rec No:	18588	Other Loc:	2500 Ponderosa Lane
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 T9 SF
Start Date:	09/18/1974, 12:00 AM	Restrict :	0.0
Finish Date:	09/30/1974, 12:00 AM	Section:	03

Wells and Additional Sources Detail Report

Plug Date:		Township:	16N
Log File D:	10/10/1974, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	138	UTM Zone:	13
Depth of Water:	52	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411808.1
Pcw Rcv Da:		Northing:	3945194.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/22/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1722362.0
Static Lev:	0	Y:	1690763.0
Tract Nbr:		Point Y:	35.64665005
Map Nbr:		Point X:	-105.97417996
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
195	NW	0.95	5,032.21	6,763.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	25985	Surv Map:	
POD Rec No:	50390	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411194.7
Pcw Rcv Da:		Northing:	3947731.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/29/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	580000.0
Static Lev:	0	Y:	1699000.0
Tract Nbr:		Point Y:	35.66946645
Map Nbr:		Point X:	-105.98123454
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Approx. 1000' Sw Of Osage Well		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
197	NW	0.95	5,035.25	6,764.41	WATER WELLS

License Nb:	228	District Office S:	
POD No:	36845	Surv Map:	
POD Rec No:	15451	Other Loc:	1008 Osage Circle, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	5 1 SF

Wells and Additional Sources Detail Report

Start Date:	06/04/1982, 12:00 AM	Restrict :	0.0
Finish Date:	06/10/1982, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	06/17/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	190	UTM Zone:	13
Depth of Water:	70	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	12	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-36845-/	Easting:	411177.4
Pcw Rcv Da:		Northing:	3947714.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/16/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411177.4
Static Lev:	0	Y:	3947714.3
Tract Nbr:		Point Y:	35.66930622
Map Nbr:		Point X:	-105.98142372
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052098039061000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
198	ESE	0.96	5,045.92	6,900.36	WATER WELLS

License Nb:	622	District Office S:	
POD No:	33766	Surv Map:	
POD Rec No:	331159	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:	09/04/1980, 12:00 AM	Restrict :	0.0
Finish Date:	09/04/1980, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	09/11/1980, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	280	UTM Zone:	13
Depth of Water:	50	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413732.2
Pcw Rcv Da:		Northing:	3945962.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/19/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	588400.0
Static Lev:	0	Y:	1693300.0
Tract Nbr:		Point Y:	35.65374015
Map Nbr:		Point X:	-105.95301094
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
199	SSW	0.96	5,055.72	6,754.24	WATER WELLS

License Nb:	497	District Office S:	
POD No:	31917	Surv Map:	
POD Rec No:	39891	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	0 SF
Start Date:	03/05/1979, 12:00 AM	Restrict :	0.0
Finish Date:	03/06/1979, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	03/13/1979, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	140	UTM Zone:	13
Depth of Water:	80	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411844.0
Pcw Rcv Da:		Northing:	3945174.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/07/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Rhoda	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64646484
Map Nbr:		Point X:	-105.97378116
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
200	SW	0.97	5,108.63	6,738.83	WATER WELLS

License Nb:	622	District Office S:	
POD No:	38742	Surv Map:	
POD Rec No:	15632	Other Loc:	2257 Calle Pulido
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	11 5 SF
Start Date:	10/04/1982, 12:00 AM	Restrict :	0.0
Finish Date:	10/04/1982, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	10/15/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	240	UTM Zone:	13
Depth of Water:	140	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411306.9
Pcw Rcv Da:		Northing:	3945463.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Los Cedros	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720706.0
Static Lev:	0	Y:	1691625.0
Tract Nbr:		Point Y:	35.64903022
Map Nbr:		Point X:	-105.97974517
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
201	SW	0.97	5,119.20	6,740.64	WATER WELLS

License Nb:	253	District Office S:	
POD No:	38518	Surv Map:	
POD Rec No:	44581	Other Loc:	2261 Calle Pulido
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/01/1982, 12:00 AM	Restrict :	0.0
Finish Date:	10/30/1982, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	11/03/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	116	UTM Zone:	13
Depth of Water:	47	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411312.1
Pcw Rcv Da:		Northing:	3945454.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/02/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1720723.4
Static Lev:	0	Y:	1691595.7
Tract Nbr:		Point Y:	35.64894955
Map Nbr:		Point X:	-105.97968675
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
203	NW	0.97	5,115.53	6,758.47	WATER WELLS

License Nb:	1004	District Office S:	
POD No:	54398	Surv Map:	
POD Rec No:	36563	Other Loc:	
POD Basin:	RG	Zone :	C

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/18/1991, 12:00 AM	Restrict :	0.0
Finish Date:	11/19/1991, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	11/25/1991, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	50	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	35	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411040.4
Pcw Rcv Da:		Northing:	3947581.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/15/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579500.0
Static Lev:	0	Y:	1698500.0
Tract Nbr:		Point Y:	35.66809667
Map Nbr:		Point X:	-105.98292259
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
204	NW	0.97	5,119.91	6,761.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	64975	Surv Map:	
POD Rec No:	58891	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411071.5
Pcw Rcv Da:		Northing:	3947626.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/16/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579600.0
Static Lev:	0	Y:	1698650.0
Tract Nbr:		Point Y:	35.66850786
Map Nbr:		Point X:	-105.98258402
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
205	WNW	0.97	5,133.74	6,742.42	WATER WELLS

License Nb:	0	District Office S:	
POD No:	09462	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	42505	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	33
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410844.0
Pcw Rcv Da:		Northing:	3947215.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/17/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6647749
Map Nbr:		Point X:	-105.98505176
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
205	WNW	0.97	5,133.74	6,742.42	WATER WELLS

License Nb:	228	District Office S:	

Wells and Additional Sources Detail Report

POD No:	01428	Surv Map:	
POD Rec No:	60986	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/14/1957, 12:00 AM	Restrict :	0.0
Finish Date:	12/18/1957, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	02/07/1958, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	233	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	410844.0
Pcw Rcv Da:		Northing:	3947215.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/16/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6647749
Map Nbr:		Point X:	-105.98505176
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
206	WNW	0.97	5,133.23	6,755.44	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	622	District Office S:	
POD No:	79402	Surv Map:	
POD Rec No:	186588	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/02/2003, 12:00 AM	Restrict :	0.0
Finish Date:	09/02/2003, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	09/10/2003, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PD
Depth of Well:	240	UTM Zone:	13
Depth of Water:	92	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410993.9
Pcw Rcv Da:		Northing:	3947521.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/11/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579350.0
Static Lev:	0	Y:	1698300.0
Tract Nbr:		Point Y:	35.66754796
Map Nbr:		Point X:	-105.98342963
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
207	W	0.98	5,179.63	6,747.17	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	57862	Surv Map:	
POD Rec No:	51486	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	33
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410739.0
Pcw Rcv Da:		Northing:	3946712.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/01/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6602308
Map Nbr:		Point X:	-105.98615594
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
208	WSW	0.99	5,204.52	6,726.57	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	253	District Office S:	
POD No:	00592	Surv Map:	
POD Rec No:	26402	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	REPAIR 2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/30/1965, 12:00 AM	Restrict :	0.0
Finish Date:	09/07/1965, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	06/01/1966, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	252	UTM Zone:	13
Depth of Water:	212	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410833.0
Pcw Rcv Da:		Northing:	3946117.0
Sched Date:		Latitude Degree:	0
Use of Wel:	COM	Latitude Minute:	0
Sys Date:	01/15/1992, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65487531
Map Nbr:		Point X:	-105.98505169
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

208	WSW	0.99	5,204.52	6,726.57	WATER WELLS

License Nb:	49	District Office S:	
POD No:	00592	Surv Map:	
POD Rec No:	20514	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	S	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/25/1997, 12:00 AM	Restrict :	8.3
Finish Date:	07/27/1997, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	08/15/1997, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	500	UTM Zone:	13
Depth of Water:	200	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	7.88	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410833.0
Pcw Rcv Da:		Northing:	3946117.0
Sched Date:		Latitude Degree:	0
Use of Wel:	COMMERCIAL	Latitude Minute:	0
Sys Date:	10/21/1997, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65487531
Map Nbr:		Point X:	-105.98505169
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

208	WSW	0.99	5,204.52	6,726.57	WATER WELLS

License Nb:	253	District Office S:	
POD No:	00592	Surv Map:	
POD Rec No:	63762	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	REPAIR 1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/24/1964, 12:00 AM	Restrict :	0.0
Finish Date:	04/25/1964, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	12/09/1964, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	235	UTM Zone:	13
Depth of Water:	218	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410833.0
Pcw Rcv Da:		Northing:	3946117.0
Sched Date:		Latitude Degree:	0
Use of Wel:	COM	Latitude Minute:	0
Sys Date:	01/15/1992, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65487531
Map Nbr:		Point X:	-105.98505169
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
209	SSW	0.98	5,163.24	6,748.46	WATER WELLS

License Nb:	606	District Office S:	
POD No:	26805	Surv Map:	
POD Rec No:	14615	Other Loc:	2205 Rancho Siringo Road, Sf
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/01/1976, 12:00 AM	Restrict :	0.0
Finish Date:	04/01/1976, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	04/27/1976, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	100	UTM Zone:	13
Depth of Water:	50	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411461.1
Pcw Rcv Da:		Northing:	3945324.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/21/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411461.1
Static Lev:	0	Y:	3945324.4
Tract Nbr:		Point Y:	35.64778645
Map Nbr:		Point X:	-105.9780267
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Parcel Number 1052096137316000000		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
210	SSW	0.98	5,157.62	6,754.74	WATER WELLS

License Nb:	606	District Office S:	
POD No:	30797	Surv Map:	
POD Rec No:	54089	Other Loc:	2211 Paseo De Los Chamisos
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	6 SF
Start Date:	07/01/1978, 12:00 AM	Restrict :	0.0
Finish Date:	07/01/1978, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	08/09/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	288	UTM Zone:	13
Depth of Water:	240	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411743.0
Pcw Rcv Da:		Northing:	3945178.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/01/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Los Chamisos	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1722149.0
Static Lev:	0	Y:	1690705.0
Tract Nbr:		Point Y:	35.64649187
Map Nbr:		Point X:	-105.97489712
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
211	W	0.99	5,206.03	6,747.27	WATER WELLS

License Nb:	0	District Office S:	
POD No:	30838	Surv Map:	
POD Rec No:	51242	Other Loc:	2707 Cerrillos Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TD SF
Start Date:		Restrict :	0.0
Finish Date:	01/01/1938, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	190	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:	SUBMER	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410731.0
Pcw Rcv Da:		Northing:	3946650.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/30/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1718767.0
Static Lev:	0	Y:	1695495.0
Tract Nbr:		Point Y:	35.65967745
Map Nbr:		Point X:	-105.98623752
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant :

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SW	0.98	5,186.70	6,745.42	WATER WELLS

License Nb:	253	District Office S:	
POD No:	38301	Surv Map:	
POD Rec No:	61976	Other Loc:	2582 Camino Chueco, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	19 4 SF
Start Date:	07/26/1982, 12:00 AM	Restrict :	0.0
Finish Date:	07/27/1982, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	08/03/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	96	UTM Zone:	13
Depth of Water:	47	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411377.5
Pcw Rcv Da:		Northing:	3945375.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/18/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Los Cedros	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411377.5
Static Lev:	0	Y:	3945375.7
Tract Nbr:		Point Y:	35.64824142
Map Nbr:		Point X:	-105.97895569
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant :
Legal: Parcel Number 1052096108339000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
213	SW	0.99	5,214.80	6,722.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	38408	Surv Map:	
POD Rec No:	16176	Other Loc:	2706 Alamosa Dr
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 14 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	03
Plug Date:		Township:	16N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411140.8
Pcw Rcv Da:		Northing:	3945582.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/31/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Carlos Rey	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720156.0
Static Lev:	0	Y:	1692008.0
Tract Nbr:		Point Y:	35.65008718
Map Nbr:		Point X:	-105.98159286
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
214	E	0.99	5,227.66	6,963.17	WATER WELLS

License Nb:	0	District Office S:	
POD No:	21152	Surv Map:	
POD Rec No:	62730	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413920.0
Pcw Rcv Da:		Northing:	3946356.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/09/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	589000.0
Static Lev:	0	Y:	1694600.0
Tract Nbr:		Point Y:	35.65730674
Map Nbr:		Point X:	-105.95097863

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
215	W	0.99	5,230.69	6,737.37	WATER WELLS

License Nb:	253	District Office S:	
POD No:	08562	Surv Map:	
POD Rec No:	70300	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/07/1963, 12:00 AM	Restrict :	3.0
Finish Date:	03/08/1963, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	03/27/1963, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	239	UTM Zone:	13
Depth of Water:	206	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410739.0
Pcw Rcv Da:		Northing:	3946912.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	09/27/2005, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66203383

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.98617812
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
215	W	0.99	5,230.69	6,737.37	WATER WELLS

License Nb:	0	District Office S:	
POD No:	01237	Surv Map:	
POD Rec No:	46452	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/01/1947, 12:00 AM	Restrict :	0.0
Finish Date:	12/31/1947, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	08/16/1957, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	216	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410739.0
Pcw Rcv Da:		Northing:	3946912.0
Sched Date:		Latitude Degree:	0
Use of Wel:	COM/DOM	Latitude Minute:	0
Sys Date:	05/09/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.66203383
Map Nbr:		Point X:	-105.98617812
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Corner Of Maes And Rosina Street.		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
215	W	0.99	5,230.69	6,737.37	WATER WELLS

License Nb:	1173	District Office S:	
POD No:	01237	Surv Map:	
POD Rec No:	47640	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	REPAR	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/17/1957, 12:00 AM	Restrict :	0.0
Finish Date:	08/20/1957, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	09/25/1957, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	239	UTM Zone:	13
Depth of Water:	197	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.62	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410739.0
Pcw Rcv Da:		Northing:	3946912.0
Sched Date:		Latitude Degree:	0
Use of Wel:	COMM	Latitude Minute:	0
Sys Date:	05/09/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0

Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66203383
Map Nbr:		Point X:	-105.98617812
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
216	WNW	0.99	5,211.27	6,753.10	WATER WELLS

License Nb:	0	District Office S:	
POD No:	66947	Surv Map:	
POD Rec No:	54204	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410947.8
Pcw Rcv Da:		Northing:	3947491.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/09/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:		X:	579200.0
Static Lev:	0	Y:	1698200.0
Tract Nbr:		Point Y:	35.66727425
Map Nbr:		Point X:	-105.98393562
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
217	SW	0.99	5,223.02	6,743.97	WATER WELLS

License Nb:	227	District Office S:	
POD No:	31199	Surv Map:	
POD Rec No:	325631	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/30/1978, 12:00 AM	Restrict :	0.0
Finish Date:	12/14/1978, 12:00 AM	Section:	03
Plug Date:		Township:	16N
Log File D:	12/20/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	175	UTM Zone:	13
Depth of Water:	73	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411350.0
Pcw Rcv Da:		Northing:	3945382.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/17/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.64829575
Map Nbr:		Point X:	-105.97926012
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
218	NE	0.99	5,247.05	6,920.04	WATER WELLS

License Nb:	0	District Office S:	
POD No:	88182	Surv Map:	
POD Rec No:	223314	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	26
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413263.0
Pcw Rcv Da:		Northing:	3947996.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/11/2006, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67203141
Map Nbr:		Point X:	-105.95841267
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
218	NE	0.99	5,247.05	6,920.04	WATER WELLS

License Nb:	0	District Office S:	
POD No:	88182	Surv Map:	
POD Rec No:	223401	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	26
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413263.0
Pcw Rcv Da:		Northing:	3947996.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/11/2006, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67203141
Map Nbr:		Point X:	-105.95841267
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
219	NNW	0.99	5,243.55	6,810.41	WATER WELLS

License Nb:	0	District Office S:	
POD No:	46972	Surv Map:	
POD Rec No:	7550	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 15 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411853.0
Pcw Rcv Da:		Northing:	3948216.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	09/07/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Barro La Canada	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67388972
Map Nbr:		Point X:	-105.97401477
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
219	NNW	0.99	5,243.55	6,810.41	WATER WELLS

License Nb:	0	District Office S:	
POD No:	45085	Surv Map:	1941 TCRS #2
POD Rec No:	67083	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	TA	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Taos
Ref :		Easting:	411853.0
Pcw Rcv Da:		Northing:	3948216.0
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	09/22/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:	16	Point Y:	35.67388972
Map Nbr:	20	Point X:	-105.97401477
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	TAOS		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
219	NNW	0.99	5,243.55	6,810.41	WATER WELLS

License Nb:	253	District Office S:	
POD No:	03611	Surv Map:	
POD Rec No:	42626	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	B TB SF
Start Date:	07/31/1959, 12:00 AM	Restrict :	0.0
Finish Date:	08/04/1959, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	09/29/1959, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	94	UTM Zone:	13
Depth of Water:	13	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411853.0
Pcw Rcv Da:		Northing:	3948216.0

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/05/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Small Holding Claim 413	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67388972
Map Nbr:		Point X:	-105.97401477
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
220	ESE	1.00	5,266.77	6,972.11	WATER WELLS

License Nb:	0	District Office S:	
POD No:	98894	Surv Map:	
POD Rec No:	327476	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413894.9

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3946197.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/14/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1729167.5
Static Lev:	0	Y:	1694138.5
Tract Nbr:		Point Y:	35.65586843
Map Nbr:		Point X:	-105.95123886
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
221	WNW	1.00	5,255.98	6,753.17	WATER WELLS

License Nb:	225	District Office S:	
POD No:	11473	Surv Map:	
POD Rec No:	67733	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/05/1982, 12:00 AM	Restrict :	0.0
Finish Date:	07/05/1982, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	07/19/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	125	UTM Zone:	13
Depth of Water:	30	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	410947.0
Pcw Rcv Da:		Northing:	3947516.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	09/23/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66749775
Map Nbr:		Point X:	-105.9839472
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
221	WNW	1.00	5,255.98	6,753.17	WATER WELLS

License Nb:	0	District Office S:	
POD No:	27890	Surv Map:	
POD Rec No:	21794	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410947.0
Pcw Rcv Da:		Northing:	3947516.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/22/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66749775
Map Nbr:		Point X:	-105.9839472
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
221	WNW	1.00	5,255.98	6,753.17	WATER WELLS

License Nb:	228	District Office S:	
POD No:	14291	Surv Map:	
POD Rec No:	39933	Other Loc:	Nw 1/4
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/04/1966, 12:00 AM	Restrict :	0.0
Finish Date:	09/05/1966, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	06/12/1967, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	60	UTM Zone:	13
Depth of Water:	18	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	4.5	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	410947.0
Pcw Rcv Da:		Northing:	3947516.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/29/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66749775
Map Nbr:		Point X:	-105.9839472
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
221	WNW	1.00	5,255.98	6,753.17	WATER WELLS

License Nb:	225	District Office S:	
POD No:	11473	Surv Map:	
POD Rec No:	328592	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/05/1982, 12:00 AM	Restrict :	0.0
Finish Date:	07/05/1982, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	07/19/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	125	UTM Zone:	13
Depth of Water:	56	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	60	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410947.0
Pcw Rcv Da:		Northing:	3947516.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/23/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66749775
Map Nbr:		Point X:	-105.9839472
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
222	NNW	1.00	5,266.71	6,797.45	WATER WELLS

License Nb:	1004	District Office S:	
POD No:	55005	Surv Map:	
POD Rec No:	339490	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:	04/30/1993, 12:00 AM	Restrict :	0.0
Finish Date:	05/01/1993, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	05/03/1993, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	240	UTM Zone:	13
Depth of Water:	133	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411682.4
Pcw Rcv Da:		Northing:	3948160.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/09/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411682.4
Static Lev:	0	Y:	3948160.6
Tract Nbr:		Point Y:	35.67337502
Map Nbr:		Point X:	-105.97589355
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number: 1052098204266000000		

Public Water Supply Wells

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
3	ESE	0.15	817.90	6,869.97	PWSW

TINWSF Is No:	1948	City:	SANTA FE
No:	NM3505126	County:	SANTA FE
TINWSYS No:	380	Latitude:	35.659083
TINWSF No:	380	Longitude:	-105.965694
Alternate St No:		River Reach Ind Cd:	Yes
Stage2 CDS ID:	1880	Rvr Rch Miles Qty:	0
St Asgn Ident Cd:	05126012	Pump Type Code:	VT
Finds No:		Wtr Body Nm Txt:	
Owner Type Code:	L	External Sys No:	1948
Owner Type Desc:	Local Government	Treatment Stat Cd:	Treated
Oper Category Cd:	WS4	D Source Flag:	Yes
Operating Cat Cd:		Avg Pct Water Qty:	0
Fed Prim Src Cd:	SW	Physical Modif Dt:	
Fed Prim Src Desc:	Surface water	Water Type Code Dt:	11/26/2007
PWS Fed Type Cd:	C	Swap Report Status:	
PWS Fed Type Desc:	Community water system	Swap Rpt Status Dt:	
Type Code:	WL	Filtration Status:	
Population Count:	90810	Filtration Stat Dt:	
History Ind Cd:	C	Pump Description:	
History Ind Desc:	Current	Water Type Code:	GW

Wells and Additional Sources Detail Report

Ttl Stor Cap Msr:	36150000	Water Type Desc:	Ground water
PWS St Type Cd:	C	Horiz Ref Datum Cd:	003
Non Pipe Fac Tp Cd:		Data Collection Dt:	9/27/2010
Constructed Date:	1/1/1983	Depth of Well:	800
Surf Wtr Ratio:	20	Depth of Well UOM:	FT
Surf Wtr Pur Ratio:	40	Well Diameter:	16
Grnd Wtr Ratio:	40	Well Diameter UOM:	IN
Grnd Wtr Pur Ratio:	0	Static Water Level:	282
Grnd Wtr Udi Ratio:	0	Static Wtr Lvl UOM:	FT
Grnd Wtr Udi Purch:	0	Last Inv Updt Ts:	3/1/2024 1:46:30 PM
Availability Code:	P - Permanent Utilization	Last Snty Srv Dt:	
TINWSYS Name:	SANTA FE WATER SYSTEM (CITY OF)	Prt Gw Sr Ind Cd:	No
TINWSYS Local Nm:		Tcr Mcl Vio Dt:	
TINWSYS St Code:	NM	Inv Chg Ind Cd:	
TINWSF Name:	ST MICHAELS WELL	Dsnfct Gw Ind Cd:	
TINWSF Local Nm:		Swgudi Fl Ind Cd:	
TINWSF St Code:	NM	St Prim Src Cd:	SW
TINWSYS User ID Cd:	VGURULE	Sell Treat Ind Cd:	
TINWSYS Initial Ts:	1/7/2003 11:13:09 AM	Usgs Hydro Unit Cd:	
TINWSYS Init User:	SSWR1	Storet Ext Hydro U:	
TINWSF User ID Cd:	DRAMIREZ	Days Serving Count:	
TINWSF Initial Ts:	1/1/2005		
TINWSF Act Rsn Txt:	Well is out of service from 4-26-17 through 6-30-17 as per Wayne Jeffs.		
TINWSYS Act Rsn Txt:	Santa fe water quality division attached to city of santa fe...added 65 population and an extra 9 connections to city.		
TINWSYS Cds Trigger Ts:	2/15/2022 8:57:51 AM		
TINWSYS Cds Trigger User:	VGURULE		
TINWSF Last Updt Ts:	4/26/2017 2:54:56 PM		
TINWSF Init User ID:	SSWR1		
TINWSF Cds Trig Ts:	4/26/2017 2:54:57 PM		
TINWSF Cds Trigger User:	DRAMIREZ		
TINWSF TINWSYS St Code:	NM		
TINWSF Act Status Cd:	A		
TINWSF Act Status Desc:	Active		
TINWSF Act Date:	4/26/2017		
TINWSYS Act Status Cd:	A		
TINWSYS Act Status Desc:	Active		
TINWSYS Act Date:	6/1/1977		
TINWSF Act Reason Cd:			
TINWSYS Act Reason Cd:			
TINWSYS D Last Updt Ts:	2/15/2022 8:57:50 AM		
On River Reach Ind Desc:			
New Ws Flag:	N - No, indicating the Water System has more than the minimum data valued in TINWSYS.		
Directions Text:			
Memo Text:	Permitted water rights: 19,905 acre-ft/year		

Radon Information

This section lists any relevant radon information found for the target property.

Federal EPA Radon Zone for *SANTA FE* County: **1**

Zone 1: Counties with predicted average indoor radon screening levels greater than 4 pCi/L
Zone 2: Counties with predicted average indoor radon screening levels from 2 to 4 pCi/L
Zone 3: Counties with predicted average indoor radon screening levels less than 2 pCi/L

Federal Area Radon Information for *SANTA FE* County

No Measures/Homes:	73
Geometric Mean:	3.2
Arithmetic Mean:	4.6
Median:	3.5
Standard Deviation:	3.8
Maximum:	21.6
% >4 pCi/L:	41
% >20 pCi/L:	1
Notes on Data Table:	TABLE 1. Screening indoor radon data from the EPA/State Residential Radon Survey of New Mexico conducted during 1988-89. Data represent 2-7 day charcoal canister measurements from the lowest level of each home tested.

Appendix

Federal Sources

FEMA National Flood Hazard Layer — **FEMA FLOOD**

The National Flood Hazard Layer (NFHL) data incorporates Flood Insurance Rate Map (FIRM) databases published by the Federal Emergency Management Agency (FEMA), and any Letters Of Map Revision (LOMRs) that have been issued against those databases since their publication date. The FIRM Database is the digital, geospatial version of the flood hazard information shown on the published paper FIRMs. The FIRM Database depicts flood risk information and supporting data used to develop the risk data. The FIRM Database is derived from Flood Insurance Studies (FISs), previously published FIRMs, flood hazard analyses performed in support of the FISs and FIRMs, and new mapping data, where available.

Indoor Radon Data — **INDOOR RADON**

Indoor radon measurements tracked by the Environmental Protection Agency(EPA) and the State Residential Radon Survey.

Public Water Systems Violations and Enforcement Data — **PWSV**

This list of drinking water violations and enforcement actions is sourced from the U.S Environmental Protection Agency's (EPA) Enforcement and Compliance History Online (ECHO) system that incorporates Public Water Systems data from EPA's Safe Drinking Water Information System (SDWIS) database, as part of the national download of Safe Drinking Water Act (SDWA) data. SDWIS contains information on public water systems from the Public Water System Supervision (PWSS) Program, including monitoring, enforcement, and violation data related to requirements established by the SWDA. Address information provided in SWDIS may correspond either with the physical location of the water system, or with a contact address.

Radon Zone Level — **RADON ZONE**

Areas showing the level of Radon Zones (level 1, 2 or 3) by county. This data is maintained by the Environmental Protection Agency (EPA).

Safe Drinking Water Information System (SDWIS) — **SDWIS**

This national download of Safe Drinking Water Act (SDWA) data is sourced from the U.S Environmental Protection Agency's (EPA) Enforcement and Compliance History Online (ECHO) system that incorporates Public Water Systems data from EPA's Safe Drinking Water Information System (SDWIS) database. SDWIS contains information on public water systems from the Public Water System Supervision (PWSS) Program related to requirements established by the Safe Drinking Water Act (SDWA). Address information provided in SWDIS may correspond either with the physical location of the water system, or with a contact address.

Soil Survey Geographic database — **SSURGO**

The Soil Survey Geographic database (SSURGO) contains information about soil as collected by the National Cooperative Soil Survey at the Natural Resources Conservation Service (NRCS). Soil maps outline areas called map units. The map units are linked to soil properties in a database. Each map unit may contain one to three major components and some minor components.

U.S. Fish & Wildlife Service Wetland Data — **US WETLAND**

The U.S. Fish & Wildlife Service Wetland layer represents the approximate location and type of wetlands and deepwater habitats in the United States.

USGS Current Topo — **US TOPO**

US Topo topographic maps are produced by the National Geospatial Program of the U.S. Geological Survey (USGS). The project was launched in late 2009, and the term "US Topo" refers specifically to quadrangle topographic maps published in 2009 and later.

USGS Geology — **US GEOLOGY**

Seamless maps depicting geological information provided by the United States Geological Survey (USGS).

USGS National Water Information System — **FED USGS**

The U.S. Geological Survey's (USGS) National Water Information System (NWIS) is the nation's principal repository of water resources data. The data includes comprehensive information of well-construction details, time-series data for gage height, streamflow, groundwater level, and precipitation and water use data. This NWIS database information is obtained through the Water Quality Data Portal (WQP). The WQP

is a cooperative service sponsored by the USGS, the Environmental Protection Agency (EPA), and the National Water Quality Monitoring Council (NWQMC).

State Sources

Oil and Gas Wells **OGW**

Oil and Gas Well Data collected by New Mexico Oil Conservation Division.

Point of Diversion Report **WATER WELLS**

Point of Diversion report provided by the New Mexico Office of the State Engineer (OSE). This data comes from the NM Water Rights Reporting System (NMWRRS). The report returns a summary of water rights use, owner, wells, point of diversion and location and other information. This list includes declared, complete, in-progress, and plugged wells.

Public Water Supply Wells **PWSW**

A list of public water supply systems maintained by the New Mexico Environment Department (NMED), Drinking Water Bureau (DWB). This database includes active and inactive public water systems.

Liability Notice

Reliance on information in Report: The Physical Setting Report (PSR) DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a review of environmental databases and physical characteristics for the site or adjacent properties.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS Information Inc. disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report(s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

APPENDIX E

User Provided Information

[RESERVED]

APPENDIX F

Historical Fire Insurance Maps

FIRE INSURANCE MAPS

Project Property: New Method Cleaners
1911 St Michaels Dr Santa Fe NM 87505
Project No: NMENV.M007.SF-WALDO
Requested By: INTERA Incorporated
Order No: 25121700734
Date Completed: December 17, 2025

Please note that no information was found for your site or adjacent properties.

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

APPENDIX G

Historical City Directories

CITY DIRECTORY

Project Property:	*New Method Cleaners* *1911 St Michaels Dr* *Santa Fe,NM 87505*
Project No:	*NMENV.M007.SF-WALDO*
Requested By:	*INTERA Incorporated*
Order No:	*25121700734*
Date Completed:	*December 22, 2025*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

December 22, 2025
RE: CITY DIRECTORY RESEARCH
1911 St Michaels Dr
Santa Fe,NM 87505

Thank you for contacting ERIS for an City Directory Search for the site described above. Our staff has conducted a reverse listing City Directory search to determine prior occupants of the subject site and adjacent properties. We have provided the nearest addresses(s) when adjacent addresses are not listed. If we have searched a range of addresses, all addresses in that range found in the Directory are included.

Note: Reverse Listing Directories generally are focused on more highly developed areas. Newly developed areas may be covered in the more recent years, but the older directories will tend to cover only the "central" parts of the city. To complete the search, we have either utilized the ACPL, Library of Congress, State Archives, and/or a regional library or history center as well as multiple digitized directories. These do not claim to be a complete collection of all reverse listing city directories produced.

ERIS has made every effort to provide accurate and complete information but shall not be held liable for missing, incomplete or inaccurate information. To complete this search we used the general range(s) below to search for relevant findings. If you believe there are additional addresses or streets that require searching please contact us at 866-517-5204.

Search Criteria:
1700 - 1925 of 5th St
1700 - END of St Michaels Dr
Search Notes:

Search Results Summary

Date	Source	Comment
2024	DIGITAL BUSINESS DIRECTORY	
2020	DIGITAL BUSINESS DIRECTORY	
2016	DIGITAL BUSINESS DIRECTORY	
2011	DIGITAL BUSINESS DIRECTORY	
2008	DIGITAL BUSINESS DIRECTORY	
2003	DIGITAL BUSINESS DIRECTORY	
2000	DIGITAL BUSINESS DIRECTORY	
1996	POLKS	
1993	POLKS	
1988	POLKS	
1983	POLKS	
1978	POLKS	
1973	POLKS	
1968	HUDSPETHS	
1964	HUDSPETHS	
1960	HUDSPETHS	
1955	HUDSPETHS	
1949	HUDSPETHS	
1944	HUDSPETHS	
1940	HUDSPETHS	
1936-37	HUDSPETHS	
1930-31	HUDSPETHS	
1928-29	HUDSPETHS	

2024 5TH ST

SOURCE: DIGITAL BUSINESS DIRECTORY

1828 **JAMES BARRETT**...*RESIDENTIAL*
1830 **CITY BAZZAR**...*SECOND HAND STORES*
1911 **24 HOUR TRUCK TRAILER COML**...*TIRE-RETREADING & REPAIRING*
1911 **COUNSELING SERVICES**...*MARRIAGE & FAMILY COUNSELORS*
1911 **GENTIVA HOSPICE**...*HOSPICES*
1911 **JARAMILLO INSURANCE FNCL**...*INSURANCE*
1911 **MORRIS, ELIZABETH**...*SOCIAL WORKERS*
1911 **MOSS, NATALIA C PHD**...*PSYCHOLOGISTS*
1911 **NATURAL RESOURCES CONSERVATION**...*FEDERAL GOVERNMENT-CONSERVATION DEPTS*
1911 **NORTHERN NM HEARING-BALANCE**...*HEARING IMPAIRED EQUIPMENT & SUPPLIES*
1911 **NYDES PROPERTIES**...*REAL ESTATE*
1911 **PEPIN, EMILY**...*SOCIAL WORKERS*
1911 **SANTA FE COMMUNITY INFANT PROGRAM**...*EQUIPMENT RENTAL AND LEASING, NEC*
1911 **SOCIAL SECURITY ADMINISTRATION**...*FEDERAL GOVERNMENT-SOCIAL & HUMAN RSRCS*
1911 **SONG, MELINDA E NP**...*NURSES-PRACTITIONERS*
1911 **WATSON ASSOCIATES LLC**...*FINANCIAL ADVISORY SERVICES*
1919 **AT FACE VALUE**...*WEIGHT CONTROL SERVICES*
1919 **DIAMOND CUSTOM HOMES**...*HOME BUILDERS*
1919 **FAMILY TREE MIDWIFERY**...*MIDWIVES*
1919 **FAMILY TREE MIDWIFERY LC**...*MIDWIVES*
1919 **FARMERS INSURANCE**...*INSURANCE*
1919 **FULREADER, CYNTHIA**...*PSYCHOTHERAPISTS*
1919 **M A LOPEZ ROOFING**...*ROOFING CONTRACTORS*
1919 **MC Z INC**...*NONCLASSIFIED ESTABLISHMENTS*
1919 **ORTIZ, XAVIER C**...*SPEECH PATHOLOGISTS*
1919 **PASSPORT HEALTH INC**...*HEALTH SERVICES*
1919 **PAT LOPEZ ROOFING**...*ROOFING CONTRACTORS*
1919 **PONCIROLI, ARLA**...*MARRIAGE & FAMILY COUNSELORS*
1919 **REESE, ELLEN T**...*MARRIAGE & FAMILY COUNSELORS*
1919 **ROOF DOCTOR LLC**...*ROOFING CONTRACTORS*
1919 **STEVE MARTINEZ ALLSTATE AGENT**...*INSURANCE AGENTS, BROKERS, AND SERVICE, NEC*
1919 **TANABESYSTEMS.COM**...*ADVERTISING-COMPUTER*
1919 **TARGET SAFE SECURITY SYSTEMS**...*BURGLAR ALARM SYSTEMS-MONITORING*
1920 **CHILDREN YOUTH FAMILIES DEPT**...*GOVERNMENT OFFICES-STATE*
1920 **NATIONAL ASSOCIATION-CACFP PRO**...*STAIR TREADS*
1922 **SOCIAL SECURITY ADMINISTRATION**...*GOVERNMENT OFFICES-STATE*
1922 **SOCIAL SECURITY ADMINISTRATION**...*MISCELLANEOUS RETAIL STORES NEC*
1922 **SOCIAL SECURITY ADMINISTRATION**...*FEDERAL GOVERNMENT-SOCIAL & HUMAN RSRCS*

2024 ST MICHAELS DR

SOURCE: DIGITAL BUSINESS DIRECTORY

1700 **ARIANA'S BEAUTY SALON**...*BEAUTY SALONS*
1700 **CINDY BARRERAS**...*RESIDENTIAL*
1700 **COINSTAR**...*SIGN PAINTERS*
1700 **CORNERSTONE BOOKS GIFTS**...*CHURCH SUPPLIES*
1700 **CORNERSTONE CHRISTIAN BOOKS**...*CHRISTIAN BOOKS & SUPPLIES-RETAIL*
1700 **EXPOUND BIBLE CHURCH**...*REAL ESTATE AGENTS AND MANAGERS*
1700 **FABY FASHION**...*FASHION DESIGNERS*
1700 **LLANO CHEVRON**...*SERVICE STATIONS-GASOLINE & OIL*
1700 **LOWE'S**...*GROCERIES*
1700 **NEW MEXICO GAS CO**...*SNACKS*
1700 **REALM OF POSSIBILITIES**...*GAMES & GAME SUPPLIES*
1700 **ST MICHAELS CHEVRON**...*SERVICE STATIONS-GASOLINE & OIL*
1700 **TRI CORE REFERENCE LABS**...*LABORATORIES-MEDICAL*
1700 **TRICORE REFERENCE LABORATORIES**...*LABORATORIES-MEDICAL*
1700 **WATER BOYZ**...*BOTTLED WATER*
1701 **JMB ENTERPRISES LLC**...*NONCLASSIFIED ESTABLISHMENTS*
1701 **ZIA KIA**...*NEW CAR DEALERS*
1710 **NUSENDA CREDIT UNION**...*CREDIT UNIONS*
1721 **SONIC DRIVE-IN**...*RESTAURANTS*
1722 **ABC DRIVERS EDUCATION & DEFENSIVE**...*FAMILY CLOTHING STORES*
1722 **ASIAN SPA**...*SPAS - HEALTH*
1722 **DRESS CODE**...*WOMEN'S APPAREL-RETAIL*
1722 **PIZZERIA ESPIRITU**...*PIZZA*
1722 **STRATEGIES IN DESIGN**...*DESIGNERS*
1722 **TLC DRIVING SCHOOLS**...*DRIVING INSTRUCTION*
1722 **TORTILLERIA CHABELITA**...*FOOD PRODUCTS MANUFACTURERS*
1722 **VILLAGE HAIR DESIGN**...*BARBERS*
1851 **RAFAEL ALDNA & ASSOC**...*RESTAURANTS*
1881 **LOANMAX**...*LOANS*
1899 **ALLSUP'S CONVENIENCE STORE**...*CONVENIENCE STORES*
1899 **ATM**...*AUTOMATED TELLER MACHINES*
1899 **PHILLIPS 66**...*SERVICE STATIONS-GASOLINE & OIL*
1901 **LIQUID CO PACKAGE LIQUOR STORE**...*LIQUORS-RETAIL*
1905 **SHERWIN-WILLIAMS**...*PAINT*
1907 **ALLEGRA MARKETING PRINT MAIL**...*PRINTERS*
1907 **ALLEGRA PRINT & IMAGING**...*PRINTERS*
1907 **FARMERS INSURANCE**...*INSURANCE*
1907 **NEW MEXICO TOP ORGANICS-ULTRA**...*CROP FARMS*
1907 **NM TOP ORGANICS LLC**...*HEALTH & FITNESS PROGRAM CONSULTANTS*
1909 **MIRAGE SPAS**...*HOT TUBS & SPAS*
1909 **TURTLE WORLD ART STUDIO**...*POTTERY*
1911 **NEW METHOD CLEANERS**...*CLEANERS*
1911 **NEW METHOD DRY CLEANERS**...*CLEANERS*
1911 **SUBWAY**...*RESTAURANTS*
1955 **A1 SANTA FE SNOW REMOVAL**...*SWEEPERS-INDUSTRIAL*
1955 **JOSEPH LOPEZ**...*RESIDENTIAL*
1955 **PAUL THOMPSON ASSOC INC**...*TRANSPORTATION*
1955 **SANTA FE FILM SUPPORT**...*MOTION PICTURE PRODUCERS & STUDIOS*
1955 **SANTA FE VALET**...*LIMOUSINE SERVICES*
2000 **PARKHILL, BRIAN D**...*COUNSELORS*
2000 **PROBATION & PAROLE OFFICE**...*PROBATION SERVICES*
2001 **CEDARWOOD VETERINARY CLINIC**...*ANIMAL HOSPITALS*
2001 **LAUER**...*OFFICES AND CLINICS OF PODIATRISTS*
2001 **LAUER, JEAN DVM**...*VETERINARIANS*
2001 **SAGA, VIKKI DVM**...*VETERINARIANS*
2004 **BLAKE'S LOTABURGER**...*RESTAURANTS*
2005 **ELECTRIC CHARGING STATION**...*ELECTRIC CHARGING STATION*
2005 **GARCIA NISSAN**...*NEW CAR DEALERS*
2008 **AWS**...*DISABILITY SERVICES*
2008 **CARIDE DANCE STUDIO**...*DANCING INSTRUCTION*
2008 **FRONTIER FRAMES**...*WHOLESALE PICTURE FRAMES*
2008 **HIGH DESERT ARTS**...*PRINTMAKING WORKSHOPS*
2008 **HIGH DESERT ARTS**...*PHOTOGRAPHERS-DIGITAL IMAGING*
2008 **SANTA FE EYES**...*CONTACT LENS MANUFACTURERS*
2008 **SANTA FE EYES DR PHILIP TREU**...*OPTOMETRISTS OD*

2020 5TH ST

SOURCE: DIGITAL BUSINESS DIRECTORY

1715 **DARA MINKIN**...*RESIDENTIAL*
1828 **BOB HAOZOUS**...*RESIDENTIAL*
1828 **JAMES BARRETT**...*RESIDENTIAL*
1830 **CITY BAZZAR**...*SECOND HAND STORES*
1911 **COUNSELING SERVICES**...*MARRIAGE & FAMILY COUNSELORS*
1911 **EVERCARE FAMILY PRACTICE**...*PHYSICIANS & SURGEONS*
1911 **HIGH DESERT STRUCTURAL ENGRNG**...*ENGINEERS-STRUCTURAL*
1911 **HIGH DESERT STRUCTURAL ENGRNG**...*UNCLASSIFIED ESTABLISHMENTS*
1911 **HULETT, RUTH L MD**...*ACUPUNCTURE*
1911 **JARAMILLO INSURANCE FNCL**...*INSURANCE AGENCIES & BROKERAGES*
1911 **KAUFMAN, ROBERT**...*MARRIAGE & FAMILY COUNSELORS*
1911 **LAS CUMBRES COMMUNITY SVC**...*ASSOCIATIONS*
1911 **NATURAL RESOURCES CONSERVATION**...*FEDERAL GOVERNMENT-CONSERVATION DEPTS*
1911 **NATURAL RESOURCES CONSERVATION**...*FEDERAL GOVERNMENT CONTRACTORS*
1911 **NORTHERN NM HEARING BALANCE**...*HEARING AIDS*
1911 **NYDES PROPERTIES**...*REAL ESTATE*
1911 **O'DAY, KAREN C**...*NURSES-PRACTITIONERS*
1911 **SHELLS, CLAUDIA RN**...*ACUPUNCTURE*
1911 **US CONSOLIDATED FARM SVC AGCY**...*STATE GOVERNMENTCONSERVATION DEPTS*
1911 **US CONSOLIDATED FARM SVC AGCY**...*GOVERNMENT OFFICES-US*
1911 **WATSON ASSOCIATES LLC**...*FINANCIAL ADVISORY SERVICES*
1919 **AT FACE VALUE**...*WEIGHT CONTROL SERVICES*
1919 **BARBER, ANGELA**...*OFFICES-PHYSICAL, OCCPTNL/SPEECH THRPSTS/AUDLGSTS*
1919 **CHRIS R WALKER PC**...*BUILDING INSPECTION SERVICE*
1919 **CHRIS R WALKER PC**...*ENGINEERS-STRUCTURAL*
1919 **DIAMOND CUSTOM HOMES**...*HOME BUILDERS*
1919 **FAMILY TREE MIDWIFERY**...*MIDWIVES*
1919 **FARMERS INSURANCE**...*INSURANCE*
1919 **FULREADER, CYNTHIA**...*PSYCHOTHERAPISTS*
1919 **L M CONSULTANTS LLC**...*CONSULTANTS-BUSINESS NEC*
1919 **MC Z INC**...*NONCLASSIFIED ESTABLISHMENTS*
1919 **ORTIZ, XAVIER C**...*SPEECH PATHOLOGISTS*
1919 **PASSPORT HEALTH INC**...*HEALTH SERVICES*
1919 **PAT LOPEZ ROOFING**...*ROOFING CONTRACTORS*
1919 **PONCIROLI, ARLA**...*MARRIAGE & FAMILY COUNSELORS*
1919 **REESE, ELLEN T**...*MARRIAGE & FAMILY COUNSELORS*
1919 **SANTA CLARA CONSTRUCTION LLC**...*CONSTRUCTION COMPANIES*
1919 **SCHMIDT-NOWARA, WOLFGANG MD**...*PHYSICIANS & SURGEONS*
1919 **SCHMIDT-NOWARA, WOLFGANG MD**...*MEDICAL & SURGICAL SVC ORGANIZATIONS*
1919 **SCIACCA, CHERYL**...*COUNSELORS*
1919 **SOUTHWESTERN SLEEP CTR**...*PHYSICIANS & SURGEONS*
1919 **SOUTHWESTERN SLEEP CTR**...*DENTISTS*
1919 **SOUTHWESTERN SLEEP CTR**...*CLINICS*
1919 **SOUTHWESTERN SLEEP CTR**...*SLEEP DISORDERS-DIAGNOSTIC/TREATMENT*
1919 **SW FAMILY GUIDANCE CTR**...*MARRIAGE & FAMILY COUNSELORS*
1919 **TANABESYSTEMS.COM**...*ADVERTISING-COMPUTER*
1919 **TARGET SAFE SECURITY SYSTEMS**...*BURGLAR ALARM SYSTEMS-MONITORING*
1920 **CHILDREN YOUTH FAMILIES DEPT**...*GOVERNMENT OFFICES-STATE*
1920 **CHILDREN YOUTH FAMILIES DEPT**...*ENGINEERSAERONAUTICAL*
1920 **NATIONAL ASSOCIATION-CACFP PRO**...*FEDERAL GOVERNMENT CONTRACTORS*
1922 **SOCIAL SECURITY ADMINISTRATION**...*GOVERNMENT OFFICES-STATE*
1922 **SOCIAL SECURITY ADMINISTRATION**...*FEDERAL GOVERNMENT-SOCIAL & HUMAN RSRCS*
1922 **SOCIAL SECURITY ADMINISTRATION**...*MISCELLANEOUS RETAIL STORES NEC*

2020 ST MICHAELS DR

SOURCE: DIGITAL BUSINESS DIRECTORY

117 total records. Part 1 of 2

1700 **ARIANA'S BEAUTY SALON**...*BEAUTY SALONS*
1700 **LLANO CHEVRON**...*ALTERNATIVE FUELS*
1700 **LLANO CHEVRON**...*CONVENIENCE STORES*
1700 **LLANO CHEVRON**...*SERVICE STATIONS-GASOLINE & OIL*
1700 **LOWE'S**...*GROCERS-RETAIL*
1700 **LOWE'S**...*CONVENIENCE STORES*
1700 **ST MICHAELS CHEVRON**...*SERVICE STATIONS-GASOLINE & OIL*
1700 **TRI CORE REFERENCE LABS**...*HOSPITALS*
1700 **TRI CORE REFERENCE LABS**...*LABORATORIES-MEDICAL*
1700 **TRICORE REFERENCE LABORATORIES**...*HOSPITALS*
1700 **TRICORE REFERENCE LABORATORIES**...*MEDICAL LABORATORIES*
1700 **TWICE AS NICE**...*CONSIGNMENT SHOPS*
1700 **WATER BOYZ**...*FEDERAL GOVERNMENT CONTRACTORS*
1700 **WATER BOYZ**...*WATER COMPANIES-BOTTLED, BULK, ETC*
1701 **ZIA KIA**...*AUTOMOBILE DEALERS-USED CARS*
1701 **ZIA KIA**...*TRUCKDEALERSUSED*
1701 **ZIA KIA**...*AUTOMOBILE DEALERS-NEW CARS*
1710 **NUSENDA CREDIT UNION**...*CREDIT UNIONS*
1712 **KMART**...*DEPARTMENT STORES*
1712 **KMART**...*ECOMMERCE*
1712 **KMART**...*PHARMACIES*
1712 **KMART**...*GROCERSWHOLESALE*
1712 **KMART PHARMACY**...*PHARMACIES & DRUG STORES*
1712 **KMART PHARMACY**...*GROCERSWHOLESALE*
1716 **CORNERSTONE CHRISTIAN BOOKS**...*VIDEO TAPES & DISCSRENTING & LEASING*
1716 **CORNERSTONE CHRISTIAN BOOKS**...*CHRISTIAN BOOKS & SUPPLIES-RETAIL*
1716 **CORNERSTONE CHRISTIAN BOOKS**...*COUNSELINGTRANSFORMATION SERVICES*
1716 **CORNERSTONE CHRISTIAN BOOKS**...*BOOK DEALERS-RETAIL*
1721 **SONIC DRIVE-IN**...*RESTAURANTS*
1721 **SONIC DRIVE-IN**...*FOODS-CARRY OUT*
1721 **SONIC DRIVE-IN**...*CAFES*
1722 **ASIAN SPA**...*HEALTH SPAS*
1722 **BARTON'S FLOWERS**...*TUXEDOS*
1722 **BARTON'S FLOWERS**...*FLORISTS-RETAIL*
1722 **BARTON'S FLOWERS**...*CANDY & CONFECTIONERYRETAIL*
1722 **BARTON'S FLOWERS**...*WEDDING SUPPLIES & SERVICES*
1722 **DRESS CODE**...*WOMEN'S APPAREL-RETAIL*
1722 **NATIONAL GUARD RECRUITING**...*GOVERNMENT OFFICES-STATE*
1722 **NATIONAL GUARD RECRUITING**...*RECRUITING-US ARMED FORCES*
1722 **PIZZERIA ESPIRITU**...*PIZZA*
1722 **PIZZERIA ESPIRITU**...*HOTELS & MOTELS*
1722 **PIZZERIA ESPIRITU**...*FOODSCARRY OUT*
1722 **PIZZERIA ESPIRITU**...*RESTAURANTS*
1722 **TLC DRIVING SCHOOLS**...*DRIVING INSTRUCTION*
1722 **TORTILLERIA CHABELITA**...*FOOD PRODUCTS & MANUFACTURERS*
1722 **US ARMY NATIONAL GUARD RECRUIT**...*FEDERAL GOVERNMENT-NATIONAL SECURITY*
1722 **US ARMY NATIONAL GUARD RECRUIT**...*SCHOOLS-BUSINESS & VOCATIONAL*
1722 **VILLAGE HAIR DESIGN**...*BARBERS*
1851 **RAFAEL ALDNA & ASSOC**...*FOODSCARRY OUT*
1851 **RAFAEL ALDNA & ASSOC**...*RESTAURANTS*
1881 **LOANMAX**...*TITLE LOANS*
1881 **LOANMAX**...*LOANS*
1899 **ALLSUP'S CONVENIENCE STORE**...*CONVENIENCE STORES*
1899 **ALLSUP'S CONVENIENCE STORE**...*GROCERS-RETAIL*
1899 **PHILLIPS 66**...*SERVICE STATIONS-GASOLINE & OIL*
1901 **LIQUID CO PACKAGE LIQUOR STORE**...*LIQUORS-RETAIL*
1905 **SHERWIN-WILLIAMS**...*HARDWARERETAIL*
1905 **SHERWIN-WILLIAMS**...*PAINT-RETAIL*
1905 **SHERWIN-WILLIAMS**...*SPRAYING EQUIPMENT-MANUFACTURERS*
1907 **ALLEGRA MARKETING PRINT MAIL**...*PRINTERS (MFRS)*
1907 **ALLEGRA PRINT & IMAGING**...*PRINTERS (MFRS)*
1907 **ALLEGRA PRINT & IMAGING**...*OFFICE FURNITURE & EQUIPDEALERS (WHLS)*
1907 **ALLEGRA PRINT & IMAGING**...*COPYING & DUPLICATING SERVICE*
1907 **FARMERS INSURANCE**...*PHOTOGRAPHERS-PORTRAIT*
1907 **FARMERS INSURANCE**...*INSURANCE*
1907 **NEW MEXICO TOP ORGANICS-ULTRA**...*GENERAL CROP FARMS*

2020 ST MICHAELS DR

SOURCE: DIGITAL BUSINESS DIRECTORY

Part 2 of 2

1907 **NM TOP ORGANICS LLC**...*HEALTH & FITNESS PROGRAM CONSULTANTS*
1909 **MIRAGE SPAS**...*HOT TUBS & SPAS*
1909 **TURTLE WORLD ART STUDIO**...*POTTERY*
1911 **CHRISTIE'S HAIR BOUTIQUE**...*HEALTH SPAS*
1911 **CHRISTIE'S HAIR BOUTIQUE**...*MANICURING*
1911 **CHRISTIE'S HAIR BOUTIQUE**...*BEAUTY SALONS*
1911 **M & S SPAS**...*HOT TUBS & SPAS*
1911 **NEW METHOD CLEANERS**...*CLEANERS*
1911 **NEW METHOD CLEANERS**...*BRIDAL GOWN PRESERVATION SERVICE*
1911 **NEW METHOD CLEANERS**...*LAUNDRIES*
1911 **SUBWAY**...*RESTAURANTS*
1911 **SUBWAY**...*FOODSCARRY OUT*
1911 **SUBWAY**...*DELICATESSENS*
1911 **TURTLE WORLD**...*POTTERY*
1911 **TURTLE WORLD**...*NONCLASSIFIED ESTABLISHMENTS*
1911 **TURTLE WORLD**...*POTTERY INSTRUCTION*
1911 **WESTERN FINANCE SVC**...*LOANS*
1955 **PAUL THOMPSON ASSOC INC**...*TRANSPORTATION*
1955 **PAUL THOMPSON ASSOC INC**...*AIR CARGO SERVICE*
1955 **SANTA FE FILM SUPPORT**...*THEATRESMOVIE*
1955 **SANTA FE FILM SUPPORT**...*MOTION PICTURE PRODUCERS & STUDIOS*
1955 **SANTA FE VALET**...*LIMOUSINE SERVICE*
2000 **GONZALES, CARLOS**...*COUNSELORS*
2000 **MESA FINANCIAL**...*FINANCING*
2000 **PARKHILL, BRIAN D**...*COUNSELORS*
2000 **PROBATION PAROLE OFFICE**...*GOVERNMENT OFFICES-STATE*
2000 **PROBATION PAROLE OFFICE**...*ENGINEERSAERONAUTICAL*
2000 **PROBATION & PAROLE OFFICE**...*PROBATION SERVICES*
2000 **PROBATION & PAROLE OFFICE**...*SCHOOLS*
2001 **CEDARWOOD VETERINARY CLINIC**...*VETERINARIANS*
2001 **CEDARWOOD VETERINARY CLINIC**...*VETERINARY SERVICES*
2001 **LAUER, JEAN DVM**...*ANIMAL HOSPITALS*
2001 **LAUER, JEAN DVM**...*VETERINARIANS*
2004 **BLAKE'S LOTABURGER**...*FOODS-CARRY OUT*
2004 **BLAKE'S LOTABURGER**...*RESTAURANTS*
2004 **BLAKE'S LOTABURGER**...*CAFES*
2005 **GARCIA NISSAN**...*AUTOMOBILE DEALERS-NEW CARS*
2005 **GARCIA NISSAN**...*AUTOMOBILE DEALERSUSED CARS*
2008 **AWS**...*FEDERAL GOVERNMENT CONTRACTORS*
2008 **AWS**...*DISABILITY SERVICES*
2008 **CARIDE DANCE STUDIO**...*DANCING INSTRUCTION*
2008 **FRONTIER FRAMES**...*PICTURE FRAMESMANUFACTURERS*
2008 **FRONTIER FRAMES**...*PICTURE FRAMES-WHOLESALE*
2008 **FRONTIER FRAMES**...*WOOD CARVING*
2008 **FRONTIER FRAMES**...*PICTURE FRAMES-DEALERS*
2008 **FRONTIER FRAMES**...*WOOD PRODUCTS NEC (MFRS)*
2008 **SANTA FE CHILDREN'S DENTISTRY**...*OFFICES OF DENTISTS*
2008 **SANTA FE EYES**...*CLINICS*
2008 **SANTA FE EYES**...*CONTACT LENSES*
2008 **SANTA FE EYES DR PHILIP TREU**...*OPTOMETRISTS OD*
2008 **SANTA FE EYES DR PHILIP TREU**...*CONTACT LENSES*

2016 5TH ST

SOURCE: DIGITAL BUSINESS DIRECTORY

1828 **BOB HAOZOUS**...*RESIDENTIAL*
1828 **JAMES BARRETT**...*RESIDENTIAL*
1830 **CYBER MESA TELECOM**...*TELECOMMUNICATIONS SERVICES*
1911 **24 HOUR TRUCK TRAILER COML**...*TIRE-RETREADING & REPAIRING*
1911 **COUNSELING SERVICES**...*MARRIAGE & FAMILY COUNSELORS*
1911 **GENTIVA HOSPICE**...*HOSPICES*
1911 **HIGH DESERT STRUCTURAL ENGRNG**...*UNCLASSIFIED ESTABLISHMENTS*
1911 **HULETT, RUTH L MD**...*PHYSICIANS & SURGEONS*
1911 **JARAMILLO INSURANCE FNCL**...*INSURANCE AGENCIES & BROKERAGES*
1911 **NATURAL RESOURCES CONSERVATION**...*FEDERAL GOVERNMENT-CONSERVATION DEPTS*
1911 **NYDES PROPERTIES**...*REAL ESTATE*
1911 **SOCIAL SECURITY ADMINISTRATION**...*FEDERAL GOVERNMENT-SOCIAL & HUMAN RSRCS*
1919 **AT FACE VALUE**...*WEIGHT CONTROL SERVICES*
1919 **BARBER, ANGELA**...*OFFICES-PHYSICAL, OCCPTNL/SPEECH THRPSTS/AUDLGSTS*
1919 **CHRIS R WALKER PC**...*ENGINEERS-STRUCTURAL*
1919 **DIAMOND CUSTOM HOMES**...*HOME BUILDERS*
1919 **EL MIRADOR HOME CARE**...*HEALTH CARE FACILITIES*
1919 **FARMERS INSURANCE**...*INSURANCE*
1919 **FULREADER, CYNTHIA**...*PSYCHOTHERAPISTS*
1919 **MC Z INC**...*NONCLASSIFIED ESTABLISHMENTS*
1919 **PASSPORT HEALTH INC**...*HEALTH SERVICES*
1919 **PAT LOPEZ ROOFING**...*ROOFING CONTRACTORS*
1919 **PONCIROLI, ARLA**...*MARRIAGE & FAMILY COUNSELORS*
1919 **REESE, ELLEN T**...*MARRIAGE & FAMILY COUNSELORS*
1919 **ROOF DOCTOR LLC**...*ROOFING CONTRACTORS*
1919 **SANTOS, ALBERTO L MD**...*PHYSICIANS & SURGEONS*
1919 **SOUTHWESTERN SLEEP CTR**...*SLEEP DISORDERS-DIAGNOSTIC/TREATMENT*
1919 **SW FAMILY GUIDANCE CTR**...*MARRIAGE & FAMILY COUNSELORS*
1920 **CHILDREN YOUTH FAMILIES DEPT**...*GOVERNMENT OFFICES-STATE*
1920 **NATIONAL ASSOCIATION-CACFP PRO**...*UNCLASSIFIED ESTABLISHMENTS*
1922 **SOCIAL SECURITY ADMINISTRATION**...*MISCELLANEOUS RETAIL STORES NEC*

83 total records. Part 1 of 2

1700 **ARIANA'S BEAUTY SALON**...BEAUTY SALONS
1700 **COINSTAR**...COIN & BILL COUNTING/SORTING SVC KIOSKS
1700 **FABY FASHION**...FASHION DESIGNERS
1700 **LLANO CHEVRON**...SERVICE STATIONS-GASOLINE & OIL
1700 **LLANO CHEVRON**...CONVENIENCE STORES
1700 **LOWE'S**...GROCERS-RETAIL
1700 **NEW MEXICO GAS CO**...CONVENIENCE STORES
1700 **REALM OF POSSIBILITIES**...GAMES & GAME SUPPLIES
1700 **ST MICHAELS CHEVRON**...SERVICE STATIONS-GASOLINE & OIL
1700 **ST MICHAELS CHEVRON**...OTHER GASOLINE STATIONS
1700 **TRI CORE REFERENCE LABS**...LABORATORIES-MEDICAL
1700 **TRICORE REFERENCE LABORATORIES**...MEDICAL LABORATORIES
1700 **WATER BOYZ**...WATER COMPANIES-BOTTLED, BULK, ETC
1701 **ZIA KIA**...AUTOMOBILE DEALERS-NEW CARS
1701 **ZIA KIA**...AUTOMOBILE DEALERS-USED CARS
1710 **NUSENDA CREDIT UNION**...CREDIT UNIONS
1712 **ATM**...AUTOMATED TELLER MACHINES
1712 **COINSTAR**...COIN & BILL COUNTING/SORTING SVC KIOSKS
1712 **KMART**...DEPARTMENT STORES
1712 **KMART**...PHARMACIES
1712 **KMART PHARMACY**...PHARMACIES & DRUG STORES
1714 **HAMMING, ZWAANTJE H CNP**...NURSES-PRACTITIONERS
1716 **CORNERSTONE CHRISTIAN BOOKS**...BOOK DEALERS-RETAIL
1716 **CORNERSTONE CHRISTIAN BOOKS**...CHRISTIAN BOOKS & SUPPLIES-RETAIL
1721 **SONIC DRIVE-IN**...RESTAURANTS
1721 **SONIC DRIVE-IN**...FOODS-CARRY OUT
1722 **AMERICAN CLASSIFIEDS**...ADVERTISING-NEWSPAPER
1722 **BARTON'S FLOWERS**...FLORISTS-RETAIL
1722 **BARTON'S FLOWERS**...WEDDING SUPPLIES & SERVICES
1722 **NATIONAL GUARD RECRUITING**...RECRUITING-US ARMED FORCES
1722 **PIZZERIA ESPIRITU**...PIZZA
1722 **PIZZERIA ESPIRITU**...RESTAURANTS
1722 **TLC DRIVING SCHOOLS**...DRIVING INSTRUCTION
1722 **TORTILLERIA CHABELITA**...FOOD PRODUCTS & MANUFACTURERS
1722 **US ARMY NATIONAL GUARD RECRUIT**...FEDERAL GOVERNMENT-NATIONAL SECURITY
1722 **US ARMY NATIONAL GUARD RECRUIT**...SCHOOLS-BUSINESS & VOCATIONAL
1722 **VILLAGE HAIR DESIGN**...BARBERS
1722 **WESTERN FINANCE SVC**...LOANS
1790 **ATM**...AUTOMATED TELLER MACHINES
1790 **CENTURY BANK**...BANKS
1851 **RAFAEL ALDNA & ASSOC**...RESTAURANTS
1881 **LOANMAX**...TITLE LOANS
1881 **LOANMAX**...LOANS
1899 **ALLSUP'S CONVENIENCE STORE**...CONVENIENCE STORES
1899 **ALLSUP'S CONVENIENCE STORE**...GROCERS-RETAIL
1899 **ATM**...AUTOMATED TELLER MACHINES
1905 **SHERWIN-WILLIAMS**...PAINT-RETAIL
1905 **SHERWIN-WILLIAMS**...SPRAYING EQUIPMENT-MANUFACTURERS
1907 **ALLEGRA PRINT & IMAGING**...PRINTERS (MFRS)
1907 **ALLEGRA PRINT & IMAGING**...COPYING & DUPLICATING SERVICE
1907 **FARMERS INSURANCE**...INSURANCE
1907 **FARMERS INSURANCE**...PHOTOGRAPHERS-PORTRAIT
1907 **QUE BONITA**...COSMETICS & PERFUMES-RETAIL
1909 **MIRAGE SPAS**...HOT TUBS & SPAS
1909 **TURTLE WORLD ART STUDIO**...POTTERY
1911 **CHRISTIE'S HAIR BOUTIQUE**...BEAUTY SALONS
1911 **CHRISTIE'S HAIR BOUTIQUE**...MANICURING
1911 **M & S SPAS**...HOT TUBS & SPAS
1911 **NEW METHOD CLEANERS**...CLEANERS
1911 **NEW METHOD CLEANERS**...BRIDAL GOWN PRESERVATION SERVICE
1911 **SUBWAY**...DELICATESSENS
1911 **SUBWAY**...RESTAURANTS
1955 **SANTA FE FILM SUPPORT**...MOTION PICTURE PRODUCERS & STUDIOS
2000 **GREAT WESTERN INVESTORS**...REAL ESTATE DEVELOPERS
2000 **MESA FINANCIAL**...LOANS
2000 **MESA FINANCIAL**...FINANCING
2000 **PROBATION & PAROLE OFFICE**...PROBATION SERVICES

2016 ST MICHAELS DR
SOURCE: DIGITAL BUSINESS DIRECTORY

Part 2 of 2

2001 **CEDARWOOD VETERINARY CLINIC**...VETERINARIANS
2001 **CEDARWOOD VETERINARY CLINIC**...VETERINARY SERVICES
2001 **LAUER, JEAN DVM**...VETERINARIANS
2001 **SAGA, VIKKI DVM**...VETERINARIANS
2004 **BLAKE'S LOTABURGER**...RESTAURANTS
2004 **BLAKE'S LOTABURGER**...FOODS-CARRY OUT
2005 **ELECTRIC CHARGING STATION**...ELECTRIC CHARGING STATION
2005 **GARCIA NISSAN**...AUTOMOBILE DEALERS-NEW CARS
2006 **TREU, PHILIP**...OPTICAL GOODS-RETAIL
2008 **AWS**...DISABILITY SERVICES
2008 **FRONTIER FRAMES**...WOOD PRODUCTS NEC (MFRS)
2008 **FRONTIER FRAMES**...PICTURE FRAMES-WHOLESALE
2008 **SANTA FE CHILDREN'S DENTISTRY**...OFFICES OF DENTISTS
2008 **SANTA FE EYES**...CONTACT LENSES
2008 **SANTA FE EYES DR PHILIP TREU**...OPTOMETRISTS OD
2008 **TREU, PHILIP OD**...OPTOMETRISTS OD

2011 5TH ST

SOURCE: DIGITAL BUSINESS DIRECTORY

1713 **MONSERRAT GONZALEZ**...*RESIDENTIAL*
1713 **OCTAVIO CHAVEZ**...*RESIDENTIAL*
1713 **SANDRA ORTEGA**...*RESIDENTIAL*
1804 **JOSE LOPEZ**...*RESIDENTIAL*
1830 **KARI MC CULLOCH**...*RESIDENTIAL*
1911 **DESTINATION 505**...*TOUR OPERATORS*
1911 **EDNA SANCHEZ**...*RESIDENTIAL*
1911 **FELDMAN SYDELE**...*RESIDENTIAL*
1911 **FELDMAN, SYDELE DC**...*OFFICES OF CHIROPRACTORS*
1911 **KAUFMAN, ROBERT**...*OTHER INDIVIDUAL & FAMILY SVCS*
1911 **NATURAL RESOURCES CONSERVATION**...*ADMINISTRATION OF CONSERVATION PROGRAMS*
1911 **ODYSSEY HEALTH CARE**...*NURSING CARE FACILITIES*
1911 **US CONSOLIDATED FARM SVC AGCY**...*ADMINISTRATION OF CONSERVATION PROGRAMS*
1911 **US SOCIAL SECURITY ADMIN**...*OTHER HUMAN RESOURCE PROGRAMS ADMINISTRATION*
1919 **ALLSTATE INSURANCE**...*INVESTMENT ADVICE*
1919 **ALLSTATE INSURANCE CO**...*INSURANCE AGENCIES & BROKERAGES*
1919 **ALLSTATE INSURANCE CO**...*INVESTMENT ADVICE*
1919 **APPROVED HOME FINANCE**...*REAL ESTATE CREDIT*
1919 **AT FACE VALUE**...*DIET & WEIGHT REDUCING CENTERS*
1919 **BEA LOCKHART**...*RESIDENTIAL*
1919 **CHAMIZA FOUNDATION**...*OTHER SOCIAL ADVOCACY ORGANIZATIONS*
1919 **DIAMOND CUSTOM HOMES**...*NEW SINGLE-FAMILY GENERAL CONTRS*
1919 **DREW, TONI**...*OFFICES OF MENTAL HEALTH PRACTITIONERS*
1919 **EXPRESS MORTGAGE LTD CO**...*CONSUMER LENDING*
1919 **FULREADER, CYNTHIA**...*OFFICES OF MENTAL HEALTH PRACTITIONERS*
1919 **JEFF HOWLEY INSURANCE INC**...*INVESTMENT ADVICE*
1919 **JEFF HOWLEY LUTCF**...*INVESTMENT ADVICE*
1919 **MC Z INC**
1919 **PASSPORT HEALTH INC**...*MISC AMBULATORY HEALTH CARE SVCS*
1919 **PAT LOPEZ ROOFING**...*ROOFING CONTRS*
1919 **PONCIROLI, ARLA**...*OFFICES OF MENTAL HEALTH PRACTITIONERS*
1919 **REESE, ELLEN T**...*OTHER INDIVIDUAL & FAMILY SVCS*
1919 **ROOF DOCTOR**...*ROOFING CONTRS*
1919 **SOFT SHOES ARCHITECTS BUILDERS**...*ARCHITECTURAL SVCS*
1919 **SOUTHWESTERN SLEEP CTR**...*OFFICES OF PHYSICIANS, EXCEPT MENTAL HEALTH*
1919 **TARGET SAFE SECURITY SYSTEMS**...*SECURITY SYSTEMS SVCS, EXCEPT LOCKSMITHS*
1919 **THOMASON BROWN**...*RESIDENTIAL*
1919 **THOMASON BROWN & ASSOC**...*OFFICE ADMINISTRATIVE SVCS*
1922 **US SOCIAL SECURITY ADMIN**...*OTHER HUMAN RESOURCE PROGRAMS ADMINISTRATION*

2011 ST MICHAELS DR

SOURCE: DIGITAL BUSINESS DIRECTORY

1700 **BREWER CHEVRON**...*OTHER GASOLINE STATIONS*
1700 **LOWES FOODS**...*SUPERMARKETS & OTHER GROCERY STORES*
1700 **ST MICHAELS CHEVRON**...*OTHER GASOLINE STATIONS*
1701 **CAR WORLD**...*USED CAR DEALERS*
1701 **CAR WORLD KIA**...*NEW CAR DEALERS*
1712 **KMART**...*DEPARTMENT STORES, EXCEPT DISCOUNT*
1716 **CORNERSTONE BOOKS ETC**...*BOOK STORES*
1721 **SONIC DRIVE-IN**...*FULL-SERVICE RESTAURANTS*
1722 **ALGEGUNDA NICKEL**...*RESIDENTIAL*
1722 **AMERICAN CLASSIFIEDS**...*ADVERTISING AGENCIES*
1722 **BARTONS FLOWERS**...*FLORISTS*
1722 **NEW MEXICO ARMY NATIONAL GUARD**...*BUSINESS & SECRETARIAL SCHOOLS*
1722 **PIZZERIA ESPIRITU**...*FULL-SERVICE RESTAURANTS*
1722 **TORTILLERIA CHABELITA**...*ALL OTHER MISC FOOD MFG*
1722 **US ARMY NATIONAL GUARD RECRUIT**...*NATIONAL SECURITY*
1722 **VILLAGE HAIR DESIGN**...*BARBER SHOPS*
1722 **XANGO INDEPENDENT DISTR**...*FOOD, HEALTH, SUPPLEMENT STORES*
1851 **GREEN ONION SPORTS PUB**...*FULL-SERVICE RESTAURANTS*
1851 **O GREEN**...*RESIDENTIAL*
1881 **LOANMAX**...*CONSUMER LENDING*
1899 **ALLSUPS CONVENIENCE STORE**...*CONVENIENCE STORES*
1901 **LIQUID CO PACKAGE LIQUOR STORE**...*BEER, WINE, & LIQUOR STORES*
1905 **SHERWIN-WILLIAMS**...*PAINT & WALLPAPER STORES*
1907 **ALLEGRA PRINT & IMAGING**...*OTHER BUSINESS SVC CENTERS*
1907 **MARTIN VARELA**...*RESIDENTIAL*
1907 **MARTIN VARELA INSURANCE**...*INSURANCE AGENCIES & BROKERAGES*
1907 **MONEY NOW CHECK CASHING**...*CONSUMER LENDING*
1907 **TRUTH & HEART LANDSCAPING**...*LANDSCAPING SVCS*
1907 **VARELA INSURANCE**...*INVESTMENT ADVICE*
1907 **VARELA PHOTOGRAPHY**...*PHOTOGRAPHIC STUDIOS, PORTRAIT*
1909 **MIRAGE TANNING**...*STORE RETAILERS NOT SPECIFIED ELSEWHERE*
1911 **CHRISTIES HAIR BOUTIQUE**...*BEAUTY SALONS*
1911 **CUTTING EDGE CATALOG**...*FOOD, HEALTH, SUPPLEMENT STORES*
1911 **NEW METHOD CLEANERS**...*DRYCLEANING & LAUNDRY SVCS*
1911 **SUBWAY**...*FULL-SERVICE RESTAURANTS*
2000 **EMBROIDERY IMPRESSIONS**...*OTHER SPECIALIZED DESIGN SVCS*
2000 **MESA FINANCIAL**...*CONSUMER LENDING*
2000 **PROBATION & PAROLE OFFICE**...*PAROLE OFFICES & PROBATION OFFICES*
2001 **CEDARWOOD VETERINARY CLINIC**...*VETERINARY SVCS*
2001 **LAUER, JEAN DVM**...*VETERINARY SVCS*
2001 **SAGA, VIKKI DVM**...*VETERINARY SVCS*
2004 **BLAKES LOTABURGER**...*FULL-SERVICE RESTAURANTS*
2008 **FRONTIER FRAMES**...*STORE RETAILERS NOT SPECIFIED ELSEWHERE*
2008 **MOSAIC**...*OTHER SOCIAL ADVOCACY ORGANIZATIONS*
2008 **SANTA FE EYES**...*OFFICES OF OPTOMETRISTS*
2008 **SMALL SMILES DENTAL CLINIC**...*OFFICES OF DENTISTS*

1713 **CENOVIO R ROSAS**...*RESIDENTIAL*
1714 **I J ROMERO**...*RESIDENTIAL*
1715 **RAYMOND G MARTINEZ**...*RESIDENTIAL*
1804 **ISELE VELAZQUEZ**...*RESIDENTIAL*
1830 **INTERNET AT CYBER MESA**...*INTERNET SERVICE*
1911 **DENISE AUGHTMAN**...*ACUPUNCTURE*
1911 **DESTINATION 505**...*TOURS-OPERATORS & PROMOTERS*
1911 **K&D SELF STORAGE LLC**...*GENERAL WAREHOUSE/STORAGE*
1911 **NATURAL RESOURCES CONSERVATION**...*FEDERAL GOVERNMENT-CONSERVATION DEPTS*
1911 **NYDES PROPERTIES**...*REAL ESTATE*
1911 **SOCIAL SECURITY ADMINISTRATION**...*SOCIAL SECURITY ADMINISTRATION*
1911 **US SOCIAL SECURITY ADM**...*FEDERAL GOVERNMENT-SOCIAL & HUMAN RSRCS*
1919 **ALLSTATE INSURANCE**...*INSURANCE*
1919 **ALLSTATE INSURANCE CO**...*INSURANCE*
1919 **AT FACE VALUE**...*SKIN TREATMENTS*
1919 **BEA CASTELLANO LOCKHART**...*ATTORNEYS*
1919 **BODY MIND AWARENESS PC**...*MARRIAGE & FAMILY COUNSELORS*
1919 **CAPITAL CITY HOME LOANS & FIN**...*MORTGAGE BROKER*
1919 **CASTELLANO LOCKHART BEA**...*LEGAL SERVICES OFFICE*
1919 **CONTA-DORA BOOKKEEPING & TAX**...*ACCOUNTANTS*
1919 **DIAMOND CUSTOM HOMES**...*HOME BUILDERS*
1919 **EMBROIDERY IMPRESSIONS**...*EMBROIDERY*
1919 **EXPRESS MORTGAGE LTD CO**...*LOANS*
1919 **EXPRESS MORTGAGE LTD CO**...*MORTGAGE BROKERS*
1919 **HEART SPACE HEALING**...*MARRIAGE & FAMILY COUNSELORS*
1919 **HEARTSPACE HEALING**...*MISC PERSONAL SERVICES*
1919 **HOME INSTEAD SENIOR CARE 144**...*HOME CARE SERVICES*
1919 **JEFF HOWLEY INSURANCE INC**...*INSURANCE*
1919 **JEFF HOWLEY LUTCF**...*INSURANCE AGENT/BROKER*
1919 **MCDONALDS**...*EATING PLACE*
1919 **PASSPORT HEALTH OF NEW MEXICO**...*HEALTH SERVICES*
1919 **PAT LOPEZ ROOFING**...*ROOFING CONTRACTORS*
1919 **PRO-ACTIVE CHIROPRACTIC**...*CHIROPRACTORS DC*
1919 **SHARON FINN LPCC**...*NONCLASSIFIED ESTABLISHMENTS*
1919 **STEVE MARTINEZ**...*RESIDENTIAL*
1919 **SUNSET SLEEP CTR**...*PSYCHOLOGISTS*
1919 **TAMI SCHNEIDER**...*ATTORNEYS*
1919 **TARGET SAFE SECURITY SYSTEMS**...*BURGLAR ALARM SYSTEMS (WHOLESALE)*
1919 **THOMASON BROWN & ASSOC**...*MEDICAL BUSINESS ADMINISTRATION*
1919 **TONI DREW**...*MARRIAGE & FAMILY COUNSELORS*
1920 **CHILDREN YUTH FAMILIES NM DEPT**...*JUVENILE PROTECTIVE SERVICES*

69 total records. Part 1 of 2

1700 **BREWER CHEVRON**...*SERVICE STATIONS-GASOLINE & OIL*
1700 **LOWES SUPER SAVE**...*GROCERS-RETAIL*
1701 **CAR WORLD KIA**...*AUTOMOBILE DEALERS-NEW CARS*
1701 **HORACE KIA**...*AUTOMOBILE DEALERS-USED CARS*
1701 **JOE HRACE CHRYSLR-PLYMUTH-JEEP**...*RET NEW/USED AUTOMOBILES RET AUTO/HOME SUPPLIES RET USE*
1701 **SANTA FE CHRYSLER JEEP**...*AUTOMOBILE DEALERS-NEW CARS*
1712 **KMART**...*DEPARTMENT STORES*
1714 **GORDONS JEWELERS**...*JEWELERS-RETAIL*
1714 **GORDONS JEWELRY INC**...*RET JEWELRY*
1716 **CORNERSTONE BOOKS & GIFTS**...*BOOK DEALERS-RETAIL*
1716 **PLAY IT AGAIN SPORTS**...*SPORTING GOODS-RETAIL*
1718 **CARROWS**...*EATING PLACE*
1718 **CARROWS RESTAURANT**...*RESTAURANTS*
1718 **CARROWS RESTAURANTS**...*RESTAURANTS*
1721 **SONIC DRIVE-IN**...*EATING PLACE*
1722 **AMERICAN CLASSIFIEDS**...*ADVERTISING-NEWSPAPER*
1722 **BARTONS FLOWERS**...*FLORISTS-RETAIL*
1722 **NEW MEXICO ARMY NATIONAL GUARD**...*SCHOOLS-BUSINESS & VOCATIONAL*
1722 **PIZZERIA ESPIRITU**...*RESTAURANTS*
1722 **PIZZERIA ESPIRITU INC**...*EATING PLACE*
1722 **TEENS LUV CARS DRIVERS ED SCHL**...*DRIVING INSTRUCTION*
1722 **TLC DRIVING SCHOOL**...*SCHOOL/EDUCATIONAL SERVICES*
1722 **TORTILLERIA CHABELITA**...*FOOD PRODUCTS & MANUFACTURERS*
1722 **VILLAGE HAIR DESIGN**...*BARBERS*
1790 **CENTURY BANK**...*BANKS*
1851 **GREEN ONION SPORTS PUB**...*RESTAURANTS*
1851 **GREEN ONION TAVERN**...*RESTAURANT & BAR*
1881 **CHARTER MORTGAGE COMPANY INC**...*MORTGAGE BANKERS*
1881 **LOAN MAX**...*TITLE LOANS*
1899 **ALLSUPS 344**...*RET GROCERIES GASOLINE SERVICE STATION*
1899 **ALLSUPS CONVENIENCE STORE**...*CONVENIENCE STORES*
1901 **LIQUID CO PACKAGE LIQUOR STORE**...*LIQUORS-RETAIL*
1901 **LIQUID PACKAGE COMPANY LIQUORS**...*DRINKING PLACE EATING PLACE*
1905 **SHERWIN-WILLIAMS PAINTS**...*PAINT-RETAIL*
1907 **ALLEGRA PRINT & IMAGING**...*COPYING & DUPLICATING SERVICE*
1907 **INSTY-PRINTS**...*PUBLISHING-DESKTOP*
1907 **LOCK SHOP**...*LOCKS & LOCKSMITHS*
1907 **LOCK SHOP THE**...*REPAIR SERVICES*
1907 **MONEY NOW CHECK CASHING**...*LOANS*
1907 **SQUARE DEAL SHOE SHOP**...*SHOE & BOOT REPAIRING*
1907 **VARELA INSURANCE**...*INSURANCE*
1907 **VARELA PHOTOGRAPHY**...*PHOTOGRAPHERS-PORTRAIT*
1909 **CAL SPAS**...*RET MISC MERCHANDISE*
1909 **MIRAGE CORP TANNING**...*TANNING SALONS*
1909 **MIRAGE SPAS & TANNING**...*HOT TUBS & SPAS*
1911 **CHRISTIES HAIR BOUTIQUE**...*BEAUTY SALONS*
1911 **CHRISTIES HAIR BOUTIQUE**...*BEAUTY SHOP*
1911 **CURVES**...*HEALTH CLUBS STUDIOS & GYMNASIUMS*
1911 **CURVES FOR WOMEN**...*HEALTH CLUBS STUDIOS & GYMNASIUMS*
1911 **CUTTING EDGE CATALOG**...*HEALTH & DIET FOODS-RETAIL*
1911 **EMERGNCY VTRNRIAN CLNIC OF S F**...*VETERINARY SERVICES*
1911 **GIMME GOLF OF NEW MEXICO**...*GOLF EQUIPMENT & SUPPLIES-RETAIL*
1911 **NEW METHOD CLEANERS**...*CLEANERS*
1911 **SHORT SET HAIR BOUTIQUE**...*BEAUTY SALONS*
1911 **SUBWAY SANDWICHES & SALADS**...*RESTAURANTS*
2000 **MESA FINANCIAL**...*FINANCIAL ADVISORY SERVICES*
2000 **NCA ARCHITECTS**...*ARCHITECTS*
2000 **PROBATION & PAROLE DIST OFFICE**...*PROBATION SERVICES*
2001 **CEDARWOOD VETERINARY CLINIC PC**...*VETERINARY CLINIC*
2001 **MICHEAL DVM TREITLER**...*RESIDENTIAL*
2001 **STEPHEN DC PERLSTEIN**...*RESIDENTIAL*
2004 **BLAKES LOTA BURGER 41**...*FAST FOOD RESTAURANT*
2004 **BLAKES LOTABURGER**...*RESTAURANTS*
2005 **HYUNDAI OF SANTA FE**...*AUTOMOBILE DEALERS-NEW CARS*
2008 **FRONTIER FRAMES**...*PICTURE FRAMING*
2008 **SAMLL SMILES OF SANTA FE**...*DENTIST'S OFFICE*
2008 **SMALL SMILES DENTISTRY-CHLDRN**...*DENTISTS*

2008 ST MICHAELS DR

SOURCE: DIGITAL BUSINESS DIRECTORY

Part 2 of 2

2008 **STEPHEN CARVER OD**...*OPTOMETRISTS OD*
2008 **STEPHEN OD CARVER**...*RESIDENTIAL*

2003 5TH ST

SOURCE: DIGITAL BUSINESS DIRECTORY

1713 **T PADILLA**...*RESIDENTIAL*
1714 **IGNACIO J ROMERO**...*RESIDENTIAL*
1715 **RAYMOND G MARTINEZ**...*RESIDENTIAL*
1828 **ANASTASIO SALCIDO**...*RESIDENTIAL*
1830 **CYBER MESA COMPUTER SYSTEMS**
1830 **INTERNET AT CYBER MESA**
1911 **B T HOUSING**
1911 **LOS MILAGROS**
1911 **NYDES PROPERTIES**
1911 **UNIVERSAL MORTGAGE & INVSTMNTS**
1911 **US CONSOLIDATED FARM SVC AGCY**...*WILDLIFE CONSERVATION AGENCIES*
1911 **US SOCIAL SECURITY ADM**...*INCOME MAINTENANCE PROGRAMS*
1919 **ALLSTATE INSURANCE**
1919 **BEA CASTELLANO LOCKHART**
1919 **CAPITAL CITY HOME LOANS**
1919 **CASTELLANO BEA L ATTY**
1919 **DIAMOND CUSTOM HOMES**
1919 **EXPRESS MORTGAGE LTD CO**...*AUTOMOBILE AND CONSUMER FINANCE COMPANIES*
1919 **GONZALES CAROLYN H CPA**...*AUDITING SERVICES*
1919 **HEART SPACE HEALING**
1919 **HOME INSTEAD SENIOR CARE**...*GENERAL COUNSELING SERVICES*
1919 **HOWLEY AGENCY**
1919 **INVESTORS ESCROW INC**
1919 **JANET BAILEY THERAPIST**
1919 **JENNINGS ANN V**
1919 **MC Z INC**
1919 **NEW MEXICO STATE AGENCY**
1919 **NEW YORK LIFE INSURANCE**
1919 **PAT LOPEZ ROOFING**
1919 **TARGET SAFE SECURITY SYSTEMS**...*LIGHTING FIXTURES*

2003 ST MICHAELS DR

SOURCE: DIGITAL BUSINESS DIRECTORY

1700 **BREWER CHEVRON**
1700 **LOWE'S SUPER SAVE**
1700 **ST MICHAEL'S CHEVRON**
1701 **HORACE AUTOMOTIVE**
1701 **SANTA FE CHRYSLER JEEP**
1712 **K MART**
1714 **GORDON'S JEWELERS**...*JEWELRY REPAIR SERVICES*
1716 **PLAY IT AGAIN SPORTS**
1718 **CARROWS RESTAURANT**...*STEAK AND BARBECUE RESTAURANTS*
1721 **SONIC DRIVE-IN**...*STEAK AND BARBECUE RESTAURANTS*
1722 **BARTON'S FLOWERS**
1722 **NEW MEXICO ARMY NATIONAL GUARD**
1722 **PIZZERIA ESPIRITU**...*STEAK AND BARBECUE RESTAURANTS*
1722 **THRIFTY NICKEL WANT ADS**...*NEWSPAPERS, PUBLISHING AND PRINTING*
1722 **VILLAGE HAIR DESIGN**
1790 **CENTURY BANK**
1851 **GREEN ONION SPORTS PUB**...*STEAK AND BARBECUE RESTAURANTS*
1881 **CHARTER**
1881 **CHARTER BANK**...*AUTOMOBILE AND CONSUMER FINANCE COMPANIES*
1881 **CHARTER INSURANCE**
1881 **CHARTER MORTGAGE CO**
1899 **ALLSUP'S CONVENIENCE STORE**
1901 **LIQUID CO PACKAGE LIQUOR STORE**
1905 **SHERWIN WILLIAMS CO**...*ABRASIVES AND ADHESIVES*
1907 **ADVANTAGE RENT-A-CAR**
1907 **INSTY-PRINTS**...*PROMOTIONAL PRINTING, LITHOGRAPHIC*
1907 **LOCK SHOP**
1907 **MONEY NOW CHECK CASHING**...*AUTOMOBILE AND CONSUMER FINANCE COMPANIES*
1907 **VARELA INSURANCE**
1907 **VARELA PHOTOGRAPHY**
1909 **MIRAGE CORP TANNING**
1909 **MIRAGE SPA SALES**...*EDUCATIONAL AIDS AND ELECTRONIC TRAINING MATERIALS*
1911 **CURVES FOR WOMEN**...*PHYSICAL FITNESS CLUBS WITH TRAINING EQUIPMENT*
1911 **EMERGENCY VETERINARY CLINIC**
1911 **NEW METHOD CLEANERS**...*LAUNDRY AND DRYCLEANER AGENTS*
1911 **SHORT SET HAIR BOUTIQUE**...*BEAUTY SCHOOLS*
1911 **SUBWAY SANDWICHES & SALADS**...*STEAK AND BARBECUE RESTAURANTS*
1911 **TEENS LUV CARS DRIVERS ED SCHL**...*EDUCATIONAL SERVICES*
1955 **SANTA FE MITSUBISHI & HYUNDAI**...*ENGINE REPAIR*
2000 **TRANSAMERICANO CORP**
2001 **CEDARWOOD VETERINARY CLINIC**
2001 **FAMILY CHIROPRACTIC CTR**
2001 **LAUER JEAN DVM**
2004 **BLAKE'S LOTA BURGER INC**...*STEAK AND BARBECUE RESTAURANTS*
2005 **SANTA FE NISSAN**...*ENGINE REPAIR*
2008 **ALLEGRO CENTER**...*COMMERCIAL AND INDUSTRIAL BUILDING OPERATION*
2008 **ALLEGRO MUSIC PERFORMANCE CTR**
2008 **CARVER STEPHEN OD**...*SPECIALIZED OPTOMETRISTS*
2008 **SMALL SMILES DENTISTRY-CHLDRN**...*SPECIALIZED DENTAL PRACTITIONERS*

2000 5TH ST

SOURCE: DIGITAL BUSINESS DIRECTORY

1713 **T PADILLA**...*RESIDENTIAL*
1714 **IGNACIO J ROMERO**...*RESIDENTIAL*
1715 **RAYMOND G MARTINEZ**...*RESIDENTIAL*
1828 **ANASTASIO SALCIDO**...*RESIDENTIAL*
1830 **CYBER MESA COMPUTER SYSTEMS**...*COMPUTER SOFTWARE AND ACCESSORIES*
1830 **INTERNET AT CYBER MESA**
1911 **BUSINESS COMMUNICATIONS SVC**...*COMPUTER PERIPHERAL EQUIPMENT*
1911 **GUARD IT SECURITY SVC**...*DETECTIVE SERVICES*
1911 **JOHN FLORES & SONS SURVEYING**
1911 **NATURAL RESOURCES CONSERVATION**...*WILDLIFE CONSERVATION AGENCIES*
1911 **NYDES PROPERTIES**
1911 **US CONSOLIDATED FARM SVC AGCY**...*WILDLIFE CONSERVATION AGENCIES*
1911 **US SOCIAL SECURITY ADM**...*INCOME MAINTENANCE PROGRAMS*
1919 **ADOBE CITY APPRAISAL**
1919 **ALLSTATE INSURANCE**
1919 **AMERICAN BUILDING INSPECTIONS**...*METAL CUTTING SERVICES*
1919 **AUTHENTIC SOUTHWEST WINDOWS**...*DOOR AND WINDOW PRODUCTS*
1919 **EXPRESS MORTGAGE LTD**...*AUTOMOBILE AND CONSUMER FINANCE COMPANIES*
1919 **GONZALES CAROLYN H CPA**...*AUDITING SERVICES*
1919 **HOWLEY AGENCY**
1919 **HOWLEY INSURANCE**
1919 **INVESTORS ESCROW INC**
1919 **JANET BAILEY THERAPIST**
1919 **JENNINGS ANN V**
1919 **L F PERRY & ASSOC**
1919 **LOCKHART BEA C ATTY**
1919 **MC DONALD'S**...*STEAK AND BARBECUE RESTAURANTS*
1919 **MC Z INC**
1919 **PADILLA & ASSOC ARCHITECTS**
1919 **PEBSCO-NEW MEXICO**
1919 **SYCAMORE CONSTRUCTION LTD**
1919 **TARGET SAFE SECURITY SYSTEMS**...*LIGHTING FIXTURES*
1919 **TJOLAND CAROLYN**
1919 **TRINITY MORTGAGE CO**...*AUTOMOBILE AND CONSUMER FINANCE COMPANIES*

2000 ST MICHAELS DR

SOURCE: DIGITAL BUSINESS DIRECTORY

1700 **BREWER CHEVRON**
1700 **FURR'S SUPERMARKET**
1700 **ST MICHAEL'S CHEVRON**
1701 **CHRYSLER PLYMOUTH JEEP EAGLE**
1712 **K MART**
1714 **GORDON'S JEWELERS**...*JEWELRY REPAIR SERVICES*
1716 **PLAY IT AGAIN SPORTS**
1718 **CARROWS RESTAURANT**...*STEAK AND BARBECUE RESTAURANTS*
1721 **SONIC DRIVE-IN**...*STEAK AND BARBECUE RESTAURANTS*
1722 **CARD SHOP**
1722 **CORNERSTONE BOOKS & GIFTS**
1722 **PIZZERIA ESPIRITU**...*STEAK AND BARBECUE RESTAURANTS*
1722 **THRIFTY NICKEL WANT ADS**
1722 **US ARMY NATIONAL GUARD RECRUIT**
1722 **VILLAGE HAIR DESIGN**
1790 **CENTURY BANK**
1851 **GREEN ONION SPORTS PUB**...*STEAK AND BARBECUE RESTAURANTS*
1881 **CHARTER BANK**...*AUTOMOBILE AND CONSUMER FINANCE COMPANIES*
1881 **CHARTER MORTGAGE CO**
1899 **ALLSUP'S CONVENIENCE STORE**
1901 **LIQUID CO PACKAGE LIQUOR STORE**...*BARS AND LOUNGES*
1905 **SHERWIN-WILLIAMS CO**...*ABRASIVES AND ADHESIVES*
1907 **ADVANTAGE RENT-A-CAR**
1907 **INSTY-PRINTS**...*PROMOTIONAL PRINTING, LITHOGRAPHIC*
1907 **LOCK SHOP**...*AIRCRAFT AND HEAVY EQUIPMENT REPAIR SERVICES*
1907 **MONEY NOW CHECK CASHING**...*AUTOMOBILE AND CONSUMER FINANCE COMPANIES*
1907 **SPECTRUM PHOTOWORKS**...*PHOTOGRAPHIC SERVICES*
1909 **CAL SPAS**...*EDUCATIONAL AIDS AND ELECTRONIC TRAINING MATERIALS*
1909 **MIRAGE STOVES**...*EDUCATIONAL AIDS AND ELECTRONIC TRAINING MATERIALS*
1909 **MIRAGE TANNING EQUIPMENT**
1911 **EMERGENCY VETERINARY CLINIC**
1911 **NEW METHOD CLEANERS**...*LAUNDRY AND DRYCLEANER AGENTS*
1911 **SHORT SET HAIR BOUTIQUE**...*BEAUTY SCHOOLS*
1911 **SQUARE DEAL**
1911 **SUBWAY SANDWICHES & SALADS**...*STEAK AND BARBECUE RESTAURANTS*
2000 **IMAGING CONCEPTS OF NEW MEXICO**...*TYPEWRITER AND DICTATION EQUIPMENT*
2000 **LEEDSHILL-HERKENHOFF INC**
2000 **PROBATION & PAROLE DIST OFFICE**
2001 **CEDARWOOD VETERINARY CLINIC**
2001 **FAMILY CHIROPRACTIC CTR**
2001 **LAUER JEAN DVM**
2004 **BLAKE'S LOTA BURGER INC**...*STEAK AND BARBECUE RESTAURANTS*
2005 **SANTA FE MITSUBISHI & HYUNDAI**...*ENGINE REPAIR*
2005 **SANTA FE NISSAN**...*ENGINE REPAIR*

1996 5TH ST

SOURCE: POLKS

5TH ST to S 5TH ST

5TH ST cont'd

Address		Zip+4	Carr Rte	Phone
911	Arnold Michael P	-4357	C004	425-1853
	Duke Kathar	-4357	C004	425-6978
	Gurule Julia	-4357	C004	425-5742
	Wilson David R	-4357	C004	425-7022
914	Tsyltee Edward	-4332	C004	425-8874
915	Reed Clyde H	-4331	C004	454-0051
917	Eskridge Theresa	-4331	C004	454-8638
918	Bama L E	-4332	C004	425-5972
920	Mossman Susie	-4332	C004	454-1624
	Mossman Terry	-4332	C004	454-1624
921	Romero Sam	-4331	C004	454-9569
1008	Sanchez Henry A	-4334	C004	425-3624
1017	Lindsey Sean	-4333	C004	425-7063
1021	Harris Jay G	-4333	C004	454-0438
1024	Stauffer Lee	-4334	C004	454-8781
1026	Herrera Joe D	-4334	C004	425-5574
1029	Garcia Ernest Jr	-4333	C004	425-5634
1030	Roybal Paul	-4300	C004	425-5380
	Smith Ben F	-4300	C004	425-5309
1033	Delaney Charles S	-4333	C004	425-3174
1034	Hartzler J K	-4334	C004	425-1017
1035	Nitcznski Ed	-4333	C004	425-6349
1038	Lewis Myrtle K	-4334	C004	425-8717
1041	Martinez Jose O	-4333	C004	454-1677
1044	Kerr J	-4334	C004	454-0483
	Montoya Antonio	-4334	C004	425-6430
1045	Cozens Gwynne	-4333	C004	425-5851
	Cozens Michael	-4333	C004	425-5851
1047	Salas Al	-4333	C004	454-9560
1051	Gilbert Carlos	-4333	C004	425-8283
1052	Summers Carol	-4334	C004	425-1610
1205	King Terry L	-4336	C004	425-5733
1211	Burger Robert R	-4336	C004	425-7260
1217	Lucero Miranda	-4336	C004	425-9041
1219	Romero A D	-4336	C004	425-6880
	Romero Tony	-4336	C004	425-9701
1221	Clayton T	-4336	C004	425-1435
1231	Branch Richard	-4336	C004	425-8144
1233	Ludi S A	-4336	C004	425-0436
1235	Apellanes Simmie	-4336	C004	454-1086
1237	Browning Roy	-4336	C004	425-7124
1239	Valenzuela Gonzalo	-4336	C004	425-3987
1312	Breuning Carl G	-4302	C004	425-7446
1316	Schlosser Jon A	-4302	C004	425-3063
1320	Boyles Linda	-4302	C004	454-8972
	Boyles Michael	-4302	C004	454-8972
1325	Sanchez Gilbert	-4301	C004	454-1117
	Sanchez Lorena	-4301	C004	454-1117
1329	Albers Wally	-4301	C004	425-5887
1404	Thompson F E	-4304	C004	425-7126

BUSINESSES 5 HOUSEHOLDS 75

5TH ST *(LA)* 87544

1148	Bezzerides A V	-3105	C001	662-5370
1149	Hogan Billy M	-3104	C001	662-9612
1190	Damjanovich Robert P	-3105	C001	662-4384
1191	Korzekwa David	-3104	C001	662-5228
	Korzekwa Deniece	-3104	C001	662-5228

HOUSEHOLDS 5

5TH ST *(RA)*

411	Sanchez Alfonso	445-3046
	Sanchez Kathryn	445-3046
737	Gonzales Gina	445-8754
	Gonzales Tom C	445-8754
1105	Gabriele Gary E	445-5832
	Gabriele Kelli	445-5832

HOUSEHOLDS 6

5TH ST *(SF)* 87505

1500	B CALICO-HICKEY DC	-3480	C022	984-0972
	BERGSTRALH SHAW & NEWMAN	-3480	C022	984-1650
	CON CARINO HAIR SALON	-3480	C022	989-8480
	DAVID SCHUTZ & CO	-3480	C022	438-3146
	DESERT STATE LIFE MANAGEMENT	-3480	C022	988-5550
	DIANE BLACK	-3480	C022	984-2129
	EAST WEST MEDICAL ARTS	-3480	C022	983-2032
	FAMILY INSTITUTE OF NORTHERN	-3480	C022	982-4704
	INNER SMILE	-3480	C022	983-2233
	J MICHAEL MOORE ACUPUNCTURIST	-3480	C022	982-2138
	OPTIMUM HEALTH INSTITUTE	-3480	C022	989-8269
	SANTA FE AREA HOME BUILDERS	-3480	C022	982-1774
	Black Diane	-3480	C022	984-2129

5TH ST cont'd

Address		Zip+4	Carr Rte	Phone
	Ross John	-3480	C022	983-2032
1501	AUDIO VISIONS	-3427	C022	988-3850
1505	SPIRIT CLUB	-3427	C022	986-8828
1513	SANTA FE JEWELERS SUPPLY	-3427	C022	988-9157
1515	GOLD LEAF FRAMEMAKERS	-3427	C022	988-5005
1519	CALVARY CHAPEL DE SANTA FE	-3427	C022	988-3291
1520	BEN'S AUTOMOTIVE SVC	-3428	C022	983-1031
1521	ACOMA OPTICAL	-3427	C022	988-5321
1525	FUND FOR FOLK CULTURE	-3427	C022	984-2534
	Boddy Brian	-3427	C022	988-9689
	Boddy Cynthia	-3427	C022	988-9689
	Boddy R M	-3427	C022	983-1692
	Williams N L	-3427	C022	988-1985
1526	Gonzales Casimi	-3428	C022	983-7950
1527	HOLMES ELECTRIC	-3427	C022	982-0256
1530	Quintana Aurelio	-3428	C022	982-5370
	Romero Aurelia	-3428	C022	983-8303
1605	Benavidez Joe A	-3429	C022	983-7494
1607	Calles Guille R	-3429	C022	986-8449
1713	Padilla T	-3431	C022	986-9248
1714	Romero J	-3432	C022	983-9483
1715	Martinez Raymond G	-3431	C022	982-8013
1804	Gravel Greg	-3443	C022	989-4236
1828	Salcido Anasta	-3443	C022	986-9026
1830	ROADRUNNER COMPUTER SYSTEMS	-3443	C022	988-9200
1911	ENTERPRISE RENT A CAR	-5403	C037	473-3600
	ENVIRONMENT DEPT	-5403	C037	473-3473
	NATURAL RESOURCES CONSERVATION	-5403	C037	988-6605
	UNIVERSAL MORTGAGE & INVESTMNT	-5403	C037	471-2269
	US AGRICULTURAL STABILIZATION	-5403	C037	988-6253
	US CONSOLIDATED FARM SVC AGCY	-5403	C037	988-6253
	US SOCIAL SECURITY ADM	-5403	C037	988-6452
	US SOIL CONSERVATION SVC	-5403	C037	988-6605
	VANPOOL ASSOC OF NORTHERN NM	-5403	C037	471-7255
2067	AMIGO TOWING	-5405	C037	473-5779
	Garcia Bennie	-5405	C037	473-7834
	Salazar Lilly	-5405	C037	473-7834
2074	Martinez Jesse J	-5404	C037	473-0681
2075	Ortizypino Jana	-5405	C037	473-3054
	Ortizypino Paul	-5405	C037	473-3054
2081	Brown Sidney S	-5490	C037	471-3768
2082	Huskey Bobby G	-5479	C037	471-4693
2084	Keim P C	-5479	C037	438-9244
2086	PIGEON EXPRESS	-5479	C037	473-3447
	Odell Richard B	-5479	C037	473-1449
2087	Ramirez R A	-5481	C037	471-7894
2088	Whitmore Gary	-5479	C037	471-8641
2089	Narvaiz Michel A	-5481	C037	438-8571
2091	Gonzales Y P	-5481	C037	473-2650
2092	Garcia C L	-5479	C037	471-8211
2094	Cisneros Charle	-5479	C037	471-6810
	Cisneros Sammy	-5479	C037	471-6810
2095	Segura Gilbert	-5481	C037	471-7753
2098	Prucino Roger P	-5479	C037	471-6290

BUSINESSES 33 HOUSEHOLDS 34

5TH ST *(SP)*

104	Yohn Gineth	483-5053
316	Herrera Daniel R	483-2948
413½	MOTOR VEHICLE DIV	483-2802
425	Floyd J W	483-2755
710	ST JOSEPH'S CATHOLIC CHURCH	483-2775
812	Hampson E	483-2372
815	Pena Carlos	483-5026
913	Valdez Elito	483-2220

BUSINESSES 2 HOUSEHOLDS 6

E 5TH ST *(RA)* 87740

602	Rogers Kathy L	-2731	C004	445-3911
715	Sanchez Louis	-2734	C004	445-9338
727	Martinez R	-2734	C004	445-2904
733	Wheeler George	-2734	C004	445-2526
807	Biswell E M	-2736	C004	445-2253
809	Romero Vicky	-2736	C004	445-8163
820	Horner Matt	-2735	C004	445-3502
827	Shaw Jim	-2722	C004	445-5658
	Shaw Mary	-2722	C004	445-5658

1996 ST MICHAELS DR

SOURCE: POLKS

SAINT MICHAELS DR cont'd

Address		Zip+4	CarrRte	Phone
	EGGERS SANTA FE	-7615	C022	473-7100
	INFO LINK OF SANTA FE	-7615	C022	473-1000
	INSTITUTE OF AMER INDIAN ARTS	-7615	C022	988-6463
	NEW MEXICO INDIAN EDUCATION	-7615	C022	473-6116
	Bartuslak Ronald	-7615	C022	473-4407
	Brown J K	-7615	C022	471-1243
	Hetzel George	-7615	C022	471-6870
1601	ST VINCENT HOME HEALTH SVC	-7614	C022	989-9331
	TITLES DE SANTA FE INC	-7614	C022	820-1409
1605	ST MICHAELS COIN OP LAUNDRY	-7614	C022	983-9960
1606	IMPERIAL HAIR SALON	-7615	C022	473-9858
1607	VELVET CUSHION BILLIARDS	-7614	C022	982-9056
1608	FRONTIER FRAMES	-7615	C022	473-1901
1610	READER'S HARVEST BOOK SHOP	-7615	C022	983-4866
1611	SANTA FE SCHWINN	-7614	C022	983-4473
1612	US AIR FORCE RECRUITING	-7615	C022	473-4949
	US ARMY RECRUITING	-7615	C022	471-7821
	US MARINE CORPS RECRUITING	-7615	C022	471-1448
	US NAVAL RECRUITING	-7615	C022	471-4139
1620	SERGIO'S RISTORANTE ITALIANO	-7615	C022	471-7107
1624	GARSON'S	-7615	C022	473-5837
1628	PET POURRI	-7615	C022	471-9040
	SANTA FE WATER GARDENS	-7615	C022	473-2683
1632	ROB & CHARLIE'S	-7615	C022	471-9119
1636	LOGOS BOOK STORE	-7615	C022	473-0435
1638	NATIONAL PHONE CTR	-7615	C022	473-5723
1640	HARDEE'S	-7615	C022	471-7794
1644	AAA INSURANCE	-7615	C022	471-6620
1698	GIANT SERVICE STA	-7615	C022	438-9800
1700	FURR'S SUPERMARKET	-7617	C022	471-8673
	GRAHAM'S CHEVRON	-7617	C022	471-8049
1701	CHRYSLER PLYMOUTH JEEP EAGLE	-7616	C022	982-1956
1712	K MART	-7620	C022	471-9007
1714	GORDON'S JEWELERS	-7617	C022	471-7665
1716	PREMIERE VIDEO	-7617	C022	473-4112
1718	CARROWS RESTAURANT	-7617	C022	471-7856
	CARROWS RESTAURANTS	-7617	C022	471-7856
1721	SONIC DRIVE-IN	-7616	C022	984-2522
1722	CORNERSTONE BOOKS ETC	-7650	C022	473-0306
	COYOTE BICYCLE SHOP	-7650	C022	471-1682
	SANTA FE TRAIL COINS & CARDS	-7650	C022	471-7818
	THRIFTY NICKEL WANT ADS	-7650	C022	473-4111
	US ARMY NATIONAL GUARD RECRUIT	-7650	C022	473-4541
	VILLAGE HAIR DESIGN	-7650	C022	473-4844
1790	CENTURY BANK FEDERAL SAVINGS	-7617	C022	471-6666
1851	GREEN ONION PUB	-7618	C022	983-5198
1881	CHARTER BANK FOR SAVINGS	-7618	C022	982-2534
	CHARTER SOUTHWEST MORTGAGE	-7618	C022	982-0025
1901	LIQUID CO	-7626	C022	984-1219
1905	SHERWIN-WILLIAMS CO	-7626	C022	982-3559
1907	INFOTEC DEVELOPMENT INC	-7626	C022	982-2201
	INSTY-PRINTS	-7626	C022	982-0122
	SANTA FE SUN INC	-7626	C022	989-8381
1909	MIRAGE TANNING EQUIPMENT	-7626	C022	989-3277
1911	EMERGENCY VETERINARY CLINIC	-7653	C022	984-0625
	NEW METHOD CLEANERS	-7653	C022	982-0271
	SUBWAY SANDWICHES & SALADS	-7653	C022	986-1300
1955	SANTA FE MITSUBISHI	-7626	C022	982-3637
2000	ALLSUP'S CONVENIENCE STORES	-7624	C022	471-8973
2001	CEDARWOOD VETERINARY CLINIC	-7623	C022	982-4469
	FAMILY CHIROPRACTIC CTR	-7623	C022	984-0006
	Lyle J D	-7623	C022	982-4469
2004	BLAKE'S LOTA BURGER INC	-7624	C022	471-8694
2005	SANTA FE NISSAN	-7623	C022	983-7337
2008	PARKS NURSERY	-7624	C022	471-8499

BUSINESSES 203 HOUSEHOLDS 77

SALAZAR (T)

201	Gomez Albert	758-4479
208	Vigil Tammy C	758-1275
309	Hopper Toni K	758-1289
319	Valdez Merced F	751-0192
421	Thompson Marc	758-0630
519	Gallegos Elizab	751-0472
	Gallegos Jorge	751-0472
521	Thompson Marc	758-0630
712	Roybal Tammy	758-2169
906	Thomas Glenn	758-3592
1005	JOHN C FLEXNER	758-0106

BUSINESSES 1 HOUSEHOLDS 10

SALAZAR GARCIA CIR (SP)

103	Armijo Dina	483-0150
104	Chavez Anna	483-2986
105	Valdez Aileen	483-0411
	Valdez Manuel	483-0411
109	Sanchez Renee G	483-2880
111	Salazar M A	483-0317
112	Ortiz Anna M	483-2973
114	Deherrera Ralph	483-2751
117	Archuleta Joe E	483-5585
118	Gabbert Maria O	483-2923
119	Duran Frances	483-5049
206	Baca Helen	483-2281
209	Marcus Maria O	483-5941
211	Pinario V	483-2842
215	Urban Rose	483-5907
217	Kennedy Lynn V Jr	483-2701
219	Pillars Rhonda	483-5018

HOUSEHOLDS 17

SALAZAR PL (SF) 87501

400	ROBERT RICHARDS	-2444	C061	988-2386
	Richards Robert	-2444	C061	988-2386
	Roberts Dick	-2444	C061	989-8574
402	Salazar Alex	-2444	C061	983-7478
405	Sheasby Daniel C	-2443	C061	988-5285
407	Scott R	-2443	C061	989-4279
408	Thompson Joseph M	-2444	C061	984-2746
409	Aguirre Jack M	-2443	C061	983-3829
410	Sanchez Emilio	-2444	C061	982-5230
	Sanchez Virgin	-2444	C061	982-5230
411	Letcher Chris	-2443	C061	820-6577
412	Wheeler John F	-2444	C061	983-5768
413	Roybal Gloria	-2443	C061	983-2845
	Sweat Randy	-2443	C061	983-2845
414	Romero Stjohn C	-2444	C061	982-0566
415	Aguiar J	-2443	C061	986-3927
419	HOWLAND CONSTRUCTION	-2443	C061	982-5453
	Howland Joseph J	-2443	C061	982-5453
420	Trujillo Anna	-2444	C061	982-8487

BUSINESSES 2 HOUSEHOLDS 17

SALAZAR ST (ES) 87532

305	Salazar Richard R	-2653	C002	747-1517

HOUSEHOLDS 1

SALAZAR ST (LV) 87701

928	Luby Michael S	-3584	C006	425-5105
1017	Gonzales C	-3541	C006	425-7657
1020	Maes Paz	-3542	C006	454-0665
1026	Madrid Gilbert	-3542	C006	425-5961
1109	Carreon Gloria	-3543	C006	454-1197
1114	Roybal Jose B	-3544	C006	425-6406
1116	Espinoza Lorrai	-3544	C006	425-3462
1313	Ulibarri Michael	-3545	C006	454-9538
1314	Lucero Tina	-3546	C006	425-1419
1315	Ulibarri Max	-3545	C006	454-9224
1318	Chavez Henry L	-3546	C006	454-0485
1400	Fresquez Alan	-3548	C006	454-8217
1402	Ulibarri Antonio	-3548	C006	454-8528
1408	Gabaldon Jeanet	-3548	C006	425-1750
1505	Lucero Anita S	-3549	C006	425-5896

HOUSEHOLDS 15

SALAZAR ST (SF) 87501

501	Fabec Todd	-3641	C061	989-7792
	Gordon Derek	-3641	C061	986-0625
	Smith Darren	-3641	C061	989-7792
504	Fukui Haruo	-3642	C061	989-4668
505	Lyon Dilman S	-3641	C061	983-3763

1993 5TH ST

SOURCE: POLKS

(505) 982-4621

P.O. Box 1941 (87504)

◎ HOMEOWNER

5TH ST--Contd

1505 PROFESSIONAL RECORD MGMT & STORAGE doument storage & shredding
1513 GOLDLEAF FRAME MAKERS art galleries 988-5005
SANTA FE JEWELERS SUPPLY 988-9157
1519 CALVARY CHAPEL DE SANTA FE 988-3291
1520 BEN'S AUTOMOTIVE SERVICES antique cars 983-1031
1521 ACOMA OPTICAL 988-5321
1524 STORAGE
1525 Boddy Richd M [2]
1526 Gonzales Casimiro & Alice [9]+ ◎ 983-7950
Gonzalez Gose 983-7950
1527 HOLMES ELECTRIC 982-0256
1530 Romero Aurelia [9]+ ◎ 983-8303
1535a West S L [2] 983-2395
Parsons Richard 983-2395
• QUAPAW INTERSECTS
1605 Benavidez Joe A & Frances [4] ◎ 983-7494
1607 Martinez Sam R & May [4] ◎ 988-1367
1609 Gonzales K [2]
• HOPEWELL INTERSECTS
1713 Vela Joe J & Susie [9]+ 983-4137
Apartments
1 Padilla Theresa [2] 986-9248
2 Enncinias Manuel [2]
3 Vela Dianne [3]
4 Robey Paxton [2]
1714 Romero Ignacio J & Eliza E [9]+ ◎ 983-9483
1715 Martinez Raymond G & Luisa [9]+ ◎ 982-8013
1 Dadilla J 982-8013
Martinez Cecilia 982-8013
• MANN INTERSECTS
1804 Not Verified
1804½ Gravel Greg wood carver
1828 Not Verified
1830 DONA ELENA'S MEXICAN KITCHEN restr 983-9941
• ST MICHAELS DR INTERSECTS
1911 Building
101 U S DEPT HEALTH-HUMAN SERV SOCIAL SECURITY ADMN 988-6452
102 ENTERPRISE RENT-A-CAR 473-3600
U S DEPT OF AGRICULTURE 471-9160
202 N M ENVIRONMENT DEPARTMENT 473-3473
203 UNIVERSAL MORTGAGE INVESTMENT 471-2269
204 N M ENVIRONMENT DEPARTMENT overflow
205 STATE ENVIRONMENTAL DEPARTMENT 473-3473
206 U S DEPARTMENT OF AGRICULTURE overflow
207 U S DEPT OF AGRL 988-6605
208 U S D A SOIL CONSERVATION SERV 471-7607
209 SOIL CONSERVATION overflow
210 OLD AMERICAN COMPANY INC insurance 471-0065
211 U S DEPT OF AGRL STABILIZATION SERV 988-6253
• WARREN AV INTERSECTS

139

• ZIP CODE 87505

2074 Martinez Jesse J & Patty L [4] ◎ 473-0681
2075 Ortiz Y Pino Paul & Jana [8] ◎ 473-3054
2076 Light Dick E & Joan [2] ◎ 471-3316
2080 Baros Augustin B Jr & Dora [9]+ ◎ 471-8748
2081 Brown Sidney S & Rebecca [9]+ ◎ 471-3768
2082★Housman Fred
2084 Keim Patricia C [2] 438-9244
Keim Christopher G 438-9244
2087 Ramirez Robert A & Priscilla [9]+ ◎ 471-7894
2088 Whitmore Gary C & Carole A [9]+ ◎ 471-8641
2089 Narvaiz Larry A & Angie [9]+ ◎ 438-8571
2090 Not Verified
2091 Serna Robert F & Priscilla A [9]+ ◎ 471-7636
Serna Danny 471-7636
2092 Garcia Pat A [9]+ ◎ 471-8211
2093 Alejandro John [7] ◎ 986-0346
2094 Cisneros Sammy L & Charlene A [2] ◎ 471-6810
Cisneros Charlene 471-6810
2095 Not Verified
2096 Durr Edwin E & Priscilla M [9]+ ◎ 471-8150
2097 Sandoval Aurelio [4]
2098 Downes Ann [3] 473-3085
• SIRINGO RD INTERSECTS
35 HOUSEHOLDS
26 BUSINESSES

31

6TH ST -FROM 1500 5TH WEST AND SOUTH TO ST MICHAELS DR

• ZIP CODE 87501
• BERRY INTERSECTS
1501★Norskog Jody 982-1111
1505 PROFESSIONAL RECORD MANAGEMENT & STORAGE 984-1580
SOLS PLUMBING & HTG 989-8570
1549 PLUMBING ASSOCIATES INC THE 986-3875
DURAN ENTERPRISES genl contracting 988-5650
1-1549 Not Verified (3 Apts)
ELECTRICAL BUILDER & SERV CO 986-5086
A15★Montoya C A & Paula M ◎ 988-7243
12★Miramontes Arturo 983-7051
17★Martinez C 986-0425
1606★Bolleter James T 984-1889
• QUAPAW INTERSECTS
• HOPEWELL INTERSECTS
1650 Not Verified
• MANN ST INTERSECTS
• ST MICHAEL'S DR INTERSECTS
6 HOUSEHOLDS
2 BUSINESSES

6

ABEYTA ST -FROM 774 ACEQUIA MADRE SOUTH

• ZIP CODE 87501
• CAMINO DEL PONIENTE BEGINS
404 Beckman Dale B [2] 989-7290
418 Sadotl Jas N [4] 988-4081
422 Hoyt Lucinda [2] 982-8510
424 Baustian Robt F [9]+ ◎ 983-1734
426 Hirsch Stanton H [3] ◎ 982-1436
428 Apodaca Benny & Rosina J [9]+ ◎ 982-2419
430★Naylor David ◎ 983-6188
Webber Sydney A 983-6188
432 Not Verified
500★Frey Johanthan 988-5807
502 Granzow Todd J & Mary B [4] ◎ 982-2870
503 Jordan M [2] ◎ 982-9791
504 Stein Sherry B [4]
508 Lucero Filia [2]
509 Vasquez S [2] 984-0065
512 Apodaca Clara M [9]+ ◎ Kwasek Madge
516★Harper L ◎ 982-3092
517 Spinden Ailes [9]+ ◎ 988-2184
Spinden Jos 988-2184
523 Not Verified
525★Endsley Richard A 984-0345
527★Stuart J 986-0435
528★Robbins Whitney K ◎ 988-7165
• EL CAMINITO INTERSECTS
601 Felicity Ruth [2] 986-1408
603★Calamaria Peter 989-4615
609 Hagman Kristina artist ◎ 982-3644
Masler Daniel 982-3644
• CAMINO RANCHITOS BEGINS
800 Kilgore M Karen [2] ◎ 982-5446
801 Vigil Dan & Veronica [2] ◎
801½ Martinez Stella [2] 986-0829
807 Apodaca Julia [9]+ ◎ 983-2411
Vigil Carlos R 983-2411
809 Apodaca Roman & Frances C [9]+ ◎ 982-2952
810 Elliott Freda [2] 982-5295
810½ Romero Alphonso P [2] 983-3188
812 Apartments
A Vacant
D Not Verified
E-812 Vacant (2 Apts)
31 HOUSEHOLDS
1 BUSINESS

1993 ST MICHAELS DR

SOURCE: POLKS

1611 SANTA FE SCHWINN ret bicycles 983-4473
1612 U S AIR FORCE RECRUTING STATION govt ofc 473-4949
U S MARINE CORP RECRUTING STATION govt ofc 471-1448
U S ARMY RECRUITING STA govt ofc 471-7822
U S NAVY RECRUITING STATION govt ofc 471-0986
1616 Vacant
1620 COMO'S RISTORANTE ITALIANO restr 438-8121
1622 Vacant
1624 GARSON & SONS religious articles 473-5837
1626 PET POURRI 471-9040
1632 ROB & CHARLIE'S INC bicycle shop & restr 471-9119
1634 ROB & CHARLIE'S INC overflow 471-9119
1636 JAZZERCISE 471-8399
1638 NATIONAL PHONE CENTER 473-5723
1640 HARDEE'S RESTAURANT 471-7794
1644 A A A AMERICAN AUTO ASSN 471-6620
1650 FOX PHOTO 471-2246
1698 EXXON SERVICE STATION gas sta 438-9800
1699 GRAND ILLUSION 471-8935
• LLANO INTERSECTS
1700 GRAHAM'S CHEVRON gas sta 471-8049
FURR'S SUPERMARKET NO 384 gro-ret 471-8673
1701 HORACE CHRYSLER-PLYMOUTH-DODGE OF SANTA FE 982-1956
1712 K-MART NO 3301 471-9007
1714 GORDON JEWELERS 471-7665
1716 Vacant
1718 CARROW'S RESTAURANT 471-7856
1721c SONIC DRIVE IN restr 984-2525
1722a CORNESTONE BOOKS ETC bookstore 473-0306
1722b Not Verified
1722c Not Verified
1722d THRIFTY NICKEL WANT ADS 473-4111
1722e THRIFTY NICKEL overflow
1722f NEW MEXICO ARMY NATL GUARD recruiting sta 473-4403
1722g VILLAGE HAIR DESIGN beauty shop 473-4844
1722h SANTA FED TRAIL COINS & BASEBALL CARDS coins & baseball cards ret 471-7818
1790 CENTURY BANK FEDERAL SAVINGS BANK 471-6666
• FIFTH ST INTERSECTS
1851 GREEN ONION RESTR 983-5198
1881 CHARTER BANK FOR SAVINGS F S B 982-2534
1899 ALLSUP'S CONVENIENCE STORE 986-0776
• FIFTH ST INTERSECTS
1901 Not Verified
1905 SHERWIN-WILLIAMS CO THE paint 982-3559
1907a Vacant
1907b INFOTEC DATA PRODUCTS 982-2201
1907c-1907d Vacant (2 Businesses)
1907e NORTHERN NEW MEXICO COMPUTER'S 983-4644
F Vacant
1 1907g Not Verified
1911a NEW METHOD CLEANERS 982-0271
1911b SUBWAY RESTR 986-1300
1911c INSTY PRINTS 982-0122
1911d VETERINARY CLINIC
1911e SANTA FE VOGUE COLLEGE OF COSMETOLOGY overflow
1911f SANTA FE VOGUE COLLEGE OF COSMETOLOGY overflow
1911g SANTA FE VOGUE COLLEGE OF COSMETOLOGY 983-7322
1955 SANTA FE MITSUBISHI autos retail 982-3637
• ESPINACITAS ST INTERSECTS
• WARNER ST INTERSECTS
2000 ALLSUP'S CONVENIENCE STORE 473-4387
ALLSUPS DISTRICT OFFICE grocers-ret 471-8973
2001 CEDARWOOD SMALL ANIMAL CLINIC 982-4469
FAMILY CHIROPRACTIC CENTER OF SANTA FE 984-0006

ST MICHAELS DR–Contd

2004 BLAKE'S LOTA BURGER NO 41 8
471-8694
2005 SANTA FE NISSAN 983-7337
2008 PARKS NURSERY 471-8499
173 BUSINESSES 1

39

SALAZAR PL –FROM 1300 LOPEZ SOUTH TO AGUA FRIA 1

• ZIP CODE 87501

400 Richard S Robt [4] 988-2386
402 Salazar Alex & Stephie [9]+ © 983-7478
404 Not Verified
405★Manchego Juan B 986-1876
406 Not Verified
407 R SCOTT 989-4279
Not Verified
408 Ahrendsen David [4] © 982-6856
409 Aguirre Jack M [9]+ © 983-3829
Aguirre Carlos 983-3829
410 Sanchez Emilio A & Virginia L [9]+ © 982-5230
411★Clark W Andrew 982-2645
Mc Donald Jame L 982-2645
412 Wheeler John F & Molly P [9]+ © 983-5758
413★Sweet Randy & Gloria R © 983-2845
414 Romero Manuela A [9]+ © 982-0566
415 Strimple K [2] 982-5765
416 Not Verified
418 Leyba Clyde A & Lillian [9]+ ©
419 HOWLAND CONSTRUCTION CO 982-5453
Howland Jos [8] © 982-5453
420 Trujillo Anna M [9]+ © 982-8487
18 HOUSEHOLDS
1 BUSINESS

11

SALAZAR ST –FROM 1130 AGUA FRIA SOUTH TO CAMINO SIERRA VISTA

• ZIP CODE 87501

501 Vacant
502 Padilla Cheryl [2] 986-0357
504★Javor Henry R & Betty © 982-3986
505 Lyon Dilman S [9]+ © 983-3763
510 Escusero [2]
513 Olonia Joe D & Virginia F [9]+ © 983-8882
514★Pepperl Jim © 983-1175
516 Sanchez Stella F [2]
517 Miller L [2]
521★Sandstrum Christina © 986-0181
525 Sattley Linda [2] 984-8155
526 Smith David [9]+ © 988-5772
Smith Mary O 988-5772
Smith Robt 988-5772
533 Fresquez Sam C [9]+ © 983-4856
534★Bowles Joe 1
535 De Vargas Christine [9]+ ©
537 Bowles Delfina G [9]+ © 983-7883
538 Gonzales Ricky [2]
541★Perrone Bobette © 984-0048
542 Moya Ramon L & Teresa F [9]+ © 983-6431
544 Mascarenas Salomon [9]+ © 982-8333
• HICKOX INTERSECTS
601 Garcia Arth J [3]
602 Not Verified
603 Garcia Arth F & Rose S [9]+ © 982-3237
604 Giron Joe E & Julia A [9]+ © 982-8057
Rear Vacant
605★Shafer Janie 986-9141
606 Lawrence Lourdes [9]+ © 988-2374
Lawrence David 988-2374
Lawrence Edward Jr 988-2374
Lawrence Jimmy 988-2374
607 Horst Edw L & Loretta C [2] © 988-9660
610 Perez Isabele [9]+ © 983-7555
Perez Robt G 983-7555
Perez Vincent M 983-7555
611★Stone David L © 982-4832
612 Valdez Elena E [9]+ © 982-9344
612a Gallegos Jose J & Tony [2]
613★Manchezo Edw J 986-8909
614 ALARID'S PLASTERING plastering 982-0293
Alarid Tony & Connie G [5] © 982-0293
Alarid Tina L 982-0293
615 Blea Sarita [9]+ © 983-9148
618 Moore Garland & Jean C [9]+ © 983-3979
629 Aranda Raymond R & Raquel N [9]+ © 983-7283
35 HOUSEHOLDS
1 BUSINESS

1988 5TH ST

SOURCE: POLKS

6TH BEGINS
1500 Apartments
1 Youth Network adolescent counseling agency 982-4704
2 Youth Network (Overflow)
3 Youth Network (Overflow)
4 Vacant
5 Milewski John V conslt 988-1819
6 Vacant
8 Vacant
9 Hickey Calico B chiropractor 984-0972
10 Con Carino Hair Salon beauty shops 989-8480
11 Albuquerque Door Co 984-3053
12 Vacant
13 Moore J Michael acupuncture 982-2138
14★Barela Patk
16 Dictograph Security Alarm Systems sls & installation 984-8400
1501 Audio Visions retail auto electronics 988-3850
1 1505 Nava Ralph B P C acct 982-2149
1511 A A A American Automobile Assn 982-4633
A A A Travel Agency 982-4633
1513 Santa Fe Jewelers Supply 988-9157
1515 Southwest Building Maintenance & Supply jan sup 982-4856
1517 Harris Eliz L 983-8688
1519 Vacant
1520 Ben's Automotive Services antique cars 983-1031
1521 Acoma Optical Industries 988-5321
1524★Geister Scott 983-5861
1525 Vacant
1526 Gonzales Casimiro © 983-7950
1527 Holmes Electric 982-0256
1530 Romero Tony S © 983-8303
1535a Mc Pherson K 988-7162
1535b★Reiss E 986-0645
QUAPAW INTERSECTS
1605★Benavidez Joe A 983-7494
1607★Martinez Sam R © 988-1367
1609★Montoya Marjie
HOPEWELL INTERSECTS
1713 Vela Joe 983-4137
Apartments
1★Gonzales Joe
2★Garden Al
3 Vacant
4★Barrera Lee
1714 Romero Ignacio J © 983-9483
1715 Martinez Raymond G © 982-8013
MANN INTERSECTS
1804★Black Jos H © 983-1478
1804½ Gravel Greg woodwkr
1828 Gutierrez Frances 982-3116
1 1830 Dona Elena's Mexican Kitchen restr 983-9941
ST MICHAELS DR INTERSECTS
1911 Building
Suites

5TH ST–Contd

101 U S Dept Health-Human Serv Social Security Admn 988-6451
102 Dataflo System mtr vehicle data 471-2572
U S Dept Of Agriculture (Soil Conservation) 471-9160
203 Amptelco long distance phone serv 471-4099
Real Estate Schools Of Santa Fe 473-1958
205 State Health & Environment 473-3473
207 Dept Of Agrl (Soil Conservation Serv Design Ofc) 988-6605
208 U S D A Soil Conservation Serv 471-7607
209 C A R M Corporation computer & mgmt consits 473-7831
210 City Different Insurance Agency 473-2117
211 U S Dept Of Agrl Stabilization Serv) 988-6253

13

ZIP CODE 87501
2067 Martinez Katie 473-1714
WARNER AV DEAD ENDS
CALLE PERDIZ ENDS
2074★Martinez Jeff
2075 Ortizy-Pino Paul © 473-3054
2076 Baca Edward B © 473-4334
2080 Baros Augustin B Jr © 471-8748
2081 Brown Sidney S © 471-3768
2082 Elmore Jim © 471-2314
2084 Dwyer Robert E © 471-4483
2086 Pigeon Express small pkg courier & air cargo 473-3447
Odell Richd B © 473-1449
2087 Ramirez Robert A © 471-7894
2088 Whitmore Gary © 471-8641
2089 Narvaiz Larry 471-7695
2090 Smith Daniel 471-8183
2091 Serna Robert F © 471-7636
2092 Garcia C L 471-8211
2093 Alejandro John © 471-8048
2094 Ortiz Patk © 471-8214
2095 Segura Gilbert 471-7753
2096 Durr Edwin E © 471-8150
2097★Sandoval Aurelio
2098 Downes Ann 473-3085
SIRINGO RD INTERSECTS

31

6TH ST –FROM 1500 5TH WEST AND SOUTH TO ST MICHAELS DR

ZIP CODE 87501
BERRY INTERSECTS
1500 Klubandy Tim Sculptor 984-2829
1505 Mini-Warehouses storage units
Al's Plumbing & Heating 988-1852
HOPEWELL INTERSECTS

ST MICHAELS DR-Contd

565 Northern New Mexico Podiatric Medical Assn 983-7393
Wilner Ronald J phys 983-7393
Wilner Joel phys 983-7393
575 Placita Medical Bldg
Scandinavian Health Care Clinic 982-9921
PACHECO ST INTERSECTS
711 Shell Service Station 983-1517
715 Payne's Nurseries & Greenhouses Inc 988-9626
720J Santa Fe Schwinn Cyclery 471-3394
725 No Return
770 United New Mexico Bank At Santa Fe 471-1414
800 Navarro Olds & Cadillac Inc 471-6600
805 New Mexico Federal Savings & Loan Assn 983-4312
Daniels Insurance Inc 982-4302
809 Xerox Corporation duplicating machs & sup 982-3517
Bank Of Santa Fe The 984-0500
810 Vacant
811 Visiting Nurse Service Inc 984-2571
Gibbs Steven dentist 983-1312
Bentley Bookkeeping Inc 982-1394
Travel Connection The 982-4437
813 A B Q Bank 988-9701
850 Checker Auto Parts 473-0400
851 Candyman The sound sys & equip 988-9309
Desert Rose Fashion Boutique clo ret 984-2720
Camera Shop The 982-4655
Mc Millan Gallery & Woodworks Ltd art 983-5007
854 Paul's Transmission Specialist 471-2095
858 Union Bus Depot 471-0008
901 Salvage Company The whse 988-9100

31

PINON DR INTERSECTS
1234 Sunwest Bank 471-1234
1447 Century 21 Evans Real Estate 982-3522 Building
ROOMS
1 Vacant
1500 Sauter Lincoln-Mercury-Toyota 982-1901
1601 Vacant
1602 First Interstate Bank
1604 F I B (Day & Night Auto Teller)
1605 Shockey's Speed Queen 983-9960
1606 Imperial Beauty & Barber Prods sup 473-9898
1607 Velvet Cushion Billiards 982-9056
1608 Frontier Frames picture frames 473-1901
1609 Vacant
1610 Vacant
1611 House Of Movies video rentals 984-8464
1612 U S Air Force Recruting Station govt ofc 473-4949
U S Marine Corp Recruting Station govt ofc 471-1448
U S Army Recruiting Sta govt ofc 471-7821
U S Navy Recruiting Station govt ofc 988-6289
1620 Godfather's Pizza 471-8341
1624 Flowers By Flor Al 471-3395
1626 Pet Pourri (Addl Sp)
1628 Pet Pourri 471-9040
1632 Rob & Charlie's Inc bicycle shop & restr 471-9119
1634 Rob & Charlies Inc overflow 471-9119
1638 National Phone Center 473-5723
1640 Hardee's Restaurant 471-7794
1644 A T & T Business Tel Equip & Repr Service tel equip & repr serv 473-1636
1650 Fox Photo 471-2246
1698 Saint Michael's Village Exxon Service Station gas sta 471-9061
Capital Theatre The 471-8935
1700 Graham's Chevron gas sta 471-8049
1701 Chrysler-Plymouth-Dodge Of Santa Fe 982-1956
1711 Santa Fe Lock & Key retail locksmiths 471-2060
1712 K-Mart No 3301 471-9007
1714 Gordon Jewelers 471-7665
1716 Revco Discount Drug Center 471-7870
1718 Carrow's Restaurant 471-7856
1722a Kachina Kitchen restr 471-6172
1722d Music Shop The 471-2833
1722e Thrifty Nickel Want Ads 473-4111
1722f Video Square rental 473-0990
1722g Village Hair Design beauty shop 473-4844
1722h Santa Fe Trail Coins & Currency 292-1989
1751 Safeway Stores Inc 471-8673
1791 A B Q Bank 473-3144
1790 Century Federal Savings & Loan Assn 471-6666
1851 Green Onion Drive-Up Liquor 983-5198
Green Onion Restr 983-5198
1881 Charter Bank For Savings F S B 982-2534
1899 S F Car Company (JEEP) retail auto 984-0024
1901 Liquid Company The cocktail lounge 983-9935
1905 Sherwin-Williams Decorating Center paint 982-3559
1907 Northern New Mexico Computers Inc 983-4644
1907e Vacant
1907g Laino-Ludwig Inc adv 984-0747
1907h Vacant
1907m Vogue College For Cosmetology (Addl Classrm)
1911a Vacant
New Method Cleaners 982-0271
1911b Vacant
1911d Garson's Catholic Religious Articles 983-2233
1911e Santa Fe Vogue (Overflow)
1911f Santa Fe Vogue (Overflow)
1911g Santa Fe Vogue College Of Cosmetology 983-7322
1955 Ken John's Auto Mart (Addl Sp) autos retail
ESPINACITAS ST ENDS
2000 Seven To Eleven Drive-In Food Stores Inc No 6 471-9810
Wine Wall The liquor store 471-1146
2001 Cedarwood Small Animal Clinic 982-4469
Family Chiropractic Center Of Santa Fe 984-0006

ST MICHAELS DR-Contd

2004 Blake's Lota Burger No 41 471-8694
2005 John's Ken Santa Fe Nissan 983-7337
2008 Parks Nursery 471-8499
cor College Of Santa Fe 473-6011

39

SALAZAR PL -FROM 1300 LOPEZ SOUTH TO AGUA FRIA

ZIP CODE 87501
400★Richard Robt 989-8574
402 Salazar Alex © 983-7478
404 Sena Phillip A © 988-2417
405★Plattner Sarah © 988-5873
406 Sandoval Paula L Mrs © 827-3700
407 Roxanne's Home Cooking & Baking 982-4866
Piersol Stephen P 982-4866
408★Ahrendsen David CPA © 982-6856
409 Aguirre Jack M © 983-3829
410 Sanchez Emilio A © 982-5230
411 Ueda Eiji
412 Wheeler John F © 983-5768
413 Roybal Gloria A Mrs © 983-2845
414 Romero Manuela A Mrs © 982-0566
415 Roybal Mary D 988-4332
416 Brennan Jan 983-2773
418 Leyba Clyde A ©
419 Howland Construction Co 982-5453
Howland Jos © 982-5453
420 Trujillo Anna M Mrs © 982-8487

11

SALAZAR ST -FROM 1130 AGUA FRIA SOUTH TO CAMINO SIERRA VISTA

ZIP CODE 87501
501 Armijo Benny © 982-3450
502 Montoya Servana D Mrs © 983-3552
504★Miranda John © 982-3986
505 Lyon Dilman S © 983-3763
510 Escudero Jim A ©
513 Olonia Joe D © 983-8882
514★Chipman Jos © 988-3447
516 Sanchez Larry 982-2989
517 Linquist Susanne J © 984-0398
521★Mendoza J R © 986-1714
525★Sattley Linda 984-8155
526 Smith David © 988-5772
533 Fresquez Sam C © 983-4856
534 Sandoval Donocia
535 De Vargas Jay 988-3116
537 Bowles Delfina G Mrs © 983-7883
538 Vacant
541 Krueger Victoria © 988-7500
542 Moya Ramon L © 983-6431
544 Mascarenas Salomon © 982-8333
HICKOX INTERSECTS
601 Vacant
602 C De Baca Pina © 983-3488
603 Garcia Arth F © 982-3237
604 Giron Joe E © 982-8057
605★Martinez Michl R
606 Lawrence Edw © 988-2374
607 Apodaca C © 988-9660
610 Perez Isabelle Mrs © 983-7555
611 Miller Jennifer 983-6499
612 Valdez Elena E Mrs © 982-9344
612a Gallegos Jas J © 983-4896
613 Manchego D J © 983-5822
614 Alarid's Plastering contractor 982-8276
Alarid Tony © 982-0293
615 Blea Sarita Mrs © 983-9148
618 Moore Garland © 983-3979
629 Science Center Inc med equip mfg 988-7562
Aranda Raymond R © 983-7263

25

SAM ST (TORREON ADDN)-FROM 1600 W ALAMEDA NORTH

ZIP CODE 87501
102 Twitty David L
103★Knuffke Mary J 989-9514
105 Martinez Dan S © 982-0077
106 Malczewski John © 988-3744
107 Garcia Gerald © 982-3704
109 Roberts Adrian
111 Tapia Phil S © 983-1811
112 Duran Casilda Mrs © 982-0222
113 Tapia Jose G © 982-2065
114 Trujillo Tilly M ©
115 Montoya Clara Mrs © 983-8157
116 Martinez Martin ©
118★Montoya Gloria J
119 G M B Construction 982-2840
Barela Geo © 982-2840
120 Carrillo Charles D © 988-4504
121 Mc Duff Gerald © 983-6825
122 Kleinbord Jan C © 983-4211
125 Martinez Dulcinea R © 988-3846
125½ Martinez Florian A
129★Albert Norman J 983-7672
131 Buonaiuto Michl © 983-2163
202 Morris Phyllis J © 982-0513

6

SAN ANTONIO ST -FROM 700 ACEQUIA MADRE SOUTH

ZIP CODE 87501
403 Vacant
404 Broh-Kahn Eleanor Mrs © 982-4098
407 Gershen Sheila 988-3143
409 No Return
411 Ortiz Anna G Mrs © 983-3645
417 Craver David 982-8610
424★La Berge Suzan R © 989-8991
426 Cross Norma © 988-5947
427 Stanford David 988-1855
S OSAYA BEGINS
428★Cross D © 988-3625
433 Vacant
435 Ireland Thos S 988-1337

4TH ST—Contd
1410 Wine Press The wine wholesalers 988-9129
1411 Anaya's Joe Front End Shop 983-5777
1412 Wine Press The (Overflow)
1414 Postal Instant Press 982-8250
1501 Sandoval Manuel E ◎
1503 Cordova Mike J ◎ 982-3750
1505 Gembreska John R 982-6724
1507 Montoya Larry J
1507½ Chavez Juliana 988-5828
1509 Smith Frank N ◎ 982-0041
1519 Atwell Thos T genl contr
JAY ENDS
1602 Sena Fidel ◎ 983-8253
1608 Valdez Henry M 983-1123
1612★Hoffman Leon W 984-1781
Rear Collins David H 982-0009
1620 Ortega Michael
QUAPAW INTERSECTS

31

5TH ST —FROM 1802 CERRILLOS RD SOUTH TO SIRINGO RD

ZIP CODE 87501
6TH BEGINS
1500 Sunset Apartments 988-8931
1 Strait Marta B
2 Trujillo Rita M
3★Quintana Margaret 982-3179
4★Armendares Victor
5★Roberts Elizabeth 983-5784
6 Vacant
7 Romero Ed
8 Orozo Rudy
9 Lopez Paul
10 Nieto Bernie
11★Jimenez Ray
12 Lopez Larry
13★Sussillo Vicki
14★Garduno Alfred
15 Rodriguez Anna
16 Monroe Pete
1501 Henry's Top Shop auto seat covers 982-5896
Henry's Tees & Transfers t-shirts 982-5896
1503★Nava Ralph B
1505 Under Constn
1511 A A A American Automobile Assn 982-4633
1513 Piper & Piper Inc furn 988-9127
1520 Ben's Automotive Services antique cars 983-1031
1521 Acoma Optical Industries 988-5321
1524 Padilla A Dolores ◎ 983-8594
1525 Montoya Horace ◎ 982-4141
1526 Gonzales Casimiro ◎ 983-7950
1527 Valdez Plumbing & Heating 983-1123
Holmes Electric contr elec 982-0256
1530 Romero Tony S ◎ 983-8303
1535 Vacant
QUAPAW INTERSECTS
1605 Benavidez Joe A ◎ 983-7494
1607 Gonzales Joe A ◎
1609 Romero John W
HOPEWELL INTERSECTS
1713★Vela Joe ◎ 983-4137
Apartments
1 Hennigan Heather C
2★Arroyo Nicolas
3★Varela Cecelia M
4★Cattany Liz
1714 Romero Ignacio J ◎ 983-9483
1715 Martinez Raymond G ◎ 982-8013
MANN INTERSECTS
1804 No Return
1828 Gutierrez Frances 982-3116
1830 Dona Elena's Mexican Kitchen restr 983-9941
1911 State Farm Insurance 471-7942
Social Security Administration 988-6451
New Mexico Right To Work 471-6810
Agriculture Stabilization And Conservation Service 988-6253
Le Master Sylvia & Associates real est agcy 471-6556
Dept Of Agriculture (Soil Conservation Serv) 471-9160
State Health & Environment Dept 984-0020
Mascarenas Insurance Agcy Inc 471-1883
Santa Fe Adv & Mktg 471-8876
City Different Ins Agency 473-2117

139

ZIP CODE 87501
2067 Silva Kathy
WARNER AV DEAD ENDS
CALLE PERDIZ ENDS
2074 Durr Harold W Jr ◎ 471-8878
2075 Montoya Joe ◎ 471-7972
2076 Baca Edward B ◎ 471-8419
2080 Baros Augustin B Jr ◎ 471-8748
2081★Brown Sidney
2082 Elmore Jim ◎ 471-8685
2084 Dwyer Robert E ◎ 471-4493
2086★Odell Richd B
2087 Ramirez Robert A ◎ 471-7894
2088 Whitmore Gary 471-8641
2089 Narvaiz Larry ◎ 471-7695
2090 Mike King P Jr ◎ 471-8163
2091 Serna Robert F ◎ 471-7636
2092 Garcia Pat
2093 No Return
2094 Ortiz Patk ◎ 471-8214
2095★Caraven C
2096 Durr Edwin E 471-8150
2097 Sandoval Aurelia ◎
2098★Willhoite Steven B
SIRINGO RD INTERSECTS

221

ST MICHAELS DR—Contd
715 Payne's Nursery & Greenhouse 988-9626
725 State Office Bldg
State Health & Environmental Dept 984-0060
Environmental Improvement Div 984-0020
Environmental Improvement Div (Food Quality Div) 984-0020
770 American National Bank Of Santa Fe 471-1414
800 Durham Cadillac & Olds Inc 471-6600
805 New Mexico Federal Savings & Loan Assn 988-8011
Daniels Insurance Inc 982-4302
809 Xerox Corporation 982-3517
Bank Of Santa Fe The 983-3374
New Mexico Health & Environment Dept 984-0060
811 K S A F Television television sta 982-1800
Dunmar & Associates real est brokers 982-4393
New Mexico Tax Revenue Dept Dist 1 827-8330
I B M Corporation 988-7645
Travel Connection The travel agcy 982-4437
Interstate West Realty real est broker 984-0656
State Health & Environment Agcy residential treatment servs 984-0020
813 Albuquerque Federal Savings & Loan Assn 988-9701
850 Checker Auto Parts auto parts 473-0400
854 Paul's Transmission Specialist 471-2095
901 Bag N Save whse 988-9100

31

PINON DR INTERSECTS
1203 Hadley J H Oil Station 471-8193
1234 Sunwest Bank The 471-1234
1447 Evans Real Estate 982-3522
BLDG
ROOMS
1 New Mexico Parole Board 827-2103
1451 New Mexico Juvenile Bd 827-5631
2 Mental Health Bureau (Human Resource Dev Program)
3 New Mexico Parole Bd (Ofcs)
STREET CONTINUED
1500 Sauter Lincoln-Mercury-Toyota 982-1901
1601 Health Spa & Racquet Club 988-4446
Fitness Shop The health food store-dancewear 983-5409
Tony's Pizzeria 983-9341
Santa Fe Martial Arts Academy 984-0002
1604 Village Hairmasters styling salon 471-7983
1605 Shockey's Speed Queen 983-9960
1606 Flowers By Flor Al florist 471-3395
1607 Velvet Cushion Billiards 982-9056
1608 Computers Plus retail computers 471-3384
Mountain Bell 982-4104
1609 Southwestern Stationers 982-4366
1610 Moore's Men's Wear mens store 471-6367
1611 Music Villa Inc instruments 982-8561
1612 U S A F Recruiting Sta 988-6250
U S M C Recruiting Sta 988-6304
U S Army Recruiting Sta 471-7821
U S N Recruiting Sta 988-6289
1614 Uslife Credit Corp finance 471-8479
1620 Godfather's Pizza 471-8341
1624 Vacant
1626 Specialty Cake Shoppe bakery 471-8718
1628 Pete's Pets pet shop 471-9040
1632 Music 'n More 471-6767
1634 Heirloom Brass Beds 471-6692
1640 Hardee Charbroil Burgers 471-7794
1644 Mountain Bell serv center 982-4104
1650 Fox Photo 471-2246
Capital Theatre The 471-8935
1700 Graham's Chevron gas sta 471-8049
1701 Garcia's Julian Plaza Mtrs auto dlrs 982-1956
1704 Saint Michl's Village serv station 471-9061
1708 No Return
1712 K-Mart No 3301 471-9007
1714 Gordon Jewelers 471-7665
1716 Revco Discount Drug Center 471-7870
1718 Carrow's Restaurant 471-7856
1751 Safeway Stores Inc 471-8673
1790 Century Federal Savings & Loan Assn 471-6666
1851 Green Onion Drive-In liquor & wines retail 983-5198
Green Onion Restr 983-5198
1881 Devargas Savings & Loan Bank 982-2534
Sanchez Alfonso G lwyr 982-3848
1899 Discount Vacuum & Sewing Center 983-4466
Waldo's Radio & T V radio & t v repr 982-5588
1900 Liquid Company The 983-9935
1905 Sherwin-Williams Decorating Center paint 982-3559
1907 Sleep-N-Aire Mattress Co genl bed sls 983-2202
1907e Wherritt Engineering Co mech engs 982-9718
1907g Lunchroom The restr 984-0151
1907h Lunchroom The (Overflow)
1907m Ortega Realty 984-1248
1911 Santa Fe Tire Inc 982-2552
1955 Souders Incorporated furn 983-4341
ESPINACITAS ST ENDS
2000 Speedway Drive-In Food Stores Inc No 6 471-9810
2001 Cedarwood Small Animal Clinic 982-4469

ST MICHAELS DR—Contd
Family Chiropractic Clinic Of Santa Fe 984-0006
2004 Blake's Lota Burger No 41 471-8694
2005 Auto Trading Post Inc 983-7337
2008 Parks Nursery 471-8499
cor College Of Santa Fe

39

SALAZAR PL —FROM 1300 LOPEZ SOUTH TO AGUA FRIA

ZIP CODE 87501
400 Sanchez Rita Mrs ◎
402 Salazar Alex ◎ 983-7478
404 Sena Phillip A ◎ 988-2417
405 Beddow G R ◎ 983-3074
406 Sandoval Paula L Mrs ◎
407 Kalivoda Grant 983-5373
408 Mulders Peter
409★Aguirre Jack M 983-3829
410 Sanchez Emilio A ◎ 982-5230
411 Rancich Lisa 983-7138
412 Wheeler John ◎ 983-5768
413 Roybal Gloria A Mrs ◎ 983-2845
414 Romero Manuela A Mrs ◎ 982-0566
415 No Return
416★Williams Mike
418 Leyba Clyde A ◎
419 Russell John
420 Trujillo Anna M Mrs ◎ 982-8487

11

SALAZAR ST —FROM 1130 AGUA FRIA SOUTH TO CAMINO SIERRA VISTA

ZIP CODE 87501
501 Benny's Body Shop auto paint-body repair 983-2828
Armijo Benny ◎ 983-2828
502 Montoya Servana Mrs ◎ 983-3552
504 Wright Irene G Mrs ◎ 983-3901
505 Lyon Dilman S ◎ 983-3763
510 Escudero Jim A
513 Olonia Joe D ◎ 983-8882
514 Baca Florence Mrs ◎ 982-4845
516 Sandoval Stella
517 Bewley Lois ◎ 988-5237
525 Larson
526 Smith David ◎ 988-5772
533 Fresquez Sam C ◎ 983-4856
534 Vacant
535★De Vargas Tina
537 Bowles Baudilio ◎ 983-7883
538 Vacant
541 Bolls Desmond V ◎ 983-8804
542 Moya Ramon L ◎ 983-6431
544 Mascarenas Salomon ◎ 982-8333
HICKOX INTERSECTS
601 Garcia Escolastica Mrs ◎ 983-6773
602 C De Baca Pina ◎ 983-3488
603 Garcia Arth F ◎ 982-3237
604 Giron Joe E ◎ 982-8057
605★Luty Michl 982-6202
606 Lawrence Edw ◎ 988-2374
607 Perez Richd 983-1985
610 Perez Vincent ◎ 983-7555
611★Applegate Nancy K 983-6073
612 Valdez Roman ◎ 982-9344
612a Gallegos Jose J ◎ 983-4896
613 Manchego Domingo ◎ 983-5822
614 Alarid Tony ◎ 982-0293
615 Blea Sarita Mrs ◎ 983-9148
618 Moore Garland ◎ 983-3979
629 Aranda Raymond R ◎ 983-7263

25

SAM ST (TORREON ADDN)—FROM 1600 W ALAMEDA NORTH TO A DEAD END

ZIP CODE 87501
102 Boddy Mattie J Mrs ◎ 933-3470
103★Jose Byrdian ◎ 983-8040
105 Martinez Dan S ◎ 982-0077
106 Vacant
107 Garcia Gerald 982-3704
109 Spinale Vito 982-5353
111 Tapia Phil 983-1811
112 Duran Casilda Mrs ◎ 982-0222
113 Hurtado Margarita Mrs ◎ 982-2065
114 Trujillo Tillie Mrs ◎
115 Montoya Clara Mrs ◎ 983-8157
116 Martinez Martin F ◎
118 Sandoval Emmy
119 Barela Geo bldg contr ◎ 982-2840
120 Carrillo Charles D ◎
121 Mc Duff Delia Mrs ◎ 983-6825
122 Vacant
125 Martinez Florian ◎ 988-3846
129 Garcia Jose ◎ 983-5479
131 Garcia Sofia H Mrs ◎ 983-7663
202 Morris Phyllis J ◎ 982-0513

6

SAN ANTONIO ST —FROM 700 ACEQUIA MADRE SOUTH TO A DEAD END

ZIP CODE 87501
403 Vacant
404 Broh-Kahn Eleanor Mrs 982-4098
407 Carrillo James
411 Ortiz Anna G Mrs ◎ 983-3645
417 Garcia Elisa Mrs ◎ 983-3446
424 Croce Margt Mrs ◎ 982-2849
426 Cross Norma ◎ 988-5947
427 Price Geraldine ◎ 983-5573
S OSAYA BEGINS
428 Hammond Ralph E ◎ 983-4809
433 Powers Marcella Mrs ◎
435 Branham Mary 982-9531
501 Mc Nally J Jerome 982-8571
505 Olivas Luis ◎ 983-3543
511 Sumner Phoebe ◎ 983-5679
554 Dawson Darrell ◎ 982-3241

5TH ST—Contd
3 Vacant
4 Kieley Walter A 988-5984
5 Roberts E 983-5784
6 Berry Elaine A Mrs
7 Crespin Wm E 983-6748
8 Newton Linda 988-5893
9 Baca Cath
10 Gonzales Tommy
11 Martinez Cecelia Mrs 983-9267
12 Lopez Larry
13 Gonzales Gilbert
14 Pedro Vincente
15 Vacant
16 Lestory Jas
1501 Henry's Top Shop auto seat covers 982-5896
Henry's Teed & Transfers
1520 Ben's Auto Shop antique cars 983-1031
1524 Padilla Rafaelita ◎ 983-8594
1525 Montoya Horacio ◎ 982-4141
1526 Gonzales Casimiro ◎ 983-7950
1527 Vacant
1530 Romero Tony bldg contr ◎ 983-8303
1535★Lambert Joseph J 983-9605
QUAPAW INTERSECTS
1605 Benavidez Joe A ◎ 983-7494
1607★Gonzales Joe A ◎
1609 Romero John W 983-4510
HOPEWELL INTERSECTS
1713 Lucero Louis ◎ 982-5703
Garcia Arthur
1714 Romero I J ◎ 983-9483
1715 Martinez Raymond G ◎ 982-8013
MANN INTERSECTS
1804 Mary's Beauty Salon 983-7411
Catanach Jesse L ◎ 983-7411
1828 Vacant
1830 El Taco Drive In restr 983-9941

31

6TH ST —FROM 1500 5TH WEST AND SOUTH TO ST MICHAELS DR

ZIP CODE 87501
BERRY INTERSECTS
1549 Stamm Development Co real est 983-5172
Matthews L C investment 982-3291
HOPEWELL INTERSECTS
1550 Mountain View Trailer Village 983-4262
Lots
A Tilseth Henry
1 Doles J B 982-5604
2★Weaver R C
3 Vacant
3 Vacant
3a Vacant
7 Vacant
8★Sander Delbert
11a Martinez Chencha 982-1274
12 Vacant
14 Vacant
15 Vacant
16 Vacant
17 Pena Gabino C
28★Taylor Wm
29★Sena Rose
31 Fernandez Rudy
32 Maestas
33★Covarrubias Gabriel
34★Valdez Ricky
36 Archuleta
37 Joly Paul
38 Couchman Frey 982-9447
39 Vacant
40★Kamoroff Jan
41 Doty Jan
42 Vacant
43 Padilla Amos
44★Thompson
45 Vacant (Lots 45-49)
50★Hubert Joann
52 Segura Natalie Mrs 983-2266
53 Martinez Joe 983-1780
54★Ortega Toni
55★Swaigert David
56 Gonzales Bernadette
57 Valdez Rudy 983-6514
58 Tobias Curtis J 982-2827
59 Vacant
60 Moore Celine 983-9453
61★Galaway Beth
62★Brown Vincent
63 Gomez E Eloy 988-1598
64★Martinez Mariann
65★Vissorigas Rebecca
66 Vacant
67★Chapman Lee
68 Vacant
69 Schultz Linda A
70★Padilla Grace
71 Adams Jonna
72★Sullivan Anita
73★Strong Pat
74 Steward Mary
75 Mc Gregor Robt 982-2157
76★Rowl Dennis
77★Sena Albert J
78★Rivera Martin
79★Paguin Sylvester
80★Cruz Estella
81★Jarmillo Mike
82 Carter Clyde C 983-1106
83★Otero Barbara
84★Martinez Fred
85★Martinez Francisicus
86★Weis Bob
87★Corpam Marsh
88★Sena Rosa
89 Trujillo Jose P 983-5832
90★Lievens Maryann
91★Morales Eloy
92★Martinez Mike
93★Quinlin Joseph
94★Esquibel Ernest

ST MICHAELS DR—Contd
555 Four Seasons Nursing Center 982-2574
565 Wilner Ronald J phys 983-7393
Northern N M Podiatry Assoc P A
575 Placita Medica Bldg
Harris Payne S phys 982-4457
Placita Medical ret druggists 983-5323
Ron's Pharmacy 983-5323
Zia Real Estate & Investments Inc 982-5526
Groves Robt A phys
H & J Inc General Contracting 982-8549
STREET CONTINUED
PACHECO ST INTERSECTS
711 Shell Service Station 983-1517
715 Payne's On St Michaels Dr nurseymen 983-6522
725 State Office Bldg B-2430
State Department Of Health & Social Serv 827-3201
State Health Agency 827-5271
State Dept Hlth & Social Servs (Food Quality Div) 827-2431
State Health Dept (Child Support Enforcemtnt Div) 827-5355
St Dept Of Hlth & Social Serv (Vector Cntrl Prog) 827-5271
State Hlth Agcy (Air Mgmt Div) 827-5271
State Dept Of Hlth & Social Serv (Milk Program) 827-5271
Dept Of Hlth & Social Serv (Engineering Ofc) 827-5271
State Hlth Agcy (Program Development Planning) 827-5271
State Health Agency (Air Quality Div) 827-5211
State Health Agency (Legal Ofc) 827-5271
State Hlth Agcy (Enforcement Section) 827-5271
State Hlth Agcy (Monitoring & Surveillance Sec) 827-5211
State Hlth Agcy (Special Projects Section) 827-5271
State Health Agency (Constn Grants Program) 827-5271
State Hlth Agcy (Planning Standards & Reg Dev) 827-5271
State Health Agency (Staff Serv Support Ofc) 827-3201
Dept Hlth Agcy (Occupational Hlth Safety) radiation protection div 827-5271
State Health Agency (Food & Institutional Div) 827-5271
State Health Agency (Meteorology Section) 827-5271
State Health Agency (Dept Of Environ Hlth) 827-5271
State Health Agency (Water Quality Div) 827-5271
State Health Agency (Water Supply Program) 827-5271
State Health Agency (Solid Waste Program) 827-5271
797 State Of Santa Fe
800 Durham Cadillac & Olds Inc 988-5566
805 First Northern Savings 988-8011
Daniels Insurance Inc 982-4302
811 Dunmar Real Estate 982-4393
I B M Corporation 988-4411
901 Gibson Discount Center 988-3552

31

PINON DR INTERSECTS
1203 Hadley J H Oil Station 471-4692
1234 Capital Bank The 982-4431
1447 Evans Real Est 982-3522
1451 New Mexico Security Finance 988-2824
BLDG
ROOMS
3 Zlotnick James & Co acct 982-3894
5 New Mexico Parole Board 827-2103
N M Juvenile Bd
STREET CONTINUED
1500 Sauter Lincoln-Mercury-Toyota 982-1901
1601 Health & Beauty Spa 988-4446
Vita Bin health food store-dancewear 982-8818
Trade-A-Tape 988-5001
Tony's Pizzeria
1605 Shockey's Speed Queen 983-9960
1607 Velvet Cushion Billiards 982-9056
1609 Southwestern Stationers 982-4366
1610 Moore's mens store 983-6223
1611 Music Villa Inc instruments 982-8561
1612 U S A F Recruiting Sta 988-6250
U S M Recruiting Sta 988-6304
U S Army Recruiting Sta 982-3574
U S N Recruiting Sta 988-6289
1614 U S Life Credit
Capital Theatre
1700 Carl's Chevron gas sta 982-9364
1701 Plaza Motors Inc 982-1956
1704 Saint Michael's Gulf (Horn Oil) 983-9946
1712 K-Mart No 3301 988-8061
1714 Gordon Jewelers
1716 G C Super Drugs 982-4319
1718 Carrow's Restaurants Inc 982-3980
1751 Safeway Number 935
1790 Mutual Building & Loan Assn Of Santa Fe The truman johnson v-pres & br mgr 982-4629
1851 Green Onion Drive-In liquor & wines retail 983-5198
Green Onion Restaurant 983-5198
1881 De Vargas Savings & Loan Asan 982-2534
1899 Phil's Home Cntr telev appl 982-5588
1900 Zodiac Lounge
1905 Sherwin-Williams Decorating Center paint 982-5162
1911 Santa Fe Tire & Supply Co Inc 982-2552

177

ST MICHAELS DR—Contd
1955 Souders Incorporated furn 983-4341
ESPINACITAS ST ENDS
2000 Speedway Drive-In Food Stores No 6 gro 983-9826
2001 Cedarwood Small Animal Clinic 982-4469
2004 Blake's Lota Burger No 41
2005 Auto Trading Post Inc 983-7337
2008 Parks Nursery 983-6722

39

SALAZAR PL —FROM 1300 LOPEZ SOUTH TO AGUA FRIA

ZIP CODE 87501
400 Sanchez Ray ◎
402 Salazar Alex ◎ 983-7478
404 Tapia Rudolph ◎
405 Beddo G Richd ◎ 983-3074
406 Sandoval Paula L Mrs ◎
407 Kalivoda Grant 983-5373
408★Roseberg Wm J 988-1695
409 Jack's Tailor Shop 983-3829
Aguirre Jack M ◎ 983-3829
410 Sanchez Emilio A ◎ 982-5230
411 Masters Paul W ◎ 983-4178
412 Wheeler John ◎ 983-5768
413★Roybal Richd S ◎ 983-2845
414 Romero Saint John C ◎ 982-0566
415 No Return
416 Romero Dora Mrs ◎ 982-1063
418 Leyba Clyde A ◎ 983-2259
419 Howland Joseph 982-5453
420 Trujillo Anna M Mrs ◎ 982-8487
521★Larson Mary Mrs ◎
525★O'Connor Thos

11

SALAZAR ST —FROM 1130 AGUA FRIA SOUTH TO CAMINO SIERRA VISTA

ZIP CODE 87501
501 Benny's Body Shop 983-2828
Armijo Benny ◎ 983-2828
502 Montoya Servana Mrs ◎ 983-3552
505 Lyon Dilman S ◎ 983-3763
510 Escudero Jim A
513 Olonia Joe D ◎ 983-8882
514 Morgan Florence Mrs ◎ 988-4227
516★Fresquez Stella 982-2989
517 Bewley Hershel M ◎ 988-5237
521 No Return
525 Garcia Rose M 982-2870
526 Smith David ◎ 988-5772
533 Fresquez Sam C ◎ 983-4856
534 Lawrelin Bruce J 988-3541
535 Diloreto Jeanne 988-3460
537 Bowles Baudilio ◎ 983-7883
541 Leyba Marshall H ◎ 988-2327
542 Moya Ramon L ◎ 983-6431
544 Mascarenas Salomon ◎ 982-8333
HICKOX INTERSECTS
601 Garcia Escolastica Mrs ◎ 983-6773
602★De Baca Pina ◎ 983-3488
603 Garcia Arth F ◎ 982-3237
604 Giron Joe E ◎ 982-8057
605 Montoya Richd J ◎ 988-4098
606 Lawrence Edw ◎ 988-2374
607 Baca Rexie
610 Perez Vincent ◎ 983-7555
611 Carrillo Desi Jr 983-2280
612 Valdez Roman ◎ 982-9344
612a Gallegos Jose J ◎ 983-4896
613 Manchego Domingo ◎ 983-5822
614 Alarid Tony ◎ 982-8276
615 Blea Sarita Mrs ◎ 983-9148
618 Moore Garland ◎ 983-3979
629 Aranda Raymond R ◎ 983-7263

25

SAM ST (TORREON ADDN)—FROM 1600 W ALAMEDA NORTH TO A DEAD END

ZIP CODE 87501
102 Boddy Robt A ◎ 983-3470
103★Washington Jonah W 983-6163
105 Martinez Dan S ◎ 982-0077
106 Lucero Juan I ◎ 982-0485
107 Planeda Frank ◎
109 Tapia Timoteo ◎ 983-1382
111 Tapia Phil ◎ 983-1811
112 Duran Casilda Mrs ◎ 982-0222
113 Hurtado Margarita Mrs ◎ 982-2065
114 Trujillo Tillie Mrs ◎
115 Montoya Clara Mrs ◎ 983-8157
116 Martinez Martin F ◎
118 Naranjo Martha
119 Barela Geo bldg contr ◎ 982-2840
120★Carrillo Charlie
121 Mc Dufe Della ◎ 983-6825
122 Valencia Florentino Jr ◎ 983-8675
125 Martinez Florian ◎ 988-3846
131 Garcia Roman E ◎ 983-7663
202 Morris Phyllis J ◎ 982-0513

6

SAN ANTONIO ST —FROM 700 ACEQUIA MADRE SOUTH TO A DEAD END

ZIP CODE 87501
403 Radcliffe Keith A 983-7826
404 Brooks Beatrice A Mrs 982-4098
Brohn-Kahn Eleanor 982-4098
407 Vacant
411 Ortiz Anna G Mrs ◎ 983-3645
417 Garcia Elisa Mrs ◎ 983-3446
424 Croce Nello 982-2849
426 Thibbodeau Dick 983-4147
427 Price Geraldine ◎ 983-5573
S OSAYA BEGINS
428 Hammond Ralph E 983-4809
433 Powers Macella Mrs ◎
435 Branham Mary

3D ST—Contd
1729 Chavez Refugio C ◎ 983-3814

31

4TH ST —FROM 2400 CERRILLOS RD SOUTHEAST TO QUAPAW

ZIP CODE 87501
1411 Anaya's Joe Front End Shop 983-5777
1501 Sandoval Manuel
1503 Cordova Mike ◎ 982-3750
1505 ★ Dunn R B
1507 Fernandez Rudy 983-2118
1507½ Vacant
1509 Smith Frank N ◎ 982-0041
JAY ENDS
1602 Sena Fidel ◎ 983-8253
1608 Valdez Plumbing & Heating Co 983-1123
Valdez Henry M ◎ 982-8318
1612 ★ Carter Clyde C
Rear Vacant
1618 ★ Garduno Jerry
QUAPAW INTERSECTS

31

5TH ST —FROM 1802 CERRILLOS RD SOUTH TO ST MICHAELS DR

ZIP CODE 87501
6TH BEGINS
1501 Henry's Top Shop auto seat covers 982-5896
1502 Sunset Apartments 982-2525
1 ★ Carroll Steven
2 Vacant
3 Vacant
4 ★ Hart Jerome
5 Vacant
6 ★ Martinez Rudy
7 ★ Meek Ganda
8 Vacant
9 Vacant
10 ★ Balling Mary L
11 ★ Lucero Lonnie
12 ★ Berry Elaine
13 ★ Baker Curtis L
14 ★ Pelcher Dennis
15 ★ Maestas Lola R
16 ★ Wilkinson Yvonne
1520 Ben's Auto Shop antique cars 983-1031
1524 Padilla Rafaelita ◎ 983-8594
1525 Montoya Horacio ◎
1526 Gonzales Casimiro ◎ 983-7950
1527 ★ Gallegas Maria J ◎ 982-0400
1530 Romero Tony bldg contr ◎ 983-8303
★ Romero Patrick
1535 Rivera Clara Mrs 983-5244
1545 Allen Thos T bldg contr
QUAPAW INTERSECTS
1605 Benavidez Joe A ◎ 983-7494
1607 Garcia Lorenzita Mrs ◎ 982-0668
1609 ★ Romero Johnny
HOPEWELL INTERSECTS
1713 Lucero Louis ◎ 982-5703 Apartments
1 ★ Wright Leroy
2 ★ Oslona Milton
3 Martinez Horacio 982-3120
1714 Romero Ignacio J ◎ 983-9483
1715 Martinez Raymond G ◎ 982-8013
MANN INTERSECTS
1804 Mary's Beauty Salon 983-7411
Catanach Jesse L ◎ 983-7411
1828 Gutierrez Frances Mrs ◎ Vacant
1830 Vigil Juanita Mrs
El Taco Drive Inn restr 983-9941
1900 Vacant
2080 Under Constn (2080-2098)

S ST FRANCIS DR—Contd
W CORDOVA RD INTERSECTS
1105 County Welfare Dept 827-2376
ALTA VISTA INTERSECTS
1251 ★ Romero Eloy E 982-3263
COLUMBIA INTERSECTS
1305 ★ Sena Robt
1309 Aragon Ross ◎ 983-6261
1311 Aragon Benny 982-2888
1313 Carrillo Juan
1315 Vacant
1435a Tapia Manuel C tree serv ◎ 983-3457
1435b ★ Lucero Eddie ◎ 988-1546
1441 Montoya Virginia Mrs ◎ 983-7804
1443 Rodriguez Ruben 983-9744
1450 ★ Smith Kenneth D ◎ 982-4973
ANAYA BEGINS
1500 Stamm Nursing Home
1593 Johnson Service Co boat repr 983-8927
1595 Osborne Ernest Jr 982-3939
1597 Ringhand Norman
1599 ★ Gagalos Jose
CAMINO DE MONTE REY BEGINS
SAN MATEO DR INTERSECTS

115

1601 Saint Bede's Episcopal Church 982-1133
ST MICHAELS DR INTERSECTS

115

ST MICHAELS DR —FROM OLD PECOS TRAIL WEST TO 2000 CERRILLOS RD

ZIP CODE 87501
GALISTEO INTERSECTS
555 Four Seasons Nursing Home 982-2574
565 Wilner Ronald J phys 983-7393
575 Placita Medica Bldg
Harris Payne S phys 982-4457
Draggon Bob Pharmacy 983-5323
STREET CONTINUED
715 Payne's Nursery 983-6522
801 Crown Discount Store genl merch 982-2540
901 Gibson Discount Center 982-4311
Gibson's Pharmacy 983-4307

31

PINON DR INTERSECTS
1203 Hadley J H Oil Station serv sta
1234 Capital Bank The 982-4431
1451 Harvey's Bill Restaurant & Lounge 983-7463
1500 Sauter Lincoln-Mercury-Toyota 982-1901
1601 Los Banos Encantados Spa 982-8569
1607 Velvet Cushion Billiards 982-9056
1609 Southwestern Stationers 982-4366
1611 Music Villa Inc instruments 982-8561
1698 Under Constn
1700 Royal City Motors Inc 982-1956
1704 Under Constn
1790 Mutual Building & Loan Assn Of Santa Fe 982-4629
1851 Gaslight Lounge lounge 988-3136
1899 Good Housekeeping Shop telev appl 982-5588
1900 Town & Country Carpets 982-3585
1901 Under Constn
1911 Santa Fe Tire And Supply Co Inc 982-2552
1955 Souders Inc furn 983-4341
ESPINACITAS ST ENDS
2001 Cedarwood Clinic 982-4469

1968 5TH ST

SOURCE: HUDSPETHS

31

4TH ST -FROM 2400
CERRILLOS RD SOUTHEAST
TO QUAPAW

---ZIP CODE 87501
1501 SANDOVAL MANUEL ●
983-9533
1503 CORDOVA MIKE ●
982-3750
1505 REAL ROSE M MRS
982-0236
1507 GAGE JACK ● 982-7860
1507½ LAUGHLIN TRISHA MRS
982-1076
1509 SMITH FRANK N ●
982-0041
---JAY ENDS
1602 SENA FIDEL ●
983-8253
1608 VALDEZ HENRY M ●
982-8318
1612 GARDUNO ERNEST
REAR PATTERSON MARTIN L ●
1618 VIZARRAGA PROCOPIO
---QUAPAW INTERSECTS

31

5TH ST -FROM 1802
CERRILLOS RD SOUTH TO
ST MICHAELS DR

---ZIP CODE 87501
---6TH BEGINS
1520 HOFFMAN'S GREENHOUSE
983-6959
1524 PADILLA RAFAELITA
MRS ● 983-8594
1525 MONTOYA HORACIO ●
1526 GONZALES CASIMIRO ●
983-7950
1527 MONTOYA SAML D ●
982-0400
REAR GALLEGOS MARIA MRS
982-0400
1530 ROMERO TONY BLDG
CONTR ● 983-8303
1535 CORCORAN WM F
983-5189
---QUAPAW INTERSECTS
1605 BENAVIDEZ JOE A ●
983-7494
1607 GARCIA ROSENDO ●
982-0668
1609 LOVATO JOE E
982-9832
---HOPEWELL INTERSECTS
1713 LUCERO LOUIS ●
982-5703
APARTMENTS
1 NO RETURN
2 KING ERNEST
3 CHAPARRO ALBERT L
1714 ROMERO IGNACIO J ●
983-9483
1715 MARTINEZ RAYMOND G ●
982-8013
---MANN INTERSECTS
1804 MARY'S BEAUTY SALON
983-7411
CATANACH JESSE L ●
983-7411
1828 GUTIERREZ FRANCES
MRS ● 983-3215
ROMERO ELOY R
983-3271
1830 VIGIL JUANITA MRS
982-8835
TACO DRIVE IN RESTR

31

6TH ST -FROM 1500 5TH
WEST AND SOUTH TO ST
MICHAELS DR

---ZIP CODE 87501
---BERRY INTERSECTS
COR MEAD'S BAKERY
983-7502
1549 ACME REAL ESTATE CO
982-8022
MOUNTAIN VIEW
TRAILER SALES
982-8022
1550 MOUNTAIN VIEW
TRAILER VILLAGE
LEASING 983-4262
DOLES JENNINGS B
982-5604
GULLEY NORMA
983-6964
1551 MENS ORIAN
---QUAPAW ENDS
---HOPEWELL INTERSECTS
---MANN ENDS
1650 MOUNTAIN STATES
TELEPHONE CO (SHOP)

6

ABEYTA ST -FROM 774
ACEQUIA MADRE SOUTH TO
A DEAD END

---ZIP CODE 87501
404 NO RETURN
---CAMINO DEL PONIENTE
BEGINS

1968 ST MICHAELS DR

SOURCE: HUDSPETHS

15

ST MICHAELS DR -FROM OLD
PECOS TRAIL WEST TO
2000 CERRILLOS RD

---ZIP CODE 87501
---GALISTEO INTERSECTS
575 PLACITA MEDICAL BLDG
HARRIS PAYNE S PHYS
982-4457
SCHARF THEODORE J
PHYS 982-1054
SOLDOW FRED L PHYS
982-4457
---STREET CONTINUED

31

---PINON DR INTERSECTS
1451 CHANDLER'S
RESTAURANT 983-7463
GONZALES HENRY
1500 SAUTER LINCOLN
MERCURY & TOYOTA
982-1901
1601 SIERRA LANES BOWLING
983-6376
1605 SIERRA LOUNGE
983-6376
1609 SOUTHWESTERN
STATIONERS 982-4366
1851 BOTTLE & GLASS
LIQUORS 982-3601

39

SALAZAR PL -FROM 1300
LOPEZ SOUTH TO AGUA
FRIA

---ZIP CODE 87501
400 ARMIJO GREGORIO N
402 SALAZAR ALEX ●
983-7478
404 LEYBA LEE ● 982-9668
405 VILLA JOHN D ●
406 SANDOVAL DON ●
407 REDMAN LAWRENCE E ●
982-1280
408 SMYTH LON
409 JACK'S TAILOR SHOP
983-3829
AGUIRRE JACK M ●
983-3829
410 SANCHEZ EMILIO A ●
982-5230
411 MASTERS PAUL W ●
983-4178
412 WHEELER JOHN R ●
982-8467
413 LUCERO ARTH S ●
982-8058
414 ROMERO ST JOHN C ●
982-0566
415 SOMMERS IRVING E
982-9798
416 ROMERO HENRY ●
982-1063
418 KUHNS CHARLES ●
419 BRUNBERG EDNA MRS ●
420 TRUJILLO ANNA M MRS ●
982-8487

11

SALAZAR ST -FROM 1130
AGUA FRIA SOUTH TO
CAMINO SIERRA VISTA

---ZIP CODE 87501
501 GARCIA IGNACIO
REAR BENNY'S PAINT & BODY
SHOP AUTO 983-3622
502 MONTOYA EDWARDO S ●
983-3552
505 LYON DILMAN S ●
983-3763
510 WINSOR HENRY D ●
513 OLONIA JOE D ●
983-8882
514 CHAVEZ TONY G ●
983-4817
516 C DE BACA LOUIE
517 BASSETT CHARLES E ●
982-1315
521 DOST AMELIA G MRS ●
982-0583
525 HUFFAKER MAE R
982-5152
526 SMITH DAVID ●
533 FRESQUEZ SAM C ●
983-4856
534 MILLIGAN MAY ●
535 VACANT
537 BOWLES BAUDILIO ●
983-7883
541 LEYBA MARSHALL ●
983-7425
542 MOYA RAMON L ●
982-0124
544 MASCARENAS SALOMON ●
---HICKOX INTERSECTS
600 GARCIA CELESTINO T ●
983-6773
603 C DE BACA JIMMIE S ●
982-0592
604 SANDOVAL ERNEST ●
983-4230
607 GIRON JOE E ●
982-8057
609 GARCIA FRANK E
610 PEREZ VINCENT ●
983-7555

1964 5TH ST

SOURCE: HUDSPETHS

4TH ST--CONTD

1602 SENA FIDEL •
983-8253
1608 VALDEZ HENRY M •
982-8318
1612 JOHNSON FREDRICK R
982-5289
REAR PATTERSON MARTIN L •
1618 VISARRAGA PROCOPIO •
---QUAPAW INTERSECTS

17

5TH ST -FROM 1802 CERRILLOS RD SOUTH TO ST MICHAEL'S DR

---6TH BEGINS
1520 HOFFMAN'S GREENHOUSE
983-6959
1524 PADILLA RAFAELITA
MRS • 983-8594
1525 MONTOYA HORACIO •
983-4863
1526 GONZALES CASIMIRO •
982-7950
1527 MONTOYA SAML D •
982-0400
REAR GALLEGOS MANUEL JR
982-0400
1530 ROMERO TONY BLDG
CONTR • 983-8303
1535 QUINTANA ANSELMO
---QUAPAW INTERSECTS
1605 BENAVIDEZ JOE A •
983-7494
1607 GARCIA ROSENDO •
982-0668
1609 LOVATO JOE E
982-2834
---HOPEWELL INTERSECTS
1713 LUCERO LOUIS •
982-5703
1 WITT ROBT 982-8240
2 BAKER CARL
3 MILLER LEONARD G
1714 ROMERO IGNACIO J •
983-9483
1715 MARTINEZ RAYMOND G •
982-8013
---MANN INTERSECTS
1804 MARY'S BEAUTY SALON
983-7411
CATANACH JESSE L •
983-7411
1828 GUTIERREZ FRANCES
MRS • 983-3215
1828½ ROMERO ELOY R
983-3271
1830 VIGIL JUANITA MRS

17

6TH ST -FROM 1500 5TH WEST AND SOUTH TO ST MICHAELS DR

---BERRY INTERSECTS
AV MEAD'S BAKERY
983-7502
1550 ACME REAL ESTATE CO
982-8022
GARCIA SILAS AGENCY
REAL EST 982-5284
MOUNTAIN VIEW
TRAILER SALES
983-4262
MOUNTAIN VIEW
TRAILER VILLAGE
983-4262
TILSETH HENRY
983-4262
BOGGS L A LAND
EXCAVATION
COOPER KENNETH •
982-1392
1606 GALLEGOS JOE •
982-8803
---QUAPAW ENDS
---HOPEWELL INTERSECTS
---MANN ENDS
MANN MOUNTAIN STATES
TELEPHONE CO
(SHOP)

6

ABEYTA ST -FROM 774 ACEQUIA MADRE SOUTH TO A DEAD END

404 FROST FLOYD J •
982-8077
418 HARTLEY ROLAND E
422 GEISSLER ROSINA MRS
982-8658
424 HARTLEY LILLIAN MRS
983-3998
426 STEPHENS BLANCHE A
MRS 982-2210
428 APODACA BENNY J •
982-2419
430 GURULE ALFONSO •
982-2443
---CAMINO DEL PONTIENTE
BEGINS
500 VACANT
502 BLACKBURN VINT
503 RIOS RUDOLFO J •
982-8953
504 VACANT
508 LUCERO FLAVIANO •
509 GABALDON MAX •

1964 ST MICHAELS DR

SOURCE: HUDSPETHS

ROYBAL ST--CONTD

901 LUCERO AUGUSTINE •
983-8127
910 DURAN GUILLERMO •
983-4273
911 DURAN LORETO •
983-3253
912 CHAVEZ EDWINGEN M MRS
• 983-4154
920 VACANT
929 MARTINEZ FIDEL •
982-8305
930 VIGIL FLAVIO •
931 RIVERA RICHO •

25

SAINT FRANCIS DR NORTH -FROM 800 W ALAMEDA NORTH TO ROSARIO

---CAMINO DE LAS CRUCITAS
INTERSECTS

21

---ALAMO DR INTERSECTS
---ROSARIO INTERSECTS

7

SAINT FRANCIS DR SOUTH -FROM 800 W ALAMEDA SOUTH TO ST MICHAELS DR

---ALTO INTERSECTS
---ROYBAL INTERSECTS
---DUNLAP INTERSECTS
---AGUA FRIA INTERSECTS

9

---W MANHATTAN AV
INTERSECTS
---HICKOX INTERSECTS
---NINITA INTERSECTS
---CAMINO SIERRA VISTA
INTERSECTS
---MERCER INTERSECTS

13

---CERRILLOS RD
INTERSECTS
---PEN RD INTERSECTS
1004 SMITH VETERINARY
HOSPITAL • 983-4741
1090 SAFEWAY STORES INC
(BR) GRO 982-2040
1096 CARL'S PONTIAC-BUICK
-GMC-OPEL 982-8511

15

CORDOVA RD INTERSECTS
---ALTA VISTA INTERSECTS
---COLUMBIA INTERSECTS
1413 TILLIE'S REST HOME
982-5287
1415 ARAGON ROSS •
983-6261
---NAVE ENDS
1435 TAPIA MANUEL C •
1439 LUCERO CLYDE TRUCKER
1441 MONTOYA RAMON N
MASON CONTR •
983-7804
---AUAYA BEGINS
1599 COOPER EARL R •
982-2285
---SARAGOSA BEGINS
---CAMINO DE MONTE REY
BEGINS
---W SAN MATEO RD
INTERSECTS
---ST MICHAELS DR
INTERSECTS

15

SAINT MICHAELS DR -FROM OLD PECOS TRAIL WEST TO 2000 CERRILLOS RD

17

---PINON DR INTERSECTS
1451 CHANDLER'S
RESTAURANT 983-7463
GONZALES HENRY
1601 SIERRA LANES
983-6376
1605 SIERA LOUNGE
983-6376
1851 BOTTLE & GLASS
LIQUORS 982-3601

7

SALAZAR PL -FROM 1300 LOPEZ SOUTH TO AGUA FRIA

400 NICHOLS GEORGE W
982-0905
402 SALAZAR ALEX •
983-7478
404 LEYBA LEE • 982-9668
405 VILLA JOHN 982-8798
406 GABALDON JOE P •
983-8792
407 REDMAN LAWRENCE E •
982-1280
408 VALDEZ JOHNNY B

5TH–Contd
1529–Contd
Vaughn Carl J
ΔYU2-0400
1605 Benavidez Joe ◎
1607 Garcia Ben ◎ ΔYU3-8306
Garcia Rosendo ◎
ΔYU2-0668
1609 Vacant
1713 Lucero Louis ◎
1714 Romero Ignacio J ◎
ΔYU3-4983
1715 Martinez Raymond ◎
ΔYU2-8103
1804 Catanach Jesse L ◎
ΔYU3-7411
Mary's Beauty Salon
ΔYU3-7411
1828 Gutierrez Crestino N ◎
ΔYU3-3215
1830 Vigil Steve A ◎
ΔYU3-8285

17

6TH–From 2600 Cerrillos rd south

Berry intersects

cor Mead's Bakery
ΔYU3-7502
1550 Mountain View Trailer Village ΔYU3-4262
Allied Real Est Co
ΔYU2-8022
1606 Gallegos Joe ◎
cor Mountain View Trailer Court ΔYU3-4262
Tilseth Henry

Quapaw intersects

6

ABEYTA–From 792 Camino Poniente south (Right Even)

418 Hartley Roland E
424 Hartley Lillian Mrs
ΔYU3-3998
426 Stephens Blanche A Mrs
ΔYU2-2210
428 Apodaca Benny J ◎
ΔYU2-2419
428½ Gurule Alfonso ◎

Apodaca intersects

502 Rivera Emerejildo ◎
503 Rios Rudolfo ◎
504 Montoya Nellie Mrs
508 Romero Manuelita S Mrs ◎
509 Gabaldon Max ◎
511 No Return
512 Apodaca Gregorita Mrs ◎ ΔYU3-6664
516 Marquez Jas ◎
ΔYU3-6146
517 Segura Vivian
523 Vacant
523½ Avila John S
525 Sando Lawrence
527 Lopez Jerry
528 Abeyta Ramon ◎
ΔYU3-4238
601 Vacant
603 Vacant
605 Flores Ike M ΔYU3-3073
609 Chauvenet Wm
800 Apodaca Henry
ΔYU3-8112
801 Lucero Lucinda Mrs ◎
ΔYU2-8188
803 Apodaca Victoriano ◎
807 Apodaca Julia ◎
ΔYU3-4897
809 Apodaca Roman ◎
810 Gonzales Vivian J ◎
ΔYU3-3188
Gonzales Victoriano ◎
812 **Apartments**
A Friedman Wm
B Johnson Gloria
C Rapp Fred
D Jordan Raymond U
E Dye Lee

6

ACEQUIA MADRE–From 507 Garcia east to Camino Cabra (Right Even)

506 Hess Seymour I ◎
ΔYU3-9445
507 McMahon Patrick
508a Schaefer Christopher Mrs ΔYU2-2024
508b Vacant
508½ Ganotos Andy
ΔYU2-5774
509 Jones David J jr ◎
ΔYU3-3158

STREET NOT LISTED

2D—Contd
1728 Under constn
1729 Vacant

Lenna intersects

end Hovey Concrete Products Co Inc 3-4303

13

3D—From Jay south, about 1 block east of Cerrillos rd

1518 Lazaros Willie D Mrs ⓪
1524 Lucero Alfredo M ⓪ 3-3932
1608 Dalton Jas S ⓪ 2-0503
1611 Padilla Solomon ⓪
1613 Vacant

Quapaw intersects

1703 Salazar Pete ⓪
1706 Lucero Procopio ⓪ 2-1139
1708 Felix Jose R ⓪ 3-7169
1709 Vacant
1710 Felix Johnny ⓪
1712 Montano Leo ⓪
1714 Armijo Eloy ⓪
1718 Rivera Joe ⓪
1719 Lopez Genovevo
1729 Chavez Refugio ⓪
1731 Vacant

Hopewell intersects

13

4TH—From 2400 Cerrillos rd south

1501 Watts James R ⓪ 3-9724
1503 Talache Jose M
1505 Gutierrez Joseph V jr ⓪ 2-0062
1505½ Richardson Gene R 3-5170
1507 Lujan Joe E ⓪ 2-0041
1509 Smith Frank N ⓪ 2-0041
1602 Sena Fidel ⓪ 3-8253
1612 Patterson Morton L ⓪ 3-3402
1618 Tapia Antonio F

13

5TH—From Cerrillos rd ext south

1601 Montoya Saml D ⓪ 3-5284
1603 Leyba Pete
1604 Padilla Rafaelita Mrs ⓪ 3-8594
1608 Gonzales Casimiro ⓪
1714 Romero Ignacio J ⓪ 3-9483
1804 Catanach Jesse L ⓪ 3-7984
1825 Vargas Richd ⓪

13

6TH—From 2600 Cerrillos rd south

1606 No return

6

ABEYTA — From 792 Camino Poniente south (Right Even)

404a Ford Donald S 2-1358
404b La Rosa Nina 2-1041
418 Hartley Roland E 3-3998
424 Clum Shirley ⓪ 3-8969
426 Read Theo H ⓪ 2-0256
428 Apodaca Benny ⓪ 2-0056

Apodaca intersects

502 Rivera Josefita Mrs ⓪
503 Vickrey Martha C 2-0319
504 Vacant
508 Barela Jose T
509 Gabaldon Max ⓪
511 Johnson Patrocina Mrs 3-5453
512-14 Apodaca Gregorita Mrs ⓪ 3-6664
516 Marquez Jas ⓪ 3-6146
517 Garcia Dorateo
523-25 Gomez Pedro J ⓪ 3-5244
523½ Goldman Albert M
527 Williams Billy P
528 Abeyta Ramon ⓪ 3-4238
601 Comer Virginia L 3-4236
603 Cochrell Boyd 2-0162
605 Cole Theo D
609 Chauvenet Wm ⓪ 3-7125
801 Lucero Luis ⓪
803 Apodaca Victoriano ⓪
807 Apodaca Ramon ⓪
810 Gonzales Victoriano ⓪
812 Ward Thos C 3-8820
812a Catron John S 2-0894
812b Metcalf Grace K 2-0390
812c Potter Kenneth C
812d Ohlinger Betty 3-4148

6

ACEQUIA MADRE — From 507 Garcia east to Camino Cobra (Right Even)

506 Hess Seymour I ⓪ 3-9445
507 Magill Wm J 3-8190
508a Beheler Laura F 3-7822
508½ Nielsen Billie
508b Deaver James 3-3152
509 Vacant
511 Dickenson Earl Mrs 3-8238
512 Tito's Mkt gro 3-9212
Griego Tito S ⓪ 3-9212
515 Peck Irene Mrs ⓪ 3-9245
518 Johnson Lyle Mrs ⓪ 3-4538
520 Gilliland Minnie O ⓪ 2-0598

Placita Rafael intersects

522 Von Horvath Artemy A ⓪ 3-3812

Delgado intersects

603 Boulton Jack ⓪ 3-5253
614 Curtin Leonora Mrs ⓪ 3-6538
615 Hausner Eric P ⓪ 3-3139
617 Cooke Claude E 3-8595
619 Jordan Joan Mrs ⓪ 3-9450

Plaza Balentin begins ns
Calle Corvo ends
San Antonio begins ss

712 Chavez Fabian ⓪ 3-8878

Calle LaPaz intersects

716 Rodgers Gladys L Mrs ⓪ 3-6738
ns Acequia Madre School 3-5465

Camino Manzano begins

720 Apartments
1 Gardner Hazel
2 Huff Anna C
3 Wiltsie Fern
4 Whittaker Alfred P
5 Leonard Willard L ⓪ 3-5738
6 Smith Howard jr
7 Coykendahl Arth
8 Hoff Anna C Mrs
9 Corcoran Wilson A 3-7896

Street continued

739 Rodriguez Francisco M ⓪ 3-6846
740 Edwards Pamela S Mrs ⓪ 3-6447
740½ Champion Deda
751 Valdes Conrad P ⓪ 3-5638
753 Warren Fredk L ⓪ 3-4647
754 Berchtold Norbert H ⓪ 3-5839

Sasoya la begins

755 McKay Wm S ⓪ 3-8763
755½ Fathree Howard R ⓪ 3-6549
756 Allen David J ⓪ 3-6547
767 Finch Ernest ⓪ 2-1178
767½ Garcia Alfons R ⓪ 3-8354
769 Ortiz Alfredo ⓪ 3-5488
770 Leakey Ruth Mrs ⓪ 3-6245
774 Kleinfeld Gerald J ⓪ 3-6785

Tranquilo begins

777 Alarid Benj B ⓪ 3-9347

Gormley intersects

STREET NOT LISTED

1949 5TH ST

SOURCE: HUDSPETHS

STREET NOT LISTED

1949 ST MICHAELS DR

SOURCE: HUDSPETHS

STREET NOT LISTED

1944 5TH ST

SOURCE: HUDSPETHS

STREET NOT LISTED

1944 ST MICHAELS DR

SOURCE: HUDSPETHS

STREET NOT LISTED

1940 5TH ST

SOURCE: HUDSPETHS

STREET NOT LISTED

1940 ST MICHAELS DR

SOURCE: HUDSPETHS

STREET NOT LISTED

1936-37 5TH ST

SOURCE: HUDSPETHS

STREET NOT LISTED

1936-37 ST MICHAELS DR

SOURCE: HUDSPETHS

STREET NOT LISTED

1930-31 5TH ST

SOURCE: HUDSPETHS

STREET NOT LISTED

1930-31 ST MICHAELS DR

SOURCE: HUDSPETHS

STREET NOT LISTED

1928-29 5TH ST

SOURCE: HUDSPETHS

STREET NOT LISTED

1928-29 ST MICHAELS DR

SOURCE: HUDSPETHS

STREET NOT LISTED

APPENDIX H

Database Report

DATABASE REPORT

Project Property:	*New Method Cleaners* *1911 St Michaels Dr* *Santa Fe NM 87505*
Project No:	*NMENV.M007.SF-WALDO*
Report Type:	*Database Report*
Order No:	*25121700734*
Requested by:	*INTERA Incorporated*
Date Completed:	*December 20, 2025*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....8
Executive Summary: Site Report Summary - Surrounding Properties.....9
Executive Summary: Summary by Data Source.....16
Map.....26
Aerial.....29
Topographic Map.....30
Detail Report.....31
Unplottable Summary.....131
Unplottable Report.....132
Appendix: Database Descriptions.....133
Definitions.....148

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:		*New Method Cleaners* *1911 St Michaels Dr Santa Fe NM 87505*
Project No:		*NMENV.M007.SF-WALDO*
Coordinates:		
	Latitude:	*35.6599385*
	Longitude:	*-105.96852438*
	UTM Northing:	*3,946,663.71*
	UTM Easting:	*412,334.64*
	UTM Zone:	*UTM Zone 13S*
Elevation:		*6,845 FT*

Order Information:

Order No:	*25121700734*
Date Requested:	*December 17, 2025*
Requested by:	*INTERA Incorporated*
Report Type:	*Database Report*

Historicals/Products:

Aerial Photographs	*Historical Aerials (with Project Boundaries)*
Chain of Title & Lien Searches	*ASTM E1527-21 Compliant Environmental Lien Search (back to 1980) with Historic Chain of Title (back to 1932)*
City Directory Search	*CD - 2 Street Search*
ERIS Xplorer	*ERIS Xplorer*
Excel Add-On	*Excel Add-On*
Fire Insurance Maps	*US Fire Insurance Maps*
Physical Setting Report (PSR)	*Physical Setting Report (PSR)*
Topographic Map	*Topographic Maps*

Executive Summary: Report Summary

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
Standard Environmental Records								
Federal								
NPL	Y	1	0	0	0	0	0	0
PROPOSED NPL	Y	1	0	0	0	0	0	0
DELETED NPL	Y	0.5	0	0	0	0	-	0
SEMS	Y	0.5	0	0	0	0	-	0
ODI	Y	0.5	0	0	0	0	-	0
SEMS ARCHIVE	Y	0.5	0	0	0	0	-	0
CERCLIS	Y	0.5	0	0	0	0	-	0
IODI	Y	0.5	0	0	0	0	-	0
CERCLIS NFRAP	Y	0.5	0	0	0	0	-	0
CERCLIS LIENS	Y	PO	0	-	-	-	-	0
RCRA CORRACTS	Y	1	0	0	0	0	0	0
RCRA TSD	Y	0.5	0	0	0	0	-	0
RCRA LQG	Y	0.25	0	0	0	-	-	0
RCRA SQG	Y	0.25	0	0	0	-	-	0
RCRA VSQG	Y	0.25	0	**1**	**6**	-	-	**7**
RCRA NON GEN	Y	0.25	**2**	0	**8**	-	-	**10**
RCRA CONTROLS	Y	0.5	0	0	0	0	-	0
FED ENG	Y	0.5	0	0	0	0	-	0
FED INST	Y	0.5	0	0	0	0	-	0
LUCIS	Y	0.5	0	0	0	0	-	0
NPL IC	Y	0.5	0	0	0	0	-	0
ERNS 1982 TO 1986	Y	PO	0	-	-	-	-	0
ERNS 1987 TO 1989	Y	PO	0	-	-	-	-	0
ERNS	Y	PO	0	-	-	-	-	0
FED BROWNFIELDS	Y	0.5	0	0	0	0	-	0
FEMA UST	Y	0.25	0	0	0	-	-	0
FRP	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
DELISTED FRP	Y	0.25	0	0	0	-	-	0
HIST GAS STATIONS	Y	0.25	0	0	0	-	-	0
REFN	Y	0.25	0	0	0	-	-	0
BULK TERMINAL	Y	0.25	0	0	0	-	-	0
SEMS LIEN	Y	PO	0	-	-	-	-	0
SUPERFUND ROD	Y	1	0	0	0	0	0	0
State								
SCS	Y	1	0	0	0	**1**	**4**	**5**
DELISTED SCS	Y	1	0	0	0	0	**1**	**1**
SWF/LF	Y	0.5	0	0	0	**3**	-	**3**
HIST LF	Y	0.5	0	0	0	0	-	0
RECYCLING	Y	0.5	0	0	0	0	-	0
LST	Y	0.5	0	**1**	**3**	**7**	-	**11**
DELISTED LST	Y	0.5	0	0	0	0	-	0
LUST HIST	Y	0.5	0	**1**	**4**	**5**	-	**10**
UST	Y	0.25	0	**2**	**7**	-	-	**9**
AST	Y	0.25	0	0	0	-	-	0
TANKS	Y	0.25	0	**2**	**7**	-	-	**9**
UST HIST	Y	0.25	0	**2**	**8**	-	-	**10**
AST HIST	Y	0.25	0	0	0	-	-	0
DELISTED TANK	Y	0.25	0	0	0	-	-	0
INST	Y	0.5	0	0	0	0	-	0
VCP	Y	0.5	0	0	**1**	**3**	-	**4**
BROWNFIELDS	Y	0.5	0	0	0	0	-	0
Tribal								
INDIAN LUST	Y	0.5	0	0	0	0	-	0
INDIAN UST	Y	0.25	0	**1**	0	-	-	**1**
DELISTED INDIAN LST	Y	0.5	0	0	0	0	-	0
DELISTED INDIAN UST	Y	0.25	0	0	0	-	-	0
County	***No County databases were selected to be included in the search.***							

Additional Environmental Records

Federal

PFAS GHG	Y	0.5	0	0	0	0	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
OSC RESPONSE	Y	0.125	0	0	-	-	-	0
FINDS/FRS	Y	PO	**3**	-	-	-	-	**3**
TRIS	Y	PO	0	-	-	-	-	0
PFAS NPL	Y	0.5	0	0	0	0	-	0
PFAS FED SITES	Y	0.5	0	0	0	0	-	0
PFAS SSEHRI	Y	0.5	0	0	0	0	-	0
PFAS ERNS	Y	0.5	0	0	0	0	-	0
PFAS NPDES	Y	0.5	0	0	0	0	-	0
PFAS TRI	Y	0.5	0	0	0	0	-	0
PFAS WATER	Y	0.5	0	0	0	0	-	0
PFAS TSCA	Y	0.5	0	0	0	0	-	0
PFAS E-MANIFEST	Y	0.5	0	0	0	0	-	0
PFAS IND	Y	0.5	0	0	0	0	-	0
HMIRS	Y	0.125	0	0	-	-	-	0
NCDL	Y	0.125	0	0	-	-	-	0
TSCA	Y	0.125	0	0	-	-	-	0
HIST TSCA	Y	0.125	0	0	-	-	-	0
FTTS ADMIN	Y	PO	0	-	-	-	-	0
FTTS INSP	Y	PO	0	-	-	-	-	0
PRP	Y	PO	0	-	-	-	-	0
SCRD DRYCLEANER	Y	0.5	0	0	0	0	-	0
ICIS	Y	PO	**1**	-	-	-	-	**1**
FED DRYCLEANERS	Y	0.25	**1**	0	0	-	-	**1**
DELISTED FED DRY	Y	0.25	0	0	0	-	-	0
FUDS	Y	1	0	0	0	0	0	0
FUDS MRS	Y	1	0	0	0	0	0	0
FORMER NIKE	Y	1	0	0	0	0	0	0
PIPELINE INCIDENT	Y	PO	0	-	-	-	-	0
MLTS	Y	PO	0	-	-	-	-	0
HIST MLTS	Y	PO	0	-	-	-	-	0
MINES	Y	0.25	0	0	0	-	-	0
SMCRA	Y	1	0	0	0	0	0	0
MRDS	Y	1	0	0	0	0	0	0
LM SITES	Y	1	0	0	0	0	0	0
ALT FUELS	Y	0.25	0	0	**3**	-	-	**3**

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
CONSENT DECREES	Y	0.25	0	0	0	-	-	0
AFS	Y	PO	**1**	-	-	-	-	**1**
SSTS	Y	0.25	0	0	0	-	-	0
PCBT	Y	0.5	0	0	0	0	-	0
PCB	Y	0.5	0	0	0	0	-	0
POWER PLANTS	Y	0.125	0	0	-	-	-	0
HIST RISK	Y	0.125	0	0	-	-	-	0
State								
HAZ	Y	0.5	0	0	0	0	-	0
SPILLS	Y	0.125	0	**1**	-	-	-	**1**
SPILLS OIL	Y	0.125	0	0	-	-	-	0
CDL	Y	0.125	0	0	-	-	-	0
PFAS	Y	0.5	0	0	0	0	-	0
GW DISCHARGE	Y	PO	0	-	-	-	-	0
URANIUM	Y	0.5	0	0	0	0	-	0
Tribal	***No Tribal additional environmental record sources available for this State.***							
County	***No County additional environmental record sources available for this State.***							
Total:			***8***	***11***	***47***	***19***	***5***	***90***

**** PO – Property Only***
**** 'Property and adjoining properties' database search radii are set at 0.25 miles.***

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	AFS	NEW METHOD DRY CLEANERS/ST. MICHAELS DR.	1911 ST. MICHAELS DR. SANTA FE NM 87505	E	0.00 / 0.00	2	31
1	FED DRYCLEANERS	NEW METHOD DRY CLEANERS/ST. MICHAELS DR.	1911A SAINT MICHAELS DRIVE SANTA FE NM 87505 ***FRS Facility ID:*** *110004274151*	E	0.00 / 0.00	2	32
1	FINDS/FRS	PROSPER INC DBA INSTY-PRINTS	1911 ST MICHAELS DR #C SANTA FE NM 87501 ***Registry ID:*** *110004276104*	E	0.00 / 0.00	2	32
1	FINDS/FRS	NEW METHOD DRY CLEANERS/ST. MICHAELS DR.	1911A SAINT MICHAELS DRIVE SANTA FE NM 87505-7653 ***Registry ID:*** *110004274151*	E	0.00 / 0.00	2	33
1	FINDS/FRS	NEW METHOD DRY CLEANERS - SANTA FE	1911 A ST MICHAELS DR SANTA FE NM 87505 ***Registry ID:*** *110022745528*	E	0.00 / 0.00	2	33
1	ICIS	NEW METHOD DRY CLEANERS/ST. MICHAELS DR.	1911 ST. MICHAELS DR. SANTA FE NM 87505 ***Registry ID:*** *110004274151*	E	0.00 / 0.00	2	34
1	RCRA NON GEN	PROSPER INC DBA INSTY-PRINTS	1911 ST MICHAELS DR #C SANTA FE NM 87501 ***Handler ID | Recycler Activity?:*** *NMD986668333 | NO*	E	0.00 / 0.00	2	34
1	RCRA NON GEN	NEW METHOD CLNRS	1911-A ST MICHAELS DR SANTA FE NM 87505 ***Handler ID | Recycler Activity?:*** *NMD981512999 | NO*	E	0.00 / 0.00	2	37

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
2	RCRA VSQG	THE SHERWIN-WILLIAMS STORE #7252	1905 ST MICHAELS DR SANTA FE NM 87501	W	0.03 / 184.74	-6	40
			***Handler ID	Recycler Activity?:*** NMD076447721 | NO			
3	INDIAN UST	Allsup's #323	Rt. 5, Box 36A Santa Fe NM	SSW	0.08 / 406.02	-3	48
			Facility ID: P192NM				
4	LST	ATEX ALLSUPS #327	1899 SAINT MICHAELS DR SANTA FE NM	W	0.09 / 450.60	-10	48
			***Release ID	Facility ID	Status:*** 1826 | 26541 | No Further Action, Confirmed Release		
4	LUST HIST	ATEX ALLSUPS #327	1899 SAINT MICHAELS DR SANTA FE NM	W	0.09 / 450.60	-10	50
4	SPILLS		2920 Nelson Rd MN 55359 Santa Fe NM	W	0.09 / 450.60	-10	50
			***Notification ID	Status:*** 13872 | No Further Action Needed - Complaint Closed			
4	TANKS	ALLSUPS 344	1899 SAINT MICHAELS DR SANTA FE NM 87501	W	0.09 / 450.60	-10	50
			***FID	In Use AST	In Use UST:*** 26541 | 0 | 3		
4	UST	ALLSUP'S # 102344	1899 SAINT MICHAELS DR SANTA FE NM 87501	W	0.09 / 450.60	-10	51
			Facility ID: 26541 ***In Use UST	Removed UST:*** 3 | 0			
4	UST HIST	ALLSUPS 344	1899 SAINT MICHAELS DR SANTA FE NM 87501	W	0.09 / 450.60	-10	52
			Facility ID: 26541 ***Tank ID	Tank Status:*** 20967 | CURRENTLY IN USE, 20969 | CURRENTLY IN USE, 20969 | CURRENTLY IN USE, 20968 | CURRENTLY IN USE, 20968 | CURRENTLY IN USE, 20967 | CURRENTLY IN USE		
5	TANKS	ALLSUPS 327	2000 SAINT MICHAELS DR SANTA FE NM 87501	ESE	0.10 / 545.77	18	53
			***FID	In Use AST	In Use UST:*** 26524 | 0 | 0		
5	UST	ALLSUPS 327	2000 SAINT MICHAELS DR SANTA FE NM 87501	ESE	0.10 / 545.77	18	53
			Facility ID: 26524 ***In Use UST	Removed UST:*** 0 | 2			
5	UST HIST	ALLSUPS 327	2000 SAINT MICHAELS DR SANTA FE NM 87501	ESE	0.10 / 545.77	18	54
			Facility ID: 26524 ***Tank ID	Tank Status:*** 20915 | REMOVED, 20916 | REMOVED			
6	ALT FUELS	Fiesta Nissan	2005 St Michaels Dr Santa Fe NM 87505	E	0.13 / 711.08	25	54
			ID: 49915				

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
6	ALT FUELS	Fiesta Nissan	2005 St Michaels Dr Santa Fe NM 87505 ***ID:*** 49916	E	0.13 / 711.08	25	55
6	ALT FUELS	Fiesta Nissan	2005 Saint Michaels Drive Santa Fe NM 87505 ***ID:*** 377488	E	0.13 / 711.08	25	56
6	RCRA VSQG	FIESTA NISSAN	2005 SAINT MICHAELS DRIVE SANTA FE NM 87501 ***Handler ID | Recycler Activity?:*** NMD986674786 | NO	E	0.13 / 711.08	25	56
6	TANKS	SANTA FE PARTNERS	2005 SAINT MICHAELS DR SANTA FE NM 87501 ***FID | In Use AST | In Use UST:*** 30459 | 0 | 0	E	0.13 / 711.08	25	60
6	UST	SANTA FE PARTNERS	2005 SAINT MICHAELS DR SANTA FE NM 87501 ***Facility ID:*** 30459 ***In Use UST | Removed UST:*** 0 | 1	E	0.13 / 711.08	25	60
6	UST HIST	SANTA FE PARTNERS	2005 SAINT MICHAELS DR SANTA FE NM 87501 ***Facility ID:*** 30459 ***Tank ID | Tank Status:*** 30188 | REMOVED	E	0.13 / 711.08	25	61
6	VCP	Premier Nissan	2005 St. Michael's Drive Santa Fe NM	E	0.13 / 711.08	25	61
7	RCRA NON GEN	KMART #3301	1712 ST MICHAELS DRIVE SANTA FE NM 87505 ***Handler ID | Recycler Activity?:*** NMR000017822 | NO	SSW	0.16 / 837.89	-14	61
7	TANKS	KMART NUMBER 3301	1712 SAINT MICHAELS DR SANTA FE NM 87501 ***FID | In Use AST | In Use UST:*** 28953 | 0 | 0	SSW	0.16 / 837.89	-14	65
7	UST	KMART NUMBER 3301	1712 SAINT MICHAELS DR SANTA FE NM 87501 ***Facility ID:*** 28953 ***In Use UST | Removed UST:*** 0 | 1	SSW	0.16 / 837.89	-14	66
7	UST HIST	KMART NUMBER 3301	1712 SAINT MICHAELS DR SANTA FE NM 87501 ***Facility ID:*** 28953 ***Tank ID | Tank Status:*** 26608 | REMOVED	SSW	0.16 / 837.89	-14	66
8	RCRA VSQG	BETO'S AUTO REPAIR	1650 6TH ST SANTA FE NM 87505 ***Handler ID | Recycler Activity?:*** NMR000011528 | NO	W	0.16 / 863.94	-20	67
9	RCRA NON GEN	SANTA FE SPORTS AND IMAGES	2701 WARNER CIRCLE SANTA FE NM 87505 ***Handler ID | Recycler Activity?:*** NMR000026237 | NO	SE	0.17 / 915.33	9	69
10	RCRA VSQG	TOYOTECH	1640 6TH ST SANTA FE NM 87505	WNW	0.18 / 932.57	-20	71

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			***Handler ID	Recycler Activity?:*** NMR000011452 | NO			
11	LST	GRAHAMS CHEVRN	1700 SAINT MICHAELS DR SANTA FE NM	WSW	0.21 / 1,089.96	-24	75
			***Release ID	Facility ID	Status:*** 762 | 27330 | No Further Action, Confirmed Release		
11	LUST HIST	GRAHAMS CHEVRN	1700 SAINT MICHAELS DR SANTA FE NM	WSW	0.21 / 1,089.96	-24	76
11	RCRA NON GEN	CHEVRON STATION #76047	1700 ST MICHAELS DR SANTA FE NM 87501	WSW	0.21 / 1,089.96	-24	76
			***Handler ID	Recycler Activity?:*** NMD986676724 | NO			
11	TANKS	CHEVRON 76047	1700 SAINT MICHAELS DR SANTA FE NM 87501	WSW	0.21 / 1,089.96	-24	79
			***FID	In Use AST	In Use UST:*** 27330 | 0 | 0		
11	TANKS	LLANO CHEVRON	1700 SAINT MICHAELS DR SANTA FE NM 87501	WSW	0.21 / 1,089.96	-24	79
			***FID	In Use AST	In Use UST:*** 1480 | 0 | 3		
11	UST	LLANO SHELL	1700 SAINT MICHAELS DR SANTA FE NM 87501	WSW	0.21 / 1,089.96	-24	79
			Facility ID: 1480 ***In Use UST	Removed UST:*** 3 | 0			
11	UST	CHEVRON 76047	1700 SAINT MICHAELS DR SANTA FE NM 87501	WSW	0.21 / 1,089.96	-24	80
			Facility ID: 27330 ***In Use UST	Removed UST:*** 0 | 5			
11	UST HIST	CHEVRON 76047	1700 SAINT MICHAELS DR SANTA FE NM 87501	WSW	0.21 / 1,089.96	-24	81
			Facility ID: 27330 ***Tank ID	Tank Status:*** 22800 | REMOVED, 22798 | REMOVED, 22801 | REMOVED, 22799 | REMOVED, 22797 | REMOVED			
11	UST HIST	LLANO CHEVRON	1700 SAINT MICHAELS DR SANTA FE NM 87501	WSW	0.21 / 1,089.96	-24	82
			Facility ID: 1480 ***Tank ID	Tank Status:*** 18426 | CURRENTLY IN USE, 18424 | CURRENTLY IN USE, 18425 | CURRENTLY IN USE, 18425 | CURRENTLY IN USE, 18426 | CURRENTLY IN USE, 18424 | CURRENTLY IN USE			
12	LST	HORACE CHRYSLER JEEP AND KIA	1701 ST MICHAELS DR SANTA FE NM	W	0.21 / 1,131.65	-25	83
			***Release ID	Facility ID	Status:*** 4451 | 27353 | No Further Action, Confirmed Release		
12	LUST HIST	Horace Chrysler Jeep	1701 St Michaels Dr Santa Fe NM 87501	W	0.21 / 1,131.65	-25	84
12	RCRA VSQG	SANTA FE KIA	1701 ST MICHAELS DR SANTA FE NM 87505	W	0.21 / 1,131.65	-25	85
			***Handler ID	Recycler Activity?:*** NMD981610397 | NO			
12	TANKS	HORACE CHRYSLER JEEP AND KIA	1701 ST MICHAELS DR SANTA FE NM 87501	W	0.21 / 1,131.65	-25	90

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			FID* | *In Use AST* | *In Use UST: 27353 | 0 | 0				
12	UST	HORACE CHRYSLER JEEP AND KIA	1701 ST MICHAELS DR SANTA FE NM 87501 ***Facility ID:*** 27353 ***In Use UST* | *Removed UST:*** 0 | 3	W	0.21 / 1,131.65	-25	90
12	UST HIST	CHRYSLER PLYMOUTH DODGE OF SANTA FE	1701 SAINT MICHAELS DR SANTA FE NM 87501 ***Facility ID:*** 27354	W	0.21 / 1,131.65	-25	91
12	UST HIST	CHRYSLER PLYMOUTH	1701 ST MICHAELS DR SANTA FE NM 87501 ***Facility ID:*** 27353 ***Tank ID* | *Tank Status:*** 22856 | REMOVED, 22858 | REMOVED, 22857 | REMOVED	W	0.21 / 1,131.65	-25	91
13	RCRA NON GEN	STREAMLINE CUSTOM PAINTING INC	1808 2ND ST SUITE G SANTA FE NM 87505 ***Handler ID* | *Recycler Activity?:*** NMR000012278 | NO	NE	0.21 / 1,133.76	26	92
13	RCRA NON GEN	CERL INC	1808 SECOND ST STE D SANTA FE NM 87505 ***Handler ID* | *Recycler Activity?:*** NMD986684611 | NO	NE	0.21 / 1,133.76	26	95
13	RCRA NON GEN	CHANDLER CHAIR COMPANY	1808 SECOND STREET SUITE L SANTA FE NM 87505 ***Handler ID* | *Recycler Activity?:*** NMR000012039 | NO	NE	0.21 / 1,133.76	26	99
13	RCRA VSQG	VISIONS PHOTO LAB	1808 SECOND ST SUITE C SANTA FE NM 87505 ***Handler ID* | *Recycler Activity?:*** NMR000021444 | NO	NE	0.21 / 1,133.76	26	102
14	RCRA NON GEN	FURROW BLDG MATERIALS	900 W SAN MATEO SANTA FE NM 87501 ***Handler ID* | *Recycler Activity?:*** NMD986682912 | NO	ENE	0.23 / 1,221.08	38	105
15	RCRA VSQG	TOY AUTO MAN LLC	1802 2ND ST SANTA FE NM 87501 ***Handler ID* | *Recycler Activity?:*** NMD986676567 | NO	NE	0.24 / 1,254.08	24	107
16	LUST HIST	GIANT STOPNGO	1693 ST MICHAELS DR SANTA FE NM	W	0.24 / 1,262.77	-23	110
17	RCRA NON GEN	AAMCO TRANSMISSION	854 ST MICHEALS SANTA FE NM 87505 ***Handler ID* | *Recycler Activity?:*** NMR000004754 | NO	ESE	0.24 / 1,287.37	-1	110
17	TANKS	PAULS TRANSMISSION	854 SAINT MICHAELS DR SANTA FE NM 87501 ***FID* | *In Use AST* | *In Use UST:*** 29884 | 0 | 0	ESE	0.24 / 1,287.37	-1	113
17	UST	PAULS TRANSMISSION	854 SAINT MICHAELS DR SANTA FE NM 87501	ESE	0.24 / 1,287.37	-1	113

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			Facility ID: 29884 ***In Use UST | Removed UST:*** 0 | 1				
17	UST HIST	PAULS TRANSMISSION	854 SAINT MICHAELS DR SANTA FE NM 87501	ESE	0.24 / 1,287.37	-1	114
			Facility ID: 29884 ***Tank ID | Tank Status:*** 28723 | REMOVED				
18	LST	ALLSUPS 252	2007 CALLE LORCA SANTA FE NM	ESE	0.25 / 1,300.07	0	115
			Release ID | Facility ID | Status: 2526 | 26511 | No Further Action, Confirmed Release				
18	LUST HIST	ALLSUPS 252	CORNER CALLE LORCA AND SANTA FE NM	ESE	0.25 / 1,300.07	0	116
18	TANKS	ALLSUPS 252 FINA	2007 CALLE LORCA SANTA FE NM 87501	ESE	0.25 / 1,300.07	0	116
			FID | In Use AST | In Use UST: 26511 | 0 | 2				
18	UST	ALLSUP'S # 102252	2007 CALLE LORCA SANTA FE NM 87501	ESE	0.25 / 1,300.07	0	116
			Facility ID: 26511 ***In Use UST | Removed UST:*** 2 | 3				
18	UST HIST	ALLSUPS 252 FINA	CORNER CALLE LORCA AND SANTA FE NM 87501	ESE	0.25 / 1,300.07	0	117
			Facility ID: 26511 ***Tank ID | Tank Status:*** 20866 | REMOVED, 20868 | CURRENTLY IN USE, 20869 | CURRENTLY IN USE, 20865 | REMOVED, 20868 | CURRENTLY IN USE, 20869 | CURRENTLY IN USE, 20867 | REMOVED				
19	LST	GIANT 6056	1698 ST MICHAELS DR SANTA FE NM	W	0.27 / 1,415.91	-28	118
			Release ID | Facility ID | Status: 4630 | 28317 | No Further Action, Confirmed Release				
19	LST	GIANT STOPNGO	1698 ST MICHAELS DR SANTA FE NM	W	0.27 / 1,415.91	-28	120
			Release ID | Facility ID | Status: 1987 | 28317 | No Further Action, Confirmed Release				
20	SCS	1710 Llano	1710 Llano Santa Fe NM	WSW	0.27 / 1,446.19	-34	120
20	VCP	1710 Llano St.	1710 Llano Street, Santa Fe Santa Fe NM	WSW	0.27 / 1,446.19	-34	120
21	VCP	Smith's #491 Fuel Center	800 St. Michael's Drive Santa Fe NM	E	0.29 / 1,524.33	17	121
22	SWF/LF	City of Santa Fe - Sangre de Cristo Water Division	801 W. San Mateo, Santa Fe, New Mexico 87505 NM	ENE	0.39 / 2,059.88	42	121
23	LST	SQUEAKY CLEAN CAR WASH	1900 CERRILLOS RD SANTA FE NM	WNW	0.40 / 2,096.69	-28	121

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
			Release ID* | *Facility ID* | *Status: 1484 | 30744 | No Further Action, Confirmed Release				
23	LUST HIST	SQUEAKY CLEAN CAR WA	1900 CERRILLOS RD SANTA FE NM	WNW	0.40 / 2,096.69	-28	122
24	VCP	Park Avenue Cleaners - SF	720 St. Michaels Drive, Suite K Santa Fe NM	E	0.40 / 2,114.93	39	123
25	SWF/LF	Concentra Urgent Care	720 St. Michaels Drive, Suite C, Santa Fe, New Mexico NM	ESE	0.40 / 2,133.36	46	123
26	LST	1901 CERRILLOS CHEVRON	1901 CERRILLOS RD SANTA FE NM	NW	0.43 / 2,279.38	-31	123
			Release ID* | *Facility ID* | *Status: 4614 | 1031 | No Further Action, Confirmed Release				
26	SWF/LF	Amigo Tire and Auto	1901 Cerrillos Road, Santa Fe, New Mexico NM	NW	0.43 / 2,279.38	-31	125
27	LST	SHUTTLEJACK	1600 LENA RD SANTA FE NM	NE	0.46 / 2,453.77	37	125
			Release ID* | *Facility ID* | *Status: 2661 | 30595 | No Further Action, Confirmed Release				
27	LUST HIST	SHUTTLEJACK	1600 LENA RD SANTA FE NM	NE	0.46 / 2,453.77	37	126
28	LST	ST MICHAELS SHELL	711 SAINT MICHAELS SANTA FE NM	E	0.49 / 2,563.09	39	126
			Release ID* | *Facility ID* | *Status: 1611 | 1768 | No Further Action, Confirmed Release				
28	LST	SAINT MIKES SHELL	711 SAINT MICHAELS SANTA FE NM	E	0.49 / 2,563.09	39	127
			Release ID* | *Facility ID* | *Status: 2435 | 1768 | No Further Action, Confirmed Release				
28	LUST HIST	ST MIKE'S SHELL	711 SAINT MICHAELS SANTA FE NM	E	0.49 / 2,563.09	39	128
28	LUST HIST	ST MICHAELS SHELL	711 SAINT MICHAELS SANTA FE NM	E	0.49 / 2,563.09	39	128
28	LUST HIST	SAINT MIKES SHELL	711 SAINT MICHAELS SANTA FE NM	E	0.49 / 2,563.09	39	128
29	SCS	Jiffy Lube	1975 Cerrillos Santa Fe NM	WNW	0.51 / 2,684.47	-49	129

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
30	SCS	Exxon Station 6-7231	2045 Cerrillos Rd Santa Fe NM	W	0.60 / 3,186.85	-63	129
31	DELISTED SCS	Fmr White Swan Laundry Facility	1368 Cerrillos Road Santa Fe NM	NNE	0.73 / 3,866.16	39	129
32	SCS	Berridge Distributing Co	1255 Cerrillos Rd Santa Fe NM	NNE	0.93 / 4,916.19	48	130
33	SCS	NMDOT Main Yard/GOC	1120 Cerrillos Road Santa Fe NM	NE	1.00 / 5,262.84	66	130

Executive Summary: Summary by Data Source

Standard

Federal

RCRA VSQG - RCRA Very Small Quantity Generators List

A search of the RCRA VSQG database, dated Sep 1, 2025 has found that there are 7 RCRA VSQG site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
FIESTA NISSAN	2005 SAINT MICHAELS DRIVE SANTA FE NM 87501	E	0.13 / 711.08	6
	Handler ID* | *Recycler Activity?: *NMD986674786* | *NO*			
VISIONS PHOTO LAB	1808 SECOND ST SUITE C SANTA FE NM 87505	NE	0.21 / 1,133.76	13
	Handler ID* | *Recycler Activity?: *NMR000021444* | *NO*			
TOY AUTO MAN LLC	1802 2ND ST SANTA FE NM 87501	NE	0.24 / 1,254.08	15
	Handler ID* | *Recycler Activity?: *NMD986676567* | *NO*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
THE SHERWIN-WILLIAMS STORE #7252	1905 ST MICHAELS DR SANTA FE NM 87501	W	0.03 / 184.74	2
	Handler ID* | *Recycler Activity?: *NMD076447721* | *NO*			
BETO'S AUTO REPAIR	1650 6TH ST SANTA FE NM 87505	W	0.16 / 863.94	8
	Handler ID* | *Recycler Activity?: *NMR000011528* | *NO*			
TOYOTECH	1640 6TH ST SANTA FE NM 87505	WNW	0.18 / 932.57	10
	Handler ID* | *Recycler Activity?: *NMR000011452* | *NO*			
SANTA FE KIA	1701 ST MICHAELS DR SANTA FE NM 87505	W	0.21 / 1,131.65	12
	Handler ID* | *Recycler Activity?: *NMD981610397* | *NO*			

RCRA NON GEN - RCRA Non-Generators

A search of the RCRA NON GEN database, dated Sep 1, 2025 has found that there are 10 RCRA NON GEN site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEW METHOD CLNRS	1911-A ST MICHAELS DR SANTA FE NM 87505	E	0.00 / 0.00	1

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
	***Handler ID | Recycler Activity?**: NMD981512999 | NO*			
PROSPER INC DBA INSTY-PRINTS	1911 ST MICHAELS DR #C SANTA FE NM 87501	E	0.00 / 0.00	1
	***Handler ID | Recycler Activity?**: NMD986668333 | NO*			
SANTA FE SPORTS AND IMAGES	2701 WARNER CIRCLE SANTA FE NM 87505	SE	0.17 / 915.33	9
	***Handler ID | Recycler Activity?**: NMR000026237 | NO*			
CHANDLER CHAIR COMPANY	1808 SECOND STREET SUITE L SANTA FE NM 87505	NE	0.21 / 1,133.76	13
	***Handler ID | Recycler Activity?**: NMR000012039 | NO*			
CERL INC	1808 SECOND ST STE D SANTA FE NM 87505	NE	0.21 / 1,133.76	13
	***Handler ID | Recycler Activity?**: NMD986684611 | NO*			
STREAMLINE CUSTOM PAINTING INC	1808 2ND ST SUITE G SANTA FE NM 87505	NE	0.21 / 1,133.76	13
	***Handler ID | Recycler Activity?**: NMR000012278 | NO*			
FURROW BLDG MATERIALS	900 W SAN MATEO SANTA FE NM 87501	ENE	0.23 / 1,221.08	14
	***Handler ID | Recycler Activity?**: NMD986682912 | NO*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
KMART #3301	1712 ST MICHAELS DRIVE SANTA FE NM 87505	SSW	0.16 / 837.89	7
	***Handler ID | Recycler Activity?**: NMR000017822 | NO*			
CHEVRON STATION #76047	1700 ST MICHAELS DR SANTA FE NM 87501	WSW	0.21 / 1,089.96	11
	***Handler ID | Recycler Activity?**: NMD986676724 | NO*			
AAMCO TRANSMISSION	854 ST MICHEALS SANTA FE NM 87505	ESE	0.24 / 1,287.37	17
	***Handler ID | Recycler Activity?**: NMR000004754 | NO*			

State

SCS - State Cleanup Sites Listing

A search of the SCS database, dated Feb 4, 2025 has found that there are 5 SCS site(s) within approximately 1.00miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Berridge Distributing Co	1255 Cerrillos Rd Santa Fe NM	NNE	0.93 / 4,916.19	32

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
NMDOT Main Yard/GOC	1120 Cerrillos Road Santa Fe NM	NE	1.00 / 5,262.84	33

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
1710 Llano	1710 Llano Santa Fe NM	WSW	0.27 / 1,446.19	20
Jiffy Lube	1975 Cerrillos Santa Fe NM	WNW	0.51 / 2,684.47	29
Exxon Station 6-7231	2045 Cerrillos Rd Santa Fe NM	W	0.60 / 3,186.85	30

DELISTED SCS - Delisted State Cleanup Sites

A search of the DELISTED SCS database, dated Feb 4, 2025 has found that there are 1 DELISTED SCS site(s) within approximately 1.00miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Fmr White Swan Laundry Facility	1368 Cerrillos Road Santa Fe NM	NNE	0.73 / 3,866.16	31

SWF/LF - Solid Waste Facilities

A search of the SWF/LF database, dated Oct 23, 2025 has found that there are 3 SWF/LF site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
City of Santa Fe - Sangre de Cristo Water Division	801 W. San Mateo, Santa Fe, New Mexico 87505 NM	ENE	0.39 / 2,059.88	22
Concentra Urgent Care	720 St. Michaels Drive, Suite C, Santa Fe, New Mexico NM	ESE	0.40 / 2,133.36	25

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Amigo Tire and Auto	1901 Cerrillos Road, Santa Fe, New Mexico NM	NW	0.43 / 2,279.38	26

LST - Leaking Petroleum Storage Tanks

A search of the LST database, dated Sep 16, 2025 has found that there are 11 LST site(s) within approximately 0.50miles of the project

property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
ALLSUPS 252	2007 CALLE LORCA SANTA FE NM	ESE	0.25 / 1,300.07	18
	Release ID* | *Facility ID* | *Status: *2526* | *26511* | *No Further Action, Confirmed Release*			
SHUTTLEJACK	1600 LENA RD SANTA FE NM	NE	0.46 / 2,453.77	27
	Release ID* | *Facility ID* | *Status: *2661* | *30595* | *No Further Action, Confirmed Release*			
ST MICHAELS SHELL	711 SAINT MICHAELS SANTA FE NM	E	0.49 / 2,563.09	28
	Release ID* | *Facility ID* | *Status: *1611* | *1768* | *No Further Action, Confirmed Release*			
SAINT MIKES SHELL	711 SAINT MICHAELS SANTA FE NM	E	0.49 / 2,563.09	28
	Release ID* | *Facility ID* | *Status: *2435* | *1768* | *No Further Action, Confirmed Release*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ATEX ALLSUPS #327	1899 SAINT MICHAELS DR SANTA FE NM	W	0.09 / 450.60	4
	Release ID* | *Facility ID* | *Status: *1826* | *26541* | *No Further Action, Confirmed Release*			
GRAHAMS CHEVRN	1700 SAINT MICHAELS DR SANTA FE NM	WSW	0.21 / 1,089.96	11
	Release ID* | *Facility ID* | *Status: *762* | *27330* | *No Further Action, Confirmed Release*			
HORACE CHRYSLER JEEP AND KIA	1701 ST MICHAELS DR SANTA FE NM	W	0.21 / 1,131.65	12
	Release ID* | *Facility ID* | *Status: *4451* | *27353* | *No Further Action, Confirmed Release*			
GIANT 6056	1698 ST MICHAELS DR SANTA FE NM	W	0.27 / 1,415.91	19
	Release ID* | *Facility ID* | *Status: *4630* | *28317* | *No Further Action, Confirmed Release*			
GIANT STOPNGO	1698 ST MICHAELS DR SANTA FE NM	W	0.27 / 1,415.91	19
	Release ID* | *Facility ID* | *Status: *1987* | *28317* | *No Further Action, Confirmed Release*			
SQUEAKY CLEAN CAR WASH	1900 CERRILLOS RD SANTA FE NM	WNW	0.40 / 2,096.69	23
	Release ID* | *Facility ID* | *Status: *1484* | *30744* | *No Further Action, Confirmed Release*			
1901 CERRILLOS CHEVRON	1901 CERRILLOS RD SANTA FE NM	NW	0.43 / 2,279.38	26
	Release ID* | *Facility ID* | *Status: *4614* | *1031* | *No Further Action, Confirmed Release*			

LUST HIST - Leaking Underground Storage Tanks

A search of the LUST HIST database, dated Aug 1, 2006 has found that there are 10 LUST HIST site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
ALLSUPS 252	CORNER CALLE LORCA AND SANTA FE NM	ESE	0.25 / 1,300.07	18
SHUTTLEJACK	1600 LENA RD SANTA FE NM	NE	0.46 / 2,453.77	27
ST MIKE'S SHELL	711 SAINT MICHAELS SANTA FE NM	E	0.49 / 2,563.09	28
SAINT MIKES SHELL	711 SAINT MICHAELS SANTA FE NM	E	0.49 / 2,563.09	28
ST MICHAELS SHELL	711 SAINT MICHAELS SANTA FE NM	E	0.49 / 2,563.09	28

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ATEX ALLSUPS #327	1899 SAINT MICHAELS DR SANTA FE NM	W	0.09 / 450.60	4
GRAHAMS CHEVRN	1700 SAINT MICHAELS DR SANTA FE NM	WSW	0.21 / 1,089.96	11
Horace Chrysler Jeep	1701 St Michaels Dr Santa Fe NM 87501	W	0.21 / 1,131.65	12
GIANT STOPNGO	1693 ST MICHAELS DR SANTA FE NM	W	0.24 / 1,262.77	16
SQUEAKY CLEAN CAR WA	1900 CERRILLOS RD SANTA FE NM	WNW	0.40 / 2,096.69	23

UST - Underground Storage Tanks

A search of the UST database, dated Nov 3, 2025 has found that there are 9 UST site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
ALLSUPS 327	2000 SAINT MICHAELS DR SANTA FE NM 87501 ***Facility ID**: 26524* ***In Use UST | Removed UST**: 0 | 2*	ESE	0.10 / 545.77	5

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
SANTA FE PARTNERS	2005 SAINT MICHAELS DR SANTA FE NM 87501 ***Facility ID**: 30459* ***In Use UST | Removed UST**: 0 | 1*	E	0.13 / 711.08	6
ALLSUP'S # 102252	2007 CALLE LORCA SANTA FE NM 87501 ***Facility ID**: 26511* ***In Use UST | Removed UST**: 2 | 3*	ESE	0.25 / 1,300.07	18

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ALLSUP'S # 102344	1899 SAINT MICHAELS DR SANTA FE NM 87501 ***Facility ID**: 26541* ***In Use UST | Removed UST**: 3 | 0*	W	0.09 / 450.60	4
KMART NUMBER 3301	1712 SAINT MICHAELS DR SANTA FE NM 87501 ***Facility ID**: 28953* ***In Use UST | Removed UST**: 0 | 1*	SSW	0.16 / 837.89	7
CHEVRON 76047	1700 SAINT MICHAELS DR SANTA FE NM 87501 ***Facility ID**: 27330* ***In Use UST | Removed UST**: 0 | 5*	WSW	0.21 / 1,089.96	11
LLANO SHELL	1700 SAINT MICHAELS DR SANTA FE NM 87501 ***Facility ID**: 1480* ***In Use UST | Removed UST**: 3 | 0*	WSW	0.21 / 1,089.96	11
HORACE CHRYSLER JEEP AND KIA	1701 ST MICHAELS DR SANTA FE NM 87501 ***Facility ID**: 27353* ***In Use UST | Removed UST**: 0 | 3*	W	0.21 / 1,131.65	12
PAULS TRANSMISSION	854 SAINT MICHAELS DR SANTA FE NM 87501 ***Facility ID**: 29884* ***In Use UST | Removed UST**: 0 | 1*	ESE	0.24 / 1,287.37	17

TANKS - Petroleum Storage Tanks

A search of the TANKS database, dated Jul 9, 2019 has found that there are 9 TANKS site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
ALLSUPS 327	2000 SAINT MICHAELS DR SANTA FE NM 87501 ***FID | In Use AST | In Use UST**: 26524 | 0 | 0*	ESE	0.10 / 545.77	5
SANTA FE PARTNERS	2005 SAINT MICHAELS DR SANTA FE NM 87501 ***FID | In Use AST | In Use UST**: 30459 | 0 | 0*	E	0.13 / 711.08	6

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
ALLSUPS 252 FINA	2007 CALLE LORCA SANTA FE NM 87501	ESE	0.25 / 1,300.07	18
	***FID | In Use AST | In Use UST**: 26511 | 0 | 2*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ALLSUPS 344	1899 SAINT MICHAELS DR SANTA FE NM 87501	W	0.09 / 450.60	4
	***FID | In Use AST | In Use UST**: 26541 | 0 | 3*			
KMART NUMBER 3301	1712 SAINT MICHAELS DR SANTA FE NM 87501	SSW	0.16 / 837.89	7
	***FID | In Use AST | In Use UST**: 28953 | 0 | 0*			
LLANO CHEVRON	1700 SAINT MICHAELS DR SANTA FE NM 87501	WSW	0.21 / 1,089.96	11
	***FID | In Use AST | In Use UST**: 1480 | 0 | 3*			
CHEVRON 76047	1700 SAINT MICHAELS DR SANTA FE NM 87501	WSW	0.21 / 1,089.96	11
	***FID | In Use AST | In Use UST**: 27330 | 0 | 0*			
HORACE CHRYSLER JEEP AND KIA	1701 ST MICHAELS DR SANTA FE NM 87501	W	0.21 / 1,131.65	12
	***FID | In Use AST | In Use UST**: 27353 | 0 | 0*			
PAULS TRANSMISSION	854 SAINT MICHAELS DR SANTA FE NM 87501	ESE	0.24 / 1,287.37	17
	***FID | In Use AST | In Use UST**: 29884 | 0 | 0*			

UST HIST - Underground Storage Tanks - Historical

A search of the UST HIST database, dated Aug 1, 2006 has found that there are 10 UST HIST site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
ALLSUPS 327	2000 SAINT MICHAELS DR SANTA FE NM 87501	ESE	0.10 / 545.77	5
	***Facility ID**: 26524* ***Tank ID | Tank Status**: 20915 | REMOVED, 20916 | REMOVED*			
SANTA FE PARTNERS	2005 SAINT MICHAELS DR SANTA FE NM 87501	E	0.13 / 711.08	6
	***Facility ID**: 30459* ***Tank ID | Tank Status**: 30188 | REMOVED*			
ALLSUPS 252 FINA	CORNER CALLE LORCA AND SANTA FE NM 87501	ESE	0.25 / 1,300.07	18
	***Facility ID**: 26511* ***Tank ID | Tank Status**: 20866 | REMOVED, 20868 | CURRENTLY IN USE, 20869 | CURRENTLY IN USE, 20865 | REMOVED, 20868 | CURRENTLY IN USE, 20869 | CURRENTLY IN USE, 20867 | REMOVED*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
ALLSUPS 344	1899 SAINT MICHAELS DR SANTA FE NM 87501	W	0.09 / 450.60	4
	***Facility ID**: 26541* ***Tank ID | Tank Status**: 20967 | CURRENTLY IN USE, 20969 | CURRENTLY IN USE, 20969 | CURRENTLY IN USE, 20968 | CURRENTLY IN USE, 20968 | CURRENTLY IN USE, 20967 | CURRENTLY IN USE*			
KMART NUMBER 3301	1712 SAINT MICHAELS DR SANTA FE NM 87501	SSW	0.16 / 837.89	7
	***Facility ID**: 28953* ***Tank ID | Tank Status**: 26608 | REMOVED*			
LLANO CHEVRON	1700 SAINT MICHAELS DR SANTA FE NM 87501	WSW	0.21 / 1,089.96	11
	***Facility ID**: 1480* ***Tank ID | Tank Status**: 18426 | CURRENTLY IN USE, 18424 | CURRENTLY IN USE, 18425 | CURRENTLY IN USE, 18425 | CURRENTLY IN USE, 18426 | CURRENTLY IN USE, 18424 | CURRENTLY IN USE*			
CHEVRON 76047	1700 SAINT MICHAELS DR SANTA FE NM 87501	WSW	0.21 / 1,089.96	11
	***Facility ID**: 27330* ***Tank ID | Tank Status**: 22800 | REMOVED, 22798 | REMOVED, 22801 | REMOVED, 22799 | REMOVED, 22797 | REMOVED*			
CHRYSLER PLYMOUTH DODGE OF SANTA FE	1701 SAINT MICHAELS DR SANTA FE NM 87501	W	0.21 / 1,131.65	12
	***Facility ID**: 27354*			
CHRYSLER PLYMOUTH	1701 ST MICHAELS DR SANTA FE NM 87501	W	0.21 / 1,131.65	12
	***Facility ID**: 27353* ***Tank ID | Tank Status**: 22856 | REMOVED, 22858 | REMOVED, 22857 | REMOVED*			
PAULS TRANSMISSION	854 SAINT MICHAELS DR SANTA FE NM 87501	ESE	0.24 / 1,287.37	17
	***Facility ID**: 29884* ***Tank ID | Tank Status**: 28723 | REMOVED*			

VCP - Voluntary Remediation Program Sites

A search of the VCP database, dated Sep 30, 2025 has found that there are 4 VCP site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Premier Nissan	2005 St. Michael's Drive Santa Fe NM	E	0.13 / 711.08	6
Smith's #491 Fuel Center	800 St. Michael's Drive Santa Fe NM	E	0.29 / 1,524.33	21
Park Avenue Cleaners - SF	720 St. Michaels Drive, Suite K Santa Fe NM	E	0.40 / 2,114.93	24

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
1710 Llano St.	1710 Llano Street, Santa Fe Santa Fe NM	WSW	0.27 / 1,446.19	20

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key

Tribal

INDIAN UST - Underground Storage Tanks on Tribal/Indian Lands

A search of the INDIAN UST database, dated Apr 21, 2025 has found that there are 1 INDIAN UST site(s) within approximately 0.25 miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Allsup's #323	Rt. 5, Box 36A Santa Fe NM ***Facility ID**: P192NM*	SSW	0.08 / 406.02	3

Non Standard

Federal

FINDS/FRS - Facility Registry Service/Facility Index

A search of the FINDS/FRS database, dated Oct 10, 2025 has found that there are 3 FINDS/FRS site(s) within approximately 0.02miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEW METHOD DRY CLEANERS/ST. MICHAELS DR.	1911A SAINT MICHAELS DRIVE SANTA FE NM 87505-7653 ***Registry ID**: 110004274151*	E	0.00 / 0.00	1
PROSPER INC DBA INSTY-PRINTS	1911 ST MICHAELS DR #C SANTA FE NM 87501 ***Registry ID**: 110004276104*	E	0.00 / 0.00	1
NEW METHOD DRY CLEANERS - SANTA FE	1911 A ST MICHAELS DR SANTA FE NM 87505 ***Registry ID**: 110022745528*	E	0.00 / 0.00	1

ICIS - Integrated Compliance Information System (ICIS)

A search of the ICIS database, dated May 3, 2025 has found that there are 1 ICIS site(s) within approximately 0.02miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEW METHOD DRY CLEANERS/ST. MICHAELS DR.	1911 ST. MICHAELS DR. SANTA FE NM 87505 ***Registry ID**: 110004274151*	E	0.00 / 0.00	1

FED DRYCLEANERS - Drycleaner Facilities

A search of the FED DRYCLEANERS database, dated Jul 19, 2025 has found that there are 1 FED DRYCLEANERS site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEW METHOD DRY CLEANERS/ST. MICHAELS DR.	1911A SAINT MICHAELS DRIVE SANTA FE NM 87505 ***FRS Facility ID**: 110004274151*	E	0.00 / 0.00	1

ALT FUELS - Alternative Fueling Stations

A search of the ALT FUELS database, dated Aug 1, 2025 has found that there are 3 ALT FUELS site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Fiesta Nissan	2005 St Michaels Dr Santa Fe NM 87505 ***ID**: 49916*	E	0.13 / 711.08	6
Fiesta Nissan	2005 St Michaels Dr Santa Fe NM 87505 ***ID**: 49915*	E	0.13 / 711.08	6
Fiesta Nissan	2005 Saint Michaels Drive Santa Fe NM 87505 ***ID**: 377488*	E	0.13 / 711.08	6

AFS - Air Facility System

A search of the AFS database, dated Oct 17, 2014 has found that there are 1 AFS site(s) within approximately 0.02miles of the project property.


Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
NEW METHOD DRY CLEANERS/ST. MICHAELS DR.	1911 ST. MICHAELS DR. SANTA FE NM 87505	E	0.00 / 0.00	1

State

SPILLS - Spills

A search of the SPILLS database, dated May 31, 2025 has found that there are 1 SPILLS site(s) within approximately 0.12miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
	2920 Nelson Rd MN 55359 Santa Fe NM ***Notification ID**	**Status**: 13872 | No Further Action Needed - Complaint Closed*	W	0.09 / 450.60	4



Map: 1.0 Mile Radius


Order Number: 25121700734

Address: 1911 St Michaels Dr, Santa Fe, NM

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.5 Mile Radius


Order Number: 25121700734

Address: 1911 St Michaels Dr, Santa Fe, NM

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.25 Mile Radius


Order Number: 25121700734

Address: 1911 St Michaels Dr, Santa Fe, NM

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Aerial **Year: 2024**


Address: 1911 St Michaels Dr, Santa Fe, NM

Source: ESRI World Imagery

Order Number: 25121700734

ERIS

© ERIS Information Limited Partnership



Topographic Map

Year: 2023

Order Number: 25121700734

Address: 1911 St Michaels Dr, NM

Quadrangle(s): Agua Fria NM, Santa Fe NM

Source: USGS Topographic Map

© ERIS Information Inc.

Detail Report

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	1 of 8	E	0.00 / 0.00	6,846.92 / 2	NEW METHOD DRY CLEANERS/ST. MICHAELS DR. 1911 ST. MICHAELS DR. SANTA FE NM 87505	AFS

Afs ID: 3504978036
Plant ID: 931328
Epa Region: 06
Plant County: Santa Fe
State No: 35
Primary Sic Code: 7216
Secondary Sic Code:
Naics Code: 812320
Fed Reportable: No
Current Hpv:
Loc Contrl Region: 00
Afs Gov Fac Code: 0
Operating Status: O
Epa Class Code: B
Epa Complian Stat: C
State Comp Status: C
Afs Gov Facility Des: PRIVATELY OWNED/OPERATED
Operating Status Def: Operating
Epa Classification Des: Potential uncontrolled emissions <100 tons/year
Epa Compliance Status: In Compliance With Procedural Requirements
State Compliance Status: In Compliance With Procedural Requirements

Actions

Plant ID: 931328
Anu1: 1
Date Achieved: 19960829
Penalty Amount: 0
Record Updated Dt: 19960903
Creation Date:
Key Action No:
Regional Data Element:
National Actn Type: FS
All Air Prog Codes: M
Result Code: MV
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:
National Action Desc: STATE CONDUCTED FCE/ON-SITE
All Air Program Def: M-MACT (Section 63 NESHAPS)
Result Def: IN VIOLATION
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Actions

Plant ID: 931328
Anu1: 2
Date Achieved: 19990108
Penalty Amount: 0
Record Updated Dt: 19990115
Creation Date:
Key Action No:
Regional Data Element:
National Actn Type: FS
All Air Prog Codes: M
Result Code: MC
Pollutant Code:
Violating Poll Cds:
Violation Type Cds:
National Action Desc: STATE CONDUCTED FCE/ON-SITE
All Air Program Def: M-MACT (Section 63 NESHAPS)
Result Def: IN COMPLIANCE
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Historical Compliance - Air Program Level

Air Program Code: M

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Air Program Code Ref: MACT (Section 63 NESHAPS)
Historical Compliance Date: 0604, 0701, 0702, 0703, 0704, 0801, 0802, 0803, 0804, 0901
Historical Compliance Status: W
Historical Compliance Stat Ref: In Violation With Regard To Procedural Compliance

Historical Compliance - Air Program Level

Air Program Code: M
Air Program Code Ref: MACT (Section 63 NESHAPS)
Historical Compliance Date: 0902, 0903, 0904, 1001, 1002, 1003, 1004, 1101, 1102, 1103, 1104, 1201, 1202, 1203, 1204, 1301, 1302, 1303, 1304, 1401, 1402, 1403
Historical Compliance Status: C
Historical Compliance Stat Ref: In Compliance With Procedural Requirements

Air Program

Plant ID: 931328
Air Program Code: M
Air Program Status: O
Pollutant Code: HC53
Chemical Abstract Service Nmbr:
Air Program Code Subparts:
Poll Classificatn: B
Poll Compli Status: C
Epa Class Code: B
Epa Compli Status: C
Air Program Code Ref: MACT (Section 63 NESHAPS)
Epa Classification Code Ref: Potential uncontrolled emissions <100 tons/year
Epa Compliance Status Ref: In Compliance With Procedural Requirements
Pollutant Code Ref:
Pollutant Classification Ref: Potential uncontrolled emissions <100 tons/year
Pollutant Complian Status Ref: In Compliance With Procedural Requirements

---

1	2 of 8	E	0.00 / 0.00	6,846.92 / 2	NEW METHOD DRY CLEANERS/ST. MICHAELS DR. 1911A SAINT MICHAELS DRIVE SANTA FE NM 87505	FED DRYCLEANERS

FRS Facility ID: 110004274151
NPDES IDs:
NAICS Codes: 812320
SIC Codes: 7216
Latitude: 35.65913
Longitude: -105.969238

1	3 of 8	E	0.00 / 0.00	6,846.92 / 2	PROSPER INC DBA INSTY-PRINTS 1911 ST MICHAELS DR #C SANTA FE NM 87501	FINDS/FRS

Registry ID: 110004276104
FIPS Code: 35049
HUC Code: 13020201
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 01-MAR-00
Update Date: 29-DEC-14
Interest Types: UNSPECIFIED UNIVERSE
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:
Conveyor: FRS-GEOCODE
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Congressional Dist No: 03
Census Block Code: 350490010023025
EPA Region Code: 06
County Name: SANTA FE
US/Mexico Border Ind:
Latitude: 35.65944
Longitude: -105.9685
Reference Point: CENTER OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 30
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110004276104
Program Acronyms:

RCRAINFO:NMD986668333

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	4 of 8	E	0.00 / 0.00	6,846.92 / 2	NEW METHOD DRY CLEANERS/ST. MICHAELS DR. 1911A SAINT MICHAELS DRIVE SANTA FE NM 87505-7653	FINDS/FRS

Registry ID: 110004274151
FIPS Code: 35049
HUC Code: 13020201
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 01-MAR-00
Update Date: 09-JAN-15
Interest Types: AIR MINOR, UNSPECIFIED UNIVERSE
SIC Codes: 7216
SIC Code Descriptions: DRYCLEANING PLANTS, EXCEPT RUG CLEANING
NAICS Codes: 812320
NAICS Code Descriptions: DRYCLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED).
Conveyor: RCRIS
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 03
Census Block Code: 350490011032004
EPA Region Code: 06
County Name: SANTA FE
US/Mexico Border Ind:
Latitude: 35.65913
Longitude: -105.969238
Reference Point: PLANT ENTRANCE (GENERAL)
Coord Collection Method: ADDRESS MATCHING-BLOCK FACE
Accuracy Value: 200
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110004274151
Program Acronyms:

AIR:NM0000003504978036, AIRS/AFS:3504978036, RCRAINFO:NMD981512999

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	5 of 8	E	0.00 / 0.00	6,846.92 / 2	NEW METHOD DRY CLEANERS - SANTA FE 1911 A ST MICHAELS DR SANTA FE NM 87505	FINDS/FRS

Registry ID: 110022745528

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

FIPS Code:	04935
HUC Code:	
Site Type Name:	STATIONARY
Location Description:	NM-TEMPO
Supplemental Location:	
Create Date:	19-SEP-05
Update Date:	29-DEC-14
Interest Types:	STATE MASTER
SIC Codes:	7216
SIC Code Descriptions:	DRYCLEANING PLANTS, EXCEPT RUG CLEANING
NAICS Codes:	
NAICS Code Descriptions:	
Conveyor:	
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	
Census Block Code:	
EPA Region Code:	06
County Name:	SANTA FE
US/Mexico Border Ind:	
Latitude:	
Longitude:	
Reference Point:	
Coord Collection Method:	
Accuracy Value:	
Datum:	NAD83
Source:	
Facility Detail Rprt URL:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110022745528
Program Acronyms:	

NM-TEMPO:1528

1	6 of 8	E	0.00 / 0.00	6,846.92 / 2	NEW METHOD DRY CLEANERS/ST. MICHAELS DR. 1911 ST. MICHAELS DR. SANTA FE NM 87505	ICIS

EPA Region:	06	**Federal Fac ID:**	
Registry ID:	110004274151	**Tribal Land Code:**	
Pgm Sys ID:	NM0000003504978036	**County:**	Santa Fe
Pgm Sys Acrnm:	AIR	**Latitude 83:**	35.659417
Permit Type:		**Longitude 83:**	-105.969356

1	7 of 8	E	0.00 / 0.00	6,846.92 / 2	PROSPER INC DBA INSTY-PRINTS 1911 ST MICHAELS DR #C SANTA FE NM 87501	RCRA NON GEN

Handler ID:	NMD986668333
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Sep 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	**Used Oil Transpor:**	No

Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		

Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Additional Handler Summary Details

Source Type:	N	**NAIC 1:**	
Seq No:	2	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20041209	**NAIC 4:**	
Active Site:	-----	**State:**	NM
Land Type:	P	**Location Latitude:**	35.659471
In Handler Univ:	N	**Location Longitude:**	-105.968463
In A Universe:	N	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	NM
Accessibility:		**State District:**	02
Region:	06		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	NM
State Waste Generator:	7
Short Term Generator:	N
Uni Waste:	N
Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20050510
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	PROSPER INC DBA INSTY-PRINTS

Location Street No:	1911
Location Street1:	ST MICHAELS DR #C
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87501
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	VICTOR PERRY
Contact Street No:	
Contact Street1:	1911 ST MICHAELS DR #C
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87501
Contact Country:	US
Contact Phone & Ext:	505-982-0122
Contact Fax:	
Contact Email Address:	
Contact Title:	
Owner Name:	PROSPER INC
Owner Type:	P
Owner Seq:	1
Operator Name:	PROSPER INC
Operator Type:	P
Operator Seq:	2
Public Notes:	

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	19890814
Handler Name:	PROSPER INC DBA INSTY-PRINTS
Fed Waste Generator:	2
Generator Code Description:	Small Quantity Generator
Source Type:	Notification
TSD Activity:	N

Waste Code Details

Waste Code:	D002
Waste Code Desc:	CORROSIVE WASTE

Hazardous Waste Handler Details

Seq No:	2
Receive Date:	20041209
Handler Name:	PROSPER INC DBA INSTY-PRINTS
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Notification
TSD Activity:	N

Waste Code Details

Waste Code:	D002
Waste Code Desc:	CORROSIVE WASTE

Owner/Operator Details

Owner/Operator Ind: Current Operator **Street No:**

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Type:	Private	**Street1:**	UNKNOWN
Name:	PROSPER INC	**Street2:**	
Dt Became Current:		**City:**	UNKNOWN
Dt Ended Current:		**State:**	NM
Phone:	000-000-0000	**Country:**	
Source Type:	Notification	**Zip:**	00000-0000
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street1:**	UNKNOWN
Name:	PROSPER INC	**Street2:**	
Dt Became Current:		**City:**	UNKNOWN
Dt Ended Current:		**State:**	NM
Phone:	000-000-0000	**Country:**	
Source Type:	Notification	**Zip:**	00000-0000

Historical Handler Details

Receive Dt:	19890814
Generator Code Description:	Small Quantity Generator
Handler Name:	PROSPER INC DBA INSTY-PRINTS

1	*8 of 8*	*E*	*0.00 / 0.00*	*6,846.92 / 2*	***NEW METHOD CLNRS 1911-A ST MICHAELS DR SANTA FE NM 87505***	***RCRA NON GEN***

Handler ID:	NMD981512999
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Sep 2025.

Evaluation Details

Eval Start Date:	20041208
Eval Type Desc:	COMPLIANCE ASSISTANCE VISIT
Viol Short Desc:	
Actual Rtc Date:	
Eval Agency:	State

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	**NAIC 1:**	
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Receive Date:	20101102	**NAIC 4:**	
Active Site:	-----	**State:**	NM
Land Type:	P	**Location Latitude:**	35.659469
In Handler Univ:	N	**Location Longitude:**	-105.968544
In A Universe:	N	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	NM
Accessibility:		**State District:**	02
Region:	06		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	NM
State Waste Generator:	6
Short Term Generator:	N
Uni Waste:	N
Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20101123
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	NEW METHOD CLNRS
Location Street No:	1911-A
Location Street1:	ST MICHAELS DR
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87505
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	GAIL KAPLAN
Contact Street No:	
Contact Street1:	1911-A ST MICHAELS DR
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87505

Contact Country: US
Contact Phone & Ext: 505-982-0271
Contact Fax:
Contact Email Address:
Contact Title:
Owner Name: GAIL KAPLAN OR SONDRA EVERHART
Owner Type: P
Owner Seq: 1
Operator Name: KOCH JAMES
Operator Type: P
Operator Seq: 2
Public Notes:

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 19960515
Handler Name: NEW METHOD CLNRS
Fed Waste Generator: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification
TSD Activity: N

Waste Code Details

Waste Code: F002
Waste Code Desc: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Seq No: 2
Receive Date: 20030501
Handler Name: NEW METHOD CLNRS
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Notification
TSD Activity: N

Hazardous Waste Handler Details

Seq No: 3
Receive Date: 20041209
Handler Name: NEW METHOD CLNRS
Fed Waste Generator: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification
TSD Activity: N

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20101102
Handler Name: NEW METHOD CLNRS
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

TSD Activity: N

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street1:**	UNKNOWN
Name:	KOCH JAMES	**Street2:**	
Dt Became Current:		**City:**	UNKNOWN
Dt Ended Current:		**State:**	NM
Phone:	000-000-0000	**Country:**	
Source Type:	Implementer	**Zip:**	00000-0000

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street1:**	1911-A ST MICHAELS DRIVE
Name:	GAIL KAPLAN OR SONDRA EVERHART	**Street2:**	
Dt Became Current:		**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:	505-982-0271	**Country:**	
Source Type:	Notification	**Zip:**	87505

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street1:**	1911-A ST MICHAELS DRIVE
Name:	GAIL KAPLAN OR SONDRA EVERHART	**Street2:**	
Dt Became Current:		**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:	505-982-0271	**Country:**	
Source Type:	Implementer	**Zip:**	87505

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street1:**	UNKNOWN
Name:	KOCH JAMES	**Street2:**	
Dt Became Current:		**City:**	UNKNOWN
Dt Ended Current:		**State:**	NM
Phone:	000-000-0000	**Country:**	
Source Type:	Notification	**Zip:**	00000-0000

Historical Handler Details

Receive Dt:	20041209
Generator Code Description:	Very Small Quantity Generator
Handler Name:	NEW METHOD CLNRS

Receive Dt:	20030501
Generator Code Description:	Not a Generator, Verified
Handler Name:	NEW METHOD CLNRS

Receive Dt:	19960515
Generator Code Description:	Very Small Quantity Generator
Handler Name:	NEW METHOD CLNRS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	1 of1	W	0.03 / 184.74	6,839.60 / -6	**THE SHERWIN-WILLIAMS STORE #7252** **1905 ST MICHAELS DR** **SANTA FE NM 87501**	RCRA VSQG

Handler ID: NMD076447721
Generator Status: VSG
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Sep 2025.

Evaluation Details

Eval Start Date:	20200217
Eval Type Desc:	COMPLIANCE EVALUATION INSPECTION
Viol Short Desc:	
Actual Rtc Date:	
Eval Agency:	State

Eval Start Date:	20100915
Eval Type Desc:	COMPLIANCE ASSISTANCE VISIT
Viol Short Desc:	
Actual Rtc Date:	
Eval Agency:	State

Handler Summary

Importer:	No	***Used Oil Transpor:***	No
Mixed Waste Gen:	No	***Used Oil Trans Fac:***	No
Transporter:	No	***Used Oil Processor:***	No
Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	***NAIC 1:***	44412
Seq No:	3	***NAIC 2:***	
Non Notifier:		***NAIC 3:***	
Receive Date:	20200219	***NAIC 4:***	
Active Site:	H----	***State:***	NM
Land Type:	P	***Location Latitude:***	35.66253
In Handler Univ:	Y	***Location Longitude:***	-105.977229
In A Universe:	Y	***Loc GIS Primary:***	N
Gen Status:	VSG	***Loc GIS Origin:***	AG
Report Cycle:		***State District Owner:***	NM
Accessibility:		***State District:***	02
Region:	06		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	NM		
State Waste Generator:	N		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	------		
As Converter Tsdf:	------		
As State Regulated Tsdf:	------		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	------		
Permwrk ID:	------		
Perm Prog:	------		
Pcwrkld:	------		
Closwrkld:	------		
GPRA Ca:	N		
Cawrkld:	N		

Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20200220
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	THE SHERWIN-WILLIAMS STORE #7252
Location Street No:	1905
Location Street1:	ST MICHAELS DR
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87501
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	LANE HALL
Contact Street No:	1905
Contact Street1:	ST MICHAELS DR
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87501
Contact Country:	US
Contact Phone & Ext:	505-982-3559
Contact Fax:	
Contact Email Address:	SW7252@SHERWIN.COM
Contact Title:	STORE MANAGER
Owner Name:	LORRAINE MORGAN
Owner Type:	P
Owner Seq:	1
Operator Name:	THE SHERWIN-WILLIAMS STORE #7252
Operator Type:	P
Operator Seq:	2
Public Notes:	

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	19800818
Handler Name:	SHERWIN WILLIAMS CO
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Notification
TSD Activity:	N

Waste Code Details

Waste Code:	D000
Waste Code Desc:	DESCRIPTION
Waste Code:	D001

Waste Code Desc:	IGNITABLE WASTE
Waste Code:	D002
Waste Code Desc:	CORROSIVE WASTE
Waste Code:	D003
Waste Code Desc:	REACTIVE WASTE
Waste Code:	F002
Waste Code Desc:	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F003
Waste Code Desc:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F005
Waste Code Desc:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F017
Waste Code Desc:	DESCRIPTION
Waste Code:	F018
Waste Code Desc:	DESCRIPTION
Waste Code:	P090
Waste Code Desc:	DESCRIPTION
Waste Code:	U002
Waste Code Desc:	2-PROPANONE (I) (OR) ACETONE (I)
Waste Code:	U031
Waste Code Desc:	1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)
Waste Code:	U112
Waste Code Desc:	ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)
Waste Code:	U150
Waste Code Desc:	L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN
Waste Code:	U154
Waste Code Desc:	METHANOL (I) (OR) METHYL ALCOHOL (I)
Waste Code:	U159
Waste Code Desc:	2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)
Waste Code:	U161
Waste Code Desc:	4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-
Waste Code:	U220
Waste Code Desc:	BENZENE, METHYL- (OR) TOLUENE
Waste Code:	U239
Waste Code Desc:	BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20100216
Handler Name: SHERWIN WILLIAMS CO
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer
TSD Activity: N

Waste Code Details

Waste Code: D000
Waste Code Desc: DESCRIPTION

Waste Code: D001
Waste Code Desc: IGNITABLE WASTE

Waste Code: D002
Waste Code Desc: CORROSIVE WASTE

Waste Code: D003
Waste Code Desc: REACTIVE WASTE

Waste Code: F002
Waste Code Desc: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F003
Waste Code Desc: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Code Desc: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F017
Waste Code Desc: DESCRIPTION

Waste Code: F018
Waste Code Desc: DESCRIPTION

Waste Code: P090
Waste Code Desc: DESCRIPTION

Waste Code: U002
Waste Code Desc: 2-PROPANONE (I) (OR) ACETONE (I)

Waste Code: U031
Waste Code Desc: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Waste Code: U112
Waste Code Desc: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

Waste Code: U150
Waste Code Desc: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

Waste Code: U154
Waste Code Desc: METHANOL (I) (OR) METHYL ALCOHOL (I)

Waste Code: U159
Waste Code Desc: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Waste Code: U161
Waste Code Desc: 4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-

Waste Code: U220
Waste Code Desc: BENZENE, METHYL- (OR) TOLUENE

Waste Code: U239
Waste Code Desc: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Hazardous Waste Handler Details

Seq No: 2
Receive Date: 20100614
Handler Name: THE SHERWIN-WILLIAMS STORE #7252
Fed Waste Generator: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification
TSD Activity: N

Waste Code Details

Waste Code: D001
Waste Code Desc: IGNITABLE WASTE

Waste Code: P090
Waste Code Desc: DESCRIPTION

Waste Code: U002
Waste Code Desc: 2-PROPANONE (I) (OR) ACETONE (I)

Waste Code: U031
Waste Code Desc: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Waste Code: U112
Waste Code Desc: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

Waste Code: U150
Waste Code Desc: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

Waste Code: U154
Waste Code Desc: METHANOL (I) (OR) METHYL ALCOHOL (I)

Waste Code: U159
Waste Code Desc: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Waste Code: U161
Waste Code Desc: 4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-

Waste Code: U220
Waste Code Desc: BENZENE, METHYL- (OR) TOLUENE

Waste Code: U239
Waste Code Desc: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Hazardous Waste Handler Details

Seq No: 2
Receive Date: 20110411
Handler Name: THE SHERWIN-WILLIAMS STORE #7252
Fed Waste Generator: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer
TSD Activity: N

Waste Code Details

Waste Code: D001
Waste Code Desc: IGNITABLE WASTE

Waste Code: P090
Waste Code Desc: DESCRIPTION

Waste Code: U002
Waste Code Desc: 2-PROPANONE (I) (OR) ACETONE (I)

Waste Code: U031
Waste Code Desc: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

Waste Code: U112
Waste Code Desc: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

Waste Code: U150
Waste Code Desc: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

Waste Code: U154
Waste Code Desc: METHANOL (I) (OR) METHYL ALCOHOL (I)

Waste Code: U159
Waste Code Desc: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

Waste Code: U161
Waste Code Desc: 4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-

Waste Code: U220
Waste Code Desc: BENZENE, METHYL- (OR) TOLUENE

Waste Code: U239
Waste Code Desc: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Hazardous Waste Handler Details

Seq No: 3
Receive Date: 20200219
Handler Name: THE SHERWIN-WILLIAMS STORE #7252
Fed Waste Generator: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer
TSD Activity: N

Waste Code Details

Waste Code: D001
Waste Code Desc: IGNITABLE WASTE

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Street No: 813
Street1: SALAMANCA ST NW

Name:	LORRAINE MORGAN	**Street2:**	
Dt Became Current:		**City:**	ALBUQUERQUE
Dt Ended Current:		**State:**	NM
Phone:		**Country:**	US
Source Type:	Implementer	**Zip:**	87107
Owner/Operator Ind:	Current Operator	**Street No:**	1905
Type:	Private	**Street1:**	ST MICHAELS DR
Name:	THE SHERWIN-WILLIAMS STORE #7252	**Street2:**	
Dt Became Current:	19960101	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:		**Country:**	US
Source Type:	Implementer	**Zip:**	87501
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street1:**	UNKNOWN
Name:	SHERWIN WILLIAMS CORP	**Street2:**	
Dt Became Current:		**City:**	UNKNOWN
Dt Ended Current:		**State:**	NM
Phone:	000-000-0000	**Country:**	
Source Type:	Implementer	**Zip:**	00000-0000
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street1:**	PO BOX 1794
Name:	RED II, LLC	**Street2:**	
Dt Became Current:	20060101	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:		**Country:**	US
Source Type:	Notification	**Zip:**	87504
Owner/Operator Ind:	Current Operator	**Street No:**	1905
Type:	Private	**Street1:**	ST MICHAELS DR
Name:	THE SHERWIN-WILLIAMS STORE #7252	**Street2:**	
Dt Became Current:	19960101	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:		**Country:**	US
Source Type:	Notification	**Zip:**	87501
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street1:**	UNKNOWN
Name:	SHERWIN WILLIAMS CORP	**Street2:**	
Dt Became Current:		**City:**	UNKNOWN
Dt Ended Current:		**State:**	NM
Phone:	000-000-0000	**Country:**	
Source Type:	Notification	**Zip:**	00000-0000
Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street1:**	PO BOX 1794
Name:	RED II, LLC	**Street2:**	
Dt Became Current:	20060101	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:		**Country:**	US
Source Type:	Implementer	**Zip:**	87504

Historical Handler Details

Receive Dt:	20110411
Generator Code Description:	Very Small Quantity Generator
Handler Name:	THE SHERWIN-WILLIAMS STORE #7252
Receive Dt:	20100614
Generator Code Description:	Small Quantity Generator
Handler Name:	THE SHERWIN-WILLIAMS STORE #7252
Receive Dt:	20100216
Generator Code Description:	Not a Generator, Verified
Handler Name:	SHERWIN WILLIAMS CO

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Receive Dt: 19800818
Generator Code Description: Not a Generator, Verified
Handler Name: SHERWIN WILLIAMS CO

---

3 | **1 of1** | **SSW** | **0.08 / 406.02** | **6,842.12 / -3** | **Allsup's #323, Rt. 5, Box 36A, Santa Fe NM** | **INDIAN UST**

Facility ID: P192NM
Latitude: 35.65866192
Longitude: -105.9691047
Tribe: Pueblo of Tesuque, New Mexico
Land Status: Indian Land
Region: 6
Loc Name: Allsup's #323

Tank

Tank Name: Tank 1

Region 6 UST Tank Info

Tank Status: Permanently Out of Use
Date Installed: 3/1/1981
Tnk Status Chng Dt:
Substance Description: Gasoline (containing <=10% ethanol)
Tank Capacity: 8000
Fed Reg Tank: TRUE

Region 6 UST Tank Compartments Info

Compartment Nm: Tank 1 Compartment
Compartment Stat: Permanently Out of Use
Tnk Status Chng Dt:
Compartment Cap: 8000
Substance Desc: Gasoline (containing <=10% ethanol)
Overfill Installed: FALSE
Spill Installed: Unknown
Fed Regulated: TRUE

Tank

Tank Name: Tank 2

Region 6 UST Tank Info

Tank Status: Permanently Out of Use
Date Installed: 3/1/1981
Tnk Status Chng Dt:
Substance Description: Gasoline (containing <=10% ethanol)
Tank Capacity: 8000
Fed Reg Tank: TRUE

Region 6 UST Tank Compartments Info

Compartment Nm: Tank 2 Compartment
Compartment Stat: Permanently Out of Use
Tnk Status Chng Dt:
Compartment Cap: 8000
Substance Desc: Gasoline (containing <=10% ethanol)
Overfill Installed: FALSE
Spill Installed: Unknown
Fed Regulated: TRUE

---

4 | **1 of6** | **W** | **0.09 / 450.60** | **6,834.88 / -10** | **ATEX ALLSUPS #327, 1899 SAINT MICHAELS DR, SANTA FE NM** | **LST**

Release ID: 1826
Facility ID: 26541
Status: No Further Action, Confirmed Release
Address:
City:
Latitude (Map): 35.659652
Longitude (Map): -105.970103
Address (Map): 1899 SAINT MICHAELS DR
Address2 (Map):
City (Map): SANTA FE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

County:		**State (Map):**	NM
Address (NFA):	1899 SAINT MICHAELS DR	**Zip (Map):**	87501
City (NFA):	SANTA FE	**Address (Priority):**	
County (NFA):	SANTA FE	**City (Priority):**	
Facility Release IDs (Map):	1826	**County (Priority):**	

Data Source: NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)

PSTB No Further Action Sites

Status: No Further Action, Confirmed Release
NFA Date: 10/26/1993
NFA PDF: https://cloud.env.nm.gov/resources/collection/10811

Leaking Petroleum Storage Tank Sites

Status Date Dt:	1993-10-26 00:00:00 UTC	**NAPL Off Site Val:**	0
Within SWPA Val:	0	**Plume Area No:**	
Surface Water Val:	0	**Plume Area Val:**	2
Private Well Val:	0	**Max Thickness No:**	
Municipal Well Val:	0	**Max Thickness Val:**	
LUWU Sco:	0	**NAPLSco:**	0
Surficial Conc Des:		**Priority2 Sco:**	0
Surficial Conc Val:	0	**Impact Type Des:**	
Leaching Conc Des:		**Impact Type Val:**	0
Leaching Conc Val:	0	**WS Type Des:**	
Construct Conc Des:		**WS Type Val:**	0
Construct Conc Val:	0	**WTR Sys Repl Des:**	
Building Type Des:		**WTR Sys Repl Val:**	0
Building Type Val:	0	**Population No:**	
Vad Off Site Val:	1	**Population Val:**	1
Vadose Sco:	0	**WS Sco:**	0
Conc Des:		**Toxic Vapor Des:**	
Conc Val:	0	**Toxic Vapor Val:**	0
Plume Mob Des:		**Toxic Vapor Sco:**	0
Plume Mob Val:	0	**Priority1 Sco:**	0
GWDPP Off Site Val:	0	**Total Sco:**	0
Benzene Area No:		**Tempo Total Sco:**	
Benzene Area Val:	1	**Current Priority:**	
GWDPP Sco:	0	**Tempo Current Rank:**	
Priority3 Sco:	0	**Tempo Curr Priorty:**	
CSS Age Des:		**Point X:**	-105.970103
CSS Age Val:	0	**Point Y:**	35.659651999999994
CSS Type Des:		**Irrigation Well Val:**	0
CSS Type Val:	0	**Subsurf Conc Des:**	
CSS Off Site Val:	1	**Subsurface Conc Val:**	0
CSS Sco:	0	**Petrol Soil Bldg Val:**	1
CSS Volume No:		**Petrol Soil Vol Val:**	0
CSS Volume Val:	3	**Hydraulic Grad Val:**	0
Release Pm:	UNKNOWN	**Depth to GW:**	
NAPL Type Des:		**Depth to GW Val:**	2
NAPL Type Val:	0	**Explosive Vapor Des:**	
NAPL Age Des:		**Explosive Vapor Val:**	0
NAPL Age Val:	0	**Explosive Vapor Sco:**	0
NAPLCondition Des:		**Eco Impact Val:**	0
NAPLCondition Val:	0	**Eco Impact Sco:**	0

Facility Name: ALLSUP'S # 102344
Current Status: No Further Action, Confirmed Release
Aquifer Water Quality Des:
Aquifer Water Quality Val: 0
Residential Property Val: 0
NAPL Plume Mobility Des:
NAPL Plume Mobility Val: 0
Property Damage Des:
Property Damage Val: 0
Property Damage Sco: 0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
4	2 of6	W	0.09 / 450.60	6,834.88 / -10	ATEX ALLSUPS #327 1899 SAINT MICHAELS DR SANTA FE NM	LUST HIST

Form No:	1826	**Contact:**	ALLSUPS CONVENI
Facility ID:	26541	**CRC 32:**	12648962
Status:	NFA	**Aggrav Factor Score:**	
Facility Status:	No Further Action	**Mitigat Factor Score:**	
Stat Date:		**Water Supply Impact:**	U
Date Reported:	29-APR-93	**Vapor Explos Impact:**	U
SR Result:		**Prpty Damage Impact:**	U
Priority:		**Staff:**	UNK
Score:		**Unloc:**	FALSE
St:		**Latitude:**	0
Site Priority Rank:		**Longitude:**	0
Total Score:		**Facility County:**	
Tie Score:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
4	3 of6	W	0.09 / 450.60	6,834.88 / -10	2920 Nelson Rd MN 55359 Santa Fe NM	SPILLS

Notification ID:	13872	**Nearest City:**	Santa Fe
Notification Type:	Spills	**County:**	Santa Fe
Notification Date:	10/16/2019 9:08:18 AM	**Incident District:**	
Notificat Priority:		**Field Office:**	
EJ Issue:		**Created by:**	
Assigned Bureau:	Ground Water Quality Bureau	**Date Created:**	10/16/2019 9:08:18 AM
Assigned Staff:		**Entered Sep ID:**	public
Status Date:	10/23/2019 11:59:37 AM		

Status:	No Further Action Needed - Complaint Closed
Suspect Resp Party:	Groendyke Transportation
Resp Party Address1:	5555 Broadway SE
Resp Party Address2:	
Resp Party City:	Albuquerque
Resp Party State:	NM
Resp Party Zip:	87105
Resp Party Phone:	505-873-4030
Reporter Name:	Chris Hamilton
Reporter Address 1:	2905 Rodeo Park Drive East
Reporter Address 2:	Building 1
Reporter City:	Santa Fe
Reporter State:	New Mexico
Reporter Zip:	87505
Reporter Phone:	505-476-4391
Reporter Email:	Chris.Hamilton@state.nm.us
Description:	Groendyke Transportation spilled @25-30 gallons of diesel fuel from their delivery truck's onboard fuel tank when it was punctured by a plate which popped up and struck the fuel tank. The spill occurred late in the afternoon on 10/15/2019. Allsups Petroleum Inc.reported the spill to the Petroleum Storage Tank bureau at @ 8:45 AM on 10/16/2019. Allsups Petroleum Inc. reported that Groendyke Transportation was taking responsibility for the spill and had already hired an Environmental firm to clean up and document the spill. For referral to the Ground Water Quality Bureau.
Location:	Allsups 334, 1899 Saint Michaels Drive, Santa Fe, NM 87501. The site is located on the NW corner of Saint Michaels Drive and 5th Street.
Data Source:	Environmental Notification Reporting - Spills Reported From 2015 to 2019 (as of 31 Dec 2019)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
4	4 of6	W	0.09 / 450.60	6,834.88 / -10	ALLSUPS 344 1899 SAINT MICHAELS DR SANTA FE NM 87501	TANKS

FID:	26541	**Sold AST:**	0
In Use AST:	0	**Sold UST:**	0
In Use UST:	3	**No Data AST:**	0
Temp Out AST:	0	**No Data UST:**	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Temp Out UST:	0	**County:**	SANTA FE
Removed AST:	0	**Owner ID:**	16400
Removed UST:	0	**City (Deliv Prohib):**	
Exempt AST:	0	**Cty (Del Prohib):**	
Exempt UST:	0		
Owner Name:	ALLSUPS CONVENIENCE STORES INC		
Fac Name (Del Prohibition):			
Fac Owner (Deliv Prohib):			
Fac Add (Delivery Prohibition):			
Source:	All Storage Tank List		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
4	5 of6	W	0.09 / 450.60	6,834.88 / -10	ALLSUP'S # 102344 1899 SAINT MICHAELS DR SANTA FE NM 87501	UST

Facility ID:	26541	**Facility (Active):**	ALLSUP'S # 102344
Facility Name:	ALLSUP'S # 102344	**Street (Active):**	1899 SAINT MICHAELS DR
Facility Address:	1899 SAINT MICHAELS DR	**Street 2 (Active):**	
Address 2:		**Zip (Active):**	87501
City:	SANTA FE	**City (Active):**	SANTA FE
County:	SANTA FE	**County (Active):**	SANTA FE
Zip:	87501	**Fac Name (Map-In):**	
Fac Name (Map):	ALLSUP'S # 102344	**Fac Addr (Map-In):**	
Fac Addr (Map):	1899 SAINT MICHAELS DR	**Address 2 (Map-In):**	
Address2 (Map):		**City (Map-In):**	
City (Map):	SANTA FE	**County (Map-In):**	
County (Map):	SANTA FE	**Zip Cd (Map-In):**	
Fac ZIP (Map):	87501	**Lat (Map-In):**	
Latitude (Map):	35.659652	**Lon (Map-In):**	
Longitude (Map):	-105.970103	**Fac Name (Prohib):**	
Fac Name (Map-Pro):		**Fac Addr (Prohib):**	
Fac Addr (Map-Pro):		**City (Prohib):**	
City (Map-Pro):		**County (Prohib):**	
County (Map-Pro):			
Data Source:	NMED PSTB All Storage Tanks Report (as of 14 Oct 2025); NMED Open Data - Underground Storage Tank Facilities (Map) (as of 3 Nov 2025); NMED PSTB Active Storage Tank List (Active) (as of 14 Oct 2025)		

NMED PSTB Report - Tank Detail(s) (as of October 14, 2025)

In Use UST:	3	**Sold UST:**	0
Removed UST:	0	**No Data UST:**	0
Exempt UST:	0	**Owner ID:**	276362
Temp Out UST:	0	**Owner Name:**	BW GAS CONVENIENCE JOBBER LLC

NM Open Data UST

Active:	-1	**Oldest Tnk Age Type:**	25 years or more
UST:	3	**AST:**	0
UST Curr in Use:	3	**AST Curr in Use:**	0
UST Exempt:	0	**AST Exempt:**	0
UST Removed:	0	**AST Removed:**	0
UST Temp Out of Use:	0	**AST Temp Out of Use:**	0
Tanks:	3	**Shape:**	
Tanks Curr in Use:	3	**Owner ID:**	276362
Tanks Exempt:	0	**Owner Size Type:**	12 or more
Tanks Removed:	0	**Owner Name:**	BW GAS CONVENIENCE JOBBER LLC
Tanks Temp Out of Use:	0		

NMED PSTB Active Storage Tank List (as of October 14, 2025)

UST:	3
Owner ID:	276362
Owner Name:	BW GAS CONVENIENCE JOBBER LLC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
4	6 of6	W	0.09 / 450.60	6,834.88 / -10	ALLSUPS 344 1899 SAINT MICHAELS DR SANTA FE NM 87501	UST HIST

Facility ID: 26541
Facility Addr2:
Facility County: SANTA FE

Details

Tank ID: 20967
Tank Type: Underground
Tank Status: CURRENTLY IN USE
Tank Capacity (GAL): 12000
Tank Contents: UNLEADED GASOLINE
Owner ID: 16400
Owner Name: ALLSUPS CONVENIENCE STORES INC
Owner Address: PO BOX 1907
Owner Add2:
Owner City: CLOVIS
Owner St: NM
Owner ZIP: 88101
Owner Ph: 505-769-2311

Details

Tank ID: 20969
Tank Type: Underground
Tank Status: CURRENTLY IN USE
Tank Capacity (GAL): 10000
Tank Contents: DIESEL
Owner ID: 16400
Owner Name: ALLSUPS PETROLEUM INC
Owner Address: PO BOX 1907
Owner Add2:
Owner City: CLOVIS
Owner St: NM
Owner ZIP: 88102
Owner Ph: 505-769-2311

Details

Tank ID: 20969
Tank Type: Underground
Tank Status: CURRENTLY IN USE
Tank Capacity (GAL): 10000
Tank Contents: DIESEL
Owner ID: 16400
Owner Name: ALLSUPS CONVENIENCE STORES INC
Owner Address: PO BOX 1907
Owner Add2:
Owner City: CLOVIS
Owner St: NM
Owner ZIP: 88101
Owner Ph: 505-769-2311

Details

Tank ID: 20968
Tank Type: Underground
Tank Status: CURRENTLY IN USE
Tank Capacity (GAL): 12000
Tank Contents: SUPER UNLEADED
Owner ID: 16400
Owner Name: ALLSUPS CONVENIENCE STORES INC
Owner Address: PO BOX 1907
Owner Add2:
Owner City: CLOVIS
Owner St: NM
Owner ZIP: 88101
Owner Ph: 505-769-2311

Details

Tank ID: 20968
Tank Type: Underground
Tank Status: CURRENTLY IN USE
Tank Capacity (GAL): 12000
Tank Contents: SUPER UNLEADED
Owner ID: 16400
Owner Name: ALLSUPS PETROLEUM INC
Owner Address: PO BOX 1907
Owner Add2:
Owner City: CLOVIS
Owner St: NM
Owner ZIP: 88102
Owner Ph: 505-769-2311

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Details

Tank ID:	20967	***Owner Add2:***	
Tank Type:	Underground	***Owner City:***	CLOVIS
Tank Status:	CURRENTLY IN USE	***Owner St:***	NM
Tank Capacity (GAL):	12000	***Owner ZIP:***	88102
Tank Contents:	UNLEADED GASOLINE	***Owner Ph:***	505-769-2311
Owner ID:	16400		
Owner Name:	ALLSUPS PETROLEUM INC		
Owner Address:	PO BOX 1907		

5	*1 of3*	*ESE*	*0.10 / 545.77*	*6,863.27 / 18*	***ALLSUPS 327*** ***2000 SAINT MICHAELS DR*** ***SANTA FE NM 87501***	***TANKS***

FID:	26524	***Sold AST:***	0
In Use AST:	0	***Sold UST:***	0
In Use UST:	0	***No Data AST:***	0
Temp Out AST:	0	***No Data UST:***	0
Temp Out UST:	0	***County:***	SANTA FE
Removed AST:	0	***Owner ID:***	16400
Removed UST:	2	***City (Deliv Prohib):***	
Exempt AST:	0	***Cty (Del Prohib):***	
Exempt UST:	0		
Owner Name:	ALLSUPS CONVENIENCE STORES INC		
Fac Name (Del Prohibition):			
Fac Owner (Deliv Prohib):			
Fac Add (Delivery Prohibition):			
Source:	All Storage Tank List		

5	*2 of3*	*ESE*	*0.10 / 545.77*	*6,863.27 / 18*	***ALLSUPS 327*** ***2000 SAINT MICHAELS DR*** ***SANTA FE NM 87501***	***UST***

Facility ID:	26524	***Facility (Active):***	
Facility Name:	ALLSUPS 327	***Street (Active):***	
Facility Address:	2000 SAINT MICHAELS DR	***Street 2 (Active):***	
Address 2:		***Zip (Active):***	
City:	SANTA FE	***City (Active):***	
County:	SANTA FE	***County (Active):***	
Zip:	87501	***Fac Name (Map-In):***	ALLSUPS 327
Fac Name (Map):		***Fac Addr (Map-In):***	2000 SAINT MICHAELS DR
Fac Addr (Map):		***Address 2 (Map-In):***	
Address2 (Map):		***City (Map-In):***	SANTA FE
City (Map):		***County (Map-In):***	SANTA FE
County (Map):		***Zip Cd (Map-In):***	87501
Fac ZIP (Map):		***Lat (Map-In):***	
Latitude (Map):		***Lon (Map-In):***	
Longitude (Map):		***Fac Name (Prohib):***	
Fac Name (Map-Pro):		***Fac Addr (Prohib):***	
Fac Addr (Map-Pro):		***City (Prohib):***	
City (Map-Pro):		***County (Prohib):***	
County (Map-Pro):			
Data Source:	NMED PSTB All Storage Tanks Report (as of 14 Oct 2025); NMED Open Data - Inactive Facilities (Map-In) (as of 3 Nov 2025)		

NMED PSTB Report - Tank Detail(s) (as of October 14, 2025)

In Use UST:	0	***Sold UST:***	0
Removed UST:	2	***No Data UST:***	0
Exempt UST:	0	***Owner ID:***	16400
Temp Out UST:	0	***Owner Name:***	ALLSUPS PETROLEUM INC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

NMED Open Data - Inactive Facilities

Active:	0	***Oldest Tnk Age Type:***	
UST:	2	***AST:***	0
UST Curr in Use:	0	***AST Curr in Use:***	0
UST Exempt:	0	***AST Exempt:***	0
UST Removed:	2	***AST Removed:***	0
UST Temp Out of Use:	0	***AST Temp Out of Use:***	0
Tanks:	2	***Shape:***	
Tanks Curr in Use:	0	***Owner ID:***	16400
Tanks Exempt:	0	***Owner Size Type:***	
Tanks Removed:	2	***Owner Name:***	ALLSUPS PETROLEUM INC
TanksTemp OutofUse:	0		

5	***3 of3***	***ESE***	***0.10 / 545.77***	***6,863.27 / 18***	***ALLSUPS 327 2000 SAINT MICHAELS DR SANTA FE NM 87501***	***UST HIST***

Facility ID:	26524
Facility Addr2:	
Facility County:	SANTA FE

Details

Tank ID:	20915	***Owner Add2:***	
Tank Type:	Underground	***Owner City:***	CLOVIS
Tank Status:	REMOVED	***Owner St:***	NM
Tank Capacity (GAL):	10000	***Owner ZIP:***	88102
Tank Contents:	GASOLINE UNKNOWN TYPE	***Owner Ph:***	505-769-2311
Owner ID:	16400		
Owner Name:	ALLSUPS PETROLEUM INC		
Owner Address:	PO BOX 1907		

Details

Tank ID:	20916	***Owner Add2:***	
Tank Type:	Underground	***Owner City:***	CLOVIS
Tank Status:	REMOVED	***Owner St:***	NM
Tank Capacity (GAL):	6000	***Owner ZIP:***	88102
Tank Contents:	GASOLINE UNKNOWN TYPE	***Owner Ph:***	505-769-2311
Owner ID:	16400		
Owner Name:	ALLSUPS PETROLEUM INC		
Owner Address:	PO BOX 1907		

6	***1 of8***	***E***	***0.13 / 711.08***	***6,870.84 / 25***	***Fiesta Nissan 2005 St Michaels Dr Santa Fe NM 87505***	***ALT FUELS***

ID:	49915	***CNG Dispenser No:***	
Fuel Type Code:	ELEC: Electric	***CNG Site Renew Src:***	
Station Phone:	505-955-1000	***CNG Tot Compr Cap:***	
Expected Date:		***CNG Storage Cap:***	
BD Blends:		***CNG Fill Type Code:***	
NG PSI:		***CNG PSI:***	
Federal Agency ID:		***CNG Vehicle Class:***	
Open Date:	2012-10-25	***LNG Site Renew Src:***	
Hydrogen is Retail:		***LNG Vehicle Class:***	
Federal Agency:		***LPG Nozzle Types:***	
Facility Type:	CAR_DEALER	***Hydrogen Pressures:***	
Dt Last Confirmed:	2024-02-12	***Hydrogen Standards:***	
Updated at:	2025-02-12 00:16:32 UTC	***Latitude:***	35.659801
Access Code:	public	***Longitude:***	-105.966558
Access Detail Code:	CALL		
Groups with Access Code:	Public - Call ahead		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Groups with Access Code Fr:	Public - Appeler à l'avance
Fed Agency Name:	
Hydrogen Status Link:	
E85 Other Ethanol Blends:	
NPS Unit Name:	
Cards Accepted:	
CNG Statn Sells Renewable Na:	
LNG Statn Sells Renewable Na:	
Maximum Vehicle Class:	
RD Blended With Biodiesel:	
RD Blends:	
RD Blends French:	
RD Maximum Biodiesel Level:	
Status:	Open: The station is open.
Owner Type Desc:	Privately owned
E85 Blender Pump Desc:	
NG Fill Type Desc:	
NG Vehicle Class Desc:	
Geocode Status Desc:	Premise (building name, property name, shopping center, etc.) level accuracy.
Group with Access Desc:	Publicly available, but customers should call before visiting the station. See "Station Phone" for more details.
LPG Primary Desc:	
Intersection Directions:	
Access Days Time:	Dealership business hours
Restricted Access:	false
Ev Workplace Charging:	false
Funding Sources:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
6	2 of8	E	0.13 / 711.08	6,870.84 / 25	Fiesta Nissan 2005 St Michaels Dr Santa Fe NM 87505	ALT FUELS

ID:	49916	**CNG Dispenser No:**	
Fuel Type Code:	ELEC: Electric	**CNG Site Renew Src:**	
Station Phone:	505-955-1000	**CNG Tot Compr Cap:**	
Expected Date:		**CNG Storage Cap:**	
BD Blends:		**CNG Fill Type Code:**	
NG PSI:		**CNG PSI:**	
Federal Agency ID:		**CNG Vehicle Class:**	
Open Date:	2012-10-25	**LNG Site Renew Src:**	
Hydrogen is Retail:		**LNG Vehicle Class:**	
Federal Agency:		**LPG Nozzle Types:**	
Facility Type:	CAR_DEALER	**Hydrogen Pressures:**	
Dt Last Confirmed:	2024-02-12	**Hydrogen Standards:**	
Updated at:	2025-02-12 00:16:32 UTC	**Latitude:**	35.659801
Access Code:	private	**Longitude:**	-105.966558
Access Detail Code:			

Groups with Access Code:	Private
Groups with Access Code Fr:	Privé
Fed Agency Name:	
Hydrogen Status Link:	
E85 Other Ethanol Blends:	
NPS Unit Name:	
Cards Accepted:	
CNG Statn Sells Renewable Na:	
LNG Statn Sells Renewable Na:	
Maximum Vehicle Class:	
RD Blended With Biodiesel:	
RD Blends:	
RD Blends French:	
RD Maximum Biodiesel Level:	
Status:	Open: The station is open.
Owner Type Desc:	Privately owned
E85 Blender Pump Desc:	
NG Fill Type Desc:	
NG Vehicle Class Desc:	
Geocode Status Desc:	Premise (building name, property name, shopping center, etc.) level accuracy.
Group with Access Desc:	Private Station

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

LPG Primary Desc:
Intersection Directions:
Access Days Time:
Restricted Access:
Ev Workplace Charging: false
Funding Sources:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
6	3 of8	E	0.13 / 711.08	6,870.84 / 25	Fiesta Nissan 2005 Saint Michaels Drive Santa Fe NM 87505	ALT FUELS

ID: 377488
Fuel Type Code: ELEC: Electric
Station Phone: 888-998-2546
Expected Date:
BD Blends:
NG PSI:
Federal Agency ID:
Open Date: 2024-12-23
Hydrogen is Retail:
Federal Agency:
Facility Type:
Dt Last Confirmed: 2025-08-01
Updated at: 2025-08-01 00:44:53 UTC
Access Code: public
Access Detail Code:
Groups with Access Code: Public
Groups with Access Code Fr: Public
Fed Agency Name:
Hydrogen Status Link:
E85 Other Ethanol Blends:
NPS Unit Name:
Cards Accepted:
CNG Statn Sells Renewable Na:
LNG Statn Sells Renewable Na:
Maximum Vehicle Class:
RD Blended With Biodiesel:
RD Blends:
RD Blends French:
RD Maximum Biodiesel Level:
Status: Open: The station is open.
Owner Type Desc:
E85 Blender Pump Desc:
NG Fill Type Desc:
NG Vehicle Class Desc:
Geocode Status Desc: The location is from a real GPS readout at the station.
Group with Access Desc: Publicly available to all customers.
LPG Primary Desc:
Intersection Directions:
Access Days Time: 24 hours daily
Restricted Access:
Ev Workplace Charging: false
Funding Sources:

CNG Dispenser No:
CNG Site Renew Src:
CNG Tot Compr Cap:
CNG Storage Cap:
CNG Fill Type Code:
CNG PSI:
CNG Vehicle Class:
LNG Site Renew Src:
LNG Vehicle Class:
LPG Nozzle Types:
Hydrogen Pressures:
Hydrogen Standards:
Latitude: 35.6602093310012
Longitude: -105.96652601939273

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
6	4 of8	E	0.13 / 711.08	6,870.84 / 25	FIESTA NISSAN 2005 SAINT MICHAELS DRIVE SANTA FE NM 87501	RCRA VSQG

Handler ID: NMD986674786
Generator Status: VSG
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Sep 2025.

Evaluation Details

Eval Start Date: 20220629
Eval Type Desc: COMPLIANCE EVALUATION INSPECTION
Viol Short Desc:
Actual Rtc Date:
Eval Agency: State

Handler Summary

Importer:	No	***Used Oil Transpor:***	No
Mixed Waste Gen:	No	***Used Oil Trans Fac:***	No
Transporter:	No	***Used Oil Processor:***	No
Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		

Used Oil Market Burner: No
Used Oil Spec Marketer: No

Additional Handler Summary Details

Source Type:	I	***NAIC 1:***	423110
Seq No:	2	***NAIC 2:***	
Non Notifier:		***NAIC 3:***	
Receive Date:	20220714	***NAIC 4:***	
Active Site:	H----	***State:***	NM
Land Type:	P	***Location Latitude:***	35.659525
In Handler Univ:	Y	***Location Longitude:***	-105.966472
In A Universe:	Y	***Loc GIS Primary:***	N
Gen Status:	VSG	***Loc GIS Origin:***	AG
Report Cycle:		***State District Owner:***	NM
Accessibility:		***State District:***	02
Region:	06		

Fed Waste Gen Owner: HQ
State Waste Generator Owner: NM
State Waste Generator: N
Short Term Generator: N
Uni Waste: N
Universal Waste Dest Facility: N
Federal Universal Waste: N
As Federally Regulated Tsdf: ------
As Converter Tsdf: ------
As State Regulated Tsdf: ------
As State Regulated Handler: ---
Federal Indicator: ---
Hsm: N
Subpart K: ----
GPRA Permit: N
GPRA Renewal: N
Permit Renewal WrkId: ------
Permwrk ID: ------
Perm Prog: ------
Pcwrkld: ------
Closwrkld: ------
GPRA Ca: N
Cawrkld: N
Subjca Tsd Discretion: N
NCAPS: N

EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20220714
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	FIESTA NISSAN
Location Street No:	2005
Location Street1:	SAINT MICHAELS DRIVE
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87501
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	MIKE LEARY
Contact Street No:	2005
Contact Street1:	SAINT MICHAELS DRIVE
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87501
Contact Country:	US
Contact Phone & Ext:	505-955-1044
Contact Fax:	
Contact Email Address:	MIKE_LEARY@FIESTAAUTOGROUP.COM
Contact Title:	SERVICE MANAGER
Owner Name:	2005 ST. MICHAELS INVESTMENTS LLC
Owner Type:	P
Owner Seq:	1
Operator Name:	FIESTA AUTO GROUP
Operator Type:	P
Operator Seq:	2
Public Notes:	

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	19910610
Handler Name:	SANTA FE NISSAN MITSUBISHI
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Notification
TSD Activity:	N

Waste Code Details

Waste Code:	D001
Waste Code Desc:	IGNITABLE WASTE

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20100222
Handler Name: SANTA FE NISSAN MITSUBISHI
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer
TSD Activity: N

Waste Code Details

Waste Code: D001
Waste Code Desc: IGNITABLE WASTE

Hazardous Waste Handler Details

Seq No: 2
Receive Date: 20220714
Handler Name: FIESTA NISSAN
Fed Waste Generator: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer
TSD Activity: N

Waste Code Details

Waste Code: F005
Waste Code Desc: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: JIM BEWLEY MITSUBISHI
Dt Became Current:
Dt Ended Current:
Phone: 505-255-3694
Source Type: Implementer
Street No:
Street1: 725 WYOMING NE
Street2:
City: ALBUQUERQUE
State: NM
Country:
Zip: 87123

Owner/Operator Ind: Current Owner
Type: Private
Name: 2005 ST. MICHAELS INVESTMENTS LLC
Dt Became Current: 20151115
Dt Ended Current:
Phone: 505-255-3694
Source Type: Implementer
Street No:
Street1: PO BOX 981011
Street2:
City: EL PASO
State: TX
Country: US
Zip: 79998

Owner/Operator Ind: Current Owner
Type: Private
Name: JIM BEWLEY MITSUBISHI
Dt Became Current:
Dt Ended Current:
Phone: 505-255-3694
Source Type: Notification
Street No:
Street1: 725 WYOMING NE
Street2:
City: ALBUQUERQUE
State: NM
Country:
Zip: 87123

Owner/Operator Ind: Current Operator
Type: Private
Name: FIESTA AUTO GROUP
Dt Became Current: 20151115
Dt Ended Current:
Street No: 2005
Street1: SAINT MICHAELS DRIVE
Street2:
City: SANTA FE
State: NM

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Phone: | **Country:** US
Source Type: Implementer | **Zip:** 87505

Historical Handler Details

Receive Dt: 20100222
Generator Code Description: Not a Generator, Verified
Handler Name: SANTA FE NISSAN MITSUBISHI

Receive Dt: 19910610
Generator Code Description: Not a Generator, Verified
Handler Name: SANTA FE NISSAN MITSUBISHI

---

6 | **5 of8** | **E** | **0.13 / 711.08** | **6,870.84 / 25** | **SANTA FE PARTNERS**
2005 SAINT MICHAELS DR
SANTA FE NM 87501 | **TANKS**

FID: 30459
In Use AST: 0
In Use UST: 0
Temp Out AST: 0
Temp Out UST: 0
Removed AST: 0
Removed UST: 1
Exempt AST: 0
Exempt UST: 0
Owner Name: SANTA FE PARTNERS
Fac Name (Del Prohibition):
Fac Owner (Deliv Prohib):
Fac Add (Delivery Prohibition):
Source: All Storage Tank List

Sold AST: 0
Sold UST: 0
No Data AST: 0
No Data UST: 0
County: SANTA FE
Owner ID: 15440
City (Deliv Prohib):
Cty (Del Prohib):

---

6 | **6 of8** | **E** | **0.13 / 711.08** | **6,870.84 / 25** | **SANTA FE PARTNERS**
2005 SAINT MICHAELS DR
SANTA FE NM 87501 | **UST**

Facility ID: 30459
Facility Name: SANTA FE PARTNERS
Facility Address: 2005 SAINT MICHAELS DR
Address 2:
City: SANTA FE
County: SANTA FE
Zip: 87501
Fac Name (Map):
Fac Addr (Map):
Address2 (Map):
City (Map):
County (Map):
Fac ZIP (Map):
Latitude (Map):
Longitude (Map):
Fac Name (Map-Pro):
Fac Addr (Map-Pro):
City (Map-Pro):
County (Map-Pro):
Data Source: NMED PSTB All Storage Tanks Report (as of 14 Oct 2025); NMED Open Data - Inactive Facilities (Map-In) (as of 3 Nov 2025)

Facility (Active):
Street (Active):
Street 2 (Active):
Zip (Active):
City (Active):
County (Active):
Fac Name (Map-In): SANTA FE PARTNERS
Fac Addr (Map-In): 2005 SAINT MICHAELS DR
Address 2 (Map-In):
City (Map-In): SANTA FE
County (Map-In): SANTA FE
Zip Cd (Map-In): 87501
Lat (Map-In): 35.660387
Lon (Map-In): -105.966311
Fac Name (Prohib):
Fac Addr (Prohib):
City (Prohib):
County (Prohib):

NMED PSTB Report - Tank Detail(s) (as of October 14, 2025)

In Use UST: 0
Removed UST: 1
Exempt UST: 0
Temp Out UST: 0

Sold UST: 0
No Data UST: 0
Owner ID: 15440
Owner Name: SANTA FE PARTNERS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

NMED Open Data - Inactive Facilities

Active:	0	***Oldest Tnk Age Type:***	
UST:	1	***AST:***	0
UST Curr in Use:	0	***AST Curr in Use:***	0
UST Exempt:	0	***AST Exempt:***	0
UST Removed:	1	***AST Removed:***	0
UST Temp Out of Use:	0	***AST Temp Out of Use:***	0
Tanks:	1	***Shape:***	
Tanks Curr in Use:	0	***Owner ID:***	15440
Tanks Exempt:	0	***Owner Size Type:***	
Tanks Removed:	1	***Owner Name:***	SANTA FE PARTNERS
TanksTemp OutofUse:	0		

6	*7 of8*	*E*	*0.13 / 711.08*	*6,870.84 / 25*	***SANTA FE PARTNERS 2005 SAINT MICHAELS DR SANTA FE NM 87501***	***UST HIST***

Facility ID:	30459
Facility Addr2:	
Facility County:	SANTA FE

Details

Tank ID:	30188	***Owner Add2:***	
Tank Type:	Underground	***Owner City:***	SANTA FE
Tank Status:	REMOVED	***Owner St:***	NM
Tank Capacity (GAL):	560	***Owner ZIP:***	87501
Tank Contents:	USED OIL	***Owner Ph:***	505-983-7337
Owner ID:	15440		
Owner Name:	SANTA FE PARTNERS		
Owner Address:	2005 SAINT MICHAELS DR		

6	*8 of8*	*E*	*0.13 / 711.08*	*6,870.84 / 25*	***Premier Nissan 2005 St. Michael's Drive Santa Fe NM***	***VCP***

VRP ID:	53062001	***Application Rcvd:***	4/6/2006
CERCLIS No:		***Cert of Completion:***	6/2/2006
Status:	Closed	***Final Work Plan Rc'd:***	
County:	Santa Fe	***Transfer CNS:***	10/22/2010
Latitude:	35.6596	***Public Notice:***	
Longitude:	-105.9663	***Conditional Elig:***	
Township Range:	T17N, R9E, Sec 34	***Final Eligibility:***	5/31/2006
Size (Acres):	2.9	***VRA Signed:***	
Applicant:	Omega Automotive Real Estate, LLC	***Termination:***	
Project Manager:	Bynum	***Recission:***	
Cov Not to Sue CNS:	6/2/2006	***Rejection:***	
Cmpt RPT Apprv:			
Condl Cert of Comp:			
Contamination Type:	Petroleum hydrocarbons associated with hydraulic lifts and sump.		
Institutional Engineering Cont:			
Land Use Restrictions:			
Final Work Plan Approved:			

7	*1 of4*	*SSW*	*0.16 / 837.89*	*6,831.42 / -14*	***KMART #3301 1712 ST MICHAELS DRIVE SANTA FE NM 87505***	***RCRA NON GEN***

Handler ID:	NMR000017822
Generator Status:	N
Recycler Activity?:	NO

Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Sep 2025.

Violation Details

Viol Type: 273.B
Citation:
Determined Date: 20130321
Scheduled Compliance Date:
Eval Activity Location: NM
Viol Determined By Agency: State
Viol Short Desc: Universal Waste - Small Quantity Handlers
Actual Rtc Date: 20130415
Found Violation: Yes
Rtc Qualifier: Documented

Enforcement Details

Enf Type: 120
Enf Type Desc: WRITTEN INFORMAL
Enf Action Date: 20130415
Disposition Status Desc:
Disposition Status Date:
Enf Agency: State
Proposed Amount:
Final Amount:
Paid Amount:

Evaluation Details

Eval Start Date: 20130321
Eval Type Desc: COMPLIANCE EVALUATION INSPECTION
Viol Short Desc: Universal Waste - Small Quantity Handlers
Actual Rtc Date: 20130415
Eval Agency: State

Handler Summary

Importer: No
Mixed Waste Gen: No
Transporter: No
Transfer Facility: No
Recycler: No
Onsite Burner Exem: No
Furnace Exemption: No
Underground Injec: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Used Oil Transpor: No
Used Oil Trans Fac: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Commercial TSD: No
Recycl Nonstorage: No

Additional Handler Summary Details

Source Type: D
Seq No: 1
Non Notifier:
Receive Date: 20200917
Active Site: -----
Land Type: P
In Handler Univ: N
In A Universe: N
Gen Status: N
NAIC 1:
NAIC 2:
NAIC 3:
NAIC 4:
State: NM
Location Latitude: 35.65922
Location Longitude: -105.969842
Loc GIS Primary: N
Loc GIS Origin: AG

Report Cycle:		**State District Owner:**	NM
Accessibility:		**State District:**	02
Region:	06		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	NM		
State Waste Generator:	N		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	------		
As Converter Tsdf:	------		
As State Regulated Tsdf:	------		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	------		
Permwrk ID:	------		
Perm Prog:	------		
Pcwrkld:	------		
Closwrkld:	------		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	------		
Full Enforcement:	------		
Snc:	N		
Unaddressed Snc:	N		
Addressed Snc:	N		
Snc With Comp Sched:	N		
Fa Required:	-----		
Hhandler Last Change:	20200917		
Recognized Trader Importer:	N		
Recognized Trader Exporter:	N		
Slab Importer:	N		
Slab Exporter:	N		
Manifest Broker:	N		
Subpart P:	N		
Contact Language:	EN		
Handler Name:	KMART #3301		
Location Street No:	1712		
Location Street1:	ST MICHAELS DRIVE		
Location Street2:			
Location City:	SANTA FE		
Location State:	NM		
Location Zip:	87505		
Location County Code:	NM049		
Location County Name:	SANTA FE		
Location Country:	US		
Contact Name:	CHRISTOPHER D LIPMAN		
Contact Street No:	3333		
Contact Street1:	BEVERLY RD #B5-348A		
Contact Street2:			
Contact City:	HOFFMANTOWN ESTATES		
Contact State:	IL		
Contact Zip:	60179		
Contact Country:	US		
Contact Phone & Ext:	847-286-0037		
Contact Fax:	847-747-9057		
Contact Email Address:	CHRIS.LIPMAN@SEARSHC.COM		
Contact Title:	ENVIRONMENTAL SPECIALIST		
Owner Name:	NYDES PROPERTIES		

Owner Type: P
Owner Seq: 1
Operator Name: KMART CORPORATION
Operator Type: P
Operator Seq: 2
Public Notes:

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20120622
Handler Name: KMART #3301
Fed Waste Generator: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification
TSD Activity: N

Waste Code Details

Waste Code: D001
Waste Code Desc: IGNITABLE WASTE

Waste Code: D002
Waste Code Desc: CORROSIVE WASTE

Waste Code: D004
Waste Code Desc: ARSENIC

Waste Code: D005
Waste Code Desc: BARIUM

Waste Code: D006
Waste Code Desc: CADMIUM

Waste Code: D007
Waste Code Desc: CHROMIUM

Waste Code: D008
Waste Code Desc: LEAD

Waste Code: D011
Waste Code Desc: SILVER

Waste Code: D016
Waste Code Desc: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

Waste Code: D018
Waste Code Desc: BENZENE

Waste Code: D027
Waste Code Desc: 1,4-DICHLOROBENZENE

Waste Code: D035
Waste Code Desc: METHYL ETHYL KETONE

Waste Code: P001
Waste Code Desc: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

Waste Code: P075
Waste Code Desc: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Hazardous Waste Handler Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Seq No: 1
Receive Date: 20200917
Handler Name: KMART #3301
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Deactivation
TSD Activity: N

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: NYDES PROPERTIES
Dt Became Current: 19760909
Dt Ended Current:
Phone: 505-473-5956
Source Type: Deactivation
Street No:
Street1: PO BOX 4247
Street2:
City: SANTA FE
State: NM
Country: US
Zip: 87502-4247

Owner/Operator Ind: Current Operator
Type: Private
Name: KMART CORPORATION
Dt Became Current: 19760909
Dt Ended Current:
Phone: 847-286-0037
Source Type: Deactivation
Street No: 3333
Street1: BEVERLY RD #B5-348A
Street2:
City: HOFFMANTOWN ESTATES
State: IL
Country: US
Zip: 60179

Owner/Operator Ind: Current Operator
Type: Private
Name: KMART CORPORATION
Dt Became Current: 19760909
Dt Ended Current:
Phone: 847-286-0037
Source Type: Notification
Street No: 3333
Street1: BEVERLY RD #B5-348A
Street2:
City: HOFFMANTOWN ESTATES
State: IL
Country: US
Zip: 60179

Owner/Operator Ind: Current Owner
Type: Private
Name: NYDES PROPERTIES
Dt Became Current: 19760909
Dt Ended Current:
Phone: 505-473-5956
Source Type: Notification
Street No:
Street1: PO BOX 4247
Street2:
City: SANTA FE
State: NM
Country: US
Zip: 87502-4247

Historical Handler Details

Receive Dt: 20120622
Generator Code Description: Very Small Quantity Generator
Handler Name: KMART #3301

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
7	2 of4	SSW	0.16 / 837.89	6,831.42 / -14	KMART NUMBER 3301 1712 SAINT MICHAELS DR SANTA FE NM 87501	TANKS

FID: 28953
In Use AST: 0
In Use UST: 0
Temp Out AST: 0
Temp Out UST: 0
Removed AST: 0
Removed UST: 1
Exempt AST: 0
Exempt UST: 0
Sold AST: 0
Sold UST: 0
No Data AST: 0
No Data UST: 0
County: SANTA FE
Owner ID: 6858
City (Deliv Prohib):
Cty (Del Prohib):
Owner Name: BUTLER JOHN WILLIAM JR ATRNY FOR DEBTOR K MART
Fac Name (Del Prohibition):
Fac Owner (Deliv Prohib):
Fac Add (Delivery Prohibition):
Source: All Storage Tank List

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
7	3 of4	SSW	0.16 / 837.89	6,831.42 / -14	KMART NUMBER 3301 1712 SAINT MICHAELS DR SANTA FE NM 87501	UST

Facility ID:	28953	**Facility (Active):**	
Facility Name:	KMART NUMBER 3301	**Street (Active):**	
Facility Address:	1712 SAINT MICHAELS DR	**Street 2 (Active):**	
Address 2:		**Zip (Active):**	
City:	SANTA FE	**City (Active):**	
County:	SANTA FE	**County (Active):**	
Zip:	87501	**Fac Name (Map-In):**	KMART NUMBER 3301
Fac Name (Map):		**Fac Addr (Map-In):**	1712 SAINT MICHAELS DR
Fac Addr (Map):		**Address 2 (Map-In):**	
Address2 (Map):		**City (Map-In):**	SANTA FE
City (Map):		**County (Map-In):**	SANTA FE
County (Map):		**Zip Cd (Map-In):**	87501
Fac ZIP (Map):		**Lat (Map-In):**	35.657356
Latitude (Map):		**Lon (Map-In):**	-105.969594
Longitude (Map):		**Fac Name (Prohib):**	
Fac Name (Map-Pro):		**Fac Addr (Prohib):**	
Fac Addr (Map-Pro):		**City (Prohib):**	
City (Map-Pro):		**County (Prohib):**	
County (Map-Pro):			

Data Source: NMED PSTB All Storage Tanks Report (as of 14 Oct 2025); NMED Open Data - Inactive Facilities (Map-In) (as of 3 Nov 2025)

NMED PSTB Report - Tank Detail(s) (as of October 14, 2025)

In Use UST:	0	**Sold UST:**	0
Removed UST:	1	**No Data UST:**	0
Exempt UST:	0	**Owner ID:**	6858
Temp Out UST:	0	**Owner Name:**	BUTLER JOHN WILLIAM JR ATRNY FOR DEBTOR K MART

NMED Open Data - Inactive Facilities

Active:	0	**Oldest Tnk Age Type:**	
UST:	1	**AST:**	0
UST Curr in Use:	0	**AST Curr in Use:**	0
UST Exempt:	0	**AST Exempt:**	0
UST Removed:	1	**AST Removed:**	0
UST Temp Out of Use:	0	**AST Temp Out of Use:**	0
Tanks:	1	**Shape:**	
Tanks Curr in Use:	0	**Owner ID:**	6858
Tanks Exempt:	0	**Owner Size Type:**	
Tanks Removed:	1	**Owner Name:**	BUTLER JOHN WILLIAM JR ATRNY FOR DEBTOR K MART
TanksTemp OutofUse:	0		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
7	4 of4	SSW	0.16 / 837.89	6,831.42 / -14	KMART NUMBER 3301 1712 SAINT MICHAELS DR SANTA FE NM 87501	UST HIST

Facility ID:	28953
Facility Addr2:	
Facility County:	SANTA FE

Details

Tank ID:	26608	**Owner Add2:**	
Tank Type:	Underground	**Owner City:**	CHICAGO
Tank Status:	REMOVED	**Owner St:**	IL

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tank Capacity (GAL):	1000	**Owner ZIP:**	60606
Tank Contents:	USED OIL	**Owner Ph:**	313-643-1790
Owner ID:	6858		
Owner Name:	BUTLER JOHN WILLIAM JR ATRNY FOR DEBTOR K MART		
Owner Address:	333 W WACKER DR STE 2100		

8	1 of1	W	0.16 / 863.94	6,825.46 / -20	BETO'S AUTO REPAIR 1650 6TH ST SANTA FE NM 87505	RCRA VSQG

Handler ID:	NMR000011528
Generator Status:	VSG
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Sep 2025.

Evaluation Details

Eval Start Date:	20060607
Eval Type Desc:	COMPLIANCE ASSISTANCE VISIT
Viol Short Desc:	
Actual Rtc Date:	
Eval Agency:	State

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	N	**NAIC 1:**	811118
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20060628	**NAIC 4:**	
Active Site:	H----	**State:**	NM
Land Type:	P	**Location Latitude:**	35.661472
In Handler Univ:	Y	**Location Longitude:**	-105.971866
In A Universe:	Y	**Loc GIS Primary:**	N
Gen Status:	VSG	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	NM
Accessibility:		**State District:**	02
Region:	06		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	NM		
State Waste Generator:	N		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	------		

As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20060705
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	BETO'S AUTO REPAIR
Location Street No:	1650
Location Street1:	6TH ST
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87505
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	ALBERTO LAGUNAS
Contact Street No:	1650
Contact Street1:	6TH ST
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87505
Contact Country:	US
Contact Phone & Ext:	505-988-7140
Contact Fax:	
Contact Email Address:	
Contact Title:	
Owner Name:	ORLANDO PACHECO
Owner Type:	P
Owner Seq:	1
Operator Name:	ALBERTO LAGUNAS
Operator Type:	P
Operator Seq:	2
Public Notes:	

Hazardous Waste Handler Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Seq No: 1
Receive Date: 20060628
Handler Name: BETO'S AUTO REPAIR
Fed Waste Generator: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification
TSD Activity: N

Waste Code Details

Waste Code: D001
Waste Code Desc: IGNITABLE WASTE

Waste Code: D002
Waste Code Desc: CORROSIVE WASTE

Waste Code: D008
Waste Code Desc: LEAD

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: ALBERTO LAGUNAS
Dt Became Current: 19900701
Dt Ended Current:
Phone: 505-988-7140
Source Type: Notification
Street No: 1650
Street1: 6TH ST
Street2:
City: SANTA FE
State: NM
Country: US
Zip: 87505

Owner/Operator Ind: Current Owner
Type: Private
Name: ORLANDO PACHECO
Dt Became Current: 19900701
Dt Ended Current:
Phone:
Source Type: Notification
Street No: 105
Street1: CALLE PALOMITA
Street2:
City: SANTA FE
State: NM
Country: US
Zip: 87505

9	1 of1	SE	0.17 / 915.33	6,854.61 / 9	SANTA FE SPORTS AND IMAGES 2701 WARNER CIRCLE SANTA FE NM 87505	RCRA NON GEN

Handler ID: NMR000026237
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Sep 2025.

Evaluation Details

Eval Start Date: 20190408
Eval Type Desc: COMPLIANCE EVALUATION INSPECTION
Viol Short Desc:
Actual Rtc Date:
Eval Agency: State

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	N	**NAIC 1:**	323113
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20190410	**NAIC 4:**	
Active Site:	-----	**State:**	NM
Land Type:	P	**Location Latitude:**	35.657668
In Handler Univ:	N	**Location Longitude:**	-105.966354
In A Universe:	N	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	
Accessibility:		**State District:**	
Region:	06		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	NM		
State Waste Generator:	N		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	------		
As Converter Tsdf:	------		
As State Regulated Tsdf:	------		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	------		
Permwrk ID:	------		
Perm Prog:	------		
Pcwrkld:	------		
Closwrkld:	------		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	------		
Full Enforcement:	------		
Snc:	N		
Unaddressed Snc:	N		
Addressed Snc:	N		
Snc With Comp Sched:	N		
Fa Required:	-----		
Hhandler Last Change:	20190410		
Recognized Trader Importer:	N		
Recognized Trader Exporter:	N		
Slab Importer:	N		
Slab Exporter:	N		
Manifest Broker:	N		
Subpart P:	N		
Contact Language:	EN		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Handler Name:	SANTA FE SPORTS AND IMAGES
Location Street No:	2701
Location Street1:	WARNER CIRCLE
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87505
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	ERIC HOLMES
Contact Street No:	2701
Contact Street1:	WARNER CIRCLE
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87505
Contact Country:	US
Contact Phone & Ext:	505-471-4100
Contact Fax:	
Contact Email Address:	ERIC@SANTAFESPORTSANDIMAGES.COM
Contact Title:	GENERAL MANAGER
Owner Name:	PGW LLC
Owner Type:	P
Owner Seq:	1
Operator Name:	SANTA FE SPORTS AND IMAGES, LLC
Operator Type:	P
Operator Seq:	2
Public Notes:	

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20190410
Handler Name:	SANTA FE SPORTS AND IMAGES
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Notification
TSD Activity:	N

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	110
Type:	Private	**Street1:**	CIBOLA CIRCLE
Name:	PGW LLC	**Street2:**	
Dt Became Current:	20060101	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:		**Country:**	US
Source Type:	Notification	**Zip:**	87505
Owner/Operator Ind:	Current Operator	**Street No:**	2701
Type:	Private	**Street1:**	WARNER CIRCLE
Name:	SANTA FE SPORTS AND IMAGES, LLC	**Street2:**	
Dt Became Current:	20060101	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:		**Country:**	US
Source Type:	Notification	**Zip:**	87505

10	1 of1	WNW	0.18 / 932.57	6,825.46 / -20	**TOYOTECH** **1640 6TH ST** **SANTA FE NM 87505**	RCRA VSQG

Handler ID:	NMR000011452
Generator Status:	VSG
Recycler Activity?:	NO

Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Sep 2025.

Violation Details

Viol Type: 279.C
Citation:
Determined Date: 20200123
Scheduled Compliance Date:
Eval Activity Location: NM
Viol Determined By Agency: State
Viol Short Desc: Used Oil - Generators
Actual Rtc Date: 20200123
Found Violation: Yes
Rtc Qualifier: Observed

Enforcement Details

Enf Type: 120
Enf Type Desc: WRITTEN INFORMAL
Enf Action Date: 20200131
Disposition Status Desc:
Disposition Status Date:
Enf Agency: State
Proposed Amount:
Final Amount:
Paid Amount:

Evaluation Details

Eval Start Date: 20200123
Eval Type Desc: COMPLIANCE EVALUATION INSPECTION
Viol Short Desc: Used Oil - Generators
Actual Rtc Date: 20200123
Eval Agency: State

Eval Start Date: 20060531
Eval Type Desc: COMPLIANCE ASSISTANCE VISIT
Viol Short Desc:
Actual Rtc Date:
Eval Agency: State

Handler Summary

Importer: No
Mixed Waste Gen: No
Transporter: No
Transfer Facility: No
Recycler: No
Onsite Burner Exem: No
Furnace Exemption: No
Underground Injec: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Used Oil Transpor: No
Used Oil Trans Fac: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Commercial TSD: No
Recycl Nonstorage: No

Additional Handler Summary Details

Source Type: N
Seq No: 1
Non Notifier:
NAIC 1: 811111
NAIC 2:
NAIC 3:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Receive Date:	20200123	**NAIC 4:**	
Active Site:	H----	**State:**	NM
Land Type:	P	**Location Latitude:**	35.661472
In Handler Univ:	Y	**Location Longitude:**	-105.971866
In A Universe:	Y	**Loc GIS Primary:**	N
Gen Status:	VSG	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	NM
Accessibility:		**State District:**	02
Region:	06		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	NM
State Waste Generator:	N
Short Term Generator:	N
Uni Waste:	N
Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20200128
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	TOYOTECH
Location Street No:	1640
Location Street1:	6TH ST
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87505
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	ROSS MARTINEZ
Contact Street No:	1640
Contact Street1:	6TH ST
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87505

Contact Country: US
Contact Phone & Ext: 505-986-8544
Contact Fax:
Contact Email Address: TOYOROSS@YAHOO.COM
Contact Title: TECHNICIAN
Owner Name: TOM KETTERMAN
Owner Type: P
Owner Seq: 1
Operator Name: TOYOTECH
Operator Type: P
Operator Seq: 2
Public Notes:

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20060629
Handler Name: AUTOMOTIVE RESOURCES
Fed Waste Generator: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer
TSD Activity: N

Waste Code Details

Waste Code: D002
Waste Code Desc: CORROSIVE WASTE

Waste Code: D008
Waste Code Desc: LEAD

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20200123
Handler Name: TOYOTECH
Fed Waste Generator: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification
TSD Activity: N

Waste Code Details

Waste Code: D001
Waste Code Desc: IGNITABLE WASTE

Waste Code: D002
Waste Code Desc: CORROSIVE WASTE

Waste Code: D008
Waste Code Desc: LEAD

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: TOM HITCH
Dt Became Current: 19930101
Dt Ended Current:
Phone: 505-995-9590
Source Type: Implementer

Street No:
Street1: 6TH ST
Street2:
City: SANTA FE
State: NM
Country: US
Zip: 87505

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Ind:	Current Owner	**Street No:**	3332
Type:	Private	**Street1:**	JAMES ST
Name:	TOM KETTERMAN	**Street2:**	
Dt Became Current:	19930101	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:	505-995-9590	**Country:**	US
Source Type:	Notification	**Zip:**	87507

Owner/Operator Ind:	Current Operator	**Street No:**	1640
Type:	Private	**Street1:**	6TH ST
Name:	TOYOTECH	**Street2:**	
Dt Became Current:	20130101	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:	505-986-8544	**Country:**	US
Source Type:	Notification	**Zip:**	87505

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street1:**	6TH ST
Name:	TOM KETTERMAN	**Street2:**	
Dt Became Current:	19930101	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:	505-995-9590	**Country:**	US
Source Type:	Implementer	**Zip:**	87505

Historical Handler Details

Receive Dt:	20060629
Generator Code Description:	Very Small Quantity Generator
Handler Name:	AUTOMOTIVE RESOURCES

11	1 of9	WSW	0.21 / 1,089.96	6,821.69 / -24	**GRAHAMS CHEVRN** **1700 SAINT MICHAELS DR** **SANTA FE NM**	LST

Release ID:	762	**Latitude (Map):**	35.658951
Facility ID:	27330	**Longitude (Map):**	-105.972338
Status:	No Further Action, Confirmed Release	**Address (Map):**	1700 SAINT MICHAELS DR
Address:		**Address2 (Map):**	
City:		**City (Map):**	SANTA FE
County:		**State (Map):**	NM
Address (NFA):	1700 SAINT MICHAELS DR	**Zip (Map):**	87501
City (NFA):	SANTA FE	**Address (Priority):**	
County (NFA):	SANTA FE	**City (Priority):**	
Facility Release IDs (Map):	762	**County (Priority):**	
Data Source:	NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)		

PSTB No Further Action Sites

Status:	No Further Action, Confirmed Release
NFA Date:	11/01/1995
NFA PDF:	https://cloud.env.nm.gov/resources/collection/8706

Leaking Petroleum Storage Tank Sites

Status Date Dt:	1995-11-01 00:00:00 UTC	**NAPL Off Site Val:**	0
Within SWPA Val:	0	**Plume Area No:**	
Surface Water Val:	0	**Plume Area Val:**	2
Private Well Val:	0	**Max Thickness No:**	
Municipal Well Val:	0	**Max Thickness Val:**	
LUWU Sco:	0	**NAPLSco:**	0
Surficial Conc Des:		**Priority2 Sco:**	0
Surficial Conc Val:	0	**Impact Type Des:**	
Leaching Conc Des:		**Impact Type Val:**	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Leaching Conc Val:	0	**WS Type Des:**	
Construct Conc Des:		**WS Type Val:**	0
Construct Conc Val:	0	**WTR Sys Repl Des:**	
Building Type Des:		**WTR Sys Repl Val:**	0
Building Type Val:	0	**Population No:**	
Vad Off Site Val:	1	**Population Val:**	1
Vadose Sco:	0	**WS Sco:**	0
Conc Des:		**Toxic Vapor Des:**	
Conc Val:	0	**Toxic Vapor Val:**	0
Plume Mob Des:		**Toxic Vapor Sco:**	0
Plume Mob Val:	0	**Priority1 Sco:**	0
GWDPP Off Site Val:	0	**Total Sco:**	0
Benzene Area No:		**Tempo Total Sco:**	
Benzene Area Val:	1	**Current Priority:**	
GWDPP Sco:	0	**Tempo Current Rank:**	
Priority3 Sco:	0	**Tempo Curr Priorty:**	
CSS Age Des:		**Point X:**	-105.97233799999998
CSS Age Val:	0	**Point Y:**	35.658951
CSS Type Des:		**Irrigation Well Val:**	0
CSS Type Val:	0	**Subsurf Conc Des:**	
CSS Off Site Val:	1	**Subsurface Conc Val:**	0
CSS Sco:	0	**Petrol Soil Bldg Val:**	1
CSS Volume No:		**Petrol Soil Vol Val:**	0
CSS Volume Val:	3	**Hydraulic Grad Val:**	0
Release Pm:	UNKNOWN	**Depth to GW:**	
NAPL Type Des:		**Depth to GW Val:**	2
NAPL Type Val:	0	**Explosive Vapor Des:**	
NAPL Age Des:		**Explosive Vapor Val:**	0
NAPL Age Val:	0	**Explosive Vapor Sco:**	0
NAPLCondition Des:		**Eco Impact Val:**	0
NAPLCondition Val:	0	**Eco Impact Sco:**	0

Facility Name:	CHEVRON 76047
Current Status:	No Further Action, Confirmed Release
Aquifer Water Quality Des:	
Aquifer Water Quality Val:	0
Residential Property Val:	0
NAPL Plume Mobility Des:	
NAPL Plume Mobility Val:	0
Property Damage Des:	
Property Damage Val:	0
Property Damage Sco:	0

---

11 | **2 of9** | **WSW** | **0.21 / 1,089.96** | **6,821.69 / -24** | **GRAHAMS CHEVRN**
1700 SAINT MICHAELS DR
SANTA FE NM | **LUST HIST**

Form No:	762	**Contact:**	TESTONS CHEVRON
Facility ID:	27330	**CRC 32:**	1732548901
Status:	NFA	**Aggrav Factor Score:**	0
Facility Status:	No Further Action	**Mitigat Factor Score:**	0
Stat Date:		**Water Supply Impact:**	N
Date Reported:	02-JUL-91	**Vapor Explos Impact:**	N
SR Result:		**Prpty Damage Impact:**	N
Priority:		**Staff:**	UNK
Score:		**Unloc:**	FALSE
St:		**Latitude:**	0
Site Priority Rank:		**Longitude:**	0
Total Score:	0	**Facility County:**	
Tie Score:	118		

---

11 | **3 of9** | **WSW** | **0.21 / 1,089.96** | **6,821.69 / -24** | **CHEVRON STATION #76047**
1700 ST MICHAELS DR
SANTA FE NM 87501 | **RCRA NON GEN**

Handler ID:	NMD986676724
Generator Status:	N

Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Sep 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	***Used Oil Transpor:***	No
Mixed Waste Gen:	No	***Used Oil Trans Fac:***	No
Transporter:	No	***Used Oil Processor:***	No
Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	N	***NAIC 1:***	
Seq No:	1	***NAIC 2:***	
Non Notifier:		***NAIC 3:***	
Receive Date:	19920128	***NAIC 4:***	
Active Site:	-----	***State:***	NM
Land Type:	O	***Location Latitude:***	35.659169
In Handler Univ:	N	***Location Longitude:***	-105.97219
In A Universe:	N	***Loc GIS Primary:***	N
Gen Status:	N	***Loc GIS Origin:***	AG
Report Cycle:		***State District Owner:***	NM
Accessibility:		***State District:***	02
Region:	06		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	NM		
State Waste Generator:	6		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	------		
As Converter Tsdf:	------		
As State Regulated Tsdf:	------		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	------		
Permwrk ID:	------		
Perm Prog:	------		
Pcwrkld:	------		
Closwrkld:	------		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	------		
Full Enforcement:	------		

Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20020503
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	CHEVRON STATION #76047
Location Street No:	1700
Location Street1:	ST MICHAELS DR
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87501
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	MD GRAHAM
Contact Street No:	
Contact Street1:	1700 ST MICHAELS DR
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87501
Contact Country:	US
Contact Phone & Ext:	505-471-8049
Contact Fax:	
Contact Email Address:	
Contact Title:	
Owner Name:	CHEVRON USA INC
Owner Type:	P
Owner Seq:	1
Operator Name:	
Operator Type:	
Operator Seq:	
Public Notes:	

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	19920128
Handler Name:	CHEVRON STATION #76047
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Notification
TSD Activity:	N

Waste Code Details

Waste Code:	D000
Waste Code Desc:	DESCRIPTION
Waste Code:	D001
Waste Code Desc:	IGNITABLE WASTE
Waste Code:	D002
Waste Code Desc:	CORROSIVE WASTE
Waste Code:	D008
Waste Code Desc:	LEAD

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Waste Code: D018
Waste Code Desc: BENZENE

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: CHEVRON USA INC
Dt Became Current: 20020502
Dt Ended Current:
Phone: 213-694-7452
Source Type: Notification
Street No:
Street1: PO BOX 2833
Street2:
City: LA HABRA
State: CA
Country:
Zip: 90632

---

11 | **4 of9** | **WSW** | **0.21 / 1,089.96** | **6,821.69 / -24** | **CHEVRON 76047**
1700 SAINT MICHAELS DR
SANTA FE NM 87501 | **TANKS**

FID: 27330
In Use AST: 0
In Use UST: 0
Temp Out AST: 0
Temp Out UST: 0
Removed AST: 0
Removed UST: 5
Exempt AST: 0
Exempt UST: 0
Sold AST: 0
Sold UST: 0
No Data AST: 0
No Data UST: 0
County: SANTA FE
Owner ID: 15464
City (Deliv Prohib):
Cty (Del Prohib):
Owner Name: CHEVRON USA INC MARKETING DEPT
Fac Name (Del Prohibition):
Fac Owner (Deliv Prohib):
Fac Add (Delivery Prohibition):
Source: All Storage Tank List

---

11 | **5 of9** | **WSW** | **0.21 / 1,089.96** | **6,821.69 / -24** | **LLANO CHEVRON**
1700 SAINT MICHAELS DR
SANTA FE NM 87501 | **TANKS**

FID: 1480
In Use AST: 0
In Use UST: 3
Temp Out AST: 0
Temp Out UST: 0
Removed AST: 0
Removed UST: 0
Exempt AST: 0
Exempt UST: 0
Sold AST: 0
Sold UST: 0
No Data AST: 0
No Data UST: 0
County: SANTA FE
Owner ID: 314
City (Deliv Prohib):
Cty (Del Prohib):
Owner Name: BREWER OIL COMPANY
Fac Name (Del Prohibition):
Fac Owner (Deliv Prohib):
Fac Add (Delivery Prohibition):
Source: All Storage Tank List

---

11 | **6 of9** | **WSW** | **0.21 / 1,089.96** | **6,821.69 / -24** | **LLANO SHELL**
1700 SAINT MICHAELS DR
SANTA FE NM 87501 | **UST**

Facility ID: 1480
Facility Name: LLANO SHELL
Facility Address: 1700 SAINT MICHAELS DR
Address 2:
City: SANTA FE
County: SANTA FE
Zip: 87501
Fac Name (Map): LLANO SHELL
Fac Addr (Map): 1700 SAINT MICHAELS DR
Facility (Active): LLANO SHELL
Street (Active): 1700 SAINT MICHAELS DR
Street 2 (Active):
Zip (Active): 87501
City (Active): SANTA FE
County (Active): SANTA FE
Fac Name (Map-In):
Fac Addr (Map-In):
Address 2 (Map-In):

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Address2 (Map):		**City (Map-In):**	
City (Map):	SANTA FE	**County (Map-In):**	
County (Map):	SANTA FE	**Zip Cd (Map-In):**	
Fac ZIP (Map):	87501	**Lat (Map-In):**	
Latitude (Map):	35.65867	**Lon (Map-In):**	
Longitude (Map):	-105.972353	**Fac Name (Prohib):**	
Fac Name (Map-Pro):		**Fac Addr (Prohib):**	
Fac Addr (Map-Pro):		**City (Prohib):**	
City (Map-Pro):		**County (Prohib):**	
County (Map-Pro):			

Data Source: NMED PSTB All Storage Tanks Report (as of 14 Oct 2025); NMED Open Data - Underground Storage Tank Facilities (Map) (as of 3 Nov 2025); NMED PSTB Active Storage Tank List (Active) (as of 14 Oct 2025)

NMED PSTB Report - Tank Detail(s) (as of October 14, 2025)

In Use UST:	3	**Sold UST:**	0
Removed UST:	0	**No Data UST:**	0
Exempt UST:	0	**Owner ID:**	76549
Temp Out UST:	0	**Owner Name:**	NEW MEXICO COMPANY OPERATIONS LLC

NM Open Data UST

Active:	-1	**Oldest Tnk Age Type:**	25 years or more
UST:	3	**AST:**	0
UST Curr in Use:	3	**AST Curr in Use:**	0
UST Exempt:	0	**AST Exempt:**	0
UST Removed:	0	**AST Removed:**	0
UST Temp Out of Use:	0	**AST Temp Out of Use:**	0
Tanks:	3	**Shape:**	
Tanks Curr in Use:	3	**Owner ID:**	76549
Tanks Exempt:	0	**Owner Size Type:**	12 or more
Tanks Removed:	0	**Owner Name:**	NEW MEXICO COMPANY OPERATIONS LLC
Tanks Temp Out of Use:	0		

NMED PSTB Active Storage Tank List (as of October 14, 2025)

UST:	3
Owner ID:	76549
Owner Name:	NEW MEXICO COMPANY OPERATIONS LLC

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
11	7 of9	WSW	0.21 / 1,089.96	6,821.69 / -24	CHEVRON 76047 1700 SAINT MICHAELS DR SANTA FE NM 87501	UST

Facility ID:	27330	**Facility (Active):**	
Facility Name:	CHEVRON 76047	**Street (Active):**	
Facility Address:	1700 SAINT MICHAELS DR	**Street 2 (Active):**	
Address 2:		**Zip (Active):**	
City:	SANTA FE	**City (Active):**	
County:	SANTA FE	**County (Active):**	
Zip:	87501	**Fac Name (Map-In):**	CHEVRON 76047
Fac Name (Map):		**Fac Addr (Map-In):**	1700 SAINT MICHAELS DR
Fac Addr (Map):		**Address 2 (Map-In):**	
Address2 (Map):		**City (Map-In):**	SANTA FE
City (Map):		**County (Map-In):**	SANTA FE
County (Map):		**Zip Cd (Map-In):**	87501
Fac ZIP (Map):		**Lat (Map-In):**	35.658951
Latitude (Map):		**Lon (Map-In):**	-105.972338
Longitude (Map):		**Fac Name (Prohib):**	
Fac Name (Map-Pro):		**Fac Addr (Prohib):**	
Fac Addr (Map-Pro):		**City (Prohib):**	
City (Map-Pro):		**County (Prohib):**	
County (Map-Pro):			

Data Source: NMED PSTB All Storage Tanks Report (as of 14 Oct 2025); NMED Open Data - Inactive Facilities (Map-In) (as of 3

Nov 2025)

NMED PSTB Report - Tank Detail(s) (as of October 14, 2025)

In Use UST:	0	***Sold UST:***	0
Removed UST:	5	***No Data UST:***	0
Exempt UST:	0	***Owner ID:***	15464
Temp Out UST:	0	***Owner Name:***	CHEVRON USA INC MARKETING DEPT

NMED Open Data - Inactive Facilities

Active:	0	***Oldest Tnk Age Type:***	
UST:	5	***AST:***	0
UST Curr in Use:	0	***AST Curr in Use:***	0
UST Exempt:	0	***AST Exempt:***	0
UST Removed:	5	***AST Removed:***	0
UST Temp Out of Use:	0	***AST Temp Out of Use:***	0
Tanks:	5	***Shape:***	
Tanks Curr in Use:	0	***Owner ID:***	15464
Tanks Exempt:	0	***Owner Size Type:***	
Tanks Removed:	5	***Owner Name:***	CHEVRON USA INC MARKETING DEPT
TanksTemp OutofUse:	0		

---

11 | ***8 of9*** | ***WSW*** | ***0.21 / 1,089.96*** | ***6,821.69 / -24*** | ***CHEVRON 76047
1700 SAINT MICHAELS DR
SANTA FE NM 87501*** | ***UST HIST***

Facility ID:	27330
Facility Addr2:	
Facility County:	SANTA FE

Details

Tank ID:	22800	***Owner Add2:***	ATTN PERMIT DESK
Tank Type:	Underground	***Owner City:***	SAN RAMON
Tank Status:	REMOVED	***Owner St:***	CA
Tank Capacity (GAL):	500	***Owner ZIP:***	94583
Tank Contents:	USED OIL	***Owner Ph:***	510-842-9002
Owner ID:	15464		
Owner Name:	CHEVRON USA INC MARKETING DEPT		
Owner Address:	PO BOX 5004		

Details

Tank ID:	22798	***Owner Add2:***	ATTN PERMIT DESK
Tank Type:	Underground	***Owner City:***	SAN RAMON
Tank Status:	REMOVED	***Owner St:***	CA
Tank Capacity (GAL):	8000	***Owner ZIP:***	94583
Tank Contents:	GASOLINE UNKNOWN TYPE	***Owner Ph:***	510-842-9002
Owner ID:	15464		
Owner Name:	CHEVRON USA INC MARKETING DEPT		
Owner Address:	PO BOX 5004		

Details

Tank ID:	22801	***Owner Add2:***	ATTN PERMIT DESK
Tank Type:	Underground	***Owner City:***	SAN RAMON
Tank Status:	REMOVED	***Owner St:***	CA
Tank Capacity (GAL):	1000	***Owner ZIP:***	94583
Tank Contents:	USED OIL	***Owner Ph:***	510-842-9002
Owner ID:	15464		

Owner Name: CHEVRON USA INC MARKETING DEPT
Owner Address: PO BOX 5004

Details

Tank ID: 22799
Tank Type: Underground
Tank Status: REMOVED
Tank Capacity (GAL): 4000
Tank Contents: GASOLINE UNKNOWN TYPE
Owner ID: 15464
Owner Name: CHEVRON USA INC MARKETING DEPT
Owner Address: PO BOX 5004
Owner Add2: ATTN PERMIT DESK
Owner City: SAN RAMON
Owner St: CA
Owner ZIP: 94583
Owner Ph: 510-842-9002

Details

Tank ID: 22797
Tank Type: Underground
Tank Status: REMOVED
Tank Capacity (GAL): 8000
Tank Contents: GASOLINE UNKNOWN TYPE
Owner ID: 15464
Owner Name: CHEVRON USA INC MARKETING DEPT
Owner Address: PO BOX 5004
Owner Add2: ATTN PERMIT DESK
Owner City: SAN RAMON
Owner St: CA
Owner ZIP: 94583
Owner Ph: 510-842-9002

11	9 of9	WSW	0.21 / 1,089.96	6,821.69 / -24	LLANO CHEVRON 1700 SAINT MICHAELS DR SANTA FE NM 87501	UST HIST

Facility ID: 1480
Facility Addr2:
Facility County: SANTA FE

Details

Tank ID: 18426
Tank Type: Underground
Tank Status: CURRENTLY IN USE
Tank Capacity (GAL): 10000
Tank Contents: SUPER UNLEADED
Owner ID: 314
Owner Name: BREWER OIL COMPANY
Owner Address: 3200 CANDELARIA RD NE
Owner Add2:
Owner City: ALBUQUERQUE
Owner St: NM
Owner ZIP: 87107
Owner Ph: 505-748-1248

Details

Tank ID: 18424
Tank Type: Underground
Tank Status: CURRENTLY IN USE
Tank Capacity (GAL): 10000
Tank Contents: UNLEADED GASOLINE
Owner ID: 314
Owner Name: BREWER OIL COMPANY
Owner Address: 2701 CANDELARIA NE
Owner Add2:
Owner City: ALBUQUERQUE
Owner St: NM
Owner ZIP: 87107
Owner Ph: 505-884-2040

Details

Tank ID: 18425
Tank Type: Underground
Tank Status: CURRENTLY IN USE
Tank Capacity (GAL): 10000
Tank Contents: UNLEADED PLUS
Owner Add2:
Owner City: ALBUQUERQUE
Owner St: NM
Owner ZIP: 87107
Owner Ph: 505-884-2040

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner ID: 314
Owner Name: BREWER OIL COMPANY
Owner Address: 2701 CANDELARIA NE

Details

Tank ID: 18425
Tank Type: Underground
Tank Status: CURRENTLY IN USE
Tank Capacity (GAL): 10000
Tank Contents: UNLEADED PLUS
Owner ID: 314
Owner Name: BREWER OIL COMPANY
Owner Address: 3200 CANDELARIA RD NE
Owner Add2:
Owner City: ALBUQUERQUE
Owner St: NM
Owner ZIP: 87107
Owner Ph: 505-748-1248

Details

Tank ID: 18426
Tank Type: Underground
Tank Status: CURRENTLY IN USE
Tank Capacity (GAL): 10000
Tank Contents: SUPER UNLEADED
Owner ID: 314
Owner Name: BREWER OIL COMPANY
Owner Address: 2701 CANDELARIA NE
Owner Add2:
Owner City: ALBUQUERQUE
Owner St: NM
Owner ZIP: 87107
Owner Ph: 505-884-2040

Details

Tank ID: 18424
Tank Type: Underground
Tank Status: CURRENTLY IN USE
Tank Capacity (GAL): 10000
Tank Contents: UNLEADED GASOLINE
Owner ID: 314
Owner Name: BREWER OIL COMPANY
Owner Address: 3200 CANDELARIA RD NE
Owner Add2:
Owner City: ALBUQUERQUE
Owner St: NM
Owner ZIP: 87107
Owner Ph: 505-748-1248

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
12	1 of7	W	0.21 / 1,131.65	6,820.20 / -25	HORACE CHRYSLER JEEP AND KIA 1701 ST MICHAELS DR SANTA FE NM	LST

Release ID: 4451
Facility ID: 27353
Status: No Further Action, Confirmed Release
Address:
City:
County:
Address (NFA): 1701 ST MICHAELS DR
City (NFA): SANTA FE
County (NFA): SANTA FE
Facility Release IDs (Map): 4451
Latitude (Map): 35.659963
Longitude (Map): -105.972394
Address (Map): 1701 ST MICHAELS DR
Address2 (Map):
City (Map): SANTA FE
State (Map): NM
Zip (Map): 87501
Address (Priority):
City (Priority):
County (Priority):
Data Source: NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)

PSTB No Further Action Sites

Status: No Further Action, Confirmed Release
NFA Date: 12/22/2008
NFA PDF: https://cloud.env.nm.gov/resources/collection/10867

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Leaking Petroleum Storage Tank Sites

Status Date Dt:	2008-12-22 00:00:00 UTC	**NAPL Off Site Val:**	0
Within SWPA Val:	0	**Plume Area No:**	
Surface Water Val:	0	**Plume Area Val:**	2
Private Well Val:	0	**Max Thickness No:**	
Municipal Well Val:	0	**Max Thickness Val:**	
LUWU Sco:	0	**NAPLSco:**	0
Surficial Conc Des:		**Priority2 Sco:**	0
Surficial Conc Val:	0	**Impact Type Des:**	
Leaching Conc Des:		**Impact Type Val:**	0
Leaching Conc Val:	0	**WS Type Des:**	
Construct Conc Des:		**WS Type Val:**	0
Construct Conc Val:	0	**WTR Sys Repl Des:**	
Building Type Des:		**WTR Sys Repl Val:**	0
Building Type Val:	0	**Population No:**	
Vad Off Site Val:	1	**Population Val:**	1
Vadose Sco:	0	**WS Sco:**	0
Conc Des:		**Toxic Vapor Des:**	
Conc Val:	0	**Toxic Vapor Val:**	0
Plume Mob Des:		**Toxic Vapor Sco:**	0
Plume Mob Val:	0	**Priority1 Sco:**	0
GWDPP Off Site Val:	0	**Total Sco:**	0
Benzene Area No:		**Tempo Total Sco:**	
Benzene Area Val:	1	**Current Priority:**	
GWDPP Sco:	0	**Tempo Current Rank:**	
Priority3 Sco:	0	**Tempo Curr Priorty:**	
CSS Age Des:		**Point X:**	-105.97239400000001
CSS Age Val:	0	**Point Y:**	35.659963000000005
CSS Type Des:		**Irrigation Well Val:**	0
CSS Type Val:	0	**Subsurf Conc Des:**	
CSS Off Site Val:	1	**Subsurface Conc Val:**	0
CSS Sco:	0	**Petrol Soil Bldg Val:**	1
CSS Volume No:		**Petrol Soil Vol Val:**	0
CSS Volume Val:	3	**Hydraulic Grad Val:**	0
Release Pm:	Susan Von Gonten	**Depth to GW:**	
NAPL Type Des:		**Depth to GW Val:**	2
NAPL Type Val:	0	**Explosive Vapor Des:**	
NAPL Age Des:		**Explosive Vapor Val:**	0
NAPL Age Val:	0	**Explosive Vapor Sco:**	0
NAPLCondition Des:		**Eco Impact Val:**	0
NAPLCondition Val:	0	**Eco Impact Sco:**	0
Facility Name:	HORACE CHRYSLER JEEP AND KIA		
Current Status:	No Further Action, Confirmed Release		
Aquifer Water Quality Des:			
Aquifer Water Quality Val:	0		
Residential Property Val:	0		
NAPL Plume Mobility Des:			
NAPL Plume Mobility Val:	0		
Property Damage Des:			
Property Damage Val:	0		
Property Damage Sco:	0		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
12	2 of7	W	0.21 / 1,131.65	6,820.20 / -25	Horace Chrysler Jeep 1701 St Michaels Dr Santa Fe NM 87501	LUST HIST

Form No:	4451	**Contact:**	
Facility ID:	27353	**CRC 32:**	2210281871
Status:	PI-C	**Aggrav Factor Score:**	
Facility Status:	Pre-Investigation, Confirmed release	**Mitigat Factor Score:**	
Stat Date:	04/15/2005	**Water Supply Impact:**	
Date Reported:	04/15/2005	**Vapor Explos Impact:**	
SR Result:		**Prpty Damage Impact:**	
Priority:		**Staff:**	Susan Von Gonten
Score:		**Unloc:**	
St:	NM	**Latitude:**	
Site Priority Rank:		**Longitude:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Total Score:				**Facility County:**	Santa Fe	
Tie Score:						

12	3 of7	W	0.21 / 1,131.65	6,820.20 / -25	SANTA FE KIA 1701 ST MICHAELS DR SANTA FE NM 87505	RCRA VSQG

Handler ID: NMD981610397
Generator Status: VSG
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Sep 2025.

Violation Details

Viol Type: 262.A
Citation:
Determined Date: 20170706
Scheduled Compliance Date:
Eval Activity Location: NM
Viol Determined By Agency: State
Viol Short Desc: Generators - General
Actual Rtc Date: 20170822
Found Violation: Yes
Rtc Qualifier: Documented

Enforcement Details

Enf Type: 120
Enf Type Desc: WRITTEN INFORMAL
Enf Action Date: 20170720
Disposition Status Desc:
Disposition Status Date:
Enf Agency: State
Proposed Amount:
Final Amount:
Paid Amount:

Violation Details

Viol Type: 279.C
Citation:
Determined Date: 20170706
Scheduled Compliance Date:
Eval Activity Location: NM
Viol Determined By Agency: State
Viol Short Desc: Used Oil - Generators
Actual Rtc Date: 20170822
Found Violation: Yes
Rtc Qualifier: Documented

Enforcement Details

Enf Type: 120
Enf Type Desc: WRITTEN INFORMAL
Enf Action Date: 20170720
Disposition Status Desc:
Disposition Status Date:
Enf Agency: State
Proposed Amount:
Final Amount:
Paid Amount:

Violation Details

Viol Type: 279.C
Citation:
Determined Date: 20060531
Scheduled Compliance Date:
Eval Activity Location: NM
Viol Determined By Agency: State
Viol Short Desc: Used Oil - Generators
Actual Rtc Date: 20060531
Found Violation: Yes
Rtc Qualifier: Documented

Enforcement Details

Enf Type: 120
Enf Type Desc: WRITTEN INFORMAL
Enf Action Date: 20060817
Disposition Status Desc:
Disposition Status Date:
Enf Agency: State
Proposed Amount:
Final Amount:
Paid Amount:

Evaluation Details

Eval Start Date: 20170706
Eval Type Desc: COMPLIANCE EVALUATION INSPECTION
Viol Short Desc: Used Oil - Generators
Actual Rtc Date: 20170822
Eval Agency: State

Eval Start Date: 20170706
Eval Type Desc: COMPLIANCE EVALUATION INSPECTION
Viol Short Desc: Generators - General
Actual Rtc Date: 20170822
Eval Agency: State

Eval Start Date: 20060531
Eval Type Desc: COMPLIANCE EVALUATION INSPECTION
Viol Short Desc: Used Oil - Generators
Actual Rtc Date: 20060531
Eval Agency: State

Handler Summary

Importer: No
Mixed Waste Gen: No
Transporter: No
Transfer Facility: No
Recycler: No
Onsite Burner Exem: No
Furnace Exemption: No
Underground Injec: No
Used Oil Market Burner: No
Used Oil Spec Marketer: No
Used Oil Transpor: No
Used Oil Trans Fac: No
Used Oil Processor: No
Used Oil Refiner: No
Used Oil Burner: No
Commercial TSD: No
Recycl Nonstorage: No

Additional Handler Summary Details

Source Type: N
Seq No: 3
Non Notifier:
Receive Date: 20170717
Active Site: H----
NAIC 1: 44111
NAIC 2: 44112
NAIC 3: 81111
NAIC 4:
State: NM

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Land Type:	P	**Location Latitude:**	35.66253
In Handler Univ:	Y	**Location Longitude:**	-105.977229
In A Universe:	Y	**Loc GIS Primary:**	N
Gen Status:	VSG	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	NM
Accessibility:		**State District:**	
Region:	06		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	NM
State Waste Generator:	N
Short Term Generator:	N
Uni Waste:	N
Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20170921
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	SANTA FE KIA
Location Street No:	1701
Location Street1:	ST MICHAELS DR
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87505
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	CASSIE ROEFIA
Contact Street No:	1701
Contact Street1:	ST MICHAELS DR
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87505
Contact Country:	US
Contact Phone & Ext:	505-982-1957

Contact Fax:
Contact Email Address: CROERIG@KIAOFSANTAFE.NET
Contact Title: HR OFFIC MGR
Owner Name: SANTA FE K LLC DBA SANTA FE KIA
Owner Type: P
Owner Seq: 1
Operator Name: SANTA FE K LLC DBA SANTA FE KIA
Operator Type: P
Operator Seq: 2
Public Notes:

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 19861006
Handler Name: SANTA FE CHRY-PLY
Fed Waste Generator: 2
Generator Code Description: Small Quantity Generator
Source Type: Notification
TSD Activity: N

Waste Code Details

Waste Code: D000
Waste Code Desc: DESCRIPTION

Waste Code: D001
Waste Code Desc: IGNITABLE WASTE

Hazardous Waste Handler Details

Seq No: 2
Receive Date: 20060614
Handler Name: CAR WORLD KIA
Fed Waste Generator: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification
TSD Activity: N

Waste Code Details

Waste Code: D002
Waste Code Desc: CORROSIVE WASTE

Waste Code: D008
Waste Code Desc: LEAD

Hazardous Waste Handler Details

Seq No: 3
Receive Date: 20170717
Handler Name: SANTA FE KIA
Fed Waste Generator: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification
TSD Activity: N

Waste Code Details

Waste Code: D008
Waste Code Desc: LEAD

Waste Code:	F003
Waste Code Desc:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F005
Waste Code Desc:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	U_OIL
Waste Code Desc:	Used Oil

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	1712
Type:	Private	***Street1:***	ST .MICHAELS DR
Name:	JOE HORACE	***Street2:***	
Dt Became Current:	20050101	***City:***	SANTA FE
Dt Ended Current:		***State:***	NM
Phone:	505-982-1950	***Country:***	US
Source Type:	Notification	***Zip:***	87505
Owner/Operator Ind:	Current Operator	***Street No:***	1712
Type:	Private	***Street1:***	ST .MICHAELS DR
Name:	CAR WORLD KIA	***Street2:***	
Dt Became Current:	20050101	***City:***	SANTA FE
Dt Ended Current:		***State:***	NM
Phone:	505-982-1950	***Country:***	US
Source Type:	Notification	***Zip:***	87505
Owner/Operator Ind:	Current Operator	***Street No:***	1712
Type:	Private	***Street1:***	ST .MICHAELS DR
Name:	SANTA FE K LLC DBA SANTA FE KIA	***Street2:***	
Dt Became Current:	20170201	***City:***	SANTA FE
Dt Ended Current:		***State:***	NM
Phone:	505-982-1950	***Country:***	US
Source Type:	Notification	***Zip:***	87505
Owner/Operator Ind:	Current Owner	***Street No:***	1712
Type:	Private	***Street1:***	ST .MICHAELS DR
Name:	SANTA FE K LLC DBA SANTA FE KIA	***Street2:***	
Dt Became Current:	20170201	***City:***	SANTA FE
Dt Ended Current:		***State:***	NM
Phone:	505-982-1950	***Country:***	US
Source Type:	Notification	***Zip:***	87505
Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street1:***	UNKNOWN
Name:	JOE HORACE	***Street2:***	
Dt Became Current:		***City:***	UNKNOWN
Dt Ended Current:		***State:***	NM
Phone:	000-000-0000	***Country:***	
Source Type:	Notification	***Zip:***	00000-0000
Owner/Operator Ind:	Current Operator	***Street No:***	
Type:	Private	***Street1:***	UNKNOWN
Name:	HORACE JOE	***Street2:***	
Dt Became Current:		***City:***	UNKNOWN

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Dt Ended Current: | **State:** NM
Phone: 000-000-0000 | **Country:**
Source Type: Notification | **Zip:** 00000-0000

Historical Handler Details

Receive Dt: 20060614
Generator Code Description: Very Small Quantity Generator
Handler Name: CAR WORLD KIA

Receive Dt: 19861006
Generator Code Description: Small Quantity Generator
Handler Name: SANTA FE CHRY-PLY

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
12	4 of7	W	0.21 / 1,131.65	6,820.20 / -25	HORACE CHRYSLER JEEP AND KIA 1701 ST MICHAELS DR SANTA FE NM 87501	TANKS

FID: 27353 | **Sold AST:** 0
In Use AST: 0 | **Sold UST:** 0
In Use UST: 0 | **No Data AST:** 0
Temp Out AST: 0 | **No Data UST:** 0
Temp Out UST: 0 | **County:** SANTA FE
Removed AST: 0 | **Owner ID:** 15213
Removed UST: 3 | **City (Deliv Prohib):**
Exempt AST: 0 | **Cty (Del Prohib):**
Exempt UST: 0
Owner Name: CHRYSLER REALTY
Fac Name (Del Prohibition):
Fac Owner (Deliv Prohib):
Fac Add (Delivery Prohibition):
Source: All Storage Tank List

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
12	5 of7	W	0.21 / 1,131.65	6,820.20 / -25	HORACE CHRYSLER JEEP AND KIA 1701 ST MICHAELS DR SANTA FE NM 87501	UST

Facility ID: 27353 | **Facility (Active):**
Facility Name: HORACE CHRYSLER JEEP AND KIA | **Street (Active):**
Facility Address: 1701 ST MICHAELS DR | **Street 2 (Active):**
Address 2: | **Zip (Active):**
City: SANTA FE | **City (Active):**
County: SANTA FE | **County (Active):**
Zip: 87501 | **Fac Name (Map-In):** HORACE CHRYSLER JEEP AND KIA
Fac Name (Map): | **Fac Addr (Map-In):** 1701 ST MICHAELS DR
Fac Addr (Map): | **Address 2 (Map-In):**
Address2 (Map): | **City (Map-In):** SANTA FE
City (Map): | **County (Map-In):** SANTA FE
County (Map): | **Zip Cd (Map-In):** 87501
Fac ZIP (Map): | **Lat (Map-In):** 35.659963
Latitude (Map): | **Lon (Map-In):** -105.972394
Longitude (Map): | **Fac Name (Prohib):**
Fac Name (Map-Pro): | **Fac Addr (Prohib):**
Fac Addr (Map-Pro): | **City (Prohib):**
City (Map-Pro): | **County (Prohib):**
County (Map-Pro):
Data Source: NMED PSTB All Storage Tanks Report (as of 14 Oct 2025); NMED Open Data - Inactive Facilities (Map-In) (as of 3 Nov 2025)

NMED PSTB Report - Tank Detail(s) (as of October 14, 2025)

In Use UST: 0 | **Sold UST:** 0
Removed UST: 3 | **No Data UST:** 0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Exempt UST:	0	**Owner ID:**	15213
Temp Out UST:	0	**Owner Name:**	CHRYSLER REALTY

NMED Open Data - Inactive Facilities

Active:	0	**Oldest Tnk Age Type:**	
UST:	3	**AST:**	0
UST Curr in Use:	0	**AST Curr in Use:**	0
UST Exempt:	0	**AST Exempt:**	0
UST Removed:	3	**AST Removed:**	0
UST Temp Out of Use:	0	**AST Temp Out of Use:**	0
Tanks:	3	**Shape:**	
Tanks Curr in Use:	0	**Owner ID:**	15213
Tanks Exempt:	0	**Owner Size Type:**	
Tanks Removed:	3	**Owner Name:**	CHRYSLER REALTY
TanksTemp OutofUse:	0		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
12	6 of7	W	0.21 / 1,131.65	6,820.20 / -25	CHRYSLER PLYMOUTH DODGE OF SANTA FE 1701 SAINT MICHAELS DR SANTA FE NM 87501	UST HIST

Facility ID:	27354
Facility Addr2:	
Facility County:	SANTA FE

Details

Tank ID:		**Owner Add2:**	
Tank Type:		**Owner City:**	
Tank Status:		**Owner St:**	
Tank Capacity (GAL):		**Owner ZIP:**	
Tank Contents:		**Owner Ph:**	
Owner ID:			
Owner Name:			
Owner Address:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
12	7 of7	W	0.21 / 1,131.65	6,820.20 / -25	CHRYSLER PLYMOUTH 1701 ST MICHAELS DR SANTA FE NM 87501	UST HIST

Facility ID:	27353
Facility Addr2:	
Facility County:	SANTA FE

Details

Tank ID:	22856	**Owner Add2:**	
Tank Type:	Underground	**Owner City:**	SANTA FE
Tank Status:	REMOVED	**Owner St:**	NM
Tank Capacity (GAL):	500	**Owner ZIP:**	87501
Tank Contents:	USED OIL	**Owner Ph:**	505-982-1956
Owner ID:	16392		
Owner Name:	HANCOCK NASH		
Owner Address:	510 NORTH GUADALUPE		

Details

Tank ID:	22858	**Owner Add2:**	
Tank Type:	Underground	**Owner City:**	SANTA FE
Tank Status:	REMOVED	**Owner St:**	NM
Tank Capacity (GAL):	2000	**Owner ZIP:**	87501

Tank Contents:	GASOLINE UNKNOWN TYPE	**Owner Ph:**	505-983-8459
Owner ID:	15200		
Owner Name:	CHAMPION OIL CO INC		
Owner Address:	PO BOX 4970		

Details

Tank ID:	22857	**Owner Add2:**	
Tank Type:	Underground	**Owner City:**	SANTA FE
Tank Status:	REMOVED	**Owner St:**	NM
Tank Capacity (GAL):	2000	**Owner ZIP:**	87501
Tank Contents:	GASOLINE UNKNOWN TYPE	**Owner Ph:**	505-983-8459
Owner ID:	15200		
Owner Name:	CHAMPION OIL CO INC		
Owner Address:	PO BOX 4970		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
13	1 of4	NE	0.21 / 1,133.76	6,871.47 / 26	STREAMLINE CUSTOM PAINTING INC 1808 2ND ST SUITE G SANTA FE NM 87505	RCRA NON GEN

Handler ID:	NMR000012278
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Sep 2025.

Evaluation Details

Eval Start Date:	20070301
Eval Type Desc:	COMPLIANCE ASSISTANCE VISIT
Viol Short Desc:	
Actual Rtc Date:	
Eval Agency:	State

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	**NAIC 1:**	23521
Seq No:	1	**NAIC 2:**	23542
Non Notifier:		**NAIC 3:**	
Receive Date:	20100423	**NAIC 4:**	
Active Site:	H----	**State:**	NM
Land Type:	P	**Location Latitude:**	35.664062
In Handler Univ:	Y	**Location Longitude:**	-105.966662

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

In A Universe:	Y	***Loc GIS Primary:***	N
Gen Status:	N	***Loc GIS Origin:***	AG
Report Cycle:		***State District Owner:***	NM
Accessibility:		***State District:***	02
Region:	06		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	NM
State Waste Generator:	7
Short Term Generator:	N
Uni Waste:	Y
Universal Waste Dest Facility:	N
Federal Universal Waste:	Y
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20100423
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	STREAMLINE CUSTOM PAINTING INC
Location Street No:	1808
Location Street1:	2ND ST SUITE G
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87505
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	JAMES BOHLMAN
Contact Street No:	1808
Contact Street1:	2ND ST SUITE G
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87505
Contact Country:	US
Contact Phone & Ext:	505-995-1994
Contact Fax:	
Contact Email Address:	STREAMLINEINC@GMAIL.COM

Contact Title:
Owner Name: NYDES PROPERTIES LTD CO
Owner Type: P
Owner Seq: 1
Operator Name: STREAMLINE CUSTOM PAINTING
Operator Type: P
Operator Seq: 2
Public Notes:

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20070305
Handler Name: STREAMLINE CUSTOM PAINTING INC
Fed Waste Generator: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification
TSD Activity: N

Waste Code Details

Waste Code: D001
Waste Code Desc: IGNITABLE WASTE

Waste Code: D006
Waste Code Desc: CADMIUM

Waste Code: D007
Waste Code Desc: CHROMIUM

Waste Code: D008
Waste Code Desc: LEAD

Waste Code: D035
Waste Code Desc: METHYL ETHYL KETONE

Waste Code: F003
Waste Code Desc: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Code Desc: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20100423
Handler Name: STREAMLINE CUSTOM PAINTING INC
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer
TSD Activity: N

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	1808
Type:	Private	***Street1:***	2ND ST SUITE G
Name:	STREAMLINE CUSTOM PAINTING	***Street2:***	
Dt Became Current:	19990101	***City:***	SANTA FE
Dt Ended Current:		***State:***	NM
Phone:	505-995-1994	***Country:***	US
Source Type:	Implementer	***Zip:***	87505

Owner/Operator Ind:	Current Owner	***Street No:***	1911
Type:	Private	***Street1:***	5TH ST SUITE 202
Name:	NYDES PROPERTIES LTD CO	***Street2:***	
Dt Became Current:	19870701	***City:***	SANTA FE
Dt Ended Current:		***State:***	NM
Phone:		***Country:***	US
Source Type:	Implementer	***Zip:***	87505

Owner/Operator Ind:	Current Operator	***Street No:***	1808
Type:	Private	***Street1:***	2ND ST SUITE G
Name:	STREAMLINE CUSTOM PAINTING	***Street2:***	
Dt Became Current:	19990101	***City:***	SANTA FE
Dt Ended Current:		***State:***	NM
Phone:	505-995-1994	***Country:***	US
Source Type:	Notification	***Zip:***	87505

Owner/Operator Ind:	Current Owner	***Street No:***	1911
Type:	Private	***Street1:***	5TH ST SUITE 202
Name:	NYDES PROPERTIES LTD CO	***Street2:***	
Dt Became Current:	19870701	***City:***	SANTA FE
Dt Ended Current:		***State:***	NM
Phone:		***Country:***	US
Source Type:	Notification	***Zip:***	87505

Historical Handler Details

Receive Dt:	20070305
Generator Code Description:	Very Small Quantity Generator
Handler Name:	STREAMLINE CUSTOM PAINTING INC

13	*2 of4*	*NE*	*0.21 / 1,133.76*	*6,871.47 / 26*	***CERL INC*** ***1808 SECOND ST STE D*** ***SANTA FE NM 87505***	***RCRA NON GEN***

Handler ID:	NMD986684611
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Sep 2025.

Evaluation Details

Eval Start Date:	20050118
Eval Type Desc:	COMPLIANCE EVALUATION INSPECTION
Viol Short Desc:	
Actual Rtc Date:	
Eval Agency:	State

Handler Summary

Importer:	No	***Used Oil Transpor:***	No
Mixed Waste Gen:	No	***Used Oil Trans Fac:***	No
Transporter:	No	***Used Oil Processor:***	No
Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	N	***NAIC 1:***	
Seq No:	3	***NAIC 2:***	
Non Notifier:		***NAIC 3:***	
Receive Date:	20140304	***NAIC 4:***	
Active Site:	-----	***State:***	NM
Land Type:	P	***Location Latitude:***	35.662834
In Handler Univ:	N	***Location Longitude:***	-105.965426
In A Universe:	N	***Loc GIS Primary:***	N
Gen Status:	N	***Loc GIS Origin:***	AG
Report Cycle:		***State District Owner:***	NM
Accessibility:		***State District:***	02
Region:	06		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	NM		
State Waste Generator:	N		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	------		
As Converter Tsdf:	------		
As State Regulated Tsdf:	------		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	------		
Permwrk ID:	------		
Perm Prog:	------		
Pcwrkld:	------		
Closwrkld:	------		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	------		
Full Enforcement:	------		
Snc:	N		
Unaddressed Snc:	N		
Addressed Snc:	N		
Snc With Comp Sched:	N		
Fa Required:	-----		
Hhandler Last Change:	20140313		
Recognized Trader Importer:	N		
Recognized Trader Exporter:	N		
Slab Importer:	N		
Slab Exporter:	N		

Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	CERL INC
Location Street No:	1808
Location Street1:	SECOND ST STE D
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87505
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	MICHAEL S CURTIS
Contact Street No:	
Contact Street1:	PO BOX 4673
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87505
Contact Country:	US
Contact Phone & Ext:	505-988-4143
Contact Fax:	505-982-6759
Contact Email Address:	MCURTIS@CERL-FSI.COM
Contact Title:	PRESIDENT
Owner Name:	CERL INC
Owner Type:	P
Owner Seq:	1
Operator Name:	CERL INC
Operator Type:	P
Operator Seq:	2
Public Notes:	

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	19930721
Handler Name:	CERL INC
Fed Waste Generator:	3
Generator Code Description:	Very Small Quantity Generator
Source Type:	Notification
TSD Activity:	N

Waste Code Details

Waste Code:	D000
Waste Code Desc:	DESCRIPTION
Waste Code:	D001
Waste Code Desc:	IGNITABLE WASTE
Waste Code:	D002
Waste Code Desc:	CORROSIVE WASTE
Waste Code:	D003
Waste Code Desc:	REACTIVE WASTE
Waste Code:	D009
Waste Code Desc:	MERCURY
Waste Code:	D018
Waste Code Desc:	BENZENE
Waste Code:	D022
Waste Code Desc:	CHLOROFORM

Waste Code: D040
Waste Code Desc: TRICHLOROETHYLENE

Waste Code: F001
Waste Code Desc: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Code Desc: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F038
Waste Code Desc: PETROLEUM REFINERY SECONDARY (EMULSIFIED) OIL/WATER/SOLIDS SEPARATION SLUDGE - ANY SLUDGE AND/OR FLOAT GENERATED FROM THE PHYSICAL AND/OR CHEMICAL SEPARATION OF OIL/WATER/SOLIDS IN PROCESS WASTEWATERS AND OILY COOLING WASTEWATERS FROM PETROLEUM REFINERIES. SUCH WASTES INCLUDE, BUT ARE NOT LIMITED TO, ALL SLUDGES AND FLOATS GENERATED IN INDUCED AIR FLOTATION (IAF) UNITS, TANKS AND IMPOUNDMENTS, AND ALL SLUDGES GENERATED IN DAF UNITS. SLUDGES GENERATED IN STORMWATER UNITS THAT DO NOT RECEIVE DRY WEATHER FLOW, SLUDGES GENERATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS AS DEFINED IN SECTION 261.31(B)(2) (INCLUDING SLUDGES GENERATED IN ONE OR MORE ADDITIONAL UNITS AFTER WASTEWATERS HAVE BEEN TREATED IN AGGRESSIVE BIOLOGICAL TREATMENT UNITS), AND F037, K048, AND K051 WASTES ARE EXEMPTED FROM THIS LISTING.

Waste Code: F039
Waste Code Desc: LEACHATE RESULTING FROM THE TREATMENT, STORAGE, OR DISPOSAL OF WASTES CLASSIFIED BY MORE THAN ONE WASTE CODE UNDER SUBPART D, OR FROM A MIXTURE OF WASTES CLASSIFIED UNDER SUBPARTS C AND D OF THIS PART. (LEACHATE RESULTING FROM THE MANAGEMENT OF ONE OR MORE OF THE FOLLOWING EPA HAZARDOUS WASTES AND NO OTHER HAZARDOUS WASTES RETAINS ITS HAZARDOUS WASTE CODE(S): F020, F021, F022, F023, F026, F027, AND/OR F028.)

Hazardous Waste Handler Details

Seq No: 2
Receive Date: 20050118
Handler Name: CERL INC
Fed Waste Generator: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification
TSD Activity: N

Waste Code Details

Waste Code: D001
Waste Code Desc: IGNITABLE WASTE

Hazardous Waste Handler Details

Seq No: 3
Receive Date: 20140304
Handler Name: CERL INC
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Notification
TSD Activity: N

Owner/Operator Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street1:**	PO BOX 4673
Name:	CERL INC	**Street2:**	
Dt Became Current:	19900101	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:	505-988-4143	**Country:**	US
Source Type:	Notification	**Zip:**	87505

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street1:**	PO BOX 4673
Name:	CERL INC	**Street2:**	
Dt Became Current:		**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:	505-988-4143	**Country:**	
Source Type:	Notification	**Zip:**	87502

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street1:**	PO BOX 4673
Name:	CERL INC	**Street2:**	
Dt Became Current:	19900101	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:	505-988-4143	**Country:**	US
Source Type:	Notification	**Zip:**	87505

Historical Handler Details

Receive Dt:	20050118
Generator Code Description:	Very Small Quantity Generator
Handler Name:	CERL INC

Receive Dt:	19930721
Generator Code Description:	Very Small Quantity Generator
Handler Name:	CERL INC

13	*3 of4*	*NE*	*0.21 / 1,133.76*	*6,871.47 / 26*	***CHANDLER CHAIR COMPANY 1808 SECOND STREET SUITE L SANTA FE NM 87505***	***RCRA NON GEN***

Handler ID:	NMR000012039
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Sep 2025.

Evaluation Details

Eval Start Date:	20061030
Eval Type Desc:	COMPLIANCE ASSISTANCE VISIT
Viol Short Desc:	
Actual Rtc Date:	
Eval Agency:	State

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No

Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	**NAIC 1:**	337212
Seq No:	1	**NAIC 2:**	81142
Non Notifier:		**NAIC 3:**	23599
Receive Date:	20150807	**NAIC 4:**	
Active Site:	-----	**State:**	NM
Land Type:	P	**Location Latitude:**	35.662534
In Handler Univ:	N	**Location Longitude:**	-105.965117
In A Universe:	N	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	NM
Accessibility:		**State District:**	02
Region:	06		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	NM
State Waste Generator:	N
Short Term Generator:	N
Uni Waste:	N
Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20150821
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	CHANDLER CHAIR COMPANY
Location Street No:	1808
Location Street1:	SECOND STREET SUITE L
Location Street2:	
Location City:	SANTA FE

Location State:	NM
Location Zip:	87505
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	PETER CHANDLER
Contact Street No:	1808
Contact Street1:	SECOND STREET SUITE L
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87505
Contact Country:	US
Contact Phone & Ext:	505-982-2588
Contact Fax:	
Contact Email Address:	
Contact Title:	
Owner Name:	NYDES PROPERTIES, LTD CO
Owner Type:	P
Owner Seq:	1
Operator Name:	PETER CHANDLER
Operator Type:	P
Operator Seq:	2
Public Notes:	

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20061128
Handler Name:	CHANDLER CHAIR COMPANY
Fed Waste Generator:	3
Generator Code Description:	Very Small Quantity Generator
Source Type:	Notification
TSD Activity:	N

Waste Code Details

Waste Code:	D001
Waste Code Desc:	IGNITABLE WASTE
Waste Code:	D009
Waste Code Desc:	MERCURY
Waste Code:	F003
Waste Code Desc:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20150807
Handler Name:	CHANDLER CHAIR COMPANY
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Implementer
TSD Activity:	N

Owner/Operator Details

Owner/Operator Ind:	Current Operator	**Street No:**	1808
Type:	Private	**Street1:**	SECOND STREET SUITE L
Name:	PETER CHANDLER	**Street2:**	
Dt Became Current:	20000101	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:	505-982-2588	**Country:**	US
Source Type:	Notification	**Zip:**	87505

Owner/Operator Ind:	Current Operator	**Street No:**	1808
Type:	Private	**Street1:**	SECOND STREET SUITE L
Name:	PETER CHANDLER	**Street2:**	
Dt Became Current:	20000101	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:	505-982-2588	**Country:**	US
Source Type:	Implementer	**Zip:**	87505

Owner/Operator Ind:	Current Owner	**Street No:**	1911
Type:	Private	**Street1:**	5TH STREET SUITE 202
Name:	NYDES PROPERTIES, LTD CO	**Street2:**	
Dt Became Current:	19870701	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:		**Country:**	US
Source Type:	Implementer	**Zip:**	87505

Owner/Operator Ind:	Current Owner	**Street No:**	1911
Type:	Private	**Street1:**	5TH STREET SUITE 202
Name:	NYDES PROPERTIES, LTD CO	**Street2:**	
Dt Became Current:	19870701	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:		**Country:**	US
Source Type:	Notification	**Zip:**	87505

Historical Handler Details

Receive Dt:	20061128
Generator Code Description:	Very Small Quantity Generator
Handler Name:	CHANDLER CHAIR COMPANY

13	4 of4	NE	0.21 / 1,133.76	6,871.47 / 26	**VISIONS PHOTO LAB** **1808 SECOND ST SUITE C** **SANTA FE NM 87505**	RCRA VSQG

Handler ID:	NMR000021444
Generator Status:	VSG
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	VIOLATION or UNDETERMINED: There are VIOLATION or UNDETERMINED details or records associated with this facility (EPA ID) in the Compliance Monitoring and Enforcement table dated Sep 2025.

Violation Details

Viol Type:	270.A	**Actual Rtc Date:**	20150511
Citation:		**Found Violation:**	Yes
Determined Date:	20150408	**Rtc Qualifier:**	Documented
Scheduled Compliance Date:			
Eval Activity Location:	NM		
Viol Determined By Agency:	State		
Viol Short Desc:	Permits - General Information		

Enforcement Details

Enf Type:	120
Enf Type Desc:	WRITTEN INFORMAL
Enf Action Date:	20150511
Disposition Status Desc:	
Disposition Status Date:	
Enf Agency:	State
Proposed Amount:	
Final Amount:	
Paid Amount:	

Evaluation Details

Eval Start Date:	20150408
Eval Type Desc:	COMPLIANCE EVALUATION INSPECTION
Viol Short Desc:	Permits - General Information
Actual Rtc Date:	20150511
Eval Agency:	State

Handler Summary

Importer:	No	***Used Oil Transpor:***	No
Mixed Waste Gen:	No	***Used Oil Trans Fac:***	No
Transporter:	No	***Used Oil Processor:***	No
Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	N	***NAIC 1:***	443142
Seq No:	1	***NAIC 2:***	
Non Notifier:		***NAIC 3:***	
Receive Date:	20150408	***NAIC 4:***	
Active Site:	H----	***State:***	NM
Land Type:	P	***Location Latitude:***	35.664062
In Handler Univ:	Y	***Location Longitude:***	-105.966662
In A Universe:	Y	***Loc GIS Primary:***	N
Gen Status:	VSG	***Loc GIS Origin:***	AG
Report Cycle:		***State District Owner:***	NM
Accessibility:		***State District:***	02
Region:	06		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	NM		
State Waste Generator:	N		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	------		
As Converter Tsdf:	------		
As State Regulated Tsdf:	------		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal WrkId:	------		
Permwrk ID:	------		

Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20150421
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	VISIONS PHOTO LAB
Location Street No:	1808
Location Street1:	SECOND ST SUITE C
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87505
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	NIKKOL BROTHERS
Contact Street No:	1808
Contact Street1:	SECOND ST SUITE C
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87505
Contact Country:	US
Contact Phone & Ext:	505-986-9076
Contact Fax:	
Contact Email Address:	
Contact Title:	OWNER
Owner Name:	DAVID NYDES
Owner Type:	P
Owner Seq:	1
Operator Name:	VISIONS PHOTO LAB
Operator Type:	P
Operator Seq:	2
Public Notes:	

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20150408
Handler Name:	VISIONS PHOTO LAB
Fed Waste Generator:	3
Generator Code Description:	Very Small Quantity Generator
Source Type:	Notification
TSD Activity:	N

Waste Code Details

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Waste Code: D011
Waste Code Desc: SILVER

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street1:**	PO BOX 4247
Name:	DAVID NYDES	**Street2:**	
Dt Became Current:		**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:	505-473-5956	**Country:**	US
Source Type:	Notification	**Zip:**	87505
Owner/Operator Ind:	Current Operator	**Street No:**	1808
Type:	Private	**Street1:**	SECOND ST SUITE C
Name:	VISIONS PHOTO LAB	**Street2:**	
Dt Became Current:	20120101	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:	505-986-9076	**Country:**	US
Source Type:	Notification	**Zip:**	87505

14	1 of1	ENE	0.23 / 1,221.08	6,883.51 / 38	FURROW BLDG MATERIALS 900 W SAN MATEO SANTA FE NM 87501	RCRA NON GEN

Handler ID: NMD986682912
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Sep 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	N	**NAIC 1:**	
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	19920911	**NAIC 4:**	
Active Site:	-----	**State:**	NM
Land Type:	O	**Location Latitude:**	35.661427
In Handler Univ:	N	**Location Longitude:**	-105.963715
In A Universe:	N	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	NM
Accessibility:		**State District:**	02
Region:	06		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	NM
State Waste Generator:	7
Short Term Generator:	N
Uni Waste:	N
Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20020815
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	FURROW BLDG MATERIALS
Location Street No:	900
Location Street1:	W SAN MATEO
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87501
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	DAVE MCKEE
Contact Street No:	
Contact Street1:	PO BOX 419466
Contact Street2:	
Contact City:	KANSAS CITY
Contact State:	MO
Contact Zip:	64141-0466
Contact Country:	US
Contact Phone & Ext:	816-234-6000
Contact Fax:	
Contact Email Address:	
Contact Title:	
Owner Name:	PAYLESS CASHWAYS INC
Owner Type:	P
Owner Seq:	1
Operator Name:	

Operator Type:
Operator Seq:
Public Notes:

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 19920911
Handler Name: FURROW BLDG MATERIALS
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Notification
TSD Activity: N

Waste Code Details

Waste Code: D000
Waste Code Desc: DESCRIPTION

Waste Code: D001
Waste Code Desc: IGNITABLE WASTE

Waste Code: D002
Waste Code Desc: CORROSIVE WASTE

Waste Code: D003
Waste Code Desc: REACTIVE WASTE

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: PAYLESS CASHWAYS INC
Dt Became Current:
Dt Ended Current:
Phone: 816-234-6000
Source Type: Notification

Street No:
Street1: PO BOX 419466
Street2:
City: KANSAS CITY
State: MO
Country:
Zip: 64141-0466

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
15	1 of1	NE	0.24 / 1,254.08	6,869.75 / 24	TOY AUTO MAN LLC 1802 2ND ST SANTA FE NM 87501	RCRA VSQG

Handler ID: NMD986676567
Generator Status: VSG
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Sep 2025.

Evaluation Details

Eval Start Date: 20030723
Eval Type Desc: COMPLIANCE ASSISTANCE VISIT
Viol Short Desc:
Actual Rtc Date:
Eval Agency: State

Handler Summary

Importer:	No	***Used Oil Transpor:***	No
Mixed Waste Gen:	No	***Used Oil Trans Fac:***	No
Transporter:	No	***Used Oil Processor:***	No
Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	N	***NAIC 1:***	81111
Seq No:	2	***NAIC 2:***	
Non Notifier:		***NAIC 3:***	
Receive Date:	20030724	***NAIC 4:***	
Active Site:	H----	***State:***	NM
Land Type:	P	***Location Latitude:***	35.664062
In Handler Univ:	Y	***Location Longitude:***	-105.966662
In A Universe:	Y	***Loc GIS Primary:***	N
Gen Status:	VSG	***Loc GIS Origin:***	AG
Report Cycle:		***State District Owner:***	NM
Accessibility:		***State District:***	02
Region:	06		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	NM		
State Waste Generator:	N		
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	------		
As Converter Tsdf:	------		
As State Regulated Tsdf:	------		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	------		
Permwrk ID:	------		
Perm Prog:	------		
Pcwrkld:	------		
Closwrkld:	------		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	------		
Full Enforcement:	------		
Snc:	N		
Unaddressed Snc:	N		
Addressed Snc:	N		
Snc With Comp Sched:	N		
Fa Required:	-----		
Hhandler Last Change:	20030724		
Recognized Trader Importer:	N		
Recognized Trader Exporter:	N		
Slab Importer:	N		
Slab Exporter:	N		

Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	TOY AUTO MAN LLC
Location Street No:	1802
Location Street1:	2ND ST
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87501
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	STEPHEN INOVE
Contact Street No:	
Contact Street1:	1802 2ND ST
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87501
Contact Country:	US
Contact Phone & Ext:	505-983-9463
Contact Fax:	
Contact Email Address:	
Contact Title:	
Owner Name:	FRANK SCHULTHEIS
Owner Type:	P
Owner Seq:	1
Operator Name:	TOY AUTO MAN LLC
Operator Type:	P
Operator Seq:	3
Public Notes:	

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	19920127
Handler Name:	JAPANESE AUTO PERFORMANCE
Fed Waste Generator:	2
Generator Code Description:	Small Quantity Generator
Source Type:	Notification
TSD Activity:	N

Hazardous Waste Handler Details

Seq No:	2
Receive Date:	20030724
Handler Name:	TOY AUTO MAN LLC
Fed Waste Generator:	3
Generator Code Description:	Very Small Quantity Generator
Source Type:	Notification
TSD Activity:	N

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street1:***	1802 2ND ST
Name:	FRANK SCHULTHEIS	***Street2:***	
Dt Became Current:		***City:***	SANTA FE
Dt Ended Current:		***State:***	NM
Phone:	505-983-9463	***Country:***	
Source Type:	Notification	***Zip:***	87501
Owner/Operator Ind:	Current Operator	***Street No:***	1802
Type:	Private	***Street1:***	2ND ST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Name:	TOY AUTO MAN LLC	**Street2:**	
Dt Became Current:	20000703	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:	505-983-9463	**Country:**	
Source Type:	Notification	**Zip:**	87505
Owner/Operator Ind:	Current Owner	**Street No:**	1802
Type:	Private	**Street1:**	2ND ST
Name:	TOY AUTO MAN LLC	**Street2:**	
Dt Became Current:	20000703	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:	505-983-9463	**Country:**	
Source Type:	Notification	**Zip:**	87505

Historical Handler Details

Receive Dt:	19920127
Generator Code Description:	Small Quantity Generator
Handler Name:	JAPANESE AUTO PERFORMANCE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
16	1 of1	W	0.24 / 1,262.77	6,822.00 / -23	GIANT STOPNGO 1693 ST MICHAELS DR SANTA FE NM	LUST HIST

Form No:	1987	**Contact:**	GIANT INDUSTRIE
Facility ID:	28317	**CRC 32:**	2974526887
Status:	NFA	**Aggrav Factor Score:**	0
Facility Status:	No Further Action	**Mitigat Factor Score:**	5
Stat Date:		**Water Supply Impact:**	N
Date Reported:	05-AUG-93	**Vapor Explos Impact:**	N
SR Result:		**Prpty Damage Impact:**	N
Priority:		**Staff:**	UNK
Score:		**Unloc:**	FALSE
St:		**Latitude:**	0
Site Priority Rank:	743	**Longitude:**	0
Total Score:	0	**Facility County:**	
Tie Score:	150		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
17	1 of4	ESE	0.24 / 1,287.37	6,844.70 / -1	AAMCO TRANSMISSION 854 ST MICHEALS SANTA FE NM 87505	RCRA NON GEN

Handler ID:	NMR000004754
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Sep 2025.

Evaluation Details

Eval Start Date:	19990920
Eval Type Desc:	COMPLIANCE ASSISTANCE VISIT
Viol Short Desc:	
Actual Rtc Date:	
Eval Agency:	State

Handler Summary

Importer:	No	***Used Oil Transpor:***	No
Mixed Waste Gen:	No	***Used Oil Trans Fac:***	No
Transporter:	No	***Used Oil Processor:***	No
Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	***NAIC 1:***	
Seq No:	1	***NAIC 2:***	
Non Notifier:		***NAIC 3:***	
Receive Date:	20100401	***NAIC 4:***	
Active Site:	H----	***State:***	NM
Land Type:	O	***Location Latitude:***	35.66253
In Handler Univ:	Y	***Location Longitude:***	-105.977229
In A Universe:	Y	***Loc GIS Primary:***	N
Gen Status:	N	***Loc GIS Origin:***	AG
Report Cycle:		***State District Owner:***	NM
Accessibility:		***State District:***	02
Region:	06		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:	NM		
State Waste Generator:	7		
Short Term Generator:	N		
Uni Waste:	Y		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	Y		
As Federally Regulated Tsdf:	------		
As Converter Tsdf:	------		
As State Regulated Tsdf:	------		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	------		
Permwrk ID:	------		
Perm Prog:	------		
Pcwrkld:	------		
Closwrkld:	------		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	------		
Full Enforcement:	------		
Snc:	N		
Unaddressed Snc:	N		
Addressed Snc:	N		
Snc With Comp Sched:	N		
Fa Required:	-----		
Hhandler Last Change:	20100401		
Recognized Trader Importer:	N		
Recognized Trader Exporter:	N		
Slab Importer:	N		
Slab Exporter:	N		
Manifest Broker:	N		
Subpart P:	N		

Contact Language: EN
Handler Name: AAMCO TRANSMISSION
Location Street No: 854
Location Street1: ST MICHEALS
Location Street2:
Location City: SANTA FE
Location State: NM
Location Zip: 87505
Location County Code: NM049
Location County Name: SANTA FE
Location Country: US
Contact Name: JOHN EMORY
Contact Street No:
Contact Street1: 854 ST. MICHEALS
Contact Street2:
Contact City: SANTA FE
Contact State: NM
Contact Zip: 87505
Contact Country: US
Contact Phone & Ext: 505-438-2701
Contact Fax:
Contact Email Address:
Contact Title:
Owner Name: JOHN EMORY
Owner Type: P
Owner Seq: 1
Operator Name:
Operator Type:
Operator Seq:
Public Notes:

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20010219
Handler Name: AAMCO TRANSMISSION
Fed Waste Generator: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification
TSD Activity: N

Hazardous Waste Handler Details

Seq No: 2
Receive Date: 20020702
Handler Name: AAMCO TRANSMISSION
Fed Waste Generator: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification
TSD Activity: N

Waste Code Details

Waste Code: D008
Waste Code Desc: LEAD

Waste Code: U220
Waste Code Desc: BENZENE, METHYL- (OR) TOLUENE

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20100401

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Handler Name: AAMCO TRANSMISSION
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Implementer
TSD Activity: N

Waste Code Details

Waste Code: D008
Waste Code Desc: LEAD

Waste Code: U220
Waste Code Desc: BENZENE, METHYL- (OR) TOLUENE

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: JOHN EMORY
Dt Became Current:
Dt Ended Current:
Phone: 505-438-2701
Source Type: Notification
Street No:
Street1: 854 ST MICHAELS DR
Street2:
City: SANTA FE
State: NM
Country:
Zip: 87505

Owner/Operator Ind: Current Owner
Type: Private
Name: JOHN EMORY
Dt Became Current:
Dt Ended Current:
Phone: 505-438-2701
Source Type: Implementer
Street No:
Street1: 854 ST MICHAELS DR
Street2:
City: SANTA FE
State: NM
Country:
Zip: 87505

Historical Handler Details

Receive Dt: 20020702
Generator Code Description: Very Small Quantity Generator
Handler Name: AAMCO TRANSMISSION

Receive Dt: 20010219
Generator Code Description: Very Small Quantity Generator
Handler Name: AAMCO TRANSMISSION

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
17	2 of4	ESE	0.24 / 1,287.37	6,844.70 / -1	PAULS TRANSMISSION 854 SAINT MICHAELS DR SANTA FE NM 87501	TANKS

FID: 29884
In Use AST: 0
In Use UST: 0
Temp Out AST: 0
Temp Out UST: 0
Removed AST: 0
Removed UST: 1
Exempt AST: 0
Exempt UST: 0
Owner Name: PAULS TRANSMISSION
Fac Name (Del Prohibition):
Fac Owner (Deliv Prohib):
Fac Add (Delivery Prohibition):
Source: All Storage Tank List
Sold AST: 0
Sold UST: 0
No Data AST: 0
No Data UST: 0
County: SANTA FE
Owner ID: 14594
City (Deliv Prohib):
Cty (Del Prohib):

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
17	3 of4	ESE	0.24 / 1,287.37	6,844.70 / -1	PAULS TRANSMISSION 854 SAINT MICHAELS DR SANTA FE NM 87501	UST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility ID:	29884	**Facility (Active):**	
Facility Name:	PAULS TRANSMISSION	**Street (Active):**	
Facility Address:	854 SAINT MICHAELS DR	**Street 2 (Active):**	
Address 2:		**Zip (Active):**	
City:	SANTA FE	**City (Active):**	
County:	SANTA FE	**County (Active):**	
Zip:	87501	**Fac Name (Map-In):**	PAULS TRANSMISSION
Fac Name (Map):		**Fac Addr (Map-In):**	854 SAINT MICHAELS DR
Fac Addr (Map):		**Address 2 (Map-In):**	
Address2 (Map):		**City (Map-In):**	SANTA FE
City (Map):		**County (Map-In):**	SANTA FE
County (Map):		**Zip Cd (Map-In):**	87501
Fac ZIP (Map):		**Lat (Map-In):**	35.658944
Latitude (Map):		**Lon (Map-In):**	-105.964251
Longitude (Map):		**Fac Name (Prohib):**	
Fac Name (Map-Pro):		**Fac Addr (Prohib):**	
Fac Addr (Map-Pro):		**City (Prohib):**	
City (Map-Pro):		**County (Prohib):**	
County (Map-Pro):			

Data Source: NMED PSTB All Storage Tanks Report (as of 14 Oct 2025); NMED Open Data - Inactive Facilities (Map-In) (as of 3 Nov 2025)

NMED PSTB Report - Tank Detail(s) (as of October 14, 2025)

In Use UST:	0	**Sold UST:**	0
Removed UST:	1	**No Data UST:**	0
Exempt UST:	0	**Owner ID:**	14594
Temp Out UST:	0	**Owner Name:**	PAULS TRANSMISSION

NMED Open Data - Inactive Facilities

Active:	0	**Oldest Tnk Age Type:**	
UST:	1	**AST:**	0
UST Curr in Use:	0	**AST Curr in Use:**	0
UST Exempt:	0	**AST Exempt:**	0
UST Removed:	1	**AST Removed:**	0
UST Temp Out of Use:	0	**AST Temp Out of Use:**	0
Tanks:	1	**Shape:**	
Tanks Curr in Use:	0	**Owner ID:**	14594
Tanks Exempt:	0	**Owner Size Type:**	
Tanks Removed:	1	**Owner Name:**	PAULS TRANSMISSION
TanksTemp OutofUse:	0		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
17	4 of4	ESE	0.24 / 1,287.37	6,844.70 / -1	PAULS TRANSMISSION 854 SAINT MICHAELS DR SANTA FE NM 87501	UST HIST

Facility ID:	29884
Facility Addr2:	
Facility County:	SANTA FE

Details

Tank ID:	28723	**Owner Add2:**	
Tank Type:	Underground	**Owner City:**	SANTA FE
Tank Status:	REMOVED	**Owner St:**	NM
Tank Capacity (GAL):	800	**Owner ZIP:**	87501
Tank Contents:	USED OIL	**Owner Ph:**	505-471-2095
Owner ID:	14594		
Owner Name:	PAULS TRANSMISSION		
Owner Address:	854 SAINT MICHAELS DR		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
18	1 of5	ESE	0.25 / 1,300.07	6,845.18 / 0	ALLSUPS 252 2007 CALLE LORCA SANTA FE NM	LST

Release ID:	2526	**Latitude (Map):**	35.658589
Facility ID:	26511	**Longitude (Map):**	-105.963792
Status:	No Further Action, Confirmed Release	**Address (Map):**	2007 CALLE LORCA
Address:		**Address2 (Map):**	
City:		**City (Map):**	SANTA FE
County:		**State (Map):**	NM
Address (NFA):	2007 CALLE LORCA	**Zip (Map):**	87501
City (NFA):	SANTA FE	**Address (Priority):**	
County (NFA):	SANTA FE	**City (Priority):**	
Facility Release IDs (Map):	2526	**County (Priority):**	

Data Source: NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)

PSTB No Further Action Sites

Status:	No Further Action, Confirmed Release
NFA Date:	06/16/2003
NFA PDF:	https://cloud.env.nm.gov/resources/collection/9855

Leaking Petroleum Storage Tank Sites

Status Date Dt:	2003-06-16 00:00:00 UTC	**NAPL Off Site Val:**	0
Within SWPA Val:	0	**Plume Area No:**	
Surface Water Val:	0	**Plume Area Val:**	2
Private Well Val:	0	**Max Thickness No:**	
Municipal Well Val:	0	**Max Thickness Val:**	
LUWU Sco:	0	**NAPLSco:**	0
Surficial Conc Des:		**Priority2 Sco:**	0
Surficial Conc Val:	0	**Impact Type Des:**	
Leaching Conc Des:		**Impact Type Val:**	0
Leaching Conc Val:	0	**WS Type Des:**	
Construct Conc Des:		**WS Type Val:**	0
Construct Conc Val:	0	**WTR Sys Repl Des:**	
Building Type Des:		**WTR Sys Repl Val:**	0
Building Type Val:	0	**Population No:**	
Vad Off Site Val:	1	**Population Val:**	1
Vadose Sco:	0	**WS Sco:**	0
Conc Des:		**Toxic Vapor Des:**	
Conc Val:	0	**Toxic Vapor Val:**	0
Plume Mob Des:		**Toxic Vapor Sco:**	0
Plume Mob Val:	0	**Priority1 Sco:**	0
GWDPP Off Site Val:	0	**Total Sco:**	0
Benzene Area No:		**Tempo Total Sco:**	
Benzene Area Val:	1	**Current Priority:**	
GWDPP Sco:	0	**Tempo Current Rank:**	
Priority3 Sco:	0	**Tempo Curr Priorty:**	
CSS Age Des:		**Point X:**	-105.96379200000001
CSS Age Val:	0	**Point Y:**	35.658589000000006
CSS Type Des:		**Irrigation Well Val:**	0
CSS Type Val:	0	**Subsurf Conc Des:**	
CSS Off Site Val:	1	**Subsurface Conc Val:**	0
CSS Sco:	0	**Petrol Soil Bldg Val:**	1
CSS Volume No:		**Petrol Soil Vol Val:**	0
CSS Volume Val:	3	**Hydraulic Grad Val:**	0
Release Pm:	Lorena Goerger	**Depth to GW:**	
NAPL Type Des:		**Depth to GW Val:**	2
NAPL Type Val:	0	**Explosive Vapor Des:**	
NAPL Age Des:		**Explosive Vapor Val:**	0
NAPL Age Val:	0	**Explosive Vapor Sco:**	0
NAPLCondition Des:		**Eco Impact Val:**	0
NAPLCondition Val:	0	**Eco Impact Sco:**	0
Facility Name:	ALLSUP'S # 102252		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Current Status: No Further Action, Confirmed Release
Aquifer Water Quality Des:
Aquifer Water Quality Val: 0
Residential Property Val: 0
NAPL Plume Mobility Des:
NAPL Plume Mobility Val: 0
Property Damage Des:
Property Damage Val: 0
Property Damage Sco: 0

---

18 | **2 of5** | **ESE** | **0.25 / 1,300.07** | **6,845.18 / 0** | **ALLSUPS 252 CORNER CALLE LORCA AND SANTA FE NM** | **LUST HIST**

Form No: 2526
Facility ID: 26511
Status: NFA
Facility Status: No Further Action
Stat Date:
Date Reported: 26-JAN-95
SR Result: 8
Priority:
Score:
St:
Site Priority Rank: 683
Total Score: 0
Tie Score: 158

Contact: ALLSUPS CONVENI
CRC 32: 1207885643
Aggrav Factor Score: 0
Mitigat Factor Score: 1
Water Supply Impact: N
Vapor Explos Impact: N
Prpty Damage Impact: N
Staff: LLG
Unloc: FALSE
Latitude: 0
Longitude: 0
Facility County:

---

18 | **3 of5** | **ESE** | **0.25 / 1,300.07** | **6,845.18 / 0** | **ALLSUPS 252 FINA 2007 CALLE LORCA SANTA FE NM 87501** | **TANKS**

FID: 26511
In Use AST: 0
In Use UST: 2
Temp Out AST: 0
Temp Out UST: 0
Removed AST: 0
Removed UST: 3
Exempt AST: 0
Exempt UST: 0
Owner Name: ALLSUPS CONVENIENCE STORES INC
Fac Name (Del Prohibition):
Fac Owner (Deliv Prohib):
Fac Add (Delivery Prohibition):
Source: All Storage Tank List

Sold AST: 0
Sold UST: 0
No Data AST: 0
No Data UST: 0
County: SANTA FE
Owner ID: 16400
City (Deliv Prohib):
Cty (Del Prohib):

---

18 | **4 of5** | **ESE** | **0.25 / 1,300.07** | **6,845.18 / 0** | **ALLSUP'S # 102252 2007 CALLE LORCA SANTA FE NM 87501** | **UST**

Facility ID: 26511
Facility Name: ALLSUP'S # 102252
Facility Address: 2007 CALLE LORCA
Address 2:
City: SANTA FE
County: SANTA FE
Zip: 87501
Fac Name (Map): ALLSUP'S # 102252
Fac Addr (Map): 2007 CALLE LORCA
Address2 (Map):
City (Map): SANTA FE
County (Map): SANTA FE
Fac ZIP (Map): 87501
Latitude (Map): 35.658589

Facility (Active): ALLSUP'S # 102252
Street (Active): 2007 CALLE LORCA
Street 2 (Active):
Zip (Active): 87501
City (Active): SANTA FE
County (Active): SANTA FE
Fac Name (Map-In):
Fac Addr (Map-In):
Address 2 (Map-In):
City (Map-In):
County (Map-In):
Zip Cd (Map-In):
Lat (Map-In):
Lon (Map-In):

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Longitude (Map): -105.963792
Fac Name (Map-Pro):
Fac Addr (Map-Pro):
City (Map-Pro):
County (Map-Pro):
Fac Name (Prohib):
Fac Addr (Prohib):
City (Prohib):
County (Prohib):
Data Source: NMED PSTB All Storage Tanks Report (as of 14 Oct 2025); NMED Open Data - Underground Storage Tank Facilities (Map) (as of 3 Nov 2025); NMED PSTB Active Storage Tank List (Active) (as of 14 Oct 2025)

NMED PSTB Report - Tank Detail(s) (as of October 14, 2025)

In Use UST: 2
Removed UST: 3
Exempt UST: 0
Temp Out UST: 0
Sold UST: 0
No Data UST: 0
Owner ID: 276362
Owner Name: BW GAS CONVENIENCE JOBBER LLC

NM Open Data UST

Active: -1
UST: 5
UST Curr in Use: 2
UST Exempt: 0
UST Removed: 3
UST Temp Out of Use: 0
Tanks: 5
Tanks Curr in Use: 2
Tanks Exempt: 0
Tanks Removed: 3
Tanks Temp Out of Use: 0
Oldest Tnk Age Type: 25 years or more
AST: 0
AST Curr in Use: 0
AST Exempt: 0
AST Removed: 0
AST Temp Out of Use: 0
Shape:
Owner ID: 276362
Owner Size Type: 12 or more
Owner Name: BW GAS CONVENIENCE JOBBER LLC

NMED PSTB Active Storage Tank List (as of October 14, 2025)

UST: 2
Owner ID: 276362
Owner Name: BW GAS CONVENIENCE JOBBER LLC

---

18 | ***5 of5*** | ***ESE*** | ***0.25 / 1,300.07*** | ***6,845.18 / 0*** | ***ALLSUPS 252 FINA CORNER CALLE LORCA AND SANTA FE NM 87501*** | ***UST HIST***

Facility ID: 26511
Facility Addr2: SAINT MICHAELS DR
Facility County: SANTA FE

Details

Tank ID: 20866
Tank Type: Underground
Tank Status: REMOVED
Tank Capacity (GAL): 10000
Tank Contents: GASOLINE UNKNOWN TYPE
Owner ID: 16400
Owner Name: ALLSUPS PETROLEUM INC
Owner Address: PO BOX 1907
Owner Add2:
Owner City: CLOVIS
Owner St: NM
Owner ZIP: 88102
Owner Ph: 505-769-2311

Details

Tank ID: 20868
Tank Type: Underground
Tank Status: CURRENTLY IN USE
Tank Capacity (GAL): 10000
Tank Contents: UNLEADED GASOLINE
Owner Add2:
Owner City: CLOVIS
Owner St: NM
Owner ZIP: 88101
Owner Ph: 505-769-2311

Owner ID: 16400
Owner Name: ALLSUPS CONVENIENCE STORES INC
Owner Address: PO BOX 1907

Details

Tank ID: 20869
Tank Type: Underground
Tank Status: CURRENTLY IN USE
Tank Capacity (GAL): 10000
Tank Contents: SUPER UNLEADED
Owner ID: 16400
Owner Name: ALLSUPS CONVENIENCE STORES INC
Owner Address: PO BOX 1907
Owner Add2:
Owner City: CLOVIS
Owner St: NM
Owner ZIP: 88101
Owner Ph: 505-769-2311

Details

Tank ID: 20865
Tank Type: Underground
Tank Status: REMOVED
Tank Capacity (GAL): 10000
Tank Contents: GASOLINE UNKNOWN TYPE
Owner ID: 16400
Owner Name: ALLSUPS PETROLEUM INC
Owner Address: PO BOX 1907
Owner Add2:
Owner City: CLOVIS
Owner St: NM
Owner ZIP: 88102
Owner Ph: 505-769-2311

Details

Tank ID: 20868
Tank Type: Underground
Tank Status: CURRENTLY IN USE
Tank Capacity (GAL): 10000
Tank Contents: UNLEADED GASOLINE
Owner ID: 16400
Owner Name: ALLSUPS PETROLEUM INC
Owner Address: PO BOX 1907
Owner Add2:
Owner City: CLOVIS
Owner St: NM
Owner ZIP: 88102
Owner Ph: 505-769-2311

Details

Tank ID: 20869
Tank Type: Underground
Tank Status: CURRENTLY IN USE
Tank Capacity (GAL): 10000
Tank Contents: SUPER UNLEADED
Owner ID: 16400
Owner Name: ALLSUPS PETROLEUM INC
Owner Address: PO BOX 1907
Owner Add2:
Owner City: CLOVIS
Owner St: NM
Owner ZIP: 88102
Owner Ph: 505-769-2311

Details

Tank ID: 20867
Tank Type: Underground
Tank Status: REMOVED
Tank Capacity (GAL): 6000
Tank Contents: GASOLINE UNKNOWN TYPE
Owner ID: 16400
Owner Name: ALLSUPS PETROLEUM INC
Owner Address: PO BOX 1907
Owner Add2:
Owner City: CLOVIS
Owner St: NM
Owner ZIP: 88102
Owner Ph: 505-769-2311

19	1 of2	W	0.27 / 1,415.91	6,817.16 / -28	GIANT 6056 1698 ST MICHAELS DR SANTA FE NM	LST

Release ID:	4630	**Latitude (Map):**	35.659127
Facility ID:	28317	**Longitude (Map):**	-105.973362
Status:	No Further Action, Confirmed Release	**Address (Map):**	1698 ST MICHAELS DR
Address:		**Address2 (Map):**	
City:		**City (Map):**	SANTA FE
County:		**State (Map):**	NM
Address (NFA):	1698 ST MICHAELS DR	**Zip (Map):**	87501
City (NFA):	SANTA FE	**Address (Priority):**	
County (NFA):	SANTA FE	**City (Priority):**	
Facility Release IDs (Map):	1987,4630	**County (Priority):**	

Data Source: NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)

PSTB No Further Action Sites

Status:	No Further Action, Confirmed Release
NFA Date:	12/14/2011
NFA PDF:	https://cloud.env.nm.gov/resources/collection/10914

Leaking Petroleum Storage Tank Sites

Status Date Dt:	2011-12-14 00:00:00 UTC	**NAPL Off Site Val:**	0
Within SWPA Val:	0	**Plume Area No:**	
Surface Water Val:	0	**Plume Area Val:**	2
Private Well Val:	0	**Max Thickness No:**	
Municipal Well Val:	0	**Max Thickness Val:**	
LUWU Sco:	0	**NAPLSco:**	0
Surficial Conc Des:		**Priority2 Sco:**	0
Surficial Conc Val:	0	**Impact Type Des:**	
Leaching Conc Des:		**Impact Type Val:**	0
Leaching Conc Val:	0	**WS Type Des:**	
Construct Conc Des:		**WS Type Val:**	0
Construct Conc Val:	0	**WTR Sys Repl Des:**	
Building Type Des:		**WTR Sys Repl Val:**	0
Building Type Val:	0	**Population No:**	
Vad Off Site Val:	1	**Population Val:**	1
Vadose Sco:	0	**WS Sco:**	0
Conc Des:		**Toxic Vapor Des:**	
Conc Val:	0	**Toxic Vapor Val:**	0
Plume Mob Des:		**Toxic Vapor Sco:**	0
Plume Mob Val:	0	**Priority1 Sco:**	0
GWDPP Off Site Val:	0	**Total Sco:**	0
Benzene Area No:		**Tempo Total Sco:**	
Benzene Area Val:	1	**Current Priority:**	
GWDPP Sco:	0	**Tempo Current Rank:**	
Priority3 Sco:	0	**Tempo Curr Priorty:**	
CSS Age Des:		**Point X:**	-105.97336200000001
CSS Age Val:	0	**Point Y:**	35.65912700000001
CSS Type Des:		**Irrigation Well Val:**	0
CSS Type Val:	0	**Subsurf Conc Des:**	
CSS Off Site Val:	1	**Subsurface Conc Val:**	0
CSS Sco:	0	**Petrol Soil Bldg Val:**	1
CSS Volume No:		**Petrol Soil Vol Val:**	0
CSS Volume Val:	3	**Hydraulic Grad Val:**	0
Release Pm:	Susan Von Gonten	**Depth to GW:**	
NAPL Type Des:		**Depth to GW Val:**	2
NAPL Type Val:	0	**Explosive Vapor Des:**	
NAPL Age Des:		**Explosive Vapor Val:**	0
NAPL Age Val:	0	**Explosive Vapor Sco:**	0
NAPLCondition Des:		**Eco Impact Val:**	0
NAPLCondition Val:	0	**Eco Impact Sco:**	0
Facility Name:	GIANT 6056		
Current Status:	No Further Action, Confirmed Release		
Aquifer Water Quality Des:			
Aquifer Water Quality Val:	0		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Residential Property Val: 0
NAPL Plume Mobility Des:
NAPL Plume Mobility Val: 0
Property Damage Des:
Property Damage Val: 0
Property Damage Sco: 0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
19	2 of2	W	0.27 / 1,415.91	6,817.16 / -28	GIANT STOPNGO 1698 ST MICHAELS DR SANTA FE NM	LST

Release ID: 1987
Facility ID: 28317
Status: No Further Action, Confirmed Release
Address:
City:
County:
Address (NFA): 1698 ST MICHAELS DR
City (NFA): SANTA FE
County (NFA): SANTA FE
Facility Release IDs (Map):
Latitude (Map):
Longitude (Map):
Address (Map):
Address2 (Map):
City (Map):
State (Map):
Zip (Map):
Address (Priority):
City (Priority):
County (Priority):
Data Source: NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025)

PSTB No Further Action Sites

Status: No Further Action, Confirmed Release
NFA Date: 12/13/1993
NFA PDF:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
20	1 of2	WSW	0.27 / 1,446.19	6,811.53 / -34	1710 Llano 1710 Llano Santa Fe NM	SCS

County: Santa Fe
Latitude: 35.65815228
Longitude: -105.97307434
Data source(s): Active State Cleanup Sites

Active Detail

Project Manager: Noel
Depth To Water (Ft): unknown
Flow Direction: unknown
Media Impacted: Soil Vapor
Regulatory Status: CAR 1203.A
Size Acres: <1
Contam of Concern: PCE, TCE
Assmnt/Abatement: Passive Soil Vapor Survey conducted, RP is reviewing remedial options

---

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
20	2 of2	WSW	0.27 / 1,446.19	6,811.53 / -34	1710 Llano St. 1710 Llano Street, Santa Fe Santa Fe NM	VCP

VRP ID: 53251003
CERCLIS No:
Status: Active
County: Santa Fe
Latitude: 35.65816
Longitude: -105.9731
Township Range: T17N, R9E, Section 34
Size (Acres): 0.3
Applicant: TP SMVW, LLC c/o Forrest Thomas
Project Manager: Noger
Application Rcvd: 2/19/2025
Cert of Completion:
Final Work Plan Rc'd: 7/17/2025
Transfer CNS:
Public Notice: 5/22/2025
Conditional Elig:
Final Eligibility: 6/24/2025
VRA Signed: 6/24/2025
Termination:
Recission:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Cov Not to Sue CNS: **Rejection:**
Cmpt RPT Apprv:
Condl Cert of Comp:
Contamination Type: chlorinated solvents
Institutional Engineering Cont:
Land Use Restrictions:
Final Work Plan Approved: 9/11/2025

---

21 | **1 of1** | **E** | **0.29 / 1,524.33** | **6,862.74 / 17** | **Smith's #491 Fuel Center**
800 St. Michael's Drive
Santa Fe NM | **VCP**

VRP ID: 53131002
CERCLIS No:
Status: Closed
County: Santa Fe
Latitude: 35.6589
Longitude: -105.963
Township Range: Santa Fe Grant
Size (Acres): 2.1
Applicant: Smith's Food and Drug Stores
Project Manager: Furmall
Cov Not to Sue CNS: 9/25/2015
Cmpt RPT Apprv: 3/6/2015
Condl Cert of Comp:
Contamination Type: TPH-DRO, TPH-ORO in soil
Institutional Engineering Cont:
Land Use Restrictions:
Final Work Plan Approved: 7/21/2014

Application Rcvd: 9/4/2013
Cert of Completion: 5/15/2015
Final Work Plan Rc'd: 7/11/2014
Transfer CNS:
Public Notice: 1/10/2014
Conditional Elig: 11/7/2013
Final Eligibility: 4/11/2014
VRA Signed: 5/2/2014
Termination:
Recission:
Rejection:

---

22 | **1 of1** | **ENE** | **0.39 / 2,059.88** | **6,887.46 / 42** | **City of Santa Fe - Sangre de Cristo Water Division**
801 W. San Mateo, Santa Fe, New Mexico 87505
NM | **SWF/LF**

Permit Reg No: 0226463
Status: Open
Facility Type: Special Waste Hauler
Reg Type: New
Reg Issue Date: 7/9/2009
Reg Expire Date: 7/9/2014
EA: 2
Address: P.O. Box 909
City: Santa Fe
State: NM
Zip: 87505
Contact: Brian Snyder, Director
Contact Phone: 5059554200

Spcl Waste Perm No:
Spcl Expire Date:
Spcl Issue Date:
Spcl Type:
County: Santa Fe
Latitude:
Longitude:

---

23 | **1 of2** | **WNW** | **0.40 / 2,096.69** | **6,817.51 / -28** | **SQUEAKY CLEAN CAR WASH**
1900 CERRILLOS RD
SANTA FE NM | **LST**

Release ID: 1484
Facility ID: 30744
Status: No Further Action, Confirmed Release
Address:
City:
County:
Address (NFA): 1900 CERRILLOS RD
City (NFA): SANTA FE
County (NFA): SANTA FE

Latitude (Map): 35.663803
Longitude (Map): -105.974284
Address (Map): 1900 CERRILLOS RD
Address2 (Map):
City (Map): SANTA FE
State (Map): NM
Zip (Map): 87502
Address (Priority):
City (Priority):

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Facility Release IDs (Map): 1484 **County (Priority):**
Data Source: NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)

PSTB No Further Action Sites

Status: No Further Action, Confirmed Release
NFA Date: 05/24/1993
NFA PDF: https://cloud.env.nm.gov/resources/collection/9196

Leaking Petroleum Storage Tank Sites

Status Date Dt:	1993-05-24 00:00:00 UTC	**NAPL Off Site Val:**	0
Within SWPA Val:	0	**Plume Area No:**	
Surface Water Val:	0	**Plume Area Val:**	2
Private Well Val:	0	**Max Thickness No:**	
Municipal Well Val:	0	**Max Thickness Val:**	
LUWU Sco:	0	**NAPLSco:**	0
Surficial Conc Des:		**Priority2 Sco:**	0
Surficial Conc Val:	0	**Impact Type Des:**	
Leaching Conc Des:		**Impact Type Val:**	0
Leaching Conc Val:	0	**WS Type Des:**	
Construct Conc Des:		**WS Type Val:**	0
Construct Conc Val:	0	**WTR Sys Repl Des:**	
Building Type Des:		**WTR Sys Repl Val:**	0
Building Type Val:	0	**Population No:**	
Vad Off Site Val:	1	**Population Val:**	1
Vadose Sco:	0	**WS Sco:**	0
Conc Des:		**Toxic Vapor Des:**	
Conc Val:	0	**Toxic Vapor Val:**	0
Plume Mob Des:		**Toxic Vapor Sco:**	0
Plume Mob Val:	0	**Priority1 Sco:**	0
GWDPP Off Site Val:	0	**Total Sco:**	0
Benzene Area No:		**Tempo Total Sco:**	
Benzene Area Val:	1	**Current Priority:**	
GWDPP Sco:	0	**Tempo Current Rank:**	
Priority3 Sco:	0	**Tempo Curr Priorty:**	
CSS Age Des:		**Point X:**	-105.97428400000001
CSS Age Val:	0	**Point Y:**	35.66380299999997
CSS Type Des:		**Irrigation Well Val:**	0
CSS Type Val:	0	**Subsurf Conc Des:**	
CSS Off Site Val:	1	**Subsurface Conc Val:**	0
CSS Sco:	0	**Petrol Soil Bldg Val:**	1
CSS Volume No:		**Petrol Soil Vol Val:**	0
CSS Volume Val:	3	**Hydraulic Grad Val:**	0
Release Pm:	UNKNOWN	**Depth to GW:**	
NAPL Type Des:		**Depth to GW Val:**	2
NAPL Type Val:	0	**Explosive Vapor Des:**	
NAPL Age Des:		**Explosive Vapor Val:**	0
NAPL Age Val:	0	**Explosive Vapor Sco:**	0
NAPLCondition Des:		**Eco Impact Val:**	0
NAPLCondition Val:	0	**Eco Impact Sco:**	0

Facility Name: SQUEAKY CLEAN CARWASH
Current Status: No Further Action, Confirmed Release
Aquifer Water Quality Des:
Aquifer Water Quality Val: 0
Residential Property Val: 0
NAPL Plume Mobility Des:
NAPL Plume Mobility Val: 0
Property Damage Des:
Property Damage Val: 0
Property Damage Sco: 0

23	2 of2	WNW	0.40 / 2,096.69	6,817.51 / -28	SQUEAKY CLEAN CAR WA 1900 CERRILLOS RD	LUST HIST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					SANTA FE NM	

Form No:	1484	Contact:	BERRIDGE DISTRI
Facility ID:	30744	CRC 32:	3791299116
Status:	NFA	Aggrav Factor Score:	0
Facility Status:	No Further Action	Mitigat Factor Score:	3
Stat Date:		Water Supply Impact:	N
Date Reported:	21-AUG-92	Vapor Explos Impact:	N
SR Result:		Prpty Damage Impact:	N
Priority:		Staff:	UNK
Score:		Unloc:	FALSE
St:		Latitude:	0
Site Priority Rank:		Longitude:	0
Total Score:	0	Facility County:	
Tie Score:	158		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
24	1 of1	E	0.40 / 2,114.93	6,884.52 / 39	Park Avenue Cleaners - SF 720 St. Michaels Drive, Suite K Santa Fe NM	VCP

VRP ID:	53161003	Application Rcvd:	2/22/2016
CERCLIS No:		Cert of Completion:	
Status:	Active-CCOC	Final Work Plan Rc'd:	7/8/2016 11/19/2016
County:	Santa Fe	Transfer CNS:	
Latitude:	35.657733	Public Notice:	4/8/2016
Longitude:	-105.961197	Conditional Elig:	3/25/2016
Township Range:	T17N, R9E, Sec 35	Final Eligibility:	6/3/2016
Size (Acres):	6.577	VRA Signed:	6/27/2016
Applicant:	Del Sol Shopping Center Partners	Termination:	
Project Manager:	Muus	Recission:	
Cov Not to Sue CNS:		Rejection:	
Cmpt RPT Apprv:	12/4/2020		
Condl Cert of Comp:	7/8/2021		
Contamination Type:	PCE in sub-slab soils		
Institutional Engineering Cont:			
Land Use Restrictions:			
Final Work Plan Approved:	7/25/2016		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
25	1 of1	ESE	0.40 / 2,133.36	6,891.44 / 46	Concentra Urgent Care 720 St. Michaels Drive, Suite C, Santa Fe, New Mexico NM	SWF/LF

Permit Reg No:		Spcl Waste Perm No:	
Status:	Open	Spcl Expire Date:	
Facility Type:	Infectious Waste Generator	Spcl Issue Date:	
Reg Type:		Spcl Type:	
Reg Issue Date:		County:	Santa Fe
Reg Expire Date:		Latitude:	
EA:	2	Longitude:	
Address:	720 Saint Michaels Drive, Suite C		
City:	Santa Fe		
State:	NM		
Zip:	87505		
Contact:	Jeremy Leyba		
Contact Phone:	505-438-9402		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
26	1 of2	NW	0.43 / 2,279.38	6,814.37 / -31	1901 CERRILLOS CHEVRON 1901 CERRILLOS RD SANTA FE NM	LST

Release ID:	4614	Latitude (Map):	35.664315

Facility ID:	1031	**Longitude (Map):**	-105.974589
Status:	No Further Action, Confirmed Release	**Address (Map):**	1901 CERRILLOS RD
Address:		**Address2 (Map):**	
City:		**City (Map):**	SANTA FE
County:		**State (Map):**	NM
Address (NFA):	1901 CERRILLOS RD	**Zip (Map):**	87504
City (NFA):	SANTA FE	**Address (Priority):**	
County (NFA):	SANTA FE	**City (Priority):**	
Facility Release IDs (Map):	4614	**County (Priority):**	

Data Source: NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)

PSTB No Further Action Sites

Status: No Further Action, Confirmed Release
NFA Date: 10/06/2010
NFA PDF: https://cloud.env.nm.gov/resources/collection/8547

Leaking Petroleum Storage Tank Sites

Status Date Dt:	2010-10-06 00:00:00 UTC	**NAPL Off Site Val:**	0
Within SWPA Val:	0	**Plume Area No:**	
Surface Water Val:	0	**Plume Area Val:**	2
Private Well Val:	0	**Max Thickness No:**	
Municipal Well Val:	0	**Max Thickness Val:**	
LUWU Sco:	0	**NAPLSco:**	0
Surficial Conc Des:		**Priority2 Sco:**	0
Surficial Conc Val:	0	**Impact Type Des:**	
Leaching Conc Des:		**Impact Type Val:**	0
Leaching Conc Val:	0	**WS Type Des:**	
Construct Conc Des:		**WS Type Val:**	0
Construct Conc Val:	0	**WTR Sys Repl Des:**	
Building Type Des:		**WTR Sys Repl Val:**	0
Building Type Val:	0	**Population No:**	
Vad Off Site Val:	1	**Population Val:**	1
Vadose Sco:	0	**WS Sco:**	0
Conc Des:		**Toxic Vapor Des:**	
Conc Val:	0	**Toxic Vapor Val:**	0
Plume Mob Des:		**Toxic Vapor Sco:**	0
Plume Mob Val:	0	**Priority1 Sco:**	0
GWDPP Off Site Val:	0	**Total Sco:**	0
Benzene Area No:		**Tempo Total Sco:**	
Benzene Area Val:	1	**Current Priority:**	
GWDPP Sco:	0	**Tempo Current Rank:**	
Priority3 Sco:	0	**Tempo Curr Priorty:**	
CSS Age Des:		**Point X:**	-105.97458899999998
CSS Age Val:	0	**Point Y:**	35.66431499999999
CSS Type Des:		**Irrigation Well Val:**	0
CSS Type Val:	0	**Subsurf Conc Des:**	
CSS Off Site Val:	1	**Subsurface Conc Val:**	0
CSS Sco:	0	**Petrol Soil Bldg Val:**	1
CSS Volume No:		**Petrol Soil Vol Val:**	0
CSS Volume Val:	3	**Hydraulic Grad Val:**	0
Release Pm:	George Beaumont	**Depth to GW:**	
NAPL Type Des:		**Depth to GW Val:**	2
NAPL Type Val:	0	**Explosive Vapor Des:**	
NAPL Age Des:		**Explosive Vapor Val:**	0
NAPL Age Val:	0	**Explosive Vapor Sco:**	0
NAPLCondition Des:		**Eco Impact Val:**	0
NAPLCondition Val:	0	**Eco Impact Sco:**	0
Facility Name:	1901 CERRILLOS CHEVRON		
Current Status:	No Further Action, Confirmed Release		
Aquifer Water Quality Des:			
Aquifer Water Quality Val:	0		
Residential Property Val:	0		
NAPL Plume Mobility Des:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

NAPL Plume Mobility Val: 0
Property Damage Des:
Property Damage Val: 0
Property Damage Sco: 0

---

26 | **2 of2** | **NW** | **0.43 / 2,279.38** | **6,814.37 / -31** | **Amigo Tire and Auto**
1901 Cerrillos Road, Santa Fe, New Mexico
NM | **SWF/LF**

Permit Reg No:
Status: Open
Facility Type: Tire Generator
Reg Type:
Reg Issue Date:
Reg Expire Date:
EA: 2
Address: 1901 Cerrillos Road
City: Santa Fe
State: NM
Zip: 87505
Contact: Eben Cohan
Contact Phone: 505-984-0900

Spcl Waste Perm No:
Spcl Expire Date:
Spcl Issue Date:
Spcl Type:
County: Santa Fe
Latitude:
Longitude:

---

27 | **1 of2** | **NE** | **0.46 / 2,453.77** | **6,881.91 / 37** | **SHUTTLEJACK**
1600 LENA RD
SANTA FE NM | **LST**

Release ID: 2661
Facility ID: 30595
Status: No Further Action, Confirmed Release
Address:
City:
County:
Address (NFA): 1600 LENA RD
City (NFA): SANTA FE
County (NFA): SANTA FE
Facility Release IDs (Map): 2661
Data Source: NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)

Latitude (Map): 35.665537
Longitude (Map): -105.963516
Address (Map): 1600 LENA RD
Address2 (Map):
City (Map): SANTA FE
State (Map): NM
Zip (Map): 87501
Address (Priority):
City (Priority):
County (Priority):

PSTB No Further Action Sites

Status: No Further Action, Confirmed Release
NFA Date: 11/04/1999
NFA PDF: https://cloud.env.nm.gov/resources/collection/9220

Leaking Petroleum Storage Tank Sites

Status Date Dt: 1999-11-04 00:00:00 UTC
Within SWPA Val: 0
Surface Water Val: 0
Private Well Val: 0
Municipal Well Val: 0
LUWU Sco: 0
Surficial Conc Des:
Surficial Conc Val: 0
Leaching Conc Des:
Leaching Conc Val: 0
Construct Conc Des:
Construct Conc Val: 0
Building Type Des:
Building Type Val: 0

NAPL Off Site Val: 0
Plume Area No:
Plume Area Val: 2
Max Thickness No:
Max Thickness Val:
NAPLSco: 0
Priority2 Sco: 0
Impact Type Des:
Impact Type Val: 0
WS Type Des:
WS Type Val: 0
WTR Sys Repl Des:
WTR Sys Repl Val: 0
Population No:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Vad Off Site Val:	1	**Population Val:**	1
Vadose Sco:	0	**WS Sco:**	0
Conc Des:		**Toxic Vapor Des:**	
Conc Val:	0	**Toxic Vapor Val:**	0
Plume Mob Des:		**Toxic Vapor Sco:**	0
Plume Mob Val:	0	**Priority1 Sco:**	0
GWDPP Off Site Val:	0	**Total Sco:**	0
Benzene Area No:		**Tempo Total Sco:**	
Benzene Area Val:	1	**Current Priority:**	
GWDPP Sco:	0	**Tempo Current Rank:**	
Priority3 Sco:	0	**Tempo Curr Priorty:**	
CSS Age Des:		**Point X:**	-105.96351600000003
CSS Age Val:	0	**Point Y:**	35.66553699999997
CSS Type Des:		**Irrigation Well Val:**	0
CSS Type Val:	0	**Subsurf Conc Des:**	
CSS Off Site Val:	1	**Subsurface Conc Val:**	0
CSS Sco:	0	**Petrol Soil Bldg Val:**	1
CSS Volume No:		**Petrol Soil Vol Val:**	0
CSS Volume Val:	3	**Hydraulic Grad Val:**	0
Release Pm:	Lorena Goerger	**Depth to GW:**	
NAPL Type Des:		**Depth to GW Val:**	2
NAPL Type Val:	0	**Explosive Vapor Des:**	
NAPL Age Des:		**Explosive Vapor Val:**	0
NAPL Age Val:	0	**Explosive Vapor Sco:**	0
NAPLCondition Des:		**Eco Impact Val:**	0
NAPLCondition Val:	0	**Eco Impact Sco:**	0

Facility Name:	SHUTTLEJACK
Current Status:	No Further Action, Confirmed Release
Aquifer Water Quality Des:	
Aquifer Water Quality Val:	0
Residential Property Val:	0
NAPL Plume Mobility Des:	
NAPL Plume Mobility Val:	0
Property Damage Des:	
Property Damage Val:	0
Property Damage Sco:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	2 of2	NE	0.46 / 2,453.77	6,881.91 / 37	SHUTTLEJACK 1600 LENA RD SANTA FE NM	LUST HIST

Form No:	2661	**Contact:**	SENA
Facility ID:	30595	**CRC 32:**	1535353042
Status:	NFA	**Aggrav Factor Score:**	
Facility Status:	No Further Action	**Mitigat Factor Score:**	
Stat Date:		**Water Supply Impact:**	U
Date Reported:	11-JUL-95	**Vapor Explos Impact:**	U
SR Result:		**Prpty Damage Impact:**	U
Priority:		**Staff:**	LLG
Score:		**Unloc:**	FALSE
St:		**Latitude:**	0
Site Priority Rank:		**Longitude:**	0
Total Score:		**Facility County:**	
Tie Score:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
28	1 of5	E	0.49 / 2,563.09	6,884.76 / 39	ST MICHAELS SHELL 711 SAINT MICHAELS SANTA FE NM	LST

Release ID:	1611	**Latitude (Map):**	
Facility ID:	1768	**Longitude (Map):**	
Status:	No Further Action, Confirmed Release	**Address (Map):**	
Address:		**Address2 (Map):**	
City:		**City (Map):**	
County:		**State (Map):**	
Address (NFA):	711 SAINT MICHAELS	**Zip (Map):**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

City (NFA):	SANTA FE	**Address (Priority):**	
County (NFA):	SANTA FE	**City (Priority):**	
Facility Release IDs (Map):		**County (Priority):**	
Data Source:	NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025)		

PSTB No Further Action Sites

Status:	No Further Action, Confirmed Release
NFA Date:	05/14/1993
NFA PDF:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
28	2 of5	E	0.49 / 2,563.09	6,884.76 / 39	SAINT MIKES SHELL 711 SAINT MICHAELS SANTA FE NM	LST

Release ID:	2435	**Latitude (Map):**	35.660159
Facility ID:	1768	**Longitude (Map):**	-105.960033
Status:	No Further Action, Confirmed Release	**Address (Map):**	711 SAINT MICHAELS
Address:		**Address2 (Map):**	
City:		**City (Map):**	SANTA FE
County:		**State (Map):**	NM
Address (NFA):	711 SAINT MICHAELS	**Zip (Map):**	87504
City (NFA):	SANTA FE	**Address (Priority):**	
County (NFA):	SANTA FE	**City (Priority):**	
Facility Release IDs (Map):	1611,2435	**County (Priority):**	
Data Source:	NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)		

PSTB No Further Action Sites

Status:	No Further Action, Confirmed Release
NFA Date:	01/06/1995
NFA PDF:	https://cloud.env.nm.gov/resources/collection/10747

Leaking Petroleum Storage Tank Sites

Status Date Dt:	1995-01-06 00:00:00 UTC	**NAPL Off Site Val:**	0
Within SWPA Val:	0	**Plume Area No:**	
Surface Water Val:	0	**Plume Area Val:**	2
Private Well Val:	0	**Max Thickness No:**	
Municipal Well Val:	0	**Max Thickness Val:**	
LUWU Sco:	0	**NAPLSco:**	0
Surficial Conc Des:		**Priority2 Sco:**	0
Surficial Conc Val:	0	**Impact Type Des:**	
Leaching Conc Des:		**Impact Type Val:**	0
Leaching Conc Val:	0	**WS Type Des:**	
Construct Conc Des:		**WS Type Val:**	0
Construct Conc Val:	0	**WTR Sys Repl Des:**	
Building Type Des:		**WTR Sys Repl Val:**	0
Building Type Val:	0	**Population No:**	
Vad Off Site Val:	1	**Population Val:**	1
Vadose Sco:	0	**WS Sco:**	0
Conc Des:		**Toxic Vapor Des:**	
Conc Val:	0	**Toxic Vapor Val:**	0
Plume Mob Des:		**Toxic Vapor Sco:**	0
Plume Mob Val:	0	**Priority1 Sco:**	0
GWDPP Off Site Val:	0	**Total Sco:**	0
Benzene Area No:		**Tempo Total Sco:**	
Benzene Area Val:	1	**Current Priority:**	
GWDPP Sco:	0	**Tempo Current Rank:**	
Priority3 Sco:	0	**Tempo Curr Priorty:**	
CSS Age Des:		**Point X:**	-105.96003300000001
CSS Age Val:	0	**Point Y:**	35.66015900000002

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CSS Type Des:		Irrigation Well Val:	0
CSS Type Val:	0	Subsurf Conc Des:	
CSS Off Site Val:	1	Subsurface Conc Val:	0
CSS Sco:	0	Petrol Soil Bldg Val:	1
CSS Volume No:		Petrol Soil Vol Val:	0
CSS Volume Val:	3	Hydraulic Grad Val:	0
Release Pm:	UNKNOWN	Depth to GW:	
NAPL Type Des:		Depth to GW Val:	2
NAPL Type Val:	0	Explosive Vapor Des:	
NAPL Age Des:		Explosive Vapor Val:	0
NAPL Age Val:	0	Explosive Vapor Sco:	0
NAPLCondition Des:		Eco Impact Val:	0
NAPLCondition Val:	0	Eco Impact Sco:	0
Facility Name:	ST. MICHAEL'S SHELL		
Current Status:	No Further Action, Confirmed Release		
Aquifer Water Quality Des:			
Aquifer Water Quality Val:	0		
Residential Property Val:	0		
NAPL Plume Mobility Des:			
NAPL Plume Mobility Val:	0		
Property Damage Des:			
Property Damage Val:	0		
Property Damage Sco:	0		

28	3 of5	E	0.49 / 2,563.09	6,884.76 / 39	ST MIKE'S SHELL 711 SAINT MICHAELS SANTA FE NM	LUST HIST

Form No:	713	Contact:	BREWER OIL CO
Facility ID:	1768	CRC 32:	2815911513
Status:	NFA	Aggrav Factor Score:	
Facility Status:	No Further Action	Mitigat Factor Score:	
Stat Date:		Water Supply Impact:	U
Date Reported:	16-MAY-91	Vapor Explos Impact:	U
SR Result:		Prpty Damage Impact:	U
Priority:		Staff:	UNK
Score:		Unloc:	FALSE
St:		Latitude:	0
Site Priority Rank:		Longitude:	0
Total Score:		Facility County:	
Tie Score:			

28	4 of5	E	0.49 / 2,563.09	6,884.76 / 39	ST MICHAELS SHELL 711 SAINT MICHAELS SANTA FE NM	LUST HIST

Form No:	1611	Contact:	BREWER OIL CO
Facility ID:	1768	CRC 32:	2815911513
Status:	NFA	Aggrav Factor Score:	
Facility Status:	No Further Action	Mitigat Factor Score:	
Stat Date:		Water Supply Impact:	U
Date Reported:	17-NOV-92	Vapor Explos Impact:	U
SR Result:		Prpty Damage Impact:	U
Priority:		Staff:	UNK
Score:		Unloc:	FALSE
St:		Latitude:	0
Site Priority Rank:		Longitude:	0
Total Score:		Facility County:	
Tie Score:			

28	5 of5	E	0.49 / 2,563.09	6,884.76 / 39	SAINT MIKES SHELL 711 SAINT MICHAELS SANTA FE NM	LUST HIST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Form No:	2435	**Contact:**	BREWER OIL CO
Facility ID:	1768	**CRC 32:**	2815911513
Status:	NFA	**Aggrav Factor Score:**	
Facility Status:	No Further Action	**Mitigat Factor Score:**	
Stat Date:		**Water Supply Impact:**	U
Date Reported:	27-SEP-94	**Vapor Explos Impact:**	U
SR Result:		**Prpty Damage Impact:**	U
Priority:		**Staff:**	UNK
Score:		**Unloc:**	FALSE
St:		**Latitude:**	0
Site Priority Rank:		**Longitude:**	0
Total Score:		**Facility County:**	
Tie Score:			

29	1 of1	WNW	0.51 / 2,684.47	6,796.61 / -49	**Jiffy Lube** **1975 Cerrillos** **Santa Fe NM**	SCS

County:	Santa Fe
Latitude:	35.663583
Longitude:	-105.975493
Data source(s):	Closed/Inactive State Cleanup Sites(Closed)

Closed Detail

Status:	closed
Date :	6/27/2005
Discharge Dt:	4/26/2005
Event:	500 gal tank overflowed with windshield wash containing isopropyl alcohol
Action Taken:	City removed 35 gal

30	1 of1	W	0.60 / 3,186.85	6,782.25 / -63	**Exxon Station 6-7231** **2045 Cerrillos Rd** **Santa Fe NM**	SCS

County:	Santa Fe
Latitude:	35.662774
Longitude:	-105.977086
Data source(s):	Closed/Inactive State Cleanup Sites(Closed)

Closed Detail

Status:	closed
Date :	1/03/1989
Discharge Dt:	unknown
Event:	petroleum contamination
Action Taken:	Settlement Agreement directed remediation

31	1 of1	NNE	0.73 / 3,866.16	6,884.10 / 39	**Fmr White Swan Laundry Facility** **1368 Cerrillos Road** **Santa Fe NM**	DELISTED SCS

Title:	Active State Cleanup Sites
Size (Acres):	1.5
County:	Santa Fe
Latitude:	35.670472
Longitude:	-105.964247
Original Source:	SCS
Record Date:	01-JAN-2023

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
32	1 of1	NNE	0.93 / 4,916.19	6,893.02 / 48	Berridge Distributing Co 1255 Cerrillos Rd Santa Fe NM	SCS

County: Santa Fe
Latitude: 35.673615
Longitude: -105.960259
Data source(s): Closed/Inactive State Cleanup Sites(Closed)

Closed Detail

Status: closed
Date : 12/06/1995
Discharge Dt: 10/27/1995
Event: former bulk plant
Action Taken: soil excavation

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
33	1 of1	NE	1.00 / 5,262.84	6,911.42 / 66	NMDOT Main Yard/GOC 1120 Cerrillos Road Santa Fe NM	SCS

County: Santa Fe
Latitude: 35.673806
Longitude: -105.958712
Data source(s): Active State Cleanup Sites

Active Detail

Project Manager: Kate
Depth To Water (Ft): 350, 127 perched zone (2011)
Flow Direction: W
Media Impacted: Soil, Soil Vapor
Regulatory Status: CAR 1203.A
Size Acres: 5
Contam of Concern: PCE, TCE
Assmnt/Abatement: Vapor Intrusion assessment needed.

Unplottable Summary

Total: 0 Unplottable sites

DB	Company Name/Site Name	Address	City	Zip	ERIS ID

No unplottable records were found that may be relevant for the search criteria.

Unplottable Report

No unplottable records were found that may be relevant for the search criteria.

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ERIS updates databases as set out in ASTM Standard E1527-13 and E1527-21, Section 8.1.8 Sources of Standard Source Information:

"Government information from nongovernmental sources may be considered current if the source updates the information at least every 90 days, or, for information that is updated less frequently than quarterly by the government agency, within 90 days of the date the government agency makes the information available to the public."

Standard Environmental Record Sources

Federal

National Priority List: NPL

The U.S. Environmental Protection Agency (EPA)'s National Priorities List (NPL) includes the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program, based primarily on the score a site receives from EPA's Hazard Ranking System. A site must be on the NPL to receive money from the Superfund Trust Fund for remedial action. This data includes NPL sites represented as polygons, where available, that can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS), and is limited to those sites where the NPL Status reflects the site is 'Currently on the Final NPL (F)' and/or the 'Site is Part of NPL Site (A)'. These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. As site investigation and remediation progress, OUs may be added, modified or refined. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Sep 6, 2025

National Priority List - Proposed: PROPOSED NPL

Sites proposed by the U.S. Environmental Protection Agency (EPA), the state agency, or concerned citizens for addition to the National Priorities List (NPL) due to contamination by hazardous waste and identified by the EPA as a candidate for cleanup because it poses a risk to human health and/or the environment. Sites represented as polygons, where available, can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Sep 6, 2025

Deleted NPL: DELETED NPL

Sites deleted from the U.S. Environmental Protection Agency (EPA)'s National Priorities List (NPL). The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate. Sites represented as polygons, where available, can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Sep 6, 2025

SEMS List 8R Active Site Inventory: SEMS

The U.S. Environmental Protection Agency's (EPA) Superfund Program has deployed the Superfund Enterprise Management System (SEMS), which integrates multiple legacy systems into a comprehensive tracking and reporting tool. This inventory contains active sites evaluated by the Superfund program that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The Active Site Inventory Report displays site and location information at active SEMS sites. An active site is one at which site assessment, removal, remedial, enforcement, cost recovery, or oversight activities are being planned or conducted. This data includes SEMS sites from the List 8R Active file as well as applicable sites from the EPA's Facility Registry Service map tool. This data may also include applicable sites represented as polygons sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS), and is limited to those sites where the NPL Status reflects the site is 'Not on the NPL (N)' , 'Removed from Proposed (R)', and/or 'Pre-Proposal Site (S)'. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Aug 27, 2025

Inventory of Open Dumps, June 1985: ODI

The Resource Conservation and Recovery Act (RCRA) provides for publication of an inventory of open dumps. The Act defines "open dumps" as facilities which do not comply with EPA's "Criteria for Classification of Solid Waste Disposal Facilities and Practices" (40 CFR 257).

Government Publication Date: Jun 1985

SEMS List 8R Archive Sites: SEMS ARCHIVE

The U.S. Environmental Protection Agency's (EPA) Superfund Enterprise Management System (SEMS) Archived Site Inventory displays site and location information at sites archived from SEMS. An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. This data includes sites from the List 8R Archived site file. This data may also include applicable sites represented as polygons sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS), and is limited to those sites where the NPL Status reflects the site is 'Not on the NPL (N)' , 'Removed from Proposed (R)', and/or 'Pre-Proposal Site (S)'. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Aug 27, 2025

Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS: CERCLIS

Superfund is a program administered by the United States Environmental Protection Agency (EPA) to locate, investigate, and clean up the worst hazardous waste sites throughout the United States. CERCLIS is a database of potential and confirmed hazardous waste sites at which the EPA Superfund program has some involvement. It contains sites that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The EPA administers the Superfund program in cooperation with individual states and tribal governments; this database is made available by the EPA.

Government Publication Date: Oct 25, 2013

EPA Report on the Status of Open Dumps on Indian Lands: IODI

Public Law 103-399, The Indian Lands Open Dump Cleanup Act of 1994, enacted October 22, 1994, identified congressional concerns that solid waste open dump sites located on American Indian or Alaska Native (AI/AN) lands threaten the health and safety of residents of those lands and contiguous areas. The purpose of the Act is to identify the location of open dumps on Indian lands, assess the relative health and environment hazards posed by those sites, and provide financial and technical assistance to Indian tribal governments to close such dumps in compliance with Federal standards and regulations or standards promulgated by Indian Tribal governments or Alaska Native entities.

Government Publication Date: Dec 31, 1998

CERCLIS - No Further Remedial Action Planned: CERCLIS NFRAP

An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. The Archive designation means that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL). This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Government Publication Date: Oct 25, 2013

CERCLIS Liens: CERCLIS LIENS

A Federal Superfund lien exists at any property where EPA has incurred Superfund costs to address contamination ("Superfund site") and has provided notice of liability to the property owner. A Federal CERCLA ("Superfund") lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. This database is made available by the United States Environmental Protection Agency (EPA). This database was provided by the United States Environmental Protection Agency (EPA). Refer to SEMS LIEN as the current data source for Superfund Liens.

Government Publication Date: Jan 30, 2014

RCRA CORRACTS-Corrective Action: RCRA CORRACTS

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. At these sites, the Corrective Action Program ensures that cleanups occur. EPA and state regulators work with facilities and communities to design remedies based on the contamination, geology, and anticipated use unique to each site.

Government Publication Date: Sep 1, 2025

RCRA non-CORRACTS TSD Facilities: RCRA TSD

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. This database includes Non-Corrective Action sites that have indicated engagement in the treatment, storage, or disposal of hazardous waste which requires a RCRA hazardous waste permit.

Government Publication Date: Sep 1, 2025

RCRA Generator List: RCRA LQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Large Quantity Generators (LQGs) generate 1,000 kilograms per month or more of hazardous waste or more than one kilogram per month of acutely hazardous waste. This list also includes RCRAInfo sites that have notified as LQGs that do not have a registered Site Manager or Certifier in RCRAInfo.

Government Publication Date: Sep 1, 2025

RCRA Small Quantity Generators List: RCRA SQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Small Quantity Generators (SQGs) generate more than 100 kilograms, but less than 1,000 kilograms, of hazardous waste per month. This list also includes RCRAInfo sites that have notified as SQGs that do not have a registered Site Manager or Certifier in RCRAInfo.

Government Publication Date: Sep 1, 2025

RCRA Very Small Quantity Generators List: RCRA VSQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Very Small Quantity Generators (VSQG) generate 100 kilograms or less per month of hazardous waste, or one kilogram or less per month of acutely hazardous waste. Additionally, VSQG may not accumulate more than 1,000 kilograms of hazardous waste at any time.

Government Publication Date: Sep 1, 2025

RCRA Non-Generators: RCRA NON GEN

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Non-Generators do not presently generate hazardous waste.

Government Publication Date: Sep 1, 2025

RCRA Sites with Controls: RCRA CONTROLS

List of Resource Conservation and Recovery Act (RCRA) facilities with institutional controls in place. RCRA gives the U.S. Environmental Protection Agency (EPA) the authority to control hazardous waste from the "cradle-to-grave." This includes the generation, transportation, treatment, storage, and disposal of hazardous waste. RCRA also set forth a framework for the management of non-hazardous solid wastes. The 1986 amendments to RCRA enabled EPA to address environmental problems that could result from underground tanks storing petroleum and other hazardous substances.

Government Publication Date: Sep 1, 2025

Federal Engineering Controls-ECs: FED ENG

List of Engineering controls (ECs) made availabe by the United States Environmental Protection Agency (EPA). ECs encompass a variety of engineered and constructed physical barriers (e.g., soil capping, sub-surface venting systems, mitigation barriers, fences) to contain and/or prevent exposure to contamination on a property. The EC listing includes remedy component data from Superfund decision documents for applicable sites on the final or deleted on the National Priorities List (NPL); and sites with a Superfund Alternative Approach (SAA) Agreement in place. The only sites included that are not on the NPL; proposed for NPL; or removed from proposed NPL, are those with an SAA Agreement in place.

Government Publication Date: Sep 29, 2025

Federal Institutional Controls- ICs: FED INST

List of Institutional controls (ICs) made available by the United States Environmental Protection Agency (EPA). ICs are non-engineered instruments, such as administrative and legal controls, that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Although it is EPA's expectation that treatment or engineering controls will be used to address principal threat wastes and that groundwater will be returned to its beneficial use whenever practicable, ICs play an important role in site remedies because they reduce exposure to contamination by limiting land or resource use and guide human behavior at a site. The IC listing includes remedy component data from Superfund decision documents for applicable sites on the final or deleted on the National Priorities List (NPL); and sites with a Superfund Alternative Approach (SAA) Agreement in place. The only sites included that are not on the NPL; proposed for NPL; or removed from proposed NPL, are those with an SAA Agreement in place.

Government Publication Date: Sep 29, 2025

Land Use Controls Information System: LUCIS

The Land Use Controls Information System (LUCIS) database is sourced from the U.S. Department of the Navy (DON). This data contains information for former Base Realignment and Closure (BRAC) properties across the United States. DON's BRAC office was tasked with tracking certain base closures while requiring the prevention of risks to human health and the environment of those properties with LUCs in place. Regarding currently available LUC Sites data, the sites listing is limited to centroid point locations for the overall installation property boundaries. Formerly obtained LUC Sites data may reflect site details that applied previously for a BRAC property.

Government Publication Date: Jun 13, 2024

Institutional Control Boundaries at NPL sites: NPL IC

These boundaries of Institutional Control areas at sites on the U.S. Environmental Protection Agency's (EPA) National Priorities List (NPL), or as Proposed or Deleted, are sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). The EPA's NPL includes the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. Institutional controls are non-engineered instruments such as administrative and legal controls that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes.

Government Publication Date: Sep 6, 2025

Emergency Response Notification System: ERNS 1982 TO 1986

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1982-1986

Emergency Response Notification System: ERNS 1987 TO 1989

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1987-1989

Emergency Response Notification System: ERNS

Database of oil and hazardous substances spill reports made available by the United States Coast Guard National Response Center (NRC). The NRC fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. These data contain initial incident data that has not been validated or investigated by a federal/state response agency.

Government Publication Date: Sep 7, 2025

The Assessment, Cleanup and Redevelopment Exchange System (ACRES) Brownfield Database: FED BROWNFIELDS

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties protects the environment, reduces blight, and takes development pressures off greenspaces and working lands. This data is provided by the United States Environmental Protection Agency (EPA) and includes Brownfield sites from the Cleanups in My Community (CIMC) web application.

Government Publication Date: Sep 8, 2025

FEMA Underground Storage Tank Listing: FEMA UST

The Federal Emergency Management Agency (FEMA) of the Department of Homeland Security maintains a list of FEMA owned underground storage tanks.

Government Publication Date: Dec 31, 2017

Facility Response Plan: FRP

This listing contains facilities that have submitted Facility Response Plans (FRPs) to the U.S. Environmental Protection Agency (EPA). Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit FRPs. Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments. The list includes FRP facilities sourced from the EPA FOIA office and from previously available Homeland Infrastructure Foundation-Level Data (HIFLD) file/s. Disclaimer: Per the EPA FOIA Office, the verification process for current requested FRP data is undergoing review and revision, and any similar reporting will be made public in Fiscal Year 2026. For this reason, the latest available FOIA file may be incomplete.

Government Publication Date: Jun 1, 2025

Delisted Facility Response Plans: DELISTED FRP

Facilities that once appeared in - and have since been removed from - the list of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Jun 1, 2025

Historical Gas Stations: HIST GAS STATIONS

This historic directory of service stations is provided by the Cities Service Company. The directory includes Cities Service filling stations that were located throughout the United States in 1930.

Government Publication Date: Jul 1, 1930

Petroleum Refineries: REFN

This list of petroleum refineries is sourced from the U.S. Energy Information Administration (EIA), Refinery Capacity Report. The listing includes operating and idle petroleum refineries (including new refineries under construction) and refineries shut down during the previous year. The geographic area the report covers is the 50 States, the District of Columbia, Puerto Rico, the U.S. Virgin Islands, Guam, and other U.S. possessions. Per the EIA, the facility location data represents the approximate location based on research of publicly available information from sources such as Federal agencies, company websites, and satellite images on public websites.

Government Publication Date: Oct 31, 2024

Petroleum Product and Crude Oil Rail Terminals: BULK TERMINAL

A list of petroleum product and crude oil rail terminals from the U.S. Energy Information Administration (EIA), as well as petroleum terminals sourced from Oak Ridge National Laboratory hosted by the Homeland Infrastructure Foundation-Level Database. Data includes operable bulk petroleum product terminals with a total bulk shell storage capacity of 50,000 barrels or more, and/or the ability to receive volumes from tanker, barge, or pipeline; also rail terminals handling the loading and unloading of crude oil with activity between 2017 and 2018. EIA petroleum product terminal data comes from the EIA-815 Bulk Terminal and Blender Report, which includes working, shell in operation, and shell idle for several major product groupings.

Government Publication Date: Jun 5, 2025

LIEN on Property: SEMS LIEN

The U.S. Environmental Protection Agency's (EPA) Superfund Enterprise Management System (SEMS) provides Lien details on applicable properties, such as the Superfund lien on property activity, the lien property information, and the parties associated with the lien.

Government Publication Date: Aug 27, 2025

Superfund Decision Documents: SUPERFUND ROD

This database contains a list of decision documents for Superfund sites. Decision documents serve to provide the reasoning for the choice of (or) changes to a Superfund Site cleanup plan. The decision documents include completed Records of Decision (ROD), ROD Amendments, Explanations of Significant Differences (ESD) for active and archived sites stored in the Superfund Enterprise Management System (SEMS), along with other associated memos and files. This information is maintained and made available by the U.S. Environmental Protection Agency.

Government Publication Date: Oct 30, 2025

State

State Cleanup Sites Listing: SCS

List of active and closed State Clean Up Sites made available by the Ground Water Quality Bureau's Remediation Oversight Section of the New Mexico Environment Department (NMED). The Remediation Oversight Section encourages and oversees voluntary efforts to clean up contaminated sites, and administers the Water Quality Control Commission Regulations that require responsible parties to clean up contaminated soil and ground water. This database serves a purpose similar to that of the federal Superfund Enterprise Management System (SEMS), functioning as a state-level counterpart for tracking potential hazardous substance release sites.

Government Publication Date: Feb 4, 2025

Delisted State Cleanup Sites: DELISTED SCS

List of sites removed from State Clean Up Sites made available by the Ground Water Quality Bureau's Remediation Oversight Section of the New Mexico Environment Department (NMED).

Government Publication Date: Feb 4, 2025

Solid Waste Facilities: SWF/LF

List of currently or formerly permitted/registered facilities in New Mexico, including haulers, landfills, transfer stations, collection centers, generators, recycling facilities, and composting facilities. This list includes facilities that are currently open and reporting as well as facilities that are closed but previously held a permit. This list is made available by the New Mexico Environment Department (NMED)'s Solid Waste Bureau.

Government Publication Date: Oct 23, 2025

Historical Solid Waste Landfills: HIST LF

List of historical landfill sites provided by the New Mexico Environment Department (NMED) Solid Waste Bureau, and sites from the Bureau of Land Management which were closed prior to 1984. Public Land Survey System (PLSS) locations provided by the source are subject to accuracy limitations inherent to the PLSS system.

Government Publication Date: Aug 21, 2014

Recycling Centers: RECYCLING

List of registered and other recycling centers made available by the New Mexico Environment Department's (NMED) Solid Waste Bureau.

Government Publication Date: Nov 6, 2025

Leaking Petroleum Storage Tanks: LST

This list of Leaking Petroleum Storage Tank sites is made available by the New Mexico Environment Department's (NMED) Petroleum Storage Tank Bureau (PSTB). Includes records from PSTB listings, and records from the NMED Open Map Portal.

Government Publication Date: Sep 16, 2025

Delisted Active and No Further Action Leaking Tanks: DELISTED LST

This database contains a list of leaking storage tank sites that were removed from the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau.

Government Publication Date: Sep 16, 2025

Leaking Underground Storage Tanks: LUST HIST

Historical list of leaking underground leaking tanks provided by the New Mexico Environment Department (NMED). This list was last updated in August of 2006.

Government Publication Date: Aug 1, 2006

Underground Storage Tanks: UST

List of Underground Storage Tank sites made available by the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau (PSTB). Includes Underground Storage Tank Facilities from the NMED Open Data Portal.

Government Publication Date: Nov 3, 2025

Aboveground Storage Tanks: AST

List of Aboveground Storage Tank sites made available by the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau (PSTB). Includes Aboveground Storage Tank Facilities from the NMED Open Data Portal.

Government Publication Date: Nov 3, 2025

Petroleum Storage Tanks: TANKS

List of Storage Tank Sites made available by the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau. Includes sites with underground and aboveground tanks.

Government Publication Date: Jul 9, 2019

Underground Storage Tanks - Historical: UST HIST

Historical listing of underground storage tanks registered with the New Mexico Environment Department (NMED). This data was last updated in August 2006.

Government Publication Date: Aug 1, 2006

Aboveground Storage Tanks - Historical: AST HIST

Historical listing of aboveground storage tank facilities registered with the New Mexico Environment Department (NMED. This data was last updated in August 2006.

Government Publication Date: Aug 4, 2006

Delisted Tanks: DELISTED TANK

List of Storage Tank Sites removed from the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau's list of underground and aboveground tanks.

Government Publication Date: Nov 3, 2025

Sites with Institutional and Engineering Controls: INST

List of sites in the New Mexico Environment Department (NMED)'s Public Record of Voluntary Remediation Program (VRP) Sites with institutional and/or engineering controls.

Government Publication Date: Sep 30, 2025

Voluntary Remediation Program Sites: VCP

Public Record of Voluntary Remediation Program (VRP) Sites made available by the New Mexico Environment Department (NMED). New Mexico's Voluntary Remediation Program (VRP) provides incentives for the voluntary cleanup of contaminated properties and encourages their redevelopment. VRP participants that complete the program successfully will receive site closure documentation from the NMED including a Certificate of Completion or Conditional Certificate of Completion.

Government Publication Date: Sep 30, 2025

Targeted Brownfields Assessment Sites: BROWNFIELDS

List of Targeted Brownfields Assessment Sites made available by the New Mexico Environment Department (NMED). Brownfields are properties whose redevelopment is complicated by the presence or potential presence of hazardous substances or petroleum products. NMED provides no-cost environmental assessments of brownfield sites to local or tribal governments. NMED also manages a Brownfields Revolving Loan Fund providing low-interest loans for brownfield cleanups where redevelopment is planned.

Government Publication Date: Sep 30, 2025

Tribal

Leaking Underground Storage Tanks on Tribal/Indian Lands: INDIAN LUST

This list of leaking underground storage tanks (LUSTs) on Tribal/Indian Lands in Region 6, which includes New Mexico, is provided by the United States Environmental Protection Agency (EPA).

Government Publication Date: Apr 21, 2025

Underground Storage Tanks on Tribal/Indian Lands: INDIAN UST

This list of underground storage tanks (USTs) on Tribal/Indian Lands in Region 6, which includes New Mexico, is provided by the United States Environmental Protection Agency (EPA).

Government Publication Date: Apr 21, 2025

Delisted Tribal Leaking Storage Tanks: DELISTED INDIAN LST

Leaking Underground Storage Tank (LUST) facilities which once appeared on - and have since been removed from - the Regional Tribal/Indian LUST lists made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: May 22, 2025

Delisted Tribal Underground Storage Tanks: DELISTED INDIAN UST

Underground Storage Tank (UST) facilities which once appeared on - and have since been removed from - the Regional Tribal/Indian UST lists made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: May 22, 2025

County

No County databases were selected to be included in the search.

Additional Environmental Record Sources

Federal

PFAS Greenhouse Gas Emissions Data: PFAS GHG

The U.S. Environmental Protection Agency's (EPA) Greenhouse Gas Reporting Program (GHGRP) collects Greenhouse Gas (GHG) data from large emitting facilities (25,000 metric tons of carbon dioxide equivalent (CO2e) per year), and suppliers of fossil fuels and industrial gases that results in GHG emissions when used. This dataset is sourced from the EPA's PFAS Analytic Tools, and it includes GHG emissions data for facilities that emit or have emitted since 2010 chemicals identified as PFAS based on EPA's CompTox Chemicals Dashboard lists of PFAS with defined and undefined structures. PFAS emissions data has been identified for facilities engaged in the following industrial processes: Aluminum Production (GHGRP Subpart F), HCFC-22 Production and HFC-23 Destruction (Subpart O), Electronics Manufacturing (Subpart I), Fluorinated Gas Production (Subpart L), Magnesium Production (Subpart T), Electrical Transmission and Distribution Equipment Use (Subpart DD), and Manufacture of Electric Transmission and Distribution Equipment (Subpart SS). Over time, other industrial processes with required GHGRP reporting may include PFAS emissions data and the list of reportable gases may change over time. Note that some regulatory programs have specified chemical structure requirements that define PFAS differently than the lists in EPA's CompTox Chemicals Dashboard.

Government Publication Date: Oct 7, 2025

On-Scene Coordinator Response Sites: OSC RESPONSE

This list of On-Scene Coordinator (OSC) Response Sites is provided by the U.S. Environmental Protection Agency (EPA). OSCs are the federal officials responsible for monitoring or directing responses to all oil spills and hazardous substance releases reported to the federal government. OSCs coordinate all federal efforts with, and provide support and information to local, state, and regional response communities. An OSC is an agent of either EPA or the U.S. Coast Guard (USCG), depending on where the incident occurs. EPA's OSCs have primary responsibility for spills and releases to inland areas and waters. USCG OSCs have responsibility for coastal waters and the Great Lakes. In general, an OSC has the following key responsibilities during and after a response: Assessment, Monitoring, Response Assistance, and Evaluation.

Government Publication Date: Oct 8, 2025

Facility Registry Service/Facility Index: FINDS/FRS

The Facility Registry Service (FRS) is a centrally managed database that identifies facilities, sites, or places subject to environmental regulations or of environmental interest. FRS creates high-quality, accurate, and authoritative facility identification records through rigorous verification and management procedures that incorporate information from program national systems, state master facility records, and data collected from EPA's Central Data Exchange registrations and data management personnel. This list is made available by the U.S. Environmental Protection Agency (EPA).

Government Publication Date: Oct 10, 2025

Toxics Release Inventory (TRI) Program: TRIS

The U.S. Environmental Protection Agency's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of toxic chemicals from U.S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment. There are currently 770 individually listed chemicals and 33 chemical categories covered by the TRI Program. Facilities that manufacture, process or otherwise use these chemicals in amounts above established levels must submit annual reporting forms for each chemical. Note that the TRI chemical list does not include all toxic chemicals used in the U.S. One of TRI's primary purposes is to inform communities about toxic chemical releases to the environment. This database includes TRI Reporting Data for calendar years 1987 through 2021 and Preliminary Data for 2022.

Government Publication Date: Sep 20, 2023

PFOA/PFOS Contaminated Sites: PFAS NPL

This list of Superfund Sites with Per- and Polyfluoroalkyl Substances (PFAS) detections is made available by the U.S. Environmental Protection Agency (EPA) in their PFAS Analytic Tools data, previously the list was obtained by EPA FOIA requests. EPA's Office of Land and Emergency Management and EPA Regional Offices maintain what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment. Limitations: Detections of PFAS at National Priorities List (NPL) sites do not mean that people are at risk from PFAS, are exposed to PFAS, or that the site is the source of the PFAS. The information in the Superfund NPL and Superfund Alternative Agreement (SAA) PFAS detection site list is years old and may not be accurate today. Site information such as site name, site ID, and location has been confirmed for accuracy; however, PFAS-related information such as media sampled, drinking water being above the health advisory, or mitigation efforts has not been verified. For Federal Facilities data, the other Federal agencies (OFA) are the lead agency for their data and provided them to EPA.

Government Publication Date: Sep 26, 2025

Federal Agency Locations with Known or Suspected PFAS Detections: PFAS FED SITES

This list of federal agency locations with known or suspected detections of Per- and Polyfluoroalkyl Substances (PFAS) is made available by the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools data. The EPA outlines that these data are gathered from several federal entities, such as the federal Superfund program, Department of Defense (DOD), National Aeronautics and Space Administration (NASA), Department of Transportation (DOT), and Department of Energy (DOE). The dates this data was extracted for the PFAS Analytic Tools range from 2022 to 2025 per agency entity dataset. Sites on this list do not necessarily reflect the source/s of PFAS contamination and detections do not indicate level of risk or human exposure at the site. Agricultural notifications in this data are limited to DOD sites only. At this time, the EPA is aware that this list is not comprehensive of all Federal agencies.

Government Publication Date: May 30, 2025

SSEHRI PFAS Contamination Sites: PFAS SSEHRI

This PFAS Contamination Site Tracker database is compiled by the PFAS Project Lab, part of the Social Science Environmental Health Research Institute (SSEHRI) at Northeastern University. According to the SSEHRI, the database records qualitative and quantitative data from each known site of PFAS contamination, including timeline of discovery, sources, levels, health impacts, community response, and government response. The goal of this database is to compile information and support public understanding of the rapidly unfolding issue of PFAS contamination. All data presented was extracted from government websites, news articles, or publicly available documents. Locations for the Known PFAS Contamination Sites are sourced from the PFAS Sites and Community Resources Map by the PFAS-REACH team, credited to PFAS Project Lab, Silent Spring Institute, and PFAS Exchange. Disclaimer: The source conveys the data undergoes regular updates as new information becomes available, some sites may be missing and/or contain information that is incorrect or outdated, as well as their information represents all contamination sites SSEHRI is aware of, not all possible contamination sites. This data is not intended to be used for legal purposes. Access the following source link for the most current information: https://pfasproject.com/pfas-sites-and-community-resources/

Government Publication Date: Aug 1, 2025

National Response Center PFAS Spills: PFAS ERNS

This Per- and Poly-Fluoroalkyl Substances (PFAS) Spills dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The National Response Center (NRC), operated by the U.S. Coast Guard, is the designated federal point of contact for reporting all oil, chemical, and other discharges into the environment, for the United States and its territories. This dataset contains NRC spill information from 1990 to the present that is restricted to records associated with PFAS and PFAS-containing materials. Incidents are filtered to include only records with a "Material Involved" or "Incident Description" related to Aqueous Film Forming Foam (AFFF). The keywords used to filter the data included "AFFF," "Fire Fighting Foam," "Aqueous Film Forming Foam," "Fire Suppressant Foam, "PFAS," "PERFL," "PFOA," "PFOS," and "Genx." Limitations: The data from the NRC website contains initial incident data that has not been validated or investigated by a federal/state response agency. Keyword searches may misidentify some incident reports that do not contain PFAS. This dataset should also not be considered to be exhaustive of all PFAS spills/release incidents.

Government Publication Date: Dec 1, 2025

PFAS NPDES Discharge Monitoring: PFAS NPDES

This list of National Pollutant Discharge Elimination System (NPDES) permitted facilities with required monitoring for Per- and Polyfluoroalkyl (PFAS) Substances is made available via the U.S. Environmental Protection Agency (EPA)'s PFAS Analytic Tools. Any point-source wastewater discharger to waters of the United States must have a NPDES permit, which defines a set of parameters for pollutants and monitoring to ensure that the discharge does not degrade water quality or impair human health. This list includes NPDES permitted facilities associated with permits that monitor for Per- and Polyfluoroalkyl Substances (PFAS), limited to the years 2007 - present. EPA further advises the following regarding these data: currently, fewer than half of states have required PFAS monitoring for at least one of their permittees, and fewer states have established PFAS effluent limits for permittees. For states that may have required monitoring, some reporting and data transfer issues may exist on a state-by-state basis.

Government Publication Date: Dec 16, 2024

Perfluorinated Alkyl Substances (PFAS) from Toxic Release Inventory: PFAS TRI

List of Toxics Release Inventory (TRI) facilities at which the reported chemical is a per- or polyfluoroalkyl (PFAS) substance included in the U.S. Environmental Protection Agency's (EPA) consolidated PFAS Master List of PFAS Substances. Encompasses Toxics Release Inventory records included in the EPA PFAS Analytic Tools. The EPA's TRI database currently tracks information on disposal or releases of 770 individually listed toxic chemicals and 33 chemical categories from thousands of U.S. facilities and details about how facilities manage those chemicals through recycling, energy recovery, and treatment. This listing includes TRI Reporting Data for calendar years 1987 through 2021 and Preliminary Data for 2022.

Government Publication Date: Sep 20, 2023

PFAS Water Quality Portal Sampling Data: PFAS WATER

This Per- and Poly-Fluoroalkyl Substances (PFAS) Environmental Media Sampling Data is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The Water Quality Portal (WQP), as a cooperative service sponsored by the United States Geological Survey, the EPA, and the National Water Quality Monitoring Council, is part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations, and individuals submit project details and sampling results to this public repository. Limitations: EPA did not carry out the sampling or testing of a majority of the data in the WQP PFAS dataset. EPA can only speak to the accuracy and completeness of the data from projects like the National Aquatic Resource Surveys for which EPA is the data owner/organization. Data may exist within the file on Quality Assurance Project Plans (QAPPs) and the approving agency of the QAPP, if a QAPP is entered.

Government Publication Date: Jul 21, 2025

PFAS TSCA Manufacture and Import Facilities: PFAS TSCA

The U.S. Environmental Protection Agency (EPA) issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. This list is specific only to TSCA Manufacture and Import Facilities with reported per- and poly-fluoroalkyl (PFAS) substances. Data file is sourced from EPA's PFAS Analytic Tools TSCA dataset which includes CDR/Inventory Update Reporting data from 1998 up to 2020. Disclaimer: This data file includes production and importation data for chemicals identified in EPA's CompTox Chemicals Dashboard list of PFAS without explicit structures and list of PFAS structures in DSSTox. Note that some regulations have specific chemical structure requirements that define PFAS differently than the lists in EPA's CompTox Chemicals Dashboard. Reporting information on manufactured or imported chemical substance amounts should not be compared between facilities, as some companies claim Chemical Data Reporting Rule data fields for PFAS information as Confidential Business Information.

Government Publication Date: Jan 5, 2023

PFAS Waste Transfers from RCRA e-Manifest: PFAS E-MANIFEST

This Per- and Poly-Fluoroalkyl Substances (PFAS) Waste Transfers dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. Every shipment of hazardous waste in the U.S. must be accompanied by a shipment manifest, which is a critical component of the cradle-to-grave tracking of wastes mandated by the Resource Conservation and Recovery Act (RCRA). According to the EPA, currently no Federal Waste Code exists for any PFAS compounds. To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: • PFAS • PFOA • PFOS • PERFL • AFFF • GENX • GEN-X (plus the Vermont state-specific waste codes). Limitations: Amount or concentration of PFAS being transferred cannot be determined from the manifest information. Keyword searches may misidentify some manifest records that do not contain PFAS. This dataset should also not be considered to be exhaustive of all PFAS waste transfers.

Government Publication Date: Oct 4, 2025

PFAS Industry Sectors: PFAS IND

This Per- and Poly-Fluoroalkyl Substances (PFAS) Industry Sectors dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The EPA developed the dataset from various sources that show which industries may be handling PFAS including: EPA's Enforcement and Compliance History Online (ECHO) records restricted to potential PFAS-handling industry sectors; ECHO records for Fire Training Sites identified where fire-fighting foam may have been used in training exercises; and 14 CFR Part 139 Airports compiled from historic and current records from the FAA Airport Data and Information Portal. Since July 2006, all certificated Part 139 Airports are required to have fire-fighting foam onsite that meet certain military specifications, which to date have been fluorinated (Aqueous Film Forming Foam). Limitations: Inclusion in this dataset does not indicate that PFAS are being manufactured, processed, used, or released by the facility. Listed facilities potentially handle PFAS based on their industrial profile, but are unconfirmed by the EPA. Keyword searches in ECHO for Fire Training sites may misidentify some facilities and should not be considered to be an exhaustive list of fire training facilities in the U.S.

Government Publication Date: Sep 1, 2025

Hazardous Materials Information Reporting System: HMIRS

The Hazardous Materials Incident Reporting System (HMIRS) database contains unintentional hazardous materials release information reported to the U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration.

Government Publication Date: May 28, 2025

National Clandestine Drug Labs: NCDL

The U.S. Department of Justice ("the Department"), Drug Enforcement Administration (DEA), provides this data as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy.

Government Publication Date: Nov 30, 2023

Toxic Substances Control Act: TSCA

The U.S. Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule. The CDR enables EPA to collect and publish information on the manufacturing, processing, and use of commercial chemical substances and mixtures (referred to hereafter as chemical substances) on the TSCA Chemical Substance Inventory (TSCA Inventory). This includes current information on chemical substance production volumes, manufacturing sites, and how the chemical substances are used. This information helps the Agency determine whether people or the environment are potentially exposed to reported chemical substances. EPA publishes submitted CDR data that is not Confidential Business Information (CBI). EPA CDR collections occur approximately every four years and reporting requirements change per collection.

Government Publication Date: May 12, 2022

Hist TSCA: HIST TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.
The 2006 IUR data summary report includes information about chemicals manufactured or imported in quantities of 25,000 pounds or more at a single site during calendar year 2005. In addition to the basic manufacturing information collected in previous reporting cycles, the 2006 cycle is the first time EPA collected information to characterize exposure during manufacturing, processing and use of organic chemicals. The 2006 cycle also is the first time manufacturers of inorganic chemicals were required to report basic manufacturing information.

Government Publication Date: Dec 31, 2006

FTTS Administrative Case Listing: FTTS ADMIN

An administrative case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

FTTS Inspection Case Listing: FTTS INSP

An inspection case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

Potentially Responsible Parties List: PRP

Early in the site cleanup process, the U.S. Environmental Protection Agency (EPA) conducts a search to find the Potentially Responsible Parties (PRPs). The EPA looks for evidence to determine liability by matching wastes found at the site with parties that may have contributed wastes to the site. This listing contains PRPs, Noticed Parties, at sites in the EPA's Superfund Enterprise Management System (SEMS).

Government Publication Date: Sep 29, 2025

State Coalition for Remediation of Drycleaners Listing: SCRD DRYCLEANER

The State Coalition for Remediation of Drycleaners (SCRD) was established in 1998, with support from the U.S. Environmental Protection Agency (EPA) Office of Superfund Remediation and Technology Innovation. Coalition members are states with mandated programs and funding for drycleaner site remediation. Current members are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin. Since 2017, the SCRD no longer maintains this data, refer to applicable state source data where available.

Government Publication Date: Nov 08, 2017

Integrated Compliance Information System (ICIS): ICIS

The Integrated Compliance Information System (ICIS) database contains integrated enforcement and compliance information across most of U.S. Environmental Protection Agency's (EPA) programs. The vision for ICIS is to replace EPA's independent databases that contain enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions and a subset of the Permit Compliance System (PCS), which supports the National Pollutant Discharge Elimination System (NPDES). This information is maintained by the EPA Headquarters and at the Regional offices. A future release of ICIS will completely replace PCS and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities that support compliance and enforcement programs, including incident tracking, compliance assistance, and compliance monitoring.

Government Publication Date: May 3, 2025

Drycleaner Facilities: FED DRYCLEANERS

A list of drycleaner facilities from Enforcement and Compliance History Online (ECHO) data as made available by the U.S. Environmental Protection Agency (EPA), sourced from the ECHO Exporter file. This EPA source file tracks facilities that possess NAICS and SIC codes that classify businesses as drycleaner establishments.

Government Publication Date: Jul 19, 2025

Delisted Drycleaner Facilities: DELISTED FED DRY

List of sites which once appeared on - and have since been removed from - the list of drycleaner facilities included in Enforcement and Compliance History Online (ECHO) data as made available by the U.S. Environmental Protection Agency (EPA), sourced from the ECHO Exporter file. This EPA source file tracks facilities that possess NAICS and SIC codes that classify businesses as drycleaner establishments.

Government Publication Date: Jul 19, 2025

Formerly Used Defense Sites: FUDS

Formerly Used Defense Sites (FUDS) are properties that were formerly owned by, leased to, or otherwise possessed by and under the jurisdiction of the Secretary of Defense prior to October 1986, where the Department of Defense (DOD) is responsible for an environmental restoration. The FUDS Annual Report to Congress (ARC) is published by the U.S. Army Corps of Engineers (USACE). This data is compiled from the USACE's Geospatial FUDS data layers and Homeland Infrastructure Foundation-Level Data (HIFLD) FUDS dataset which applies to the Fiscal Year 2021 FUDS Inventory.

Government Publication Date: May 15, 2023

FUDS Munitions Response Sites: FUDS MRS

Boundaries of Munitions Response Sites (MRS), published with the Formerly Used Defense Sites (FUDS) Annual Report to Congress (ARC) by the U.S. Army Corps of Engineers (USACE). An MRS is a discrete location within a Munitions response area (MRA) that is known to require a munitions response. An MRA means any area on a defense site that is known or suspected to contain unexploded ordnance (UXO), discarded military munitions (DMM), or munitions constituents (MC). This data is compiled from the USACE's Geospatial MRS data layers and Homeland Infrastructure Foundation-Level Data (HIFLD) MRS dataset.

Government Publication Date: May 15, 2023

Former Military Nike Missile Sites: FORMER NIKE

This information was taken from report DRXTH-AS-IA-83A016 (Historical Overview of the Nike Missile System, 12/1984) which was performed by Environmental Science and Engineering, Inc. for the U.S. Army Toxic and Hazardous Materials Agency Assessment Division. The Nike system was deployed between 1954 and the mid-1970's. Among the substances used or stored on Nike sites were liquid missile fuel (JP-4); starter fluids (UDKH, aniline, and furfuryl alcohol); oxidizer (IRFNA); hydrocarbons (motor oil, hydraulic fluid, diesel fuel, gasoline, heating oil); solvents (carbon tetrachloride, trichloroethylene, trichloroethane, stoddard solvent); and battery electrolyte. The quantities of material a disposed of and procedures for disposal are not documented in published reports. Virtually all information concerning the potential for contamination at Nike sites is confined to personnel who were assigned to Nike sites. During deactivation most hardware was shipped to depot-level supply points. There were reportedly instances where excess materials were disposed of on or near the site itself at closure. There was reportedly no routine site decontamination.

Government Publication Date: Dec 2, 1984

PHMSA Pipeline Safety Flagged Incidents: PIPELINE INCIDENT

This list of flagged pipeline incidents is made available by the U.S. Department of Transportation (US DOT) Pipeline and Hazardous Materials Safety Administration (PHMSA). PHMSA regulations require incident and accident reports for five different pipeline system types. Accidents reported on hazardous liquid gravity lines (§195.13) and reporting-regulated-only hazardous liquid gathering lines (§195.15) and incidents reported on Type R gas gathering (§192.8(c)) are not included in the flagged incident file data.

Government Publication Date: Jul 10, 2025

Material Licensing Tracking System (MLTS): MLTS

A list of sites that store radioactive material subject to the Nuclear Regulatory Commission (NRC) licensing requirements. This list is maintained by the NRC. As of September 2016, the NRC no longer releases location information for sites. Site locations were last received in July 2016.

Government Publication Date: May 11, 2021

Historic Material Licensing Tracking System (MLTS) sites: HIST MLTS

A historic list of sites that have inactive licenses and/or removed from the Material Licensing Tracking System (MLTS). In some cases, a site is removed from the MLTS when the state becomes an "Agreement State". An Agreement State is a State that has signed an agreement with the Nuclear Regulatory Commission (NRC) authorizing the State to regulate certain uses of radioactive materials within the State.

Government Publication Date: Jan 31, 2010

Mines Master Index File: MINES

The Master Index File (MIF) is provided by the United States Department of Labor, Mine Safety and Health Administration (MSHA). This file, which was originally created in the 1970's, contained many Mine-IDs that were invalid. MSHA removes invalid IDs from the MIF upon discovery. MSHA applicable data includes the following: all Coal and Metal/Non-Metal mines under MSHA's jurisdiction since 1/1/1970; mine addresses for all mines in the database except for Abandoned mines prior to 1998 from MSHA's legacy system (addresses may or may not correspond with the physical location of the mine itself); violations that have been assessed penalties as a result of MSHA inspections beginning on 1/1/2000; and violations issued as a result of MSHA inspections conducted beginning on 1/1/2000.

Government Publication Date: Aug 8, 2025

Surface Mining Control and Reclamation Act Sites: SMCRA

This inventory of land and water impacted by past mining (primarily legacy coal mining operations) is maintained by the U.S. Department of the Interior's Office of Surface Mining Reclamation and Enforcement (OSMRE), as it provides information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). This inventory contains information on the type and extent of Abandoned Mine Land (AML) Problems, as well as information on the cost associated with the reclamation of those problems. The data is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed. Disclaimer: Per the OSMRE, States and tribes who enter their data into e-AMLIS (AML Inventory System) may truncate their latitude and longitude so the precise location of usually dangerous AMLs is not revealed in an effort to protect the public from searching for these AMLs, most of which are on private property. If more precise location information is needed, please contact the applicable state/tribe of interest.

Government Publication Date: Oct 30, 2025

Mineral Resource Data System: MRDS

The Mineral Resource Data System (MRDS) is a collection of reports describing metallic and nonmetallic mineral resources throughout the world. Included are deposit name, location, commodity, deposit description, geologic characteristics, production, reserves, resources, and references. This database contains the records previously provided in the Mineral Resource Data System (MRDS) of USGS and the Mineral Availability System/Mineral Industry Locator System (MAS/MILS) originated in the U.S. Bureau of Mines, which is now part of USGS. The USGS has ceased systematic updates of the MRDS database with their focus more recently on deposits of critical minerals while providing a well-documented baseline of historical mine locations from USGS topographic maps.

Government Publication Date: Mar 15, 2016

DOE Legacy Management Sites: LM SITES

The U.S. Department of Energy (DOE) Office of Legacy Management (LM) currently manages radioactive and chemical waste, environmental contamination, and hazardous material at over 100 sites across the U.S. The LM manages sites with diverse regulatory drivers (statutes or programs that direct cleanup and management requirements at DOE sites) or as part of internal DOE or congressionally-recognized programs, such as but not limited to: Formerly Utilized Sites Remedial Action Program (FUSRAP), Uranium Mill Tailings Radiation Control Act (UMTRCA Title I, Tile II), Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), Resource Conservation and Recovery Act (RCRA), Decontamination and Decommissioning (D&D), Nuclear Waste Policy Act (NWPA). The intent of the site location is to provide a general reference point to the site on a national scale. The coordinates of each site point can be the location of a site monument, the centroid of the site boundary, or a general location of the site. This site listing includes data exported from the DOE Office of LM's Geospatial Environmental Mapping System (GEMS). GEMS Data disclaimer: The DOE Office of LM makes no representation or warranty, expressed or implied, regarding the use, accuracy, availability, or completeness of the data presented herein.

Government Publication Date: Nov 6, 2025

Alternative Fueling Stations: ALT FUELS

This list of alternative fueling stations is sourced from the Alternative Fuels Data Center (AFDC). The U.S. Department of Energy's Office of Energy Efficiency & Renewable Energy launched the AFDC in 1991 as a repository for alternative fuel vehicle performance data, which provides a wealth of information and data on alternative and renewable fuels, advanced vehicles, fuel-saving strategies, and emerging transportation technologies. The data includes Biodiesel (B20 and above), Compressed Natural Gas (CNG), Electric, Ethanol (E85), Hydrogen, Liquefied Natural Gas (LNG), Propane (LPG), and Renewable Diesel (R20 and above) fuel type locations.

Government Publication Date: Aug 1, 2025

Superfunds Consent Decrees: CONSENT DECREES

This list of Superfund consent decrees is provided by the Department of Justice, Environment & Natural Resources Division (ENRD) through a Freedom of Information Act (FOIA) applicable file. This listing includes Cases filed since 2010 limited to the following: Consent Decrees for CERCLA or Superfund Sites filed and/or as proposed within the ENRD's Case Management System (CMS); and applicable ENRD's Environmental Defense Section (EDS) CERCLA Cases with "Consent" in History Note. CMS may not reflect the latest developments in a case, nor can the agency guarantee the accuracy of the data. ENRD Disclaimer: Congress excluded three discrete categories of law enforcement and national security records from the requirements of the FOIA; response is limited to those records that are subject to the requirements of the FOIA; however, this should not be taken as an indication that excluded records do, or do not, exist.

Government Publication Date: Jun 26, 2024

Air Facility System: AFS

This EPA retired Air Facility System (AFS) dataset contains emissions, compliance, and enforcement data on stationary sources of air pollution. Regulated sources cover a wide spectrum; from large industrial facilities to relatively small operations such as dry cleaners. AFS does not contain data on facilities that are solely asbestos demolition and/or renovation contractors, or landfills. ECHO Clean Air Act data from AFS are frozen and reflect data as of October 17, 2014; the EPA retired this system for Clean Air Act stationary sources and transitioned to ICIS-Air.

Government Publication Date: Oct 17, 2014

Registered Pesticide Establishments: SSTS

This national list of active EPA-registered foreign and domestic pesticide and/or device-producing establishments is based on data from the Section Seven Tracking System (SSTS). The Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) Section 7 requires that each producing establishment must place its EPA establishment number on the label or immediate container of each pesticide, active ingredient or device produced. An EPA establishment number on a pesticide product label identifies the EPA registered location where the product was produced. The list of establishments is made available by the U.S. Environmental Protection Agency (EPA).

Government Publication Date: Sep 26, 2025

Polychlorinated Biphenyl (PCB) Transformers: PCBT

Locations of Transformers Containing Polychlorinated Biphenyls (PCBs) registered with the United States Environmental Protection Agency. PCB transformer owners must register their transformer(s) with EPA. Although not required, PCB transformer owners who have removed and properly disposed of a registered PCB transformer may notify EPA to have their PCB transformer de-registered. Data made available by EPA.

Government Publication Date: Oct 15, 2019

Polychlorinated Biphenyl (PCB) Notifiers: PCB

Facilities included in the national list of facilities that have notified the United States Environmental Protection Agency (EPA) of Polychlorinated Biphenyl (PCB) activities. Any company or person storing, transporting or disposing of PCBs or conducting PCB research and development must notify the EPA and receive an identification number.

Government Publication Date: May 23, 2024

Power Plants: POWER PLANTS

This list of power plants is provided by the U.S. Energy Information Administration (EIA). The listing includes operable electric generating plants in the United States by energy source, originating from the EIA-860, Annual Electric Generator Report; EIA-860M, Monthly Update to the Annual Electric Generator Report; and EIA-923, Power Plant Operations Report. It includes all operable plants by energy source with a combined nameplate capacity of 1 megawatt or more that are operating, are on standby, or out of service for short- or long-term.

Government Publication Date: Jun 5, 2025

Historical Business Activity Risk: HIST RISK

Proprietary list of sites identified as potentially having engaged in business activity that poses a higher-than-normal risk of contamination. Records originate from historical city directories, and are included in this list based on broad business categories Potentially Hazardous Chemical Users and Fuel and Automotive, including but not limited to Dry Cleaners and Fuel Stations, Garages, etc. Inclusion in this listing does not indicate that there is or ever has been contamination; rather, sites are included in this list due to their potential for having engaged in a business activity presenting an elevated risk of contamination. The list was compiled from various city directories including Polks, Millers, Mullin Kille, Interstate Directory, and State Directory Co; spanning roughly 1920s through 1960 depending on information available by city.

Government Publication Date: Jan 1, 1960

State

Hazardous Waste Facilities: HAZ

List of hazardous waste generators and treatment, storage, and disposal facilities overseen by the Hazardous Waste Bureau (HWB), New Mexico Environment Department (NMED).

Government Publication Date: Apr 24, 2018

Spills: SPILLS

A listing of spills included in the New Mexico Environment Department's Environmental Notification Tracking System.

Government Publication Date: May 31, 2025

Spills and Incidents - Oil Conservation Division: SPILLS OIL

List of Spills and Incidents made available by the State of New Mexico Oil Conservation Division.

Government Publication Date: Oct 23, 2025

Clandestine Drug Lab Discoveries: CDL

List of addresses of locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. The sources of the entries are law enforcement agencies, and although the list is made available by the New Mexico Environment Department (NMED), NMED has not verified the data and does not guarantee its accuracy. Sites listed were seized prior to January 1, 2008, were not subject to the New Mexico Clandestine Drug Lab Cleanup Rule.

Government Publication Date: May 17, 2018

Per- and Polyfluoroalkyl Substances (PFAS): PFAS

List of PFAS/PFOS sites of concern and sampling locations made available by the New Mexico Environment Department (NMED). Includes sites known to the NMED where PFAS/PFOS containing material may be of concern, as well as USGS PFAS groundwater sampling locations.

Government Publication Date: Feb 4, 2025

Ground Water Discharge Permits: GW DISCHARGE

The Ground Water Pollution Prevention Section of the New Mexico Environment Department reviews and approves discharges that have the potential to impact ground water quality pursuant to Subparts III and V of the Water Quality Control Commission (WQCC) regulations (20.6.2 NMAC). Ground water discharge permits address a wide variety of discharges including domestic wastewater treatment plants, commercial septic tank leach fields, power generating plants, commercial laundries not served by sanitary sewers, dairies, food processing plants, commercial land farms for treatment of contaminated soil, industrial discharges, injection wells and ground water remediation systems. This list does not include permits for mines or agricultural facilities.

Government Publication Date: Dec 20, 2024

Southwest Research and Information Center Uranium Sites: URANIUM

This database contains information on Northwestern New Mexico uranium projects located in Navajo Country and is maintained by the Southwest Research and Information Center. This organization was founded in 1971 for the purpose of providing information to the public on the effects of energy development and resource exploitation on the people and their cultures, lands, water, and air of New Mexico and the Southwest.

Government Publication Date: Oct 18, 2006

Tribal

No Tribal additional environmental record sources available for this State.

County

No County additional environmental record sources available for this State.

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

APPENDIX I

Supplemental Records

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

October 25, 1993

J. R. Jacobs
Allsups Convenience Stores, Inc.
P. O. Box 1907
Clovis NM 88102-1907

RE: ALLSUPS #327 UST CONTAMINATION SITE,
2000 ST. MICHAEL'S, SANTA FE

Dear Mr. Jacobs:

The New Mexico Environment Department (NMED) has received driller's logs and other ground water information submitted by Billings & Associates, Inc. for the above named site. The NMED has determined that this site does not pose an immediate public health or environmental threat for the following reasons:

1. Depth to ground water is 120 feet.

2. Ground water is greater than fifty (50) feet from the depth of contamination.

3. Contamination is apparently contained on-site.

Therefore, NMED is not requiring additional work on this site at this time. However, NMED does reserve the right to require additional work in the future should information become available which indicates that a threat to public health or the environment exists.

Again, thank you for your cooperation in this matter. If you have any questions or desire further information please contact me at the letterhead address or by telephone, at (505) 827-2999.

Sincerely,

Phillis Stevens
Geological Engineer
Remedial Action Program
Underground Storage Tank Bureau

PS:mtf

e-file: 1231

cc: NMED District II Office
Daniel J. Behles, Behles and Associates
Geoffery Sloane, Esq., NMED Office of General Counsel
Ted. L. Hartley, Esq.
Jim Griswold, Billings and Associates
Anna M. Richards, Manager, Remedial Action Program

STATE OF NEW MEXICO
ENVIRONMENT DEPARTMENT

Bruce King
Governor

Judith M. Espinosa
Secretary

Ron Curry
Deputy Secretary

Harold Runnels Building
1190 St. Francis Drive
P.O. Box 26110
Santa Fe, NM 87502
(505) 827-2850
FAX (505) 827-2836

DRUG FREE

Notification for Underground Storage Tanks

OMB NO. 2050-0068
APPROVAL EXPIRES 9-30-97

UNDERGROUND STORAGE TANK BUREAU
1190 St. Francis Drive
Harold Runnels Bldg. N2164
Santa Fe, NM 87503

I.D. Number

STATE USE ONLY

Date Received

RECEIVED
SEP 28 1994

GENERAL INFORMATION

Notification is required by Federal law for all underground tanks that have been used to store regulated substances since January 1, 1974, that are in the ground as of May 8, 1986, or that are brought into use after May 8, 1986. The information requested is required by Section 9002 of the Resource Conservation and Recovery Act (RCRA), as amended.

The primary purpose of this notification program is to locate and evaluate underground tanks that store or have stored petroleum or hazardous substances. It is expected that the information you provide will be based on reasonably available records, or, in the absence of such records, your knowledge, belief, or recollection.

Who Must Notify? Section 9002 of RCRA, as amended, requires that, unless exempted, owners of underground tanks that store regulated substances must notify designated State or local agencies of the existence of their tanks. Owner means—
(a) in the case of an underground storage tank in use on November 8, 1984, or brought into use after that date, any person who owns an underground storage tank used for the storage, use, or dispensing of regulated substances, and
(b) in the case of any underground storage tank in use before November 8, 1984, but no longer in use on that date, any person who owned such tank immediately before the discontinuation of its use.

What Tanks Are Included? Underground storage tank is defined as any one or combination of tanks that (1) is used to contain an accumulation of "regulated substances," and (2) whose volume (including connected underground piping) is 10% or more beneath the ground. Some examples are underground tanks storing: 1. gasoline, used oil, or diesel fuel, and 2. industrial solvents, pesticides, herbicides or fumigants.

What Tanks Are Excluded? Tanks removed from the ground are not subject to notification. Other tanks excluded from notification are:
1. farm or residential tanks of 1,100 gallons or less capacity used for storing motor fuel for noncommercial purposes;
2. tanks used for storing heating oil for consumptive use on the premises where stored;
3. septic tanks;
4. pipeline facilities (including gathering lines) regulated under the Natural Gas Pipeline Safety Act of 1968, or the Hazardous Liquid Pipeline Safety Act of 1979, or which is an intrastate pipeline facility regulated under State laws;
5. surface impoundments, pits, ponds, or lagoons;
6. storm water or waste water collection systems;
7. flow-through process tanks;
8. liquid traps or associated gathering lines directly related to oil or gas production and gathering operations;
9. storage tanks situated in an underground area (such as a basement, cellar, mineworking, drift, shaft, or tunnel) if the storage tank is situated upon or above the surface of the floor.

What Substances Are Covered? The notification requirements apply to underground storage tanks that contain regulated substances. This includes any substance defined as hazardous in section 101 (14) of the Comprehensive Environmental Response, Compensation and Liability Act of 1980 (CERCLA), with the exception of those substances regulated as hazardous waste under Subtitle C of RCRA. It also includes petroleum, e.g., crude oil or any fraction thereof which is liquid at standard conditions of temperature and pressure (60 degrees Fahrenheit and 14.7 pounds per square inch absolute).

Where To Notify? Completed notification forms should be sent to the address given at the top of this page.

When To Notify? 1. Owners of underground storage tanks in use or that have been taken out of operation after January 1, 1974, but still in the ground, must notify by May 8, 1986. 2. Owners who bring underground storage tanks into use after May 8, 1986, must notify within 30 days of bringing the tanks into use.

Penalties: Any owner who knowingly fails to notify or submits false information shall be subject to a civil penalty not to exceed $10,000 for each tank for which notification is not given or for which false information is submitted.

INSTRUCTIONS

Please type or print in ink all items except "signature" in Section V. This form must be completed for each location containing underground storage tanks. If more than 5 tanks are owned at this location, photocopy the reverse side, and staple continuation sheets to this form.

Indicate number of continuation sheets attached

I. OWNERSHIP OF TANK(S)

Owner Name (Corporation, Individual, Public Agency, or Other Entity)
SANTA FE PARTNERS

Street Address
2005 St Michaels Dr

County
SANTA FE

City: SANTA FE | State: NM | ZIP Code: 87501

Area Code: 505 | Phone Number: 983-7337

Type of Owner (Mark all that apply ☒)
☒ Current ☐ Former ☐ State or Local Gov't ☐ Federal Gov't (GSA facility I.D. no. _____) ☒ Private or Corporate ☐ Ownership uncertain

II. LOCATION OF TANK(S)

(If same as Section I, mark box here ☒)

Facility Name or Company Site Identifier, as applicable

Street Address or State Road, as applicable

County

City (nearest) | State | ZIP Code

Indicate number of tanks at this location: 6

Mark box here if tank(s) are located on land within an Indian reservation or on other Indian trust lands ☐

III. CONTACT PERSON AT TANK LOCATION

Name (If same as Section I, mark box here ☐) | Job Title | Area Code | Phone Number
ROBERT L. TOBIN | SERVICE MANAGER | 505 | 983-7337

IV. TYPE OF NOTIFICATION

☐ Mark box here only if this is an amended or subsequent notification for this location.

V. CERTIFICATION (Read and sign after completing Section VI.)

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete.

Name and official title of owner or owner's authorized representative | Signature | Date Signed
[signature] | ROBERT L TOBIN | 9/20/94

2005

Owner Name (from Section I) SFE PARTNERS Location (from Section II) 50 - 54 Mike Page No. 1 of 1 Pages

VI. DESCRIPTION OF UNDERGROUND STORAGE TANKS (Complete for each tank at this location.)

Tank Identification No. (e.g., ABC-123), or Arbitrarily Assigned Sequential Number (e.g., 1,2,3...)		Tank No. 1	Tank No.	Tank No.	Tank No.	Tank No.
1. Status of Tank (Mark all that apply ☒)	Currently in Use	☐	☐	☐	☐	☐
	Temporarily Out of Use	☐	☐	☐	☐	☐
	Permanently Out of Use	☒	☐	☐	☐	☐
	Brought into Use after 5/8/86	☐	☐	☐	☐	☐
2. Estimated Age (Years)		21				
3. Estimated Total Capacity (Gallons)		560				
4. Material of Construction (Mark one ☒)	Steel	☒	☐	☐	☐	☐
	Concrete	☐	☐	☐	☐	☐
	Fiberglass Reinforced Plastic	☐	☐	☐	☐	☐
	Unknown	☐	☐	☐	☐	☐
	Other, Please Specify					
5. Internal Protection (Mark all that apply ☒)	Cathodic Protection	☐	☐	☐	☐	☐
	Interior Lining (e.g., epoxy resins)	☐	☐	☐	☐	☐
	None	☒	☐	☐	☐	☐
	Unknown	☐	☐	☐	☐	☐
	Other, Please Specify					
6. External Protection (Mark all that apply ☒)	Cathodic Protection	☐	☐	☐	☐	☐
	Painted (e.g., asphaltic)	☐	☐	☐	☐	☐
	Fiberglass Reinforced Plastic Coated	☐	☐	☐	☐	☐
	None	☒	☐	☐	☐	☐
	Unknown	☐	☐	☐	☐	☐
	Other, Please Specify					
7. Piping (Mark all that apply ☒)	Bare Steel	☒	☐	☐	☐	☐
	Galvanized Steel	☐	☐	☐	☐	☐
	Fiberglass Reinforced Plastic	☐	☐	☐	☐	☐
	Cathodically Protected	☐	☐	☐	☐	☐
	Unknown	☐	☐	☐	☐	☐
	Other, Please Specify					
8. Substance Currently or Last Stored in Greatest Quantity by Volume (Mark all that apply ☒)	a. Empty	☐	☐	☐	☐	☐
	b. Petroleum					
	Diesel	☐	☐	☐	☐	☐
	Kerosene	☐	☐	☐	☐	☐
	Gasoline (including alcohol blends)	☐	☐	☐	☐	☐
	Used Oil	☒	☐	☐	☐	☐
	Other, Please Specify					
	c. Hazardous Substance	☐	☐	☐	☐	☐
	Please Indicate Name of Principal CERCLA Substance					
	OR					
	Chemical Abstract Service (CAS) No.					
	Mark box ☒ if tank stores a mixture of substances	☐	☐	☐	☐	☐
	d. Unknown	☐	☐	☐	☐	☐
9. Additional Information (for tanks permanently taken out of service)	a. Estimated date last used (mo/yr)	7-29 94	1	1	1	1
	b. Estimated quantity of substance remaining (gal.)	0				
	c. Mark box ☒ if tank was filled with inert material (e.g., sand, concrete)	☐	☐	☐	☐	☐

TANK CLOSURE WORKSHEET
(COMPLETE & RETURN TO UST BUREAU AFTER CLOSURE)

Tank Owner SANTA FE PARTNERS Phone # 983-7337
Mailing Address 7005 St Michaels Dr - SF. NM
Tank Address Same
Contractor Name Rite Phil Phone # 867-1629
Address P.O Box 720 Penalta NM 87047
Tank Closure Date 7-20/94 Content of Tank(s) WASTE oil
Size of Tank(s) 560
# of Tank(s) Closed 1

****

I. Tank Closure Initial Procedures (check measures complied with):

- ✓ Obtain recommended safety equipment for all personnel
- ___ Contact Fire Marshall or other fire official(s)
- ✓ Bond or ground equipment
- ✓ Drain product from piping & tank
- ✓ Disconnect, then cap or remove piping
- ✓ Remove all residual product from tank
- ✓ Excavate to tank top
- ✓ Remove all tank fixtures
- ✓ Properly purge or inert tank of all flammable vapors using approved method
- ___ Continually monitor for explosive vapors while tank is being removed

II. Tank Removal

- ✓ Create vent hole
- ✓ Excavate tank using all safety precautions
- ✓ Clean and inspect tank
- ✓ Check excavation for evidence of leaks & notify EID (within 24 hours) and other proper authorities if leak is found
- ✓ Check vapor levels in tank before transporting
- ✓ Dispose of tank in approved manner

Tank disposal location R-A-C Yard
City State
How did you assess site for leakage? SOIL SAMPLES TO LAB
Closure report kept at SANTA FE NM 87501, ENVIR DEPT
NOTE: Immediately report any evidence of leakage to EID at 827-0397

The New Mexico Environmental Improvement Division (EID) does not grant a release from liability by this form. EID does reserve the right to require remediation of soils and groundwater at this site in the future if evidence is revealed which indicates that contamination of soils and groundwater was caused by this site.

I hereby state that the above information is correct

7-20-94
Signature of owner or contractor performing work

FOR EID USE ONLY
Notification Received 7-20-94 Approved By
Inspection Date 7-20-94 Inspector

End. 8394 DW

NM Environment Department
Underground Storage Tank Bureau
Prevention/Inspection Section
P.O. Box 26110
Santa Fe, New Mexico 87502-6110
(505) 827-0216

INSPECTION REPORT


DATE	CASE NUMBER	OPENING CONFERENCE TIME
7-20-94	032	2 PM

INSPECTION TYPE: ☐ COMPLIANCE ☐ REINSPECTION ☐ ~~TANK~~ CLOSURE ☐ INSTALLATION ☐ REPAIR ☐ COMPLAINT ☐ MODIFICATION

Facility Name 1. SANTA FE ~~NISSAN~~ PARTNERS	Facility No. 5594001	Phone No. 983-7337
Address 2005 St. Michaels Drive	SANTA FE, NM 87501	ZIP Code
Owner Name 2. SANTA FE ~~NISSAN~~ PARTNERS	Owner No. 5594	Phone No.
Address 2005 St Michaels Drive	SANTA FE - NM 87501	ZIP Code
Facility Operator 3. SAMS #1 Bob Tobin ~~Service~~ Mgr		Phone No.
Address		ZIP Code
Contractor Name 4. RHC - Phil PRATT	Installer No.	Phone No. (505) 869-6686
Address PO Box 720	PERALTA NM 87042	ZIP Code

TANK NO.	SIZE	CONTENTS	INSTALLATION DATE	TANK CONSTRUCTION	PIPING CONSTRUCTION	TANK RELEASE DETECTION	PIPING RELEASE DETECTION	TANK STATUS
1	560	WASTE OIL	11-73	STEEL	STEEL	NO	NO	REMOVED

SITE MAP



DISTRIBUTION: **WHITE** - Owner **CANARY** - Operator **PINK** - USTB **GOLDENROD** - Compliance Officer

SF NISSAN

New Mexico Underground Storage Tank Bureau **INSPECTION REPORT**

		Yes	No	Unk.	N/A
1. All applicable tanks on site are registered.	1.	X			
2. Proper notification was made for the following:	2.				
a. Closure	a.	X			
b. Installation	b.				X
c. Modification	c.				X
d. Repair	d.				X
3. Tanks closed properly.	3.	X			
4. Tanks installed properly.	4.				X
5. Tanks repaired/modified properly.	5.				X
6. Release detection — tanks.	6.				X
7. Release detection — piping.	7.				X
8. Record keeping:	8.				
a. Cathodic protection monitoring.	a.				X
b. Impressed current monitoring.	b.				X
c. Tank tightness test.	c.				X
d. Line tightness test.	d.				X
e. Line leak detector test.	e.				X
f. Release detection performance claims, tests.	f.				X
g. Release detection sampling/testing results.	g.				X
h. Inventory records. Weekly Emptied on Thursdays	h.				
i. Permanent closure records.	i.	X			
j. Proof of financial responsibility.	j.				X
9. Evidence of release/spill. None Noted - LAB SAMPLE to be TAKEN	9.		X		

COMMENTS: 7-20-94 TANK Pull For used/waste oil. Bottom of tank Appears Sound. Top of tank has 3 holes Near Vent. Photo taken. TANK, Venting & misc piping Removed AST 285 gal Kolhaas tank to be installed per Fire Marshall direction, using Same inside piping w/ new pump system - According to Bob Tabit, Service Manager.

LAB Sample to be taken - (under tank center 1½ below tank area.

Existing tank was emptied on Wkly basis - Estimate 30 oil change/wk. (≈ 120-140 qts)

CLOSING CONFERENCE:	DATE 7-20-94	TIME 2:15 PM
Compliance Officer's Signature	Date	
M Pearsall	7-20-94	

On-site Representative's Signature — Date 7/20/94

DISTRIBUTION: **WHITE** - Owner **CANARY** - Operator **PINK** - USTB **GOLDENROD** - Compliance Officer

State of New Mexico
ENVIRONMENT DEPARTMENT
Petroleum Storage Tank Bureau
2044 Galisteo Street
Santa Fe, New Mexico 87504
Telephone (505) 984-1741
Fax (505) 984-1738
www.nmenv.state.nm.us

BILL RICHARDSON
Governor

RON CURRY
Secretary

June 16, 2003

Mr. Jeff Scarbrough
Allsups Petroleum Inc.
P.O. Box 1907
Clovis, New Mexico 88102

RE: No Further Action Status at Allsups #252, 2007 Calle Lorca, Santa Fe, New Mexico

Facility #: 13818013/26511 SID #: 2526

Dear Mr. Scarbrough:

The New Mexico Environment Department (Department) has reviewed the following for the subject site:

1. Minimum Site Assessment dated January 29, 1999.
2. Phase I Hydrogeologic Investigation Report dated February 7, 2000.
3. Groundwater Sampling Event dated April 9, 2002.
4. First Quarterly Monitoring Report dated November 8, 2002.
5. Groundwater Sampling Event dated January 30, 2003.
6. Well Abandonment Report dated May 1, 2003.

The Department concurs that this site does not pose an immediate threat to public health or the environment based upon the following current site-specific conditions:

1. Depth to groundwater at the site is unknown. A monitoring well completed at 220 feet below ground surface did not produce any water.
2. Sediments at the site consist of silts, sands and gravels.
3. A total of five (5) soil borings were advanced on-site and three (3) soil borings were advanced off-site. The soil borings were advanced to depths of 92 - 112 feet below ground surface.
4. Soil contamination was noted in soil boring 1/monitor well 1 (SB 1/MW 1) to a depth of approximately 105 feet below ground surface. This SB/MW was located in the old tank pit. Other soil borings advanced on and off site indicate no soil contamination.
5. Three attempts were made to gather a groundwater sample from MW-1 but no groundwater was present in enough quantity to gather a sample. Water found in the monitor well may have been condensation.
6. The monitoring well was plugged and abandoned according to PSTB Guidelines on April 28, 2003.
7. Soil contamination is noted at the site in the old tank pit and extends to a depth of approximately 105 feet below ground surface. No groundwater was encountered at a depth of 220 feet below ground surface. The St. Michaels public supply well is located approximately 100 yards to the west of the site and has a reported depth to groundwater of approximately 400 feet below ground surface.

Therefore, the Department is not requiring additional work at this time. However, the Department does reserve the right to require additional work in the future, should information become available which indicates that a threat to public health or the environment exists.

If you have any questions, please contact me at (505) 984-1941. Thank you for your cooperation in this matter.

Sincerely,

Lorena Goerger
Geologist
Petroleum Storage Tank Bureau

LG:mmr

cc: John Bunch, RESPEC Inc.
Joyce Shearer, Manager, PSTB Remedial Action Program
Joyce R. Croker, EPD Office of Finance and Budget
John Kovacs, Natural Sciences Manager, PSTB
Joseph Romero, Prevention/Inspection Program, PSTB
Courte Voorhees, Manager, NMED District II

APPENDIX J

Photographic Log



Photograph 1. Photo showing Union washing machine inside the facility.



Photograph 2. Photo showing machinery inside the facility.



Photograph 3. Photo showing machinery inside the facility.



Photograph 4. Photo showing view of facility interior.



Photograph 5. Photo showing machinery inside the facility.



Photograph 6. Photo showing washing machine inside the facility.



Photograph 7. Photo showing view of facility interior.



Photograph 8. Photo showing machinery inside the facility.



Photograph 9. Photo showing machinery and tank inside the facility.



Photograph 10. Photo showing water heater inside the facility.



Photograph 11. Photo showing water on floor in water heater room inside the facility.



Photograph 12. Photo showing piping and water on floor in water heater room.



Photograph 13. Photo showing drum of Seitz Intense PCE-free solvent at the facility.



Photograph 14. Photo showing drum of waste solvent with locking ring lid outside facility.



Photograph 15. Photo showing tanks outside of the facility.



Photograph 16. Photo showing tank outside of facility.



Photograph 17. Photo showing view of the east adjoining property, Fiesta Hyundai.



Photograph 18. Photo showing view of stormwater drainage culvert along the eastern Subject Property boundary.



Photograph 19. Photo showing view facing northwest from northeast corner of the Subject Property.



Photograph 20. Photo showing view facing northeast towards St Michaels Drive from the northeast corner of the Subject Property.



Photograph 21. Photo showing view facing southeast towards St Michaels Drive from northeast corner of the Subject Property.



Photograph 22. Photo showing view facing southwest from the northeast corner of the Subject Property.



Photograph 23. Photo showing view of the main entrance to the primary Site building, facing west.



Photograph 24. Photo showing view of the entrance of the Subject Property, facing northwest.



Photograph 25. Photo showing view facing southwest towards the west adjoining property.



Photograph 26. Photo showing another commercial suite located on the Subject Property.



Photograph 27. Photo showing an additional commercial suite located on the Subject Property which is immediately west of the suite shown in Photograph 26.



Photograph 28. Photo showing the three westernmost commercial suites located on the Subject Property.



Photograph 29. Photo showing the hot tub store currently occupying the western adjoining property with the parking lot which forms the southwestern interior of the Subject Property visible in the foreground of the photo.



Photograph 30. Photo showing the bay doors located along the western exterior of the primary Site building in northwest corner of the Subject Property, facing northeast.



Photograph 31. Photo showing the western exterior wall of the Subject Property building, facing south with the perimeter fence visible in the left of the photo.



Photograph 32. Photo showing tanks and machinery along the western wall of the Subject Property building.



Photograph 33. Photo showing gas meters along the western wall of the Subject Property building.



Photograph 34. Photo showing the commercial suite located immediately south of New Method Cleaners which is currently occupied by Subway.



Photograph 35. Photo showing the parking lot forming the south-central portion of Subject Property, view facing south-southeast.



Photograph 36. Additional photo showing the parking lot forming the south-central portion of Subject Property, view facing southwest.



Photograph 37. View of the eastern Subject Property boundary with the municipal sidewalk forming the frontage along St. Michaels Drive.



Photograph 38. View of the overhead electrical lines along the eastern Subject Property boundary.



Photograph 39. View of Saint Michaels Drive taken from the median east of the Subject Property facing west with Fiesta Hyundai cars visible in the right of the photograph.



Photograph 40. View of the vacant lot forming the easternmost portion of the south adjoining property. View facing southwest.



Photograph 41. Additional view of the vacant lot facing south.



Photograph 42. View of the Bank of America building on the south adjoining property, view facing southwest.



Photograph 43. View of the Subject Property taken from the southern edge of Saint Michaels Drive facing west.



Photograph 44. View of the intersection of Saint Michaels Drive and 5th Street south of the Subject Property. Photo taken from the southeastern corner of the intersection facing northwest.



Photograph 45. View of the Sherwin-Williams Paints Store located at 1905 Saint Michaels Drive, south of the Subject Property.



Photograph 46. View of the south adjoining property facing northwest from the southwestern corner of the property.

APPENDIX K

Interviews

1140 - P. Gutierrez & A. Murphy on site @ Lopez Cleaners
↳ 57°F/Sunny

Objectives - Complete site recon/access for five former dry cleaner sites in SF w/ one site ~~access~~ recon @ New Method Dry Cleaner.

1143 - TGSM complete, take photos & begin

838 E Palace Ave / Lopez Cleaners
- Residential w/ 2nd structure in rear
- E adjoining = Palace Grocery (853-A E Palace)
- Left ltr/access package in entryway gate after knocking w/ no answer
- All other props = residential

1150 - Depart for 622 Canyon Rd.

1154 - @ 622 Canyon Rd / Universal Cleaners
- Access not granted, photos from dirt rd/alley way
- W adjoining = 622 residence
- N adjoining = 626 w/ const. permit displayed for addition
- S adjoining = residential through alley
- E adjoing = 630 Canyon Olive Rush Studios Art Center

1205 - Depart for 105 E. Water St.

1215 - @ E. Water St. / New Method DC
- Josh owner of business w/ other partners
- Café Pasquel's Gallery = N adjoining
- Municipal PK Lot = S adj

E Water St. / New Method DC
- E adj = The Chile Shop
- W adj = Tonic cocktails / Jazz Cafe
- Per Josh Robert Spitz of the Spitz Brothers owns the bldg, but he's in his 80s & uses prop mgmt co.
- If DC on site, likely 1970s
- He'll pass paperwork on

1236 - Depart for 328 E Sandoval

1240 @ 328 E Sandoval / Master Cleaners Sandoval
- Spoke w/ Greg & prop owners still in AZ for winters
- Drop off ltr/access packet for him to pass on
- 330 = S adj / physically contiguous SF Biscochito Co.
- N adj (across Aztec) = Rainbow Gate (home goods)
- E adj = SF Judical Complex
- W adj = residential / single family 310 Aztec

1251 - Depart for 1406 2nd St.

1302 @ 1406 2nd St. / Danny's Cleaners
- Gave paperwk to Auto sales employee she'll pass to prop owner
- N adj = residental on N side 2nd St.
- E adj = SF Self Storage
- S adj = Dunn Edwards Paints
- W adj = All Tangled Up Salon

1307 - Depart 2nd St.
↳ @ 2nd St. to meet owner

1340 - 1956 Mova dug foundation. Dry cleaning fence & E. Used petroleum based cleaner. Waste hauler ABQ 1958 to 25 years ago. Sold all eqp (boilers, etc). No UST & ~~drums~~ 100 gal tank to sewer

AM


2nd st. Would fill. In gd H_2O drains. No PCE/TCE in solvents? Said shut down before "envt'l ppl". Commercial rentals since closed Accupunture, skin treatments, etc. Brother & sister own W adj. Hist. cleaner on Palace Ave closed 50 yrs ago. Walked interior w/ tenant - std bi room & H_2O heater

1412 - @ 1911 St. Mike's/New Method DC

- Bob ortega's 90 yr old mother owns the property & Lawerence Romero is tenant running business
- Romero took over business ~2000 & removed PERC machine & is on 3rd set of machinery currently
- Manufacturer = Union
- Solvent = Seitz Intense (see photo)
- Muck from unit hauled off 2x month by ABQ operator. Drum w/ lock ring outside. Evaporated ultimately
- Machine has fan, H_2O sep, still, & pumps
- 15 HP boiler (recently re-piped) in rear powers machines
- Air comp for small pneumatics on vacs for presses
- 8 yrs ago? sampling done along N prop boundary w "hoses out of ground" from spill next door Hyundai?
- vac system overhead for lint collection
- ortega owns entire strip mall & 5 unit tenant commercial prop.

1450 - Call w/ M. Hubbard (PM) re: status of all site visits. Head offsite.

Summary - Dropped 2nd copy of access agreement paperwork w/ tenants @ Water St & Sandoval sites to be delievered to prop. owners. E Palace Ave left paperwork in entryway gate. Photos taken @ 622 Canyon Rd. & 2nd St & St Mike's sites walked/met w/ owners & tenants.



APPENDIX L

Qualifications of Environmental Professionals



Matt Hubbard
Senior Environmental Scientist

Years of Experience: 14

Education:

- BS, Environmental Science, University of Texas at Austin

Professional Registrations/Affiliations:

- TCEQ Leaking Petroleum Storage Tank (LPST) Project Manager, License No. PM0000720, 2022

Professional History:

2026 – Present	Senior Environmental Scientist – INTERA Incorporated, Austin, TX
2018 – 2025	Environmental Scientist – INTERA Incorporated, Austin, TX
2017 – 2018	Environmental Specialist – City of Austin, Development Services Department, Austin, TX
2013 – 2017	Project Manager / Engineering and Corrective Action Specialist – Texas Commission on Environmental Quality, Remediation Division, Superfund Section, Austin, TX
2012 – 2013	Work Lead / Licensed Electrician – Wells Solar and Electrical Services, Austin, TX
2012	Field Research Assistant – University of Texas, Austin, TX

Training:

- MSHA Part 48 Surface New Miner Training, 2019-2023
- 40-Hour General Site Workers Training, OSHA 29 CFR 1910.120(e)(3), 2013
- 8-Hour Refresher, OSHA 29 CFR 1910.120, 2013 – 2025
- Hydrogen Sulfide (H2S) Training, 2018
- CPR, First Aid, and Bloodborne Pathogens Training, 29 CFR 1910.1030, 2024
- ArcGIS Pro, WinSitu, Strater®, Grapher™, Surfer®, PLog, LogPlot
- Land Science® Certified Vapor Barrier Inspector, 2020

Matt Hubbard is a Senior Environmental Scientist at INTERA with a BS degree in environmental science and 14 years of experience investigating and remediating contaminated sites. He serves in several capacities including Project Manager, Technical Lead, Field Lead, and Health and Safety Lead. Matt develops and implements highly technical work plans for complex technical projects and provides subject matter expertise to clients and senior leadership. His project experience includes state and federal Superfund, Brownfields, voluntary cleanup program (VCP), petroleum storage tank (PST), Phase I and Phase II Environmental Site Assessment (ESA), and imminent threat/removal assessments. Matt is an expert in field methods including sampling of surface and subsurface environmental media, field screening techniques, environmental drilling, and well construction. He has worked on contaminated sites associated with metals including hexavalent chromium, petroleum hydrocarbons, chlorinated solvents, polychlorinated biphenyls (PCBs), organochlorine and organophosphorus compounds (pesticides and herbicides), dioxins/furans, and per- and polyfluoroalkyl substances (PFAS). Matt has significant experience designing assessments and implementing innovative methods, including incremental sampling methodology (ISM), field portable x-ray fluorescence (XRF), passive soil gas (PSG), ground-penetrating radar (GPR), and electromagnetic mapping. He is also experienced in water resources development, including oversight and support of production well drilling and installation, aquifer performance analysis, dynamic flow profiling, and mass balance chemical analysis.

Project Experience – Environmental

ChemFab Phase I Environmental Site Assessment, ChemFab, LLC., Clute, TX. 2026. *Project Manager.* Conducted a Phase I ESA for a fabrication facility and an adjoining property in accordance with ASTM Standard Practice E1527-21.

Southside Storage Phase I Environmental Site Assessments, Southside Wrecker, Inc., Austin, TX. 2025 – 2026. *Project Manager.* Conducted two Phase I ESAs: one at a vacant property that was previously a sand and gravel mine and subsequently filled via unpermitted landfilling operations and another at an automotive repair and maintenance facility. The Phase I ESAs were conducted in accordance with ASTM Standard Practice E1527-21.

Hornsby Bend Biosolids Management Plant, City of Austin Water, TX. 2023 – 2026. *Project Manager.* Coordinated and led quarterly groundwater monitoring and annual soil sampling in support of the requirements of the Texas Commission on Environmental Quality (TCEQ) permit to process wastewater treatment plant sewer sludge, land apply wastewater treatment plant sewage sludge, and irrigate lagoon supernatant under provisions of Chapter 26 of the Texas Water Code, Chapter 361.121 of the Texas Health and Safety Code, and Chapter 312 of the Texas Administrative Code. Conducted independent data usability review for each quarterly groundwater event. Prepared quarterly updates to groundwater potentiometric elevation maps.

Prepared annual report for submittal to the TCEQ. Performed supplemental historical data review and assessment in support of additional reporting requested by special provision of the 2025 permit renewal and was the primary author of the supplemental report.

Jensen Drive Scrap State Superfund Site, 3603 Jensen Drive LLC, Harris County, TX. 2018 – 2026. *Environmental Scientist and Field Lead.* Drafted Annual Post Closure Care Report and Data Usability Summary for annual 2018, 2019, 2020, and 2025 site activities, which included groundwater monitoring, potentiometric mapping, and engineer's inspection of the site waste containment unit. Coordinated and conducted 2019, 2020, and 2025 groundwater monitoring events, including low-flow sampling for PCBs.

BAE TRACOR Phase I and Phase II Environmental Site Assessment, City of Austin Brownfields, TX. 2025. *Project Manager.* Conducted a Phase I ESA for the City of Austin (COA) Brownfields Program in accordance with ASTM Standard Practice E1527-21. The approximately 140-acre facility had 12 permanent structures and was formerly used for military research and development. Coordinated all aspects of project work to meet the City's expedited timeline within the 120-day due diligence period. Developed the rationale and scope of the Phase II ESA and designed the sampling plan. Soil and groundwater investigation included the installation of soil borings and monitor wells for sampling and analysis of soil and groundwater for contaminants including PFAS and nitroaromatics and nitramines. Directed the INTERA team and subcontractors for the multi-phased progressive tasks in support of the overall objective and made necessary and defensible modifications to the plan, as needed, to meet budget and scheduling restraints. Authored the Phase II ESA and provided support to the COA during negotiations leading up to and culminating with the acquisition of the property.

411 Chicon, City of Austin Brownfields, TX. 2024 – 2025. *Project Manager.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice E1527-21. Oversaw a geophysical survey of the subsurface and an exploratory investigation to determine the presence or absence of underground storage tanks.

Former Travis County Landfill, Moo Moo Meadows, LLC., Austin, TX. 2024 – 2025. *Project Manager.* Reviewed available data to determine groundwater conditions and assess landfill permittee's responsibilities for management. Provided expert environmental support in a contested dispute for site development under 30 Texas Administrative Code (TAC) 330 Subchapter T – Use of Land Over Closed Municipal Solid Waste Landfills.

Austin Bergstrom International Airport Augmented Staff, City of Austin Aviation Department, TX. 2023 – 2025. *Environmental Scientist and Field Lead.* Provided as-needed consulting and field assistance in support of ongoing development at Austin Bergstrom International Airport. Conducted liquid and solid waste sampling for disposal and consulting for the remediation of bulk PFAS chemical and PFAS-containing water in emergency response vehicles. Provided oversight and project coordination for PFAS-contaminated stockpile relocation, monitor well drilling and installation, and soil and groundwater sampling for PFAS.

In-Situ Anaerobic Bioremediation Pilot Study, Chemical Waste Management, Corpus Christi, TX. 2024. *Environmental Scientist.* Conducted baseline groundwater monitoring in support of the pilot study that was performed to evaluate in-situ anaerobic bioremediation as a remedial method groundwater contamination.

Pollution Prevention Plan, Precise Hard Chrome, LLC., Waco, TX. 2024. *Environmental Scientist.* Authored the five-year Pollution Prevention Plan for the Precise Hard Chrome facility in Waco, Texas in accordance with 30 TAC Chapter 335, Subchapter Q (*Pollution Prevention: Source Reduction and Waste Management*). The plan identified all activities that generated hazardous waste or resulted in a release of Toxic Release Inventory reportable chemicals and a prioritized list of economically and technologically feasible source reduction and waste minimization projects.

Peaceful Hill, Graham Development, Austin, TX. 2024. *Project Manager.* Assessed the regulatory framework for proposed stormwater injection to aquifer recharge wells on a commercial development (Class V Injection Well). The assessment included siting and hydrogeologic analysis and provided recommendations for additional investigation in support of implementation.

Rio Grande Coop Phase I Environmental Site Assessment, City of Austin Brownfields, TX. 2024. *Project Manager.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice E1527-21.

Anita Ferrales Coy Phase I Environmental Site Assessment and Asbestos/Lead Survey, City of Austin Brownfields, TX. 2024. *Project Manager.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice

E1527-21. Facilitated asbestos containing material and lead-containing paint survey and preparation of project remediation specifications.

McAlpine Lease Third Party Release Assessment Review, E&W Law, Stanton, TX. 2024. *Environmental Scientist and Data Reviewer.* Conducted data usability review of laboratory analytical results and senior review of the assessment review report for a crude oil and produced water release. Evaluated data relative to Railroad Commission of Texas (RRC) guidance.

Town Lake Metro Park Youth Hostel Phase I Environmental Site Assessment, City of Austin Parks and Recreation Department, TX. 2024. *Environmental Scientist.* Conducted a Phase I ESA in accordance with ASTM Standard Practice E1527-21 in support of planned redevelopment.

Environmental Impacts Assessment, Cooks Branch Conservancy, Montgomery, TX. 2024. *Environmental Scientist.* Oversaw drilling and installation of three monitoring wells. Lithologically logged each well in accordance with ASTM D2488-17e1 and Unified Soil Classification System (USCS). Conducted groundwater and surface water sampling and assessment for a range of analytes to determine impacts from a nearby mining operation. Provided technical support and senior review of data and deliverables.

Geotechnical Investigation for a Potential Compost Facility, Confidential Client, TX. 2024. *Environmental Scientist.* To determine a proposed site's suitability for TCEQ permitting of a compost facility, conducted a subsurface investigation focused on identifying shallow, low permeability clays suitable for use as an in-situ clay liner. Installed and lithologically logged 12 soil borings using the USCS. Collected soil samples from each boring at low permeability clay intervals based on field observations. Sent select samples to a geotechnical laboratory for analysis.

North Railroad Avenue Plume Superfund Site, New Mexico Environment Department, Española, NM. 2024. *Environmental Scientist and Field Lead.* Served as field lead for roto-sonic drilling and installation of a monitoring well in support of an New Mexico Environmental Department (NMED)-led cleanup at a former drycleaner site contaminated with tetrachloroethene (PCE) and its degradation products. Logged continuous core (ASTM D2488-17e1 / USCS) to 257 feet below ground surface (bgs), screened heated headspace soil samples with a photoionization detector, collected push-ahead groundwater samples at discrete depth intervals during drilling, and oversaw analysis of push-ahead groundwater samples via a FROG-5000 portable gas chromatograph. Identified the target hydrostratigraphic unit and informed the selection of the well screen interval. Assisted in work plan creation and annual reporting including software-based boring logs and potentiometric surface elevation mapping.

Per- and Polyfluorinated Substances Risk Assessment, California American Water, Duarte, CA. 2023 – 2024. *Environmental Scientist.* Assisted in the development of custom-built vadose-zone PFAS analytical solution tool to assess the vulnerability of existing and potential well sites to contamination. Identified potential contamination sources by evaluating records on former and current regulated facilities with current or former operations known to be or commonly associated with the use of PFAS. This information was used together with the spatial vulnerability analysis to assess the relative risk of PFAS contamination to existing and potential well sites. The analysis was used to develop recommendations for engineering and operational measures to mitigate the risk and impacts of future contamination. Measures could include changes in operation of existing wells, treatment, or replacement of wells that have reached the end of their service life. Prioritized recommendations for investigation and test drilling at new well sites based on operational benefits, cost, and risk of current or future contamination. The environmental data gathered for the study was provided for future use in permitting selected well sites.

JV DIRT, American AllWaste, Austin, TX. 2023 – 2024. *Environmental Scientist.* Conducted video well survey with a downhole camera. Conducted groundwater sampling. Prepared an update and revision to the site geologic/hydrogeologic report and groundwater protection plan in support of a permit renewal application for composting activities.

Remedial Investigation at Scrub-A-Dubb Barrel Company Site, Texas Commission on Environmental Quality, Lubbock, TX. 2020 – 2024. *Environmental Scientist.* Designed and conducted a remedial investigation, which was a targeted surface soil assessment in compliance with the site-specific field sampling plan (FSP) and the quality assurance program plan developed for the former drum recycling site utilizing ISM for the TCEQ Superfund Section. The primary contaminants of concern included volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), and metals. Used direct-push methodology to collect over 700 soil increments (aliquots) to generate data to assess soils down to five feet bgs for the entirety of the five-acre site during one field mobilization. Collected replicate data to determine statistically if data generated for each ISM decision unit (DU) were representative and defensible. The field activity report was finalized and approved by the TCEQ in March 2022.

Data evaluation confirmed the success of the ISM approach. Authored an affected property assessment report for the TCEQ Remediation Division, compiling data from assessment over an approximately five-year span including soil, sediment, and groundwater.

Voluntary Cleanup Program Post-Response Assistance, Ice Man, Inc., Belton, TX. 2023. *Environmental Scientist.* Conducted on-site review and documentation of the condition of the side slope of an engineering control cap constructed and the adjacent creek bank at a TCEQ VCP site as part of the required post-response care actions. Prepared a memorandum describing the observations made and recommended future actions.

St. Johns Redevelopment Site, City of Austin Economic Development Department via the Austin Brownfield Revitalization Office, TX. 2023. *Project Manager.* Designed and implemented a Limited Phase II ESA for the assessment of a former industrial facility and TCEQ Leaking Petroleum Storage Tank site for planned redevelopment as residential multifamily affordable housing. The assessment included (1) third-party review and assessment of previous site investigation data to identify potential data gaps and areas of concern relative to potential contaminant impacts and (2) soil gas sampling and assessment to assess the potential vapor exposure risk to occupants of future site buildings. Installed a grid of 31 passive soil gas sampling devices over the former site operations area and assessed the laboratory analytical results after a 14-day uptake period, compared to United States Environmental Protection Agency (EPA) Vapor Intrusion Screening Levels. Prepared report documenting the assessment and recommended future actions and guidelines for the Austin Economic Development Department's agreement with the site developer.

Fairfield Lake State Park Environmental Assessment, Texas Parks and Wildlife Department, Freestone County, TX. 2023. *Environmental Scientist.* Provided technical support in discussions with client regarding conduct of Phase I and Phase II ESAs in aid of State of Texas eminent domain condemnation procedures for approximately 5,000 acres, including Fairfield Lake and the immediate surrounding property that was formerly designated as Fairfield Lake State Park. Of specific concern was possible impacts to surface water, sediments, and aquatic life from heavy metals and PCBs related to a former coal-fired power plant located along the northern end of the property. Conducted the site reconnaissance and prepared the Phase I ESA (ASTM Standard E1527-21), which identified several Recognized Environmental Conditions (RECs); however, additional work to address the RECs was halted when Texas Parks and Wildlife Department decided to end condemnation procedures.

Langford Elementary Phase I Environmental Site Assessment, City of Ausitn Brownfields Program, TX. 2023. *Environmental Scientist.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice E1527-21.

Whisper Valley, City of Austin Brownfields Program, TX. 2023. *Environmental Scientist.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice E1527-21.

Emergency Response Waste Sampling at the Mexican American Cultural Center, City of Austin, TX. 2023. *Environmental Scientist.* Conducted emergency sampling of uncovered landfill waste material during the redevelopment of the Mexican American Cultural Center in downtown Austin, Texas.

Limited Phase II Environmental Site Assessment, American AllWaste, Lake Charles, LA. 2023. *Environmental Scientist.* Developed and sampled groundwater for VOCs, SVOCs, metals, petroleum hydrocarbons, pesticides, herbicides, PCBs, and PFAS. Prepared the report documenting the analytical results including a data usability summary. Provided recommendations for additional assessment based on the client's proposed property transaction.

Austin Nature Science Center Outpost, Soil Assessment, City of Austin Parks Department, TX. 2022 – 2023. *Environmental Scientist.* Performed soil assessment to delineate polycyclic aromatic hydrocarbons and heavy metals to Texas Risk Reduction Program (TRRP) Tier 1 Residential Total-soil-combined protective concentrations levels (PCLs) related to former skeet and firing range operations. This work was conducted in support of the implementation of a forthcoming removal action to restore the site to residential standards. Sampling approaches included ISM and ex-situ XRF methods. Authored the work plan and assessment report for this project.

Limited Phase II Environmental Site Assessment for Shield Park, Texas Commission on Environmental Quality Brownfields Program, Galveston, TX. 2022 – 2023. *Project Manager*. Oversaw completion of a geophysical survey implementing GPR and electromagnetic mapping to assess the presence of suspected underground storage tanks (USTs). Provided technical review and implemented TCEQ's soil assessment strategy including installing, screening, and sampling 20 soil borings. Logged each

boring according to the USCS. Prepared the Limited Phase II ESA report documenting site activities and analytical results for VOCs, SVOCs, metals, PCBs, and total petroleum hydrocarbons (TPH). Conducted technical data review and usability assessment and prepared a memorandum in accordance with the TCEQ Quality Assurance Project Plan and applicable EPA guidance.

Limited Phase II Environmental Site Assessment for Hargrave Fleet Services Property, City of Austin Brownfields Program, TX. 2022 – 2023. *Environmental Scientist.* The scope of the Phase II ESA included a full asbestos and lead-containing paint inspection survey, soil gas, surface soil, and groundwater assessment. Contaminants of concern included heavy metals, VOCs, SVOCs, dioxins/furans, and PFAS. Authored the work plan and led the field event to install passive soil gas sampling devices, groundwater monitoring wells, and soil borings. Categorized the groundwater in the shallow groundwater bearing in accordance with TRRP guidelines.

Phase I and II Environmental Site Assessment, Foundation Communities Brownfields Redevelopment Project - Airport Boulevard, Austin, TX. 2022. *Environmental Scientist.* Performed Phase II ESA in preparation for the development of an affordable housing apartment complex by Foundation Communities. Activities assessed two vapor encroachment conditions and two RECs. Deployed a total of 20 PSGs to assess soil gas. Installed four soil borings to assess site soils and the shallow groundwater-bearing unit.

Phase I Environmental Site Assessment, Tract 1-B: Paseo del Pueblo Sur and Los Pandos Road, Taos Hotel Associates, LLC., Taos, NM. 2022. *Environmental Scientist.* Conducted and prepared a Phase I ESA report in accordance with ASTM Standard E1527-21 and resultant volume estimate for a proposed removal of identified petroleum-contaminated soil more than the NMED action level of 100 parts per million by volume.

Scrub-A-Dubb Barrell Company Proposed State Superfund Site, Texas Commission on Environmental Quality, Lubbock County, TX. 2019 – 2023. *Environmental Scientist.* Drafted the TCEQ State Superfund FSP to implement assessment of on- and off-site soils for metals and VOCs referencing Interstate Technology Regulatory Council ISM. The ISM protocol would be used to assess risk to nearby human health and sensitive environmental receptors and to support a potential removal action. Results were compared to TRRP action levels.

Groundwater Sampling & Reporting, Chemical Waste Management, Port Arthur, Texas. 2022. *Environmental Scientist*. Conducted quarterly groundwater monitoring activities for a closed hazardous waste landfill facility. Sampling included groundwater collection at approximately 30 site monitoring wells for VOCs and arsenic.

Gem Dandy 14 Phase I Environmental Site Assessment, Texas Commission on Environmental Quality Brownfields Program, Hamilton, TX. 2022 – 2023. *Project Manager.* Conducted a Phase I ESA for the TCEQ Brownfields Program in accordance with ASTM Standard Practice E1527-21. Oversaw completion of a geophysical survey implementing GPR and electromagnetic mapping to confirm the presence of a UST. Conducted removal of one 12,000-gallon UST and associated infrastructure. Prepared and submitted a report in accordance with TCEQ Regulatory Guidance (RG) 411 documenting removal and restoration activities.

IWC Winters Landfill, Texas Commission on Environmental Quality Superfund Site Discovery and Assessment Program, Orange, TX. 2022 – 2023. *Project Manager.* Designed and conducted initial assessment of this former industrial waste landfill that had become partially submerged and had a history of fires near Adams Bayou in Orange, TX. Sampling of soil, sediment, groundwater, and surface water was conducted for VOCs, SVOCs, organochlorine and organophosphorus pesticides, metals, PCBs, dioxins/furans, and PFAS. Prepared the assessment report including technical data review in accordance with the TCEQ Quality Assurance Project Plan and applicable EPA guidance for all media and analytes.

Former Frank Ortiz Landfill, City of Santa Fe Environmental Services Division, NM. 2021 – 2023. *Environmental Scientist*. Prepared Stage 1 Abatement Plan Quarterly Monitoring Reports detailing ongoing monitoring efforts at the site including soil vapor sampling, groundwater monitoring, and landfill gas monitoring.

Rockwool Industries Federal Superfund Site, Texas Commission on Environmental Quality, Bell County, TX. 2018 – 2023. *Project Manager.* Conducted annual groundwater monitoring and semi-annual site inspections, provided oversight for site maintenance, and drafted the annual reports including potentiometric surface and isoconcentration maps, documenting all site activities, and providing conclusions and recommendations for future site activities.

Calhoun and Griggs Soil Assessment, Texas Commission on Environmental Quality, Houston, TX. 2022. *Project Manager.* Designed and conducted a soils assessment for metals and prepared a report documenting the findings.

Magic Tunnel Geophysical Survey, Texas Commission on Environmental Quality Brownfields Program, Texarkana, TX. 2022. *Project Manager*. Oversaw the completion of a geophysical survey implementing GPR and electromagnetic mapping to determine the presence of suspected USTs.

Former Nursing Home Phase I Environmental Site Assessment, Texas Commission on Environmental Quality Brownfields Program, Hamilton, TX. 2022. *Project Manager.* Conducted a Phase I ESAs for the TCEQ Brownfields Program in accordance with ASTM Standard Practice E1527-21.

Kirtland Air Force Base Environmental Baseline Surveys, Albuquerque Bernalillo County Water Utility Authority, NM. 2020 – 2022. *Environmental Scientist.* Authored and certified two Environmental Baseline Survey (EBS) Reports to meet appropriate property due diligence practices for the easement between Albuquerque Bernalillo County Water Utility Authority (ABCWUA) and Kirtland Air Force Base (KAFB), in accordance with Air Force Instruction 32-7066. The property locations included a 5.29-mile-long easement and a 24-acre parcel, all located on KAFB and Department of Energy property. The project included installing an interceptor pipeline and booster station by ABCWUA, with INTERA responsible for all federal due diligence requirements associated with construction projects occurring on federal facilities. Air Force EBS reports are generally comparable to an environmental due diligence report (Phase I ESA) but also include National Environmental Policy Act review, including cultural natural/biological resource review. Updated the sewer interceptor line easement in February 2022. The EBS reports were approved by the ABCWUA and KAFB in 2022.

Former Santa Fe Generating Station, Public Service Company of New Mexico, Santa Fe County, NM. 2018 – 2022. *Environmental Scientist*. Provided data review services of laboratory analytical and field and laboratory quality assurance/quality control for periodic groundwater monitoring. Reviewed figures and tables and created contaminant trends time series data visualizations with Grapher™ software for quarterly progress reporting (2019-2022). Conducted groundwater monitoring (2021) for VOCs and nitrate/nitrite utilizing piston driven Bennett Pump. Conducted a detailed review of historical aerial photographs for evidence of potential sources to petroleum contamination at the site. Drafted a report including a detailed spatiotemporal summary of findings with correlation to historical documentation.

South State Highway 16, Texas Commission on Environmental Quality Superfund Site Discovery and Assessment Program, San Antonio, TX. 2021. *Project Manager.* Designed and conducted a Superfund Site Discovery and Assessment Program (SSDAP) Eligibility Sampling groundwater assessment in the vicinity of a former illegal dump site used by a pesticide applicator to assess impacts to nearby human health receptors at target sole source water wells.

Airline & Aldine, Texas Commission on Environmental Quality Superfund Site Discovery and Assessment Program, Houston, TX. 2021. *Project Manager.* Designed and conducted a State Screening groundwater assessment in the vicinity of a former public water supply well with chlorinated solvent contamination to assess impacts to human health receptors at target sole source water wells.

Elm Street Phase I Environmental Site Assessments, Texas Commission on Environmental Quality Brownfields Program, Texarkana, TX. 2021. *Environmental Scientist.* Conducted two Phase I ESAs for the TCEQ Brownfields Program in accordance with ASTM Standard Practice E1527-13.

Site Investigation of Former Drilling Fluids Disposal Pit, Mo-Vac Service Company, Alice, TX. 2021. *Environmental Scientist.* Conducted a site investigation of a former drilling fluids disposal pit pursuant to an RRC letter to INTERA's client. Conducted a pump test to properly classify the groundwater and conducted groundwater sampling.

Covenant Testing Technologies Railroad Commission of Texas Pit Closure, Covenant Testing Technologies, Midland, TX. 2021. *Environmental Scientist*. Conducted sampling event to close an in-ground steel tank and wash pads that were used to collect hydrocarbon contaminated equipment wash water. Assisted in preparing submittal to the RRC documenting that the site met RRC closure criteria.

Wally's Flying Service Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Uvalde County, TX. 2020. *Environmental Scientist.* Prepared the site-specific health and safety plan (SSHASP) and FSP. Conducted field event including groundwater sampling for SVOCs by method 8270E, organochlorine pesticides by method 8081B, and organophosphorus pesticides by method 8141B. Target contaminants of concerns, glyphosate and endothall, were also sampled and analyzed via EPA drinking water methods 547 and 548.1, respectively. Prepared the final SSDAP Letter Report documenting sampling and comparing analytical results to TRRP PCLs.

G&L Spraying Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Tom Green County, TX. 2020 – 2021. *Project Manager.* Designed and conducted a State Screening groundwater assessment in the vicinity of a former pesticide applicator with a history of releases to the ground surface to assess impacts to human health receptors at target sole source water wells. Conducted groundwater sampling for metals (primarily arsenic) and SVOC pesticides pendimethalin and trifluralin.

Jain Lane / Govalle Soil Vapor Assessment and Vapor Intrusion Mitigation Assistance, Cesar Chavez Foundation, Austin, TX. 2019 – 2021. *Environmental Scientist.* Prepared an updated FSP to conduct soil vapor assessment for a proposed multi-unit residential development. Conducted soil vapor sampling to assess soil vapor impacts from hydrocarbon-affected groundwater from an adjoining, upgradient site. Prepared a Limited Phase II Report for soil vapor assessment concluding potential risk of vapor intrusion to the proposed development and provided recommendations for a vapor barrier system to mitigate potential impacts. Provided mitigation design assistance during the planning stages for construction. Provided certified third party inspection during vapor barrier and venting system installation for a multi-tenant residential complex. Provided final report documenting mitigation effort to satisfy requirements to obtain financial assistance.

Former First Baptist Church, University of New Mexico, Albuquerque, NM. 2020. *Environmental Scientist.* Prepared and submitted a Phase I ESA Report in accordance with ASTM Standard Practice E1527-13. Reviewed available historical records evaluated site visit findings to identify, to the extent possible, any RECs, as defined by ASTM. The Subject Property consisted of mixed use educational, residential, and creative space development. The development is in a highly developed area of Albuquerque and is also immediately south of a chlorinated solvent groundwater plume that is part of a federal superfund site on the national priority list.

Hospital Drive, Anchorum St. Vincent c/o Colliers International, Santa Fe, NM. 2020. *Environmental Scientist.* Prepared and submitted a Phase I ESA Report in accordance with ASTM Standard Practice E1527-13. Reviewed available historical records evaluated site visit findings to identify, to the extent possible, any RECs, as defined by ASTM. The Subject Property consisted of an outpatient medical facility in a mixed commercial and residential area.

Oltorf Street Phase I Environmental Site Assessment, City of Austin, TX. 2020. *Environmental Scientist*. Prepared and submitted a Phase I ESA Report in accordance with ASTM Standard Practice E1527-13. Reviewed available historical records conducted site visit to identify, to the extent possible, any RECs, as defined by ASTM. The Subject Property consisted of a 2.57-mile corridor through commercial and residential areas for a proposed reclaimed water main project.

Loco Ocho Hydrogeologic Assessment, Confidential Client, Wimberly, TX. 2020. *Environmental Scientist*. Conducted groundwater sampling at a private water supply well to establish baseline water quality.

Frank's Conoco, New Mexico Environmental Department Petroleum Storage Tank Bureau, Las Cruces, NM. 2020.
Environmental Scientist. Prepared Groundwater Monitoring Report for a petroleum hydrocarbons release site where INTERA gauged depth to water/light non-aqueous phase liquid (LNAPL) collected groundwater samples. Groundwater was analyzed for VOCs. Reporting included calculating and graphically depicting the groundwater gradient and potentiometric surface. Analytical results were compared to New Mexico Water Quality Control Commission (NMWQCC) standards.

Highway Texaco, New Mexico Environmental Department Petroleum Storage Tank Bureau, Las Cruces, NM. 2020.
Environmental Scientist. Prepared a work plan and cost estimate to conduct a single groundwater monitoring event including monitoring well gauging, sampling, and analysis for dissolved iron and manganese, and VOCs. Analytical results were compared to NMWQCC standards. The sampling monitored petroleum hydrocarbon contaminants in groundwater associated with releases from a former gasoline service station.

Corrales Chevron, New Mexico Environmental Department Petroleum Storage Tank Bureau, Corrales, NM. 2020.
Environmental Scientist. Prepared a work plan and cost estimate to conduct a semi-annual groundwater monitoring at an active gasoline service station with historical releases from the former operations of a preceding service station. The scope of work for this project included monitoring petroleum hydrocarbon contamination in groundwater from a series of 10 monitoring wells and from six nearby water supply wells (i.e., wells with a sealed wellhead). Analytical results of sampling conducted for VOCs were compared to NMWQCC standards.

Caldwell Motor Company, New Mexico Environmental Department Petroleum Storage Tank Bureau, Belen, NM. 2020.
Environmental Scientist. Prepared a work plan and cost estimate to conduct a semi-annual groundwater monitoring at a

former gasoline service station with a historical presence of LNAPL and an undefined dissolved phase contaminant plume. The sampling monitored the contaminant plume from the existing four monitoring wells and compared analytical results to NMWQCC standards.

Old Exxon Jobber Site, Texas Commission on Environmental Quality, San Patricio County, TX. 2019 – 2020. *Environmental Scientist.* Conducted site reconnaissance and scoping meeting with TCEQ to facilitate preparation of the FSP for tank removal activities and release determination sampling. Prepared FSP in accordance with TCEQ Regulatory Guidance 411 (RG-411) to conduct permanent tank removal activities for two registered 22,000-gallon USTs, and all associated components, and to conduct confirmation and surface release assessment. Conducted field oversight for removal of the tanks and collected confirmation samples for petroleum hydrocarbon contaminants including benzene, toluene, ethylbenzene, xylenes (BTEX), methyl-tert butyl ether (MTBE) via EPA Method 8260/5035, polycyclic aromatic hydrocarbons (PAHs) via EPA Method 8270D, and TPH via TCEQ Method 1005. Prepared and submitted a Release Determination Report in accordance with applicable standard (TCEQ-00621)

Union Pacific Rail Yard, Texas Commission on Environmental Quality, Cameron County, TX. 2019. *Environmental Scientist*. Conducted a Phase I ESA and prepared and submitted a Phase I ESA Report in accordance with ASTM Standard Practice E1527-13. Reviewed available historical records and conducted a site visit to identify, to the extent possible, any RECs, as defined by ASTM. The Subject Property consisted of approximately 25.5 acres of land within an urban mixed residential and commercial industrial area that was formerly a train depot and railway switchyard.

Texaco Building, Texas Commission on Environmental Quality, Cameron County, TX. 2019. *Environmental Scientist.* Conducted a Limited Phase II ESA in which 8,000-gallon steel tank and one 12,000-gallon steel tank and associated piping and conducted sampling and analysis in accordance with TCEQ RG-411. Collected confirmation samples for petroleum hydrocarbon contaminants including BTEX, MTBE via EPA Method 8260/5035, PAHs via EPA Method 8270D, and TPH via TCEQ Method 1005. Prepared and submitted an Release Determination Report in accordance with applicable standard (TCEQ-00621).

City of Hondo Landfill Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Medina County, TX. 2019. *Environmental Scientist.* Prepared the SSHASP and FSP. Conducted field event including groundwater sampling for metals, VOCs, SVOCs, and PCBs. Prepared the final SSDAP Letter Report documenting sampling and comparing analytical results to TRRP PCLs.

Russell Flying Service Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Medina County, TX. 2019. *Environmental Scientist.* Prepared the SSHASP and FSP. Conducted field event including groundwater sampling for metals including hexavalent chromium, SVOCs, VOCs, pesticides, and herbicides. Prepared the final SSDAP Letter Report documenting sampling and comparing analytical results to TRRP PCLs.

The Word Church Phase II Environmental Site Assessment, Texas Commission on Environmental Quality, Bexar County, TX. 2019. *Environmental Scientist.* Provided oversight of drilling via solid stem auger and installation of a monitoring well. Conducted well development and collected a representative groundwater sample via low-flow technique.

Sand Hill Energy Center Release Assessment in Support of Affected Property Assessment Report, City of Austin, TX. 2019. *Environmental Scientist.* Provided oversight for hydro-vac to clear utilities down to six feet at the facility, drilling via hollow-stem auger, and installing and developing three monitoring wells. Collected soil and groundwater samples for analysis of TPH and PAHs. Assisted in preparing an affected property assessment report for submission to TCEQ.

Mineral Wool Insulation Manufacturing Company Proposed State Superfund Site Additional Offsite Evaluation in Support of Remediation, Texas Commission on Environmental Quality, Bell County, TX. 2018 – 2019. *Environmental Scientist.* Conducted detailed overland migration characterization and subsurface sediment sampling using a gravity core sampling device deployed from a boat. Drafted report documenting field activities and providing comprehensive descriptions of the migration pathway with estimation of anticipated volumes for removal based on impacted soils above site specific ecological PCLs. Also collected agricultural samples for nutrient analysis to determine the viability and practicality of repurposing on and offsite soils in the design of a containment cell cap with effective vegetative growth.

Schumann Property Petroleum Storage Tank Removal and Brownfields Site Assessment, Texas Commission on Environmental Quality, Concho County, TX. 2018. *Environmental Scientist.* Prepared the FSP based on TCEQ Regulatory Guidance RG-411. Implemented the FSP including oversight of PST removal (550-gallon "ghost tank"), conducted field screening and

confirmation sampling. Prepared the Release Determination Report documenting removal activities and analytical results with respect to PST Action Levels.

Hamlin Municipal Development District Phase I Environmental Site Assessment, Texas Commission on Environmental Quality, Jones County, TX. 2018. *Environmental Scientist.* Conducted the Phase I ESA site reconnaissance to identify and document RECs.

West Texas Phase I Environmental Site Assessment, Confidential Client, Loving County, TX. 2018. *Environmental Scientist.* Provided historical document review and drafted the historical portion of the Phase I ESA Report for approximately 50 square miles of property in accordance with Standard Practice E2247-16 of ASTM International.

Medical Drive Groundwater Plume Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Bexar County, TX. 2018. *Environmental Scientist.* Conducted groundwater sampling at public and domestic drinking water wells for PCE on rapid 24-hour turnaround time (EPA Drinking Water Method 524.2) and drafted the report to document the release and impacts to receptors in the critical pathway of exposure to facilitate Hazard Ranking System scoring.

South Austin Regional Wastewater Treatment Plant Phase I Environmental Site Assessment, City of Austin Public Works, TX. 2018. *Environmental Scientist*. Conducted the Phase I ESA historical document review and site reconnaissance to identify and document RECs.

The Word Church Phase II Environmental Site Assessment, Texas Commission on Environmental Quality, Bexar County, TX. 2018. *Environmental Scientist*. Provided oversight of environmental borehole drilling with direct push technology for the collection of soil samples to a depth of 15 feet. Assisted in lithological logging, field screened and sampled for VOCs or petroleum products. Drafted the Phase II ESA Report. Work was conducted in accordance with Standard Practice E1903-11 of ASTM International. Provided oversight of drilling via solid stem auger and installation of a monitoring well. Conducted well development and collected a representative groundwater sample via low-flow technique.

Cass County Treating Company State Superfund Site Immediate Removal Action, Texas Commission on Environmental Quality, Cass County, TX. 2016 – 2017. *Project Manager*. Coordinated and provided oversight for removal of soils affected with pentachlorophenol and dioxins/furans at a residential property. The scope of the project included air sampling for the development of protective particulate monitoring action levels, confirmation sampling via ISM including development of a pentachlorophenol screening level concentration indicative of dioxins/furans concentrations as a screening tool, and site restoration.

North Andrews Highway Health and Safety Plan and Preliminary Assessment, U.S. Environmental Protection Agency, Ector County, TX. 2016 – 2017. *Project Manager*. Developed the site health and safety plan. Authored the preliminary assessment report based on research and available site information, including consolidating and analyzing historical site knowledge and analytical data, describing the geologic setting and aquifer characteristics, evaluating major migration and exposure pathways, and producing figures and tables.

Harvey Industries State Superfund Site, Texas Commission on Environmental Quality, Henderson County, TX. 2016 – 2017. *Project Manager*. Coordinated and oversaw operations and maintenance activities at the site including soil gas monitoring and cap inspection/maintenance.

First Quality Cylinders State Superfund Site, Texas Commission on Environmental Quality, Bexar County, TX. 2014 – 2017. *Assistant Project Manager and Project Manager.* Coordinated and provided oversight for the continuous removal of affected groundwater contained behind a slurry wall from on-site extraction wells. Reviewed engineering documents and assisted in project management for the implementation of the final remedy which included groundwater remediation via direct push in-situ chemical reduction of hexavalent chromium in the shallow groundwater bearing unit and the installation of a continuous onsite pump and treat system. Managed operations and maintenance activities for the on-site treatment system.

Jerrell B Thompson Battery State Superfund Site, Texas Commission on Environmental Quality, Van Zandt County, TX. 2013 – 2017. *Project Manager.* Conducted annual inspection to ensure site controls for waste remained undisturbed and in good condition as part of operations and maintenance activities.

JCS Company State Superfund Site, Texas Commission on Environmental Quality, Van Zandt County, TX. 2013 – 2017. *Project Manager.* Coordinated and provided oversight for annual operations and maintenance activities at the site including cap inspection and maintenance as well as groundwater monitoring activities.

Deepwater Horizon RESTORE Act Proposal Evaluations, Texas Commission on Environmental Quality Natural Resource Damage Assessment, Austin, TX. 2016. *Evaluator.* Was selected to be part of a six-member interdisciplinary committee that evaluated more than 200 proposals requesting funds allocated to the state by the RESTORE Act for the Deepwater Horizon oil spill.

Schaefer Road Drum Immediate Removal Action, Texas Commission on Environmental Quality, Bexar County, TX. 2016. *Project Manager.* Coordinated and provided oversight for HAZCAT classification, removal, and proper disposal of abandoned bulk and containerized wastes, and affected site soils. Authored legal documents for cost recovery.

Methodist Hospital Health and Safety Plan and Preliminary Assessment, U.S. Environmental Protection Agency, Bexar County, TX. 2016. *Project Manager*. Developed the site health and safety plan. Authored the preliminary assessment report based on site reconnaissance, research, and available site information including consolidating and analyzing historical site knowledge and analytical data, describing the geologic setting and aquifer characteristics, evaluating major migration/exposure pathways, and producing figures and tables.

Highway 18 Groundwater Plume Expanded Site Investigation, U.S. Environmental Protection Agency, Winkler County, TX. 2016. *Field Project Manager.* Responsible for the field event, which included coordination and sampling of soils at potential source locations and sampling sole source water wells for evaluation of impact to human health receptors in the groundwater migration pathway.

Lane Plating Works Site Investigation, U.S. Environmental Protection Agency, Dallas County, TX. 2016. *Field Project Manager*. Acted as Project Manager for the field event, which included identifying representative sampling locations in the field and sampling of soils, sediments, and surface water.

Southwestern Plating Works Immediate Removal 2015, Texas Commission on Environmental Quality, Lubbock County, TX. 2015 – 2016. *Project Manager*. Coordinated and provided oversight for the classification, removal, and proper disposal of abandoned plating vats and containerized wastes. Conducted SSDAP state screening activities, including soil and groundwater sampling and analysis and authored legal documents for cost recovery.

Ector Drum Site Investigation, U.S. Environmental Protection Agency, Ector County, TX. 2015 – 2016. *Project Manager*. Conducted the field effort, including sampling of residential and commercial sole source groundwater wells. Analyzed the collected groundwater data, compared data to EPA Maximum Concentration Levels, and authored the final technical report.

Absolute Fuels Superfund Site, Texas Commission on Environmental Quality, Lamb County, TX. 2015. *Project Manager*. Coordinated and provided oversight for the assessment and investigation of impact to human health receptors via the groundwater pathway and the completion of the final Removal Action Report. Authored legal documents, including a property lien for cost recovery.

Industrial Waste Control Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Orange County, TX. 2015. *Project Manager*. Coordinated and provided oversight for the assessment and investigation of impact to human health receptors in the groundwater migration pathway. Analyzed and compared data to TRRP PCLs to provide conclusions and site recommendations.

Browning Ferris Industries Landfill Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Orange County, TX. 2015. *Project Manager.* Coordinated and provided oversight for the assessment and investigation of impact to human health receptors in the groundwater migration pathway. Analyzed data, compared data to TRRP PCLs, and provided conclusions and site recommendations.

Lonesome Trail Site Investigation, U.S. Environmental Protection Agency, Bexar County, TX. 2014. *SI Team Member*. Conducted soil and groundwater sampling to assist in the completion of the Site Investigation.

River City Metal Finishing Superfund Site, Texas Commission on Environmental Quality, Bexar County, TX. 2014. *Project Manager.* Conducted closeout activities, including authoring legal documents and notices including a restrictive covenant and property lien.

Battery Recyclers of Houston Superfund Site, Texas Commission on Environmental Quality, Brazoria County, TX. 2014. *Project Manager.* Coordinated and provided oversight for the assessment and investigation of impact to human health receptors in the groundwater and soils migration pathways. Analyzed data, compared data to TRRP protective concentration levels, and provided conclusions and site recommendations.

Sampling of Vegetation Transects in the Okavango Delta, Dr. Kelley Crews and Dr. Thoralf Meyer, Undergraduate Research, Botswana, Africa. 2012. *Field Research Assistant.* Conducted sampling in remote parts of Botswana, Africa as part of a ground truthing effort for remotely sensed data. Responsibilities included gathering data using high resolution spectral imagery as well as identifying and measuring woody vegetation across ecological regimes. Applied data gathered for analyzing carbon sequestration in above ground woody biomass using the allometric relation of basal area to biomass.

Project Experience – Water Resources

Vertical Flow Profiling for Production Well, Porter Special Utility District, TX. 2021. *Environmental Scientist.* Provided oversight for "lift and shift" and ultimately the complete removal and reinstallation of a 560 ft, 10-inch pump column. Conducted vertical flow profiling utilizing BESST's upgraded and proprietary version of the U.S. Geological Survey tracer flowmeter and targeted depth interval groundwater sampling using the BESST HydroBooster sampling pump. Analytes included hydrogen sulfide (H2S), adenosine triphosphate (ATP), sulfate reducing bacteria (SRBs), iron reducing bacteria (IRBs), dissolved sulfide, total sulfides, total iron, total organic carbon, methane, chloride, sodium, oxidation/reduction potential (ORP), and specific conductivity. Field testing was also performed including H2S, ORP, dissolved oxygen (DO), pH, temperature, turbidity, and specific conductivity. Wellhead samples were also collected, representing blended composites of zonal chemical mass contribution from each contributing flow interval.

Evangeline Laguna Borehole Surveys and Pump Testing, Confidential Client, San Patricio County, TX. 2020. *Environmental Scientist*. Performed video surveys of wells to determine conditions and screened intervals. Conducted oversight of pump removal and installation and 36-hour pump tests in three wells with In-Situ Trolls and WinSitu software while obtaining manual water level and flow measurements. Collected water samples to analyze water chemistry before, during, and after pump tests.

Dynamic Flow and Water Chemistry Profiling, West Harris County Municipal Utility District, Houston and Katy, TX. 2020. *Environmental Scientist.* Conducted downhole investigation at two public water supply wells to: (1) measure zonal flow contribution within the well under steady-state pumping conditions; (2) characterize zonal chemical contribution of arsenic, iron, and exsolved methane; and (3) determine viable economical options to physically modify the well screen to reduce or eliminate treatment for arsenic and iron and to mitigate methane influx. Conducted dynamic flow profiling to calculate zonal flow contributions over hundreds of feet of intermittently perforated well screen by injecting rhodamine dye at discrete depth intervals and measuring peak return rates at the surface via fluorometer. Conducted depth-dependent groundwater sampling to characterize zonal chemical contribution.

New Braunfels Utilities Aquifer Storage and Recovery Monitoring, ARCADIS, New Braunfels, TX. 2020. *Environmental Scientist.* Provided oversight for drop pipe and transducer installation at monitoring wells supporting aquifer storage and recovery monitoring.

Constant Rate Test for Turtle Creek No. 3 Pump Station, San Antonio Water System, Bexar County, TX. 2019. *Environmental Scientist.* Provided oversight for the constant rate test at 7,000 gallons per minute.

El Dorado Sand Mine Water Supply Wells Development and Performance Analysis, Black Mountain Sand, Winkler County, TX. 2019. *Environmental Scientist.* Provided well development (bailing and airlifting) and pump installation oversight, including water quality monitoring; conducted step drawdown tests to assess supply well performance; and collected aquifer test data for four wells using water level meters and multiple transducers. Collected data using In-Situ Trolls and WinSitu software.

Observation Well Drilling Oversight and Sampling - Oversight for Vertical Flow Profiling for Production Well, Confidential Client, San Patricio County, TX. 2018 – 2019. *Environmental Scientist.* Provided oversight for well drilling activities of observation well to depth greater than 1,000 feet bgs and collected mud rotary cuttings samples for sieve analysis. Provided oversight for BESST, Inc. implementing their ambient flow profiling service using the DyeTracer system developed by the U.S. Geological Survey.

Bigfoot Sand Mine Water Supply Well Installation, Turnkey Processing Solutions, Atascosa County, TX. 2018. *Environmental Scientist.* Provided well drilling and installation oversight. Logged drilling cuttings, conducted step drawdown tests, and collected aquifer test data using water level meters and multiple transducers.



Joseph Tracy, PG

Principal Geologist | Senior Vice President

Years of Experience: 31

Education:

- BS, 1993, Environmental Geology, Ohio University

Professional Registrations/Affiliations:

- Professional Geologist, AZ, 2003, No. 38741
- Professional Geologist, TN, 1999, No. TN4417
- Professional Geologist, TX, 2013, No. 11588

Professional History:

2000 – Present	Senior Vice President, Principal Geologist – INTERA Incorporated, Albuquerque, NM
1999 – 2000	Environmental Specialist – GeoTek Insite, Albuquerque, NM
1997 – 1999	Staff Geologist – Professional Services Industries, Inc. (PSI), Cleveland, OH
1994 – 1997	Staff Geologist – Terranext, Inc., Denver, CO

Training:

- OSHA Health and Safety Training, 29 CFR 1910.120, (40-Hour), 1994
- OSHA Health and Safety Training, Annual Refresher, (8-Hour), current
- DOT HM 126 Hazardous Material Transportation Training, 49 CFR 172.700, 1996
- Confined Space Entry Training, 29 CFR 1910.140, 1995
- National Ground Water Association – Fate and Transport of Light Non-Aqueous Phase Liquids/Dense Non-Aqueous Phase Liquids (LNAPLs/DNAPLs) Training, 1995
- Asbestos Inspector and Management Planner (Toxic Substance Control Act Sec. 206, Title II) Training, 1997
- Asbestos Contractor Supervisor (Toxic Substance Control Act Title II and AHERA) Training, 2000
- Vapor Intrusion Training, 2011
- Red Cross First Aid/CPR Training, current
- Sulfuric Acid Handling Training, 2013
- Interstate Technology Regulatory Council (ITRC) Training – Vapor Intrusion Pathway: Investigative Approaches for Typical Scenarios (2008)

Joseph "Joe" Tracy is a Principal Geologist and Senior Vice President at INTERA with a BS degree in environmental geology and over three decades of consulting experience focused on environmental assessments, site investigations, remedial planning, and site remediation. He has evaluated the environmental impacts to soil and groundwater at leaking petroleum storage tank (PST) sites, Superfund sites, Brownfield sites, and a variety of operational and former industrial properties and facilities. Mr. Tracy leads multidisciplinary teams of scientists and engineers to complete investigations and remediation of contaminants that include petroleum hydrocarbons, heavy metals, chlorinated solvents, polychlorinated biphenyls (PCBs), per- and polyfluoroalkyl substance (PFAS), and asbestos. He develops remedial plans under voluntary remediation and Superfund programs and prepares and implements work plans, quality assurance project plans, and remedial action plans for Brownfields and other redevelopment projects. Mr. Tracy's experience also includes performing investigations and related work at municipal landfills where activities have included the installation and monitoring of landfill gas (LFG) probes, preparing landfill management plans, operation and maintenance of LFG extraction/destruction systems, developing and implementing grading and drainage plans, and profiling the nature and extent of landfill wastes. Mr. Tracy is a Senior Vice President within INTERA's Southwest Region, where he oversees multi-site contracts with state, county, and municipal agencies, and is responsible for directing all environmental services marketing efforts within the INTERA Mining and Environmental Line of Business Unit.

Project Experience – Environmental

Santa Fe County Investigation of Per- and Polyfluoroalkyl Substance Contaminants in Domestic Wells, Santa Fe County, NM. 2024 – Present.

Project Manager. Santa Fe County The sampling and analysis of drinking water in October 2023 from six domestic wells within the communities of La Cienega and La Cieneguilla, Santa Fe County discovered PFAS at concentrations above the safe drinking water standards recently established by the USEPA. Driven by the health concerns related to this discovery, the County, in collaboration with the New Mexico Environment Department (NMED) Construction Programs Bureau (CPB) and the City of Santa Fe, successfully acted to obtain a USEPA grant to help fund the assessment of the potential PFAS impacts to area groundwater. Mr. Tracy is leading the INTERA Team to achieve the overarching project goals of determining the extent of the PFAS contamination in groundwater and developing alternatives for mitigation and/or remediation of the contamination. Mr. Tracy is currently assisting the County with the initial project activities including the development of a conceptual site model (CSM) and selecting additional domestic wells for PFAS sampling. In addition, Mr. Tracy is working with INTERA subcontractor, John Shomaker and Associates, Inc. (JSAI), in the development of a groundwater flow model, in an effort to determine preferential flow paths for underlying PFAS contamination in ground water.

Environmental Investigations, City of Albuquerque – Department of Municipal Development, Albuquerque, NM. 2005 – 2018 and 2023 – Present. *Contract Manager and Project Manager.* Contract Manager City of Albuquerque Department of Municipal Development Environmental On-Call Services contract. Performed Phase I and Phase II Environmental Site Assessments (ESAs) for the City of Albuquerque (COA) as part of this contract. In addition, provided environmental assistance to the COA Department of Municipal Development on an as-needed basis as project environmental issues develop. Environmental issues included extraction well evaluation at the former Los Angeles Landfill, maintenance and monitoring services at the former Los Angeles Landfill, geophysical investigations in the downtown Albuquerque area, micro-turbine analysis at the former Los Angeles Landfill, engineering evaluation/cost analysis (EE/CA) for the Hotel La Posada del Albuquerque, conducting a soil vapor survey at the City of Albuquerque 1st and Central Site which is located adjacent to the former BNSF East Bound Fueling Facility, ambient air monitoring within residential houses in the Albuquerque area, and asbestos and lead-based paint surveys at several city facilities (i.e., Los Duranes Community Center, Jeanne Bellamah Community Center, Holiday Park Community Center, Barelas Community Center, Mesa Verde Community Center, APD Education Building, Dennis Chavez Community Center, Rio Grande Fire House, Pino Yard Senior Games Building, North Valley Senior Center, Palo Duro Senior Center, Environmental Health Department offices), city-owned former historic hotels (El Vado and De Anza), and city-acquired properties (Brown Property, Caravan Building, Loan Pawn Shop). Facilitated on-call projects such as the development of a CSM for the Kirtland Air Force Base Fuel Spill, development of a voluntary remediation approach for at the Marble-Arno Property and the downtown Railyard, locating a new COA storm water facility, conducting an archaeological survey at the Singing Arrow Community Center, and several landfill maintenance projects for the COA Solid Waste Division Cerro Colorado landfill. Currently projects for the COA include the assessment of asbestos and lead-based paint in several buildings at the COA BioPark (Zoo), which is undergoing a full-scale remodeling and renovation, as well as continuing groundwater monitoring activities at the Marble-Arno Property under the Voluntary Remediation Program (VRP). Secured an additional environmental services on-call contract with the COA in late 2023 and work began in 2024. Mr. Tracy is currently leading the environmental surveys associated with the renovation of the COA Gibson Health Hub (GHH) and several COA community centers and libraries.

Santa Fe Well-S (Santa Fe Generating Station) Petroleum Storage Tank Investigation, Public Service Company of New Mexico, Santa Fe, NM. 2018 – Present. *Project Principal.* Providing contract support for the investigation of fuel and chlorinated solvent release at a former power generating station and other, off-site sources. The release(s) have impacted a City of Santa Fe municipal supply well, causing production of drinking water from this well to be discontinued. The investigation includes the installation of 25 monitoring wells to depths ranging from approximately 300 to over 400 feet using roto-sonic drilling and sampling techniques. Portable gas chromatography and a photoionization detector are being used to analyze soil and groundwater samples in the field so that contaminated zones can be identified, and real-time, informed decisions can be made concerning screen intervals. The results of the in-field screening have identified zones, some as thin as three feet, containing mobile light non-aqueous phase liquid (LNAPL) and conveying highly contaminated groundwater. Responsibilities have included contract and technical discussions with the client and project team as well as attending several scoping and status meetings with Public Service Company of New Mexico, the City, and NMED representatives. In addition to providing support of environmental services associated with the fuel plume, also reviewing efforts associated with State 1 abatement plan (S1AP) investigations regarding chlorinated solvents and nitrates contamination present in ground water at the site.

Hop Canyon/Waldo Mill Site Phase II Site Investigation and Voluntary Remediation Program Activities, ASARCO, Magdalena, NM. 2000 – 2002 and 2018 – Present. *Project Principal, Project Manager, and Staff Geologist.* Implemented a Work Plan to characterize an American former Smelting and Refining Company (ASARCO) mining mill tailings site in Magdalena, New Mexico. The voluntary remediation activities included characterization and removal of affected soil and construction of an onsite tailings impoundment capped with clean soil. Surface drainage issues included interfacing with the U.S. Army Corps of Engineers to present erosion of the impoundment cap and surrounding soils. Initiated additional work at this site on behalf of the ASARCO Trust in 2018. INTERA is currently responsible for Site Caretaker Operations, which are essentially weekly Site visits to make certain the tailings impoundment cover remains in good condition. INTERA will prepare a VRP Work Plan to guide the repair work of the tailing impoundment cover. NMED and/or the ASARCO Trust identified several areas of the tailings impoundment cover in 2017 that are recommended for repair. The remainder of the ASARCO property at the site was legally transferred into ASARCO Trust ownership in late 2023. Currently working with ASARCO Trust representatives and the INTERA Project Team to design and conduct cap repair activities and secure a VRP Conditional Certificate of Completion (CCOC).

Las Vegas Patrol Yard Groundwater Remediation System Operation and Maintenance, New Mexico Department of Transportation, Las Vegas, NM. 2017 – Present. *Project Principal.* Began operation and maintenance (O&M) activities of a groundwater remediation system associated with the two contaminant plumes: an inorganic (chloride and total dissolved solids [TDS]) plume and organic (petroleum and chlorinated compound) plume located at the New Mexico Department of Transportation (NMDOT) Las Vegas Patrol Yard. The groundwater remediation system was originally operated by another firm but due to performance issues INTERA was asked to conduct O&M activities at the site. The groundwater remediation system consists of five interceptor trenches (four of the trenches focus on capturing the inorganic and petroleum plume and one focuses on capturing the chlorinated solvent plume) which capture contaminated groundwater and convey the water to two treatment containers. The treatment system consists of a filter media capable of removing iron and manganese, an air stripper which targets volatile organic compounds (VOCs), and reverse osmosis (RO) membranes which removes TDS and chlorides. The treated groundwater is reinjected into the subsurface via three infiltration trenches. Monthly influent and effluent samples are collected from the groundwater remediation system to ensure the system is operating effectively and that the effluent water quality meets the approved discharge permit requirements. O&M activities include maintaining all parts (pumps, inline sensors, filters) of the system, monitoring the dosing rate of the system additives (sodium hypochlorite, sodium metabisulfite, caustic soda, and anti-scaling agent), analyzing field water quality parameters/compounds (pH, TDS, free chlorine, total iron, total manganese) using handheld meters or Hach kits, replacing filters, monitoring system pressures, maintaining adequate additive volumes in vessels, and performing high- and low-pH cleaning of the RO membranes when necessary. The data collected during O&M activities and recorded remotely using a programmable logic controller is tracked and analyzed on a weekly basis to make sure the system is operating as designed. Treatment system operation has been suspended in recent years due to a discharge permit issue, but are estimated to be re-started in 2024.

Investigation of the Former Frank Ortiz Landfill, City of Santa Fe, NM. 2016 – Present. *Project Manager.* The Frank Ortiz Landfill operated as a City of Santa Fe municipal landfill between 1954 to 1968. Since no solid waste management regulations were in place during this period of operation, the landfill is not regulated by the NMED Solid Waste Bureau. The landfill site was re-developed by the city with soccer fields from 1987 to 1993 and currently serves as a dog park. In April 1993, soil vapor samples were collected from the fill and soil cover areas. Laboratory analysis of the samples showed that they contained hydrocarbons, chlorinated solvents, and chlorinated solvent degradation products. Concentrations of some of the contaminants exceeded 1,000 parts per billion. A single groundwater monitoring well (Ortiz Park No. 1) was installed approximately 500 feet southwest of the landfill in 2004. A groundwater sample collected from the well indicated that groundwater had been impacted from VOCs, hydrocarbons, metals, and nitrogen believed to have originated at the landfill site. Periodic groundwater and soil vapor sampling have continued at the site since 2004. An S1AP was developed for the Site in 2010 and submitted to NMED for review and approval. In 2013, NMED issued a letter noting several deficiencies in the S1AP including: the lack of a plan for maintenance of a two-foot cap over the former landfill; inadequate definition of the nature and extent of the landfill waste; inadequate definition of contaminant concentrations in the vadose zone below the waste; inadequate definition of the potential contaminant impacts to groundwater; the lack of a long-term monitoring program; and the need for a quality assurance project plan, health and safety plan, and a schedule for implementing the additional investigation activities and analyses necessary to address the identified deficiencies.

In 2015, at the request of NMED, the City conducted a geophysical investigation to define the areal extent of buried waste at the landfill. INTERA was awarded a contract from the City in September 2016 to help address the remaining S1AP deficiencies. Helped develop and reviewed an integrated Sampling and Analysis Plan (SAP)/Quality Assurance Project Plan (QAPP) for the former landfill that was submitted to and approved by NMED. The SAP outlined several steps for the City to address the noted NMED concerns, including: installation of test pits to determine type and extent of waste; the collection of soil samples to determine the impact to soil immediately below the buried waste (extent of contamination in the vadose zone); installation of groundwater monitoring wells; groundwater sample collection; and an approach for a long-term groundwater monitoring program. Field sampling activities associated with the SAP/QAPP were completed in July 2017. Met with the NMED to go over the report findings and discuss recommendations for next steps. The investigation revealed the approximate extent and depth of buried waste, determined the extent of the vapor plume, and provided information on the landfill cover content and thickness. To address NMED's final concern, additional groundwater monitoring wells co-located with three soil vapor monitoring wells and an additional soil vapor monitoring well were recommended and the approximate locations were determined.

The additional wells were installed at the Ortiz Landfill in late 2019 and early 2020 and a final report was submitted to by INTERA to NMED in May 2020. The report findings indicated a direct impact to Site soil vapor likely from the presence of the buried waste, but it appears that Site groundwater is largely unimpacted. INTERA has successfully negotiated with NMED a period of monitoring work for the three years and includes the addition of Surface Emission Monitoring (SEM) on a quarterly basis of the entire Ortiz Landfill property (historic fill area and adjacent land within the property boundary). Once this period has expired, Mr. Tracy will work with City and NMED representatives to determine the need and location(s) for any future additional groundwater and soil vapor monitoring well installations.

The INTERA former Frank Ortiz Landfill work is being conducted in concert with additional investigation and monitoring activities at the adjacent Paseo de Vista (PDV) Landfill. The monitoring and maintenance of the PDV Landfill was added to the INTERA Ortiz Landfill contract by the City in 2019. The work at PDV has largely been conducted by personnel from INTERA's partner, Parkhill, under INTERA oversight. All PDV deliverables are prepared by Parkhill and reviewed by Mr. Tracy prior to submittal to the City and NMED. Mr. Tracy currently leads the long-term monitoring (LTM) activities at both landfills on behalf of the City and manages subcontractor Parkhill. The City of Santa Fe has requested that INTERA assist with NMED updated S1AP activities which are scheduled to begin in July 2025. This will consist of the installation of an additional ground water monitoring well, several LFG monitoring wells, and sampling ground water for PFAS in addition to the required analysis suite.

North Railroad Avenue Plume Superfund Project, New Mexico Environment Department - Groundwater Quality Bureau, Española, NM. 2016 – Present. *Project Principal*. A bio-amendment injection event was performed to remediate residual contamination (tetrachloroethene [PCE] and daughter products) in discrete intervals of fine-grained material identified in the source area (SA) and hot spot (HS) of the site. INTERA evaluated available data, identified six treatment areas, determined targeted treatment intervals, selected emulsified soybean oil as the carbon substrate, and devised an injection method to ensure that the substrate is delivered precisely. INTERA oversaw the bio-amendment substrate injection event which was conducted in two separate events: the first was completed in April 2017 via a direct-push injection tool within sonic casing and the second event was conducted with direct sonic injection in September 2017. INTERA conducted follow-up performance groundwater monitoring. Results of the performance monitoring events confirmed the successful distribution of the carbon substrate through the presence of the dye tracer (Rhodamine WT) and elevated total organic carbon (TOC) in monitoring wells within the anticipated radius of influence (ROI). Additionally, the groundwater analytical results from the first performance monitoring event provided evidence that in-situ reductive dichlorination was enhanced through the injection of the carbon substrate. Performance monitoring is currently ongoing. Serves as a Project Principal for INTERA's NMED contract, which includes INTERA's work at the NRAP site as well as INTERA's work at the Eagle Picher site in Socorro, New Mexico.

Former Central Works Equipment Facility Remediation Activities "COA Rail Yards," City of Albuquerque, NM. 2006 – Present. *Project Manager.* Managed the removal of contaminated soil at the former Central Works Equipment (CWE) facility in Albuquerque, New Mexico. The project included the removal of approximately 600 cubic yards of lead-contaminated soil previously stockpiled at the site. Developed a Work Plan to investigate petroleum-hydrocarbon and metals contamination at this site using Targeted Brownfields Assessment (TBA) funding. Led an additional Phase II investigation at the site in 2012. The Phase II investigation consisted of surface and subsurface soil sampling, building sub-slab vapor sampling, and groundwater sampling. This effort was conducted to determine what impacts (if any) the historical operations of the site as a railyard would have on future redevelopment. It was determined that a petroleum-hydrocarbon plume was present at the southwest corner of the site. Limited impacts were present in surface and subsurface soils. Developed several cost estimates for the remediation of soil and groundwater at the site for the city to use depending on the redevelopment scenario they selected. Further site investigation work was completed in 2012 as the city moved toward redevelopment of the site. Served as Project Manager for an Additional Site Investigation (ASI) that included completing a data evaluation/remediation options document to compile and analyze all existing contaminant data for the entire city railyard, which included former tank areas, oil/water separator, and a former locomotive roundhouse, among others. The evaluation resulted in identifying several data gaps which were investigated during the ASI. Contaminants of concern for this site included VOCs, TPH, PAHs, lead, and arsenic. The site investigation included (1) collecting surface soil samples from thirteen locations, (2) drilling oversight of 18 soil borings using direct push technology methods, (3) collection and screening of soils samples using a photoionization detector (PID) and Dexsil PetroFLAG field test kit to aid in selection of samples for laboratory analysis, (4) collection of eleven groundwater samples with the SP-16 sampler, temporary monitoring wells, and

existing monitoring wells, (5) installation of a soil vapor sample point, and (6) collection of a soil vapor sample using a Vapor PinTM. INTERA provided the client with a completed report, which included several remediation scenarios based on various redevelopment options.

Oversaw the remediation of the Blacksmith Shop building at the CWE facility in 2013. The remediation work consisted of the abatement of asbestos as well as the encapsulation of lead-based paint on the ceiling of the Blacksmith Shop. The Blacksmith Shop was redeveloped by COA into an open-air market following remediation activities. The redeveloped Blacksmith Shop opened in June 2013.

Worked with the COA selected developer, Samitaur, on a VRP approach for all portions of the Railyard property. This included a multi-option remediation approach as several redevelopment options (residential, commercial, open space) will be implemented at the site. Oversaw the development of a CSM for the site. INTERA compiled all available information related to environmental site conditions such as historical soil and groundwater data to help determine the nature and extent of the contamination across the site with regard to depth and COCs in the CSM to provide a foundation for remedial action decisions. Activities completed as part of the CSM included developing a database in Microsoft Access, connecting the database to ArcGIS to allow for visual data analysis, and identifying key data gaps. The CSM was also used as a foundation for development of a remediation work plan required to address data gaps at the site. The remediation work plan was developed in conjunction with potential redevelopment scenarios identified for the site. Implementation of the remediation work plan was completed early 2017 and included the collection of soil samples, soil vapor samples, groundwater samples, sub-slab soil vapor samples, and the completion of asbestos and lead-based paint surveys on all site buildings. The results of the data collection were compiled into ten different reports, one for each of the 10 railyard parcels. The intent of separate reporting for each of the 10 parcels was to allow phased development of the site over a lengthier time period than is customary under the VRP.

Contracted in late 2018 to develop a revised VRP Application and Preliminary Work Plan for the COA Rail Yards, splitting the COA Rail Yards into two VRP sites (COA Rail Yards North and COA Rail Yards South). Currently, the COA Rail Yards North has received conditional eligibility to enter the VRP and Public Notice and a Public Meeting was held in April 2019 to outline for the public the proposed remedial actions. Assisted with the Public Notice requirements for the COA Environmental Health Department personnel. The COA implemented soil removal activities within the COA Rail Yards North in May and June 2019.

Contracted in early 2020 to help the COA develop a VRCR for the COA Rail Yards North and to implement an off-Site groundwater monitoring well installation Preliminary Work Plan for the COA Rail Yards South. INTERA developed a VRCR for the COA Rail Yards North and submitted it to NMED in September 2020. INTERA also, as requested by the COA, developed, submitted to NMED, and received NMED approval for a Contaminated Soil Management Plan (SMP) in July 2020. This SMP will be followed as additional impacted soil is excavated at the COA Rail Yards. Either developed or provided final review of this documents. INTERA installed 5 ground water monitoring wells at off-site locations surrounding the COA Rail Yards South. These monitoring wells were installed in February 2021. Provided interface with the client during the field work and also provided daily direction to the INTERA field team. Finally, INTERA will work with the COA's Rail Yards management team to develop the remediation approaches for the COA Rail Yards South depending on the selected future development. Secured a VRP CCOC for the Rail Yards North in 2021. Currently leading the LTM activities associated with ground water and soil vapor at the Site and leading efforts to secure a CCOC for the Rail Yards South. In addition to LTM activities, currently providing quality assurance inspections for the installation of a soil vapor mitigation system in the Boiler Shop, prior to it's redevelopment as a movie studio for CNM (abqrailyards.com).

Technical Support Services for the Red Hill Bulk Fuel Storage Facility, Honolulu Board of Water Supply, Honolulu, HI. 2015 – Present.
Project Manager. Providing third-party technical review of technical documents and data produced and collected by the U.S. Navy and its contractors at the Red Hill Bulk Fuel Storage Facility (RHBFSF). The RHBFSF contains 20 large field-constructed underground storage tanks, each containing approximately 12.5 million gallons of fuel. These tanks are located at depths ranging from 120 to 175 feet below ground surface within the Koolau Basalt and lie 100 feet above the aquifer. Fuel leaks from the facility both historic and recent (January 2014 – 27,000-gallon release) have impacted the underlying EPA-designated Sole Source Southern Oahu Basal Aquifer and are potentially threatening the Honolulu Board of Water Supply (BWS) water supply wells and production shaft. The 2014 release resulted in the Navy, the EPA, and the Hawaii Department of Health (DOH) signing an Administrative Order on Consent (AOC) to assess the RHBFSF and determine what impact this release and previous releases have had on the environment and to determine what the appropriate tank

upgrade solution may be. Activities included reviewing technical reports and extracting and compiling data collected at the RHBFSF from these reports. Reviewed and provided over 135 comment letters to date to the DOH and the EPA on various Navy work plans and reports. Led the INTERA Team's development of a CSM that describes the processes and features controlling the migration of fuel contamination and identifies potential exposure pathways and receptors. Additionally, supported the development of a Monitoring Well Construction and Installation Plan, sampling plan, and quality assurance plan for several sentinel wells installed by INTERA for the BWS. The first monitoring well was completed in 2017, and quarterly groundwater monitoring was in 2017 and 2018. Semi-annual sampling of this monitoring well began in 2019 and continues in 2021. Hired Exponent as a subcontractor and oversee their technical work associated with tank infrastructure, release detection, corrosion and metal fatigue, risk assessment, and toxicology services. This expertise has been needed on various comment letters developed by INTERA for the BWS since the initiation of the contract. Representing BWS interest in numerous technical working meetings associated with the Red Hill AOC and the AOC Statement of Work (SOW) since contract initiation in 2015. Participates in Groundwater Modeling Working Group meetings to review the progress of the Navy's flow and transport groundwater model. Assists the BWS with the development of community meeting and BWS Board presentations and regularly attends all public meetings in California and/or Hawaii held by the EPA, DOH, and the Navy on the Red Hill matter. Negotiated a 2020 contract renewal with BWS that extended INTERA's work on this project for the next several years.

Led INTERA's efforts in 2021 and 2022 to support the BWS in response to the Red Hill Hawaii Department of Health (DOH) Emergency Order which requires the complete defueling of the facility by June 2024 (defueling was completed by the Navy in March 2024). These efforts have included reviewing and commenting on Navy deliverables (Defueling Plan, Closure Plan, Notice of Intent [NOI] data reports, groundwater flow model reports, etc.) and providing this information to BWS. In addition, because of the May and November 2021 fuel releases at Red Hill, the BWS has been forced to shut down several drinking water sources in the area. Mr. Tracy is currently focused on supporting the BWS with the identification of monitoring well and exploratory production well sites and working with the INTERA Project Team to design each monitoring and exploratory well and exploratory well pumping tests. INTERA has developed well designs for over ten monitoring wells and four exploratory well locations and is currently developing the drilling plans and testing plans associated with these wells. Assisting the BWS with the development of bid documents to procure drilling services for monitoring and exploratory well installations. Providing management and scheduling assistance for INTERA field teams overseeing well installation activities by BWS general and drilling contractors.

Sites Assessments, New Mexico Department of Transportation, Various Locations, NM. 2015 – Present. *Principal in Charge.* Provides senior technical review of Initial Site Assessments (ISAs), preliminary site investigations (PSIs) and Detailed Site Investigations (DSI) at several NMDOT construction project sites in New Mexico. These NMDOT projects involve the evaluation of properties either NMDOT-owned or NMDOT right-of-way (ROW) acquisitions as part of highway improvement projects. The ISAs completed generally follow the ASTM Standard E1527-13 and the NMDOT Handbook for site assessments. The PSIs and DSI include Phase II activities (investigative excavations, soil boring drilling, soil sampling, and geophysical surveys) for further evaluation of NMDOT property. Supervises the field teams conducting this work and provides senior technical review of all project deliverables. Manages overall contract issues and interfaces directly with the INTERA Project Manager and NMDOT management. Most of these assessments are completed in areas where NMDOT is going to expand their infrastructure with either additional traffic lanes or an upgrading of their maintenance yards.

Site Monitoring and Emergency Response Contract, New Mexico Environment Department - Petroleum Storage Tank Bureau, Various Locations, NM. 2014 – Present. *Project Principal.* Providing administrative and technical review of work conducted for contaminant characterization investigations and groundwater monitoring activities. These activities seek to determine the nature and extent of subsurface petroleum hydrocarbon contamination originating from above ground and underground storage tank sites. Investigations include the analysis of soil, groundwater, and soil vapor impacts to these various sites across New Mexico. Work includes the following partial listing of INTERA Petroleum Storage Tank Bureau (PSTB) state-led sites: Barelas Bridge Site in Albuquerque, New Mexico; Bell Gas Site in Truth or Consequences, New Mexico; Brewer Self-Serve Site in Roswell, New Mexico; City Market Site in San Miquel, New Mexico; Frank's Conoco Site in Bernalillo, New Mexico; Corrales Chevron in Corrales, New Mexico; Robinson Texaco in Taos, New Mexico; Rodgers Drilling Site in Albuquerque, New Mexico; Village Market and the Former Caldwell Motors sites in Belen, New Mexico; and the Montoya Well Site in El Prado, New Mexico.

Dry Cleaning Site Investigation and Remediation of Tetrachloroethene Contamination, Elite Laundry and Cleaning, Gallup, NM. 2013 – Present. *Project Manager.* Leading efforts to investigate and remediate groundwater impacted by PCE as a result of previous releases from this operating dry-cleaning facility. The impacted groundwater was discovered during a Phase II ESA conducted on an adjacent property. In response to a letter from NMED to address the contamination, efforts have included providing technical support and advice to Elite Laundry and Cleaners representatives to determine the most appropriate path forward. This included addressing the identified contamination under the NMED VRP. Prepared and submitted a VRP work plan and VRP application to NMED. The proposed VRP investigation activities include the installation of monitoring well on- and offsite to characterize and delineate the PCE in groundwater contamination. The field activities identified in the VRP Work Plan were initiated in late 2018 and early 2019, which included the installation of additional monitoring wells as well as subsurface soil and indoor air vapor sampling activities. Off-site passive vapor sampling activities were completed by INTERA under Mr. Tracy's oversight at the Site and within the area in 2020. Additional site characterization activities and preliminary design for a remediation system to prevent the off-site migration of contaminants in soil vapor and ground water are planned for 2025, including the installation of a soil vapor extraction system for the removal of VOCs in soil gas to prevent the potential for offsite migration.

Judge Steve Herrera Judicial Complex Site Investigation, Remediation, and Monitoring, Santa Fe County, NM. 2009 – Present. *Contract Manager and Project Manager.* Leads INTERA's efforts to develop a remedial solution for the Santa Fe County Judicial Complex which involves interfacing with both the NMED VRP and PSTB. INTERA was contracted by Santa Fe County in March 2009 to support their efforts to re-develop a Brownfields property comprising a three-story judicial complex and associated plaza and subsurface parking garage in downtown Santa Fe, New Mexico. A large excavation and steel/wood shoring system was constructed beginning in the fall of 2008. During shoring activities, a two-foot layer of LNAPL was discovered near the water table. INTERA performed additional site investigation activities and determined that the LNAPL plume was predominately present in the proposed location of a subsurface two-story parking garage. Construction of the garage and associated judicial complex was delayed, enabling the county and NMED's PSTB to develop an appropriate response action. PSTB subsequently designed and is operating a soil vapor extraction system for the areas outside of the judicial complex excavation to remediate the historic contamination. The county was responsible for the remediation of their property even though they were not a responsible party. Led the development of a petroleum contaminated soil (PCS) work plan including development of a dewatering plan, excavation and removal of over 20,000 tons of PCS, installation of a vapor intrusion/ground water barrier (liner) on all parts of the development located below grade, and development of a vapor monitoring system for the final development of the site. The Work Plan was approved by VRP and PSTB. The excavation work is complicated because of two primary factors: (1) soil must be excavated below the water table requiring dewatering for safe removal; and (2) construction activities are scheduled to take place immediately following soil remediation efforts, requiring that dewatering continue for several months until construction infrastructure can be put in place below the water table for the two-story parking garage. Helped initiate the development of a soil gas passive venting system around the subsurface parking garage and initiated the installation of this system in January 2012.

Additionally, prepared and submitted a VRP application to secure a certificate of completion for the remediation work; supervised risk assessors in the development of a document pertaining to future building occupancy and currently participates in numerous stakeholder meetings with the county and PSTB representatives. Either conducted or supervised INTERA staff employees or subcontractors in assessing, reviewing, and selecting mitigation measures for the complex; identifying and developing measures to isolate the proposed infrastructure from contacting LNAPL remaining in the plume around the building (i.e. liner selection process); LNAPL sampling and characterization; air emissions testing and permitting; waste profiling; preparation and submittal of a groundwater discharge permit application; LNAPL removal and disposal; LNAPL bail-down testing; a Phase I ESA of the site; slug testing to determine aquifer properties; weekly VRP update reporting, and subcontractor oversight of remediation activities. The PCS removal activities were completed at the site in February 2011. Continues to work with the county to develop a VRP Completion Report and secure a CCOC for the site. The judicial complex was completed in February 2013 and began operating in June 2013. Continues to oversee quarterly groundwater monitoring activities at the site as part of the county's VRP Work Plan. Secured a Voluntary Remediation Agreement (VRA) for the site on July 9, 2015. Completed the Voluntary Remediation Completion Report (VRCR) for the site in February 2016 and assisted the county in obtaining a VRP CCOC from NMED also in February 2016. Groundwater monitoring activities were completed by INTERA at the site in October 2016. Currently assisting the county by reviewing the work conducted by the PSTB at the site and providing status reports to the county. For example, observed multi-dual phase extraction activities conducted by PSTB and their contractor at the site in 2017. The final goal is to assist the county in

securing a VRP CCOC with only a land use restriction in 2024. Helped the County discontinue the NMED judicial complex discharge permit (NMED DP-1747) in late 2023 and currently negotiating on the County's behalf with NMED to modify the VRP CCOC in 2025.

SunZia Transmission Line Phase I Environmental Site Assessment, New Mexico and Arizona Approximate 550-Mile Corridor. 2021 – 2024. *Project Principal*. INTERA was retained by SunZia Transmission, LLC located in Albuquerque, New Mexico to perform a Phase I ESA for a 550-mile corridor starting southeast of Phoenix, Arizona and terminating in Corona, New Mexico. The proposed transmission line would ultimately aid in the transportation of wind farm produced electricity across New Mexico and into the Tucson area of Arizona. Provided Project Principal review and contract management duties for the project. Worked with the Project Team to develop Phase II site characterization goals for the recognized environmental conditions (RECs) identified during the Phase I ESA work. The Phase II recommendations included geophysical surveys for two former bombing ranges that the Project Corridor intersects in New Mexico and for soil cleanup of an above-ground storage tank release at a commercial agriculture operation at a property in Arizona. The geophysical investigations for the two former bombing ranges were completed in 2023 (no mitigation needed) and the soil cleanup for the Arizona commercial agriculture operation is scheduled to be conducted in 2024.

Data Gap Monitoring Well for the Albuquerque Bernalillo County Water Utility Authority, Albuquerque, NM. 2022 – 2023. *Project Manager.* The Albuquerque Bernalillo County Water Utility Authority (ABCWUA) received funding from the State of New Mexico CPB in 2021 to drill, install, and sample a monitoring well downgradient of the ethylene dibromide (EDB) and petroleum hydrocarbon plumes in groundwater migrating offsite from Kirtland Air Force Base (KAFB). Provided technical input on recommended location and design of a >500-ft deep monitoring well to address a potential data gap toward the distal end of the known EDB plume. Led the installation of the monitoring well (sonic drilling methods) and initial well development which was completed in April 2022. Led initial one-year long-term monitoring activities of the data gap monitoring well in late 2022 and early 2023 until the LTM duties were shifted from INTERA to an ABCWUA on-call contractor.

Kirtland Air Force Base Environmental Baseline Surveys, Albuquerque Bernalillo County Water Utility Authority, NM. 2018 – 2022. *Project Principal.* Provided technical oversight and review of final deliverables for the INTERA effort to conduct two Environmental Baseline Surveys (EBS) for the ABCWUA to meet appropriate property due diligence practices for the easement agreement between ABCWUA and KAFB. The property locations included a 5.29-mile-long easement and a 24-acre parcel, all located on KAFB and Department of Energy (DOE) property. The project includes the ABCWUA installing an interceptor pipeline and booster station and INTERA is responsible for all federal due diligence requirements associated with construction projects occurring on federal facilities. Responsible for internal team communications, client meetings, and final review of the two EBS reports. The EBS reports were completed and approved by the ABCWUA and KAFB in 2022.

Phase I Environmental Site Assessment of Mt. Chalchihuitl and Cerrillos Gravel Products Properties, Santa Fe County, Cerrillos, NM. 2004 – 2022. *Project Manager.* Project Manager for the Phase I ESA of the combined 745-acre Mt. Chalchihuitl and Cerrillos Gravel Products properties. Assessment activities are being conducted using the EPA's All Appropriate Inquiry (AAI) and ASTM Standard E1527-05 as guidance. Performed risk assessment and remediation alternative analysis activities at the Mt. Chalchihuitl portion of the site (545 acres) in 2004. The entire site was historically used for mining activities, located at the center of the Cerrillos Mining District South area. Santa Fe County plans to re-develop the site as open space by incorporating it into the Cerrillos Hills Historic Park, and INTERA continues to work with Santa Fe County to determine remediation options for the site. The development objective is to include these properties in the Cerrillos Hills Mining District Open Space Park.

Developed a VRP Work Plan for the site in 2012, which selected a previously determined remedial option and submitted the Work Plan to Santa Fe County for review. The selected remediation includes the construction of tailings impoundment and cap in a former gravel pit and long-term monitoring to make certain the cap integrity is secured. The remainder of the site will be used as a public open space, allowing the public to observe some of the oldest mines in North America. Completed and submitted the VRP Application and Preliminary VRP Work Plan for this Site in September 2017. The county would like to acquire the properties in 2018 and begin soil remediation as soon as possible after property acquisition. Currently assisting the county legal team with the development of a VRA between the county and NMED. Also, were recently awarded a contract to sample soils in the arroyo to the south of the Cerrillos Gravel Products property and to sample three area drinking water wells to determine any potential water quality impacts.

Responded to a Letter of Interest (LOI) released by the County in 2019 to assess ground water conditions at the Mt. Chal site. After selection by the County in response to the LOI, led the INTERA Team in sampling an upgradient private water well and a monitoring well at the Cerrillos Gravel Products property. Determined elevated metals concentrations are present in site groundwater and offered recommendation to the County for addition work at the site and the potential installation of a new monitoring well in a down gradient location. Due to a disagreement on overall value with the landowner (both property and mineral rights), the County passed a resolution and discontinued their Mt. Chalchihuitl acquisition initiatives in 2022.

Redevelopment of the Former First Baptist Church Site, Lobo Development, Albuquerque, NM. 2013 – 2021. *Project Manager.* Provided oversight for voluntary remediation activities associated with redevelopment of this property in downtown Albuquerque. Previously conducted Phase I and II ESAs and identified subsurface soil and groundwater contamination that was believed to be the result of a diesel fuel release at the adjacent Burlington Northern Santa Fe (BNSF) Railway Railyard. Evaluated site investigation data and determined that the property had been impacted by both off-site sources and historic site uses that required limited remediation prior to site redevelopment. The site was entered in the NMED VRP to secure a Certification of Completion (COC) to facilitate redevelopment. Activities included interaction with NMED to ensure the COC was issued in a timely manner and assisting in obtaining a Covenant Not to Sue (CNS). After receiving the COC and CNS, Lobo Development acquired the property in 2014 and the site was re-developed as part of the City of Albuquerque's "Innovate ABQ" development initiative. Worked with the Innovate ABQ development team to manage the environmental risks associated with the planned redevelopment of the Site. Assisted the Site developer (Signet) with renovation and demolition activities completed within the former First Baptist Church in 2016. Assisted the developer with VRP reporting activities in 2016, 2017, and 2018 associated with the construction of a three-story building at the site. VRP reporting activities are required in order to maintain the COC by guiding the developer to implement the proper engineering controls. The newly constructed three-story commercial building is known as the "Lobo Rainforest" and serves as an entrepreneur center for business associated with "Innovate ABQ," a downtown Albuquerque technology park. Led a team that updated the Phase I ESA in 2020 on behalf of the University of New Mexico (UNM). Also helped secure a U.S. Environmental Protection Agency (EPA) "Comfort Letter" for UNM and a CNS prior to the property transfer. UNM assumed ownership of the site in late December 2020.

Redevelopment of the Former Galles Chevrolet Automobile Dealership Property, University of New Mexico, Albuquerque, NM. 2018 – 2020. *Project Manager.* Provided oversight for voluntary remediation activities associated with redevelopment of this property in the UNM area of Albuquerque. Previously conducted Phase I and II ESAs identified subsurface soil and groundwater contamination that was believed to be the result of gasoline and diesel fuel releases from former underground storage tanks (USTs) located at the property. Additional environmental contamination was also identified by the operation of over 70 underground hydraulic lifts as well as five former oil/water separators (OWS) in use at the property. Evaluated site investigation data and determined that the property has been impacted by historic site uses that required limited remediation prior to site redevelopment. The site was entered in the NMED VRP to secure a COC to facilitate redevelopment. Activities included interaction with the NMED to ensure the COC was issued in a timely manner and assisting in obtaining a CNS. The issuance of the COC and CNS are still pending. Conducted an on-site soil vapor survey to determine areas of elevated soil vapor concentrations and developed a plan for the construction and use of vapor intrusion barriers for any newly constructed buildings at the Site. Evaluated the remediation activities conducted by the landowner (Sandia Corporation) to determine what impact, if any, the remedial work may have on future UNM activities at the site. Worked with subcontractor DC Environmental to prepare a cost estimate associated with the asbestos and lead-based paint abatement at current Site buildings prior to demolition and/or renovation. UNM leased the property in late 2019. Worked with UNM Medical Center personnel to assist with the development of short-term uses for the site prior to full-scale redevelopment.

Investigation of the Santa Fe River Targeted Brownfields Assessment Area, City of Santa Fe, NM. 2010 – 2019. *Project Manager.* Led an investigation in the downtown Santa Fe area to (1) develop a better understanding of groundwater flow within the area so that appropriate decisions can be made about remediation of petroleum hydrocarbons and other groundwater contaminants, (2) determine what impact, if any, will occur within the shallow groundwater aquifer if stream flow in the Santa Fe River is increased, and (3) determine the nature and extent of petroleum hydrocarbon contamination so engineering controls can be evaluated for future development within the TBA area. Activities included developing a geologic model and implementing a drilling program to confirm model accuracy. Field investigations showed that the

geologic model is accurate, and the City of Santa Fe and NMED used the geologic model to guide additional investigations being conducted by NMED and EPA in the downtown Santa Fe area. These investigations were completed to identify sources of petroleum hydrocarbon as well as chlorinated hydrocarbon contamination in ground water in the downtown Santa Fe area. Activities in 2016 and 2017 included the installation of additional groundwater monitoring wells, groundwater sampling, installation of soil vapor monitoring wells, soil vapor sampling, indoor air sampling, and groundwater sampling of additional monitoring wells owned by several different entities in the downtown Santa Fe area to determine groundwater characteristics and the potential sources of identified contamination. Subsurface soil gas sampling was conducted at this Site in June 2019 using "Waterloo Membrane Samplers" placed at several facilities within the TBA area that may have been sources of the underlying ground water contamination. Helped NMED develop a report for the 2019 sampling event and discussed the findings with NMED.

Proposed Belen Fire Station Property Investigation and Remediation, Molzen Corbin, Belen, NM. 2017 – 2018. *Project Manager.* Supervised Site investigation and remediation services at the proposed new Belen Fire Station property located in Belen, New Mexico. Prior to site redevelopment activities, Molzen Corbin Engineers contracted INTERA to conduct site investigation activities to determine if any impact from petroleum hydrocarbons occurred at the Site during historical activities (automobile repair activities) and to conduct geophysical investigation work to determine if any relic USTs were present at the site. INTERA advanced 15 soil borings at the site using geoprobe investigation methods to collect soil and groundwater samples. Investigation results determined that approximately 2,800 cubic yards of PCS were present at the site and one UST was in the northwest corner of the property. INTERA provided a map of the locations of the PCS and the UST. The PCS and UST were removed by City of Belen contractors in 2017. In addition, groundwater impacts by petroleum hydrocarbons were also verified, but no concentrations identified were above New Mexico Water Quality Control Commission (NMWQCC) standards or PSTB action levels. Continued to provide consulting services to Molzen Corbin at the Site as Fire Station building construction was initiated in 2017. INTERA recommended removal of the PCS and installation of a vapor intrusion barrier and sub-slab venting system to protect future building occupants and Site users. INTERA developed specification documents for both PCS removal and vapor intrusion barrier installation and provided to Molzen Corbin Engineers to include in the general contractor bid package. Construction of the Belen Fire Station was completed in 2018. The Belen Fire Station redevelopment project received the "Environmental" award from the New Mexico Chapter of the American Council of Engineering Companies in September 2020.

Investigation of Perchloroethylene Contamination at the Griggs and Walnut Superfund Site, Confidential Client, Las Cruces, NM. 2015 – 2018. *Senior Scientist.* Assisted the technical team evaluating the release timing and locations of PCE contamination in the area of the Griggs Street and Walnut Avenue intersection in the northern section of the City of Las Cruces. The timing information was critical in demonstrating occurrences for insurance reimbursement purposes. Assisted in the development of the CSM for the potential release sites in the area. The CSM would be used by Dona Ana County and the City to help further their understanding of the Superfund site.

Facility Environmental Audits and Stormwater Management Plans, Wood Group/TurboCare Generator Services/Ethos Energy, Farmington, NM. 2010 – 2018. *Project Manager.* Performed environmental audits of three electric generator parts manufacturing facilities, focused on determining volumes of hazardous waste generated at each facility. Reviewed information to calculate volumes to determine the correct generator status (conditionally exempt, small or large), obtain a correct hazardous waste generator identification number, and calculate and pay the associated hazardous waste fees to the NMED Hazardous Waste Bureau for each facility. After calculating these volumes, the Wood Group reported previous quantities of generated waste and paid current and past hazardous waste-generation fees, bringing the facilities back into regulatory compliance. Prepared stormwater pollution protection plans (SWPPPs) for each facility and provided ongoing support with stormwater issues. Due to facility operator transfer and the closing of the two of the facilities, worked with INTERA staff in 2017 and 2018 to update the SWPPP and file Notice of Termination of discharge and NOI to discharge for the new ownership group (Ethos Energy).

Reclamation of the San Vicente Mill Site, New Mexico Environment Department, Silver City, NM. 2013 – 2016. *Project Manager.* Led environmental investigation and remediation/reclamation activities to address an above-grade tailings pile, resulting from former milling and smelting operations for lead, silver, copper, and gold that operated from the 1880s to the 1940s. The tailings pile contained metals (e.g., arsenic and lead) at levels exceeding established human health standards. Water quality had been impacted by the erosion of the tailings pile and the subsequent transport of contaminated material to an adjacent creek. Groundwater also contains elevated concentrations of metals. Project activities included negotiating access

agreements, as portions of the site were on private property; determining the extent of tailings and contaminated soils on-site and offsite; organizing and holding a community meeting to inform property owners as well as Town of Silver City representatives and citizens of potential community impacts; providing contractor oversight for removal of contaminated materials (approximately 50,000 cubic yards); transporting and disposing of contaminated materials at a nearby operational mine site; restoring disturbed areas with placement of soil cover; and reseeding with a native seed mixture. Implemented a reclamation approach that included performing additional characterization efforts while removal of the main tailings area material was being conducted. The single mobilization resulted in cost savings and a project that was completed ahead of schedule. Responsible for developing the Final Removal Assessment Report which documented the quantity of tailings removed and the restoration activities including clean fill placement, grading, and institution of property engineering controls.

Environmental Site Assessments, Los Alamos County, NM. 2005 – 2016. *Contract Manager and Project Manager.* Served as Contract Manager for Los Alamos On-Call Services contract. Investigated and characterized the environmental conditions at several Los Alamos County and Los Alamos School District properties. These properties were formerly operated by Los Alamos National Laboratory. Currently managing this work, which includes Phase I and Phase II ESAs, asbestos and lead-based paint surveys, archaeological investigations, archaeological stabilization activities, surface water sampling, and other general environmental consulting activities. Special projects have included a hazardous materials survey at the Los Alamos County Golf Course, an Environmental Assessment (EA) of the Los Alamos County Canyon Dam site, and a NMED VRP application for the Los Alamos County Trinity Redevelopment site.

Designed and constructed a stormwater detention pond engineering controls at the Trinity Redevelopment site in 2012. The pond was constructed as a solution to an NMED action that required the county to control stormwater runoff into the canyon to the south of the site. Managed the project that included engineering design, construction, and reporting to NMED. Following the construction of the drainage improvement, Los Alamos County began redeveloping the site with a shopping center to include a grocery store, small businesses, and restaurants.

Provided oversight of the removal of a historic OWS from the Trinity Redevelopment Site in 2013. The OWS was discovered during redevelopment construction activities. Secured a subcontractor and provided the county with expedited services during the OWS removal and subsequent sampling so that the construction activities scheduled for the site were not compromised.

Former Eubank Landfill Assessment of Remediation Alternatives, City of Albuquerque/New Mexico Environment Department, NM. 2003 – 2016. *Project Manager.* Led an effort on behalf of the COA and NMED to characterize the nature and extent of landfill gas contamination at the former Eubank Landfill (northeast fill area). Also worked at this site on behalf of Albuquerque Public Schools, an owner of an adjacent property; Bernalillo County, a stakeholder related to the Eubank Landfill; the U.S. Army Corps of Engineers; and the New Mexico State Land Office. The northeast fill area of the former COA Eubank Landfill was operated between 1963 and 1973 on property leased from the New Mexico State Land Office. The Eubank Landfill northeast fill area was unlined and covered approximately 21 acres, with a waste depth in the range of approximately 30 to 40 feet. Material placed at the Eubank Landfill was reported to be mainly residential and commercial waste.

Conducted an assessment of the former Eubank Landfill southwest fill area in 2011 for the proposed future development as a solar panel system field. Worked for a private solar development company along with the COA to evaluate this use of the site and how this use may be impacted by the potential migration of landfill gas. Also worked with INTERA engineers in the development of a final landfill gas management plan as well as a surface grading and drainage plan. In 2012, managed the project, which included additional grading plans for several types of solar panel designs selected for the site. This included the development of a Waste Excavation Plan (WEP). The WEP included the use of waste as fill material, the first of its kind in the State of New Mexico.

Developed an approach for Emcore Solar Power to install and operate a solar panel field at the surface of the former Eubank Landfill southwest fill area. This included LFG investigation activities as well as a geotechnical investigation conducted in order to develop recommendations for landfill gas control measures as well as geotechnical foundation of the solar panel trackers. This work included communicating with civil engineers, architects, electricians, and others to facilitate the successful project. The solar field is currently online and provides power to the Emcore manufacturing facility located

adjacent to the former landfill. Responsible for final reporting and periodic site inspections concerning the condition of the landfill surface.

Hyder Property Site Investigation, City of Albuquerque, NM. 2003 – 2016. *Project Manager.* Developed the investigation work plan at this Brownfield redevelopment property which was the site of a former dry-cleaning facility. The work plan included the execution of a geophysical survey as well as investigative digging to find historic underground solvent storage tanks. Investigative excavations were constructed at the Hyder property, and six USTs were discovered. Conducted a Phase II site investigation at the Hyder property, which included the collection of surface soil, subsurface soil, soil gas, and groundwater samples. Wrote the VRP Completion Report for this site; property received a Certificate of Completion from the NMED VRP. Worked with the site developer, YES Housing, to oversee excavation of soils to determine if contamination was present during construction in late 2014. Site redevelopment as the Imperial Building began in early 2015. Worked with the construction contractor to address environmental contamination (removal of petroleum-contaminated soils and two underground storage tanks) during building excavation and construction work. Submitted the VRCR for the site to NMED in December 2015. Assisted the site developer in securing a CNS from the NMED VRP in early 2016. The Imperial Building includes residential housing on the two upper floors and a community garden on the roof, with commercial spaces (including a grocery store) on the first floor. One level of parking is included in a subsurface parking lot located below the building. The Imperial Building officially opened in September 2016.

500 Copper Square Property Soil Vapor Investigation, First Financial, Albuquerque, NM. 2014 – 2015. *Project Manager.* Led efforts to determine presence of VOCs in site soil vapor. Collected sub-slab soil gas samples at locations within the building basement and compared analytical results to EPA's recommended commercial and residential vapor intrusion screening levels (VISLs) to determine whether VOC contaminants were impacting air quality in the building. Tetrachloroethene (PERC)—a dry cleaning solvent—was present in several of the soil vapor samples, but concentrations did not exceed applicable VISLs for PERC. Entered site into the state VRP in order to obtain a COC to document that current conditions meet applicable environmental quality standards and provide liability protection for lenders. NMED issued at COC in 2015, and a CNS can be transferred to any lender or future owner of the property.

Former Sterling Manufactured Gas Plant Voluntary Cleanup Program Site, Centennial Mental Health Center, Sterling, CO. 2014 – 2015. *Senior Technical Advisor.* Assisted with additional site investigation activities within the VCP investigation and remediation activities at the former Sterling Manufactured Gas Plant site. This site was remediated through the Colorado Department of Public Health and the Environment (CDPHE) VCP for future development into a parking lot for use by the future landowner and neighboring facility, Centennial Mental Health Center. The initial site investigation and targeted brownfields assessment were completed by CDPHE and identified polyaromatic hydrocarbons (PAH) organics and metals contamination above the regulatory limits in the site soils. Project tasks have included potholing of site soils to define further the extent of soil contamination, sampling of an upgradient groundwater monitoring well to determine if metals contamination can be attributed to an off-site source, determination of the most cost-effective method to sample near and around a transformer on site, and completion of the work plan, cost estimate, and health and safety plan for the excavation of site contaminated soils. To accommodate funding schedules, the remediation activities, which consisted of excavation, hauling, and off-site disposal of 814.5 cubic yards of soils contaminated with PAHs, were performed using a phased approach and were completed in 2015. A No Action Determination (NAD) was submitted and formal acceptance of the NAD by CDPHE was received in December 2015.

Characterization and Remediation of the Former Bell Trading Post Property, City of Albuquerque, NM. 2001 – 2005 and 2015. *Project Manager.* Developed a Work Plan to characterize this facility adequately for ultimate inclusion into the VRP. The Bell Trading Post building was formerly a jewelry manufacturing facility as well as a photograph development facility. Heavy metals and solvents were in use at this historic facility. The Work Plan included Geoprobe soil boring installations, subsurface soil sampling, and groundwater sample collection. In addition, on behalf of the COA, supervised a subcontractor conducting a limited asbestos survey at the Bell Trading Post facility building. Completed the VRP Application for this site and developed a VRP Work Plan for the remedial work, which included an integrated QAPP. The remediation consisted of contaminated soil removal as well as the remediation of asbestos and lead-based paint. This was the first Work Plan/QAPP developed for asbestos/lead-based paint remediation in EPA Region VI. Provided oversight of the remediation work and documented the progress on behalf of the COA and its developer, Family Housing Development Corporation. Remediation work completed included the cleaning of a substantial amount of pigeon droppings, asbestos and lead-based paint abatement, lead-in-soil removal, and the removal of all light ballasts from the building. Wrote the VRCR for this facility and

helped the COA obtain a Certificate of Completion from the NMED VRP. This facility was later renovated and developed with residential housing units and commercial office space. Lead a soil vapor intrusion assessment of the renovated building on behalf of the NMED in 2015.

Municipal Separate Storm Sewer System Audit and Application, Santa Fe County, NM. 2012 – 2013. *Project Manager.* Led efforts to assist the county in submitting a municipal separate storm sewer system (MS4) application to the EPA. Reviewed and evaluated documents regarding the history of the MS4 and the NOI Plan; prepared summary report for the county to document current status of the EPA requirements for the MS4 Plan and NOI and define options, deliverables, action items, and schedules/timelines; and helped the county resubmit the MS4 Application to EPA. By working cooperatively with both the county and EPA, helped avoid financial penalties for the county.

Phase I and Phase II Assessments, Northwest New Mexico Council of Governments, Gallup, NM. 2010 – 2013. *Contract Manager and Project Manager.* Contract Manager for Northwest New Mexico Council of Governments (NWNMCOG) On-Call Services contract. This contract was established by the NWNMCOG to evaluate potential Brownfields within the NWNMCOG area (Gallup, San Juan, and Cibola counties). Performed Phase I and Phase II Assessments for the NWNMCOG as part of this contract. Brownfield site characterization activities are the general focus of the contract for those sites located within the NWNMCOG area. Phase II activities conducted under this contract included hollow-stem and air rotary drilling, geophysical survey using electromagnetic (EM) and ground-penetrating radar (GPR) equipment, surface and subsurface soil sampling, groundwater sampling, and investigative excavations using a backhoe.

An example of a NWNMCOG project is the Coal & Puerco Site in Gallup, New Mexico. This site is proposed to be redeveloped with a live/work facility by Community Area Resource Enterprise 66. A dry-cleaning facility is located immediately north of the site. Led INTERA's efforts to investigate the redevelopment site and determine what remedial actions or engineering controls would need to be implemented at the site to although for safe and cost-effective redevelopment. INTERA conducted surface and subsurface soil sampling, soil vapor sampling, and groundwater sampling at the site. PERC was identified in site groundwater and soil vapor. Based on findings of the investigation, recommended that a vapor intrusion barrier be placed below the proposed site building to prevent impacted soil vapor from entering building indoor air. Additionally, worked with the NWNMCOG and NMED to investigate impacts to groundwater in the immediate area surrounding the site and determined that PERC was present in several off-site areas. INTERA is currently working with NMED and the responsible party to determine the vertical and lateral extent of the PCE groundwater plume and determine remedial options.

4407 Lomas Boulevard Site Investigation, Parnell Lomas, Albuquerque, NM. 2012. *Project Manager.* Led a Phase II Site Investigation at this site to determine if former operations as a gasoline service station had negatively impacted soil, soil vapor, or groundwater. The site included an office building and the client was trying to decide whether to purchase the property. After the investigation, it was determined that the site had not been negatively impacted by former operation as a gasoline service station, but that soil vapor was impacted with PCE, most likely from off-site historical dry cleaners. It was concluded that PCE could enter the current office building at levels above EPA screening levels. A proposal was prepared for a vapor mitigation system. Client decided not to purchase the property due to the cost of implementing the vapor mitigation system and associated ongoing monitoring.

Former Tulip Drive Landfill Phase I ESA and Phase II Site Investigation Activities, Luna County, Deming, NM. 2010 – 2012. *Project Manager.* Served as INTERA's Project Manager for the performance of a Phase II ESA performed at the 75-acre tract of land, including the Former Tulip Drive Landfill, located in Deming, Luna County, New Mexico. The Phase II ESA was performed for the county and city using funds provided by the EPA Brownfields Assessment Grant Program. Responsible for the development of a site-specific SAP, which guided field activities. The site was a vacant tract of land owned by the city located southeast of the intersection of New Mexico Highway 26 and U.S. Highway 180, along the Mimbres River. It was the city's and county's intent to redevelop the site as recreational open space; therefore, the objective of the Phase II ESA was twofold: (1) obtain additional information regarding the character of the former Tulip Landfill, such as cover thickness, depths and types of waste, and the extent of the former Tulip Landfill area, and (2) determine if soil and/or groundwater impacts exist from the recognized environmental concerns identified as part of the Phase I ESA completed by INTERA in 2011. INTERA conducted the following Phase II ESA field activities in 2012: (1) investigative excavation of 15 test pits located within the footprint of the former Tulip Drive Landfill, (2) hollow-stem auger (HSA) drilling and sampling of eight shallow exploratory soil borings, (3) HSA drilling and sampling of three deep soil borings, (4) installation and development of three

groundwater monitoring wells (within the deep soil borings), and (5) a single groundwater sampling event. Due to only minimal exceedances of applicable standards in site soil and no exceedances in site groundwater, recommended proceeding with site development upon completion of the following additional remediation/characterization activities:

- Consolidation of the numerous surface litter and debris piles scattered through the vacant lot to within the confines of the former Tulip Drive Landfill
- Preparation of preliminary design and installation of an evapotranspirative cap over the consolidation area to (a) minimize exposure to potentially harmful waste and (b) stabilize waste to deter further offsite transport of site contaminants via surficial processes (i.e., storm water, wind)
- Provision of bank stabilization and erosion control of property land located along the Mimbres River to mitigate the negative effects of progressive undercutting by seasonal surficial processes and help minimize future transport of site contaminants off-site
- Securing the site to prevent future indiscriminate dumping
- Installation of at least one additional ground water monitoring well in the northeast corner of the site to confirm groundwater remained unimpacted by the presence of the landfill
- Completion of one or more additional groundwater sampling events to further assess and monitor groundwater site conditions
- Completion of all additional site remediation/characterization efforts through participation in the NMED VRP.

Hotel La Posada de Albuquerque Redevelopment, City of Albuquerque, NM. 2007 – 2011. *Project Manager.* Developed a QAPP and asbestos specifications for the removal of asbestos from the Hotel La Posada de Albuquerque. Also developed an EE/CA that evaluated the remediation options for the renovation of this historic hotel. Significant quantities of asbestos and lead-based paint were present within La Posada. The EE/CA was used to support the use of the COA Brownfields Cleanup Revolving Loan Fund for a portion of the remediation. Through the EE/CA report, documented the alternative selection process for a non-time-critical removal action that was completed in accordance with 40 CFR 300.415 of the National Oil and Hazardous Substances Pollution Contingency Plan. The Hotel La Posada de Albuquerque was successfully remediated, renovated, and reopened as the Andaluz Hotel in October 2009. Prepared a self-certification document in 2011 that was submitted to the EPA for the voluntary remediation conducted at this building. Site was renamed the "Hotel Andaluz."

Casa Grande Property/El Vado Hotel Phase I Environmental Site Assessment, and Phase II Site Investigation, City of Albuquerque, NM. 2009 – 2010. *Project Manager.* Led an environmental evaluation of the Casa Grande Property on behalf of the COA. The COA proposed redeveloping the Casa Grande Property/El Vado Hotel located at 2500 Central Avenue with mixed use development (residential/commercial) and contracted INTERA to perform a National Environmental Policy Act (NEPA) Environmental Assessment, a Phase I ESA, and a Phase II Site Investigation at the site. The Phase I ESA and Phase II Site Investigation were performed with support from other key INTERA staff members. The Phase I ESA identified a historical property use (gasoline pumps at the El Vado Hotel) and a historic gasoline release at the Casa Grande Chevron located across the street as potential recognized environmental conditions and recommended subsurface soil borings as well as a geophysical investigation be completed at the property. Eight subsurface soil borings were completed at the site in areas believed to have been potentially impacted by historical property and area uses. No impact from petroleum hydrocarbons in soils and/or groundwater was identified. In addition, the geophysical investigation, conducted by Sunbelt Geophysics, did not identify any evidence of abandoned USTs at the site.

Managed the completion of a NEPA Environmental Assessment at the site as prescribed by the lead federal agency, which in this case was the Department of Housing and Urban Development. The EA was completed with support from Parametrix (cultural and biological surveys). The ESA was required to release Community Development Block Grant funds for the property purchase and additional property redevelopment work.

New Mexico Rail Runner Site Assessments, Parsons Brinckerhoff Quade & Douglas, Santa Fe, NM. 2006 – 2009. *Project Manager.* INTERA was retained by Parsons Brinckerhoff Quade & Douglas (PB) in 2006 to perform ISAs for Phase 2 of the Mid-Region Council of Governments/ NMDOT Belen to Santa Fe New Mexico Rail Runner Express Commuter Rail Project. Performed an ISA for the existing BNSF railroad line from Bernalillo to Lamy, New Mexico, and an ISA for the proposed commuter rail line from La Bajada Hill to downtown Santa Fe, New Mexico. Acted as the designated INTERA Project Manager for each ISA

project. The ISA included the assessment of existing railroad lines and facilities (BNSF and Santa Fe Southern), as well as several miles of railroad tracks constructed on undeveloped ranch land to facilitate commuter rail service between Albuquerque and Santa Fe. Project management duties included developing and implementing the schedule for the records reviews, field reconnaissance, and report development. Led field activities for each ISA (the combined assessment length of the two ISA totals over 70 miles) and coordinated with the PB Project Manager, the NMDOT Environmental Geology Section representatives, and NMDOT legal counsel with the finals of each ISA Report. The New Mexico Rail Runner Express began operations in 2009.

Landfill Gas Assessment of Five Formerly City-Owned and/or Operated Landfills, New Mexico Environmental Health Department, Albuquerque, NM. 2003 – 2009. *Contract Manager and Project Manager.* Contract Manager for INTERA's COA landfill gas assessment project. Over 100 landfill gas monitoring wells have been installed to monitor landfill gas migration at five of the COA formerly owned and/or operated solid waste landfills under direction. Managed the landfill gas monitoring well installation and supervised landfill gas sample collection. Other duties conducted include contract budget tracking, future landfill gas monitoring well locating, and landfill gas sample results interpretation. Developed the current COA landfill gas well installation report format as well as the format used for the landfill gas monitoring reports. Also developed landfill management plans to guide development on and adjacent to the former Eubank and San Antonio landfills.

Former Peru Hill Mill Site Phase I Environmental Site Assessment and Phase II Site Investigation and Remediation, New Mexico Environment Department, Deming, NM. 2001 – 2008. *Project Manager.* Performed a Phase I ESA and Phase II Site Investigation of the former Peru Hill Mill mining mill facility in Deming, New Mexico. The Peru Hill Mill primarily processed zinc sulfide ore. Peru Mining Company, a subsidiary of Illinois Zinc Company, constructed the Peru Hill Mill and operated it from 1928 to 1967. Barite of America acquired the facility in 1979 and operated it intermittently until 1985, when the company filed for bankruptcy. Luna County acquired the property in 2001 and deeded it to the City of Deming. The major environmental concerns at the site were uncontained tailings in a 104-acre impoundment and redistributed tailings transported from the impoundment by wind erosion and surface water runoff. The tailings formed dunes around the impoundment that blanketed an area of approximately 161 acres. The total area of the tailings impoundment and redistributed tailings was approximately 265 acres.

Prior to initiating the site investigation, a Phase I ESA was completed at the site. Used the results of the Phase I efforts to complete a work plan and QAPP for the Phase II Site Investigation. Soil sampling results indicated lead, arsenic, and zinc concentrations in surficial soils were in excess of NMED soil screening levels (SSLs). Recommended that surficial soils containing metals concentrations above SSLs be placed within a site tailings impoundment area and that the tailings be capped with soil to prevent further migration by wind and/or water erosion. Secured an engineering firm to design the tailings impoundment cap and a soil consolidation plan. Prior to implementation, the City ultimately used the Phase I ESA report and the information in the site investigation report to submit a VRP application to NMED.

Excavation activities were completed by the City and the tailings were excavated and redistributed to the designated tailings impoundment area. Helped develop a confirmation soil sampling plan to assure that the tailings removal effort was successful. Directed Neptune and Company (subcontractor) in the development of a site-specific remedial action goal for arsenic at the site. Remediation efforts were completed according to plan at Peru Hill Mill and a VRP Completion Report was developed for this facility in 2008. The site received a Conditional Certificate of Completion from VRP in 2009.

Plaza Del Sol Property Site Investigation, City of Albuquerque, NM. 2001 – 2008. *Project Manager.* Led the investigation of this Brownfields redevelopment site, which was believed to be impacted by a historic petroleum hydrocarbon release in the local area. Investigation activities included the preparation of a Phase I ESA, installation of monitoring wells, and groundwater sample collection. Completed additional work at this site on behalf of the COA and private developers in 2008 and developed a VRP Completion Report for the site. The site received a Certificate of Completion from the NMED VRP in 2008 and has since been developed with residential housing.

City of Santa Fe Railyard (including Phillips Petroleum) Brownfields Investigation, City of Santa Fe/New Mexico Environment Department, NM. 2000 – 2008. *Project Manager.* Led several stages of work completed at the City of Santa Fe Railyard for either the City of Santa Fe or the NMED. The work included the development of a Phase I ESA for a 33-acre portion of the site, a preliminary evaluation of groundwater impacts, a subsurface soil clean-up of tar, and the development of a VRP Completion Report. The Phase I ESA focused on identifying more fully potential responsible parties so that the City could consider this information in its Brownfields redevelopment strategies. The City development plan was to redevelop the underutilized

railyard with a railyard park to include open space and trails, green space, and a farmer's market area. A VRP Application and Work Plan were developed by the City and the site was accepted into the VRP.

Construction at the site began in 2006, and tar was discovered in subsurface soils during archaeological excavation work being conducted at the site. Provided the planning and oversight of the removal of subsurface soil containing tar at the site in 2006 and 2007. Developed a report which was submitted to NMED documenting the tar removal activities completed on behalf of the City.

Performed a Phase I ESA at the Phillips Petroleum site, which is located within the Santa Fe Railyard. Completed a VRP application and developed a work plan to address petroleum hydrocarbon contamination in surface soils located at the Phillips Petroleum site. The work plan included additional groundwater monitoring, but no other work was recommended. The Phillips Petroleum site was incorporated into the Santa Fe Railyard Certificate of Completion once the VRP Completion Report was developed and submitted. After receiving a NMED VRP Certificate of Completion and Covenant Not to Sue, this site is now completely redeveloped.

Tender Loving Care Cleaners Phase I Environmental Site Assessment, New Mexico Department of Transportation, Belen, NM. 2006. *Project Manager.* Conducted a Phase I ESA at the former Tender Loving Care (TLC) Dry Cleaning facility located in Belen, New Mexico. Conducted the Phase I ESA to meet the assessment and EPA AAI requirements of the ASTM Standard E1527-05, "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process" and the reporting requirements of the NMDOT 1999 Hazardous Waste Assessment Handbook. The site operated as a dry cleaner under the name "Sunshine Cleaners" from 1987 to 1990 and as TLC Cleaners from approximately 1990 to 1997. NMED conducted a Phase II Site Investigation at the facility and determined that chlorinated solvent contamination was present in subsurface soils and groundwater. The Phase I ESA developed recommended additional sampling to delineate the extent of soil and groundwater contamination. NMDOT ultimately decided not to acquire the property for use as a New Mexico Rail Runner stop.

Former Hillcrest Hospital Facility Site Characterization, New Mexico Environment Department, Silver City, NM. 2004 – 2006. *Project Manager.* Managed the characterization of an abandoned hospital building proposed to be redeveloped as a library. The site characterization included the evaluation of the building for the presence of asbestos and lead-based paint. Additional work included the characterization of site soils for asbestos contamination as well as excavations completed to find an abandoned petroleum storage tank. Developed the QAPP to guide sampling to adequately characterize the facility. Prepared the integrated work plan for the remedial efforts and assisted the Town of Silver City in the selection of a remediation contractor. Managed the remediation work which included asbestos and lead-based paint abatement, as well as a clean-up for pigeon droppings. After successful remediation, the building was demolished and the site was considered ready for redevelopment.

Proposed Rio Grande Silvery Minnow Sanctuary, U.S. Department of Interior - Bureau of Reclamation, Albuquerque, NM. 2005. *Project Manager.* Served as the project manager for a Phase II site investigation evaluating a proposed site for use as a minnow sanctuary. Developed the work plan and provided oversight for the field work consisting of soil, subsurface soil, surface water, and groundwater sampling. Performed an additional site investigation using biological testing of fish to further evaluate the site for suitability as a minnow sanctuary. The site was ultimately selected by the Bureau of Reclamation for the location of the Rio Grande Silvery Minnow Sanctuary.

Phase II Site Investigation and Soil Remediation Activities at Former Araho Well Injection Disposal Facility, New Mexico Oil Conservation Division, Lovington, NM. 2003 – 2005. *Project Manager.* Managed a Phase II site investigation and subsequent soil remediation activities at a former well injection facility. Evaluated the site for the presence of petroleum hydrocarbons and chloride content in soil and then developed a work plan for remediation. Supervised the soil remediation efforts including soil excavation, transportation, and disposal and the subsequent placement of clean fill. Assisted engineers in the development of a cap for the site and provided oversight for the cap construction.

Former San Antonio Landfill Phase II Site Investigation, City of Albuquerque, NM. 2002 – 2003. *Project Manager.* Led a geophysical investigation at the former San Antonio Landfill on behalf of the COA and NMED to determine the volume of waste and thickness of cover at the site. The landfill consisted of approximately 42.5 acres in northeast Albuquerque in an area that was once on the outskirts of town but later became a residential and commercial area. Owned partially by the COA and partially by private landowners, the landfill reportedly accepted municipal waste from 1968 until 1970, at which time it was

capped and informally closed. Data from the geophysical survey provided enough evidence to conclude that the depth of soil cover across the San Antonio Landfill ranged from 2 to 6 feet. Based on the geophysical evidence of the thickness of the soil cover, it was determined it was very unlikely that landfill-related waste was present in surface soils at the site. The results of this investigation were subsequently used several times to help the COA guide development work on and near the former landfill.

Voluntary Remediation Program Assistance (Brownfields Awareness), New Mexico Environment Department, Santa Fe, NM. 2002. *Project Manager.* Managed a NMED project to increase awareness of the number of brownfields sites within New Mexico and the funding assistance available to New Mexico municipalities for brownfields site investigation and remediation. Project included extensive file review, database management, and coordination of a conference for public and private sector representatives. Consistent interaction with the VRP manager and VRP staff was essential to complete this task.

Historic Waterworks Property Site Investigation, New Mexico Environment Department, Silver City, NM. 2002. *Project Manager.* Led investigation to characterize site for inclusion in the state VRP. Site characterization activities included surface soil sampling, soil boring installation, subsurface soil sampling, and groundwater sample collection. In addition, asbestos and lead-based paint sampling were conducted in the historic building located on the site. Site characterization activities required interaction with NMED and the State Historic Preservation Officer.

Old Silver City Landfill Site Investigation, Town of Silver City, NM. 2000 – 2002. *Project Manager.* Led a Phase II Site Investigation of the closed municipal waste landfill known as the Old Silver City Landfill on behalf of the Town of Silver City and the NMED in 2000. The landfill operated from 1968 to 1993 and was historically used by the Town of Silver City and Grant County residents and businesses. The landfill was unlined and placed over arroyos and suspected to be serving as a source for methane gas and groundwater contaminants. Performed an evaluation of potential sources for chlorinated solvents in the vicinity of the landfill that might have been related to groundwater contamination in the area. This task was completed by collecting surface soil samples at an onsite machine shop; subsequent analysis of these samples showed the machine shop was not a source of the contamination.

In addition, the Town of Silver City and NMED asked for an evaluation of viability of harnessing the methane gas from the landfill for energy purposes to be conducted. As a first stage of this work, performed a site reconnaissance of the landfill with landfill engineers, collected landfill gas samples, and reviewed all the available existing records on disposal history and methane gas detection. This information was used to estimate the landfill gas volume and methane concentration using industry-accepted methods. It was determined that there was not enough landfill gas available to provide a viable energy source.