Phase I Environmental Site Assessment

Universal Cleaners

622 Canyon Road

Santa Fe, New Mexico

Prepared for:

New Mexico Environment Department
Groundwater Quality Bureau
1190 S St. Francis Dr
Santa Fe, NM 87505

Prepared by:

INTERA Incorporated
2440 Louisiana Blvd. NE Suite 700
Albuquerque, NM 87110
505.246.1600

MAY 29, 2026

Executive Summary

This report documents the methods, findings, opinions, and conclusions of a Phase I Environmental Site Assessment (ESA) performed by INTERA Incorporated (INTERA) for Universal Cleaners, 622 Canyon Road, Santa Fe, New Mexico 87501 (Site/Subject Property) (**Figure 1**). The New Mexico Environment Department (NMED) Ground Water Quality Bureau (GWQB) (User) is using Professional Services Contract #24-667-2030-27724, Work Order Number INTE08-ROS-21, to contract the performance of a due diligence assessment of the Subject Property. The Phase I ESA was conducted to document current and former conditions relative to historical operations at the Site.

INTERA performed this Phase I ESA following the procedures of Standard Practice E1527-21 of ASTM International (ASTM), entitled *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process* (ASTM, 2021). The objective of the Phase I ESA was (1) to identify, to the extent possible, any *recognized environmental conditions* (RECs) as defined by the ASTM and (2) to collect reasonably ascertainable information about the environmental condition of the Subject Property. Additionally, based on reviews of Subject Property, adjoining properties, and vicinity properties' findings within the default *area of concern* (AOC) as defined by ASTM Standard E2600-22, *Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions* (ASTM, 2022), *vapor encroachment conditions* (VECs) were also assessed for the migration potential of hazardous substances and/or petroleum products within or near the Subject Property.

The Subject Property is composed of four Santa Fe County parcels of land in Santa Fe, New Mexico, totaling approximately 0.40 acres, with five separate addresses. Based on review of historical records, the Subject Property has a history of operating as mixed residential and commercial space, with evidence of use as a private residence from 1929 to present day, a dry cleaning operation from 1949 to 1964, a clothing store in 1983, and an art gallery from 1988 to present day. The immediate vicinity of the Subject Property is depicted in **Figure 2**.

The Phase I ESA included:

- a review of the Subject Property and adjoining properties' historical and current land use records,
- review of standard environmental regulatory agency records,
- a site reconnaissance, and
- interviews with individual(s) having knowledge of past and/or present uses of the Subject Property.

These activities were performed to assess sources of surface and subsurface contamination that potentially exist at the Subject Property and within ASTM-specified distances from the Subject Property. This information was integrated with the physical setting data and future occupancy or development plans for the Subject Property to form an opinion concerning whether properties found to be a potential source of contamination may, in fact, be a REC with regard to the Subject Property as defined by ASTM. The Phase I ESA was performed by environmental professional(s) as defined in 40 CFR § 312.10 and as identified in this report.

INTERA has performed a Phase I ESA in conformance with the scope and limitations of ASTM Standard E1527-21 for the Subject Property. Based on the completion of the scope of services provided in support of this Phase I ESA, one REC and one VEC were identified in connection with the Subject Property, as follows:

- Approximately 15 years (1949-1964) of dry cleaning operations conducted at the Subject Property corroborated by a limited account of one of the Subject Property owners and the *significant data gap* identified due to the environmental professional not having physical access to the Subject Property or building interiors is considered a **REC/VEC** in connection with the Subject Property.

Based on the conclusions of this Phase I ESA, INTERA recommends the following:

Perform a Phase II site investigation to assess the potential impacts to environmental media from the REC identified in connection with the Subject Property.

Table of Contents

1.0 Introduction 1
1.1 Purpose 1
1.2 Detailed Scope of Services 1
1.2.1 Vapor Encroachment Considerations 2
1.2.2 Non-Scope Environmental Considerations 3
1.3 Significant Assumptions 3
1.4 Limitations and Exceptions 4
1.5 Special Terms and Conditions 4
1.6 User Reliance 4
2.0 Site Description 6
2.1 Location and Legal Description 6
2.2 Site Vicinity and General Characteristics 7
2.3 Physical Setting 7
2.3.1 Topography and Watershed 7
2.3.2 Average Precipitation and Temperature 8
2.3.3 Flood Plain 8
2.3.4 Soil Characterization 8
2.3.5 Geology and Hydrogeology 8
2.4 Descriptions and Current Uses of Adjoining Properties 9
3.0 User-Provided Information 10
4.0 Records Review 11
4.1 Historical Use of the Site and Adjoining Properties 11
4.1.1 Chain of Title and Environmental Lien Search 11
4.1.2 Historical Topographic Maps 11
4.1.3 Historical Aerial Photographs 12
4.1.4 Fire Insurance Maps 13
4.1.5 Historical City Directories 13
4.2 Environmental Database Records Review 14
4.2.1 Mapped Locations 14
4.3 Regulatory Agency and Supplemental Records Review 15
5.0 Site Reconnaissance 16
5.1 Methodology and Limiting Conditions 16

5.2 Subject Property 16
5.3 Adjoining Properties 17
5.4 Surrounding Properties 17
6.0 Interviews 18
6.1 Key Site Manager 18
6.2 Local Government Officials 18
7.0 Findings and Opinions 19
7.1 Subject Property Findings and Opinions 19
7.2 Adjoining Property Findings and Opinions 19
7.3 Vicinity Findings and Opinions 19
7.4 Tier 1 Vapor Encroachment Screening 19
7.5 Data Gaps 20
8.0 Conclusions 21
9.0 Recommendations 22
10.0 References 23
11.0 Disclaimer 24
12.0 Qualifications and Signatures of Environmental Professionals 25

List of Appendices

Appendix A Environmental Lien and Activity and Use Limitation Search
Appendix B Historical Topographic Maps
Appendix C Historical Aerial Photographs
Appendix D Physical Setting Documentation
Appendix E User Provided Information [RESERVED]
Appendix F Historical Fire Insurance Maps
Appendix G Historical City Directories
Appendix H Database Report
Appendix I Supplemental Records [RESERVED]
Appendix J Photographic Log
Appendix K Interviews
Appendix L Qualifications of Environmental Professionals

List of Figures

Figure 1 Site Location
Figure 2 Site Plan

List of Tables

Table 1. Summary of Subject Property Tax Parcel(s) Information 6
Table 2. User-Provided Information 10
Table 3. City Directory Listings 14
Table 4. File Review Information 15

Acronyms and Abbreviations

°F	degree(s) Fahrenheit
AAI	All Appropriate Inquiry
AMSD	approximate minimum search distance
AOC	area of concern
ASTM	American Society for Testing and Materials International
AUL	Activity and Use Limitation
bgs	below ground surface
CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act
COC	chemical of concern
EPA	United States Environmental Protection Agency
ERIS	Environmental Risk Information Services
ESA	Environmental Site Assessment
GWQB	Ground Water Quality Bureau
FIM	fire insurance map
FINDS/FRS	Facility Registry Service
ft	foot or feet
INTERA	INTERA Incorporated
LST	Leaking Storage Tank
LUST HIST	Leaking Underground Storage Tank (Historical)
msl	mean sea level
NMED	New Mexico Environment Department
NMOSE	New Mexico Office of the State Engineer
PCB	polychlorinated biphenyl
RCRA	Resource Conservation and Recovery Act
REC	Recognized Environmental Condition
SCS	State Cleanup Site
SFCA	Santa Fe County Assessor
Site or Subject Property	622 Canyon Road, Santa Fe, New Mexico
User	NMED Ground Water Quality Bureau
USGS	United States Geological Survey

VEC	vapor encroachment condition
VES	Vapor Encroachment Screening

1.0 Introduction

INTERA Incorporated (INTERA) under contract with the New Mexico Environment Department (NMED) Ground Water Quality Bureau (GWQB) (User), was tasked to perform a Phase I Environmental Site Assessment (ESA) of the property located at 622 Canyon Road, Santa Fe, New Mexico 87501 (Universal Cleaners), hereafter referred to as the Site or Subject Property (SFCA, 2026). The location of the Subject Property is illustrated in **Figure 1.**

The User is funding consultant resources from its Professional Services Contract #24-667-2030-27724, Work Order Number INTE08-ROS-21, to document current and historical conditions relative to historical operations at the Site.

1.1 Purpose

This Phase I ESA was performed (1) to identify, to the extent possible, any recognized environmental conditions (RECs), defined below in **Section 1.2**, and (2) to collect all reasonably ascertainable information about the environmental condition of the Subject Property. This was performed, consistent with good commercial and customary practice, to allow potential future redevelopment of the Subject Property and to qualify the User for statutory limitations of potential liability under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), a.k.a. Superfund.

This Phase I ESA was performed to meet the assessment and all appropriate inquiries (AAIs) requirements of American Society for Testing and Materials International (ASTM) Standard E1527-21, *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process* (ASTM, 2021). In 2005, the United States Environmental Protection Agency (EPA) issued *Standards and Practices for All Appropriate Inquiries, Final Rule* (EPA final rule; EPA, 2005), and in 2021 ASTM issued ASTM Standard E1527-21 (ASTM, 2021). Both the EPA final rule and the 2021 ASTM Standard E1527-21 implement the CERCLA as amended by the Small Business Liability Relief and Brownfields Revitalization Act of 2002. Under the EPA final rule, effective November 1, 2006, satisfaction of the CERCLA AAI requirement for liability protection as an innocent landowner, a bona fide prospective purchaser, or a contiguous landowner is met by an assessment conducted in accordance with ASTM Standard E1527-21.

1.2 Detailed Scope of Services

In general, the Phase I ESA scope of services included the following four components:

- Records review;
- Site reconnaissance;
- Interviews; and
- Report.

INTERA has completed a Phase I ESA for the Subject Property in accordance with ASTM Standard E1527-21, with the exception of any deviations listed in **Section 1.4** or data gaps listed in **Section 7.5**.

For the purposes of this Phase I ESA report, the definition of the term "*Recognized Environmental Condition*" is as outlined in Section 3.2.73 of ASTM Standard E1527-21:

> "(1) the presence of *hazardous substances* or *petroleum products* in, on, or at the *subject property* due to *release or likely release* to the *environment*; (2) the likely presence of *hazardous substances* or *petroleum products* in, on, or at the *subject property* due to a *release* to the *environment*; or (3) the presence of *hazardous substances* or *petroleum products* in, on, or at the *subject property* under conditions that pose a *material threat* of a future *release* to the *environment.*" (ASTM, 2021, p. 8)

For the purposes of this Phase I ESA report, the definition of the term "*Historical Recognized Environmental Condition*" is as outlined in Section 3.2.39 of ASTM Standard E1527-21:

> "A previous *release* of any *hazardous substances* or *petroleum products* affecting the *subject property* that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the *subject property* to any controls (for example, *activity and use limitations* or other *property use limitations*). A *historical recognized environmental condition* is not a *recognized environmental condition*." (ASTM, 2021, p. 6)

For the purposes of this Phase I ESA report, the definition of the term "*Controlled Recognized Environmental Condition*" is as outlined in Section 3.2.17 of ASTM Standard E1527-21:

> "*A recognized environmental condition* affecting the *subject property* that has been addressed to the satisfaction of the applicable regulatory authority or authorities with *hazardous substances* or *petroleum products* allowed to remain in place subject to the implementation of required controls (for example, activity and use limitations or other property use limitations)." (ASTM, 2021, p. 4)

An additional term related to this Phase I ESA report is "*de minimis condition*". It is defined by Section 3.2.20 of ASTM Standard E1527-21 as:

> "a condition related to a *release* that generally does not present a threat to human health or the *environment* and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. A condition determined to be a *de minimis condition* is not a *recognized environmental condition* nor a *controlled recognized environmental condition.*" (ASTM, 2021, p. 4-5)

1.2.1 Vapor Encroachment Considerations

ASTM Standard E1527-21 requires the assessment of the migration potential of hazardous substances and/or petroleum products within or near the Subject Property.

The definition of the term "*migrate/migration*" is outlined in Section 3.2.53 of ASTM Standard E1527-21:

> "…the movement of *hazardous substances* or *petroleum products* in any form, including, for example, solid and liquid at the surface or subsurface, and vapor in the subsurface." (ASTM, 2021, p. 7)

Vapor migration in the subsurface is described in ASTM Standard E2600-22, *Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions* (ASTM, 2022); however, ASTM Standard E1527-21 does not require its application to achieve compliance with AAI (ASTM, 2021, p. 7).

In order to assess potential migration of hazardous substances and/or petroleum products that may migrate as vapors into the vadose zone as a result of contaminated soil and/or groundwater on or near the Subject Property, INTERA has completed a Tier 1 Vapor Encroachment Screening (VES) in accordance with ASTM Standard E2600-22 for the Subject Property. The objective of the VES is to determine if a vapor encroachment condition (VEC) exists at the Subject Property. For the purposes of this Phase I ESA report, the definition of the term "*Vapor Encroachment Condition*" is as outlined in Section 3.2.37 of ASTM Standard E2600-22:

> "[The] presence or likely presence of [chemical of concern (COC)] vapors in the vadose zone of the [Subject Property] caused by the release of vapors from contaminated soil and/or groundwater either on or near the [Subject Property]…" (ASTM, 2022, p. 4)

The results of the Tier 1 VES are presented in **Section 7.4**.

1.2.2 Non-Scope Environmental Considerations

Non-scope environmental considerations such as those identified in Section 13.1.5 of ASTM E1527-21 were not evaluated as part of this ESA. Non-scope considerations may include, but are not limited to: presence of potential asbestos-containing building materials unrelated to releases into the environment; biological agents; cultural and historic resources, ecological resources; endangered species; health and safety; indoor air quality unrelated to releases of hazardous substances or petroleum products into the environment; industrial hygiene; presence of potential lead-based paint unrelated to releases into the environment; lead in drinking water; mold or microbial growth conditions; polychlorinated biphenyl (PCB)-containing building materials; naturally-occurring radon; regulatory compliance; substances not defined as hazardous substances (including some substances sometimes generally referred to as emerging contaminants) unless or until such substances are classified as a CERCLA hazardous substance; and wetlands (ASTM, 2021, p. 25).

1.3 Significant Assumptions

Significant assumptions pertaining to this Phase I ESA are briefly summarized as follows:

- Environmental database information (and facility locations) generated by Environmental Risk Information Services (ERIS) is accurate and complete;
- The User has provided INTERA with all the information in its possession that would help determine the presence of RECs;
- Interview information provided to INTERA by various parties and individuals is accurate and was provided without bias; and
- Publicly available reasonably ascertainable information accessed by INTERA is accurate and complete.

The significant assumptions underlying the preparation of any Phase I ESA are specified in the principles set forth by ASTM Standard E1527-21. The principles are presented in their entirety in Section 4.5 of ASTM Standard E1527-21 (ASTM, 2021, p. 10).

1.4 Limitations and Exceptions

Any Phase I ESA is by nature limited and qualitative in scope, being based predominantly on the examination of selected maps, agency records, interviews, and visual and/or physical observations made during the site reconnaissance. As such, this Phase I ESA should not be construed to be a complete characterization of environmental regulatory compliance of conditions above or below ground surface (bgs) at the Subject Property. Instead, the ESA process is designed to provide information regarding apparent existing or potential adverse environmental conditions related to the Subject Property in accordance with good commercial and customary practice. Any significant data gaps that would further limit the scope of the Phase I ESA are identified in **Section 7.5**.

This Phase I ESA is limited to the reasonably ascertainable information available or known to INTERA as of the date of this report. Consistent with ASTM Standard E1527-21, no intrusive testing or sampling of concealed or subsurface conditions was performed at the Subject Property as part of this Phase I ESA. The findings, opinions, and conclusions contained in this report are limited to those that could be identified during the Phase I ESA performed in accordance with ASTM Standard E1527-21. INTERA has accepted as true the information provided by interviewees on current and historical uses of the Subject Property and surrounding area. INTERA does not warrant or guarantee the accuracy or completeness of information provided by other sources.

INTERA represents that the Phase I ESA was performed in a competent manner by environmental professionals, consistent with the practices and procedures contemplated under ASTM E1527-21. However, even with proper application of the ASTM methodology, environmental conditions may be present that cannot be identified within the scope of the Phase I ESA or that may not be reasonably identifiable from the available information. As such, no warranty is expressed or implied as to the findings, conclusions, and/or recommendations presented in this Phase I ESA Report beyond matters amenable to empirical review and visual confirmation within the limits under ASTM E1527-21 and/or the specified scope of work.

1.5 Special Terms and Conditions

Since a property transaction was not part of the rationale for conducting the Phase I ESA, some of the discussion related to purpose, liability protection, and User reliance herein may not be relevant. This language is included for consistency and transparency of describing the intention of the Phase I ESA to meet the ASTM Standard.

1.6 User Reliance

This Phase I ESA has been prepared for the use of the User. There are no third-party rights or benefits conferred under this report. Use of or reliance on this Phase I ESA report by any third party is at the sole risk of that party.

This Phase I ESA is valid for 180 days prior to acquisition of the Site and/or transactions not involving acquisition of the Site. In accordance with the ASTM Standard, if the Phase I ESA is to be used by a different user other than the intended user within the 180 days, then the new user must satisfy the requirements in Section 6 of ASTM E1527-21. The Phase I ESA can be valid for longer if the Phase I ESA has been updated within one year of the date of acquisition or intended transaction, provided that the following components have been completed within 180 days of the acquisition or transaction: interviews; searches for recorded environmental cleanup liens; review of federal, tribal, state, and local government records; visual inspection of the property and of adjoining properties; and the declaration by the environmental professional responsible for the assessment or update (ASTM, 2021, p. 11).

2.0 Site Description

As required by ASTM Standard E1527-21, INTERA gathered information concerning the location, characteristics, current land uses, and physical improvements of the Subject Property, adjoining properties, and vicinity properties. Sources for this information were United States Geological Survey (USGS) 7.5-minute historical topographic maps, geologic and hydrologic publications, aerial photographs, observations made during the site reconnaissance, interviews, and consulting other publicly available information.

The Subject Property is composed of four parcels making up a roughly rectangular area, approximately 180 feet (ft) long in the north to south direction, and approximately 70 ft long in the east to west direction at its maximum width. Each parcel has a variation of the 622 Canyon address (**Table 1**) and a corresponding structure. The Subject Property is located in a mixed residential and commercial area. Adjoining properties are described in **Section 2.4.** The Site and immediate vicinity thereof are depicted in **Figure 2.**

2.1 Location and Legal Description

The Subject Property is composed of four parcels of land in Santa Fe, Santa Fe County, New Mexico, totaling approximately 0.40 acres. General real estate property tax information was gathered from the Santa Fe County Assessor's (SFCA) website for the Subject Property, summarized in **Table 1** (SFCA, 2026).

Table 1. Summary of Subject Property Tax Parcel(s) Information

Address	Parcel 1: 622 Canyon Road, Santa Fe, NM 87501 Parcel 2: 622 A [and 622 ½ C] Canyon Road, Santa Fe, NM 87501 Parcel 3: 622 ½ Canyon Road [B], Santa Fe, NM 87501 Parcel 4: 622 ½ Canyon Road [A], Santa Fe, NM 87501
Owner Name	1: Rios, Linda J 2: Rios y Torres, Esteban G 3: Bane, Marilyn A 4: Strine, Helen Frink
Parcel Number	1: 12225664 2: 12208256 3: 12204672 4: 11159550
Legal Description	1: T17N R10E S30, NW4 622 & 622 1/2 CANYON RD, LOT 26 2: T17N R10E S30, NW4, BLK 8, LOT 29 3: T17N R10E S30 NW4 LOT 27 BLK 8 4: T17N R10E S30 NW4 LOT 25 BLK 8

Size (acres)	1: 0.1928 2: 0.0806 3: 0.04 4: 0.0874
Deed Date	1: 1/14/1987 2: 5/3/2017 3: Unknown 4: 4/30/2013
Instrument	1: 571/481 (plat book/page) 2: 1824695 3: 941/852 (plat book/page) 4: 1704022

An Environmental Lien and Activity and Use Limitation (AUL) search was performed for the Subject Property parcel for the current owner. No environmental liens or AULs were identified for the Subject Property in the Lien Search Report (ERIS, 2026a – **Appendix A**).

2.2 Site Vicinity and General Characteristics

ASTM Standard E1527-21 specifies that the only standard physical setting source that must be checked during the Phase I ESA is the current USGS 7.5-minute topographic map (or equivalent). Other physical setting sources used for this Phase I ESA were historical topographic maps (ERIS, 2025b – **Appendix B**) and historical aerial photographs (ERIS, 2025c – **Appendix C**), discussed in **Section 4**.

2.3 Physical Setting

Several sources were reviewed to determine the physical setting of the Subject Property. Information from published physical settings maps (ERIS, 2025d – **Appendix D**) are discussed in the following subsections.

2.3.1 Topography and Watershed

The most recent (2023) USGS 7.5-minute topographic map of the Site area was obtained and reviewed as specified in ASTM Standard E1527-21 Section 8.2.1 (ASTM, 2021). The USGS Santa Fe, NM quadrangle provides coverage of the Subject Property and vicinity (USGS, 2023). Historical topographic maps were reviewed for surface topography and drainage information in the vicinity of the Subject Property, and are provided in **Appendix B**.

According to the topographic maps, the Subject Property slopes gently to the west, with a surface elevation of approximately 7,073 ft above mean sea level (msl). The general area drains to the northwest before reaching the Santa Fe River, which is an intermittent stream located approximately 0.15 miles north of the Subject Property. The Santa Fe River flows west through downtown Santa Fe before turning southwest and ultimately discharges to the Rio Grande approximately 30 miles downstream. The site topography was confirmed during the site reconnaissance (**Section 5**). Surface drainage at the Subject Property follows the surface topography (**Figure 1**).

2.3.2 Average Precipitation and Temperature

The average annual precipitation in Santa Fe, New Mexico is approximately 13.69 inches per year. Most of the precipitation historically occurs in July. The highest average temperature historically is in July, at 72.2 degrees Fahrenheit (°F); the lowest average temperature historically is in January, at 31.6 °F (NOAA, 2026).

2.3.3 Flood Plain

The Subject Property is outside of the 100- and 500-year floodplains (ERIS, 2025d – **Appendix D**).

2.3.4 Soil Characterization

The soil map provided by ERIS was reviewed to identify local surface soils underlying the Site. Soils at the Subject Property are composed of the Devargas-Urban land complex, with 1 to 3 percent slopes. Devargas is well-drained soil with parent material derived from stacked alluvium from sandstone on top of alluvium from granite. Urban land is a miscellaneous categorization for highly developed areas (ERIS, 2025d).

2.3.5 Geology and Hydrogeology

The Subject Property is located near the base of the Sangre de Cristo Mountains, the southernmost subrange of the Rocky Mountains. Santa Fe is located on a large system of dissected alluvial fans stretching from the base of the Sangre de Cristos to the bottom of the Rio Grande rift valley. The geologic map provided by ERIS was reviewed to determine the general geologic setting at the Subject Property (ERIS 2025d – **Appendix D**). The geologic maps show that the Subject Property is underlain by older Quaternary alluvium (Qoa). In the immediate area, there are also Quaternary piedmont deposits and older (Quaternary to Oligocene) alluvial fan-type deposits of the Santa Fe Group. The low hills to the south of the Subject Property are made up of younger Quaternary-aged Santa Fe Group, and the taller hills to the north are made up of older Tertiary-aged Santa Fe Group. The source of the sediment that makes up this alluvial fan system is primarily the Mesoproterozoic and Paleoproterozoic plutonic bedrock that makes up the Sangre de Cristo Mountains directly to the east.

The primary source of groundwater in the area of the Subject Property is the series of aquifers within the Santa Fe Group, which is primarily unconsolidated silts, sands, and gravels. ERIS reports a total of 551 water wells within a one-mile radius of the Subject Property. Sources queried included:

- Public Water Systems Violations and Enforcement Data,
- Safe Drinking Water Information System,
- USGS National Water Information System,
- The New Mexico Office of the State Engineer (NMOSE) Point of Diversion (POD) Database.

Of the nine wells listed within 500 feet of the Subject Property, depth to water ranges from 18–83 ft bgs (ERIS, 2025d). Although the shallow groundwater gradient is unknown, groundwater likely flows to the northwest in this area, following the surface gradient down to the Santa Fe River.

2.4 Descriptions and Current Uses of Adjoining Properties

The Subject Property is bound by the following:

- Two parcels of land on the west side (from north to south):
  - SFCA parcel No. 910006395, 616 Canyon Road – Commercial/residential property including an art gallery, a publicly accessible alleyway, and residences.
  - SFCA parcel No. 10951650, 616 1/2 Canyon Road – Commercial/residential property including art galleries, a publicly accessible alleyway, and residences.
- A single residential property to the south, SFCA parcel No. 10952064, 624 Canyon Road.
- Two parcels of land on the east side (from north to south):
  - SFCA parcel No. 10164608, 626 Canyon Road – Commercial/residential property including a residence and clothing store.
  - SFCA parcel No. 12482176, 630 Canyon Road – Commercial/residential property including a historic home, art studio, and a museum.
- A single parcel north of Canyon Road, SFCA parcel No. 12074112, 624 East Alameda Street, which is occupied by an art gallery/retail space, and a complex of condos extending all the way to Alameda Street to the north.

The Site and immediate vicinity thereof are depicted in **Figure 2**.

3.0 User-Provided Information

During project initiation, the User provided a summary of their knowledge of the Subject Property, summarized in **Table 2**.

Table 2. User-Provided Information

Site Type	Dry cleaner
Site Name	Universal Cleaners
Location	622 Canyon Road, Santa Fe, New Mexico
Source of Identification	Historical City Directories between 1953 and 1964
Previous Investigations	None
Major Contaminant Concern	1,1-dichloroethane (1,1-DCA); 1,1-dicloroethylene (1,1-DCE); 1,1,1-trichlorethane (1,1,1-TCA); trichloroethylene (TCE), tetrachloroethylene (PCE), vinyl chloride (VC)

Other than the information provided in **Table 2**, it is INTERA's understanding that the User has no additional knowledge of the Subject Property including those topics outlined in Section 6 of ASTM Standard E1527-21 as the User's responsibilities, summarized as follows:

- The User has no knowledge of any environmental liens or AULs for the Subject Property. However, INTERA has performed a review of land title records and performed a search for environmental liens and AULs on behalf of the User (**Section 4.1.1**).
- The User had no specialized knowledge or experience related to the Subject Property beyond the standard knowledge of an environmental regulatory agency relative to common contaminants associated with dry cleaning operations in general.
- Since a property transaction is not part of the rationale for this Phase I ESA, INTERA did not inquire about the purchase price or fair market value of the Subject Property.
- The User was unaware of any commonly known or reasonably ascertainable information other than what is summarized in **Table 2**, including knowledge of any contamination, spills/releases, or cleanups that have taken place at the Subject Property.
- The User was unaware of any obvious indicators of the presence or likely presence of releases at the Subject Property.

Any supplemental information relative to the User's responsibilities as defined in Section 6 of ASTM Standard E1521-21 is provided in **Appendix E**.

4.0 Records Review

In accordance with ASTM requirements, INTERA reviewed historical topographic maps and aerial imagery, and standard federal, state, local, and tribal environmental regulatory agency documents. A discussion of records reviewed is provided in the following subsections.

4.1 Historical Use of the Site and Adjoining Properties

INTERA contracted ERIS to search for and provide historical topographic maps, historical aerial photographs, historical city directories, and historical fire insurance maps (FIMs) for the Subject Property and surrounding properties. ERIS also provided environmental lien and AUL search services. INTERA reviewed the historical sources of information to investigate the history of development and prior land uses associated with the Subject Property, adjoining properties, and surrounding area, and to identify past land uses that may indicate that hazardous substances or petroleum products were used. A summary of the historical records reviewed is provided below.

4.1.1 Chain of Title and Environmental Lien Search

INTERA contracted ERIS to perform historical chain of tile and environmental lien and AUL search for the Subject Property. ERIS searched county, state, and federal records associated with the Subject Property address and parcel identifier (12208256) back to 1932 for the chain of title and back to 1980 for the lien and AUL search.

The Chain of Title Report identified six deed conveyances, with the earliest being in 1978. The conveyance details did not indicate any new information related to the use or activities at the Subject Property, including dry cleaning operations. No environmental liens and/or AULs were found (ERIS, 2025a). A copy of the combined Chain of Title Report and Environmental Lien Report is included in **Appendix A**.

4.1.2 Historical Topographic Maps

INTERA reviewed historical topographic maps provided by ERIS dated 1952, 1961, 1977, 1993, 2002, 2013, 2017, 2020, and 2023 (ERIS, 2025b), which are provided in **Appendix B**. A brief description of the Subject Property and the surrounding area derived from the review of historical and recent topographic maps is provided below.

- 1952:
  - The Subject Property is located in a developed area within the City of Santa Fe. Some of the surrounding roads are unpaved.
- 1961:
  - Development surrounding the Subject Property has expanded. The Acequia Madre School is depicted on the map, south of the Subject Property.
- 1977:
  - Development of the downtown Santa Fe area continues to increase, more roads in the area are indicated as paved.

- 1993:
  - Continued development of the downtown Santa Fe area is observed.
- 2002:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.
- 2013:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.
- 2017:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.
- 2020:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.
- 2023:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.

4.1.3 Historical Aerial Photographs

INTERA reviewed historical aerial photographs provided by ERIS dated 1935, 1948, 1951, 1960, 1967, 1975, 1981, 1991, 1996, 2005, 2009, 2011, 2014, 2016, 2018, 2020, and 2022 (ERIS, 2025c – **Appendix C**). A brief description of each historical aerial photograph reviewed is provided below**.**

- 1935: Image Resolution – Fair
  - Structures are visible on the subject property. The surrounding area appears to be moderately developed with agricultural fields. Most of the roads appear unpaved.
- 1948: Image Resolution – Poor
  - More of the surrounding area is now developed. There are still some fields visible.
- 1951: Image Resolution – Good
  - Development surrounding the Subject Property continues to increase. There are now very few fields and undeveloped areas left, and the hills to the north and south are being developed.
- 1960: Image Resolution – Good
  - The Subject Property and surrounding area appear relatively unchanged from the previous image. There are now structures visible on the Acequia Madre School property to the south.
- 1967: Image Resolution – Good
  - Some of the roads in the area, including Canyon Road, now appear to be paved.
- 1975: Image Resolution – Good
  - The Subject Property and vicinity appear relatively unchanged from the previous image.
- 1981: Image Resolution – Poor

  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 1991: Image Resolution – Good
  - All previously vacant lots in the immediate area of the Subject Property have now been infilled with development.
- 1996: Image Resolution – Good
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2005: Image Resolution – Good
  - This is the first full-color image. The Subject Property and vicinity appear relatively unchanged since the previous image, but most streets now appear to be paved.
- 2009: Image Resolution – Good
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2011: Image Resolution – Good
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2014: Image Resolution – Good
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2016: Image Resolution – Excellent
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2018: Image Resolution – Excellent
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2020: Image Resolution –Excellent
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2022: Image Resolution – Excellent
  - The Subject Property and vicinity appear relatively unchanged since the previous image.

4.1.4 Fire Insurance Maps

Historical FIMs can be used to identify historical uses of a property including the presence of hazardous substances and petroleum products. However, no information was found for the Subject Property or adjacent properties (ERIS, 2025e – **Appendix F**).

4.1.5 Historical City Directories

Historical city directories provide a method for researching historical uses of property. INTERA reviewed historical city directories obtained from ERIS to determine current and historical uses of the Subject Property and adjoining properties (ERIS, 2025f – **Appendix G**). ERIS provided historical City Directory Reports for Canyon Road (550-700) and East Alameda Street (550-800). Additional results may be provided if included on the historical directory pages for the ranges provided by ERIS. ERIS provided results for the years 1928-29, 1930-31, 1936-37, 1940, 1944, 1949, 1955, 1960, 1964, 1968, 1973, 1978, 1983, 1988, 1993, 1996, 2000, 2003, 2007, 2011, 2016, 2020, and 2023. The city directory listings that could be reasonably presumed to be commercial or retail properties that may be associated with

historical operations utilizing petroleum products (e.g., filling stations, gas stations) or other hazardous substances (e.g., drycleaners or manufacturing facilities) are as follows:

Table 3. City Directory Listings

Address	Property Listing(s) (Year(s))
622 Canyon Road	Universal Cleaners (1949, 1955, 1960, 1964)
1201 East Alameda Street	Settys Body Shop Auto Repair (1944)
548 East Alameda Street	Help Yourself Laundry (1940)
209–213 East Alameda Street	White Swan Laundry (1940, 1936-37)

4.2 Environmental Database Records Review

ERIS was contracted to provide a listing of standard environmental records within the ASTM-specified approximate minimum search distance (AMSD) from the Subject Property. ERIS also provides results from non-standard databases that may be relevant with respect to the objective of a Phase I ESA (i.e., without a specified AMSD). ERIS provided results from 105 unique federal, state, and tribal databases using the ASTM-specified AMSD or otherwise relevant search distance for each database. The ASTM-compliant regulatory database report is included as **Appendix H**.

4.2.1 Mapped Locations

Based on 13 total results of the database search, ERIS identified 10 sites (mapped locations) within 1-mile of the Subject Property. Two of the results were identified for the Subject Property. Sites may be identified in multiple databases, some may be identified in the same database more than once, and some may be for former and/or current operations. Findings based on results of select databases that returned significant results that support the objective of the Phase I ESA and opinions of those findings are discussed in **Section 7**. The mapped locations are summarized in **Table 4**. The ERIS Database Report, which describes and shows these facility locations, is included in **Appendix H** (ERIS, 2025g).

Table 4. File Review Information

Database Record[1]	AMSD (miles)	Total Sites Identified	Within AMSD	On Site Property	Data Source
Standard ASTM Environmental Record Resources					
Federal – RCRA Non-Generators	Subject Property and Adjoining Properties	1	0	0	ERIS
State -- SCS	1.0	6	6	0	ERIS
State – LST	0.5	1	1	0	ERIS
State – LUST HIST	0.5	1	1	0	ERIS
Non-Standard Environmental Records Resources					
Federal – FINDS/FRS	NA	1	NA	0	ERIS
Federal -- FUDS	NA	1	NA	0	ERIS
Federal – HIST RISK	NA	2	NA	2[2]	ERIS

Notes:

[1] Full descriptions of the database sources of information can be found in the ERIS Database Report (Appendix H)

[2] One or more mapped locations listed more than one time

4.3 Regulatory Agency and Supplemental Records Review

If the Subject Property or a property adjoining the Subject Property is identified in a review of standard ASTM environmental records resources, supplemental records review must be conducted (Section 8.2.3.1 of ASTM E1527-21). Neither the Subject Property nor adjoining properties were identified during review of standard ASTM environmental records resources and therefore mandatory supplemental review was not conducted.

If records review was required, relevant supplemental records obtained would be presented in **Appendix I**. Since no records were required/obtained, **Appendix I** is "reserved."

5.0 Site Reconnaissance

In general, the following was observed during the site reconnaissance to obtain information for the evaluation of RECs in connection with the Subject Property:

- Since access to conduct the Phase I ESA site reconnaissance was not obtained, the exterior of the Subject Property was observed from the public right-of-way.
- Adjoining properties from the Subject Property boundary and/or the public right-of-way.
- General topography and surface drainage in the vicinity of the Subject Property.

INTERA personnel conducted the site reconnaissance on February 12, 2026. It should be noted that access to the interior portions of the property was denied by the property owner, so observations from Site reconnaissance are from public right-of-way outside of the property only. Photographic documentation of the site visit is included in **Appendix J**. Findings documented during the site reconnaissance are summarized in **Section 7** of this report.

Conditions observed are presented below; a check mark in any box indicates that INTERA observed evidence of the item during the Site reconnaissance.

☐ Hazardous substances and/ or petroleum products	☐ Unidentified substance containers	☐ Stressed vegetation
☐ Storage tanks	☐ PCBs	☐ Solid waste
☐ Odors	☐ Drains and Sumps	☐ Utilities/Pipelines
☐ Pools of liquid	☐ Pits, ponds, or lagoons	☐ Wastewater
☐ Drums/Containers	☐ Stained soil or pavement	☐ Wells
☐ Hazardous substance and/or petroleum product containers	☐ Stains or Corrosion	☐ Septic systems

Relevant discussion of the conditions observed, including but not limited to the items identified above, is discussed in the following subsections.

5.1 Methodology and Limiting Conditions

The methodology for the site reconnaissance was based on ASTM Standard E1527-21 (ASTM, 2021). INTERA physically inspected the Subject Property and adjoining properties to the extent possible from the right-of-way, and the general site vicinity, to identify RECs or evidence of RECs as specified in Section 9 of ASTM Standard E1527-21 (ASTM, 2021).

5.2 Subject Property

The Subject Property is located on four parcels totaling approximately 0.40 acres. Each parcel has a variation of the 622 Canyon address (**Table 1**), with four corresponding structures. The Subject Property

is located in a mixed residential and commercial area. The Site and immediate vicinity thereof are depicted in **Figure 2**.

Generally, the site reconnaissance did not identify any obvious signs of contamination or hazardous substances as a result of chemicals used during former dry cleaning activities.

Photographs taken during the site reconnaissance are included in **Appendix J**.

5.3 Adjoining Properties

INTERA observed properties from the boundary of the Subject Property and from public rights-of-way to the extent possible. Evidence of contamination or hazardous substances was not directly observed. Descriptions of adjoining properties are provided in **Section 2.4**.

5.4 Surrounding Properties

Surrounding properties were generally commercial along Canyon Road with residential properties in the surrounding areas (i.e., behind the commercial properties).

6.0 Interviews

In accordance with requirements of Sections 10 and 11 of ASTM Standard E1527-21 (ASTM, 2021 p. 21-23), INTERA interviewed the *key site manager* and *local government officials* for knowledge of any past or present RECs in connection with the Subject Property.

Any findings associated with these interviews are indicated in **Section 7**.

6.1 Key Site Manager

Ms. Stella Finch of INTERA interviewed one of the Subject Property owners, Megan Rios, business owner and Key Site Manager for the Subject Property, on December 20, 2025. Megan indicated that she owns the property with her husband Esteban Rios. Ms. Rios indicated that to her knowledge, she was unaware of any environmental conditions of concern, i.e., no known incidents of releases of chemicals or petroleum products since during their ownership Subject Property. However, Ms. Rios suspected that Unit C on the property was involved with dry cleaning operations due to some suspicious areas identified when they previously conducted some renovations. Additional details were not provided. Mr. Matt Hubbard of INTERA attempted to contact Ms. Megan Rios for clarification by email on April 17, 2026, but a response was not received. Documentation of the interview with the Key Site Manager is provided in **Appendix K**.

6.2 Local Government Officials

NMED provided available information for the Subject Property during project initiation as described in **Section 3**. The information provided is considered satisfactory to meet the requirements of the Standard. No additional information from local government officials was obtained.

7.0 Findings and Opinions

This section presents the findings of the Phase I ESA Report for the Subject Property and summarizes the results of the Phase I ESA records review, site reconnaissance, and interviews as they relate to the potential presence of RECs. A discussion of Subject Property findings related to the use, storage, and disposal of hazardous substances and petroleum products is presented in **Section 7.1**. A discussion of the findings for adjoining and surrounding vicinity properties is included in **Sections 7.2** and **7.3**, respectively. **Section 7.4** discusses the results of the Tier 1 VES. This section also presents INTERA's opinions concerning the potential of the findings to contaminate Subject Property environmental media and whether the finding is considered a REC. The findings presented in this section are the basis for the Phase I ESA conclusions presented by INTERA in **Section 8** of this Phase I ESA Report.

7.1 Subject Property Findings and Opinions

The Subject Property is composed of four Santa Fe County parcels of land in Santa Fe, New Mexico, totaling approximately 0.40 acres, with five separate addresses. Based on review of historical records, the Subject Property has a history of operating as mixed residential and commercial space, with evidence of use as a private residence from 1929 to present day, a dry-cleaning operation from 1949 to 1964, a clothing store in 1983, and an art gallery from 1988 to present day.

Based on the information available, including one of the Subject Property owner's limited personal account (**Section 6.1**), a REC exists in connection with the Subject Property due to its operational history as a dry cleaner for approximately 15 years and the probability of the use of hazardous chemicals including chlorinated solvents during a time when regulations for the use, storage, and disposal of those chemicals was limited.

7.2 Adjoining Property Findings and Opinions

No relevant findings were identified associated with adjoining properties.

7.3 Vicinity Findings and Opinions

No relevant findings were identified associated with adjoining properties.

7.4 Tier 1 Vapor Encroachment Screening

ASTM Standard E2600-22 defines the default area of concern (AOC) based on $^{1}/_{3}$-mile for hazardous substances and $^{1}/_{10}$-mile for petroleum hydrocarbon contaminants. The AOC is measured from the Subject Property boundary to a contaminated property with known or suspected contamination of soil and/or groundwater (ASTM, 2022).

Based on review of Subject Property, adjoining property, and vicinity property findings within the default AOC, the dry cleaning operations that likely occurred at the Subject Property are considered a VEC.

7.5 Data Gaps

A *data gap* exists in connection with the Subject Property due to the environmental professional not being able to observe all areas of the Subject Property because access to the Subject Property was not obtained. It is our professional opinion that this is a *significant data gap* based on the initial account of the property owner corroborating concern about the dry cleaning operations.

8.0 Conclusions

INTERA has performed a Phase I ESA in conformance with the scope and limitations of ASTM Standard E1527-21 for the Subject Property. Any exceptions to or deletions from this practice are described in **Section 7.5**. Based on the completion of the scope of services provided in support of this Phase I ESA, one REC and one VEC were identified in connection with the Subject Property, as follows:

- Approximately 15 years (1949-1964) of dry cleaning operations conducted at the Subject Property corroborated by a limited account of one of the Subject Property owners and the *significant data gap* identified due to the environmental professional not having physical access to the Subject Property or building interiors is considered a **REC/VEC** in connection with the Subject Property.

9.0 Recommendations

Based on the AAIs performed by the environmental professional in conformance with 40 CFR 312.31(a) and (b), this Phase I ESA has revealed evidence of one or more RECs/VECs or *significant data gaps* in connection with the Subject Property. Based on the conclusions of this Phase I ESA, INTERA recommends the following:

- Perform a Phase II site investigation to assess the potential impacts to environmental media from the REC identified in connection with the Subject Property.

10.0 References

ASTM International (ASTM). 2021. *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process.* Standard E1527-21. West Conshohocken, Pennsylvania: ASTM International.

———. 2022. *Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions*. Standard E2600-22. West Conshohocken, Pennsylvania. May 18, 2022.

ERIS. 2026a. Chain of Title Report and Environmental Lien Search.

———. 2025b. Topographic Maps.

———. 2025c. Historical Aerials.

———. 2025d. Physical Setting Report.

———. 2025e. Fire Insurance Maps.

———. 2025f. City Directory.

———. 2025g. Database Report.

National Oceanic and Atmospheric Administration (NOAA), 2026. National Weather Service Climate Data. https://www.weather.gov/wrh/Climate?wfo=hgx. Accessed March 31, 2026.

Santa Fe County Assessor (SFCA) Parcel Viewer. 2026. https://www.santafecountynm.gov/assessor/tools. Accessed January 6, 2026.

United States Environmental Protection Agency (EPA). 2005. *Standards and Practices for All Appropriate Inquiries*, Final Rule. 40 CFR Part 312. Washington, D.C.: Government Printing Office. Federal Register 70(210): November 1, 2005.

United States Geological Survey (USGS), 2023. *Santa Fe Quadrangle, New Mexico – Santa Fe County 7.5 Minute Series.* Accessed January 2026.

11.0 Disclaimer

The findings and conclusions contained in this report were derived using the methodologies provided in ASTM Standard E1527-21 (ASTM, 2021). The findings and conclusions contain all limitations inherent in these methodologies. There is the possibility that even with proper application of these methodologies, conditions may exist at the Subject Property that could not be identified within the scope of the Phase I ESA or that were not reasonably identifiable from the available information.

INTERA has prepared this report in accordance with the generally accepted environmental professional practices in use at the time of our study. This report may be used only by the User(s) and only for the purposes stated within a reasonable time from its issuance as outlined in ASTM Standard E1527-21 (ASTM, 2021). Land use, Site conditions (both onsite and offsite), or other factors may change over time, and additional work may be required with the passage of time. Any party other than the User(s) who wishes to use this report shall notify the User(s) of the intended use. Non-compliance with any of these requirements will release INTERA from any liability resulting from the use of this report.

INTERA does not warrant or guarantee in any manner, expressed or implied, that the conclusions and findings reported in this Phase I ESA, or the information obtained for this Phase I ESA from the records review or from other sources, including site reconnaissance observations, personal interviews, and correspondence, are accurate or complete beyond the limits of the methods applied. The methodologies of this Phase I ESA assessment are intended to meet the scope of a Phase I ESA in accordance with ASTM Standard E1527-21 (ASTM, 2021).

INTERA conducted this Phase I ESA and AAI into previous property ownership and uses in a manner consistent with ASTM Standard E1527-21 and the EPA AAI Final Rule (EPA, 2005) definitions of good commercial and customary ESA and AAI practices in the United States of America.


This Phase I ESA report is intended for use solely by the User(s). Any party other than the User(s) is explicitly denied any rights to rely on the findings, opinions, and conclusions of this Phase I ESA report.

12.0 Qualifications and Signatures of Environmental Professionals


Complete copies of resumes outlining the qualifications of the individuals completing this Phase I ESA report are included as **Appendix L.**

"I declare that, to the best of my professional knowledge and belief, I meet the definition of environmental professional as defined in Section 312.10 of 40 CFR 312. I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the Subject Property. I have developed and performed all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR part 312."

Matt Hubbard, Senior Environmental Scientist/Environmental Professional

Signature: 

Joeseph Tracy, P.G., Principal Geologist/Environmental Professional

Signature: 

FIGURES




Figure 1
Site Location
Universal Cleaners
622 Canyon Road, Santa Fe, New Mexico

Exported: 4/22/2026 10:36 AM

S:\ABQ\NMENV.M007.SF-WALDO\Graphics\SantaFe_Waldo_P1P2_Proposal\SantaFe_Waldo_P1P2_Proposal.aprx

User: mhubbard

Layout: Figure 1 - 622 Canyon Location

INTERA



Legend

- Subject Property Addresses
- Subject Property Parcels

0 75 150

US Feet

N

Figure 2
Site Plan
Universal Cleaners
622 Canyon Road, Santa Fe, New Mexico

Exported: 5/29/2026 5:55 PM

S:\ABQ\NMENV.M007.SF-WALDO\Graphics\SantaFe_Waldo_P1P2_Proposal\SantaFe_Waldo_P1P2_Proposal.aprx

User: mhubbard

Layout: Figure 2 - Site Plan 622 Canyon

INTERA

APPENDIX A

Chain of Title Report and Environmental Lien and Activity and Use Limitation Search

CHAIN OF TITLE

Project Property: *622 CANYON RD*
SANTA FE, NM 87501
Order No: *25121700733-COT1*
Date Completed: *01/05/2026*

ERIS – Environmental Risk Information Services hereby submits the following historical chain-of-title to the land described below.

Title to the estate or interest covered by this report appears to be vested in:

BARBARA G. RIOS

The following is the current property legal description (See deed for full legal description):

T17N R10E S30, NW4, BLK 8, LOT 29

Assessor's Parcel Number(s): 012208256 AND 1-055-098-031-506

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

CHAIN OF TITLE REPORT

Order No: *25121700733-COT1*

HISTORICAL CHAIN OF TITLE

Public Records were searched at the SANTA FE COUNTY Assessor's office and the SANTA FE COUNTY Clerk's office back to 1932. The following conveyances were found of record.

1.	Deed Type:	TRANSFER ON DEATH DEED
	Deed Date:	05/03/2017
	Recorded:	05/03/2017
	Grantor:	BARBARA G RIOS
	Grantee:	ESTEBAN G. RIOS Y TORRES
	Instrument:	1824695
	Notes:	NA

2.	Deed Type:	QUIT CLAIM DEED
	Deed Date:	02/24/1986
	Recorded:	02/24/1986
	Grantor:	RUDOLFO RIOS
	Grantee:	BARBARA G. RIOS
	Instrument:	BOOK 543 / PAGE 767
	Notes:	NA

3.	Deed Type:	DEED
	Deed Date:	03/16/1978
	Recorded:	03/16/1978
	Grantor:	MARGARET TESSIE GURULE & JAMES E. RODRIGUEZ
	Grantee:	BARBARA G. & RUDOLFO RIOS
	Instrument:	417149
	Notes:	NA

4.	Deed Type:	DEED
	Deed Date:	02/28/1978
	Recorded:	02/28/1978
	Grantor:	FRANCES W. & LOUIS P. RODRIGUEZ
	Grantee:	ESTATE OF DAN P. RODRIGUEZ
	Instrument:	416332
	Notes:	NA

5.	Deed Type:	DEED
	Deed Date:	02/28/1978
	Recorded:	02/28/1978
	Grantor:	ERNESTINE L. & PEDRO J. RODRIGUEZ
	Grantee:	ESTATE OF DAN P. RODRIGUEZ
	Instrument:	416331
	Notes:	NA

6.	Deed Type:	DEED
	Deed Date:	02/24/1978
	Recorded:	02/24/1978
	Grantor:	SANTA FE CITY
	Grantee:	ESTATE OF DANIEL RODRIGUEZ
	Instrument:	416148
	Notes:	NA

LEASES AND MISCELLANEOUS

Comments: NONE IDENTIFIED.

Thank You for Your Business
Please contact ERIS at **416-510-5204** or **info@erisinfo.com**
with any questions or comments

LIMITATION

This report is neither a guarantee of title, a commitment to insure, or a policy of title insurance. ERIS – Environmental Risk Information Services does not guarantee nor include any warranty of any kind whether expressed or implied, about the validity of all information included in this report since this information is retrieved as it is recorded from various agencies that make it available. The total liability is limited to the fee paid for this report.

TRANSFER ON DEATH DEED

Barbara G. Rios as owner transfers on death to my son Esteban G. Rios y Torres, By marriage, as grantee beneficiary, the following described interest in real property. THIS TRANSFER ON DEATH DEED IS REVOCABLE. IT DOES NOT TRANSFER ANY OWNERSHIP UNTIL THE DEATH OF THE OWNER. IT REVOKES ALL PRIOR BENEFICIARY DESIGNATIONS BY THIS OWNER FOR THIS INTEREST IN REAL PROPERTY. 622 Canyon Road Santa Fe, N. Mex

A certain tract or parcel of land, lying and being situated in Lot 29, Block 8, Section 30, Q-2, of the Santa Fe County Assessment Survey, within the City of Santa Fe, State of New Mexico, being more particularly bounded and described as follows, to-wit:

Beginning at a point for the northwesterly corner of the tract herein described (marked by a 3/8" re-bar) which point bears S72°18' 29" W, a distance of 18.9 feet from Manhole Cover No. 7 of Line W5; thence S66°36' 30" E, a distance of 40.6 feet; thence, S20°45' 39"W, a distance of 23.41 feet; thence, S19° 55'°12" W, a distance of 89.91 feet; thence, N73° 37'W, a distance of 17.04 feet; thence N15°18' 06"E, a distance of 47.9 feet; thence N66°01' 30" W, a distance of 20.8 feet; thence, N21°09' 30" E, a distance of 68.35 feet to the point and place of beginning. All as shown on plat of survey entitled 'PLAT OF SURVEY OF THE ESTATE OF DAN P. RODRIGUEZ, deceased" by Arsenio S. Martinez, L.S. No. 4254 on December 23, 1977.

SFC CLERK RECORDED 05/03/2017

5-3-17

ACKNOWLEDGEMENT FOR NATURAL PERSONS

STATE OF NEW MEXICO)
) ss.
COUNTY OF Santa Fe)

X Barbara G. Rios

This instrument was acknowledged before me on May 3, 2017

by Barbara G. Rios

My commission expires: 5/14/19
(Seal)

Estrella Martinez
NOTARY PUBLIC

OFFICIAL SEAL
ESTRELLA MARTINEZ
Notary Public
State of New Mexico
My Comm. Expires 5/14/19

TRANSFER ON DEATH DEED

COUNTY OF SANTA FE)
STATE OF NEW MEXICO) ss

PAGES: 2

I Hereby Certify That This Instrument Was Filed for Record On The 3RD Day Of May, 2017 at 12:56:53 PM And Was Duly Recorded as Instrument # **1824695** Of The Records Of Santa Fe County

Witness My Hand And Seal Of Office
Geraldine Salazar
Deputy Veronica Duran County Clerk, Santa Fe, NM



843767

QUITCLAIM DEED

RUDOLFO RIOS, a single man, for consideration paid, and pursuant to the Final Decree (BARBARA RIOS vs. RUDOLFO J. RIOS, Cause Number DR 83-57) entered June 22, 1983, quitclaims to BARBARA G. RIOS, single woman, the following described real estate in Santa Fe, County, New Mexico.

A certain tract or parcel of land, lying and being situated in Lot 29, Block 8, Section 30, Q-2, of the Santa Fe County Assessment Survey, within the City of Santa Fe, State of New Mexico, being more particularly bounded and described as follows, to-wit:

Beginning at a point for the northwesterly corner of the tract herein described (marked by a 3/8" re-bar) which point bears S72°18' 29" W, a distance of 18.9 feet from Manhole Cover No. 7 of Line W5; thence S66°36' 30" E, a distance of 40.6 feet; thence, S20°46' 39"W, a distance of 23.41 feet; thence, S19° 55'°12" W, a distance of 89.91 feet; thence, N73° 37'W, a distance of 17.04 feet; thence N15°18' 06"E, a distance of 47.9 feet; thence N68°01' 30" W, a distance of 20.8 feet; thence, N21°09' 30" E, a distance of 68.35 feet to the point and place of beginning. All as shown on plat of survey entitled 'PLAT OF SURVEY OF THE ESTATE OF DAN P. RODRIGUEZ, deceased" by Arsenio J. Martinez, L.S. No. 4254 on December 23, 1977.

WITNESS my hand and seal this 24 day of February, 1986.

Rudolfo J Rios
RUDOLFO RIOS

ACNOWLEDGMENT

STATE OF NEW MEXICO)
)ss
COUNTY OF SANTA FE)

The foregoing instrument was acknowledged before me this

543768

24th day of February, 1986, by RUDOLFO RIOS.

MARINA CHISM
NOTARY PUBLIC

NOTARY
My Commission Expires:
October 1, 1988
STATE OF NEW MEXICO

586796

COUNTY OF SANTA FE
STATE OF NEW MEXICO

I hereby certify that this instrument was filed for record on the 24 day of Feb A.D 19 86, at 2:56 o'clock P m. and was duly recorded in book 543, page 167 of the records of Santa Fe County.

Witness my Hand and Seal of Office
ANGIE VIGIL PEREZ
County Clerk, Santa Fe County, N.M.

Dena Cardenas
Deputy

SANTA FE COUNTY

543 MISC 4 2886

CHAIN OF TITLE & LIEN SEARCHES

Project Property: *622 CANYON RD*
SANTA FE, NM 87501
Order No: *25121700733-COTEL1*
Date Completed: *01/05/2026*

Title to the estate or interest covered by this report appears to be vested in:
ESTEBAN G. RIOS Y TORRES
BARBARA G. RIOS

The following is the current property legal description (See deed for full legal description):
T17N R10E S30, NW4, BLK 8, LOT 29

Assessor's Parcel Number(s):
012208256 AND 1-055-098-031-506

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

TARGET PROPERTY INFORMATION

ADDRESS

622 CANYON RD
SANTA FE, NM 87501

RESEARCH SOURCES

RECORDER:	SANTA FE COUNTY RECORDER'S OFFICE
ASSESSOR:	SANTA FE COUNTY ASSESSOR'S OFFICE
STATE:	NEW MEXICO ENVIRONMENT DEPARTMENT
FEDERAL:	UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
OTHER:	JUDICIAL RECORDS NOT SEARCHED. BASED ON AVAILABLE INFORMATION EVALUATED BY THE TITLE SEARCH PROFESSIONAL, THE JURISDICTION DOES NOT REQUIRE A SEARCH OF JUDICIAL RECORDS IN ORDER TO IDENTIFY ENVIRONMENTAL LIENS.
NOTES:	PUBLIC RECORDS OF SANTA FE COUNTY, NM WERE SEARCHED FROM JANUARY 1, 1980 TO DECEMBER 29, 2025, AND NO OTHER DEEDS VESTING TITLE IN THE SUBJECT PROPERTY WERE FOUND OF RECORD DURING THE PERIOD SEARCHED.

ENVIRONMENTAL LIENS

Environmental Lien: [X] NOT FOUND

ACTIVITY AND USE LIMITATIONS (AULs)

AULs: [X] NOT FOUND

CHAIN OF TITLE TO 1980

1. Deed Type: TRANSFER ON DEATH DEED
   Deed Date: 05/03/2017
   Recorded: 05/03/2017
   Grantor: BARBARA G RIOS
   Grantee: ESTEBAN G. RIOS Y TORRES
   Instrument: 1824695
   Notes:

2. Deed Type: QUIT CLAIM DEED
   Deed Date: 02/24/1986
   Recorded: 02/24/1986
   Grantor: RUDOLFO RIOS
   Grantee: BARBARA G. RIOS
   Instrument: BOOK 543 / PAGE 767
   Notes:

3. Deed Type: DEED
   Deed Date: 03/16/1978
   Recorded: 03/16/1978
   Grantor: MARGARET TESSIE GURULE & JAMES E. RODRIGUEZ
   Grantee: BARBARA G. & RUDOLFO RIOS
   Instrument: 417149
   Notes:

4. Deed Type: DEED
   Deed Date: 02/28/1978
   Recorded: 02/28/1978
   Grantor: FRANCES W. & LOUIS P. RODRIGUEZ
   Grantee: ESTATE OF DAN P. RODRIGUEZ
   Instrument: 416332
   Notes:

5. Deed Type: DEED
   Deed Date: 02/28/1978
   Recorded: 02/28/1978
   Grantor: ERNESTINE L. & PEDRO J. RODRIGUEZ
   Grantee: ESTATE OF DAN P. RODRIGUEZ
   Instrument: 416331
   Notes:

6.	Deed Type:	DEED
	Deed Date:	02/24/1978
	Recorded:	02/24/1978
	Grantor:	SANTA FE CITY
	Grantee:	ESTATE OF DANIEL RODRIGUEZ
	Instrument:	416148
	Notes:	RESEARCH CONDUCTED BACK TO 1980. THIS IS THE OLDEST DEED OF RECORD FOUND WITHIN SCOPE OF SEARCH.

LEASES AND MISCELLANEOUS

Comments: NONE IDENTIFIED.

The ERIS Environmental Lien Search Report to 1980 provides results from a search of available current land title records for environmental cleanup liens and other activity and use limitations, such as engineering and institutional controls.

A network of professional, trained researchers, following established procedures, uses client supplied property information to:

- Search for parcel information and / or legal description
- Search for ownership information
- Research official land title documents recorded at jurisdictional agencies such as recorder's' office, registries of deeds, county clerks' offices, etc.
- Access copies of deeds to 1980
- Search for environmental encumbrance(s) associated with the deeds
- Provide a copy of any environmental encumbrance(s) based upon a review of keywords in the instrument(s) (title, parties involved and description)
- Provide a copy of the deeds or cite documents reviewed

Thank You for Your Business
Please contact ERIS at **416-510-5204** or **info@erisinfo.com**
with any questions or comments

LIMITATION

This report is neither a guarantee of title, a commitment to insure, or a policy of title insurance. ERIS – Environmental Risk Information Services does not guarantee nor include any warranty of any kind whether expressed or implied, about the validity of all information included in this report since this information is retrieved as it is recorded from various agencies that make it available. The total liability is limited to the fee paid for this report.

DEED EXHIBIT

TRANSFER ON DEATH DEED

Barbara G. Rios as owner transfers on death to my son Esteban G. Rios y Torres, By marriage, as grantee beneficiary, the following described interest in real property. THIS TRANSFER ON DEATH DEED IS REVOCABLE. IT DOES NOT TRANSFER ANY OWNERSHIP UNTIL THE DEATH OF THE OWNER. IT REVOKES ALL PRIOR BENEFICIARY DESIGNATIONS BY THIS OWNER FOR THIS INTEREST IN REAL PROPERTY. 622 Canyon Road Santa Fe, N. Mex

A certain tract or parcel of land, lying and being situated in Lot 29, Block 8, Section 30, Q-2, of the Santa Fe County Assessment Survey, within the City of Santa Fe, State of New Mexico, being more particularly bounded and described as follows, to-wit:

Beginning at a point for the northwesterly corner of the tract herein described (marked by a 3/8" re-bar) which point bears S72°18' 29" W, a distance of 18.9 feet from Manhole Cover No. 7 of Line W5; thence S66°36' 30" E, a distance of 40.6 feet; thence, S20°45' 39"W, a distance of 23.41 feet; thence, S19° 55'°12" W, a distance of 89.91 feet; thence, N73° 37'W, a distance of 17.04 feet; thence N15°18' 06"E, a distance of 47.9 feet; thence N66°01' 30" W, a distance of 20.8 feet; thence, N21°09' 30" E, a distance of 68.35 feet to the point and place of beginning. All as shown on plat of survey entitled 'PLAT OF SURVEY OF THE ESTATE OF DAN P. RODRIGUEZ, deceased" by Arsenio S. Martinez, L.S. No. 4254 on December 23, 1977.

SFC CLERK RECORDED 05/03/2017

5-3-17

ACKNOWLEDGEMENT FOR NATURAL PERSONS

STATE OF NEW MEXICO)
) ss.
COUNTY OF Santa Fe)

X Barbara G. Rios

This instrument was acknowledged before me on May 3, 2017

by Barbara G. Rios

My commission expires: 5/14/19
(Seal)

Estrella Martinez
NOTARY PUBLIC

OFFICIAL SEAL
ESTRELLA MARTINEZ
Notary Public
State of New Mexico
My Comm. Expires 5/14/19

TRANSFER ON DEATH DEED

COUNTY OF SANTA FE)
STATE OF NEW MEXICO) ss

PAGES: 2

I Hereby Certify That This Instrument Was Filed for Record On The 3RD Day Of May, 2017 at 12:56:53 PM And Was Duly Recorded as Instrument # **1824695** Of The Records Of Santa Fe County

Witness My Hand And Seal Of Office
Geraldine Salazar
Deputy Veronica Duran County Clerk, Santa Fe, NM



843767

QUITCLAIM DEED

RUDOLFO RIOS, a single man, for consideration paid, and pursuant to the Final Decree (BARBARA RIOS vs. RUDOLFO J. RIOS, Cause Number DR 83-57) entered June 22, 1983, quitclaims to BARBARA G. RIOS, single woman, the following described real estate in Santa Fe, County, New Mexico.

A certain tract or parcel of land, lying and being situated in Lot 29, Block 8, Section 30, Q-2, of the Santa Fe County Assessment Survey, within the City of Santa Fe, State of New Mexico, being more particularly bounded and described as follows, to-wit:

Beginning at a point for the northwesterly corner of the tract herein described (marked by a 3/8" re-bar) which point bears S72°18' 29" W, a distance of 18.9 feet from Manhole Cover No. 7 of Line W5; thence S66°36' 30" E, a distance of 40.6 feet; thence, S20°46' 39"W, a distance of 23.41 feet; thence, S19° 55'°12" W, a distance of 89.91 feet; thence, N73° 37'W, a distance of 17.04 feet; thence N15°18' 06"E, a distance of 47.9 feet; thence N68°01' 30" W, a distance of 20.8 feet; thence, N21°09' 30" E, a distance of 68.35 feet to the point and place of beginning. All as shown on plat of survey entitled 'PLAT OF SURVEY OF THE ESTATE OF DAN P. RODRIGUEZ, deceased" by Arsenio J. Martinez, L.S. No. 4254 on December 23, 1977.

WITNESS my hand and seal this 24 day of February, 1986.

Rudolfo J Rios
RUDOLFO RIOS

ACNOWLEDGMENT

STATE OF NEW MEXICO)
)ss
COUNTY OF SANTA FE)

The foregoing instrument was acknowledged before me this

543768

24th day of February, 1986, by RUDOLFO RIOS.

MARINA CHISM
NOTARY PUBLIC

NOTARY
My Commission Expires:
October 1, 1988
STATE OF NEW MEXICO

586796

COUNTY OF SANTA FE
STATE OF NEW MEXICO

I hereby certify that this instrument was filed for record on the 24 day of Feb A.D 19 86, at 2:56 o'clock P m. and was duly recorded in book 543, page 167 of the records of Santa Fe County.

Witness my Hand and Seal of Office
ANGIE VIGIL PEREZ
County Clerk, Santa Fe County, N.M.

Dena Cardenas
Deputy

SANTA FE COUNTY

543 MISC 4 2886

APPENDIX B

Historical Topographic Maps

TOPOGRAPHIC MAPS

Project Property:	Universal Cleaners 622 Canyon Rd Santa Fe NM 87501
Project No:	NMENV.M007.SF-WALDO
Requested By:	INTERA Incorporated
Order No:	25121700733
Date Completed:	December 17, 2025

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

We have searched USGS collections of current topographic maps and historical topographic maps for the project property. Below is a list of maps found for the project property and adjacent area. Maps are from 7.5 and 15 minute topographic map series, if available.

Year	Map Series
2023	7.5
2020	7.5
2017	7.5
2013	7.5
2002	7.5
1993	7.5
1977	7.5
1961	7.5
1952	7.5

Topographic Map Symbology for the maps may be available in the following documents:

Pre-1947

Page 223 of 1918 Topographic Instructions

Page 130 of 1928 Topographic Instructions


1947-2009

Topographic Map Symbols

2009-present

US Topo Map Symbols

Topographic Maps included in this report are produced by the USGS and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property.
No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc.(in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS', using Topographic Maps produced by the USGS. This maps contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.



2023

Order No. 25121700733

Available Quadrangle(s): Santa Fe, NM



Source: USGS 7.5 Minute Topographic Map



2020


Order No. 25121700733

Available Quadrangle(s): Santa Fe, NM



Source: USGS 7.5 Minute Topographic Map

ERIS




2017

Order No. 25121700733

Available Quadrangle(s): Santa Fe, NM



Source: USGS 7.5 Minute Topographic Map



2013


Order No. 25121700733

Available Quadrangle(s): Santa Fe, NM



Source: USGS 7.5 Minute Topographic Map

ERIS



2002 (1-2002)


Aerial Photo Year: 1996

Order No. 25121700733

Available Quadrangle(s): Santa Fe, NM(1-2002)



Source: USGS 7.5 Minute Topographic Map



1993 (1-1993)


Aerial Photo Year: 1990

Order No. 25121700733

Available Quadrangle(s): Santa Fe, NM(1-1993)



Source: USGS 7.5 Minute Topographic Map



1977 (1-1977)

Aerial Photo Year: 1976


Photo Revision Year: 1977

Order No. 25121700733

Available Quadrangle(s): Santa Fe, NM(1-1977)



Source: USGS 7.5 Minute Topographic Map



1961 (1-1961)

Aerial Photo Year: 1960


Order No. 25121700733

Available Quadrangle(s): Santa Fe, NM(1-1961)



Source: USGS 7.5 Minute Topographic Map

ERIS



1952 (1-1952)

Aerial Photo Year: 1951

Order No. 25121700733

Available Quadrangle(s): Santa Fe, NM(1-1952)



Source: USGS 7.5 Minute Topographic Map

APPENDIX C

Historical Aerial Photographs

HISTORICAL AERIALS

Project Property: Universal Cleaners
622 Canyon Rd
Santa Fe NM 87501

Project No: NMENV.M007.SF-WALDO

Requested By: INTERA Incorporated


Order No: 25121700733

Date Completed: December 19,2025

Aerial Maps included in this report are produced by the sources listed above and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property. ERIS provides no warranty of accuracy or liability. The information contained in this report has been produced using aerial photos listed in above sources by ERIS Information Inc. (in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS'. The maps contained in this report do not purport to be and do not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Date	Source	Scale	Comments
2022	United States Department of Agriculture	1" = 500'	
2020	United States Department of Agriculture	1" = 500'	
2018	United States Department of Agriculture	1" = 500'	
2016	United States Department of Agriculture	1" = 500'	
2014	United States Department of Agriculture	1" = 500'	
2011	United States Department of Agriculture	1" = 500'	
2009	United States Department of Agriculture	1" = 500'	
2005	United States Geological Survey	1" = 500'	
1996	United States Geological Survey	1" = 500'	
1991	United States Geological Survey	1" = 500'	
1981	United States Geological Survey	1" = 500'	
1975	Pacific Western Techonolgies	1" = 500'	
1967	Pacific Western Techonolgies	1" = 500'	Adjacent Frame Unavailable
1960	United States Geological Survey	1" = 500'	
1951	United States Geological Survey	1" = 500'	
1948	United States Geological Survey	1" = 500'	
1935	Agricultural Stabilization & Conserv. Service	1" = 500'	




Year: 2022
Source: USDA
Scale: 1" = 500'
Comment:

Address: 622 Canyon Rd, Santa Fe, NM
Approx Center: -105.92829458,35.68133383

Order No: 25121700733

ERIS




Year: 2020
Source: USDA
Scale: 1" = 500'
Comment:

Address: 622 Canyon Rd, Santa Fe, NM
Approx Center: -105.92829458,35.68133383

Order No: 25121700733

ERIS




Year: 2018
Source: USDA
Scale: 1" = 500'
Comment:

Address: 622 Canyon Rd, Santa Fe, NM
Approx Center: -105.92829458,35.68133383

Order No: 25121700733

ERIS




Year: 2016
Source: USDA
Scale: 1" = 500'
Comment:

Address: 622 Canyon Rd, Santa Fe, NM
Approx Center: -105.92829458,35.68133383

Order No: 25121700733

ERIS




Year: 2014
Source: USDA
Scale: 1" = 500'
Comment:

Address: 622 Canyon Rd, Santa Fe, NM
Approx Center: -105.92829458,35.68133383

Order No: 25121700733

ERIS




Year: 2011
Source: USDA
Scale: 1" = 500'
Comment:

Address: 622 Canyon Rd, Santa Fe, NM
Approx Center: -105.92829458,35.68133383

Order No: 25121700733

ERIS




Year: 2009
Source: USDA
Scale: 1" = 500'
Comment:

Address: 622 Canyon Rd, Santa Fe, NM
Approx Center: -105.92829458,35.68133383

Order No: 25121700733

ERIS



Year: 2005
Source: USGS
Scale: 1" = 500'
Comment:

Address: 622 Canyon Rd, Santa Fe, NM
Approx Center: -105.92829458,35.68133383

Order No: 25121700733

ERIS



Year: 1996
Source: USGS
Scale: 1" = 500'
Comment:

Address: 622 Canyon Rd, Santa Fe, NM
Approx Center: -105.92829458,35.68133383

Order No: 25121700733

ERIS



Year: 1991
Source: USGS
Scale: 1" = 500'
Comment:

Address: 622 Canyon Rd, Santa Fe, NM
Approx Center: -105.92829458,35.68133383

Order No: 25121700733

ERIS



Year: 1981
Source: USGS
Scale: 1" = 500'
Comment:

Address: 622 Canyon Rd, Santa Fe, NM
Approx Center: -105.92829458,35.68133383

Order No: 25121700733

ERIS



Year: 1975
Source: PWT
Scale: 1" = 500'
Comment:

Address: 622 Canyon Rd, Santa Fe, NM
Approx Center: -105.92829458,35.68133383

Order No: 25121700733

ERIS




Year: 1967
Source: PWT
Scale: 1" = 500'
Comment: Adjacent Frame Unavailable

Address: 622 Canyon Rd, Santa Fe, NM
Approx Center: -105.92829458,35.68133383

Order No: 25121700733

ERIS



Year: 1960
Source: USGS
Scale: 1" = 500'
Comment:

Address: 622 Canyon Rd, Santa Fe, NM
Approx Center: -105.92829458,35.68133383

Order No: 25121700733

ERIS



Year: 1951
Source: USGS
Scale: 1" = 500'
Comment:

Address: 622 Canyon Rd, Santa Fe, NM
Approx Center: -105.92829458,35.68133383

Order No: 25121700733

ERIS



Year: 1948
Source: USGS
Scale: 1" = 500'
Comment:

Address: 622 Canyon Rd, Santa Fe, NM
Approx Center: -105.92829458,35.68133383

Order No: 25121700733

ERIS



Year: 1935
Source: ASCS
Scale: 1" = 500'
Comment:

Address: 622 Canyon Rd, Santa Fe, NM
Approx Center: -105.92829458,35.68133383

Order No: 25121700733

ERIS

APPENDIX D

Physical Setting Documentation

PSR
PHYSICAL SETTING REPORT

Property Information

Order Number:		25121700733p
Date Completed:		December 17, 2025
Project Number:		NMENV.M007.SF-WALDO
Project Property:		Universal Cleaners 622 Canyon Rd Santa Fe NM 87501
Coordinates:		
	Latitude:	35.68133383
	Longitude:	-105.92829458
	UTM Northing:	3949001.58908 Meters
	UTM Easting:	415998.536163 Meters
	UTM Zone:	UTM Zone 13S
	Elevation:	7,073.48 ft
	Slope Direction:	NNW

Topographic Information....2
Hydrologic Information....4
Geologic Information....7
Soil Information....10
Wells and Additional Sources....23
  Summary....24
  Detail Report....34
Radon Information....633
Appendix....634
Liability Notice....636


The ERIS ***Physical Setting Report - PSR*** provides comprehensive information about the physical setting around a site and includes a complete overview of topography and surface topology, in addition to hydrologic, geologic and soil characteristics. The location and detailed attributes of oil and gas wells, water wells, public water systems and radon are also included for review.

The compilation of both physical characteristics of a site and additional attribute data is useful in assessing the impact of migration of contaminants and subsequent impact on soils and groundwater.

Disclaimer

This Report does not provide a full environmental evaluation for the site or adjacent properties. Please see the terms and disclaimer at the end of the Report for greater detail.

Topographic Information



Current USGS Topo (2023)

0 0.2 0.4 0.8 Miles

N

Quadrangle(s): Santa Fe,NM


Source: USGS 7.5 Minute Topographic Map

Topographic Information


The previous topographic map(s) are created by seamlessly merging and cutting current USGS topographic data. Below are shaded relief map(s), derived from USGS elevation data to show surrounding topography in further detail.

Topographic information at project property:

Elevation:	7,073.48 ft
Slope Direction:	NNW



Hydrologic Information



Wetland

Miles
0 0.075 0.15 0.3

N

This map shows wetland existence using data from US Fish & Wildlife.
Data coverage is shown to the right. Gray indicates no data available in the area.

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland
- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond
- Lake
- Other
- Riverine

ERIS

Hydrologic Information



Flood Hazard Zones

This map shows FEMA flood hazard zones based on FEMA's National Flood Hazard Layer. FIRM Panels are overlayed. An absent FIRM panel represents no data available.

Miles
0 0.05 0.1

N

- 1% Annual Chance Flood Hazard
- Regulatory Floodway
- Special Floodway
- Area of Undetermined Flood Hazard
- 0.2% Annual Chance Flood Hazard
- Future Conditions 1% Annual Chance Flood Hazard
- Area with Reduced Risk Due to Levee
- Area with Risk Due to Levee
- Open Water

Quadrangle(s): Santa Fe,NM

ERIS

Hydrologic Information

The Wetland Type map shows wetland existence overlaid on an aerial imagery. The Flood Hazard Zones map shows FEMA flood hazard zones overlaid on an aerial imagery. Relevant FIRM panels and detailed zone information is provided below.
For detailed Zone descriptions please click the link: https://floodadvocate.com/fema-zone-definitions

Available FIRM Panels in area:	35049C0416E(effective:2012-12-04)

Flood Zone AE-11

Zone:	AE
Zone subtype:	FLOODWAY


Flood Zone X-01

Zone:	X
Zone subtype:	0.2 PCT ANNUAL CHANCE FLOOD HAZARD

Flood Zone X-12

Zone:	X
Zone subtype:	AREA OF MINIMAL FLOOD HAZARD

Geologic Information



Geologic Units

This maps shows geologic units in the area. Please refer to the report for detailed descriptions.

N

0 0.125 0.25 Miles

ERIS

Geologic Information

The previous page shows USGS geology information. Detailed information about each unit is provided below.

Geologic Unit Qoa

Unit Name:	Older alluvial deposits of upland plains and piedmont areas, and calcic soils and eolian cover sediments of High Plains region
Unit Age:	Middle to lower Pleistocene
Primary Rock Type:	Unconsolidated
Secondary Rock Type:	
Unit Description:	Includes scattered lacustrine, playa, and alluvial deposits of the Tahoka, Double Tanks, Tule, Blanco, Blackwater Draw, and Gatuna Formations, the latter of which may be Pliocene at base; outcrops, however, are basically of Quaternary deposits.

Geologic Unit Qp

Unit Name:	Piedmont alluvial deposits
Unit Age:	Holocene to lower Pleistocene
Primary Rock Type:	Unconsolidated
Secondary Rock Type:	
Unit Description:	Includes deposits of higher gradient tributaries bordering major stream valleys, alluvial veneers of the piedmont slope, and alluvial fans. May locally include uppermost Pliocene deposits.

Geologic Unit QTs

Unit Name:	Upper Santa Fe Group
Unit Age:	Middle Pleistocene to uppermost Miocene
Primary Rock Type:	Conglomerate-sandstone
Secondary Rock Type:	Coarse-detrital
Unit Description:	Includes Camp Rice, Fort Hancock, Palomas, Sierra Ladrones, Arroyo Ojito, Ancha, Puye, and Alamosa Formations.

Geologic Unit Tsf

Unit Name:	Lower Santa Fe Group
Unit Age:	Upper Miocene to uppermost Oligocene
Primary Rock Type:	Conglomerate-sandstone
Secondary Rock Type:	Coarse-detrital
Unit Description:	Includes Hayner Ranch, Rincon Valley, Popotosa, Cochiti, Tesuque, Chamita, Abiquiu, Zia, and other formations.


Geologic Unit YXp

Unit Name:	Mesoproterozoic and Paleoproterozoic plutonic rocks, undivided
Unit Age:	Mesoproterozoic and Paleoproterozoic
Primary Rock Type:	Plutonic
Secondary Rock Type:	

Geologic Information

Unit Description:	Mesoproterozoic and Paleoproterozoic plutonic rocks, undivided

Soil Information



SSURGO Soils

N

0 0.125 0.25 Miles

This maps shows SSURGO soil units around the target property. Please refer to the report for detailed soil descriptions.

ERIS

Soil Information

The previous page shows a soil map using SSURGO data from USDA Natural Resources Conservation Service. Detailed information about each unit is provided below.

Map Unit 113 (2.1%)

Map Unit Name:	Delvalle-Urban land complex, 0 to 2 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.
Major components are printed below	
Delvalle(60%)	
horizon A(0cm to 8cm)	Fine sandy loam
horizon Bk1(8cm to 25cm)	Fine sandy loam
horizon Bk2(25cm to 48cm)	Fine sandy loam
horizon Bk3(48cm to 86cm)	Fine sandy loam
horizon Bk4(86cm to 137cm)	Sandy loam
horizon BCk1(137cm to 160cm)	Very gravelly sand
horizon BCk2(160cm to 183cm)	Extremely gravelly coarse sand
horizon C1(183cm to 234cm)	Very gravelly loamy coarse sand
horizon C2(234cm to 266cm)	Sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 113 - Delvalle-Urban land complex, 0 to 2 percent slopes

Component: Delvalle (60%)
The Delvalle component makes up 60 percent of the map unit. Slopes are 0 to 2 percent. This component is on stream terraces, valleys. The parent material consists of alluvium derived from granite, gneiss, and schist. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 3 percent. This component is in the R035XA112NM Loamy ecological site. Nonirrigated land capability classification is 6c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 3 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Urban land (30%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Devargas (5%)
Generated brief soil descriptions are created for major soil components. The Devargas soil is a minor component.

Component: Riovista (3%)
Generated brief soil descriptions are created for major soil components. The Riovista soil is a minor component.

Component: Dumps (2%)
Generated brief soil descriptions are created for major soil components. The Dumps soil is a minor component.

Map Unit 114 (8.24%)

Map Unit Name:	Devargas-Urban land complex, 1 to 3 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	

Soil Information

Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	C - Soils in this group have moderately high runoff potential when thoroughly wet. Water transmission through the soil is somewhat restricted.

Major components are printed below

Devargas(50%)

horizon A(0cm to 5cm)	Loam
horizon Bt1(5cm to 23cm)	Loam
horizon Bt2(23cm to 43cm)	Clay loam
horizon Btk1(43cm to 63cm)	Clay loam
horizon Btk2(63cm to 76cm)	Loam
horizon Bk(76cm to 84cm)	Very gravelly coarse sandy loam
horizon 2BCk(84cm to 107cm)	Extremely gravelly loamy coarse sand
horizon 2C1(107cm to 170cm)	Extremely cobbly coarse sand
horizon 2C2(170cm to 216cm)	Extremely gravelly loamy coarse sand
horizon 2C3(216cm to 239cm)	Very gravelly coarse sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 114 - Devargas-Urban land complex, 1 to 3 percent slopes

Component: Devargas (50%)
The Devargas component makes up 50 percent of the map unit. Slopes are 1 to 3 percent. This component is on high stream terraces, valleys. The parent material consists of alluvium derived from sandstone over alluvium derived from granite, gneiss, and schist. Depth to a root restrictive layer, strongly contrasting textural stratification, is 28 to 31 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the R035XA112NM Loamy ecological site. Nonirrigated land capability classification is 6c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 4 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Urban land (45%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Delvalle (3%)
Generated brief soil descriptions are created for major soil components. The Delvalle soil is a minor component.

Component: Panky (1%)
Generated brief soil descriptions are created for major soil components. The Panky soil is a minor component.

Component: Dumps (1%)
Generated brief soil descriptions are created for major soil components. The Dumps soil is a minor component.

Map Unit 122 (0.75%)

Map Unit Name:	Cuyamungue-Riverwash complex, 0 to 2 percent slopes, flooded
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Excessively drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.

Major components are printed below

Cuyamungue(60%)

horizon AC(0cm to 8cm)	Very gravelly coarse sand
horizon C1(8cm to 43cm)	Stratified gravelly coarse sand to very gravelly coarse sand
horizon C2(43cm to 61cm)	Stratified gravelly coarse sand to very gravelly coarse sand
horizon C3(61cm to 89cm)	Very gravelly coarse sand

horizon C4(89cm to 147cm)	Stratified gravelly coarse sand to extremely gravelly coarse sand
horizon C5(147cm to 218cm)	Stratified very gravelly coarse sand to extremely gravelly coarse sand
horizon C6(218cm to 254cm)	Extremely gravelly loamy coarse sand
Riverwash(30%)	
horizon C1(0cm to 25cm)	Gravelly coarse sand
horizon C2(25cm to 127cm)	Very gravelly coarse sand
horizon C3(127cm to 165cm)	Gravelly sandy loam
horizon C4(165cm to 216cm)	Gravelly coarse sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 122 - Cuyamungue-Riverwash complex, 0 to 2 percent slopes, flooded

Component: Cuyamungue (60%)
The Cuyamungue component makes up 60 percent of the map unit. Slopes are 0 to 2 percent. This component is on flood plains on valley floors, valleys. The parent material consists of alluvium derived from granite, gneiss, schist, and granitic sandstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is excessively drained. Water movement in the most restrictive layer is very high. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is low. This soil is frequently flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 0 percent. This component is in the F036XA005NM Riverine Riparian ecological site. Nonirrigated land capability classification is 4w. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 1 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Riverwash (30%)
Generated brief soil descriptions are created for major soil components. The Riverwash is a miscellaneous area.

Component: Zia (4%)
Generated brief soil descriptions are created for major soil components. The Zia soil is a minor component.

Component: Bosquecito (3%)
Generated brief soil descriptions are created for major soil components. The Bosquecito soil is a minor component.

Component: Mirada (2%)
Generated brief soil descriptions are created for major soil components. The Mirada soil is a minor component.

Component: Scogg (1%)
Generated brief soil descriptions are created for major soil components. The Scogg soil is a minor component.

Map Unit 204 (0.15%)

Map Unit Name:	Altazano loamy sand, 0 to 2 percent slopes, flooded
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Somewhat excessively drained
Hydrologic Group - Dominant:	B - Soils in this group have moderately low runoff potential when thoroughly wet. Water transmission through the soil is unimpeded.
Major components are printed below	
Altazano(85%)	
horizon AC(0cm to 8cm)	Loamy sand
horizon C1(8cm to 20cm)	Fine sandy loam
horizon C2(20cm to 30cm)	Loamy sand
horizon C3(30cm to 46cm)	Stratified sandy loam to loam
horizon C4(46cm to 66cm)	Gravelly loamy coarse sand
horizon Btkb1(66cm to 74cm)	Loam
horizon Btkb2(74cm to 91cm)	Loam
horizon Bkb(91cm to 147cm)	Loam
horizon BCkb1(147cm to 193cm)	Gravelly coarse sandy loam

horizon BCkb2(193cm to 234cm)	Gravelly coarse sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 204 - Altazano loamy sand, 0 to 2 percent slopes, flooded

Component: Altazano (85%)
The Altazano component makes up 85 percent of the map unit. Slopes are 0 to 2 percent. This component is on flood plains on valley floors, valleys. The parent material consists of alluvium derived from granite, gneiss, schist, granitic sandstone, fanglomerate, and mudstone. Depth to a root restrictive layer, strongly contrasting textural stratification, is 22 to 30 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is low. This soil is occasionally flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the R035XG114NM Gravelly ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 4 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Buckhorse (5%)
Generated brief soil descriptions are created for major soil components. The Buckhorse soil is a minor component.

Component: Levante (3%)
Generated brief soil descriptions are created for major soil components. The Levante soil is a minor component.

Component: Tanoan (3%)
Generated brief soil descriptions are created for major soil components. The Tanoan soil is a minor component.

Component: Riverwash (2%)
Generated brief soil descriptions are created for major soil components. The Riverwash soil is a minor component.

Component: Urban land (2%)
Generated brief soil descriptions are created for major soil components. The Urban land soil is a minor component.

Map Unit 206 (1.51%)

Map Unit Name:	Encantado very cobbly sandy loam, 25 to 45 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Somewhat excessively drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.

Major components are printed below

Encantado(90%)

horizon ABk(0cm to 5cm)	Very cobbly sandy loam
horizon Bk1(5cm to 20cm)	Gravelly sandy loam
horizon Bk2(20cm to 30cm)	Gravelly coarse sandy loam
horizon Bk3(30cm to 61cm)	Very gravelly coarse sandy loam
horizon BCk(61cm to 79cm)	Gravelly loamy sand
horizon BCk1(79cm to 142cm)	Very gravelly loamy coarse sand
horizon BCk2(142cm to 170cm)	Gravelly loamy sand
horizon C(170cm to 208cm)	Gravelly loamy coarse sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 206 - Encantado very cobbly sandy loam, 25 to 45 percent slopes

Component: Encantado (90%)
The Encantado component makes up 90 percent of the map unit. Slopes are 25 to 45 percent. This component is on eroded fan

remnants, fan piedmonts. The parent material consists of colluvium derived from granite, gneiss, and schist over residuum weathered from granitic fanglomerate and sandstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the F036XA136NM Pinyon-juniper-apache Plume ecological site. Nonirrigated land capability classification is 7e. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 23 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Nazario (4%)
Generated brief soil descriptions are created for major soil components. The Nazario soil is a minor component.

Component: Encantado (3%)
Generated brief soil descriptions are created for major soil components. The Encantado soil is a minor component.

Component: Urban land (2%)
Generated brief soil descriptions are created for major soil components. The Urban land soil is a minor component.

Component: Rock outcrop (1%)
Generated brief soil descriptions are created for major soil components. The Rock outcrop soil is a minor component.

Map Unit 207 (45.14%)

Map Unit Name: Urban land

No more attributes available for this map unit

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 207 - Urban land

Component: Urban land (85%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Alire (4%)
Generated brief soil descriptions are created for major soil components. The Alire soil is a minor component.

Component: Panky (3%)
Generated brief soil descriptions are created for major soil components. The Panky soil is a minor component.

Component: Altazano (2%)
Generated brief soil descriptions are created for major soil components. The Altazano soil is a minor component.

Component: Buckhorse (2%)
Generated brief soil descriptions are created for major soil components. The Buckhorse soil is a minor component.

Component: Predawn (2%)
Generated brief soil descriptions are created for major soil components. The Predawn soil is a minor component.

Component: Delvalle (1%)
Generated brief soil descriptions are created for major soil components. The Delvalle soil is a minor component.

Component: Tanoan (1%)
Generated brief soil descriptions are created for major soil components. The Tanoan soil is a minor component.

Map Unit 208 (24.84%)

Map Unit Name: Alire-Urban land complex, 2 to 8 percent slopes

Bedrock Depth - Min:

Watertable Depth - Annual Min:

Soil Information

Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	C - Soils in this group have moderately high runoff potential when thoroughly wet. Water transmission through the soil is somewhat restricted.

Major components are printed below

Alire(50%)

horizon A(0cm to 10cm)	Loam
horizon Bt(10cm to 28cm)	Clay loam
horizon Btk1(28cm to 51cm)	Clay loam
horizon Btk2(51cm to 69cm)	Loam
horizon Bk1(69cm to 107cm)	Loam
horizon Bk2(107cm to 130cm)	Gravelly loam
horizon Bkq1(130cm to 175cm)	Gravelly loam
horizon Bkq2(175cm to 241cm)	Gravelly loam
horizon C(241cm to 251cm)	Gravelly sandy loam

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 208 - Alire-Urban land complex, 2 to 8 percent slopes

Component: Alire (50%)
The Alire component makes up 50 percent of the map unit. Slopes are 2 to 8 percent. This component is on beveled eroded fan remnants, fan piedmonts. The parent material consists of alluvium derived from granite, gneiss, schist, and loess. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is high. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the R035XA112NM Loamy ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 23 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 9 within 30 inches of the soil surface.

Component: Urban land (40%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Predawn (4%)
Generated brief soil descriptions are created for major soil components. The Predawn soil is a minor component.

Component: Tanoan (3%)
Generated brief soil descriptions are created for major soil components. The Tanoan soil is a minor component.

Component: Altazano (2%)
Generated brief soil descriptions are created for major soil components. The Altazano soil is a minor component.

Component: Encantado (1%)
Generated brief soil descriptions are created for major soil components. The Encantado soil is a minor component.

Map Unit 210 (0.87%)

Map Unit Name:	Urban land-Buckhorse-Altazano complex, 2 to 8 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	
Hydrologic Group - Dominant:	

Major components are printed below

Buckhorse(20%)

horizon A(0cm to 10cm)	Coarse sandy loam
horizon Bt(10cm to 28cm)	Coarse sandy loam
horizon Btk1(28cm to 56cm)	Loam

horizon Btk2(56cm to 94cm)	Loam
horizon Bk(94cm to 124cm)	Fine sandy loam
horizon BCk(124cm to 155cm)	Sandy loam
horizon C(155cm to 211cm)	Gravelly coarse sand
Altazano(10%)	
horizon AC(0cm to 5cm)	Gravelly sandy loam
horizon C1(5cm to 20cm)	Gravelly coarse sandy loam
horizon C2(20cm to 48cm)	Very gravelly loamy coarse sand
horizon C3(48cm to 74cm)	Gravelly sandy loam
horizon Btkb1(74cm to 117cm)	Loam
horizon Btkb2(117cm to 165cm)	Loam
horizon BCkb(165cm to 188cm)	Gravelly coarse sandy loam
horizon Ckb(188cm to 229cm)	Gravelly loamy coarse sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 210 - Urban land-Buckhorse-Altazano complex, 2 to 8 percent slopes

Component: Urban land (60%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Buckhorse (20%)
The Buckhorse component makes up 20 percent of the map unit. Slopes are 2 to 8 percent. This component is on eroded fan remnants, fan piedmonts. The parent material consists of slope alluvium derived from granite, gneiss, schist, granitic sandstone, fanglomerate, and mudstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the R035XA112NM Loamy ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 10 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Altazano (10%)
The Altazano component makes up 10 percent of the map unit. Slopes are 2 to 8 percent. This component is on eroded fan remnants, fan piedmonts. The parent material consists of slope alluvium derived from granite, gneiss, schist, granitic sandstone, fanglomerate, and mudstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is frequently flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the R035XG114NM Gravelly ecological site. Nonirrigated land capability classification is 4w. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 13 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Levante (7%)
Generated brief soil descriptions are created for major soil components. The Levante soil is a minor component.

Component: Riverwash (3%)
Generated brief soil descriptions are created for major soil components. The Riverwash soil is a minor component.

Map Unit 211 (13.47%)

Map Unit Name:	Tanoan-Encantado-Urban land complex, 5 to 25 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Somewhat excessively drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.

Major components are printed below

Soil Information

Tanoan(35%)

horizon A(0cm to 8cm)	Gravelly sandy loam
horizon Bk1(8cm to 18cm)	Loam
horizon Bk2(18cm to 61cm)	Loam
horizon Bk3(61cm to 81cm)	Sandy loam
horizon Bkq(81cm to 145cm)	Loam
horizon BCk1(145cm to 178cm)	Gravelly loamy coarse sand
horizon BCk2(178cm to 213cm)	Gravelly coarse sandy loam

Encantado(30%)

horizon ABk(0cm to 8cm)	Very gravelly sandy loam
horizon Bk1(8cm to 23cm)	Very gravelly loam
horizon Bk2(23cm to 56cm)	Very gravelly coarse sandy loam
horizon BCk1(56cm to 84cm)	Gravelly loamy coarse sand
horizon BCk2(84cm to 114cm)	Very gravelly loamy coarse sand
horizon BCk3(114cm to 137cm)	Very gravelly loamy coarse sand
horizon C1(137cm to 160cm)	Gravelly loamy sand
horizon C2(160cm to 216cm)	Very gravelly loamy sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 211 - Tanoan-Encantado-Urban land complex, 5 to 25 percent slopes

Component: Tanoan (35%)
The Tanoan component makes up 35 percent of the map unit. Slopes are 5 to 15 percent. This component is on eroded fan remnants, fan piedmonts. The parent material consists of alluvium derived from granite, gneiss, schist, and loess over residuum weathered from basaltic tuff or granitic sandstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the F036XA136NM Pinyon-juniper-apache Plume ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 15 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Encantado (30%)
The Encantado component makes up 30 percent of the map unit. Slopes are 10 to 25 percent. This component is on eroded fan remnants, fan piedmonts. The parent material consists of colluvium and slope alluvium derived from granite, gneiss, and schist over residuum weathered from granitic fanglomerate and sandstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the F036XA136NM Pinyon-juniper-apache Plume ecological site. Nonirrigated land capability classification is 4s. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 27 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Urban land (25%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Altazano (4%)
Generated brief soil descriptions are created for major soil components. The Altazano soil is a minor component.

Component: Junebee (3%)
Generated brief soil descriptions are created for major soil components. The Junebee soil is a minor component.

Component: Nazario (2%)
Generated brief soil descriptions are created for major soil components. The Nazario soil is a minor component.

Component: Alire (1%)
Generated brief soil descriptions are created for major soil components. The Alire soil is a minor component.

Soil Information

Map Unit 213 (0.33%)

Map Unit Name:	Levante-Riverwash complex, 1 to 3 percent slopes, flooded
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Excessively drained
Hydrologic Group - Dominant:	A - Soils in this group have low runoff potential when thoroughly wet. Water is transmitted freely through the soil.

Major components are printed below

Levante(55%)	
horizon AC(0cm to 10cm)	Loamy sand
horizon C1(10cm to 43cm)	Coarse sand
horizon C2(43cm to 81cm)	Gravelly coarse sand
horizon C3(81cm to 114cm)	Stratified gravelly loamy coarse sand to gravelly coarse sand
horizon C4(114cm to 147cm)	Gravelly loamy coarse sand
horizon C5(147cm to 218cm)	Very gravelly coarse sand
horizon C6(218cm to 310cm)	Very gravelly coarse sand
Riverwash(35%)	
horizon C1(0cm to 25cm)	Gravelly coarse sand
horizon C2(25cm to 127cm)	Very gravelly coarse sand
horizon C3(127cm to 165cm)	Gravelly sandy clay loam
horizon C4(165cm to 216cm)	Gravelly coarse sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 213 - Levante-Riverwash complex, 1 to 3 percent slopes, flooded

Component: Levante (55%)
The Levante component makes up 55 percent of the map unit. Slopes are 1 to 3 percent. This component is on narrow flood plains on valley floors, valleys. The parent material consists of alluvium derived from granite, gneiss, schist, and granitic sandstone. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is excessively drained. Water movement in the most restrictive layer is high. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is low. This soil is occasionally flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the R035XA113NM Sandy ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 7 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Riverwash (35%)
Generated brief soil descriptions are created for major soil components. The Riverwash is a miscellaneous area.

Component: Altazano (5%)
Generated brief soil descriptions are created for major soil components. The Altazano soil is a minor component.

Component: Dondiego (3%)
Generated brief soil descriptions are created for major soil components. The Dondiego soil is a minor component.

Component: Urban land (2%)
Generated brief soil descriptions are created for major soil components. The Urban land soil is a minor component.

Map Unit 214 (1.02%)

Map Unit Name:	Nazario-Urban land complex, 2 to 8 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	B - Soils in this group have moderately low runoff potential when thoroughly

	wet. Water transmission through the soil is unimpeded.

Major components are printed below

Nazario(55%)

horizon ABk(0cm to 5cm)	Gravelly loam
horizon Bk1(5cm to 18cm)	Gravelly loam
horizon Bk2(18cm to 38cm)	Gravelly loam
horizon Bk3(38cm to 61cm)	Gravelly loam
horizon 2BCk1(61cm to 109cm)	Very gravelly loamy coarse sand
horizon 2BCk2(109cm to 132cm)	Gravelly loamy coarse sand
horizon 2C1(132cm to 170cm)	Coarse sand
horizon 2C2(170cm to 239cm)	Gravelly coarse sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 214 - Nazario-Urban land complex, 2 to 8 percent slopes

Component: Nazario (55%)
The Nazario component makes up 55 percent of the map unit. Slopes are 2 to 8 percent. This component is on beveled eroded fan remnants, fan piedmonts. The parent material consists of alluvium derived from granite, gneiss, schist, and loess over residuum weathered from granitic fanglomerate and sandstone. Depth to a root restrictive layer, strongly contrasting textural stratification, is 20 to 28 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the F036XA136NM Pinyon-juniper-apache Plume ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 28 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Urban land (30%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Alire (8%)
Generated brief soil descriptions are created for major soil components. The Alire soil is a minor component.

Component: Encantado (4%)
Generated brief soil descriptions are created for major soil components. The Encantado soil is a minor component.

Component: Tanoan (3%)
Generated brief soil descriptions are created for major soil components. The Tanoan soil is a minor component.

Map Unit 301 (0.22%)

Map Unit Name:	Enmedio-Atalaya-Rock outcrop complex, 5 to 60 percent slopes
Bedrock Depth - Min:	117cm
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	C - Soils in this group have moderately high runoff potential when thoroughly wet. Water transmission through the soil is somewhat restricted.

Major components are printed below

Enmedio(60%)

horizon A(0cm to 5cm)	Extremely cobbly sandy loam
horizon Bt1(5cm to 13cm)	Very gravelly sandy clay loam
horizon Bt2(13cm to 32cm)	Very gravelly sandy clay loam
horizon Bt3(32cm to 47cm)	Very gravelly sandy clay loam
horizon 2Ct(47cm to 89cm)	Cobbles
horizon 2C(89cm to 117cm)	Cobbles
horizon 2R(117cm to 142cm)	Bedrock

Atalaya(20%)

horizon A(0cm to 3cm)	Very gravelly sandy loam
horizon Bt1(3cm to 10cm)	Gravelly coarse sandy loam
horizon Bt2(10cm to 18cm)	Gravelly coarse sandy loam
horizon Bt3(18cm to 31cm)	Gravelly coarse sandy loam
horizon BC1(31cm to 60cm)	Gravelly coarse sandy loam
horizon BC2(60cm to 87cm)	Cobbly coarse sandy loam
horizon 2CBk(87cm to 127cm)	Cobbles
horizon 2R(127cm to 152cm)	Bedrock

Rock outcrop(10%)

horizon R(0cm to 158cm)	Bedrock

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 301 - Enmedio-Atalaya-Rock outcrop complex, 5 to 60 percent slopes

Component: Enmedio (60%)
The Enmedio component makes up 60 percent of the map unit. Slopes are 15 to 60 percent. This component is on hills, foothills. The parent material consists of colluvium derived from granite, gneiss, and schist over residuum weathered from granite. Depth to a root restrictive layer, strongly contrasting textural stratification, is 18 to 39 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is very low. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the F048AY015NM Unspecified ecological site. Nonirrigated land capability classification is 7e. This soil does not meet hydric criteria. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Atalaya (20%)
The Atalaya component makes up 20 percent of the map unit. Slopes are 5 to 15 percent. This component is on beveled hills, foothills. The parent material consists of slope alluvium derived from granite, gneiss, and schist over residuum weathered from granite and schist. Depth to a root restrictive layer, strongly contrasting textural stratification, is 20 to 39 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is very low. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the F048AY015NM Unspecified ecological site. Nonirrigated land capability classification is 4e. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 3 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Rock outcrop (10%)
Generated brief soil descriptions are created for major soil components. The Rock outcrop is a miscellaneous area.

Component: Setonville (7%)
Generated brief soil descriptions are created for major soil components. The Setonville soil is a minor component.

Component: Urban land (3%)
Generated brief soil descriptions are created for major soil components. The Urban land soil is a minor component.

Map Unit 304 (1.37%)

Map Unit Name:	Legate-Yohalem-Zarmand complex, 5 to 50 percent slopes
Bedrock Depth - Min:	38cm
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Somewhat excessively drained
Hydrologic Group - Dominant:	D - Soils in this group have high runoff potential when thoroughly wet. Water movement through the soil is restricted or very restricted.

Major components are printed below

Legate(60%)

horizon Ak(0cm to 5cm)	Extremely gravelly sandy loam
horizon Bk1(5cm to 23cm)	Very gravelly fine sandy loam

horizon Bk2(23cm to 36cm)	Very gravelly sandy loam
horizon Bk3(36cm to 46cm)	Very gravelly sandy loam
horizon 2R(46cm to 71cm)	Bedrock
Yohalem(20%)	
horizon A(0cm to 3cm)	Very gravelly clay loam
horizon Bw(3cm to 18cm)	Paragravelly clay loam
horizon BCky(18cm to 38cm)	Extremely paragravelly clay
horizon Cr(38cm to 63cm)	Bedrock
Zarmand(15%)	
horizon A(0cm to 3cm)	Extremely channery fine sandy loam
horizon ABk(3cm to 23cm)	Gravelly fine sandy loam
horizon Bk1(23cm to 43cm)	Gravelly loam
horizon 2Bk2(43cm to 61cm)	Paragravelly loam
horizon 2Crk(61cm to 74cm)	Bedrock
horizon 2R(74cm to 99cm)	Bedrock

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 304 - Legate-Yohalem-Zarmand complex, 5 to 50 percent slopes

Component: Legate (60%)
The Legate component makes up 60 percent of the map unit. Slopes are 15 to 45 percent. This component is on hills, foothills. The parent material consists of colluvium derived from limestone. Depth to a root restrictive layer, bedrock, lithic, is 10 to 20 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is very low. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is moderate. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the F048AY015NM Unspecified ecological site. Nonirrigated land capability classification is 7s. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 72 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.


Component: Yohalem (20%)
The Yohalem component makes up 20 percent of the map unit. Slopes are 30 to 50 percent. This component is on hills, foothills. The parent material consists of colluvium derived from shale and limestone over residuum weathered from shale. Depth to a root restrictive layer, bedrock, paralithic, is 10 to 20 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is very low. Available water to a depth of 60 inches (or restricted depth) is very low. Shrink-swell potential is very high. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the F048AY015NM Unspecified ecological site. Nonirrigated land capability classification is 6e. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 5 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Zarmand (15%)
The Zarmand component makes up 15 percent of the map unit. Slopes are 5 to 15 percent. This component is on foothills. The parent material consists of alluvium derived from limestone and sandstone over residuum weathered from limestone. Depth to a root restrictive layer, bedrock, paralithic, is 20 to 30 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is very low. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is moderate. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the F048AY015NM Unspecified ecological site. Nonirrigated land capability classification is 7s. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 58 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Rock outcrop (3%)
Generated brief soil descriptions are created for major soil components. The Rock outcrop soil is a minor component.

Component: Urban land (2%)
Generated brief soil descriptions are created for major soil components. The Urban land soil is a minor component.

Wells and Additional Sources



Wells & Additional Sources

N

0 0.15 0.3 0.6 Miles

- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- OGW Sites with Higher Elevation
- OGW Sites with Same Elevation
- OGW Sites with Lower Elevation
- OGW Sites with Unknown Elevation

ERIS

Wells and Additional Sources Summary

Federal Sources

Public Water Systems Violations and Enforcement Data

Map Key	PWS ID	Distance (ft)	Direction
200	NM3580226	3149.45	NW
308	NM3590826	4317.07	NW

Safe Drinking Water Information System (SDWIS)

Map Key	PWS ID	Distance (ft)	Direction
200	NM3580226	3149.45	NW
206	NM3591526	3333.81	E
308	NM3590826	4317.07	NW

USGS National Water Information System

Map Key	Site No	Distance (ft)	Direction
27	USGS-354053105552601	1087.05	E
45	USGS-354104105555010	1332.27	NW
68	USGS-354104105555510	1621.83	NW
73	USGS-354046105560001	1725.23	WSW
96	USGS-354103105560210	2049.14	WNW
114	USGS-354039105560301	2277.11	SW
145	USGS-354113105560201	2668.60	NW
185	USGS-354025105555501	2975.87	SSW
237	USGS-354113105561801	3696.97	WNW
242	USGS-354052105562701	3845.18	W
245	USGS-354032105562001	3838.17	WSW
252	USGS-354100105562701	3919.49	WNW
263	USGS-354106105562610	3993.48	WNW
273	USGS-354107105562700	4105.03	WNW
297	USGS-354019105550701	4258.80	SE
412	USGS-354130105561210	4523.57	NW
452	USGS-354020105562001	4592.04	SW
509	USGS-354007105560401	4940.45	SSW
514	USGS-354029105563401	4992.49	WSW
529	USGS-354026105563401	5140.23	WSW
536	USGS-354135105561701	5174.81	NW
536	USGS-354135105561702	5174.81	NW
550	USGS-354002105555801	5249.19	SSW

State Sources

Oil and Gas Wells

Map Key	ID	Distance (ft)	Direction
	No records found		

Point of Diversion Report

Map Key	POD Rec No	Distance (ft)	Direction

Wells and Additional Sources Summary

1	3555	130.35	SSE
2	49698	362.59	W
3	11264	341.83	S
4	40696	412.64	W
5	39279	389.44	SSW
6	199068	421.29	NNW
7	51451	467.40	ENE
8	212857	459.89	NNE
9	11080	523.89	WNW
10	47351	497.39	NNW
11	67859	529.93	N
12	20448	541.59	SSE
13	287608	593.64	NW
14	3523	730.08	N
15	21922	782.44	WSW
16	48250	790.75	NNE
17	333772	821.69	ENE
18	205389	864.43	NW
19	21582	866.40	S
20	244529	874.30	NNW
21	18737	883.83	SW
22	17079	912.71	SE
23	66847	974.05	SE
24	170246	1023.16	WNW
25	161433	979.63	NNW
26	180566	1036.94	ESE
28	22644	1044.99	S
29	236868	1136.96	SW
29	237237	1136.96	SW
30	55843	1188.78	WNW
31	25978	1174.31	SW
32	44087	1217.44	WNW
33	145523	1220.30	WNW
34	44008	1181.13	S
35	61605	1188.60	N
36	51673	1215.28	NNE
37	58127	1241.85	S
38	51116	1275.17	NW
39	197077	1320.26	W
40	282754	1281.90	SW
41	50259	1310.52	SE
42	16933	1305.42	SSW
43	34043	1314.82	N
44	37913	1325.59	SW
46	18083	1351.44	WSW
47	64511	1341.44	NE
48	28211	1333.93	SSE
49	157764	1382.42	SW
50	54526	1381.37	N
51	334346	1429.19	ESE
52	35434	1433.99	ESE
53	170332	1453.41	E
54	26436	1432.49	N
55	146760	1451.05	N
56	147896	1467.72	S
57	24565	1522.70	WNW
58	339881	1496.58	WSW
59	272507	1539.80	E
60	37398	1578.80	ESE
61	339880	1547.25	WSW
62	26213	1565.71	NE
63	339879	1573.10	WSW
64	2148	1566.89	SE
65	19029	1629.55	E
66	59116	1587.71	NNW

Wells and Additional Sources Summary

67	47541	1605.27	NNW
69	36980	1673.78	W
70	36762	1689.51	WNW
71	57818	1668.87	SW
72	197078	1682.51	S
74	333151	1746.65	WSW
75	33301	1764.80	S
76	139929	1787.63	SW
77	285779	1787.30	S
78	23131	1795.26	NE
79	334055	1801.09	SE
80	44800	1824.54	WSW
81	337651	1822.13	SW
82	341180	1819.60	S
83	58088	1864.34	W
84	334537	1827.96	NNW
84	8784	1827.96	NNW
85	45725	1824.71	SSE
86	154803	1834.96	N
87	197079	1843.15	S
88	2300	1870.16	S
89	7415	1952.70	E
90	27075	1959.77	WNW
91	169331	1961.52	W
92	197877	1921.24	S
93	275692	1991.60	W
93	6700	1991.60	W
94	65820	2009.61	WNW
95	6181	2025.82	ESE
97	60337	2032.16	SE
98	173238	2034.19	SSE
99	38433	2062.89	SE
100	196983	2070.20	ENE
101	45295	2064.47	SSW
102	67447	2120.17	WNW
103	296840	2090.59	SW
104	46176	2107.51	WSW
105	147430	2122.88	NW
106	50582	2106.43	SW
107	25205	2170.37	SSE
108	48425	2207.67	SSE
109	105580	2214.68	SSE
110	63677	2261.03	W
111	147388	2277.10	E
112	40319	2234.53	SE
113	24289	2251.75	N
115	221255	2288.44	SW
116	8592	2286.65	NNE
116	26510	2286.65	NNE
116	143661	2286.65	NNE
117	34267	2322.15	SSE
118	58289	2373.44	ESE
119	335283	2374.01	WNW
120	32816	2353.26	NW
121	52631	2362.29	SW
122	27388	2361.80	SSE
123	2688	2416.90	W
124	42534	2376.95	S
125	12660	2390.26	SW
126	60616	2382.54	NNE
127	15734	2388.71	S
128	51104	2396.33	S
129	49621	2405.08	NNW
130	290334	2428.62	WSW
130	54561	2428.62	WSW
131	34861	2418.13	SSE

132	291975	2474.52	WNW
133	69509	2450.61	SSW
133	333099	2450.61	SSW
134	53638	2460.89	SW
135	195967	2464.91	NNW
136	241265	2547.62	E
136	13479	2547.62	E
137	146889	2543.26	ESE
138	142014	2511.83	S
139	196558	2621.61	WSW
140	47085	2638.11	E
141	355653	2625.06	SW
142	338812	2675.12	W
143	63741	2652.69	SW
144	339032	2661.70	WSW
146	61887	2665.35	NNE
147	15951	2690.87	WSW
148	11795	2708.45	NNW
149	13668	2736.26	WSW
150	307222	2735.69	SW
151	12420	2798.77	E
152	40682	2800.18	WNW
153	42592	2754.44	S
154	29795	2758.91	NNW
155	246340	2798.01	W
156	196619	2774.28	SSE
157	246341	2844.37	W
158	42191	2820.92	SW
159	343503	2851.06	W
160	45114	2810.53	SSE
161	197575	2827.36	SSE
162	6748	2864.35	ESE
163	343502	2867.35	W
164	330690	2861.40	WSW
165	246336	2870.84	W
165	271064	2870.84	W
166	14937	2854.66	SE
167	9958	2911.89	E
168	343505	2893.78	W
169	343504	2896.02	W
170	343506	2897.07	W
171	235372	2872.98	SSW
172	343507	2904.63	W
173	327368	2910.75	W
174	80129	2880.73	SW
175	291430	2915.62	W
175	291429	2915.62	W
176	343501	2918.10	W
177	327367	2925.56	W
178	327370	2928.24	W
179	25067	2896.55	NNE
180	291431	2929.90	W
180	271096	2929.90	W
181	325503	2950.81	E
182	327369	2954.46	W
183	305087	2959.75	W
184	16097	2960.60	SW
186	131410	2975.27	SSW
187	70020	2976.85	SSW
188	199573	3007.67	WSW
189	42901	3056.20	E
190	152366	3063.38	SE
191	139844	3073.87	SW
192	162543	3124.85	E
193	69858	3072.90	SSE
194	23145	3096.67	SE

195	56428	3105.66	SW
196	10217	3155.97	ESE
197	105647	3123.03	SW
198	146887	3135.92	WSW
199	49303	3143.86	NW
201	29206	3158.30	SSW
202	59540	3167.58	SSE
203	163069	3223.53	SSW
204	67600	3254.62	ENE
205	301879	3237.88	NW
207	301873	3323.16	NW
208	12381	3354.91	E
209	31947	3365.89	WNW
210	3655	3350.28	ENE
211	52864	3343.65	WSW
212	36099	3368.36	E
213	155871	3372.48	W
214	301874	3393.69	WNW
215	32100	3409.88	ESE
216	21085	3414.80	NNW
217	202114	3435.98	SSE
218	52131	3478.28	SE
218	17495	3478.28	SE
219	62125	3466.12	SSE
220	36502	3536.67	E
221	301876	3518.61	NW
222	20920	3504.77	S
223	58504	3554.29	WNW
224	44010	3541.79	ESE
225	301872	3541.08	NW
226	177236	3571.16	E
226	151588	3571.16	E
227	295910	3572.11	E
228	297680	3575.05	NW
229	58529	3565.66	SW
230	67173	3562.40	S
231	64655	3570.37	S
232	8653	3592.29	SW
233	333096	3584.88	SSE
234	22175	3588.97	SSE
235	42452	3616.33	SW
236	3300	3665.35	W
238	130574	3668.40	SSE
238	148509	3668.40	SSE
239	36178	3668.52	SSE
240	54636	3740.25	WNW
241	21290	3771.10	E
243	241491	3804.95	S
244	104934	3848.23	E
244	80815	3848.23	E
246	338183	3832.40	SW
247	301877	3839.50	NW
248	301878	3852.37	NW
249	15825	3876.16	ESE
250	324797	3856.03	SSW
251	147732	3892.19	W
253	24157	3874.11	SSW
254	338891	3890.76	NW
255	28075	3889.65	S
256	146943	3946.31	E
257	301875	3936.25	NW
258	297677	3962.37	WNW
259	80814	3951.98	E
259	338069	3951.98	E
260	28625	3940.75	WSW
260	333618	3940.75	WSW

261	287038	3980.89	WNW
262	25832	3991.16	E
264	33152	3975.15	SW
265	65668	3980.66	SW
266	6470	3978.04	S
267	10548	4029.71	E
268	43641	4058.97	W
269	31617	4029.64	WSW
270	325652	4035.57	SSW
271	30475	4049.25	SSW
272	145138	4042.01	SSE
274	19910	4118.70	E
275	5004	4082.26	SW
276	26776	4103.21	WSW
277	57187	4120.13	WSW
277	48503	4120.13	WSW
278	297679	4177.39	WNW
279	48012	4186.17	E
280	54226	4163.57	SSW
281	61848	4155.04	S
282	15057	4172.52	SSW
283	327416	4226.63	WNW
284	327417	4229.39	WNW
285	327418	4231.46	WNW
286	327419	4241.46	WNW
287	44048	4215.43	SW
288	327413	4262.03	WNW
289	327415	4264.22	WNW
290	18487	4224.47	NNW
291	54726	4226.94	SSW
292	13817	4227.77	SSW
293	252205	4283.56	WNW
294	336462	4285.99	WNW
295	336460	4291.34	WNW
296	336461	4294.68	WNW
298	336463	4314.89	WNW
299	336464	4319.44	WNW
300	336465	4323.56	WNW
301	252443	4326.54	WNW
302	147121	4275.97	S
303	251645	4332.76	WNW
304	336466	4333.89	WNW
305	41531	4300.73	SSW
306	37909	4295.81	SSE
307	28666	4307.72	SSW
309	336467	4366.97	WNW
310	336468	4371.07	WNW
311	251627	4372.75	WNW
312	336426	4399.85	WNW
313	252445	4405.61	WNW
314	336423	4409.93	WNW
315	336424	4412.06	WNW
316	336413	4413.41	WNW
317	336425	4414.25	WNW
318	248174	4413.57	WNW
319	336415	4419.25	WNW
320	248121	4420.61	WNW
320	336414	4420.61	WNW
321	336416	4421.29	WNW
322	6899	4369.08	S
323	336417	4423.39	WNW
324	336418	4425.55	WNW
325	336403	4426.82	WNW
326	336419	4427.76	WNW
327	336404	4428.69	WNW
328	251074	4428.77	WNW

329	336420	4430.90	WNW
330	251072	4430.83	WNW
331	336405	4430.61	WNW
332	246533	4432.68	WNW
332	336422	4432.68	WNW
333	336421	4433.21	WNW
334	246471	4433.10	WNW
335	336406	4433.52	WNW
336	336407	4435.54	WNW
337	327422	4438.18	WNW
338	336408	4437.62	WNW
339	336447	4439.11	WNW
340	12807	4399.48	SW
341	336409	4439.75	WNW
342	336410	4441.93	WNW
343	336402	4442.16	WNW
344	336448	4445.55	WNW
345	336401	4443.99	WNW
346	249128	4444.04	WNW
347	336411	4445.05	WNW
348	145440	4425.52	NW
349	249127	4445.89	WNW
350	336400	4445.88	WNW
351	336412	4447.33	WNW
352	336399	4447.81	WNW
353	17464	4394.38	S
354	336398	4449.81	WNW
355	336397	4449.90	WNW
356	249126	4450.94	WNW
357	248173	4452.23	WNW
358	336395	4454.13	WNW
359	336396	4454.87	WNW
360	336449	4457.10	WNW
361	336394	4456.33	WNW
362	22249	4433.48	ENE
363	249129	4461.66	WNW
364	336453	4464.63	WNW
365	248056	4464.35	WNW
366	336450	4465.81	WNW
367	247133	4464.21	WNW
368	336391	4470.51	WNW
369	336389	4472.65	WNW
369	249045	4472.65	WNW
370	336455	4474.71	WNW
371	291322	4476.75	WNW
371	336451	4476.75	WNW
372	336454	4477.00	WNW
373	249122	4475.57	WNW
374	57856	4421.95	SSE
375	336392	4480.26	WNW
376	336452	4482.61	WNW
377	249082	4483.48	WNW
378	336456	4486.23	WNW
379	327420	4487.65	WNW
380	336390	4486.69	WNW
381	327421	4489.99	WNW
382	336388	4489.38	WNW
382	336393	4489.38	WNW
383	258265	4489.81	WNW
384	246116	4489.82	WNW
385	255130	4487.97	WNW
386	246117	4494.97	WNW
386	249120	4494.97	WNW
387	327423	4495.54	WNW
388	336458	4497.32	WNW
389	336457	4497.81	WNW

390	248075	4497.55	WNW
391	288952	4500.52	W
392	336459	4501.61	WNW
393	331148	4506.73	E
394	288951	4504.44	WNW
395	249130	4506.64	WNW
396	249046	4511.05	WNW
397	289383	4515.50	WNW
398	249047	4515.03	WNW
399	2551	4521.78	E
400	3509	4512.66	ESE
401	36804	4520.41	E
402	252446	4531.43	WNW
403	46479	4539.82	E
404	143277	4522.18	E
405	249081	4540.52	WNW
405	249121	4540.52	WNW
406	147086	4491.50	NNW
407	249131	4548.78	WNW
408	258870	4551.00	WNW
409	246113	4552.93	WNW
410	33239	4522.19	WSW
411	336446	4554.92	WNW
411	337893	4554.92	WNW
413	291717	4570.04	WNW
414	19072	4521.83	N
415	252450	4578.28	WNW
416	291715	4581.49	WNW
417	291716	4582.15	WNW
418	249050	4582.83	WNW
419	337892	4589.53	WNW
420	336445	4591.19	WNW
421	336442	4593.74	WNW
421	336444	4593.74	WNW
421	337890	4593.74	WNW
422	288953	4599.85	WNW
423	249085	4599.11	WNW
423	249084	4599.11	WNW
423	249083	4599.11	WNW
424	337891	4597.97	WNW
425	337887	4598.65	WNW
425	337888	4598.65	WNW
426	44043	4547.49	S
427	258264	4602.32	WNW
428	336443	4601.95	WNW
429	27335	4557.93	SSW
430	337889	4605.92	WNW
431	255116	4605.48	WNW
432	337886	4608.25	WNW
433	258266	4611.35	WNW
434	336441	4611.55	WNW
435	249923	4610.83	WNW
436	337882	4614.58	WNW
436	336438	4614.58	WNW
437	336440	4615.05	WNW
437	337884	4615.05	WNW
438	337880	4617.53	WNW
438	336436	4617.53	WNW
439	336439	4618.34	WNW
440	260234	4618.87	WNW
441	337878	4619.30	WNW
442	337885	4620.09	WNW
442	336437	4620.09	WNW
443	337883	4621.84	WNW
443	288950	4621.84	WNW
443	327424	4621.84	WNW

444	249048	4624.51	WNW
445	337876	4622.87	WNW
446	336434	4623.29	WNW
447	337881	4624.18	WNW
447	336435	4624.18	WNW
448	337879	4624.32	WNW
448	336433	4624.32	WNW
449	288999	4626.87	WNW
450	337877	4628.91	WNW
451	336432	4631.88	WNW
451	337875	4631.88	WNW
453	336431	4639.28	WNW
453	337874	4639.28	WNW
454	249049	4641.36	WNW
455	9616	4641.40	E
456	337873	4644.48	WNW
457	260231	4645.75	WNW
458	336430	4648.48	WNW
459	337872	4652.48	WNW
460	336429	4656.49	WNW
460	337871	4656.49	WNW
461	291714	4657.24	WNW
462	142917	4615.43	NE
463	288912	4664.53	WNW
464	45676	4640.32	WSW
465	337870	4665.11	WNW
465	336428	4665.11	WNW
465	260233	4665.11	WNW
466	258263	4669.37	WNW
467	42243	4638.68	WSW
468	64154	4628.03	SW
469	337869	4671.12	WNW
469	336427	4671.12	WNW
470	46592	4631.31	SSW
471	62555	4682.42	E
472	57161	4669.58	W
473	21806	4686.39	ESE
474	35272	4666.65	WSW
475	45459	4687.84	E
476	249051	4700.87	WNW
477	5017	4709.36	W
478	196985	4695.54	E
479	249086	4711.36	WNW
480	25462	4710.06	W
481	291713	4716.39	WNW
482	249054	4726.51	WNW
483	49353	4705.95	WSW
484	19063	4702.00	SW
485	249053	4762.76	WNW
486	314995	4760.32	W
487	249052	4769.70	WNW
488	289031	4748.63	NW
489	65187	4749.93	WSW
490	287034	4785.93	W
491	8445	4728.45	N
492	50448	4794.42	ESE
493	18946	4739.91	SSE
493	52541	4739.91	SSE
494	214481	4756.94	SW
495	139928	4752.73	SSE
496	11048	4755.74	S
497	62618	4787.66	SW
498	302086	4800.15	NNW
499	298337	4813.17	NNW
500	63919	4862.21	W
501	16434	4862.39	E

502	289030	4857.03	NW
503	147367	4883.76	ESE
504	298338	4855.70	NNW
505	289029	4870.95	NW
506	42419	4885.59	SW
507	210209	4911.51	SW
508	143935	4916.36	SW
510	46889	4954.82	WSW
511	287037	5000.61	WNW
512	146884	4991.94	E
513	35290	5000.62	E
515	281378	4989.85	SW
516	4919	5006.59	WSW
517	48299	5042.71	SE
518	31094	5029.70	SW
519	49702	5078.66	ESE
520	53939	5064.99	WSW
521	24079	5064.71	SE
522	33932	5061.77	SW
523	18603	5088.40	SW
524	21074	5137.69	E
525	243539	5100.39	SW
526	351493	5138.62	E
527	40237	5140.30	WSW
528	25726	5135.06	WSW
530	51519	5147.83	WSW
531	9399	5167.23	SE
532	40804	5153.87	SSW
533	60584	5187.23	E
534	70893	5164.73	SW
535	146313	5166.13	SSW
537	323699	5206.72	W
538	28562	5194.31	SE
539	26682	5202.67	SW
540	297678	5244.13	WNW
541	32070	5197.60	SSW
542	67652	5208.48	WSW
543	15787	5248.35	E
544	16972	5239.02	WSW
545	20267	5231.21	WSW
546	7905	5221.75	S
547	33033	5258.32	NW
548	303892	5225.73	SSE
549	47363	5232.60	N
551	53338	5259.27	SSE

Public Water Supply Wells

Map Key	ID	Distance (ft)	Direction
	No records found		

Public Water Systems Violations and Enforcement Data

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
200	NW	0.60	3,149.45	7,002.29	PWSV

PWS ID:	NM3580226
PWS Type Code:	TNCWS
PWS Type Description:	Transient non-community system
Primary Source Code:	GW
Primary Source Desc:	Ground water
PWS Activity Code:	N
PWS Activity Description:	Changed from public to non-public
PWS Deactivation Date:	01/26/2006
Zip Code:	87501
Phone No:	505-988-9232
Phone Ext No:	
Admin Name:	
Alt Phone No:	
Email Addr:	
Fax No:	
Cds ID:	
Population Served Count:	0
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	05/18/1987
Gw or Sw:	Groundwater
Gw Sw Code:	GW
Is Grant Eligible Ind:	No
Outstanding Performer:	
Is School or Daycare Ind:	No
Is Source Water Protection:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Lt2 Schedule Cat Code:	
Last Reported Date:	06/25/2025
Org Name:	
Outstanding Perform Begin Date:	
Owner Type:	Private
Pop Cat 11:	<=100
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Season Begin Date:	01-01

Season End Date:	12-31
Service Connections Count:	1
Submission Status Code:	Y
Submissionyearquarter:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin Date:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	
County Served:	Santa Fe
Source Water Protection Code:	N

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
308	NW	0.82	4,317.07	6,996.13	PWSV

PWS ID:	NM3590826
PWS Type Code:	NTNCWS
PWS Type Description:	Non-Transient non-community system
Primary Source Code:	GW
Primary Source Desc:	Ground water
PWS Activity Code:	N
PWS Activity Description:	Changed from public to non-public
PWS Deactivation Date:	02/09/2006
Zip Code:	87504
Phone No:	505-984-6543
Phone Ext No:	
Admin Name:	
Alt Phone No:	
Email Addr:	
Fax No:	
Cds ID:	
Population Served Count:	80
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	03/12/1980
Gw or Sw:	Groundwater
Gw Sw Code:	GW
Is Grant Eligible Ind:	No
Outstanding Performer:	
Is School or Daycare Ind:	No

Is Source Water Protection:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Lt2 Schedule Cat Code:	
Last Reported Date:	06/25/2025
Org Name:	
Outstanding Perform Begin Date:	
Owner Type:	Local government
Pop Cat 11:	<=100
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	12
Submission Status Code:	Y
Submissionyearquarter:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin Date:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	
County Served:	Santa Fe
Source Water Protection Code:	N

Safe Drinking Water Information System (SDWIS)

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
200	NW	0.60	3,149.45	7,002.29	SDWIS

PWS ID:	NM3580226
PWS Type Code:	TNCWS
PSW Type:	Transient non-community system
Primary Source Code:	GW
Primary Source:	Ground water
Pws Activity Code:	N
Activity:	Changed from public to non-public
PWS Deactivation Dt:	01/26/2006

Phone No:	505-988-9232
Phone Ext No:	
Admin Name:	
Alt Phone No:	
Email Addr:	
Fax No:	
Cds ID:	
Population Served Count:	0
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	05/18/1987
Gw or Sw:	Groundwater
Is Grant Eligible Ind:	No
Outstanding Performer:	
Is School or Daycare Ind:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Last Reported Date:	06/25/2025
Org Name:	
Outstanding Perform Begin Date:	
Owner Type:	Private
Pop Cat 11:	<=100
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Primacy Agency Code:	NM
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	1
Submission Yr Qtr:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	
County Served:	Santa Fe

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
206	E	0.63	3,333.81	7,132.42	SDWIS

Wells and Additional Sources Detail Report

PWS ID:	NM3591526
PWS Type Code:	TNCWS
PSW Type:	Transient non-community system
Primary Source Code:	GW
Primary Source:	Ground water
Pws Activity Code:	I
Activity:	Inactive
PWS Deactivation Dt:	03/01/1981
Phone No:	505-982-4484
Phone Ext No:	
Admin Name:	NAMBE HEADSTART
Alt Phone No:	
Email Addr:	
Fax No:	
Cds ID:	
Population Served Count:	60
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	03/12/1980
Gw or Sw:	Groundwater
Is Grant Eligible Ind:	No
Outstanding Performer:	
Is School or Daycare Ind:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Last Reported Date:	07/24/1995
Org Name:	
Outstanding Perform Begin Date:	
Owner Type:	
Pop Cat 11:	<=100
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Primacy Agency Code:	NM
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	1
Submission Yr Qtr:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin:	

Reduced Monitoring End Date:
Reduced Rtcr Monitoring:
Seasonal Startup System:
Source Protection Begin Date:
City Served:
County Served: Santa Fe

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
308	NW	0.82	4,317.07	6,996.13	SDWIS

PWS ID: NM3590826
PWS Type Code: NTNCWS
PSW Type: Non-Transient non-community system
Primary Source Code: GW
Primary Source: Ground water
Pws Activity Code: N
Activity: Changed from public to non-public
PWS Deactivation Dt: 02/09/2006
Phone No: 505-984-6543
Phone Ext No:
Admin Name:
Alt Phone No:
Email Addr:
Fax No:
Cds ID:
Population Served Count: 80
Epa Region Desc: Region 6
Epa Region: 06
First Reported Date: 03/12/1980
Gw or Sw: Groundwater
Is Grant Eligible Ind: No
Outstanding Performer:
Is School or Daycare Ind: No
Is Wholesaler Ind: No
Lt2 Schedule Cat:
Last Reported Date: 06/25/2025
Org Name:
Outstanding Perform Begin Date:
Owner Type: Local government
Pop Cat 11: <=100
Pop Cat 2: <10,000
Pop Cat 3: <=3300
Pop Cat 4: <10K
Pop Cat 5: <=500
Primacy Agency: New Mexico

Wells and Additional Sources Detail Report

Primacy Agency Code:	NM
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	12
Submission Yr Qtr:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	
County Served:	Santa Fe

USGS National Water Information System

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
27	E	0.21	1,087.05	7,079.77	FED USGS

Site No:	USGS-354053105552601
Site Type:	Well
Formation Type:	
Date Drilled:	
Well Depth:	
Well Depth Unit:	
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	17N.10E.30.121
Latitude:	35.68141990000000
Longitude:	-105.9244654000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
45	NW	0.25	1,332.27	7,025.97	FED USGS

Site No:	USGS-354104105555010
Site Type:	Stream
Formation Type:	
Date Drilled:	
Well Depth:	
Well Depth Unit:	
Well Hole Depth:	
Well Hole Depth Unit:	

Wells and Additional Sources Detail Report

Reporting Agency: USGS New Mexico Water Science Center
Station Name: SANTA FE R AT DELGADO ST BRIDGE,SANTA FE NM
Latitude: 35.68447530000000
Longitude: -105.9311322000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	NW	0.31	1,621.83	7,021.48	FED USGS

Site No: USGS-354104105555510
Site Type: Stream
Formation Type:
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: SANTA FE RIVER ABV CASTILLO ST AT SANTA FE, NM
Latitude: 35.68447530000000
Longitude: -105.9325211000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
73	WSW	0.33	1,725.23	7,053.57	FED USGS

Site No: USGS-354046105560001
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19770524
Well Depth: 243
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.25.21442
Latitude: 35.67947545000000
Longitude: -105.9339100000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
96	WNW	0.39	2,049.14	7,021.18	FED USGS

Site No: USGS-354103105560210
Site Type: Stream
Formation Type:
Date Drilled:
Well Depth:

Well Depth Unit:
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: SANTA FE RIVER BLW CASTILLO ST AT SANTA FE, NM
Latitude: 35.68419750000000
Longitude: -105.9344656000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
114	SW	0.43	2,277.11	7,062.79	FED USGS

Site No: USGS-354039105560301
Site Type: Well
Formation Type:
Date Drilled: 19510401
Well Depth: 85.0
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.25.232
Latitude: 35.67753105000000
Longitude: -105.9347433000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
145	NW	0.51	2,668.60	7,021.69	FED USGS

Site No: USGS-354113105560201
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19780124
Well Depth: 165
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.24.414
Latitude: 35.68697520000000
Longitude: -105.9344656000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
185	SSW	0.56	2,975.87	7,126.77	FED USGS

Site No: USGS-354025105555501
Site Type: Well

Formation Type:
Date Drilled: 19510801
Well Depth: 255
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.25.421
Latitude: 35.67364229000000
Longitude: -105.9325210000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
237	WNW	0.70	3,696.97	6,987.92	FED USGS

Site No: USGS-354113105561801
Site Type: Well
Formation Type:
Date Drilled: 19250101
Well Depth: 255
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.24.324
Latitude: 35.68697520000000
Longitude: -105.9389101000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
242	W	0.73	3,845.18	7,000.25	FED USGS

Site No: USGS-354052105562701
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19761010
Well Depth: 300
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.25.121
Latitude: 35.68114200000000
Longitude: -105.9414102000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
245	WSW	0.73	3,838.17	7,060.96	FED USGS

Site No: USGS-354032105562001
Site Type: Well
Formation Type:
Date Drilled:
Well Depth: 50.0
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.25.144
Latitude: 35.67558660000000
Longitude: -105.9394656000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
252	WNW	0.74	3,919.49	6,991.45	FED USGS

Site No: USGS-354100105562701
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19250101
Well Depth: 180
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.24.343
Latitude: 35.68336416000000
Longitude: -105.9414102000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
263	WNW	0.76	3,993.48	6,981.04	FED USGS

Site No: USGS-354106105562610
Site Type: Stream
Formation Type:
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: SANTA FE RIVER AT SANTA FE, NM
Latitude: 35.68503079000000
Longitude: -105.9411324000000

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
273	WNW	0.78	4,105.03	6,977.49	FED USGS

Site No:	USGS-354107105562700
Site Type:	Stream
Formation Type:	
Date Drilled:	
Well Depth:	
Well Depth Unit:	
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	SANTA FE RIVER AT SANTA FE,NM
Latitude:	35.68530856000000
Longitude:	-105.9414102000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
297	SE	0.81	4,258.80	7,285.04	FED USGS

Site No:	USGS-354019105550701
Site Type:	Well
Formation Type:	
Date Drilled:	19310101
Well Depth:	238
Well Depth Unit:	ft
Well Hole Depth:	238
Well Hole Depth Unit:	ft
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	17N.10E.30.413
Latitude:	35.67197577000000
Longitude:	-105.9191875000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
412	NW	0.86	4,523.57	7,012.49	FED USGS

Site No:	USGS-354130105561210
Site Type:	Stream
Formation Type:	
Date Drilled:	
Well Depth:	
Well Depth Unit:	
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	ARROYO RANCHITO AT SANTA FE, NM

Latitude: 35.69169730000000
Longitude: -105.9372435000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
452	SW	0.87	4,592.04	7,071.56	FED USGS

Site No: USGS-354020105562001
Site Type: Well
Formation Type:
Date Drilled: 19510101
Well Depth: 280
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.25.324
Latitude: 35.67225338000000
Longitude: -105.9394656000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
509	SSW	0.94	4,940.45	7,101.38	FED USGS

Site No: USGS-354007105560401
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19720513
Well Depth: 240
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.25.434
Latitude: 35.66864240000000
Longitude: -105.9350210000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
514	WSW	0.95	4,992.49	7,031.27	FED USGS

Site No: USGS-354029105563401
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:

Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: SANTA FE GRANT(354029105563401)
Latitude: 35.67475328000000
Longitude: -105.9433546000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
529	WSW	0.97	5,140.23	7,022.47	FED USGS

Site No: USGS-354026105563401
Site Type: Well
Formation Type:
Date Drilled: 19510501
Well Depth: 106
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.25.312
Latitude: 35.67391997000000
Longitude: -105.9433546000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
536	NW	0.98	5,174.81	6,998.83	FED USGS

Site No: USGS-354135105561701
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19510401
Well Depth: 100
Well Depth Unit: ft
Well Hole Depth: 100
Well Hole Depth Unit: ft
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.24.124
Latitude: 35.69308614000000
Longitude: -105.9386324000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
536	NW	0.98	5,174.81	6,998.83	FED USGS

Site No: USGS-354135105561702
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled:

Well Depth:	180
Well Depth Unit:	ft
Well Hole Depth:	180
Well Hole Depth Unit:	ft
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	17N.09E.24.124A
Latitude:	35.69308614000000
Longitude:	-105.9386324000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
550	SSW	0.99	5,249.19	7,122.26	FED USGS

Site No:	USGS-354002105555801
Site Type:	Well
Formation Type:	
Date Drilled:	19720501
Well Depth:	240
Well Depth Unit:	ft
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	17N.09E.36.2211
Latitude:	35.66725357000000
Longitude:	-105.9333544000000

Point of Diversion Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	SSE	0.02	130.35	7,079.75	WATER WELLS

License Nb:	214	District Office S:	
POD No:	28576	Surv Map:	
POD Rec No:	3555	Other Loc:	634 Canyon Road, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	20 8 SF
Start Date:	05/08/1977, 12:00 AM	Restrict :	0.0
Finish Date:	05/13/1977, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	05/24/1977, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	1	UTM Source:	EA
Depth of Well:	265	UTM Zone:	13
Depth of Water:	40	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416025.6
Pcw Rcv Da:		Northing:	3948937.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/05/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416025.6
Static Lev:	0	Y:	3948937.2
Tract Nbr:		Point Y:	35.68075565
Map Nbr:		Point X:	-105.92798881
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098040483000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
2	W	0.07	362.59	7,069.47	WATER WELLS

License Nb:	622	District Office S:	
POD No:	29177	Surv Map:	
POD Rec No:	49698	Other Loc:	544 Canyon Road, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/30/1978, 12:00 AM	Restrict :	0.0
Finish Date:	07/31/1978, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	08/01/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	320	UTM Zone:	13
Depth of Water:	41	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415873.4
Pcw Rcv Da:		Northing:	3948982.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/14/2011, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595300.0
Static Lev:	0	Y:	1703300.0
Tract Nbr:		Point Y:	35.68115377
Map Nbr:		Point X:	-105.92967533
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
3	S	0.06	341.83	7,083.40	WATER WELLS

License Nb:	228	District Office S:	
POD No:	32879	Surv Map:	
POD Rec No:	11264	Other Loc:	739 Acequia Madre, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/09/1980, 12:00 AM	Restrict :	0.0
Finish Date:	07/14/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	07/22/1980, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	60	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415988.1
Pcw Rcv Da:		Northing:	3948868.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/24/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415988.1
Static Lev:	0	Y:	3948868.0
Tract Nbr:		Point Y:	35.6801286
Map Nbr:		Point X:	-105.92839595
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098031453000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	W	0.08	412.64	7,066.74	WATER WELLS

License Nb:	214	District Office S:	
POD No:	29622	Surv Map:	
POD Rec No:	40696	Other Loc:	544 Canyon Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TC1 SF
Start Date:	01/30/1978, 12:00 AM	Restrict :	0.0
Finish Date:	02/06/1978, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	02/10/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	417	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	37	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415861.3
Pcw Rcv Da:		Northing:	3949015.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/17/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735502.0
Static Lev:	0	Y:	1703467.0
Tract Nbr:		Point Y:	35.68144303
Map Nbr:		Point X:	-105.92981239
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
5	SSW	0.07	389.44	7,082.06	WATER WELLS

License Nb:	214	District Office S:	
POD No:	28797	Surv Map:	
POD Rec No:	39279	Other Loc:	751 Acequia Madre, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/05/1977, 12:00 AM	Restrict :	0.0
Finish Date:	08/09/1977, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/12/1977, 12:00 AM	Range:	

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	252	UTM Zone:	13
Depth of Water:	30	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415963.3
Pcw Rcv Da:		Northing:	3948859.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/02/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595600.0
Static Lev:	0	Y:	1702900.0
Tract Nbr:		Point Y:	35.68005256
Map Nbr:		Point X:	-105.92866912
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
6	NNW	0.08	421.29	7,061.12	WATER WELLS

License Nb:	0	District Office S:	
POD No:	81923	Surv Map:	
POD Rec No:	199068	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	01/01/1957, 12:00 AM	Section:	25
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	EA
Depth of Well:	50	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415937.4
Pcw Rcv Da:		Northing:	3949147.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/04/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595503.0
Static Lev:	0	Y:	1703842.0
Tract Nbr:		Point Y:	35.68264133
Map Nbr:		Point X:	-105.92898533
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
7	ENE	0.09	467.40	7,067.55	WATER WELLS

License Nb:	214	District Office S:	
POD No:	22780	Surv Map:	
POD Rec No:	51451	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/02/1973, 12:00 AM	Restrict :	0.0
Finish Date:	03/03/1973, 12:00 AM	Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:	03/08/1973, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	135	UTM Zone:	13
Depth of Water:	43	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	18	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416148.8
Pcw Rcv Da:		Northing:	3949070.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/06/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596200.0
Static Lev:	0	Y:	1703600.0
Tract Nbr:		Point Y:	35.68196967
Map Nbr:		Point X:	-105.92664143
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	NNE	0.09	459.89	7,059.12	WATER WELLS

License Nb:	49	District Office S:	
POD No:	85765	Surv Map:	
POD Rec No:	212857	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/10/2005, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	11/18/2005, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	11/28/2005, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	170	UTM Zone:	13
Depth of Water:	18	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	6.62	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416060.9
Pcw Rcv Da:		Northing:	3949157.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/29/2005, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595908.0
Static Lev:	0	Y:	1703881.0
Tract Nbr:	B1A	Point Y:	35.68274471
Map Nbr:		Point X:	-105.92762175
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
9	WNW	0.10	523.89	7,063.22	WATER WELLS

License Nb:	253	District Office S:	
POD No:	35549	Surv Map:	
POD Rec No:	11080	Other Loc:	540 Canyon Road, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:	03/17/1981, 12:00 AM	Restrict :	0.0
Finish Date:	03/19/1981, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	03/25/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	160	UTM Zone:	13
Depth of Water:	34	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415836.6
Pcw Rcv Da:		Northing:	3949067.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/03/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415836.6
Static Lev:	0	Y:	3949067.2
Tract Nbr:		Point Y:	35.68191151
Map Nbr:		Point X:	-105.93009078
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1054098504516000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
10	NNW	0.09	497.39	7,056.66	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34872	Surv Map:	
POD Rec No:	47351	Other Loc:	130 Camino Escondido
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	22 SF
Start Date:		Restrict :	0.0
Finish Date:	08/01/1951, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	107	UTM Zone:	13
Depth of Water:	85	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	26	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415945.6
Pcw Rcv Da:		Northing:	3949176.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/27/2024, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735772.0
Static Lev:	0	Y:	1703999.0
Tract Nbr:		Point Y:	35.68290167
Map Nbr:		Point X:	-105.92889773
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
11	N	0.10	529.93	7,054.01	WATER WELLS

License Nb:	0	District Office S:	
POD No:	59924	Surv Map:	
POD Rec No:	67859	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415998.0
Pcw Rcv Da:		Northing:	3949194.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/10/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595700.0
Static Lev:	0	Y:	1704000.0
Tract Nbr:		Point Y:	35.68307382
Map Nbr:		Point X:	-105.92832066
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
12	SSE	0.10	541.59	7,090.06	WATER WELLS

License Nb:	0	District Office S:	
POD No:	39401	Surv Map:	
POD Rec No:	20448	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416084.8
Pcw Rcv Da:		Northing:	3948827.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/16/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596000.0
Static Lev:	0	Y:	1702800.0
Tract Nbr:		Point Y:	35.67977352
Map Nbr:		Point X:	-105.92732326
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	NW	0.11	593.64	7,059.03	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94235	Surv Map:	
POD Rec No:	287608	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EG
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415841.0
Pcw Rcv Da:		Northing:	3949127.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/13/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1735430.7
Static Lev:	0	Y:	1703833.9
Tract Nbr:		Point Y:	35.682451
Map Nbr:		Point X:	-105.93004842
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
14	N	0.14	730.08	7,045.34	WATER WELLS

License Nb:	0	District Office S:	
POD No:	36840	Surv Map:	
POD Rec No:	3523	Other Loc:	564 East Alameda, Santa Fe
POD Basin:	RG	Zone :	C

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415998.8
Pcw Rcv Da:		Northing:	3949255.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/15/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595700.0
Static Lev:	0	Y:	1704200.0
Tract Nbr:		Point Y:	35.68362292
Map Nbr:		Point X:	-105.92831818
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	WSW	0.15	782.44	7,064.11	WATER WELLS

License Nb:	214	District Office S:	
POD No:	31840	Surv Map:	
POD Rec No:	21922	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/01/1979, 12:00 AM	Restrict :	0.0
Finish Date:	02/07/1979, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	02/13/1979, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	387	UTM Zone:	13
Depth of Water:	387	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415750.7
Pcw Rcv Da:		Northing:	3948923.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/28/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594900.0
Static Lev:	0	Y:	1703100.0
Tract Nbr:		Point Y:	35.68060779
Map Nbr:		Point X:	-105.93102489
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	NNE	0.15	790.75	7,046.40	WATER WELLS

License Nb:	622	District Office S:	
POD No:	22780	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	48250	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/03/1978, 12:00 AM	Restrict :	0.0
Finish Date:	07/05/1978, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/26/1978, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	140	UTM Zone:	13
Depth of Water:	15	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-22780-X/	Easting:	416090.2
Pcw Rcv Da:		Northing:	3949254.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/06/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596000.0
Static Lev:	0	Y:	1704200.0
Tract Nbr:		Point Y:	35.68361988
Map Nbr:		Point X:	-105.92730809
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
17	ENE	0.16	821.69	7,062.45	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	34990	Surv Map:	
POD Rec No:	333772	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416241.0
Pcw Rcv Da:		Northing:	3949130.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/19/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596500.0
Static Lev:	0	Y:	1703800.0
Tract Nbr:		Point Y:	35.68251662
Map Nbr:		Point X:	-105.92562887
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
18	NW	0.16	864.43	7,047.61	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	83535	Surv Map:	
POD Rec No:	205389	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415833.1
Pcw Rcv Da:		Northing:	3949240.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/12/2025, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595157.0
Static Lev:	0	Y:	1704143.0
Tract Nbr:	C	Point Y:	35.68347085
Map Nbr:		Point X:	-105.93014756
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
19	S	0.16	866.40	7,090.96	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	228	District Office S:	
POD No:	44736	Surv Map:	
POD Rec No:	21582	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/17/1986, 12:00 AM	Restrict :	0.0
Finish Date:	01/17/1986, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	02/04/1986, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	240	UTM Zone:	13
Depth of Water:	160	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415991.8
Pcw Rcv Da:		Northing:	3948707.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595700.0
Static Lev:	0	Y:	1702400.0
Tract Nbr:		Point Y:	35.67867746
Map Nbr:		Point X:	-105.92833825
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
20	NNW	0.17	874.30	7,045.76	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	91291	Surv Map:	
POD Rec No:	244529	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415869.3
Pcw Rcv Da:		Northing:	3949267.7
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	08/06/2009, 12:00 AM	Latitude Second:	1.4
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	55
Ditch Name:		Longitude Second:	47.1
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68372186
Map Nbr:		Point X:	-105.92975043
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

21	SW	0.17	883.83	7,071.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	65241	Surv Map:	
POD Rec No:	18737	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415779.7
Pcw Rcv Da:		Northing:	3948801.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/05/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595000.0
Static Lev:	0	Y:	1702700.0
Tract Nbr:		Point Y:	35.6795086
Map Nbr:		Point X:	-105.93069166
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

22	SE	0.17	912.71	7,098.27	WATER WELLS

License Nb:	790	District Office S:	
POD No:	34376	Surv Map:	
POD Rec No:	17079	Other Loc:	823 Acequia Madre
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	A SF
Start Date:	08/25/1980, 12:00 AM	Restrict :	0.0
Finish Date:	08/26/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	09/04/1980, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	65	UTM Zone:	13
Depth of Water:	21	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	1	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416228.0
Pcw Rcv Da:		Northing:	3948806.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/29/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736714.0
Static Lev:	0	Y:	1702798.0
Tract Nbr:		Point Y:	35.67959367
Map Nbr:		Point X:	-105.92573876
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
23	SE	0.18	974.05	7,103.08	WATER WELLS

License Nb:	815	District Office S:	
POD No:	53086	Surv Map:	
POD Rec No:	66847	Other Loc:	827 Camino Del Poniente
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TC SF
Start Date:	11/12/1990, 12:00 AM	Restrict :	0.0
Finish Date:	11/19/1990, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	11/28/1990, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	280	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416198.9
Pcw Rcv Da:		Northing:	3948747.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/19/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736621.0
Static Lev:	0	Y:	1702602.0
Tract Nbr:		Point Y:	35.6790557
Map Nbr:		Point X:	-105.92605411
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	WNW	0.19	1,023.16	7,052.08	WATER WELLS

License Nb:	0	District Office S:	
POD No:	40581	Surv Map:	
POD Rec No:	170246	Other Loc:	318 Delgado St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	5&6 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	24
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415684.2
Pcw Rcv Da:		Northing:	3949086.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Delgado Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734918.0
Static Lev:	0	Y:	1703695.0
Tract Nbr:		Point Y:	35.68207429
Map Nbr:		Point X:	-105.9317768
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
25	NNW	0.19	979.63	7,041.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	74753	Surv Map:	
POD Rec No:	161433	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415908.1
Pcw Rcv Da:		Northing:	3949317.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/06/2000, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595400.0
Static Lev:	0	Y:	1704400.0
Tract Nbr:		Point Y:	35.68417503
Map Nbr:		Point X:	-105.92932691
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
26	ESE	0.20	1,036.94	7,093.02	WATER WELLS

License Nb:	0	District Office S:	
POD No:	78478	Surv Map:	
POD Rec No:	180566	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	01/01/1700, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	20	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	1	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416298.4
Pcw Rcv Da:		Northing:	3948855.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/12/2002, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596700.0
Static Lev:	0	Y:	1702900.0
Tract Nbr:		Point Y:	35.6800423
Map Nbr:		Point X:	-105.92496599
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
28	S	0.20	1,044.99	7,093.52	WATER WELLS

License Nb:	228	District Office S:	
POD No:	35391	Surv Map:	
POD Rec No:	22644	Other Loc:	459 Camino Manzano
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	Y SF
Start Date:	12/06/1980, 12:00 AM	Restrict :	0.0
Finish Date:	12/09/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	01/29/1981, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	80	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415960.9
Pcw Rcv Da:		Northing:	3948655.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/19/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735844.0
Static Lev:	0	Y:	1702292.0
Tract Nbr:		Point Y:	35.67821145
Map Nbr:		Point X:	-105.9286743
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
29	SW	0.22	1,136.96	7,074.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	90264	Surv Map:	PLATT BOOK 552
POD Rec No:	236868	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415747.3
Pcw Rcv Da:		Northing:	3948724.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/10/2008, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1735140.0
Static Lev:	0	Y:	1702509.0
Tract Nbr:	B-1A	Point Y:	35.67881347
Map Nbr:		Point X:	-105.93104162

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
29	SW	0.22	1,136.96	7,074.40	WATER WELLS

License Nb:	1616	District Office S:	
POD No:	90264	Surv Map:	
POD Rec No:	237237	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	05/19/2008, 12:00 AM	Restrict :	0.0
Finish Date:	05/28/2008, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	06/12/2008, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	240	UTM Zone:	13
Depth of Water:	84	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	12	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415747.3
Pcw Rcv Da:		Northing:	3948724.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/12/2008, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1735140.0
Static Lev:	0	Y:	1702509.0
Tract Nbr:	B 1A	Point Y:	35.67881347

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.93104162
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
30	WNW	0.23	1,188.78	7,049.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	28882	Surv Map:	USGS 7.5 QUAD SANTA FE
POD Rec No:	55843	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415630.8
Pcw Rcv Da:		Northing:	3949077.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/08/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594500.0
Static Lev:	0	Y:	1703600.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.68198498
Map Nbr:		Point X:	-105.93236587
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Usgs 7.5' Quad Of Santa Fe.		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
31	SW	0.22	1,174.31	7,066.42	WATER WELLS

License Nb:	228	District Office S:	
POD No:	07413	Surv Map:	
POD Rec No:	25978	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/28/1960, 12:00 AM	Restrict :	0.0
Finish Date:	06/28/1962, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	11/21/1962, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	115	UTM Zone:	13
Depth of Water:	20	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	415687.0
Pcw Rcv Da:		Northing:	3948777.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	10/09/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0

Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67928251
Map Nbr:		Point X:	-105.9317134
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
32	WNW	0.23	1,217.44	7,045.41	WATER WELLS

License Nb:	214	District Office S:	
POD No:	29621	Surv Map:	
POD Rec No:	44087	Other Loc:	414 Canyon Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/08/1978, 12:00 AM	Restrict :	0.0
Finish Date:	02/21/1978, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	03/02/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	303	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415641.7
Pcw Rcv Da:		Northing:	3949149.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/17/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:	NA	X:	1734776.0
Static Lev:	0	Y:	1703900.0
Tract Nbr:		Point Y:	35.68263861
Map Nbr:		Point X:	-105.93225302
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
33	WNW	0.23	1,220.30	7,046.87	WATER WELLS

License Nb:	225	District Office S:	
POD No:	70612	Surv Map:	
POD Rec No:	145523	Other Loc:	334 Garcia St, Santa Fe, 87501
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/11/1998, 12:00 AM	Restrict :	0.0
Finish Date:	11/23/1998, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	01/05/2000, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	394	UTM Zone:	13
Depth of Water:	18	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415631.4
Pcw Rcv Da:		Northing:	3949123.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM SAN	Latitude Minute:	0
Sys Date:	10/12/2000, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594500.0
Static Lev:	0	Y:	1703750.0
Tract Nbr:		Point Y:	35.68239703
Map Nbr:		Point X:	-105.93236403
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	S	0.22	1,181.13	7,094.49	WATER WELLS

License Nb:	228	District Office S:	
POD No:	35396	Surv Map:	
POD Rec No:	44008	Other Loc:	463 Camino Manzano
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	13 3 SF
Start Date:	12/09/1980, 12:00 AM	Restrict :	0.0
Finish Date:	12/11/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	01/29/1981, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	80	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415923.0
Pcw Rcv Da:		Northing:	3948620.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735721.0
Static Lev:	0	Y:	1702176.0
Tract Nbr:		Point Y:	35.67789358
Map Nbr:		Point X:	-105.92908942
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
35	N	0.23	1,188.60	7,052.61	WATER WELLS

License Nb:	0	District Office S:	
POD No:	38634	Surv Map:	
POD Rec No:	61605	Other Loc:	1317 Cerro Gordo, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415997.0
Pcw Rcv Da:		Northing:	3949395.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/31/2022, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68488039
Map Nbr:		Point X:	-105.92835264
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
36	NNE	0.23	1,215.28	7,073.05	WATER WELLS

License Nb:	228	District Office S:	
POD No:	44144	Surv Map:	
POD Rec No:	51673	Other Loc:	639 E Palace Ave
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1A SF
Start Date:	07/18/1985, 12:00 AM	Restrict :	0.0
Finish Date:	07/19/1985, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	08/16/1985, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	160	UTM Zone:	13
Depth of Water:	30	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416134.3
Pcw Rcv Da:		Northing:	3949375.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	08/02/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736383.0
Static Lev:	0	Y:	1704661.0
Tract Nbr:		Point Y:	35.68471538
Map Nbr:		Point X:	-105.92683342
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
37	S	0.24	1,241.85	7,099.62	WATER WELLS

License Nb:	228	District Office S:	
POD No:	40770	Surv Map:	
POD Rec No:	58127	Other Loc:	465 Camino Manzano
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	14 3 T2 SF
Start Date:	06/12/1984, 12:00 AM	Restrict :	0.0
Finish Date:	06/15/1984, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	10/11/1984, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	75	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415956.5
Pcw Rcv Da:		Northing:	3948595.9
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	03/17/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735832.0
Static Lev:	0	Y:	1702096.0
Tract Nbr:		Point Y:	35.67767286
Map Nbr:		Point X:	-105.92871668
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
38	NW	0.24	1,275.17	7,032.48	WATER WELLS

License Nb:	622	District Office S:	
POD No:	54536	Surv Map:	
POD Rec No:	51116	Other Loc:	208 Delgado St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/01/1991, 12:00 AM	Restrict :	0.0
Finish Date:	11/04/1991, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	11/19/1991, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	360	UTM Zone:	13
Depth of Water:	83	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415697.7
Pcw Rcv Da:		Northing:	3949281.9

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/17/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734954.0
Static Lev:	0	Y:	1704336.0
Tract Nbr:		Point Y:	35.68383522
Map Nbr:		Point X:	-105.93164809
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
39	W	0.25	1,320.26	7,047.21	WATER WELLS

License Nb:	0	District Office S:	
POD No:	81449	Surv Map:	
POD Rec No:	197077	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415585.1

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3949032.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/20/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594352.0
Static Lev:	0	Y:	1703452.0
Tract Nbr:	1	Point Y:	35.68157989
Map Nbr:		Point X:	-105.93286617
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
40	SW	0.24	1,281.90	7,065.02	WATER WELLS

License Nb:	0	District Office S:	
POD No:	28796	Surv Map:	
POD Rec No:	282754	Other Loc:	433 Delgado Lane
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	415657.5
Pcw Rcv Da:		Northing:	3948762.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734844.0
Static Lev:	0	Y:	1702629.0
Tract Nbr:		Point Y:	35.67914656
Map Nbr:		Point X:	-105.9320378
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
41	SE	0.25	1,310.52	7,113.58	WATER WELLS

License Nb:	214	District Office S:	
POD No:	16898	Surv Map:	
POD Rec No:	50259	Other Loc:	Address: 425 Camino Manzano
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/11/1969, 12:00 AM	Restrict :	0.0
Finish Date:	09/01/1969, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	02/06/1970, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	281	UTM Zone:	13
Depth of Water:	32	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416291.0
Pcw Rcv Da:		Northing:	3948693.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/24/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6785767
Map Nbr:		Point X:	-105.92503085
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
42	SSW	0.25	1,305.42	7,101.68	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34900	Surv Map:	NA
POD Rec No:	16933	Other Loc:	Na
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-34900-/	Easting:	415898.8
Pcw Rcv Da:		Northing:	3948586.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/08/2017, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1735643.0
Static Lev:	0	Y:	1702064.0
Tract Nbr:	NA	Point Y:	35.6775868
Map Nbr:	NA	Point X:	-105.92935328
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
43	N	0.25	1,314.82	7,061.31	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35576	Surv Map:	
POD Rec No:	34043	Other Loc:	607 E Palace Ave
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 6 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416023.5
Pcw Rcv Da:		Northing:	3949432.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/04/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736017.0
Static Lev:	0	Y:	1704843.0
Tract Nbr:		Point Y:	35.68521801
Map Nbr:		Point X:	-105.9280637
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
44	SW	0.25	1,325.59	7,080.54	WATER WELLS

License Nb:	228	District Office S:	
POD No:	37932	Surv Map:	
POD Rec No:	37913	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/12/1982, 12:00 AM	Restrict :	0.0
Finish Date:	05/14/1982, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	05/20/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	320	UTM Zone:	13
Depth of Water:	80	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	

Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415747.3
Pcw Rcv Da:		Northing:	3948649.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/29/2011, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594900.0
Static Lev:	0	Y:	1702200.0
Tract Nbr:		Point Y:	35.67813552
Map Nbr:		Point X:	-105.93103374
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	WSW	0.26	1,351.44	7,058.07	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31455	Surv Map:	
POD Rec No:	18083	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415597.2
Pcw Rcv Da:		Northing:	3948834.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/14/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594400.0
Static Lev:	0	Y:	1702800.0
Tract Nbr:		Point Y:	35.6797887
Map Nbr:		Point X:	-105.93271161
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
47	NE	0.25	1,341.44	7,102.22	WATER WELLS

License Nb:	253	District Office S:	
POD No:	33401	Surv Map:	
POD Rec No:	64511	Other Loc:	729 E. Palace Ave, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:	04/04/1980, 12:00 AM	Restrict :	0.0
Finish Date:	04/05/1980, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	04/09/1980, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	148	UTM Zone:	13
Depth of Water:	47	UTM Accura:	10

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416306.9
Pcw Rcv Da:		Northing:	3949310.1
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	04/27/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	La Reina Compound/Condos	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416306.9
Static Lev:	0	Y:	3949310.1
Tract Nbr:		Point Y:	35.68414135
Map Nbr:		Point X:	-105.92491937
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055099134063ca0000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
48	SSE	0.25	1,333.93	7,119.43	WATER WELLS

License Nb:	228	District Office S:	
POD No:	36889	Surv Map:	
POD Rec No:	28211	Other Loc:	831 El Caminito, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/16/1982, 12:00 AM	Restrict :	0.0
Finish Date:	01/18/1982, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	01/22/1982, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	220	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	40	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416153.0
Pcw Rcv Da:		Northing:	3948592.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/16/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416153.0
Static Lev:	0	Y:	3948592.6
Tract Nbr:		Point Y:	35.67765984
Map Nbr:		Point X:	-105.92654518
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098089368000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
49	SW	0.26	1,382.42	7,068.58	WATER WELLS

License Nb:	0	District Office S:	
POD No:	74064	Surv Map:	
POD Rec No:	157764	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN

Wells and Additional Sources Detail Report

Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415656.6
Pcw Rcv Da:		Northing:	3948711.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/12/2000, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594600.0
Static Lev:	0	Y:	1702400.0
Tract Nbr:		Point Y:	35.67868761
Map Nbr:		Point X:	-105.93204241
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
50	N	0.26	1,381.37	7,068.92	WATER WELLS

License Nb:	214	District Office S:	
POD No:	29008	Surv Map:	
POD Rec No:	54526	Other Loc:	607 E Palace Ave, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 6 SF
Start Date:	02/18/1981, 12:00 AM	Restrict :	0.0
Finish Date:	02/20/1981, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	03/13/1981, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	1	UTM Source:	EA
Depth of Well:	131	UTM Zone:	13
Depth of Water:	30	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416029.6
Pcw Rcv Da:		Northing:	3949452.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/07/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416029.6
Static Lev:	0	Y:	3949452.5
Tract Nbr:		Point Y:	35.68540154
Map Nbr:		Point X:	-105.92799841
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055099038105000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
51	ESE	0.27	1,429.19	7,104.54	WATER WELLS

License Nb:	0	District Office S:	
POD No:	36474	Surv Map:	
POD Rec No:	334346	Other Loc:	830 Canyon Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	L 9/10 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416395.6
Pcw Rcv Da:		Northing:	3948781.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/30/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1737265.0
Static Lev:	0	Y:	1702723.0
Tract Nbr:		Point Y:	35.67938252
Map Nbr:		Point X:	-105.92388428
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
52	ESE	0.27	1,433.99	7,107.56	WATER WELLS

License Nb:	0	District Office S:	
POD No:	27033	Surv Map:	
POD Rec No:	35434	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	100	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416388.7
Pcw Rcv Da:		Northing:	3948762.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/21/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597000.0
Static Lev:	0	Y:	1702600.0
Tract Nbr:		Point Y:	35.67921515
Map Nbr:		Point X:	-105.9239586
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Santa Fe Usgs 7.5 Min Quad "Santa Fe"		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
53	E	0.28	1,453.41	7,112.04	WATER WELLS

License Nb:	547	District Office S:	
POD No:	75949	Surv Map:	
POD Rec No:	170332	Other Loc:	5 Cerro Gordo Rd, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/16/2004, 12:00 AM	Restrict :	0.0
Finish Date:	02/16/2004, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	02/02/2004, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	80	UTM Zone:	13
Depth of Water:	21	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	100	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416457.0
Pcw Rcv Da:		Northing:	3949031.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/13/2019, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1737456.0
Static Lev:	0	Y:	1703545.0
Tract Nbr:		Point Y:	35.68163883
Map Nbr:		Point X:	-105.92323178
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
54	N	0.27	1,432.49	7,069.83	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35901	Surv Map:	
POD Rec No:	26436	Other Loc:	535 E Palace Ave
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TC SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N
Log File D:		Range:	10E

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416004.2
Pcw Rcv Da:		Northing:	3949469.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/15/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735952.0
Static Lev:	0	Y:	1704963.0
Tract Nbr:		Point Y:	35.68554813
Map Nbr:		Point X:	-105.92828081
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
55	N	0.27	1,451.05	7,064.66	WATER WELLS

License Nb:	1310	District Office S:	
POD No:	71015	Surv Map:	
POD Rec No:	146760	Other Loc:	531 E Palace Ave
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA SF
Start Date:	08/15/1999, 12:00 AM	Restrict :	0.0
Finish Date:	08/19/1999, 12:00 AM	Section:	19
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:	08/16/2000, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415965.9
Pcw Rcv Da:		Northing:	3949474.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/29/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415965.9
Static Lev:	0	Y:	3949474.0
Tract Nbr:		Point Y:	35.68558994
Map Nbr:		Point X:	-105.92870456
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number: 1055099024127000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
56	S	0.28	1,467.72	7,119.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	71391	Surv Map:	
POD Rec No:	147896	Other Loc:	W/In City Limits Of Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	30

Wells and Additional Sources Detail Report

Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416019.9
Pcw Rcv Da:		Northing:	3948523.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/21/2001, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595800.0
Static Lev:	0	Y:	1701800.0
Tract Nbr:		Point Y:	35.67702826
Map Nbr:		Point X:	-105.92800864
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
57	WNW	0.29	1,522.70	7,040.33	WATER WELLS

License Nb:	0	District Office S:	
POD No:	51376	Surv Map:	
POD Rec No:	24565	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415540.2
Pcw Rcv Da:		Northing:	3949139.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/18/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594200.0
Static Lev:	0	Y:	1703800.0
Tract Nbr:		Point Y:	35.68253707
Map Nbr:		Point X:	-105.93337349
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
58	WSW	0.28	1,496.58	7,062.80	WATER WELLS

License Nb:	0	District Office S:	
POD No:	58226	Surv Map:	
POD Rec No:	339881	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415593.0
Pcw Rcv Da:		Northing:	3948742.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/04/2024, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594390.0
Static Lev:	0	Y:	1702500.0
Tract Nbr:		Point Y:	35.67896435
Map Nbr:		Point X:	-105.93274843
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
59	E	0.29	1,539.80	7,126.73	WATER WELLS

License Nb:	0	District Office S:	
POD No:	28711	Surv Map:	
POD Rec No:	272507	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416483.2
Pcw Rcv Da:		Northing:	3949005.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597300.0
Static Lev:	0	Y:	1703400.0
Tract Nbr:		Point Y:	35.68141026
Map Nbr:		Point X:	-105.92293962
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
60	ESE	0.30	1,578.80	7,092.25	WATER WELLS

License Nb:	0	District Office S:	
POD No:	39982	Surv Map:	
POD Rec No:	37398	Other Loc:	909 Canyon Road, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416469.0
Pcw Rcv Da:		Northing:	3948847.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/23/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597260.0
Static Lev:	0	Y:	1702880.0
Tract Nbr:		Point Y:	35.67998194
Map Nbr:		Point X:	-105.92308009
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	909 Canyon Rd Santa Fe Nm		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
61	WSW	0.29	1,547.25	7,062.80	WATER WELLS

License Nb:	0	District Office S:	
POD No:	58226	Surv Map:	
POD Rec No:	339880	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0

Wells and Additional Sources Detail Report

POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415577.7
Pcw Rcv Da:		Northing:	3948738.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/04/2024, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594340.0
Static Lev:	0	Y:	1702485.0
Tract Nbr:		Point Y:	35.67892337
Map Nbr:		Point X:	-105.93291702
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
62	NE	0.30	1,565.71	7,126.47	WATER WELLS

License Nb:	253	District Office S:	
POD No:	38853	Surv Map:	
POD Rec No:	26213	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/16/1983, 12:00 AM	Restrict :	0.0
Finish Date:	05/17/1983, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/26/1983, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	188	UTM Zone:	13
Depth of Water:	31	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	180	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416395.7
Pcw Rcv Da:		Northing:	3949311.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/09/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597000.0
Static Lev:	0	Y:	1704400.0
Tract Nbr:		Point Y:	35.68416061
Map Nbr:		Point X:	-105.92393827
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
63	WSW	0.30	1,573.10	7,062.35	WATER WELLS

License Nb:	0	District Office S:	
POD No:	58226	Surv Map:	
POD Rec No:	339879	Other Loc:	
POD Basin:	RG	Zone :	

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 8 39 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415565.6
Pcw Rcv Da:		Northing:	3948742.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/04/2024, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Kings Map	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594300.0
Static Lev:	0	Y:	1702500.0
Tract Nbr:		Point Y:	35.6789647
Map Nbr:		Point X:	-105.93305121
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
64	SE	0.30	1,566.89	7,127.01	WATER WELLS

License Nb:	214	District Office S:	
POD No:	29317	Surv Map:	
POD Rec No:	2148	Other Loc:	439 Camino Del Monte Sol, Sf

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/13/1978, 12:00 AM	Restrict :	0.0
Finish Date:	02/17/1978, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	02/23/1978, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	211	UTM Zone:	13
Depth of Water:	150	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416289.6
Pcw Rcv Da:		Northing:	3948588.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/11/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416289.6
Static Lev:	0	Y:	3948588.5
Tract Nbr:		Point Y:	35.67763448
Map Nbr:		Point X:	-105.92503545
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098128366000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
65	E	0.31	1,629.55	7,120.37	WATER WELLS

License Nb:	228	District Office S:	
POD No:	54428	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	19029	Other Loc:	2 Cerro Gordo Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3B SF
Start Date:	11/30/1991, 12:00 AM	Restrict :	0.0
Finish Date:	12/15/1991, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	12/26/1991, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	230	UTM Zone:	13
Depth of Water:	5	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	100	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416506.3
Pcw Rcv Da:		Northing:	3948956.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/03/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1737621.0
Static Lev:	0	Y:	1703302.0
Tract Nbr:		Point Y:	35.68097047
Map Nbr:		Point X:	-105.92267929
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
66	NNW	0.30	1,587.71	7,052.69	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	32365	Surv Map:	
POD Rec No:	59116	Other Loc:	511 E Palace Ave
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 47 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	24
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415852.7
Pcw Rcv Da:		Northing:	3949494.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/14/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	King Map	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735454.0
Static Lev:	0	Y:	1705041.0
Tract Nbr:		Point Y:	35.6857669
Map Nbr:		Point X:	-105.92995761
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
67	NNW	0.30	1,605.27	7,040.59	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	32540	Surv Map:	
POD Rec No:	47541	Other Loc:	124 Delgado, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415726.9
Pcw Rcv Da:		Northing:	3949441.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/14/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594800.0
Static Lev:	0	Y:	1704800.0
Tract Nbr:		Point Y:	35.68527925
Map Nbr:		Point X:	-105.93134218
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
69	W	0.32	1,673.78	7,038.38	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	53901	Surv Map:	
POD Rec No:	36980	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415478.1
Pcw Rcv Da:		Northing:	3949048.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/23/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594000.0
Static Lev:	0	Y:	1703500.0
Tract Nbr:		Point Y:	35.68171496
Map Nbr:		Point X:	-105.93405017
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
70	WNW	0.32	1,689.51	7,035.69	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	225	District Office S:	
POD No:	08786	Surv Map:	
POD Rec No:	36762	Other Loc:	1011 Paseo De Peralta Sf 87501
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	PLG	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA1A SF
Start Date:	11/30/1998, 12:00 AM	Restrict :	0.0
Finish Date:	12/05/1998, 12:00 AM	Section:	25
Plug Date:	01/06/2001, 12:00 AM	Township:	17N
Log File D:	01/05/2000, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	293	UTM Zone:	13
Depth of Water:	25	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	55	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	415481.5
Pcw Rcv Da:		Northing:	3949110.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/07/2025, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734252.0
Static Lev:	0	Y:	1703765.0
Tract Nbr:		Point Y:	35.6822724
Map Nbr:		Point X:	-105.93401909
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

71	SW	0.32	1,668.87	7,081.27	WATER WELLS

License Nb:	622	District Office S:	
POD No:	65048	Surv Map:	
POD Rec No:	57818	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415655.1
Pcw Rcv Da:		Northing:	3948589.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594600.0
Static Lev:	0	Y:	1702000.0
Tract Nbr:		Point Y:	35.67758853
Map Nbr:		Point X:	-105.93204621
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

72	S	0.32	1,682.51	7,126.56	WATER WELLS

License Nb:	0	District Office S:	
POD No:	81451	Surv Map:	
POD Rec No:	197078	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	17 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415896.1
Pcw Rcv Da:		Northing:	3948469.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/20/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co #1	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595396.0
Static Lev:	0	Y:	1701616.0
Tract Nbr:		Point Y:	35.67652638
Map Nbr:		Point X:	-105.92937082
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
74	WSW	0.33	1,746.65	7,058.83	WATER WELLS

License Nb:	0	District Office S:	
POD No:	32201	Surv Map:	
POD Rec No:	333151	Other Loc:	488 Arroyo Tenorio
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415504.7
Pcw Rcv Da:		Northing:	3948743.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/09/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594100.0
Static Lev:	0	Y:	1702500.0
Tract Nbr:		Point Y:	35.6789667
Map Nbr:		Point X:	-105.9337242
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
75	S	0.33	1,764.80	7,135.16	WATER WELLS

License Nb:	228	District Office S:	
POD No:	45875	Surv Map:	
POD Rec No:	33301	Other Loc:	858 Camino Ranchitos
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7A SF
Start Date:	07/18/1986, 12:00 AM	Restrict :	0.0
Finish Date:	07/22/1986, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/19/1986, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	340	UTM Zone:	13
Depth of Water:	70	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415992.2
Pcw Rcv Da:		Northing:	3948433.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/23/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Gault Comp	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735956.0
Static Lev:	0	Y:	1701564.0
Tract Nbr:		Point Y:	35.67621003
Map Nbr:		Point X:	-105.92830525
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
76	SW	0.34	1,787.63	7,080.98	WATER WELLS

License Nb:	547	District Office S:	
POD No:	68739	Surv Map:	
POD Rec No:	139929	Other Loc:	608 Garcia St, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	18 134 SF
Start Date:	01/05/1998, 12:00 AM	Restrict :	0.0
Finish Date:	01/06/1998, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	01/15/1998, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	72	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	33	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415618.2
Pcw Rcv Da:		Northing:	3948573.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/13/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415618.2
Static Lev:	0	Y:	3948573.7
Tract Nbr:		Point Y:	35.67744383
Map Nbr:		Point X:	-105.93245227
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal: Parcel Number 1054098430352000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
77	S	0.34	1,787.30	7,132.94	WATER WELLS

License Nb:	1382	District Office S:	
POD No:	94187	Surv Map:	
POD Rec No:	285779	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	PLG	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:	05/09/2025, 12:00 AM	Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EG
Depth of Well:	135	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415906.2
Pcw Rcv Da:		Northing:	3948434.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/30/2025, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1735673.6
Static Lev:	0	Y:	1701565.7
Tract Nbr:		Point Y:	35.67621712
Map Nbr:		Point X:	-105.92925563
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
78	NE	0.34	1,795.26	7,161.74	WATER WELLS

License Nb:	0	District Office S:	
POD No:	36973	Surv Map:	
POD Rec No:	23131	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416346.4
Pcw Rcv Da:		Northing:	3949459.5
Sched Date:		Latitude Degree:	0
Use of Wel:	COM, IRR	Latitude Minute:	0
Sys Date:	05/10/1991, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596832.0
Static Lev:	0	Y:	1704884.0
Tract Nbr:		Point Y:	35.68549158
Map Nbr:		Point X:	-105.92449844
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
79	SE	0.34	1,801.09	7,134.91	WATER WELLS

License Nb:	122	District Office S:	
POD No:	63354	Surv Map:	
POD Rec No:	334055	Other Loc:	503 Camino Del Monte Sol
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416355.5
Pcw Rcv Da:		Northing:	3948550.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/03/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596900.0
Static Lev:	0	Y:	1701900.0
Tract Nbr:		Point Y:	35.67729299
Map Nbr:		Point X:	-105.9243033

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
80	WSW	0.35	1,824.54	7,052.57	WATER WELLS

License Nb:	214	District Office S:	
POD No:	28712	Surv Map:	
POD Rec No:	44800	Other Loc:	481 Arroyo Tenorio
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 SF
Start Date:	05/24/1977, 12:00 AM	Restrict :	0.0
Finish Date:	05/27/1977, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	06/08/1977, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	243	UTM Zone:	13
Depth of Water:	60	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415457.4
Pcw Rcv Da:		Northing:	3948796.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734186.0
Static Lev:	0	Y:	1702732.0
Tract Nbr:		Point Y:	35.67943504

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.93425234
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	SW	0.35	1,822.13	7,089.39	WATER WELLS

License Nb:	0	District Office S:	
POD No:	44528	Surv Map:	
POD Rec No:	337651	Other Loc:	618 1/2 Garcia St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4B 134 SF
Start Date:		Restrict :	0.0
Finish Date:	12/31/1891, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	65	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415663.6
Pcw Rcv Da:		Northing:	3948523.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Kings Map	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734874.0
Static Lev:	0	Y:	1701846.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.67699515
Map Nbr:		Point X:	-105.93194538
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
82	S	0.34	1,819.60	7,135.57	WATER WELLS

License Nb:	72	District Office S:	
POD No:	94187	Surv Map:	
POD Rec No:	341180	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/30/2024, 12:00 AM	Restrict :	0.0
Finish Date:	10/02/2024, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	10/11/2024, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	360	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415899.1
Pcw Rcv Da:		Northing:	3948426.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/17/2024, 12:00 AM	Latitude Second:	34.1
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	55
Ditch Name:		Longitude Second:	45.6
Well Tag:	NA	X:	0.0

Wells and Additional Sources Detail Report

Static Lev:	116	Y:	0.0
Tract Nbr:		Point Y:	35.67613898
Map Nbr:		Point X:	-105.92933317
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
83	W	0.35	1,864.34	7,039.48	WATER WELLS

License Nb:	214	District Office S:	
POD No:	34694	Surv Map:	
POD Rec No:	58088	Other Loc:	1075 Paseo Del Peralta
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	19 126 SF
Start Date:	07/09/1980, 12:00 AM	Restrict :	0.0
Finish Date:	07/21/1980, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	07/25/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	390	UTM Zone:	13
Depth of Water:	35	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415415.8
Pcw Rcv Da:		Northing:	3948953.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/11/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:	NA	X:	1734043.0
Static Lev:	0	Y:	1703245.0
Tract Nbr:		Point Y:	35.68084596
Map Nbr:		Point X:	-105.93472849
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
84	NNW	0.35	1,827.96	7,044.27	WATER WELLS

License Nb:	0	District Office S:	
POD No:	37628	Surv Map:	
POD Rec No:	334537	Other Loc:	511 East Palace Ave., Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415697.2
Pcw Rcv Da:		Northing:	3949503.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594700.0
Static Lev:	0	Y:	1705000.0
Tract Nbr:		Point Y:	35.68582934
Map Nbr:		Point X:	-105.9316768
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
84	NNW	0.35	1,827.96	7,044.27	WATER WELLS

License Nb:	253	District Office S:	
POD No:	37629	Surv Map:	
POD Rec No:	8784	Other Loc:	519 East Palace Ave., Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/22/1985, 12:00 AM	Restrict :	0.0
Finish Date:	02/23/1985, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	09/27/1985, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	80	UTM Zone:	13
Depth of Water:	28	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415697.2
Pcw Rcv Da:		Northing:	3949503.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594700.0
Static Lev:	0	Y:	1705000.0
Tract Nbr:		Point Y:	35.68582934
Map Nbr:		Point X:	-105.9316768
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
85	SSE	0.35	1,824.71	7,144.62	WATER WELLS

License Nb:	228	District Office S:	
POD No:	19533	Surv Map:	
POD Rec No:	45725	Other Loc:	520 Camino Del Monte Sol
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1
Start Date:	03/29/1972, 12:00 AM	Restrict :	0.0
Finish Date:	05/06/1972, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	05/15/1972, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	265	UTM Zone:	13
Depth of Water:	100	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	416204.3
Pcw Rcv Da:		Northing:	3948452.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/13/2021, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736651.0
Static Lev:	0	Y:	1701637.0
Tract Nbr:		Point Y:	35.67640477
Map Nbr:		Point X:	-105.92596381
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	516-520 Camino Del Monte Sol		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
86	N	0.35	1,834.96	7,077.35	WATER WELLS

License Nb:	622	District Office S:	
POD No:	73263	Surv Map:	
POD Rec No:	154803	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415972.6
Pcw Rcv Da:		Northing:	3949591.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	06/14/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595600.0
Static Lev:	0	Y:	1705300.0
Tract Nbr:		Point Y:	35.68664619
Map Nbr:		Point X:	-105.92864276
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
87	S	0.35	1,843.15	7,143.70	WATER WELLS

License Nb:	0	District Office S:	
POD No:	81448	Surv Map:	
POD Rec No:	197079	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1-3 2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415954.2
Pcw Rcv Da:		Northing:	3948411.6
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	11/20/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Galt Compound	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595589.0
Static Lev:	0	Y:	1701429.0
Tract Nbr:		Point Y:	35.67601116
Map Nbr:		Point X:	-105.92872284
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
88	S	0.35	1,870.16	7,138.74	WATER WELLS

License Nb:	0	District Office S:	
POD No:	60365	Surv Map:	
POD Rec No:	2300	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416033.6
Pcw Rcv Da:		Northing:	3948401.7

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/26/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Galt Compound	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595850.0
Static Lev:	0	Y:	1701400.0
Tract Nbr:		Point Y:	35.67592867
Map Nbr:		Point X:	-105.92784453
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
89	E	0.37	1,952.70	7,117.22	WATER WELLS

License Nb:	214	District Office S:	
POD No:	30918	Surv Map:	
POD Rec No:	7415	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	S-CLW	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/08/1979, 12:00 AM	Restrict :	0.0
Finish Date:	05/17/1979, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/22/1979, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	264	UTM Zone:	13
Depth of Water:	25	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-30918-X-2/	Easting:	416604.3

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3948943.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	11/19/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597700.0
Static Lev:	0	Y:	1703200.0
Tract Nbr:		Point Y:	35.68085706
Map Nbr:		Point X:	-105.92159503
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
90	WNW	0.37	1,959.77	7,026.37	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34783	Surv Map:	SANTA FE RIVER HYDRO SURVEY
POD Rec No:	27075	Other Loc:	**Tct 11.133
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	01/01/1915, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	ES
Depth of Well:	330	UTM Zone:	13
Depth of Water:	12	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	415431.7
Pcw Rcv Da:		Northing:	3949233.8
Sched Date:		Latitude Degree:	0
Use of Wel:	COM, IRR.	Latitude Minute:	0
Sys Date:	07/11/2024, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593840.0
Static Lev:	0	Y:	1704105.0
Tract Nbr:	**	Point Y:	35.6833788
Map Nbr:	19	Point X:	-105.93458232
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
91	W	0.37	1,961.52	7,037.71	WATER WELLS

License Nb:	0	District Office S:	
POD No:	30918	Surv Map:	SANTA FE RIVER HYDROSURVEY
POD Rec No:	169331	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	12/31/1940, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	210	UTM Zone:	13
Depth of Water:	180	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.5	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415385.5
Pcw Rcv Da:		Northing:	3948958.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/03/2001, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593700.0
Static Lev:	0	Y:	1703200.0
Tract Nbr:	8.14	Point Y:	35.68089295
Map Nbr:	2	Point X:	-105.93506387
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
92	S	0.36	1,921.24	7,143.94	WATER WELLS

License Nb:	1310	District Office S:	
POD No:	81673	Surv Map:	
POD Rec No:	197877	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7-A 1 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415992.6
Pcw Rcv Da:		Northing:	3948386.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/30/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Galt Compound	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595716.0
Static Lev:	0	Y:	1701347.0
Tract Nbr:		Point Y:	35.67578454
Map Nbr:		Point X:	-105.9282959
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
93	W	0.38	1,991.60	7,042.37	WATER WELLS

License Nb:	0	District Office S:	
POD No:	08786	Surv Map:	
POD Rec No:	275692	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	A	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.945
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415384.0
Pcw Rcv Da:		Northing:	3948880.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/08/2012, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68018512
Map Nbr:		Point X:	-105.93507218
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
93	W	0.38	1,991.60	7,042.37	WATER WELLS

License Nb:	622	District Office S:	
POD No:	40890	Surv Map:	
POD Rec No:	6700	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/26/1983, 12:00 AM	Restrict :	0.0
Finish Date:	10/26/1983, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	11/08/1983, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	345	UTM Zone:	13
Depth of Water:	125	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415384.0
Pcw Rcv Da:		Northing:	3948880.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68018512
Map Nbr:		Point X:	-105.93507218
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
94	WNW	0.38	2,009.61	7,026.00	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34782	Surv Map:	SANTA FE RIVER HYDRO SURVEY
POD Rec No:	65820	Other Loc:	**Tct 11.133
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	01/01/1946, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	ES
Depth of Well:	60	UTM Zone:	13
Depth of Water:	12	UTM Accura:	
Ground Water Src:	S	UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415407.0
Pcw Rcv Da:		Northing:	3949211.2
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	07/29/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593760.0
Static Lev:	0	Y:	1704030.0
Tract Nbr:	**	Point Y:	35.68317294
Map Nbr:	19	Point X:	-105.93485288
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
95	ESE	0.38	2,025.82	7,123.76	WATER WELLS

License Nb:	214	District Office S:	
POD No:	28813	Surv Map:	
POD Rec No:	6181	Other Loc:	976 Acequia Madre, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7 10 SF
Start Date:	06/06/1977, 12:00 AM	Restrict :	0.0
Finish Date:	06/10/1977, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	06/22/1977, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	139	UTM Zone:	13
Depth of Water:	40	UTM Accura:	10

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416561.9
Pcw Rcv Da:		Northing:	3948706.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416561.9
Static Lev:	0	Y:	3948706.1
Tract Nbr:		Point Y:	35.67871776
Map Nbr:		Point X:	-105.92203896
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:	Parcel Number 1055098220415000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
97	SE	0.38	2,032.16	7,143.07	WATER WELLS

License Nb:	228	District Office S:	
POD No:	36880	Surv Map:	
POD Rec No:	60337	Other Loc:	587 Camino Del Monte Sol, Sf
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/14/1982, 12:00 AM	Restrict :	0.0
Finish Date:	08/15/1982, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	11/15/1982, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	175	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	90	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-36880-/	Easting:	416382.5
Pcw Rcv Da:		Northing:	3948480.1
Sched Date:		Latitude Degree:	0
Use of Wel:	1HH DOM	Latitude Minute:	0
Sys Date:	11/16/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416382.5
Static Lev:	0	Y:	3948480.1
Tract Nbr:		Point Y:	35.67666511
Map Nbr:		Point X:	-105.92399771
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:	Parcel Number 1055098166315000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
98	SSE	0.39	2,034.19	7,151.88	WATER WELLS

License Nb:	0	District Office S:	
POD No:	76563	Surv Map:	
POD Rec No:	173238	Other Loc:	535 Camino Del Monte Sol
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T1B SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA

Wells and Additional Sources Detail Report

Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416313.5
Pcw Rcv Da:		Northing:	3948433.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/27/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Land Of William/Linda Herrmann	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416313.5
Static Lev:	0	Y:	3948433.5
Tract Nbr:		Point Y:	35.67623915
Map Nbr:		Point X:	-105.92475525
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number: 1055098145279000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
99	SE	0.39	2,062.89	7,134.00	WATER WELLS

License Nb:	214	District Office S:	
POD No:	28798	Surv Map:	
POD Rec No:	38433	Other Loc:	934 Acequia Madre
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/06/1977, 12:00 AM	Restrict :	0.0
Finish Date:	06/08/1977, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	06/17/1977, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	5	UTM Source:	EA
Depth of Well:	115	UTM Zone:	13
Depth of Water:	29	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	150	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416529.2
Pcw Rcv Da:		Northing:	3948625.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1737710.0
Static Lev:	0	Y:	1702218.0
Tract Nbr:		Point Y:	35.67799106
Map Nbr:		Point X:	-105.92239194
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
100	ENE	0.39	2,070.20	7,138.29	WATER WELLS

License Nb:	1382	District Office S:	
POD No:	81438	Surv Map:	
POD Rec No:	196983	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N
Log File D:	09/05/2013, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	102	UTM Zone:	13
Depth of Water:	18	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.26	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416561.1
Pcw Rcv Da:		Northing:	3949338.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/03/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1737785.0
Static Lev:	0	Y:	1704557.0
Tract Nbr:		Point Y:	35.68441623
Map Nbr:		Point X:	-105.92211337
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
101	SSW	0.39	2,064.47	7,107.32	WATER WELLS

License Nb:	253	District Office S:	
POD No:	37721	Surv Map:	
POD Rec No:	45295	Other Loc:	646 Garcia Street, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10E SF
Start Date:	06/14/1982, 12:00 AM	Restrict :	0.0
Finish Date:	06/17/1982, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	06/28/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	260	UTM Zone:	13
Depth of Water:	54	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	70	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415670.8
Pcw Rcv Da:		Northing:	3948431.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/28/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415670.8
Static Lev:	0	Y:	3948431.4
Tract Nbr:		Point Y:	35.67616546
Map Nbr:		Point X:	-105.93185617
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
102	WNW	0.40	2,120.17	7,022.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34781	Surv Map:	SANTA FE RIVER HYDRO SURVEY
POD Rec No:	67447	Other Loc:	**Tct 11.133
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	07/01/1946, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	ES
Depth of Well:	50	UTM Zone:	13
Depth of Water:	8	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415379.8
Pcw Rcv Da:		Northing:	3949232.9
Sched Date:		Latitude Degree:	0
Use of Wel:	COM. IRR & DOM	Latitude Minute:	0
Sys Date:	07/29/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593670.0
Static Lev:	0	Y:	1704100.0
Tract Nbr:	**	Point Y:	35.68336623
Map Nbr:	19	Point X:	-105.93515572
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Tr. 11.133 Sheet 19		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
103	SW	0.40	2,090.59	7,088.95	WATER WELLS

License Nb:	1472	District Office S:	
POD No:	29354	Surv Map:	
POD Rec No:	296840	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	09/18/2015, 12:00 AM	Restrict :	0.0
Finish Date:	09/21/2015, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	09/30/2015, 12:00 AM	Range:	

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	120	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.32	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415576.6
Pcw Rcv Da:		Northing:	3948486.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/19/2015, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1734590.0
Static Lev:	0	Y:	1701722.0
Tract Nbr:		Point Y:	35.67665685
Map Nbr:		Point X:	-105.93290279
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
104	WSW	0.40	2,107.51	7,055.77	WATER WELLS

License Nb:	0	District Office S:	
POD No:	65265	Surv Map:	
POD Rec No:	46176	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	

Wells and Additional Sources Detail Report

Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-65265-/	Easting:	415412.5
Pcw Rcv Da:		Northing:	3948683.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/11/2019, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593800.0
Static Lev:	0	Y:	1702300.0
Tract Nbr:		Point Y:	35.67841968
Map Nbr:		Point X:	-105.93473665
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
105	NW	0.40	2,122.88	7,017.93	WATER WELLS

License Nb:	622	District Office S:	
POD No:	71196	Surv Map:	
POD Rec No:	147430	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/05/1999, 12:00 AM	Restrict :	0.0
Finish Date:	04/07/1999, 12:00 AM	Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:	05/03/1999, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	408	UTM Zone:	13
Depth of Water:	8	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415451.9
Pcw Rcv Da:		Northing:	3949384.4
Sched Date:		Latitude Degree:	0
Use of Wel:	DRINK/SANITARY	Latitude Minute:	0
Sys Date:	05/07/1999, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593900.0
Static Lev:	0	Y:	1704600.0
Tract Nbr:		Point Y:	35.68473823
Map Nbr:		Point X:	-105.93437494
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
106	SW	0.40	2,106.43	7,093.91	WATER WELLS

License Nb:	0	District Office S:	
POD No:	29354	Surv Map:	USGS 7.5' QUAD SANTA FE
POD Rec No:	50582	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:		Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415592.6
Pcw Rcv Da:		Northing:	3948468.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/22/2015, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594400.0
Static Lev:	0	Y:	1701600.0
Tract Nbr:		Point Y:	35.67649143
Map Nbr:		Point X:	-105.93272407
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
107	SSE	0.41	2,170.37	7,158.96	WATER WELLS

License Nb:	214	District Office S:	
POD No:	31512	Surv Map:	
POD Rec No:	25205	Other Loc:	535 Camino Del Monte Sol
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T2 SF

Wells and Additional Sources Detail Report

Start Date:	05/30/1979, 12:00 AM	Restrict :	0.0
Finish Date:	06/05/1979, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	06/06/1979, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	285	UTM Zone:	13
Depth of Water:	240	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	18	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416345.7
Pcw Rcv Da:		Northing:	3948404.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/27/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416345.7
Static Lev:	0	Y:	3948404.7
Tract Nbr:		Point Y:	35.67598224
Map Nbr:		Point X:	-105.92439648
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number: 1055098147297000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
108	SSE	0.42	2,207.67	7,158.97	WATER WELLS

License Nb:	547	District Office S:	
POD No:	66183	Surv Map:	
POD Rec No:	48425	Other Loc:	541 Camino Rancheros, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	M 5-7 SF
Start Date:	03/27/1997, 12:00 AM	Restrict :	0.0
Finish Date:	03/28/1997, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	04/04/1997, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	42	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416203.0
Pcw Rcv Da:		Northing:	3948328.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416203.0
Static Lev:	0	Y:	3948328.4
Tract Nbr:		Point Y:	35.67528226
Map Nbr:		Point X:	-105.92596521
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098102281000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
109	SSE	0.42	2,214.68	7,168.54	WATER WELLS

License Nb:	622	District Office S:	
POD No:	68337	Surv Map:	
POD Rec No:	105580	Other Loc:	535 Camino Del Monte Sol
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T2 SF
Start Date:	10/04/1997, 12:00 AM	Restrict :	0.0
Finish Date:	10/08/1997, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	10/27/1997, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416299.2
Pcw Rcv Da:		Northing:	3948364.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/27/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416299.2
Static Lev:	0	Y:	3948364.1
Tract Nbr:		Point Y:	35.67561228
Map Nbr:		Point X:	-105.92490603
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number: 1055098147297000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
110	W	0.43	2,261.03	7,032.60	WATER WELLS

License Nb:	0	District Office S:	
POD No:	30918	Surv Map:	
POD Rec No:	63677	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	S	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	12/31/1919, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	40	UTM Zone:	13
Depth of Water:	35	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:	SUBMER	XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	36.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415294.1
Pcw Rcv Da:		Northing:	3948959.7
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	04/03/2001, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593400.0
Static Lev:	0	Y:	1703200.0
Tract Nbr:		Point Y:	35.68089592
Map Nbr:		Point X:	-105.93607392
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
111	E	0.43	2,277.10	7,103.42	WATER WELLS

License Nb:	0	District Office S:	
POD No:	71243	Surv Map:	
POD Rec No:	147388	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416694.9
Pcw Rcv Da:		Northing:	3948880.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/20/1999, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598000.0
Static Lev:	0	Y:	1703000.0
Tract Nbr:		Point Y:	35.68030487
Map Nbr:		Point X:	-105.92058751
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
112	SE	0.42	2,234.53	7,154.98	WATER WELLS

License Nb:	214	District Office S:	
POD No:	09839	Surv Map:	
POD Rec No:	40319	Other Loc:	
POD Basin:	RG	Zone :	

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/24/1963, 12:00 AM	Restrict :	0.0
Finish Date:	10/07/1963, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	12/13/1963, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	255	UTM Zone:	13
Depth of Water:	37	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416485.0
Pcw Rcv Da:		Northing:	3948488.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	12/14/2005, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67674502
Map Nbr:		Point X:	-105.92286601
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
113	N	0.43	2,251.75	7,145.87	WATER WELLS

License Nb:	0	District Office S:	
POD No:	42150	Surv Map:	
POD Rec No:	24289	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415913.2
Pcw Rcv Da:		Northing:	3949713.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595400.0
Static Lev:	0	Y:	1705700.0
Tract Nbr:		Point Y:	35.6877464
Map Nbr:		Point X:	-105.92931197
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
115	SW	0.43	2,288.44	7,077.59	WATER WELLS

License Nb:	622	District Office S:	
POD No:	87703	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	221255	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/21/2006, 12:00 AM	Restrict :	0.0
Finish Date:	08/23/2006, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	09/13/2006, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	EA
Depth of Well:	360	UTM Zone:	13
Depth of Water:	70	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415479.2
Pcw Rcv Da:		Northing:	3948495.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/04/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594027.0
Static Lev:	0	Y:	1701684.0
Tract Nbr:		Point Y:	35.67672513
Map Nbr:		Point X:	-105.93397986
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
116	NNE	0.43	2,286.65	7,102.51	WATER WELLS

License Nb:	49	District Office S:	

Wells and Additional Sources Detail Report

POD No:	56309	Surv Map:	
POD Rec No:	8592	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/14/1993, 12:00 AM	Restrict :	0.0
Finish Date:	02/04/1993, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	06/17/1993, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	300	UTM Zone:	13
Depth of Water:	240	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416156.9
Pcw Rcv Da:		Northing:	3949710.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/14/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596200.0
Static Lev:	0	Y:	1705700.0
Tract Nbr:		Point Y:	35.68773921
Map Nbr:		Point X:	-105.92661863
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
116	NNE	0.43	2,286.65	7,102.51	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	49	District Office S:	
POD No:	56310	Surv Map:	
POD Rec No:	26510	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	12/05/1992, 12:00 AM	Restrict :	0.0
Finish Date:	01/10/1993, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	01/27/1993, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	470	UTM Zone:	13
Depth of Water:	140	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416156.9
Pcw Rcv Da:		Northing:	3949710.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/19/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596200.0
Static Lev:	0	Y:	1705700.0
Tract Nbr:		Point Y:	35.68773921
Map Nbr:		Point X:	-105.92661863
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
116	NNE	0.43	2,286.65	7,102.51	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	49	District Office S:	
POD No:	69928	Surv Map:	
POD Rec No:	143661	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/14/1993, 12:00 AM	Restrict :	3.0
Finish Date:	01/14/1993, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	06/17/1993, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	240	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416156.9
Pcw Rcv Da:		Northing:	3949710.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/27/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596200.0
Static Lev:	0	Y:	1705700.0
Tract Nbr:		Point Y:	35.68773921
Map Nbr:		Point X:	-105.92661863
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
117	SSE	0.44	2,322.15	7,169.04	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	30416	Surv Map:	
POD Rec No:	34267	Other Loc:	555 Camino Del Monte Sol, Sf
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416337.7
Pcw Rcv Da:		Northing:	3948346.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/19/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416337.7
Static Lev:	0	Y:	3948346.5
Tract Nbr:		Point Y:	35.67545687
Map Nbr:		Point X:	-105.92447882
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098144277000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

118	ESE	0.45	2,373.44	7,122.60	WATER WELLS

License Nb:	606	District Office S:	
POD No:	29259	Surv Map:	
POD Rec No:	58289	Other Loc:	1015 Canyon Road, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	8 8 SF
Start Date:	08/01/1977, 12:00 AM	Restrict :	0.0
Finish Date:	08/31/1977, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	09/07/1977, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	103	UTM Zone:	13
Depth of Water:	81	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416700.7
Pcw Rcv Da:		Northing:	3948777.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/10/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416700.7
Static Lev:	0	Y:	3948777.1
Tract Nbr:		Point Y:	35.67936958
Map Nbr:		Point X:	-105.92051267
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:	Parcel Number 1055098268432000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

119	WNW	0.45	2,374.01	7,015.98	WATER WELLS

License Nb:	0	District Office S:	
POD No:	40016	Surv Map:	
POD Rec No:	335283	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	24
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415297.6
Pcw Rcv Da:		Northing:	3949233.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/25/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593400.0
Static Lev:	0	Y:	1704100.0
Tract Nbr:		Point Y:	35.68336819
Map Nbr:		Point X:	-105.93606412
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
120	NW	0.45	2,353.26	7,023.59	WATER WELLS

License Nb:	1004	District Office S:	
POD No:	66323	Surv Map:	
POD Rec No:	32816	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415484.3
Pcw Rcv Da:		Northing:	3949536.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/16/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594000.0
Static Lev:	0	Y:	1705100.0
Tract Nbr:		Point Y:	35.68611041
Map Nbr:		Point X:	-105.93403289
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
121	SW	0.45	2,362.29	7,084.12	WATER WELLS

License Nb:	0	District Office S:	
POD No:	19261	Surv Map:	
POD Rec No:	52631	Other Loc:	803 Camino Atalaya
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3G 134 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415499.9
Pcw Rcv Da:		Northing:	3948445.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734340.0
Static Lev:	0	Y:	1701582.0
Tract Nbr:		Point Y:	35.67627434
Map Nbr:		Point X:	-105.93374587
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
122	SSE	0.45	2,361.80	7,173.02	WATER WELLS

License Nb:	0	District Office S:	
POD No:	50460	Surv Map:	
POD Rec No:	27388	Other Loc:	555 Camino Del Monte Sol
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-50460-/	Easting:	416321.5
Pcw Rcv Da:		Northing:	3948324.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/31/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	613E6	X:	416321.5
Static Lev:	0	Y:	3948324.8
Tract Nbr:		Point Y:	35.67525987
Map Nbr:		Point X:	-105.92465555
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
123	W	0.46	2,416.90	7,026.01	WATER WELLS

License Nb:	0	District Office S:	
POD No:	30918	Surv Map:	
POD Rec No:	2688	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	S-2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	12/31/1919, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	40	UTM Zone:	13
Depth of Water:	35	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	36.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415249.3
Pcw Rcv Da:		Northing:	3949036.5
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	04/03/2001, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593250.0
Static Lev:	0	Y:	1703450.0
Tract Nbr:		Point Y:	35.68158444
Map Nbr:		Point X:	-105.93657703
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
124	S	0.45	2,376.95	7,128.23	WATER WELLS

License Nb:	0	District Office S:	
POD No:	33036	Surv Map:	
POD Rec No:	42534	Other Loc:	665 Garcia Street, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415925.0
Pcw Rcv Da:		Northing:	3948250.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/02/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595500.0
Static Lev:	0	Y:	1700900.0
Tract Nbr:		Point Y:	35.67455811
Map Nbr:		Point X:	-105.92902866
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
125	SW	0.45	2,390.26	7,065.94	WATER WELLS

License Nb:	228	District Office S:	
POD No:	42151	Surv Map:	NA
POD Rec No:	12660	Other Loc:	460 Camino De Las Animas
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	09/28/1984, 12:00 AM	Restrict :	0.0
Finish Date:	10/01/1984, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	10/18/1984, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	80	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415407.7
Pcw Rcv Da:		Northing:	3948531.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734034.0
Static Lev:	0	Y:	1701860.0
Tract Nbr:	NA	Point Y:	35.67704084
Map Nbr:	NA	Point X:	-105.93477361

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
126	NNE	0.45	2,382.54	7,100.73	WATER WELLS

License Nb:	606	District Office S:	
POD No:	29582	Surv Map:	
POD Rec No:	60616	Other Loc:	Usgs 7.5' Quad, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/01/1979, 12:00 AM	Restrict :	0.0
Finish Date:	07/01/1979, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/1979, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	162	UTM Zone:	13
Depth of Water:	40	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416157.3
Pcw Rcv Da:		Northing:	3949741.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/01/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596200.0
Static Lev:	0	Y:	1705800.0
Tract Nbr:		Point Y:	35.68801421

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.92661739
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
127	S	0.45	2,388.71	7,131.33	WATER WELLS

License Nb:	228	District Office S:	
POD No:	45498	Surv Map:	
POD Rec No:	15734	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/30/1986, 12:00 AM	Restrict :	0.0
Finish Date:	07/08/1986, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/19/1986, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	360	UTM Zone:	13
Depth of Water:	60	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415894.6
Pcw Rcv Da:		Northing:	3948251.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/09/2012, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595400.0
Static Lev:	0	Y:	1700900.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.67455913
Map Nbr:		Point X:	-105.92936458
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
128	S	0.45	2,396.33	7,165.47	WATER WELLS

License Nb:	0	District Office S:	
POD No:	56393	Surv Map:	
POD Rec No:	51104	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416107.9
Pcw Rcv Da:		Northing:	3948248.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/14/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596100.0

Wells and Additional Sources Detail Report

Static Lev:	0	Y:	1700900.0
Tract Nbr:		Point Y:	35.67455296
Map Nbr:		Point X:	-105.92700761
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
129	NNW	0.46	2,405.08	7,056.60	WATER WELLS

License Nb:	815	District Office S:	
POD No:	50828	Surv Map:	
POD Rec No:	49621	Other Loc:	347 Hillside, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	13 SF
Start Date:	07/23/1990, 12:00 AM	Restrict :	0.0
Finish Date:	07/27/1990, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	08/31/1990, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	80	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415693.5
Pcw Rcv Da:		Northing:	3949700.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/04/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:	NA	X:	415693.5
Static Lev:	0	Y:	3949700.5
Tract Nbr:		Point Y:	35.68760863
Map Nbr:		Point X:	-105.93173838
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1054099457198000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
130	WSW	0.46	2,428.62	7,058.00	WATER WELLS

License Nb:	228	District Office S:	
POD No:	51218	Surv Map:	
POD Rec No:	290334	Other Loc:	See Exhibit "A" For Location
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/31/1989, 12:00 AM	Restrict :	0.0
Finish Date:	10/31/1989, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	06/29/1990, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	400	UTM Zone:	13
Depth of Water:	80	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:	SUBMER	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415350.4
Pcw Rcv Da:	07/25/1990, 12:00 AM	Northing:	3948593.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/17/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593600.0
Static Lev:	0	Y:	1702000.0
Tract Nbr:		Point Y:	35.67759758
Map Nbr:		Point X:	-105.93541328
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
130	WSW	0.46	2,428.62	7,058.00	WATER WELLS

License Nb:	0	District Office S:	
POD No:	50456	Surv Map:	
POD Rec No:	54561	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415350.4
Pcw Rcv Da:		Northing:	3948593.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/31/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593600.0
Static Lev:	0	Y:	1702000.0
Tract Nbr:		Point Y:	35.67759758
Map Nbr:		Point X:	-105.93541328
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
131	SSE	0.46	2,418.13	7,162.70	WATER WELLS

License Nb:	1281	District Office S:	
POD No:	57883	Surv Map:	
POD Rec No:	34861	Other Loc:	909 Camino Santander
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T2 SF
Start Date:	11/11/1993, 12:00 AM	Restrict :	0.0
Finish Date:	11/16/1993, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	04/13/1994, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	228	UTM Zone:	13
Depth of Water:	48	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	100	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416401.7
Pcw Rcv Da:		Northing:	3948350.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/06/2023, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1737303.0
Static Lev:	0	Y:	1701309.0
Tract Nbr:	NA	Point Y:	35.67549746
Map Nbr:		Point X:	-105.9237721
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
132	WNW	0.47	2,474.52	7,013.27	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94886	Surv Map:	
POD Rec No:	291975	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 52B NA
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EG
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415266.2
Pcw Rcv Da:		Northing:	3949235.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	07/28/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	415266.2
Static Lev:	0	Y:	3949235.4
Tract Nbr:	NA	Point Y:	35.68337901
Map Nbr:	NA	Point X:	-105.93641125
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
133	SSW	0.46	2,450.61	7,133.60	WATER WELLS

License Nb:	214	District Office S:	
POD No:	34618	Surv Map:	
POD Rec No:	69509	Other Loc:	660 Garcia St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/26/1980, 12:00 AM	Restrict :	0.0
Finish Date:	06/27/1980, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	07/03/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	345	UTM Zone:	13
Depth of Water:	62	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	400	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415804.0
Pcw Rcv Da:		Northing:	3948251.3
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	10/06/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735346.0
Static Lev:	0	Y:	1700959.0
Tract Nbr:		Point Y:	35.6745532
Map Nbr:		Point X:	-105.93036561
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
133	SSW	0.46	2,450.61	7,133.60	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31225	Surv Map:	
POD Rec No:	333099	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415803.2
Pcw Rcv Da:		Northing:	3948252.3

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595100.0
Static Lev:	0	Y:	1700900.0
Tract Nbr:		Point Y:	35.67456215
Map Nbr:		Point X:	-105.93037456
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
134	SW	0.47	2,460.89	7,063.25	WATER WELLS

License Nb:	214	District Office S:	
POD No:	27838	Surv Map:	SANTA FE USGS QUAD SANTA FE
POD Rec No:	53638	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/15/1977, 12:00 AM	Restrict :	0.0
Finish Date:	02/21/1977, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	02/23/1977, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	109	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	38	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415380.1

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3948532.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/08/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593700.0
Static Lev:	0	Y:	1701800.0
Tract Nbr:		Point Y:	35.67704749
Map Nbr:		Point X:	-105.93507867
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
135	NNW	0.47	2,464.91	7,045.69	WATER WELLS

License Nb:	1173	District Office S:	
POD No:	81257	Surv Map:	
POD Rec No:	195967	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	EA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	415660.4
Pcw Rcv Da:		Northing:	3949705.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/15/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594571.0
Static Lev:	0	Y:	1705663.0
Tract Nbr:		Point Y:	35.68765268
Map Nbr:		Point X:	-105.9321047
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
136	E	0.48	2,547.62	7,142.74	WATER WELLS

License Nb:	1173	District Office S:	
POD No:	13375	Surv Map:	
POD Rec No:	241265	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/18/1990, 12:00 AM	Restrict :	0.0
Finish Date:	11/01/1990, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	11/20/1990, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	155	UTM Zone:	13
Depth of Water:	24	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	100	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416790.0
Pcw Rcv Da:		Northing:	3948986.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	08/04/2015, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68126041
Map Nbr:		Point X:	-105.91954757
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
136	E	0.48	2,547.62	7,142.74	WATER WELLS

License Nb:	253	District Office S:	
POD No:	13375	Surv Map:	
POD Rec No:	13479	Other Loc:	100 Ft North Of Santa Fe River
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	12/01/1965, 12:00 AM	Restrict :	0.0
Finish Date:	12/03/1965, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	11/30/1966, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	22	UTM Zone:	13
Depth of Water:	4	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416790.0
Pcw Rcv Da:		Northing:	3948986.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	10/05/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68126041
Map Nbr:		Point X:	-105.91954757
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
137	ESE	0.48	2,543.26	7,146.93	WATER WELLS

License Nb:	622	District Office S:	
POD No:	71032	Surv Map:	
POD Rec No:	146889	Other Loc:	111 Victoria St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	29 10 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416682.2
Pcw Rcv Da:		Northing:	3948595.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/06/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416682.2
Static Lev:	0	Y:	3948595.5
Tract Nbr:		Point Y:	35.67773084
Map Nbr:		Point X:	-105.92069828
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:	Parcel Number: 1055098258377000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
138	S	0.48	2,511.83	7,168.75	WATER WELLS

License Nb:	622	District Office S:	
POD No:	69336	Surv Map:	
POD Rec No:	142014	Other Loc:	826 Camino Ranchitos, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 2 SF
Start Date:	12/16/1998, 12:00 AM	Restrict :	0.0
Finish Date:	12/17/1998, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	01/12/1999, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	340	UTM Zone:	13
Depth of Water:	108	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	M
Estimate Yield:	6	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416141.2
Pcw Rcv Da:		Northing:	3948218.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Los Rancheros	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416141.2
Static Lev:	0	Y:	3948218.3
Tract Nbr:		Point Y:	35.67428443
Map Nbr:		Point X:	-105.92663655
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098082241000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
139	WSW	0.50	2,621.61	7,031.31	WATER WELLS

License Nb:	1382	District Office S:	
POD No:	81376	Surv Map:	
POD Rec No:	196558	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415196.8
Pcw Rcv Da:		Northing:	3948839.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/04/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593086.0
Static Lev:	0	Y:	1702800.0
Tract Nbr:	1	Point Y:	35.67979942
Map Nbr:		Point X:	-105.93713632
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
140	E	0.50	2,638.11	7,150.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	36922	Surv Map:	
POD Rec No:	47085	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416818.4
Pcw Rcv Da:		Northing:	3949001.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/10/1991, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598400.0
Static Lev:	0	Y:	1703400.0
Tract Nbr:		Point Y:	35.68140074
Map Nbr:		Point X:	-105.91923534
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
141	SW	0.50	2,625.06	7,076.38	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A2193	Surv Map:	
POD Rec No:	355653	Other Loc:	449 Camino Monte Vista
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415381.7
Pcw Rcv Da:		Northing:	3948450.0
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	09/15/2025, 12:00 AM	Latitude Second:	34.71
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	6.19
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67630838
Map Nbr:		Point X:	-105.93505237
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
142	W	0.51	2,675.12	7,025.80	WATER WELLS

License Nb:	539	District Office S:	
POD No:	50779	Surv Map:	
POD Rec No:	338812	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/10/1989, 12:00 AM	Restrict :	0.0
Finish Date:	07/12/1989, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	12/29/1989, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA

Wells and Additional Sources Detail Report

Depth of Well:	100	UTM Zone:	13
Depth of Water:	30	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415171.4
Pcw Rcv Da:		Northing:	3948900.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/10/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593000.0
Static Lev:	0	Y:	1703000.0
Tract Nbr:		Point Y:	35.68034986
Map Nbr:		Point X:	-105.93742344
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
143	SW	0.50	2,652.69	7,067.08	WATER WELLS

License Nb:	228	District Office S:	
POD No:	42587	Surv Map:	
POD Rec No:	63741	Other Loc:	444 Camino De Las Animas
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/04/1984, 12:00 AM	Restrict :	0.0
Finish Date:	10/08/1984, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	03/29/1999, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	5	UTM Source:	EA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	40	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415329.9
Pcw Rcv Da:		Northing:	3948501.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/11/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1733780.0
Static Lev:	0	Y:	1701761.0
Tract Nbr:		Point Y:	35.67677092
Map Nbr:		Point X:	-105.93563015
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
144	WSW	0.50	2,661.70	7,062.08	WATER WELLS

License Nb:	815	District Office S:	
POD No:	51434	Surv Map:	
POD Rec No:	339032	Other Loc:	428 Camino De Las Animas
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T2/1 SF
Start Date:	07/13/1990, 12:00 AM	Restrict :	0.0
Finish Date:	07/16/1990, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	08/30/1990, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	320	UTM Zone:	13
Depth of Water:	240	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415291.5
Pcw Rcv Da:		Northing:	3948554.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/29/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415291.5
Static Lev:	0	Y:	3948554.3
Tract Nbr:		Point Y:	35.67724092
Map Nbr:		Point X:	-105.93605996
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1054098329347000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
146	NNE	0.50	2,665.35	7,148.87	WATER WELLS

License Nb:	622	District Office S:	
POD No:	62774	Surv Map:	
POD Rec No:	61887	Other Loc:	400 Kachina Ct, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	19 SF
Start Date:	05/10/1996, 12:00 AM	Restrict :	0.0
Finish Date:	05/13/1996, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	05/29/1996, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	360	UTM Zone:	13
Depth of Water:	120	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416354.6
Pcw Rcv Da:		Northing:	3949761.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/14/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Kachina Hills	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416354.6
Static Lev:	0	Y:	3949761.6
Tract Nbr:		Point Y:	35.68821578
Map Nbr:		Point X:	-105.92443925
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055099143210000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
147	WSW	0.51	2,690.87	7,044.82	WATER WELLS

License Nb:	0	District Office S:	
POD No:	28254	Surv Map:	
POD Rec No:	15951	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415229.3
Pcw Rcv Da:		Northing:	3948655.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/02/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593200.0
Static Lev:	0	Y:	1702200.0
Tract Nbr:		Point Y:	35.67815062
Map Nbr:		Point X:	-105.93675791
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
148	NNW	0.51	2,708.45	7,064.47	WATER WELLS

License Nb:	986	District Office S:	
POD No:	50497	Surv Map:	
POD Rec No:	11795	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:	04/12/1989, 12:00 AM	Restrict :	0.0
Finish Date:	04/22/1989, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/27/1989, 12:00 AM	Range:	

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	206	UTM Zone:	13
Depth of Water:	60	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415644.3
Pcw Rcv Da:		Northing:	3949779.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/31/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415644.3
Static Lev:	0	Y:	3949779.4
Tract Nbr:		Point Y:	35.68831572
Map Nbr:		Point X:	-105.93229034
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1054099438216000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
149	WSW	0.52	2,736.26	7,060.63	WATER WELLS

License Nb:	122	District Office S:	
POD No:	51434	Surv Map:	
POD Rec No:	13668	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:	08/30/1990, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	170	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415258.6
Pcw Rcv Da:		Northing:	3948564.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/29/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593300.0
Static Lev:	0	Y:	1701900.0
Tract Nbr:		Point Y:	35.67732554
Map Nbr:		Point X:	-105.9364245
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
150	SW	0.52	2,735.69	7,083.66	WATER WELLS

License Nb:	1768	District Office S:	
POD No:	04309	Surv Map:	
POD Rec No:	307222	Other Loc:	450 Camino Monte Vista
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 3 NA SF
Start Date:	04/16/2018, 12:00 AM	Restrict :	0.0
Finish Date:	04/17/2018, 12:00 AM	Section:	25

Wells and Additional Sources Detail Report

Plug Date:		Township:	17N
Log File D:	04/20/2018, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	360	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	45	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415383.8
Pcw Rcv Da:		Northing:	3948398.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/05/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1733961.0
Static Lev:	96	Y:	1701423.0
Tract Nbr:		Point Y:	35.67584067
Map Nbr:		Point X:	-105.93502371
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
151	E	0.53	2,798.77	7,121.49	WATER WELLS

License Nb:	253	District Office S:	
POD No:	28871	Surv Map:	USGS 7.5'QUAD SANTA FE
POD Rec No:	12420	Other Loc:	1117 E. Alameda, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/22/1977, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	07/25/1977, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	07/29/1977, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	85	UTM Zone:	13
Depth of Water:	12	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416863.3
Pcw Rcv Da:		Northing:	3948945.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416863.3
Static Lev:	0	Y:	3948945.7
Tract Nbr:		Point Y:	35.68090327
Map Nbr:		Point X:	-105.91873346
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098327485000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
152	WNW	0.53	2,800.18	7,010.69	WATER WELLS

License Nb:	0	District Office S:	
POD No:	30341	Surv Map:	
POD Rec No:	40682	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:		Restrict :	0.0
Finish Date:	01/01/1959, 12:00 AM	Section:	
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	200	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415158.7
Pcw Rcv Da:		Northing:	3949217.4
Sched Date:		Latitude Degree:	0
Use of Wel:	IRR.	Latitude Minute:	0
Sys Date:	06/20/1991, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592945.0
Static Lev:	0	Y:	1704040.0
Tract Nbr:		Point Y:	35.68320749
Map Nbr:		Point X:	-105.93759721
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
153	S	0.52	2,754.44	7,171.78	WATER WELLS

License Nb:	622	District Office S:	
POD No:	60399	Surv Map:	
POD Rec No:	42592	Other Loc:	540 Camino Rancheros
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	1 2 SF
Start Date:	10/17/1994, 12:00 AM	Restrict :	0.0
Finish Date:	10/18/1994, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	12/09/1994, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	370	UTM Zone:	13
Depth of Water:	99	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	5	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416151.3
Pcw Rcv Da:		Northing:	3948144.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/27/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416151.3
Static Lev:	0	Y:	3948144.6
Tract Nbr:		Point Y:	35.67362086
Map Nbr:		Point X:	-105.92651728
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098087223000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
154	NNW	0.52	2,758.91	7,102.49	WATER WELLS

License Nb:	0	District Office S:	
POD No:	30796	Surv Map:	
POD Rec No:	29795	Other Loc:	321 Hillside Ave
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	9 40 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415670.5
Pcw Rcv Da:		Northing:	3949808.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/01/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1734843.0
Static Lev:	0	Y:	1706064.0
Tract Nbr:		Point Y:	35.68858301
Map Nbr:		Point X:	-105.9320039
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
155	W	0.53	2,798.01	7,027.21	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91533	Surv Map:	
POD Rec No:	246340	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0

Wells and Additional Sources Detail Report

POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415139.4
Pcw Rcv Da:		Northing:	3948853.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	06/25/2009, 12:00 AM	Latitude Second:	47.73
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	15.98
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6799252
Map Nbr:		Point X:	-105.93777208
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
156	SSE	0.53	2,774.28	7,178.41	WATER WELLS

License Nb:	0	District Office S:	
POD No:	81392	Surv Map:	
POD Rec No:	196619	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416286.7
Pcw Rcv Da:		Northing:	3948173.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/06/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596690.0
Static Lev:	0	Y:	1700663.0
Tract Nbr:		Point Y:	35.67389651
Map Nbr:		Point X:	-105.92502435
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
157	W	0.54	2,844.37	7,027.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91534	Surv Map:	
POD Rec No:	246341	Other Loc:	
POD Basin:	RG	Zone :	

Wells and Additional Sources Detail Report

POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415127.9
Pcw Rcv Da:		Northing:	3948839.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	06/25/2009, 12:00 AM	Latitude Second:	47.26
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	16.43
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67979439
Map Nbr:		Point X:	-105.93789763
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
158	SW	0.53	2,820.92	7,072.26	WATER WELLS

License Nb:	253	District Office S:	
POD No:	38146	Surv Map:	
POD Rec No:	42191	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/31/1982, 12:00 AM	Restrict :	0.0
Finish Date:	09/01/1982, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	09/08/1982, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	125	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	60	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415287.9
Pcw Rcv Da:		Northing:	3948472.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/30/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593400.0
Static Lev:	0	Y:	1701600.0
Tract Nbr:		Point Y:	35.67650046
Map Nbr:		Point X:	-105.93609109
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
159	W	0.54	2,851.06	7,026.27	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94832	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	343503	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD13	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415122.1
Pcw Rcv Da:		Northing:	3948859.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/26/2023, 12:00 AM	Latitude Second:	47.92
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	16.67
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6799778
Map Nbr:		Point X:	-105.93796387
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
160	SSE	0.53	2,810.53	7,182.65	WATER WELLS

License Nb:	225	District Office S:	

Wells and Additional Sources Detail Report

POD No:	44857	Surv Map:	
POD Rec No:	45114	Other Loc:	600 Camino Rancheros, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	26 4 SF
Start Date:	12/30/1985, 12:00 AM	Restrict :	0.0
Finish Date:	01/04/1986, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	02/21/1986, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	410	UTM Zone:	13
Depth of Water:	411	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	5	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416192.0
Pcw Rcv Da:		Northing:	3948135.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/23/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	De Vargas	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416192.0
Static Lev:	0	Y:	3948135.6
Tract Nbr:		Point Y:	35.67354319
Map Nbr:		Point X:	-105.92606667
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098097215000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
161	SSE	0.54	2,827.36	7,187.32	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	81586	Surv Map:	
POD Rec No:	197575	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416389.1
Pcw Rcv Da:		Northing:	3948199.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/12/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597025.0
Static Lev:	0	Y:	1700752.0
Tract Nbr:		Point Y:	35.67413779
Map Nbr:		Point X:	-105.92389565
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
162	ESE	0.54	2,864.35	7,175.38	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	65773	Surv Map:	
POD Rec No:	6748	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416782.5
Pcw Rcv Da:		Northing:	3948575.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/04/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598300.0
Static Lev:	0	Y:	1702000.0
Tract Nbr:		Point Y:	35.6775554
Map Nbr:		Point X:	-105.91958793
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
163	W	0.54	2,867.35	7,025.94	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	343502	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD12	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415117.8
Pcw Rcv Da:		Northing:	3948856.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/26/2023, 12:00 AM	Latitude Second:	47.82
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	16.84
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67995038
Map Nbr:		Point X:	-105.93801107
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

164	WSW	0.54	2,861.40	7,033.50	WATER WELLS

License Nb:	0	District Office S:	
POD No:	99395	Surv Map:	
POD Rec No:	330690	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415142.3
Pcw Rcv Da:		Northing:	3948747.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/11/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1733154.0
Static Lev:	0	Y:	1702560.0
Tract Nbr:		Point Y:	35.67897164
Map Nbr:		Point X:	-105.93772888
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

165	W	0.54	2,870.84	7,025.94	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91532	Surv Map:	
POD Rec No:	246336	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415115.8
Pcw Rcv Da:		Northing:	3948861.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	06/25/2009, 12:00 AM	Latitude Second:	47.97
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	16.92
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67999168
Map Nbr:		Point X:	-105.93803365
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
165	W	0.54	2,870.84	7,025.29	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91532	Surv Map:	
POD Rec No:	271064	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415115.8
Pcw Rcv Da:		Northing:	3948861.7
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	03/29/2012, 12:00 AM	Latitude Second:	47.99
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	16.92
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67999709
Map Nbr:		Point X:	-105.93803371
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
166	SE	0.54	2,854.66	7,197.59	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31909	Surv Map:	
POD Rec No:	14937	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416627.4
Pcw Rcv Da:		Northing:	3948363.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/07/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597800.0
Static Lev:	0	Y:	1701300.0
Tract Nbr:		Point Y:	35.67563647
Map Nbr:		Point X:	-105.92127975
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
167	E	0.55	2,911.89	7,121.61	WATER WELLS

License Nb:	0	District Office S:	
POD No:	17579	Surv Map:	
POD Rec No:	9958	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416891.0
Pcw Rcv Da:		Northing:	3948887.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/18/2008, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68037641
Map Nbr:		Point X:	-105.91842132
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
168	W	0.55	2,893.78	7,025.19	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	343505	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD15	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415109.3
Pcw Rcv Da:		Northing:	3948856.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/26/2023, 12:00 AM	Latitude Second:	47.82
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.18
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67994965
Map Nbr:		Point X:	-105.93810499
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
169	W	0.55	2,896.02	7,025.03	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	343504	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD14	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415108.3
Pcw Rcv Da:		Northing:	3948863.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/26/2023, 12:00 AM	Latitude Second:	48.06
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.22
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68001628
Map Nbr:		Point X:	-105.93811682
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
170	W	0.55	2,897.07	7,025.99	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	343506	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD16	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415109.7
Pcw Rcv Da:		Northing:	3948849.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/26/2023, 12:00 AM	Latitude Second:	47.59
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.16
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67988658
Map Nbr:		Point X:	-105.93809983

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
171	SSW	0.54	2,872.98	7,122.07	WATER WELLS

License Nb:	0	District Office S:	
POD No:	90099	Surv Map:	
POD Rec No:	235372	Other Loc:	Nad 27
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415590.2
Pcw Rcv Da:		Northing:	3948195.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	11/30/2018, 12:00 AM	Latitude Second:	26.5
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	55
Ditch Name:		Longitude Second:	57.8
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67402827

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.93272193
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
172	W	0.55	2,904.63	7,026.16	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	343507	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD17	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415108.6
Pcw Rcv Da:		Northing:	3948841.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/26/2023, 12:00 AM	Latitude Second:	47.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.2
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.67981076
Map Nbr:		Point X:	-105.9381111
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
173	W	0.55	2,910.75	7,024.45	WATER WELLS

License Nb:	1522	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	327368	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD8	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/09/2020, 12:00 AM	Restrict :	0.0
Finish Date:	07/11/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/17/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	60	UTM Zone:	13
Depth of Water:	43	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415102.9
Pcw Rcv Da:		Northing:	3948871.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	04/27/2022, 12:00 AM	Latitude Second:	48.29
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.44
Well Tag:	NA	X:	0.0

Static Lev:	43	Y:	0.0
Tract Nbr:		Point Y:	35.68008072
Map Nbr:		Point X:	-105.93817724
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
174	SW	0.55	2,880.73	7,096.28	WATER WELLS

License Nb:	214	District Office S:	
POD No:	67599	Surv Map:	
POD Rec No:	80129	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415373.7
Pcw Rcv Da:		Northing:	3948345.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/21/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	De Vargas Development Co.	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:		X:	593687.0
Static Lev:	0	Y:	1701188.0
Tract Nbr:		Point Y:	35.6753656
Map Nbr:		Point X:	-105.93512977
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
175	W	0.55	2,915.62	7,024.45	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	291430	Other Loc:	Mw-7, 600 Old Santa Fe Trail
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	MW-7	Subdiv Loc:	
Start Date:	07/14/2014, 12:00 AM	Restrict :	0.0
Finish Date:	07/15/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/05/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	50	UTM Zone:	13
Depth of Water:	46	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415101.6
Pcw Rcv Da:		Northing:	3948866.2
Sched Date:		Latitude Degree:	35
Use of Wel:	MON	Latitude Minute:	40
Sys Date:	10/02/2018, 12:00 AM	Latitude Second:	48.13
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	17.49
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68003644
Map Nbr:		Point X:	-105.93819109
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
175	W	0.55	2,915.62	7,024.45	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	291429	Other Loc:	Mw-6
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	MW-6	Subdiv Loc:	
Start Date:	07/14/2014, 12:00 AM	Restrict :	0.0
Finish Date:	07/15/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/05/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	50	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415101.6
Pcw Rcv Da:		Northing:	3948866.2
Sched Date:		Latitude Degree:	35
Use of Wel:	MON	Latitude Minute:	40
Sys Date:	10/09/2019, 12:00 AM	Latitude Second:	48.13
Subdiv Nam:		Longitude Degree:	105

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.49
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68003644
Map Nbr:		Point X:	-105.93819109
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
176	W	0.55	2,918.10	7,025.15	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	343501	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD11	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415104.6
Pcw Rcv Da:		Northing:	3948843.0
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/26/2023, 12:00 AM	Latitude Second:	47.38

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.36
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67982754
Map Nbr:		Point X:	-105.93815549
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
177	W	0.55	2,925.56	7,024.39	WATER WELLS

License Nb:	1522	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	327367	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD7	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/07/2020, 12:00 AM	Restrict :	0.0
Finish Date:	07/08/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/17/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	50	UTM Zone:	13
Depth of Water:	43	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415100.2
Pcw Rcv Da:		Northing:	3948857.2
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40

Wells and Additional Sources Detail Report

Sys Date:	04/27/2022, 12:00 AM	Latitude Second:	47.84
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.54
Well Tag:	NA	X:	0.0
Static Lev:	43	Y:	0.0
Tract Nbr:		Point Y:	35.67995518
Map Nbr:		Point X:	-105.93820561
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
178	W	0.55	2,928.24	7,024.39	WATER WELLS

License Nb:	1522	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	327370	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD10	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/14/2020, 12:00 AM	Restrict :	0.0
Finish Date:	07/15/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/17/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	50	UTM Zone:	13
Depth of Water:	43	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415099.9
Pcw Rcv Da:		Northing:	3948852.6
Sched Date:		Latitude Degree:	35

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	40
Sys Date:	04/27/2022, 12:00 AM	Latitude Second:	47.69
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.55
Well Tag:	NA	X:	0.0
Static Lev:	43	Y:	0.0
Tract Nbr:		Point Y:	35.67991368
Map Nbr:		Point X:	-105.93820844
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
179	NNE	0.55	2,896.55	7,122.63	WATER WELLS

License Nb:	622	District Office S:	
POD No:	65227	Surv Map:	
POD Rec No:	25067	Other Loc:	412 Calle Kokopelli
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7 SF
Start Date:	01/09/2000, 12:00 AM	Restrict :	0.0
Finish Date:	01/14/2000, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	04/17/2000, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	285	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416270.7
Pcw Rcv Da:		Northing:	3949871.9

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/04/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Kachina Hills	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416270.7
Static Lev:	0	Y:	3949871.9
Tract Nbr:		Point Y:	35.68920304
Map Nbr:		Point X:	-105.92537788
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055099113239000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
180	W	0.55	2,929.90	7,025.15	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	291431	Other Loc:	Mw-8
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	MW-8	Subdiv Loc:	
Start Date:	07/14/2014, 12:00 AM	Restrict :	0.0
Finish Date:	07/15/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/05/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	50	UTM Zone:	13
Depth of Water:	40	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415099.6

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3948849.2
Sched Date:		Latitude Degree:	35
Use of Wel:	MON	Latitude Minute:	40
Sys Date:	10/09/2019, 12:00 AM	Latitude Second:	47.58
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.56
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67988301
Map Nbr:		Point X:	-105.9382114
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
180	W	0.55	2,929.90	7,025.15	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91532	Surv Map:	
POD Rec No:	271096	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	415099.6
Pcw Rcv Da:		Northing:	3948849.2
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	03/30/2012, 12:00 AM	Latitude Second:	47.58
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.56
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67988301
Map Nbr:		Point X:	-105.9382114
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
181	E	0.56	2,950.81	7,196.29	WATER WELLS

License Nb:	122	District Office S:	
POD No:	32089	Surv Map:	
POD Rec No:	325503	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	76	UTM Zone:	13
Depth of Water:	65	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	6	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416911.0
Pcw Rcv Da:		Northing:	3949091.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/04/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598700.0
Static Lev:	0	Y:	1703700.0
Tract Nbr:		Point Y:	35.68222172
Map Nbr:		Point X:	-105.91822146
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
182	W	0.56	2,954.46	7,023.53	WATER WELLS

License Nb:	1522	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	327369	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD9	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/12/2020, 12:00 AM	Restrict :	0.0
Finish Date:	07/13/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/17/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	50	UTM Zone:	13
Depth of Water:	43	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415089.0
Pcw Rcv Da:		Northing:	3948872.8
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	04/27/2022, 12:00 AM	Latitude Second:	48.34
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.99
Well Tag:	NA	X:	0.0
Static Lev:	43	Y:	0.0
Tract Nbr:		Point Y:	35.68009485
Map Nbr:		Point X:	-105.93833101
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
183	W	0.56	2,959.75	7,022.71	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	94832	Surv Map:	
POD Rec No:	305087	Other Loc:	Mw-11
POD Basin:	RG	Zone :	
POD Suffix:	POD6	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/03/2017, 12:00 AM	Restrict :	0.0
Finish Date:	02/04/2017, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	02/21/2017, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	50	UTM Zone:	13
Depth of Water:	35	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415086.9
Pcw Rcv Da:		Northing:	3948880.8
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	10/09/2019, 12:00 AM	Latitude Second:	48.6
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	18.08
Well Tag:		X:	0.0
Static Lev:	35	Y:	0.0
Tract Nbr:		Point Y:	35.68016679
Map Nbr:		Point X:	-105.93835506
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
184	SW	0.56	2,960.60	7,075.26	WATER WELLS

License Nb:	214	District Office S:	
POD No:	27930	Surv Map:	USGS 7.5' QUAD SANTA FE
POD Rec No:	16097	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/23/1978, 12:00 AM	Restrict :	0.0
Finish Date:	02/06/1978, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	02/16/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	335	UTM Zone:	13
Depth of Water:	72	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415257.0
Pcw Rcv Da:		Northing:	3948442.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/28/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593300.0
Static Lev:	0	Y:	1701500.0
Tract Nbr:		Point Y:	35.67622645
Map Nbr:		Point X:	-105.93642934
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
186	SSW	0.56	2,975.27	7,117.10	WATER WELLS

License Nb:	547	District Office S:	
POD No:	68665	Surv Map:	
POD Rec No:	131410	Other Loc:	909 Old Santa Fe Trail
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2&3 134 SF
Start Date:	10/28/1997, 12:00 AM	Restrict :	0.0
Finish Date:	10/29/1997, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	11/10/1997, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	95	UTM Accura:	10
Ground Water Src:	S	UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	28	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415509.4
Pcw Rcv Da:		Northing:	3948205.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/07/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415509.4
Static Lev:	0	Y:	3948205.2
Tract Nbr:		Point Y:	35.6741124
Map Nbr:		Point X:	-105.93361572
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1054098405240000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
187	SSW	0.56	2,976.85	7,140.66	WATER WELLS

License Nb:	214	District Office S:	
POD No:	16082	Surv Map:	
POD Rec No:	70020	Other Loc:	925 Old Santa Fe Trail
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T69A SF
Start Date:	09/10/1968, 12:00 AM	Restrict :	0.0
Finish Date:	09/10/1968, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	10/17/1968, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	85	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415748.2
Pcw Rcv Da:		Northing:	3948100.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/02/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	8	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735169.0
Static Lev:	0	Y:	1700463.0
Tract Nbr:		Point Y:	35.67319254
Map Nbr:		Point X:	-105.93096638
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	WSW	0.57	3,007.67	7,054.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	81960	Surv Map:	
POD Rec No:	199573	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415161.4
Pcw Rcv Da:		Northing:	3948572.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/13/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592981.0
Static Lev:	0	Y:	1701923.0
Tract Nbr:		Point Y:	35.67739111
Map Nbr:		Point X:	-105.93749933
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
189	E	0.58	3,056.20	7,120.51	WATER WELLS

License Nb:	227	District Office S:	
POD No:	66701	Surv Map:	
POD Rec No:	42901	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA C SF
Start Date:	04/12/1998, 12:00 AM	Restrict :	0.0
Finish Date:	04/14/1998, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/15/1998, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA

Wells and Additional Sources Detail Report

Depth of Well:	100	UTM Zone:	13
Depth of Water:	18	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	5	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416930.0
Pcw Rcv Da:		Northing:	3948845.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/19/2015, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1739016.0
Static Lev:	0	Y:	1702956.0
Tract Nbr:	C	Point Y:	35.68000647
Map Nbr:		Point X:	-105.91798612
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
190	SE	0.58	3,063.38	7,222.22	WATER WELLS

License Nb:	0	District Office S:	
POD No:	72757	Surv Map:	
POD Rec No:	152366	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416780.9
Pcw Rcv Da:		Northing:	3948453.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/04/1999, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598300.0
Static Lev:	0	Y:	1701600.0
Tract Nbr:		Point Y:	35.67645631
Map Nbr:		Point X:	-105.919593
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
191	SW	0.58	3,073.87	7,085.71	WATER WELLS

License Nb:	547	District Office S:	
POD No:	68724	Surv Map:	
POD Rec No:	139844	Other Loc:	832 Old Pecos Trl, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:	10/25/1999, 12:00 AM	Restrict :	0.0
Finish Date:	10/27/1999, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	10/29/1999, 12:00 AM	Range:	04E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	149	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	37	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415277.7
Pcw Rcv Da:		Northing:	3948361.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/12/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415277.7
Static Lev:	0	Y:	3948361.0
Tract Nbr:		Point Y:	35.6754971
Map Nbr:		Point X:	-105.93619209
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1054098322296000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
192	E	0.59	3,124.85	7,120.47	WATER WELLS

License Nb:	0	District Office S:	
POD No:	74962	Surv Map:	
POD Rec No:	162543	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416953.9
Pcw Rcv Da:		Northing:	3948871.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/13/2000, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598850.0
Static Lev:	0	Y:	1702980.0
Tract Nbr:		Point Y:	35.68024198
Map Nbr:		Point X:	-105.91772471
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
193	SSE	0.58	3,072.90	7,186.94	WATER WELLS

License Nb:	1173	District Office S:	
POD No:	50629	Surv Map:	
POD Rec No:	69858	Other Loc:	623 Camino Rancheros
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	15 5 U1 SF
Start Date:	05/08/1989, 12:00 AM	Restrict :	0.0
Finish Date:	05/18/1989, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/07/1989, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	236	UTM Zone:	13
Depth of Water:	120	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	12	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416311.5
Pcw Rcv Da:		Northing:	3948086.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1737018.0
Static Lev:	0	Y:	1700438.0
Tract Nbr:		Point Y:	35.67310708
Map Nbr:		Point X:	-105.92474121
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
194	SE	0.59	3,096.67	7,204.20	WATER WELLS

License Nb:	214	District Office S:	
POD No:	30590	Surv Map:	
POD Rec No:	23145	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/12/1978, 12:00 AM	Restrict :	0.0
Finish Date:	06/17/1978, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	06/21/1978, 12:00 AM	Range:	10E

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	380	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	5	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416564.5
Pcw Rcv Da:		Northing:	3948212.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597600.0
Static Lev:	0	Y:	1700800.0
Tract Nbr:		Point Y:	35.67426444
Map Nbr:		Point X:	-105.921959
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
195	SW	0.59	3,105.66	7,109.24	WATER WELLS

License Nb:	0	District Office S:	
POD No:	33565	Surv Map:	
POD Rec No:	56428	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	

Wells and Additional Sources Detail Report

Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415406.6
Pcw Rcv Da:		Northing:	3948226.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593800.0
Static Lev:	0	Y:	1700800.0
Tract Nbr:		Point Y:	35.67429922
Map Nbr:		Point X:	-105.9347538
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
196	ESE	0.60	3,155.97	7,166.15	WATER WELLS

License Nb:	0	District Office S:	
POD No:	65777	Surv Map:	
POD Rec No:	10217	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416905.1
Pcw Rcv Da:		Northing:	3948634.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/04/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598700.0
Static Lev:	0	Y:	1702200.0
Tract Nbr:		Point Y:	35.67810125
Map Nbr:		Point X:	-105.91823945
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
197	SW	0.59	3,123.03	7,095.27	WATER WELLS

License Nb:	547	District Office S:	
POD No:	68359	Surv Map:	
POD Rec No:	105647	Other Loc:	844 Old Santa Fe Trail
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	5 128 SF
Start Date:	10/14/1997, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	10/15/1997, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	10/27/1997, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	150	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415307.3
Pcw Rcv Da:		Northing:	3948307.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/05/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415307.3
Static Lev:	0	Y:	3948307.4
Tract Nbr:		Point Y:	35.67501642
Map Nbr:		Point X:	-105.9358594
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
198	WSW	0.59	3,135.92	7,056.83	WATER WELLS

License Nb:	622	District Office S:	
POD No:	71054	Surv Map:	
POD Rec No:	146887	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	280	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415136.3
Pcw Rcv Da:		Northing:	3948535.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/10/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592900.0
Static Lev:	0	Y:	1701800.0
Tract Nbr:		Point Y:	35.67705449
Map Nbr:		Point X:	-105.93777275
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
199	NW	0.60	3,143.86	7,002.15	WATER WELLS

License Nb:	228	District Office S:	
POD No:	44557	Surv Map:	
POD Rec No:	49303	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:	04/29/1986, 12:00 AM	Restrict :	0.0
Finish Date:	05/15/1986, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	06/26/1986, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	230	UTM Zone:	13
Depth of Water:	40	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415272.5
Pcw Rcv Da:		Northing:	3949660.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593300.0
Static Lev:	0	Y:	1705500.0
Tract Nbr:		Point Y:	35.68721553
Map Nbr:		Point X:	-105.93638646
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
201	SSW	0.60	3,158.30	7,118.41	WATER WELLS

License Nb:	228	District Office S:	
POD No:	31517	Surv Map:	
POD Rec No:	29206	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7A SF
Start Date:	02/21/1979, 12:00 AM	Restrict :	0.0
Finish Date:	02/21/1979, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	03/02/1979, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	EA
Depth of Well:	140	UTM Zone:	13
Depth of Water:	15	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	22	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415466.8
Pcw Rcv Da:		Northing:	3948165.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/28/2019, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Heights	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	594000.0
Static Lev:	0	Y:	1700600.0
Tract Nbr:		Point Y:	35.67374724
Map Nbr:		Point X:	-105.93408217
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
202	SSE	0.60	3,167.58	7,207.15	WATER WELLS

License Nb:	227	District Office S:	
POD No:	34163	Surv Map:	
POD Rec No:	59540	Other Loc:	632 Camino Del Monte Sol, Sf
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 SF
Start Date:	04/25/1980, 12:00 AM	Restrict :	0.0
Finish Date:	04/28/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	05/05/1980, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	110	UTM Zone:	13
Depth of Water:	84	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416413.3
Pcw Rcv Da:		Northing:	3948096.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/30/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416413.3
Static Lev:	0	Y:	3948096.6
Tract Nbr:		Point Y:	35.67321037
Map Nbr:		Point X:	-105.92361757
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098168195000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
203	SSW	0.61	3,223.53	7,118.69	WATER WELLS

License Nb:	0	District Office S:	
POD No:	48630	Surv Map:	
POD Rec No:	163069	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	S	BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	06
Plug Date:		Township:	16N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415454.4
Pcw Rcv Da:		Northing:	3948150.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/01/2000, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593960.0
Static Lev:	0	Y:	1700550.0
Tract Nbr:		Point Y:	35.67361095
Map Nbr:		Point X:	-105.9342176
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
204	ENE	0.62	3,254.62	7,203.29	WATER WELLS

License Nb:	0	District Office S:	
POD No:	66975	Surv Map:	
POD Rec No:	67600	Other Loc:	
POD Basin:	RG	Zone :	C

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416974.2
Pcw Rcv Da:		Northing:	3949273.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/09/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598900.0
Static Lev:	0	Y:	1704300.0
Tract Nbr:		Point Y:	35.68386872
Map Nbr:		Point X:	-105.91754191
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Salvador Gonzales/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
205	NW	0.61	3,237.88	7,015.56	WATER WELLS

License Nb:	0	District Office S:	
POD No:	96123	Surv Map:	
POD Rec No:	301879	Other Loc:	Dsf-06

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:	POD8	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415395.7
Pcw Rcv Da:		Northing:	3949816.7
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	06/17/2016, 12:00 AM	Latitude Second:	19.07
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	6.15
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68863068
Map Nbr:		Point X:	-105.93504144
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
207	NW	0.63	3,323.16	6,998.35	WATER WELLS

License Nb:	0	District Office S:	
POD No:	96123	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	301873	Other Loc:	Dsf-02a
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415204.7
Pcw Rcv Da:		Northing:	3949665.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	06/17/2016, 12:00 AM	Latitude Second:	14.09
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	13.69
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68724756
Map Nbr:		Point X:	-105.93713612
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
208	E	0.64	3,354.91	7,142.35	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	34548	Surv Map:	
POD Rec No:	12381	Other Loc:	1176 Cerro Gordo Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	16 12 TA SF
Start Date:		Restrict :	0.0
Finish Date:	12/31/1925, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	26	UTM Zone:	13
Depth of Water:	12	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	14	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417036.2
Pcw Rcv Da:		Northing:	3949048.1
Sched Date:		Latitude Degree:	0
Use of Wel:	IRR	Latitude Minute:	0
Sys Date:	10/05/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1739356.0
Static Lev:	0	Y:	1703625.0
Tract Nbr:		Point Y:	35.681841
Map Nbr:		Point X:	-105.91683355
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
209	WNW	0.64	3,365.89	7,001.47	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	214	District Office S:	
POD No:	32605	Surv Map:	
POD Rec No:	31947	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/20/1979, 12:00 AM	Restrict :	0.0
Finish Date:	07/26/1979, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/06/1979, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	240	UTM Zone:	13
Depth of Water:	205	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	35	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414993.2
Pcw Rcv Da:		Northing:	3949268.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/14/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592400.0
Static Lev:	0	Y:	1704200.0
Tract Nbr:		Point Y:	35.68365211
Map Nbr:		Point X:	-105.93943134
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
210	ENE	0.63	3,350.28	7,206.94	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	1173	District Office S:	
POD No:	50645	Surv Map:	
POD Rec No:	3655	Other Loc:	200a Gonzales Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 SF
Start Date:	07/30/1991, 12:00 AM	Restrict :	0.0
Finish Date:	08/01/1991, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	10/28/1991, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	215	UTM Zone:	13
Depth of Water:	30	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	100	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416985.4
Pcw Rcv Da:		Northing:	3949341.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1739177.0
Static Lev:	0	Y:	1704584.0
Tract Nbr:		Point Y:	35.6844782
Map Nbr:		Point X:	-105.91742512
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
211	WSW	0.63	3,343.65	7,054.96	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	622	District Office S:	
POD No:	34614	Surv Map:	
POD Rec No:	52864	Other Loc:	321 E Berger
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	11** 109 TB SF
Start Date:	07/15/1980, 12:00 AM	Restrict :	0.0
Finish Date:	07/15/1980, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	07/24/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	340	UTM Zone:	13
Depth of Water:	110	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415082.8
Pcw Rcv Da:		Northing:	3948501.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/06/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Buena Vista	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1732969.0
Static Lev:	0	Y:	1701748.0
Tract Nbr:		Point Y:	35.67674246
Map Nbr:		Point X:	-105.93836027
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

212	E	0.64	3,368.36	7,161.90	WATER WELLS

License Nb:	228	District Office S:	
POD No:	35503	Surv Map:	
POD Rec No:	36099	Other Loc:	101 Rim Rd, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	107* 1 SF
Start Date:	01/29/1981, 12:00 AM	Restrict :	0.0
Finish Date:	02/02/1981, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	02/18/1981, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	160	UTM Zone:	13
Depth of Water:	60	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417037.0
Pcw Rcv Da:		Northing:	3949112.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1739356.0
Static Lev:	0	Y:	1703835.0
Tract Nbr:		Point Y:	35.68241805
Map Nbr:		Point X:	-105.91683131
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098368521000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

213	W	0.64	3,372.48	7,012.71	WATER WELLS

License Nb:	0	District Office S:	
POD No:	73396	Surv Map:	
POD Rec No:	155871	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	200	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.58	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414958.1
Pcw Rcv Da:		Northing:	3948903.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/23/2000, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592300.0
Static Lev:	0	Y:	1703000.0
Tract Nbr:		Point Y:	35.68035583
Map Nbr:		Point X:	-105.93978057
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
214	WNW	0.64	3,393.69	6,995.10	WATER WELLS

License Nb:	0	District Office S:	
POD No:	96123	Surv Map:	
POD Rec No:	301874	Other Loc:	Dsf-02b
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415105.1
Pcw Rcv Da:		Northing:	3949558.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	06/17/2016, 12:00 AM	Latitude Second:	10.6
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	17.61
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68627797
Map Nbr:		Point X:	-105.93822549
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
215	ESE	0.65	3,409.88	7,171.27	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35592	Surv Map:	
POD Rec No:	32100	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416996.9
Pcw Rcv Da:		Northing:	3948663.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/04/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	599000.0
Static Lev:	0	Y:	1702300.0
Tract Nbr:		Point Y:	35.67837313
Map Nbr:		Point X:	-105.91722815
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
216	NNW	0.65	3,414.80	7,032.22	WATER WELLS

License Nb:	253	District Office S:	
POD No:	29042	Surv Map:	
POD Rec No:	21085	Other Loc:	235 Otero St, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	20 26
Start Date:	01/24/1978, 12:00 AM	Restrict :	0.0
Finish Date:	01/27/1978, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	02/01/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	165	UTM Zone:	13
Depth of Water:	37	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415446.6
Pcw Rcv Da:		Northing:	3949917.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/07/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415446.6
Static Lev:	0	Y:	3949917.4
Tract Nbr:		Point Y:	35.68954288
Map Nbr:		Point X:	-105.93448955
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal: Parcel Number 1054099378248000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
217	SSE	0.65	3,435.98	7,205.50	WATER WELLS

License Nb:	1195	District Office S:	
POD No:	82610	Surv Map:	
POD Rec No:	202114	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	33 U1 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	EA
Depth of Well:	500	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416244.1
Pcw Rcv Da:		Northing:	3947951.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	04/28/2004, 12:00 AM	Latitude Second:	18.8
Subdiv Nam:	De Vargas Development Co.	Longitude Degree:	105
Surface Co:	0	Longitude Minute:	55
Ditch Name:		Longitude Second:	31.7
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6718888
Map Nbr:		Point X:	-105.92547189
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
218	SE	0.66	3,478.28	7,313.72	WATER WELLS

License Nb:	0	District Office S:	
POD No:	53900	Surv Map:	
POD Rec No:	52131	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416871.2
Pcw Rcv Da:		Northing:	3948360.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/23/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598600.0
Static Lev:	0	Y:	1701300.0
Tract Nbr:		Point Y:	35.67562911
Map Nbr:		Point X:	-105.91858571
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
218	SE	0.66	3,478.28	7,313.72	WATER WELLS

License Nb:	0	District Office S:	
POD No:	51374	Surv Map:	
POD Rec No:	17495	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416871.2
Pcw Rcv Da:		Northing:	3948360.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/18/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598600.0
Static Lev:	0	Y:	1701300.0
Tract Nbr:		Point Y:	35.67562911
Map Nbr:		Point X:	-105.91858571

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
219	SSE	0.66	3,466.12	7,222.25	WATER WELLS

License Nb:	0	District Office S:	
POD No:	47857	Surv Map:	
POD Rec No:	62125	Other Loc:	644 Camino Del Monte Sol
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416458.4
Pcw Rcv Da:		Northing:	3948017.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/19/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1737503.0
Static Lev:	0	Y:	1700220.0
Tract Nbr:		Point Y:	35.67250379

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.9231111
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Lot 7 De Vargas Subdv		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
220	E	0.67	3,536.67	7,135.02	WATER WELLS

License Nb:	214	District Office S:	
POD No:	31705	Surv Map:	
POD Rec No:	36502	Other Loc:	1201 Canyon Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	A1 SF
Start Date:	12/18/1978, 12:00 AM	Restrict :	0.0
Finish Date:	12/22/1978, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	01/03/1979, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	159	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417083.8
Pcw Rcv Da:		Northing:	3948891.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/19/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417083.8
Static Lev:	0	Y:	3948891.3

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.68043141
Map Nbr:		Point X:	-105.91629142
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1-055-098-412-461		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
221	NW	0.67	3,518.61	7,003.98	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	96123	Surv Map:	
POD Rec No:	301876	Other Loc:	Dsf-04
POD Basin:	RG	Zone :	
POD Suffix:	POD5	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/26/2016, 12:00 AM	Restrict :	0.0
Finish Date:	06/26/2016, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/07/2018, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	29	UTM Zone:	13
Depth of Water:	24	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415275.9
Pcw Rcv Da:		Northing:	3949828.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/19/2018, 12:00 AM	Latitude Second:	19.41
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	10.92
Well Tag:		X:	0.0

Wells and Additional Sources Detail Report

Static Lev:	19	Y:	0.0
Tract Nbr:		Point Y:	35.68872497
Map Nbr:		Point X:	-105.93636653
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
222	S	0.66	3,504.77	7,172.42	WATER WELLS

License Nb:	547	District Office S:	
POD No:	66039	Surv Map:	
POD Rec No:	20920	Other Loc:	711 Camino Corrales, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	66 SF
Start Date:	08/22/1997, 12:00 AM	Restrict :	0.0
Finish Date:	08/26/1997, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	09/08/1997, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	126	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	27	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415894.4
Pcw Rcv Da:		Northing:	3947908.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/09/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:	NA	X:	415894.4
Static Lev:	0	Y:	3947908.0
Tract Nbr:		Point Y:	35.67146598
Map Nbr:		Point X:	-105.92933093
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098011154000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
223	WNW	0.67	3,554.29	6,987.06	WATER WELLS

License Nb:	214	District Office S:	
POD No:	35065	Surv Map:	
POD Rec No:	58504	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/16/1980, 12:00 AM	Restrict :	0.0
Finish Date:	09/18/1980, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	09/29/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	243	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	23	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414995.6
Pcw Rcv Da:		Northing:	3949451.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/15/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592400.0
Static Lev:	0	Y:	1704800.0
Tract Nbr:		Point Y:	35.6853003
Map Nbr:		Point X:	-105.93942414
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
224	ESE	0.67	3,541.79	7,273.26	WATER WELLS

License Nb:	0	District Office S:	
POD No:	57536	Surv Map:	
POD Rec No:	44010	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416932.9
Pcw Rcv Da:		Northing:	3948420.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/07/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598800.0
Static Lev:	0	Y:	1701500.0
Tract Nbr:		Point Y:	35.67617703
Map Nbr:		Point X:	-105.91791021
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
225	NW	0.67	3,541.08	6,996.12	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	96123	Surv Map:	
POD Rec No:	301872	Other Loc:	Dsf-01
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/23/2016, 12:00 AM	Restrict :	0.0
Finish Date:	06/23/2016, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/07/2018, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	35	UTM Zone:	13
Depth of Water:	27	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415165.0
Pcw Rcv Da:		Northing:	3949722.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/19/2018, 12:00 AM	Latitude Second:	15.93

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	15.29
Well Tag:		X:	0.0
Static Lev:	20	Y:	0.0
Tract Nbr:		Point Y:	35.68775801
Map Nbr:		Point X:	-105.93758084
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
226	E	0.68	3,571.16	7,134.25	WATER WELLS

License Nb:	0	District Office S:	
POD No:	04930	Surv Map:	
POD Rec No:	177236	Other Loc:	Point Of Div. Of Acequia Madre
POD Basin:	SD	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417097.7
Pcw Rcv Da:		Northing:	3948921.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	04/01/2002, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	599320.0
Static Lev:	0	Y:	1703150.0
Tract Nbr:		Point Y:	35.68070484
Map Nbr:		Point X:	-105.91614094
Driller:			
POD Basin Desc:	Surface Declaration		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
226	E	0.68	3,571.16	7,134.25	WATER WELLS

License Nb:	0	District Office S:	
POD No:	04682	Surv Map:	SANTA FE (VOLUME II)
POD Rec No:	151588	Other Loc:	Acequia Madre
POD Basin:	SD	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417097.7
Pcw Rcv Da:		Northing:	3948921.5
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	02/09/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	599320.0
Static Lev:	0	Y:	1703150.0
Tract Nbr:		Point Y:	35.68070484
Map Nbr:	19	Point X:	-105.91614094
Driller:			
POD Basin Desc:	Surface Declaration		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
227	E	0.68	3,572.11	7,134.25	WATER WELLS

License Nb:	0	District Office S:	
POD No:	04899	Surv Map:	
POD Rec No:	295910	Other Loc:	
POD Basin:	SP	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417098.0
Pcw Rcv Da:		Northing:	3948918.1

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/20/2015, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1739564.0
Static Lev:	0	Y:	1703201.0
Tract Nbr:		Point Y:	35.68067422
Map Nbr:		Point X:	-105.91613728
Driller:			
POD Basin Desc:	Surface Permit		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
228	NW	0.68	3,575.05	6,996.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	95469	Surv Map:	
POD Rec No:	297680	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD4	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415180.2

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3949755.0
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	08/06/2015, 12:00 AM	Latitude Second:	17.0
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	14.7
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68805592
Map Nbr:		Point X:	-105.93741634
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
229	SW	0.68	3,565.66	7,105.63	WATER WELLS

License Nb:	0	District Office S:	
POD No:	32610	Surv Map:	
POD Rec No:	58529	Other Loc:	1001 Old Pecos Trail
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	500	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	415309.6
Pcw Rcv Da:		Northing:	3948124.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/15/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1733729.0
Static Lev:	0	Y:	1700522.0
Tract Nbr:		Point Y:	35.67336773
Map Nbr:		Point X:	-105.93581474
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
230	S	0.67	3,562.40	7,178.51	WATER WELLS

License Nb:	214	District Office S:	
POD No:	28950	Surv Map:	
POD Rec No:	67173	Other Loc:	1011 Old Santa Fe Trail, Sf
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	65 3B SF
Start Date:	06/27/1977, 12:00 AM	Restrict :	0.0
Finish Date:	06/29/1977, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	07/07/1977, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	356	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415999.8
Pcw Rcv Da:		Northing:	3947885.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/05/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415999.8
Static Lev:	0	Y:	3947885.8
Tract Nbr:		Point Y:	35.67127482
Map Nbr:		Point X:	-105.92816413
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098033131000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
231	S	0.68	3,570.37	7,179.46	WATER WELLS

License Nb:	228	District Office S:	
POD No:	50246	Surv Map:	
POD Rec No:	64655	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/27/1989, 12:00 AM	Restrict :	0.0
Finish Date:	05/03/1989, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/26/1989, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	440	UTM Zone:	13
Depth of Water:	110	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416042.3
Pcw Rcv Da:		Northing:	3947883.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/30/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	595900.0
Static Lev:	0	Y:	1699700.0
Tract Nbr:		Point Y:	35.6712577078761
Map Nbr:		Point X:	-105.927694335246
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	JUAN DE GABALDON		
Legal:	LOT NO. 64 OF SUBDIVISION 1 OF DEVARGAS DEVELOPMENT		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
232	SW	0.68	3,592.29	7,089.67	WATER WELLS

License Nb:	0	District Office S:	
POD No:	30514	Surv Map:	
POD Rec No:	8653	Other Loc:	1002 Old Pecos Trail
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415183.6
Pcw Rcv Da:		Northing:	3948230.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/23/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ramona	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1733311.0
Static Lev:	0	Y:	1700864.0
Tract Nbr:		Point Y:	35.67431072
Map Nbr:		Point X:	-105.937218
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
233	SSE	0.68	3,584.88	7,212.82	WATER WELLS

License Nb:	214	District Office S:	
POD No:	31224	Surv Map:	
POD Rec No:	333096	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/11/1979, 12:00 AM	Restrict :	0.0
Finish Date:	01/16/1979, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	01/17/1979, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	370	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	

Pump Seria:		XY Accuracy:	
Estimate Yield:	60	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416271.2
Pcw Rcv Da:		Northing:	3947911.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596650.0
Static Lev:	0	Y:	1699800.0
Tract Nbr:		Point Y:	35.67152599
Map Nbr:		Point X:	-105.92516826
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
234	SSE	0.68	3,588.97	7,226.07	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31701	Surv Map:	
POD Rec No:	22175	Other Loc:	664 Camino Del Monte Sol
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	9 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416475.6
Pcw Rcv Da:		Northing:	3947983.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/19/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416475.6
Static Lev:	0	Y:	3947983.5
Tract Nbr:		Point Y:	35.67219602
Map Nbr:		Point X:	-105.9229175
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1-055-098-185-166		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
235	SW	0.68	3,616.33	7,089.20	WATER WELLS

License Nb:	622	District Office S:	
POD No:	40601	Surv Map:	
POD Rec No:	42452	Other Loc:	1002 Old Pecos Trail
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T2 SF
Start Date:	09/15/1983, 12:00 AM	Restrict :	0.0
Finish Date:	09/15/1983, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	09/26/1983, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	120	UTM Accura:	10

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415180.7
Pcw Rcv Da:		Northing:	3948222.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ramona	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1733302.0
Static Lev:	0	Y:	1700837.0
Tract Nbr:		Point Y:	35.67423654
Map Nbr:		Point X:	-105.93724918
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
236	W	0.69	3,665.35	7,005.61	WATER WELLS

License Nb:	214	District Office S:	
POD No:	27732	Surv Map:	
POD Rec No:	3300	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/10/1975, 12:00 AM	Restrict :	0.0
Finish Date:	10/15/1976, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	10/19/1976, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	80	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	45	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414867.1
Pcw Rcv Da:		Northing:	3948934.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/26/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592000.0
Static Lev:	0	Y:	1703100.0
Tract Nbr:		Point Y:	35.68063376
Map Nbr:		Point X:	-105.94078943
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
238	SSE	0.69	3,668.40	7,228.46	WATER WELLS

License Nb:	547	District Office S:	
POD No:	68415	Surv Map:	
POD Rec No:	130574	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/15/1998, 12:00 AM	Restrict :	0.0
Finish Date:	06/15/1998, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	06/24/1998, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA

Wells and Additional Sources Detail Report

Depth of Well:	260	UTM Zone:	13
Depth of Water:	175	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	11	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416500.5
Pcw Rcv Da:		Northing:	3947969.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/06/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597400.0
Static Lev:	0	Y:	1700000.0
Tract Nbr:		Point Y:	35.67206831
Map Nbr:		Point X:	-105.9226409
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
238	SSE	0.69	3,668.40	7,228.46	WATER WELLS

License Nb:	1310	District Office S:	
POD No:	68415	Surv Map:	
POD Rec No:	148509	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	X	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/09/1999, 12:00 AM	Restrict :	0.0
Finish Date:	05/12/1999, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	06/01/1999, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	21	UTM Source:	PA
Depth of Well:	540	UTM Zone:	13
Depth of Water:	130	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416500.5
Pcw Rcv Da:		Northing:	3947969.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/06/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597400.0
Static Lev:	0	Y:	1700000.0
Tract Nbr:		Point Y:	35.67206831
Map Nbr:		Point X:	-105.9226409
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
239	SSE	0.69	3,668.52	7,223.83	WATER WELLS

License Nb:	253	District Office S:	
POD No:	38366	Surv Map:	
POD Rec No:	36178	Other Loc:	907 Garcia Street, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 SF
Start Date:	08/16/1982, 12:00 AM	Restrict :	0.0
Finish Date:	08/18/1982, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/26/1982, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	275	UTM Zone:	13
Depth of Water:	136	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	60	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-38366-/	Easting:	416412.2
Pcw Rcv Da:		Northing:	3947930.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/21/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416412.2
Static Lev:	0	Y:	3947930.5
Tract Nbr:		Point Y:	35.67171284
Map Nbr:		Point X:	-105.92361247
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098172153000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
240	WNW	0.71	3,740.25	6,987.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35733	Surv Map:	
POD Rec No:	54636	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	24
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415032.4
Pcw Rcv Da:		Northing:	3949642.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/10/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1732756.0
Static Lev:	0	Y:	1705491.0
Tract Nbr:		Point Y:	35.68702718
Map Nbr:		Point X:	-105.9390377
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
241	E	0.71	3,771.10	7,152.66	WATER WELLS

License Nb:	0	District Office S:	
POD No:	19196	Surv Map:	
POD Rec No:	21290	Other Loc:	4 Camino Pequeno
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	U1 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	2

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417162.1
Pcw Rcv Da:		Northing:	3948973.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Pequeno Compound	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1739772.0
Static Lev:	0	Y:	1703385.0
Tract Nbr:		Point Y:	35.68117815
Map Nbr:		Point X:	-105.91543469
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	4 Camino Pequeno, Santa Fe, N.M.		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
243	S	0.72	3,804.95	7,182.94	WATER WELLS

License Nb:	547	District Office S:	
POD No:	90099	Surv Map:	
POD Rec No:	241491	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/14/2013, 12:00 AM	Restrict :	0.0
Finish Date:	11/15/2013, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/30/2013, 12:00 AM	Range:	

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	400	UTM Zone:	13
Depth of Water:	110	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	8	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415951.1
Pcw Rcv Da:		Northing:	3947812.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	02/04/2014, 12:00 AM	Latitude Second:	14.2
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	55
Ditch Name:		Longitude Second:	43.3
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67061076
Map Nbr:		Point X:	-105.92869453
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
244	E	0.73	3,848.23	7,179.59	WATER WELLS

License Nb:	0	District Office S:	
POD No:	68085	Surv Map:	
POD Rec No:	104934	Other Loc:	1242 Cerro Cordo
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	340 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	

Wells and Additional Sources Detail Report

Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	22	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417185.2
Pcw Rcv Da:		Northing:	3949089.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/22/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	599600.0
Static Lev:	0	Y:	1703705.0
Tract Nbr:		Point Y:	35.68222766
Map Nbr:		Point X:	-105.91519141
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
244	E	0.73	3,848.23	7,179.59	WATER WELLS

License Nb:	0	District Office S:	
POD No:	67989	Surv Map:	
POD Rec No:	80815	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	X	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	22	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417185.2
Pcw Rcv Da:		Northing:	3949089.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/02/1997, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	599600.0
Static Lev:	0	Y:	1703705.0
Tract Nbr:		Point Y:	35.68222766
Map Nbr:		Point X:	-105.91519141
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
246	SW	0.73	3,832.40	7,086.46	WATER WELLS

License Nb:	228	District Office S:	
POD No:	47702	Surv Map:	
POD Rec No:	338183	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	12/31/1950, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	160	UTM Zone:	13
Depth of Water:	135	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415160.9
Pcw Rcv Da:		Northing:	3948148.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/19/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1733240.0
Static Lev:	0	Y:	1700593.0
Tract Nbr:		Point Y:	35.67356681
Map Nbr:		Point X:	-105.93746013
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
247	NW	0.73	3,839.50	7,001.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	96123	Surv Map:	
POD Rec No:	301877	Other Loc:	Dsf-05a
POD Basin:	RG	Zone :	
POD Suffix:	POD6	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415217.3
Pcw Rcv Da:		Northing:	3949907.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	06/17/2016, 12:00 AM	Latitude Second:	21.95
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	13.28
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68943032
Map Nbr:		Point X:	-105.9370224
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
248	NW	0.73	3,852.37	6,998.95	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	96123	Surv Map:	
POD Rec No:	301878	Other Loc:	Dsf-05b
POD Basin:	RG	Zone :	
POD Suffix:	POD7	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:	06/24/2016, 12:00 AM	Restrict :	0.0
Finish Date:	06/24/2016, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/17/2018, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	28	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415190.0
Pcw Rcv Da:		Northing:	3949887.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/19/2018, 12:00 AM	Latitude Second:	21.29
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	14.36
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68924767
Map Nbr:		Point X:	-105.93732198
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
249	ESE	0.73	3,876.16	7,219.21	WATER WELLS

License Nb:	1382	District Office S:	
POD No:	40884	Surv Map:	
POD Rec No:	15825	Other Loc:	1156 Camino Delora
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	10/31/1983, 12:00 AM	Restrict :	0.0
Finish Date:	10/31/1983, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	361	UTM Zone:	13
Depth of Water:	144	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	23	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417072.7
Pcw Rcv Da:		Northing:	3948467.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/05/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1739500.0
Static Lev:	0	Y:	1701722.0
Tract Nbr:		Point Y:	35.67661161
Map Nbr:		Point X:	-105.9163704
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
250	SSW	0.73	3,856.03	7,136.35	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31143	Surv Map:	
POD Rec No:	324797	Other Loc:	620 Barcelona Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0

Wells and Additional Sources Detail Report

POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	29 A SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415559.0
Pcw Rcv Da:		Northing:	3947881.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/18/2019, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Galisteo	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415559.0
Static Lev:	0	Y:	3947881.4
Tract Nbr:		Point Y:	35.67119752
Map Nbr:		Point X:	-105.93303373
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
251	W	0.74	3,892.19	7,006.15	WATER WELLS

License Nb:	0	District Office S:	
POD No:	71348	Surv Map:	
POD Rec No:	147732	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414805.0
Pcw Rcv Da:		Northing:	3948844.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/11/1999, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	591800.0
Static Lev:	0	Y:	1702800.0
Tract Nbr:		Point Y:	35.67981072
Map Nbr:		Point X:	-105.941466
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
253	SSW	0.73	3,874.11	7,136.35	WATER WELLS

License Nb:	228	District Office S:	
POD No:	35423	Surv Map:	
POD Rec No:	24157	Other Loc:	620 E. Barcelona Rd.
POD Basin:	RG	Zone :	C

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	29 A SF
Start Date:	01/16/1981, 12:00 AM	Restrict :	0.0
Finish Date:	01/17/1981, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	01/29/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	260	UTM Zone:	13
Depth of Water:	160	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415558.5
Pcw Rcv Da:		Northing:	3947876.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Galisteo	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734556.0
Static Lev:	0	Y:	1699719.0
Tract Nbr:		Point Y:	35.6711542
Map Nbr:		Point X:	-105.93303875
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
254	NW	0.74	3,890.76	6,992.45	WATER WELLS

License Nb:	228	District Office S:	
POD No:	50580	Surv Map:	
POD Rec No:	338891	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T1 SF
Start Date:	05/24/1989, 12:00 AM	Restrict :	0.0
Finish Date:	05/26/1989, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	06/05/1989, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	160	UTM Zone:	13
Depth of Water:	80	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	12	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415086.0
Pcw Rcv Da:		Northing:	3949794.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/16/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Zens	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6883994
Map Nbr:		Point X:	-105.93846142
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
255	S	0.74	3,889.65	7,189.20	WATER WELLS

License Nb:	228	District Office S:	
POD No:	50246	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	28075	Other Loc:	1021 Old Santa Fe Trail
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	64 3 U1 SF
Start Date:	04/27/1989, 12:00 AM	Restrict :	0.0
Finish Date:	05/03/1989, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	05/09/1989, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	440	UTM Zone:	13
Depth of Water:	110	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416080.3
Pcw Rcv Da:		Northing:	3947788.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/07/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736272.0
Static Lev:	0	Y:	1699450.0
Tract Nbr:		Point Y:	35.67039999
Map Nbr:		Point X:	-105.92726454
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Lot No. 64 Of Subdivision Number One Of De Vargas Development Co.		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
256	E	0.75	3,946.31	7,147.70	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	71076	Surv Map:	
POD Rec No:	146943	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417213.7
Pcw Rcv Da:		Northing:	3948935.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/13/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	599700.0
Static Lev:	0	Y:	1703200.0
Tract Nbr:		Point Y:	35.680839
Map Nbr:		Point X:	-105.91486061
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
257	NW	0.75	3,936.25	6,988.85	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	1664	District Office S:	
POD No:	96123	Surv Map:	
POD Rec No:	301875	Other Loc:	Dsf-03
POD Basin:	RG	Zone :	
POD Suffix:	POD4	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/25/2016, 12:00 AM	Restrict :	0.0
Finish Date:	06/26/2016, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/07/2018, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	36	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415023.6
Pcw Rcv Da:		Northing:	3949736.7
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/19/2018, 12:00 AM	Latitude Second:	16.36
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	20.92
Well Tag:		X:	0.0
Static Lev:	21	Y:	0.0
Tract Nbr:		Point Y:	35.68787745
Map Nbr:		Point X:	-105.93914492
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
258	WNW	0.75	3,962.37	6,988.38	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	95469	Surv Map:	
POD Rec No:	297677	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414819.1
Pcw Rcv Da:		Northing:	3949320.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	08/06/2015, 12:00 AM	Latitude Second:	2.8
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	28.9
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68411128
Map Nbr:		Point X:	-105.9413607
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
259	E	0.75	3,951.98	7,191.40	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	67989	Surv Map:	
POD Rec No:	80814	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	25	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417215.9
Pcw Rcv Da:		Northing:	3949102.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/02/1997, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	599700.0
Static Lev:	0	Y:	1703750.0
Tract Nbr:		Point Y:	35.68235014
Map Nbr:		Point X:	-105.91485355
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

259	E	0.75	3,951.98	7,191.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	67898	Surv Map:	
POD Rec No:	338069	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417215.9
Pcw Rcv Da:		Northing:	3949102.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	599700.0
Static Lev:	0	Y:	1703750.0
Tract Nbr:		Point Y:	35.68235014
Map Nbr:		Point X:	-105.91485355
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

260	WSW	0.75	3,940.75	7,041.17	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34747	Surv Map:	
POD Rec No:	28625	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414891.7
Pcw Rcv Da:		Northing:	3948477.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592100.0
Static Lev:	0	Y:	1701600.0
Tract Nbr:		Point Y:	35.67651142
Map Nbr:		Point X:	-105.94046921
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
260	WSW	0.75	3,940.75	7,041.17	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34748	Surv Map:	
POD Rec No:	333618	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414891.7
Pcw Rcv Da:		Northing:	3948477.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592100.0
Static Lev:	0	Y:	1701600.0
Tract Nbr:		Point Y:	35.67651142
Map Nbr:		Point X:	-105.94046921
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
261	WNW	0.75	3,980.89	6,987.64	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94330	Surv Map:	
POD Rec No:	287038	Other Loc:	Tbamw-06
POD Basin:	RG	Zone :	
POD Suffix:	POD6	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414817.7
Pcw Rcv Da:		Northing:	3949336.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	10/07/2013, 12:00 AM	Latitude Second:	3.3
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	28.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68425
Map Nbr:		Point X:	-105.9413778
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
262	E	0.76	3,991.16	7,157.17	WATER WELLS

License Nb:	253	District Office S:	
POD No:	13892	Surv Map:	
POD Rec No:	25832	Other Loc:	5 Camino Pequeno
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	12 T11 SF
Start Date:	05/10/1966, 12:00 AM	Restrict :	0.0
Finish Date:	05/25/1966, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	12/28/1966, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	30	UTM Zone:	13
Depth of Water:	6	UTM Accura:	
Ground Water Src:	A	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417228.2
Pcw Rcv Da:		Northing:	3948948.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/19/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1739990.0
Static Lev:	0	Y:	1703307.0
Tract Nbr:		Point Y:	35.68096192
Map Nbr:		Point X:	-105.91470178
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
264	SW	0.75	3,975.15	7,075.52	WATER WELLS

License Nb:	228	District Office S:	
POD No:	38562	Surv Map:	
POD Rec No:	33152	Other Loc:	326 B E. Coronado, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 18 SF
Start Date:	08/30/1982, 12:00 AM	Restrict :	0.0
Finish Date:	09/03/1982, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	09/27/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415039.1
Pcw Rcv Da:		Northing:	3948218.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/26/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ferdinand	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415039.1
Static Lev:	0	Y:	3948218.1
Tract Nbr:		Point Y:	35.67418829
Map Nbr:		Point X:	-105.93881324
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal: Parcel Number 1054098249246000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
265	SW	0.75	3,980.66	7,070.57	WATER WELLS

License Nb:	214	District Office S:	
POD No:	28575	Surv Map:	
POD Rec No:	65668	Other Loc:	318 East Coronado, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2A SF
Start Date:	05/16/1977, 12:00 AM	Restrict :	0.0
Finish Date:	05/17/1977, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	05/24/1977, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	224	UTM Zone:	13
Depth of Water:	130	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415006.6
Pcw Rcv Da:		Northing:	3948259.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/05/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ramona	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415006.6
Static Lev:	0	Y:	3948259.0
Tract Nbr:		Point Y:	35.67455421
Map Nbr:		Point X:	-105.93917664
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc:	Rio Grande
POD Sub Basin Desc:	Santa Fe River
Grant :	Santa Fe
Legal:	Parcel Number 1054098237260000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
266	S	0.75	3,978.04	7,169.49	WATER WELLS

License Nb:	622	District Office S:	
POD No:	33678	Surv Map:	
POD Rec No:	6470	Other Loc:	1006 Old Santa Fe Trail
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	82 SF
Start Date:	01/22/1980, 12:00 AM	Restrict :	0.0
Finish Date:	01/23/1980, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	01/30/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	460	UTM Zone:	13
Depth of Water:	70	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415811.7
Pcw Rcv Da:		Northing:	3947774.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/29/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	De Vargas Development Co.	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415811.7
Static Lev:	0	Y:	3947774.0
Tract Nbr:		Point Y:	35.67025088
Map Nbr:		Point X:	-105.93023061

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal: Parcel Number 1054098508109000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
267	E	0.76	4,029.71	7,209.12	WATER WELLS

License Nb:	214	District Office S:	
POD No:	35111	Surv Map:	
POD Rec No:	10548	Other Loc:	1241 Cerro Gordo Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1C SF
Start Date:	09/26/1980, 12:00 AM	Restrict :	0.0
Finish Date:	09/29/1980, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	10/28/1980, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	205	UTM Zone:	13
Depth of Water:	45	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	22	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417229.5
Pcw Rcv Da:		Northing:	3949199.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1739984.0
Static Lev:	0	Y:	1704131.0
Tract Nbr:		Point Y:	35.68322577

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.91471325
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Salvador Gonzales/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
268	W	0.77	4,058.97	6,996.51	WATER WELLS

License Nb:	0	District Office S:	
POD No:	46827	Surv Map:	
POD Rec No:	43641	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414746.0
Pcw Rcv Da:		Northing:	3948997.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/26/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	591600.0
Static Lev:	0	Y:	1703300.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.68118674
Map Nbr:		Point X:	-105.94213415
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
269	WSW	0.76	4,029.64	7,053.28	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35676	Surv Map:	
POD Rec No:	31617	Other Loc:	210 E Houghton St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	11** 8 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414899.5
Pcw Rcv Da:		Northing:	3948399.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/09/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Buena Vista Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1732372.0

Static Lev:	0	Y:	1701408.0
Tract Nbr:		Point Y:	35.67581342
Map Nbr:		Point X:	-105.94037483
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
270	SSW	0.76	4,035.57	7,106.57	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31218	Surv Map:	
POD Rec No:	325652	Other Loc:	1211 Old Pecos Trail
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	25 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415351.4
Pcw Rcv Da:		Northing:	3947923.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/17/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ramona	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:	NA	X:	415351.4
Static Lev:	0	Y:	3947923.0
Tract Nbr:		Point Y:	35.67155475
Map Nbr:		Point X:	-105.93533171
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
271	SSW	0.77	4,049.25	7,108.30	WATER WELLS

License Nb:	228	District Office S:	
POD No:	47331	Surv Map:	
POD Rec No:	30475	Other Loc:	1211 Old Pecos Trail
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	25 SF
Start Date:	05/06/1987, 12:00 AM	Restrict :	0.0
Finish Date:	05/10/1987, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	05/22/1987, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	320	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415362.0
Pcw Rcv Da:		Northing:	3947910.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/13/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ramona	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1733910.0
Static Lev:	0	Y:	1699823.0
Tract Nbr:		Point Y:	35.67144568
Map Nbr:		Point X:	-105.93521332
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
272	SSE	0.77	4,042.01	7,227.32	WATER WELLS

License Nb:	1310	District Office S:	
POD No:	70505	Surv Map:	
POD Rec No:	145138	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/28/1998, 12:00 AM	Restrict :	0.0
Finish Date:	12/04/1998, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/27/1999, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	420	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416437.6
Pcw Rcv Da:		Northing:	3947817.6
Sched Date:		Latitude Degree:	0
Use of Wel:	COND 9	Latitude Minute:	0
Sys Date:	04/29/1999, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597200.0
Static Lev:	0	Y:	1699500.0
Tract Nbr:		Point Y:	35.67069717
Map Nbr:		Point X:	-105.92332012
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
274	E	0.78	4,118.70	7,165.31	WATER WELLS

License Nb:	622	District Office S:	
POD No:	59674	Surv Map:	
POD Rec No:	19910	Other Loc:	1239 Canyon Rd
POD Basin:	RG	Zone :	C
POD Suffix:	X	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:	07/10/1994, 12:00 AM	Restrict :	0.0
Finish Date:	07/10/1994, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/01/1994, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	220	UTM Zone:	13
Depth of Water:	30	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417254.8
Pcw Rcv Da:		Northing:	3948829.8
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	07/13/2021, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417254.8
Static Lev:	0	Y:	3948829.8
Tract Nbr:		Point Y:	35.67989134
Map Nbr:		Point X:	-105.91439562
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098455453000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
275	SW	0.77	4,082.26	7,067.45	WATER WELLS

License Nb:	214	District Office S:	
POD No:	35870	Surv Map:	
POD Rec No:	5004	Other Loc:	302 E Coronado
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	F SF
Start Date:	03/25/1981, 12:00 AM	Restrict :	3.0
Finish Date:	03/27/1981, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	04/01/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	316	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414948.7
Pcw Rcv Da:		Northing:	3948287.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	11/10/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ramona	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1732538.0
Static Lev:	0	Y:	1701041.0
Tract Nbr:		Point Y:	35.67480345
Map Nbr:		Point X:	-105.93981934
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
276	WSW	0.78	4,103.21	7,027.97	WATER WELLS

License Nb:	0	District Office S:	
POD No:	42640	Surv Map:	
POD Rec No:	26776	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414801.5
Pcw Rcv Da:		Northing:	3948569.8
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	07/13/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	591800.0
Static Lev:	0	Y:	1701900.0
Tract Nbr:		Point Y:	35.67733844
Map Nbr:		Point X:	-105.94147563
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
277	WSW	0.78	4,120.13	7,053.80	WATER WELLS

License Nb:	539	District Office S:	
POD No:	51148	Surv Map:	
POD Rec No:	57187	Other Loc:	610 Don Gaspar Se
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/19/1989, 12:00 AM	Restrict :	0.0
Finish Date:	07/20/1989, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	07/09/1990, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	100	UTM Zone:	13
Depth of Water:	30	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-51148-/	Easting:	414878.0
Pcw Rcv Da:		Northing:	3948382.0

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/22/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67565199
Map Nbr:		Point X:	-105.94061051
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
277	WSW	0.78	4,120.13	7,053.80	WATER WELLS

License Nb:	228	District Office S:	
POD No:	08788	Surv Map:	
POD Rec No:	48503	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/12/1963, 12:00 AM	Restrict :	0.0
Finish Date:	04/18/1963, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	04/30/1963, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	82	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	414878.0

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3948382.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	04/19/2006, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67565199
Map Nbr:		Point X:	-105.94061051
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
278	WNW	0.79	4,177.39	6,980.32	WATER WELLS

License Nb:	0	District Office S:	
POD No:	95469	Surv Map:	
POD Rec No:	297679	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	414777.2
Pcw Rcv Da:		Northing:	3949410.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	08/06/2015, 12:00 AM	Latitude Second:	5.7
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	30.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68491633
Map Nbr:		Point X:	-105.9418332
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
279	E	0.79	4,186.17	7,169.13	WATER WELLS

License Nb:	622	District Office S:	
POD No:	59674	Surv Map:	
POD Rec No:	48012	Other Loc:	1239 Canyon Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:	07/12/1994, 12:00 AM	Restrict :	0.0
Finish Date:	07/12/1994, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/01/1994, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	220	UTM Zone:	13
Depth of Water:	60	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417274.6
Pcw Rcv Da:		Northing:	3948822.4
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	07/13/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417274.6
Static Lev:	0	Y:	3948822.4
Tract Nbr:		Point Y:	35.67982629
Map Nbr:		Point X:	-105.91417608
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:	Parcel Number 1055098455453000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
280	SSW	0.79	4,163.57	7,147.18	WATER WELLS

License Nb:	228	District Office S:	
POD No:	34909	Surv Map:	
POD Rec No:	54226	Other Loc:	635 Armenta St, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	34 SF
Start Date:	09/27/1980, 12:00 AM	Restrict :	0.0
Finish Date:	09/27/1980, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	10/15/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	80	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415621.1
Pcw Rcv Da:		Northing:	3947761.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/13/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415621.1
Static Lev:	0	Y:	3947761.1
Tract Nbr:		Point Y:	35.6701183
Map Nbr:		Point X:	-105.93233502
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1054098440098000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
281	S	0.79	4,155.04	7,202.19	WATER WELLS

License Nb:	548	District Office S:	
POD No:	57886	Surv Map:	
POD Rec No:	61848	Other Loc:	1047 Old Santa Fe Trail
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	63 2 SF
Start Date:	03/23/1995, 12:00 AM	Restrict :	0.0
Finish Date:	03/26/1995, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	04/06/1995, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	380	UTM Zone:	13
Depth of Water:	105	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	35	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416108.6
Pcw Rcv Da:		Northing:	3947708.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/06/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736368.0
Static Lev:	0	Y:	1699191.0
Tract Nbr:		Point Y:	35.66968748
Map Nbr:		Point X:	-105.92694362
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
282	SSW	0.79	4,172.52	7,121.11	WATER WELLS

License Nb:	1281	District Office S:	
POD No:	31271	Surv Map:	
POD Rec No:	15057	Other Loc:	555 Armenta St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	39 U2 SF
Start Date:	03/31/1995, 12:00 AM	Restrict :	0.0
Finish Date:	03/31/1995, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	07/19/1995, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	

Pump Seria:		XY Accuracy:	
Estimate Yield:	28	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415398.1
Pcw Rcv Da:		Northing:	3947848.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/01/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	De Vargas Development Co.	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734031.0
Static Lev:	0	Y:	1699620.0
Tract Nbr:		Point Y:	35.67088622
Map Nbr:		Point X:	-105.93480792
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
283	WNW	0.80	4,226.63	6,986.53	WATER WELLS

License Nb:	1210	District Office S:	
POD No:	98661	Surv Map:	
POD Rec No:	327416	Other Loc:	Sb-5
POD Basin:	RG	Zone :	
POD Suffix:	POD5	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/11/2020, 12:00 AM	Restrict :	0.0
Finish Date:	03/11/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/14/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	34	UTM Zone:	13
Depth of Water:	31	UTM Accura:	
Ground Water Src:	S	UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	1.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414733.0
Pcw Rcv Da:		Northing:	3949308.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/28/2021, 12:00 AM	Latitude Second:	2.37
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	32.32
Well Tag:	NA	X:	0.0
Static Lev:	31	Y:	0.0
Tract Nbr:		Point Y:	35.68399205
Map Nbr:		Point X:	-105.94231079
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
284	WNW	0.80	4,229.39	6,986.53	WATER WELLS

License Nb:	1210	District Office S:	
POD No:	98661	Surv Map:	
POD Rec No:	327417	Other Loc:	Sb-6
POD Basin:	RG	Zone :	
POD Suffix:	POD6	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/11/2020, 12:00 AM	Restrict :	0.0
Finish Date:	03/11/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/14/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	37	UTM Zone:	13
Depth of Water:	31	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	1.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414733.8
Pcw Rcv Da:		Northing:	3949316.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/28/2021, 12:00 AM	Latitude Second:	2.63
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	32.29
Well Tag:	NA	X:	0.0
Static Lev:	31	Y:	0.0
Tract Nbr:		Point Y:	35.68406424
Map Nbr:		Point X:	-105.9423028
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
285	WNW	0.80	4,231.46	6,986.03	WATER WELLS

License Nb:	1210	District Office S:	
POD No:	98661	Surv Map:	
POD Rec No:	327418	Other Loc:	Sb-7
POD Basin:	RG	Zone :	
POD Suffix:	POD7	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/11/2020, 12:00 AM	Restrict :	0.0
Finish Date:	03/11/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/14/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	32	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	31	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	1.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414734.9
Pcw Rcv Da:		Northing:	3949322.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/28/2021, 12:00 AM	Latitude Second:	2.83
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	32.25
Well Tag:	NA	X:	0.0
Static Lev:	31	Y:	0.0
Tract Nbr:		Point Y:	35.68411933
Map Nbr:		Point X:	-105.94229129
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
286	WNW	0.80	4,241.46	6,986.09	WATER WELLS

License Nb:	1210	District Office S:	
POD No:	98661	Surv Map:	
POD Rec No:	327419	Other Loc:	Sb-8
POD Basin:	RG	Zone :	
POD Suffix:	POD8	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/12/2020, 12:00 AM	Restrict :	0.0
Finish Date:	03/12/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/14/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD

Wells and Additional Sources Detail Report

Depth of Well:	38	UTM Zone:	13
Depth of Water:	31	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	1.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414732.9
Pcw Rcv Da:		Northing:	3949328.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/28/2021, 12:00 AM	Latitude Second:	3.02
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	32.33
Well Tag:	NA	X:	0.0
Static Lev:	31	Y:	0.0
Tract Nbr:		Point Y:	35.68417235
Map Nbr:		Point X:	-105.94231402
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
287	SW	0.80	4,215.43	7,085.47	WATER WELLS

License Nb:	641	District Office S:	
POD No:	35285	Surv Map:	
POD Rec No:	44048	Other Loc:	300 E Barcelona
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 NA U1TA SF
Start Date:	11/10/1980, 12:00 AM	Restrict :	0.0
Finish Date:	11/11/1980, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	03/24/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	5	UTM Source:	EA
Depth of Well:	280	UTM Zone:	13
Depth of Water:	90	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415165.2
Pcw Rcv Da:		Northing:	3947987.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/01/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Lovato Grant	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1733261.0
Static Lev:	0	Y:	1700065.0
Tract Nbr:		Point Y:	35.67211573
Map Nbr:		Point X:	-105.93739565
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
288	WNW	0.81	4,262.03	6,985.50	WATER WELLS

License Nb:	1210	District Office S:	
POD No:	98661	Surv Map:	
POD Rec No:	327413	Other Loc:	Sb-3
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/12/2020, 12:00 AM	Restrict :	0.0
Finish Date:	03/22/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/14/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	32	UTM Zone:	13
Depth of Water:	31	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	1.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414725.6
Pcw Rcv Da:		Northing:	3949324.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/28/2021, 12:00 AM	Latitude Second:	2.9
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	32.62
Well Tag:	NA	X:	0.0
Static Lev:	31	Y:	0.0
Tract Nbr:		Point Y:	35.68413926
Map Nbr:		Point X:	-105.9423943
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
289	WNW	0.81	4,264.22	6,985.13	WATER WELLS

License Nb:	1210	District Office S:	
POD No:	98661	Surv Map:	
POD Rec No:	327415	Other Loc:	Sb-4
POD Basin:	RG	Zone :	
POD Suffix:	POD4	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/12/2020, 12:00 AM	Restrict :	0.0
Finish Date:	03/12/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/14/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	36	UTM Zone:	13
Depth of Water:	31	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	1.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414726.7
Pcw Rcv Da:		Northing:	3949331.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/28/2021, 12:00 AM	Latitude Second:	3.12
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	32.58
Well Tag:	NA	X:	0.0
Static Lev:	31	Y:	0.0
Tract Nbr:		Point Y:	35.68419976
Map Nbr:		Point X:	-105.94238286
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
290	NNW	0.80	4,224.47	7,023.42	WATER WELLS

License Nb:	228	District Office S:	
POD No:	29522	Surv Map:	
POD Rec No:	18487	Other Loc:	311 Bishop Lodge Rd, Sf
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/17/1977, 12:00 AM	Restrict :	0.0
Finish Date:	11/18/1977, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	11/29/1977, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	240	UTM Zone:	13
Depth of Water:	75	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415301.2
Pcw Rcv Da:		Northing:	3950116.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/17/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	593375.0
Static Lev:	0	Y:	1706997.0
Tract Nbr:		Point Y:	35.69132803
Map Nbr:		Point X:	-105.93611734
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
291	SSW	0.80	4,226.94	7,129.31	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35302	Surv Map:	
POD Rec No:	54726	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415462.2
Pcw Rcv Da:		Northing:	3947799.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/27/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594000.0
Static Lev:	0	Y:	1699400.0
Tract Nbr:		Point Y:	35.67045088
Map Nbr:		Point X:	-105.93409459
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
292	SSW	0.80	4,227.77	7,125.77	WATER WELLS

License Nb:	622	District Office S:	
POD No:	42637	Surv Map:	
POD Rec No:	13817	Other Loc:	575 Armenta St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	38 SF
Start Date:	10/04/1984, 12:00 AM	Restrict :	0.0
Finish Date:	10/05/1984, 12:00 AM	Section:	25
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:	10/11/1984, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	360	UTM Zone:	13
Depth of Water:	120	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	35	Lat Lon SO:	
Casing Size:	5.6	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415435.1
Pcw Rcv Da:		Northing:	3947812.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/18/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734154.0
Static Lev:	0	Y:	1699502.0
Tract Nbr:		Point Y:	35.67056124
Map Nbr:		Point X:	-105.93439531
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
293	WNW	0.81	4,283.56	6,984.50	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	252205	Other Loc:	Cerrillos Galisteo & Montezuma
POD Basin:	RG	Zone :	
POD Suffix:	POD11	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414723.5
Pcw Rcv Da:		Northing:	3949341.8
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	02/25/2010, 12:00 AM	Latitude Second:	3.45
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	32.71
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68429144
Map Nbr:		Point X:	-105.9424193
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
294	WNW	0.81	4,285.99	6,985.37	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336462	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD75	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414717.1
Pcw Rcv Da:		Northing:	3949318.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731735.0
Static Lev:	0	Y:	1704415.0
Tract Nbr:		Point Y:	35.68407993
Map Nbr:		Point X:	-105.94248754
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
295	WNW	0.81	4,291.34	6,985.37	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336460	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD73	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414715.6
Pcw Rcv Da:		Northing:	3949321.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731730.0
Static Lev:	0	Y:	1704424.0
Tract Nbr:		Point Y:	35.68410504
Map Nbr:		Point X:	-105.94250441
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
296	WNW	0.81	4,294.68	6,984.50	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336461	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD74	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414713.8
Pcw Rcv Da:		Northing:	3949318.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731724.0
Static Lev:	0	Y:	1704414.0
Tract Nbr:		Point Y:	35.68407784
Map Nbr:		Point X:	-105.94252398
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
298	WNW	0.82	4,314.89	6,984.50	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336463	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD76	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414709.9
Pcw Rcv Da:		Northing:	3949325.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731711.0
Static Lev:	0	Y:	1704439.0
Tract Nbr:		Point Y:	35.68414602
Map Nbr:		Point X:	-105.94256788
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
299	WNW	0.82	4,319.44	6,984.41	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336464	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD77	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0

Wells and Additional Sources Detail Report

POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414708.4
Pcw Rcv Da:		Northing:	3949328.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731706.0
Static Lev:	0	Y:	1704449.0
Tract Nbr:		Point Y:	35.68417383
Map Nbr:		Point X:	-105.94258478
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
300	WNW	0.82	4,323.56	6,983.64	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336465	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD78	BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PLG	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:	05/03/2022, 12:00 AM	Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414706.8
Pcw Rcv Da:		Northing:	3949325.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731701.0
Static Lev:	0	Y:	1704439.0
Tract Nbr:		Point Y:	35.68414665
Map Nbr:		Point X:	-105.94260215
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
301	WNW	0.82	4,326.54	6,984.41	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	252443	Other Loc:	Cerrillos Galisteo & Montezuma
POD Basin:	RG	Zone :	

Wells and Additional Sources Detail Report

POD Suffix:	POD12	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414708.3
Pcw Rcv Da:		Northing:	3949334.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	03/04/2010, 12:00 AM	Latitude Second:	3.2
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	33.31
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68422251
Map Nbr:		Point X:	-105.94258646
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
302	S	0.81	4,275.97	7,202.09	WATER WELLS

License Nb:	0	District Office S:	
POD No:	71142	Surv Map:	
POD Rec No:	147121	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416070.0
Pcw Rcv Da:		Northing:	3947669.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/28/1998, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596000.0
Static Lev:	0	Y:	1699000.0
Tract Nbr:		Point Y:	35.66933441
Map Nbr:		Point X:	-105.92736602
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
303	WNW	0.82	4,332.76	6,984.39	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91565	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	251645	Other Loc:	Corner Of Cerrillos &Montezuma
POD Basin:	RG	Zone :	
POD Suffix:	POD10	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414710.5
Pcw Rcv Da:		Northing:	3949352.4
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	02/15/2010, 12:00 AM	Latitude Second:	3.79
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	33.23
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68438587
Map Nbr:		Point X:	-105.94256407
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
304	WNW	0.82	4,333.89	6,983.68	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	A0441	Surv Map:	
POD Rec No:	336466	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD79	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414704.7
Pcw Rcv Da:		Northing:	3949328.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731694.0
Static Lev:	0	Y:	1704447.0
Tract Nbr:		Point Y:	35.6841681
Map Nbr:		Point X:	-105.94262561
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
305	SSW	0.81	4,300.73	7,154.65	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	228	District Office S:	
POD No:	37185	Surv Map:	
POD Rec No:	41531	Other Loc:	1303 Camino Corrales
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	91 3 U2 SF
Start Date:	05/15/1982, 12:00 AM	Restrict :	0.0
Finish Date:	05/17/1982, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	07/14/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	320	UTM Zone:	13
Depth of Water:	186	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415729.8
Pcw Rcv Da:		Northing:	3947688.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/08/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735126.0
Static Lev:	0	Y:	1699110.0
Tract Nbr:		Point Y:	35.66947579
Map Nbr:		Point X:	-105.93112652
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
306	SSE	0.81	4,295.81	7,213.09	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	547	District Office S:	
POD No:	65135	Surv Map:	
POD Rec No:	37909	Other Loc:	1050 Camino Rancheros
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	64 2-4 SF
Start Date:	08/24/1998, 12:00 AM	Restrict :	0.0
Finish Date:	08/25/1998, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/31/1998, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	380	UTM Zone:	13
Depth of Water:	168	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	7	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416267.8
Pcw Rcv Da:		Northing:	3947688.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/22/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416267.8
Static Lev:	0	Y:	3947688.3
Tract Nbr:		Point Y:	35.6695171
Map Nbr:		Point X:	-105.92518265
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098121066000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
307	SSW	0.82	4,307.72	7,139.39	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	51490	Surv Map:	
POD Rec No:	28666	Other Loc:	662 Armenta St, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	92 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415552.8
Pcw Rcv Da:		Northing:	3947737.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/06/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Developement Co #2	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594300.0
Static Lev:	0	Y:	1699200.0
Tract Nbr:		Point Y:	35.66989879
Map Nbr:		Point X:	-105.93308712
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

309	WNW	0.83	4,366.97	6,983.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336467	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD80	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414695.7
Pcw Rcv Da:		Northing:	3949334.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731664.0
Static Lev:	0	Y:	1704467.0
Tract Nbr:		Point Y:	35.68422322
Map Nbr:		Point X:	-105.94272571
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

310	WNW	0.83	4,371.07	6,983.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336468	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD81	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414693.2
Pcw Rcv Da:		Northing:	3949332.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731656.0
Static Lev:	0	Y:	1704460.0
Tract Nbr:		Point Y:	35.68420407
Map Nbr:		Point X:	-105.94275312
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
311	WNW	0.83	4,372.75	6,983.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	251627	Other Loc:	Corner Of Cerrillos &Montezuma
POD Basin:	RG	Zone :	
POD Suffix:	POD9	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414693.5
Pcw Rcv Da:		Northing:	3949333.8
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	02/15/2010, 12:00 AM	Latitude Second:	3.18
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	33.9
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68421672
Map Nbr:		Point X:	-105.94274995
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
312	WNW	0.83	4,399.85	6,983.07	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336426	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD39	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414690.1
Pcw Rcv Da:		Northing:	3949353.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731645.0
Static Lev:	0	Y:	1704530.0
Tract Nbr:		Point Y:	35.68439673
Map Nbr:		Point X:	-105.94278964
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
313	WNW	0.83	4,405.61	6,983.07	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	252445	Other Loc:	Corner Of Cerrillos &Montezuma
POD Basin:	RG	Zone :	
POD Suffix:	POD13	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414688.4
Pcw Rcv Da:		Northing:	3949354.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	03/04/2010, 12:00 AM	Latitude Second:	3.85
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	34.11
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68440289
Map Nbr:		Point X:	-105.9428085
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant :

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
314	WNW	0.84	4,409.93	6,983.06	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336423	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD36	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414689.3
Pcw Rcv Da:		Northing:	3949362.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731642.0
Static Lev:	0	Y:	1704559.0
Tract Nbr:		Point Y:	35.68447689
Map Nbr:		Point X:	-105.94279942
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
315	WNW	0.84	4,412.06	6,983.07	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336424	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD37	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414687.7
Pcw Rcv Da:		Northing:	3949358.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731637.0
Static Lev:	0	Y:	1704544.0
Tract Nbr:		Point Y:	35.68443529
Map Nbr:		Point X:	-105.94281662
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
316	WNW	0.84	4,413.41	6,982.81	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336413	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD26	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414691.9
Pcw Rcv Da:		Northing:	3949377.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731650.0
Static Lev:	0	Y:	1704606.0
Tract Nbr:		Point Y:	35.68460604
Map Nbr:		Point X:	-105.94277221

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
317	WNW	0.84	4,414.25	6,983.07	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336425	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD38	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414685.9
Pcw Rcv Da:		Northing:	3949353.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731631.0
Static Lev:	0	Y:	1704530.0
Tract Nbr:		Point Y:	35.68439727

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.94283606
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
318	WNW	0.84	4,413.57	6,981.80	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	91556	Surv Map:	
POD Rec No:	248174	Other Loc:	328 Galisteo
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/11/2009, 12:00 AM	Restrict :	0.0
Finish Date:	07/11/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/27/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	40	UTM Zone:	13
Depth of Water:	30	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414696.3
Pcw Rcv Da:		Northing:	3949390.8
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/05/2018, 12:00 AM	Latitude Second:	5.03
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	33.81
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.68473083
Map Nbr:		Point X:	-105.94272505
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
319	WNW	0.84	4,419.25	6,982.39	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336415	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD28	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414688.2
Pcw Rcv Da:		Northing:	3949370.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731638.0

Static Lev:	0	Y:	1704584.0
Tract Nbr:		Point Y:	35.68454531
Map Nbr:		Point X:	-105.94281239
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
320	WNW	0.84	4,420.61	6,982.39	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	91555	Surv Map:	
POD Rec No:	248121	Other Loc:	328 Galisteo
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/11/2009, 12:00 AM	Restrict :	0.0
Finish Date:	07/11/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/27/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	40	UTM Zone:	13
Depth of Water:	30	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414688.4
Pcw Rcv Da:		Northing:	3949374.2
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/05/2018, 12:00 AM	Latitude Second:	4.49
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	34.12

Wells and Additional Sources Detail Report

Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68458049
Map Nbr:		Point X:	-105.94281059
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
320	WNW	0.84	4,420.61	6,982.39	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336414	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD27	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414689.8
Pcw Rcv Da:		Northing:	3949374.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731643.0
Static Lev:	0	Y:	1704597.0
Tract Nbr:		Point Y:	35.68458061
Map Nbr:		Point X:	-105.94279512
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
321	WNW	0.84	4,421.29	6,983.06	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336416	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD29	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414686.3
Pcw Rcv Da:		Northing:	3949366.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731632.0
Static Lev:	0	Y:	1704571.0
Tract Nbr:		Point Y:	35.68450999
Map Nbr:		Point X:	-105.94283297
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
322	S	0.83	4,369.08	7,185.95	WATER WELLS

License Nb:	228	District Office S:	
POD No:	29552	Surv Map:	
POD Rec No:	6899	Other Loc:	1014 Old Santa Fe Trail, Sf
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	85 T1 SF
Start Date:	01/09/1978, 12:00 AM	Restrict :	0.0
Finish Date:	01/14/1978, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	01/20/1978, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	500	UTM Zone:	13
Depth of Water:	200	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415946.3
Pcw Rcv Da:		Northing:	3947641.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/12/2021, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:	De Vargas Development Co.	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415946.3
Static Lev:	0	Y:	3947641.0
Tract Nbr:		Point Y:	35.66906333
Map Nbr:		Point X:	-105.92872964
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098027066000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
323	WNW	0.84	4,423.39	6,983.06	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336417	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD30	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414684.8
Pcw Rcv Da:		Northing:	3949362.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731627.0
Static Lev:	0	Y:	1704557.0
Tract Nbr:		Point Y:	35.6844711
Map Nbr:		Point X:	-105.94284909
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
324	WNW	0.84	4,425.55	6,983.07	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336418	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD31	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414682.9
Pcw Rcv Da:		Northing:	3949357.9
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731621.0
Static Lev:	0	Y:	1704543.0
Tract Nbr:		Point Y:	35.68443307
Map Nbr:		Point X:	-105.94286964
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
325	WNW	0.84	4,426.82	6,982.03	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336403	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD16	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414690.2
Pcw Rcv Da:		Northing:	3949386.4

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731644.0
Static Lev:	0	Y:	1704637.0
Tract Nbr:		Point Y:	35.68469063
Map Nbr:		Point X:	-105.94279199
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
326	WNW	0.84	4,427.76	6,982.12	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336419	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD32	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414681.0

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3949353.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731615.0
Static Lev:	0	Y:	1704529.0
Tract Nbr:		Point Y:	35.68439414
Map Nbr:		Point X:	-105.94289017
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
327	WNW	0.84	4,428.69	6,982.03	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336404	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD17	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	414688.4
Pcw Rcv Da:		Northing:	3949382.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731638.0
Static Lev:	0	Y:	1704623.0
Tract Nbr:		Point Y:	35.68465261
Map Nbr:		Point X:	-105.94281144
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
328	WNW	0.84	4,428.77	6,982.03	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	251074	Other Loc:	328 Galisteo/Cerrillos-Montzum
POD Basin:	RG	Zone :	
POD Suffix:	POD 8	BLK:	
Pod Sub Ba:	NRG	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414690.8
Pcw Rcv Da:		Northing:	3949389.0
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	02/02/2010, 12:00 AM	Latitude Second:	4.97
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	34.03
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68471412
Map Nbr:		Point X:	-105.94278564
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
329	WNW	0.84	4,430.90	6,982.12	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336420	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD33	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414679.1
Pcw Rcv Da:		Northing:	3949349.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731609.0
Static Lev:	0	Y:	1704515.0
Tract Nbr:		Point Y:	35.68435611
Map Nbr:		Point X:	-105.94291072
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
330	WNW	0.84	4,430.83	6,983.06	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	251072	Other Loc:	328 Galisteo/Cerrillos-Montzum
POD Basin:	RG	Zone :	
POD Suffix:	POD 7	BLK:	
Pod Sub Ba:	NRG	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414684.0
Pcw Rcv Da:		Northing:	3949367.8
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	02/02/2010, 12:00 AM	Latitude Second:	4.28
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	34.29
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68452241
Map Nbr:		Point X:	-105.94285853
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
331	WNW	0.84	4,430.61	6,982.39	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336405	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD18	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PLG	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:	05/10/2022, 12:00 AM	Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414686.5
Pcw Rcv Da:		Northing:	3949377.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731632.0
Static Lev:	0	Y:	1704609.0
Tract Nbr:		Point Y:	35.68461368
Map Nbr:		Point X:	-105.94283198
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
332	WNW	0.84	4,432.68	6,982.10	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	246533	Other Loc:	218 Montezuma, Santa Fe, Nm
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/10/2009, 12:00 AM	Restrict :	0.0
Finish Date:	02/10/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/27/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	40	UTM Zone:	13
Depth of Water:	30	UTM Accura:	
Ground Water Src:	S	UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414676.2
Pcw Rcv Da:		Northing:	3949340.7
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/05/2018, 12:00 AM	Latitude Second:	3.4
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	34.59
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68427743
Map Nbr:		Point X:	-105.94294185
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
332	WNW	0.84	4,432.68	6,982.10	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336422	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD35	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414676.3
Pcw Rcv Da:		Northing:	3949341.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731600.0
Static Lev:	0	Y:	1704489.0
Tract Nbr:		Point Y:	35.68428465
Map Nbr:		Point X:	-105.94294083
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
333	WNW	0.84	4,433.21	6,982.10	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336421	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD34	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414677.5
Pcw Rcv Da:		Northing:	3949345.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731604.0
Static Lev:	0	Y:	1704501.0
Tract Nbr:		Point Y:	35.68431721
Map Nbr:		Point X:	-105.94292795
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
334	WNW	0.84	4,433.10	6,982.19	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	91554	Surv Map:	
POD Rec No:	246471	Other Loc:	328 Galisteo, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/11/2009, 12:00 AM	Restrict :	0.0
Finish Date:	07/11/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/27/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA

Wells and Additional Sources Detail Report

Depth of Well:	45	UTM Zone:	13
Depth of Water:	30	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414681.2
Pcw Rcv Da:		Northing:	3949359.8
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/05/2018, 12:00 AM	Latitude Second:	4.02
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	34.4
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68445005
Map Nbr:		Point X:	-105.94288862
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
335	WNW	0.84	4,433.52	6,982.39	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336406	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD19	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414684.9
Pcw Rcv Da:		Northing:	3949373.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731627.0
Static Lev:	0	Y:	1704595.0
Tract Nbr:		Point Y:	35.68457568
Map Nbr:		Point X:	-105.94284921
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
336	WNW	0.84	4,435.54	6,982.39	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336407	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD20	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414683.0
Pcw Rcv Da:		Northing:	3949369.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731621.0
Static Lev:	0	Y:	1704582.0
Tract Nbr:		Point Y:	35.68454036
Map Nbr:		Point X:	-105.94286979
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
337	WNW	0.84	4,438.18	6,982.46	WATER WELLS

License Nb:	1210	District Office S:	
POD No:	98661	Surv Map:	
POD Rec No:	327422	Other Loc:	Sb-11
POD Basin:	RG	Zone :	
POD Suffix:	POD11	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/18/2020, 12:00 AM	Restrict :	0.0
Finish Date:	03/18/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/14/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	90	UTM Zone:	13
Depth of Water:	31	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414669.5
Pcw Rcv Da:		Northing:	3949321.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/28/2021, 12:00 AM	Latitude Second:	2.76
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	34.85
Well Tag:	NA	X:	0.0
Static Lev:	31	Y:	0.0
Tract Nbr:		Point Y:	35.68410015
Map Nbr:		Point X:	-105.9430138
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
338	WNW	0.84	4,437.62	6,982.19	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336408	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD21	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PLG	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:	05/10/2022, 12:00 AM	Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414681.1
Pcw Rcv Da:		Northing:	3949365.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731615.0
Static Lev:	0	Y:	1704568.0
Tract Nbr:		Point Y:	35.68450143
Map Nbr:		Point X:	-105.94289033
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
339	WNW	0.84	4,439.11	6,982.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336447	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD60	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414667.0
Pcw Rcv Da:		Northing:	3949310.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731571.0
Static Lev:	0	Y:	1704387.0
Tract Nbr:		Point Y:	35.68400437
Map Nbr:		Point X:	-105.9430403
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
340	SW	0.83	4,399.48	7,057.82	WATER WELLS

License Nb:	622	District Office S:	
POD No:	35864	Surv Map:	
POD Rec No:	12807	Other Loc:	115 Valencia Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	6A TJ SF
Start Date:	04/19/1981, 12:00 AM	Restrict :	0.0
Finish Date:	04/19/1981, 12:00 AM	Section:	25
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:	05/04/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	260	UTM Zone:	13
Depth of Water:	82	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414870.9
Pcw Rcv Da:		Northing:	3948228.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/21/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ramona	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1732285.0
Static Lev:	0	Y:	1700846.0
Tract Nbr:		Point Y:	35.67427025
Map Nbr:		Point X:	-105.94067275
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
341	WNW	0.84	4,439.75	6,982.19	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336409	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD22	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414679.3
Pcw Rcv Da:		Northing:	3949361.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731609.0
Static Lev:	0	Y:	1704554.0
Tract Nbr:		Point Y:	35.68446341
Map Nbr:		Point X:	-105.94290978
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
342	WNW	0.84	4,441.93	6,982.12	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336410	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD23	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414677.7
Pcw Rcv Da:		Northing:	3949357.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731604.0
Static Lev:	0	Y:	1704540.0
Tract Nbr:		Point Y:	35.6844245
Map Nbr:		Point X:	-105.942927
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
343	WNW	0.84	4,442.16	6,981.37	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336402	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD15	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PLG	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:	05/09/2022, 12:00 AM	Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414686.9
Pcw Rcv Da:		Northing:	3949390.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731633.0
Static Lev:	0	Y:	1704650.0
Tract Nbr:		Point Y:	35.68472641
Map Nbr:		Point X:	-105.94282888
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
344	WNW	0.84	4,445.55	6,982.56	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336448	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD61	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414663.9
Pcw Rcv Da:		Northing:	3949306.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731561.0
Static Lev:	0	Y:	1704375.0
Tract Nbr:		Point Y:	35.68397165
Map Nbr:		Point X:	-105.94307417
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
345	WNW	0.84	4,443.99	6,982.03	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336401	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD14	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PLG	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:	05/09/2022, 12:00 AM	Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414685.1
Pcw Rcv Da:		Northing:	3949386.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731627.0
Static Lev:	0	Y:	1704636.0
Tract Nbr:		Point Y:	35.68468839
Map Nbr:		Point X:	-105.94284833
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
346	WNW	0.84	4,444.04	6,982.03	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91765	Surv Map:	
POD Rec No:	249128	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/28/2009, 12:00 AM	Restrict :	0.0
Finish Date:	02/28/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/17/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	47	UTM Zone:	13
Depth of Water:	33	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414686.0
Pcw Rcv Da:		Northing:	3949389.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/29/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731629.8
Static Lev:	0	Y:	1704648.2
Tract Nbr:		Point Y:	35.68472182
Map Nbr:		Point X:	-105.94283877
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
347	WNW	0.84	4,445.05	6,982.12	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336411	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD24	BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414675.8
Pcw Rcv Da:		Northing:	3949352.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731598.0
Static Lev:	0	Y:	1704526.0
Tract Nbr:		Point Y:	35.68438648
Map Nbr:		Point X:	-105.94294755
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
348	NW	0.84	4,425.52	6,981.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	70214	Surv Map:	
POD Rec No:	145440	Other Loc:	
POD Basin:	RG	Zone :	C

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/30/1750, 12:00 AM	Restrict :	0.0
Finish Date:	06/30/1750, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	45	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414878.0
Pcw Rcv Da:		Northing:	3949787.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/11/1998, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592000.0
Static Lev:	0	Y:	1705900.0
Tract Nbr:		Point Y:	35.68832647
Map Nbr:		Point X:	-105.94075929
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
349	WNW	0.84	4,445.89	6,982.16	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91765	Surv Map:	
POD Rec No:	249127	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/28/2009, 12:00 AM	Restrict :	0.0
Finish Date:	02/28/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/17/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	47	UTM Zone:	13
Depth of Water:	33	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414682.0
Pcw Rcv Da:		Northing:	3949378.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/29/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731617.3
Static Lev:	0	Y:	1704612.0
Tract Nbr:		Point Y:	35.68462231
Map Nbr:		Point X:	-105.94288181
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
350	WNW	0.84	4,445.88	6,982.03	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	336400	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD13	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414683.2
Pcw Rcv Da:		Northing:	3949381.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731621.0
Static Lev:	0	Y:	1704622.0
Tract Nbr:		Point Y:	35.68464946
Map Nbr:		Point X:	-105.94286887
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
351	WNW	0.84	4,447.33	6,981.48	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	A0441	Surv Map:	
POD Rec No:	336412	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD25	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414673.9
Pcw Rcv Da:		Northing:	3949348.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731592.0
Static Lev:	0	Y:	1704512.0
Tract Nbr:		Point Y:	35.68434755
Map Nbr:		Point X:	-105.94296809
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
352	WNW	0.84	4,447.81	6,982.16	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336399	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD12	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414681.3
Pcw Rcv Da:		Northing:	3949377.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731615.0
Static Lev:	0	Y:	1704608.0
Tract Nbr:		Point Y:	35.68461143
Map Nbr:		Point X:	-105.94288942
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
353	S	0.83	4,394.38	7,202.42	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	622	District Office S:	
POD No:	41134	Surv Map:	
POD Rec No:	17464	Other Loc:	1020 Old Santa Fe Trail
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	84 1 SF
Start Date:	08/23/1984, 12:00 AM	Restrict :	0.0
Finish Date:	08/24/1984, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/29/1984, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	440	UTM Zone:	13
Depth of Water:	109	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416061.3
Pcw Rcv Da:		Northing:	3947633.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/06/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736216.0
Static Lev:	0	Y:	1698941.0
Tract Nbr:		Point Y:	35.66900191
Map Nbr:		Point X:	-105.9274583
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
354	WNW	0.84	4,449.81	6,982.16	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336398	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD11	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414679.7
Pcw Rcv Da:		Northing:	3949373.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731610.0
Static Lev:	0	Y:	1704594.0
Tract Nbr:		Point Y:	35.68457253
Map Nbr:		Point X:	-105.94290664
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

355	WNW	0.84	4,449.90	6,982.16	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336397	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD10	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414678.1
Pcw Rcv Da:		Northing:	3949369.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731605.0
Static Lev:	0	Y:	1704582.0
Tract Nbr:		Point Y:	35.68453993
Map Nbr:		Point X:	-105.94292394
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

356	WNW	0.84	4,450.94	6,982.19	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91765	Surv Map:	
POD Rec No:	249126	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/28/2009, 12:00 AM	Restrict :	0.0
Finish Date:	02/28/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/17/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	42	UTM Zone:	13
Depth of Water:	33	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414677.8
Pcw Rcv Da:		Northing:	3949367.9
Sched Date:		Latitude Degree:	0
Use of Wel:	EXP	Latitude Minute:	0
Sys Date:	12/29/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731603.9
Static Lev:	0	Y:	1704575.8
Tract Nbr:		Point Y:	35.68452278
Map Nbr:		Point X:	-105.94292705
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
357	WNW	0.84	4,452.23	6,979.84	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	91557	Surv Map:	
POD Rec No:	248173	Other Loc:	320 Galisteo
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/20/2009, 12:00 AM	Restrict :	0.0
Finish Date:	07/20/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/27/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	45	UTM Zone:	13
Depth of Water:	34	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414691.8
Pcw Rcv Da:		Northing:	3949417.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/05/2018, 12:00 AM	Latitude Second:	5.89
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	34.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68496934
Map Nbr:		Point X:	-105.94277759
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
358	WNW	0.84	4,454.13	6,982.19	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336395	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD8	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414674.4
Pcw Rcv Da:		Northing:	3949361.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731593.0
Static Lev:	0	Y:	1704553.0
Tract Nbr:		Point Y:	35.68446028
Map Nbr:		Point X:	-105.94296389
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
359	WNW	0.84	4,454.87	6,982.19	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336396	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD9	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414675.9
Pcw Rcv Da:		Northing:	3949365.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731598.0
Static Lev:	0	Y:	1704566.0
Tract Nbr:		Point Y:	35.68449647
Map Nbr:		Point X:	-105.94294774
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant :

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
360	WNW	0.84	4,457.10	6,982.56	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336449	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD62	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414659.3
Pcw Rcv Da:		Northing:	3949302.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731546.0
Static Lev:	0	Y:	1704359.0
Tract Nbr:		Point Y:	35.68392798
Map Nbr:		Point X:	-105.94312449
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
361	WNW	0.84	4,456.33	6,981.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336394	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD7	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414672.5
Pcw Rcv Da:		Northing:	3949356.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731587.0
Static Lev:	0	Y:	1704539.0
Tract Nbr:		Point Y:	35.68442225
Map Nbr:		Point X:	-105.94298444
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
362	ENE	0.84	4,433.48	7,221.20	WATER WELLS

License Nb:	228	District Office S:	
POD No:	43193	Surv Map:	
POD Rec No:	22249	Other Loc:	1298 Lejano Ln, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	15 NA U5 SF
Start Date:	06/05/1985, 12:00 AM	Restrict :	0.0
Finish Date:		Section:	19
Plug Date:		Township:	17N
Log File D:	07/17/1985, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	120	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417309.6
Pcw Rcv Da:		Northing:	3949409.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Valle Lejano	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417309.6
Static Lev:	0	Y:	3949409.7
Tract Nbr:		Point Y:	35.68512389
Map Nbr:		Point X:	-105.91384972

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Salvador Gonzales/Santa Fe
Legal: Parcel Number 1055099442074000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
363	WNW	0.85	4,461.66	6,980.96	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91765	Surv Map:	
POD Rec No:	249129	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD4	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/28/2009, 12:00 AM	Restrict :	0.0
Finish Date:	02/28/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/17/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	47	UTM Zone:	13
Depth of Water:	33	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414684.3
Pcw Rcv Da:		Northing:	3949402.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/29/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731623.8
Static Lev:	0	Y:	1704690.9
Tract Nbr:		Point Y:	35.68483887

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.94285894
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
364	WNW	0.85	4,464.63	6,982.44	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336453	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD66	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414660.1
Pcw Rcv Da:		Northing:	3949313.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731548.0
Static Lev:	0	Y:	1704396.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.68402992
Map Nbr:		Point X:	-105.94311685
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
365	WNW	0.85	4,464.35	6,981.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	248056	Other Loc:	210 & 218 Montezuma Corner
POD Basin:	RG	Zone :	
POD Suffix:	POD 3	BLK:	
Pod Sub Ba:	NRG	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414669.5
Pcw Rcv Da:		Northing:	3949352.2
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	05/29/2014, 12:00 AM	Latitude Second:	3.77
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	34.86
Well Tag:		X:	0.0

Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68438052
Map Nbr:		Point X:	-105.9430171
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
366	WNW	0.85	4,465.81	6,982.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336450	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD63	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414655.6
Pcw Rcv Da:		Northing:	3949297.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:	NA	X:	1731534.0
Static Lev:	0	Y:	1704345.0
Tract Nbr:		Point Y:	35.68388979
Map Nbr:		Point X:	-105.94316493
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
367	WNW	0.85	4,464.21	6,973.76	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	247133	Other Loc:	200 Galisteo
POD Basin:	RG	Zone :	
POD Suffix:	POD 2	BLK:	
Pod Sub Ba:	NRG	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/02/2009, 12:00 AM	Restrict :	0.0
Finish Date:	08/02/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/27/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	43	UTM Zone:	13
Depth of Water:	33	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414702.3
Pcw Rcv Da:		Northing:	3949460.7
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/05/2018, 12:00 AM	Latitude Second:	7.3
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	33.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68536151
Map Nbr:		Point X:	-105.94266617
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
368	WNW	0.85	4,470.51	6,981.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336391	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD4	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414669.5
Pcw Rcv Da:		Northing:	3949359.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731577.0
Static Lev:	0	Y:	1704548.0
Tract Nbr:		Point Y:	35.68444723
Map Nbr:		Point X:	-105.94301789
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
369	WNW	0.85	4,472.65	6,981.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336389	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414669.2
Pcw Rcv Da:		Northing:	3949363.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731576.0
Static Lev:	0	Y:	1704562.0
Tract Nbr:		Point Y:	35.68448507
Map Nbr:		Point X:	-105.94302165
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
369	WNW	0.85	4,472.65	6,981.30	WATER WELLS

License Nb:	225	District Office S:	
POD No:	91760	Surv Map:	
POD Rec No:	249045	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/07/2009, 12:00 AM	Restrict :	0.0
Finish Date:	08/07/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/18/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	40	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414669.9
Pcw Rcv Da:		Northing:	3949364.2
Sched Date:		Latitude Degree:	0
Use of Wel:	EXP	Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	02/11/2010, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731578.1
Static Lev:	0	Y:	1704563.1
Tract Nbr:		Point Y:	35.68448874
Map Nbr:		Point X:	-105.94301395
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
370	WNW	0.85	4,474.71	6,982.44	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336455	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD68	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414656.4
Pcw Rcv Da:		Northing:	3949310.7
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731536.0
Static Lev:	0	Y:	1704387.0
Tract Nbr:		Point Y:	35.68400526
Map Nbr:		Point X:	-105.94315745
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
371	WNW	0.85	4,476.75	6,982.66	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	291322	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD 28	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414651.6
Pcw Rcv Da:		Northing:	3949294.9

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/20/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731521.0
Static Lev:	0	Y:	1704335.0
Tract Nbr:	NA	Point Y:	35.6838624
Map Nbr:	NA	Point X:	-105.94320882
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
371	WNW	0.85	4,476.75	6,982.66	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336451	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD64	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414652.5

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3949294.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731524.0
Static Lev:	0	Y:	1704335.0
Tract Nbr:		Point Y:	35.68386248
Map Nbr:		Point X:	-105.94319887
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
372	WNW	0.85	4,477.00	6,982.44	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336454	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD67	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	414656.4
Pcw Rcv Da:		Northing:	3949314.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731536.0
Static Lev:	0	Y:	1704398.0
Tract Nbr:		Point Y:	35.68403501
Map Nbr:		Point X:	-105.9431578
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
373	WNW	0.85	4,475.57	6,981.13	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91764	Surv Map:	
POD Rec No:	249122	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/21/2009, 12:00 AM	Restrict :	0.0
Finish Date:	04/21/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/17/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	20	UTM Zone:	13
Depth of Water:	13	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	6965.0	County:	Santa Fe
Ref :		Easting:	414677.2
Pcw Rcv Da:		Northing:	3949392.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/29/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731600.9
Static Lev:	0	Y:	1704657.2
Tract Nbr:		Point Y:	35.6847463
Map Nbr:		Point X:	-105.94293631
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
374	SSE	0.84	4,421.95	7,221.94	WATER WELLS

License Nb:	0	District Office S:	
POD No:	59723	Surv Map:	
POD Rec No:	57856	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416344.3
Pcw Rcv Da:		Northing:	3947666.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/07/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	596900.0
Static Lev:	0	Y:	1699000.0
Tract Nbr:		Point Y:	35.66932616
Map Nbr:		Point X:	-105.9243352
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
375	WNW	0.85	4,480.26	6,981.36	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336392	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD5	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414665.5
Pcw Rcv Da:		Northing:	3949357.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731564.0
Static Lev:	0	Y:	1704542.0
Tract Nbr:		Point Y:	35.68443066
Map Nbr:		Point X:	-105.94306189
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
376	WNW	0.85	4,482.61	6,982.66	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336452	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD65	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414649.4
Pcw Rcv Da:		Northing:	3949292.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731514.0
Static Lev:	0	Y:	1704326.0
Tract Nbr:		Point Y:	35.68383787
Map Nbr:		Point X:	-105.94323284
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
377	WNW	0.85	4,483.48	6,979.99	WATER WELLS

License Nb:	225	District Office S:	
POD No:	91762	Surv Map:	
POD Rec No:	249082	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/03/2009, 12:00 AM	Restrict :	0.0
Finish Date:	05/03/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/18/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	15	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414676.8
Pcw Rcv Da:		Northing:	3949402.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	02/11/2010, 12:00 AM	Latitude Second:	5.39
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	34.59
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68483101
Map Nbr:		Point X:	-105.94294173
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
378	WNW	0.85	4,486.23	6,982.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336456	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD69	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414651.7
Pcw Rcv Da:		Northing:	3949306.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731521.0
Static Lev:	0	Y:	1704373.0
Tract Nbr:		Point Y:	35.68396699
Map Nbr:		Point X:	-105.94320894
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
379	WNW	0.85	4,487.65	6,982.66	WATER WELLS

License Nb:	1210	District Office S:	
POD No:	98661	Surv Map:	
POD Rec No:	327420	Other Loc:	Sb-9
POD Basin:	RG	Zone :	
POD Suffix:	POD9	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/14/2020, 12:00 AM	Restrict :	0.0
Finish Date:	03/14/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/14/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	45	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	31	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414649.1
Pcw Rcv Da:		Northing:	3949295.7
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/28/2021, 12:00 AM	Latitude Second:	1.93
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	35.65
Well Tag:	NA	X:	0.0
Static Lev:	31	Y:	0.0
Tract Nbr:		Point Y:	35.6838694
Map Nbr:		Point X:	-105.94323652
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
380	WNW	0.85	4,486.69	6,980.52	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336390	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA

Wells and Additional Sources Detail Report

Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414664.6
Pcw Rcv Da:		Northing:	3949362.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731561.0
Static Lev:	0	Y:	1704556.0
Tract Nbr:		Point Y:	35.68446935
Map Nbr:		Point X:	-105.9430723
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
381	WNW	0.85	4,489.99	6,982.44	WATER WELLS

License Nb:	1210	District Office S:	
POD No:	98661	Surv Map:	
POD Rec No:	327421	Other Loc:	Sb-10
POD Basin:	RG	Zone :	
POD Suffix:	POD10	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/14/2020, 12:00 AM	Restrict :	0.0
Finish Date:	03/14/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/14/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	0	UTM Source:	PD
Depth of Well:	45	UTM Zone:	13
Depth of Water:	31	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414651.8
Pcw Rcv Da:		Northing:	3949312.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/28/2021, 12:00 AM	Latitude Second:	2.49
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	35.55
Well Tag:	NA	X:	0.0
Static Lev:	31	Y:	0.0
Tract Nbr:		Point Y:	35.68402469
Map Nbr:		Point X:	-105.94320852
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
382	WNW	0.85	4,489.38	6,980.52	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336388	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414665.0
Pcw Rcv Da:		Northing:	3949365.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731562.0
Static Lev:	0	Y:	1704568.0
Tract Nbr:		Point Y:	35.68450184
Map Nbr:		Point X:	-105.94306826
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
382	WNW	0.85	4,489.38	6,980.52	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336393	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD6	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414665.0
Pcw Rcv Da:		Northing:	3949365.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731562.0
Static Lev:	0	Y:	1704568.0
Tract Nbr:		Point Y:	35.68450184
Map Nbr:		Point X:	-105.94306826
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
383	WNW	0.85	4,489.81	6,980.41	WATER WELLS

License Nb:	0	District Office S:	
POD No:	92385	Surv Map:	
POD Rec No:	258265	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414669.8
Pcw Rcv Da:		Northing:	3949383.0
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	11/30/2018, 12:00 AM	Latitude Second:	4.77
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	34.86
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68465821
Map Nbr:		Point X:	-105.94301705
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
384	WNW	0.85	4,489.82	6,980.41	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91504	Surv Map:	
POD Rec No:	246116	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414671.4
Pcw Rcv Da:		Northing:	3949390.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	06/15/2009, 12:00 AM	Latitude Second:	5.0
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	34.8
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68472236
Map Nbr:		Point X:	-105.94300013
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
385	WNW	0.85	4,487.97	6,968.37	WATER WELLS

License Nb:	225	District Office S:	
POD No:	92152	Surv Map:	
POD Rec No:	255130	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD 2	BLK:	
Pod Sub Ba:	NRG	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	MONITORING WELL 2	Subdiv Loc:	
Start Date:	06/23/2010, 12:00 AM	Restrict :	0.0
Finish Date:	06/23/2010, 12:00 AM	Section:	
Plug Date:		Township:	

Wells and Additional Sources Detail Report

Log File D:	08/19/2010, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	30	UTM Zone:	13
Depth of Water:	26	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414702.5
Pcw Rcv Da:		Northing:	3949482.2
Sched Date:		Latitude Degree:	35
Use of Wel:	MON	Latitude Minute:	41
Sys Date:	06/28/2011, 12:00 AM	Latitude Second:	8.0
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	33.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68555535
Map Nbr:		Point X:	-105.94266624
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
386	WNW	0.85	4,494.97	6,980.52	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91505	Surv Map:	
POD Rec No:	246117	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414663.7
Pcw Rcv Da:		Northing:	3949368.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	06/15/2009, 12:00 AM	Latitude Second:	4.3
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	35.1
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68452787
Map Nbr:		Point X:	-105.94308293
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
386	WNW	0.85	4,494.97	6,980.52	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91764	Surv Map:	
POD Rec No:	249120	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/21/2009, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	04/21/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/17/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	20	UTM Zone:	13
Depth of Water:	12	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	6964.0	County:	Santa Fe
Ref :		Easting:	414664.3
Pcw Rcv Da:		Northing:	3949368.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/29/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731559.6
Static Lev:	0	Y:	1704576.6
Tract Nbr:		Point Y:	35.68452522
Map Nbr:		Point X:	-105.94307627
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
387	WNW	0.85	4,495.54	6,981.36	WATER WELLS

License Nb:	1210	District Office S:	
POD No:	98661	Surv Map:	
POD Rec No:	327423	Other Loc:	Sb-12
POD Basin:	RG	Zone :	
POD Suffix:	POD12	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:	03/20/2020, 12:00 AM	Restrict :	0.0
Finish Date:	03/20/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/14/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	80	UTM Zone:	13
Depth of Water:	31	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414661.1
Pcw Rcv Da:		Northing:	3949359.4
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/28/2021, 12:00 AM	Latitude Second:	4.0
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	35.2
Well Tag:	NA	X:	0.0
Static Lev:	31	Y:	0.0
Tract Nbr:		Point Y:	35.6844447
Map Nbr:		Point X:	-105.94311068
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
388	WNW	0.85	4,497.32	6,982.44	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336458	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD71	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PLG	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:	05/03/2022, 12:00 AM	Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414650.0
Pcw Rcv Da:		Northing:	3949314.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731515.0
Static Lev:	0	Y:	1704399.0
Tract Nbr:		Point Y:	35.68403806
Map Nbr:		Point X:	-105.94322856
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
389	WNW	0.85	4,497.81	6,981.78	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336457	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD70	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414646.8
Pcw Rcv Da:		Northing:	3949302.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731505.0
Static Lev:	0	Y:	1704361.0
Tract Nbr:		Point Y:	35.68393411
Map Nbr:		Point X:	-105.9432627
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
390	WNW	0.85	4,497.55	6,980.65	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	248075	Other Loc:	210 & 218 Montezuma Ave, Sf
POD Basin:	RG	Zone :	
POD Suffix:	POD 4	BLK:	
Pod Sub Ba:	NRG	Percent Sh:	0

Wells and Additional Sources Detail Report

POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414657.2
Pcw Rcv Da:		Northing:	3949347.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	09/18/2009, 12:00 AM	Latitude Second:	3.6
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	35.35
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68433348
Map Nbr:		Point X:	-105.94315247
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
391	W	0.85	4,500.52	6,982.98	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	288952	Other Loc:	35.683625, -105.943340
POD Basin:	RG	Zone :	
POD Suffix:	POD24	BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/17/2014, 12:00 AM	Restrict :	0.0
Finish Date:	03/23/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/02/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	PD
Depth of Well:	40	UTM Zone:	13
Depth of Water:	22	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414639.5
Pcw Rcv Da:		Northing:	3949268.7
Sched Date:		Latitude Degree:	0
Use of Wel:	MON	Latitude Minute:	0
Sys Date:	06/18/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	414639.5
Static Lev:	0	Y:	3949268.7
Tract Nbr:		Point Y:	35.68362516
Map Nbr:		Point X:	-105.94333974
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
392	WNW	0.85	4,501.61	6,981.78	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336459	Other Loc:	
POD Basin:	RG	Zone :	

Wells and Additional Sources Detail Report

POD Suffix:	POD72	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414647.6
Pcw Rcv Da:		Northing:	3949312.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731507.0
Static Lev:	0	Y:	1704393.0
Tract Nbr:		Point Y:	35.68402162
Map Nbr:		Point X:	-105.94325489
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
393	E	0.85	4,506.73	7,157.72	WATER WELLS

License Nb:	214	District Office S:	
POD No:	33748	Surv Map:	
POD Rec No:	331148	Other Loc:	1242 Canyon Road, Santa Fe

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TB
Start Date:	01/17/1980, 12:00 AM	Restrict :	0.0
Finish Date:	01/22/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	02/07/1980, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	98	UTM Zone:	13
Depth of Water:	22	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417378.9
Pcw Rcv Da:		Northing:	3948866.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/16/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417378.9
Static Lev:	0	Y:	3948866.2
Tract Nbr:		Point Y:	35.6802299
Map Nbr:		Point X:	-105.91302812
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:	Parcel Number 1055098493440000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
394	WNW	0.85	4,504.44	6,980.65	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	91565	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	288951	Other Loc:	35.684413, -105.943147 Dec Deg
POD Basin:	RG	Zone :	
POD Suffix:	POD23	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/17/2014, 12:00 AM	Restrict :	0.0
Finish Date:	03/23/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/02/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	PD
Depth of Well:	40	UTM Zone:	13
Depth of Water:	20	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414657.8
Pcw Rcv Da:		Northing:	3949355.9
Sched Date:		Latitude Degree:	0
Use of Wel:	MON	Latitude Minute:	0
Sys Date:	06/18/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	414657.8
Static Lev:	0	Y:	3949355.9
Tract Nbr:		Point Y:	35.68441286
Map Nbr:		Point X:	-105.94314678
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
395	WNW	0.85	4,506.64	6,979.40	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	91765	Surv Map:	
POD Rec No:	249130	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD5	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/28/2009, 12:00 AM	Restrict :	0.0
Finish Date:	02/28/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/17/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	47	UTM Zone:	13
Depth of Water:	34	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414672.0
Pcw Rcv Da:		Northing:	3949409.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/29/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731583.2
Static Lev:	0	Y:	1704710.5
Tract Nbr:		Point Y:	35.6848937
Map Nbr:		Point X:	-105.94299551
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
396	WNW	0.85	4,511.05	6,979.40	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	91760	Surv Map:	
POD Rec No:	249046	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414668.1
Pcw Rcv Da:		Northing:	3949401.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/28/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731570.8
Static Lev:	0	Y:	1704685.4
Tract Nbr:		Point Y:	35.68482485
Map Nbr:		Point X:	-105.9430378
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
397	WNW	0.86	4,515.50	6,981.78	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	1186	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	289383	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD27	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/17/2014, 12:00 AM	Restrict :	0.0
Finish Date:	03/23/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/02/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	PD
Depth of Well:	40	UTM Zone:	13
Depth of Water:	22	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414644.2
Pcw Rcv Da:		Northing:	3949315.3
Sched Date:		Latitude Degree:	0
Use of Wel:	MON	Latitude Minute:	0
Sys Date:	06/17/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	414644.2
Static Lev:	0	Y:	3949315.3
Tract Nbr:		Point Y:	35.68404567
Map Nbr:		Point X:	-105.94329275
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
398	WNW	0.86	4,515.03	6,979.40	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	225	District Office S:	
POD No:	91760	Surv Map:	
POD Rec No:	249047	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/04/2009, 12:00 AM	Restrict :	0.0
Finish Date:	08/04/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/18/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	22	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414668.2
Pcw Rcv Da:		Northing:	3949405.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/11/2010, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731570.9
Static Lev:	0	Y:	1704697.8
Tract Nbr:		Point Y:	35.68485821
Map Nbr:		Point X:	-105.94303709
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

399	E	0.86	4,521.78	7,207.33	WATER WELLS

License Nb:	0	District Office S:	
POD No:	56223	Surv Map:	
POD Rec No:	2551	Other Loc:	1243 Canyon Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417369.4
Pcw Rcv Da:		Northing:	3948769.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/19/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417369.4
Static Lev:	0	Y:	3948769.2
Tract Nbr:		Point Y:	35.67935462
Map Nbr:		Point X:	-105.91312312
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number: 1055098489437000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

400	ESE	0.85	4,512.66	7,231.89	WATER WELLS

License Nb:	1173	District Office S:	
POD No:	11665	Surv Map:	
POD Rec No:	3509	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/19/1964, 12:00 AM	Restrict :	0.0
Finish Date:	08/31/1964, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/20/1965, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	286	UTM Zone:	13
Depth of Water:	118	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417289.0
Pcw Rcv Da:		Northing:	3948481.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/24/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:	C4	Point Y:	35.67674968
Map Nbr:		Point X:	-105.91398187
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Tract Tr C4		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
401	E	0.86	4,520.41	7,205.21	WATER WELLS

License Nb:	253	District Office S:	
POD No:	33106	Surv Map:	
POD Rec No:	36804	Other Loc:	107 South Armijo Ln, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	43
Start Date:	09/10/1979, 12:00 AM	Restrict :	0.0
Finish Date:	09/20/1979, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	09/25/1979, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	150	UTM Zone:	13
Depth of Water:	64	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417390.3
Pcw Rcv Da:		Northing:	3949100.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/07/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417390.3
Static Lev:	0	Y:	3949100.7
Tract Nbr:		Point Y:	35.68234494
Map Nbr:		Point X:	-105.91292623
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
402	WNW	0.86	4,531.43	6,972.14	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	252446	Other Loc:	Property Behind Santa Fe Inn
POD Basin:	RG	Zone :	
POD Suffix:	POD14	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414683.2
Pcw Rcv Da:		Northing:	3949468.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	03/04/2010, 12:00 AM	Latitude Second:	7.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	34.36
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68543378
Map Nbr:		Point X:	-105.9428781
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
403	E	0.86	4,539.82	7,192.65	WATER WELLS

License Nb:	214	District Office S:	
POD No:	31318	Surv Map:	
POD Rec No:	46479	Other Loc:	1243 Canyon Road, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA
Start Date:	01/16/1980, 12:00 AM	Restrict :	0.0
Finish Date:	01/18/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	02/07/1980, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	136	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	200	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417379.0
Pcw Rcv Da:		Northing:	3948793.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417379.0
Static Lev:	0	Y:	3948793.0
Tract Nbr:		Point Y:	35.67956999
Map Nbr:		Point X:	-105.91301949
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Talaya Hill/Santa Fe
Legal: Parcel Number 1055098489437000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
404	E	0.86	4,522.18	7,230.01	WATER WELLS

License Nb:	0	District Office S:	
POD No:	69847	Surv Map:	
POD Rec No:	143277	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417370.3
Pcw Rcv Da:		Northing:	3949268.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	600200.0
Static Lev:	0	Y:	1704300.0
Tract Nbr:		Point Y:	35.68385603
Map Nbr:		Point X:	-105.91316447
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
405	WNW	0.86	4,540.52	6,979.33	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91762	Surv Map:	
POD Rec No:	249081	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414658.3
Pcw Rcv Da:		Northing:	3949398.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/28/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731538.6
Static Lev:	0	Y:	1704676.3
Tract Nbr:		Point Y:	35.68479966
Map Nbr:		Point X:	-105.94314581
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
405	WNW	0.86	4,540.52	6,979.33	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91764	Surv Map:	
POD Rec No:	249121	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/20/2009, 12:00 AM	Restrict :	0.0
Finish Date:	04/20/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/17/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	28	UTM Zone:	13
Depth of Water:	12	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	6964.0	County:	Santa Fe
Ref :		Easting:	414658.3
Pcw Rcv Da:		Northing:	3949398.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/29/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731538.6
Static Lev:	0	Y:	1704676.3
Tract Nbr:		Point Y:	35.68479966
Map Nbr:		Point X:	-105.94314581

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
406	NNW	0.85	4,491.50	7,063.87	WATER WELLS

License Nb:	0	District Office S:	
POD No:	71157	Surv Map:	
POD Rec No:	147086	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415647.1
Pcw Rcv Da:		Northing:	3950357.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/24/1998, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594500.0
Static Lev:	0	Y:	1707800.0
Tract Nbr:		Point Y:	35.69352405

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.93232001
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
407	WNW	0.86	4,548.78	6,978.50	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91765	Surv Map:	
POD Rec No:	249131	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD6	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/28/2009, 12:00 AM	Restrict :	0.0
Finish Date:	02/28/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/17/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	47	UTM Zone:	13
Depth of Water:	29	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414659.6
Pcw Rcv Da:		Northing:	3949414.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/29/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731542.3
Static Lev:	0	Y:	1704728.9

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.68494402
Map Nbr:		Point X:	-105.94313314
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
408	WNW	0.86	4,551.00	6,972.72	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	258870	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD16	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414675.1
Pcw Rcv Da:		Northing:	3949463.4
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	11/15/2010, 12:00 AM	Latitude Second:	7.38
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	34.68
Well Tag:		X:	0.0

Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6853835
Map Nbr:		Point X:	-105.94296702
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
409	WNW	0.86	4,552.93	6,979.33	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91503	Surv Map:	
POD Rec No:	246113	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414653.9
Pcw Rcv Da:		Northing:	3949399.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	06/15/2009, 12:00 AM	Latitude Second:	5.3
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	35.5

Wells and Additional Sources Detail Report

Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68480559
Map Nbr:		Point X:	-105.9431945
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
410	WSW	0.86	4,522.19	7,045.72	WATER WELLS

License Nb:	0	District Office S:	
POD No:	29818	Surv Map:	
POD Rec No:	33239	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414738.2
Pcw Rcv Da:		Northing:	3948387.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/02/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	591600.0
Static Lev:	0	Y:	1701300.0
Tract Nbr:		Point Y:	35.6756913
Map Nbr:		Point X:	-105.94215574
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
411	WNW	0.86	4,554.92	6,974.01	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336446	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD59	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414672.9
Pcw Rcv Da:		Northing:	3949461.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731584.0
Static Lev:	0	Y:	1704882.0
Tract Nbr:		Point Y:	35.68536437
Map Nbr:		Point X:	-105.94299111
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
411	WNW	0.86	4,554.92	6,974.01	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337893	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD106	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414672.6
Pcw Rcv Da:		Northing:	3949461.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731583.0
Static Lev:	0	Y:	1704883.0
Tract Nbr:		Point Y:	35.68536705
Map Nbr:		Point X:	-105.94299445
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
413	WNW	0.87	4,570.04	6,980.43	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	291717	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD33	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	08/06/2014, 12:00 AM	Restrict :	0.0
Finish Date:	08/13/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/25/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	36	UTM Zone:	13
Depth of Water:	22	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	8.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414628.4
Pcw Rcv Da:		Northing:	3949319.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	09/08/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731444.0
Static Lev:	0	Y:	1704414.0
Tract Nbr:	NA	Point Y:	35.68407946
Map Nbr:	NA	Point X:	-105.94346775
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
414	N	0.86	4,521.83	7,072.82	WATER WELLS

License Nb:	0	District Office S:	
POD No:	37084	Surv Map:	
POD Rec No:	19072	Other Loc:	205 Williams Street, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415738.9
Pcw Rcv Da:		Northing:	3950386.4
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	12/06/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594800.0
Static Lev:	0	Y:	1707900.0
Tract Nbr:		Point Y:	35.69379605
Map Nbr:		Point X:	-105.93130857
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
415	WNW	0.87	4,578.28	6,971.42	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	252450	Other Loc:	Property Behind Santa Fe Inn
POD Basin:	RG	Zone :	
POD Suffix:	POD15	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414669.5
Pcw Rcv Da:		Northing:	3949473.3

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	03/04/2010, 12:00 AM	Latitude Second:	7.7
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	34.91
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68547226
Map Nbr:		Point X:	-105.94302995
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
416	WNW	0.87	4,581.49	6,979.45	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	291715	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD31	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	08/06/2014, 12:00 AM	Restrict :	0.0
Finish Date:	08/13/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/25/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	40	UTM Zone:	13
Depth of Water:	22	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	8.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414635.7

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3949365.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/08/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731466.0
Static Lev:	0	Y:	1704566.0
Tract Nbr:	NA	Point Y:	35.6844975
Map Nbr:	NA	Point X:	-105.943392
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
417	WNW	0.87	4,582.15	6,980.10	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	291716	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD32	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	08/06/2014, 12:00 AM	Restrict :	0.0
Finish Date:	08/13/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/25/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	39	UTM Zone:	13
Depth of Water:	22	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	8.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	414630.9
Pcw Rcv Da:		Northing:	3949348.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/08/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731451.0
Static Lev:	0	Y:	1704509.0
Tract Nbr:	NA	Point Y:	35.68434112
Map Nbr:	NA	Point X:	-105.94344321
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
418	WNW	0.87	4,582.83	6,971.01	WATER WELLS

License Nb:	225	District Office S:	
POD No:	91760	Surv Map:	
POD Rec No:	249050	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD6	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/08/2009, 12:00 AM	Restrict :	0.0
Finish Date:	08/08/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/18/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	37	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414672.1
Pcw Rcv Da:		Northing:	3949484.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/11/2010, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731580.4
Static Lev:	0	Y:	1704959.3
Tract Nbr:		Point Y:	35.68557706
Map Nbr:		Point X:	-105.94300245
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
419	WNW	0.87	4,589.53	6,972.90	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337892	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD105	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414665.7
Pcw Rcv Da:		Northing:	3949472.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731560.0
Static Lev:	0	Y:	1704919.0
Tract Nbr:		Point Y:	35.68546652
Map Nbr:		Point X:	-105.94307188
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
420	WNW	0.87	4,591.19	6,973.31	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336445	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD58	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414665.1
Pcw Rcv Da:		Northing:	3949472.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731558.0
Static Lev:	0	Y:	1704918.0
Tract Nbr:		Point Y:	35.68546377
Map Nbr:		Point X:	-105.94307847
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
421	WNW	0.87	4,593.74	6,972.90	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336442	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD55	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414664.9
Pcw Rcv Da:		Northing:	3949475.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731557.0
Static Lev:	0	Y:	1704928.0
Tract Nbr:		Point Y:	35.68549079
Map Nbr:		Point X:	-105.943081
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
421	WNW	0.87	4,593.74	6,972.90	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336444	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD57	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414664.9
Pcw Rcv Da:		Northing:	3949475.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731557.0
Static Lev:	0	Y:	1704928.0
Tract Nbr:		Point Y:	35.68549079
Map Nbr:		Point X:	-105.943081
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
421	WNW	0.87	4,593.74	6,972.90	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337890	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD103	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414665.8
Pcw Rcv Da:		Northing:	3949475.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731560.0
Static Lev:	0	Y:	1704927.0
Tract Nbr:		Point Y:	35.68548817
Map Nbr:		Point X:	-105.94307103
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
422	WNW	0.87	4,599.85	6,981.52	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	288953	Other Loc:	35.683720, -105.943660 Dec Deg
POD Basin:	RG	Zone :	
POD Suffix:	POD25	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/17/2014, 12:00 AM	Restrict :	0.0
Finish Date:	03/23/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/02/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	PD
Depth of Well:	40	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	20	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414610.6
Pcw Rcv Da:		Northing:	3949279.5
Sched Date:		Latitude Degree:	0
Use of Wel:	MON	Latitude Minute:	0
Sys Date:	06/18/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	414610.6
Static Lev:	0	Y:	3949279.5
Tract Nbr:		Point Y:	35.68372002
Map Nbr:		Point X:	-105.94366023
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
423	WNW	0.87	4,599.11	6,977.74	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91762	Surv Map:	
POD Rec No:	249085	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD5	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA

Wells and Additional Sources Detail Report

Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414643.4
Pcw Rcv Da:		Northing:	3949413.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/28/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731489.2
Static Lev:	0	Y:	1704723.5
Tract Nbr:		Point Y:	35.68492999
Map Nbr:		Point X:	-105.943312
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
423	WNW	0.87	4,599.11	6,977.74	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91762	Surv Map:	
POD Rec No:	249084	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD4	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414643.4
Pcw Rcv Da:		Northing:	3949413.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/28/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731489.2
Static Lev:	0	Y:	1704723.5
Tract Nbr:		Point Y:	35.68492999
Map Nbr:		Point X:	-105.943312
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
423	WNW	0.87	4,599.11	6,977.74	WATER WELLS

License Nb:	225	District Office S:	
POD No:	91762	Surv Map:	
POD Rec No:	249083	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/03/2009, 12:00 AM	Restrict :	0.0
Finish Date:	05/03/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/18/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	17	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414643.4
Pcw Rcv Da:		Northing:	3949413.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/11/2010, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731489.2
Static Lev:	0	Y:	1704723.5
Tract Nbr:		Point Y:	35.68492999
Map Nbr:		Point X:	-105.943312
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
424	WNW	0.87	4,597.97	6,972.90	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337891	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD104	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414663.6
Pcw Rcv Da:		Northing:	3949473.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731553.0
Static Lev:	0	Y:	1704922.0
Tract Nbr:		Point Y:	35.68547445
Map Nbr:		Point X:	-105.94309518
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
425	WNW	0.87	4,598.65	6,972.90	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337887	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD100	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414664.0
Pcw Rcv Da:		Northing:	3949476.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731554.0
Static Lev:	0	Y:	1704930.0
Tract Nbr:		Point Y:	35.68549613
Map Nbr:		Point X:	-105.94309101
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
425	WNW	0.87	4,598.65	6,972.90	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337888	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD101	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414664.0
Pcw Rcv Da:		Northing:	3949476.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731554.0
Static Lev:	0	Y:	1704930.0
Tract Nbr:		Point Y:	35.68549613
Map Nbr:		Point X:	-105.94309101
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
426	S	0.86	4,547.49	7,217.21	WATER WELLS

License Nb:	214	District Office S:	
POD No:	34695	Surv Map:	
POD Rec No:	44043	Other Loc:	1110 Old Santa Fe Trail
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	102* U2 SF
Start Date:	07/28/1980, 12:00 AM	Restrict :	0.0
Finish Date:	07/31/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:	08/13/1980, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	28	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416171.7
Pcw Rcv Da:		Northing:	3947595.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/07/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1736580.0
Static Lev:	0	Y:	1698821.0
Tract Nbr:		Point Y:	35.66866871
Map Nbr:		Point X:	-105.92623465
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
427	WNW	0.87	4,602.32	6,977.74	WATER WELLS

License Nb:	0	District Office S:	
POD No:	92385	Surv Map:	
POD Rec No:	258264	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414644.3
Pcw Rcv Da:		Northing:	3949419.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	11/30/2018, 12:00 AM	Latitude Second:	5.96
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	35.89
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68498867
Map Nbr:		Point X:	-105.94330275
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
428	WNW	0.87	4,601.95	6,972.90	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336443	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD56	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414662.7
Pcw Rcv Da:		Northing:	3949474.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731550.0
Static Lev:	0	Y:	1704924.0
Tract Nbr:		Point Y:	35.68547979
Map Nbr:		Point X:	-105.94310519
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
429	SSW	0.86	4,557.93	7,145.91	WATER WELLS

License Nb:	228	District Office S:	
POD No:	41555	Surv Map:	
POD Rec No:	27335	Other Loc:	1313 Camino Corrales
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	90 U2 SF

Wells and Additional Sources Detail Report

Start Date:	06/04/1984, 12:00 AM	Restrict :	0.0
Finish Date:	06/07/1984, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	08/15/1984, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	320	UTM Zone:	13
Depth of Water:	200	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415676.5
Pcw Rcv Da:		Northing:	3947621.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/13/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1734954.0
Static Lev:	0	Y:	1698886.0
Tract Nbr:		Point Y:	35.6688618
Map Nbr:		Point X:	-105.9317083
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
430	WNW	0.87	4,605.92	6,972.90	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337889	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD102	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414661.5
Pcw Rcv Da:		Northing:	3949474.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731546.0
Static Lev:	0	Y:	1704926.0
Tract Nbr:		Point Y:	35.68548599
Map Nbr:		Point X:	-105.94311852
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
431	WNW	0.87	4,605.48	6,967.08	WATER WELLS

License Nb:	225	District Office S:	
POD No:	92152	Surv Map:	
POD Rec No:	255116	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD 1	BLK:	
Pod Sub Ba:	NRG	Percent Sh:	100
POD Status:	INC	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:	MONITORING WELL 1	Subdiv Loc:	
Start Date:	06/24/2010, 12:00 AM	Restrict :	0.0
Finish Date:	06/24/2010, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/19/2010, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	40	UTM Zone:	13
Depth of Water:	20	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414678.7
Pcw Rcv Da:		Northing:	3949522.5
Sched Date:		Latitude Degree:	35
Use of Wel:	MON	Latitude Minute:	41
Sys Date:	06/28/2011, 12:00 AM	Latitude Second:	9.3
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	34.56
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6859166
Map Nbr:		Point X:	-105.94293351
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
432	WNW	0.87	4,608.25	6,972.90	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337886	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD99	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0

Wells and Additional Sources Detail Report

POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414661.5
Pcw Rcv Da:		Northing:	3949477.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731546.0
Static Lev:	0	Y:	1704934.0
Tract Nbr:		Point Y:	35.68550763
Map Nbr:		Point X:	-105.94311878
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
433	WNW	0.87	4,611.35	6,978.44	WATER WELLS

License Nb:	0	District Office S:	
POD No:	92385	Surv Map:	
POD Rec No:	258266	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD4	BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414630.6
Pcw Rcv Da:		Northing:	3949381.2
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	11/30/2018, 12:00 AM	Latitude Second:	4.7
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	36.42
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68463859
Map Nbr:		Point X:	-105.94345002
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
434	WNW	0.87	4,611.55	6,972.90	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336441	Other Loc:	
POD Basin:	RG	Zone :	

Wells and Additional Sources Detail Report

POD Suffix:	POD54	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414660.0
Pcw Rcv Da:		Northing:	3949475.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731541.0
Static Lev:	0	Y:	1704927.0
Tract Nbr:		Point Y:	35.68548857
Map Nbr:		Point X:	-105.94313513
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
435	WNW	0.87	4,610.83	6,966.10	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91854	Surv Map:	
POD Rec No:	249923	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:	POD 1	BLK:	
Pod Sub Ba:	NRG	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414677.7
Pcw Rcv Da:		Northing:	3949525.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	12/22/2009, 12:00 AM	Latitude Second:	9.4
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	34.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68594447
Map Nbr:		Point X:	-105.94294489
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
436	WNW	0.87	4,614.58	6,972.90	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	337882	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD95	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414660.1
Pcw Rcv Da:		Northing:	3949480.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731541.0
Static Lev:	0	Y:	1704945.0
Tract Nbr:		Point Y:	35.68553816
Map Nbr:		Point X:	-105.94313461
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
436	WNW	0.87	4,614.58	6,972.90	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	A0441	Surv Map:	
POD Rec No:	336438	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD51	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414660.7
Pcw Rcv Da:		Northing:	3949480.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731543.0
Static Lev:	0	Y:	1704945.0
Tract Nbr:		Point Y:	35.68553821
Map Nbr:		Point X:	-105.94312798
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
437	WNW	0.87	4,615.05	6,972.90	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336440	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD53	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414660.0
Pcw Rcv Da:		Northing:	3949478.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731541.0
Static Lev:	0	Y:	1704937.0
Tract Nbr:		Point Y:	35.68551561
Map Nbr:		Point X:	-105.94313545
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
437	WNW	0.87	4,615.05	6,972.90	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337884	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD97	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414660.0
Pcw Rcv Da:		Northing:	3949478.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731541.0
Static Lev:	0	Y:	1704937.0
Tract Nbr:		Point Y:	35.68551561
Map Nbr:		Point X:	-105.94313545
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
438	WNW	0.87	4,617.53	6,971.59	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337880	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD93	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414660.4
Pcw Rcv Da:		Northing:	3949482.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731542.0
Static Lev:	0	Y:	1704952.0
Tract Nbr:		Point Y:	35.68555712
Map Nbr:		Point X:	-105.94313151
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

438	WNW	0.87	4,617.53	6,971.59	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336436	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD49	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414661.0
Pcw Rcv Da:		Northing:	3949484.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731544.0
Static Lev:	0	Y:	1704956.0
Tract Nbr:		Point Y:	35.68556799
Map Nbr:		Point X:	-105.94312501
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

439	WNW	0.87	4,618.34	6,973.17	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336439	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD52	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414657.6
Pcw Rcv Da:		Northing:	3949476.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731533.0
Static Lev:	0	Y:	1704932.0
Tract Nbr:		Point Y:	35.68550188
Map Nbr:		Point X:	-105.94316181
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
440	WNW	0.87	4,618.87	6,970.00	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	260234	Other Loc:	200 W Devargas Condominium
POD Basin:	RG	Zone :	
POD Suffix:	POD19	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414663.9
Pcw Rcv Da:		Northing:	3949495.2
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	03/01/2011, 12:00 AM	Latitude Second:	8.41
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	35.14
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68566921
Map Nbr:		Point X:	-105.94309415
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
441	WNW	0.87	4,619.30	6,971.59	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337878	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD91	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414660.7
Pcw Rcv Da:		Northing:	3949485.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731543.0
Static Lev:	0	Y:	1704960.0
Tract Nbr:		Point Y:	35.68557878
Map Nbr:		Point X:	-105.94312845
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
442	WNW	0.88	4,620.09	6,973.17	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337885	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD98	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414657.6
Pcw Rcv Da:		Northing:	3949477.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731533.0
Static Lev:	0	Y:	1704934.0
Tract Nbr:		Point Y:	35.68550729
Map Nbr:		Point X:	-105.94316187
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant :

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
442	WNW	0.88	4,620.09	6,973.17	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336437	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD50	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414657.9
Pcw Rcv Da:		Northing:	3949478.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731534.0
Static Lev:	0	Y:	1704939.0
Tract Nbr:		Point Y:	35.68552174
Map Nbr:		Point X:	-105.94315873
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
443	WNW	0.88	4,621.84	6,973.17	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337883	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD96	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414657.6
Pcw Rcv Da:		Northing:	3949479.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731533.0
Static Lev:	0	Y:	1704941.0
Tract Nbr:		Point Y:	35.68552712
Map Nbr:		Point X:	-105.9431621
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
443	WNW	0.88	4,621.84	6,973.17	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	288950	Other Loc:	35.685527, -105.943164 Dec Deg
POD Basin:	RG	Zone :	
POD Suffix:	POD22	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/17/2014, 12:00 AM	Restrict :	0.0
Finish Date:	03/23/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/02/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	PD
Depth of Well:	40	UTM Zone:	13
Depth of Water:	20	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414657.4
Pcw Rcv Da:		Northing:	3949479.5
Sched Date:		Latitude Degree:	0
Use of Wel:	MON	Latitude Minute:	0
Sys Date:	06/18/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	414657.4
Static Lev:	0	Y:	3949479.5
Tract Nbr:		Point Y:	35.68552711
Map Nbr:		Point X:	-105.94316431

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
443	WNW	0.88	4,621.84	6,973.17	WATER WELLS

License Nb:	1210	District Office S:	
POD No:	98661	Surv Map:	
POD Rec No:	327424	Other Loc:	Sb-13
POD Basin:	RG	Zone :	
POD Suffix:	POD13	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/22/2020, 12:00 AM	Restrict :	0.0
Finish Date:	03/22/2020, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/14/2020, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	90	UTM Zone:	13
Depth of Water:	31	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414658.2
Pcw Rcv Da:		Northing:	3949480.2
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	07/28/2021, 12:00 AM	Latitude Second:	7.92
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	35.36
Well Tag:	NA	X:	0.0
Static Lev:	31	Y:	0.0
Tract Nbr:		Point Y:	35.68553349

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.94315555
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
444	WNW	0.88	4,624.51	6,977.43	WATER WELLS

License Nb:	225	District Office S:	
POD No:	91760	Surv Map:	
POD Rec No:	249048	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD4	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/04/2009, 12:00 AM	Restrict :	0.0
Finish Date:	08/04/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/18/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	33	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414632.3
Pcw Rcv Da:		Northing:	3949404.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/11/2010, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731453.1
Static Lev:	0	Y:	1704692.2

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.68484429
Map Nbr:		Point X:	-105.94343366
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
445	WNW	0.88	4,622.87	6,971.59	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337876	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD89	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414660.5
Pcw Rcv Da:		Northing:	3949488.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731542.0

Wells and Additional Sources Detail Report

Static Lev:	0	Y:	1704970.0
Tract Nbr:		Point Y:	35.68560671
Map Nbr:		Point X:	-105.94313099
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
446	WNW	0.88	4,623.29	6,971.59	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336434	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD47	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414660.1
Pcw Rcv Da:		Northing:	3949486.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:	NA	X:	1731541.0
Static Lev:	0	Y:	1704965.0
Tract Nbr:		Point Y:	35.68559315
Map Nbr:		Point X:	-105.94313525
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
447	WNW	0.88	4,624.18	6,973.17	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337881	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD94	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414657.9
Pcw Rcv Da:		Northing:	3949481.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731534.0
Static Lev:	0	Y:	1704949.0
Tract Nbr:		Point Y:	35.68554879
Map Nbr:		Point X:	-105.94315904
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
447	WNW	0.88	4,624.18	6,973.17	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336435	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD48	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PLG	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:	05/03/2022, 12:00 AM	Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414658.2
Pcw Rcv Da:		Northing:	3949482.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731535.0
Static Lev:	0	Y:	1704951.0
Tract Nbr:		Point Y:	35.68555422
Map Nbr:		Point X:	-105.94315579
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
448	WNW	0.88	4,624.32	6,971.95	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337879	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD92	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414658.3
Pcw Rcv Da:		Northing:	3949484.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731535.0
Static Lev:	0	Y:	1704956.0
Tract Nbr:		Point Y:	35.68556775
Map Nbr:		Point X:	-105.94315485
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
448	WNW	0.88	4,624.32	6,971.95	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336433	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD46	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414658.6
Pcw Rcv Da:		Northing:	3949485.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731536.0
Static Lev:	0	Y:	1704962.0
Tract Nbr:		Point Y:	35.68558491
Map Nbr:		Point X:	-105.94315173
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
449	WNW	0.88	4,626.87	6,971.59	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	288999	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD26	BLK:	
Pod Sub Ba:	NRG	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/17/2014, 12:00 AM	Restrict :	0.0
Finish Date:	03/23/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/08/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	65	UTM Zone:	13
Depth of Water:	30	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414659.8
Pcw Rcv Da:		Northing:	3949489.7
Sched Date:		Latitude Degree:	35

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	41
Sys Date:	06/17/2014, 12:00 AM	Latitude Second:	8.23
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	35.3
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68561927
Map Nbr:		Point X:	-105.94313888
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
450	WNW	0.88	4,628.91	6,971.95	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337877	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD90	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414658.3
Pcw Rcv Da:		Northing:	3949486.5

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731535.0
Static Lev:	0	Y:	1704964.0
Tract Nbr:		Point Y:	35.68559029
Map Nbr:		Point X:	-105.94315511
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
451	WNW	0.88	4,631.88	6,971.95	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336432	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD45	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414658.3

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3949488.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731535.0
Static Lev:	0	Y:	1704972.0
Tract Nbr:		Point Y:	35.68561193
Map Nbr:		Point X:	-105.94315537
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
451	WNW	0.88	4,631.88	6,971.95	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337875	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD88	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	414658.0
Pcw Rcv Da:		Northing:	3949489.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731534.0
Static Lev:	0	Y:	1704974.0
Tract Nbr:		Point Y:	35.68561731
Map Nbr:		Point X:	-105.94315875
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
453	WNW	0.88	4,639.28	6,971.95	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336431	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD44	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414656.5
Pcw Rcv Da:		Northing:	3949491.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731529.0
Static Lev:	0	Y:	1704980.0
Tract Nbr:		Point Y:	35.68563431
Map Nbr:		Point X:	-105.94317552
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
453	WNW	0.88	4,639.28	6,971.95	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337874	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD87	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414656.5
Pcw Rcv Da:		Northing:	3949491.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731529.0
Static Lev:	0	Y:	1704980.0
Tract Nbr:		Point Y:	35.68563431
Map Nbr:		Point X:	-105.94317552
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
454	WNW	0.88	4,641.36	6,973.02	WATER WELLS

License Nb:	225	District Office S:	
POD No:	91760	Surv Map:	
POD Rec No:	249049	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD5	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/08/2009, 12:00 AM	Restrict :	0.0
Finish Date:	08/08/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/18/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	33	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414649.8
Pcw Rcv Da:		Northing:	3949474.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/11/2010, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731507.6
Static Lev:	0	Y:	1704924.2
Tract Nbr:		Point Y:	35.68548137
Map Nbr:		Point X:	-105.94324776
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
455	E	0.88	4,641.40	7,164.76	WATER WELLS

License Nb:	0	District Office S:	
POD No:	32171	Surv Map:	
POD Rec No:	9616	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417427.4
Pcw Rcv Da:		Northing:	3948963.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/08/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	600400.0
Static Lev:	0	Y:	1703300.0
Tract Nbr:		Point Y:	35.68110664
Map Nbr:		Point X:	-105.91250215
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
456	WNW	0.88	4,644.48	6,970.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337873	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD86	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414655.3
Pcw Rcv Da:		Northing:	3949493.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731525.0
Static Lev:	0	Y:	1704986.0
Tract Nbr:		Point Y:	35.68565043
Map Nbr:		Point X:	-105.94318897
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
457	WNW	0.88	4,645.75	6,971.95	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	260231	Other Loc:	Parking Lot 200 Devargas Condo
POD Basin:	RG	Zone :	
POD Suffix:	POD18	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414652.5
Pcw Rcv Da:		Northing:	3949486.4
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	03/01/2011, 12:00 AM	Latitude Second:	8.12
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	35.59
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68558889
Map Nbr:		Point X:	-105.94321919
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
458	WNW	0.88	4,648.48	6,970.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336430	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD43	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414654.7
Pcw Rcv Da:		Northing:	3949494.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731523.0
Static Lev:	0	Y:	1704989.0
Tract Nbr:		Point Y:	35.6856585
Map Nbr:		Point X:	-105.9431957
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
459	WNW	0.88	4,652.48	6,970.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337872	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD85	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA

Wells and Additional Sources Detail Report

Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414653.8
Pcw Rcv Da:		Northing:	3949495.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731520.0
Static Lev:	0	Y:	1704992.0
Tract Nbr:		Point Y:	35.68566743
Map Nbr:		Point X:	-105.94320575
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
460	WNW	0.88	4,656.49	6,970.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336429	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD42	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414652.9
Pcw Rcv Da:		Northing:	3949496.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731517.0
Static Lev:	0	Y:	1704997.0
Tract Nbr:		Point Y:	35.68568088
Map Nbr:		Point X:	-105.94321585
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
460	WNW	0.88	4,656.49	6,970.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337871	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD84	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414652.6
Pcw Rcv Da:		Northing:	3949496.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731516.0
Static Lev:	0	Y:	1704998.0
Tract Nbr:		Point Y:	35.68568356
Map Nbr:		Point X:	-105.9432192
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
461	WNW	0.88	4,657.24	6,973.02	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	291714	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD30	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	08/06/2014, 12:00 AM	Restrict :	0.0
Finish Date:	08/13/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/25/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	39	UTM Zone:	13
Depth of Water:	21	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	8.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414646.0
Pcw Rcv Da:		Northing:	3949478.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/08/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731495.0
Static Lev:	0	Y:	1704938.0
Tract Nbr:	NA	Point Y:	35.68551891
Map Nbr:	NA	Point X:	-105.9432902
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
462	NE	0.87	4,615.43	7,224.72	WATER WELLS

License Nb:	0	District Office S:	
POD No:	69688	Surv Map:	
POD Rec No:	142917	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416923.8
Pcw Rcv Da:		Northing:	3950097.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/27/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	598700.0
Static Lev:	0	Y:	1707000.0
Tract Nbr:		Point Y:	35.69128854
Map Nbr:		Point X:	-105.91818391
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
463	WNW	0.88	4,664.53	6,972.06	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	288912	Other Loc:	35.685633, -105.943266 Dec Deg
POD Basin:	RG	Zone :	
POD Suffix:	POD21	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/17/2014, 12:00 AM	Restrict :	0.0
Finish Date:	03/23/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/02/2014, 12:00 AM	Range:	

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	PD
Depth of Well:	40	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414648.3
Pcw Rcv Da:		Northing:	3949491.3
Sched Date:		Latitude Degree:	0
Use of Wel:	MON	Latitude Minute:	0
Sys Date:	06/18/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	414648.3
Static Lev:	0	Y:	3949491.3
Tract Nbr:		Point Y:	35.6856327
Map Nbr:		Point X:	-105.94326612
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
464	WSW	0.88	4,640.32	7,026.02	WATER WELLS

License Nb:	0	District Office S:	
POD No:	33160	Surv Map:	
POD Rec No:	45676	Other Loc:	133 W. Houghton, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	

Wells and Additional Sources Detail Report

Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414648.4
Pcw Rcv Da:		Northing:	3948510.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/14/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	591300.0
Static Lev:	0	Y:	1701700.0
Tract Nbr:		Point Y:	35.67679331
Map Nbr:		Point X:	-105.94316098
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
465	WNW	0.88	4,665.11	6,970.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337870	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD83	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414651.1
Pcw Rcv Da:		Northing:	3949498.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731511.0
Static Lev:	0	Y:	1705004.0
Tract Nbr:		Point Y:	35.68570056
Map Nbr:		Point X:	-105.94323598
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
465	WNW	0.88	4,665.11	6,970.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336428	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD41	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414651.1
Pcw Rcv Da:		Northing:	3949499.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731511.0
Static Lev:	0	Y:	1705005.0
Tract Nbr:		Point Y:	35.68570326
Map Nbr:		Point X:	-105.94323601
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
465	WNW	0.88	4,665.11	6,970.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	260233	Other Loc:	Parking Lot 200 Devargas Condo
POD Basin:	RG	Zone :	
POD Suffix:	POD20	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414650.6
Pcw Rcv Da:		Northing:	3949500.0
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	03/01/2011, 12:00 AM	Latitude Second:	8.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	35.67
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68571133
Map Nbr:		Point X:	-105.94324163
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
466	WNW	0.88	4,669.37	6,977.39	WATER WELLS

License Nb:	0	District Office S:	
POD No:	92385	Surv Map:	
POD Rec No:	258263	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414619.5
Pcw Rcv Da:		Northing:	3949405.4
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	11/30/2018, 12:00 AM	Latitude Second:	5.48
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	36.87
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6848558
Map Nbr:		Point X:	-105.94357525
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
467	WSW	0.88	4,638.68	7,044.05	WATER WELLS

License Nb:	214	District Office S:	
POD No:	34169	Surv Map:	
POD Rec No:	42243	Other Loc:	918 Don Gaspar, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7 1 SF
Start Date:	04/14/1980, 12:00 AM	Restrict :	0.0
Finish Date:	04/15/1980, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	04/23/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	246	UTM Zone:	13
Depth of Water:	190	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414701.9
Pcw Rcv Da:		Northing:	3948381.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/01/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Buena Vista	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	414701.9
Static Lev:	0	Y:	3948381.5
Tract Nbr:		Point Y:	35.67563227
Map Nbr:		Point X:	-105.94255615
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
468	SW	0.88	4,628.03	7,082.20	WATER WELLS

License Nb:	250	District Office S:	
POD No:	01837	Surv Map:	
POD Rec No:	64154	Other Loc:	1200 Madrid Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:	08/22/1958, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	210	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	415012.7
Pcw Rcv Da:		Northing:	3947954.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/27/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Lovato	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1732762.0
Static Lev:	0	Y:	1699952.0
Tract Nbr:		Point Y:	35.6718096
Map Nbr:		Point X:	-105.93907708
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
469	WNW	0.88	4,671.12	6,970.80	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	337869	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD82	BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	8	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414649.9
Pcw Rcv Da:		Northing:	3949500.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731507.0
Static Lev:	0	Y:	1705010.0
Tract Nbr:		Point Y:	35.68571668
Map Nbr:		Point X:	-105.94324943
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
469	WNW	0.88	4,671.12	6,970.80	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0441	Surv Map:	
POD Rec No:	336427	Other Loc:	
POD Basin:	RG	Zone :	

Wells and Additional Sources Detail Report

POD Suffix:	POD40	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414649.3
Pcw Rcv Da:		Northing:	3949501.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731505.0
Static Lev:	0	Y:	1705013.0
Tract Nbr:		Point Y:	35.68572474
Map Nbr:		Point X:	-105.94325616
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
470	SSW	0.88	4,631.31	7,135.32	WATER WELLS

License Nb:	622	District Office S:	
POD No:	47033	Surv Map:	
POD Rec No:	46592	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/11/1987, 12:00 AM	Restrict :	0.0
Finish Date:	02/12/1987, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	02/18/1987, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	420	UTM Zone:	13
Depth of Water:	190	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415612.2
Pcw Rcv Da:		Northing:	3947614.7
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	08/17/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594500.0
Static Lev:	0	Y:	1698800.0
Tract Nbr:		Point Y:	35.6687977
Map Nbr:		Point X:	-105.932418
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
471	E	0.89	4,682.42	7,183.77	WATER WELLS

License Nb:	0	District Office S:	
POD No:	33318	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	62555	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Taos
Ref :	RG-33318-/	Easting:	417425.5
Pcw Rcv Da:		Northing:	3948810.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/18/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	600400.0
Static Lev:	0	Y:	1702800.0
Tract Nbr:		Point Y:	35.67973346
Map Nbr:		Point X:	-105.91250751
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
472	W	0.88	4,669.58	6,986.81	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	35007	Surv Map:	
POD Rec No:	57161	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414562.0
Pcw Rcv Da:		Northing:	3948908.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/15/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	591000.0
Static Lev:	0	Y:	1703000.0
Tract Nbr:		Point Y:	35.68036756
Map Nbr:		Point X:	-105.9441578
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
473	ESE	0.89	4,686.39	7,247.37	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	622	District Office S:	
POD No:	66994	Surv Map:	
POD Rec No:	21806	Other Loc:	126 Canyon Rd, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1&2 9 SF
Start Date:	06/19/1997, 12:00 AM	Restrict :	0.0
Finish Date:	06/19/1997, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	06/27/1997, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417405.3
Pcw Rcv Da:		Northing:	3948686.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/10/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417405.3
Static Lev:	0	Y:	3948686.4
Tract Nbr:		Point Y:	35.67861117
Map Nbr:		Point X:	-105.91271795
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:	Parcel Number 1055098515393000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
474	WSW	0.88	4,666.65	7,005.46	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	35485	Surv Map:	
POD Rec No:	35272	Other Loc:	715 Galisteo St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3 3 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414602.7
Pcw Rcv Da:		Northing:	3948636.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/03/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Buena Vista Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731388.0
Static Lev:	0	Y:	1702173.0
Tract Nbr:		Point Y:	35.67792346
Map Nbr:		Point X:	-105.94367927
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
475	E	0.89	4,687.84	7,195.53	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	622	District Office S:	
POD No:	41873	Surv Map:	
POD Rec No:	45459	Other Loc:	1330 Cerro Gordo Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TF SF
Start Date:	05/29/1984, 12:00 AM	Restrict :	0.0
Finish Date:	05/29/1984, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	06/04/1984, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	205	UTM Zone:	13
Depth of Water:	70	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417441.9
Pcw Rcv Da:		Northing:	3949074.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/21/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1740686.0
Static Lev:	0	Y:	1703728.0
Tract Nbr:		Point Y:	35.68211216
Map Nbr:		Point X:	-105.91235336
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

476	WNW	0.89	4,700.87	6,977.47	WATER WELLS

License Nb:	225	District Office S:	
POD No:	91760	Surv Map:	
POD Rec No:	249051	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD7	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/06/2009, 12:00 AM	Restrict :	0.0
Finish Date:	08/06/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/08/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	30	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414607.7
Pcw Rcv Da:		Northing:	3949399.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/11/2010, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731372.7
Static Lev:	0	Y:	1704676.8
Tract Nbr:		Point Y:	35.68480249
Map Nbr:		Point X:	-105.94370502
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

477	W	0.89	4,709.36	6,981.13	WATER WELLS

License Nb:	622	District Office S:	
POD No:	55914	Surv Map:	
POD Rec No:	5017	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/17/1992, 12:00 AM	Restrict :	0.0
Finish Date:	09/18/1992, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	09/29/1992, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	260	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414565.9
Pcw Rcv Da:		Northing:	3949212.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/19/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	591000.0
Static Lev:	0	Y:	1704000.0
Tract Nbr:		Point Y:	35.68311483
Map Nbr:		Point X:	-105.94414707
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
478	E	0.89	4,695.54	7,227.77	WATER WELLS

License Nb:	622	District Office S:	
POD No:	81437	Surv Map:	
POD Rec No:	196985	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417431.1
Pcw Rcv Da:		Northing:	3949227.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/09/2012, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	600401.0
Static Lev:	0	Y:	1704167.0
Tract Nbr:	1-B	Point Y:	35.68348879
Map Nbr:		Point X:	-105.91248839
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
479	WNW	0.89	4,711.36	6,976.57	WATER WELLS

License Nb:	225	District Office S:	
POD No:	91762	Surv Map:	
POD Rec No:	249086	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD6	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/03/2009, 12:00 AM	Restrict :	0.0
Finish Date:	05/03/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/18/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	15	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414604.7
Pcw Rcv Da:		Northing:	3949401.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/11/2010, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731362.6
Static Lev:	0	Y:	1704681.9
Tract Nbr:		Point Y:	35.68481665
Map Nbr:		Point X:	-105.94373834
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
480	W	0.89	4,710.06	6,987.21	WATER WELLS

License Nb:	225	District Office S:	
POD No:	43032	Surv Map:	
POD Rec No:	25462	Other Loc:	1411 Paseo De Peralta
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	6 SF
Start Date:	03/13/1985, 12:00 AM	Restrict :	0.0
Finish Date:	03/14/1985, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	03/22/1985, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	179	UTM Zone:	13
Depth of Water:	53	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-43032-/	Easting:	414548.0
Pcw Rcv Da:		Northing:	3948962.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/01/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Chavez Pl Addn	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731195.0
Static Lev:	0	Y:	1703240.0
Tract Nbr:		Point Y:	35.68085678
Map Nbr:		Point X:	-105.94431827
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
481	WNW	0.89	4,716.39	6,969.00	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	91565	Surv Map:	
POD Rec No:	291713	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD29	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	08/06/2014, 12:00 AM	Restrict :	0.0
Finish Date:	08/13/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/25/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	32	UTM Zone:	13
Depth of Water:	22	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	8.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414640.4
Pcw Rcv Da:		Northing:	3949515.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/08/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731475.0
Static Lev:	0	Y:	1705057.0
Tract Nbr:	NA	Point Y:	35.68584658
Map Nbr:	NA	Point X:	-105.94335595
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
482	WNW	0.90	4,726.51	6,974.06	WATER WELLS

License Nb:	225	District Office S:	
POD No:	91760	Surv Map:	
POD Rec No:	249054	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD10	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/10/2009, 12:00 AM	Restrict :	0.0
Finish Date:	08/10/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/08/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	48	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414621.6
Pcw Rcv Da:		Northing:	3949472.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/11/2010, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731415.1
Static Lev:	0	Y:	1704915.3
Tract Nbr:		Point Y:	35.6854573
Map Nbr:		Point X:	-105.94355912
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
483	WSW	0.89	4,705.95	7,027.59	WATER WELLS

License Nb:	297	District Office S:	
POD No:	04716	Surv Map:	
POD Rec No:	49353	Other Loc:	127 Houghton St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	29 2 SF
Start Date:	05/24/1960, 12:00 AM	Restrict :	0.0
Finish Date:	05/24/1960, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	06/10/1960, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	117	UTM Zone:	13
Depth of Water:	83	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414634.6
Pcw Rcv Da:		Northing:	3948489.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/12/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Buena Vista Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	414634.6
Static Lev:	0	Y:	3948489.5
Tract Nbr:		Point Y:	35.67660009
Map Nbr:		Point X:	-105.9433112

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal: Parcel Number 1-054-098-115-034

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
484	SW	0.89	4,702.00	7,087.19	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34414	Surv Map:	
POD Rec No:	19063	Other Loc:	1239 Madrid Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7 U1TA SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415088.6
Pcw Rcv Da:		Northing:	3947858.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/30/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Santa Fe Holding Company	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1733015.0
Static Lev:	0	Y:	1699640.0
Tract Nbr:		Point Y:	35.67095068

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.93822839
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
485	WNW	0.90	4,762.76	6,975.25	WATER WELLS

License Nb:	225	District Office S:	
POD No:	91760	Surv Map:	
POD Rec No:	249053	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD9	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/06/2009, 12:00 AM	Restrict :	0.0
Finish Date:	08/06/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/18/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	30	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414597.2
Pcw Rcv Da:		Northing:	3949434.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/11/2010, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1731336.7
Static Lev:	0	Y:	1704790.1

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.68511441
Map Nbr:		Point X:	-105.94382473
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
486	W	0.90	4,760.32	6,986.44	WATER WELLS

License Nb:	622	District Office S:	
POD No:	29243	Surv Map:	
POD Rec No:	314995	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/19/1982, 12:00 AM	Restrict :	0.0
Finish Date:	05/19/1982, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/26/1982, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	65	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414532.3
Pcw Rcv Da:		Northing:	3948966.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/01/2025, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	590900.0

Wells and Additional Sources Detail Report

Static Lev:	0	Y:	1703190.0
Tract Nbr:		Point Y:	35.68089057
Map Nbr:		Point X:	-105.94449217
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
487	WNW	0.90	4,769.70	6,975.25	WATER WELLS

License Nb:	225	District Office S:	
POD No:	91760	Surv Map:	
POD Rec No:	249052	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD8	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/05/2009, 12:00 AM	Restrict :	0.0
Finish Date:	08/05/2009, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/18/2009, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	15	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414597.2
Pcw Rcv Da:		Northing:	3949438.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/11/2010, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:		X:	1731336.7
Static Lev:	0	Y:	1704802.7
Tract Nbr:		Point Y:	35.68514866
Map Nbr:		Point X:	-105.94382514
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
488	NW	0.90	4,748.63	6,982.70	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	94518	Surv Map:	
POD Rec No:	289031	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	MW-3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	03/11/2014, 12:00 AM	Restrict :	0.0
Finish Date:	03/14/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/02/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	D	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414933.8
Pcw Rcv Da:		Northing:	3950016.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	05/29/2014, 12:00 AM	Latitude Second:	25.4
Subdiv Nam:	Na	Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.69038855
Map Nbr:		Point X:	-105.94016681
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
489	WSW	0.90	4,749.93	7,033.70	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35601	Surv Map:	
POD Rec No:	65187	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414647.2
Pcw Rcv Da:		Northing:	3948419.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/04/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	591300.0
Static Lev:	0	Y:	1701400.0
Tract Nbr:		Point Y:	35.67596921
Map Nbr:		Point X:	-105.94316454
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
490	W	0.91	4,785.93	6,979.67	WATER WELLS

License Nb:	225	District Office S:	
POD No:	94330	Surv Map:	
POD Rec No:	287034	Other Loc:	Tbamw-03
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	TBAMW-03	Subdiv Loc:	
Start Date:	01/29/2014, 12:00 AM	Restrict :	0.0
Finish Date:	01/29/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	02/19/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	38	UTM Zone:	13
Depth of Water:	26	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414542.5
Pcw Rcv Da:		Northing:	3949212.3
Sched Date:		Latitude Degree:	35
Use of Wel:	MON	Latitude Minute:	40
Sys Date:	05/30/2014, 12:00 AM	Latitude Second:	59.19

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	39.86
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68310829
Map Nbr:		Point X:	-105.94440559
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
491	N	0.90	4,728.45	7,062.59	WATER WELLS

License Nb:	228	District Office S:	
POD No:	41844	Surv Map:	
POD Rec No:	8445	Other Loc:	205 Williams St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	28 SF
Start Date:	07/28/1984, 12:00 AM	Restrict :	0.0
Finish Date:	07/30/1984, 12:00 AM	Section:	24
Plug Date:		Township:	17N
Log File D:	10/11/1984, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	225	UTM Zone:	13
Depth of Water:	60	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415740.0
Pcw Rcv Da:		Northing:	3950451.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	06/21/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735044.0
Static Lev:	0	Y:	1708176.0
Tract Nbr:		Point Y:	35.69438393
Map Nbr:		Point X:	-105.93130325
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
492	ESE	0.91	4,794.42	7,244.57	WATER WELLS

License Nb:	253	District Office S:	
POD No:	34855	Surv Map:	
POD Rec No:	50448	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	D 7 SF
Start Date:	06/17/1981, 12:00 AM	Restrict :	0.0
Finish Date:	06/20/1981, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	06/30/1981, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	236	UTM Zone:	13
Depth of Water:	134	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-34855-/	Easting:	417419.8
Pcw Rcv Da:		Northing:	3948606.9
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	09/24/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1740633.0
Static Lev:	0	Y:	1702193.0
Tract Nbr:		Point Y:	35.67789567
Map Nbr:		Point X:	-105.91254957
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
493	SSE	0.90	4,739.91	7,234.66	WATER WELLS

License Nb:	228	District Office S:	
POD No:	34938	Surv Map:	
POD Rec No:	18946	Other Loc:	1125 Old Santa Fe Trail, Sf
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/18/1980, 12:00 AM	Restrict :	0.0
Finish Date:	11/25/1980, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/12/1980, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	90	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416373.6
Pcw Rcv Da:		Northing:	3947574.6

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/18/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597000.0
Static Lev:	0	Y:	1698700.0
Tract Nbr:		Point Y:	35.66850104
Map Nbr:		Point X:	-105.92400195
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
493	SSE	0.90	4,739.91	7,234.66	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35863	Surv Map:	
POD Rec No:	52541	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416373.6

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3947574.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/08/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	597000.0
Static Lev:	0	Y:	1698700.0
Tract Nbr:		Point Y:	35.66850104
Map Nbr:		Point X:	-105.92400195
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
494	SW	0.90	4,756.94	7,085.16	WATER WELLS

License Nb:	0	District Office S:	
POD No:	86261	Surv Map:	
POD Rec No:	214481	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	415071.2
Pcw Rcv Da:		Northing:	3947851.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/19/2005, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592715.0
Static Lev:	0	Y:	1699553.0
Tract Nbr:		Point Y:	35.67088247
Map Nbr:		Point X:	-105.93841985
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
495	SSE	0.90	4,752.73	7,250.95	WATER WELLS

License Nb:	1310	District Office S:	
POD No:	68741	Surv Map:	
POD Rec No:	139928	Other Loc:	797 Camino Del Monte Sol
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TB SF
Start Date:	06/14/1998, 12:00 AM	Restrict :	0.0
Finish Date:	06/18/1998, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	10/28/1998, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	80	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416561.2
Pcw Rcv Da:		Northing:	3947633.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/13/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	416561.2
Static Lev:	0	Y:	3947633.5
Tract Nbr:		Point Y:	35.66904793
Map Nbr:		Point X:	-105.92193547
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055098217053000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
496	S	0.90	4,755.74	7,185.90	WATER WELLS

License Nb:	253	District Office S:	
POD No:	37517	Surv Map:	
POD Rec No:	11048	Other Loc:	751 Camino Pinones
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	85 U2T2 SF
Start Date:	06/18/1982, 12:00 AM	Restrict :	0.0
Finish Date:	06/21/1982, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	07/23/1982, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	130	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415935.5
Pcw Rcv Da:		Northing:	3947523.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/04/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735808.0
Static Lev:	0	Y:	1698575.0
Tract Nbr:		Point Y:	35.66799951
Map Nbr:		Point X:	-105.92883664
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
497	SW	0.91	4,787.66	7,049.10	WATER WELLS

License Nb:	228	District Office S:	
POD No:	36700	Surv Map:	
POD Rec No:	62618	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	12/03/1981, 12:00 AM	Restrict :	0.0
Finish Date:	12/04/1981, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/15/1981, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	245	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	40	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414855.8
Pcw Rcv Da:		Northing:	3948051.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/19/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592000.0
Static Lev:	0	Y:	1700200.0
Tract Nbr:		Point Y:	35.67266604
Map Nbr:		Point X:	-105.94082077
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
498	NNW	0.91	4,800.15	7,013.09	WATER WELLS

License Nb:	0	District Office S:	
POD No:	96127	Surv Map:	
POD Rec No:	302086	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	MW-1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	24
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415207.7
Pcw Rcv Da:		Northing:	3950265.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	09/14/2018, 12:00 AM	Latitude Second:	33.58
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	13.8
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.69266145
Map Nbr:		Point X:	-105.9371663
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
499	NNW	0.91	4,813.17	7,011.88	WATER WELLS

License Nb:	0	District Office S:	
POD No:	95571	Surv Map:	
POD Rec No:	298337	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415200.0
Pcw Rcv Da:		Northing:	3950266.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/18/2015, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	415200.0
Static Lev:	0	Y:	3950266.0
Tract Nbr:		Point Y:	35.69266439
Map Nbr:		Point X:	-105.93725143
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
500	W	0.92	4,862.21	6,983.44	WATER WELLS

License Nb:	0	District Office S:	
POD No:	36528	Surv Map:	
POD Rec No:	63919	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10

Wells and Additional Sources Detail Report

Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414502.6
Pcw Rcv Da:		Northing:	3949030.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/29/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	590800.0
Static Lev:	0	Y:	1703400.0
Tract Nbr:		Point Y:	35.68146768
Map Nbr:		Point X:	-105.94482717
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
501	E	0.92	4,862.39	7,218.43	WATER WELLS

License Nb:	622	District Office S:	
POD No:	33218	Surv Map:	
POD Rec No:	16434	Other Loc:	1320 Cerro Gordo, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	46 4 SF
Start Date:	06/23/1982, 12:00 AM	Restrict :	0.0
Finish Date:	06/23/1982, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	07/07/1982, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	150	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	60	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	7	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417488.8
Pcw Rcv Da:		Northing:	3949176.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/16/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417488.8
Static Lev:	0	Y:	3949176.9
Tract Nbr:		Point Y:	35.68304015
Map Nbr:		Point X:	-105.91184564
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055099514003000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
502	NW	0.92	4,857.03	6,983.27	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	94518	Surv Map:	
POD Rec No:	289030	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	MW-2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	03/11/2014, 12:00 AM	Restrict :	0.0
Finish Date:	03/14/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/02/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD

Wells and Additional Sources Detail Report

Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	D	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414931.7
Pcw Rcv Da:		Northing:	3950062.4
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	05/29/2014, 12:00 AM	Latitude Second:	26.9
Subdiv Nam:	Na	Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	24.7
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.69080577
Map Nbr:		Point X:	-105.94019492
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
503	ESE	0.92	4,883.76	7,230.10	WATER WELLS

License Nb:	622	District Office S:	
POD No:	71206	Surv Map:	
POD Rec No:	147367	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/16/1999, 12:00 AM	Restrict :	0.0
Finish Date:	11/19/1999, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	01/03/2000, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	21	UTM Source:	UN
Depth of Well:	240	UTM Zone:	13
Depth of Water:	126	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417358.7
Pcw Rcv Da:		Northing:	3948354.4
Sched Date:		Latitude Degree:	0
Use of Wel:	ONE HOUSEHOLD	Latitude Minute:	0
Sys Date:	01/04/2000, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	600200.0
Static Lev:	0	Y:	1701300.0
Tract Nbr:		Point Y:	35.67561419
Map Nbr:		Point X:	-105.91319874
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
504	NNW	0.92	4,855.70	7,010.18	WATER WELLS

License Nb:	0	District Office S:	
POD No:	95571	Surv Map:	
POD Rec No:	298338	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415188.0
Pcw Rcv Da:		Northing:	3950273.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/18/2015, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	415188.0
Static Lev:	0	Y:	3950273.0
Tract Nbr:		Point Y:	35.69272646
Map Nbr:		Point X:	-105.93738479
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
505	NW	0.92	4,870.95	6,985.62	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	94518	Surv Map:	
POD Rec No:	289029	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	MW-1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	NA NA NA
Start Date:	03/11/2014, 12:00 AM	Restrict :	0.0
Finish Date:	03/14/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/02/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	D	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414947.0
Pcw Rcv Da:		Northing:	3950083.8
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	05/29/2014, 12:00 AM	Latitude Second:	27.6
Subdiv Nam:	Na	Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	24.1
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.69100002
Map Nbr:		Point X:	-105.9400281
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
506	SW	0.93	4,885.59	7,066.26	WATER WELLS

License Nb:	253	District Office S:	
POD No:	20599	Surv Map:	
POD Rec No:	42419	Other Loc:	1203 Seville Rd, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3A-1 TC SF
Start Date:	07/12/1972, 12:00 AM	Restrict :	0.0
Finish Date:	08/14/1972, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	08/17/1972, 12:00 AM	Range:	08E
Wrats S ID:	0	Quarter 4th:	3

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	290	UTM Zone:	13
Depth of Water:	102	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414898.8
Pcw Rcv Da:		Northing:	3947958.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/22/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	414898.8
Static Lev:	0	Y:	3947958.1
Tract Nbr:		Point Y:	35.67183224
Map Nbr:		Point X:	-105.94033586
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1054098202142000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
507	SW	0.93	4,911.51	7,046.31	WATER WELLS

License Nb:	0	District Office S:	
POD No:	85091	Surv Map:	
POD Rec No:	210209	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414816.4
Pcw Rcv Da:		Northing:	3948039.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/26/2005, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	591871.0
Static Lev:	0	Y:	1700161.0
Tract Nbr:		Point Y:	35.67255986
Map Nbr:		Point X:	-105.94125487
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
508	SW	0.93	4,916.36	7,073.38	WATER WELLS

License Nb:	49	District Office S:	
POD No:	70078	Surv Map:	
POD Rec No:	143935	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/24/1998, 12:00 AM	Restrict :	0.0
Finish Date:	07/28/1998, 12:00 AM	Section:	
Plug Date:		Township:	

Wells and Additional Sources Detail Report

Log File D:	10/07/1998, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	360	UTM Zone:	13
Depth of Water:	70	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	14	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414945.3
Pcw Rcv Da:		Northing:	3947897.5
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	12/22/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592300.0
Static Lev:	0	Y:	1699700.0
Tract Nbr:		Point Y:	35.67128993
Map Nbr:		Point X:	-105.93981571
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
510	WSW	0.94	4,954.82	7,033.74	WATER WELLS

License Nb:	0	District Office S:	
POD No:	33034	Surv Map:	
POD Rec No:	46889	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10-A NA T-J SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25

Wells and Additional Sources Detail Report

Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414705.0
Pcw Rcv Da:		Northing:	3948174.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/15/2025, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Galisteo #1	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731743.0
Static Lev:	0	Y:	1700660.2
Tract Nbr:		Point Y:	35.67376459
Map Nbr:		Point X:	-105.94249994
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
511	WNW	0.95	5,000.61	6,970.15	WATER WELLS

License Nb:	225	District Office S:	
POD No:	94330	Surv Map:	
POD Rec No:	287037	Other Loc:	Tbamw-05
POD Basin:	RG	Zone :	
POD Suffix:	POD5	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	TBAMW-05	Subdiv Loc:	
Start Date:	02/02/2014, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	02/05/2014, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	02/19/2014, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	89	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	D	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414548.5
Pcw Rcv Da:		Northing:	3949517.9
Sched Date:		Latitude Degree:	35
Use of Wel:	MON	Latitude Minute:	41
Sys Date:	05/30/2014, 12:00 AM	Latitude Second:	9.11
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	39.74
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68586386
Map Nbr:		Point X:	-105.94437176
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
512	E	0.95	4,991.94	7,246.08	WATER WELLS

License Nb:	622	District Office S:	
POD No:	71051	Surv Map:	
POD Rec No:	146884	Other Loc:	1317b Cerro Gordo Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T1 SF

Wells and Additional Sources Detail Report

Start Date:	01/27/1999, 12:00 AM	Restrict :	0.0
Finish Date:	02/03/1999, 12:00 AM	Section:	19
Plug Date:		Township:	17N
Log File D:	02/24/1999, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	340	UTM Zone:	13
Depth of Water:	67	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417511.1
Pcw Rcv Da:		Northing:	3949296.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/10/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417511.1
Static Lev:	0	Y:	3949296.2
Tract Nbr:		Point Y:	35.68411754
Map Nbr:		Point X:	-105.91161147
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Numbers: 1056099009109000000, 1056099003057000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
513	E	0.95	5,000.62	7,217.78	WATER WELLS

License Nb:	253	District Office S:	
POD No:	28268	Surv Map:	
POD Rec No:	35290	Other Loc:	1330a Cerro Gordo Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	TA1 SF
Start Date:	03/05/1977, 12:00 AM	Restrict :	0.0
Finish Date:	03/08/1977, 12:00 AM	Section:	20
Plug Date:		Township:	17N
Log File D:	03/10/1977, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	50	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417532.8
Pcw Rcv Da:		Northing:	3949157.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/02/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1740981.0
Static Lev:	0	Y:	1704005.0
Tract Nbr:		Point Y:	35.68286984
Map Nbr:		Point X:	-105.91135747
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
515	SW	0.95	4,989.85	7,083.67	WATER WELLS

License Nb:	537	District Office S:	
POD No:	21523	Surv Map:	
POD Rec No:	281378	Other Loc:	Within A Radius Of 2 Miles
POD Basin:	RG	Zone :	
POD Suffix:	X9	BLK:	
Pod Sub Ba:	NRG	Percent Sh:	100
POD Status:	ACT	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/23/1972, 12:00 AM	Restrict :	0.0
Finish Date:	08/23/1972, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/29/1972, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415095.7
Pcw Rcv Da:		Northing:	3947743.2
Sched Date:		Latitude Degree:	0
Use of Wel:	OBSERVATION	Latitude Minute:	0
Sys Date:	03/01/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592800.0
Static Lev:	0	Y:	1699200.0
Tract Nbr:		Point Y:	35.66991184
Map Nbr:		Point X:	-105.93813778
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :	Sebastian De Vargas		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
516	WSW	0.95	5,006.59	7,033.71	WATER WELLS

License Nb:	622	District Office S:	
POD No:	40210	Surv Map:	
POD Rec No:	4919	Other Loc:	1105 Don Gaspar, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/10/1984, 12:00 AM	Restrict :	0.0
Finish Date:	02/11/1984, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	02/14/1984, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	330	UTM Zone:	13
Depth of Water:	110	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414704.7
Pcw Rcv Da:		Northing:	3948144.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/28/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	591500.0
Static Lev:	0	Y:	1700500.0
Tract Nbr:		Point Y:	35.673495
Map Nbr:		Point X:	-105.94250008
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
517	SE	0.96	5,042.71	7,291.09	WATER WELLS

License Nb:	0	District Office S:	
POD No:	44384	Surv Map:	
POD Rec No:	48299	Other Loc:	700 Camino Cabra
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417225.1
Pcw Rcv Da:		Northing:	3948038.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Armstrong	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1740018.0
Static Lev:	0	Y:	1700319.0
Tract Nbr:		Point Y:	35.67275235
Map Nbr:		Point X:	-105.91464235
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
518	SW	0.95	5,029.70	7,077.50	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34603	Surv Map:	
POD Rec No:	31094	Other Loc:	231 E Cordova Rd
POD Basin:	RG	Zone :	

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	6 9 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415023.4
Pcw Rcv Da:		Northing:	3947782.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/06/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Lovato Grant	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1732804.0
Static Lev:	0	Y:	1699388.0
Tract Nbr:		Point Y:	35.67025991
Map Nbr:		Point X:	-105.93894071
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
519	ESE	0.96	5,078.66	7,255.23	WATER WELLS

License Nb:	253	District Office S:	
POD No:	29273	Surv Map:	USGS 7.5' QUAD SANTA FE
POD Rec No:	49702	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/01/1978, 12:00 AM	Restrict :	0.0
Finish Date:	09/05/1978, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	09/11/1978, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	182	UTM Zone:	13
Depth of Water:	85	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	12	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417514.5
Pcw Rcv Da:		Northing:	3948626.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/27/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	600700.0
Static Lev:	0	Y:	1702200.0
Tract Nbr:		Point Y:	35.6780821
Map Nbr:		Point X:	-105.91150524
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Talaya Hill/Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
520	WSW	0.96	5,064.99	7,026.32	WATER WELLS

License Nb:	0	District Office S:	
POD No:	27292	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	53939	Other Loc:	138 W Coronado Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	8A SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414560.7
Pcw Rcv Da:		Northing:	3948379.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/22/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ramona	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731261.0
Static Lev:	0	Y:	1701328.0
Tract Nbr:		Point Y:	35.67560292
Map Nbr:		Point X:	-105.94411604
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
521	SE	0.96	5,064.71	7,316.32	WATER WELLS

License Nb:	253	District Office S:	

Wells and Additional Sources Detail Report

POD No:	35536	Surv Map:	
POD Rec No:	24079	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/10/1981, 12:00 AM	Restrict :	0.0
Finish Date:	04/13/1981, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/24/1981, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	450	UTM Zone:	13
Depth of Water:	106	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	70	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417170.8
Pcw Rcv Da:		Northing:	3947960.6
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	06/18/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	599600.0
Static Lev:	0	Y:	1700000.0
Tract Nbr:		Point Y:	35.67204821
Map Nbr:		Point X:	-105.91523429
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
522	SW	0.96	5,061.77	7,055.91	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	622	District Office S:	
POD No:	57696	Surv Map:	
POD Rec No:	33932	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/27/1993, 12:00 AM	Restrict :	0.0
Finish Date:	07/28/1993, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/10/1993, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	355	UTM Zone:	13
Depth of Water:	200	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414824.2
Pcw Rcv Da:		Northing:	3947960.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/10/1993, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	591900.0
Static Lev:	0	Y:	1699900.0
Tract Nbr:		Point Y:	35.67184293
Map Nbr:		Point X:	-105.94116027
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
523	SW	0.96	5,088.40	7,074.46	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	29184	Surv Map:	USGS 7.5 QUAD SANTA FE
POD Rec No:	18603	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415004.7
Pcw Rcv Da:		Northing:	3947774.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/20/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	592500.0
Static Lev:	0	Y:	1699300.0
Tract Nbr:		Point Y:	35.67018888
Map Nbr:		Point X:	-105.93914649
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
524	E	0.97	5,137.69	7,197.90	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	21187	Surv Map:	
POD Rec No:	21074	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417580.5
Pcw Rcv Da:		Northing:	3949022.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/09/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	600900.0
Static Lev:	0	Y:	1703500.0
Tract Nbr:		Point Y:	35.68165136
Map Nbr:		Point X:	-105.91081649
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

525	SW	0.97	5,100.39	7,067.20	WATER WELLS

License Nb:	547	District Office S:	
POD No:	34702	Surv Map:	
POD Rec No:	243539	Other Loc:	1225 Seville Rd
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7 NA NA SF
Start Date:	07/03/2012, 12:00 AM	Restrict :	0.0
Finish Date:	07/09/2012, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	07/27/2012, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	500	UTM Zone:	13
Depth of Water:	122	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	55	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414899.7
Pcw Rcv Da:		Northing:	3947863.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Lovato Grant	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1732395.0
Static Lev:	0	Y:	1699648.0
Tract Nbr:		Point Y:	35.67097767
Map Nbr:		Point X:	-105.9403159
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

526	E	0.97	5,138.62	7,214.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35749	Surv Map:	
POD Rec No:	351493	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD 2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2-A NA NA SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	20
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417579.0
Pcw Rcv Da:		Northing:	3949092.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/01/2025, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	61703	X:	1741135.2
Static Lev:	0	Y:	1703792.3
Tract Nbr:		Point Y:	35.6822841
Map Nbr:		Point X:	-105.91084026
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
527	WSW	0.97	5,140.30	7,017.67	WATER WELLS

License Nb:	227	District Office S:	
POD No:	34453	Surv Map:	
POD Rec No:	40237	Other Loc:	908 Galisteo St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TC SF
Start Date:	06/03/1980, 12:00 AM	Restrict :	0.0
Finish Date:	06/05/1980, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	06/13/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	131	UTM Zone:	13
Depth of Water:	78	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414506.8
Pcw Rcv Da:		Northing:	3948453.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/04/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731081.0
Static Lev:	0	Y:	1701569.0
Tract Nbr:		Point Y:	35.67626717
Map Nbr:		Point X:	-105.94471946
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
528	WSW	0.97	5,135.06	7,026.38	WATER WELLS

License Nb:	228	District Office S:	
POD No:	42119	Surv Map:	
POD Rec No:	25726	Other Loc:	115 Coronado Lane
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 NA SF
Start Date:	04/12/1985, 12:00 AM	Restrict :	0.0
Finish Date:	04/22/1985, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	04/25/1985, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	70	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414573.7
Pcw Rcv Da:		Northing:	3948296.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Lovato Grant	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731307.0
Static Lev:	0	Y:	1701057.0
Tract Nbr:		Point Y:	35.67485848
Map Nbr:		Point X:	-105.94396363
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
530	WSW	0.97	5,147.83	7,026.59	WATER WELLS

License Nb:	0	District Office S:	
POD No:	42165	Surv Map:	
POD Rec No:	51519	Other Loc:	1104 Don Gaspar, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	15A 17 TJ SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414653.6
Pcw Rcv Da:		Northing:	3948144.2
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	05/17/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	414653.6
Static Lev:	0	Y:	3948144.2
Tract Nbr:		Point Y:	35.67348878
Map Nbr:		Point X:	-105.94306464
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal: Parcel Number: 1054098121218000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
531	SE	0.98	5,167.23	7,262.53	WATER WELLS

License Nb:	0	District Office S:	
POD No:	44385	Surv Map:	
POD Rec No:	9399	Other Loc:	704 Camino Cabra
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2A SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	30
Plug Date:		Township:	17N
Log File D:		Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417285.4
Pcw Rcv Da:		Northing:	3948055.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Armstrong	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1740215.0
Static Lev:	0	Y:	1700378.0
Tract Nbr:		Point Y:	35.67291247
Map Nbr:		Point X:	-105.91397789
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant : Talaya Hill/Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
532	SSW	0.98	5,153.87	7,086.89	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35267	Surv Map:	
POD Rec No:	40804	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4A NA NA
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415168.7
Pcw Rcv Da:		Northing:	3947634.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1733287.0
Static Lev:	0	Y:	1698908.0
Tract Nbr:		Point Y:	35.66893726
Map Nbr:		Point X:	-105.93731981
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
533	E	0.98	5,187.23	7,239.50	WATER WELLS

License Nb:	815	District Office S:	
POD No:	50329	Surv Map:	
POD Rec No:	60584	Other Loc:	1402 Cerro Gordo, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	41 1 SF
Start Date:	01/07/1989, 12:00 AM	Restrict :	0.0
Finish Date:	02/14/1989, 12:00 AM	Section:	20
Plug Date:		Township:	17N
Log File D:	02/23/1989, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	217	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-50329-/	Easting:	417585.1
Pcw Rcv Da:		Northing:	3949200.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/31/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	417585.1
Static Lev:	0	Y:	3949200.9
Tract Nbr:		Point Y:	35.68326457
Map Nbr:		Point X:	-105.91078399

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal: Parcel Number 1056099027032000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
534	SW	0.98	5,164.73	7,048.43	WATER WELLS

License Nb:	228	District Office S:	
POD No:	46975	Surv Map:	
POD Rec No:	70893	Other Loc:	110 E Barcelona Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	6 13 SF
Start Date:	05/04/1987, 12:00 AM	Restrict :	0.0
Finish Date:	05/06/1987, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	05/22/1987, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	340	UTM Zone:	13
Depth of Water:	110	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414762.0
Pcw Rcv Da:		Northing:	3947984.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/13/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Galisteo	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731938.0
Static Lev:	0	Y:	1700040.0
Tract Nbr:		Point Y:	35.67205843

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.94185007
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
535	SSW	0.98	5,166.13	7,120.56	WATER WELLS

License Nb:	547	District Office S:	
POD No:	70866	Surv Map:	
POD Rec No:	146313	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/25/1999, 12:00 AM	Restrict :	0.0
Finish Date:	01/26/1999, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	02/08/1999, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	260	UTM Zone:	13
Depth of Water:	115	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	26	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415549.3
Pcw Rcv Da:		Northing:	3947463.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/28/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	594300.0
Static Lev:	0	Y:	1698300.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.66742651
Map Nbr:		Point X:	-105.93309702
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
537	W	0.99	5,206.72	6,987.58	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31289	Surv Map:	
POD Rec No:	323699	Other Loc:	248 Anita Place
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	13 102 NA SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414414.1
Pcw Rcv Da:		Northing:	3948738.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/10/2019, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Sterns Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	414414.1

Wells and Additional Sources Detail Report

Static Lev:	0	Y:	3948738.9
Tract Nbr:		Point Y:	35.67882936
Map Nbr:		Point X:	-105.94577402
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
538	SE	0.98	5,194.31	7,328.23	WATER WELLS

License Nb:	253	District Office S:	
POD No:	40259	Surv Map:	
POD Rec No:	28562	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/09/1983, 12:00 AM	Restrict :	0.0
Finish Date:	09/10/1983, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	09/14/1983, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	137	UTM Zone:	13
Depth of Water:	35	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417170.1
Pcw Rcv Da:		Northing:	3947899.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/28/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:		X:	599600.0
Static Lev:	0	Y:	1699800.0
Tract Nbr:		Point Y:	35.67149912
Map Nbr:		Point X:	-105.91523576
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Sebastian De Vargas		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
539	SW	0.99	5,202.67	7,034.94	WATER WELLS

License Nb:	0	District Office S:	
POD No:	37074	Surv Map:	
POD Rec No:	26682	Other Loc:	1106 Don Gaspar, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414673.4
Pcw Rcv Da:		Northing:	3948083.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/06/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	591400.0
Static Lev:	0	Y:	1700300.0
Tract Nbr:		Point Y:	35.67294598
Map Nbr:		Point X:	-105.94283948
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
540	WNW	0.99	5,244.13	6,970.22	WATER WELLS

License Nb:	0	District Office S:	
POD No:	95469	Surv Map:	
POD Rec No:	297678	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414437.8
Pcw Rcv Da:		Northing:	3949407.7
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	41
Sys Date:	08/06/2015, 12:00 AM	Latitude Second:	5.5
Subdiv Nam:		Longitude Degree:	105

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	56
Ditch Name:		Longitude Second:	44.1
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.68486078
Map Nbr:		Point X:	-105.94558329
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
541	SSW	0.98	5,197.60	7,085.11	WATER WELLS

License Nb:	622	District Office S:	
POD No:	62724	Surv Map:	
POD Rec No:	32070	Other Loc:	317 Cordova Ln
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	6 TB SF
Start Date:	07/19/1995, 12:00 AM	Restrict :	2.0
Finish Date:	07/20/1995, 12:00 AM	Section:	25
Plug Date:		Township:	17N
Log File D:	08/01/1995, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	360	UTM Zone:	13
Depth of Water:	90	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415102.6
Pcw Rcv Da:		Northing:	3947661.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/25/2020, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:	Santa Fe Holding Co No. 1	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1733069.0
Static Lev:	0	Y:	1698994.0
Tract Nbr:		Point Y:	35.66917498
Map Nbr:		Point X:	-105.93805292
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
542	WSW	0.99	5,208.48	7,022.44	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34590	Surv Map:	
POD Rec No:	67652	Other Loc:	1103 Barcelona Lane
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	14B 17 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414612.7
Pcw Rcv Da:		Northing:	3948176.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	10/05/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Lovato Heights	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731440.0
Static Lev:	0	Y:	1700664.0
Tract Nbr:		Point Y:	35.67377733
Map Nbr:		Point X:	-105.94351996
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
543	E	0.99	5,248.35	7,234.75	WATER WELLS

License Nb:	622	District Office S:	
POD No:	34699	Surv Map:	
POD Rec No:	15787	Other Loc:	1402 Cerro Gordo Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2B
Start Date:	02/10/1981, 12:00 AM	Restrict :	0.0
Finish Date:	02/10/1981, 12:00 AM	Section:	20
Plug Date:		Township:	17N
Log File D:	02/19/1981, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	260	UTM Zone:	13
Depth of Water:	130	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	417607.9
Pcw Rcv Da:		Northing:	3949164.6
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	10/07/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1741227.0
Static Lev:	0	Y:	1704031.0
Tract Nbr:		Point Y:	35.68293923
Map Nbr:		Point X:	-105.91052834
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
544	WSW	0.99	5,239.02	7,008.24	WATER WELLS

License Nb:	0	District Office S:	
POD No:	42324	Surv Map:	
POD Rec No:	16972	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414465.2
Pcw Rcv Da:		Northing:	3948482.6

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/01/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	590700.0
Static Lev:	0	Y:	1701600.0
Tract Nbr:		Point Y:	35.6765232
Map Nbr:		Point X:	-105.94518215
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
545	WSW	0.99	5,231.21	7,028.74	WATER WELLS

License Nb:	0	District Office S:	
POD No:	07385	Surv Map:	
POD Rec No:	20267	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	25
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414643.3

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3948114.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/09/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	591300.0
Static Lev:	0	Y:	1700400.0
Tract Nbr:		Point Y:	35.67322194
Map Nbr:		Point X:	-105.94317531
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
546	S	0.99	5,221.75	7,188.25	WATER WELLS

License Nb:	214	District Office S:	
POD No:	29769	Surv Map:	
POD Rec No:	7905	Other Loc:	750 Camino Pinones
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	105 SF
Start Date:	02/09/1978, 12:00 AM	Restrict :	0.0
Finish Date:	02/10/1978, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	02/16/1978, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	285	UTM Zone:	13
Depth of Water:	160	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	415986.7
Pcw Rcv Da:		Northing:	3947379.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/19/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Devargas Development Co #2	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1735982.0
Static Lev:	0	Y:	1698106.0
Tract Nbr:		Point Y:	35.66671019
Map Nbr:		Point X:	-105.92825602
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
547	NW	1.00	5,258.32	6,965.97	WATER WELLS

License Nb:	0	District Office S:	
POD No:	51159	Surv Map:	
POD Rec No:	33033	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	24
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	414679.1
Pcw Rcv Da:		Northing:	3949947.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/28/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1731584.0
Static Lev:	0	Y:	1706477.0
Tract Nbr:		Point Y:	35.68974629
Map Nbr:		Point X:	-105.94297416
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
548	SSE	0.99	5,225.73	7,243.80	WATER WELLS

License Nb:	0	District Office S:	
POD No:	96346	Surv Map:	
POD Rec No:	303892	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416418.2
Pcw Rcv Da:		Northing:	3947433.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	09/19/2016, 12:00 AM	Latitude Second:	2.04
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	55
Ditch Name:		Longitude Second:	24.58
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66723367
Map Nbr:		Point X:	-105.92349458
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
549	N	0.99	5,232.60	7,073.41	WATER WELLS

License Nb:	622	District Office S:	
POD No:	36890	Surv Map:	
POD Rec No:	47363	Other Loc:	119 Valley Drive, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 SF
Start Date:	10/14/1981, 12:00 AM	Restrict :	0.0
Finish Date:	10/14/1981, 12:00 AM	Section:	18
Plug Date:		Township:	17N
Log File D:	10/21/1981, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	215	UTM Zone:	13
Depth of Water:	110	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	415978.6
Pcw Rcv Da:		Northing:	3950627.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/16/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Catron	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	415978.6
Static Lev:	0	Y:	3950627.4
Tract Nbr:		Point Y:	35.69598918
Map Nbr:		Point X:	-105.92868475
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1055099023489000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
551	SSE	1.00	5,259.27	7,265.90	WATER WELLS

License Nb:	547	District Office S:	
POD No:	34709	Surv Map:	
POD Rec No:	53338	Other Loc:	49 & 50 Mount Carmel Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/06/1980, 12:00 AM	Restrict :	0.0
Finish Date:	08/07/1980, 12:00 AM	Section:	30
Plug Date:		Township:	17N
Log File D:	08/09/1980, 12:00 AM	Range:	10E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	160	UTM Zone:	13
Depth of Water:	28	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	416831.0
Pcw Rcv Da:		Northing:	3947597.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1738743.0
Static Lev:	0	Y:	1698857.0
Tract Nbr:		Point Y:	35.66874797
Map Nbr:		Point X:	-105.91895103
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Radon Information

This section lists any relevant radon information found for the target property.

Federal EPA Radon Zone for *SANTA FE* County: **1**

Zone 1: Counties with predicted average indoor radon screening levels greater than 4 pCi/L
Zone 2: Counties with predicted average indoor radon screening levels from 2 to 4 pCi/L
Zone 3: Counties with predicted average indoor radon screening levels less than 2 pCi/L

Federal Area Radon Information for *SANTA FE* County

No Measures/Homes:	73
Geometric Mean:	3.2
Arithmetic Mean:	4.6
Median:	3.5
Standard Deviation:	3.8
Maximum:	21.6
% >4 pCi/L:	41
% >20 pCi/L:	1
Notes on Data Table:	TABLE 1. Screening indoor radon data from the EPA/State Residential Radon Survey of New Mexico conducted during 1988-89. Data represent 2-7 day charcoal canister measurements from the lowest level of each home tested.

Appendix

Federal Sources

FEMA National Flood Hazard Layer — **FEMA FLOOD**

The National Flood Hazard Layer (NFHL) data incorporates Flood Insurance Rate Map (FIRM) databases published by the Federal Emergency Management Agency (FEMA), and any Letters Of Map Revision (LOMRs) that have been issued against those databases since their publication date. The FIRM Database is the digital, geospatial version of the flood hazard information shown on the published paper FIRMs. The FIRM Database depicts flood risk information and supporting data used to develop the risk data. The FIRM Database is derived from Flood Insurance Studies (FISs), previously published FIRMs, flood hazard analyses performed in support of the FISs and FIRMs, and new mapping data, where available.

Indoor Radon Data — **INDOOR RADON**

Indoor radon measurements tracked by the Environmental Protection Agency(EPA) and the State Residential Radon Survey.

Public Water Systems Violations and Enforcement Data — **PWSV**

This list of drinking water violations and enforcement actions is sourced from the U.S Environmental Protection Agency's (EPA) Enforcement and Compliance History Online (ECHO) system that incorporates Public Water Systems data from EPA's Safe Drinking Water Information System (SDWIS) database, as part of the national download of Safe Drinking Water Act (SDWA) data. SDWIS contains information on public water systems from the Public Water System Supervision (PWSS) Program, including monitoring, enforcement, and violation data related to requirements established by the SWDA. Address information provided in SWDIS may correspond either with the physical location of the water system, or with a contact address.

Radon Zone Level — **RADON ZONE**

Areas showing the level of Radon Zones (level 1, 2 or 3) by county. This data is maintained by the Environmental Protection Agency (EPA).

Safe Drinking Water Information System (SDWIS) — **SDWIS**

This national download of Safe Drinking Water Act (SDWA) data is sourced from the U.S Environmental Protection Agency's (EPA) Enforcement and Compliance History Online (ECHO) system that incorporates Public Water Systems data from EPA's Safe Drinking Water Information System (SDWIS) database. SDWIS contains information on public water systems from the Public Water System Supervision (PWSS) Program related to requirements established by the Safe Drinking Water Act (SDWA). Address information provided in SWDIS may correspond either with the physical location of the water system, or with a contact address.

Soil Survey Geographic database — **SSURGO**

The Soil Survey Geographic database (SSURGO) contains information about soil as collected by the National Cooperative Soil Survey at the Natural Resources Conservation Service (NRCS). Soil maps outline areas called map units. The map units are linked to soil properties in a database. Each map unit may contain one to three major components and some minor components.

U.S. Fish & Wildlife Service Wetland Data — **US WETLAND**

The U.S. Fish & Wildlife Service Wetland layer represents the approximate location and type of wetlands and deepwater habitats in the United States.

USGS Current Topo — **US TOPO**

US Topo topographic maps are produced by the National Geospatial Program of the U.S. Geological Survey (USGS). The project was launched in late 2009, and the term "US Topo" refers specifically to quadrangle topographic maps published in 2009 and later.

USGS Geology — **US GEOLOGY**

Seamless maps depicting geological information provided by the United States Geological Survey (USGS).

USGS National Water Information System — **FED USGS**

The U.S. Geological Survey's (USGS) National Water Information System (NWIS) is the nation's principal repository of water resources data. The data includes comprehensive information of well-construction details, time-series data for gage height, streamflow, groundwater level, and precipitation and water use data. This NWIS database information is obtained through the Water Quality Data Portal (WQP). The WQP

is a cooperative service sponsored by the USGS, the Environmental Protection Agency (EPA), and the National Water Quality Monitoring Council (NWQMC).

State Sources

Oil and Gas Wells **OGW**

Oil and Gas Well Data collected by New Mexico Oil Conservation Division.

Point of Diversion Report **WATER WELLS**

Point of Diversion report provided by the New Mexico Office of the State Engineer (OSE). This data comes from the NM Water Rights Reporting System (NMWRRS). The report returns a summary of water rights use, owner, wells, point of diversion and location and other information. This list includes declared, complete, in-progress, and plugged wells.

Public Water Supply Wells **PWSW**

A list of public water supply systems maintained by the New Mexico Environment Department (NMED), Drinking Water Bureau (DWB). This database includes active and inactive public water systems.

Liability Notice

Reliance on information in Report: The Physical Setting Report (PSR) DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a review of environmental databases and physical characteristics for the site or adjacent properties.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS Information Inc. disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report(s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

APPENDIX E

User Provided Information

[RESERVED]

APPENDIX F

Historical Fire Insurance Maps

FIRE INSURANCE MAPS

Project Property: Universal Cleaners
622 Canyon Rd Santa Fe NM 87501
Project No: NMENV.M007.SF-WALDO
Requested By: INTERA Incorporated
Order No: 25121700733
Date Completed: December 17, 2025

Please note that no information was found for your site or adjacent properties.

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

APPENDIX G

Historical City Directories

CITY DIRECTORY

Project Property:	*Universal Cleaners* *622 Canyon Rd* *Santa Fe,NM 87501*
Project No:	*NMENV.M007.SF-WALDO*
Requested By:	*INTERA Incorporated*
Order No:	*25121700733*
Date Completed:	*December 19, 2025*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

December 19, 2025
RE: CITY DIRECTORY RESEARCH
622 Canyon Rd
Santa Fe,NM 87501

Thank you for contacting ERIS for an City Directory Search for the site described above. Our staff has conducted a reverse listing City Directory search to determine prior occupants of the subject site and adjacent properties. We have provided the nearest addresses(s) when adjacent addresses are not listed. If we have searched a range of addresses, all addresses in that range found in the Directory are included.

Note: Reverse Listing Directories generally are focused on more highly developed areas. Newly developed areas may be covered in the more recent years, but the older directories will tend to cover only the "central" parts of the city. To complete the search, we have either utilized the ACPL, Library of Congress, State Archives, and/or a regional library or history center as well as multiple digitized directories. These do not claim to be a complete collection of all reverse listing city directories produced.

ERIS has made every effort to provide accurate and complete information but shall not be held liable for missing, incomplete or inaccurate information. To complete this search we used the general range(s) below to search for relevant findings. If you believe there are additional addresses or streets that require searching please contact us at 866-517-5204.

Search Criteria:
550-700 of Canyon Rd
550-800 of E Alameda St
Search Notes:

Search Results Summary

Date	Source	Comment
2023	DIGITAL BUSINESS DIRECTORY	
2020	DIGITAL BUSINESS DIRECTORY	
2016	DIGITAL BUSINESS DIRECTORY	
2011	DIGITAL BUSINESS DIRECTORY	
2007	DIGITAL BUSINESS DIRECTORY	
2003	DIGITAL BUSINESS DIRECTORY	
2000	DIGITAL BUSINESS DIRECTORY	
1996	POLKS	
1993	POLKS	
1988	POLKS	
1983	POLKS	
1978	POLKS	
1973	POLKS	
1968	HUDSPETHS	
1964	HUDSPETHS	
1960	HUDSPETHS	
1955	HUDSPETHS	
1949	HUDSPETHS	
1944	HUDSPETHS	
1940	HUDSPETHS	
1936-37	HUDSPETHS	
1930-31	HUDSPETHS	
1928-29	HUDSPETHS	

2023 CANYON RD

SOURCE: DIGITAL BUSINESS DIRECTORY

550 **HOMEFROCKS STUDIO**...*WOMEN'S APPAREL-RETAIL*
550 **PUSHKIN GALLERY**...*ART GALLERIES & DEALERS*
550 **RADIOFREEAMERICA**...*NONCLASSIFIED ESTABLISHMENTS*
551 **CHESTER JOHNSON**...*RESIDENTIAL*
553 **E C THAW CHARITABLE TRUST**...*NON-PROFIT ORGANIZATIONS*
554 **PATRICIA CARLISLE FINE ART**...*ART GALLERIES & DEALERS*
555 **ROBER BRASHEARS**...*RESIDENTIAL*
555 **S R BRENNEN GALLERY**...*ART GALLERIES & DEALERS*
558 **GEBERT CONTEMPORARY**...*ART GALLERIES & DEALERS*
600 **KAY CONTEMPORARY ART**...*ART GALLERIES & DEALERS*
601 **ERNESTO MAYANS GALLERY**...*ART GALLERIES & DEALERS*
606 **BERNARND BUSCH**...*RESIDENTIAL*
608 **CLAIBORNE GALLERY**...*ANTIQUES-DEALERS*
608 **CLAIBORNE GALLERY**...*IMPORTERS (WHLS)*
610 **NEW CONCEPT GALLERY**...*ART GALLERIES & DEALERS*
616 **CATENARY ART GALLERY**...*ART GALLERIES & DEALERS*
616 **DEBORAH GOLD GALLERY**...*ART GALLERIES & DEALERS*
618 **CANYON ROAD ART BROKERAGE**...*ART GALLERIES & DEALERS*
618 **NORDWALL GALLERY & STUDIO**...*ART GALLERIES & DEALERS*
619 **TANSEY CONTEMPORARY**...*ART GALLERIES & DEALERS*
621 **BILL HESTER FINE ART**...*INDEPENDENT ARTISTS, WRITERS & PERFORMERS*
622 **CANYON ROAD CONTEMPORARY ART**...*ART GALLERIES & DEALERS*
622 **MARILYN BANE**...*RESIDENTIAL*
622 **WAXLANDER GALLERY**...*ART GALLERIES & DEALERS*
622 **WAXLANDER GALLERY**...*MURALS*
624 **JOE GONZALES**...*RESIDENTIAL*
626 **ELLEN BACIGALUPA**...*RESIDENTIAL*
634 **BRAD SMITH GALLERY**...*ART GALLERIES & DEALERS*
634 **SIX SEVEN**...*NONCLASSIFIED ESTABLISHMENTS*
640 **ACOSTA STRONG FINE ART**...*ART GALLERIES & DEALERS*
640 **GRANT HAYUNGA STUDIO GALLERY**...*ART GALLERIES & DEALERS*
640 **SHERRY LOSEY**...*RESIDENTIAL*
644 **CHRISTOPHER MARTIN GALLERY**...*ART GALLERIES & DEALERS*
644 **MARGARET MERTZ**...*RESIDENTIAL*
644 **MARTHA KEATS GALLERY**...*MUSEUMS*
644 **PATRICIA PIPKIN**...*RESIDENTIAL*
644 **ROBERT PIPKIN**...*RESIDENTIAL*
652 **AHMYO RIVER GALLERY**...*ART GALLERIES & DEALERS*
653 **BELLAS ARTES**...*MUSEUMS*
653 **BELLAS ARTES LTD**...*ART GALLERIES & DEALERS*
653 **COMPOUND RESTAURANT**...*BANQUET ROOMS*
653 **COMPOUND RESTAURANT**...*WEDDING & RECEPTION SITES*
653 **DAVID FLEISCHAKER**...*RESIDENTIAL*
653 **DEIRDRE HOWLEY**...*RESIDENTIAL*
653 **HAILEY KANARD**...*RESIDENTIAL*
653 **MEADE MARTIN**...*RESIDENTIAL*
653 **NARROW GATE SECURITY AGENCY**...*SECURITY CONTROL EQUIP & SYSTEMS-WHLS*
653 **SAM WOLF**...*RESIDENTIAL*
656 **KARINA ON CANYON LLC**...*RETAIL SHOPS*
656 **TRESA VORENBERG GOLDSMITHS**...*WATCHESREPAIRING*
656 **TRESA VORENBERG GOLDSMITHS**...*JEWELERS-RETAIL*
656 **TRESA VORENBERG GOLDSMITHS**...*JEWELRY DESIGNERS*
656 **TRESA VORENBERG GOLDSMITHS**...*JEWELRYREPAIRING*
660 **BRUCE BESSER**...*RESIDENTIAL*
662 **JOHN RIPPEL USA**...*NONCLASSIFIED ESTABLISHMENTS*
662 **KANIA FERRIN GALLERY**...*ANTIQUES-DEALERS*
662 **LAKIND GALLERY**...*ART GALLERIES & DEALERS*
667 **BITTER SWEET**...*JEWELERS-RETAIL*
667 **DANCING LADIES DE SANTA FE**...*SEWING SHOPS-CUSTOM*
667 **DANCING LADIES DE SANTA FE**...*CLOTHING-CUSTOM MADE*
669 **DELONEY NEWKIRK FINE ART**...*ART GALLERIES & DEALERS*
670 **NUART GALLERY**...*ART*
670 **NUART GALLERY**...*ART GALLERIES & DEALERS*
670 **VELADURA**...*NONCLASSIFIED ESTABLISHMENTS*

2023 E ALAMEDA ST

SOURCE: DIGITAL BUSINESS DIRECTORY

550 **CRAIG SMITH**...*RESIDENTIAL*
550 **ERIC ILLICK**...*RESIDENTIAL*
550 **JENNA ILLICK**...*RESIDENTIAL*
564 **DEBORAH SMITH**...*RESIDENTIAL*
607 **DIRK MEYER**...*RESIDENTIAL*
618 **LAURIE GUNST**...*RESIDENTIAL*
624 **AMADO GUTIERREZ**...*RESIDENTIAL*
624 **DENISE BETESH**...*NONCLASSIFIED ESTABLISHMENTS*
624 **KENNETH TERRY**...*RESIDENTIAL*
624 **LAYNE SMITH**...*RESIDENTIAL*
624 **PATTY VAUGHAN**...*RESIDENTIAL*
624 **QUE TENGA BUENA MANO**...*ART GALLERIES & DEALERS*
630 **DAVID JOHNSON**...*RESIDENTIAL*
630 **GRANVILLE GREENE**...*RESIDENTIAL*
630 **HOWARD BOBBS**...*RESIDENTIAL*
630 **IAN ARMSTRONG**...*RESIDENTIAL*
630 **STAN BERNING STUDIOS**...*NONCLASSIFIED ESTABLISHMENTS*
633 **CHARLES MACNEILL**...*RESIDENTIAL*
651 **SARAH RUSSELL**...*RESIDENTIAL*
701 **BARBARA CLACK**...*RESIDENTIAL*
701 **JASON CLACK**...*RESIDENTIAL*
701 **MARILYN BRADFORD**...*RESIDENTIAL*

2020 CANYON RD
SOURCE: DIGITAL BUSINESS DIRECTORY

77 total records. Part 1 of 2

550 **HOMEFROCKS STUDIO**...*WOMEN'S APPAREL-RETAIL*
550 **PUSHKIN GALLERY**...*ART GALLERIES & DEALERS*
550 **RADIOFREEAMERICA**...*NONCLASSIFIED ESTABLISHMENTS*
551 **CHESTER JOHNSON**...*RESIDENTIAL*
553 **E C THAW CHARITABLE TRUST**...*NON-PROFIT ORGANIZATIONS*
554 **PATRICIA CARLISLE FINE ART**...*MURALS*
554 **PATRICIA CARLISLE FINE ART**...*ART GALLERIES & DEALERS*
555 **ROBER BRASHEARS**...*RESIDENTIAL*
555 **S R BRENNEN GALLERY**...*ART GALLERIES & DEALERS*
558 **GEBERT CONTEMPORARY**...*ART GALLERIES & DEALERS*
600 **SELBY FLEETWOOD GALLERY**...*ART*
600 **SELBY FLEETWOOD GALLERY**...*ART GALLERIES & DEALERS*
601 **ERNESTO MAYANS GALLERY**...*ART GALLERIES & DEALERS*
602 **MEDICINE MAN GALLERY**...*ART GALLERIES & DEALERS*
602 **MEDICINE MAN GALLERY**...*NATIVE AMERICAN GOODS*
606 **BERNARND BUSCH**...*RESIDENTIAL*
608 **CLAIBORNE GALLERY**...*IMPORTERS (WHLS)*
608 **CLAIBORNE GALLERY**...*ANTIQUES-DEALERS*
610 **NEW CONCEPT GALLERY**...*ART GALLERIES & DEALERS*
616 **ANAHITA GALLERY**...*ART GALLERIES & DEALERS*
616 **CATENARY ART GALLERY**...*ART GALLERIES & DEALERS*
616 **DEBORAH GOLD GALLERY**...*ART GALLERIES & DEALERS*
618 **CANYON ROAD ART BROKERAGE**...*ART GALLERIES & DEALERS*
618 **NORDWALL GALLERY & STUDIO**...*ART GALLERIES & DEALERS*
619 **TANSEY CONTEMPORARY**...*UNCLASSIFIED ESTABLISHMENTS*
619 **TANSEY CONTEMPORARY**...*ART GALLERIES & DEALERS*
620 **GINA DENNIS**...*NONCLASSIFIED ESTABLISHMENTS*
621 **BILL HESTER FINE ART**...*INDEPENDENT ARTISTS, WRITERS & PERFORMERS*
622 **MARILYN BANE**...*RESIDENTIAL*
622 **WAXLANDER GALLERY**...*ART GALLERIES & DEALERS*
622 **WAXLANDER GALLERY**...*MURALS*
624 **JOE GONZALES**...*RESIDENTIAL*
626 **ELLEN BACIGALUPA**...*RESIDENTIAL*
630 **FRIENDS MEETING**...*CHURCHES*
634 **BRAD SMITH GALLERY**...*ART GALLERIES & DEALERS*
634 **SIX SEVEN**...*NONCLASSIFIED ESTABLISHMENTS*
640 **ACOSTA STRONG FINE ART**...*ARTISTS-FINE ARTS*
640 **SHERRY LOSEY**...*RESIDENTIAL*
644 **CHRISTOPHER MARTIN GALLERY**...*ART GALLERIES & DEALERS*
644 **FRANK CROFT FINE ART**...*ART GALLERIES & DEALERS*
644 **MARTHA KEATS GALLERY**...*MUSEUMS*
644 **PATRICIA PIPKIN**...*RESIDENTIAL*
651 **ZAPLIN-LAMPERT GALLERY**...*AUTOMOBILE APPRAISERS*
651 **ZAPLIN-LAMPERT GALLERY**...*MURALS*
651 **ZAPLIN-LAMPERT GALLERY**...*APPRAISERS*
651 **ZAPLIN-LAMPERT GALLERY**...*ART GALLERIES & DEALERS*
652 **AHMYO RIVER GALLERY**...*ART GALLERIES & DEALERS*
652 **JANE SAUER GALLERY**...*MURALS*
652 **JANE SAUER GALLERY**...*ART GALLERIES & DEALERS*
653 **BELLAS ARTES**...*MUSEUMS*
653 **BELLAS ARTES LTD**...*ART GALLERIES & DEALERS*
653 **COMPOUND RESTAURANT**...*WEDDING & RECEPTION SITES*
653 **COMPOUND RESTAURANT**...*BANQUET ROOMS*
653 **DAVID FLEISCHAKER**...*RESIDENTIAL*
653 **DEIRDRE HOWLEY**...*RESIDENTIAL*
653 **HAILEY KANARD**...*RESIDENTIAL*
653 **MEADE MARTIN**...*RESIDENTIAL*
653 **NARROW GATE SECURITY AGCY LLC**...*SECURITY CONTROL EQUIP & SYSTEMS-WHLS*
653 **SAM WOLF**...*RESIDENTIAL*
656 **KARINA ON CANYON LLC**...*RETAIL SHOPS*
656 **SILVER SUN**...*NATIVE AMERICAN GOODS-WHOLESALE*
656 **SILVER SUN**...*NATIVE AMERICAN GOODS*
656 **TRESA VORENBERG GOLDSMITHS**...*WATCHESREPAIRING*
656 **TRESA VORENBERG GOLDSMITHS**...*JEWELRYREPAIRING*
656 **TRESA VORENBERG GOLDSMITHS**...*JEWELRY DESIGNERS*
656 **TRESA VORENBERG GOLDSMITHS**...*JEWELERS-RETAIL*
660 **BRUCE BESSER**...*RESIDENTIAL*
662 **JOHN RIPPEL USA**...*NONCLASSIFIED ESTABLISHMENTS*

Part 2 of 2

662 **KANIA-FERRIN GALLERY**...*ANTIQUES-DEALERS*
662 **LAKIND GALLERY**...*ART GALLERIES & DEALERS*
667 **BITTER SWEET**...*JEWELERS-RETAIL*
667 **DANCING LADIES DE SANTA FE**...*CLOTHING-CUSTOM MADE*
667 **DANCING LADIES DE SANTA FE**...*SEWING SHOPS-CUSTOM*
669 **DELONEY NEWKIRK FINE ART**...*ART GALLERIES & DEALERS*
670 **NUART GALLERY**...*ART GALLERIES & DEALERS*
670 **NUART GALLERY**...*ART*
670 **VELADURA**...*NONCLASSIFIED ESTABLISHMENTS*

2020 E ALAMEDA ST

SOURCE: DIGITAL BUSINESS DIRECTORY

550 **CRAIG SMITH**...*RESIDENTIAL*
550 **ERIC ILLICK**...*RESIDENTIAL*
564 **DEBORAH SMITH**...*RESIDENTIAL*
607 **DIRK MEYER**...*RESIDENTIAL*
618 **LAURIE GUNST**...*RESIDENTIAL*
624 **AMADO GUTIERREZ**...*RESIDENTIAL*
624 **DENISE BETESH**...*NONCLASSIFIED ESTABLISHMENTS*
624 **KENNETH TERRY**...*RESIDENTIAL*
624 **LAYNE SMITH**...*RESIDENTIAL*
624 **PATTY VAUGHAN**...*RESIDENTIAL*
624 **QUE TENGA BUENA MANO**...*ART GALLERIES & DEALERS*
630 **DAVID JOHNSON**...*RESIDENTIAL*
630 **FRESH MIND CUISINE**...*RESTAURANTS*
630 **GRANVILLE GREENE**...*RESIDENTIAL*
630 **HOWARD BOBBS**...*RESIDENTIAL*
630 **IAN ARMSTRONG**...*RESIDENTIAL*
630 **STAN BERNING STUDIOS**...*NONCLASSIFIED ESTABLISHMENTS*
633 **CHARLES MACNEILL**...*RESIDENTIAL*
651 **SARAH RUSSELL**...*RESIDENTIAL*
701 **BARBARA CLACK**...*RESIDENTIAL*
701 **JASON CLACK**...*RESIDENTIAL*
705 **EDDY RICHARD LIFESTYLE CHFFR**...*LIMOUSINE SERVICE*

2016 CANYON RD

SOURCE: DIGITAL BUSINESS DIRECTORY

72 total records. Part 1 of 2

550 **PUSHKIN GALLERY**...*ART GALLERIES & DEALERS*
551 **ANTIQUE CLOCK REPAIR**...*CLOCKS-REPAIRING & PARTS*
553 **E C THAW CHARITABLE TRUST**...*NON-PROFIT ORGANIZATIONS*
554 **PATRICIA CARLISLE FINE ART**...*ART GALLERIES & DEALERS*
555 **ROBER BRASHEARS**...*RESIDENTIAL*
555 **S R BRENNEN GALLERY**...*ART GALLERIES & DEALERS*
558 **GEBERT CONTEMPORARY**...*ART GALLERIES & DEALERS*
600 **ERS**...*NONCLASSIFIED ESTABLISHMENTS*
600 **SELBY FLEETWOOD GALLERY**...*ART GALLERIES & DEALERS*
601 **ERNESTO MAYANS GALLERY**...*ART GALLERIES & DEALERS*
602 **MEDICINE MAN GALLERY**...*NATIVE AMERICAN GOODS*
602 **MEDICINE MAN GALLERY**...*ART GALLERIES & DEALERS*
606 **BERNARND BUSCH**...*RESIDENTIAL*
608 **CLAIBORNE GALLERY**...*IMPORTERS (WHLS)*
608 **CLAIBORNE GALLERY**...*ANTIQUES-DEALERS*
610 **NEW CONCEPT GALLERY**...*ART GALLERIES & DEALERS*
610 **RIVER TRADING POST**...*NATIVE AMERICAN GOODS*
613 **ADIEB KHADOURE FINE ARTS**...*CARPET & RUG DEALERS-NEW*
613 **ADIEB KHADOURE FINE ARTS**...*ART GALLERIES & DEALERS*
613 **JULIA VIGIL**...*RESIDENTIAL*
613 **PAUL VIGIL**...*RESIDENTIAL*
616 **ANAHITA GALLERY**...*ART GALLERIES & DEALERS*
616 **CANYON HIDEOUT**...*COFFEE SHOPS*
616 **CATENARY ART GALLERY**...*ART GALLERIES & DEALERS*
616 **DEBORAH GOLD GALLERY**...*ART GALLERIES & DEALERS*
616 **HANDSEL GALLERY**...*ART GALLERIES & DEALERS*
618 **CANYON ROAD ART BROKERAGE**...*ART GALLERIES & DEALERS*
618 **NORDWALL GALLERY & STUDIO**...*ART GALLERIES & DEALERS*
619 **SCULPTURE 619**...*ART GALLERIES & DEALERS*
619 **TANSEY CONTEMPORARY**...*UNCLASSIFIED ESTABLISHMENTS*
621 **BILL HESTER FINE ART**...*INDEPENDENT ARTISTS, WRITERS & PERFORMERS*
621 **DOMINIQUE BOISJOLI FINE ART**...*ARTISTS-FINE ARTS*
622 **MARILYN BANE**...*RESIDENTIAL*
622 **WAXLANDER GALLERY**...*ART GALLERIES & DEALERS*
624 **JOE GONZALES**...*RESIDENTIAL*
624 **JOSE GONZALES**...*RESIDENTIAL*
626 **ELLEN BACIGALUPA**...*RESIDENTIAL*
630 **FRIENDS MEETING**...*CHURCHES*
630 **OLIVE RUSH GUEST APT**...*APARTMENTS*
634 **BRAD SMITH GALLERY**...*ART GALLERIES & DEALERS*
640 **ACOSTA STRONG FINE ART**...*ARTISTS-FINE ARTS*
644 **FRANK CROFT FINE ART**...*ART GALLERIES & DEALERS*
644 **MARGARET MERTZ**...*RESIDENTIAL*
644 **MARTHA KEATS GALLERY**...*ART GALLERIES & DEALERS*
644 **NANCY MERTZ**...*RESIDENTIAL*
644 **PATRICIA PIPKIN**...*RESIDENTIAL*
644 **ROBERT PIPKIN**...*RESIDENTIAL*
651 **ZAPLIN-LAMPERT GALLERY**...*APPRAISERS*
651 **ZAPLIN-LAMPERT GALLERY**...*ART GALLERIES & DEALERS*
652 **JANE SAUER GALLERY**...*ART GALLERIES & DEALERS*
652 **THIRTEEN MOONS GALLERY**...*ART GALLERIES & DEALERS*
653 **BELLAS ARTES LTD**...*ART GALLERIES & DEALERS*
653 **COMPOUND RESTAURANT**...*BANQUET ROOMS*
653 **DAVID FLEISCHAKER**...*RESIDENTIAL*
653 **DEIRDRE HOWLEY**...*RESIDENTIAL*
653 **HAILEY KANARD**...*RESIDENTIAL*
653 **MEADE MARTIN**...*RESIDENTIAL*
653 **ROBIN MARTIN**...*RESIDENTIAL*
653 **SAM WOLF**...*RESIDENTIAL*
653 **SUSAN KANARD**...*RESIDENTIAL*
656 **SILVER SUN**...*NATIVE AMERICAN GOODS*
656 **SILVER SUN**...*NATIVE AMERICAN GOODS-MANUFACTURERS*
656 **SILVER SUN**...*NATIVE AMERICAN GOODS-WHOLESALE*
656 **TRESA VORENBERG GOLDSMITHS**...*JEWELERS-RETAIL*
656 **TRESA VORENBERG GOLDSMITHS**...*JEWELRY DESIGNERS*
660 **BRUCE BESSER**...*RESIDENTIAL*
662 **KANIA-FERRIN GALLERY**...*ANTIQUES-DEALERS*
662 **LAKIND GALLERY**...*ART GALLERIES & DEALERS*

2016 CANYON RD

SOURCE: DIGITAL BUSINESS DIRECTORY

Part 2 of 2

667 **DANCING LADIES DE SANTA FE**...*CLOTHING-CUSTOM MADE*
669 **DELONEY NEWKIRK FINE ART**...*ART GALLERIES & DEALERS*
670 **NUART GALLERY**...*ART GALLERIES & DEALERS*
670 **VELADURA**...*NONCLASSIFIED ESTABLISHMENTS*

2016 E ALAMEDA ST

SOURCE: DIGITAL BUSINESS DIRECTORY

550 **CRAIG SMITH**...*RESIDENTIAL*
550 **ERIC ILLICK**...*RESIDENTIAL*
550 **JENNA ILLICK**...*RESIDENTIAL*
550 **JOSEPH ILLICK**...*RESIDENTIAL*
564 **DEBORAH SMITH**...*RESIDENTIAL*
607 **DIRK MEYER**...*RESIDENTIAL*
624 **AMADO GUTIERREZ**...*RESIDENTIAL*
624 **JAMES VAUGHAN JR**...*RESIDENTIAL*
624 **KENNETH TERRY**...*RESIDENTIAL*
624 **LAYNE SMITH**...*RESIDENTIAL*
624 **MARYLINDA GUTIERREZ**...*RESIDENTIAL*
624 **PATTY VAUGHAN**...*RESIDENTIAL*
624 **QUE TENGA BUENA MANO**...*ART GALLERIES & DEALERS*
630 **DAVID JOHNSON**...*RESIDENTIAL*
630 **FRESH MIND CUISINE**...*RESTAURANTS*
630 **HOWARD BOBBS**...*RESIDENTIAL*
630 **IAN ARMSTRONG**...*RESIDENTIAL*
630 **KATRINA GODSHALK**...*RESIDENTIAL*
630 **MARGERY JOHNSON**...*RESIDENTIAL*
630 **MARIEL JOHNSON**...*RESIDENTIAL*
630 **SHEILA ARMSTRONG**...*RESIDENTIAL*
630 **STAN BERNING STUDIOS**...*NONCLASSIFIED ESTABLISHMENTS*
633 **CHARLES MACNEILL**...*RESIDENTIAL*
651 **SARAH RUSSELL**...*RESIDENTIAL*
701 **BARBARA CLACK**...*RESIDENTIAL*
701 **JASON CLACK**...*RESIDENTIAL*
705 **DAVID BLOOM**...*RESIDENTIAL*
705 **EDDY RICHARD LIFESTYLE CHFFR**...*LIMOUSINE SERVICE*
705 **PAMELA WELLS**...*RESIDENTIAL*

93 total records. Part 1 of 2

550 PUSHKIN GALLERY...ART DEALERS
551 ANTIQUE CLOCK REPAIR...OTHER HOUSEHOLD GOODS REPAIR & MAINTENANCE
553 E C THAW CHARITABLE TRUST...OTHER SOCIAL ADVOCACY ORGANIZATIONS
554 PATRICIA CARLISLE FINE ART...ART DEALERS
555 NEDRA MATTEUCCI FINE ART...ART DEALERS
555 RICHARD MATTEUCCI...RESIDENTIAL
558 GEBERT CONTEMPORARY...ART DEALERS
600 PAUL ROCHFORD...RESIDENTIAL
600 SELBY FLEETWOOD GALLERY...ART DEALERS
601 ERNESTO MAYANS...RESIDENTIAL
601 ERNESTO MAYANS GALLERY...ART DEALERS
602 MEDICINE MAN GALLERY...USED MERCHANDISE STORES
608 CLAIBORNE GALLERY...USED MERCHANDISE STORES
608 OMER CLAIBORNE...RESIDENTIAL
610 ADIEB KHADOURE FINE ARTS...ART DEALERS
610 FRANCESCA KECK...RESIDENTIAL
610 NEW CONCEPT GALLERY...ART DEALERS
610 RIVER TRADING POST...ART DEALERS
613 ADP HOMEBUILDERS...NEW SINGLE-FAMILY GENERAL CONTRS
613 WILLIAM BROWN...RESIDENTIAL
616 DEBORAH GOLD GALLERY...ART DEALERS
616 HANDSEL GALLERY...ART DEALERS
616 TAI GALLERY/TEXTILE ARTS...ART DEALERS
617 D TRUJILLO...RESIDENTIAL
617 MICHAEL COCHRAN...RESIDENTIAL
618 ADIEB NISSAN...RESIDENTIAL
618 NORDWALL STUDIO...ART DEALERS
618 RICHARD CAMPIGLIO...RESIDENTIAL
619 SCULPTURE 619...ART DEALERS
620 CAROLA BELL...RESIDENTIAL
621 CANYON ROAD FINE ART...ART DEALERS
621 GLENN OLAH...RESIDENTIAL
622 J HUMPHREYS...RESIDENTIAL
622 WAXLANDER GALLERY...ART DEALERS
626 ELLEN BACIGALUPA...RESIDENTIAL
630 FRIENDS MEETING...RELIGIOUS ORGANIZATION
630 OLIVE RUSH GUEST APT...LESSORS OF RESIDENTIAL BUILDINGS
630 ROLAND POOL...RESIDENTIAL
634 DELONEY NEWKIRK FINE ART...ART DEALERS
634 TIM PARROTT...RESIDENTIAL
640 BILL THORNTON...RESIDENTIAL
640 DARNELL FINE ART...ART DEALERS
640 SHERRY LOSEY...RESIDENTIAL
641 JEFFREY THURSTON...RESIDENTIAL
644 DEBORAH LEHAN...RESIDENTIAL
644 DONALD PIPKIN...RESIDENTIAL
644 FRANK CROFT...RESIDENTIAL
644 FRANK CROFT FINE ART...ART DEALERS
644 MARTHA KEATS GALLERY...ART DEALERS
644 PATRICIA PIPKIN...RESIDENTIAL
644 REBECCA PIPKIN...RESIDENTIAL
644 ROBERT PIPKIN...RESIDENTIAL
644 SALLIE HAMPTON...RESIDENTIAL
651 KELLY GLASGOW...RESIDENTIAL
651 MARK ZAPLIN...RESIDENTIAL
651 ZAPLIN-LAMPERT GALLERY...ART DEALERS
653 BARBARA CHRISTIAN...RESIDENTIAL
653 BELLAS ARTES LTD...ART DEALERS
653 COMPOUND RESTAURANT...FULL-SERVICE RESTAURANTS
653 DAVID FLEISCHAKER...RESIDENTIAL
653 DEBBIE FLEISCHAKER...RESIDENTIAL
653 DEIRDRE HOWLEY...RESIDENTIAL
653 DILWORTH SELLERS...RESIDENTIAL
653 HAILEY KANARD...RESIDENTIAL
653 J BENNETT...RESIDENTIAL
653 JUDITH SELLERS...RESIDENTIAL
653 KATHERINE LOO...RESIDENTIAL
653 LESTER LOO...RESIDENTIAL

2011 CANYON RD
SOURCE: DIGITAL BUSINESS DIRECTORY

Part 2 of 2

653 LINDA NELSON...RESIDENTIAL
653 MEADE MARTIN...RESIDENTIAL
653 ROBERT CUSTER...RESIDENTIAL
653 ROBIN MARTIN...RESIDENTIAL
653 ROBYN ROGERS...RESIDENTIAL
653 ROSE DEWINDT...RESIDENTIAL
653 SAM WOLF...RESIDENTIAL
653 SUSAN KANARD...RESIDENTIAL
656 CABALLO FINE CUSTOM BELTS...LUGGAGE & LEATHER GOODS STORES
656 CHERYL INGRAM...RESIDENTIAL
656 HELEN HARDIN ESTATE...ART DEALERS
656 MERRILY PIERSON...RESIDENTIAL
656 SILVER SUN...GIFT, NOVELTY, & SOUVENIR STORES
656 TRESA VORENBERG GOLDSMITHS...JEWELRY STORES
656 VORENBERG TRESA...RESIDENTIAL
660 BESSER GROUP...LAND SUBDIVISION
660 BRUCE BESSER...RESIDENTIAL
662 JERRY PORTER...RESIDENTIAL
662 MARY PORTER...RESIDENTIAL
662 PETER JOHNSON...RESIDENTIAL
667 DANCING LADIES DE SANTA FE...OTHER CLOTHING STORES
667 LA BODEGA...JEWELRY STORES
668 KLAUDIA MARR GALLERY...ART DEALERS
668 MARR KLAUDIA...RESIDENTIAL
670 NUART GALLERY...ART DEALERS

2011 E ALAMEDA ST

SOURCE: DIGITAL BUSINESS DIRECTORY

550 **CRAIG SMITH**...*RESIDENTIAL*
550 **GINA BROWNING**...*RESIDENTIAL*
550 **GINA ILLICK**...*RESIDENTIAL*
550 **JENNA ILLICK**...*RESIDENTIAL*
550 **JOSEPH ILLICK**...*RESIDENTIAL*
550 **VIRGINIA BROWNING**...*RESIDENTIAL*
605 **DANA FRICKE**...*RESIDENTIAL*
605 **KARL FRICKE**...*RESIDENTIAL*
605 **M BAUMANN**...*RESIDENTIAL*
605 **ROBERT BAUMANN**...*RESIDENTIAL*
607 **DARRELL MEYER**...*RESIDENTIAL*
616 **ROBERT HEATON**...*RESIDENTIAL*
617 **DIANA JARAMILLO**...*RESIDENTIAL*
618 **CHERYLE OSBORN**...*RESIDENTIAL*
618 **DAN TARDELLA**...*RESIDENTIAL*
624 **AMADO GUTIERREZ**...*RESIDENTIAL*
624 **CHRISTOPHER BOWER**...*RESIDENTIAL*
624 **CYNTHIA KRISTENSEN**...*RESIDENTIAL*
624 **DAWN BOWER**...*RESIDENTIAL*
624 **FRED YATES**...*RESIDENTIAL*
624 **GRANT LAFARGE**...*RESIDENTIAL*
624 **JAMES LUTTJOHANN**...*RESIDENTIAL*
624 **JILL SULLIVAN**...*RESIDENTIAL*
624 **KATHRYN LEWIS**...*RESIDENTIAL*
624 **LEW SULLIVAN**...*RESIDENTIAL*
624 **MARY PERRY**...*RESIDENTIAL*
624 **MARY WILLIAMS**...*RESIDENTIAL*
624 **MARYLINDA GUTIERREZ**...*RESIDENTIAL*
624 **NANCY SULLIVAN**...*RESIDENTIAL*
624 **O PERRY**...*RESIDENTIAL*
624 **PATRICIA LAFARGE**...*RESIDENTIAL*
624 **PETER LEWIS**...*RESIDENTIAL*
624 **PETER SULLIVAN**...*RESIDENTIAL*
624 **RICK SMITH**...*RESIDENTIAL*
624 **ROXANNE YATES**...*RESIDENTIAL*
624 **VERE GAYNOR**...*RESIDENTIAL*
624 **WILLIAM FRISSELL**...*RESIDENTIAL*
630 **DAVID JOHNSON**...*RESIDENTIAL*
630 **FRANK CROFT**...*RESIDENTIAL*
630 **GRANVILLE GREENE**...*RESIDENTIAL*
630 **HOWARD BOBBS**...*RESIDENTIAL*
630 **SHEILA ARMSTRONG**...*RESIDENTIAL*
635 **PATRICK DONLEY**...*RESIDENTIAL*
651 **JOHN RUSSELL**...*RESIDENTIAL*
651 **SARAH RUSSELL**...*RESIDENTIAL*
701 **ALMA HORN**...*RESIDENTIAL*
701 **ANDREA HORN**...*RESIDENTIAL*
701 **BERNADETTE BARTLETT**...*RESIDENTIAL*
701 **DAVE HORN**...*RESIDENTIAL*
701 **ROBERT HORN**...*RESIDENTIAL*
705 **DANA HASSETT**...*RESIDENTIAL*
705 **DAVID BLOOM**...*RESIDENTIAL*
705 **PAMELA WELLS**...*RESIDENTIAL*
705 **PAULA OFLANAGAN**...*RESIDENTIAL*

2007 CANYON RD

SOURCE: DIGITAL BUSINESS DIRECTORY

105 total records. Part 1 of 2

550 **PUSHKIN GALLERY**...*ART GALLERIES & DEALERS*
551 **ANTIQUE CLOCK REPAIR**...*CLOCKS-REPAIRING & PARTS*
551 **CHESTER JOHNSON**...*RESIDENTIAL*
553 **E C THAW CHARITABLE TRUST**...*NON-PROFIT ORGANIZATIONS*
554 **PATRICIA CARLISLE FINE ART**...*ART GALLERIES & DEALERS*
555 **S R BRENNEN GALLERY**...*ART GALLERIES & DEALERS*
558 **GEBERT CONTEMPORARY**...*ART GALLERIES & DEALERS*
570 **PETER RIVERA**...*RESIDENTIAL*
586 **JOSEPH ILLICK**...*RESIDENTIAL*
586 **V BROWNING**...*RESIDENTIAL*
600 **B W BUSCH**...*RESIDENTIAL*
600 **SELBY FLEETWOOD GALLERY**...*ART GALLERIES & DEALERS*
601 **ANNA M PEREA**...*RESIDENTIAL*
601 **ERNESTO MAYANS GALLERY**...*ART GALLERIES & DEALERS*
602 **MEDICINE MAN GALLERY**...*ANTIQUES-DEALERS*
604 **E S GLENN**...*RESIDENTIAL*
608 **CLAIBORNE GALLERY**...*ANTIQUES-DEALERS*
610 **KHADOURE F ADIEB**...*RESIDENTIAL*
610 **LYNN YOUNGER**...*RESIDENTIAL*
610 **NEW CONCEPT GALLERY**...*ART GALLERIES & DEALERS*
610 **RIVER TRADING POST**...*ART GALLERIES & DEALERS*
610 **S E GARCIA**...*RESIDENTIAL*
613 **ADIEB KHADOURE FINE ARTS**...*ART GALLERIES & DEALERS*
613 **IGNACIO L VIGIL**...*RESIDENTIAL*
613 **WILLIAM W BROWN**...*RESIDENTIAL*
616 **ANAHITA INTERNATIONAL PHTGRPHY**...*ART GALLERIES & DEALERS*
616 **CANYON HIDEOUT**...*COFFEE SHOPS*
616 **DEBORAH GOLD GALLERY**...*ART GALLERIES & DEALERS*
616 **DISH N SPOON GIFTS**...*KITCHEN ACCESSORIES*
616 **F MACDOUGALL**...*RESIDENTIAL*
616 **FLORENCE MACDOUGALL**...*RESIDENTIAL*
616 **HANDSEL GALLERY**...*ART GALLERIES & DEALERS*
617 **PEG J WOOD**...*RESIDENTIAL*
617 **THELMA BURKE**...*RESIDENTIAL*
618 **NORDWALL GALLERY & STUDIO**...*ART GALLERIES & DEALERS*
618 **ROBERT GILORMO**...*RESIDENTIAL*
619 **SCULPTURE 619**...*ART GALLERIES & DEALERS*
620 **LINDEN K GILBERT**...*RESIDENTIAL*
620 **VICTORIA M STOLL**...*RESIDENTIAL*
621 **DOMINIQUE BOISJOLI FINE ART**...*ART GALLERIES & DEALERS*
621 **PERCY ORTIZ**...*RESIDENTIAL*
622 **J R HUMPHREYS**...*RESIDENTIAL*
622 **LORETTO ROMERO**...*RESIDENTIAL*
622 **M A BANE**...*RESIDENTIAL*
622 **MARGRET H**...*RESIDENTIAL*
622 **WAXLANDER GALLERY**...*ART GALLERIES & DEALERS*
624 **JOE A GONZALES**...*RESIDENTIAL*
626 **A & E BACIGALUPA**...*RESIDENTIAL*
628 **J PENELOPE**...*RESIDENTIAL*
628 **JUDITH & ROY STEPHENSON**...*RESIDENTIAL*
630 **FRIENDS MEETING**...*CHURCHES*
630 **OLIVE RUSH GUEST APT**...*APARTMENTS*
630 **S COHEN**...*RESIDENTIAL*
634 **ALICE PARROTT**...*RESIDENTIAL*
634 **DELONEY NEWKIRK FINE ART**...*ART GALLERIES & DEALERS*
634 **MARK VALDES**...*RESIDENTIAL*
634 **SMITH OBA FINE ART**...*ART GALLERIES & DEALERS*
639 **K C CHEESEMAN**...*RESIDENTIAL*
640 **DARNELL FINE ART**...*ART GALLERIES & DEALERS*
640 **GRAHAM E JONES**...*RESIDENTIAL*
640 **RONALD MALLORY**...*RESIDENTIAL*
641 **J M MRS KIRTLEY**...*RESIDENTIAL*
641 **LOUISE TAICHERT**...*RESIDENTIAL*
644 **FRANK CROFT FINE ART**...*ART GALLERIES & DEALERS*
644 **JAMES FARIS**...*RESIDENTIAL*
644 **MARTHA KEATS GALLERY**...*ART GALLERIES & DEALERS*
644 **MARY EMMERLING**...*RESIDENTIAL*
650 **MICHAEL PATERNITI**...*RESIDENTIAL*
650 **S CORBETT**...*RESIDENTIAL*

2007 CANYON RD

SOURCE: DIGITAL BUSINESS DIRECTORY

Part 2 of 2

651 **ZAPLIN-LAMPERT GALLERY**...*ART GALLERIES & DEALERS*
652 **THIRTEEN MOONS GALLERY**...*ART GALLERIES & DEALERS*
653 **ADELINE FLEISCHAKER**...*RESIDENTIAL*
653 **BELLAS ARTES LTD**...*ART GALLERIES & DEALERS*
653 **CASWELL SILVER**...*RESIDENTIAL*
653 **COMPOUND RESTAURANT**...*RESTAURANTS*
653 **D P SELLERS**...*RESIDENTIAL*
653 **E H DENDAHL**...*RESIDENTIAL*
653 **EDWARD M NICHOLAS**...*RESIDENTIAL*
653 **GINGER EVANS**...*RESIDENTIAL*
653 **HAILEY & SUSAN KANARD**...*RESIDENTIAL*
653 **J A JR HOULE**...*RESIDENTIAL*
653 **J M SAMUEL**...*RESIDENTIAL*
653 **JERRY STIRMAN**...*RESIDENTIAL*
653 **JUDY RHYMES**...*RESIDENTIAL*
653 **LESTER B LOO**...*RESIDENTIAL*
653 **MILTON H WARD**...*RESIDENTIAL*
653 **N REICHMAN**...*RESIDENTIAL*
653 **PHILLIP CITRIN**...*RESIDENTIAL*
656 **HELEN HARDIN ESTATE**...*ART GALLERIES & DEALERS*
656 **MERRILY PIERSON**...*RESIDENTIAL*
656 **SILVER SUN**...*NATIVE AMERICAN GOODS-MANUFACTURERS*
656 **TRESA VORENBERG GOLDSMITHS**...*JEWELRY DESIGNERS*
662 **CLAY & STONE**...*POTTERY*
662 **LAKIND GALLERY**...*ART GALLERIES & DEALERS*
662 **M DIAMOND**...*RESIDENTIAL*
667 **DANCING LADIES DE SANTA FE**...*CLOTHING-CUSTOM MADE*
667 **TICHAVA MILLS FINEART**...*ART GALLERIES & DEALERS*
668 **FRED SPENCER**...*RESIDENTIAL*
668 **JIM B LOWREY**...*RESIDENTIAL*
669 **DELONEY NEWKIRK FINE ART**...*ART GALLERIES & DEALERS*
669 **MATTHEW'S GALLERY**...*ART GALLERIES & DEALERS*
669 **STEVE BOONE**...*RESIDENTIAL*
670 **CAROL HENLE**...*RESIDENTIAL*
670 **NUART GALLERY**...*ART GALLERIES & DEALERS*
670 **S BROADHURST**...*RESIDENTIAL*

2007 E ALAMEDA ST

SOURCE: DIGITAL BUSINESS DIRECTORY

550 **CLEVES DR WEBER**...*RESIDENTIAL*
550 **STEVEN WEBER**...*RESIDENTIAL*
605 **MARIA ANDERSON**...*RESIDENTIAL*
607 **JAMES PEARL**...*RESIDENTIAL*
609 **INGRID FERGUSON**...*RESIDENTIAL*
611 **MERRITT PAULSON**...*RESIDENTIAL*
614 **J K TREAT**...*RESIDENTIAL*
615 **RAND L CARROLL**...*RESIDENTIAL*
616 **BARBARA HILL**...*RESIDENTIAL*
616 **GORDON TRAVERS**...*RESIDENTIAL*
617 **ROBERT MERCER**...*RESIDENTIAL*
618 **BARBARA MABLI**...*RESIDENTIAL*
618 **PATSY T HERRERA**...*RESIDENTIAL*
624 **BYRON O JR SIMS**...*RESIDENTIAL*
624 **CHARLES GIBSON**...*RESIDENTIAL*
624 **DAVID & MARILYN SALMAN**...*RESIDENTIAL*
624 **EDITH WALLACE**...*RESIDENTIAL*
624 **EVELYN M & WILLIAM D FRISSELL**...*RESIDENTIAL*
624 **GILBERT A MASON**...*RESIDENTIAL*
624 **GRANT LAFARGE**...*RESIDENTIAL*
624 **JOE & ANN FERTITTA**...*RESIDENTIAL*
624 **JOHN PENCE**...*RESIDENTIAL*
624 **KELLY E LYON**...*RESIDENTIAL*
624 **NANCY & LEW SULLIVAN**...*RESIDENTIAL*
624 **PATRICIA LAFARGE**...*RESIDENTIAL*
624 **QUE TENGA BUENA MANO**...*ART GALLERIES & DEALERS*
624 **RALPH WILLIAMS**...*RESIDENTIAL*
624 **RICK & LAYNE SMITH**...*RESIDENTIAL*
624 **ROBERT L HULL**...*RESIDENTIAL*
624 **ROBERT LINDRUD**...*RESIDENTIAL*
624 **S L ALLISON**...*RESIDENTIAL*
630 **ERNESTO MAYANS**...*RESIDENTIAL*
630 **HOWARD BOBBS**...*RESIDENTIAL*
630 **J L LEONARD**...*RESIDENTIAL*
630 **JAMES FORKIN**...*RESIDENTIAL*
630 **JEFFREY A THURSTON**...*RESIDENTIAL*
630 **JOHN THORNDIKE**...*RESIDENTIAL*
630 **RENEE CASTAGNOLA**...*RESIDENTIAL*
630 **RIGO BRUECK**...*RESIDENTIAL*
630 **THADDEUS RICHARDSON**...*RESIDENTIAL*
633 **CHARLES & GALE MACNEILL**...*RESIDENTIAL*
701 **JANE COOK**...*RESIDENTIAL*
701 **P HAUGE**...*RESIDENTIAL*
705 **ADAM BENNETT**...*RESIDENTIAL*
705 **DAVID BLOOM**...*RESIDENTIAL*
705 **GERALD LEE**...*RESIDENTIAL*
705 **JAMES W MEEKER**...*RESIDENTIAL*
705 **JOHN P BALDWIN**...*RESIDENTIAL*
705 **MAUREEN MACLELLAN**...*RESIDENTIAL*
705 **PAULA DAVIS**...*RESIDENTIAL*
705 **PETER MATTAIR**...*RESIDENTIAL*
705 **R SALZMANN**...*RESIDENTIAL*

97 total records. Part 1 of 2

550 PATRICIA ABAD...RESIDENTIAL
550 PUSHKIN GALLERY
551 ANTIQUE CLOCK REPAIR
551 CHESTER JOHNSON...RESIDENTIAL
552 JANE SMITH LTD...INSPECTION AND TESTING SERVICES
553 E C THAW CHARITABLE TRUST
554 PATRICIA CARLISLE FINE ART
555 NEDRA MATTEUCCI FINE ART
556 MARK FLETCHER...RESIDENTIAL
558 ALLENE LAPIDES GALLERY
600 B W BUSCH...RESIDENTIAL
600 MILES CHAFFEE...RESIDENTIAL
600 RON MESSICK FINE ART...ANTIQUES
601 ANNA M PEREA...RESIDENTIAL
601 ERNESTO MAYANS GALLERY
602 DOUGLAS ATWILL...RESIDENTIAL
602 E S GLENN...RESIDENTIAL
602 RICHARD MAC DONALD FINE ART
610 ADIEB KHADOURE FINE ART
610 DAVID ROSS STUDIO
610 TOM HAMILL...RESIDENTIAL
610 WILLIAM PALOU...RESIDENTIAL
613 CELEBRATIONS RESTAURANT...STEAK AND BARBECUE RESTAURANTS
613 GLENYS CARL...RESIDENTIAL
613 IGNACIO L VIGIL...RESIDENTIAL
613 WILLIAM WALKER BROWN...RESIDENTIAL
616 BACKROOM COFFEE BAR...STEAK AND BARBECUE RESTAURANTS
616 DEBORAH GOLD GALLERY
616 LESLIE MICHAELSON...RESIDENTIAL
616 OFF THE WALL
616 SUZEE MACDOUGALL...RESIDENTIAL
617 P J WOOD...RESIDENTIAL
618 CMC GALLERY
618 CRUZ JEWELRY STUDIO
618 KAREN WIGHT GALLERY STUDIO
618 ROBERT GILORMO...RESIDENTIAL
620 JULIA DICKENSON...RESIDENTIAL
620 NORDWALL GALLERY & STUDIO
621 CANYON ROAD FINE ART
621 PERCY ORTIZ...RESIDENTIAL
621 VEIKKO & ELIZABETH ANTTILA...RESIDENTIAL
622 A CORSO PAINTINGS
622 J RICHARD HUMPHREYS...RESIDENTIAL
622 M A BANE...RESIDENTIAL
622 NIRVAN HOPE...RESIDENTIAL
622 WAXLANDER GALLERY
624 JOE A GONZALES...RESIDENTIAL
626 A & E BACIGALUPA...RESIDENTIAL
630 FRIENDS MEETING
630 MARGUERITE CULP...RESIDENTIAL
630 OLIVE RUSH GUEST APT
634 ALICE PARROTT...RESIDENTIAL
634 DELONEY NEWKIRK FINE ART
640 LYN HUTCHINGS...RESIDENTIAL
640 RUNNING RIDGE GALLERY
641 J M KIRTLEY...RESIDENTIAL
644 BERNICE PETTIT-MACMILLAN...RESIDENTIAL
644 FRANK CROFT FINE ART...LEGAL AND TAX SERVICES
644 JAMES FARIS...RESIDENTIAL
644 KEATS GALLERY
644 KELLY HOWELL...RESIDENTIAL
651 ZAPLIN-LAMPERT GALLERY...LEGAL AND TAX SERVICES
652 THIRTEEN MOONS GALLERY
653 BELLAS ARTES LTD
653 CASWELL SILVER...RESIDENTIAL
653 COMPOUND...STEAK AND BARBECUE RESTAURANTS
653 D P SELLERS...RESIDENTIAL
653 E H DENDAHL...RESIDENTIAL
653 EDWARD M NICHOLAS...RESIDENTIAL

2003 CANYON RD
SOURCE: DIGITAL BUSINESS DIRECTORY

Part 2 of 2

653 GINGER EVANS...RESIDENTIAL
653 J A JR HOULE...RESIDENTIAL
653 J M GUESTHOUSE SAMUEL...RESIDENTIAL
653 J M SAMUEL...RESIDENTIAL
653 JACK SATIN...RESIDENTIAL
653 JERRY STIRMAN...RESIDENTIAL
653 JOHN C BAGWELL...RESIDENTIAL
653 JUDY RHYMES...RESIDENTIAL
653 LESTER B LOO...RESIDENTIAL
653 M GOODWIN...RESIDENTIAL
653 MILTON H WARD...RESIDENTIAL
653 N REICHMAN...RESIDENTIAL
653 RICHARD FLEISCHAKER...RESIDENTIAL
653 SEAN GRAYSTONE...RESIDENTIAL
656 CABALLO FINE CUSTOM BELTS
656 DEBORA CLARE...RESIDENTIAL
656 HELEN HARDIN ESTATE GALLERY
656 SILVER SUN
656 TRESA VORENBERG GOLDSMITHS
660 BESSER GROUP
662 KANIA-FERRIN GALLERY...ANTIQUES
662 M DIAMOND...RESIDENTIAL
667 LA BODEGA...WOMEN'S SPECIALTY CLOTHING STORES
668 MITCHELL TUFTS...RESIDENTIAL
668 VAN DE GRIFF/MARR GALLERY
669 DELONEY NEWKIRK FINE ART
669 STEVE BOONE...RESIDENTIAL
670 NUART GALLERY

Report ID: 25121700733 - 12/19/2025
www.erisinfo.com

2003 E ALAMEDA ST

SOURCE: DIGITAL BUSINESS DIRECTORY

550 **STEVEN WEBER**...*RESIDENTIAL*
605 **MARIA ANDERSON**...*RESIDENTIAL*
607 **DARRELL MEYER**...*RESIDENTIAL*
609 **G DARRINGTON**...*RESIDENTIAL*
611 **HELEN BURGESS**...*RESIDENTIAL*
614 **J K TREAT**...*RESIDENTIAL*
615 **MICHAEL JAMES SCHROEDER**...*RESIDENTIAL*
617 **JEFF JOHNSON**...*RESIDENTIAL*
618 **BARRY E STILES**...*RESIDENTIAL*
618 **CHELSEA K MCCARTHY**...*RESIDENTIAL*
618 **M A HAYES**...*RESIDENTIAL*
618 **PATSY T HERRERA**...*RESIDENTIAL*
618 **PHILLIP KATZ**...*RESIDENTIAL*
624 **BYRON O SIMS**...*RESIDENTIAL*
624 **CHARLES A GIBSON**...*RESIDENTIAL*
624 **DAVID & MARILYN SALMAN**...*RESIDENTIAL*
624 **EDITH WALLACE**...*RESIDENTIAL*
624 **EVELYN M & WILLIAM D FRISSELL**...*RESIDENTIAL*
624 **GEORGE GOLDSTEIN**...*RESIDENTIAL*
624 **GILBERT A MASON**...*RESIDENTIAL*
624 **GRANT LAFARGE**...*RESIDENTIAL*
624 **JOHN PENCE**...*RESIDENTIAL*
624 **JOHN R MCCUNE**...*RESIDENTIAL*
624 **LAYNE VICKERS SMITH**...*RESIDENTIAL*
624 **NANCY & LEW SULLIVAN**...*RESIDENTIAL*
624 **P LAFARGE**...*RESIDENTIAL*
624 **QUE TENGA BUENA MANO**
624 **RALPH WILLIAMS**...*RESIDENTIAL*
624 **RICHARD J SMITH**...*RESIDENTIAL*
624 **RICK & LAYNE SMITH**...*RESIDENTIAL*
624 **ROBERT L HULL**...*RESIDENTIAL*
630 **CROFT FRANK**...*LEGAL AND TAX SERVICES*
630 **E REED**...*RESIDENTIAL*
630 **ERNESTO MAYANS**...*RESIDENTIAL*
630 **FRANK CROFT**
630 **HOWARD BOBBS**...*RESIDENTIAL*
630 **JEFFREY A THURSTON**...*RESIDENTIAL*
630 **JOHN THORNDIKE**...*RESIDENTIAL*
630 **JUDITH & PETER HURLEY**...*RESIDENTIAL*
630 **PETER HIERS**...*RESIDENTIAL*
630 **RENEE CASTAGNOLA**...*RESIDENTIAL*
630 **THADDEUS RICHARDSON**...*RESIDENTIAL*
633 **CHARLES & GALE MACNEILL**...*RESIDENTIAL*
637 **T M MONAHAN**...*RESIDENTIAL*
701 **GORDON MANSELL**...*RESIDENTIAL*
701 **SUN GROUP DESIGN**
705 **BRIAN P OMALLEY**...*RESIDENTIAL*
705 **C MORGAN**...*RESIDENTIAL*
705 **DAVID BLOOM**...*RESIDENTIAL*
705 **DAVID JACOBSON**...*RESIDENTIAL*
705 **FRONTIER EDUCATION CTR**
705 **JAMES W MEEKER**...*RESIDENTIAL*
705 **MATTHEW SANBORN**...*RESIDENTIAL*
705 **PAULA DAVIS**...*RESIDENTIAL*
705 **ROEENA LASKY**...*RESIDENTIAL*

2000 CANYON RD

SOURCE: DIGITAL BUSINESS DIRECTORY

94 total records. Part 1 of 2

550 **JANE SMITH INTERIORS**...*INSPECTION AND TESTING SERVICES*
550 **PATRICIA ABAD**...*RESIDENTIAL*
550 **SANDRA WIRTH STUDIO GALLERY**
551 **ANTIQUE CLOCK REPAIR**
551 **CHESTER JOHNSON**...*RESIDENTIAL*
553 **E C THAW CHARITABLE TRUST**
554 **PATRICIA CARLISLE FINE ART**
555 **NEDRA MATTEUCCI FINE ART**
556 **MARK FLETCHER**...*RESIDENTIAL*
558 **ALLENE LAPIDES GALLERY**
600 **B W BUSCH**...*RESIDENTIAL*
600 **MILES CHAFFEE**...*RESIDENTIAL*
600 **RON MESSICK FINE ART**...*ANTIQUES*
601 **ANNA M PEREA**...*RESIDENTIAL*
601 **ERNESTO MAYANS GALLERY**
602 **DOUGLAS ATWILL**...*RESIDENTIAL*
602 **E S GLENN**...*RESIDENTIAL*
602 **ROSS MOXLEY NARANJO SCULPTURE**
608 **CLAIBORNE GALLERY**...*ANTIQUES*
608 **DOUGLAS ATWILL STUDIO**
610 **ADIEB KHADOURE FINE ART**
610 **DAVID ROSS STUDIO-GALLERY**
610 **TOM HAMILL**...*RESIDENTIAL*
610 **WILLIAM PALOU**...*RESIDENTIAL*
613 **CELEBRATIONS RESTAURANT**...*STEAK AND BARBECUE RESTAURANTS*
613 **GLENYS CARL**...*RESIDENTIAL*
613 **IGNACIO L VIGIL**...*RESIDENTIAL*
613 **WILLIAM WALKER BROWN**...*RESIDENTIAL*
616 **BACKROOM COFFEEBAR**...*STEAK AND BARBECUE RESTAURANTS*
616 **LESLIE MICHAELSON**...*RESIDENTIAL*
616 **OFF THE WALL**
616 **SUZEE MACDOUGALL**...*RESIDENTIAL*
617 **P J WOOD**...*RESIDENTIAL*
618 **CRUZ JEWELRY STUDIO**
618 **ROBERT GILORMO**...*RESIDENTIAL*
620 **JULIA DICKENSON**...*RESIDENTIAL*
620 **NORDWALL GALLERY & STUDIO**
621 **CANYON ROAD FINE ART**
621 **PERCY ORTIZ**...*RESIDENTIAL*
621 **VEIKKO & ELIZABETH ANTTILA**...*RESIDENTIAL*
622 **ATELIER CORSO FINE ART**
622 **J RICHARD HUMPHREYS**...*RESIDENTIAL*
622 **M A BANE**...*RESIDENTIAL*
622 **NIRVAN HOPE**...*RESIDENTIAL*
622 **WAXLANDER GALLERY**
624 **JOE A GONZALES**...*RESIDENTIAL*
626 **A & E BACIGALUPA**...*RESIDENTIAL*
630 **FRIENDS MEETING**
630 **MARGUERITE CULP**...*RESIDENTIAL*
634 **ALICE PARROTT**...*RESIDENTIAL*
634 **DELONEY NEWKIRK FINE ART**
640 **LYN HUTCHINGS**...*RESIDENTIAL*
640 **RUNNING RIDGE GALLERY**
641 **J M KIRTLEY**...*RESIDENTIAL*
644 **BERNICE PETTIT-MACMILLAN**...*RESIDENTIAL*
644 **FRANK CROFT FINE ART**...*LEGAL AND TAX SERVICES*
644 **JAMES FARIS**...*RESIDENTIAL*
644 **KEATS GALLERY**
644 **KELLY HOWELL**...*RESIDENTIAL*
651 **ZAPLIN-LAMPERT GALLERY**...*ANTIQUES*
652 **THIRTEEN MOONS GALLERY**
653 **BELLAS ARTES LTD**
653 **CASWELL SILVER**...*RESIDENTIAL*
653 **COMPOUND**...*STEAK AND BARBECUE RESTAURANTS*
653 **D P SELLERS**...*RESIDENTIAL*
653 **E H DENDAHL**...*RESIDENTIAL*
653 **EDWARD M NICHOLAS**...*RESIDENTIAL*
653 **GINGER EVANS**...*RESIDENTIAL*
653 **J A JR HOULE**...*RESIDENTIAL*

2000 CANYON RD

SOURCE: DIGITAL BUSINESS DIRECTORY

Part 2 of 2

653 **J M GUESTHOUSE SAMUEL**...*RESIDENTIAL*
653 **J M SAMUEL**...*RESIDENTIAL*
653 **JACK SATIN**...*RESIDENTIAL*
653 **JERRY STIRMAN**...*RESIDENTIAL*
653 **JOHN C BAGWELL**...*RESIDENTIAL*
653 **JUDY RHYMES**...*RESIDENTIAL*
653 **LESTER B LOO**...*RESIDENTIAL*
653 **M GOODWIN**...*RESIDENTIAL*
653 **MILTON H WARD**...*RESIDENTIAL*
653 **N REICHMAN**...*RESIDENTIAL*
653 **RICHARD FLEISCHAKER**...*RESIDENTIAL*
653 **SEAN GRAYSTONE**...*RESIDENTIAL*
656 **DEBORA CLARE**...*RESIDENTIAL*
656 **HELEN HARDIN ESTATE GALLERY**
656 **SILVER SUN**
656 **SOUTHWESTERN INDEPENDENT JWLRY**
656 **SW INDEPENDENT JEWELERY**...*LEGAL AND TAX SERVICES*
656 **TRESA VORENBERG GOLDSMITHS**
660 **BESSER GROUP**
662 **KANIA-FERRIN GALLERY**...*ANTIQUES*
662 **M DIAMOND**...*RESIDENTIAL*
667 **LA BODEGA**...*WOMEN'S SPECIALTY CLOTHING STORES*
668 **MITCHELL TUFTS**...*RESIDENTIAL*
668 **VAN DE GRIFF GALLERY**
669 **STEVE BOONE**...*RESIDENTIAL*

2000 E ALAMEDA ST

SOURCE: DIGITAL BUSINESS DIRECTORY

550 **STEVEN WEBER**...*RESIDENTIAL*
605 **MARIA ANDERSON**...*RESIDENTIAL*
607 **DARRELL MEYER**...*RESIDENTIAL*
609 **G DARRINGTON**...*RESIDENTIAL*
611 **HELEN BURGESS**...*RESIDENTIAL*
614 **J K TREAT**...*RESIDENTIAL*
615 **MICHAEL JAMES SCHROEDER**...*RESIDENTIAL*
617 **JEFF JOHNSON**...*RESIDENTIAL*
618 **BARRY E STILES**...*RESIDENTIAL*
618 **CHELSEA K MCCARTHY**...*RESIDENTIAL*
618 **M A HAYES**...*RESIDENTIAL*
618 **PATSY T HERRERA**...*RESIDENTIAL*
618 **PHILLIP KATZ**...*RESIDENTIAL*
624 **BYRON O SIMS**...*RESIDENTIAL*
624 **CHARLES A GIBSON**...*RESIDENTIAL*
624 **DAVID & MARILYN SALMAN**...*RESIDENTIAL*
624 **EDITH WALLACE**...*RESIDENTIAL*
624 **EVELYN M & WILLIAM D FRISSELL**...*RESIDENTIAL*
624 **GEORGE GOLDSTEIN**...*RESIDENTIAL*
624 **GILBERT A MASON**...*RESIDENTIAL*
624 **GRANT LAFARGE**...*RESIDENTIAL*
624 **JOHN PENCE**...*RESIDENTIAL*
624 **JOHN R MCCUNE**...*RESIDENTIAL*
624 **LAYNE VICKERS SMITH**...*RESIDENTIAL*
624 **NANCY & LEW SULLIVAN**...*RESIDENTIAL*
624 **P LAFARGE**...*RESIDENTIAL*
624 **RALPH WILLIAMS**...*RESIDENTIAL*
624 **RICHARD J SMITH**...*RESIDENTIAL*
624 **RICK & LAYNE SMITH**...*RESIDENTIAL*
624 **ROBERT L HULL**...*RESIDENTIAL*
630 **E REED**...*RESIDENTIAL*
630 **ERNESTO MAYANS**...*RESIDENTIAL*
630 **HOWARD BOBBS**...*RESIDENTIAL*
630 **JEFFREY A THURSTON**...*RESIDENTIAL*
630 **JOHN THORNDIKE**...*RESIDENTIAL*
630 **JUDITH & PETER HURLEY**...*RESIDENTIAL*
630 **PETER HIERS**...*RESIDENTIAL*
630 **RENEE CASTAGNOLA**...*RESIDENTIAL*
630 **THADDEUS RICHARDSON**...*RESIDENTIAL*
633 **CHARLES & GALE MACNEILL**...*RESIDENTIAL*
637 **T M MONAHAN**...*RESIDENTIAL*
701 **GORDON MANSELL**...*RESIDENTIAL*
701 **SUN GROUP DESIGN**
705 **BRIAN P OMALLEY**...*RESIDENTIAL*
705 **C MORGAN**...*RESIDENTIAL*
705 **DAVID BLOOM**...*RESIDENTIAL*
705 **DAVID JACOBSON**...*RESIDENTIAL*
705 **IRON SERPENT GALLERY**
705 **JAMES W MEEKER**...*RESIDENTIAL*
705 **LEEVAN PAUL SIMON ATTY**
705 **MATTHEW SANBORN**...*RESIDENTIAL*
705 **PAULA DAVIS**...*RESIDENTIAL*
705 **ROEENA LASKY**...*RESIDENTIAL*

1996 CANYON RD

SOURCE: POLKS

CANYON RD cont'd

Address	Zip+4	CarrRte	Phone
540 Burdine Roddey B	-2720	C003	984-0043
544 Coughlin B T	-2720	C003	982-1045
545 HISTORIC SANTA FE FOUNDATION	-2754	C003	983-2567
LEE K LITTLE	-2754	C003	982-1622
Arne Robert C	-2754	C003	982-9286
Celiucci Laurie	-2754	C003	983-1390
Defoe M	-2754	C003	989-9882
Little Lee K	-2754	C003	982-1622
Loomis S G	-2754	C003	982-5963
546 Blount Brian	-2720	C003	989-7503
550 Abad Patric	-2720	C003	989-8007
551 ANTIQUE CLOCK REPAIR	-2719	C003	982-8233
Johnson Chester	-2719	C003	982-8233
555 NEDRA MATTEUCCI FINE ART	-2719	C003	983-2731
Fletcher Mark	-2720	C003	984-9924
556 CLAIBORNE GALLERY	-2720	C003	982-8019
558 Busch B W	-2722	C003	988-2840
Chaffee Miles	-2722	C003	988-4675
600 ERNESTO MAYANS GALLERY	-2721	C003	983-8068
Perea Anna M	-2721	C003	983-6444
601 AL LUCKETT JR FINE PAINTINGS	-2722	C003	988-7550
Glenn E S	-2722	C003	986-0665
602 Atwill Douglas	-2722	C003	983-2852
604 DAVID ROSS STUDIO-GALLERY	-2722	C003	988-4017
Hamill Tom	-2722	C003	983-1897
Palou William	-2722	C003	982-1082
610 CELEBRATIONS RESTAURANT	-2721	C003	989-8904
Brown William W	-2721	C003	988-4079
Carl Glenys	-2721	C003	820-0869
Vigil Ignacio L	-2721	C003	982-0052
613 BACKROOM COFFEEBAR INC	-2722	C003	988-5323
FRANK CROFT FINE ART	-2722	C003	984-2220
OFF THE WALL	-2722	C003	983-8337
Macdougall Suzee	-2722	C003	982-6356
Michaelson Leslie	-2722	C003	984-8725
616 Wood P J	-2721	C003	986-5049
617 Gilormo Robert	-2722	C003	983-9507
618 Dickenson Julia	-2722	C003	984-0860
620 CANYON ROAD FINE ART	-2721	C003	988-9511
Antilla Elizab	-2721	C003	982-4173
Antilla Veikko	-2721	C003	982-4173
Ortiz Percy	-2721	C003	982-1238
621 GALLERY ON CANYON ROAD	-2722	C003	988-5504
SUN BOY GALLERY	-2722	C003	983-3042
WAXLANDER GALLERY	-2722	C003	984-2202
Bane M A	-2722	C003	984-8428
Hope Nirvan	-2722	C003	820-6741
Humphreys J R	-2722	C003	983-5685
622 Gonzales Joe A	-2722	C003	983-6653
624 Bacigalupa A	-2722	C003	982-0054
Bacigalupa E	-2722	C003	982-0054
626 FRIENDS MEETING	-2722	C003	983-7241
Culp Margue	-2722	C003	984-3091
630 AOI GALLERY	-2722	C003	982-3456
PARROTT FABRICS INC	-2722	C003	982-0794
Parrott Alice	-2722	C003	982-0794
634 RUNNING RIDGE GALLERY	-2722	C003	988-2515
Hutchings Lyn	-2722	C003	988-1488
640 Kirtley J M	-2721	C003	988-3613
641 MARTHA KEATS GALLERY	-2773	C003	982-6686
Faris James	-2773	C003	989-5052
Howell Kelly	-2773	C003	984-0036
644 Pettitmacmillan Bernice	-2773	C003	984-0970
ZAPLIN-LAMPERT GALLERY	-2721	C003	982-6100
Hiers Peter	-2721	C003	984-1421
651 QUILTS LIMITED	-2722	C003	988-5888
652 BELLAS ARTES LTD	-2762	C003	983-2745
COMPOUND	-2762	C003	982-4353
Bagwell John C	-2762	C003	983-8343
Dendahl E H	-2762	C003	982-1177
Evans Ginger	-2762	C003	988-5217
Fleischaker Richard	-2762	C003	988-5740
Goodwin M	-2762	C003	989-3835
Graystone Sean	-2762	C003	983-2237
Houle J A Jr	-2762	C003	983-0483
Loo Lester B	-2762	C003	989-9250
Nicholas Edward M	-2762	C003	982-8311
Reichman N	-2762	C003	988-1713
Rhymes Judy	-2762	C003	988-5217
Samuel J M	-2762	C003	983-5461
Satin Jack	-2762	C003	988-1713
Sellers D P	-2762	C003	983-8343
Silver Caswell	-2762	C003	983-6575

CANYON RD cont'd

Address	Zip+4	CarrRte	Phone
Stirman Jerry	-2762	C003	988-9806
Ward Milton H	-2762	C003	988-7192
656 HELEN HARDIN ESTATE GALLERY	-2722	C003	983-0553
SILVER SUN	-2722	C003	983-8743
TRESA VORENBERG GOLDSMITHS	-2722	C003	988-7215
Clare Debora	-2722	C003	982-4246
660 Besser Bruce	-2722	C003	989-8801
Besser Kate	-2722	C003	989-8801
662 KANIA-FERRIN GALLERY	-2722	C003	982-8767
Diamond M	-2722	C003	986-8962
667 LA BODEGA	-2721	C003	982-8043
668 FLETCHER GALLERY FINE ARTS	-2722	C003	983-9441
Tufts Mitche	-2722	C003	989-4373
669 STEVEN BOONE GALLERY	-2721	C003	988-9655
Boone Steve	-2721	C003	988-9655
670 CANYON TRADING POST	-2722	C003	988-5012
701 UMBRELLO	-2723	C003	984-8566
702 GRAPHICS HOUSE	-2724	C003	983-2654
Sawyer Anne	-2724	C003	983-2654
702½ DENISE ROBERGE GALLERY	-2724	C003	820-2008
707 EDITH LAMBERT GALLERY	-2723	C003	984-2783
VOLKER DE LA HARPE CARVED SIGN	-2723	C003	983-4074
708 CAROLE LA ROCHE GALLERY	-2751	C003	982-1186
GENTLE SPIRIT GALLERY	-2751	C003	989-4793
LA VIE STUDIO GALLERY	-2751	C003	989-4944
LEAPING LIZARD GALLERY	-2751	C003	984-8434
OOTI GALLERY	-2751	C003	984-1676
Iarrobino C	-2751	C003	988-2497
Kippenbrock W	-2751	C003	989-8991
Loretto Estella C	-2751	C003	989-4793
Mullins Donald S	-2751	C003	989-7567
Panchy J	-2751	C003	984-0920
Perazioltkin C	-2751	C003	983-2188
Ross Tom	-2751	C003	984-8434
713 HOUSHANG'S GALLERY CANYON RD	-2723	C003	988-3322
714 JUDY'S UNIQUE APPAREL	-2724	C003	988-5746
717 ARTISAN SANTA FE INC	-2723	C003	988-2179
Banta William R	-2723	C003	988-4648
Young J S	-2723	C003	988-4648
724 GEROMINO LODGE	-2724	C003	982-1500
725 CARROLL TURNER GALLERY	-2723	C003	986-9800
DESERT SON	-2723	C003	982-9499
Lara Armond R	-2723	C003	982-9593
727 CABALLO	-2723	C003	984-0971
EAST WEST TRADING-SENDERO	-2723	C003	986-3489
728 PANZUSZ THE MOLA GALLERY	-2724	C003	982-8569
Heffron Max	-2724	C003	982-8569
Heffron P	-2724	C003	982-8569
Rios Juan	-2724	C003	983-1179
731 IMPERIAL WOK ORIENTAL GOURMET	-2723	C003	988-7100
802 WILLY'S CANTINA	-2726	C003	986-3833
808 EL FAROL RESTAURANT & LOUNGE	-2726	C003	983-9912
Salazar David	-2726	C003	983-8780
808½ DUNBAR STAINED GLASS STUDIO	-2726	C003	984-8515
812 TIQUA GALLERY	-2726	C003	984-8704
820 DOWNEY GALLERY	-2726	C003	982-6701
Rogers David	-2726	C003	983-4891
821 CANYON ROAD POTTERY	-2725	C003	983-9426
GALLERY 821	-2725	C003	983-2000
JOANNA NEDBOY STUDIO-GALLERY	-2725	C003	983-9662
Lynn S	-2725	C003	986-8592
Miller George	-2725	C003	982-9298
822 THIRD PHASE	-2726	C003	983-1696
TRINITY ANTIQUES & ART	-2726	C003	986-1635
Montoya Viola	-2726	C003	988-3067
Vigil Emily	-2726	C003	988-4965
824 Young Landon	-2726	C003	982-9835
826 NIGHT SKY GALLERY	-2726	C003	982-1468
Newkirk Reita	-2726	C003	982-1468
830 COMO NO	-2726	C003	986-5816
Salazar Roman	-2726	C003	982-0647
836 Kessler Alan	-2726	C003	986-0123
901 CRYSTAL FARM ANTLER CHANDELIER	-6121	C047	986-0065
906 EPRO INC	-6122	C047	867-0990
Gustafson Lynn	-6122	C047	989-1806

1996 E ALAMEDA ST

SOURCE: POLKS

E ALAMEDA ST cont'd

Address	Zip+4	CarrRte	Phone
275 ST FRANCIS CATHEDRAL SCHOOL	-2113	C040	982-0331
SUN WEST SVC	-2113	C040	989-1623
301 SHORT SET HAIR BOUTIQUE	-2289	C003	983-4406
303 INN ON THE ALAMEDA	-2229	C003	984-2121
324 Rabgay Pema	-2266	C003	820-0732
Thondup Paljor	-2266	C003	988-4142
331 Sanchez Mary I	-2229	C003	982-8025
335 Sandoval John R	-2229	C003	983-2430
337 Fogelman Cather	-2229	C003	986-1272
338 Alarid A	-2266	C003	988-2135
Alarid Brad	-2266	C003	986-9097
Alarid P	-2266	C003	988-2135
Alarid Pam J	-2266	C003	989-1742
Newman Todd	-2266	C003	984-8773
Oneill J	-2266	C003	986-8972
Ortiz K A	-2266	C003	988-2200
339 Yim Leslie	-2229	C003	988-4597
341 Khalsa Kartar K	-2229	C003	984-2601
Kleinke Benjul	-2229	C003	986-1789
343 Duran Bernard A	-2229	C003	983-8896
351 Torres Gonzalo L	-2229	C003	820-6538
401 Viles L	-2202	C047	982-9917
403 Cantu Alfredo	-2202	C047	983-7644
Garcia L J	-2202	C047	982-1004
Willock Dolores	-2202	C047	982-2715
523 Scullin J S	-2203	C047	982-9955
Scullin Joseph	-2203	C047	982-9955
527 Scoggins T	-2201	C047	982-5607
528 Zarember Tami	-2231	C047	820-7719
540 Spiegel Austin	-2231	C047	988-3645
Spiegel Austin G	-2231	C047	983-0641
541 Funtanilla Victor	-2269	C047	984-1648
Hucko Bruce	-2269	C047	989-8562
Monette F	-2269	C047	984-1730
550 Weber Steven	-2231	C047	983-3832
564 ESTHER SUTIN STUDIO	-2231	C047	984-8716
605 Anderson Maria	-2204	C047	820-7816
607 Meyer Darrell	-2204	C047	820-7435
609 Darrington G	-2204	C047	820-6351
611 Burgess Helen	-2204	C047	983-1351
614 Treat J K	-2205	C047	986-9290
615 Schroeder Michael J	-2204	C047	988-9195
617 Johnson Jeff	-2204	C047	986-3467
618 Hayes M A	-2205	C047	989-1532
Herrera Patsy T	-2205	C047	983-3427
Katz Phillip	-2205	C047	982-8002
McCarthy Chelsea K	-2205	C047	820-1135
Stiles Barry E	-2205	C047	820-1135
624 Frissell Evelyn	-2237	C047	989-7844
Frissell William D	-2237	C047	989-7844
Gibson Charles A	-2237	C047	983-7786
Goldstein George	-2237	C047	986-8537
Hull Robert L	-2237	C047	988-3728
Lafarge Grant	-2237	C047	983-5104
Lafarge Grant	-2237	C047	988-5196
Lafarge Patric	-2237	C047	983-2358
Mason Gilbert A	-2237	C047	989-7395
McCune John R	-2237	C047	988-7425
Pence John	-2237	C047	982-1246
Salman David	-2237	C047	984-0781
Salman Marilyn	-2237	C047	984-0781
Sims Byron O Jr	-2237	C047	984-8158
Smith Layne	-2237	C047	983-7574
Smith Richard J	-2237	C047	983-7574
Smith Rick	-2237	C047	983-7574
Sullivan Lew	-2237	C047	983-1599
Sullivan Nancy	-2237	C047	983-1599
Wallace Edith	-2237	C047	984-3009
Williams Ralph	-2237	C047	988-9129
630 ERNESTO MAYANS GALLERY	-2205	C047	982-1999
Bobbs Howard	-2205	C047	983-5570
Castagnola Renee	-2205	C047	988-8974
Hiers Peter	-2205	C047	984-1421
Hurley Judith	-2205	C047	989-1935
Hurley Peter	-2205	C047	989-1935
Mayans Ernesto	-2205	C047	989-7312
Reed Elizab	-2205	C047	989-9620
Richardson Thadde	-2205	C047	989-8836
Thorndike John	-2205	C047	983-4073
Thurston Jeffrey A	-2205	C047	988-3905
633 Macneill Charles	-2204	C047	989-4587
Macneill Gale	-2204	C047	989-4587
637 Monahan T M	-2204	C047	983-3354
701 Mansell Gordon	-6418	C047	982-3603
705 Bloom David	-6426	C047	983-3294
Davis Paula	-6426	C047	983-2406
Jacobson David	-6426	C047	986-1579
Lasky Roeena	-6426	C047	983-7848
Meeker James W	-6426	C047	983-2853

E ALAMEDA ST cont'd

Address	Zip+4	CarrRte	Phone
Meeker James W	-6426	C047	984-8926
Morgan C	-6426	C047	988-9255
Omalley Brian P	-6426	C047	983-6834
Sanborn Matthew	-6426	C047	984-1557
803 Smith Alan	-2207	C047	983-9116
815 Fleck L	-2207	C047	984-0623
Huser Channi	-2207	C047	983-7851
Johnston Stewart	-2207	C047	983-7851
Muhs Chloe	-2207	C047	983-5780
817 McKenna Philip	-2207	C047	982-2763
Urffer Sallie	-2207	C047	986-1627
Valenzuela Gilber	-2207	C047	983-6278
827 Griego John	-2207	C047	983-3553
829 Griego Agustin	-2207	C047	983-7536
833 Banks Barbara	-2207	C047	982-1202
835 Banks Harold E	-2207	C047	982-2341
837 Gabaldon Miguel	-2207	C047	982-0296
839 Baros Gus	-2207	C047	982-0392
840 Bear Lynden	-2208	C047	982-9406
Pacheco Susan E	-2208	C047	988-1376
Rimbach Frank	-2208	C047	989-9031
Scholl B	-2208	C047	986-1213
841 Bove Paul W	-2207	C047	986-8576
Strong Ron	-2207	C047	988-2095
Young Blaine	-2207	C047	988-5105
868 Bustamante Nheari	-2208	C047	982-7792
Trujillo Donelia	-2208	C047	983-3004
870 Baker Adrien	-2208	C047	989-7248
Baker Kelly	-2208	C047	989-7248
Baker Reese	-2208	C047	989-7248
874 Thompson Jonath P	-2208	C047	982-7437
1001 JAMES JEREB DESIGN	-2284	C047	989-8765
Jereb James F	-2284	C047	989-8765
Mullen Jennif	-2284	C047	982-7285
Mullen Richard	-2284	C047	982-7285
1005 THEODORE WADDELL ASSOC	-2284	C047	983-1252
Maclellan B L	-2284	C047	982-0280
McMahan Jamie L	-2284	C047	982-0280
Summers A	-2284	C047	986-9745
Waddell Theodo	-2284	C047	988-2686
1115 Stuart Paul S	-2286	C047	988-5961
1117 Anaya Joseph E Jr	-2286	C047	982-3907
1122 Lindfors M	-2285	C047	983-7824
1131 Messick R	-2286	C047	983-9533
1145 Nakk Marrika A	-2286	C047	982-7555
1149 Shapiro Jay J	-2286	C047	982-4255
Shapiro Leigh	-2286	C047	982-1003
1169 Ohlsen Gerald G	-2286	C047	982-0310
Ohlsen Linnea D	-2286	C047	982-0310

BUSINESSES 13 HOUSEHOLDS 231

W ALAMEDA ST *(SF)* 87501

DOC'S SPEED ACRES	474-0253
SOUTHWEST SATELLITE	471-8831
TOP PLUMBING & HEATING	471-8192
Althouse Robert C	471-3900
Arguello Gloria	471-3044
Baldinger Louise	471-9070
Baucom Clifton D	473-2916
Beckman Frank	471-7961
Binette Margar J	473-9767
Borrego Placido	471-7712
Boylan Ed	473-5602
Burgel J A	471-4075
Caputo David	473-9294
Carnes Carol	438-6131
Catanach Patty	438-0063
Claggett Caroll	473-2621
Conway Jim J	471-5122
Cornett L L	471-3774
Cowell Raymond C	471-7716
Davis Blake	474-2877
Davis Dovie M	473-2243
Drake James R	471-3360
Elliott Alvin R	473-3658
Erdoes Eric P	438-8511
Farella A	471-1203
Forkin James	438-3066
Forkin Kris	438-3066
Gonzales David A	473-0449
Hansen R W	471-8090
Hartse Hans	473-9366
Head Ivan R Jr	471-8345
Head Patrick	438-0771
Hill Stanley	471-7693
Kenney Nancy	471-3900
Kesler Charles	471-1321
Koska David S	474-0813
Kruger Wolfga	471-8731
Lopez Garrett	473-0431

CANYON RD –FROM PASEO DE PERALTA EAST

• ZIP CODE 87501
200 STREETS OF TAOS indian arts & crafts retail 983-8268
201 MABEL'S ret 986-9105
202★Street Heater & Michl
221★Tesoros C 982-1738
223a Delgado Genevieve [9]+ ◎ 983-8902
223b★Bull Amanda G
225 ECONOMUS WORKS OF ART art works gallery 982-6347
225 MUNSON GALLERY art gallery 983-1657
Units
16 SCARLETT'S antiques & galleries 983-7092
2 MARIPOSA SANTA FE arts & craft sups 982-3032
3 FLYNT LESLIE GALLERY art 983-5178
5 ESTES DESIGN INTERNATIONAL 989-8841
6 SPIDER WOMAN DESIGN decorative accessories 984-0136
Dunn Gretchen [2] ◎
4 GALLERY TEN INC 983-9707
11 JANUS GALLERY contemp art gallery 983-1590
14 MEYER GALLERY art gallery 983-1434
18 LITESIDE GALLERY art galleries 982-5501
19 NEW TRENDS GALLERY art 988-1199
20 LA MESA OF SANTA FE 984-1688
C MAURO GARY GALLERY art gallery 988-3048
233 BOBBY'S PLAZA GALLERY 989-7193
MOON DANCE GALLERY art gallery 982-3421
• DE VARGAS INTERSECTS
234 Not Verified
• GARCIA INTERSECTS
400 DURHAM LINDA GALLERY fine contempory art 988-1313
403 SHAMBALLA FINE ARTS 986-9812
ART VENTURES 983-0433
COPELAND-RUTHERFORD FINE ART LTD art gallery 983-1588
PROJECT TIBET non proft organization 982-3002
409 GALERIA CAPISTRANO 984-3024
414 CANFIELD GALLERY 988-4199
415 Loeffler Rudolf [4] 982-9500
418 Theimer Jack [2] 982-4729
419 NICHOLS ROBERT F GALLERY indian pottery antiques am art 982-2145
421 Gurrola Lucian J [6] ◎ 982-4826
423 CANYON ROAD FLOWERS 983-9785
424★Barclay Rutgers & Leslie 986-1400
• DELGADO INTERSECTS
500 Vacant
503 MC ADOO LINDA GALLERIES LTD art 983-7182
513 MORNING STAR GALLERY 982-8187
519 Matteucci Richd L [2] ◎ 983-5195
523 Buchanan Jean M [9]+ ◎ 982-0344
526 CLINE GALLERY 982-5328
530 Vacant
540 Burdine Roddey B [4] ◎ 984-0043
544 Coughlin Bert T [9]+ ◎ 982-1045
545 EL ZAGUAN APARTMENTS 983-2567
1 Martin Harold [9]+
2 Turkle Brinton [9]+ 983-6683
2b Rubin Howard A [5] 988-1728
3 HISTORIC SANTA FE FOUNDATION THE 983-2567
4 Cellucci Laurie [5] 983-1390
5 Thomas Mack [2]
6 Arne Robt C [9]+ 982-9286
7 Loomis Sylvia G [9]+ 982-6963
9★Dunne Frances 983-9493
546★Pinson E 982-3681
550 THROCKMORTON FINE ARTS INC art gallery 988-1698
550½★Knickerbocker B 988-8857
551 Johnson Chester H [9]+ ◎ 982-8233
552★Johnson Jan 986-1228
553 FREMONT ELLIS STUDIO GALLERY 982-5008
Ellis Bambi [3] ◎ 982-5008
554 GOLD CANYON STUDIO GALLERY studio & art gallery 989-7424
555a MATTEUCCI NEDRA FINE ART art gallery 983-2731
555b Not Verified
558 CLAIBORNE GALLERY 982-8019
• CAMINO ESCONDIDIO INTERSECTS
606a Pederson John [2] 983-3235
608a Leutsch Dorit & Miriam [2]
604a Glenn Edna [2] 986-0665
608b★Chaffe Miles A
601 MAYANS ERNESTO GALLERY art 983-8068
601a Vigil Antonio F [9]+ ◎ 983-6444
Perea Anna M 983-6444
600 FINE PAINTINGS & ANTIGUES art gallery 988-7550

12
602 ATWILL DOUGLAS STUDIO 983-2852
610 Apartments
A Not Verified
C Palou Willa [9]+ ◎ 982-1082
D Not Verified
613 CELEBRATIONS restr & caterers 989-8904
Apartments
1 Not Verified
2★Brown Wm 988-4079
3 Not Verified
4★Seyda Barbara 986-8328
5 Vigil Ignacio L [2] 982-0052
6 Padilla Martha [3]
7 Vacant
616 OFF THE WALL 983-8337
BOOKROOM COFFEE BAR THE 988-5323
616a CROFT FRANK FINE ART gallery 984-2220
Croft Frank [2] 984-2220
616b Not Verified
616c Vacant
616½ No Return
617 Stromberg Diane E [2] 984-8746
618a Not Verified
618b Sortino Bill [2] 982-0918
619 O'Neill Mollie L [7] 983-1159
621 CANYON ROAD FINE ART gallery 988-9511
621½ Mercer Fritz [2] 989-9657
622 WAXLANDER GALLERY 984-2202
622a CANYON ROAD FURNITURE 988-5504
622b SUNBOY GALLERY 983-3042
622½a Humphryes J Richd & Peggy [4] ◎ 983-6685
624 Gonzales Jose A [9]+ ◎ 983-6653
626 STUDIO OF GIAN ANDREA THE artists 982-0054
Bacigalupa Andrea [9]+ ◎ 982-0054
630 RELIGIOUS SOCIETY OF FRIENDS quaker meeting hse 983-7241
634 PARROTT FABRICS retail 982-0794
MARKET THE 982-0794
635 Not Verified
640 RUNNING RIDGE GALLERY 988-2515
641 Kirtley M [5] ◎ 988-3613
644 Apartments
1 POSTERS OF SANTA FE INC 983-9697
2 KEATS GALLERY & ANTIQUES 982-6686
3 Pettit-Mac Millan [2]
1 POSTERS OF STANTA FE 983-9697
2 KEATS GALLERY 982-6686
4★Faris Jas 984-8961
5 Young Boyce S [9]+ 988-1543
6★Rhymes Evans
BIBO STUDIO
8 Grobowski [2]
9 Bibo Jim [2] 982-6197
10 Not Verified
11 Hutchings
12 Goetz P W
11 Hutchings [3]
12 Goetz P W [4] 989-8277
650 Mayans Roberto [2]
651 ZAPLIN-LAMPERT GALLERY art gallery 982-6100
652 QUILTS LIMITED 988-5888
653 COMPOUND RESTAURANT 982-4353
BELLAS ARTES LTD 983-2748
COMPOUND APARTMENTS THE 983-4483
1 Nicholas Edw M [9]+ ◎ 982-8311
2 Sellers D P [9]+ ◎ 988-8343
3 Mann C L [9]+ ◎ 983-6539
4 Satin Jack H [9]+ ◎ 988-1713
5-653 Not Verified (2 Apts)
7 Blair Donald [9]+ ◎ 983-2140
8 Fleischaker R H [9]+ ◎ 988-5740
9 Maxwell Marilyn [8] ◎ 983-5484
10 Dendahl Eleanor H [9]+ ◎ 982-1177
11 Samuel Ruth [3] 983-5461
12 Blommer Robt H [3] ◎ 986-1343
13 Loo Lester [8] ◎ 989-9250
14★Samuel Ruth 983-9689
15★Rhynes Julia 988-5217
16★Silver Eliz 983-6575
16 Silver Eliz [9]+ ◎ 983-6575
656 SILVER SUN INDIAN JEWELRY 983-8743
HARDIN HELEN ESTATE
VORENBERG TRESA GOLDSMITH 988-7215
CONCEPTS COOPERATIVE GALLERY sculptors 988-3743
656½★Clare Debora 982-4246
662 KANIA-FERRIN GALLERY 982-8767
662½ Porter Jerry [9]+ ◎ 982-8637
667 LA BODEGA indian crafts 982-8043
668 FLETCHER GALLERY 983-9441
669 DAVES PHIL STUDIO GALLERY art gallery 988-4892
670 CANYON TRADING POST 988-5012
701 SANTA FE NEW MEXICO UMBRELLO GALLERY furn & accessories shop 984-8566
702 GRAPHICS HOUSE GALLERY THE art 983-2654

◎ HOMEOWNER

E ALAMEDA ST–Contd
608 O'Connell Louise C [2] 986-9891
610 Atkins Nellie L [9]+ 982-9769
612 Imhof Elsie A [3] 983-8431
612 Holliday I V 983-8431
614 Miller Wava T [9]+ 983-3692
616 Hyne June J [9]+ 983-1309
618 O'Keeffe Katheryn [2] 986-9623
620 Hatcher Walter & Eugenia [2] 982-6625
622 Sekler Alex & Gisella [7] 982-4706
624 Healy Mildred N [4] 982-1107
626 Jones Maurine G [4] 982-2260
628 Johnston Virginia S [5] 984-0190
630 Jones Courtney [3] 983-3158
632 Wood Karl B & Irene L [4] 983-4930
634 Vacant
636 Blair Hazel I [9]+ 982-3022
638 La Badie Rosina [2] 983-9496
640 Hurt Bill & Vicky [5] 988-4635
275 ST FRANCIS CATHEDRAL SCHOOL parochial sch 982-0331
• PASEO DEL PERALTA INTERSECTS

12

• PASEO DE PERALTA INTERSECTS
301 ART TOURS travel guide 988-3527
3a SHORT SET HAIR BOUTIQUE 982-4406
KUZIEL TRAVEL 988-9307
303 INN ON THE ALAMEDA hotel 984-2121
329 INN ON THE ALAMEDA stge
A INN ON THE ALAMEDA overflow
B INN ON THE ALAMEDA overflow
C INN ON THE ALAMEDA overflow
D INN ON THE ALAMEDA overflow
335 Sandoval John R & Cleo [9]+ ◎ 983-2430
337 Not Verified
338 Apartments
A Not Verified
B Alarid Nancy [3]
C Ortiz Kathleen A [5] 988-2200
D Pornell Paul D [2] 982-1733
Alarid Arlene J [2] ◎ 988-2135
1★Spirit Jeffery 983-2646
2-339 Not Verified (2 Apts)
341★Mackay Frank H
343½ Not Verified
343 Duran Bernard A [9]+ 983-8896
345 Medrano Esther E [9]+ ◎ 983-4916
351½-351 Not Verified (2 Hses)
357★Baca Luis
• DELGADO INTERSECTS
401 Viles M J [3] 982-9917
403 Garcia Lawr J [4] 982-1004
Cantu Alfred & Sophie [2] ◎ 983-7644
Willock Dolores L [9]+ ◎ 982-2715
409 Not Verified
411 Garcia Christine [9]+
411a Howland Josina M [3]
522 Robinson B [7] 983-7195
523 Scullin Josephine S [9]+ 982-9955
525 Not Verified
527 Apartments
1-527 Not Verified (12 Apts)
528 No Return
528½ Not Verified
529 Apartments
540 Not Verified
541 Apartments
A Funtanilla Victor [2] 984-1648
B Hacko Bruce [2]
C Not Verified
D Monette F [2] 984-1730
E Not Verified
550 Crumm Milburn H [9]+ 982-1473
564 SUTIN ESTHER artist 984-8716
• CAMINO ESCONDIDO INTERSECTS
605 Not Verified
611 Vacant
614 Treat [2]
615 Rosenberg [2]
616 Rodriguez Felex [3]
616½a Heyman E [3] 982-3294
617 Burke Christopher [3] 986-0323
618★Montgomery Clayton J 982-8002
624 LAS PRIERTAS APARTMENTS
1 Frissel Wm D [4] 989-7844
2 Teel John D [2] 988-1065
3 Salman David & Marilyn [2] 984-0781
4 Pence John H [8] 982-1246
5 Fries John G [9]+ 988-5394
6 Mc Cune John R [3]
7 Ely [2]
7 Wickham
8 Nystrom [2]
9 Mc Connell D [9]
10 Hull Robt [3] 988-3728
11 Wallace Edith [2] 984-3009
12 Freeman Jas L [2] 984-0835
13 Williams [2]
14 Stevens John [4] ◎ 988-7424
14 Story Ron 988-7424
16 La Farge C G [3] 983-2358
16 La Farge D [8] 983-5104
17 Mason [2]
18 Sims [2]
630 Bobbs Elspeth [9]+ ◎ 983-5570
Apartments
A Reed Betsy L [2] 989-9620
B Thurston Jeffery A [9]+ 988-3905
C Richardson Thaddeus [2] 989-8836
D Not Verified
E Ingle Jon [5] 983-5786
F Castaqwola Renee [2] 988-8974
H-630 Not Verified (3 Apts)
K Myans Ernesto [2]
633 Not Verified
635 Harrick Lee [3]
635½ Ellis Oren [3] 984-2671
637 Byrne Kirsten A [2] 983-9150
701 Apartments
1 Not Verified
2 England Nancy T [2]
3★Goler Raul
4★Unger Jas L & Solveiga ◎ 983-6994
703 Not Verified
705 RIVER OAKS THE custom apts 983-2853
1★Fallon Joanne 932-0427
2★Davis Paula 983-2406
3 Lasky Roeena [2] 983-7848
4 Meeker Jas N [2] 983-2853
5 Momaday Brit [2] 986-2017
6★Cushman David W 988-5714
7-705 Not Verified (2 Apts)
9 Hagler Barbara J [3] 984-0781
10 Berry Raymond R [2] 986-5845
• EL ALAMO ST INTERSECTS
801★Moya Don D Jr 986-9865
Padilla Carmella 986-9865
803 Scott Michl [2] 986-9705
805 Not Verified
815 Apartments
1 Muhs Chloe D [4] 983-5780
2 Adams Jack [5] 984-1776
3 Gould Wm R [2] 986-8701
4 Vacant
5 Rostro Rudy [5] 988-2556
817 Apartments
1 Not Verified
2 Urffer Sally S [4] 986-1627
3 Not Verified
4 Thompson Jas [2]
5 Mc Kenna Philip [3] 982-2763
827 Griego John & Josefita B [9]+ ◎ 983-3553
829 Griego Augustine [9]+ ◎ 983-7536
Saiz Lucy C 983-7536
Saiz Rosarita 983-7536
Slaz Delores A 983-7536
833 Banks Barbara J [9]+ 982-1202
835 Banks Harold E [9]+ 982-2341
837 Gabaldon Miguel B [9]+ 982-0296
839 Baros Augustin B & Mary R [9]+ ◎ 982-0392
840 Apartments
1 Bear Lynden [2] 982-9406
2 Carter Jo [3] 988-9542
3 Rimbach Frank [2] 989-9031
4 Not Verified
5 Stevens Walt E [5] 988-2659
841a Young Blaine [6] ◎ 988-5105
Rfasoner Jennifer 988-5105
841b-841d Vacant (3 Hses)
868a Robrin Jan [2] 988-9749
868b Conner Thos [2] 988-9749
868½ Trujillo Donelia [4] 983-3004
870 Anderson Stevan T [2] 988-7033
Haygood Bill C [2] 984-1469
874 Adams J [3] 988-3018

10

• E PALACE AV INTERSECTS
1001 Jereb James [2] ◎ 989-8765
1005 WADELL THEODORE & ASSOCIATES archts 983-1252
ALMEDA HILL CONDO ASSOCIATES 983-1252
Waddell Theo H & Eleanor H [2] ◎ 988-2686
1005b Vacant
1005 Summers Ann [2] ◎ 986-9745
1005n Vacant
1009 Not Verified
1010 Vacant
1115 Sena-Stuart Edielinda T [5] ◎ 988-5961

CANDELERO ST–Contd
2194★Maldegen Larry 471-4655
2195★Rougemont Bill 471-5651
2196 Martinez Robt E 471-1477
2198 Leer S D © 473-1477
2199 Shalizi K M © 471-7725

12

CANYON RD –FROM PASEO DE PERALTA EAST

ZIP CODE 87501
200 Streets Of Taos Indian arts & crafts retail 983-8268
202 Street Heather
203 Mountain Wolf Agency real est 983-7301
221 Vacant
223a Delgado Michl © 983-8902
223b Fry Charles W 988-5488
225 Munson Gallery art gallery 983-1657
Units
1 Scarlett's antiques & galleries 983-7092
2 Gondeck Gallery 988-3580
3 Economos art gallery 982-6347
5 Economos (Addl Sp)
6 Spider Woman Design 984-0136
10 Gallery Ten Inc
11 Janus Galleries contemp art gallery 983-1590
14 Meyer Gallery art gallery 983-1434
18 Gingran Katie Gallery art galleries
19 New Trends Gallery art 988-1199
20 La Mesa Of Santa Fe 934-1688
233 Young Edgar jwlr
223a Gateway Gallery (Sculpture) art gallery 983-1818
237★Garcia Donald R 989-7193
DE VARGAS ENDS WS
GARCIA BEGINS SS
400 Durham Linda Gallery fine contempory art 988-1313
403 Santa Fe New Mexico Sombraje Galleries 984-8566
409 Galeria Capistrano imported clo sls 984-3024
414 Canfield Kenneth Indian Art 988-4199
415 American Indian Art antique indian art gallery 982-9900
★Loeffler Rudolf
418★Madison Don J
419 Nichls Robert F Gallery arts-pictures 983-4094
421 Gurrola Jon © 982-4826
421b Vacant
423 Canyon Road Flowers 983-9785
424 Vandenberg Ethel © 983-7845
DELGADO INTERSECTS
503 Mc Adoo Linda Galleries art 983-7182
513 Morning Star Gallery 982-8181
518 No Return
519 Prada J J (Ofc) 984-2119
519a No Return
523 Buchanan Jean M © 982-0344
524★Salazar Theresa
526 Mainville Eldor J 983-6529
526½ Vacant
530★Lidwig Jas
540★Burdine Roddey B © 984-0043
544 Coughlin Bert T Mrs © 982-1045
545 El Zaguan Apartments 983-2567
1 Martin Harold
2 Turkle Brinton 983-6663
2b Rubin Howard A 988-1728
3 Thomas Mack
4 Cellucci Laurie 983-1390
5 Historic Santa Fe Foundation The 983-2567
6 Arne Robt 982-9286
7 Loomis Sylvia G Mrs 982-5963
8 No Return
9 Dunne Frances © 983-9493
546★Botts J S 983-2796
550★Scholz Ray 983-3792
551 Johnson Chester 982-8233
552 Young Dwayne © 982-4693
554★Ramsey Nikolai
555a Adams Jeffrey Antiques Inc 983-6539
555b Native Market The gift shop 983-6535
556 Claibourne Gallery (Addl Sp)
558 Claiborne Gallery 982-8019
CAMINO ESCONDIDIO ENDS NS
600 Sims Agnes © 983-9437
600½ Glenn Edna S 986-0665
Pederson John E 983-3235
601 Mayans Ernesto Gallery art 983-8068
601a Vigil Antonio F © 983-6444
602 Atwill Doug artist 983-2852
Rear Sims Gallery 983-9437
602½ No Return
610 Apartments
A Ross David 988-3133
C Palou Willa Mrs © 982-1082
D Hamill Tom F 983-1897
613 Celebrations restr & caterers 989-8904
Apartments
1★Engelhart S © 982-1970
2 No Return
3 Vigil Ignacio L 982-0052
4★Martinez Martha
6★Vigil Martha
7 Vacant
616 Bookroom The book store 988-5323
616b Croft Frank Fine Art Gallery 984-2220
★Croft Frank
616c★Wysong W
616½★Wysong W W © 988-2103
Hunt Alex 988-3627
617 Young Avis
618 Vacant
619 O'Neill Mollie 983-1159
621 Eastside Furniture Makers 988-7226
Rear Vacant
622 Waxlander Gallery 984-2202
622a Pillows Plus oriental rug sls 983-5960
622b Art Of The Woods wood sculpture 984-2220

CANYON RD–Contd
622c Raven Gallery 984-2202
622½ Vacant
622½a Humphries J Richd 983-5685
624 Gonzales Jose A © 983-6653
626 Studio Of Glan Andrea The artists 982-0054
Bacigalupa Andrea © 982-0054
630 Religious Society Of Friends quaker meeting hse 983-7241
Friends Meeting House Prep Sch day care 988-5214
634 Parrott Fabrics Inc retail 982-0794
635 No Return
640 Running Ridge Gallery 988-2515
641 Kirtley M Mrs © 988-3613
644 Apartments
1 Posters Of Santa Fe 983-9697
1 Munson Larry
2 Keats Gallery & Antiques 982-6686
3 Pettit Bernice 988-3951
4 Paris
5 Young Boyce S 988-1543
6 Rhymes Judy 988-5217
7 Kilgore
8★Mitchell Willie
9 Klose C L 982-2770
10★Milani
11★O'Connell C 989-7630
12★Goetz
650 Vacant
651 Zaplin-Lampert Gallery art gallery 982-6100
652 Quilts Unlimited
653 Compound The restr 982-4353
Compound Apartments The 983-2140
1 Nicholas Edw © 982-8311
2 Sellers Peter © 988-8343
3 Mann C L © 983-6539
4 Satin Jack H © 988-1713
5 Hogan Fred © 988-2466
6 Schweitzer Gertrude © 988-4125
7 Blair Donald © 983-2140
8 Fleischaker R H © 988-5740
9 Maxwell Marilyn © 983-5484
10 Dendahl Eleanor © 982-1177
11 No Return
12 Oliver Emily © 982-1256
13 Loo Lester © 989-9250
14 Samuel Ruth 983-5312
15 Krebs Helen Mrs © 982-3353
16 Silver Caswell © 983-6575
656 Silver Sun Indian Jewelry 983-8743
Creative Eye The jwlrs 982-4982
Vorenberg Tresa Goldsmith 988-7215
Rufus Tile & Metal Studio ceramic tile 988-7215
Concepts Cooperative Gallery sculptors 988-3743
656½ Stowe Junius furn restorer 983-6627
662 Canyon Trading Post 988-5012
662½ Porter Jerry © 982-8637
667 La Bodega indian crafts 982-8043
668 Vacant
669 Daves Phil Studio Gallery art gallery 988-4892
670 Vacant
GROMLEY LA BEGINS
701 Santa Fe New Mexico Umbrello Gallery furn & accessories shop 984-8566
702 Graphics House Gallery The art 983-2654
702½ Nove Collection sculpture panting Robles Ronald A © 988-7040
702½a O'Rourke Kathleen artist 983-2176
706 Laroche Gallery art gallery
707 Lambert Edith Gallery art 984-2783
De La Harpe Volker Carved Doors 983-4074
708 Apartments
1★Mann H
2★Risbourg Wm A III 982-1358
3 Hills Osage Gallery (Ofc) 983-5548
4 Vacant
5★James D
6★Mc Gee B 988-1628
7 Iarrobino Charles 988-2497
8★Fox N
9 Caird Norma Mrs 988-5715
10 Vacant
11★Mathews Paul
★Polich Judith 986-0829
13 Vacant
710 Burke Denman & Associates 983-6014
713 Santa Fe Weaving Center 983-5003
713½ No Return
714 Judy's Unique Apparel clo 988-5746
716 Vacant
717 Artisan Santa Fe artists materials
★Banta Wm R 988-4648
718 Vacant
720 Toys For Big Boys antiques 983-8049
722 No Return
724 Carriage Trade restr 982-3541
725 Desert Son curio dlr 982-9499
725b Desert Son (Addl Sp)
725c Nanan Bloch Design 983-3177
725½ No Return
727 Juanita's Collection antiques pottery jewelry & art 982-0336
Insurance Professionals The 984-8717
728½ Vacant
729 Jones Laurel Gallery art galleries 984-3029
731 Aunt Babe's Restaurant 983-3512
CAMINO MONTE SOL BEGINS SS
802 Andrea's Restaurant 988-9177
806 El Farol (Overflow)
808 El Farol restr 983-9912
808½ Vacant
812 Vacant
820a★Gerlach Chris 986-1458
820b★Clark John 986-1302
821 Clark Pottery The
Silver Star art galleries
Nedboy Joanna artist 983-9662

1988 **E ALAMEDA ST**
SOURCE: POLKS

E ALAMEDA ST–Contd
A Vacant
B No Return
C Ortiz Kathleen A 988-2200
D Fornell Paul 982-1733
E Alrid Arlene 988-2135
339★Brown Tim
339a★Gallegos Frank
339b★Tufft M R
341 Nelson Jacqueline B Mrs
343 Duran Bernard A © 983-8896
345 Medrano Esther Mrs © 983-4916
351★Tashel Carole M 982-6153
353 Lotz Herbert © 982-0685
357 Baca Luis S © 983-4936
DELGADO INTERSECTS
401★Freydkis Emanuel 982-9577
403★Garcia L J © 982-1004
Cantu Alfredo © 983-7644
Willock Dolores Mrs © 982-2715
409 Vigil Eliz
411 Garcia Christine 982-1097
522 Robinson Billie 983-7195
523 Scullin Salorgne © 982-9955
525 Ortiz Arth L © 983-9377
527 Apartments
1★Boissiere M G 982-4557
2 Packard Richd L 983-6305
3 No Return
4 Zeigler Gregory 982-4525
5★Kennedy Gerald F 983-7599
528 Stevenson Dorothy R author © 983-7936
528½ Robbins Scott A
529 Apartments
6★Weydo Gary
7 No Return
8★Astle Narcell
9 Neels Kath 982-2891
10 Kessler Carol A 989-8381
11 Idar Ed 988-7249
12 No Return
540 Spiegel Zane © 982-8658
541 Apartments
A★Stay Randy 982-0311
B★Gomez John 983-1985
C★O'Leary D 988-2160
D Monette Florelle 984-1730
5e Brown David A 983-5388
550 Crumm John C © 982-1473
564 Sutin Esther artist 984-8716
CAMINO ESCONDIDO BEGINS SS
605 No Return
607 No Return
609★Iovino Anita L 986-1125
611★Prince M L 983-3259
614 Reynolds Stephen E © 982-5140
615 Martin Meade P 982-5647
616 No Return
616½a Bolton J M 982-3294
617 No Return
618 Hererra Gilbert © 983-3427
Rear★Neil Eric
624 Apartments
1 Frissel
2 Trudeau
3★Klotche Chas 988-4537
4 Pence John © 982-1246
5 Fries John G © 983-6667
7★Horn David R 984-8711
8 Mystrun
9 Mc Connell D
10★Huel Robt © 988-3728
11 Vacant
12★Whittenburg Eug 988-8010
13 Williams
14★Stevens Story
16 La Farge G
17★Mason Gilbert A 989-7395
18★Sims Byron O Jr 984-8158
19 No Return
630 Bobbs W Howard 983-5570
Apartments
A★O'Neill Jas 984-0378
B Thurston Jeffery A 988-3905
C Swarth Judith 982-8640
D Burt Kim 988-4497
E Ingle Jon 983-5786
F Olmstead Chas
G★Kinslow Paul 989-8050
H Kirtley Hazel
I No Return
633★Yeager Fredk © 986-0611
635 Simkins A C 984-3116
637 Barber Mary W Mrs © 983-9150
CAMINO ESCONDIDO INTERSECTS
701 Apartments
1★Rogers Gail 988-1315
2 Topia Jos 983-7369
3★Dimeff Carol S 984-0750
4 Aranda Patrick
705 River Oaks The custom apts 983-2853
1 Tsukahara Masaru
2★Fisher Jean A
3★Gross Ann E 988-7134
4★Reed Hope
5★Lujan Cynthia M 986-0936
6★Lowe Constance 986-1413
7★Fugiwara Toshihisa 988-2038
8★Augustine Judith 984-2723
9★Garnett D
10★Jenkins M G 982-4308
801★Lubet Lloyd 989-9239
803★Duffy Terry 988-1034
805★Bennett John S 989-9044
815 Apartments
1★Muhs Chloe 983-5780
2 Adams Jack
3★Digneo Bernadette 988-5303
4 Wagner Patti L 982-1609
5 Rostro Rudy 988-2556
817 Apartments
1★Reichstein Gail
2★Urffer Sally 986-1627
3 Vacant
4 Mc Kenna Philip 982-2763
5 Vacant
827 Griego John © 983-3553
829 Griego Augustine © 983-7536
833 Banks Michl © 982-1202
835 Banks Harold E © 982-2341
837 Gabaldon Miguel B © 982-0296
839 Baros Augustin B © 982-0392
840 Apartments
1 No Return
2★Corter Joe 988-9542
3★Hafer Mariannn 989-7495
4★Collins Wm M 988-4918
5 Stevens Walt E 988-2659
841a Young Blaine © 983-3791
841c★Kanter Joel E 989-7846
841b Strong Ron W 988-2095
868a Stark Thekla © 988-1573

1983 **CANYON RD-A**
SOURCE: POLKS

CANDELERO ST–Contd
2198 No Return
2199★Shalizi K M 471-7725

CANYON RD –FROM 323 E CASTILLO EAST TO CITY LIMITS

ZIP CODE 87501
200 Streets Of Taos Gallery 983-8268
202 Vacant
203 Mountain Wolf Agency real est 983-7301
205 Vacant
207 Vacant
221 Vacant
223a Delgado Michl P © 983-8902
223b Fry Charles W 988-5488
225 Under Constn
234 Vacant
DE VARGAS ENDS WS
GARCIA BEGINS SS
400 Durham Linda Gallery fine contempory art 988-1313
Durham Linda 988-1313
403 Oriental Carpets 988-4142
409 Gordon Galleries Ltd art 983-5779
414 Kegal Katherine
415 No Return
418 No Return
419 Santa Fe Co The antiques 983-4094
421 Vacant
421b No Return
423 Vacant
424 Vandenberg Ethel © 983-7845
DELGADO INTERSECTS
503 Mc Adoo Linda Galleries art 983-7182
513 Vacant
519 Van Soelen Danl D © 982-1022
519a★Snyder Tom
523 Buchanan Jean M © 982-0344
524 Talbot John © 983-1242
526 Mainville Eldor J © 983-6529
526½ Baker Dee Anne I 982-3435
530 Ramsburg Charlie 983-8394
540 Smalley Ike M © 982-2950
544 Coughlin John G © 982-1045
545 El Zaguan Apartments
1★Martin Harold
2★Turkle Brinton
2b Rubin Howard 988-1728
3★Thomas Mack
4 Cellocci L 983-1390
5 Vacant
6★Arne Robt
7 Loomis Sylvia Mrs 982-5963
8 Vacant
9 Dunne Frances L © 983-9493
546★Ross John 983-6119
550★Geyssler Teresa
551 Johnson Chester 982-8233
552 Vacant
553 Ellis Fremont F artist © 983-4694
554 Barlow Bonita
555a Adams Jeffrey Antiques Inc 982-1922
555b Native Market The
556 Vacant
558 Apartments
1 Harvest The clo 982-0160
2 Israel Jake
3 Vacant
5 Murphy Virginia ©
6 Vacant
CAMINO ESCONDIDIO ENDS NS
600 Aswell Mary L 983-3235
600a Sims Agnes © 983-9437
600b Goodwin Marion F © 982-3219
600½ Mc Mahon Molly
601 Mayans Ernesto Gallery art 983-8068
601a Vigil Antonio F 983-6444
602★Atwill Doug artist 983-2852
Rear Sims Gallery 983-9437
602½ Koontz Julia I 983-5223
610 Apartments
A Ross David 988-3133
C Palou Wm © 982-1082
D Hamill Tom F 983-1897
613 Haven The restr 988-5888
Apartments
1 No Return
2 Ernst Neal
3 Vacant
4★Corkins Christopher 983-6481
5 Vigil Ignacio L 982-0052
6 Storey David
7 Vacant
616 Prescott's Arlene Boutique clothes 983-5543
616b Santa Fe Weavers blanket sls 983-8518
616½ Gonzales Catalina Mrs © 983-1577
Quinn S A
★Hunt Alex
617 O'Neill Mollie
618 Vacant
619 Penotte Pam 982-0630
621 Canyon Road Custom Frame picture frames mfg 983-2120
Rear Jordan Cookie
Rear Ortiz Val © 982-1238
622 Rios Leather Wear Boots & Shoes 982-8953
622a Wagoneers The 988-2957
622b Hill David
622c★Jennings Richd 984-0337
622½ Rios Barbara 982-8953
622½b Vacant
622½c Humphreys John R
624 Gonzales Jose A © 983-6653
626 Studio Of Gian Andrea The artists 982-0054
Bacigalupa Andrea © 982-0054
630 Religious Society Of Friends quaker meeting hse 983-7241
634 Parrott Fabrics Inc retail 982-0794
640a Running Ridge Gallery 988-2515
641 Vacant
644 Apartments

CANYON RD—Contd
1 Vacant
1 Vacant
3★Tuchey Dorie
4 Buller Fanny P
5 Young Boyce S 988-1543
6 House Max
7 Le Blanc L H
9 No Return
650 Moya Ignacio D ◎
651 Bobbs Howard Art Gallery 983-5672
652 Nichols Robert Antique Store 982-2415
653 Compound The restr 982-4353
Munson Galleries art 983-1657
Compound Apartments The 983-2140
1 Nicholas Edw ◎ 982-8311
2 Sellers Peter ◎ 988-8343
3 Mann C L ◎ 983-6539
4 Satin Jack ◎ 988-1713
5 Hogan Fred ◎ 988-2466
6 Schweitzer Gertrude ◎ 988-4125
7 Blair Donald ◎ 983-2140
8★Fleischaker R H ◎ 988-5740
9 Erwin Robert ◎ 988-4654
10 Dendahl Eleanor ◎ 982-1177
11 Samuel J M Mrs ◎ 983-3544
12★Oliver Emily ◎ 982-9735
13 Kaiser Augustus
14 Carlton Gertrude ◎
15 Krebs Helen Mrs ◎ 982-3353
16 Silver Caswell ◎ 983-2476
656 Bronson C J Designer Of Jewelry & Sculpture 988-2601
Silver Sun Indian Jewelry 983-8743
Aquarius Glass stain glass 988-4837
656½ Vacant
662★Stewart
662½ Porter Jerry ◎ 982-8637
667 La Bodega indian crafts 982-8043
668 Gormley Francis J ◎ 982-0938
669 Mirage Restaurant 982-0388
670 Gormley's gro 982-0938
GROMLEY LA BEGINS
701 Claiborne Gallery 982-8019
702 Graphics House Gallery The 983-2654
702½★Robles Ron 988-7040
702½a Ernies Restaurant (Guest House)
702½b Vacant
706 Vacant
707 Oriental Rugs 988-2348
De La Harpe Volker Carved Doors 983-4074
708 Vacant
Apartments
1 No Return
2 Vacant
3 Vorenberg Tresa Goldsmith 988-7215
4 Weavings Of Joy
5 Rufus Tile & Metal Studio
6 Kotala Hand Loomed & Embellished Clothing
7★Thielen Madeleine 988-2273
8 Vacant
9 Vacant
10 Collins Mike
11 Fish H 983-1318
710 Canyon Road Art Gallery 983-6831
713 Tate Bill artist 983-9321
714 Judy's Unique Apparel 988-5746
716 Park Row Editions 983-3866
717 No Return
720 Fickery The arts & craft
Homire Cynthia
702½ Vacant
724 Alfonso's 982-3541
725 Desert Son curio dlr 983-9801
725b Pretty Outrageous 984-1889
725c Bird Watcher Shop The 982-9912
725½★Lynch Jerry
727 Allen Edda Lynne Studio-Gallery art 988-2120
Three Centuries Gallery 982-4545
Monte Sol Realtors Limited 988-9671
Lee-Tzu Boutique 982-1462
782 Von Horvath Irene 983-8872
728½ Rios Juan R ◎ 983-1179
731 Ernie's Restaurant 982-4274
CAMINO MONTE SOL BEGINS SS
802 El Farol Restaurant & Gallery 983-9825
806 El Farol Antiques
808 El Farol Lounge 983-9825
812 Architectural Antiques Ltd 982-0042
820★Hale Lynn 988-5091
821 Melting Point Glass Works & Pottery 988-2662
Santa Fe Weaving Center 983-5003
822★Ortiz Luis 983-6221
824 Salazar Walter
826 Moskowite Richard
830 Salazar Sophie Mrs ◎ 982-8929
Rear Salazar Roman G ◎ 982-0647
★Kohen Eliot
834 Midyette John T III Architect 983-2639
836 Midyette John T III

10

PALACE AV ENDS
901 La Esquina Antiques 982-4130
Farnsworth Bernice Mrs
906 Wright Louise S ◎ 983-3838
907 Gallegos Al
907½ Delnmeau Greg 983-1324
908 Vacant
908½ Vacant
912 Le Van John A ◎ 988-1912
914 Jones Robt M ◎ 988-3312
917 Vigil Jake ◎ 983-8037
922 Southwest Spanish Craftsmen Inc designers 982-1767
922a Chris Perry
922b★Hubbell Richd S 983-7730
923 Lopez J V 988-4907
924 Delapena Books 982-1299
Durham Bart ◎ 982-1299
924½ Wilson Julius L phys ◎ 983-9507
925 Ed's Appliance Service 982-9598

10★Weeks Danl
11★Idar Ed
12★Bickley Nancy 982-6795
540 Espejo Juan ◎
541 Apartments
A★Delgado Fred
B No Return
C★Lovald Ruth
D Kenrr Tod
550 Crumm John C 982-1473
564★Daly Richd M ◎
CAMINO ESCONDIDO BEGINS SS
609 Vacant
611 Secretary Bird The 988-9180
614 Reynolds Stephen E ◎ 982-5140
615 Markin Meade 982-5647
616 Rodriguez Felix ◎
616½a Wysong Wiona E
617 Vacant
618★Kirby Ken 982-6163
★Matson Pamela H
Rear Herrera Patsy Mrs 983-3427
Apartments
1 Croy Donald D ◎
2★Klotsche Charles 988-1700
3★Dant J R 983-8372
4 Vacant
5★Fries John G
6 Vacant
7 No Return
8★Treisman Eric 983-3033
9 Vacant
11 Vacant
12 Vacant
13★Edmundson J
14 No Return (apts 14-16)
17 Vacant
18 No Return
10★Charnas Juliet 983-1754
630 Apartments
Bobbs W Howard 983-5570
A★Reed Eliz 983-5091
B Thurston Jeff 988-3905
C★Lancaster J M 988-1801
D★Redding Geo H III 983-6076
E★Moore Jane
F Armstrong Michl 983-6680
G★Dillon Nancy P
H★Kimball Tracey
I Vacant
633 Vacant
637 Barber Mary W Mrs ◎ 983-9150
CAMINO ESCONDIDO INTERSECTS
705 Villa Alameda Apartments
1★Fox Elliot 984-1610
2★Weiland W C 988-3465
3 De Vito Janis
4★Bonifer Steven
5 Maremont Steve
6★Good Jack
7★Stebbins Don 983-1720
8★Young Richd L 982-8900
9 Sigunak Sally

E ALAMEDA ST—Contd
10 Gurdo Wally
801★Hunter Tim 982-3084
803 Vacant
805 Golaria Arguero
815 Apartments
1 Baker Greg 988-1825
2 Vacant
3★Bond Gordon
4 Vacant
5 Rostro Rudy 988-2556
817 Apartments
1★Garcia Joe
2★Segura Victor 988-6110
3 Mc Intee Tim
4★Mc Kenna Philip 982-2763
5 O'Schaughnessy Gary 982-0519
827 Griego John ◎ 983-3553
829★Griego Augustine ◎ 983-7536
833 Banks Michl ◎ 982-1202
835 Banks Harold E ◎ 982-2341
837 Gabaldon Miguel B ◎ 982-0296
839 Baros Augustin B ◎ 982-0392
840 Apartments
1 Stevens Walt 988-2659
2★Wynn Meridee
3★Lee Jack
4★Wood Clayton 983-7781
5 Browne Elizabeth T 983-1070
868 Whiteridge Jackie ◎ 988-9252
A Dorman
B Hernandez
868½ Trujillo Donelia ◎ 983-3004
870 Montoya Joe S ◎ 983-4436
874 Phillips Steph B 982-1080

10

E PALACE AV INTERSECTS
1001 Smith Kip F 983-3825
1005 Waddell Theo H ◎ 988-2686
Apartments
1★Underwood Betty
2 Vacant
3 Halla Frank Z 983-8041
1010 Abeyta Tony ◎ 983-8665
1115 Sena Louis A ◎
1117 Anaya Joseph E ◎ 982-3907
1120 Morris Robert E ◎
1122 Bell David ◎ 982-8715
1127 Vacant
1131 Mireles Angie S 983-6243
1133 Shirley Wayne 982-3825
1135 Abeyta Gilbert R

1

ALAMEDA ST WEST —FROM 234 DON GASPAR AV WEST TO CITY LIMITS

ZIP CODE 87501
GALISTCO INTERSECTS
100 Santa Fe River Park
N JEFFERSON INTERSECTS
HANCOCK ST INTERSECTS

1978 CANYON RD

SOURCE: POLKS

550 Rabinowe Steve 983-5003
551 Santa Fe Historical Foundation 982-8233
552 Robertson Robt L © 983-7709
553 Ellis Fremont F artist © 983-4694
554★Neymark Shel
555a Circa Inc antique furn 983-9797
556 Robertson John 983-9235
558 Apartments
1 Harvest The clo 982-0160
2 No Return
3 Coy V M 983-1867
4★Kennedy Susan 988-5606
5 Fullerton Ava L © 982-2846
6★Brooker Valerie 988-5840
CAMINO ESCONDIDIO ENDS NS
600a Sims Agnes © 983-9437
600b Goodwin M F © 982-3219
600½★Temple Mary 982-5198
601 Vacant
601a Vigil Antonio F 983-6444
602 Vacant
602½ Koontz Julia I 983-5223
610 Apartments
A Ross David 988-3133
C Palou Willa Mrs © 982-1082
D Hamill Thos
613 Haven The restr 988-5888
Apartments
1★Mc Bride Glenn 988-1152
2 Vacant
4★Nichols Edw M 982-8311
5★Gilkey Gordon 988-3225
6★Simms Agnes C 983-9437
7 Vigil Ignacio L © 982-0052
616 Handworks jwlry
616b Anderson Tom
616c★Kaufman Sarah
616½ Gonzales Catalina Mrs ©
Gonzales Edward R
617★O'Neill Mollie 983-2903
618 Vacant
619 Walden V W
621 Plum Tree The picture frames mfg 983-2120
Rear Needham Sandra 982-8615
622 Vacant
622a Rodriguez Louis P © 982-9235
622b★Trujillo Ernest
622c Scrafford Randy A 983-4797
622½a Vacant
622½b Cooper Jill Z 988-1133
622½c Humphreys John R 983-8541
622½ Vacant
624 Gonzales Jose A © 983-6653
626 Studio Of Gian Andrea The artists 982-0054
Bacigalupa Andrea © 982-0054
630 Religious Society Of Friends quaker meeting hse 983-7241
Religious Society Of Friends children's meeting rm
Olive Rush Studio (Religions Society Of Friends)

CANYON RD—Contd
630½ Nassiter Dale
634 Parrott Fabrics Inc whol 982-0794
Parrott Allen M © 982-0794
640 Archer Hazel L 983-6753
640½ No Return
641★Robles Ronald A 988-5921
644a Coppery copper wks 988-5857
644b Atwill Douglas © 983-2852
644c★Young Boyce S 988-1543
644d★Gilmore Margt 983-8075
644★Jebb Robt 983-9748
646 Vacant
650 Moya Ignacio D © 988-1960
652 Vacant
Vacant
653 Compound The restr 982-4353
Blair Galleries Ltd 983-9219
655 Compound Apartments The 983-2140
1 Nicholas Edw © 982-8311
2 Boerstler Theo © 982-0845
3★Mann C L © 983-6539
4 Satin Jack © 988-1713
5 Hogan Fred © 988-2466
6 Schweitzer Will P
7 Blair Donald © 983-2140
8 Flaischaker R H © 988-5740
9 No Return
10 Russell J B © 982-9655
11 Samuel J M Mrs © 983-5461
12★Cartwright John © 982-9755
13★Horwitch Arnold © 982-2344
14 Block Jere F © 983-5760
15★Krebbs Helen Mrs © 982-3353
16★Mc Grath Frances © 983-2476
656 Vacant
656½ Stowe Junius Z Jr furniture fnshr 983-6627
656½a★Santiago Dolores
662 Vacant
662½★Porter Jerry © 982-8637
667 Cate Anne L 988-3824
668 Gormley Francis J © 982-0938
669 Mirage Restaurant 982-0388
670 Gormley's gro 982-0938
GORMLEY BEGINS SS
701 Kachina House arts & crafts wks 982-8415
702 Santa Fe Painters Gallery
702½ Matheson Dianna ©
702½a Vacant
★Sisson John 983-3998
702½b Loundes C
703 Vacant
705 Vacant
707 De La Harpe Volker Carved Doors 983-4074
708 One Of A Kind gallery 988-4867
Apartments
1 Cooke Geo
2 Manley P
3 Roush Ralph R
4★Krebs H M 982-3353

1978 E ALAMEDA ST

SOURCE: POLKS

331½★Palmer Bob
335★Sandoval John R © 983-2430
337 Watson Richd ©
338 Ortiz Elmer
Lamkin Michl C 988-4924
338a No Return
338b Alarid Peter 988-2135
338c Lucero M N 988-5463
339 Kretzmann John Aw 983-1659
339a Vacant
339b★Rivera R M 988-4731
341 Nelson Jack H © 982-9939
343 Duran Bernard A © 983-8896
345 Apartments
1★Lyngen Margarita K 988-2392
3 Alarid Frank
4 Vigil Anthony
5 Medrano Tom ©
351 Vacant
353 Dohrer John V ©
357 Baca Luis S © 983-4936
DELGADO INTERSECTS
401 Turner Drew H © 983-3981
403a Garcia Isabelle L Mrs © 982-3162
403b Cantu Alfredo M © 983-7644
403c Willock Dolores Mrs © 982-2715
409★Wigley K R 983-6646
411★Garcia Christine 982-1097
520 Vacant
522 Robinson Billie Mrs oil & gas leases © 983-7195
523 Scullin Salorgne Mrs © 982-9955
525 Ortiz Arth © 983-9377
527 Apartments
1★Wood Helen
2 Candelaria Mary 988-5453
3★Kline Rayann 982-1113
★Bakewell Anderson 982-5166
5 Pert Carmen 983-3952
528 Stevenson Dorothy R author 983-7936
529 Apartments
6 Harding Happy 988-3366
7 Romero Glory V
8★Watts Glenn C 982-2190
9 Neels Kath 982-2891
540 Espejo Juan © 982-8658
541 Apartments
A★Vernon Patricia 982-0471
B★Johnson L E 982-8011
C★Ramsey Sherri 988-1891
D★Bonal Gerald
550 Enfield Robt N © 982-0092
564 Otero Ted M real est © 982-0493
CAMINO ESCONDIDO BEGINS SS
609 Mc Fall Geffory G 983-3215
614 Reynolds Stephen E © 982-5140
615 Herkenham Linda L 983-1553
616 Rodriguez Felix ©
616½a★Hagen Dan 982-1197
616½b Martinez Leronard
617★Burke B 988-4338
618★Sisneros Julio 983-3427
Rear Herrera Gilbert

E ALAMEDA ST—Contd
630 Apartments
A Bobbs W Howard 983-5570
A Moore Jane
B Johnstone James C
C Johnson David
D Kelly Maria
E Leonard Jeanne 983-1327
F Bobbs Sheila 983-6680
633 Blythe School 983-1034
637 Barber Mary W Mrs © 983-9150
CAMINO ESCONDIDO INTERSECTS
705 Villa Alameda Apartments
1★Norman Rae 988-1011
2 King Herbert A 983-1049
3 De Vito Janis
4 Bodenhamer Jerry L
5★Fisher Thellan
6★Forrer K 982-0744
7 Vacant
8 Stokie Glen
9★Velasquez Robt
★Lujan P J 983-2630
801★Koch Karen
803 No Return
805 Vacant
815 Apartments
1★O'Shaughnessy Gary
2★Alcott Margt 983-2996
3★Lujan Sostella
4★Vigil Joanne 983-5096
5★Moreno Al 983-5235
817 Apartments
1★Weber Kurt 988-1795
2 Painter Ernest
3a Murphy Dennis P © 988-2383
3b Vacant
4 Coy Lillian B
5★Kellogg Kara 983-3135
827 Griego John © 983-3553
829 Saiz Narciso © 983-7536
835 Banks Harold E © 982-2341
837 Gabaldon Michl B © 982-0296
837½ Berthrong Sonja 983-4867
839 Baros Augustin © 982-0392
840 Apartments
1 No Return
868★Ambrose C 983-2286
868½ Ortiz Donelia ©
870 Montoya Joe S © 983-4436
874 Phillips Steph B 982-1080

E PALACE AV INTERSECTS
1005 Griffith J W © 983-8204
1115 Sena Louis A © 988-5961
1117 Anaya Joseph E Jr
1120 Gross Mari © 983-5184
1122 Buffington Robt O ©
1127★Sloan Jeff
1131 Roybal Lorenzo © 983-6243
1133 Hubbard Karen

CANYON RD—Contd
Garcia Bobby ◎ 982-0826
234 Valdes Fred 983-4787
234½ Young Eliz M Mrs
DE VARGAS ENDS WS
GARCIA BEGINS SS
400 Wilson Galleries 982-8911
403 Casa Delgado handcarved furn & accessories
409 Candles Tambien 983-8170
Holmes Russell ◎ 983-8170
414★Tubis Seymour 983-9627
415 Vacant
Dougherty Doris A ◎ 983-2305
418 Madtson Don J Antiques 982-4102
Madtson Don J ◎ 982-4102
419 Plum Tree Frame Shop 983-2120
421a Collectors Corner antiques 982-3955
421b Vacant
421c Vacant
423 Prince William Real Estate 982-3955
424 Vandenberg Ethel A ◎ 983-7845
DELGADO INTERSECTS
503 Drew-Pilat int dec 983-4461
Pilat Leonard
513 Jameson Thomas H ◎ 982-5336
519 Van Soelen Danl D ◎ 982-1022
519a Baker Dee A
523 Buchanan Jean ◎ 982-0344
524 Salazar Roman ◎ 983-9456
526 Mainville Eldor J ◎ 983-6529
526½★Bourchart Alex
530 Denning Mary L 983-7214
532 Vacant
540 Smalley Ike M ◎ 982-2950
544 Coughlin John G ◎ 982-1045
545 El Zaguan Apartments 982-1242
1 Skeggs Marion B Mrs 982-3452
2 Campbell Isabel 983-4492
2b Vacant
3 Chamberlain John 983-2782
4 Vacant
5 Old Santa Fe Association 982-1242
6 Larson Dorothy H Mrs 983-3203
7 Loomis Sylvia Mrs 982-5963
7 El Zaguan Inc real est 982-1242
8 Work Allene 983-3830
9 Dunne Frances L 983-9493
546★Vanderlaan Peter
550★Della Penta Cathy 988-3683
552 Robertson Robt L ◎ 983-7709
553 Ellis Fremont F artist 983-4694
554 Vacant
555 Little Bazaar The gifts 983-9585
Valdes Fred M Jr ◎ 983-9585
Reed Charles E 983-9625
556 Vacant
558 Apartments
1 Artium Orbis Gallery 982-9316
2★Lee E Fredrickson 983-8356
3 Coy Virginia M 983-1867
5 Fullerton Ava L 982-2846
6 Odell Maggie 983-1607
CAMINO ESCONDIDIO ENDS NS
600 Sims Agnes C ◎ 983-9437
600a Aswell Mary L Mrs 983-3235
600b Goodwin Marian Mrs 982-3219
600½★Flint Richd W II 982-3306
601a Vacant
601b Perea Anna M Mrs ◎ 983-6444
602 Sims Agnes Studio art gallery 983-9437
Florence gifts 982-3362
Anderson Florence Mrs ◎ 982-3362
602½ Archer Ruth Mrs
610 Apartments
A Tea & Coffee 983-9961
B Mc Bain Kathleen R Mrs

CANYON RD—Contd
C Palou Willa Mrs ◎ 982-1082
D Hamill Tom
613 Apartments
1 La Boheme restr
2★Mc Murdo Christine
3 Vacant
4 Miller Bobbie J 982-9131
5 Vacant
6 Vacant
7 Vigil Ignacio L ◎ 982-0052
616★Schuck Steven
616b★Lawson B
616c★Jimneinck C
616d★Romero Ben
616½ Gonzales Felberto ◎ 983-3438
617★Susco Laurel 988-3321
618 Wood James R ◎
619 Girard Ophelia
621 Genesis Gallery Corp 988-2312
★Davis David
Rear Needham Sandra
622 Rodriguez D Padilla ◎ 983-9153
622a Rodriguez Louis P ◎ 982-9235
622b★Ortega Leo
622c★Kirwin Jerry R
622½★Briggs David
624 Gonzales Jose A
626 Studio Of Gian Andrea The artists
Bacigalupa Andrea ◎ 982-0054
630 Religious Society Of Friends quaker meeting hse 983-9430
Religious Society Of Friends children's meeting rm
Stothart Robt F 983-9430
630½★Glasser Milliane
634 Parrott Fabrics Inc whol 982-0794
Parrott Allen M ◎ 982-0794
640 Shop The antiques 983-7652
640½ Aleknovitch Alex 983-1204
644a★Gilmore Margt B 983-6474
644b Stewart Victor L ◎ 983-2852
644c Bettina Studio art
644d★Underhill John
646 Stewart Victor L archt
650 Moya Ignacio D ◎ 988-1960
652 Vacant
Stephens Kay Santa Fe Shirts 983-8052
Majestic Dry Goods
Que Tenga Buena Mano leatherworks 982-2912
653 Compound The restr 982-4353
Blair Galleries Ltd 983-9219
Blair Donald ◎ 983-2140
656 Leather Shop
656½ Stowe Junius Z Jr 983-2151
656½c Martinez Tony
662 Moya Richd
662½ No Return
663 Rael Ezequiel T ◎ 983-3839
667 Rael Romancita Mrs ◎ 982-0753
668 Gormley Francis J ◎ 982-0938
669 Garrison Robt
670 Gormley's gro 982-0938
GORMLEY BEGINS SS
701 Neilson Gallery
702 Gallery Santa Fe The 983-5214
702½ Randolph Elvira M Mrs ◎
702½a Home Brew restr
Luboff Ken
702½b★Nauratil Mary 983-5676
705 Stitching Horse Corp leatherwork & weaving 982-8423
Field Contemporary artist 988-1955
707 De La Harpe Volker Carved Doors 983-4074
708 Apartments
1 Compron Donald
2 Rodriguez Rudy F 983-9589
3★Wilson Janice
4 Sather Tom
5★Calloway Merrill B
Home Of Miniatures The art 988-2062
6★Mc Laughlin R
7★Mayes Jackie

1973 E ALAMEDA ST

SOURCE: POLKS

E ALAMEDA ST—Contd
1 ★ Lujuane W E
2 Vacant
3 Matson Joseph T 982-9459
4 Dodds Gertrude G Mrs 982-5740
5 Trujillo Edw A 983-2888
528 Stevenson Dorothy R author
529 Apartments
1 Vacant
2 ★ Mc Dermott Wm J
3 Vacant
4 ★ Lopez Dorothy
5 ★ Roberts Willie
6 ★ Porter Even
7 No Return
8 ★ Wright Billy
9 Meals Katy 982-8049
540 Spiegel Zane ◎ 982-8658
541 Apartments
1 Chegaras Antonios D
2 Vacant
3 Vacant
4 Wallis Janice M Mrs
550 Scott Eleanor M Mrs ◎ 982-5653
564 Otero Ted M real est ◎ 982-0493

CAMINO ESCONDIDO BEGINS SS

614 Reynolds Stephen E ◎ 982-5140
615 Vacant
616 Overman Dennis 983-1128
616½ Saiz Joe I ◎
Lanes Jim
617 Berry Weldon 983-5408
618 Sundown Paul
Herrera Gilbert E ◎
Rear Vacant
630 Bobbs Howard 983-5570
Rear Vacant
633 Blythe School 982-5912
637 Barber Mary W Mrs ◎ 983-9150
650 Compound The apts
Apartments
1 Under Constn (17 Apts)

CAMINO ESCONDIDO INTERSECTS

705 Zamora Patricia
711 Under Constn
803 Vacant
805 Vacant
815 Apartments
1 Evans Ernestine D Mrs
2 Fleming Janet I 983-1340
3 ★ Goodwin Lorin Mrs
4 Batista Mario 982-9273
5 Vacant
817 Apartments
1 King Marjorie F Mrs 983-4938
2 Vacant
3 Hickey Thos E 982-0611
4 Vacant
5 ★ Sorensen Nielson
827 Griego John ◎ 983-3553
829 Saiz Narciso ◎ 983-7536
835 Banks Harold E ◎ 982-2341
837 Gabaldon Michl ◎ 982-0296
837½ Vacant
839 Baros Augustine ◎ 982-0392
840 Apartments
1 ★ Sandoval L
2 No Return
3 No Return
4 Sisneros Rose Mrs
868 Vacant
868½ Trujillo Donelia Mrs 983-9657
870 Montoya Joe S ◎ 983-4436
874 ★ Montoya Pete

E PALACE AV INTERSECTS

1005 Vacant
1115 Sena Louis A ◎
1117 Anaya Joe 982-3907
1120 Durham Lee ◎
1122 Buffington Robt O ◎ 983-2373
1127 Holmes Leroy P ◎
1131 Roybal Lorenzo ◎ 983-6243
1133 Vacant

1968 CANYON RD-A

SOURCE: HUDSPETHS

CANYON RD--CONTD
414 TUBIS SEYMOUR 983-9607
415 CONNOISSEUR THE ART GALLERY 982-8306
DOUGHERTY & DONNELLY ADV SERV 982-8306
DOUGHERTY DORIS A ◎ 982-8306
418 THOMPSON BARBARA ◎ 983-3061
419 HAND CRAFT HOUSE HOBBY SYPS
PALETTE THE CRAFT SHOP
SANTA FE SCHOOL OF FINE ARTS ART SCH 982-2245
421A VACANT
421B VACANT
423 VACANT
424 VANDENBERG ETHEL A ◎ 983-7845

---DELGADO INTERSECTS

503 FITCH DAVE L
513 REED MARGT A MRS ◎ 982-5336
519 VAN SOELEN DANL D ◎ 982-1022
519A HILL R KERMIT
523 BUCHANAN JEAN ◎ 982-0344
524 SALAZAR ROMAN ◎ 983-9456
526 MAINVILLE ELDOR J 983-6529
530 FERRICK MARIE MRS 983-8585
532 BRADSHAW JOSEPH A
540 SMALLEY IKE M ◎ 982-2950
544 PATE BERT T MRS ◎ 982-1045
545 EL ZAGUAN APARTMENTS 982-1242
1 SKEGGS MARION B MRS 982-3452
2 BAILEY FREDRICK
3 NIXON H MRS
4 BILLINGS M
5 LANDSCAPE JOHN B JACKSON PUBL MAGAZINE 982-0964
6 LARSON DOROTHY MRS
7 LOOMIS SYLVIA MRS 982-5963
7 SPANISH COLONIAL ARTS SOCIETY 982-1242
7 HISTORIC SANTA FE FOUNDATION 982-1242
7 OLD SANTA FE ASSOCIATION 982-1242
7 EL ZAGUAN INC REAL EST 982-1242
8 WORK ALLENE 983-3830
9 DUNNE FRANCES L 983-9493
546 VACANT
550 DUENKLER ARNO H
551 VACANT
552 BINKLEY BEE MRS ◎ 982-0443
553 ELLIS FREMONT F ARTIST 983-4694
554 MOES LEO
555 LITTLE BAZAAR THE GIFTS
VALDEZ FRED M JR ◎ 983-9585
REED CHARLES E
556 WHITTAKER JAMES M 982-8492
558 DAWLEY WALTER W 982-4735
ZAGAR MARCHA MRS
558A VACANT
558B VACANT

---CAMINO ESCONDIDIO ENDS NS

600 SIMS AGNES ART GALLERY 983-9437
SIMS AGNES C ◎ 983-9437
ASWELL MARY L MRS 983-3235
600½ VACANT
601 WEST HAL GALLERY ART GALLERY 983-7674
WEST HAROLD E 983-7674
PEREA ANNA M MRS ◎ 983-6444
602 FLORENCE GIFTS
ANDERSON FLORENCE MRS ◎ 982-3362
602½ VACANT
610 ALLEN ROBT
PALOU WM B ◎ 982-1082
613 APARTMENTS
1 VACANT
2 VACANT
3 ORLANDO'S BARBER SHOP
4 VIGIL IGNACIO L ◎ 982-0052
616 VACANT

CANYON RD--CONTD

616B VACANT
616C KING ALEXANDER
616½ GONZALES FELBERTO ● 983-3438
617 ABSHER LLOYD
618 PADILLA FRANK JR ● 983-8838
619 VACANT
621 PERCY'S GROCERY & MARKET 982-1238
ORTIZ PERCY ● 982-1238
622 VACANT
622A RODRIGUEZ DANL P 983-9153
622B VACANT
622½ GONZALES ALFONSO
624 GONZALES JOSE A ●
626 STUDIO OF GIAN ANDREA THE ARTISTS
BACIGALUPA ANDREA ● 982-0054
630 MILLER DUNCAN WRITER 982-5147
634 PARROTT FABRICS INC WHOL 982-0794
PARROTT ALLEN M ● 982-0794
640 SHOP THE ANTIQUES 983-7652
640½ RUTHLING FLOYD
644 OLIVAS LOUIS ● 983-3543
ABBOTT WARD W 983-5542
RALSTON RICHD J
646 YANDA BILL F 983-6661
650 MOYA IGNACIO D ●
652 PAPER BOOK GALLERY 982-9542
STEPHENS KAY SANTA FE SHIRTS 983-8052
JEWEL CASE JWLRS MFRS 983-5606
656 DILLARD THURMON ART GALLERY
CLAUDE'S RESTR 983-9825
656½ VACANT
662 MOYA MAGDALENA MRS ● 982-5438
662½ DELORA SANTIAGO
663 RAEL EZEQUIEL ● 983-3839
667 RAEL ROMANCITA MRS ●
668 GURMLEY FRANCIS J ● 982-0938
669 GARRISON ROBT 982-0061
670 GORMLEY'S GRO 982-0938
---GORMLEY BEGINS SS
701 DE LA HARPE VOLKER CARVED DOORS 983-4074
702 PUERTA DE ORO GALLERY ART 982-8101
702½ RANDOLPH ELVIRA M MRS ●
VIGIL JESSIE MRS 983-7281
708 BLUE VOYAGE GALLERY ART
708½ APARTMENTS
1 HOUGE GENE
3 MOYSON JANE
4 VACANT
5 GONZALES GENE
6 WILSON SANDRA
7 RODRIGUEZ RUDY F ● 983-9589
710 SPIESS PAULINA A MRS 982-3710
710½ NO RETURN
713 LYNCH CHARLES M ● 983-6460
713½ CULLIVAN JOHN
716 SANTA FE JEWEL SHOP
716½ MC DONALD DONALD
717 MC HUGH KIDDER ARCHTS 982-8556
717½ STUDIO THE ART GALLERY
FORD WM
718 RUSSELL BELLA
722 RICHARDSON E C
724 THREE CITIES OF SPAIN RESTR 983-9815
725 MAITLAND-STOKES GALLERIES ART GALLERY 983-5231
725½ ROMERO JOE M 982-2031
727 POOR RICHARD ART GALLERY
PAMPER HOUSE PET SUPPLY & GROOMING 982-1262
D A S INC GIFT SHOP 983-6042
728 VON HORVATH IRENE A ● 983-8872
728½ RIOS JUANITO R
APODACA BERNARDINO ●
729 FEATHER MOON GIFT SHOP
731 INTERIOR ACCENTS OF SANTA FE INT DEC 982-1603

ALAMEDA ST EAST--CONTD

EL CASTILLO APARTMENTS--CONTD
604 CLIFFORD GERALDINE A 982-3745
606 MC EWEN HILDA W MRS 982-1108
608 MC DOUGALL CAROLYN S
612 VACANT
614 COOK JAMES
616 GARCIA ENOS E 982-9349
618 MUSSER C M
620 CULLEN DALE
622 VACANT
624 CROSS FLOYD
626 HOOVER LOUISE W
628 CLARKSON LUCY G
630 VACANT
632 VERNON WM H 983-4671
634 VACANT
636 VACANT
638 VACANT
640 VACANT

12
---S CASTILLO INTERSECTS
275 SAINT FRANCIS CATHEDRAL SCHOOL 982-0331
301 CASITAS DEL RIO APARTMENTS
1 GRAVES D DANE 982-3525
2 SCHWEISER JULIET S MRS 983-9176
3 JONES ELLEN M 982-3793
4 JONES HESTOR 982-1793
5 HENRY THOS P MRS 982-5987
6 STATE DEPT OF EDUCATION (VOCATIONAL DIV)
311 HARVEY GLADYS R MRS ● 983-4987
328 WHEELER ALTA MRS ● 983-4138
NORVELL FLORENCE MRS 983-4138
329 SALAZAR RICHD 982-3738
331 APARTMENTS
1 RAMIREZ ROBT A
2 THOMAS MARCELLA
3 HARDING WADE 982-3394
331½ WHEELER GEO G ● 982-0955
335 VACANT
337 GUTIERREZ RAFELITE ●
338A GONZALES RICHD M 983-3529
338B NEWSINGER AUREL B
339 GONZALES JOSE V ● 983-9577
339A VACANT
339B JIMENEZ JUAN M
341 HAYDOCK JOSEPH ● 982-9418
343 DURAN BERNAD A ● 983-8896
345 MEDRANO TOM J ● 983-5851
APARTMENTS
1 BREWER ROBT
2 MEDRANO ROBT A 982-1055
3 LOPEZ ROBT
4 PEREA JOE
349 VACANT
351 MEDRANO THOS JR ● 983-5851
353 DOHRER JOHN V ●
357 BACA LUIS S ● 983-4936
---DELGADO INTERSECTS
401 GRIFFIN DOROTHY MRS ● 983-8038
403 GARCIA ISABELLE L MRS ● 982-3162
CANTU ALFREDO M ● 983-7644
WILLOCK DOLORES MRS ● 982-2715
409 HOWLAND SARA MRS
411 MIERA LOUIS F ● 983-8435
520 SANDERS WILTON L
522 ROBINSON BILLIE MRS OIL & GAS LEASES ● 983-7195
523 MAGERS H BRADY ● 983-8736
525 ORTIZ ARTH ● 983-9377
527 APARTMENTS
1 STEWART ROBT H 983-7849
2 KEROS KAY 982-8090
3 MATSON JOSEPH T 982-9459
4 DODDS GERTRUDE MRS 982-5740
5 THOMPSON NELLIE
528 STEVENSON DOROTHY R AUTHOR
529 APARTMENTS
6 VACANT
7 GOWAN DAN
8 WALKER FRED J
9 PRICE HUGH 982-7486
540 SPIEGEL ZANE ● 982-8658
550 SCOTT WINFIELD T AUTHOR ● 982-5653
564 OTERO TED M REAL EST ● 982-0493
---CAMINO ESCONDIDO BEGINS SS
614 REYNOLDS STEPHEN E ● 982-5140

1968 E ALAMEDA ST-B

SOURCE: HUDSPETHS

ALAMEDA ST EAST--CONTD

615 BUCKLEY KATHRYN MRS
982-5193
616 GALLEGOS DANL
616½ SAIZ JOE I •
FICK CYNTHIA STUDIO
ARTIST
617 WESCHE ALICE 982-8659
618 GARCIA FLORIAN
982-9680
HERRERA GILBERT •
REAR VACANT
630 BABBS HOWARD 983-5672
REAR VACANT
633 BLYTHE SCHOOL
982-5912
637 BARBER MARY W MRS •
983-9150
650 COMPOUND THE RESTR
982-4353
APARTMENTS
1 KINNEY MARIAN C MRS
982-5838
2 MC CHESNEY EVA J
MRS 983-4842
3 HOOTON WM 982-5097
4 DUHOYS ALEX
5 STETSON HAFFORD MRS
983-8778
6 VACANT
7 BIEBER C FRANCES
982-1038
8 SCOTT MARY 982-9760
---CAMINO ESCONDIDO
INTERSECTS
803 DURAN ROBT J
805 GABALDON BEN A
983-6787
815 APARTMENTS
1 NO RETURN
2 CALDWELL MARJORIE
983-6818
3 JOHNSON JAMES R
AUTHOR 982-4186
4 BULLARD DEWEY
5 SULLIVAN WM
817 APARTMENTS
1 KING MARJORIE F
983-4938
2 COLLEY EDWIN
3 JOE J R MRS
4 COY LILLIAN B
982-4167
827 GRIEGO JOHN •
983-3553
829 SAIZ NARCISO •
983-7536
835 BANKS HAROLD E •
982-2341
837 VACANT
837½ COHN ROLF
839 BAROS AGUSTIN •
982-8312
840 APARTMENTS
1 MILLER MARILLITA
MRS • 983-9536
2 MADRID JOE M
3 GONZALES REYNALDO L
4 ORTIZ SOTERO
868 MARQUEZ MARY MRS
MONTOYA TESSIE MRS
868½ TRUJILLO JAKE R
983-9657
870 MONTOYA JOE S •
983-4436

10

---E PALACE AV INTERSECTS
1115 SENA LOUIS A •
1117 ANAYA JOSEPH E JR •
982-3907
1120 GROSS MARIE DE VILLE
MRS • 982-0536
1122 CARTER MERLE W MRS
983-7888
1127 HOLMES OLIVER •
983-6465
1131 ROYBAL LORENZO •
983-6243
1133 SCHOENFELD PETER

1

ALAMEDA ST WEST -FROM 234
DON GASPAR AV WEST TO
CITY LIMITS

---ZIP CODE 87501
---GALISTEO INTERSECTS
100 SANTA FE RIVER PARK
213 SCHIFANI BROS
PRINTING CO INC
982-2489
235 HOLMAN APARTMENTS
1 LEYBA TONY
2 VACANT
3 VACANT
4 CHAVEZ RAMON
5 SWEENEY SARAH MRS
6 PALOMINO MARCELLA
MRS
7 CHAVEZ JERRY
8 ANAYA HELEN
9 PADILLA MARY
10 RIVERA NACRIO
237 VACANT
239 CAPITOL OFFICE
MACHINES 982-9691
241 FIRST NORTHERN SAVING
& LOAN ASSN 983-4314
---N JEFFERSON INTERSECTS
---HANCOCK ST INTERSECTS
425 FOODWAY MARKETS
982-0741
451 INDEPENDENT GROCERY
982-1011
459 VACANT
---DE FOURI BEGINS
461 MOYA ENRIQUE
463 TRUITT ANTONIO
465 CRESPIN ABEL
467 SALAZAR FRANCISCO
469 MARTINEZ VICTORIA MRS
471 GALLEGOS SOLEDAD
473 RIVERA RUFINA M
982-0333

1964 CANYON RD-A

SOURCE: HUDSPETHS

CANYON RD--CONTD

400 WILSON GALLERIES OF
FINE ART &
APPRAISALS ANTIQUES
982-8911
WILSON GALLERIES
ANTIQUES 982-8911
409 DELGADO URSULA MRS •
982-0095
414 NO RETURN
415 CONNOISSEUR THE ART
GALLERY 982-8306
DOUGHERTY & DONNELLY
ADV SERV 982-8306
DOUGHERTY DORIS A •
982-8306
418 ROBEY ROBERTA •
982-5320
419 HAND CRAFT HOUSE
PALATTE THE CRAFT SUP
SANTA FE SCHOOL OF
FINE ARTS ART SCH
982-2245
421B GOMEZ ANN MRS
423 BOBCHAK JOHNNY
424 VANDENBERG ETHEL •
983-7845
---DELGADO INTERSECTS
503 TALAVERA S FRED
513 REED MARGT A MRS •
982-5336
519 VAN SOELEN DANL D •
982-1022
523 BUCHANAN JEAN
524 FICK JORGE ARTIST
982-8859
526 MORANG DOROTHY STUDIO
ART GALLERY 983-8846
MORANG DOROTHY MRS
983-8846
530 FERRICK MARIE MRS
983-8585
532 ZIMMERMANN MAUD W MRS
• 982-9487
540 CATRON JANET S MRS •
982-0738
544 PATE BERT T MRS •
982-1045
545 EL ZAGUAN APARTMENTS
982-1243
1 SKEGGS MARION MRS
2 BAILEY FREDRICK
3 LAMBERT RUTH
4 OGLE EDW M 982-2471
5 NO RETURN
6 ARMIJO TERESA MRS
7 LOOMIS SYLVIA MRS
982-5963
8 VACANT
9 DUNNE F L 983-9493
546 HONEA ANN MRS
983-8876
550 WILEY THOMAS R
982-0528
551 JOHNSON JOSEPH J
982-2408
552 BINKLEY BEE MRS
982-0443
553 ELLIS FREMONT F
ARTIST 983-4694
554 ARMSTRONG GREG P
1 REED CHARLES
2 VALDES FRED M JR •
983-9585
556 WHITTAKER JAMES M
982-2064
558 UNITED PROTESTANT
ADOPTION AGCY
982-4014
1 NEW MEXICO
TUBERCULOSIS ASSN
982-1071
4 SANTA FE
ASSOCIATION OF
ARTS & CRAFTS
GALLERY
4 JOHNSON JOHN L
5 VACANT
---CAMINO ESCONDIDIO ENDS
NS
600 SIMS AGNES C •
983-9437
600½ NO RETURN
601 WEST HAL GALLERY ART
GALLERY 983-7674
WEST HAROLD E
983-7674
PEREA ANNA M MRS •
983-6444
602 FLORENCE GIFTS
982-1175
ANDERSON FLORENCE MRS
• 982-3362
602½ NO RETURN
610 KACHINA HOUSE CURIOS
982-8415
PALOU WM B • 982-1082
1 CARSON JOEL M
983-3918
2 VIGIL ORLANDO E
2 GARCIA EDDIE J
STONE MASON
982-4102
3 VIGIL IGNACIO L •
982-0052
4 ARMIJO ALBERT
616 NO RETURN
616½ GONZALES FELBERTO •
983-3438
617 HOUSTON FERN MRS
983-6023

1964 CANYON RD-B

SOURCE: HUDSPETHS

CANYON RD--CONTD

618 PADILLA FRANK JR • 983-8838
619 KURTH ROBT W 983-8730
621 PERCY'S GROCERY & MARKET 982-1238
ORTIZ PERCY • 982-1238
622 UNIVERSAL CLEANERS 983-8612
622A RODRIGUEZ DANL P 983-9153
622B RODRIGUEZ LUIS P • 983-8612
622½ RODRIGUEZ BRAULIA P MRS • 983-7953
QUINTANA ASCENCION
624 GONZALES JOSE A • 983-6653
626 STUDIO OF GIAN ANDREA THE ARTISTS
BACIGALUPA ANDREA • 982-0054
630 RUSH OLIVE ARTIST • 983-7935
STEEPER DOURTHY •
634 PARROTT FABRICS INC FABRIC 982-0794
PARROTT ALLEN M • 982-0794
640 SHOP THE ANTIQUES 983-7652
640½ JOHNSON MARJORIE MRS •
644 OLIVAS LOUIS • 983-3543
HADDOX KATH
GOODNIGHT HAROLD E
646 COLLINS PATRICIA
650 MOYA IGNACIO D • 983-4643
652 NO RETURN
PAPER BOOK GALLERY 982-9542
STEPHENS KAY SANTA FE SHIRTS 983-8052
PEASANT SHOP LADIES CLOTHING
656 D A S INCORPORATED ART GALLERY 983-6042
CLAUDE'S RESTR 983-4683
656½ NO RETURN
662 MOYA MAGDALENA MRS • 982-5438
663 RAEL EZEQUIEL • 983-3839
667 RAEL ROMANCITA MRS • 982-0753
668 GORMLEY FRANCIS J • 982-0938
669 VACANT
669½ SENA ANTHONY •
670 GORMLEY'S GRO 982-0938
---GORMLEY BEGINS SS
702 PUERTA DE ORO GALLERY ART 982-8101
702½ RANDOLPH ELVIRA M MRS • 982-9406
708 LEGGETT LUCILLE W ARTIST 983-9723
REAR VACANT
708½ STOWE JUNIUS Z JR FURNITURE REFINISHING 983-7903
STOWE JUNIUS Z JR 983-7903
HAGUE EUGENE L
RODRIGUEZ RUDY F • 983-9589
710 SPIESS PAULINE MRS •
710½ ALARID LUCILLE •
713 LYNCH CHARLES M • 083-6460
713½ GREGOR DORIS J MRS 982-9396
716 SIMS AGNES ART GALLERY 983-7410
716½ NO RETURN
717 MC HUGH-KIDDER-PLETTENBERG ARCHTS 982-8556
717½ FORD WM
718 HOLLEY JESSYE M
ALLEN FRANK 982-3081
720 SIMS AGGIE STUDIO ARTIST 982-7410
722 THOMPSON ANNE C 982-3194
724 NO RETURN
725 LYNCH JOHN • 983-9537
725½ JACQUEZ TONY 982-9580
727 HACHMEISTER ALBERT ACCOUNTANTS 983-6263
PAMPER HOUSE PET SUPPLY & GROOMING 982-1262
TAOS CONTEMPORARY FURNITURE MFG 982-2455
REAR GREENWAY FRED H 982-2455
728 VON HORVATH IRENE A • 983-8872
728½ RIOS JUANITO R
APODACA BERNARDINO •
729 VACANT

1964 E ALAMEDA ST

SOURCE: HUDSPETHS

ALAMEDA ST E--CONTD

528 STEVENSON FREDK R • 983-7936
STEVENSON DOROTHY R AUTHOR
528½ VACANT
6 BOWERSOCK DALE D 982-0878
7 COLLINS TERRENCE 983-4295
8 CALDWELL MARJORIE 983-6818
9 HAEGBERG R J
540 VACANT
550 SCOTT WINFIELD T AUTHOR • 982-5653
564 OTERO TED M REAL EST • 982-0493
---CAMINO ESCONDIDO BEGINS SS
610 NO RETURN
613 UNDER CONSTN
614 REYNOLDS STEPHEN E 982-5140
615 BUCKLEY GEO H 982-5193
616 RODRIGUEZ FRANCES V MRS • 983-4246
616½ SAIZ JOE V •
617 WESCHE ALICE MRS 982-8659
618 SISNEROS JULIO • 983-7545
GARCIA FLORIAN 982-9680
SAIZ ROBERT
HERRERA GILBERT • 982-2934
REAR ORTIZ MARIE MRS
630 ANDERSON HORACE PRINTER • 983-4437
REAR VACANT
633 BLYTHE SCHOOL 982-5912
637 BARBER MARY W MRS • 983-9150
650 RUTHERFORD J C
A EHRICH JUDITH
B CLAPPER CHARLES 982-3982
1 KINNEY MARIAN C MRS 982-5838
2 MC CHESNEY EVA J 983-4842
3 SHAPARIO JOSEPH
4 WORK ALLENE 983-3830
5 STETSON HAFFORD MRS 983-8778
6 DU HAYES ALEXANDER 983-6368
7 BIEBER C FRANCES 982-1038
8 SIMPSON JAMES C 983-4630
---CAMINO ESCONDIDO INTERSECTS
801 LESTER HARRY L 982-9284
803 VACANT
805 VACANT
1 JOHNSON JAMES R AUTHOR 982-4186
2 CAMPBELL CHARLES
3 DALLAS GENE MRS 982-9385
4 CURRIE ELEANOR 982-9264
1 VACANT
2 CHANDLER EDWARD S 983-7463
3 BRANNAN DAVID M 982-5774
4 COY LILLIAN B 982-4167
827 GRIEGO JOHN • 983-3553
829 SAIZ NARCIO • 983-7536
835 BANKS HAROLD E • 983-4834
837 CDE BACA FRANK
837½ VIALPONDO IKE J
839 BAROS AGUSTIN •
1 MILLER MARILLITO R MRS • 983-9536
2 MADRID JOE
3 VACANT
4 BAROS AGUSTIN B JR
7 VACANT
10 VACANT
11 VACANT
868 LOVATO DAN
MONTOYA TESSIE MRS
868½ TRUJILLO JAKE R • 983-9657
870 MONTOYA JOE S • 983-4436
8 CALDWELL MARJORIE MRS • 983-6818

---E PALACE AV INTERSECTS
1115 SANA LOUIE •
1117 ANOYA JOSEPH E • 982-3907
1120 GROSS MARK • 982-2207
1122 CARTER MERLE W MRS 983-7888
1127 HOLMES OLIVER • 983-6465

CANYON RD--Contd
400-Contd
Linder Lois Mrs artist ΔYU2-1778
Berge Lillian M Mrs ΔYU3-9286
403 Delgado Dolores ◎
409 Delgado Ursula Mrs ◎ ΔYU2-0095
414 Bowen Ben ΔYU2-1546
415 Daugherty Doris A
415 Donnelly Margt V artist ΔYU2-8306
418a Johnson Beulah M
419 Parra Jas W
421a Bain Otho C ΔYU2-2825
421b Lucero Ludger ΔYU2-0528
423 Jacquez Antonio
423b Waunek Jennie Mrs
424 Vandenberg Ethel ◎ ΔYU3-7845

Delgado intersects

503 Delgado Frank ◎ ΔYU2-5446
503a Devault Karen ΔYU3-6556
513 Reed M Ann Mrs ◎ ΔYU2-5336
519 Dietrich Margretta S Mrs ◎ ΔYU2-0238
Buchanan Jean
519a MacDonals Susan R Mrs ΔYU3-7970
524 Fern-Rae Studio art studio
526 Morang Dorothy Mrs ΔYU3-8846
Morang Dorothy Studio art gallery
530 Abraham Jas R ΔYU3-9327
532 Zimmermann Maud W M Mrs ◎
540 Catron Fletcher A ◎ ΔYU2-0738
544 Pate Saml J ◎ ΔYU2-1045
545 **El Zaguan Apartments**
Apartments:
1 Thomas Eliz
2 Travis Tamara Mrs ΔYU3-7287
2b Hurley Hazel
3-4 Scholta John E ΔYU2-5750
5 Jefferson Martha ΔYU2-9321
6 Jones Forrest J
7 Connell Mary K artist ΔYU3-3936
8 Guest Grace D ΔYU3-8553
9 McChesney Eva J ΔYU3-4842
10 Thompson Ezra M ΔYU2-9503

Street continued

546 Gerhart Margt M Mrs ΔYU2-0518
550 Johnson Frank W ΔYU2-0470
551 Vacant
552 Binkley Bee Mrs ◎ ΔYU2-0443
553 Ellis Fremont F artist ΔYU3-4694
554 Grauhn Wm
555 Howland's Barber Shop
Howland Domicita Mrs ◎ ΔYU2-0019
Reed Alex
556 Should Arnold ΔYU2-5464
558 **Apartments**
1 Vacant
2-3 New Mexico TB Assn ΔYU2-1071
4 Griego Steve J ΔYU3-9448
5 Mellencamp Virginia L ΔYU3-9448
6 Apodaca Richd B ΔYU2-5688

Camino Escondido ends ns

600 Sims Agnes C ◎ ΔYU3-9437
Aswell Mary L Mrs author
600½ Vacant
601 Perea Anna Mrs ◎ ΔYU3-6444

RAY JONES

CANYON RD--Contd
601--Contd
West Hal Western Gallery ΔYU3-7674
West Harold E ΔYU3-7674
602 Bates Wm S ΔYU2-4297
602½ Peckham Stewart L ΔYU2-2936
610a Bowman Jan
610b Vacant
610c Palou Wm B ◎ ΔYU2-1082

613 **Apartments**
1 Bennett Guthrie B ΔYU2-5988
2 Niki knit gds ΔYU2-9481
3 Vigil Ignacio ◎ ΔYU2-0052
4 Chillicut Sue

Street continued

616a Crawford Milo
616b Lacy Beverly artist ΔYU2-5698
616½ Gonzales Fileberto ◎ ΔYU3-3438
617 Elworthy Robt W
618 Padilla Frank ◎ ΔYU3-8838
619 Vacant
621 Percy's Gro & Mkt
Ortiz Percy ◎ ΔYU2-1238
rear Ortiz Richd ΔYU3-6453

622 Universal Cleaners ΔYU3-8612
622a Rodriguez Danl P ◎ ΔYU3-9153
622b Rodriguez Luis P ◎
622½ Rodriguez Braulia P Mrs ◎ ΔYU3-7953
Gonzales Jose A ◎ ΔYU3-6653
626 Bacigalupa Andrea ◎ ΔYU2-0054
Studio of Gian Andrea artist
630 Rush Olive ◎ artist ΔYU3-7935
630 White Len O
Ferret Andres Mrs
634 Parrott Allen ◎ ΔYU2-0794
Market The gifts
640 Parton Mildred Mrs ◎
640½ Adams John E jr ΔYU3-3954
644 Olivas Louis ◎ ΔYU3-3543
Haddox Kath
646 Moya Gudalupe L
650 Moya Ignacio D ◎ ΔYU3-4643
651 Vacant
652 Quivira Shop (br) gifts ΔYU3-7852
Patio Gallery art ΔYU3-8052
Stephens Kay Santa Fe Shirts ΔYU3-8052
Tea House of Patio 652 ΔYU3-8052
656 Claude's restr ΔYU3-4683
656½ Perry Jas J ΔYU3-6545
Garcia Rufus V ΔYU2-0188
Cook Edw R ΔYU2-0367
662 Moya Magdalena Mrs ◎ ΔYU2-5438
622½ Alarid Waldo ◎ ΔYU3-8033
663 Rael Ezequiel ◎ ΔYU3-3839
667 Rael Antonio J ◎ ΔYU2-0753
668 Gormley Francis J ◎ ΔYU2-0938
669½ Sena Virginia Mrs ◎ ΔYU2-5189
670 Gormley's gro ΔYU2-0938

Gormley begins ss

702 Purerta de Oro Gallery ΔYU2-8101
702½ Moya Juan B ◎
Randolph Vera M Mrs ◎ ΔYU2-0153
708 Leggett Lucille W artist ΔYU3-9723
rear Stow Julius Furniture Refinishing ΔYU3-7782
Stow Julius
708½ Shorty Virginia ΔYU2-5219
Winters Shm
710 Alarid Maria Mrs ◎
Spiess Roofing Serv ΔYU3-6533
713 Lynch Ahas M ◎ ΔYU3-6460
713½ Daniels Mildred Mrs ΔYU2-9500
716 Sims Agnes Art Gallery
716½ Ritchie Jean
717 McHugh-Hooker Bradley
P Kidder & Assoc archts ΔYU3-8473

1960 E ALAMEDA ST

SOURCE: HUDSPETHS

522 Robinson Richd H ◎
ΔYU3-7195
523 Magers H Brady ◎
ΔYU3-8736
525 Ortiz Arth ◎
ΔYU3-9377
527-29 **Apartments**
1 Bankson Lewis M
2 Thompson Van
3 Matson Jos T
ΔYU2-9459
4 Marler Joe ΔYU2-2880
5 Vacant
6 Scott Robt W
7 Vigil Ray J ΔYU2-1659
8 Coldwell Marjorie Mrs
9 Bushnell David L
ΔYU2-2896
528 StevensonF Robt ◎
ΔYU3-7936
540 Proebstel Edith W Mrs ◎
ΔYU3-4249
550 Scott W T ◎ ΔYU2-5653
564 Wangerien Harry A ◎
ΔYU3-3638
Camino Escondido begins ss
614 Reynolds Steven E ◎
ΔYU2-5140
615 Buckley Geo H
ΔYU2-5193
616 Rodriguez Frances V Mrs
◎ ΔYU3-4246
Romero Antonio
ΔYU2-2209
Trujillo Louis
ΔYU2-5281
616½ Manzanares Julia Mrs
◎
Saiz Joe V ◎ ΔYU2-1670
617 Wesche Alice Mrs
618 Sisneros Julio ◎
ΔYU3-7545
Garcia Florian
630 Anderson Horace ◎
prntr ΔYU3-4437
Ilfeld Wm C ΔYU3-4023
633 Blythe Sch ΔYU2-5912
637 Barber Mary Mrs ◎
nurse ΔYU3-9150
Davis Almeta M ◎
ΔYU3-9150
650 **Apartments**
Beckman Edgar
ΔYU2-9485
A Gates Marie E
ΔYU3-4638
B Hughes Rowena Mrs
ΔYU3-7923
1 Kinney Marian C Mrs
ΔYU2-5838

ALAMEDA E—Contd
650—Contd
2 Charles Rose E Mrs
ΔYU3-8337
3 Crosby Edith A Mrs
ΔYU3-6935
4 Work Allene ΔYU3-3830
5 Stetson Hafford Mrs
ΔYU3-8778
6 Knopp Geo ΔYU3-7731
7 Bieber C Frances
ΔYU2-1038
8 McComb Sara W Mrs ◎
ΔYU2-0839
Camino Escondido intersects
801 Weltman Moe ΔYU2-8154
815 **Apartments**
1 Lusk Alice M
2 VanCourt Frances A
ΔYU3-8164
3 Dallas Gene Mrs
Street continued
827 Griego John ◎ ΔYU3-3553
829 Saiz Narcio ◎ ΔYU3-7536
835 Banks Harold ◎
ΔYU3-4834
837 C de Baca Frank
837½ Vialpando Ike
839 Baros Agustin ◎
840 **Apartments**
1 Miller Marillta R Mrs ◎
ΔYU3-9536
3 Stone Codell ΔYU2-2234
7 McGill Ernest
10 Wright Bennie C
ΔYU2-5637
11 Vacant
Street continued
868½ Trujillo Jake R ◎
870 Montoya Jos S ◎
ΔYU3-4436

10

E Palace av intersects

1115 Sena Louis ◎ ΔYU3-9326
1117 Maes Cabinet Shop
Maes Miguel ◎
ΔYU3-8848
1120 Gross Mark ◎
ΔYU3-7980
1122 Carter Merle W Mrs
ΔYU3-7888
1127 Holmes Oliver ◎
ΔYU3-6465
1131 Roybal Lorenzo ◎
ΔYU3-6243

1

ALAMEDA W—From 234 Don Gaspar av west to city limits (Right Odd)

1955 CANYON RD

SOURCE: HUDSPETHS

CANYON ROAD—Contd
403 Delgado Manuel ◎
Hammond Ralph E 3-4809
Marks Florence 3-9286
409 Delgado Hilario A ◎ 2-0095
414 Knight Geo C 3-5764
415 Dwyre Burton G 2-0587
418 Van Stolk C M
418a Boynton Beryl Mrs ◎
418b Thompson Valley 3-8394
419 Delgado Richd H
421a Grant David H 3-7275
421b Calles Aurelio
423 Calles Silviano ◎ 3-3616
424 Vandenberg Ethel ◎ 3-7845
Delgado intersects
503 Delgado Frank ◎ 3-5446
503a Igleheart Lewis T 3-4227
513 Reed Jos D ◎ 3-5336
519 Dietrich Margretta S Mrs ◎
2-0238
519a MacDonald Susan R Mrs
3-7970
519b Kretchmer Murial W 3-3243
524 Morang Dorothy Mrs
526 Sahula Dycke Ignatz artist
2-0258
530 Abraham James R 3-9327
Zimmerman Maude Mrs ◎
540 Catron Fletcher A ◎ 2-0738
544 Hubbard Philena W Mrs ◎
3-7868
545 El Zaguan Apartments
Apartments:
1 Cawthon Edith Mrs3-9637
2 McKay Marjorie Mrs
2b Hurley Hazel
3 Scholts John E 3-5750
4 Stewart John H 3-5101
5 Buchanan Jean
6 Jones Forrest J
7 Connell Mary K 3-3936
8 Guest Grace D 3-8553
9 Shishkin Julia K Mrs 3-7753
10 Altice Harry 3-5146
Street continued
546 Richards Mary Mrs 3-3470
550 Faulker Francis
552 Binkley Bee Mrs ◎ 2-0443
553 Baylis Wm 3-4758
554 Rutherford Diane 2-0309
555 Howland'sBarber Shop 3-9337
555a Howland Alf ◎ 3-9337
555b Reed Chas E
558 **Apartments**
1 Griego Steve 3-9414
2-3 N M Tuberculosis Assn 2-1071
4 Russel Robt D 3-9340
558a Wetzel Don 3-5910
558b Swanwick Wm W ◎ 3-5950
Camino Escondido ends ns
600a Haughton Augustine ◎ 3-9437
600b Pease Chester B jr 3-3587
600½ Blake Gertrude
601 Perea Anna Mrs ◎ 3-6444
Shaffer Ralph picture framing
West Hall Western Gallery
3-7674
West Hal 3-7674
602 Kitts Willard F 3-8094
602½ Fox Robt E 3-3955
610 Logan Dorothy F 2-0736
610a Palou Billy ◎ 2-1082
602a Whisonant Henry C 2-0804
613a Miller Jaffa 3-7480
613b Sena Robt G
613c Vigil Ignacio ◎ 2-0052
616a Morris Wm P
616b Tedford Donald E eng
616½ Gonazles Filiberto ◎ 3-3438
617 Elwell Bill
618 Padilla Frank ◎
619 Marsh Converse E 3-5823
621 Percy's Gro & Mkt 2-1238
Ortiz Percy ◎ 2-1238
Garcia Luz
Cooper John
622 Universal Cleaners 3-8612
622a Rodriguez Danl P ◎ 3-9153
622b Rodriguez Luis P ◎ 3-8612
622½a Rodriguez Braulia P Mrs ◎
3-7953
622½c Gonzales Jose A ◎
626 Vacant
628 Rael Mike R ◎ 3-3642
630 Rush Olive ◎ 3-7935
Paull Joe
634 Weber David E 2-0895
640 Parton Mildred Mrs ◎
640½ DuHaime Wm 3-8579
644 Olivas Louis ◎
646 Moya Guadalupe L
Garduno Gilbert W
650 Moya Ignacio D ◎ 3-4643
652 Studio Gallery art and books
3-9302
Bopst W Howard ◎ 3-9302
656 Johnnie's Nite Club 3-9904
656 Sil's Superite gro 3-8512
Martinez Silverio ◎ acct 3-8512
656½a Martinez Eloy A ◎
656½b Mounce Harold O 3-8804
656½d Morang Alf
662 Moya Magdalena Mrs ◎ 3-5438
662½ Alarid Waldo ◎ 3-8033
663 Rael Ezequiel ◎ 3-3839
667 Rael Antonio J ◎ 2-0753
668 Gormley Francis J ◎ 2-0938
669 Quintana Sandy ◎ 3-5456
669½ Sena Tony ◎
670 Gormley's gro 2-0938
Gormley begins ss
702a Lawhon Pearl R Mrs 3-3154
702b White Earl
702½ Moya Juan B ◎ 2-0153
708 Bibo Carl D 3-5237
708½ Stoumbis John 3-3523
708¾ Dieman Clare Mrs 3-5137
710 Alarid Maria Mrs ◎ 3-6533
713 Lynch Chas M ◎ 3-6460
713½ Buchanan H Clay 3-9147
716 Baca Gloria
717 Vacant
720 Weingarten Leslie
724 Tewa Enterprises signs 3-4498
Artists' Exchange Gallery
3-4498
Barrows Chas 3-4498
725 Lynch John ◎ 3-9537
725½ Lynch Edw ◎
727-29 Rio Grande Weavers Inc
3-5688
728 von Horvath Irene ◎ 3-8872
728½ Encinas Fedencio
731 Native Products Inc novelty
mfrs 3-4813
Camino Monte Sol begins ss
802 Thompson Aida dress designer
802½ Montoya Viola Mrs 3-3970
806 Sisneros Andres
808 Canyon Road Bar beer 3-9963
Vigil Lazaro ◎ 3-8035
812 Vigil Demecio ◎ 2-0946
820 Hullenkremer Oden 3-3990
820a Sight & Sound Shop sound
systems 3-4114
822 Vigil Beatriz ◎ 3-7843
822½ Trujillo Ramon ◎
826 Vigil Juan P ◎ 2-0537
830 Friendly Mkt gro 3-6912
Salazar Ross ◎ 3-6912
830½ Vigil Rafael ◎ 3-7637
832 Neels Harry M ◎ 3-7609
832½ Sandoval Rita T Mrs ◎
3-7969
834 Andrews Frank W ◎ 2-4983
Palace av ends
906 Vacant
907 Virgin Dorothy E ◎ 2-1136
907½ Rivera Antonia Mrs ◎ 3-8842
908 Day Sterling A 2-0992
908½ Quasthoff Donna
909 Smith Betty M 2-0479
912-12½ McCandless Wm ◎ 3-7854

1955 E ALAMEDA ST
SOURCE: HUDSPETHS

ALAMEDA E—Contd
301-05 **Casitas Del Rio Apts**
1 Kimbrell Anna
2 O'Brien Mary A Mrs 3-8788
3 Roberts Rose Mrs
4 Brown Richmond P 3-4981
5 Oldham Florence I 3-6208
6 Stephens Danl B 3-6693
Street continued
311 Harvey Jas C ⓪ 3-4987
328 Wheeler Edgar L ⓪ 3-4138
329 Lindgren Roy P 3-9590
331 Castillo Margarita ⓪
331½ Wheeler Geo ⓪ 2-0955
335 Jimenez Juan B ⓪ 3-6954
337 Jimenez Juan M ⓪
339 Gonzales Jose V ⓪ 3-9577
Garcia Arth A 3-8947
341 Slater Arth ⓪ 3-8306
343 Gonzales Ismael ⓪ 3-8896
345 Medrano Tom ⓪
Apartments
1 Medrano Tom jr
2 Archuleta Delfina 3-3268
3 Ortega Laurencita
4 Martinez Cipriano
Street continued
349 Wheeler John ⓪ 3-9495
351 Roybal Enrique
353 Dohrer John V ⓪ 3-4888
Delgado intersects
401 Goxem Gunhild ⓪ 3-8038
403 Garcia Lsabelle Mrs ⓪
403½ Cantu Alfredo M ⓪ 3-7644
411 Howland Lourdes Mrs ⓪ 2-0137
520 Pearson Harry W ⓪ 2-0915
523 Magers H Brady ⓪ 3-8736
528 Stevenson F Robt ⓪ 3-7936
540 Proebstel Edith Mrs ⓪ 3-4249
550 Hapgood Eleanor Mrs ⓪ 3-9366
564 Wangerien Harry A ⓪ 3-3638
Camino Escondido begins ss
614 Funk Ilo C ⓪ 3-5337
615 O'Neil Floyd B
616 Montoya Narciso
616½ Romero Antonio J ⓪
Saiz Jose V ⓪
617 Overton Veda 3-8264
618 Sisneros Julio ⓪ 3-7545
630 Anderson Horace ⓪ 3-4437
633 Blythe School 3-5912
637 Barber Mary Mrs ⓪ nurse 3-9150
Davis Almeta nurse
650 **Apartments**
Russell John D 4-5359
A Gates Maire E 3-4638
B Hill Gertrude F 3-6643
1 Kinney Marian C Mrs 3-5838
2 Charles Rose E Mrs 3-8337
3 Crosby Edith A Mrs 3-6935
4 Work Allene 3-3834
5 Stetson Hafford Mrs 3-8778
6 Alfau Rafael Mrs 2-1138
7 Bieber C Frances 2-1038
8 McComb Sara WMrs ⓪ 2-0839
Camino Escondido intersects
815 **Apartments**
1 Janssen Geo
2 Groh Lee D 3-3695
3 Kubotso Teruko
Street continued
827 Kriego John ⓪ 3-3553
829 Griego Pablo S ⓪ 3-7536
835 Banks Harold ⓪ 3-4834
837 Sheppard Eug 3-8313
837½ Vacant
839 Baros Agustin ⓪
840 Miller May R Mrs ⓪ 3-9536
Wright Venesee 3-5637
E Palace av intersects
870 Montoya Joe S ⓪ 3-4436
1001 Morrow Mable ⓪ 3-8874

1
ALAMEDA W—From 234 Don Gaspar av west to city limits (Right Odd)
Agua Fria intersects
211 Vacant
237 Emble mSheet Mtl Wks 3-8812
N Jefferson intersects
425 Farmway Feed & Equip Co 2-0911
468 Independent Gro 2-1011
7
Park av intersects
530 Rivera Alfred oR ⓪ 2-0016
532 Vigil Ramon ⓪ 2-1124
532½ Roybal Juan ⓪
534 Montoya Castelita Mrs ⓪ 3-7919
534½ Gonazles Balvinita Mrs ⓪
536 Jaramillo Anastacia Mrs ⓪
536½ Silva Adela O Mrs ⓪ 3-3113
538 Ponce Albert L ⓪ 3-3515
Duran begins ns
600 Vieira Francisco
604 Ortiz Robt C ⓪ 3-8064
605 Orozco John N ⓪
Roybal Bennie D ⓪
606 Roybal Abedon ⓪
606½ Under constn
608 Rael Albert ⓪
Garcia Benny J ⓪
Candelario intersects
700 Rocky's Mkt gro
Apartments
1 Montoya Joe
2 Pena Pete 3-3549
3 Ortiz Pete
4 Vacant
5 Vacant
6 Padilla Tomacita Mrs
7 Barela Antonio T 3-3794
8 Vacant
9 Vacant
10 Valdez Reyes Mrs
11 Rico Ernest
12 Chavez Apolinio
13 Chavez Remijio 3-8912
Street continued
710 Silva Luis ⓪
720 Rodriguez Josefita Mrs ⓪
730 Barela Anastacio ⓪ 3-7614
Walton Victoria Mrs 3-7614
Mares Juan
Barela Ramon ⓪
734 Barela Willie ⓪ 3-5414
758 Gonzales Joe A ⓪
760 Sena Alfredo R ⓪
762 Ortiz Julio ⓪
764 Conway Clara Mrs
Muniz Pablita Mrs
766 Benavides Edw ⓪ 3-4958
768 Garcia Eladio S ⓪ 3-4444
770 Garcia Hilario S ⓪
784 Watson Noah ⓪ 2-0415
790 Fresquez Nestor 3-8110
792 Benavides Atanacio
Sandoval Adolfo ⓪
W San Francisco ends ns
nw cor Gonzales Elem Sch 3-6711
800 Quintana Joe H
804 Espinoza Gilbert
1221 Serano Press 3-8332
1405 Thompson Frank N ⓪ 3-7516
Following are Rural Delivery and Showing Box Numbers
126 Darras Juila Mrs ⓪
130 Popez Eduardo ⓪
Dooley Geo S ⓪ 2-1016
Rank Tessie
9
ALARID—From 800 W Manhattan south (Right Even)
510 Romero Ramon ⓪ 3-9643
510½ Vacant
511 Dagh Gust O ⓪ 3-8152
513 Roybal Joe L ⓪ 3-8682
513½ Weizer Dale

1949 CANYON RD-A
SOURCE: HUDSPETHS

8
CAMINO MONTE VISTA — Begins 806 College ext east (Right Even)
425Δ Gardner Ralph
427 Hazard Lonita H
439Δ Alleman Carl W
441Δ Federici Wm R
443Δ Salmons Fred
445Δ Hall Wm
447Δ Byrne Verne
450Δ Stegeman Carl ⓪
Barr H D
6
CAMINO PENA—Begins 792 Tranquilo ext east (Right Even)
105Δ Gallette ——
107Δ Gardner Ron V ⓪
107½ Vacant
108 Haddock Arth E ⓪
110Δ Wolf Benj ⓪
115Δ LaPlante Arth J ⓪
116Δ Hines Mildred W Mrs ⓪
123Δ Lawrence Pope A
123½ Adams Ruth
8
CAMINO PINONES — Begins about 1400 Pecos Trail ext east
6
CAMINO RANCHEROS — Begins end of El Caminito ext south
502Δ Eaton Thos J ⓪
541Δ Primus Edw ⓪
rear Vacant
600Δ Rernooler Dyke ⓪
630 Whitcomb Saml J
638 Goodwin Larry
838Δ Buckley Wm R ⓪
1000 Gerber Pierre
1027Δ Patraw Preston E ⓪
1045Δ Madden Frank T ⓪
6
CAMINO SANTANDER—Begins 586 Camino Monte Sol ext east
514 Romero Antonio ⓪
516Δ Tohill Noah M
601Δ Anaya Alfredo ⓪
951Δ Trujillo Jesus M ⓪
951½ Sandoval Tony ⓪
952 Rodriguez Eloy ⓪
953 Gabaldon Felipe A ⓪
960 Vacant
962Δ Catanach Jas ⓪
964Δ Shiva Ramon ⓪
rear Δ Andrews Jay ⓪
965Δ Montoya Manuel C ⓪
6
CAMINO SIN NOMBRE — Begins 1021 San Acacio ext north
(Houses not numbered)
esΔ Foster Georgene ⓪
es Gurule Lauriano ⓪
es Gurule Teresita
es Lucero Jose A
es Martinez Frank ⓪
es Montoya Thos ⓪
es Ortiz Agapito ⓪
ws Archuleta Benita Mrs
ws Barbero Frank Mrs ⓪
ws Carrillo Filiberto ⓪
ws Herrera Antonio
ws Lujan Sofia ⓪
ws Rios Geronimo ⓪
ws Samuels Geo ⓪
3
CANDELARIO—Begins 700 W Alameda ext north (Right Odd)
106Δ Perez Bernabe ⓪
109Δ Coleman Adrian M ⓪
110 Vacant
113 Rael Antonia
115Δ Padilla Elmer ⓪
117 Romero Ramon
Lucero John D
117½ Borrego Amalia Mrs
119 Valdez Avelina
123Δ Ortiz Cesario ⓪
129 Montoya Abel ⓪
130 Muniz Margt Mrs ⓪
134Δ Smith Ophelia G Mrs ⓪
135Δ Gonzalez Francisco jr ⓪
139 Trujillo Belle Mrs ⓪
145 Cole Dwight
146 Mares Manuelita ⓪
149Δ Ezequiel Teno ⓪
150 Vacant
Rosario intersects
6
CANON ROAD—Begins 323 E Castillo ext east (Right Even)
200Δ Rawlins Fredk C
201Δ Jensen Carl R ⓪
202Δ Carter Elmer F
203 Snodgrass Sybil Mrs
205 Abrams Sadie
221Δ Vigil Julia Mrs ⓪
223Δ Delgado Michl R ⓪
233 Gallegos R C
234Δ Valdez Fred ⓪
234½Δ Valdez Fred jr ⓪
E DeVargas ends ws Garcia begins ss
400Δ Berg Herbert M ⓪
403 Delgado Manuel ⓪
409Δ Delgado Hilario A ⓪
414Δ vonHinzmann Alvin artist
415Δ Dwyre Burton G
418Δ Boynton Ray ⓪ artsit
421Δ Doak Wyeth
423Δ Mell John D
424Δ Drypolcher Harry J
Delgado intersects
503Δ New Mex Handicrafts
LaTiendacita novelties
Pearce Rheva
rear Δ Herrera Robt ⓪
513Δ Reed Jos D ⓪
519Δ Dietrich Margt S Mrs ⓪
524Δ Hare Martha H ⓪
526 Herrera Medardo
530 Zimmerman Loyd Mrs ⓪
540Δ Catron Fletcher A ⓪
544Δ Whitmer Mary T Mrs ⓪
545 **El Zaguan Apts**
Apartments:
1 Cawthon Edith Mrs
2 Zavadsky Leonard
2b Dickson Robt Mrs
3Δ Connell Mary K
4 Vacant

CANON RD—Contd
El Zaguan Apts—Contd
5 Tracy Marion P Mrs
6 Collins Clayton
7 Nunn Maidie
8 Guest Grace D
9 Shishkin Julia K Mrs
10 Lippincott Harl Mrs
Street continued
553 Friedl John L ⓪
555 Howland Alf ⓪
Valdez Fred
558 Santa Fe Guidance Center
Tamotzu Chugo artist
Counts Myrtis
Young Edith Mrs
Camino Escondido ends ns
600½ Hunter Robt B
601 Hammond Elsie T
602 Stauffer Dorothy ⓪ artist
608 Vacant
610 Vacant
613 Meeks Leonard
616 Vacant
616½ Gonzalez Filiberto ⓪
617 Martin Esther Mrs
Sissneros Miguel ⓪
618 Padilla Frank ⓪
619 Vacant
621 Percy's & Gro & Mkt
Ortiz Percy ⓪
Rivera Max jr
Ortiz Ricardo
622 Universal Clnrs
Rodriguez Luis P
Rodriguez Danl ⓪
622½ Rodriguez Antonia Mrs ⓪
Cefaratti Nick
Romero Adolph ⓪
626 Pino Gregorita Mrs
630 Rush Olive ⓪
634 Sherman W C Mrs
640 Parton Mildred Mrs ⓪
640½ Finley Frank P
644 Eden Thos E
rear Davis Chas K
646 Moya Ignacio
650 Moya Ignacio ⓪
651 McComb S W Mrs ⓪
652 Parkhurst T Harmon ⓪
656 Roybal's Store & Bar
Martinez Eloy ⓪
rear Kinnard Guy E
Flores Bennie
656½ Martinez Silverio ⓪
662 Moya Magdalena Mrs ⓪
663 Rael's Tony Spanish Food
Rael Ezequiel ⓪
667 Rael Tony ⓪
668 Gormley Francis J ⓪
669 Vigil Florencio ⓪
670 Gormley's Store genl mdse
Gormley begins ss
702 Funnell Eustus
702½ Moya Juan B ⓪
708 Moya Eloy
708½ Bibo Carl
710 Digneo Ralph J ⓪
Alarid Maria ⓪
713 Jones Myers
713½ Kinney W Bruce
716 Baca Teofila ⓪
rear Martinez Aniceto A ⓪
717 Strong Ezra restr
720 Maize Jas H
722 Montoya Ernestina
724 Hegelstein Edith ⓪
725 Lynch John ⓪
728 Koury Eleanor ⓪
728½ Stark Evelyn ⓪
729 Rio Grande Weavers
Camino Monte Sol begins ss
802 Montoya David
808 Canyon Road Bar
Vigil Lazaro
812 Vigil Demecia ⓪
820 Hullenkremer Odon artist
820½ Montoya David
822 Vigil Beatrice ⓪
rear Rodriguez Sabino
Trujilla Clarita ⓪
Gonzalez Julian
826 Virgil John J ⓪
830 Friendly Mkt
Salazar Ross ⓪
832 Irick Portia
832½ Sandoval Felix P ⓪
834 Sena Margarita ⓪
836 Sena Robt G ⓪
Palace av intersects
907 Sweringen B S Mrs ⓪
907½ Rivera Antonia Mrs ⓪
Rushing Wylie
909 Baca Alf A
912 Haines Arth ⓪ theatrical tchr
912½ Saunders Sylvia
914 Adams John E ⓪
Graftsroom Catarina
916 Vacant
917 Vigil Jacobo ⓪
922 Hall Arth W ⓪
924 Boyd David F ⓪
Cassidy Ina S author
Sizer Jas H
924½ Morgan Betty A ⓪
Palace av ends
942 Montano Tina
942½ Saiz Miguel ⓪
943 Apodaca Guadalupe ⓪
Rodriguez Bernardo
943½ Vacant
945 Kennedy Olin G
948 Garcia Rufina M Mrs ⓪
950 Carrillo Dalio ⓪
998 Rydal Press
Acequia Madre ends ss
1000 Romero Juan ⓪
1002 Armenta Rubel ⓪
rear Romero Adolfo ⓪
Vigil Pedro ⓪
Duran Sofia ⓪
Lucero Albina L Mrs
Romero Felix ⓪
1004 Contreras Roberto ⓪
1005 Hill & Canyon School of Arts
Breneiser Stanley G ⓪
1008 Wendland Dorothy Mrs
Gibbs M D ⓪ phys

KELVINATOR REFRIGERATORS AND ELECTRIC RANGES

Corner Shelby and Alameda Next to Telephone Bldg. Phone 911

AGUA FRIA ROAD—Contd
33A Tafoya Juan D ⓪
36 Garcia Florentino ⓪
36½ Velarde Alejandro ⓪
37 Romero Josephine
38 Pino Nicolas ⓪
40 Baca Ramon J ⓪
41 Tapia Amarante ⓪
42 Rodrigvez Manuel V ⓪
42A Montano Gabriel ⓪
42B Gonzalez Jose B
43 Castellano Monico ⓪
43A Sandoval Fermin ⓪
44 Encinias Felipe ⓪
46 Barela Rafael

1

ALAMEDA E — Begins 300 Don Gaspar av ext east (Right Even)
113 Original Mex Cafe
Lawrence Wm J ⓪
121 Mountain States T & T Co
129 Memorial Chapel
College intersects
nw cor St Francis Cath Sch
St Francis Cath Center
Shelby ends ns
137 Potter G R
Craik Elsa Mrs
Scheid Gerda Mrs
137½ Jones Maude Mrs
138 State Park Comnr
State Bank Examnr
141 Nohl A K
143 Vohs Wm
145 Sippel Mathias A
College intersects
Cathedral pl ends ns
6
S Castillo intersects
301-05 **Casitas Del Rio**
Apartments:
1 Moranetz Walter P
2 Quigley Alice R
3 Anderson Betty
4 Drew Cullen O
5 Morrison Earl L
6 Haynes Hazel Mrs
Street continued
311 Harvey John C ⓪
328 Wheeler Edgar L ⓪
Chastain Thos M
329 Jorgenson Lewis V
331 Archuleta Mary S Mrs
335 Jimenez Juan B ⓪
337 Jimenez Juan M ⓪
339 Gonzalez Jose V ⓪
341 Burlington Mary Mrs nurse
Dunn Marcella
343 Gonzales Ismael ⓪
345 Medrano Tom ⓪
Apartments:
1 Springer Lloyd
2 Gonzales Frank
3 Moyo Luis jr
4 Garcia Silas
Street continued
349 Wheeler John jr ⓪
rear Benavides Gregorio
Martinez Carlos ⓪
353 Dohrer John V ⓪
Delgado intersects
401 Goxem Gunhild ⓪
403 McGrath Arth
403½ Cantu Alfredo M
411 Trujillo Max ⓪
Frost Chas J
523 Magers H Brady ⓪
528 Stevenson F Robt ⓪
528½ Ringer Anna H Mrs
540 Proebstel Edith Mrs ⓪
rear Eppler Barbara J
550 Hapgood H Prentice ⓪
564 Wagerien Harry A ⓪
Camino Escondido begins ss
614 Bainbridge Alex G
Broadhead Edith Mrs
615 Summers Consuelo Mrs ⓪
Hostess Club adv
616 Rodriguez Benidictio ⓪
Garcia Maria Mrs
616½ Romero Antonio
Saiz Jose V ⓪
617 McMahon Geo H
618 Pacheco Louise ⓪
Sisneros Julio ⓪
630 Anderson Horace ⓪
633 Blythe School
637 Romero Juan J jr ⓪
650 Cole Jas R
Apartments:
A Gates Marie E
B Andrews Marion
1 Kinney Marian Mrs
2 Charles H H
3 Crosby Edith Mrs
4 Tichy Marjorie Mrs
5 Bond Marion
6 Alfau Rafael
7 Bieber C Frances
8 McComb Sara W Mrs ⓪
Street continued
Camino Escondido intersects
815 **Apartments**
1 Gulesserian Mary
2 Grandstaff Ruth ⓪
3 Allison Beatrice
Street continued
827 Griego John ⓪
829 Griego Carlo S ⓪
831 Lynch Dorothy
835 Vacant
837 Galvan Catalino ⓪
837½ Banks Robt T
839 Baros Augustin ⓪
840 Miller Chas A ⓪
E Palace av intersects
870 Montoya Joe
870½ Vacant

1

ALAMEDA W — Begins 234 Don Gaspar av ext west (Right Odd)
209-13 White Swan Lndry
Agua Fria intersects
3
425 Santa Fe Hay & G Co
468 Independent Gro
530 Revera Alf ⓪
532 Vigil Ramon
534 Montoya Ramon ⓪
Roybal Juan
534½ Gonzalez Balvinia Mrs ⓪

CAMINO DELORA—Begins about 1117 San Acacio ext south (Right Even)
1181 Rodriguez Secundino
— Brito Vicente ◎

CAMINO DEL PONIENTE — Begins Gormley 1st s of Acequia Madre ext east (Right Even)
Camino Pena b ges Abeyta intersects
792△Ewing W R
793△Carter R H jr
800△Andrew Ray ◎
827△Goodwin Alice Mrs ◎
828△Hughes L A jr
Mueller C H Mrs
990 Tichy M J Mrs

CAMINO DON MIGUEL—Begins 948 Acequia Madre ext southeast

CAMINO ESCONDIDO — Begins 600 E Alameda ext south (Right Even)
115 Fetter Ferdinand
127△Kennedy J A
130△Claffey F J ◎
131 Pesenti Mony ◎
138△Beer Albert ◎
141△Rodriguez R A ◎

CAMINO LEJO—Begins near end of Pecos rd ext southwest

CAMINO MANZANO — Begins about 740 Acequia Madre ext south

CAMINO MILITAR—Begins 1243 Canon rd ext southeast
end△Andings S W ◎

CAMINO PENA—Begins 792 Camino del Poniente ext east (Right Even)
107 Stout Patk
110 Stanfer J F ◎
116 Remuller Dyke ◎

CAMINO PERROS GRANDES — Begins about 1300 Pecos Trail ext west

CAMINO PINONES—Begins about 1400 Pecos Trail ext east

CAMINO RANCHEROS — Begins end of El Camino ext south

CANADA ANCHA — Begins 1200 Cerro Gordo rd ext north
es 1 n Lucero Nasario ◎
es 2 n Roybal Climaco ◎
es 3 n Lopez Concepcion Mrs ◎
es 4 n Sandoval Emilia Mrs ◎
es 5 n Montano Clemente ◎
es 6 n Jimenez Pifanio ◎
es 7 n Jimenez Hipolito ◎
ws 1 n Garcia Remigro ◎
ws 2 n Garcia Frank ◎
ws 3 n Fisher Edw
ws 4 n Garcia Geo ◎

CANDELARIO—Begins 700 W Alameda ext north (Right Odd)
109 Cruz David
113 Padilla Elmer ◎
115 Arrey Henry ◎
117 Vacant
117½ Friday Robt
119 Sanchez Julian
121 Aranda Jerry
121½ Vacant
123 Ortiz Cesario ◎
129 Montoya Abel ◎
135 Gonzalez Francisco jr ◎
139 Trujillo Belle ◎
145 Montano Cerillo
149 Trujillo Pablita
Rosario intersects

CANON ROAD—Begins 323 E Castillo ext east (Right Even)
200 Carter E F
201△Jensen J K
202 Hopkins W D jr
221 Vigil Julia Mrs ◎
223 Delgado Michl ◎
233△Montoya Rose
234 Valdez Fred ◎
234½ Valdez Fred jr
E DeVargas ends ws Garcia bg ss
400△Berg Lillian Mrs
403 Delgado Manuel ◎
409△Delgado H A ◎
414△Turner R J
415△Dwyre B G
418 Vacant
421 Jennings Larry
423△Hensler J O
424 Rivera Ramoncita Mrs ◎
Delgado intersects
501 Vacant
503 Muniz Rafael shoe repr
505 Azeivedo Danl
513△Reed J D ◎
519△Dietrich M S Mrs ◎
524 Marvin H C Mrs
526 Herrera Medardo
530 Zimmerman Maud Mrs
540△Catron F A ◎
544△Catron T B II ◎
545 El Zaguan Apts
*1△Prince Stephanie
*2△Farrelly Cath real est
*2b△Sippel M A
*3 Connell May K
*4 Harris D L Mrs
*5 Harris R M
*6 Oetjen M
*7 Smith MH Mrs
*8△Reed E K
*9 Hazeltine Helen
*10△Mercer A F

CANON ROAD—Contd
553△Floyd C B ◎
555△Howland Alf ◎
558 Chavez Frank
Nichols Grace
Novakovich Grace
Bernard Ray
Camino Escondido ends ns
601△Vigil Cruz ◎
602-08 Scott Duncan
610 Rodriguez Juanita ◎
613 Salazar Pete
613½ West F G
616 Heindel Richd ◎
616½ Gonzalez Filiberto ◎
rear Vacant
617 Orchard C L
618 Padilla Frank ◎
619 Hall H A
rear Cisneros Miguel
621 Percy's Mkt gro
Ortiz Percy ◎
622 Rodriguez Danl ◎
1 rear△Rodriguez Antonio ◎
2 rear Rupard R G
3 rear Vacant
626 Garcia Valentin
628 Roberson C W
630△Rush Olive ◎
634△Kahler Wilhelmine Mrs
640△Parton Mildred Mrs ◎
640½ Vacant
644 Olivas Luis ◎
rear Hayes Philip
646 Avakian Nori
650 Moya Ignacio ◎
651△McComb S W Mrs ◎
652△Parkhurst T H ◎
656△Roybal J E ◎
Roybal J E Bar & Disp
Roybal J E Store & Mkt
656½ Roybal Paul ◎
rear Moya Juan
662△Moya Madeline Mrs
663 Vacant
667 Rael A J ◎ tamale mfr
668△Gormley F F ◎
669 Gomez Diego
670△Gormley's gros
Gormley begins ss
702 Vacant
702½ Moya J B ◎
708 Moya Pablo ◎
710△Alarid Zeferino ◎
713△Sims A C
713½△Lynch Chas ◎
716 Baca Presciliana
rear Baca Teofila Mrs
720 Kieve Marjorie
724 Kuencer K C
725△Lynch John ◎
728 Chavez Dionicio
rear Gonzalez Fernando
Camino del Monte Sol bg ss
802 Dean M V Mrs ◎
808 Vigil Lazaro barber
812 Vigil Damasio ◎
820 Hullenkremer Odon artist
rear Martinez J S
822△Vigil Beatriz ◎
826△Vigil J J ◎
830 Friendly Mkt
Salazar Ross ◎
rear Vigil Rafael ◎
832 Trujillo J M ◎
834 Sena Eugenio
Pallace av intersects
907 River Emeterio ◎
909△Wallace J L wood carver
912 Haines Arth ◎
914 Crow Louise Mrs
917 Vigil Jacobo ◎
922 Vacant
924△Webb Young Trader
△Boyd D F
Cassidy I S Mrs ◎
△Young Webb
924½△Morgan Betty ◎
942 Vacant
rear Rodriguez Brigida Mrs ◎
942½ Bustamante Juan ◎
943 Apodaca Guadalupe
943½ Chavez Guadalupe
950 Garcia Marcelino ◎
Carrillo Dalio ◎
998△Rydal Press
△Santa Fe News
Acequia Madre ends ss
1000 Romero Juan
1002 Armenta Rubel ◎
1004 Contreras Roberto
1 rear Romero Felix ◎
2 rear Lucero A L Mrs ◎
3 rear Vigil Pedro ◎
4 rear Romero Adolfo ◎
1005 Welch R O Mrs nurse
△Welch C E
1008 Madrid Max
1008½ Garcia Alfonso ◎
1009 Stevens Helen Mrs ◎
1010 Vacant
1014 Vacant
1014½ Rodriguez Pedro ◎
1015 Carrillo Cruz ◎
1016 Armegaud Maria E Mrs
1017 Slade W M
1018 Mora Jacobo ◎
1018½ Espinosa Manuelita ◎
Ortiz Romualdo
1019 Duran Alfonso
1025 Vacant
1027 Romero Eustaquio gro
1036 Romero Geo ◎
Camino del Cerrito intersects
1103 Vacant
1104 Vacant
1106 Chavez Martin ◎
1107 Vacant
1115 Clapp Larry contr
1117△Welton R H ◎
1120△Butler Gladys Mrs ◎
1130-32 Rodriguez J B ◎
1136 Duran A A ◎ gro
1144 Rodriguez Higineo ◎

1944 E ALAMEDA ST

SOURCE: HUDSPETHS

AGUA FRIA—Contd
927 Romero Luis ◎
928△H & H Grocery
Herrington R L
Urioste intersects Franklin pl bg ss
937 Chavez Pedro ◎
941 Sanchez Jose
943△Lyons Frank
Lyons Alma midwife
1 rear Hurtado Juanita Mrs
2 rear Lopez Eliseo ◎
3 rear Vallegos Florinda Mrs
4 rear Anaya T C Mrs ◎
5 rear Anaya Vicenta ◎
950 Pentecostal Mission
△Benavides Rubel ◎
952 Lawrence Ellen Mrs
954 Gutierrez C N ◎
985△Smith R D ◎ contr
Kathryn bg es
1201△Settys Body Shop auto repr
rear△Brown H E
1205 Nelson Wesley
1207△Hansen Lbr Co
△Hansen J O ◎
1243 Alire Miguel ◎
1247△Lamoreaux H O ◎
1251 Padilla Albino ◎
1252 Romero Celestino ◎
1253 Rodriguez Luis ◎
1255 Garcia A R ◎
1257 Alire Nicolas ◎
Cortez bg ss
Salazar bg ss

AGUA FRIA ROAD — Continuation of Agua Fria bey city
△Larragoite School

ALAMEDA EAST—Begins 300 Don Gaspar av ext east (Right Even)
113△Original Mex Cafe
Lawrence W J ◎
121△Mountain States T & T Co
129△Memorial Chapel
Shelby ends ns
137△White L E
138△State Planning Bd
State Park Comnr
Apartments
*1 Cassell Ruth Mrs
*2△Arias Raymond
*4 Ward Florence
*8 Scheid Gerda
141△Shankweiler L S Mrs
143△Vohs Wm
145 Gairey J W
College intersects Cathedral pl ends ss S Castillo intersects
301-5 Casitas Del Rio
*1 Sadler W C
*2△Lutzow M B
*3 Emantian Richd
*4△Drew Cullen
311△Harvey J C ◎
328△Wheeler E L ◎ contr
331 Castillo Margarita ◎
337 Jimenez J M ◎
339 Roybal Eugenio
rear Gonzalez J B ◎
341 Burlington Mary Mrs
343 Landwehr R J
345 Marales Anita Mrs
rear Gonzales Ismael ◎
Medrano Andres Mrs ◎
Chavez M R
349 Johnson Ramona
rear Vacant
353 Ratliff R W
Delgado intersects
401△Goxem G G
403△Lucero Wm ◎
rear Lucero P F
407 Vacant
411 Howland Lourdes Mrs ◎
523△Magers H B ◎
528△Stevenson F R ◎
540△Proebstel Chas ◎
550△Hapgood T E ◎
564△Wangerien H A ◎
Camino Escondido bg ss
614△Zahn Geo
615 Tandy Helen
616 Saiz Jose ◎
616½ Romero Antonio
617△Summers Consuelo Mrs ◎
618△Werther Wm ◎
rear Herrera Jose ◎
△Sisneros Julio ◎
637 Romero J J jr ◎
Camino Escondido intersects
829 Griego Pablo
831 Sesneros Andres
835 Vacant
837 Galvan Catarino ◎
Rodriguez Petrita
837½ Lynch Curtis
840△Miller C A ◎
rear Lobato Marcial
E Palace av intersects
868 Vacant
870 Taylor W E
rear Montoya Jose

ALAMEDA WEST — Begins 234 Don Gaspar av ext west (Right Odd)
209-13△White Swan Lndry
Agua Fria intersects
425△Santa Fe Hay & G Co
530 Lopez Theo
532 Vacant
rear Vacant
534△Flores Alexandro
536 Jaramillo J E
rear Vacant
538△Ponce Albert
600 Quintana Antonio
604 Romero Frances Mrs
606 Vacant
698 Jaramillo Porfirio
Candelario intersects
710 Barela Roque

1940 CANYON RD

SOURCE: HUDSPETHS

ws Garcia Remigio
ws Garcia Frank ◎
ws Ortiz Ignacio ◎

CANDELARIO
Begins 700 W Alameda ext north (Right Odd)
109 Ryno Mildred Mrs ◎
113 Padilla Elmer ◎
115 Padilla Walter
117 Chavez Francisca Mrs
117½Brandon J L
121 Ortiz Medardo
rear Perini Orlando
121½Roybal Benj
123 Ortiz Cesario ◎
129 Montoya Abel ◎
135 Gonzalez Francisco Jr ◎
139 Baca D B Mrs ◎
145 Phillips Rena Mrs
149 Carroll J E
Rosario intersects

CANON ROAD
Begins 323 S Castillo ext east (Right Even)
200△Carter G S
201△Jensen J K ◎
202△Streikfaden Benj
221 Vigil Julia Mrs ◎
223 Delgado Michael ◎
233 Delgado E S
234 Valdez Fred ◎
234½△Gomez J M
237 White A L Mrs
E De Vargas ends ws Garcia bg ss
400△Gay Kathryn ◎
403 Delgado Manuel ◎
409△Delgado H A ◎
414△Marsh J B
415△Dwyre B G
418 Gonzalez J M ◎
421 Dohrer J V
423△Smith R E
424 Rivera Romancita ◎
Delgado intersects
503 Delgado Efren Mrs ◎
Native Market Guild
505△Sears H D ◎
513 Vacant
513½Eastman Ida Mrs
519△Dietrich M S Mrs ◎
524△Eaton M D Mrs
526 Herrera Medardo
530△Young Webb ◎
540△Catron F A ◎
544△Catron T B II ◎
545 **El Zaguan Apts**
*1 Turner W V
*2△Reed E K
*2b Anderson Louise
*3△Gilbert Thelma
*4△Olmstead Julian
*5△Stamm Helen

CANON ROAD—(Cont'd)
*6 Webb Harold
*7△Cobb E M
*9△Gilman M R Mrs
*10 Pollak Mabel Mrs
553△Mooter Paul
555△Howland Alfred ◎
558△McDavid P E
Cunningham D W
Hunt Thos
Chavez Frank
Camino Escondido ends ns
601△Vigil Cruz ◎
602-8△Love L D
610 Rodriguez Juanita ◎
616 Will Blanca
616½Gonzalez Filiberto
618 Padilla Frank ◎
619 Garcia Santos
621△Percy's Gro & Mkt
rear Duran E S
622 Rodriguez L P Mrs ◎
1rear Rodriguez Antonio ◎
2rear Rodriguez Alfredo
3rear Holguin Guadalupe
626△Kreuch J W
628△Butler L I Mrs
630△Rush Olive ◎
634△Floersheim S A
640 Bryan R J
640½△Semine Christine Mrs
644 Olivas Luis ◎
646△Case Reece
650 Moya Ignacio ◎
651△McComb S W Mrs ◎
652△Parkhurst T H ◎
656△Roybal J E ◎
Roybal J E Bar & Disp
Roybal J E Store & Mkt
656½Roybal Paul ◎
rear Allen D J
662△Moya Madeline
663 Rael Ezequiel
667 Rael Antonio ◎
668△Gormley F F ◎
669 Gomez Diego
670△Gormley's gen mdse
Gormley begins ss
702 Vacant
702½Moya J B ◎
708 Moya Pablo ◎
710 Alarid Zeferino ◎
713△Cash Hazel Mrs
713½Lynch Chas ◎
716 Gonzalez Fernando
rear Baca Teofila Mrs
720 Ortiz Jose
724△Sims Agnes
725△Martinez Epitacia Mrs
Lynch Ino ◎
728 Chavez Dionicio
rear Gonzalez Jose ◎
Camino del Monte Sol bg ss
802 Langley L L cabtmkr
806-8 Vigil Lazario billiards

1940 E ALAMEDA ST

SOURCE: HUDSPETHS

ss Byres P E ◎
ss Cruz Aniceto ◎

ALAMEDA EAST
Begins 300 Don Gaspar av ext east (Right Even)
113 Original Mex Cafe
121 Mountain States T & T Co
129 Sayre-Andrew Funeral Home
Shelby ends ns
137 White L E
138 Williams Melba Mrs
Mahboub F W
138 State Emp Serv
State Park Comnr
141 Borders Olive Mrs
143 Vohs Wm
145 Meffert Lydia Mrs
College intersects
Cathedral pl ends ss
S Castillo intersects
301-5 **Casitas Del Rio**
*1 Wallis W R
*2 Ashmore R L
*3 Bayne C W
*4 Shamhart C A
*5 McVey V L
*6 Allen K E
311 Harvey J C ◎
328 Wheeler E L ◎ contr
331 Castillo Margarita ◎
337 Jimenez J M ◎
339 Roybal Eugenio
rear Gonzalez J B ◎
341 Payne H R
343 Trujillo J F
343½ Medrano Tomas ◎
345 Medrano Andres ◎
349 Labadie Jose ◎
353 Ratliff R W
Delgado intersects
401 Bakke M A
407 Callahan Tonita Mrs
528 Stevenson F R ◎
528½ Murphy C J
540 Proebstel Chas ◎
550 Rose A D Mrs ◎
564 Wangerien H A ◎
Camino Escondido bg ss
614 Finney R G
615 Bliss J H
616 Saiz Jose ◎
1 rear Saiz Frank ◎
2 rear Rodriguez Benedicto ◎
3 rear Ortega Manuel ◎
4 rear Armijo Adolph
617 Watson W A
618 Pacheco Ramon ◎
Sandoval Santiago ◎
637 Rodriguez D M
Camino Escondido intersects
835 Terrell G R ◎
837 Sanders Troy

ALAMEDA E (Cont'd)
840 Miller M R Mrs ◎
Martinez Eliseo
Sherman L W
E Palace av intersects
863 Pope David
870 Puckett R E

ALAMEDA WEST
Begins 234 Don Gaspar av ext west (Right Odd)
209-13 White Swan Lndry
Agua Fria intersects
451-53 Santa Fe Hay & G Co
500 Gilcrease M A Jr
508 Sanchez Lee
530 Arrey Frank ◎
600 Vigil Ray
620 Jaramillo J E ◎
Candelario intersects
710 Romero Frances Mrs
730 Montoya F B
Varela Anastacio ◎
736 Moreno Saml
738 Varela Wm
766 Benavides Pablo ◎
770 Mora Iosefita Mrs ◎
784 Watson Noah
790 Arellano Federico ◎

ALARID
Bg 800 W Manhattan ext south (Right Even)
513 Griffin B N
515 Sandoval J B ◎
517 Vacant
520 Gonzalez Cesaria Mrs ◎
527 Baca C L ◎
534 Alarid Socorro Mrs ◎
538 Miller O A
546 McNatt W C
548 Help Yourself Lndry
Hickox intersects
603 Henson French
607 Kilmer M L
609 Ackerman L A
611 Grubbs L F
rear Stephenson W C
611½ Weirich S E
617 Yates T E ◎
618 Narvaez Adolfo ◎
621 Irby C H ◎
626 Mercer D H
628 Martinez Emilia Mrs
630 Longacre Rube
Ninita intersects
701 Gonzalez Faustin ◎
703 Gonzalez Onecimo ◎

ALLENDALE
Begins ½ blk north of 224 Sena ext south (Right Even)
723 Conway T W
725 Root L F
W Buena Vista av intersects

1936-37 CANYON RD

SOURCE: HUDSPETHS

CANDELARIO
Begins 779 W San Francisco extends north to Rosario
109 Bishop O R ◎
113 Padilla Elmer ◎
117 Grajeda Antonio
121 Ortiz Julian
121½ Roybal Benjamin
123 Ortiz Cesario ◎
129 Montoya Abel ◎
135 Gonzalez Francisco Jr ◎
139 Baca D B Mrs ◎
145 Scranlin John
149 Pringle G R ◎
Rosario intersects

CANON ROAD
Begins 323 S Castillo extends east beyond city limits
200 Houk C G
201 Jensen J K ◎
202 Barton Esther M
221 Vigil Julia Mrs ◎
223 Trujillo Jose
233 Jackson F G
234 Valdez Fred ◎
234½ Stacy E L Mrs
E De Vargas ends w
Garcia bg s
400 Little Red Sch House Theatre
403 Delgado Manuel ◎
409 Delgado H A ◎
414-14½ Baca Nicanor ◎
415 Faulk C O ◎
418 Gonzalez J M ◎
421 Broome T K
423 Heard Dorothy Mrs
424 Rivera Romancita ◎
428 Howard E G
Delgado intersects
503 Delgado Efren ◎
513 Cheney H B
513½ Sullivan E J
519 Dietrich Margretta Mrs ◎
524 West H E
526 Rosario Sarah Mrs
528 Vacant
530 Winnek Marian F ◎
540 Catron F A ◎
544 Catron T B II ◎
545 El Zaguan Apts
Apartments—
*1 Lukas Julia
*2 Dennis F L
*2b Anderson W K P
*3 Lee R E
*4 Stevenson J H
*5 Erickson Eleanor
*6 Boatner Selwyn
*7 McEwen Alexandrine
*9 Hays J C
Street Continued
553 Brooks Edwin ◎
555 Howland Alfred ◎

CANON RD—Cont'd
558 Barnes W S
Rose av ends ns
601 Vigil Cruz ◎
602-8 Wilson Wayne
607 Percy's Gro & Mkt
Ortiz Presciliano ◎
610 Rodriguez Francisco ◎
616 Hullenkremer Odon
(1) rear Rodriguez Cipriano ◎
(2) rear Lucero Luis ◎
622 Rodriguez L P
(1) rear Rodriguez Antonio ◎
(2) rear Rodriguez Alfredo
(3) rear Romero Ramoncita
626 Garcia Valentin ◎
628 Bolger Sheldon
630 Rush Olive Miss ◎
640 Parton George ◎
640½ Davis J B
644 Olivas Luis
650 Moya Ignacio ◎
651 McComb S W Mrs ◎
652 Parkhurst T H ◎
656 Roybal J E ◎
662 Moya Madeline ◎
663 Sanchez Toribio
667 Rael Antonio ◎
668 Gormley F F ◎
669 Gomez Diego
670 Gormley's
Gormley begins ss
702 Moya Pablo ◎
rear Moya J B ◎
708 Schmeltzer Henry
710 Alarid Zeferino ◎
713 Cash Hazel Mrs
716 Baca Teofila Mrs ◎
Padilla Frank
720 Ortega Ramon
724 Thompson J E
(1) rear Baca Abenicio
Camino del Monte Sol bg ss
725 Martinez Epitacia Mrs ◎
Lynch Eloisa Mrs
728 Gonzalez Elias ◎
rear Chavez Dionicio
E Palace av ends ns
802 Langley L L
806-8 Vigil Lazario ◎
812 Vigil Damesio ◎
820 Matoga Weavers
Lucero Samuel
822 Vigil Beatriz ◎
rear Catanach J L
826 Vigil Cash Gro
828 Vigil Daniel
830 Vigil Feliciana Mrs ◎
rear Vigil Rafael ◎
832 Trujillo J M ◎
833 Boot & Saddle Stable
834-36 Martinez David
Palace av intersects
906 Ortiz Alberto ◎

1936-37 E ALAMEDA ST

SOURCE: HUDSPETHS

ALAMEDA E—Cont'd

540 Proebstel Chas ◎
550 Rose A D Mrs ◎
564 Wangerien H A ◎
Rose av begins ss
614 Vacant
616 Romero Daniel
(1) rear Saiz Frank ◎
(2) rear Rodrizuez Benedicto ◎
(3) rear Ortega Manuel
618 Sandoval Santiago ◎
rear Pacheco Ramon
E Palace av intersects

ALAMEDA WEST
Begins 234 Don Gaspar av extends west to Hancock
211-13 White Swan Lndry Co

ALARID
Begins 800 W Manhattan extends south to Ninita
515 Sandoval B H ◎
520 Alarid J D ◎
534 Alarid Ricardo ◎
536 Miller O A
564 Haun L M ◎
Hickox intersects
603 Wrinkle J R
607 Smith V E
609 Baca C L
611 Ortiz Florentino ◎
rear Morris M L
617 Yates T E ◎
rear Thompson J E
618 Narvaez Adolfo ◎
621 Irby C H ◎
626 Haynes W L ◎
628 Martinez E G Mrs ◎
630 Vigil J E ◎
632 de Baca L C ◎
Ninita intersects
701 Gonzalez Faustin ◎

ALLENDALE
Begins ½ blk north of 224 W Buena Vista av extends south 2 blks
723 Cooper W M
725 Burleson F E
W Buena Vista av intersects
805 Street G F ◎
808 Lopez Alfonso ◎
811 Williamson Al
812 Vacant
813 Reynolds M B
814 Nix M L
815 Cornelson F E
818 O'Hara J S ◎
819 Smith O W ◎
822 Shimp Mildred Mrs ◎
823 Sadler D K
828 Tyner C D ◎
829 Hammond H J
831 Anderson W R
832 Ashley A J

ALTO
Begins 200 De Fouri extends west beyond city limits
508 Campbell C M ◎
510 Garcia Adelaida Mrs
514 Chavez Romualdo ◎
516 Garcia Martha Mrs ◎
518 Garcia Vicente ◎
522 Espino Candelario ◎
524 Rivera Telesforo
525 Armijo Isabelita Mrs ◎
rear Armijo Pablo
526 Gonzalez Benj
527 Garcia Jose
528 Chavez Eufemia Mrs
529 Armijo Adolfo ◎
531 Garcia Francisquita
532-34 Ortiz J M ◎
536 Cisneros Benj
540 Roybal Genoveva Mrs ◎
Polaco bg ss
542 Armijo M V Mrs ◎
rear Maes Antonio
548 Sandoval Bonifacia ◎
550 Ortega J A ◎
Closson intersects
604 Vacant
605 Sena Mariano ◎
606 Sena J G ◎
608 Moya Antonio
610 Cordova Margarita
618 Montoya Miguel ◎
620 Lucero P G ◎
622 Cisneros Juan
Barela bg ss
636 Ortiz W J ◎
648 Ortiz Candido ◎
Young bg ss
724 Rivera Placida Mrs
728 Ellison Maria ◎
736 Roybal Luciano ◎
(1) rear Rivera Placida
(2) rear Roybal Jose ◎
(3) rear Romero Alejandrino ◎
(4) rear Coriz Tranquilino ◎
(5) rear Montoya Lillie Mrs
(7) rear Velarde Pomposo ◎
737 Roybal Pedro ◎
rear Salazar Jose
741 Vacant
Irvine bg ss
Ambrosio bg ss
821 Arrey Jesus
831 Valdez Otto ◎
837-39 Rougemont Marcelino
845 Montoya Albino ◎
847 Montoya Guadalupe ◎
851 Roman Urbano ◎
853 Montoya J L ◎
Montoya intersect
903 Montoya Manuel ◎

1930-31 CANYON RD

SOURCE: HUDSPETHS

111 Vacant
rear Vacant
117-19 Chavez Rafael ◎
121-23 Trujillo Pedro ◎
rear Ortiz J W ◎
125 Ortiz Cesario
131 Vacant
135 Gonzalez Francisco Jr ◎
139-41 Baca Paul ◎
147 Scramlin John ◎
153 Martinez Andres ◎
Rosario intersects

CANON ROAD
Begins 323 S Castillo extends east beyond city limits
201 Jensen J K ◎
221 Vigil Julia Mrs
223 Delgado Antonio
233 Vacant
234 Valdez Fred ◎
238 Vacant
E De Vargas ends ws
Canon rd bg es
Garcia begins ss
se cor Canon Road School
403 Delgado Manuel ◎
409 Delgado H A
414 Chapman C J
414½ Baca Nicanor ◎
415 Faulk C O ◎
418 Gonzalez J M ◎
421 Fox P S
423 Stewart Alice Mrs
424 Rivera Joseph ◎
428 Vacant
Delgado intersects
503 Delgado Francisco ◎
513 Sears H D ◎
515 O'Hara J S
519 Dietrich Marguerite ◎
524 Weswall W W
525 El Zaguan Apts
525(1) Connelly M R Mrs
525(2) Harrington Florence Mrs
525(3) Reisfar L H Miss
525(4) Vacant
525(5) Booth L D Miss
525(6) Adams Liane Mrs
525(7) Gay Katherine Miss
525(8) Vacant
525(9) Chavez Lucas
526 Sena Nicolas ◎
528 Olivas Agustina Miss
530 Winnek M F ◎

CANON ROAD—Cont'd

553 Brooks Edwin
555 Howland Alfred ◎
558 Mallery E T ◎
Rose ends ns
601 Vigil Cruz ◎
602-8 Atalaya School
Southgate S B Mrs
610 Rodriguez Francisco ◎
rear Vacant
616 Rodriguez Cipriano ◎
rear Rodriguez Bernardita Mrs
622 Rodriguez Antonio
626 Garcia Valentin ◎
628 Vacant
630 Rush Olive Miss ◎
634 Vacant
640 Hillyer J D
rear Cunningham C A
644 Rael Griselda Mrs ◎
650 Moya Ignacio ◎
651 Mc Comb D J ◎
rear Roybal J F
652 Cohen L K
653 McKittrick Margaret Miss
656 Roybal J E ◎
662 Moya Ramoncita ◎
663 Sanchez Toribio
667 Rael Antonio ◎
668 Gormley F F ◎
669 Gomez Diego
670 Gormley F F ◎
Gormley's
Gormley begins ss
702 Moya Pablo ◎
rear Moya Juan ◎
708 Miller R M
710 Alarid Zeferino ◎
711 Vacant
716 Baca Teofila Mrs ◎
Padilla Frank
720 Gorman Miguel
rear Vacant
724 Loewenstein Josephine Mrs
(1) rear Gonzalez J F ◎
(2) rear Gonzalez Elias ◎
Camino del Monte Sol bg ss
725 Lynch John
Martinez Bros
E Palace av ends ns
802 Ortiz Ramon
806-8 Vigil Lazaro ◎
812 Vigil Demecio ◎
McDowell G R

1930-31 E ALAMEDA ST
SOURCE: HUDSPETHS

AGUA FRIA—Cont'd
734 Gorman R L ◎
rear Gutierrez Frank ◎
735 Sandoval Juanita Mrs
740 Smith J P ◎
742 Britton Josefita Mrs ◎
744 Candelaria Chas ◎
758 Martinez Melquiades ◎
Irvine bg ns
802 Vacant
803 Larragoite Armando ◎
808 Alarid Fred ◎
814 Pino Juan ◎
818-20 Davis D W ◎
824 Martinez Panfilo ◎
826 Ludi G F ◎
Juanita bg ss
840 Lamoreaux H O ◎
843 Vacant
845 Quintana Felipe
854 Vacant
858 Julian J A
863 Jacobs Dairy
864 Martinez William ◎
903 Rodriguez Agustina ◎
905 Varela Maria Mrs ◎
906 Martinez J M ◎
907 Romero Gertrudis
917 Schregardus Fred ◎
Onate pl bg
925 Vacant
927 Romero Luis ◎
928 Grace Paul ◎
930 Vacant
931 Agua Fria School
933 Urioste Antonio ◎
937 Gonzalez Eusebio ◎
rear de la Rosa Salvador
941 Sanchez Antonia ◎
Franklin bg es
945 Vacant
947 Vacant
973 Creamery Del Rico
Kathryn bg es
sw cor Moncrief W C ◎

ALAMEDA
Begins 300 Don Gaspar av extends east to Palace av
113 Mountain States Tel & Tel Co
129 Piatt E R Miss
Shelby ends ns
137 White L E
141 McKinney Isaac
143 Nelson C A
145 Wood B P
College intersects
Cathedral pl ends ns
Castillo intersects
301-5 Casitas Del Rio
*1 Olson G H
*2 Moehn R P
*3 Thompson Louise Mrs
*4 Hammond L C
*5 Radcliffe M W
*6 Anderson A G
311 Harvey J C ◎
331 Castillo Margarita ◎
339 Ortiz Manuel ◎
341 Daley Daniel ◎
343 Vacant
345 Medrano Andres ◎
Miller J A
349 Lavidea Jose ◎
Canon rd bg ss
ss Wheeler E L ◎
Delgado intersects
528 Stevenson F R ◎
540 Webster Charles ◎
550 Rose William ◎
564 Wangerien H A ◎
Rose begins ss
614 Taylor L J M Mrs ◎
616 Sais Pascual ◎
(1) rear Sais Frank
(2) rear Vigil D G Mrs ◎
618 Ortega Frances Mrs
rear Smith Nelson
E Palace av intersects

ALARID
Begins 800 W Manhattan extends south to Ninita
ws Alarid Jacob ◎
ws Alarid Ricardo ◎
ws Snow D W
Hickox intersects
es Vacant
es Vacant
es Ortiz Florentino ◎
es Romero Raymond
es Roak J C ◎
es Vacant

ALLENDALE
Begins ½ blk north of 224 Sena extends south 2 blks
723 Thompson Gladys
725 Montgomery A K
Sena intersects
805 Bennett R W
811 Lathrop A S ◎

1928-29 CANYON RD-A
SOURCE: HUDSPETHS

131 Medrano Ambrosio (o)
132 Valencia Juan
138 Aguirre Lazaro
140 Vacant
Galisteo intersects
Allendale intersects
Don Cubera intersects
407 Gregory M A (o)
Don Diego av intersects

BURRO ALLEY
Begins 207 W San Francisco extends north to Palace av
64 O'Neal Thomas
66 Rusler J H
68 Gavin Carmelita (o)
W Palace av ends es

COMINO ATALAYA
Begins E Buena Vista av 1 blk east of College extends south to Pecos rd
ws Mac Millan J H (o)
ws Jonson Raymond (o)
Pecos rd intersects

CAMINO CHIQUITO
Begins Gormley first south of Manhattan extends east to Camino del Monte Sol

CAMINO DEL MONTE SOL
Begins 800 Canyon rd extends south to Garcia
306 Apodaca Bernardino (o)
330 Lovato Lola Mrs
E Manhattan intersects
405 Vigil Pedro (o)
408 Vacant
409 Quintana Jose (o)
430 Garcia F R (o)
439 Austin Mary Mrs (o)
452 Street G F
501 Myers D E (o)
504 Vacant
507 Walker W J
515 Gabaldon Gregorio
519 Gabaldon Zacarias (o)
520 Dasburg Andrew (o)
524 Callin E W (o)
529 Chapman Marie Mrs
530 Collins W D Mrs
538 Flaherty R J
542 Patterson H A
550 De Vito D C
558 Hyde Benjamin (o)
566 Nash Willard (o)
576 Bakos Jozef (o)
580 Schuster Will (o)
586 Ellis Fremont (o)
end Henderson W P (o)
Garcia intersects

CANYON ROAD
Begins 301 S Castillo extends east beyond city limits
201 Jensen J K (o)
221 Vigil Julio
223 Delgado Antonio
233 Miera Vito
Esquivel Manuel
234 Valdez Fred (o)
238 Vacant
E De Vargas ends ws
Canyon rd bg es
Garcia begins ss
se cor Canyon Road School
403 Delgado Manuel (o)
409 Delgado H A
414 Baca Jose
414½ Baca Nicanor (o)
415 Faulk C O (o)
418 Gonzalez Jesus (o)
421 Fox P S
423 Hammond Grace Miss
424 Rivera Valentin (o)
428 Vacant
440 Acuna Clemente (o)
Delgado intersects
503 Delgado Francisco (o)
513 Moulton H D Mrs
515 Muszynski Gertrude
519 Vacant
524 Mruk W E
525 Vacant
526 Sena Nicolas (o)
528 Olivas Agustina Miss
530 Requa C H
537 Vacant
543 Vacant
547 Vacant
553 Vacant
555 Howland Alfred (o)
558 Mallery E T (o)
Rose ends ns
601 Vigil Cruz (o)
602 Vacant
608 Vacant
610 Rodriguez Francisco (o)
rear Vacant
616 Rodriguez Pedro (o)

1928-29 CANYON RD-B
SOURCE: HUDSPETHS

622 Arcena Antonio (o)
626 Garcia Valentin (o)
628 Givens V R
630 Arnold Charotte Miss (o)
634 Clayton P L
640 Parton George (o)
rear Power C J
644 Rael Griselda Mrs (o)
650 Moya Ignacio (o)
651 Mc Comb D J (o)
rear Roybal Juan
652 Moya P T (o)
656 Moya J N (o)
662 Moya Ramoncita (o)
663 Olivas Vidal
667 Rael Antonio (o)
668 Gormley F F (o)
669 Gomez Diego
670 Gormley F F (o)
Gormley begins ss
702 Moyo Pablo (o)
rear Moya Juan (o)
708 Vacant
710 Alarid Zeferino (o)
716 Baca Felix (o)
720 Gorman Miguel
rear Roman Urbano
724 Canyon Rd Cash Store
(1) rear Gonzalez Elias (o)
(2) rear Gonzalez J F (o)
Camino del Monte Sol bg ss
725 Lynch John
Martinez Bros
E Palace ev ends ns
802 Ortiz Ramon
806-8 Vigil Lazaro (o)
812 Vigil Demecio (o)
820 Howland Bertha Mrs
822 Vigil Beatriz (o)
rear Trujillo C R Mrs (o)
826 Romero Maria Mrs (o)
828 Vigil J J (o)
830 Vigil Atanacio (o)
rear Vigil Rafael (o)
832 Lovato J T Mrs (o)
834 Martinez David
836 Trujillo Roman
906 Borrego Francisca (o)
907 Rivera Emeterio (o)
911 Duran M H Mrs (o)
Duran & Herrera
912 Nagle Rose Mrs
914 Nicholas C F
915 Vigil Jacobo (o)
922 Vacant
924 Cassidy Gerald (o)
942 Apodaca Cerillo (o)
945 Vacant
950 Vacant
rear Lucero Norberta (o)
E Manhattan ends ss
956 Martinez J B (o)
958 Lucero Albina Mrs (o)
1004 Carrillo Marcelina Mrs
1005 Stevens T W Mrs (o)
1008 Moya Ralph (o)
rear Montoya Esquipula Mrs
1009 Gonzalez Tonita Mrs (o)
1014 Nelson J L (o)
1015 Carrillo Cruz (o)
1017 Carrillo Petrita Mrs (o)
1019 Turner James
1023 Montoya Margarita (o)
1060 Vacant
1104 Vacant
rear Martinez Facundo (o)
1106-10 Chavez Martin (o)
1111 Chavez Rufinita Mrs
1115 Vacant
1132 Rodriguez David (o)
1144 Rodriguez Irineo (o)
1150 Manderfield School
end Braid W G (o)
Los Cerros
N M Power Co plant
N M Power Co reservoir

CAPITOL N
Begins 300 Don Gaspar av extends west to Galisteo
ns Governor's Mansion
Galisteo intersects

CAPITOL S
Begins 400 Don Gaspar av extends west to Galisteo
116 Beacham Wm (o)
120 Lamb Charles
122 Hill R J
130 Watson J C
134 Yerex Lowell
138 Chavez Miguel (o)
Galisteo intersect

CASTILLO N
Begins 301 E Palace av extends north to Hillside av
122 Reingardt August (o)

1928-29 E ALAMEDA ST
SOURCE: HUDSPETHS

722 Catanach Edward
724 Sanchez Enrique (o)
rear Vacant
725 Minchey William
728 Martinez Dalio (o)
rear Mares Santiago (o)
731 Redman L E
732 Martinez G B Mrs (o)
rear Pilkington K E
733 Ortiz G B Mrs (o)
734 Gorman R L (o)
735 Sandoval Juanita Mrs
740 Smith J P (o)
742 Britton Josefita Mrs (o)
744 Mares Felipe
746 Lopez G G
758 Martinez Melquiades (o)
Irvine bg ns
802 Vacant
803 Larragoite Armando (o)
814 Rodriguez Abran
818-20 Davis D W (o)
824 Martinez Panfilo (o)
826 Ludi G F (o)
843 Vacant
844 Lamoreux O H
845 Gonzalez Emilio (o)
854 Herrera Miguel
858 Riley Bessie Mrs
863 Jacobs Dairy
864 Martinez William (o)
Onate pl bg ss
903 Rodriguez Agustina (o)
905 Varela Maria Mrs (o)
906 Martinez J M (o)
907 Romero Gertrudis
917 Schrgardus Fred (o)
925 Martinez Seferina Mrs
927 Romero Luis (o)
931 Agua Fria School
933 Urioste Antonio (o)
937 Gonzalez Eusebio (o)
941 Sanchez Antonia (o)
945 Madrid Pino
947 Vacant
973 Solano Farm Dairy

ALAMEDA
Begins 300 Don Gaspar av extends east to Palace av
113 Mountain States Tel & Tel Co
Shelby ends ns
129 Gaastra T C

137 Wilson F B Mrs
141 Hardy W E
143 Nelson C A
145 Hoffman Violet Miss
College intersects
Cathedral pl ends ns
Castillo intersects
301-5 **Casitas Del Rio**
*1 Staplin O L
*2 Moehn R P
*3 Haralson E L
*4 Sweeney R P
*5 Rockett L C
*6 Roberts Nellie Mrs
311 Harvey J C (o)
331 Castillo Margarita (o)
339 Fayette Joseph
rear Ortiz Manuel (o)
343 Garcia Atanacio (o)
Napoleon Fred
345 Medrano Andres (o)
349 Lavidea Jose (o)
Canyon rd bg ss
ss Wheeler E L (o)
Delgado intersects
528 Stevenson F R (o)
550 Rose William (o)
564 Wangerien H A (o)
Rose begins ss
614 Taylor Knox Mrs (o)
616 Vacant
(1) rear Sais Frank (o)
(2) rear Vigil Martin (o)
618 Chavez Eusebio
rear Sandoval Santiago (o)
E Palace av inttersects

ALARID
Begins 800 W Manhattan extends south ½ blk to Hickox
ws Alarid Ricardo (o)
Hickox intersects

ALLENDALE
Begins ½ blk north of 224 Sena extends south 2 blks
723 Yashvin Morris
725 Lowe J A
Sena intersects
805 Bennett R W
811 Kaune H E
812 Teutsch L E
rear Serna Wenceslao (o)
814 Newman R B
815 Vacant

APPENDIX H

Database Report

DATABASE REPORT

Project Property:	*Universal Cleaners* *622 Canyon Rd* *Santa Fe NM 87501*
Project No:	*NMENV.M007.SF-WALDO*
Report Type:	*Database Report*
Order No:	*25121700733*
Requested by:	*INTERA Incorporated*
Date Completed:	*December 20, 2025*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....8
Executive Summary: Site Report Summary - Surrounding Properties.....9
Executive Summary: Summary by Data Source.....10
Map.....13
Aerial.....16
Topographic Map.....17
Detail Report.....18
Unplottable Summary.....26
Unplottable Report.....27
Appendix: Database Descriptions.....28
Definitions.....43

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:		*Universal Cleaners* *622 Canyon Rd Santa Fe NM 87501*
Project No:		*NMENV.M007.SF-WALDO*
Coordinates:		
	Latitude:	*35.68133383*
	Longitude:	*-105.92829458*
	UTM Northing:	*3,949,001.59*
	UTM Easting:	*415,998.54*
	UTM Zone:	*UTM Zone 13S*
Elevation:		*7,073 FT*

Order Information:

Order No:	*25121700733*
Date Requested:	*December 17, 2025*
Requested by:	*INTERA Incorporated*
Report Type:	*Database Report*

Historicals/Products:

Aerial Photographs	*Historical Aerials (with Project Boundaries)*
Chain of Title & Lien Searches	*ASTM E1527-21 Compliant Environmental Lien Search (back to 1980) with Historic Chain of Title (back to 1932)*
City Directory Search	*CD - 2 Street Search*
ERIS Xplorer	*ERIS Xplorer*
Excel Add-On	*Excel Add-On*
Fire Insurance Maps	*US Fire Insurance Maps*
Physical Setting Report (PSR)	*Physical Setting Report (PSR)*
Topographic Map	*Topographic Maps*

Executive Summary: Report Summary

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
Standard Environmental Records								
Federal								
NPL	Y	1	0	0	0	0	0	0
PROPOSED NPL	Y	1	0	0	0	0	0	0
DELETED NPL	Y	0.5	0	0	0	0	-	0
SEMS	Y	0.5	0	0	0	0	-	0
SEMS ARCHIVE	Y	0.5	0	0	0	0	-	0
ODI	Y	0.5	0	0	0	0	-	0
IODI	Y	0.5	0	0	0	0	-	0
CERCLIS	Y	0.5	0	0	0	0	-	0
CERCLIS NFRAP	Y	0.5	0	0	0	0	-	0
CERCLIS LIENS	Y	PO	0	-	-	-	-	0
RCRA CORRACTS	Y	1	0	0	0	0	0	0
RCRA TSD	Y	0.5	0	0	0	0	-	0
RCRA LQG	Y	0.25	0	0	0	-	-	0
RCRA SQG	Y	0.25	0	0	0	-	-	0
RCRA VSQG	Y	0.25	0	0	0	-	-	0
RCRA NON GEN	Y	0.25	0	***1***	0	-	-	***1***
RCRA CONTROLS	Y	0.5	0	0	0	0	-	0
FED ENG	Y	0.5	0	0	0	0	-	0
FED INST	Y	0.5	0	0	0	0	-	0
LUCIS	Y	0.5	0	0	0	0	-	0
NPL IC	Y	0.5	0	0	0	0	-	0
ERNS 1982 TO 1986	Y	PO	0	-	-	-	-	0
ERNS 1987 TO 1989	Y	PO	0	-	-	-	-	0
ERNS	Y	PO	0	-	-	-	-	0
FED BROWNFIELDS	Y	0.5	0	0	0	0	-	0
FEMA UST	Y	0.25	0	0	0	-	-	0
FRP	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
DELISTED FRP	Y	0.25	0	0	0	-	-	0
HIST GAS STATIONS	Y	0.25	0	0	0	-	-	0
REFN	Y	0.25	0	0	0	-	-	0
BULK TERMINAL	Y	0.25	0	0	0	-	-	0
SEMS LIEN	Y	PO	0	-	-	-	-	0
SUPERFUND ROD	Y	1	0	0	0	0	0	0
State								
SCS	Y	1	0	0	0	0	**6**	**6**
DELISTED SCS	Y	1	0	0	0	0	0	0
SWF/LF	Y	0.5	0	0	0	0	-	0
HIST LF	Y	0.5	0	0	0	0	-	0
RECYCLING	Y	0.5	0	0	0	0	-	0
LST	Y	0.5	0	0	0	**1**	-	**1**
DELISTED LST	Y	0.5	0	0	0	0	-	0
LUST HIST	Y	0.5	0	0	0	**1**	-	**1**
UST	Y	0.25	0	0	0	-	-	0
AST	Y	0.25	0	0	0	-	-	0
TANKS	Y	0.25	0	0	0	-	-	0
UST HIST	Y	0.25	0	0	0	-	-	0
AST HIST	Y	0.25	0	0	0	-	-	0
DELISTED TANK	Y	0.25	0	0	0	-	-	0
INST	Y	0.5	0	0	0	0	-	0
VCP	Y	0.5	0	0	0	0	-	0
BROWNFIELDS	Y	0.5	0	0	0	0	-	0
Tribal								
INDIAN LUST	Y	0.5	0	0	0	0	-	0
INDIAN UST	Y	0.25	0	0	0	-	-	0
DELISTED INDIAN LST	Y	0.5	0	0	0	0	-	0
DELISTED INDIAN UST	Y	0.25	0	0	0	-	-	0
County	***No County databases were selected to be included in the search.***							

Additional Environmental Records

Federal

PFAS GHG	Y	0.5	0	0	0	0	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
OSC RESPONSE	Y	0.125	0	0	-	-	-	0
FINDS/FRS	Y	PO	0	**1**	-	-	-	**1**
TRIS	Y	PO	0	-	-	-	-	0
PFAS NPL	Y	0.5	0	0	0	0	-	0
PFAS FED SITES	Y	0.5	0	0	0	0	-	0
PFAS SSEHRI	Y	0.5	0	0	0	0	-	0
PFAS ERNS	Y	0.5	0	0	0	0	-	0
PFAS NPDES	Y	0.5	0	0	0	0	-	0
PFAS TRI	Y	0.5	0	0	0	0	-	0
PFAS WATER	Y	0.5	0	0	0	0	-	0
PFAS TSCA	Y	0.5	0	0	0	0	-	0
PFAS E-MANIFEST	Y	0.5	0	0	0	0	-	0
PFAS IND	Y	0.5	0	0	0	0	-	0
HMIRS	Y	0.125	0	0	-	-	-	0
NCDL	Y	0.125	0	0	-	-	-	0
TSCA	Y	0.125	0	0	-	-	-	0
HIST TSCA	Y	0.125	0	0	-	-	-	0
FTTS ADMIN	Y	PO	0	-	-	-	-	0
FTTS INSP	Y	PO	0	-	-	-	-	0
PRP	Y	PO	0	-	-	-	-	0
SCRD DRYCLEANER	Y	0.5	0	0	0	0	-	0
ICIS	Y	PO	0	-	-	-	-	0
FED DRYCLEANERS	Y	0.25	0	0	0	-	-	0
DELISTED FED DRY	Y	0.25	0	0	0	-	-	0
FUDS	Y	1	0	0	0	0	**1**	**1**
FUDS MRS	Y	1	0	0	0	0	0	0
FORMER NIKE	Y	1	0	0	0	0	0	0
PIPELINE INCIDENT	Y	PO	0	-	-	-	-	0
MLTS	Y	PO	0	-	-	-	-	0
HIST MLTS	Y	PO	0	-	-	-	-	0
MINES	Y	0.25	0	0	0	-	-	0
SMCRA	Y	1	0	0	0	0	0	0
MRDS	Y	1	0	0	0	0	0	0
LM SITES	Y	1	0	0	0	0	0	0
ALT FUELS	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
CONSENT DECREES	Y	0.25	0	0	0	-	-	0
AFS	Y	PO	0	-	-	-	-	0
SSTS	Y	0.25	0	0	0	-	-	0
PCBT	Y	0.5	0	0	0	0	-	0
PCB	Y	0.5	0	0	0	0	-	0
POWER PLANTS	Y	0.125	0	0	-	-	-	0
HIST RISK	Y	0.125	**2**	0	-	-	-	**2**
State								
HAZ	Y	0.5	0	0	0	0	-	0
SPILLS	Y	0.125	0	0	-	-	-	0
SPILLS OIL	Y	0.125	0	0	-	-	-	0
CDL	Y	0.125	0	0	-	-	-	0
PFAS	Y	0.5	0	0	0	0	-	0
GW DISCHARGE	Y	PO	0	-	-	-	-	0
URANIUM	Y	0.5	0	0	0	0	-	0
Tribal	***No Tribal additional environmental record sources available for this State.***							
County	***No County additional environmental record sources available for this State.***							
	Total:		**2**	**2**	0	**2**	**7**	**13**

**** PO – Property Only***
**** 'Property and adjoining properties' database search radii are set at 0.25 miles.***

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	HIST RISK	Universal Cleaners	622 Canyon Santa FE NM	N	0.00 / 0.00	-2	18
1	HIST RISK	Universal Cleaners	622 Canon Santa FE NM	N	0.00 / 0.00	-2	18

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
2	FINDS/FRS	PARROTT FABRICS INC	634 CANYON RD SANTA FE NM 87501 ***Registry ID:*** 110004271635	SE	0.02 / 97.30	3	18
2	RCRA NON GEN	PARROTT FABRICS INC	634 CANYON RD SANTA FE NM 87501 ***Handler ID | Recycler Activity?:*** NMD035792506 | NO	SE	0.02 / 97.30	3	19
3	LST	Pera Bldg	PASEO DE PERALTA SANTA FE NM 87502 ***Release ID | Facility ID | Status:*** 2701 | 30766 | No Further Action, Confirmed Release	W	0.45 / 2,389.49	-51	21
3	LUST HIST	PERA BLDG	PASEO DE PERALTA SANTA FE NM	W	0.45 / 2,389.49	-51	22
4	SCS	Ruben Well	Camino Sin Nombre and Camino San Acacio, 623 Camino Rancheros Santa Fe NM	SE	0.53 / 2,779.56	115	22
5	FUDS	FORT MARCY	SANTA FE NM ***FUDS Property No:*** K06NM0417	NE	0.61 / 3,196.92	97	23
6	SCS	913 Old Pecos Trial	913 Old Pecos Trial Santa Fe NM	SW	0.63 / 3,318.01	9	23
7	SCS	PKG Building	218 Montezuma Santa Fe NM	W	0.87 / 4,568.98	-93	24
8	SCS	Masters Cleaners	238 Sandoval St. Santa Fe NM	WNW	0.88 / 4,638.40	-109	24
9	SCS	Santa Fe Beaver Reintroduction by Forest Guardians	312 Montezuma Santa Fe NM	W	0.95 / 4,999.81	-99	24
10	SCS	Garcia Honda	607 Cerrillos Santa Fe NM	W	1.00 / 5,258.77	-98	25

Executive Summary: Summary by Data Source

Standard

Federal

RCRA NON GEN - RCRA Non-Generators

A search of the RCRA NON GEN database, dated Sep 1, 2025 has found that there are 1 RCRA NON GEN site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
PARROTT FABRICS INC	634 CANYON RD SANTA FE NM 87501	SE	0.02 / 97.30	2
	Handler ID* | *Recycler Activity?: *NMD035792506 | NO*			

State

SCS - State Cleanup Sites Listing

A search of the SCS database, dated Feb 4, 2025 has found that there are 6 SCS site(s) within approximately 1.00miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Ruben Well	Camino Sin Nombre and Camino San Acacio, 623 Camino Rancheros Santa Fe NM	SE	0.53 / 2,779.56	4
913 Old Pecos Trial	913 Old Pecos Trial Santa Fe NM	SW	0.63 / 3,318.01	6

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
PKG Building	218 Montezuma Santa Fe NM	W	0.87 / 4,568.98	7
Masters Cleaners	238 Sandoval St. Santa Fe NM	WNW	0.88 / 4,638.40	8
Santa Fe Beaver Reintroduction by Forest Guardians	312 Montezuma Santa Fe NM	W	0.95 / 4,999.81	9
Garcia Honda	607 Cerrillos Santa Fe NM	W	1.00 / 5,258.77	10

LST - Leaking Petroleum Storage Tanks

A search of the LST database, dated Sep 16, 2025 has found that there are 1 LST site(s) within approximately 0.50miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Pera Bldg	PASEO DE PERALTA SANTA FE NM 87502	W	0.45 / 2,389.49	3
	***Release ID** | **Facility ID** | **Status**: 2701 | 30766 | No Further Action, Confirmed Release*			

LUST HIST - Leaking Underground Storage Tanks

A search of the LUST HIST database, dated Aug 1, 2006 has found that there are 1 LUST HIST site(s) within approximately 0.50miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
PERA BLDG	PASEO DE PERALTA SANTA FE NM	W	0.45 / 2,389.49	3

Non Standard

Federal

FINDS/FRS - Facility Registry Service/Facility Index

A search of the FINDS/FRS database, dated Oct 10, 2025 has found that there are 1 FINDS/FRS site(s) within approximately 0.02miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
PARROTT FABRICS INC	634 CANYON RD SANTA FE NM 87501	SE	0.02 / 97.30	2
	***Registry ID**: 110004271635*			

FUDS - Formerly Used Defense Sites

A search of the FUDS database, dated May 15, 2023 has found that there are 1 FUDS site(s) within approximately 1.00miles of the project property.


Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
FORT MARCY	SANTA FE NM	NE	0.61 / 3,196.92	5
	***FUDS Property No**: K06NM0417*			

HIST RISK - Historical Business Activity Risk

A search of the HIST RISK database, dated Jan 1, 1960 has found that there are 2 HIST RISK site(s) within approximately 0.12miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Universal Cleaners	622 Canyon Santa FE NM	N	0.00 / 0.00	1

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Universal Cleaners	622 Canon Santa FE NM	N	0.00 / 0.00	1



Map: 1.0 Mile Radius


Order Number: 25121700733

Address: 622 Canyon Rd, Santa Fe, NM

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.5 Mile Radius


Order Number: 25121700733

Address: 622 Canyon Rd, Santa Fe, NM

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.25 Mile Radius


Order Number: 25121700733

Address: 622 Canyon Rd, Santa Fe, NM

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Aerial


Year: 2024

Order Number: 25121700733

Address: 622 Canyon Rd, Santa Fe, NM

Source: ESRI World Imagery

© ERIS Information Limited Partnership



Topographic Map

Year: 2023

Order Number: 25121700733

Address: 622 Canyon Rd, NM

Quadrangle(s): Santa Fe NM

Source: USGS Topographic Map

© ERIS Information Inc.

Detail Report

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	1 of 2	N	0.00 / 0.00	7,071.52 / -2	Universal Cleaners 622 Canyon Santa FE NM	HIST RISK

Historic Potential Business Activity Risk

Year:	1953
Directory Publisher:	HUDSPETHS
Broad Term:	Potential Hazardous Chemical User
Directory Heading:	1953
Listing:	Universal Cleaners
Address:	622 Canyon
Address2:	
City:	Santa FE
State:	NM
Zip:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	2 of 2	N	0.00 / 0.00	7,071.52 / -2	Universal Cleaners 622 Canon Santa FE NM	HIST RISK

Historic Potential Business Activity Risk

Year:	1949
Directory Publisher:	HUDSPETHS
Broad Term:	Potential Hazardous Chemical User
Directory Heading:	1949
Listing:	Universal Cleaners
Address:	622 Canon
Address2:	
City:	Santa FE
State:	NM
Zip:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	1 of2	SE	0.02 / 97.30	7,076.95 / 3	PARROTT FABRICS INC 634 CANYON RD SANTA FE NM 87501	FINDS/FRS

Registry ID:	110004271635
FIPS Code:	35049
HUC Code:	13020201
Site Type Name:	STATIONARY
Location Description:	
Supplemental Location:	
Create Date:	01-MAR-00
Update Date:	09-AUG-10
Interest Types:	UNSPECIFIED UNIVERSE
SIC Codes:	
SIC Code Descriptions:	
NAICS Codes:	315191
NAICS Code Descriptions:	OUTERWEAR KNITTING MILLS.
Conveyor:	FRS-GEOCODE
Federal Facility Code:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 03
Census Block Code: 350490005001018
EPA Region Code: 06
County Name: SANTA FE
US/Mexico Border Ind:
Latitude: 35.68144
Longitude: -105.92771
Reference Point: CENTER OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 30
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110004271635
Program Acronyms:

RCRAINFO:NMD035792506

2	2 of2	SE	0.02 / 97.30	7,076.95 / 3	PARROTT FABRICS INC 634 CANYON RD SANTA FE NM 87501	RCRA NON GEN

Handler ID: NMD035792506
Generator Status: N
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO RECORDS: As of Sep 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	N	**NAIC 1:**	315191
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	19800721	**NAIC 4:**	
Active Site:	-----	**State:**	NM
Land Type:		**Location Latitude:**	35.681427
In Handler Univ:	N	**Location Longitude:**	-105.927755
In A Universe:	N	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	NM
Accessibility:		**State District:**	02
Region:	06		
Fed Waste Gen Owner:	HQ		

State Waste Generator Owner:	NM
State Waste Generator:	N
Short Term Generator:	N
Uni Waste:	N
Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20150414
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	PARROTT FABRICS INC
Location Street No:	634
Location Street1:	CANYON RD
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87501
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	ALICE PARROTT
Contact Street No:	
Contact Street1:	634 CANYON RD
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87501
Contact Country:	US
Contact Phone & Ext:	505-982-0794
Contact Fax:	
Contact Email Address:	
Contact Title:	
Owner Name:	PARROTT ALICE
Owner Type:	P
Owner Seq:	1
Operator Name:	
Operator Type:	

Operator Seq:
Public Notes:

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	19800721
Handler Name:	PARROTT FABRICS INC
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Notification
TSD Activity:	N

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street1:***	UNKNOWN
Name:	PARROTT ALICE	***Street2:***	
Dt Became Current:		***City:***	UNKNOWN
Dt Ended Current:		***State:***	NM
Phone:	000-000-0000	***Country:***	
Source Type:	Notification	***Zip:***	00000-0000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
3	1 of2	W	0.45 / 2,389.49	7,022.61 / -51	Pera Bldg PASEO DE PERALTA SANTA FE NM 87502	LST

Release ID:	2701	***Latitude (Map):***	35.682693
Facility ID:	30766	***Longitude (Map):***	-105.935825
Status:	No Further Action, Confirmed Release	***Address (Map):***	PASEO DE PERALTA
Address:		***Address2 (Map):***	
City:		***City (Map):***	SANTA FE
County:		***State (Map):***	NM
Address (NFA):	PASEO DE PERALTA	***Zip (Map):***	87502
City (NFA):	SANTA FE	***Address (Priority):***	
County (NFA):	SANTA FE	***City (Priority):***	
Facility Release IDs (Map):	2701	***County (Priority):***	
Data Source:	NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)		

PSTB No Further Action Sites

Status:	No Further Action, Confirmed Release
NFA Date:	10/20/1987
NFA PDF:	https://cloud.env.nm.gov/resources/collection/9192

Leaking Petroleum Storage Tank Sites

Status Date Dt:	1987-10-20 00:00:00 UTC	***NAPL Off Site Val:***	0
Within SWPA Val:	0	***Plume Area No:***	
Surface Water Val:	0	***Plume Area Val:***	2
Private Well Val:	0	***Max Thickness No:***	
Municipal Well Val:	0	***Max Thickness Val:***	
LUWU Sco:	0	***NAPLSco:***	0
Surficial Conc Des:		***Priority2 Sco:***	0
Surficial Conc Val:	0	***Impact Type Des:***	
Leaching Conc Des:		***Impact Type Val:***	0
Leaching Conc Val:	0	***WS Type Des:***	
Construct Conc Des:		***WS Type Val:***	0
Construct Conc Val:	0	***WTR Sys Repl Des:***	
Building Type Des:		***WTR Sys Repl Val:***	0
Building Type Val:	0	***Population No:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Vad Off Site Val:	1		Population Val:	1	
Vadose Sco:	0		WS Sco:	0	
Conc Des:			Toxic Vapor Des:		
Conc Val:	0		Toxic Vapor Val:	0	
Plume Mob Des:			Toxic Vapor Sco:	0	
Plume Mob Val:	0		Priority1 Sco:	0	
GWDPP Off Site Val:	0		Total Sco:	0	
Benzene Area No:			Tempo Total Sco:		
Benzene Area Val:	1		Current Priority:		
GWDPP Sco:	0		Tempo Current Rank:		
Priority3 Sco:	0		Tempo Curr Priorty:		
CSS Age Des:			Point X:	-105.93582500000002	
CSS Age Val:	0		Point Y:	35.68269299999997	
CSS Type Des:			Irrigation Well Val:	0	
CSS Type Val:	0		Subsurf Conc Des:		
CSS Off Site Val:	1		Subsurface Conc Val:	0	
CSS Sco:	0		Petrol Soil Bldg Val:	1	
CSS Volume No:			Petrol Soil Vol Val:	0	
CSS Volume Val:	3		Hydraulic Grad Val:	0	
Release Pm:	UNKNOWN		Depth to GW:		
NAPL Type Des:			Depth to GW Val:	2	
NAPL Type Val:	0		Explosive Vapor Des:		
NAPL Age Des:			Explosive Vapor Val:	0	
NAPL Age Val:	0		Explosive Vapor Sco:	0	
NAPLCondition Des:			Eco Impact Val:	0	
NAPLCondition Val:	0		Eco Impact Sco:	0	

Facility Name:	STATE OF NM PERA BUILDING
Current Status:	No Further Action, Confirmed Release
Aquifer Water Quality Des:	
Aquifer Water Quality Val:	0
Residential Property Val:	0
NAPL Plume Mobility Des:	
NAPL Plume Mobility Val:	0
Property Damage Des:	
Property Damage Val:	0
Property Damage Sco:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
3	2 of2	W	0.45 / 2,389.49	7,022.61 / -51	PERA BLDG PASEO DE PERALTA SANTA FE NM	LUST HIST

Form No:	2701	Contact:	STATE OF NEW ME
Facility ID:	30766	CRC 32:	3499036257
Status:	NFA	Aggrav Factor Score:	
Facility Status:	No Further Action	Mitigat Factor Score:	
Stat Date:		Water Supply Impact:	U
Date Reported:	01-OCT-87	Vapor Explos Impact:	U
SR Result:	9	Prpty Damage Impact:	U
Priority:		Staff:	UNK
Score:		Unloc:	FALSE
St:		Latitude:	0
Site Priority Rank:		Longitude:	0
Total Score:		Facility County:	
Tie Score:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
4	1 of1	SE	0.53 / 2,779.56	7,188.88 / 115	Ruben Well Camino Sin Nombre and Camino San Acacio, 623 Camino Rancheros Santa Fe NM	SCS

County:	Santa Fe
Latitude:	
Longitude:	
Data source(s):	Closed/Inactive State Cleanup Sites(Closed)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Closed Detail

Status: referred to SOS
Date :
Discharge Dt: pre1997
Event: PCE discovered in domestic well
Action Taken: CERCLA conducting an investigation to discover sources sampling of domestic wells in area. No source or RP identified.
Concentrations have decreased over time.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
5	1 of1	NE	0.61 / 3,196.92	7,170.34 / 97	FORT MARCY SANTA FE NM	FUDS

FUDS Property No: K06NM0417
EMS Map Link: https://fudsportal.usace.army.mil/ems/inventory/map?id=61502
FUDS INST ID: NM69799F621400
Status: Properties without projects
SDS ID:
NPL Status Code:
Eligibility: Eligible
Site Eligib:
Current Owner: PRIV: PRIVATE UNKNOWN ; STATE: STATE UNKNOWN
Has Project: No
DOD FUDS Pro: K06NM0417
Project Required: No
No Further Action:
Congressional District: 03
Congressional Dist 117: 03
Media ID:
Metadata ID:
Feature Desc:
EPA Region: 06
County: SANTA FE
Latitude: 35.68888889
Longitude: -105.92222222
Fiscal year: 2021
USACE Division: SPD
USACE District: Los Angeles District (SPL)
Centroid Lat:
Centroid Long:
Se Anno Cad Data:
Shape Length:
Shape Area:
Shape Len:
X: -105.922180176
Y: 35.689025879
Data Source: U.S. Army Corps of Engineers Geospatial Open Data
Property History:

Feature Description:

The DOD began use of the site in 1846 when U.S. troops under General Stephen Watts Kearney occupied the area. The military post was intended as a citadel to which troops could retreat and hold out until help arrived. The site was abandoned in 1894 as a military post and transferred to the city of Santa Fe in 1904.

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
6	1 of1	SW	0.63 / 3,318.01	7,082.86 / 9	913 Old Pecos Trial 913 Old Pecos Trial Santa Fe NM	SCS

County: Santa Fe
Latitude: 35.675081
Longitude: -105.936761
Data source(s): Active State Cleanup Sites

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Active Detail

Project Manager: Kate
Depth To Water (Ft): unknown
Flow Direction: unknown
Media Impacted: Soil Vapor
Regulatory Status: CAR 1203.A
Size Acres: <1
Contam of Concern: PCE, TCE, VOCs
Assmnt/Abatement: Assessment in progress

7	1 of1	W	0.87 / 4,568.98	6,980.25 / -93	PKG Building 218 Montezuma Santa Fe NM	SCS

County: Santa Fe
Latitude: 35.684341
Longitude: -105.94241
Data source(s): Closed/Inactive State Cleanup Sites(Closed)

Closed Detail

Status: closed
Date : 6/15/1984
Discharge Dt: 1984
Event: indoor air and soil vapor showed low levels of CCl2F2
Action Taken:

8	1 of1	WNW	0.88 / 4,638.40	6,964.26 / -109	Masters Cleaners 238 Sandoval St. Santa Fe NM	SCS

County: Santa Fe
Latitude: 35.68626
Longitude: -105.943017
Data source(s): Closed/Inactive State Cleanup Sites(Closed)

Closed Detail

Status: closed
Date : 1/18/2006
Discharge Dt: unknown
Event: Phase 2 showed PCE of 12 mg/kg at 1-5 ft.
Action Taken: 3 soil borings to 50 and 100 ft showed no GW and ND for VOCs, soil vapor at 25' showed 19 ug/lair.

9	1 of1	W	0.95 / 4,999.81	6,974.42 / -99	Santa Fe Beaver Reintroduction by Forest Guardians 312 Montezuma Santa Fe NM	SCS

County: Santa Fe
Latitude: 35.684628
Longitude: -105.94441
Data source(s): Closed/Inactive State Cleanup Sites(Closed)

Closed Detail

Status: referred to SWQB
Date : 2/01/2014
Discharge Dt: unknown
Event: beaver dam created by beaver reintroduction project creating diversion of potentially contaminated water making a reported threat to residents

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Action Taken:		investigation showed no ground water concerns				
10	1 of1	W	1.00 / 5,258.77	6,975.16 / -98	Garcia Honda 607 Cerrillos Santa Fe NM	SCS

County: Santa Fe
Latitude: 35.6823
Longitude: -105.945349
Data source(s): Closed/Inactive State Cleanup Sites(Closed)

Closed Detail

Status: closed
Date : 7/26/1990
Discharge Dt: 12/11/1989
Event: used oil LUST site
Action Taken: soil excavation

Unplottable Summary

Total: 0 Unplottable sites

DB	Company Name/Site Name	Address	City	Zip	ERIS ID

No unplottable records were found that may be relevant for the search criteria.

Unplottable Report

No unplottable records were found that may be relevant for the search criteria.

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ERIS updates databases as set out in ASTM Standard E1527-13 and E1527-21, Section 8.1.8 Sources of Standard Source Information:

"Government information from nongovernmental sources may be considered current if the source updates the information at least every 90 days, or, for information that is updated less frequently than quarterly by the government agency, within 90 days of the date the government agency makes the information available to the public."

Standard Environmental Record Sources

Federal

National Priority List: NPL

The U.S. Environmental Protection Agency (EPA)'s National Priorities List (NPL) includes the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program, based primarily on the score a site receives from EPA's Hazard Ranking System. A site must be on the NPL to receive money from the Superfund Trust Fund for remedial action. This data includes NPL sites represented as polygons, where available, that can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS), and is limited to those sites where the NPL Status reflects the site is 'Currently on the Final NPL (F)' and/or the 'Site is Part of NPL Site (A)'. These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. As site investigation and remediation progress, OUs may be added, modified or refined. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Sep 6, 2025

National Priority List - Proposed: PROPOSED NPL

Sites proposed by the U.S. Environmental Protection Agency (EPA), the state agency, or concerned citizens for addition to the National Priorities List (NPL) due to contamination by hazardous waste and identified by the EPA as a candidate for cleanup because it poses a risk to human health and/or the environment. Sites represented as polygons, where available, can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Sep 6, 2025

Deleted NPL: DELETED NPL

Sites deleted from the U.S. Environmental Protection Agency (EPA)'s National Priorities List (NPL). The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate. Sites represented as polygons, where available, can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Sep 6, 2025

SEMS List 8R Active Site Inventory: SEMS

The U.S. Environmental Protection Agency's (EPA) Superfund Program has deployed the Superfund Enterprise Management System (SEMS), which integrates multiple legacy systems into a comprehensive tracking and reporting tool. This inventory contains active sites evaluated by the Superfund program that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The Active Site Inventory Report displays site and location information at active SEMS sites. An active site is one at which site assessment, removal, remedial, enforcement, cost recovery, or oversight activities are being planned or conducted. This data includes SEMS sites from the List 8R Active file as well as applicable sites from the EPA's Facility Registry Service map tool. This data may also include applicable sites represented as polygons sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS), and is limited to those sites where the NPL Status reflects the site is 'Not on the NPL (N)' , 'Removed from Proposed (R)', and/or 'Pre-Proposal Site (S)'. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Aug 27, 2025

SEMS List 8R Archive Sites: SEMS ARCHIVE

The U.S. Environmental Protection Agency's (EPA) Superfund Enterprise Management System (SEMS) Archived Site Inventory displays site and location information at sites archived from SEMS. An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. This data includes sites from the List 8R Archived site file. This data may also include applicable sites represented as polygons sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS), and is limited to those sites where the NPL Status reflects the site is 'Not on the NPL (N)' , 'Removed from Proposed (R)', and/or 'Pre-Proposal Site (S)'. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Aug 27, 2025

Inventory of Open Dumps, June 1985: ODI

The Resource Conservation and Recovery Act (RCRA) provides for publication of an inventory of open dumps. The Act defines "open dumps" as facilities which do not comply with EPA's "Criteria for Classification of Solid Waste Disposal Facilities and Practices" (40 CFR 257).

Government Publication Date: Jun 1985

EPA Report on the Status of Open Dumps on Indian Lands: IODI

Public Law 103-399, The Indian Lands Open Dump Cleanup Act of 1994, enacted October 22, 1994, identified congressional concerns that solid waste open dump sites located on American Indian or Alaska Native (AI/AN) lands threaten the health and safety of residents of those lands and contiguous areas. The purpose of the Act is to identify the location of open dumps on Indian lands, assess the relative health and environment hazards posed by those sites, and provide financial and technical assistance to Indian tribal governments to close such dumps in compliance with Federal standards and regulations or standards promulgated by Indian Tribal governments or Alaska Native entities.

Government Publication Date: Dec 31, 1998

Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS: CERCLIS

Superfund is a program administered by the United States Environmental Protection Agency (EPA) to locate, investigate, and clean up the worst hazardous waste sites throughout the United States. CERCLIS is a database of potential and confirmed hazardous waste sites at which the EPA Superfund program has some involvement. It contains sites that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The EPA administers the Superfund program in cooperation with individual states and tribal governments; this database is made available by the EPA.

Government Publication Date: Oct 25, 2013

CERCLIS - No Further Remedial Action Planned: CERCLIS NFRAP

An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. The Archive designation means that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL). This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Government Publication Date: Oct 25, 2013

CERCLIS Liens: CERCLIS LIENS

A Federal Superfund lien exists at any property where EPA has incurred Superfund costs to address contamination ("Superfund site") and has provided notice of liability to the property owner. A Federal CERCLA ("Superfund") lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. This database is made available by the United States Environmental Protection Agency (EPA). This database was provided by the United States Environmental Protection Agency (EPA). Refer to SEMS LIEN as the current data source for Superfund Liens.

Government Publication Date: Jan 30, 2014

RCRA CORRACTS-Corrective Action: RCRA CORRACTS

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. At these sites, the Corrective Action Program ensures that cleanups occur. EPA and state regulators work with facilities and communities to design remedies based on the contamination, geology, and anticipated use unique to each site.

Government Publication Date: Sep 1, 2025

RCRA non-CORRACTS TSD Facilities: RCRA TSD

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. This database includes Non-Corrective Action sites that have indicated engagement in the treatment, storage, or disposal of hazardous waste which requires a RCRA hazardous waste permit.

Government Publication Date: Sep 1, 2025

RCRA Generator List: RCRA LQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Large Quantity Generators (LQGs) generate 1,000 kilograms per month or more of hazardous waste or more than one kilogram per month of acutely hazardous waste. This list also includes RCRAInfo sites that have notified as LQGs that do not have a registered Site Manager or Certifier in RCRAInfo.

Government Publication Date: Sep 1, 2025

RCRA Small Quantity Generators List: RCRA SQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Small Quantity Generators (SQGs) generate more than 100 kilograms, but less than 1,000 kilograms, of hazardous waste per month. This list also includes RCRAInfo sites that have notified as SQGs that do not have a registered Site Manager or Certifier in RCRAInfo.

Government Publication Date: Sep 1, 2025

RCRA Very Small Quantity Generators List: RCRA VSQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Very Small Quantity Generators (VSQG) generate 100 kilograms or less per month of hazardous waste, or one kilogram or less per month of acutely hazardous waste. Additionally, VSQG may not accumulate more than 1,000 kilograms of hazardous waste at any time.

Government Publication Date: Sep 1, 2025

RCRA Non-Generators: RCRA NON GEN

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Non-Generators do not presently generate hazardous waste.

Government Publication Date: Sep 1, 2025

RCRA Sites with Controls: RCRA CONTROLS

List of Resource Conservation and Recovery Act (RCRA) facilities with institutional controls in place. RCRA gives the U.S. Environmental Protection Agency (EPA) the authority to control hazardous waste from the "cradle-to-grave." This includes the generation, transportation, treatment, storage, and disposal of hazardous waste. RCRA also set forth a framework for the management of non-hazardous solid wastes. The 1986 amendments to RCRA enabled EPA to address environmental problems that could result from underground tanks storing petroleum and other hazardous substances.

Government Publication Date: Sep 1, 2025

Federal Engineering Controls-ECs: FED ENG

List of Engineering controls (ECs) made availabe by the United States Environmental Protection Agency (EPA). ECs encompass a variety of engineered and constructed physical barriers (e.g., soil capping, sub-surface venting systems, mitigation barriers, fences) to contain and/or prevent exposure to contamination on a property. The EC listing includes remedy component data from Superfund decision documents for applicable sites on the final or deleted on the National Priorities List (NPL); and sites with a Superfund Alternative Approach (SAA) Agreement in place. The only sites included that are not on the NPL; proposed for NPL; or removed from proposed NPL, are those with an SAA Agreement in place.

Government Publication Date: Sep 29, 2025

Federal Institutional Controls- ICs: FED INST

List of Institutional controls (ICs) made available by the United States Environmental Protection Agency (EPA). ICs are non-engineered instruments, such as administrative and legal controls, that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Although it is EPA's expectation that treatment or engineering controls will be used to address principal threat wastes and that groundwater will be returned to its beneficial use whenever practicable, ICs play an important role in site remedies because they reduce exposure to contamination by limiting land or resource use and guide human behavior at a site. The IC listing includes remedy component data from Superfund decision documents for applicable sites on the final or deleted on the National Priorities List (NPL); and sites with a Superfund Alternative Approach (SAA) Agreement in place. The only sites included that are not on the NPL; proposed for NPL; or removed from proposed NPL, are those with an SAA Agreement in place.

Government Publication Date: Sep 29, 2025

Land Use Controls Information System: LUCIS

The Land Use Controls Information System (LUCIS) database is sourced from the U.S. Department of the Navy (DON). This data contains information for former Base Realignment and Closure (BRAC) properties across the United States. DON's BRAC office was tasked with tracking certain base closures while requiring the prevention of risks to human health and the environment of those properties with LUCs in place. Regarding currently available LUC Sites data, the sites listing is limited to centroid point locations for the overall installation property boundaries. Formerly obtained LUC Sites data may reflect site details that applied previously for a BRAC property.

Government Publication Date: Jun 13, 2024

Institutional Control Boundaries at NPL sites: NPL IC

These boundaries of Institutional Control areas at sites on the U.S. Environmental Protection Agency's (EPA) National Priorities List (NPL), or as Proposed or Deleted, are sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). The EPA's NPL includes the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. Institutional controls are non-engineered instruments such as administrative and legal controls that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes.

Government Publication Date: Sep 6, 2025

Emergency Response Notification System: ERNS 1982 TO 1986

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1982-1986

Emergency Response Notification System: ERNS 1987 TO 1989

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1987-1989

Emergency Response Notification System: ERNS

Database of oil and hazardous substances spill reports made available by the United States Coast Guard National Response Center (NRC). The NRC fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. These data contain initial incident data that has not been validated or investigated by a federal/state response agency.

Government Publication Date: Sep 7, 2025

The Assessment, Cleanup and Redevelopment Exchange System (ACRES) Brownfield Database: FED BROWNFIELDS

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties protects the environment, reduces blight, and takes development pressures off greenspaces and working lands. This data is provided by the United States Environmental Protection Agency (EPA) and includes Brownfield sites from the Cleanups in My Community (CIMC) web application.

Government Publication Date: Sep 8, 2025

FEMA Underground Storage Tank Listing: FEMA UST

The Federal Emergency Management Agency (FEMA) of the Department of Homeland Security maintains a list of FEMA owned underground storage tanks.

Government Publication Date: Dec 31, 2017

Facility Response Plan: FRP

This listing contains facilities that have submitted Facility Response Plans (FRPs) to the U.S. Environmental Protection Agency (EPA). Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit FRPs. Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments. The list includes FRP facilities sourced from the EPA FOIA office and from previously available Homeland Infrastructure Foundation-Level Data (HIFLD) file/s. Disclaimer: Per the EPA FOIA Office, the verification process for current requested FRP data is undergoing review and revision, and any similar reporting will be made public in Fiscal Year 2026. For this reason, the latest available FOIA file may be incomplete.

Government Publication Date: Jun 1, 2025

Delisted Facility Response Plans: DELISTED FRP

Facilities that once appeared in - and have since been removed from - the list of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Jun 1, 2025

Historical Gas Stations: HIST GAS STATIONS

This historic directory of service stations is provided by the Cities Service Company. The directory includes Cities Service filling stations that were located throughout the United States in 1930.

Government Publication Date: Jul 1, 1930

Petroleum Refineries: REFN

This list of petroleum refineries is sourced from the U.S. Energy Information Administration (EIA), Refinery Capacity Report. The listing includes operating and idle petroleum refineries (including new refineries under construction) and refineries shut down during the previous year. The geographic area the report covers is the 50 States, the District of Columbia, Puerto Rico, the U.S. Virgin Islands, Guam, and other U.S. possessions. Per the EIA, the facility location data represents the approximate location based on research of publicly available information from sources such as Federal agencies, company websites, and satellite images on public websites.

Government Publication Date: Oct 31, 2024

Petroleum Product and Crude Oil Rail Terminals: BULK TERMINAL

A list of petroleum product and crude oil rail terminals from the U.S. Energy Information Administration (EIA), as well as petroleum terminals sourced from Oak Ridge National Laboratory hosted by the Homeland Infrastructure Foundation-Level Database. Data includes operable bulk petroleum product terminals with a total bulk shell storage capacity of 50,000 barrels or more, and/or the ability to receive volumes from tanker, barge, or pipeline; also rail terminals handling the loading and unloading of crude oil with activity between 2017 and 2018. EIA petroleum product terminal data comes from the EIA-815 Bulk Terminal and Blender Report, which includes working, shell in operation, and shell idle for several major product groupings.

Government Publication Date: Jun 5, 2025

LIEN on Property: SEMS LIEN

The U.S. Environmental Protection Agency's (EPA) Superfund Enterprise Management System (SEMS) provides Lien details on applicable properties, such as the Superfund lien on property activity, the lien property information, and the parties associated with the lien.

Government Publication Date: Aug 27, 2025

Superfund Decision Documents: SUPERFUND ROD

This database contains a list of decision documents for Superfund sites. Decision documents serve to provide the reasoning for the choice of (or) changes to a Superfund Site cleanup plan. The decision documents include completed Records of Decision (ROD), ROD Amendments, Explanations of Significant Differences (ESD) for active and archived sites stored in the Superfund Enterprise Management System (SEMS), along with other associated memos and files. This information is maintained and made available by the U.S. Environmental Protection Agency.

Government Publication Date: Oct 30, 2025

State

State Cleanup Sites Listing: SCS

List of active and closed State Clean Up Sites made available by the Ground Water Quality Bureau's Remediation Oversight Section of the New Mexico Environment Department (NMED). The Remediation Oversight Section encourages and oversees voluntary efforts to clean up contaminated sites, and administers the Water Quality Control Commission Regulations that require responsible parties to clean up contaminated soil and ground water. This database serves a purpose similar to that of the federal Superfund Enterprise Management System (SEMS), functioning as a state-level counterpart for tracking potential hazardous substance release sites.

Government Publication Date: Feb 4, 2025

Delisted State Cleanup Sites: DELISTED SCS

List of sites removed from State Clean Up Sites made available by the Ground Water Quality Bureau's Remediation Oversight Section of the New Mexico Environment Department (NMED).

Government Publication Date: Feb 4, 2025

Solid Waste Facilities: SWF/LF

List of currently or formerly permitted/registered facilities in New Mexico, including haulers, landfills, transfer stations, collection centers, generators, recycling facilities, and composting facilities. This list includes facilities that are currently open and reporting as well as facilities that are closed but previously held a permit. This list is made available by the New Mexico Environment Department (NMED)'s Solid Waste Bureau.

Government Publication Date: Oct 23, 2025

Historical Solid Waste Landfills: HIST LF

List of historical landfill sites provided by the New Mexico Environment Department (NMED) Solid Waste Bureau, and sites from the Bureau of Land Management which were closed prior to 1984. Public Land Survey System (PLSS) locations provided by the source are subject to accuracy limitations inherent to the PLSS system.

Government Publication Date: Aug 21, 2014

Recycling Centers: RECYCLING

List of registered and other recycling centers made available by the New Mexico Environment Department's (NMED) Solid Waste Bureau.

Government Publication Date: Nov 6, 2025

Leaking Petroleum Storage Tanks: LST

This list of Leaking Petroleum Storage Tank sites is made available by the New Mexico Environment Department's (NMED) Petroleum Storage Tank Bureau (PSTB). Includes records from PSTB listings, and records from the NMED Open Map Portal.

Government Publication Date: Sep 16, 2025

Delisted Active and No Further Action Leaking Tanks: DELISTED LST

This database contains a list of leaking storage tank sites that were removed from the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau.

Government Publication Date: Sep 16, 2025

Leaking Underground Storage Tanks: LUST HIST

Historical list of leaking underground leaking tanks provided by the New Mexico Environment Department (NMED). This list was last updated in August of 2006.

Government Publication Date: Aug 1, 2006

Underground Storage Tanks: UST

List of Underground Storage Tank sites made available by the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau (PSTB). Includes Underground Storage Tank Facilities from the NMED Open Data Portal.

Government Publication Date: Nov 3, 2025

Aboveground Storage Tanks: AST

List of Aboveground Storage Tank sites made available by the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau (PSTB). Includes Aboveground Storage Tank Facilities from the NMED Open Data Portal.

Government Publication Date: Nov 3, 2025

Petroleum Storage Tanks: TANKS

List of Storage Tank Sites made available by the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau. Includes sites with underground and aboveground tanks.

Government Publication Date: Jul 9, 2019

Underground Storage Tanks - Historical: UST HIST

Historical listing of underground storage tanks registered with the New Mexico Environment Department (NMED). This data was last updated in August 2006.

Government Publication Date: Aug 1, 2006

Aboveground Storage Tanks - Historical: AST HIST

Historical listing of aboveground storage tank facilities registered with the New Mexico Environment Department (NMED. This data was last updated in August 2006.

Government Publication Date: Aug 4, 2006

Delisted Tanks: DELISTED TANK

List of Storage Tank Sites removed from the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau's list of underground and aboveground tanks.

Government Publication Date: Nov 3, 2025

Sites with Institutional and Engineering Controls: INST

List of sites in the New Mexico Environment Department (NMED)'s Public Record of Voluntary Remediation Program (VRP) Sites with institutional and/or engineering controls.

Government Publication Date: Sep 30, 2025

Voluntary Remediation Program Sites: VCP

Public Record of Voluntary Remediation Program (VRP) Sites made available by the New Mexico Environment Department (NMED). New Mexico's Voluntary Remediation Program (VRP) provides incentives for the voluntary cleanup of contaminated properties and encourages their redevelopment. VRP participants that complete the program successfully will receive site closure documentation from the NMED including a Certificate of Completion or Conditional Certificate of Completion.

Government Publication Date: Sep 30, 2025

Targeted Brownfields Assessment Sites: BROWNFIELDS

List of Targeted Brownfields Assessment Sites made available by the New Mexico Environment Department (NMED). Brownfields are properties whose redevelopment is complicated by the presence or potential presence of hazardous substances or petroleum products. NMED provides no-cost environmental assessments of brownfield sites to local or tribal governments. NMED also manages a Brownfields Revolving Loan Fund providing low-interest loans for brownfield cleanups where redevelopment is planned.

Government Publication Date: Sep 30, 2025

Tribal

Leaking Underground Storage Tanks on Tribal/Indian Lands: INDIAN LUST

This list of leaking underground storage tanks (LUSTs) on Tribal/Indian Lands in Region 6, which includes New Mexico, is provided by the United States Environmental Protection Agency (EPA).

Government Publication Date: Apr 21, 2025

Underground Storage Tanks on Tribal/Indian Lands: INDIAN UST

This list of underground storage tanks (USTs) on Tribal/Indian Lands in Region 6, which includes New Mexico, is provided by the United States Environmental Protection Agency (EPA).

Government Publication Date: Apr 21, 2025

Delisted Tribal Leaking Storage Tanks: DELISTED INDIAN LST

Leaking Underground Storage Tank (LUST) facilities which once appeared on - and have since been removed from - the Regional Tribal/Indian LUST lists made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: May 22, 2025

Delisted Tribal Underground Storage Tanks: DELISTED INDIAN UST

Underground Storage Tank (UST) facilities which once appeared on - and have since been removed from - the Regional Tribal/Indian UST lists made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: May 22, 2025

County

No County databases were selected to be included in the search.

Additional Environmental Record Sources

Federal

PFAS Greenhouse Gas Emissions Data: PFAS GHG

The U.S. Environmental Protection Agency's (EPA) Greenhouse Gas Reporting Program (GHGRP) collects Greenhouse Gas (GHG) data from large emitting facilities (25,000 metric tons of carbon dioxide equivalent (CO2e) per year), and suppliers of fossil fuels and industrial gases that results in GHG emissions when used. This dataset is sourced from the EPA's PFAS Analytic Tools, and it includes GHG emissions data for facilities that emit or have emitted since 2010 chemicals identified as PFAS based on EPA's CompTox Chemicals Dashboard lists of PFAS with defined and undefined structures. PFAS emissions data has been identified for facilities engaged in the following industrial processes: Aluminum Production (GHGRP Subpart F), HCFC-22 Production and HFC-23 Destruction (Subpart O), Electronics Manufacturing (Subpart I), Fluorinated Gas Production (Subpart L), Magnesium Production (Subpart T), Electrical Transmission and Distribution Equipment Use (Subpart DD), and Manufacture of Electric Transmission and Distribution Equipment (Subpart SS). Over time, other industrial processes with required GHGRP reporting may include PFAS emissions data and the list of reportable gases may change over time. Note that some regulatory programs have specified chemical structure requirements that define PFAS differently than the lists in EPA's CompTox Chemicals Dashboard.

Government Publication Date: Oct 7, 2025

On-Scene Coordinator Response Sites: OSC RESPONSE

This list of On-Scene Coordinator (OSC) Response Sites is provided by the U.S. Environmental Protection Agency (EPA). OSCs are the federal officials responsible for monitoring or directing responses to all oil spills and hazardous substance releases reported to the federal government. OSCs coordinate all federal efforts with, and provide support and information to local, state, and regional response communities. An OSC is an agent of either EPA or the U.S. Coast Guard (USCG), depending on where the incident occurs. EPA's OSCs have primary responsibility for spills and releases to inland areas and waters. USCG OSCs have responsibility for coastal waters and the Great Lakes. In general, an OSC has the following key responsibilities during and after a response: Assessment, Monitoring, Response Assistance, and Evaluation.

Government Publication Date: Oct 8, 2025

Facility Registry Service/Facility Index: FINDS/FRS

The Facility Registry Service (FRS) is a centrally managed database that identifies facilities, sites, or places subject to environmental regulations or of environmental interest. FRS creates high-quality, accurate, and authoritative facility identification records through rigorous verification and management procedures that incorporate information from program national systems, state master facility records, and data collected from EPA's Central Data Exchange registrations and data management personnel. This list is made available by the U.S. Environmental Protection Agency (EPA).

Government Publication Date: Oct 10, 2025

Toxics Release Inventory (TRI) Program: TRIS

The U.S. Environmental Protection Agency's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of toxic chemicals from U.S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment. There are currently 770 individually listed chemicals and 33 chemical categories covered by the TRI Program. Facilities that manufacture, process or otherwise use these chemicals in amounts above established levels must submit annual reporting forms for each chemical. Note that the TRI chemical list does not include all toxic chemicals used in the U.S. One of TRI's primary purposes is to inform communities about toxic chemical releases to the environment. This database includes TRI Reporting Data for calendar years 1987 through 2021 and Preliminary Data for 2022.

Government Publication Date: Sep 20, 2023

PFOA/PFOS Contaminated Sites: PFAS NPL

This list of Superfund Sites with Per- and Polyfluoroalkyl Substances (PFAS) detections is made available by the U.S. Environmental Protection Agency (EPA) in their PFAS Analytic Tools data, previously the list was obtained by EPA FOIA requests. EPA's Office of Land and Emergency Management and EPA Regional Offices maintain what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment. Limitations: Detections of PFAS at National Priorities List (NPL) sites do not mean that people are at risk from PFAS, are exposed to PFAS, or that the site is the source of the PFAS. The information in the Superfund NPL and Superfund Alternative Agreement (SAA) PFAS detection site list is years old and may not be accurate today. Site information such as site name, site ID, and location has been confirmed for accuracy; however, PFAS-related information such as media sampled, drinking water being above the health advisory, or mitigation efforts has not been verified. For Federal Facilities data, the other Federal agencies (OFA) are the lead agency for their data and provided them to EPA.

Government Publication Date: Sep 26, 2025

Federal Agency Locations with Known or Suspected PFAS Detections: PFAS FED SITES

This list of federal agency locations with known or suspected detections of Per- and Polyfluoroalkyl Substances (PFAS) is made available by the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools data. The EPA outlines that these data are gathered from several federal entities, such as the federal Superfund program, Department of Defense (DOD), National Aeronautics and Space Administration (NASA), Department of Transportation (DOT), and Department of Energy (DOE). The dates this data was extracted for the PFAS Analytic Tools range from 2022 to 2025 per agency entity dataset. Sites on this list do not necessarily reflect the source/s of PFAS contamination and detections do not indicate level of risk or human exposure at the site. Agricultural notifications in this data are limited to DOD sites only. At this time, the EPA is aware that this list is not comprehensive of all Federal agencies.

Government Publication Date: May 30, 2025

SSEHRI PFAS Contamination Sites: PFAS SSEHRI

This PFAS Contamination Site Tracker database is compiled by the PFAS Project Lab, part of the Social Science Environmental Health Research Institute (SSEHRI) at Northeastern University. According to the SSEHRI, the database records qualitative and quantitative data from each known site of PFAS contamination, including timeline of discovery, sources, levels, health impacts, community response, and government response. The goal of this database is to compile information and support public understanding of the rapidly unfolding issue of PFAS contamination. All data presented was extracted from government websites, news articles, or publicly available documents. Locations for the Known PFAS Contamination Sites are sourced from the PFAS Sites and Community Resources Map by the PFAS-REACH team, credited to PFAS Project Lab, Silent Spring Institute, and PFAS Exchange. Disclaimer: The source conveys the data undergoes regular updates as new information becomes available, some sites may be missing and/or contain information that is incorrect or outdated, as well as their information represents all contamination sites SSEHRI is aware of, not all possible contamination sites. This data is not intended to be used for legal purposes. Access the following source link for the most current information: https://pfasproject.com/pfas-sites-and-community-resources/

Government Publication Date: Aug 1, 2025

National Response Center PFAS Spills: PFAS ERNS

This Per- and Poly-Fluoroalkyl Substances (PFAS) Spills dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The National Response Center (NRC), operated by the U.S. Coast Guard, is the designated federal point of contact for reporting all oil, chemical, and other discharges into the environment, for the United States and its territories. This dataset contains NRC spill information from 1990 to the present that is restricted to records associated with PFAS and PFAS-containing materials. Incidents are filtered to include only records with a "Material Involved" or "Incident Description" related to Aqueous Film Forming Foam (AFFF). The keywords used to filter the data included "AFFF," "Fire Fighting Foam," "Aqueous Film Forming Foam," "Fire Suppressant Foam, "PFAS," "PERFL," "PFOA," "PFOS," and "Genx." Limitations: The data from the NRC website contains initial incident data that has not been validated or investigated by a federal/state response agency. Keyword searches may misidentify some incident reports that do not contain PFAS. This dataset should also not be considered to be exhaustive of all PFAS spills/release incidents.

Government Publication Date: Dec 1, 2025

PFAS NPDES Discharge Monitoring: PFAS NPDES

This list of National Pollutant Discharge Elimination System (NPDES) permitted facilities with required monitoring for Per- and Polyfluoroalkyl (PFAS) Substances is made available via the U.S. Environmental Protection Agency (EPA)'s PFAS Analytic Tools. Any point-source wastewater discharger to waters of the United States must have a NPDES permit, which defines a set of parameters for pollutants and monitoring to ensure that the discharge does not degrade water quality or impair human health. This list includes NPDES permitted facilities associated with permits that monitor for Per- and Polyfluoroalkyl Substances (PFAS), limited to the years 2007 - present. EPA further advises the following regarding these data: currently, fewer than half of states have required PFAS monitoring for at least one of their permittees, and fewer states have established PFAS effluent limits for permittees. For states that may have required monitoring, some reporting and data transfer issues may exist on a state-by-state basis.

Government Publication Date: Dec 16, 2024

Perfluorinated Alkyl Substances (PFAS) from Toxic Release Inventory: PFAS TRI

List of Toxics Release Inventory (TRI) facilities at which the reported chemical is a per- or polyfluoroalkyl (PFAS) substance included in the U.S. Environmental Protection Agency's (EPA) consolidated PFAS Master List of PFAS Substances. Encompasses Toxics Release Inventory records included in the EPA PFAS Analytic Tools. The EPA's TRI database currently tracks information on disposal or releases of 770 individually listed toxic chemicals and 33 chemical categories from thousands of U.S. facilities and details about how facilities manage those chemicals through recycling, energy recovery, and treatment. This listing includes TRI Reporting Data for calendar years 1987 through 2021 and Preliminary Data for 2022.

Government Publication Date: Sep 20, 2023

PFAS Water Quality Portal Sampling Data: PFAS WATER

This Per- and Poly-Fluoroalkyl Substances (PFAS) Environmental Media Sampling Data is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The Water Quality Portal (WQP), as a cooperative service sponsored by the United States Geological Survey, the EPA, and the National Water Quality Monitoring Council, is part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations, and individuals submit project details and sampling results to this public repository. Limitations: EPA did not carry out the sampling or testing of a majority of the data in the WQP PFAS dataset. EPA can only speak to the accuracy and completeness of the data from projects like the National Aquatic Resource Surveys for which EPA is the data owner/organization. Data may exist within the file on Quality Assurance Project Plans (QAPPs) and the approving agency of the QAPP, if a QAPP is entered.

Government Publication Date: Jul 21, 2025

PFAS TSCA Manufacture and Import Facilities: PFAS TSCA

The U.S. Environmental Protection Agency (EPA) issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. This list is specific only to TSCA Manufacture and Import Facilities with reported per- and poly-fluoroalkyl (PFAS) substances. Data file is sourced from EPA's PFAS Analytic Tools TSCA dataset which includes CDR/Inventory Update Reporting data from 1998 up to 2020. Disclaimer: This data file includes production and importation data for chemicals identified in EPA's CompTox Chemicals Dashboard list of PFAS without explicit structures and list of PFAS structures in DSSTox. Note that some regulations have specific chemical structure requirements that define PFAS differently than the lists in EPA's CompTox Chemicals Dashboard. Reporting information on manufactured or imported chemical substance amounts should not be compared between facilities, as some companies claim Chemical Data Reporting Rule data fields for PFAS information as Confidential Business Information.

Government Publication Date: Jan 5, 2023

PFAS Waste Transfers from RCRA e-Manifest: PFAS E-MANIFEST

This Per- and Poly-Fluoroalkyl Substances (PFAS) Waste Transfers dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. Every shipment of hazardous waste in the U.S. must be accompanied by a shipment manifest, which is a critical component of the cradle-to-grave tracking of wastes mandated by the Resource Conservation and Recovery Act (RCRA). According to the EPA, currently no Federal Waste Code exists for any PFAS compounds. To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: • PFAS • PFOA • PFOS • PERFL • AFFF • GENX • GEN-X (plus the Vermont state-specific waste codes). Limitations: Amount or concentration of PFAS being transferred cannot be determined from the manifest information. Keyword searches may misidentify some manifest records that do not contain PFAS. This dataset should also not be considered to be exhaustive of all PFAS waste transfers.

Government Publication Date: Oct 4, 2025

PFAS Industry Sectors: PFAS IND

This Per- and Poly-Fluoroalkyl Substances (PFAS) Industry Sectors dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The EPA developed the dataset from various sources that show which industries may be handling PFAS including: EPA's Enforcement and Compliance History Online (ECHO) records restricted to potential PFAS-handling industry sectors; ECHO records for Fire Training Sites identified where fire-fighting foam may have been used in training exercises; and 14 CFR Part 139 Airports compiled from historic and current records from the FAA Airport Data and Information Portal. Since July 2006, all certificated Part 139 Airports are required to have fire-fighting foam onsite that meet certain military specifications, which to date have been fluorinated (Aqueous Film Forming Foam). Limitations: Inclusion in this dataset does not indicate that PFAS are being manufactured, processed, used, or released by the facility. Listed facilities potentially handle PFAS based on their industrial profile, but are unconfirmed by the EPA. Keyword searches in ECHO for Fire Training sites may misidentify some facilities and should not be considered to be an exhaustive list of fire training facilities in the U.S.

Government Publication Date: Sep 1, 2025

Hazardous Materials Information Reporting System: HMIRS

The Hazardous Materials Incident Reporting System (HMIRS) database contains unintentional hazardous materials release information reported to the U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration.

Government Publication Date: May 28, 2025

National Clandestine Drug Labs: NCDL

The U.S. Department of Justice ("the Department"), Drug Enforcement Administration (DEA), provides this data as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy.

Government Publication Date: Nov 30, 2023

Toxic Substances Control Act: TSCA

The U.S. Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule. The CDR enables EPA to collect and publish information on the manufacturing, processing, and use of commercial chemical substances and mixtures (referred to hereafter as chemical substances) on the TSCA Chemical Substance Inventory (TSCA Inventory). This includes current information on chemical substance production volumes, manufacturing sites, and how the chemical substances are used. This information helps the Agency determine whether people or the environment are potentially exposed to reported chemical substances. EPA publishes submitted CDR data that is not Confidential Business Information (CBI). EPA CDR collections occur approximately every four years and reporting requirements change per collection.

Government Publication Date: May 12, 2022

Hist TSCA: HIST TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.
The 2006 IUR data summary report includes information about chemicals manufactured or imported in quantities of 25,000 pounds or more at a single site during calendar year 2005. In addition to the basic manufacturing information collected in previous reporting cycles, the 2006 cycle is the first time EPA collected information to characterize exposure during manufacturing, processing and use of organic chemicals. The 2006 cycle also is the first time manufacturers of inorganic chemicals were required to report basic manufacturing information.

Government Publication Date: Dec 31, 2006

FTTS Administrative Case Listing: FTTS ADMIN

An administrative case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

FTTS Inspection Case Listing: FTTS INSP

An inspection case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

Potentially Responsible Parties List: PRP

Early in the site cleanup process, the U.S. Environmental Protection Agency (EPA) conducts a search to find the Potentially Responsible Parties (PRPs). The EPA looks for evidence to determine liability by matching wastes found at the site with parties that may have contributed wastes to the site. This listing contains PRPs, Noticed Parties, at sites in the EPA's Superfund Enterprise Management System (SEMS).

Government Publication Date: Sep 29, 2025

State Coalition for Remediation of Drycleaners Listing: SCRD DRYCLEANER

The State Coalition for Remediation of Drycleaners (SCRD) was established in 1998, with support from the U.S. Environmental Protection Agency (EPA) Office of Superfund Remediation and Technology Innovation. Coalition members are states with mandated programs and funding for drycleaner site remediation. Current members are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin. Since 2017, the SCRD no longer maintains this data, refer to applicable state source data where available.

Government Publication Date: Nov 08, 2017

Integrated Compliance Information System (ICIS): ICIS

The Integrated Compliance Information System (ICIS) database contains integrated enforcement and compliance information across most of U.S. Environmental Protection Agency's (EPA) programs. The vision for ICIS is to replace EPA's independent databases that contain enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions and a subset of the Permit Compliance System (PCS), which supports the National Pollutant Discharge Elimination System (NPDES). This information is maintained by the EPA Headquarters and at the Regional offices. A future release of ICIS will completely replace PCS and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities that support compliance and enforcement programs, including incident tracking, compliance assistance, and compliance monitoring.

Government Publication Date: May 3, 2025

Drycleaner Facilities: FED DRYCLEANERS

A list of drycleaner facilities from Enforcement and Compliance History Online (ECHO) data as made available by the U.S. Environmental Protection Agency (EPA), sourced from the ECHO Exporter file. This EPA source file tracks facilities that possess NAICS and SIC codes that classify businesses as drycleaner establishments.

Government Publication Date: Jul 19, 2025

Delisted Drycleaner Facilities: DELISTED FED DRY

List of sites which once appeared on - and have since been removed from - the list of drycleaner facilities included in Enforcement and Compliance History Online (ECHO) data as made available by the U.S. Environmental Protection Agency (EPA), sourced from the ECHO Exporter file. This EPA source file tracks facilities that possess NAICS and SIC codes that classify businesses as drycleaner establishments.

Government Publication Date: Jul 19, 2025

Formerly Used Defense Sites: FUDS

Formerly Used Defense Sites (FUDS) are properties that were formerly owned by, leased to, or otherwise possessed by and under the jurisdiction of the Secretary of Defense prior to October 1986, where the Department of Defense (DOD) is responsible for an environmental restoration. The FUDS Annual Report to Congress (ARC) is published by the U.S. Army Corps of Engineers (USACE). This data is compiled from the USACE's Geospatial FUDS data layers and Homeland Infrastructure Foundation-Level Data (HIFLD) FUDS dataset which applies to the Fiscal Year 2021 FUDS Inventory.

Government Publication Date: May 15, 2023

FUDS Munitions Response Sites: FUDS MRS

Boundaries of Munitions Response Sites (MRS), published with the Formerly Used Defense Sites (FUDS) Annual Report to Congress (ARC) by the U.S. Army Corps of Engineers (USACE). An MRS is a discrete location within a Munitions response area (MRA) that is known to require a munitions response. An MRA means any area on a defense site that is known or suspected to contain unexploded ordnance (UXO), discarded military munitions (DMM), or munitions constituents (MC). This data is compiled from the USACE's Geospatial MRS data layers and Homeland Infrastructure Foundation-Level Data (HIFLD) MRS dataset.

Government Publication Date: May 15, 2023

Former Military Nike Missile Sites: FORMER NIKE

This information was taken from report DRXTH-AS-IA-83A016 (Historical Overview of the Nike Missile System, 12/1984) which was performed by Environmental Science and Engineering, Inc. for the U.S. Army Toxic and Hazardous Materials Agency Assessment Division. The Nike system was deployed between 1954 and the mid-1970's. Among the substances used or stored on Nike sites were liquid missile fuel (JP-4); starter fluids (UDKH, aniline, and furfuryl alcohol); oxidizer (IRFNA); hydrocarbons (motor oil, hydraulic fluid, diesel fuel, gasoline, heating oil); solvents (carbon tetrachloride, trichloroethylene, trichloroethane, stoddard solvent); and battery electrolyte. The quantities of material a disposed of and procedures for disposal are not documented in published reports. Virtually all information concerning the potential for contamination at Nike sites is confined to personnel who were assigned to Nike sites. During deactivation most hardware was shipped to depot-level supply points. There were reportedly instances where excess materials were disposed of on or near the site itself at closure. There was reportedly no routine site decontamination.

Government Publication Date: Dec 2, 1984

PHMSA Pipeline Safety Flagged Incidents: PIPELINE INCIDENT

This list of flagged pipeline incidents is made available by the U.S. Department of Transportation (US DOT) Pipeline and Hazardous Materials Safety Administration (PHMSA). PHMSA regulations require incident and accident reports for five different pipeline system types. Accidents reported on hazardous liquid gravity lines (§195.13) and reporting-regulated-only hazardous liquid gathering lines (§195.15) and incidents reported on Type R gas gathering (§192.8(c)) are not included in the flagged incident file data.

Government Publication Date: Jul 10, 2025

Material Licensing Tracking System (MLTS): MLTS

A list of sites that store radioactive material subject to the Nuclear Regulatory Commission (NRC) licensing requirements. This list is maintained by the NRC. As of September 2016, the NRC no longer releases location information for sites. Site locations were last received in July 2016.

Government Publication Date: May 11, 2021

Historic Material Licensing Tracking System (MLTS) sites: HIST MLTS

A historic list of sites that have inactive licenses and/or removed from the Material Licensing Tracking System (MLTS). In some cases, a site is removed from the MLTS when the state becomes an "Agreement State". An Agreement State is a State that has signed an agreement with the Nuclear Regulatory Commission (NRC) authorizing the State to regulate certain uses of radioactive materials within the State.

Government Publication Date: Jan 31, 2010

Mines Master Index File: MINES

The Master Index File (MIF) is provided by the United States Department of Labor, Mine Safety and Health Administration (MSHA). This file, which was originally created in the 1970's, contained many Mine-IDs that were invalid. MSHA removes invalid IDs from the MIF upon discovery. MSHA applicable data includes the following: all Coal and Metal/Non-Metal mines under MSHA's jurisdiction since 1/1/1970; mine addresses for all mines in the database except for Abandoned mines prior to 1998 from MSHA's legacy system (addresses may or may not correspond with the physical location of the mine itself); violations that have been assessed penalties as a result of MSHA inspections beginning on 1/1/2000; and violations issued as a result of MSHA inspections conducted beginning on 1/1/2000.

Government Publication Date: Aug 8, 2025

Surface Mining Control and Reclamation Act Sites: SMCRA

This inventory of land and water impacted by past mining (primarily legacy coal mining operations) is maintained by the U.S. Department of the Interior's Office of Surface Mining Reclamation and Enforcement (OSMRE), as it provides information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). This inventory contains information on the type and extent of Abandoned Mine Land (AML) Problems, as well as information on the cost associated with the reclamation of those problems. The data is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed. Disclaimer: Per the OSMRE, States and tribes who enter their data into e-AMLIS (AML Inventory System) may truncate their latitude and longitude so the precise location of usually dangerous AMLs is not revealed in an effort to protect the public from searching for these AMLs, most of which are on private property. If more precise location information is needed, please contact the applicable state/tribe of interest.

Government Publication Date: Oct 30, 2025

Mineral Resource Data System: MRDS

The Mineral Resource Data System (MRDS) is a collection of reports describing metallic and nonmetallic mineral resources throughout the world. Included are deposit name, location, commodity, deposit description, geologic characteristics, production, reserves, resources, and references. This database contains the records previously provided in the Mineral Resource Data System (MRDS) of USGS and the Mineral Availability System/Mineral Industry Locator System (MAS/MILS) originated in the U.S. Bureau of Mines, which is now part of USGS. The USGS has ceased systematic updates of the MRDS database with their focus more recently on deposits of critical minerals while providing a well-documented baseline of historical mine locations from USGS topographic maps.

Government Publication Date: Mar 15, 2016

DOE Legacy Management Sites: LM SITES

The U.S. Department of Energy (DOE) Office of Legacy Management (LM) currently manages radioactive and chemical waste, environmental contamination, and hazardous material at over 100 sites across the U.S. The LM manages sites with diverse regulatory drivers (statutes or programs that direct cleanup and management requirements at DOE sites) or as part of internal DOE or congressionally-recognized programs, such as but not limited to: Formerly Utilized Sites Remedial Action Program (FUSRAP), Uranium Mill Tailings Radiation Control Act (UMTRCA Title I, Tile II), Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), Resource Conservation and Recovery Act (RCRA), Decontamination and Decommissioning (D&D), Nuclear Waste Policy Act (NWPA). The intent of the site location is to provide a general reference point to the site on a national scale. The coordinates of each site point can be the location of a site monument, the centroid of the site boundary, or a general location of the site. This site listing includes data exported from the DOE Office of LM's Geospatial Environmental Mapping System (GEMS). GEMS Data disclaimer: The DOE Office of LM makes no representation or warranty, expressed or implied, regarding the use, accuracy, availability, or completeness of the data presented herein.

Government Publication Date: Nov 6, 2025

Alternative Fueling Stations: ALT FUELS

This list of alternative fueling stations is sourced from the Alternative Fuels Data Center (AFDC). The U.S. Department of Energy's Office of Energy Efficiency & Renewable Energy launched the AFDC in 1991 as a repository for alternative fuel vehicle performance data, which provides a wealth of information and data on alternative and renewable fuels, advanced vehicles, fuel-saving strategies, and emerging transportation technologies. The data includes Biodiesel (B20 and above), Compressed Natural Gas (CNG), Electric, Ethanol (E85), Hydrogen, Liquefied Natural Gas (LNG), Propane (LPG), and Renewable Diesel (R20 and above) fuel type locations.

Government Publication Date: Aug 1, 2025

Superfunds Consent Decrees: CONSENT DECREES

This list of Superfund consent decrees is provided by the Department of Justice, Environment & Natural Resources Division (ENRD) through a Freedom of Information Act (FOIA) applicable file. This listing includes Cases filed since 2010 limited to the following: Consent Decrees for CERCLA or Superfund Sites filed and/or as proposed within the ENRD's Case Management System (CMS); and applicable ENRD's Environmental Defense Section (EDS) CERCLA Cases with "Consent" in History Note. CMS may not reflect the latest developments in a case, nor can the agency guarantee the accuracy of the data. ENRD Disclaimer: Congress excluded three discrete categories of law enforcement and national security records from the requirements of the FOIA; response is limited to those records that are subject to the requirements of the FOIA; however, this should not be taken as an indication that excluded records do, or do not, exist.

Government Publication Date: Jun 26, 2024

Air Facility System: AFS

This EPA retired Air Facility System (AFS) dataset contains emissions, compliance, and enforcement data on stationary sources of air pollution. Regulated sources cover a wide spectrum; from large industrial facilities to relatively small operations such as dry cleaners. AFS does not contain data on facilities that are solely asbestos demolition and/or renovation contractors, or landfills. ECHO Clean Air Act data from AFS are frozen and reflect data as of October 17, 2014; the EPA retired this system for Clean Air Act stationary sources and transitioned to ICIS-Air.

Government Publication Date: Oct 17, 2014

Registered Pesticide Establishments: SSTS

This national list of active EPA-registered foreign and domestic pesticide and/or device-producing establishments is based on data from the Section Seven Tracking System (SSTS). The Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) Section 7 requires that each producing establishment must place its EPA establishment number on the label or immediate container of each pesticide, active ingredient or device produced. An EPA establishment number on a pesticide product label identifies the EPA registered location where the product was produced. The list of establishments is made available by the U.S. Environmental Protection Agency (EPA).

Government Publication Date: Sep 26, 2025

Polychlorinated Biphenyl (PCB) Transformers: PCBT

Locations of Transformers Containing Polychlorinated Biphenyls (PCBs) registered with the United States Environmental Protection Agency. PCB transformer owners must register their transformer(s) with EPA. Although not required, PCB transformer owners who have removed and properly disposed of a registered PCB transformer may notify EPA to have their PCB transformer de-registered. Data made available by EPA.

Government Publication Date: Oct 15, 2019

Polychlorinated Biphenyl (PCB) Notifiers: PCB

Facilities included in the national list of facilities that have notified the United States Environmental Protection Agency (EPA) of Polychlorinated Biphenyl (PCB) activities. Any company or person storing, transporting or disposing of PCBs or conducting PCB research and development must notify the EPA and receive an identification number.

Government Publication Date: May 23, 2024

Power Plants: POWER PLANTS

This list of power plants is provided by the U.S. Energy Information Administration (EIA). The listing includes operable electric generating plants in the United States by energy source, originating from the EIA-860, Annual Electric Generator Report; EIA-860M, Monthly Update to the Annual Electric Generator Report; and EIA-923, Power Plant Operations Report. It includes all operable plants by energy source with a combined nameplate capacity of 1 megawatt or more that are operating, are on standby, or out of service for short- or long-term.

Government Publication Date: Jun 5, 2025

Historical Business Activity Risk: HIST RISK

Proprietary list of sites identified as potentially having engaged in business activity that poses a higher-than-normal risk of contamination. Records originate from historical city directories, and are included in this list based on broad business categories Potentially Hazardous Chemical Users and Fuel and Automotive, including but not limited to Dry Cleaners and Fuel Stations, Garages, etc. Inclusion in this listing does not indicate that there is or ever has been contamination; rather, sites are included in this list due to their potential for having engaged in a business activity presenting an elevated risk of contamination. The list was compiled from various city directories including Polks, Millers, Mullin Kille, Interstate Directory, and State Directory Co; spanning roughly 1920s through 1960 depending on information available by city.

Government Publication Date: Jan 1, 1960

State

Hazardous Waste Facilities: HAZ

List of hazardous waste generators and treatment, storage, and disposal facilities overseen by the Hazardous Waste Bureau (HWB), New Mexico Environment Department (NMED).

Government Publication Date: Apr 24, 2018

Spills: SPILLS

A listing of spills included in the New Mexico Environment Department's Environmental Notification Tracking System.

Government Publication Date: May 31, 2025

Spills and Incidents - Oil Conservation Division: SPILLS OIL

List of Spills and Incidents made available by the State of New Mexico Oil Conservation Division.

Government Publication Date: Oct 23, 2025

Clandestine Drug Lab Discoveries: CDL

List of addresses of locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. The sources of the entries are law enforcement agencies, and although the list is made available by the New Mexico Environment Department (NMED), NMED has not verified the data and does not guarantee its accuracy. Sites listed were seized prior to January 1, 2008, were not subject to the New Mexico Clandestine Drug Lab Cleanup Rule.

Government Publication Date: May 17, 2018

Per- and Polyfluoroalkyl Substances (PFAS): PFAS

List of PFAS/PFOS sites of concern and sampling locations made available by the New Mexico Environment Department (NMED). Includes sites known to the NMED where PFAS/PFOS containing material may be of concern, as well as USGS PFAS groundwater sampling locations.

Government Publication Date: Feb 4, 2025

Ground Water Discharge Permits: GW DISCHARGE

The Ground Water Pollution Prevention Section of the New Mexico Environment Department reviews and approves discharges that have the potential to impact ground water quality pursuant to Subparts III and V of the Water Quality Control Commission (WQCC) regulations (20.6.2 NMAC). Ground water discharge permits address a wide variety of discharges including domestic wastewater treatment plants, commercial septic tank leach fields, power generating plants, commercial laundries not served by sanitary sewers, dairies, food processing plants, commercial land farms for treatment of contaminated soil, industrial discharges, injection wells and ground water remediation systems. This list does not include permits for mines or agricultural facilities.

Government Publication Date: Dec 20, 2024

Southwest Research and Information Center Uranium Sites: URANIUM

This database contains information on Northwestern New Mexico uranium projects located in Navajo Country and is maintained by the Southwest Research and Information Center. This organization was founded in 1971 for the purpose of providing information to the public on the effects of energy development and resource exploitation on the people and their cultures, lands, water, and air of New Mexico and the Southwest.

Government Publication Date: Oct 18, 2006

Tribal

No Tribal additional environmental record sources available for this State.

County

No County additional environmental record sources available for this State.

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

APPENDIX I

Supplemental Records

[RESERVED]

APPENDIX J

Photographic Log



Photograph 1. View of Canyon Road facing west with the Subject Property visible on the left of the photograph.



Photograph 2. Photograph of the Subject Property's Canyon Road frontage taken from Canyon Road facing south-southeast with overhead electric service lines and pole mounted transformer visible in the right of the photograph. This primary Subject Property building currently houses Canyon Road Contemporary art gallery.



Photograph 3. Additional view of the Subject Property's Canyon Road frontage taken from the northern sidewalk facing southeast with a municipal sewer manhole visible in Canyon Road.



Photograph 4. View of the primary Subject Property structure's entrance which houses Canyon Road Contemporary art gallery.



Photograph 5. View from the northwestern Subject Property boundary facing northwest across Canyon Road.



Photograph 6. View from the northwestern Subject Property boundary facing northeast across Canyon Road with north adjoining property (Dominique Boisjoli Fine Art) visible.



Photograph 7. View from the northwestern Subject Property boundary facing southeast with the primary Subject Property building and courtyard area visible.

.



Photograph 8. View from the northwestern Subject Property boundary facing southwest with the western adjoining property (Cruz Gallery) and western public alleyway visible.



Photograph 9. View from the northeastern Subject Property boundary facing northwest across Canyon Road.



Photograph 10. View from the northeastern Subject Property boundary facing northeast across Canyon Road with a municipal stormwater grate visible along the northern curbline.



Photograph 11. View from the northeastern Subject Property boundary facing southeast with the eastern adjoining property (626 Canyon Road) visible.



Photograph 12. View from the northeastern Subject Property boundary facing southwest with the sign for the primary business in the rear/south of the Subject Property and mailboxes for properties in the public alleyway forming the eastern Subject Property boundary.



Photograph 13. View of the art galleries located at 618A and 618B Canyon Road on the eastern side of the public alleyway forming the Subject Property boundary. This structure is physically contiguous with the 622 Canyon Road frontage.



Photograph 14. View of the overhead electric service lines running along the public alleyway forming the western Subject Property boundary. Photograph is taken facing north from the western Subject Property boundary.



Photograph 15. Photo showing exterior of the western adjoining property taken from the public alleyway west of the Subject Property facing southwest.



Photograph 16. View of the southernmost portion of the public alleyway forming the western Subject Property boundary with art galleries located in the buildings.



Photograph 17. View of an exterior entrance located on the southeastern corner of the primary Subject Property building with a 622 Canyon Road address sign visible. Photograph taken from the public alleyway forming the eastern Subject Property boundary facing southwest.



Photograph 18. View of the exterior of the Subject Property (current address 622 C Canyon Road) believed to have been the location of historical dry-cleaning operations. View from public alleyway east of the property facing southeast.



Photograph 19. Photograph showing the residence located at 622 ½ Canyon Road located immediately south of the primary Subject Property building at the southern end of the eastern public alleyway. View from public alleyway west of the property facing southeast.



Photograph 20. Additional view of 622 C Canyon Road building taken from the southern terminus of the eastern public alleyway facing north toward Canyon Road.



Photograph 21. View of the northern adjoining property (Dineh & Company art gallery) located at 621 Canyon Road on the northern side of Canyon Road.



Photograph 22. View of the western adjoining property (Cruz gallery) located on the western side of the western public alleyway at 616 Canyon Road.



Photograph 23. Additional view of the western adjoining property.



Photograph 24. View of the exterior of the eastern adjoining property located at 626 Canyon Road. Photograph is taken from Canyon Road facing south-southwest.

APPENDIX K


Interviews



DESERT MOSS VINTAGE

Esteban, Megan & Hawthorne Rios y Torres

622 C Canyon Road, Santa Fe, New Mexico 87501



622C CANYON RD.
DESERT MOSS ~~THRIFT~~ VINTAGE

PREFER EMAIL CONTACT

Legend

Subject Property

0 50 100 Feet

N

owners of store/property - Esteban + wife Megan

desertmossvintage@gmail.com

Spoke w/ megan, she explained the back-section 622C of property was likely involved w/ dry cleaning, interested in ESA/concerned about possible fumes.

Figure 1D
Universal Cleaners
622 Canyon RD, Santa Fe, NM

622C

Exported: 11/6/2025 1:52 PM

M:\AUS\PROPOSALS\2025\P025.383.NMEN Santa Fe and Waldo Phase I & II ESAs\Graphics\SantaFe_Waldo_P1P2_Proposal\SantaFe_Waldo_P1P2_Pro...

Layout: Figure 1D - 622 Canyon

INTERA

she operates thrift store out of this section of the property - other part facing street; art store renting from Esteban

APPENDIX L

Qualifications of Environmental Professionals



Matt Hubbard
Senior Environmental Scientist

Years of Experience: 14

Education:

- BS, Environmental Science, University of Texas at Austin

Professional Registrations/Affiliations:

- TCEQ Leaking Petroleum Storage Tank (LPST) Project Manager, License No. PM0000720, 2022

Professional History:

2026 – Present	Senior Environmental Scientist – INTERA Incorporated, Austin, TX
2018 – 2025	Environmental Scientist – INTERA Incorporated, Austin, TX
2017 – 2018	Environmental Specialist – City of Austin, Development Services Department, Austin, TX
2013 – 2017	Project Manager / Engineering and Corrective Action Specialist – Texas Commission on Environmental Quality, Remediation Division, Superfund Section, Austin, TX
2012 – 2013	Work Lead / Licensed Electrician – Wells Solar and Electrical Services, Austin, TX
2012	Field Research Assistant – University of Texas, Austin, TX

Training:

- MSHA Part 48 Surface New Miner Training, 2019-2023
- 40-Hour General Site Workers Training, OSHA 29 CFR 1910.120(e)(3), 2013
- 8-Hour Refresher, OSHA 29 CFR 1910.120, 2013 – 2025
- Hydrogen Sulfide (H2S) Training, 2018
- CPR, First Aid, and Bloodborne Pathogens Training, 29 CFR 1910.1030, 2024
- ArcGIS Pro, WinSitu, Strater®, Grapher™, Surfer®, PLog, LogPlot
- Land Science® Certified Vapor Barrier Inspector, 2020

Matt Hubbard is a Senior Environmental Scientist at INTERA with a BS degree in environmental science and 14 years of experience investigating and remediating contaminated sites. He serves in several capacities including Project Manager, Technical Lead, Field Lead, and Health and Safety Lead. Matt develops and implements highly technical work plans for complex technical projects and provides subject matter expertise to clients and senior leadership. His project experience includes state and federal Superfund, Brownfields, voluntary cleanup program (VCP), petroleum storage tank (PST), Phase I and Phase II Environmental Site Assessment (ESA), and imminent threat/removal assessments. Matt is an expert in field methods including sampling of surface and subsurface environmental media, field screening techniques, environmental drilling, and well construction. He has worked on contaminated sites associated with metals including hexavalent chromium, petroleum hydrocarbons, chlorinated solvents, polychlorinated biphenyls (PCBs), organochlorine and organophosphorus compounds (pesticides and herbicides), dioxins/furans, and per- and polyfluoroalkyl substances (PFAS). Matt has significant experience designing assessments and implementing innovative methods, including incremental sampling methodology (ISM), field portable x-ray fluorescence (XRF), passive soil gas (PSG), ground-penetrating radar (GPR), and electromagnetic mapping. He is also experienced in water resources development, including oversight and support of production well drilling and installation, aquifer performance analysis, dynamic flow profiling, and mass balance chemical analysis.

Project Experience – Environmental

ChemFab Phase I Environmental Site Assessment, ChemFab, LLC., Clute, TX. 2026. *Project Manager.* Conducted a Phase I ESA for a fabrication facility and an adjoining property in accordance with ASTM Standard Practice E1527-21.

Southside Storage Phase I Environmental Site Assessments, Southside Wrecker, Inc., Austin, TX. 2025 – 2026. *Project Manager.* Conducted two Phase I ESAs: one at a vacant property that was previously a sand and gravel mine and subsequently filled via unpermitted landfilling operations and another at an automotive repair and maintenance facility. The Phase I ESAs were conducted in accordance with ASTM Standard Practice E1527-21.

Hornsby Bend Biosolids Management Plant, City of Austin Water, TX. 2023 – 2026. *Project Manager.* Coordinated and led quarterly groundwater monitoring and annual soil sampling in support of the requirements of the Texas Commission on Environmental Quality (TCEQ) permit to process wastewater treatment plant sewer sludge, land apply wastewater treatment plant sewage sludge, and irrigate lagoon supernatant under provisions of Chapter 26 of the Texas Water Code, Chapter 361.121 of the Texas Health and Safety Code, and Chapter 312 of the Texas Administrative Code. Conducted independent data usability review for each quarterly groundwater event. Prepared quarterly updates to groundwater potentiometric elevation maps.

Prepared annual report for submittal to the TCEQ. Performed supplemental historical data review and assessment in support of additional reporting requested by special provision of the 2025 permit renewal and was the primary author of the supplemental report.

Jensen Drive Scrap State Superfund Site, 3603 Jensen Drive LLC, Harris County, TX. 2018 – 2026. *Environmental Scientist and Field Lead.* Drafted Annual Post Closure Care Report and Data Usability Summary for annual 2018, 2019, 2020, and 2025 site activities, which included groundwater monitoring, potentiometric mapping, and engineer's inspection of the site waste containment unit. Coordinated and conducted 2019, 2020, and 2025 groundwater monitoring events, including low-flow sampling for PCBs.

BAE TRACOR Phase I and Phase II Environmental Site Assessment, City of Austin Brownfields, TX. 2025. *Project Manager.* Conducted a Phase I ESA for the City of Austin (COA) Brownfields Program in accordance with ASTM Standard Practice E1527-21. The approximately 140-acre facility had 12 permanent structures and was formerly used for military research and development. Coordinated all aspects of project work to meet the City's expedited timeline within the 120-day due diligence period. Developed the rationale and scope of the Phase II ESA and designed the sampling plan. Soil and groundwater investigation included the installation of soil borings and monitor wells for sampling and analysis of soil and groundwater for contaminants including PFAS and nitroaromatics and nitramines. Directed the INTERA team and subcontractors for the multi-phased progressive tasks in support of the overall objective and made necessary and defensible modifications to the plan, as needed, to meet budget and scheduling restraints. Authored the Phase II ESA and provided support to the COA during negotiations leading up to and culminating with the acquisition of the property.

411 Chicon, City of Austin Brownfields, TX. 2024 – 2025. *Project Manager.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice E1527-21. Oversaw a geophysical survey of the subsurface and an exploratory investigation to determine the presence or absence of underground storage tanks.

Former Travis County Landfill, Moo Moo Meadows, LLC., Austin, TX. 2024 – 2025. *Project Manager.* Reviewed available data to determine groundwater conditions and assess landfill permittee's responsibilities for management. Provided expert environmental support in a contested dispute for site development under 30 Texas Administrative Code (TAC) 330 Subchapter T – Use of Land Over Closed Municipal Solid Waste Landfills.

Austin Bergstrom International Airport Augmented Staff, City of Austin Aviation Department, TX. 2023 – 2025. *Environmental Scientist and Field Lead.* Provided as-needed consulting and field assistance in support of ongoing development at Austin Bergstrom International Airport. Conducted liquid and solid waste sampling for disposal and consulting for the remediation of bulk PFAS chemical and PFAS-containing water in emergency response vehicles. Provided oversight and project coordination for PFAS-contaminated stockpile relocation, monitor well drilling and installation, and soil and groundwater sampling for PFAS.

In-Situ Anaerobic Bioremediation Pilot Study, Chemical Waste Management, Corpus Christi, TX. 2024. *Environmental Scientist.* Conducted baseline groundwater monitoring in support of the pilot study that was performed to evaluate in-situ anaerobic bioremediation as a remedial method groundwater contamination.

Pollution Prevention Plan, Precise Hard Chrome, LLC., Waco, TX. 2024. *Environmental Scientist.* Authored the five-year Pollution Prevention Plan for the Precise Hard Chrome facility in Waco, Texas in accordance with 30 TAC Chapter 335, Subchapter Q (*Pollution Prevention: Source Reduction and Waste Management*). The plan identified all activities that generated hazardous waste or resulted in a release of Toxic Release Inventory reportable chemicals and a prioritized list of economically and technologically feasible source reduction and waste minimization projects.

Peaceful Hill, Graham Development, Austin, TX. 2024. *Project Manager.* Assessed the regulatory framework for proposed stormwater injection to aquifer recharge wells on a commercial development (Class V Injection Well). The assessment included siting and hydrogeologic analysis and provided recommendations for additional investigation in support of implementation.

Rio Grande Coop Phase I Environmental Site Assessment, City of Austin Brownfields, TX. 2024. *Project Manager.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice E1527-21.

Anita Ferrales Coy Phase I Environmental Site Assessment and Asbestos/Lead Survey, City of Austin Brownfields, TX. 2024. *Project Manager.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice

E1527-21. Facilitated asbestos containing material and lead-containing paint survey and preparation of project remediation specifications.

McAlpine Lease Third Party Release Assessment Review, E&W Law, Stanton, TX. 2024. *Environmental Scientist and Data Reviewer.* Conducted data usability review of laboratory analytical results and senior review of the assessment review report for a crude oil and produced water release. Evaluated data relative to Railroad Commission of Texas (RRC) guidance.

Town Lake Metro Park Youth Hostel Phase I Environmental Site Assessment, City of Austin Parks and Recreation Department, TX. 2024. *Environmental Scientist.* Conducted a Phase I ESA in accordance with ASTM Standard Practice E1527-21 in support of planned redevelopment.

Environmental Impacts Assessment, Cooks Branch Conservancy, Montgomery, TX. 2024. *Environmental Scientist.* Oversaw drilling and installation of three monitoring wells. Lithologically logged each well in accordance with ASTM D2488-17e1 and Unified Soil Classification System (USCS). Conducted groundwater and surface water sampling and assessment for a range of analytes to determine impacts from a nearby mining operation. Provided technical support and senior review of data and deliverables.

Geotechnical Investigation for a Potential Compost Facility, Confidential Client, TX. 2024. *Environmental Scientist.* To determine a proposed site's suitability for TCEQ permitting of a compost facility, conducted a subsurface investigation focused on identifying shallow, low permeability clays suitable for use as an in-situ clay liner. Installed and lithologically logged 12 soil borings using the USCS. Collected soil samples from each boring at low permeability clay intervals based on field observations. Sent select samples to a geotechnical laboratory for analysis.

North Railroad Avenue Plume Superfund Site, New Mexico Environment Department, Española, NM. 2024. *Environmental Scientist and Field Lead.* Served as field lead for roto-sonic drilling and installation of a monitoring well in support of an New Mexico Environmental Department (NMED)-led cleanup at a former drycleaner site contaminated with tetrachloroethene (PCE) and its degradation products. Logged continuous core (ASTM D2488-17e1 / USCS) to 257 feet below ground surface (bgs), screened heated headspace soil samples with a photoionization detector, collected push-ahead groundwater samples at discrete depth intervals during drilling, and oversaw analysis of push-ahead groundwater samples via a FROG-5000 portable gas chromatograph. Identified the target hydrostratigraphic unit and informed the selection of the well screen interval. Assisted in work plan creation and annual reporting including software-based boring logs and potentiometric surface elevation mapping.

Per- and Polyfluorinated Substances Risk Assessment, California American Water, Duarte, CA. 2023 – 2024. *Environmental Scientist.* Assisted in the development of custom-built vadose-zone PFAS analytical solution tool to assess the vulnerability of existing and potential well sites to contamination. Identified potential contamination sources by evaluating records on former and current regulated facilities with current or former operations known to be or commonly associated with the use of PFAS. This information was used together with the spatial vulnerability analysis to assess the relative risk of PFAS contamination to existing and potential well sites. The analysis was used to develop recommendations for engineering and operational measures to mitigate the risk and impacts of future contamination. Measures could include changes in operation of existing wells, treatment, or replacement of wells that have reached the end of their service life. Prioritized recommendations for investigation and test drilling at new well sites based on operational benefits, cost, and risk of current or future contamination. The environmental data gathered for the study was provided for future use in permitting selected well sites.

JV DIRT, American AllWaste, Austin, TX. 2023 – 2024. *Environmental Scientist.* Conducted video well survey with a downhole camera. Conducted groundwater sampling. Prepared an update and revision to the site geologic/hydrogeologic report and groundwater protection plan in support of a permit renewal application for composting activities.

Remedial Investigation at Scrub-A-Dubb Barrel Company Site, Texas Commission on Environmental Quality, Lubbock, TX. 2020 – 2024. *Environmental Scientist.* Designed and conducted a remedial investigation, which was a targeted surface soil assessment in compliance with the site-specific field sampling plan (FSP) and the quality assurance program plan developed for the former drum recycling site utilizing ISM for the TCEQ Superfund Section. The primary contaminants of concern included volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), and metals. Used direct-push methodology to collect over 700 soil increments (aliquots) to generate data to assess soils down to five feet bgs for the entirety of the five-acre site during one field mobilization. Collected replicate data to determine statistically if data generated for each ISM decision unit (DU) were representative and defensible. The field activity report was finalized and approved by the TCEQ in March 2022.

Data evaluation confirmed the success of the ISM approach. Authored an affected property assessment report for the TCEQ Remediation Division, compiling data from assessment over an approximately five-year span including soil, sediment, and groundwater.

Voluntary Cleanup Program Post-Response Assistance, Ice Man, Inc., Belton, TX. 2023. *Environmental Scientist.* Conducted on-site review and documentation of the condition of the side slope of an engineering control cap constructed and the adjacent creek bank at a TCEQ VCP site as part of the required post-response care actions. Prepared a memorandum describing the observations made and recommended future actions.

St. Johns Redevelopment Site, City of Austin Economic Development Department via the Austin Brownfield Revitalization Office, TX. 2023. *Project Manager.* Designed and implemented a Limited Phase II ESA for the assessment of a former industrial facility and TCEQ Leaking Petroleum Storage Tank site for planned redevelopment as residential multifamily affordable housing. The assessment included (1) third-party review and assessment of previous site investigation data to identify potential data gaps and areas of concern relative to potential contaminant impacts and (2) soil gas sampling and assessment to assess the potential vapor exposure risk to occupants of future site buildings. Installed a grid of 31 passive soil gas sampling devices over the former site operations area and assessed the laboratory analytical results after a 14-day uptake period, compared to United States Environmental Protection Agency (EPA) Vapor Intrusion Screening Levels. Prepared report documenting the assessment and recommended future actions and guidelines for the Austin Economic Development Department's agreement with the site developer.

Fairfield Lake State Park Environmental Assessment, Texas Parks and Wildlife Department, Freestone County, TX. 2023. *Environmental Scientist.* Provided technical support in discussions with client regarding conduct of Phase I and Phase II ESAs in aid of State of Texas eminent domain condemnation procedures for approximately 5,000 acres, including Fairfield Lake and the immediate surrounding property that was formerly designated as Fairfield Lake State Park. Of specific concern was possible impacts to surface water, sediments, and aquatic life from heavy metals and PCBs related to a former coal-fired power plant located along the northern end of the property. Conducted the site reconnaissance and prepared the Phase I ESA (ASTM Standard E1527-21), which identified several Recognized Environmental Conditions (RECs); however, additional work to address the RECs was halted when Texas Parks and Wildlife Department decided to end condemnation procedures.

Langford Elementary Phase I Environmental Site Assessment, City of Ausitn Brownfields Program, TX. 2023. *Environmental Scientist.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice E1527-21.

Whisper Valley, City of Austin Brownfields Program, TX. 2023. *Environmental Scientist.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice E1527-21.

Emergency Response Waste Sampling at the Mexican American Cultural Center, City of Austin, TX. 2023. *Environmental Scientist.* Conducted emergency sampling of uncovered landfill waste material during the redevelopment of the Mexican American Cultural Center in downtown Austin, Texas.

Limited Phase II Environmental Site Assessment, American AllWaste, Lake Charles, LA. 2023. *Environmental Scientist.* Developed and sampled groundwater for VOCs, SVOCs, metals, petroleum hydrocarbons, pesticides, herbicides, PCBs, and PFAS. Prepared the report documenting the analytical results including a data usability summary. Provided recommendations for additional assessment based on the client's proposed property transaction.

Austin Nature Science Center Outpost, Soil Assessment, City of Austin Parks Department, TX. 2022 – 2023. *Environmental Scientist.* Performed soil assessment to delineate polycyclic aromatic hydrocarbons and heavy metals to Texas Risk Reduction Program (TRRP) Tier 1 Residential Total-soil-combined protective concentrations levels (PCLs) related to former skeet and firing range operations. This work was conducted in support of the implementation of a forthcoming removal action to restore the site to residential standards. Sampling approaches included ISM and ex-situ XRF methods. Authored the work plan and assessment report for this project.

Limited Phase II Environmental Site Assessment for Shield Park, Texas Commission on Environmental Quality Brownfields Program, Galveston, TX. 2022 – 2023. *Project Manager*. Oversaw completion of a geophysical survey implementing GPR and electromagnetic mapping to assess the presence of suspected underground storage tanks (USTs). Provided technical review and implemented TCEQ's soil assessment strategy including installing, screening, and sampling 20 soil borings. Logged each

boring according to the USCS. Prepared the Limited Phase II ESA report documenting site activities and analytical results for VOCs, SVOCs, metals, PCBs, and total petroleum hydrocarbons (TPH). Conducted technical data review and usability assessment and prepared a memorandum in accordance with the TCEQ Quality Assurance Project Plan and applicable EPA guidance.

Limited Phase II Environmental Site Assessment for Hargrave Fleet Services Property, City of Austin Brownfields Program, TX. 2022 – 2023. *Environmental Scientist.* The scope of the Phase II ESA included a full asbestos and lead-containing paint inspection survey, soil gas, surface soil, and groundwater assessment. Contaminants of concern included heavy metals, VOCs, SVOCs, dioxins/furans, and PFAS. Authored the work plan and led the field event to install passive soil gas sampling devices, groundwater monitoring wells, and soil borings. Categorized the groundwater in the shallow groundwater bearing in accordance with TRRP guidelines.

Phase I and II Environmental Site Assessment, Foundation Communities Brownfields Redevelopment Project - Airport Boulevard, Austin, TX. 2022. *Environmental Scientist.* Performed Phase II ESA in preparation for the development of an affordable housing apartment complex by Foundation Communities. Activities assessed two vapor encroachment conditions and two RECs. Deployed a total of 20 PSGs to assess soil gas. Installed four soil borings to assess site soils and the shallow groundwater-bearing unit.

Phase I Environmental Site Assessment, Tract 1-B: Paseo del Pueblo Sur and Los Pandos Road, Taos Hotel Associates, LLC., Taos, NM. 2022. *Environmental Scientist.* Conducted and prepared a Phase I ESA report in accordance with ASTM Standard E1527-21 and resultant volume estimate for a proposed removal of identified petroleum-contaminated soil more than the NMED action level of 100 parts per million by volume.

Scrub-A-Dubb Barrell Company Proposed State Superfund Site, Texas Commission on Environmental Quality, Lubbock County, TX. 2019 – 2023. *Environmental Scientist.* Drafted the TCEQ State Superfund FSP to implement assessment of on- and off-site soils for metals and VOCs referencing Interstate Technology Regulatory Council ISM. The ISM protocol would be used to assess risk to nearby human health and sensitive environmental receptors and to support a potential removal action. Results were compared to TRRP action levels.

Groundwater Sampling & Reporting, Chemical Waste Management, Port Arthur, Texas. 2022. *Environmental Scientist*. Conducted quarterly groundwater monitoring activities for a closed hazardous waste landfill facility. Sampling included groundwater collection at approximately 30 site monitoring wells for VOCs and arsenic.

Gem Dandy 14 Phase I Environmental Site Assessment, Texas Commission on Environmental Quality Brownfields Program, Hamilton, TX. 2022 – 2023. *Project Manager.* Conducted a Phase I ESA for the TCEQ Brownfields Program in accordance with ASTM Standard Practice E1527-21. Oversaw completion of a geophysical survey implementing GPR and electromagnetic mapping to confirm the presence of a UST. Conducted removal of one 12,000-gallon UST and associated infrastructure. Prepared and submitted a report in accordance with TCEQ Regulatory Guidance (RG) 411 documenting removal and restoration activities.

IWC Winters Landfill, Texas Commission on Environmental Quality Superfund Site Discovery and Assessment Program, Orange, TX. 2022 – 2023. *Project Manager.* Designed and conducted initial assessment of this former industrial waste landfill that had become partially submerged and had a history of fires near Adams Bayou in Orange, TX. Sampling of soil, sediment, groundwater, and surface water was conducted for VOCs, SVOCs, organochlorine and organophosphorus pesticides, metals, PCBs, dioxins/furans, and PFAS. Prepared the assessment report including technical data review in accordance with the TCEQ Quality Assurance Project Plan and applicable EPA guidance for all media and analytes.

Former Frank Ortiz Landfill, City of Santa Fe Environmental Services Division, NM. 2021 – 2023. *Environmental Scientist*. Prepared Stage 1 Abatement Plan Quarterly Monitoring Reports detailing ongoing monitoring efforts at the site including soil vapor sampling, groundwater monitoring, and landfill gas monitoring.

Rockwool Industries Federal Superfund Site, Texas Commission on Environmental Quality, Bell County, TX. 2018 – 2023. *Project Manager.* Conducted annual groundwater monitoring and semi-annual site inspections, provided oversight for site maintenance, and drafted the annual reports including potentiometric surface and isoconcentration maps, documenting all site activities, and providing conclusions and recommendations for future site activities.

Calhoun and Griggs Soil Assessment, Texas Commission on Environmental Quality, Houston, TX. 2022. *Project Manager.* Designed and conducted a soils assessment for metals and prepared a report documenting the findings.

Magic Tunnel Geophysical Survey, Texas Commission on Environmental Quality Brownfields Program, Texarkana, TX. 2022. *Project Manager*. Oversaw the completion of a geophysical survey implementing GPR and electromagnetic mapping to determine the presence of suspected USTs.

Former Nursing Home Phase I Environmental Site Assessment, Texas Commission on Environmental Quality Brownfields Program, Hamilton, TX. 2022. *Project Manager.* Conducted a Phase I ESAs for the TCEQ Brownfields Program in accordance with ASTM Standard Practice E1527-21.

Kirtland Air Force Base Environmental Baseline Surveys, Albuquerque Bernalillo County Water Utility Authority, NM. 2020 – 2022. *Environmental Scientist.* Authored and certified two Environmental Baseline Survey (EBS) Reports to meet appropriate property due diligence practices for the easement between Albuquerque Bernalillo County Water Utility Authority (ABCWUA) and Kirtland Air Force Base (KAFB), in accordance with Air Force Instruction 32-7066. The property locations included a 5.29-mile-long easement and a 24-acre parcel, all located on KAFB and Department of Energy property. The project included installing an interceptor pipeline and booster station by ABCWUA, with INTERA responsible for all federal due diligence requirements associated with construction projects occurring on federal facilities. Air Force EBS reports are generally comparable to an environmental due diligence report (Phase I ESA) but also include National Environmental Policy Act review, including cultural natural/biological resource review. Updated the sewer interceptor line easement in February 2022. The EBS reports were approved by the ABCWUA and KAFB in 2022.

Former Santa Fe Generating Station, Public Service Company of New Mexico, Santa Fe County, NM. 2018 – 2022. *Environmental Scientist*. Provided data review services of laboratory analytical and field and laboratory quality assurance/quality control for periodic groundwater monitoring. Reviewed figures and tables and created contaminant trends time series data visualizations with Grapher™ software for quarterly progress reporting (2019-2022). Conducted groundwater monitoring (2021) for VOCs and nitrate/nitrite utilizing piston driven Bennett Pump. Conducted a detailed review of historical aerial photographs for evidence of potential sources to petroleum contamination at the site. Drafted a report including a detailed spatiotemporal summary of findings with correlation to historical documentation.

South State Highway 16, Texas Commission on Environmental Quality Superfund Site Discovery and Assessment Program, San Antonio, TX. 2021. *Project Manager.* Designed and conducted a Superfund Site Discovery and Assessment Program (SSDAP) Eligibility Sampling groundwater assessment in the vicinity of a former illegal dump site used by a pesticide applicator to assess impacts to nearby human health receptors at target sole source water wells.

Airline & Aldine, Texas Commission on Environmental Quality Superfund Site Discovery and Assessment Program, Houston, TX. 2021. *Project Manager.* Designed and conducted a State Screening groundwater assessment in the vicinity of a former public water supply well with chlorinated solvent contamination to assess impacts to human health receptors at target sole source water wells.

Elm Street Phase I Environmental Site Assessments, Texas Commission on Environmental Quality Brownfields Program, Texarkana, TX. 2021. *Environmental Scientist.* Conducted two Phase I ESAs for the TCEQ Brownfields Program in accordance with ASTM Standard Practice E1527-13.

Site Investigation of Former Drilling Fluids Disposal Pit, Mo-Vac Service Company, Alice, TX. 2021. *Environmental Scientist.* Conducted a site investigation of a former drilling fluids disposal pit pursuant to an RRC letter to INTERA's client. Conducted a pump test to properly classify the groundwater and conducted groundwater sampling.

Covenant Testing Technologies Railroad Commission of Texas Pit Closure, Covenant Testing Technologies, Midland, TX. 2021. *Environmental Scientist*. Conducted sampling event to close an in-ground steel tank and wash pads that were used to collect hydrocarbon contaminated equipment wash water. Assisted in preparing submittal to the RRC documenting that the site met RRC closure criteria.

Wally's Flying Service Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Uvalde County, TX. 2020. *Environmental Scientist.* Prepared the site-specific health and safety plan (SSHASP) and FSP. Conducted field event including groundwater sampling for SVOCs by method 8270E, organochlorine pesticides by method 8081B, and organophosphorus pesticides by method 8141B. Target contaminants of concerns, glyphosate and endothall, were also sampled and analyzed via EPA drinking water methods 547 and 548.1, respectively. Prepared the final SSDAP Letter Report documenting sampling and comparing analytical results to TRRP PCLs.

G&L Spraying Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Tom Green County, TX. 2020 – 2021. *Project Manager.* Designed and conducted a State Screening groundwater assessment in the vicinity of a former pesticide applicator with a history of releases to the ground surface to assess impacts to human health receptors at target sole source water wells. Conducted groundwater sampling for metals (primarily arsenic) and SVOC pesticides pendimethalin and trifluralin.

Jain Lane / Govalle Soil Vapor Assessment and Vapor Intrusion Mitigation Assistance, Cesar Chavez Foundation, Austin, TX. 2019 – 2021. *Environmental Scientist.* Prepared an updated FSP to conduct soil vapor assessment for a proposed multi-unit residential development. Conducted soil vapor sampling to assess soil vapor impacts from hydrocarbon-affected groundwater from an adjoining, upgradient site. Prepared a Limited Phase II Report for soil vapor assessment concluding potential risk of vapor intrusion to the proposed development and provided recommendations for a vapor barrier system to mitigate potential impacts. Provided mitigation design assistance during the planning stages for construction. Provided certified third party inspection during vapor barrier and venting system installation for a multi-tenant residential complex. Provided final report documenting mitigation effort to satisfy requirements to obtain financial assistance.

Former First Baptist Church, University of New Mexico, Albuquerque, NM. 2020. *Environmental Scientist.* Prepared and submitted a Phase I ESA Report in accordance with ASTM Standard Practice E1527-13. Reviewed available historical records evaluated site visit findings to identify, to the extent possible, any RECs, as defined by ASTM. The Subject Property consisted of mixed use educational, residential, and creative space development. The development is in a highly developed area of Albuquerque and is also immediately south of a chlorinated solvent groundwater plume that is part of a federal superfund site on the national priority list.

Hospital Drive, Anchorum St. Vincent c/o Colliers International, Santa Fe, NM. 2020. *Environmental Scientist.* Prepared and submitted a Phase I ESA Report in accordance with ASTM Standard Practice E1527-13. Reviewed available historical records evaluated site visit findings to identify, to the extent possible, any RECs, as defined by ASTM. The Subject Property consisted of an outpatient medical facility in a mixed commercial and residential area.

Oltorf Street Phase I Environmental Site Assessment, City of Austin, TX. 2020. *Environmental Scientist*. Prepared and submitted a Phase I ESA Report in accordance with ASTM Standard Practice E1527-13. Reviewed available historical records conducted site visit to identify, to the extent possible, any RECs, as defined by ASTM. The Subject Property consisted of a 2.57-mile corridor through commercial and residential areas for a proposed reclaimed water main project.

Loco Ocho Hydrogeologic Assessment, Confidential Client, Wimberly, TX. 2020. *Environmental Scientist*. Conducted groundwater sampling at a private water supply well to establish baseline water quality.

Frank's Conoco, New Mexico Environmental Department Petroleum Storage Tank Bureau, Las Cruces, NM. 2020.
Environmental Scientist. Prepared Groundwater Monitoring Report for a petroleum hydrocarbons release site where INTERA gauged depth to water/light non-aqueous phase liquid (LNAPL) collected groundwater samples. Groundwater was analyzed for VOCs. Reporting included calculating and graphically depicting the groundwater gradient and potentiometric surface. Analytical results were compared to New Mexico Water Quality Control Commission (NMWQCC) standards.

Highway Texaco, New Mexico Environmental Department Petroleum Storage Tank Bureau, Las Cruces, NM. 2020.
Environmental Scientist. Prepared a work plan and cost estimate to conduct a single groundwater monitoring event including monitoring well gauging, sampling, and analysis for dissolved iron and manganese, and VOCs. Analytical results were compared to NMWQCC standards. The sampling monitored petroleum hydrocarbon contaminants in groundwater associated with releases from a former gasoline service station.

Corrales Chevron, New Mexico Environmental Department Petroleum Storage Tank Bureau, Corrales, NM. 2020.
Environmental Scientist. Prepared a work plan and cost estimate to conduct a semi-annual groundwater monitoring at an active gasoline service station with historical releases from the former operations of a preceding service station. The scope of work for this project included monitoring petroleum hydrocarbon contamination in groundwater from a series of 10 monitoring wells and from six nearby water supply wells (i.e., wells with a sealed wellhead). Analytical results of sampling conducted for VOCs were compared to NMWQCC standards.

Caldwell Motor Company, New Mexico Environmental Department Petroleum Storage Tank Bureau, Belen, NM. 2020.
Environmental Scientist. Prepared a work plan and cost estimate to conduct a semi-annual groundwater monitoring at a

former gasoline service station with a historical presence of LNAPL and an undefined dissolved phase contaminant plume. The sampling monitored the contaminant plume from the existing four monitoring wells and compared analytical results to NMWQCC standards.

Old Exxon Jobber Site, Texas Commission on Environmental Quality, San Patricio County, TX. 2019 – 2020. *Environmental Scientist.* Conducted site reconnaissance and scoping meeting with TCEQ to facilitate preparation of the FSP for tank removal activities and release determination sampling. Prepared FSP in accordance with TCEQ Regulatory Guidance 411 (RG-411) to conduct permanent tank removal activities for two registered 22,000-gallon USTs, and all associated components, and to conduct confirmation and surface release assessment. Conducted field oversight for removal of the tanks and collected confirmation samples for petroleum hydrocarbon contaminants including benzene, toluene, ethylbenzene, xylenes (BTEX), methyl-tert butyl ether (MTBE) via EPA Method 8260/5035, polycyclic aromatic hydrocarbons (PAHs) via EPA Method 8270D, and TPH via TCEQ Method 1005. Prepared and submitted a Release Determination Report in accordance with applicable standard (TCEQ-00621)

Union Pacific Rail Yard, Texas Commission on Environmental Quality, Cameron County, TX. 2019. *Environmental Scientist*. Conducted a Phase I ESA and prepared and submitted a Phase I ESA Report in accordance with ASTM Standard Practice E1527-13. Reviewed available historical records and conducted a site visit to identify, to the extent possible, any RECs, as defined by ASTM. The Subject Property consisted of approximately 25.5 acres of land within an urban mixed residential and commercial industrial area that was formerly a train depot and railway switchyard.

Texaco Building, Texas Commission on Environmental Quality, Cameron County, TX. 2019. *Environmental Scientist.* Conducted a Limited Phase II ESA in which 8,000-gallon steel tank and one 12,000-gallon steel tank and associated piping and conducted sampling and analysis in accordance with TCEQ RG-411. Collected confirmation samples for petroleum hydrocarbon contaminants including BTEX, MTBE via EPA Method 8260/5035, PAHs via EPA Method 8270D, and TPH via TCEQ Method 1005. Prepared and submitted an Release Determination Report in accordance with applicable standard (TCEQ-00621).

City of Hondo Landfill Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Medina County, TX. 2019. *Environmental Scientist.* Prepared the SSHASP and FSP. Conducted field event including groundwater sampling for metals, VOCs, SVOCs, and PCBs. Prepared the final SSDAP Letter Report documenting sampling and comparing analytical results to TRRP PCLs.

Russell Flying Service Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Medina County, TX. 2019. *Environmental Scientist.* Prepared the SSHASP and FSP. Conducted field event including groundwater sampling for metals including hexavalent chromium, SVOCs, VOCs, pesticides, and herbicides. Prepared the final SSDAP Letter Report documenting sampling and comparing analytical results to TRRP PCLs.

The Word Church Phase II Environmental Site Assessment, Texas Commission on Environmental Quality, Bexar County, TX. 2019. *Environmental Scientist.* Provided oversight of drilling via solid stem auger and installation of a monitoring well. Conducted well development and collected a representative groundwater sample via low-flow technique.

Sand Hill Energy Center Release Assessment in Support of Affected Property Assessment Report, City of Austin, TX. 2019. *Environmental Scientist.* Provided oversight for hydro-vac to clear utilities down to six feet at the facility, drilling via hollow-stem auger, and installing and developing three monitoring wells. Collected soil and groundwater samples for analysis of TPH and PAHs. Assisted in preparing an affected property assessment report for submission to TCEQ.

Mineral Wool Insulation Manufacturing Company Proposed State Superfund Site Additional Offsite Evaluation in Support of Remediation, Texas Commission on Environmental Quality, Bell County, TX. 2018 – 2019. *Environmental Scientist.* Conducted detailed overland migration characterization and subsurface sediment sampling using a gravity core sampling device deployed from a boat. Drafted report documenting field activities and providing comprehensive descriptions of the migration pathway with estimation of anticipated volumes for removal based on impacted soils above site specific ecological PCLs. Also collected agricultural samples for nutrient analysis to determine the viability and practicality of repurposing on and offsite soils in the design of a containment cell cap with effective vegetative growth.

Schumann Property Petroleum Storage Tank Removal and Brownfields Site Assessment, Texas Commission on Environmental Quality, Concho County, TX. 2018. *Environmental Scientist.* Prepared the FSP based on TCEQ Regulatory Guidance RG-411. Implemented the FSP including oversight of PST removal (550-gallon "ghost tank"), conducted field screening and

confirmation sampling. Prepared the Release Determination Report documenting removal activities and analytical results with respect to PST Action Levels.

Hamlin Municipal Development District Phase I Environmental Site Assessment, Texas Commission on Environmental Quality, Jones County, TX. 2018. *Environmental Scientist.* Conducted the Phase I ESA site reconnaissance to identify and document RECs.

West Texas Phase I Environmental Site Assessment, Confidential Client, Loving County, TX. 2018. *Environmental Scientist.* Provided historical document review and drafted the historical portion of the Phase I ESA Report for approximately 50 square miles of property in accordance with Standard Practice E2247-16 of ASTM International.

Medical Drive Groundwater Plume Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Bexar County, TX. 2018. *Environmental Scientist.* Conducted groundwater sampling at public and domestic drinking water wells for PCE on rapid 24-hour turnaround time (EPA Drinking Water Method 524.2) and drafted the report to document the release and impacts to receptors in the critical pathway of exposure to facilitate Hazard Ranking System scoring.

South Austin Regional Wastewater Treatment Plant Phase I Environmental Site Assessment, City of Austin Public Works, TX. 2018. *Environmental Scientist*. Conducted the Phase I ESA historical document review and site reconnaissance to identify and document RECs.

The Word Church Phase II Environmental Site Assessment, Texas Commission on Environmental Quality, Bexar County, TX. 2018. *Environmental Scientist*. Provided oversight of environmental borehole drilling with direct push technology for the collection of soil samples to a depth of 15 feet. Assisted in lithological logging, field screened and sampled for VOCs or petroleum products. Drafted the Phase II ESA Report. Work was conducted in accordance with Standard Practice E1903-11 of ASTM International. Provided oversight of drilling via solid stem auger and installation of a monitoring well. Conducted well development and collected a representative groundwater sample via low-flow technique.

Cass County Treating Company State Superfund Site Immediate Removal Action, Texas Commission on Environmental Quality, Cass County, TX. 2016 – 2017. *Project Manager*. Coordinated and provided oversight for removal of soils affected with pentachlorophenol and dioxins/furans at a residential property. The scope of the project included air sampling for the development of protective particulate monitoring action levels, confirmation sampling via ISM including development of a pentachlorophenol screening level concentration indicative of dioxins/furans concentrations as a screening tool, and site restoration.

North Andrews Highway Health and Safety Plan and Preliminary Assessment, U.S. Environmental Protection Agency, Ector County, TX. 2016 – 2017. *Project Manager*. Developed the site health and safety plan. Authored the preliminary assessment report based on research and available site information, including consolidating and analyzing historical site knowledge and analytical data, describing the geologic setting and aquifer characteristics, evaluating major migration and exposure pathways, and producing figures and tables.

Harvey Industries State Superfund Site, Texas Commission on Environmental Quality, Henderson County, TX. 2016 – 2017. *Project Manager*. Coordinated and oversaw operations and maintenance activities at the site including soil gas monitoring and cap inspection/maintenance.

First Quality Cylinders State Superfund Site, Texas Commission on Environmental Quality, Bexar County, TX. 2014 – 2017. *Assistant Project Manager and Project Manager.* Coordinated and provided oversight for the continuous removal of affected groundwater contained behind a slurry wall from on-site extraction wells. Reviewed engineering documents and assisted in project management for the implementation of the final remedy which included groundwater remediation via direct push in-situ chemical reduction of hexavalent chromium in the shallow groundwater bearing unit and the installation of a continuous onsite pump and treat system. Managed operations and maintenance activities for the on-site treatment system.

Jerrell B Thompson Battery State Superfund Site, Texas Commission on Environmental Quality, Van Zandt County, TX. 2013 – 2017. *Project Manager.* Conducted annual inspection to ensure site controls for waste remained undisturbed and in good condition as part of operations and maintenance activities.

JCS Company State Superfund Site, Texas Commission on Environmental Quality, Van Zandt County, TX. 2013 – 2017. *Project Manager.* Coordinated and provided oversight for annual operations and maintenance activities at the site including cap inspection and maintenance as well as groundwater monitoring activities.

Deepwater Horizon RESTORE Act Proposal Evaluations, Texas Commission on Environmental Quality Natural Resource Damage Assessment, Austin, TX. 2016. *Evaluator.* Was selected to be part of a six-member interdisciplinary committee that evaluated more than 200 proposals requesting funds allocated to the state by the RESTORE Act for the Deepwater Horizon oil spill.

Schaefer Road Drum Immediate Removal Action, Texas Commission on Environmental Quality, Bexar County, TX. 2016. *Project Manager.* Coordinated and provided oversight for HAZCAT classification, removal, and proper disposal of abandoned bulk and containerized wastes, and affected site soils. Authored legal documents for cost recovery.

Methodist Hospital Health and Safety Plan and Preliminary Assessment, U.S. Environmental Protection Agency, Bexar County, TX. 2016. *Project Manager*. Developed the site health and safety plan. Authored the preliminary assessment report based on site reconnaissance, research, and available site information including consolidating and analyzing historical site knowledge and analytical data, describing the geologic setting and aquifer characteristics, evaluating major migration/exposure pathways, and producing figures and tables.

Highway 18 Groundwater Plume Expanded Site Investigation, U.S. Environmental Protection Agency, Winkler County, TX. 2016. *Field Project Manager.* Responsible for the field event, which included coordination and sampling of soils at potential source locations and sampling sole source water wells for evaluation of impact to human health receptors in the groundwater migration pathway.

Lane Plating Works Site Investigation, U.S. Environmental Protection Agency, Dallas County, TX. 2016. *Field Project Manager*. Acted as Project Manager for the field event, which included identifying representative sampling locations in the field and sampling of soils, sediments, and surface water.

Southwestern Plating Works Immediate Removal 2015, Texas Commission on Environmental Quality, Lubbock County, TX. 2015 – 2016. *Project Manager*. Coordinated and provided oversight for the classification, removal, and proper disposal of abandoned plating vats and containerized wastes. Conducted SSDAP state screening activities, including soil and groundwater sampling and analysis and authored legal documents for cost recovery.

Ector Drum Site Investigation, U.S. Environmental Protection Agency, Ector County, TX. 2015 – 2016. *Project Manager*. Conducted the field effort, including sampling of residential and commercial sole source groundwater wells. Analyzed the collected groundwater data, compared data to EPA Maximum Concentration Levels, and authored the final technical report.

Absolute Fuels Superfund Site, Texas Commission on Environmental Quality, Lamb County, TX. 2015. *Project Manager*. Coordinated and provided oversight for the assessment and investigation of impact to human health receptors via the groundwater pathway and the completion of the final Removal Action Report. Authored legal documents, including a property lien for cost recovery.

Industrial Waste Control Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Orange County, TX. 2015. *Project Manager*. Coordinated and provided oversight for the assessment and investigation of impact to human health receptors in the groundwater migration pathway. Analyzed and compared data to TRRP PCLs to provide conclusions and site recommendations.

Browning Ferris Industries Landfill Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Orange County, TX. 2015. *Project Manager.* Coordinated and provided oversight for the assessment and investigation of impact to human health receptors in the groundwater migration pathway. Analyzed data, compared data to TRRP PCLs, and provided conclusions and site recommendations.

Lonesome Trail Site Investigation, U.S. Environmental Protection Agency, Bexar County, TX. 2014. *SI Team Member*. Conducted soil and groundwater sampling to assist in the completion of the Site Investigation.

River City Metal Finishing Superfund Site, Texas Commission on Environmental Quality, Bexar County, TX. 2014. *Project Manager.* Conducted closeout activities, including authoring legal documents and notices including a restrictive covenant and property lien.

Battery Recyclers of Houston Superfund Site, Texas Commission on Environmental Quality, Brazoria County, TX. 2014. *Project Manager.* Coordinated and provided oversight for the assessment and investigation of impact to human health receptors in the groundwater and soils migration pathways. Analyzed data, compared data to TRRP protective concentration levels, and provided conclusions and site recommendations.

Sampling of Vegetation Transects in the Okavango Delta, Dr. Kelley Crews and Dr. Thoralf Meyer, Undergraduate Research, Botswana, Africa. 2012. *Field Research Assistant.* Conducted sampling in remote parts of Botswana, Africa as part of a ground truthing effort for remotely sensed data. Responsibilities included gathering data using high resolution spectral imagery as well as identifying and measuring woody vegetation across ecological regimes. Applied data gathered for analyzing carbon sequestration in above ground woody biomass using the allometric relation of basal area to biomass.

Project Experience – Water Resources

Vertical Flow Profiling for Production Well, Porter Special Utility District, TX. 2021. *Environmental Scientist.* Provided oversight for "lift and shift" and ultimately the complete removal and reinstallation of a 560 ft, 10-inch pump column. Conducted vertical flow profiling utilizing BESST's upgraded and proprietary version of the U.S. Geological Survey tracer flowmeter and targeted depth interval groundwater sampling using the BESST HydroBooster sampling pump. Analytes included hydrogen sulfide (H2S), adenosine triphosphate (ATP), sulfate reducing bacteria (SRBs), iron reducing bacteria (IRBs), dissolved sulfide, total sulfides, total iron, total organic carbon, methane, chloride, sodium, oxidation/reduction potential (ORP), and specific conductivity. Field testing was also performed including H2S, ORP, dissolved oxygen (DO), pH, temperature, turbidity, and specific conductivity. Wellhead samples were also collected, representing blended composites of zonal chemical mass contribution from each contributing flow interval.

Evangeline Laguna Borehole Surveys and Pump Testing, Confidential Client, San Patricio County, TX. 2020. *Environmental Scientist*. Performed video surveys of wells to determine conditions and screened intervals. Conducted oversight of pump removal and installation and 36-hour pump tests in three wells with In-Situ Trolls and WinSitu software while obtaining manual water level and flow measurements. Collected water samples to analyze water chemistry before, during, and after pump tests.

Dynamic Flow and Water Chemistry Profiling, West Harris County Municipal Utility District, Houston and Katy, TX. 2020. *Environmental Scientist.* Conducted downhole investigation at two public water supply wells to: (1) measure zonal flow contribution within the well under steady-state pumping conditions; (2) characterize zonal chemical contribution of arsenic, iron, and exsolved methane; and (3) determine viable economical options to physically modify the well screen to reduce or eliminate treatment for arsenic and iron and to mitigate methane influx. Conducted dynamic flow profiling to calculate zonal flow contributions over hundreds of feet of intermittently perforated well screen by injecting rhodamine dye at discrete depth intervals and measuring peak return rates at the surface via fluorometer. Conducted depth-dependent groundwater sampling to characterize zonal chemical contribution.

New Braunfels Utilities Aquifer Storage and Recovery Monitoring, ARCADIS, New Braunfels, TX. 2020. *Environmental Scientist.* Provided oversight for drop pipe and transducer installation at monitoring wells supporting aquifer storage and recovery monitoring.

Constant Rate Test for Turtle Creek No. 3 Pump Station, San Antonio Water System, Bexar County, TX. 2019. *Environmental Scientist.* Provided oversight for the constant rate test at 7,000 gallons per minute.

El Dorado Sand Mine Water Supply Wells Development and Performance Analysis, Black Mountain Sand, Winkler County, TX. 2019. *Environmental Scientist.* Provided well development (bailing and airlifting) and pump installation oversight, including water quality monitoring; conducted step drawdown tests to assess supply well performance; and collected aquifer test data for four wells using water level meters and multiple transducers. Collected data using In-Situ Trolls and WinSitu software.

Observation Well Drilling Oversight and Sampling - Oversight for Vertical Flow Profiling for Production Well, Confidential Client, San Patricio County, TX. 2018 – 2019. *Environmental Scientist.* Provided oversight for well drilling activities of observation well to depth greater than 1,000 feet bgs and collected mud rotary cuttings samples for sieve analysis. Provided oversight for BESST, Inc. implementing their ambient flow profiling service using the DyeTracer system developed by the U.S. Geological Survey.

Bigfoot Sand Mine Water Supply Well Installation, Turnkey Processing Solutions, Atascosa County, TX. 2018. *Environmental Scientist.* Provided well drilling and installation oversight. Logged drilling cuttings, conducted step drawdown tests, and collected aquifer test data using water level meters and multiple transducers.



Joseph Tracy, PG

Principal Geologist | Senior Vice President

Years of Experience: 31

Education:

- BS, 1993, Environmental Geology, Ohio University

Professional Registrations/Affiliations:

- Professional Geologist, AZ, 2003, No. 38741
- Professional Geologist, TN, 1999, No. TN4417
- Professional Geologist, TX, 2013, No. 11588

Professional History:

2000 – Present	Senior Vice President, Principal Geologist – INTERA Incorporated, Albuquerque, NM
1999 – 2000	Environmental Specialist – GeoTek Insite, Albuquerque, NM
1997 – 1999	Staff Geologist – Professional Services Industries, Inc. (PSI), Cleveland, OH
1994 – 1997	Staff Geologist – Terranext, Inc., Denver, CO

Training:

- OSHA Health and Safety Training, 29 CFR 1910.120, (40-Hour), 1994
- OSHA Health and Safety Training, Annual Refresher, (8-Hour), current
- DOT HM 126 Hazardous Material Transportation Training, 49 CFR 172.700, 1996
- Confined Space Entry Training, 29 CFR 1910.140, 1995
- National Ground Water Association – Fate and Transport of Light Non-Aqueous Phase Liquids/Dense Non-Aqueous Phase Liquids (LNAPLs/DNAPLs) Training, 1995
- Asbestos Inspector and Management Planner (Toxic Substance Control Act Sec. 206, Title II) Training, 1997
- Asbestos Contractor Supervisor (Toxic Substance Control Act Title II and AHERA) Training, 2000
- Vapor Intrusion Training, 2011
- Red Cross First Aid/CPR Training, current
- Sulfuric Acid Handling Training, 2013
- Interstate Technology Regulatory Council (ITRC) Training – Vapor Intrusion Pathway: Investigative Approaches for Typical Scenarios (2008)

Joseph "Joe" Tracy is a Principal Geologist and Senior Vice President at INTERA with a BS degree in environmental geology and over three decades of consulting experience focused on environmental assessments, site investigations, remedial planning, and site remediation. He has evaluated the environmental impacts to soil and groundwater at leaking petroleum storage tank (PST) sites, Superfund sites, Brownfield sites, and a variety of operational and former industrial properties and facilities. Mr. Tracy leads multidisciplinary teams of scientists and engineers to complete investigations and remediation of contaminants that include petroleum hydrocarbons, heavy metals, chlorinated solvents, polychlorinated biphenyls (PCBs), per- and polyfluoroalkyl substance (PFAS), and asbestos. He develops remedial plans under voluntary remediation and Superfund programs and prepares and implements work plans, quality assurance project plans, and remedial action plans for Brownfields and other redevelopment projects. Mr. Tracy's experience also includes performing investigations and related work at municipal landfills where activities have included the installation and monitoring of landfill gas (LFG) probes, preparing landfill management plans, operation and maintenance of LFG extraction/destruction systems, developing and implementing grading and drainage plans, and profiling the nature and extent of landfill wastes. Mr. Tracy is a Senior Vice President within INTERA's Southwest Region, where he oversees multi-site contracts with state, county, and municipal agencies, and is responsible for directing all environmental services marketing efforts within the INTERA Mining and Environmental Line of Business Unit.

Project Experience – Environmental

Santa Fe County Investigation of Per- and Polyfluoroalkyl Substance Contaminants in Domestic Wells, Santa Fe County, NM. 2024 – Present.

Project Manager. Santa Fe County The sampling and analysis of drinking water in October 2023 from six domestic wells within the communities of La Cienega and La Cieneguilla, Santa Fe County discovered PFAS at concentrations above the safe drinking water standards recently established by the USEPA. Driven by the health concerns related to this discovery, the County, in collaboration with the New Mexico Environment Department (NMED) Construction Programs Bureau (CPB) and the City of Santa Fe, successfully acted to obtain a USEPA grant to help fund the assessment of the potential PFAS impacts to area groundwater. Mr. Tracy is leading the INTERA Team to achieve the overarching project goals of determining the extent of the PFAS contamination in groundwater and developing alternatives for mitigation and/or remediation of the contamination. Mr. Tracy is currently assisting the County with the initial project activities including the development of a conceptual site model (CSM) and selecting additional domestic wells for PFAS sampling. In addition, Mr. Tracy is working with INTERA subcontractor, John Shomaker and Associates, Inc. (JSAI), in the development of a groundwater flow model, in an effort to determine preferential flow paths for underlying PFAS contamination in ground water.

Environmental Investigations, City of Albuquerque – Department of Municipal Development, Albuquerque, NM. 2005 – 2018 and 2023 – Present. *Contract Manager and Project Manager.* Contract Manager City of Albuquerque Department of Municipal Development Environmental On-Call Services contract. Performed Phase I and Phase II Environmental Site Assessments (ESAs) for the City of Albuquerque (COA) as part of this contract. In addition, provided environmental assistance to the COA Department of Municipal Development on an as-needed basis as project environmental issues develop. Environmental issues included extraction well evaluation at the former Los Angeles Landfill, maintenance and monitoring services at the former Los Angeles Landfill, geophysical investigations in the downtown Albuquerque area, micro-turbine analysis at the former Los Angeles Landfill, engineering evaluation/cost analysis (EE/CA) for the Hotel La Posada del Albuquerque, conducting a soil vapor survey at the City of Albuquerque 1st and Central Site which is located adjacent to the former BNSF East Bound Fueling Facility, ambient air monitoring within residential houses in the Albuquerque area, and asbestos and lead-based paint surveys at several city facilities (i.e., Los Duranes Community Center, Jeanne Bellamah Community Center, Holiday Park Community Center, Barelas Community Center, Mesa Verde Community Center, APD Education Building, Dennis Chavez Community Center, Rio Grande Fire House, Pino Yard Senior Games Building, North Valley Senior Center, Palo Duro Senior Center, Environmental Health Department offices), city-owned former historic hotels (El Vado and De Anza), and city-acquired properties (Brown Property, Caravan Building, Loan Pawn Shop). Facilitated on-call projects such as the development of a CSM for the Kirtland Air Force Base Fuel Spill, development of a voluntary remediation approach for at the Marble-Arno Property and the downtown Railyard, locating a new COA storm water facility, conducting an archaeological survey at the Singing Arrow Community Center, and several landfill maintenance projects for the COA Solid Waste Division Cerro Colorado landfill. Currently projects for the COA include the assessment of asbestos and lead-based paint in several buildings at the COA BioPark (Zoo), which is undergoing a full-scale remodeling and renovation, as well as continuing groundwater monitoring activities at the Marble-Arno Property under the Voluntary Remediation Program (VRP). Secured an additional environmental services on-call contract with the COA in late 2023 and work began in 2024. Mr. Tracy is currently leading the environmental surveys associated with the renovation of the COA Gibson Health Hub (GHH) and several COA community centers and libraries.

Santa Fe Well-S (Santa Fe Generating Station) Petroleum Storage Tank Investigation, Public Service Company of New Mexico, Santa Fe, NM. 2018 – Present. *Project Principal.* Providing contract support for the investigation of fuel and chlorinated solvent release at a former power generating station and other, off-site sources. The release(s) have impacted a City of Santa Fe municipal supply well, causing production of drinking water from this well to be discontinued. The investigation includes the installation of 25 monitoring wells to depths ranging from approximately 300 to over 400 feet using roto-sonic drilling and sampling techniques. Portable gas chromatography and a photoionization detector are being used to analyze soil and groundwater samples in the field so that contaminated zones can be identified, and real-time, informed decisions can be made concerning screen intervals. The results of the in-field screening have identified zones, some as thin as three feet, containing mobile light non-aqueous phase liquid (LNAPL) and conveying highly contaminated groundwater. Responsibilities have included contract and technical discussions with the client and project team as well as attending several scoping and status meetings with Public Service Company of New Mexico, the City, and NMED representatives. In addition to providing support of environmental services associated with the fuel plume, also reviewing efforts associated with State 1 abatement plan (S1AP) investigations regarding chlorinated solvents and nitrates contamination present in ground water at the site.

Hop Canyon/Waldo Mill Site Phase II Site Investigation and Voluntary Remediation Program Activities, ASARCO, Magdalena, NM. 2000 – 2002 and 2018 – Present. *Project Principal, Project Manager, and Staff Geologist.* Implemented a Work Plan to characterize an American former Smelting and Refining Company (ASARCO) mining mill tailings site in Magdalena, New Mexico. The voluntary remediation activities included characterization and removal of affected soil and construction of an onsite tailings impoundment capped with clean soil. Surface drainage issues included interfacing with the U.S. Army Corps of Engineers to present erosion of the impoundment cap and surrounding soils. Initiated additional work at this site on behalf of the ASARCO Trust in 2018. INTERA is currently responsible for Site Caretaker Operations, which are essentially weekly Site visits to make certain the tailings impoundment cover remains in good condition. INTERA will prepare a VRP Work Plan to guide the repair work of the tailing impoundment cover. NMED and/or the ASARCO Trust identified several areas of the tailings impoundment cover in 2017 that are recommended for repair. The remainder of the ASARCO property at the site was legally transferred into ASARCO Trust ownership in late 2023. Currently working with ASARCO Trust representatives and the INTERA Project Team to design and conduct cap repair activities and secure a VRP Conditional Certificate of Completion (CCOC).

Las Vegas Patrol Yard Groundwater Remediation System Operation and Maintenance, New Mexico Department of Transportation, Las Vegas, NM. 2017 – Present. *Project Principal.* Began operation and maintenance (O&M) activities of a groundwater remediation system associated with the two contaminant plumes: an inorganic (chloride and total dissolved solids [TDS]) plume and organic (petroleum and chlorinated compound) plume located at the New Mexico Department of Transportation (NMDOT) Las Vegas Patrol Yard. The groundwater remediation system was originally operated by another firm but due to performance issues INTERA was asked to conduct O&M activities at the site. The groundwater remediation system consists of five interceptor trenches (four of the trenches focus on capturing the inorganic and petroleum plume and one focuses on capturing the chlorinated solvent plume) which capture contaminated groundwater and convey the water to two treatment containers. The treatment system consists of a filter media capable of removing iron and manganese, an air stripper which targets volatile organic compounds (VOCs), and reverse osmosis (RO) membranes which removes TDS and chlorides. The treated groundwater is reinjected into the subsurface via three infiltration trenches. Monthly influent and effluent samples are collected from the groundwater remediation system to ensure the system is operating effectively and that the effluent water quality meets the approved discharge permit requirements. O&M activities include maintaining all parts (pumps, inline sensors, filters) of the system, monitoring the dosing rate of the system additives (sodium hypochlorite, sodium metabisulfite, caustic soda, and anti-scaling agent), analyzing field water quality parameters/compounds (pH, TDS, free chlorine, total iron, total manganese) using handheld meters or Hach kits, replacing filters, monitoring system pressures, maintaining adequate additive volumes in vessels, and performing high- and low-pH cleaning of the RO membranes when necessary. The data collected during O&M activities and recorded remotely using a programmable logic controller is tracked and analyzed on a weekly basis to make sure the system is operating as designed. Treatment system operation has been suspended in recent years due to a discharge permit issue, but are estimated to be re-started in 2024.

Investigation of the Former Frank Ortiz Landfill, City of Santa Fe, NM. 2016 – Present. *Project Manager.* The Frank Ortiz Landfill operated as a City of Santa Fe municipal landfill between 1954 to 1968. Since no solid waste management regulations were in place during this period of operation, the landfill is not regulated by the NMED Solid Waste Bureau. The landfill site was re-developed by the city with soccer fields from 1987 to 1993 and currently serves as a dog park. In April 1993, soil vapor samples were collected from the fill and soil cover areas. Laboratory analysis of the samples showed that they contained hydrocarbons, chlorinated solvents, and chlorinated solvent degradation products. Concentrations of some of the contaminants exceeded 1,000 parts per billion. A single groundwater monitoring well (Ortiz Park No. 1) was installed approximately 500 feet southwest of the landfill in 2004. A groundwater sample collected from the well indicated that groundwater had been impacted from VOCs, hydrocarbons, metals, and nitrogen believed to have originated at the landfill site. Periodic groundwater and soil vapor sampling have continued at the site since 2004. An S1AP was developed for the Site in 2010 and submitted to NMED for review and approval. In 2013, NMED issued a letter noting several deficiencies in the S1AP including: the lack of a plan for maintenance of a two-foot cap over the former landfill; inadequate definition of the nature and extent of the landfill waste; inadequate definition of contaminant concentrations in the vadose zone below the waste; inadequate definition of the potential contaminant impacts to groundwater; the lack of a long-term monitoring program; and the need for a quality assurance project plan, health and safety plan, and a schedule for implementing the additional investigation activities and analyses necessary to address the identified deficiencies.

In 2015, at the request of NMED, the City conducted a geophysical investigation to define the areal extent of buried waste at the landfill. INTERA was awarded a contract from the City in September 2016 to help address the remaining S1AP deficiencies. Helped develop and reviewed an integrated Sampling and Analysis Plan (SAP)/Quality Assurance Project Plan (QAPP) for the former landfill that was submitted to and approved by NMED. The SAP outlined several steps for the City to address the noted NMED concerns, including: installation of test pits to determine type and extent of waste; the collection of soil samples to determine the impact to soil immediately below the buried waste (extent of contamination in the vadose zone); installation of groundwater monitoring wells; groundwater sample collection; and an approach for a long-term groundwater monitoring program. Field sampling activities associated with the SAP/QAPP were completed in July 2017. Met with the NMED to go over the report findings and discuss recommendations for next steps. The investigation revealed the approximate extent and depth of buried waste, determined the extent of the vapor plume, and provided information on the landfill cover content and thickness. To address NMED's final concern, additional groundwater monitoring wells co-located with three soil vapor monitoring wells and an additional soil vapor monitoring well were recommended and the approximate locations were determined.

The additional wells were installed at the Ortiz Landfill in late 2019 and early 2020 and a final report was submitted to by INTERA to NMED in May 2020. The report findings indicated a direct impact to Site soil vapor likely from the presence of the buried waste, but it appears that Site groundwater is largely unimpacted. INTERA has successfully negotiated with NMED a period of monitoring work for the three years and includes the addition of Surface Emission Monitoring (SEM) on a quarterly basis of the entire Ortiz Landfill property (historic fill area and adjacent land within the property boundary). Once this period has expired, Mr. Tracy will work with City and NMED representatives to determine the need and location(s) for any future additional groundwater and soil vapor monitoring well installations.

The INTERA former Frank Ortiz Landfill work is being conducted in concert with additional investigation and monitoring activities at the adjacent Paseo de Vista (PDV) Landfill. The monitoring and maintenance of the PDV Landfill was added to the INTERA Ortiz Landfill contract by the City in 2019. The work at PDV has largely been conducted by personnel from INTERA's partner, Parkhill, under INTERA oversight. All PDV deliverables are prepared by Parkhill and reviewed by Mr. Tracy prior to submittal to the City and NMED. Mr. Tracy currently leads the long-term monitoring (LTM) activities at both landfills on behalf of the City and manages subcontractor Parkhill. The City of Santa Fe has requested that INTERA assist with NMED updated S1AP activities which are scheduled to begin in July 2025. This will consist of the installation of an additional ground water monitoring well, several LFG monitoring wells, and sampling ground water for PFAS in addition to the required analysis suite.

North Railroad Avenue Plume Superfund Project, New Mexico Environment Department - Groundwater Quality Bureau, Española, NM. 2016 – Present. *Project Principal*. A bio-amendment injection event was performed to remediate residual contamination (tetrachloroethene [PCE] and daughter products) in discrete intervals of fine-grained material identified in the source area (SA) and hot spot (HS) of the site. INTERA evaluated available data, identified six treatment areas, determined targeted treatment intervals, selected emulsified soybean oil as the carbon substrate, and devised an injection method to ensure that the substrate is delivered precisely. INTERA oversaw the bio-amendment substrate injection event which was conducted in two separate events: the first was completed in April 2017 via a direct-push injection tool within sonic casing and the second event was conducted with direct sonic injection in September 2017. INTERA conducted follow-up performance groundwater monitoring. Results of the performance monitoring events confirmed the successful distribution of the carbon substrate through the presence of the dye tracer (Rhodamine WT) and elevated total organic carbon (TOC) in monitoring wells within the anticipated radius of influence (ROI). Additionally, the groundwater analytical results from the first performance monitoring event provided evidence that in-situ reductive dichlorination was enhanced through the injection of the carbon substrate. Performance monitoring is currently ongoing. Serves as a Project Principal for INTERA's NMED contract, which includes INTERA's work at the NRAP site as well as INTERA's work at the Eagle Picher site in Socorro, New Mexico.

Former Central Works Equipment Facility Remediation Activities "COA Rail Yards," City of Albuquerque, NM. 2006 – Present. *Project Manager.* Managed the removal of contaminated soil at the former Central Works Equipment (CWE) facility in Albuquerque, New Mexico. The project included the removal of approximately 600 cubic yards of lead-contaminated soil previously stockpiled at the site. Developed a Work Plan to investigate petroleum-hydrocarbon and metals contamination at this site using Targeted Brownfields Assessment (TBA) funding. Led an additional Phase II investigation at the site in 2012. The Phase II investigation consisted of surface and subsurface soil sampling, building sub-slab vapor sampling, and groundwater sampling. This effort was conducted to determine what impacts (if any) the historical operations of the site as a railyard would have on future redevelopment. It was determined that a petroleum-hydrocarbon plume was present at the southwest corner of the site. Limited impacts were present in surface and subsurface soils. Developed several cost estimates for the remediation of soil and groundwater at the site for the city to use depending on the redevelopment scenario they selected. Further site investigation work was completed in 2012 as the city moved toward redevelopment of the site. Served as Project Manager for an Additional Site Investigation (ASI) that included completing a data evaluation/remediation options document to compile and analyze all existing contaminant data for the entire city railyard, which included former tank areas, oil/water separator, and a former locomotive roundhouse, among others. The evaluation resulted in identifying several data gaps which were investigated during the ASI. Contaminants of concern for this site included VOCs, TPH, PAHs, lead, and arsenic. The site investigation included (1) collecting surface soil samples from thirteen locations, (2) drilling oversight of 18 soil borings using direct push technology methods, (3) collection and screening of soils samples using a photoionization detector (PID) and Dexsil PetroFLAG field test kit to aid in selection of samples for laboratory analysis, (4) collection of eleven groundwater samples with the SP-16 sampler, temporary monitoring wells, and

existing monitoring wells, (5) installation of a soil vapor sample point, and (6) collection of a soil vapor sample using a Vapor PinTM. INTERA provided the client with a completed report, which included several remediation scenarios based on various redevelopment options.

Oversaw the remediation of the Blacksmith Shop building at the CWE facility in 2013. The remediation work consisted of the abatement of asbestos as well as the encapsulation of lead-based paint on the ceiling of the Blacksmith Shop. The Blacksmith Shop was redeveloped by COA into an open-air market following remediation activities. The redeveloped Blacksmith Shop opened in June 2013.

Worked with the COA selected developer, Samitaur, on a VRP approach for all portions of the Railyard property. This included a multi-option remediation approach as several redevelopment options (residential, commercial, open space) will be implemented at the site. Oversaw the development of a CSM for the site. INTERA compiled all available information related to environmental site conditions such as historical soil and groundwater data to help determine the nature and extent of the contamination across the site with regard to depth and COCs in the CSM to provide a foundation for remedial action decisions. Activities completed as part of the CSM included developing a database in Microsoft Access, connecting the database to ArcGIS to allow for visual data analysis, and identifying key data gaps. The CSM was also used as a foundation for development of a remediation work plan required to address data gaps at the site. The remediation work plan was developed in conjunction with potential redevelopment scenarios identified for the site. Implementation of the remediation work plan was completed early 2017 and included the collection of soil samples, soil vapor samples, groundwater samples, sub-slab soil vapor samples, and the completion of asbestos and lead-based paint surveys on all site buildings. The results of the data collection were compiled into ten different reports, one for each of the 10 railyard parcels. The intent of separate reporting for each of the 10 parcels was to allow phased development of the site over a lengthier time period than is customary under the VRP.

Contracted in late 2018 to develop a revised VRP Application and Preliminary Work Plan for the COA Rail Yards, splitting the COA Rail Yards into two VRP sites (COA Rail Yards North and COA Rail Yards South). Currently, the COA Rail Yards North has received conditional eligibility to enter the VRP and Public Notice and a Public Meeting was held in April 2019 to outline for the public the proposed remedial actions. Assisted with the Public Notice requirements for the COA Environmental Health Department personnel. The COA implemented soil removal activities within the COA Rail Yards North in May and June 2019.

Contracted in early 2020 to help the COA develop a VRCR for the COA Rail Yards North and to implement an off-Site groundwater monitoring well installation Preliminary Work Plan for the COA Rail Yards South. INTERA developed a VRCR for the COA Rail Yards North and submitted it to NMED in September 2020. INTERA also, as requested by the COA, developed, submitted to NMED, and received NMED approval for a Contaminated Soil Management Plan (SMP) in July 2020. This SMP will be followed as additional impacted soil is excavated at the COA Rail Yards. Either developed or provided final review of this documents. INTERA installed 5 ground water monitoring wells at off-site locations surrounding the COA Rail Yards South. These monitoring wells were installed in February 2021. Provided interface with the client during the field work and also provided daily direction to the INTERA field team. Finally, INTERA will work with the COA's Rail Yards management team to develop the remediation approaches for the COA Rail Yards South depending on the selected future development. Secured a VRP CCOC for the Rail Yards North in 2021. Currently leading the LTM activities associated with ground water and soil vapor at the Site and leading efforts to secure a CCOC for the Rail Yards South. In addition to LTM activities, currently providing quality assurance inspections for the installation of a soil vapor mitigation system in the Boiler Shop, prior to it's redevelopment as a movie studio for CNM (abqrailyards.com).

Technical Support Services for the Red Hill Bulk Fuel Storage Facility, Honolulu Board of Water Supply, Honolulu, HI. 2015 – Present.
Project Manager. Providing third-party technical review of technical documents and data produced and collected by the U.S. Navy and its contractors at the Red Hill Bulk Fuel Storage Facility (RHBFSF). The RHBFSF contains 20 large field-constructed underground storage tanks, each containing approximately 12.5 million gallons of fuel. These tanks are located at depths ranging from 120 to 175 feet below ground surface within the Koolau Basalt and lie 100 feet above the aquifer. Fuel leaks from the facility both historic and recent (January 2014 – 27,000-gallon release) have impacted the underlying EPA-designated Sole Source Southern Oahu Basal Aquifer and are potentially threatening the Honolulu Board of Water Supply (BWS) water supply wells and production shaft. The 2014 release resulted in the Navy, the EPA, and the Hawaii Department of Health (DOH) signing an Administrative Order on Consent (AOC) to assess the RHBFSF and determine what impact this release and previous releases have had on the environment and to determine what the appropriate tank

upgrade solution may be. Activities included reviewing technical reports and extracting and compiling data collected at the RHBFSF from these reports. Reviewed and provided over 135 comment letters to date to the DOH and the EPA on various Navy work plans and reports. Led the INTERA Team's development of a CSM that describes the processes and features controlling the migration of fuel contamination and identifies potential exposure pathways and receptors. Additionally, supported the development of a Monitoring Well Construction and Installation Plan, sampling plan, and quality assurance plan for several sentinel wells installed by INTERA for the BWS. The first monitoring well was completed in 2017, and quarterly groundwater monitoring was in 2017 and 2018. Semi-annual sampling of this monitoring well began in 2019 and continues in 2021. Hired Exponent as a subcontractor and oversee their technical work associated with tank infrastructure, release detection, corrosion and metal fatigue, risk assessment, and toxicology services. This expertise has been needed on various comment letters developed by INTERA for the BWS since the initiation of the contract. Representing BWS interest in numerous technical working meetings associated with the Red Hill AOC and the AOC Statement of Work (SOW) since contract initiation in 2015. Participates in Groundwater Modeling Working Group meetings to review the progress of the Navy's flow and transport groundwater model. Assists the BWS with the development of community meeting and BWS Board presentations and regularly attends all public meetings in California and/or Hawaii held by the EPA, DOH, and the Navy on the Red Hill matter. Negotiated a 2020 contract renewal with BWS that extended INTERA's work on this project for the next several years.

Led INTERA's efforts in 2021 and 2022 to support the BWS in response to the Red Hill Hawaii Department of Health (DOH) Emergency Order which requires the complete defueling of the facility by June 2024 (defueling was completed by the Navy in March 2024). These efforts have included reviewing and commenting on Navy deliverables (Defueling Plan, Closure Plan, Notice of Intent [NOI] data reports, groundwater flow model reports, etc.) and providing this information to BWS. In addition, because of the May and November 2021 fuel releases at Red Hill, the BWS has been forced to shut down several drinking water sources in the area. Mr. Tracy is currently focused on supporting the BWS with the identification of monitoring well and exploratory production well sites and working with the INTERA Project Team to design each monitoring and exploratory well and exploratory well pumping tests. INTERA has developed well designs for over ten monitoring wells and four exploratory well locations and is currently developing the drilling plans and testing plans associated with these wells. Assisting the BWS with the development of bid documents to procure drilling services for monitoring and exploratory well installations. Providing management and scheduling assistance for INTERA field teams overseeing well installation activities by BWS general and drilling contractors.

Sites Assessments, New Mexico Department of Transportation, Various Locations, NM. 2015 – Present. *Principal in Charge.* Provides senior technical review of Initial Site Assessments (ISAs), preliminary site investigations (PSIs) and Detailed Site Investigations (DSI) at several NMDOT construction project sites in New Mexico. These NMDOT projects involve the evaluation of properties either NMDOT-owned or NMDOT right-of-way (ROW) acquisitions as part of highway improvement projects. The ISAs completed generally follow the ASTM Standard E1527-13 and the NMDOT Handbook for site assessments. The PSIs and DSI include Phase II activities (investigative excavations, soil boring drilling, soil sampling, and geophysical surveys) for further evaluation of NMDOT property. Supervises the field teams conducting this work and provides senior technical review of all project deliverables. Manages overall contract issues and interfaces directly with the INTERA Project Manager and NMDOT management. Most of these assessments are completed in areas where NMDOT is going to expand their infrastructure with either additional traffic lanes or an upgrading of their maintenance yards.

Site Monitoring and Emergency Response Contract, New Mexico Environment Department - Petroleum Storage Tank Bureau, Various Locations, NM. 2014 – Present. *Project Principal.* Providing administrative and technical review of work conducted for contaminant characterization investigations and groundwater monitoring activities. These activities seek to determine the nature and extent of subsurface petroleum hydrocarbon contamination originating from above ground and underground storage tank sites. Investigations include the analysis of soil, groundwater, and soil vapor impacts to these various sites across New Mexico. Work includes the following partial listing of INTERA Petroleum Storage Tank Bureau (PSTB) state-led sites: Barelas Bridge Site in Albuquerque, New Mexico; Bell Gas Site in Truth or Consequences, New Mexico; Brewer Self-Serve Site in Roswell, New Mexico; City Market Site in San Miquel, New Mexico; Frank's Conoco Site in Bernalillo, New Mexico; Corrales Chevron in Corrales, New Mexico; Robinson Texaco in Taos, New Mexico; Rodgers Drilling Site in Albuquerque, New Mexico; Village Market and the Former Caldwell Motors sites in Belen, New Mexico; and the Montoya Well Site in El Prado, New Mexico.

Dry Cleaning Site Investigation and Remediation of Tetrachloroethene Contamination, Elite Laundry and Cleaning, Gallup, NM. 2013 – Present. *Project Manager.* Leading efforts to investigate and remediate groundwater impacted by PCE as a result of previous releases from this operating dry-cleaning facility. The impacted groundwater was discovered during a Phase II ESA conducted on an adjacent property. In response to a letter from NMED to address the contamination, efforts have included providing technical support and advice to Elite Laundry and Cleaners representatives to determine the most appropriate path forward. This included addressing the identified contamination under the NMED VRP. Prepared and submitted a VRP work plan and VRP application to NMED. The proposed VRP investigation activities include the installation of monitoring well on- and offsite to characterize and delineate the PCE in groundwater contamination. The field activities identified in the VRP Work Plan were initiated in late 2018 and early 2019, which included the installation of additional monitoring wells as well as subsurface soil and indoor air vapor sampling activities. Off-site passive vapor sampling activities were completed by INTERA under Mr. Tracy's oversight at the Site and within the area in 2020. Additional site characterization activities and preliminary design for a remediation system to prevent the off-site migration of contaminants in soil vapor and ground water are planned for 2025, including the installation of a soil vapor extraction system for the removal of VOCs in soil gas to prevent the potential for offsite migration.

Judge Steve Herrera Judicial Complex Site Investigation, Remediation, and Monitoring, Santa Fe County, NM. 2009 – Present. *Contract Manager and Project Manager.* Leads INTERA's efforts to develop a remedial solution for the Santa Fe County Judicial Complex which involves interfacing with both the NMED VRP and PSTB. INTERA was contracted by Santa Fe County in March 2009 to support their efforts to re-develop a Brownfields property comprising a three-story judicial complex and associated plaza and subsurface parking garage in downtown Santa Fe, New Mexico. A large excavation and steel/wood shoring system was constructed beginning in the fall of 2008. During shoring activities, a two-foot layer of LNAPL was discovered near the water table. INTERA performed additional site investigation activities and determined that the LNAPL plume was predominately present in the proposed location of a subsurface two-story parking garage. Construction of the garage and associated judicial complex was delayed, enabling the county and NMED's PSTB to develop an appropriate response action. PSTB subsequently designed and is operating a soil vapor extraction system for the areas outside of the judicial complex excavation to remediate the historic contamination. The county was responsible for the remediation of their property even though they were not a responsible party. Led the development of a petroleum contaminated soil (PCS) work plan including development of a dewatering plan, excavation and removal of over 20,000 tons of PCS, installation of a vapor intrusion/ground water barrier (liner) on all parts of the development located below grade, and development of a vapor monitoring system for the final development of the site. The Work Plan was approved by VRP and PSTB. The excavation work is complicated because of two primary factors: (1) soil must be excavated below the water table requiring dewatering for safe removal; and (2) construction activities are scheduled to take place immediately following soil remediation efforts, requiring that dewatering continue for several months until construction infrastructure can be put in place below the water table for the two-story parking garage. Helped initiate the development of a soil gas passive venting system around the subsurface parking garage and initiated the installation of this system in January 2012.

Additionally, prepared and submitted a VRP application to secure a certificate of completion for the remediation work; supervised risk assessors in the development of a document pertaining to future building occupancy and currently participates in numerous stakeholder meetings with the county and PSTB representatives. Either conducted or supervised INTERA staff employees or subcontractors in assessing, reviewing, and selecting mitigation measures for the complex; identifying and developing measures to isolate the proposed infrastructure from contacting LNAPL remaining in the plume around the building (i.e. liner selection process); LNAPL sampling and characterization; air emissions testing and permitting; waste profiling; preparation and submittal of a groundwater discharge permit application; LNAPL removal and disposal; LNAPL bail-down testing; a Phase I ESA of the site; slug testing to determine aquifer properties; weekly VRP update reporting, and subcontractor oversight of remediation activities. The PCS removal activities were completed at the site in February 2011. Continues to work with the county to develop a VRP Completion Report and secure a CCOC for the site. The judicial complex was completed in February 2013 and began operating in June 2013. Continues to oversee quarterly groundwater monitoring activities at the site as part of the county's VRP Work Plan. Secured a Voluntary Remediation Agreement (VRA) for the site on July 9, 2015. Completed the Voluntary Remediation Completion Report (VRCR) for the site in February 2016 and assisted the county in obtaining a VRP CCOC from NMED also in February 2016. Groundwater monitoring activities were completed by INTERA at the site in October 2016. Currently assisting the county by reviewing the work conducted by the PSTB at the site and providing status reports to the county. For example, observed multi-dual phase extraction activities conducted by PSTB and their contractor at the site in 2017. The final goal is to assist the county in

securing a VRP CCOC with only a land use restriction in 2024. Helped the County discontinue the NMED judicial complex discharge permit (NMED DP-1747) in late 2023 and currently negotiating on the County's behalf with NMED to modify the VRP CCOC in 2025.

SunZia Transmission Line Phase I Environmental Site Assessment, New Mexico and Arizona Approximate 550-Mile Corridor. 2021 – 2024. *Project Principal*. INTERA was retained by SunZia Transmission, LLC located in Albuquerque, New Mexico to perform a Phase I ESA for a 550-mile corridor starting southeast of Phoenix, Arizona and terminating in Corona, New Mexico. The proposed transmission line would ultimately aid in the transportation of wind farm produced electricity across New Mexico and into the Tucson area of Arizona. Provided Project Principal review and contract management duties for the project. Worked with the Project Team to develop Phase II site characterization goals for the recognized environmental conditions (RECs) identified during the Phase I ESA work. The Phase II recommendations included geophysical surveys for two former bombing ranges that the Project Corridor intersects in New Mexico and for soil cleanup of an above-ground storage tank release at a commercial agriculture operation at a property in Arizona. The geophysical investigations for the two former bombing ranges were completed in 2023 (no mitigation needed) and the soil cleanup for the Arizona commercial agriculture operation is scheduled to be conducted in 2024.

Data Gap Monitoring Well for the Albuquerque Bernalillo County Water Utility Authority, Albuquerque, NM. 2022 – 2023. *Project Manager.* The Albuquerque Bernalillo County Water Utility Authority (ABCWUA) received funding from the State of New Mexico CPB in 2021 to drill, install, and sample a monitoring well downgradient of the ethylene dibromide (EDB) and petroleum hydrocarbon plumes in groundwater migrating offsite from Kirtland Air Force Base (KAFB). Provided technical input on recommended location and design of a >500-ft deep monitoring well to address a potential data gap toward the distal end of the known EDB plume. Led the installation of the monitoring well (sonic drilling methods) and initial well development which was completed in April 2022. Led initial one-year long-term monitoring activities of the data gap monitoring well in late 2022 and early 2023 until the LTM duties were shifted from INTERA to an ABCWUA on-call contractor.

Kirtland Air Force Base Environmental Baseline Surveys, Albuquerque Bernalillo County Water Utility Authority, NM. 2018 – 2022. *Project Principal.* Provided technical oversight and review of final deliverables for the INTERA effort to conduct two Environmental Baseline Surveys (EBS) for the ABCWUA to meet appropriate property due diligence practices for the easement agreement between ABCWUA and KAFB. The property locations included a 5.29-mile-long easement and a 24-acre parcel, all located on KAFB and Department of Energy (DOE) property. The project includes the ABCWUA installing an interceptor pipeline and booster station and INTERA is responsible for all federal due diligence requirements associated with construction projects occurring on federal facilities. Responsible for internal team communications, client meetings, and final review of the two EBS reports. The EBS reports were completed and approved by the ABCWUA and KAFB in 2022.

Phase I Environmental Site Assessment of Mt. Chalchihuitl and Cerrillos Gravel Products Properties, Santa Fe County, Cerrillos, NM. 2004 – 2022. *Project Manager.* Project Manager for the Phase I ESA of the combined 745-acre Mt. Chalchihuitl and Cerrillos Gravel Products properties. Assessment activities are being conducted using the EPA's All Appropriate Inquiry (AAI) and ASTM Standard E1527-05 as guidance. Performed risk assessment and remediation alternative analysis activities at the Mt. Chalchihuitl portion of the site (545 acres) in 2004. The entire site was historically used for mining activities, located at the center of the Cerrillos Mining District South area. Santa Fe County plans to re-develop the site as open space by incorporating it into the Cerrillos Hills Historic Park, and INTERA continues to work with Santa Fe County to determine remediation options for the site. The development objective is to include these properties in the Cerrillos Hills Mining District Open Space Park.

Developed a VRP Work Plan for the site in 2012, which selected a previously determined remedial option and submitted the Work Plan to Santa Fe County for review. The selected remediation includes the construction of tailings impoundment and cap in a former gravel pit and long-term monitoring to make certain the cap integrity is secured. The remainder of the site will be used as a public open space, allowing the public to observe some of the oldest mines in North America. Completed and submitted the VRP Application and Preliminary VRP Work Plan for this Site in September 2017. The county would like to acquire the properties in 2018 and begin soil remediation as soon as possible after property acquisition. Currently assisting the county legal team with the development of a VRA between the county and NMED. Also, were recently awarded a contract to sample soils in the arroyo to the south of the Cerrillos Gravel Products property and to sample three area drinking water wells to determine any potential water quality impacts.

Responded to a Letter of Interest (LOI) released by the County in 2019 to assess ground water conditions at the Mt. Chal site. After selection by the County in response to the LOI, led the INTERA Team in sampling an upgradient private water well and a monitoring well at the Cerrillos Gravel Products property. Determined elevated metals concentrations are present in site groundwater and offered recommendation to the County for addition work at the site and the potential installation of a new monitoring well in a down gradient location. Due to a disagreement on overall value with the landowner (both property and mineral rights), the County passed a resolution and discontinued their Mt. Chalchihuitl acquisition initiatives in 2022.

Redevelopment of the Former First Baptist Church Site, Lobo Development, Albuquerque, NM. 2013 – 2021. *Project Manager.* Provided oversight for voluntary remediation activities associated with redevelopment of this property in downtown Albuquerque. Previously conducted Phase I and II ESAs and identified subsurface soil and groundwater contamination that was believed to be the result of a diesel fuel release at the adjacent Burlington Northern Santa Fe (BNSF) Railway Railyard. Evaluated site investigation data and determined that the property had been impacted by both off-site sources and historic site uses that required limited remediation prior to site redevelopment. The site was entered in the NMED VRP to secure a Certification of Completion (COC) to facilitate redevelopment. Activities included interaction with NMED to ensure the COC was issued in a timely manner and assisting in obtaining a Covenant Not to Sue (CNS). After receiving the COC and CNS, Lobo Development acquired the property in 2014 and the site was re-developed as part of the City of Albuquerque's "Innovate ABQ" development initiative. Worked with the Innovate ABQ development team to manage the environmental risks associated with the planned redevelopment of the Site. Assisted the Site developer (Signet) with renovation and demolition activities completed within the former First Baptist Church in 2016. Assisted the developer with VRP reporting activities in 2016, 2017, and 2018 associated with the construction of a three-story building at the site. VRP reporting activities are required in order to maintain the COC by guiding the developer to implement the proper engineering controls. The newly constructed three-story commercial building is known as the "Lobo Rainforest" and serves as an entrepreneur center for business associated with "Innovate ABQ," a downtown Albuquerque technology park. Led a team that updated the Phase I ESA in 2020 on behalf of the University of New Mexico (UNM). Also helped secure a U.S. Environmental Protection Agency (EPA) "Comfort Letter" for UNM and a CNS prior to the property transfer. UNM assumed ownership of the site in late December 2020.

Redevelopment of the Former Galles Chevrolet Automobile Dealership Property, University of New Mexico, Albuquerque, NM. 2018 – 2020. *Project Manager.* Provided oversight for voluntary remediation activities associated with redevelopment of this property in the UNM area of Albuquerque. Previously conducted Phase I and II ESAs identified subsurface soil and groundwater contamination that was believed to be the result of gasoline and diesel fuel releases from former underground storage tanks (USTs) located at the property. Additional environmental contamination was also identified by the operation of over 70 underground hydraulic lifts as well as five former oil/water separators (OWS) in use at the property. Evaluated site investigation data and determined that the property has been impacted by historic site uses that required limited remediation prior to site redevelopment. The site was entered in the NMED VRP to secure a COC to facilitate redevelopment. Activities included interaction with the NMED to ensure the COC was issued in a timely manner and assisting in obtaining a CNS. The issuance of the COC and CNS are still pending. Conducted an on-site soil vapor survey to determine areas of elevated soil vapor concentrations and developed a plan for the construction and use of vapor intrusion barriers for any newly constructed buildings at the Site. Evaluated the remediation activities conducted by the landowner (Sandia Corporation) to determine what impact, if any, the remedial work may have on future UNM activities at the site. Worked with subcontractor DC Environmental to prepare a cost estimate associated with the asbestos and lead-based paint abatement at current Site buildings prior to demolition and/or renovation. UNM leased the property in late 2019. Worked with UNM Medical Center personnel to assist with the development of short-term uses for the site prior to full-scale redevelopment.

Investigation of the Santa Fe River Targeted Brownfields Assessment Area, City of Santa Fe, NM. 2010 – 2019. *Project Manager.* Led an investigation in the downtown Santa Fe area to (1) develop a better understanding of groundwater flow within the area so that appropriate decisions can be made about remediation of petroleum hydrocarbons and other groundwater contaminants, (2) determine what impact, if any, will occur within the shallow groundwater aquifer if stream flow in the Santa Fe River is increased, and (3) determine the nature and extent of petroleum hydrocarbon contamination so engineering controls can be evaluated for future development within the TBA area. Activities included developing a geologic model and implementing a drilling program to confirm model accuracy. Field investigations showed that the

geologic model is accurate, and the City of Santa Fe and NMED used the geologic model to guide additional investigations being conducted by NMED and EPA in the downtown Santa Fe area. These investigations were completed to identify sources of petroleum hydrocarbon as well as chlorinated hydrocarbon contamination in ground water in the downtown Santa Fe area. Activities in 2016 and 2017 included the installation of additional groundwater monitoring wells, groundwater sampling, installation of soil vapor monitoring wells, soil vapor sampling, indoor air sampling, and groundwater sampling of additional monitoring wells owned by several different entities in the downtown Santa Fe area to determine groundwater characteristics and the potential sources of identified contamination. Subsurface soil gas sampling was conducted at this Site in June 2019 using "Waterloo Membrane Samplers" placed at several facilities within the TBA area that may have been sources of the underlying ground water contamination. Helped NMED develop a report for the 2019 sampling event and discussed the findings with NMED.

Proposed Belen Fire Station Property Investigation and Remediation, Molzen Corbin, Belen, NM. 2017 – 2018. *Project Manager.* Supervised Site investigation and remediation services at the proposed new Belen Fire Station property located in Belen, New Mexico. Prior to site redevelopment activities, Molzen Corbin Engineers contracted INTERA to conduct site investigation activities to determine if any impact from petroleum hydrocarbons occurred at the Site during historical activities (automobile repair activities) and to conduct geophysical investigation work to determine if any relic USTs were present at the site. INTERA advanced 15 soil borings at the site using geoprobe investigation methods to collect soil and groundwater samples. Investigation results determined that approximately 2,800 cubic yards of PCS were present at the site and one UST was in the northwest corner of the property. INTERA provided a map of the locations of the PCS and the UST. The PCS and UST were removed by City of Belen contractors in 2017. In addition, groundwater impacts by petroleum hydrocarbons were also verified, but no concentrations identified were above New Mexico Water Quality Control Commission (NMWQCC) standards or PSTB action levels. Continued to provide consulting services to Molzen Corbin at the Site as Fire Station building construction was initiated in 2017. INTERA recommended removal of the PCS and installation of a vapor intrusion barrier and sub-slab venting system to protect future building occupants and Site users. INTERA developed specification documents for both PCS removal and vapor intrusion barrier installation and provided to Molzen Corbin Engineers to include in the general contractor bid package. Construction of the Belen Fire Station was completed in 2018. The Belen Fire Station redevelopment project received the "Environmental" award from the New Mexico Chapter of the American Council of Engineering Companies in September 2020.

Investigation of Perchloroethylene Contamination at the Griggs and Walnut Superfund Site, Confidential Client, Las Cruces, NM. 2015 – 2018. *Senior Scientist.* Assisted the technical team evaluating the release timing and locations of PCE contamination in the area of the Griggs Street and Walnut Avenue intersection in the northern section of the City of Las Cruces. The timing information was critical in demonstrating occurrences for insurance reimbursement purposes. Assisted in the development of the CSM for the potential release sites in the area. The CSM would be used by Dona Ana County and the City to help further their understanding of the Superfund site.

Facility Environmental Audits and Stormwater Management Plans, Wood Group/TurboCare Generator Services/Ethos Energy, Farmington, NM. 2010 – 2018. *Project Manager.* Performed environmental audits of three electric generator parts manufacturing facilities, focused on determining volumes of hazardous waste generated at each facility. Reviewed information to calculate volumes to determine the correct generator status (conditionally exempt, small or large), obtain a correct hazardous waste generator identification number, and calculate and pay the associated hazardous waste fees to the NMED Hazardous Waste Bureau for each facility. After calculating these volumes, the Wood Group reported previous quantities of generated waste and paid current and past hazardous waste-generation fees, bringing the facilities back into regulatory compliance. Prepared stormwater pollution protection plans (SWPPPs) for each facility and provided ongoing support with stormwater issues. Due to facility operator transfer and the closing of the two of the facilities, worked with INTERA staff in 2017 and 2018 to update the SWPPP and file Notice of Termination of discharge and NOI to discharge for the new ownership group (Ethos Energy).

Reclamation of the San Vicente Mill Site, New Mexico Environment Department, Silver City, NM. 2013 – 2016. *Project Manager.* Led environmental investigation and remediation/reclamation activities to address an above-grade tailings pile, resulting from former milling and smelting operations for lead, silver, copper, and gold that operated from the 1880s to the 1940s. The tailings pile contained metals (e.g., arsenic and lead) at levels exceeding established human health standards. Water quality had been impacted by the erosion of the tailings pile and the subsequent transport of contaminated material to an adjacent creek. Groundwater also contains elevated concentrations of metals. Project activities included negotiating access

agreements, as portions of the site were on private property; determining the extent of tailings and contaminated soils on-site and offsite; organizing and holding a community meeting to inform property owners as well as Town of Silver City representatives and citizens of potential community impacts; providing contractor oversight for removal of contaminated materials (approximately 50,000 cubic yards); transporting and disposing of contaminated materials at a nearby operational mine site; restoring disturbed areas with placement of soil cover; and reseeding with a native seed mixture. Implemented a reclamation approach that included performing additional characterization efforts while removal of the main tailings area material was being conducted. The single mobilization resulted in cost savings and a project that was completed ahead of schedule. Responsible for developing the Final Removal Assessment Report which documented the quantity of tailings removed and the restoration activities including clean fill placement, grading, and institution of property engineering controls.

Environmental Site Assessments, Los Alamos County, NM. 2005 – 2016. *Contract Manager and Project Manager.* Served as Contract Manager for Los Alamos On-Call Services contract. Investigated and characterized the environmental conditions at several Los Alamos County and Los Alamos School District properties. These properties were formerly operated by Los Alamos National Laboratory. Currently managing this work, which includes Phase I and Phase II ESAs, asbestos and lead-based paint surveys, archaeological investigations, archaeological stabilization activities, surface water sampling, and other general environmental consulting activities. Special projects have included a hazardous materials survey at the Los Alamos County Golf Course, an Environmental Assessment (EA) of the Los Alamos County Canyon Dam site, and a NMED VRP application for the Los Alamos County Trinity Redevelopment site.

Designed and constructed a stormwater detention pond engineering controls at the Trinity Redevelopment site in 2012. The pond was constructed as a solution to an NMED action that required the county to control stormwater runoff into the canyon to the south of the site. Managed the project that included engineering design, construction, and reporting to NMED. Following the construction of the drainage improvement, Los Alamos County began redeveloping the site with a shopping center to include a grocery store, small businesses, and restaurants.

Provided oversight of the removal of a historic OWS from the Trinity Redevelopment Site in 2013. The OWS was discovered during redevelopment construction activities. Secured a subcontractor and provided the county with expedited services during the OWS removal and subsequent sampling so that the construction activities scheduled for the site were not compromised.

Former Eubank Landfill Assessment of Remediation Alternatives, City of Albuquerque/New Mexico Environment Department, NM. 2003 – 2016. *Project Manager.* Led an effort on behalf of the COA and NMED to characterize the nature and extent of landfill gas contamination at the former Eubank Landfill (northeast fill area). Also worked at this site on behalf of Albuquerque Public Schools, an owner of an adjacent property; Bernalillo County, a stakeholder related to the Eubank Landfill; the U.S. Army Corps of Engineers; and the New Mexico State Land Office. The northeast fill area of the former COA Eubank Landfill was operated between 1963 and 1973 on property leased from the New Mexico State Land Office. The Eubank Landfill northeast fill area was unlined and covered approximately 21 acres, with a waste depth in the range of approximately 30 to 40 feet. Material placed at the Eubank Landfill was reported to be mainly residential and commercial waste.

Conducted an assessment of the former Eubank Landfill southwest fill area in 2011 for the proposed future development as a solar panel system field. Worked for a private solar development company along with the COA to evaluate this use of the site and how this use may be impacted by the potential migration of landfill gas. Also worked with INTERA engineers in the development of a final landfill gas management plan as well as a surface grading and drainage plan. In 2012, managed the project, which included additional grading plans for several types of solar panel designs selected for the site. This included the development of a Waste Excavation Plan (WEP). The WEP included the use of waste as fill material, the first of its kind in the State of New Mexico.

Developed an approach for Emcore Solar Power to install and operate a solar panel field at the surface of the former Eubank Landfill southwest fill area. This included LFG investigation activities as well as a geotechnical investigation conducted in order to develop recommendations for landfill gas control measures as well as geotechnical foundation of the solar panel trackers. This work included communicating with civil engineers, architects, electricians, and others to facilitate the successful project. The solar field is currently online and provides power to the Emcore manufacturing facility located

adjacent to the former landfill. Responsible for final reporting and periodic site inspections concerning the condition of the landfill surface.

Hyder Property Site Investigation, City of Albuquerque, NM. 2003 – 2016. *Project Manager.* Developed the investigation work plan at this Brownfield redevelopment property which was the site of a former dry-cleaning facility. The work plan included the execution of a geophysical survey as well as investigative digging to find historic underground solvent storage tanks. Investigative excavations were constructed at the Hyder property, and six USTs were discovered. Conducted a Phase II site investigation at the Hyder property, which included the collection of surface soil, subsurface soil, soil gas, and groundwater samples. Wrote the VRP Completion Report for this site; property received a Certificate of Completion from the NMED VRP. Worked with the site developer, YES Housing, to oversee excavation of soils to determine if contamination was present during construction in late 2014. Site redevelopment as the Imperial Building began in early 2015. Worked with the construction contractor to address environmental contamination (removal of petroleum-contaminated soils and two underground storage tanks) during building excavation and construction work. Submitted the VRCR for the site to NMED in December 2015. Assisted the site developer in securing a CNS from the NMED VRP in early 2016. The Imperial Building includes residential housing on the two upper floors and a community garden on the roof, with commercial spaces (including a grocery store) on the first floor. One level of parking is included in a subsurface parking lot located below the building. The Imperial Building officially opened in September 2016.

500 Copper Square Property Soil Vapor Investigation, First Financial, Albuquerque, NM. 2014 – 2015. *Project Manager.* Led efforts to determine presence of VOCs in site soil vapor. Collected sub-slab soil gas samples at locations within the building basement and compared analytical results to EPA's recommended commercial and residential vapor intrusion screening levels (VISLs) to determine whether VOC contaminants were impacting air quality in the building. Tetrachloroethene (PERC)—a dry cleaning solvent—was present in several of the soil vapor samples, but concentrations did not exceed applicable VISLs for PERC. Entered site into the state VRP in order to obtain a COC to document that current conditions meet applicable environmental quality standards and provide liability protection for lenders. NMED issued at COC in 2015, and a CNS can be transferred to any lender or future owner of the property.

Former Sterling Manufactured Gas Plant Voluntary Cleanup Program Site, Centennial Mental Health Center, Sterling, CO. 2014 – 2015. *Senior Technical Advisor.* Assisted with additional site investigation activities within the VCP investigation and remediation activities at the former Sterling Manufactured Gas Plant site. This site was remediated through the Colorado Department of Public Health and the Environment (CDPHE) VCP for future development into a parking lot for use by the future landowner and neighboring facility, Centennial Mental Health Center. The initial site investigation and targeted brownfields assessment were completed by CDPHE and identified polyaromatic hydrocarbons (PAH) organics and metals contamination above the regulatory limits in the site soils. Project tasks have included potholing of site soils to define further the extent of soil contamination, sampling of an upgradient groundwater monitoring well to determine if metals contamination can be attributed to an off-site source, determination of the most cost-effective method to sample near and around a transformer on site, and completion of the work plan, cost estimate, and health and safety plan for the excavation of site contaminated soils. To accommodate funding schedules, the remediation activities, which consisted of excavation, hauling, and off-site disposal of 814.5 cubic yards of soils contaminated with PAHs, were performed using a phased approach and were completed in 2015. A No Action Determination (NAD) was submitted and formal acceptance of the NAD by CDPHE was received in December 2015.

Characterization and Remediation of the Former Bell Trading Post Property, City of Albuquerque, NM. 2001 – 2005 and 2015. *Project Manager.* Developed a Work Plan to characterize this facility adequately for ultimate inclusion into the VRP. The Bell Trading Post building was formerly a jewelry manufacturing facility as well as a photograph development facility. Heavy metals and solvents were in use at this historic facility. The Work Plan included Geoprobe soil boring installations, subsurface soil sampling, and groundwater sample collection. In addition, on behalf of the COA, supervised a subcontractor conducting a limited asbestos survey at the Bell Trading Post facility building. Completed the VRP Application for this site and developed a VRP Work Plan for the remedial work, which included an integrated QAPP. The remediation consisted of contaminated soil removal as well as the remediation of asbestos and lead-based paint. This was the first Work Plan/QAPP developed for asbestos/lead-based paint remediation in EPA Region VI. Provided oversight of the remediation work and documented the progress on behalf of the COA and its developer, Family Housing Development Corporation. Remediation work completed included the cleaning of a substantial amount of pigeon droppings, asbestos and lead-based paint abatement, lead-in-soil removal, and the removal of all light ballasts from the building. Wrote the VRCR for this facility and

helped the COA obtain a Certificate of Completion from the NMED VRP. This facility was later renovated and developed with residential housing units and commercial office space. Lead a soil vapor intrusion assessment of the renovated building on behalf of the NMED in 2015.

Municipal Separate Storm Sewer System Audit and Application, Santa Fe County, NM. 2012 – 2013. *Project Manager.* Led efforts to assist the county in submitting a municipal separate storm sewer system (MS4) application to the EPA. Reviewed and evaluated documents regarding the history of the MS4 and the NOI Plan; prepared summary report for the county to document current status of the EPA requirements for the MS4 Plan and NOI and define options, deliverables, action items, and schedules/timelines; and helped the county resubmit the MS4 Application to EPA. By working cooperatively with both the county and EPA, helped avoid financial penalties for the county.

Phase I and Phase II Assessments, Northwest New Mexico Council of Governments, Gallup, NM. 2010 – 2013. *Contract Manager and Project Manager.* Contract Manager for Northwest New Mexico Council of Governments (NWNMCOG) On-Call Services contract. This contract was established by the NWNMCOG to evaluate potential Brownfields within the NWNMCOG area (Gallup, San Juan, and Cibola counties). Performed Phase I and Phase II Assessments for the NWNMCOG as part of this contract. Brownfield site characterization activities are the general focus of the contract for those sites located within the NWNMCOG area. Phase II activities conducted under this contract included hollow-stem and air rotary drilling, geophysical survey using electromagnetic (EM) and ground-penetrating radar (GPR) equipment, surface and subsurface soil sampling, groundwater sampling, and investigative excavations using a backhoe.

An example of a NWNMCOG project is the Coal & Puerco Site in Gallup, New Mexico. This site is proposed to be redeveloped with a live/work facility by Community Area Resource Enterprise 66. A dry-cleaning facility is located immediately north of the site. Led INTERA's efforts to investigate the redevelopment site and determine what remedial actions or engineering controls would need to be implemented at the site to although for safe and cost-effective redevelopment. INTERA conducted surface and subsurface soil sampling, soil vapor sampling, and groundwater sampling at the site. PERC was identified in site groundwater and soil vapor. Based on findings of the investigation, recommended that a vapor intrusion barrier be placed below the proposed site building to prevent impacted soil vapor from entering building indoor air. Additionally, worked with the NWNMCOG and NMED to investigate impacts to groundwater in the immediate area surrounding the site and determined that PERC was present in several off-site areas. INTERA is currently working with NMED and the responsible party to determine the vertical and lateral extent of the PCE groundwater plume and determine remedial options.

4407 Lomas Boulevard Site Investigation, Parnell Lomas, Albuquerque, NM. 2012. *Project Manager.* Led a Phase II Site Investigation at this site to determine if former operations as a gasoline service station had negatively impacted soil, soil vapor, or groundwater. The site included an office building and the client was trying to decide whether to purchase the property. After the investigation, it was determined that the site had not been negatively impacted by former operation as a gasoline service station, but that soil vapor was impacted with PCE, most likely from off-site historical dry cleaners. It was concluded that PCE could enter the current office building at levels above EPA screening levels. A proposal was prepared for a vapor mitigation system. Client decided not to purchase the property due to the cost of implementing the vapor mitigation system and associated ongoing monitoring.

Former Tulip Drive Landfill Phase I ESA and Phase II Site Investigation Activities, Luna County, Deming, NM. 2010 – 2012. *Project Manager.* Served as INTERA's Project Manager for the performance of a Phase II ESA performed at the 75-acre tract of land, including the Former Tulip Drive Landfill, located in Deming, Luna County, New Mexico. The Phase II ESA was performed for the county and city using funds provided by the EPA Brownfields Assessment Grant Program. Responsible for the development of a site-specific SAP, which guided field activities. The site was a vacant tract of land owned by the city located southeast of the intersection of New Mexico Highway 26 and U.S. Highway 180, along the Mimbres River. It was the city's and county's intent to redevelop the site as recreational open space; therefore, the objective of the Phase II ESA was twofold: (1) obtain additional information regarding the character of the former Tulip Landfill, such as cover thickness, depths and types of waste, and the extent of the former Tulip Landfill area, and (2) determine if soil and/or groundwater impacts exist from the recognized environmental concerns identified as part of the Phase I ESA completed by INTERA in 2011. INTERA conducted the following Phase II ESA field activities in 2012: (1) investigative excavation of 15 test pits located within the footprint of the former Tulip Drive Landfill, (2) hollow-stem auger (HSA) drilling and sampling of eight shallow exploratory soil borings, (3) HSA drilling and sampling of three deep soil borings, (4) installation and development of three

groundwater monitoring wells (within the deep soil borings), and (5) a single groundwater sampling event. Due to only minimal exceedances of applicable standards in site soil and no exceedances in site groundwater, recommended proceeding with site development upon completion of the following additional remediation/characterization activities:

- Consolidation of the numerous surface litter and debris piles scattered through the vacant lot to within the confines of the former Tulip Drive Landfill
- Preparation of preliminary design and installation of an evapotranspirative cap over the consolidation area to (a) minimize exposure to potentially harmful waste and (b) stabilize waste to deter further offsite transport of site contaminants via surficial processes (i.e., storm water, wind)
- Provision of bank stabilization and erosion control of property land located along the Mimbres River to mitigate the negative effects of progressive undercutting by seasonal surficial processes and help minimize future transport of site contaminants off-site
- Securing the site to prevent future indiscriminate dumping
- Installation of at least one additional ground water monitoring well in the northeast corner of the site to confirm groundwater remained unimpacted by the presence of the landfill
- Completion of one or more additional groundwater sampling events to further assess and monitor groundwater site conditions
- Completion of all additional site remediation/characterization efforts through participation in the NMED VRP.

Hotel La Posada de Albuquerque Redevelopment, City of Albuquerque, NM. 2007 – 2011. *Project Manager.* Developed a QAPP and asbestos specifications for the removal of asbestos from the Hotel La Posada de Albuquerque. Also developed an EE/CA that evaluated the remediation options for the renovation of this historic hotel. Significant quantities of asbestos and lead-based paint were present within La Posada. The EE/CA was used to support the use of the COA Brownfields Cleanup Revolving Loan Fund for a portion of the remediation. Through the EE/CA report, documented the alternative selection process for a non-time-critical removal action that was completed in accordance with 40 CFR 300.415 of the National Oil and Hazardous Substances Pollution Contingency Plan. The Hotel La Posada de Albuquerque was successfully remediated, renovated, and reopened as the Andaluz Hotel in October 2009. Prepared a self-certification document in 2011 that was submitted to the EPA for the voluntary remediation conducted at this building. Site was renamed the "Hotel Andaluz."

Casa Grande Property/El Vado Hotel Phase I Environmental Site Assessment, and Phase II Site Investigation, City of Albuquerque, NM. 2009 – 2010. *Project Manager.* Led an environmental evaluation of the Casa Grande Property on behalf of the COA. The COA proposed redeveloping the Casa Grande Property/El Vado Hotel located at 2500 Central Avenue with mixed use development (residential/commercial) and contracted INTERA to perform a National Environmental Policy Act (NEPA) Environmental Assessment, a Phase I ESA, and a Phase II Site Investigation at the site. The Phase I ESA and Phase II Site Investigation were performed with support from other key INTERA staff members. The Phase I ESA identified a historical property use (gasoline pumps at the El Vado Hotel) and a historic gasoline release at the Casa Grande Chevron located across the street as potential recognized environmental conditions and recommended subsurface soil borings as well as a geophysical investigation be completed at the property. Eight subsurface soil borings were completed at the site in areas believed to have been potentially impacted by historical property and area uses. No impact from petroleum hydrocarbons in soils and/or groundwater was identified. In addition, the geophysical investigation, conducted by Sunbelt Geophysics, did not identify any evidence of abandoned USTs at the site.

Managed the completion of a NEPA Environmental Assessment at the site as prescribed by the lead federal agency, which in this case was the Department of Housing and Urban Development. The EA was completed with support from Parametrix (cultural and biological surveys). The ESA was required to release Community Development Block Grant funds for the property purchase and additional property redevelopment work.

New Mexico Rail Runner Site Assessments, Parsons Brinckerhoff Quade & Douglas, Santa Fe, NM. 2006 – 2009. *Project Manager.* INTERA was retained by Parsons Brinckerhoff Quade & Douglas (PB) in 2006 to perform ISAs for Phase 2 of the Mid-Region Council of Governments/ NMDOT Belen to Santa Fe New Mexico Rail Runner Express Commuter Rail Project. Performed an ISA for the existing BNSF railroad line from Bernalillo to Lamy, New Mexico, and an ISA for the proposed commuter rail line from La Bajada Hill to downtown Santa Fe, New Mexico. Acted as the designated INTERA Project Manager for each ISA

project. The ISA included the assessment of existing railroad lines and facilities (BNSF and Santa Fe Southern), as well as several miles of railroad tracks constructed on undeveloped ranch land to facilitate commuter rail service between Albuquerque and Santa Fe. Project management duties included developing and implementing the schedule for the records reviews, field reconnaissance, and report development. Led field activities for each ISA (the combined assessment length of the two ISA totals over 70 miles) and coordinated with the PB Project Manager, the NMDOT Environmental Geology Section representatives, and NMDOT legal counsel with the finals of each ISA Report. The New Mexico Rail Runner Express began operations in 2009.

Landfill Gas Assessment of Five Formerly City-Owned and/or Operated Landfills, New Mexico Environmental Health Department, Albuquerque, NM. 2003 – 2009. *Contract Manager and Project Manager.* Contract Manager for INTERA's COA landfill gas assessment project. Over 100 landfill gas monitoring wells have been installed to monitor landfill gas migration at five of the COA formerly owned and/or operated solid waste landfills under direction. Managed the landfill gas monitoring well installation and supervised landfill gas sample collection. Other duties conducted include contract budget tracking, future landfill gas monitoring well locating, and landfill gas sample results interpretation. Developed the current COA landfill gas well installation report format as well as the format used for the landfill gas monitoring reports. Also developed landfill management plans to guide development on and adjacent to the former Eubank and San Antonio landfills.

Former Peru Hill Mill Site Phase I Environmental Site Assessment and Phase II Site Investigation and Remediation, New Mexico Environment Department, Deming, NM. 2001 – 2008. *Project Manager.* Performed a Phase I ESA and Phase II Site Investigation of the former Peru Hill Mill mining mill facility in Deming, New Mexico. The Peru Hill Mill primarily processed zinc sulfide ore. Peru Mining Company, a subsidiary of Illinois Zinc Company, constructed the Peru Hill Mill and operated it from 1928 to 1967. Barite of America acquired the facility in 1979 and operated it intermittently until 1985, when the company filed for bankruptcy. Luna County acquired the property in 2001 and deeded it to the City of Deming. The major environmental concerns at the site were uncontained tailings in a 104-acre impoundment and redistributed tailings transported from the impoundment by wind erosion and surface water runoff. The tailings formed dunes around the impoundment that blanketed an area of approximately 161 acres. The total area of the tailings impoundment and redistributed tailings was approximately 265 acres.

Prior to initiating the site investigation, a Phase I ESA was completed at the site. Used the results of the Phase I efforts to complete a work plan and QAPP for the Phase II Site Investigation. Soil sampling results indicated lead, arsenic, and zinc concentrations in surficial soils were in excess of NMED soil screening levels (SSLs). Recommended that surficial soils containing metals concentrations above SSLs be placed within a site tailings impoundment area and that the tailings be capped with soil to prevent further migration by wind and/or water erosion. Secured an engineering firm to design the tailings impoundment cap and a soil consolidation plan. Prior to implementation, the City ultimately used the Phase I ESA report and the information in the site investigation report to submit a VRP application to NMED.

Excavation activities were completed by the City and the tailings were excavated and redistributed to the designated tailings impoundment area. Helped develop a confirmation soil sampling plan to assure that the tailings removal effort was successful. Directed Neptune and Company (subcontractor) in the development of a site-specific remedial action goal for arsenic at the site. Remediation efforts were completed according to plan at Peru Hill Mill and a VRP Completion Report was developed for this facility in 2008. The site received a Conditional Certificate of Completion from VRP in 2009.

Plaza Del Sol Property Site Investigation, City of Albuquerque, NM. 2001 – 2008. *Project Manager.* Led the investigation of this Brownfields redevelopment site, which was believed to be impacted by a historic petroleum hydrocarbon release in the local area. Investigation activities included the preparation of a Phase I ESA, installation of monitoring wells, and groundwater sample collection. Completed additional work at this site on behalf of the COA and private developers in 2008 and developed a VRP Completion Report for the site. The site received a Certificate of Completion from the NMED VRP in 2008 and has since been developed with residential housing.

City of Santa Fe Railyard (including Phillips Petroleum) Brownfields Investigation, City of Santa Fe/New Mexico Environment Department, NM. 2000 – 2008. *Project Manager.* Led several stages of work completed at the City of Santa Fe Railyard for either the City of Santa Fe or the NMED. The work included the development of a Phase I ESA for a 33-acre portion of the site, a preliminary evaluation of groundwater impacts, a subsurface soil clean-up of tar, and the development of a VRP Completion Report. The Phase I ESA focused on identifying more fully potential responsible parties so that the City could consider this information in its Brownfields redevelopment strategies. The City development plan was to redevelop the underutilized

railyard with a railyard park to include open space and trails, green space, and a farmer's market area. A VRP Application and Work Plan were developed by the City and the site was accepted into the VRP.

Construction at the site began in 2006, and tar was discovered in subsurface soils during archaeological excavation work being conducted at the site. Provided the planning and oversight of the removal of subsurface soil containing tar at the site in 2006 and 2007. Developed a report which was submitted to NMED documenting the tar removal activities completed on behalf of the City.

Performed a Phase I ESA at the Phillips Petroleum site, which is located within the Santa Fe Railyard. Completed a VRP application and developed a work plan to address petroleum hydrocarbon contamination in surface soils located at the Phillips Petroleum site. The work plan included additional groundwater monitoring, but no other work was recommended. The Phillips Petroleum site was incorporated into the Santa Fe Railyard Certificate of Completion once the VRP Completion Report was developed and submitted. After receiving a NMED VRP Certificate of Completion and Covenant Not to Sue, this site is now completely redeveloped.

Tender Loving Care Cleaners Phase I Environmental Site Assessment, New Mexico Department of Transportation, Belen, NM. 2006. *Project Manager.* Conducted a Phase I ESA at the former Tender Loving Care (TLC) Dry Cleaning facility located in Belen, New Mexico. Conducted the Phase I ESA to meet the assessment and EPA AAI requirements of the ASTM Standard E1527-05, "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process" and the reporting requirements of the NMDOT 1999 Hazardous Waste Assessment Handbook. The site operated as a dry cleaner under the name "Sunshine Cleaners" from 1987 to 1990 and as TLC Cleaners from approximately 1990 to 1997. NMED conducted a Phase II Site Investigation at the facility and determined that chlorinated solvent contamination was present in subsurface soils and groundwater. The Phase I ESA developed recommended additional sampling to delineate the extent of soil and groundwater contamination. NMDOT ultimately decided not to acquire the property for use as a New Mexico Rail Runner stop.

Former Hillcrest Hospital Facility Site Characterization, New Mexico Environment Department, Silver City, NM. 2004 – 2006. *Project Manager.* Managed the characterization of an abandoned hospital building proposed to be redeveloped as a library. The site characterization included the evaluation of the building for the presence of asbestos and lead-based paint. Additional work included the characterization of site soils for asbestos contamination as well as excavations completed to find an abandoned petroleum storage tank. Developed the QAPP to guide sampling to adequately characterize the facility. Prepared the integrated work plan for the remedial efforts and assisted the Town of Silver City in the selection of a remediation contractor. Managed the remediation work which included asbestos and lead-based paint abatement, as well as a clean-up for pigeon droppings. After successful remediation, the building was demolished and the site was considered ready for redevelopment.

Proposed Rio Grande Silvery Minnow Sanctuary, U.S. Department of Interior - Bureau of Reclamation, Albuquerque, NM. 2005. *Project Manager.* Served as the project manager for a Phase II site investigation evaluating a proposed site for use as a minnow sanctuary. Developed the work plan and provided oversight for the field work consisting of soil, subsurface soil, surface water, and groundwater sampling. Performed an additional site investigation using biological testing of fish to further evaluate the site for suitability as a minnow sanctuary. The site was ultimately selected by the Bureau of Reclamation for the location of the Rio Grande Silvery Minnow Sanctuary.

Phase II Site Investigation and Soil Remediation Activities at Former Araho Well Injection Disposal Facility, New Mexico Oil Conservation Division, Lovington, NM. 2003 – 2005. *Project Manager.* Managed a Phase II site investigation and subsequent soil remediation activities at a former well injection facility. Evaluated the site for the presence of petroleum hydrocarbons and chloride content in soil and then developed a work plan for remediation. Supervised the soil remediation efforts including soil excavation, transportation, and disposal and the subsequent placement of clean fill. Assisted engineers in the development of a cap for the site and provided oversight for the cap construction.

Former San Antonio Landfill Phase II Site Investigation, City of Albuquerque, NM. 2002 – 2003. *Project Manager.* Led a geophysical investigation at the former San Antonio Landfill on behalf of the COA and NMED to determine the volume of waste and thickness of cover at the site. The landfill consisted of approximately 42.5 acres in northeast Albuquerque in an area that was once on the outskirts of town but later became a residential and commercial area. Owned partially by the COA and partially by private landowners, the landfill reportedly accepted municipal waste from 1968 until 1970, at which time it was

capped and informally closed. Data from the geophysical survey provided enough evidence to conclude that the depth of soil cover across the San Antonio Landfill ranged from 2 to 6 feet. Based on the geophysical evidence of the thickness of the soil cover, it was determined it was very unlikely that landfill-related waste was present in surface soils at the site. The results of this investigation were subsequently used several times to help the COA guide development work on and near the former landfill.

Voluntary Remediation Program Assistance (Brownfields Awareness), New Mexico Environment Department, Santa Fe, NM. 2002. *Project Manager.* Managed a NMED project to increase awareness of the number of brownfields sites within New Mexico and the funding assistance available to New Mexico municipalities for brownfields site investigation and remediation. Project included extensive file review, database management, and coordination of a conference for public and private sector representatives. Consistent interaction with the VRP manager and VRP staff was essential to complete this task.

Historic Waterworks Property Site Investigation, New Mexico Environment Department, Silver City, NM. 2002. *Project Manager.* Led investigation to characterize site for inclusion in the state VRP. Site characterization activities included surface soil sampling, soil boring installation, subsurface soil sampling, and groundwater sample collection. In addition, asbestos and lead-based paint sampling were conducted in the historic building located on the site. Site characterization activities required interaction with NMED and the State Historic Preservation Officer.

Old Silver City Landfill Site Investigation, Town of Silver City, NM. 2000 – 2002. *Project Manager.* Led a Phase II Site Investigation of the closed municipal waste landfill known as the Old Silver City Landfill on behalf of the Town of Silver City and the NMED in 2000. The landfill operated from 1968 to 1993 and was historically used by the Town of Silver City and Grant County residents and businesses. The landfill was unlined and placed over arroyos and suspected to be serving as a source for methane gas and groundwater contaminants. Performed an evaluation of potential sources for chlorinated solvents in the vicinity of the landfill that might have been related to groundwater contamination in the area. This task was completed by collecting surface soil samples at an onsite machine shop; subsequent analysis of these samples showed the machine shop was not a source of the contamination.

In addition, the Town of Silver City and NMED asked for an evaluation of viability of harnessing the methane gas from the landfill for energy purposes to be conducted. As a first stage of this work, performed a site reconnaissance of the landfill with landfill engineers, collected landfill gas samples, and reviewed all the available existing records on disposal history and methane gas detection. This information was used to estimate the landfill gas volume and methane concentration using industry-accepted methods. It was determined that there was not enough landfill gas available to provide a viable energy source.