Phase I Environmental Site Assessment

Danny's Cleaners

1406 2nd Street

Santa Fe, New Mexico

Prepared for:

New Mexico Environment Department
Groundwater Quality Bureau
1190 S St Francis Dr
Santa Fe, NM 87505

Prepared by:

INTERA Incorporated
2440 Louisiana Blvd SE Suite 700
Albuquerque, NM 87110
505.246.1600

MAY 28, 2026

Executive Summary

This report documents the methods, findings, opinions, and conclusions of a Phase I Environmental Site Assessment (ESA) performed by INTERA Incorporated (INTERA) for Danny's Cleaners, 1406 2nd Street, in Santa Fe, New Mexico 87505 (Site/Subject Property) (**Figure 1**). The New Mexico Environment Department (NMED) Ground Water Quality Bureau (GWQB) (User) is using its Professional Services Contract #24-667-2030-27724, Work Order Number INTE08-ROS-21, to contract the performance of a due diligence assessment of the Subject Property. The Phase I ESA was conducted to document current and former conditions relative to historical operations at the Site.

INTERA performed this Phase I ESA following the procedures of Standard Practice E1527-21 of ASTM International (ASTM), entitled *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process* (ASTM, 2021). The objective of the Phase I ESA was (1) to identify, to the extent possible, any *recognized environmental conditions* (RECs) as defined by the ASTM and (2) to collect reasonably ascertainable information about the environmental condition of the Subject Property. Additionally, based on reviews of Subject Property, adjoining properties, and vicinity properties' findings within the default *area of concern* (AOC) as defined by ASTM Standard E2600-22, *Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions* (ASTM, 2022), *vapor encroachment conditions* (VECs) were also assessed for the migration potential of hazardous substances and/or petroleum products within or near the Subject Property.

The Subject Property is located on a 0.15-acre parcel of developed land; it is a rectangular parcel, approximately 85 feet (ft) long in the northwest to southeast direction, and approximately 110 ft long in the southwest to northeast direction. The Subject Property is located in a commercial area. A single multi-unit building is located on the Subject Property, extending onto the adjoining property to the northwest. The Subject Property has an operational history as a dry cleaning facility from 1960 until at least 2001 when the property owner sold the dry cleaning equipment. It should be noted that the Subject Property was listed as a dry cleaning business in historical city directories until at least 2008. Since ceasing operations as a dry cleaner, it has operated as an online auto sales service and salon/self-care facility. The immediate vicinity of the Subject Property is depicted in **Figure 2**.

The Phase I ESA included:

- a review of the Subject Property and adjoining properties' historical and current land use records,
- review of standard environmental regulatory agency records,
- a site reconnaissance, and
- interviews with individual(s) having knowledge of past and/or present uses of the Subject Property.

These activities were performed to assess sources of surface and subsurface contamination that potentially exist at the Subject Property and within ASTM-specified distances from the Subject Property. This information was integrated with the physical setting data and future occupancy or development plans for the Subject Property to form an opinion concerning whether properties found to be a potential

source of contamination may, in fact, be a REC with regard to the Subject Property as defined by ASTM. The Phase I ESA was performed by environmental professional(s) as defined in 40 Code of Federal Regulations §312.10 and as identified in this report.

INTERA has performed a Phase I ESA in conformance with the scope and limitations of ASTM Standard E1527-21 for the Subject Property. Based on the completion of the scope of services provided in support of this Phase I ESA, three RECs and two VECs were identified in connection with the Subject Property, as follows:

- Approximately 40 years (1960-2001) of dry cleaning operations conducted at the Subject Property corroborated by the Subject Property owner is considered a **REC/VEC** in connection with the Subject Property.
- The former UST (NMED PSTB Facility ID 49179) located at the adjoining property to the south (1407 3rd Street) is considered a **REC** due to its proximity to the Subject Property and because additional documentation of the tank removal and release determination was not identified.
- The Aspen Cleaners (1616 Cerillos Road) is considered a **REC/VEC** in connection with the Subject Property due to its close proximity and its more than 20-year history as a dry cleaner using PCE.

Based on the conclusions of this Phase I ESA, INTERA recommends the following:

- Perform a Phase II site investigation to assess the potential impacts to environmental media from the REC identified in connection with the Subject Property.

Table of Contents

1.0 Introduction 1
1.1 Purpose 1
1.2 Detailed Scope of Services 1
1.2.1 Vapor Encroachment Considerations 2
1.2.2 Non-Scope Environmental Considerations 3
1.3 Significant Assumptions 3
1.4 Limitations and Exceptions 4
1.5 Special Terms and Conditions 4
1.6 User Reliance 4
2.0 Site Description 6
2.1 Location and Legal Description 6
2.2 Site Vicinity and General Characteristics 6
2.3 Physical Setting 7
2.3.1 Topography and Watershed 7
2.3.2 Average Precipitation and Temperature 7
2.3.3 Flood Plain 7
2.3.4 Soil Characterization 7
2.3.5 Geology and Hydrogeology 7
2.4 Descriptions and Current Uses of Adjoining Properties 8
3.0 User-Provided Information 9
4.0 Records Review 10
4.1 Historical Use of the Site and Adjoining Properties 10
4.1.1 Chain of Title and Environmental Lien Search 10
4.1.2 Historical Topographic Maps 10
4.1.3 Historical Aerial Photographs 11
4.1.4 Fire Insurance Maps 13
4.1.5 Historical City Directories 13
4.2 Environmental Database Records Review 14
4.2.1 Mapped Locations 14
4.3 Regulatory Agency and Supplemental Records Review 15
5.0 Site Reconnaissance 16
5.1 Methodology and Limiting Conditions 16
5.2 Subject Property 16

5.3 Adjoining Properties 17
5.4 Surrounding Properties 17
6.0 Interviews 18
6.1 Key Site Manager 18
6.2 Local Government Officials 18
7.0 Findings and Opinions 19
7.1 Subject Property Findings and Opinions 19
7.2 Adjoining Property Findings and Opinions 19
7.3 Vicinity Findings and Opinions 20
7.4 Tier 1 Vapor Encroachment Screening 20
7.5 Data Gaps 20
8.0 Conclusions 21
9.0 Recommendations 22
10.0 References 23
11.0 Disclaimer 24
12.0 Qualifications and Signatures of Environmental Professionals 25

List of Appendices

Appendix A Environmental Lien and Activity and Use Limitation Search
Appendix B Historical Topographic Maps
Appendix C Historical Aerial Photographs
Appendix D Physical Setting Documentation
Appendix E User Provided Information [RESERVED]
Appendix F Historical Fire Insurance Maps
Appendix G Historical City Directories
Appendix H Database Report
Appendix I Supplemental Records [RESERVED]
Appendix J Photographic Log
Appendix K Interviews
Appendix L Qualifications of Environmental Professionals

List of Figures

Figure 1 Site Location
Figure 2 Site Plan

List of Tables

Table 1. Summary of Subject Property Tax Parcel(s) Information 6
Table 2. User-Provided Information 9
Table 3. City Directory Listings 13
Table 4. File Review Information 14

Acronyms and Abbreviations

AAI	all appropriate inquiry
AFS	Air Facility System
AMSD	approximate minimum search distance
AOC	area of concern
AST	Aboveground Storage Tank
ASTM	American Society for Testing and Materials International
AUL	Activity and Use Limitation
bgs	below ground surface
CERCLA	Comprehensive Environmental Response, Compensation, and Liability Act
COC	chemical of concern
EPA	United States Environmental Protection Agency
ERIS	Environmental Risk Information Services
ESA	Environmental Site Assessment
°F	degrees Fahrenheit
FEMA	Federal Emergency Management Agency
FIM	fire insurance map
ft	foot or feet
GWQB	Ground Water Quality Bureau
INTERA	INTERA Incorporated
LST	Leaking Storage Tank
LUST HIST	Historical Leaking Underground Storage Tank
msl	mean sea level
NFA	No Further Action
NFRAP	No Further Remedial Action Planned
NMED	New Mexico Environment Department
NMOSE	New Mexico Office of the State Engineer
PCB	polychlorinated biphenyl
PCE	perchloroethylene/tetrachloroethylene
POD	Point of Diversion
PSTB	Petroleum Storage Tank Bureau

RCRA	Resource Conservation and Recovery Act of 1976
REC	recognized environmental condition
SEMS	Superfund Enterprise Management System
SFCA	Santa Fe County Assessor
Site or Subject Property	1406 2nd Street, Santa Fe, New Mexico
TCE	trichloroethylene
User	New Mexico Environment Department Ground Water Quality Bureau
USGS	United States Geological Survey
UST	Underground Storage Tank
UST HIST	Underground Storage Tank (Historical)
VEC	vapor encroachment condition
VES	Vapor Encroachment Screening
VSQG	Very Small Quantity Generator
VRP	Voluntary Remediation Program

1.0 Introduction

INTERA Incorporated (INTERA) under contract with the New Mexico Environment Department (NMED) Ground Water Quality Bureau (GWQB) (User), was tasked to perform a Phase I Environmental Site Assessment (ESA) of the property located at 1406 2nd Street, Santa Fe, New Mexico 87505 (Danny's Cleaners) hereafter referred to as the Site or Subject Property (SFCA, 2026). The location of the Subject Property is illustrated in **Figure 1**.

The User is funding consultant resources from its Professional Services Contract #24-667-2030-27724, Work Order Number INTE08-ROS-21, to document current and historical conditions relative to historical operations at the Site.

1.1 Purpose

This Phase I ESA was performed (1) to identify, to the extent possible, any recognized environmental conditions (RECs), defined below in **Section 1.2**, and (2) to collect all reasonably ascertainable information about the environmental condition of the Subject Property. This was performed, consistent with good commercial and customary practice, to allow potential future redevelopment of the Subject Property and to qualify the User for statutory limitations of potential liability under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), a.k.a. Superfund.

This Phase I ESA was performed to meet the assessment and all appropriate inquiries (AAIs) requirements of American Society for Testing and Materials International (ASTM) Standard E1527-21, *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process* (ASTM, 2021). In 2005, the United States Environmental Protection Agency (EPA) issued *Standards and Practices for All Appropriate Inquiries, Final Rule* (EPA final rule; EPA, 2005), and in 2021 ASTM issued ASTM Standard E1527-21 (ASTM, 2021). Both the EPA final rule and the 2021 ASTM Standard E1527-21 implement the CERCLA as amended by the Small Business Liability Relief and Brownfields Revitalization Act of 2002. Under the EPA final rule, effective November 1, 2006, satisfaction of the CERCLA AAI requirement for liability protection as an innocent landowner, a bona fide prospective purchaser, or a contiguous landowner is met by an assessment conducted in accordance with ASTM Standard E1527-21.

1.2 Detailed Scope of Services

In general, the Phase I ESA scope of services included the following four components:

- Records review;
- Site reconnaissance;
- Interviews; and
- Report.

INTERA has completed a Phase I ESA for the Subject Property in accordance with ASTM Standard E1527-21, with the exception of any deviations listed in **Section 1.4** or data gaps listed in **Section 7.5**.

For the purposes of this Phase I ESA report, the definition of the term "*Recognized Environmental Condition*" is as outlined in Section 3.2.73 of ASTM Standard E1527-21:

> "(1) the presence of *hazardous substances* or *petroleum products* in, on, or at the *subject property* due to *release or likely release* to the *environment*; (2) the likely presence of *hazardous substances* or *petroleum products* in, on, or at the *subject property* due to a *release* to the *environment*; or (3) the presence of *hazardous substances* or *petroleum products* in, on, or at the *subject property* under conditions that pose a *material threat* of a future *release* to the *environment.*" (ASTM, 2021, p. 8)

For the purposes of this Phase I ESA report, the definition of the term "*Historical Recognized Environmental Condition*" is as outlined in Section 3.2.39 of ASTM Standard E1527-21:

> "A previous *release* of any *hazardous substances* or *petroleum products* affecting the *subject property* that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority or authorities without subjecting the *subject property* to any controls (for example, *activity and use limitations* or other *property use limitations*). A *historical recognized environmental condition* is not a *recognized environmental condition*." (ASTM, 2021, p. 6)

For the purposes of this Phase I ESA report, the definition of the term "*Controlled Recognized Environmental Condition*" is as outlined in Section 3.2.17 of ASTM Standard E1527-21:

> "*A recognized environmental condition* affecting the *subject property* that has been addressed to the satisfaction of the applicable regulatory authority or authorities with *hazardous substances* or *petroleum products* allowed to remain in place subject to the implementation of required controls (for example, activity and use limitations or other property use limitations)." (ASTM, 2021, p. 4)

An additional term related to this Phase I ESA report is "*de minimis condition*." It is defined by Section 3.2.20 of ASTM Standard E1527-21 as:

> "a condition related to a *release* that generally does not present a threat to human health or the *environment* and that generally would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies. A condition determined to be a *de minimis condition* is not a *recognized environmental condition* nor a *controlled recognized environmental condition.*" (ASTM, 2021, p. 4-5)

1.2.1 Vapor Encroachment Considerations

ASTM Standard E1527-21 requires the assessment of the migration potential of hazardous substances and/or petroleum products within or near the Subject Property.

The definition of the term "*migrate/migration*" is outlined in Section 3.2.53 of ASTM Standard E1527-21:

> "…the movement of *hazardous substances* or *petroleum products* in any form, including, for example, solid and liquid at the surface or subsurface, and vapor in the subsurface." (ASTM, 2021, p. 7)

Vapor migration in the subsurface is described in ASTM Standard E2600-22, *Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions* (ASTM, 2022); however, ASTM Standard E1527-21 does not require its application to achieve compliance with AAI (ASTM, 2021, p. 7).

In order to assess potential migration of hazardous substances and/or petroleum products that may migrate as vapors into the vadose zone as a result of contaminated soil and/or groundwater on or near the Subject Property, INTERA has completed a Tier 1 Vapor Encroachment Screening (VES) in accordance with ASTM Standard E2600-22 for the Subject Property. The objective of the VES is to determine if a vapor encroachment condition (VEC) exists at the Subject Property. For the purposes of this Phase I ESA report, the definition of the term "*Vapor Encroachment Condition*" is as outlined in Section 3.2.37 of ASTM Standard E2600-22:

> "[The] presence or likely presence of [chemical of concern (COC)] vapors in the vadose zone of the [Subject Property] caused by the release of vapors from contaminated soil and/or groundwater either on or near the [Subject Property]…" (ASTM, 2022, p. 4)

The results of the Tier 1 VES are presented in **Section 7.4**.

1.2.2 Non-Scope Environmental Considerations

Non-scope environmental considerations such as those identified in Section 13.1.5 of ASTM E1527-21 were not evaluated as part of this ESA. Non-scope considerations may include, but are not limited to: presence of potential asbestos-containing building materials unrelated to releases into the environment; biological agents; cultural and historic resources, ecological resources; endangered species; health and safety; indoor air quality unrelated to releases of hazardous substances or petroleum products into the environment; industrial hygiene; presence of potential lead-based paint unrelated to releases into the environment; lead in drinking water; mold or microbial growth conditions; polychlorinated biphenyl (PCB)-containing building materials; naturally-occurring radon; regulatory compliance; substances not defined as hazardous substances (including some substances sometimes generally referred to as emerging contaminants) unless or until such substances are classified as a CERCLA hazardous substance; and wetlands (ASTM, 2021, p. 25).

1.3 Significant Assumptions

Significant assumptions pertaining to this Phase I ESA are briefly summarized as follows:

- Environmental database information (and facility locations) generated by Environmental Risk Information Services (ERIS) is accurate and complete;
- The User has provided INTERA with all the information in its possession that would help determine the presence of RECs;
- Interview information provided to INTERA by various parties and individuals is accurate and was provided without bias; and
- Publicly available reasonably ascertainable information accessed by INTERA is accurate and complete.

The significant assumptions underlying the preparation of any Phase I ESA are specified in the principles set forth by ASTM Standard E1527-21. The principles are presented in their entirety in Section 4.5 of ASTM Standard E1527-21 (ASTM, 2021, p. 10).

1.4 Limitations and Exceptions

Any Phase I ESA is by nature limited and qualitative in scope, being based predominantly on the examination of selected maps, agency records, interviews, and visual and/or physical observations made during the site reconnaissance. As such, this Phase I ESA should not be construed to be a complete characterization of environmental regulatory compliance of conditions above or below ground surface (bgs) at the Subject Property. Instead, the ESA process is designed to provide information regarding apparent existing or potential adverse environmental conditions related to the Subject Property in accordance with good commercial and customary practice. Any significant data gaps that would further limit the scope of the Phase I ESA are identified in **Section 7.5**.

This Phase I ESA is limited to the reasonably ascertainable information available or known to INTERA as of the date of this report. Consistent with ASTM Standard E1527-21, no intrusive testing or sampling of concealed or subsurface conditions was performed at the Subject Property as part of this Phase I ESA. The findings, opinions, and conclusions contained in this report are limited to those that could be identified during the Phase I ESA performed in accordance with ASTM Standard E1527-21. INTERA has accepted as true the information provided by interviewees on current and historical uses of the Subject Property and surrounding area. INTERA does not warrant or guarantee the accuracy or completeness of information provided by other sources.

INTERA represents that the Phase I ESA was performed in a competent manner by environmental professionals, consistent with the practices and procedures contemplated under ASTM E1527-21. However, even with proper application of the ASTM methodology, environmental conditions may be present that cannot be identified within the scope of the Phase I ESA or that may not be reasonably identifiable from the available information. As such, no warranty is expressed or implied as to the findings, conclusions, and/or recommendations presented in this Phase I ESA report beyond matters amenable to empirical review and visual confirmation within the limits under ASTM E1527-21 and/or the specified scope of work.

1.5 Special Terms and Conditions

Since a property transaction was not part of the rationale for conducting the Phase I ESA, some of the discussion related to purpose, liability protection, and User reliance herein may not be relevant. This language is included for consistency and transparency of describing the intention of the Phase I ESA to meet the ASTM Standard.

1.6 User Reliance

This Phase I ESA has been prepared for the use of the User. There are no third-party rights or benefits conferred under this report. Use of or reliance on this Phase I ESA report by any third party is at the sole risk of that party.

This Phase I ESA is valid for 180 days prior to acquisition of the Site and/or transactions not involving acquisition of the Site. In accordance with the ASTM Standard, if the Phase I ESA is to be used by a different user other than the intended user within the 180 days, then the new user must satisfy the requirements in Section 6 of ASTM E1527-21. The Phase I ESA can be valid for longer if the Phase I ESA has been updated within one year of the date of acquisition or intended transaction, provided that the following components have been completed within 180 days of the acquisition or transaction: interviews; searches for recorded environmental cleanup liens; review of federal, tribal, state, and local government records; visual inspection of the property and of adjoining properties; and the declaration by the environmental professional responsible for the assessment or update (ASTM, 2021, p. 11).

2.0 Site Description

As required by ASTM Standard E1527-21, INTERA gathered information concerning the location, characteristics, current land uses, and physical improvements of the Subject Property, adjoining properties, and vicinity properties. Sources for this information were United States Geological Survey (USGS) 7.5-minute historical topographic maps, geologic and hydrologic publications, aerial photographs, observations made during the site reconnaissance, interviews, and consulting other publicly available information.

The Subject Property is located on a 0.15-acre parcel of developed land; it is a rectangular parcel, approximately 85 feet (ft) long in the northwest to southeast direction, and approximately 110 ft long in the southwest to northeast direction. The Subject Property is located in a commercial area. A single multi-unit building is located on the Subject Property, extending onto the adjoining property to the northwest. Adjoining properties are described in **Section 2.4**. The Site and immediate vicinity thereof are depicted in **Figure 2**.

2.1 Location and Legal Description

The Subject Property is a single 0.15-acre parcel in Santa Fe, Santa Fe County, New Mexico. General real estate property tax information was gathered from the Santa Fe County Assessor (SFCA) website for the Subject Property, summarized in **Table 1** (SFCA, 2026).

Table 1. Summary of Subject Property Tax Parcel(s) Information

Address	1406 Second Street, Santa Fe, NM 87505
Owner Name	Moya, Martin
Parcel No.	18600698
Legal Description	0.1506 AC LOT 1 BLK 4 CAPITAL & TOWNSITE
Size (acres)	0.1506
Deed Date	Unknown
Instrument	205/020 (plat book/page)

An Environmental Lien and Activity and Use Limitation (AUL) search was performed for the Subject Property parcel for the current owner. No environmental liens or AULs were identified for the Subject Property in the Lien Search Report (ERIS, 2026a – **Appendix A**).

2.2 Site Vicinity and General Characteristics

ASTM Standard E1527-21 specifies that the only standard physical setting source that must be checked during the Phase I ESA is the current USGS 7.5-minute topographic map (or equivalent) (USGS, 2022). Other physical setting sources used for this Phase I ESA were historical topographic maps (ERIS, 2025b – **Appendix B**) and historical aerial photographs (ERIS, 2025c – **Appendix C**), discussed in **Section 4**.

2.3 Physical Setting

Several sources were reviewed to determine the physical setting of the Subject Property. Information from published physical settings maps (ERIS, 2025d – **Appendix D**) are discussed in the following subsections.

2.3.1 Topography and Watershed

The most recent (2023) USGS 7.5-minute topographic map of the site area was obtained and reviewed as specified in ASTM Standard E1527-21 Section 8.2.1 (ASTM, 2021). The USGS Santa Fe, NM quadrangle provides coverage of the Subject Property and vicinity (USGS, 2023). Historical topographic maps were reviewed for surface topography and drainage information in the vicinity of the Subject Property, and are provided in **Appendix B**.

According to the topographic maps, the Subject Property is relatively flat, with a surface elevation of approximately 6847 ft mean seal level (msl). The general area slopes gently to the west, towards an ephemeral channel called Acequia de los Pinos. This acequia continues to the southwest and eventually joins the Santa Fe River, which is also ephemeral in this section. The Santa Fe River drains into the Rio Grande approximately 25 miles downstream to the southwest. The site topography was confirmed during the site reconnaissance (**Section 5**). Surface drainage at the Subject Property follows the surface topography (**Figure 1**).

2.3.2 Average Precipitation and Temperature

The average annual precipitation in Santa Fe, New Mexico is approximately 13.69 inches per year. Most of the precipitation historically occurs in July. The greatest average temperature historically is in July, at 72.2 degrees Fahrenheit (°F); the lowest average temperature historically is in January, at 31.6 °F (NOAA, 2026).

2.3.3 Flood Plain

The Subject Property is outside of the 100- and 500-year floodplains (ERIS, 2025d – **Appendix D**).

2.3.4 Soil Characterization

The soil map provided by ERIS was reviewed to identify local surface soils underlying the Site. Soils underlying the Subject Property are solely composed of urban land, a miscellaneous categorization for highly developed areas. Several other minor soil components make up roughly 15% of the composition of the underlying soil but the aggregate soil characteristic is not discernable from the available information (ERIS, 2025d).

2.3.5 Geology and Hydrogeology

The Subject Property is located near the foot of the Sangre de Cristo Mountains, the southernmost subrange of the Rocky Mountains. Santa Fe is located on a large system of dissected alluvial fans stretching from the foot of the Sangre de Cristos to the bottom of the Rio Grande rift valley. The geologic map provided by ERIS was reviewed to determine the general geologic setting at the Subject

Property (ERIS 2025d – **Appendix D**). The geologic maps show that the Subject Property is underlain by Quaternary piedmont alluvium deposits (Qp). Nearby, there are also areas underlain by alluvial fan-type deposits of the Upper Santa Fe Group, which are also Quaternary in age. The source of the sediment that makes up this alluvial fan system is primarily the Mesoproterozoic and Paleoproterozoic plutonic bedrock that makes up the Sangre de Cristo Mountains to the east.

The primary source of groundwater in the area of the Subject Property is the series of aquifers within the Santa Fe Group, which is primarily unconsolidated silts, sands, and gravels. ERIS reports a total of 283 water wells within a one-mile radius of the Subject Property. Sources queried included:

- Public Water Systems Violations and Enforcement Data,
- Safe Drinking Water Information System,
- USGS National Water Information System, and
- The New Mexico Office of the State Engineer (NMOSE) Point of Diversion (POD) Database.

Of the four wells listed within 1000 ft of the Subject Property, only one lists a depth to water measurement, which is 190 ft bgs (ERIS, 2025d). Although the local shallow groundwater gradient is unknown, groundwater likely flows to the west in this area, following the surface gradient down towards the Santa Fe River.

2.4 Descriptions and Current Uses of Adjoining Properties

The Subject Property is bound by the following properties and rights-of-way:

- A single commercial property to the northwest, SFCA parcel No. 11803520, 1402 2nd Street, occupied by a multi-unit commercial property as part of the same single structure that occupies the Subject Property. The units are currently occupied by a salon.
- A single commercial property to the north across 2nd Street, SFCA parcel No. 10180736, 1405 2nd Street, occupied by an office space.
- A single residential property to the northeast across 2nd Street, SFCA parcel No. 10180480, 1407 2nd Street.
- A single commercial property to the east across the intersection of 2nd Street and Berry Avenue, SFCA Parcel No. 12404608, 1409 2nd Street, occupied by vacant office space.
- A single commercial property to the southeast across Berry Avenue, SFCA parcel No. 12776910, 1501 3rd Street, occupied by a self-storage facility.
- A single commercial property to the southwest, SFCA Parcel No. 12773248, 1407 3rd Street, occupied by a paint store.

The Site and immediate vicinity thereof are depicted in **Figure 2**.

3.0 User-Provided Information

During project initiation, the User provided a summary of their knowledge of the Subject Property, summarized below in **Table 2**.

Table 2. User-Provided Information

Site Type	Dry cleaner
Site Name	Danny's Cleaners
Location	1406 2nd Street, Santa Fe, New Mexico
Source of Identification	Historical City Directories between 1964 and 2002
Previous Investigations	None
Major Contaminant Concern	Tetrachloroethylene (PCE), trichloroethylene (TCE)

Other than the information provided in **Table 2**, it is INTERA's understanding that the User has no additional knowledge of the Subject Property including those topics outlined in Section 6 of ASTM Standard E1527-21 as the User's responsibilities, summarized as follows:

- The User has no knowledge of any environmental liens or AULs for the Subject Property. However, INTERA has performed a review of land title records and performed a search for environmental liens and AULs on behalf of the User (**Section 4.1.1**).
- The User had no specialized knowledge or experience related to the Subject Property beyond the standard knowledge of a regulatory authority relative to common contaminants associated with dry cleaning operations in general.
- Since a property transaction is not part of the rationale for this Phase I ESA, INTERA did not inquire about the purchase price or fair market value of the Subject Property.
- The User was unaware of any commonly known or reasonably ascertainable information other than what is summarized in **Table 2**, including knowledge of any contamination, spills/releases, or cleanups that have taken place at the Subject Property.
- The User was unaware of any obvious indicators of the presence or likely presence of releases at the Subject Property.
- Any supplemental information relative to the User's responsibilities as defined in Section 6 of ASTM Standard E1521-21 is provided in **Appendix E**.

4.0 Records Review

In accordance with ASTM requirements, INTERA reviewed historical topographic maps and aerial imagery, and standard federal, state, local, and tribal environmental regulatory agency documents. A discussion of records reviewed is provided in the following subsections.

4.1 Historical Use of the Site and Adjoining Properties

INTERA contracted ERIS to search for and provide historical topographic maps, historical aerial photographs, historical city directories, and historical fire insurance maps (FIMs) for the Subject Property and surrounding properties. ERIS also provided environmental lien and AUL search services. INTERA reviewed the historical sources of information to investigate the history of development and prior land uses associated with the Subject Property, adjoining properties, and surrounding area, and to identify past land uses that may indicate that hazardous substances or petroleum products were used. A summary of the historical records reviewed is provided below.

4.1.1 Chain of Title and Environmental Lien Search

INTERA contracted ERIS to perform historical chain of title and environmental lien and AUL search for the Subject Property. ERIS searched county, state, and federal records associated with the Subject Property address and parcel identifier (18600698).

The Chain of Title Report identified three deed conveyances, with the earliest being in 1951. The conveyance details did not indicate any new information related to the use or activities at the Subject Property, including dry cleaning operations. However, the 1951 conveyance grantee was Daniel Moya, presumptively of Danny's Cleaners. This was corroborated during the interview with the current property owner Martin Moya (**Section 6.1**). No environmental liens and/or AULs were found (ERIS, 2025a). A copy of the combined Chain of Title Report and Environmental Lien Report is included in **Appendix A**.

4.1.2 Historical Topographic Maps

INTERA reviewed historical topographic maps provided by ERIS dated 1952, 1961, 1977, 1993, 2002, 2013, 2017, 2020, 2023 (ERIS, 2025b), which are provided in **Appendix B**. A brief description of the Subject Property and the surrounding area derived from the review of historical and recent topographic maps is provided below.

- 1952:
  - One structure is depicted on the Subject Property, located in a lightly developed area within Santa Fe. Most of the area on both sides of Cerrillos Road/US-85 is developed. Neighborhoods to the east and west of the Subject Property are infilling with residential properties.
- 1961:
  - Development surrounding the Subject Property has expanded with more surrounding streets. St Michaels Drive is depicted for the first time south of the Subject Property.

- 1977:
  - Development of the surrounding area continues to increase. St Francis Drive is depicted for the first time east of the Subject Property.
- 1993:
  - Development of the surrounding area continues to increase. Most of the map area depicts significant development.
- 2002:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.
- 2013:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.
- 2017:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.
- 2020:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.
- 2023:
  - The Subject Property and vicinity appear relatively unchanged from the previous map.

4.1.3 Historical Aerial Photographs

INTERA reviewed historical aerial photographs provided by ERIS dated 1935, 1948, 1951, 1960, 1967, 1976, 1981, 1991, 1996, 2005, 2009, 2011, 2014, 2016, 2018, 2020, and 2022 (ERIS, 2025c – **Appendix C**). A brief description of each historical aerial photograph reviewed is provided below**.**

- 1935: Image Resolution – Poor
  - The Subject Property, as well as most of the land on the southeast side of Cerrillos Road, is undeveloped with only one structure visible along Cerrillos Road, as well as some homes in the neighborhood to the east. The Santa Fe Indian School, located across Cerrillos Road on the northwest side, is developed with several structures but agricultural fields can also be seen.
- 1948: Image Resolution – Fair
  - The Subject Property is still vacant. 2nd Street has been constructed. More of the surrounding area, especially along the southeast side of Cerrillos Road and the surrounding neighborhoods, is developed with residential homes and businesses.
- 1951: Image Resolution – Fair
  - A small structure is in the north corner of the Subject Property. Development surrounding the Subject Property continues to increase. Streets other than Cerrillos Road appear to be unpaved.
- 1960: Image Resolution – Good

  - A larger structure than in the previous image is in the north corner of the Subject Property. Other than lots directly south of the Site, most of the area is now infilled with homes and businesses.
- 1967: Image Resolution – Good
  - Multiple structures are on the Subject Property, along the 2nd Street frontage. 2nd Street, as well as some other roads in the area, now appear to be paved.
- 1976: Image Resolution – Fair
  - The Subject Property appears relatively unchanged from the previous image. Some of the lots south of the Site have been infilled.
- 1981: Image Resolution – Poor
  - The Subject Property appears to be developed to its current extent. The vicinity appears relatively unchanged since the previous image.
- 1991: Image Resolution – Good
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 1996: Image Resolution – Good
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2005: Image Resolution – Good
  - This is the first full-color image. The Subject Property and vicinity appear relatively unchanged since the previous image. New buildings and sports fields appear on the Santa Fe Indian School campus.
- 2009: Image Resolution – Good
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2011: Image Resolution – Good
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2014: Image Resolution – Good
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2016: Image Resolution – Excellent
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2018: Image Resolution – Excellent
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2020: Image Resolution –Excellent
  - The Subject Property and vicinity appear relatively unchanged since the previous image.
- 2022: Image Resolution – Excellent
  - The Subject Property and vicinity appear relatively unchanged since the previous image.

4.1.4 Fire Insurance Maps

Historical FIMs can be used to identify historical uses of a property including the presence of hazardous substances and petroleum products. A single historical FIM was identified for the Subject Property, from 1970 (ERIS, 2025e – **Appendix F**). Two structures are depicted on the Subject Property and there is some illegible annotation. An alleyway borders the northwest side of the northwest adjoining property (1402 2nd Street), and across the alleyway at 1704 Cerrillos Road is an automotive service and filling station. Much of the annotation on the FIM is illegible, but there are no apparent indications of petroleum product or hazardous substance use/storage in the vicinity.

4.1.5 Historical City Directories

Historical city directories provide a method for researching historical uses of property. INTERA reviewed historical city directories obtained from ERIS to determine current and historical uses of the Subject Property and adjoining properties (ERIS, 2025f – **Appendix G**). ERIS provided historical City Directory Reports for 2nd Street (up to 1500) and all of Berry Avenue. Additional results may be provided if included on the historical directory pages for the ranges provided by ERIS. ERIS provided results for the years 1928-29, 1930-31, 1936-37, 1940, 1944, 1949, 1955, 1960, 1964, 1968, 1973, 1978, 1983, 1988, 1993, 1996, 2000, 2003, 2008, 2012, 2016, 2020, and 2023. However, 2nd Street listings only go as far back as 1949, and Berry Ave listings go as far back as 1955. The city directory listings that could be reasonably presumed to be commercial or retail properties that may be associated with historical operations utilizing petroleum products (e.g., filling stations) or other hazardous substances (e.g., dry cleaners or manufacturing facilities) are as follows:

Table 3. City Directory Listings

Address	Property Listing(s) (Year(s))
1411 2nd St	European Autowerks (2023, 2020, 2016, 2012)
1607 Berry Ave	European Automotive SVC (2023, 2020, 2016, 2012); Jags Auto Detail (2003, 2000)
1406 2nd St	Danny's Cleaners (2008, 2003, 2000, 1996, 1993, 1988, 1983, 1978, 1973, 1968, 1964, 1960)
1802 2nd St	Santa Fe Auto Detail Inc. (1996, 1993)
1725 2nd St	Dave's Body Shop (1993)
1731 2nd St	Chief Mike's Chainsaw Repair (1983)
1609 2nd St	Corky's Wrecker Service Inc. (1978)
1418 2nd St	Williams Curly Auto Parts (1973)
1404 2nd St	Coffee's Chainsaw Shop (1960)

4.2 Environmental Database Records Review

ERIS was contracted to provide a listing of standard environmental records within the ASTM-specified approximate minimum search distance (AMSD) from the Subject Property. ERIS also provides results from non-standard databases that may be relevant with respect to the objective of a Phase I ESA (i.e., without a specified AMSD). ERIS provided results from 104 unique federal, state, and tribal databases using the ASTM-specified AMSD or otherwise relevant search distance for each database. The ASTM-compliant regulatory database report is included as **Appendix H.**

4.2.1 Mapped Locations

Based on 63 total results of the database search, ERIS identified 31 sites (mapped locations) within 1-mile of the Subject Property. Five of the results were identified for the Subject Property. Sites may be identified in multiple databases, some may be identified in the same database more than once, and some may be for former and/or current operations. Findings based on results of select databases that returned significant results that support the objective of the Phase I ESA and opinions of those findings are discussed in **Section 7.** The mapped locations are summarized in **Table 4.** The ERIS Database Report, which describes and shows these facility locations, is included in **Appendix H** (ERIS, 2025g).

Table 4. File Review Information

Database Record[1]	AMSD (miles)	Total Sites Identified	Within AMSD	On Site Property	Data Source
Standard ASTM Environmental Record Resources					
Federal – SEMS Archive	0.5	1	1	0	ERIS
Federal – CERCLIS NFRAP	0.5	1	1	0	ERIS
Federal – RCRA VSQG	Subject Property and Adjoining Properties	6	2	1	ERIS
Federal – RCRA Non-Generators	Subject Property and Adjoining Properties	2	0	0	ERIS
State -- SCS	1.0	6	6	0	ERIS
State – Delisted SCS	1.0	2	2	0	ERIS
State – SWF/LF	0.5	2	2	0	ERIS
State – LST	0.5	9[2]	9	0	ERIS
State – LUST HIST	0.5	9[2]	9	0	ERIS
State -- UST	Subject Property and Adjoining Properties	5	1	0	ERIS
State – UST HIST	Subject Property and Adjoining Properties	5	1	0	ERIS
State -- TANKS	Subject Property and Adjoining Properties	5	1	0	ERIS
State -- VRP	0.5	2	2	0	
Non-Standard Environmental Records Resources					

Database Record[1]	AMSD (miles)	Total Sites Identified	Within AMSD	On Site Property	Data Source
Federal – FINDS/FRS	NA	3[2]	NA	0	ERIS
Federal -- ICIS	NA	1	NA	1	ERIS
Federal – FED DRYCLEANERS	NA	2	NA	1	ERIS
Federal – AFS	NA	1	NA	1	ERIS

Notes:

1 Full descriptions of the database sources of information can be found in the ERIS Database Report (Appendix H)

2 One or more mapped locations listed more than one time

4.3 Regulatory Agency and Supplemental Records Review

If the Subject Property or a property adjoining the Subject Property is identified in a review of standard ASTM environmental records resources, supplemental records review must be conducted (Section 8.2.3.1 of ASTM E1527-21). Unless otherwise specified in **Section 7**, INTERA reviewed supplemental records for the Subject Property and the following adjoining properties:

- Danny's Cleaners (1406 2nd St) identified in the federal Resource Conservation and Recovery Act (RCRA) Very Small-Quantity Generators (VSQG) database.
- Dunn Edward Paints No. 120 (1407 3rd St) identified in the federal RCRA VSQG database, the NMED underground storage tank (UST) and historical UST databases, and the NMED list of storage tank sites.

Relevant supplemental records obtained are presented in **Appendix I**. Pertinent references to individual documents are associated with specific findings in **Section 7**.

5.0 Site Reconnaissance

In general, the following was observed during the site reconnaissance to obtain information for the evaluation of RECs in connection with the Subject Property:

- Since access to conduct the Phase I ESA site reconnaissance was not obtained, the exterior of the Subject Property was observed from the public right-of-way.
- Adjoining properties from the Subject Property boundary and/or the public right-of-way.
- General topography and surface drainage in the vicinity of the Subject Property.

INTERA personnel conducted the site reconnaissance on February 12, 2026. Photographic documentation of the site visit is included in **Appendix J**. Findings documented during the site reconnaissance are summarized in **Section 7** of this report.

Conditions observed are presented below; a check mark in any box indicates that INTERA observed evidence of the item during the Site reconnaissance.

☐ Hazardous substances and/ or petroleum products	☐ Unidentified substance containers	☐ Stressed vegetation
☐ Storage tanks	☐ PCBs	☐ Solid waste
☐ Odors	☒ Drains and Sumps	☐ Utilities/Pipelines
☐ Pools of liquid	☐ Pits, ponds, or lagoons	☐ Wastewater
☐ Drums/Containers	☐ Stained soil or pavement	☐ Wells
☐ Hazardous substance and/or petroleum product containers	☐ Stains or Corrosion	☐ Septic systems

Relevant discussion of the conditions observed, including but not limited to the items identified above, is discussed in the following subsections.

5.1 Methodology and Limiting Conditions

The methodology for the site reconnaissance was based on ASTM Standard E1527-21 (ASTM, 2021). INTERA physically inspected the Subject Property, adjoining properties to the extent possible from the right-of-way, and the general site vicinity, to identify RECs or evidence of RECs as specified in Section 9 of ASTM Standard E1527-21 (ASTM, 2021).

5.2 Subject Property

The Subject Property is located on a 0.15-acre parcel of developed land; it is a rectangular parcel, approximately 85 ft long in the northwest to southeast direction, and approximately 110 ft long in the southwest to northeast direction. The Subject Property is located in a commercial area. A single multi-unit building is located on the Subject Property, extending onto the adjoining property to the northwest. The Site and immediate vicinity thereof are depicted in **Figure 2**.

Generally, the site reconnaissance did not identify any obvious signs of contamination or hazardous substances as a result of chemicals used during former dry cleaning activities. Several in-ground drains were observed in the property interior, presumably plumbed to the sanitary sewer.

Photographs taken during the site reconnaissance are included in **Appendix J**.

5.3 Adjoining Properties

INTERA observed properties from the boundary of the Subject Property and from public rights-of-way to the extent possible. Evidence of petroleum products or hazardous substances was not directly observed. Descriptions of adjoining properties are provided in **Section 2.4**.

5.4 Surrounding Properties

Surrounding properties were generally commercial in the immediate vicinity of the Subject Property, with residential properties in the surrounding (i.e., within 500 ft of the Subject Property).

6.0 Interviews

In accordance with requirements of Sections 10 and 11 of ASTM Standard E1527-21 (ASTM, 2021 p. 21-23), INTERA interviewed the *key site manager* and *local government officials* for knowledge of any past or present RECs in connection with the Subject Property.

Any findings associated with these interviews are indicated in **Section 7**.

6.1 Key Site Manager

Mr. Andrew Murphy of INTERA interviewed Mr. Martin Moya, owner and Key Site Manager for the Subject Property, on February 12, 2026. Mr. Moya indicated that the facility operated as a dry cleaner from 1956 to approximately 2001, when he sold all of the dry cleaning equipment. Mr. Moya confirmed that the dry cleaner facility used a petroleum-based cleaner containing PCE and trichloroethylene (TCE). Since closure of the dry cleaning operation, the building has been occupied by various commercial renters. Documentation of the interview with the Key Site Manager is provided in **Appendix K**.

6.2 Local Government Officials

NMED provided available information for the Subject Property during project initiation as described in **Section 3**. The information provided is considered satisfactory to meet the requirements of the Standard. No additional information from local government officials was obtained.

Records received from NMED are included in **Appendix K**.

7.0 Findings and Opinions

This section presents the findings of the Phase I ESA Report for the Subject Property and summarizes the results of the Phase I ESA records review, site reconnaissance, and interviews as they relate to the potential presence of RECs. A discussion of Subject Property findings related to the use, storage, and disposal of hazardous substances and petroleum products is presented in **Section 7.1**. A discussion of the findings for adjoining and surrounding vicinity properties is included in **Sections 7.2** and **7.3**, respectively. **Section 7.4** discusses the results of the Tier 1 VES. This section also presents INTERA's opinions concerning the potential of the findings to contaminate Subject Property environmental media and whether the finding is considered a REC. The findings presented in this section are the basis for the Phase I ESA conclusions presented by INTERA in **Section 8** of this Phase I ESA Report.

7.1 Subject Property Findings and Opinions

The Subject Property is located on a 0.15-acre parcel of developed land; it is a rectangular parcel, approximately 85 ft long in the northwest to southeast direction, and approximately 110 ft long in the southwest to northeast direction. The Subject Property is located in a commercial area. A single multi-unit building is located on the Subject Property, extending onto the adjoining property to the northwest. The Subject Property has an operational history as a dry cleaning facility from 1960 until at least 2001, when the property owner sold all dry cleaning equipment (**Section 6.1**). It should be noted that the Subject Property was listed as a dry cleaning business in historical city directories until at least 2008 (**Section 4.1.5**). Since ceasing operations as a dry cleaner, it has operated as an online auto sales service and salon/self-care facility. As described in **Section 3**, the NMED provided available information for the Subject Property during project initiation and additional supplemental information was not identified. Based on the information available including the property owner's accounting of the historical dry cleaning operations, a **REC** exists in connection with the Subject Property due to its extensive operational history as a dry cleaner for approximately 40 years and the known use of hazardous chlorinated solvents (PCE/TCE) during a time when regulations for the use, storage, and disposal of those chemicals were limited.

7.2 Adjoining Property Findings and Opinions

Findings associated with adjoining properties and opinions of those findings are summarized below and illustrated in **Figure 2**.

<u>Dunn Edward Paints No. 120/Thomas Property (1407 3rd Street), southwest of the Subject Property, hydraulically cross-gradient</u>

This property was identified in multiple databases for activities associated with its former use as a facility with an UST (NMED PSTB Facility ID 49179), and its current use as a paint store (RCRA VSQG). Based on available online street view imagery, the facility has been a paint store since at least 2007.

INTERA confirmed that the facility is listed on the NMED PSTB's list of facilities with a removed UST and is not listed as an active facility. ERIS reports that there was one 550-gal UST on site containing used oil, and it was removed at an unknown date sometime before August 2006, which is when NMED's historical UST database was last updated. There are no records of violations or releases associated with the former UST facility or the paint store as a generator. However, due to the close proximity of this former tank site and because no additional records of the tank removal or release determination were identified, this former UST site is considered a **REC** in connection with the Subject Property.

7.3 Vicinity Findings and Opinions

Selected findings in the vicinity of the Subject Property within the respective AMSD for the databases they are listed in are discussed in this section. Other findings from non-standard environmental records (**Table 3**) are discussed here as well where relevant.

Aspen Dry Cleaners (1616 Cerrillos Road), northeast of the Subject Property, hydraulically cross-gradient

This property is listed as a dry cleaning facility in a federal database. The facility is active and listed as a RCRA VSQG for PCE since at least 2014. There are no documented violations or releases associated with this facility. Based on available online street view imagery, the facility has been a dry cleaning site since at least 2007. Due to this facility's close proximity to the Subject Property and extensive history (greater than 20 years) as a dry cleaner using PCE, this facility is considered to be a **REC** in connection with the Subject Property.

7.4 Tier 1 Vapor Encroachment Screening

ASTM Standard E2600-22 defines the default area of concern (AOC) based on $^{1}/_{3}$-mile for hazardous substances and $^{1}/_{10}$-mile for petroleum hydrocarbon contaminants. The AOC is measured from the Subject Property boundary to a contaminated property with known or suspected contamination of soil and/or groundwater (ASTM, 2022).

Based on review of Subject Property, adjoining property, and vicinity property findings within the default AOC, the dry cleaning operations that likely occurred at the Subject Property and at the Aspen Cleaners nearby are considered **VECs**.

7.5 Data Gaps

No data gaps were identified in connection with the Subject Property.

8.0 Conclusions

INTERA has performed a Phase I ESA in conformance with the scope and limitations of ASTM Standard E1527-21 for the Subject Property. Any exceptions to or deletions from this practice are described in **Section 7.5**. Based on the completion of the scope of services provided in support of this Phase I ESA, three RECs and two VECs were identified in connection with the Subject Property, as follows:

- Approximately 40 years (1960-2001) of dry cleaning operations conducted at the Subject Property corroborated by the Subject Property owner is considered a **REC/VEC** in connection with the Subject Property.
- The former UST (NMED PSTB Facility ID 49179) located at the adjoining property to the south (1407 3rd Street) is considered a **REC** due to its proximity to the Subject Property and because additional documentation of the tank removal and release determination was not identified.
- The Aspen Cleaners (1616 Cerillos Road) is considered a **REC/VEC** in connection with the Subject Property due to its close proximity and its more than 20-year history as a dry cleaner using PCE.

9.0 Recommendations

Based on the AAIs performed by the environmental professional in conformance with 40 CFR 312.31(a) and (b), this Phase I ESA has revealed evidence of one or more RECs/VECs or *significant data gaps* in connection with the Subject Property. Based on the conclusions of this Phase I ESA, INTERA recommends the following:

- Perform a Phase II investigation to assess the potential impacts to environmental media from the REC identified in connection with the Subject Property.

10.0 References

ASTM International (ASTM). 2021. *Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process.* Standard E1527-21. West Conshohocken, Pennsylvania: ASTM International.

———. 2022. *Standard Guide for Vapor Encroachment Screening on Property Involved in Real Estate Transactions*. Standard E2600-22. West Conshohocken, Pennsylvania. May 18, 2022.

ERIS. 2026a. Chain of Title Report and Environmental Lien Search.

———. 2025b. Topographic Maps.

———. 2025c. Historical Aerials.

———. 2025d. Physical Setting Report.

———. 2025e. Fire Insurance Maps.

———. 2025f. City Directory.

———. 2025g. Database Report.

National Oceanic and Atmospheric Administration (NOAA), 2026. National Weather Service Climate Data. https://www.weather.gov/wrh/Climate?wfo=hgx. Accessed March 31, 2026.

Santa Fe County Assessor (SFCA) Parcel Viewer. 2025. https://www.santafecountynm.gov/assessor/tools. Accessed January 13, 2026.

United States Environmental Protection Agency (EPA). 2005. *Standards and Practices for All Appropriate Inquiries*, Final Rule. 40 CFR Part 312. Washington, D.C.: Government Printing Office. Federal Register 70(210): November 1, 2005.

United States Geological Survey (USGS), 2023. *Santa Fe Quadrangle, New Mexico – Santa Fe County 7.5 Minute Series.* Accessed January 2026.

11.0 Disclaimer

The findings and conclusions contained in this report were derived using the methodologies provided in ASTM Standard E1527-21 (ASTM, 2021). The findings and conclusions contain all limitations inherent in these methodologies. There is the possibility that even with proper application of these methodologies, conditions may exist at the Subject Property that could not be identified within the scope of the Phase I ESA or that were not reasonably identifiable from the available information.

INTERA has prepared this report in accordance with the generally accepted environmental professional practices in use at the time of our study. This report may be used only by the User(s) and only for the purposes stated within a reasonable time from its issuance as outlined in ASTM Standard E1527-21 (ASTM, 2021). Land use, Site conditions (both onsite and offsite), or other factors may change over time, and additional work may be required with the passage of time. Any party other than the User(s) who wishes to use this report shall notify the User(s) of the intended use. Non-compliance with any of these requirements will release INTERA from any liability resulting from the use of this report.

INTERA does not warrant or guarantee in any manner, expressed or implied, that the conclusions and findings reported in this Phase I ESA, or the information obtained for this Phase I ESA from the records review or from other sources, including site reconnaissance observations, personal interviews, and correspondence, are accurate or complete beyond the limits of the methods applied. The methodologies of this Phase I ESA assessment are intended to meet the scope of a Phase I ESA in accordance with ASTM Standard E1527-21 (ASTM, 2021).

INTERA conducted this Phase I ESA and AAI into previous property ownership and uses in a manner consistent with ASTM Standard E1527-21 and the EPA AAI Final Rule (EPA, 2005) definitions of good commercial and customary ESA and AAI practices in the United States of America.

This Phase I ESA report is intended for use solely by the User(s). Any party other than the User(s) is explicitly denied any rights to rely on the findings, opinions, and conclusions of this Phase I ESA report.

12.0 Qualifications and Signatures of Environmental Professionals

Complete copies of resumes outlining the qualifications of the individuals completing this Phase I ESA report are included as **Appendix L**.

"I declare that, to the best of my professional knowledge and belief, I meet the definition of environmental professional as defined in Section 312.10 of 40 CFR 312. I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the Subject Property. I have developed and performed all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR part 312."

Matt Hubbard, Senior Environmental Scientist/Environmental Professional

Signature: 

Joeseph Tracy, P.G., Principal Geologist/Environmental Professional

Signature: 

FIGURES




Figure 1
Site Location
Danny's Cleaners
1406 2nd Street, Santa Fe, New Mexico

Exported: 4/29/2026 10:52 AM

S:\ABQ\NMENV.M007.SF-WALDO\Graphics\SantaFe_Waldo_P1P2_Proposal\SantaFe_Waldo_P1P2_Proposal.aprx

User: mhubbard

Layout: Figure 1 - 1406 Second Location

INTERA



Legend

- Subject Property
- Aspen Dry Cleaners
- Former UST (NMED PSTB Facility ID 49179)

0 125 250

US Feet

N

Figure 2
Site Plan
Danny's Cleaners
1406 2nd Street, Santa Fe, New Mexico

Exported: 6/1/2026 10:20 AM

S:\ABQ\NMENV.M007.SF-WALDO\Graphics\SantaFe_Waldo_P1P2_Proposal\SantaFe_Waldo_P1P2_Proposal.aprx

User: mhubbard

Layout: Figure 2 - Site Plan 1406 2nd

INTERA

APPENDIX A

Chain of Title Report and Environmental Lien and Activity and Use Limitation Search

CHAIN OF TITLE

Project Property: *1406 2ND STREET*
SANTA FE, NM 87505
Order No: *25121700732-COT1*
Date Completed: *01/05/2026*

ERIS – Environmental Risk Information Services hereby submits the following historical chain-of-title to the land described below.

Title to the estate or interest covered by this report appears to be vested in:

MARTIN R. MOYA

The following is the current property legal description (See deed for full legal description):

0.1506 AC LOT 1 BLK 4 CAPITAL & TOWNSITE

Assessor's Parcel Number(s): 018600698 AND 1-052-097-483-401

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

CHAIN OF TITLE REPORT

Order No: *25121700732-COT1*

HISTORICAL CHAIN OF TITLE

Public Records were searched at the SANTA FE COUNTY Assessor's office and the SANTA FE COUNTY Clerk's office back to 1932. The following conveyances were found of record.

1.	Deed Type:	WARRANTY DEED
	Deed Date:	03/06/1990
	Recorded:	03/06/1990
	Grantor:	DANIEL MOYA AND ETHEL L. MOYA
	Grantee:	MARTIN R. MOYA
	Instrument:	BOOK 206 / PAGE 040
	Notes:	NA
2.	Deed Type:	DEED
	Deed Date:	12/29/1989
	Recorded:	12/29/1989
	Grantor:	DANIEL MOYA AND ETHEL L. MOYA
	Grantee:	MARTIN MOYA
	Instrument:	668
	Notes:	NA
3.	Deed Type:	DEED
	Deed Date:	07/17/1951
	Recorded:	07/17/1951
	Grantor:	HARREY D. OSHEL AND PAULINE OSHEL
	Grantee:	DANIEL MOYA AND ETHEL L. MOYA
	Instrument:	BOOK 59 / PAGE 147
	Notes:	NA

LEASES AND MISCELLANEOUS

Comments: NONE IDENTIFIED.

CHAIN OF TITLE REPORT

Order No: *25121700732-COT1*

Thank You for Your Business
Please contact ERIS at **416-510-5204** or **info@erisinfo.com**
with any questions or comments

LIMITATION

This report is neither a guarantee of title, a commitment to insure, or a policy of title insurance. ERIS – Environmental Risk Information Services does not guarantee nor include any warranty of any kind whether expressed or implied, about the validity of all information included in this report since this information is retrieved as it is recorded from various agencies that make it available. The total liability is limited to the fee paid for this report.

SF - 1 SHORT FORM WARRANTY DEED—Rev. 4-75—New Mexico Statutory Form THE VALLIANT CO. ALBUQUERQUE, N. M.

WARRANTY DEED

674297

DANIEL MOYA AND ETHEL L. MOYA, husband and wife

, for consideration paid, grant

to MARTIN R. MOYA

,

whose address is 1406 Second Street, Santa Fe, New Mexico 87501

,

the following described real estate in Santa Fe County, New Mexico:

LOT 1

A lot lying, being and situate within lots 21, 22, 23 & 24, Block 4, of the Capital & Townsite Co. Addition to Santa Fe, New Mexico, located at 1406 Second Street, City of Santa Fe, Santa Fe County, New Mexico described as follows:

Commencing at a sanitary sewer manhole No. C6-1 located along Second Street, thence North 83 degrees 32 minutes 37 seconds West a distance of 43.90 feet to a point on the east corner of the South property line and the point of beginning of the lot herein described; thence South 48 degrees 13 minutes 26 seconds West a distance of 100.22 feet; thence North 41 degrees 56 minutes 43 seconds a distance of 65.34 feet; thence North 48 degrees 04 minutes 31 seconds East a distance of 100.12 feet; thence South 42 degrees 01 minutes 45 seconds East a distance of 65.60 feet, to the point of beginning. Containing 0.1506 acres more or less.

All as shown on a survey plat by Ector G. Alvarado, NMRPLS No. 8877, field survey January 12, 1990, entitled "Lot Line Adjustment For Daniel and Ethel L. Moya", described as Lot 1 on the plat. Recorded as document No. 699,496, February 14, 1990, Book 206, Page 040.

with warranty covenants.

WITNESS hand S and seal S this 6TH day of MARCH, 19 90

X Daniel Moya (Seal) (Seal)

X Ethel Moya (Seal) (Seal)

ACKNOWLEDGMENT FOR NATURAL PERSONS

STATE OF NEW MEXICO }
COUNTY OF SANTA FE } ss.

The foregoing instrument was acknowledged before me this 6TH day of MARCH, 19 90,

by DANIEL MOYA & ETHEL L MOYA
(Name or Names of Person or Persons Acknowledging)

My commission expires: 9-21-92
(Seal)

OFFICIAL SEAL
Yvonne Renee Sanchez
NOTARY PUBLIC — STATE OF NEW MEXICO
My Commission Expires 9-21-92

700850

FOR RECORDER'S USE ONLY

COUNTY OF SANTA FE)SS
STATE OF NEW MEXICO)
I hereby certify that this instrument was filed for record on the 6 day of MARCH A.D. 19 90, at 11:30 o'clock A m. and was duly recorded in book 674, page 297 of the records of Santa Fe County.
Witness my Hand and Seal of Office
Jena G. Armijo
County Clerk, Santa Fe County, N.M.
By Deputy

ACKNOWLEDGMENT FOR CORPORATIONS

STATE OF NEW MEXICO }
COUNTY OF } ss.

The foregoing instrument was acknowledged before me this , 19 ,

by
(Name of Officer)

of
(Name of Corporation Acknowledging)

a corporation, on behalf of said corporation.

CHAIN OF TITLE & LIEN SEARCHES

Project Property: *1406 2ND STREET*
SANTA FE, NM 87505
Order No: *25121700732-COTEL1*
Date Completed: *01/05/2026*

Title to the estate or interest covered by this report appears to be vested in:
MARTIN R. MOYA

The following is the current property legal description (See deed for full legal description):
0.1506 AC LOT 1 BLK 4 CAPITAL & TOWNSITE

Assessor's Parcel Number(s):
018600698 AND 1-052-097-483-401

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

TARGET PROPERTY INFORMATION

ADDRESS

1406 2ND STREET
SANTA FE, NM 87505

RESEARCH SOURCES

RECORDER:	SANTA FE COUNTY RECORDER'S OFFICE
ASSESSOR:	SANTA FE COUNTY ASSESSOR'S OFFICE
STATE:	NEW MEXICO ENVIRONMENT DEPARTMENT
FEDERAL:	UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
OTHER:	JUDICIAL RECORDS NOT SEARCHED. BASED ON AVAILABLE INFORMATION EVALUATED BY THE TITLE SEARCH PROFESSIONAL, THE JURISDICTION DOES NOT REQUIRE A SEARCH OF JUDICIAL RECORDS IN ORDER TO IDENTIFY ENVIRONMENTAL LIENS.
NOTES:	PUBLIC RECORDS OF SANTA FE COUNTY, NM WERE SEARCHED FROM JANUARY 1, 1980 TO DECEMBER 29, 2025, AND NO OTHER DEEDS VESTING TITLE IN THE SUBJECT PROPERTY WERE FOUND OF RECORD DURING THE PERIOD SEARCHED.

ENVIRONMENTAL LIENS

Environmental Lien: [X] NOT FOUND

ACTIVITY AND USE LIMITATIONS (AULs)

AULs: [X] NOT FOUND

CHAIN OF TITLE TO 1980

1. Deed Type: WARRANTY DEED
   Deed Date: 03/06/1990
   Recorded: 03/06/1990
   Grantor: DANIEL MOYA AND ETHEL L. MOYA
   Grantee: MARTIN R. MOYA
   Instrument: BOOK 206 / PAGE 040
   Notes:

2. Deed Type: DEED
   Deed Date: 12/29/1989
   Recorded: 12/29/1989
   Grantor: DANIEL MOYA AND ETHEL L. MOYA
   Grantee: MARTIN MOYA
   Instrument: 668
   Notes: RESEARCH CONDUCTED BACK TO 1980. THIS IS THE OLDEST DEED OF RECORD FOUND POST DECEMBER 31, 1979 (BETWEEN 01/01/1980 AND 12/29/1989).

LEASES AND MISCELLANEOUS

Comments: NONE IDENTIFIED.

The ERIS Environmental Lien Search Report to 1980 provides results from a search of available current land title records for environmental cleanup liens and other activity and use limitations, such as engineering and institutional controls.

A network of professional, trained researchers, following established procedures, uses client supplied property information to:

- Search for parcel information and / or legal description
- Search for ownership information
- Research official land title documents recorded at jurisdictional agencies such as recorder's' office, registries of deeds, county clerks' offices, etc.
- Access copies of deeds to 1980
- Search for environmental encumbrance(s) associated with the deeds
- Provide a copy of any environmental encumbrance(s) based upon a review of keywords in the instrument(s) (title, parties involved and description)
- Provide a copy of the deeds or cite documents reviewed

Thank You for Your Business
Please contact ERIS at **416-510-5204** or **info@erisinfo.com**
with any questions or comments

LIMITATION

This report is neither a guarantee of title, a commitment to insure, or a policy of title insurance. ERIS – Environmental Risk Information Services does not guarantee nor include any warranty of any kind whether expressed or implied, about the validity of all information included in this report since this information is retrieved as it is recorded from various agencies that make it available. The total liability is limited to the fee paid for this report.

DEED EXHIBIT

SF - 1 SHORT FORM WARRANTY DEED—Rev. 4-75—New Mexico Statutory Form THE VALLIANT CO. ALBUQUERQUE, N. M.

WARRANTY DEED

674297

DANIEL MOYA AND ETHEL L. MOYA, husband and wife

, for consideration paid, grant

to MARTIN R. MOYA

,

whose address is 1406 Second Street, Santa Fe, New Mexico 87501

,

the following described real estate in Santa Fe County, New Mexico:

LOT 1

A lot lying, being and situate within lots 21, 22, 23 & 24, Block 4, of the Capital & Townsite Co. Addition to Santa Fe, New Mexico, located at 1406 Second Street, City of Santa Fe, Santa Fe County, New Mexico described as follows:

Commencing at a sanitary sewer manhole No. C6-1 located along Second Street, thence North 83 degrees 32 minutes 37 seconds West a distance of 43.90 feet to a point on the east corner of the South property line and the point of beginning of the lot herein described; thence South 48 degrees 13 minutes 26 seconds West a distance of 100.22 feet; thence North 41 degrees 56 minutes 43 seconds a distance of 65.34 feet; thence North 48 degrees 04 minutes 31 seconds East a distance of 100.12 feet; thence South 42 degrees 01 minutes 45 seconds East a distance of 65.60 feet, to the point of beginning. Containing 0.1506 acres more or less.

All as shown on a survey plat by Ector G. Alvarado, NMRPLS No. 8877, field survey January 12, 1990, entitled "Lot Line Adjustment For Daniel and Ethel L. Moya", described as Lot 1 on the plat. Recorded as document No. 699,496, February 14, 1990, Book 206, Page 040.

with warranty covenants.

WITNESS hand S and seal S this 6TH day of MARCH, 19 90

X Daniel Moya (Seal) (Seal)

X Ethel Moya (Seal) (Seal)

ACKNOWLEDGMENT FOR NATURAL PERSONS

STATE OF NEW MEXICO }
COUNTY OF SANTA FE } ss.

The foregoing instrument was acknowledged before me this 6TH day of MARCH, 19 90,

by DANIEL MOYA & ETHEL L MOYA
(Name or Names of Person or Persons Acknowledging)

My commission expires: 9-21-92
(Seal)

OFFICIAL SEAL
Yvonne Renee Sanchez
NOTARY PUBLIC — STATE OF NEW MEXICO
My Commission Expires 9-21-92

700850

FOR RECORDER'S USE ONLY

COUNTY OF SANTA FE)SS
STATE OF NEW MEXICO)
I hereby certify that this instrument was filed for record on the 6 day of MARCH A.D. 19 90, at 11:30 o'clock A m. and was duly recorded in book 674, page 297 of the records of Santa Fe County.
Witness my Hand and Seal of Office
Jena G. Armijo
County Clerk, Santa Fe County, N.M.
By Deputy

ACKNOWLEDGMENT FOR CORPORATIONS

STATE OF NEW MEXICO }
COUNTY OF } ss.

The foregoing instrument was acknowledged before me this , 19 ,

by
(Name of Officer)

of
(Name of Corporation Acknowledging)

a corporation, on behalf of said corporation.

APPENDIX B

Historical Topographic Maps

TOPOGRAPHIC MAPS

Project Property:	Danny's Cleaners 1406 2nd Street Santa Fe NM 87505
Project No:	NMENV.M007.SF-WALDO
Requested By:	INTERA Incorporated
Order No:	25121700732
Date Completed:	December 17, 2025

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

We have searched USGS collections of current topographic maps and historical topographic maps for the project property. Below is a list of maps found for the project property and adjacent area. Maps are from 7.5 and 15 minute topographic map series, if available.

Year	Map Series
2023	7.5
2020	7.5
2017	7.5
2013	7.5
2002	7.5
1993	7.5
1977	7.5
1961	7.5
1952	7.5

Topographic Map Symbology for the maps may be available in the following documents:

Pre-1947

Page 223 of 1918 Topographic Instructions

Page 130 of 1928 Topographic Instructions


1947-2009

Topographic Map Symbols

2009-present

US Topo Map Symbols

Topographic Maps included in this report are produced by the USGS and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property.
No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc.(in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS', using Topographic Maps produced by the USGS. This maps contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.



2023

Order No. 25121700732



Available Quadrangle(s): Santa Fe, NM

Source: USGS 7.5 Minute Topographic Map

ERIS



2020


Order No. 25121700732

Available Quadrangle(s): Santa Fe, NM



Source: USGS 7.5 Minute Topographic Map

ERIS



2017


Order No. 25121700732



Available Quadrangle(s): Santa Fe, NM

Source: USGS 7.5 Minute Topographic Map

ERIS




2013

Order No. 25121700732

Available Quadrangle(s): Santa Fe, NM



Source: USGS 7.5 Minute Topographic Map




2002 (1-2002)

Aerial Photo Year: 1996

Order No. 25121700732

Available Quadrangle(s): Santa Fe, NM(1-2002)

Source: USGS 7.5 Minute Topographic Map



1993 (1-1993)

Aerial Photo Year: 1990


Order No. 25121700732



Available Quadrangle(s): Santa Fe, NM(1-1993)

Source: USGS 7.5 Minute Topographic Map

ERIS



1977 (1-1977)


Aerial Photo Year: 1976
Photo Revision Year: 1977

Order No. 25121700732



Available Quadrangle(s): Santa Fe, NM(1-1977)

Source: USGS 7.5 Minute Topographic Map



1961 (1-1961)

Aerial Photo Year: 1960

Order No. 25121700732



Available Quadrangle(s): Santa Fe, NM(1-1961)

Source: USGS 7.5 Minute Topographic Map

ERIS



1952 (1-1952)

Aerial Photo Year: 1951

Order No. 25121700732



Available Quadrangle(s): Santa Fe, NM(1-1952)

Source: USGS 7.5 Minute Topographic Map

APPENDIX C

Historical Aerial Photographs

HISTORICAL AERIALS

Project Property: Danny's Cleaners
1406 2nd Street
Santa Fe NM 87505

Project No: NMENV.M007.SF-WALDO

Requested By: INTERA Incorporated

Order No: 25121700732

Date Completed: December 19,2025

Aerial Maps included in this report are produced by the sources listed above and are to be used for research purposes including a phase I report. Maps are not to be resold as commercial property. ERIS provides no warranty of accuracy or liability. The information contained in this report has been produced using aerial photos listed in above sources by ERIS Information Inc. (in the US) and ERIS Information Limited Partnership (in Canada), both doing business as 'ERIS'. The maps contained in this report do not purport to be and do not constitute a guarantee of the accuracy of the information contained herein. Although ERIS has endeavored to present information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Date	Source	Scale	Comments
2022	United States Department of Agriculture	1" = 500'	
2020	United States Department of Agriculture	1" = 500'	
2018	United States Department of Agriculture	1" = 500'	
2016	United States Department of Agriculture	1" = 500'	
2014	United States Department of Agriculture	1" = 500'	
2011	United States Department of Agriculture	1" = 500'	
2009	United States Department of Agriculture	1" = 500'	
2005	United States Geological Survey	1" = 500'	
1996	United States Geological Survey	1" = 500'	
1991	United States Geological Survey	1" = 500'	
1981	United States Geological Survey	1" = 500'	
1976	United States Geological Survey	1" = 500'	Best Copy Available
1967	Pacific Western Techonolgies	1" = 500'	
1960	United States Geological Survey	1" = 500'	
1951	United States Geological Survey	1" = 500'	
1948	United States Geological Survey	1" = 500'	
1935	Agricultural Stabilization & Conserv. Service	1" = 500'	



Year: 2022
Source: USDA
Scale: 1" = 500'
Comment:

Address: 1406 2nd Street, Santa Fe, NM
Approx Center: -105.96932056,35.66627768

Order No: 25121700732

ERIS



Year: 2020
Source: USDA
Scale: 1" = 500'
Comment:

Address: 1406 2nd Street, Santa Fe, NM
Approx Center: -105.96932056,35.66627768

Order No: 25121700732

ERIS



Year: 2018
Source: USDA
Scale: 1" = 500'
Comment:

Address: 1406 2nd Street, Santa Fe, NM
Approx Center: -105.96932056,35.66627768

Order No: 25121700732

ERIS



Year: 2016
Source: USDA
Scale: 1" = 500'
Comment:

Address: 1406 2nd Street, Santa Fe, NM
Approx Center: -105.96932056,35.66627768

Order No: 25121700732

ERIS



Year: 2014
Source: USDA
Scale: 1" = 500'
Comment:

Address: 1406 2nd Street, Santa Fe, NM
Approx Center: -105.96932056,35.66627768

Order No: 25121700732

ERIS




Year: 2011
Source: USDA
Scale: 1" = 500'
Comment:

Address: 1406 2nd Street, Santa Fe, NM
Approx Center: -105.96932056,35.66627768

Order No: 25121700732

ERIS



Year: 2009
Source: USDA
Scale: 1" = 500'
Comment:

Address: 1406 2nd Street, Santa Fe, NM
Approx Center: -105.96932056,35.66627768

Order No: 25121700732

ERIS



Year: 2005
Source: USGS
Scale: 1" = 500'
Comment:

Address: 1406 2nd Street, Santa Fe, NM
Approx Center: -105.96932056,35.66627768

Order No: 25121700732

ERIS



Year: 1996
Source: USGS
Scale: 1" = 500'
Comment:

Address: 1406 2nd Street, Santa Fe, NM
Approx Center: -105.96932056,35.66627768

Order No: 25121700732

ERIS



Year: 1991
Source: USGS
Scale: 1" = 500'
Comment:

Address: 1406 2nd Street, Santa Fe, NM
Approx Center: -105.96932056,35.66627768

Order No: 25121700732

ERIS



Year: 1981
Source: USGS
Scale: 1" = 500'
Comment:

Address: 1406 2nd Street, Santa Fe, NM
Approx Center: -105.96932056,35.66627768

Order No: 25121700732

ERIS



Year: 1976
Source: USGS
Scale: 1" = 500'
Comment: Best Copy Available

Address: 1406 2nd Street, Santa Fe, NM
Approx Center: -105.96932056,35.66627768

Order No: 25121700732

ERIS



Year: 1967
Source: PWT
Scale: 1" = 500'
Comment:

Address: 1406 2nd Street, Santa Fe, NM
Approx Center: -105.96932056,35.66627768

Order No: 25121700732

ERIS



Year: 1960
Source: USGS
Scale: 1" = 500'
Comment:

Address: 1406 2nd Street, Santa Fe, NM
Approx Center: -105.96932056,35.66627768

Order No: 25121700732

ERIS



Year: 1951
Source: USGS
Scale: 1" = 500'
Comment:

Address: 1406 2nd Street, Santa Fe, NM
Approx Center: -105.96932056,35.66627768

Order No: 25121700732

ERIS



Year: 1948
Source: USGS
Scale: 1" = 500'
Comment:

Address: 1406 2nd Street, Santa Fe, NM
Approx Center: -105.96932056,35.66627768

Order No: 25121700732

ERIS



Year: 1935
Source: ASCS
Scale: 1" = 500'
Comment:

Address: 1406 2nd Street, Santa Fe, NM
Approx Center: -105.96932056,35.66627768

Order No: 25121700732

ERIS

APPENDIX D

Physical Setting Documentation

PSR
PHYSICAL SETTING REPORT

Property Information

Order Number:		25121700732p
Date Completed:		December 17, 2025
Project Number:		NMENV.M007.SF-WALDO
Project Property:		Danny's Cleaners 1406 2nd Street Santa Fe NM 87505
Coordinates:		
	Latitude:	35.66627768
	Longitude:	-105.96932056
	UTM Northing:	3947367.51908 Meters
	UTM Easting:	412269.502319 Meters
	UTM Zone:	UTM Zone 13S
	Elevation:	6,847.34 ft
	Slope Direction:	W

Topographic Information....2
Hydrologic Information....4
Geologic Information....9
Soil Information....11
Wells and Additional Sources....17
Summary....18
Detail Report....25
Radon Information....438
Appendix....439
Liability Notice....441


The ERIS ***Physical Setting Report - PSR*** provides comprehensive information about the physical setting around a site and includes a complete overview of topography and surface topology, in addition to hydrologic, geologic and soil characteristics. The location and detailed attributes of oil and gas wells, water wells, public water systems and radon are also included for review.

The compilation of both physical characteristics of a site and additional attribute data is useful in assessing the impact of migration of contaminants and subsequent impact on soils and groundwater.

Disclaimer

This Report does not provide a full environmental evaluation for the site or adjacent properties. Please see the terms and disclaimer at the end of the Report for greater detail.

Topographic Information



Current USGS Topo (2023)

0 0.2 0.4 0.8 Miles

N

Quadrangle(s): Santa Fe,NM


Source: USGS 7.5 Minute Topographic Map

Topographic Information

The previous topographic map(s) are created by seamlessly merging and cutting current USGS topographic data. Below are shaded relief map(s), derived from USGS elevation data to show surrounding topography in further detail.

Topographic information at project property:

Elevation:	6,847.34 ft
Slope Direction:	W



Hydrologic Information



Wetland

0 0.075 0.15 0.3 Miles

N

This map shows wetland existence using data from US Fish & Wildlife.
Data coverage is shown to the right. Gray indicates no data available in the area.

- Estuarine and Marine Deepwater
- Estuarine and Marine Wetland
- Freshwater Emergent Wetland
- Freshwater Forested/Shrub Wetland
- Freshwater Pond
- Lake
- Other
- Riverine

ERIS

Hydrologic Information



Flood Hazard Zones

This map shows FEMA flood hazard zones based on FEMA's National Flood Hazard Layer. FIRM Panels are overlayed. An absent FIRM panel represents no data available.

Miles
0 0.05 0.1

N

- 1% Annual Chance Flood Hazard
- Regulatory Floodway
- Special Floodway
- Area of Undetermined Flood Hazard
- 0.2% Annual Chance Flood Hazard
- Future Conditions 1% Annual Chance Flood Hazard
- Area with Reduced Risk Due to Levee
- Area with Risk Due to Levee
- Open Water

Quadrangle(s): Santa Fe,NM

ERIS

Hydrologic Information

The Wetland Type map shows wetland existence overlaid on an aerial imagery. The Flood Hazard Zones map shows FEMA flood hazard zones overlaid on an aerial imagery. Relevant FIRM panels and detailed zone information is provided below.
For detailed Zone descriptions please click the link: https://floodadvocate.com/fema-zone-definitions

Available FIRM Panels in area:	35049C0411E(effective:2012-12-04) 35049C0412E(effective:2012-12-04)

Flood Zone AE-01

Zone:	AE
Zone subtype:	

Flood Zone X-12

Zone:	X
Zone subtype:	AREA OF MINIMAL FLOOD HAZARD

Hydrologic Information

FEMA Flood Zone Definitions

Special Flood Hazard Areas – High Risk

Special Flood Hazard Areas represent the area subject to inundation by 1-percent-annual chance flood. Structures located within the SFHA have a 26-percent chance of flooding during the life of a standard 30-year mortgage. Federal floodplain management regulations and mandatory flood insurance purchase requirements apply in these zones.

ZONE	DESCRIPTION
A	Areas subject to inundation by the 1-percent-annual-chance flood event. Because detailed hydraulic analyses have not been performed, no Base Flood Elevations (BFEs) or flood depths are shown.
AE, A1-A30	Areas subject to inundation by the 1-percent-annual-chance flood event determined by detailed methods. BFEs are shown within these zones. (Zone AE is used on new and revised maps in place of Zones A1–A30.)
AH	Areas subject to inundation by 1-percent-annual-chance shallow flooding (usually areas of ponding) where average depths are 1–3 feet. BFEs derived from detailed hydraulic analyses are shown in this zone.
AO	Areas subject to inundation by 1-percent-annual-chance shallow flooding (usually sheet flow on sloping terrain) where average depths are 1–3 feet. Average flood depths derived from detailed hydraulic analyses are shown within this zone.
AR	Areas that result from the decertification of a previously accredited flood protection system that is determined to be in the process of being restored to provide base flood protection.
A99	Areas subject to inundation by the 1-percent-annual-chance flood event, but which will ultimately be protected upon completion of an under-construction Federal flood protection system. These are areas of special flood hazard where enough progress has been made on the construction of a protection system, such as dikes, dams, and levees, to consider it complete for insurance rating purposes. Zone A99 may be used only when the flood protection system has reached specified statutory progress toward completion. No BFEs or flood depths are shown.

Coastal High Hazard Areas – High Risk

Coastal High Hazard Areas (CHHA) represent the area subject to inundation by 1-percent-annual chance flood, extending from offshore to the inland limit of a primary front al dune along an open coast and any other area subject to high velocity wave action from storms or seismic sources. Structures located within the CHHA have a 26-percent chance of flooding during the life of a standard 30-year mortgage. Federal floodplain management regulations and mandatory purchase requirements apply in these zones.

ZONE	DESCRIPTION
V	Areas along coasts subject to inundation by the 1-percent-annual-chance flood event with additional hazards associated with storm-induced waves. Because detailed coastal analyses have not been performed, no BFEs or flood depths are shown.
VE, V1-V30	Areas along coasts subject to inundation by the 1-percent-annual-chance flood event with additional hazards due to storm-induced velocity wave action. BFEs derived from detailed hydraulic coastal analyses are shown within these zones. (Zone VE is used on new and revised maps in place of Zones V1–V30.)

Hydrologic Information

Moderate and Minimal Risk Areas


Areas of moderate or minimal hazard are studied based upon the principal source of flood in the area. However, buildings in these zones could be flooded by severe, concentrated rainfall coupled with inadequate local drainage systems. Local stormwater drainage systems are not normally considered in a community's flood insurance study. The failure of a local drainage system can create areas of high flood risk within these zones. Flood insurance is available in participating communities, but is not required by regulation in these zones. Nearly 25-percent of all flood claims filed are for structures located within these zones.

ZONE	DESCRIPTION
B, X (shaded)	Moderate risk areas within the 0.2-percent-annual-chance floodplain, areas of 1-percent-annual-chance flooding where average depths are less than 1 foot, areas of 1-percent-annual-chance flooding where the contributing drainage area is less than 1 square mile, and areas protected from the 1-percent-annual-chance flood by a levee. No BFEs or base flood depths are shown within these zones. (Zone X (shaded) is used on new and revised maps in place of Zone B.)
C, X (unshaded)	Minimal risk areas outside the 1-percent and .2-percent-annual-chance floodplains. No BFEs or base flood depths are shown within these zones. (Zone X (unshaded) is used on new and revised maps in place of Zone C.)

Undetermined Risk Areas

ZONE	DESCRIPTION
D	Unstudied areas where flood hazards are undetermined, but flooding is possible. No mandatory flood insurance purchase requirements apply, but coverage is available in participating communities.

Geologic Information



Geologic Units

This maps shows geologic units in the area. Please refer to the report for detailed descriptions.

N

Miles
0 0.125 0.25

ERIS

Geologic Information

The previous page shows USGS geology information. Detailed information about each unit is provided below.


Geologic Unit Qp

Unit Name:	Piedmont alluvial deposits
Unit Age:	Holocene to lower Pleistocene
Primary Rock Type:	Unconsolidated
Secondary Rock Type:	
Unit Description:	Includes deposits of higher gradient tributaries bordering major stream valleys, alluvial veneers of the piedmont slope, and alluvial fans. May locally include uppermost Pliocene deposits.

Geologic Unit QTs

Unit Name:	Upper Santa Fe Group
Unit Age:	Middle Pleistocene to uppermost Miocene
Primary Rock Type:	Conglomerate-sandstone
Secondary Rock Type:	Coarse-detrital
Unit Description:	Includes Camp Rice, Fort Hancock, Palomas, Sierra Ladrones, Arroyo Ojito, Ancha, Puye, and Alamosa Formations.

Soil Information



SSURGO Soils

N

0 0.125 0.25 Miles

This maps shows SSURGO soil units around the target property. Please refer to the report for detailed soil descriptions.

ERIS

Soil Information

The previous page shows a soil map using SSURGO data from USDA Natural Resources Conservation Service. Detailed information about each unit is provided below.

Map Unit 114 (27.83%)

Map Unit Name:	Devargas-Urban land complex, 1 to 3 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	C - Soils in this group have moderately high runoff potential when thoroughly wet. Water transmission through the soil is somewhat restricted.

Major components are printed below

Devargas(50%)

horizon A(0cm to 5cm)	Loam
horizon Bt1(5cm to 23cm)	Loam
horizon Bt2(23cm to 43cm)	Clay loam
horizon Btk1(43cm to 63cm)	Clay loam
horizon Btk2(63cm to 76cm)	Loam
horizon Bk(76cm to 84cm)	Very gravelly coarse sandy loam
horizon 2BCk(84cm to 107cm)	Extremely gravelly loamy coarse sand
horizon 2C1(107cm to 170cm)	Extremely cobbly coarse sand
horizon 2C2(170cm to 216cm)	Extremely gravelly loamy coarse sand
horizon 2C3(216cm to 239cm)	Very gravelly coarse sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 114 - Devargas-Urban land complex, 1 to 3 percent slopes

Component: Devargas (50%)
The Devargas component makes up 50 percent of the map unit. Slopes are 1 to 3 percent. This component is on high stream terraces, valleys. The parent material consists of alluvium derived from sandstone over alluvium derived from granite, gneiss, and schist. Depth to a root restrictive layer, strongly contrasting textural stratification, is 28 to 31 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is low. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the R035XA112NM Loamy ecological site. Nonirrigated land capability classification is 6c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 4 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 2 within 30 inches of the soil surface.

Component: Urban land (45%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Delvalle (3%)
Generated brief soil descriptions are created for major soil components. The Delvalle soil is a minor component.

Component: Panky (1%)
Generated brief soil descriptions are created for major soil components. The Panky soil is a minor component.

Component: Dumps (1%)
Generated brief soil descriptions are created for major soil components. The Dumps soil is a minor component.

Map Unit 200 (6.17%)

Map Unit Name:	Predawn loam, 1 to 4 percent slopes

Soil Information

Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	C - Soils in this group have moderately high runoff potential when thoroughly wet. Water transmission through the soil is somewhat restricted.

Major components are printed below

Predawn(90%)

horizon A(0cm to 5cm)	Loam
horizon BA(5cm to 10cm)	Loam
horizon Bt(10cm to 23cm)	Clay loam
horizon Btk1(23cm to 36cm)	Clay loam
horizon Btk2(36cm to 48cm)	Clay loam
horizon Bk1(48cm to 69cm)	Loam
horizon Bk2(69cm to 91cm)	Loam
horizon BCk1(91cm to 132cm)	Gravelly sandy loam
horizon BCk2(132cm to 196cm)	Very gravelly coarse sand
horizon C(196cm to 218cm)	Gravelly loamy sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 200 - Predawn loam, 1 to 4 percent slopes

Component: Predawn (90%)
The Predawn component makes up 90 percent of the map unit. Slopes are 1 to 4 percent. This component is on eroded fan remnants, fan piedmonts. The parent material consists of alluvium derived from granite, gneiss, schist, loess, and volcanic ash. Depth to a root restrictive layer, abrupt textural change, is 2 to 6 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately low. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the R035XA112NM Loamy ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 33 percent. The soil has a slightly saline horizon within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 9 within 30 inches of the soil surface.

Component: Alire (6%)
Generated brief soil descriptions are created for major soil components. The Alire soil is a minor component.

Component: Encantado (3%)
Generated brief soil descriptions are created for major soil components. The Encantado soil is a minor component.

Component: Urban land (1%)
Generated brief soil descriptions are created for major soil components. The Urban land soil is a minor component.

Map Unit 204 (0.28%)

Map Unit Name:	Altazano loamy sand, 0 to 2 percent slopes, flooded
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Somewhat excessively drained
Hydrologic Group - Dominant:	B - Soils in this group have moderately low runoff potential when thoroughly wet. Water transmission through the soil is unimpeded.

Major components are printed below

Altazano(85%)

horizon AC(0cm to 8cm)	Loamy sand
horizon C1(8cm to 20cm)	Fine sandy loam
horizon C2(20cm to 30cm)	Loamy sand
horizon C3(30cm to 46cm)	Stratified sandy loam to loam

horizon C4(46cm to 66cm)	Gravelly loamy coarse sand
horizon Btkb1(66cm to 74cm)	Loam
horizon Btkb2(74cm to 91cm)	Loam
horizon Bkb(91cm to 147cm)	Loam
horizon BCkb1(147cm to 193cm)	Gravelly coarse sandy loam
horizon BCkb2(193cm to 234cm)	Gravelly coarse sand

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 204 - Altazano loamy sand, 0 to 2 percent slopes, flooded

Component: Altazano (85%)
The Altazano component makes up 85 percent of the map unit. Slopes are 0 to 2 percent. This component is on flood plains on valley floors, valleys. The parent material consists of alluvium derived from granite, gneiss, schist, granitic sandstone, fanglomerate, and mudstone. Depth to a root restrictive layer, strongly contrasting textural stratification, is 22 to 30 inches. The natural drainage class is somewhat excessively drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is moderate. Shrink-swell potential is low. This soil is occasionally flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 1 percent. This component is in the R035XG114NM Gravelly ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 4 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 1 within 30 inches of the soil surface.

Component: Buckhorse (5%)
Generated brief soil descriptions are created for major soil components. The Buckhorse soil is a minor component.

Component: Levante (3%)
Generated brief soil descriptions are created for major soil components. The Levante soil is a minor component.

Component: Tanoan (3%)
Generated brief soil descriptions are created for major soil components. The Tanoan soil is a minor component.

Component: Riverwash (2%)
Generated brief soil descriptions are created for major soil components. The Riverwash soil is a minor component.

Component: Urban land (2%)
Generated brief soil descriptions are created for major soil components. The Urban land soil is a minor component.

Map Unit 207 (47.93%)

Map Unit Name: Urban land

No more attributes available for this map unit

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 207 - Urban land

Component: Urban land (85%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Alire (4%)
Generated brief soil descriptions are created for major soil components. The Alire soil is a minor component.

Component: Panky (3%)
Generated brief soil descriptions are created for major soil components. The Panky soil is a minor component.

Component: Altazano (2%)
Generated brief soil descriptions are created for major soil components. The Altazano soil is a minor component.

Component: Buckhorse (2%)

Soil Information

Generated brief soil descriptions are created for major soil components. The Buckhorse soil is a minor component.

Component: Predawn (2%)
Generated brief soil descriptions are created for major soil components. The Predawn soil is a minor component.

Component: Delvalle (1%)
Generated brief soil descriptions are created for major soil components. The Delvalle soil is a minor component.

Component: Tanoan (1%)
Generated brief soil descriptions are created for major soil components. The Tanoan soil is a minor component.

Map Unit 208 (17.79%)

Map Unit Name:	Alire-Urban land complex, 2 to 8 percent slopes
Bedrock Depth - Min:	
Watertable Depth - Annual Min:	
Drainage Class - Dominant:	Well drained
Hydrologic Group - Dominant:	C - Soils in this group have moderately high runoff potential when thoroughly wet. Water transmission through the soil is somewhat restricted.

Major components are printed below

Alire(50%)

horizon A(0cm to 10cm)	Loam
horizon Bt(10cm to 28cm)	Clay loam
horizon Btk1(28cm to 51cm)	Clay loam
horizon Btk2(51cm to 69cm)	Loam
horizon Bk1(69cm to 107cm)	Loam
horizon Bk2(107cm to 130cm)	Gravelly loam
horizon Bkq1(130cm to 175cm)	Gravelly loam
horizon Bkq2(175cm to 241cm)	Gravelly loam
horizon C(241cm to 251cm)	Gravelly sandy loam

Component Description:

Minor map unit components are excluded from this report.

Map Unit: 208 - Alire-Urban land complex, 2 to 8 percent slopes

Component: Alire (50%)
The Alire component makes up 50 percent of the map unit. Slopes are 2 to 8 percent. This component is on beveled eroded fan remnants, fan piedmonts. The parent material consists of alluvium derived from granite, gneiss, schist, and loess. Depth to a root restrictive layer is greater than 60 inches. The natural drainage class is well drained. Water movement in the most restrictive layer is moderately high. Available water to a depth of 60 inches (or restricted depth) is high. Shrink-swell potential is low. This soil is not flooded. It is not ponded. There is no zone of water saturation within a depth of 72 inches. Organic matter content in the surface horizon is about 2 percent. This component is in the R035XA112NM Loamy ecological site. Nonirrigated land capability classification is 4c. This soil does not meet hydric criteria. The calcium carbonate equivalent within 40 inches, typically, does not exceed 23 percent. There are no saline horizons within 30 inches of the soil surface. The soil has a maximum sodium adsorption ratio of 9 within 30 inches of the soil surface.

Component: Urban land (40%)
Generated brief soil descriptions are created for major soil components. The Urban land is a miscellaneous area.

Component: Predawn (4%)
Generated brief soil descriptions are created for major soil components. The Predawn soil is a minor component.

Component: Tanoan (3%)
Generated brief soil descriptions are created for major soil components. The Tanoan soil is a minor component.


Component: Altazano (2%)
Generated brief soil descriptions are created for major soil components. The Altazano soil is a minor component.

Component: Encantado (1%)

Soil Information

Generated brief soil descriptions are created for major soil components. The Encantado soil is a minor component.

Wells and Additional Sources



Wells & Additional Sources

N

0 0.15 0.3 0.6 Miles

- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- OGW Sites with Higher Elevation
- OGW Sites with Same Elevation
- OGW Sites with Lower Elevation
- OGW Sites with Unknown Elevation

ERIS

Wells and Additional Sources Summary

Federal Sources

Public Water Systems Violations and Enforcement Data

Map Key	PWS ID	Distance (ft)	Direction
93	NM3593519	3647.25	ENE
93	NM3590218	3647.25	ENE
93	NM3590231	3647.25	ENE

Safe Drinking Water Information System (SDWIS)

Map Key	PWS ID	Distance (ft)	Direction
93	NM3590218	3647.25	ENE
93	NM3593519	3647.25	ENE
93	NM3590231	3647.25	ENE
129	NM3592119	4030.88	NE

USGS National Water Information System

Map Key	Site No	Distance (ft)	Direction
9	USGS-354013105580601	1405.52	NNE
32	USGS-353945105574501	2216.32	SE
32	USGS-353945105574503	2216.32	SE
32	USGS-353945105574502	2216.32	SE
50	USGS-353933105575601	2650.09	SSE
62	USGS-353948105573201	3023.90	ESE
89	USGS-353925105575201	3523.25	SSE
95	USGS-354032105574801	3666.79	NNE
105	USGS-354018105584801	3791.22	WNW
109	USGS-354033105582901	3823.95	NNW
121	USGS-354038105580301	3916.03	N
123	USGS-354022105584701	3947.70	NW
131	USGS-354023105584701	4008.81	NW
135	USGS-354034105574301	4039.88	NNE
153	USGS-354006105585801	4142.17	W
159	USGS-354033105583701	4169.85	NW
170	USGS-354041105581301	4224.38	N
186	USGS-353933105585101	4358.06	SW
220	USGS-354021105585901	4729.79	WNW
227	USGS-08316535	4779.87	NNW
237	USGS-354013105590501	4872.58	WNW
255	USGS-353947105590801	5041.83	WSW
256	USGS-354034105585201	5054.84	NW
263	USGS-353916105573201	5110.21	SSE
265	USGS-354013105590801	5109.43	WNW

State Sources

Oil and Gas Wells

Map Key	ID	Distance (ft)	Direction
	No records found		

Wells and Additional Sources Summary

Point of Diversion Report

Map Key	POD Rec No	Distance (ft)	Direction
1	177055	303.72	NE
2	26352	373.35	E
3	35998	756.12	S
4	20878	982.67	SSW
5	51436	1031.79	NNE
6	12254	1133.68	ESE
7	146964	1290.81	E
8	47567	1384.34	WSW
10	53640	1443.30	WSW
11	50778	1438.17	ESE
12	10205	1470.89	W
13	27181	1671.86	WNW
14	40391	1740.52	WNW
15	33899	1784.39	NE
16	49038	1770.41	W
17	189490	1786.13	NW
18	49565	1820.14	NW
19	10092	1822.77	E
20	291277	1897.50	WNW
21	193400	1904.12	ESE
22	339114	2090.52	NE
23	28861	2072.20	WNW
24	291265	2090.28	W
25	174796	2100.33	SSE
25	174796	2100.33	SSE
26	42431	2121.75	NNW
27	57940	2156.96	NW
28	35556	2164.64	ESE
29	325646	2178.40	NW
30	42763	2180.30	E
31	8325	2199.52	W
33	264937	2277.86	SW
34	35609	2278.60	NW
35	264938	2320.54	SW
36	9001	2351.26	SE
37	54438	2375.27	E
37	59990	2375.27	E
38	339403	2437.23	WSW
39	337726	2427.06	WNW
39	37406	2427.06	WNW
40	325604	2466.56	W
41	33631	2472.95	W
42	325634	2498.96	NW
43	8067	2582.95	NW
44	291276	2570.08	W
45	284474	2588.50	N
46	6730	2606.24	E
47	54566	2599.99	W
48	49938	2612.73	WNW
48	333202	2612.73	WNW
49	60802	2616.74	W
51	25717	2675.96	ESE
53	264936	2768.03	SSW
54	44430	2801.35	NE
54	31584	2801.35	NE
55	39428	2779.17	WNW
56	51536	2857.20	NW
57	61486	2899.22	ENE
58	63913	2886.96	NW
59	7016	2933.02	WNW
60	52363	2947.34	WNW

60	287003	2947.34	WNW
61	7550	3009.93	NNW
61	67083	3009.93	NNW
61	42626	3009.93	NNW
63	8941	3112.23	W
64	339490	3155.41	NW
65	45116	3146.93	NNW
66	64690	3179.46	W
67	62930	3197.42	WNW
68	48042	3213.65	ESE
69	46048	3221.99	NW
70	22801	3242.79	WNW
71	68074	3268.60	NNW
72	51166	3278.27	WNW
73	24662	3289.27	WSW
74	5776	3297.47	NW
75	52939	3290.78	W
76	4922	3298.52	ESE
77	68392	3342.42	WNW
78	61622	3346.00	WNW
79	213917	3369.72	NW
80	59389	3358.28	W
81	49375	3403.40	W
82	30276	3427.76	WSW
83	32953	3425.17	W
84	325609	3450.64	WSW
85	52690	3472.89	W
86	291256	3474.43	W
87	67631	3492.79	W
88	3071	3489.79	W
90	23581	3543.15	W
91	48839	3625.78	WNW
92	50390	3628.52	WNW
94	349483	3646.04	NNE
96	147918	3654.66	N
97	15451	3664.53	WNW
98	15389	3728.53	WSW
99	181001	3726.88	NW
99	181001	3726.88	NW
100	30331	3729.47	NNW
101	44424	3748.95	NNW
102	336369	3758.16	NNE
103	152365	3758.88	N
104	223314	3796.21	ENE
104	223401	3796.21	ENE
107	33563	3795.46	W
108	16648	3820.04	WNW
110	18815	3824.12	S
111	147442	3831.09	NNE
113	304918	3850.48	SSW
114	194621	3863.00	WNW
115	34673	3886.32	NNW
115	193419	3886.32	NNW
116	139842	3889.31	NNW
117	49602	3897.09	NNE
117	49602	3897.09	NNE
117	49602	3897.09	NNE
118	312000	3898.95	NNE
119	40912	3888.41	SSE
120	64008	3898.27	SSW
122	58891	3926.16	WNW
124	16666	3962.15	E
125	37998	3972.22	WSW
126	23926	3979.44	WSW
127	40086	3982.26	NW
128	313727	3997.70	NE

130	36563	3998.50	W
132	334455	4019.35	W
133	341362	4026.52	NNW
134	313728	4043.37	NNE
134	313726	4043.37	NNE
134	313725	4043.37	NNE
136	146781	4043.06	NW
137	154509	4033.00	WNW
138	139796	4035.93	WNW
139	338328	4049.09	WNW
140	27469	4084.17	WNW
141	349484	4111.08	NNE
142	343037	4141.21	SW
143	312001	4133.48	NE
144	305038	4150.72	SW
145	343038	4150.48	SW
146	186588	4121.88	W
147	21479	4128.22	WNW
148	305036	4161.96	SW
149	14441	4134.23	WNW
150	190920	4137.02	WNW
151	200699	4151.08	NW
152	50209	4146.40	E
152	7104	4146.40	E
154	343041	4185.37	SW
155	343039	4184.97	SW
156	343040	4189.53	SW
157	305037	4192.06	SW
158	15035	4155.33	WNW
160	304643	4201.23	SW
161	58148	4171.71	WNW
162	289866	4181.26	SSW
163	313724	4211.31	NE
163	313723	4211.31	NE
164	50580	4202.95	NNW
165	7850	4199.41	W
166	343042	4242.75	SW
167	195280	4223.56	NNE
167	195280	4223.56	NNE
168	13204	4214.65	SSE
169	59650	4236.83	NW
169	35269	4236.83	NW
171	313721	4249.12	NE
171	313722	4249.12	NE
173	10148	4243.71	NW
174	34007	4268.23	NW
175	343043	4293.07	SW
176	304644	4295.39	SW
177	61117	4263.69	WNW
178	68364	4265.35	W
179	54204	4263.19	W
180	305035	4300.01	SW
181	67733	4273.61	W
181	21794	4273.61	W
181	39933	4273.61	W
181	328592	4273.61	W
182	35372	4280.42	NNW
183	335262	4290.89	W
184	17257	4283.32	N
184	17257	4283.32	N
184	17257	4283.32	N
185	191062	4320.90	NW
187	188762	4329.21	WNW
188	289817	4339.38	SSW
188	289816	4339.38	SSW
188	289832	4339.38	SSW

188	289830	4339.38	SSW
188	289815	4339.38	SSW
188	289822	4339.38	SSW
188	289837	4339.38	SSW
188	289833	4339.38	SSW
188	289824	4339.38	SSW
188	289823	4339.38	SSW
188	289829	4339.38	SSW
188	289827	4339.38	SSW
188	289831	4339.38	SSW
188	289835	4339.38	SSW
188	289818	4339.38	SSW
188	289821	4339.38	SSW
188	289814	4339.38	SSW
188	289826	4339.38	SSW
188	289828	4339.38	SSW
188	289836	4339.38	SSW
188	289820	4339.38	SSW
188	289838	4339.38	SSW
188	289825	4339.38	SSW
188	289819	4339.38	SSW
189	245161	4346.01	N
189	56130	4346.01	N
190	188782	4372.51	WNW
191	39567	4392.83	WNW
191	161618	4392.83	WNW
191	35766	4392.83	WNW
191	18078	4392.83	WNW
192	8591	4415.97	E
193	289862	4415.92	SSW
194	41405	4421.84	NW
195	9498	4440.28	NW
196	52313	4432.52	W
197	3137	4448.13	NNW
198	4805	4455.60	NNW
199	289863	4465.97	SSW
199	289864	4465.97	SSW
199	289865	4465.97	SSW
199	289867	4465.97	SSW
200	194622	4469.07	WNW
201	313736	4499.57	NNE
201	313735	4499.57	NNE
202	259927	4538.88	NE
203	349485	4510.99	NNE
204	47012	4535.01	WNW
205	289810	4538.84	SSW
205	289811	4538.84	SSW
205	289809	4538.84	SSW
205	289808	4538.84	SSW
205	289813	4538.84	SSW
205	289812	4538.84	SSW
206	46451	4596.22	WNW
206	67975	4596.22	WNW
206	45510	4596.22	WNW
206	26618	4596.22	WNW
207	283516	4608.73	SSW
208	42505	4614.78	W
208	60986	4614.78	W
209	45512	4661.61	NE
210	289871	4644.47	SSW
210	289869	4644.47	SSW
210	289872	4644.47	SSW
210	289868	4644.47	SSW
210	289870	4644.47	SSW
210	289873	4644.47	SSW
211	63318	4640.35	W

211	194224	4640.35	W
211	31900	4640.35	W
212	289853	4661.95	SSW
212	289846	4661.95	SSW
212	289842	4661.95	SSW
212	289852	4661.95	SSW
212	289859	4661.95	SSW
212	289860	4661.95	SSW
212	289854	4661.95	SSW
212	289858	4661.95	SSW
212	289845	4661.95	SSW
212	289848	4661.95	SSW
212	289861	4661.95	SSW
212	289857	4661.95	SSW
212	289841	4661.95	SSW
212	289843	4661.95	SSW
212	289844	4661.95	SSW
212	289850	4661.95	SSW
212	289849	4661.95	SSW
212	289856	4661.95	SSW
212	289847	4661.95	SSW
212	289840	4661.95	SSW
212	289851	4661.95	SSW
212	289839	4661.95	SSW
212	289855	4661.95	SSW
213	51629	4705.35	NE
214	11927	4674.47	N
214	49017	4674.47	N
215	197319	4688.05	W
216	335483	4702.46	NNE
217	31820	4705.31	NW
218	16369	4715.80	NW
218	66191	4715.80	NW
218	3563	4715.80	NW
218	39923	4715.80	NW
219	59074	4716.25	N
221	311999	4754.03	NNE
222	47954	4742.61	WNW
222	13595	4742.61	WNW
223	335487	4758.79	NNE
223	335486	4758.79	NNE
224	18058	4741.53	SSE
225	311998	4774.26	NNE
226	197472	4756.64	WNW
228	335635	4833.52	NE
229	30372	4812.11	WNW
230	322431	4832.84	NNE
231	313732	4842.38	NNE
231	313731	4842.38	NNE
232	311995	4854.23	NNE
233	27630	4851.25	WNW
234	335484	4869.48	NE
234	335485	4869.48	NE
235	204248	4868.51	WNW
236	313729	4888.20	NNE
236	313730	4888.20	NNE
238	333583	4877.46	N
239	35210	4887.64	WNW
239	329702	4887.64	WNW
240	315719	4914.30	NNE
241	313737	4920.87	NNE
242	11421	4926.48	W
243	39599	4926.58	N
244	60094	4953.36	WSW
244	6722	4953.36	WSW
245	60902	4944.14	ESE

246	336371	4977.47	NE
246	336370	4977.47	NE
247	311996	4978.49	NNE
248	343013	4968.29	W
249	70667	4990.21	ESE
250	25408	4998.46	WNW
251	311997	5037.05	NNE
252	9522	5040.66	WSW
253	53445	5025.88	WNW
253	68360	5025.88	WNW
254	18771	5030.07	WNW
254	202910	5030.07	WNW
254	14619	5030.07	WNW
254	31733	5030.07	WNW
254	48187	5030.07	WNW
254	55854	5030.07	WNW
254	59793	5030.07	WNW
254	334255	5030.07	WNW
254	65759	5030.07	WNW
254	49448	5030.07	WNW
254	21212	5030.07	WNW
254	26393	5030.07	WNW
257	13294	5048.72	W
258	196620	5063.60	W
259	24462	5069.06	NNW
260	36509	5071.73	W
261	60850	5102.90	NE
262	80704	5089.41	NNE
264	34019	5114.75	W
266	36482	5142.39	WSW
266	29277	5142.39	WSW
267	50043	5118.38	W
268	336372	5138.86	NNE
268	336373	5138.86	NNE
269	313733	5141.54	NE
269	313734	5141.54	NE
270	12170	5126.42	WNW
271	181277	5162.32	SW
272	28332	5149.99	ENE
273	70300	5158.98	WSW
273	46452	5158.98	WSW
273	47640	5158.98	WSW
274	44399	5171.83	NNW
275	22336	5173.78	WNW
276	16596	5174.64	NNW
277	50304	5191.48	WNW
278	199572	5206.94	WNW
278	31284	5206.94	WNW
278	53950	5206.94	WNW
279	58344	5226.89	NW
280	54384	5239.90	E
281	25444	5241.82	NW
281	7170	5241.82	NW
281	67450	5241.82	NW
282	35347	5243.50	NNW
283	38132	5274.74	WNW

Public Water Supply Wells

Map Key	TINWSF Is No	Distance (ft)	Direction
52	1948	2737.20	SSE
106	1950	3798.58	NW
112	1947	3844.94	NNE
172	1937	4227.95	N

Public Water Systems Violations and Enforcement Data

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
93	ENE	0.69	3,647.25	6,934.98	PWSV

PWS ID:	NM3593519
PWS Type Code:	TNCWS
PWS Type Description:	Transient non-community system
Primary Source Code:	GW
Primary Source Desc:	Ground water
PWS Activity Code:	A
PWS Activity Description:	Active
PWS Deactivation Date:	
Zip Code:	87505
Phone No:	505-699-4669
Phone Ext No:	
Admin Name:	BAKER, COLLEEN
Alt Phone No:	
Email Addr:	colleen.baker@emnrd.nm.gov
Fax No:	
Cds ID:	
Population Served Count:	150
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	01/10/1981
Gw or Sw:	Groundwater
Gw Sw Code:	GW
Is Grant Eligible Ind:	Yes
Outstanding Performer:	
Is School or Daycare Ind:	No
Is Source Water Protection:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Lt2 Schedule Cat Code:	
Last Reported Date:	06/25/2025
Org Name:	BAKER, COLLEEN
Outstanding Perform Begin Date:	
Owner Type:	State government
Pop Cat 11:	101-500
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Season Begin Date:	01-01

Wells and Additional Sources Detail Report

Season End Date:	12-31
Service Connections Count:	29
Submission Status Code:	Y
Submissionyearquarter:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin Date:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	ALAMOGORDO
County Served:	Otero
Source Water Protection Code:	N

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
93	ENE	0.69	3,647.25	6,934.98	PWSV

PWS ID:	NM3590218
PWS Type Code:	TNCWS
PWS Type Description:	Transient non-community system
Primary Source Code:	GW
Primary Source Desc:	Ground water
PWS Activity Code:	A
PWS Activity Description:	Active
PWS Deactivation Date:	
Zip Code:	87505
Phone No:	505-699-4669
Phone Ext No:	
Admin Name:	BAKER, COLLEEN
Alt Phone No:	
Email Addr:	colleen.baker@emnrd.nm.gov
Fax No:	
Cds ID:	
Population Served Count:	50
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	03/12/1980
Gw or Sw:	Groundwater
Gw Sw Code:	GW
Is Grant Eligible Ind:	Yes
Outstanding Performer:	
Is School or Daycare Ind:	No

Is Source Water Protection:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Lt2 Schedule Cat Code:	
Last Reported Date:	06/25/2025
Org Name:	BAKER, COLLEEN
Outstanding Perform Begin Date:	
Owner Type:	State government
Pop Cat 11:	<=100
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	23
Submission Status Code:	Y
Submissionyearquarter:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin Date:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	GUADALUPITA
County Served:	Mora
Source Water Protection Code:	N

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
93	ENE	0.69	3,647.25	6,934.98	PWSV

PWS ID:	NM3590231
PWS Type Code:	TNCWS
PWS Type Description:	Transient non-community system
Primary Source Code:	GW
Primary Source Desc:	Ground water
PWS Activity Code:	A
PWS Activity Description:	Active
PWS Deactivation Date:	
Zip Code:	87505

Wells and Additional Sources Detail Report

Phone No:	505-699-4669
Phone Ext No:	
Admin Name:	BAKER, COLLEEN
Alt Phone No:	
Email Addr:	colleen.baker@emnrd.nm.gov
Fax No:	
Cds ID:	
Population Served Count:	178
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	03/12/1980
Gw or Sw:	Groundwater
Gw Sw Code:	GW
Is Grant Eligible Ind:	Yes
Outstanding Performer:	
Is School or Daycare Ind:	No
Is Source Water Protection:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Lt2 Schedule Cat Code:	
Last Reported Date:	06/25/2025
Org Name:	BAKER, COLLEEN
Outstanding Perform Begin Date:	
Owner Type:	State government
Pop Cat 11:	101-500
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	1
Submission Status Code:	Y
Submissionyearquarter:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin Date:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	CLAYTON
County Served:	Union

Source Water Protection Code: N

Safe Drinking Water Information System (SDWIS)

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
93	ENE	0.69	3,647.25	6,934.98	SDWIS

PWS ID:	NM3590218
PWS Type Code:	TNCWS
PSW Type:	Transient non-community system
Primary Source Code:	GW
Primary Source:	Ground water
Pws Activity Code:	A
Activity:	Active
PWS Deactivation Dt:	
Phone No:	505-699-4669
Phone Ext No:	
Admin Name:	BAKER, COLLEEN
Alt Phone No:	
Email Addr:	colleen.baker@emnrd.nm.gov
Fax No:	
Cds ID:	
Population Served Count:	50
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	03/12/1980
Gw or Sw:	Groundwater
Is Grant Eligible Ind:	Yes
Outstanding Performer:	
Is School or Daycare Ind:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Last Reported Date:	06/25/2025
Org Name:	BAKER, COLLEEN
Outstanding Perform Begin Date:	
Owner Type:	State government
Pop Cat 11:	<=100
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Primacy Agency Code:	NM
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	23

Wells and Additional Sources Detail Report

Submission Yr Qtr:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	GUADALUPITA
County Served:	Mora

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
93	ENE	0.69	3,647.25	6,934.98	SDWIS

PWS ID:	NM3593519
PWS Type Code:	TNCWS
PSW Type:	Transient non-community system
Primary Source Code:	GW
Primary Source:	Ground water
Pws Activity Code:	A
Activity:	Active
PWS Deactivation Dt:	
Phone No:	505-699-4669
Phone Ext No:	
Admin Name:	BAKER, COLLEEN
Alt Phone No:	
Email Addr:	colleen.baker@emnrd.nm.gov
Fax No:	
Cds ID:	
Population Served Count:	150
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	01/10/1981
Gw or Sw:	Groundwater
Is Grant Eligible Ind:	Yes
Outstanding Performer:	
Is School or Daycare Ind:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Last Reported Date:	06/25/2025
Org Name:	BAKER, COLLEEN
Outstanding Perform Begin Date:	
Owner Type:	State government
Pop Cat 11:	101-500

Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Primacy Agency Code:	NM
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	29
Submission Yr Qtr:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	ALAMOGORDO
County Served:	Otero

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
93	ENE	0.69	3,647.25	6,934.98	SDWIS

PWS ID:	NM3590231
PWS Type Code:	TNCWS
PSW Type:	Transient non-community system
Primary Source Code:	GW
Primary Source:	Ground water
Pws Activity Code:	A
Activity:	Active
PWS Deactivation Dt:	
Phone No:	505-699-4669
Phone Ext No:	
Admin Name:	BAKER, COLLEEN
Alt Phone No:	
Email Addr:	colleen.baker@emnrd.nm.gov
Fax No:	
Cds ID:	
Population Served Count:	178
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	03/12/1980
Gw or Sw:	Groundwater
Is Grant Eligible Ind:	Yes

Wells and Additional Sources Detail Report

Outstanding Performer:	
Is School or Daycare Ind:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Last Reported Date:	06/25/2025
Org Name:	BAKER, COLLEEN
Outstanding Perform Begin Date:	
Owner Type:	State government
Pop Cat 11:	101-500
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Primacy Agency Code:	NM
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	1
Submission Yr Qtr:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	CLAYTON
County Served:	Union

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
129	NE	0.76	4,030.88	6,905.91	SDWIS

PWS ID:	NM3592119
PWS Type Code:	TNCWS
PSW Type:	Transient non-community system
Primary Source Code:	GW
Primary Source:	Ground water
Pws Activity Code:	I
Activity:	Inactive
PWS Deactivation Dt:	06/01/1983
Phone No:	505-983-0100
Phone Ext No:	
Admin Name:	CLOUDCROFT HIGHWAY SPRING

Alt Phone No:	
Email Addr:	
Fax No:	
Cds ID:	
Population Served Count:	25
Epa Region Desc:	Region 6
Epa Region:	06
First Reported Date:	03/12/1980
Gw or Sw:	Groundwater
Is Grant Eligible Ind:	No
Outstanding Performer:	
Is School or Daycare Ind:	No
Is Wholesaler Ind:	No
Lt2 Schedule Cat:	
Last Reported Date:	12/20/1996
Org Name:	
Outstanding Perform Begin Date:	
Owner Type:	State government
Pop Cat 11:	<=100
Pop Cat 2:	<10,000
Pop Cat 3:	<=3300
Pop Cat 4:	<10K
Pop Cat 5:	<=500
Primacy Agency:	New Mexico
Primacy Agency Code:	NM
Season Begin Date:	01-01
Season End Date:	12-31
Service Connections Count:	1
Submission Yr Qtr:	2025Q2
Primacy Type:	State
Dbpr Schedule Category:	
Submission Status:	Reported and accepted
Reduced Monitoring Begin:	
Reduced Monitoring End Date:	
Reduced Rtcr Monitoring:	
Seasonal Startup System:	
Source Protection Begin Date:	
City Served:	
County Served:	Santa Fe

USGS National Water Information System

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
9	NNE	0.27	1,405.52	6,851.28	FED USGS

Site No: USGS-354013105580601
Site Type: Well
Formation Type: Santa Fe Group
Date Drilled: 19050101
Well Depth: 989
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.27.441
Latitude: 35.67022220000000
Longitude: -105.9679167000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
32	SE	0.42	2,216.32	6,884.46	FED USGS

Site No: USGS-353945105574501
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19860916
Well Depth: 1952
Well Depth Unit: ft
Well Hole Depth: 2020
Well Hole Depth Unit: ft
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.35.1314A SANTA FE 1 DEEP PIEZO.
Latitude: 35.66253120000000
Longitude: -105.9630770000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
32	SE	0.42	2,216.32	6,884.46	FED USGS

Site No: USGS-353945105574503
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19860916
Well Depth: 780
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.35.1314C SANTA FE 1 SHALLOW PIEZO.
Latitude: 35.66253120000000
Longitude: -105.9630770000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
32	SE	0.42	2,216.32	6,884.46	FED USGS

Site No: USGS-353945105574502
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19860916
Well Depth: 1060
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.35.1314B SANTA FE 1 MIDDLE PIEZO.
Latitude: 35.66253120000000
Longitude: -105.9630770000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
50	SSE	0.50	2,650.09	6,867.25	FED USGS

Site No: USGS-353933105575601
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19570304
Well Depth: 820
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.34.422
Latitude: 35.65919797000000
Longitude: -105.9661327000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
62	ESE	0.57	3,023.90	6,904.05	FED USGS

Site No: USGS-353948105573201
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19780601
Well Depth: 356
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.35.141
Latitude: 35.66336457000000

Longitude: -105.9594659000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
89	SSE	0.67	3,523.25	6,831.95	FED USGS

Site No: USGS-353925105575201
Site Type: Well
Formation Type:
Date Drilled:
Well Depth: 820
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.34.4224
Latitude: 35.65697580000000
Longitude: -105.9650215000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
95	NNE	0.69	3,666.79	6,867.14	FED USGS

Site No: USGS-354032105574801
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.26.133SNTFEGRANT
Latitude: 35.67558640000000
Longitude: -105.9639105000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
105	WNW	0.72	3,791.22	6,765.87	FED USGS

Site No: USGS-354018105584801
Site Type: Well
Formation Type:
Date Drilled:
Well Depth: 68.0
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:

Wells and Additional Sources Detail Report

Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.27.31344
Latitude: 35.67169750000000
Longitude: -105.9805775000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
109	NNW	0.72	3,823.95	6,786.58	FED USGS

Site No: USGS-354033105582901
Site Type: Well
Formation Type:
Date Drilled: 19530101
Well Depth: 88.0
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.27.144
Latitude: 35.67586410000000
Longitude: -105.9752996000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
121	N	0.74	3,916.03	6,845.71	FED USGS

Site No: USGS-354038105580301
Site Type: Well
Formation Type:
Date Drilled: 19430101
Well Depth: 140
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.27.241
Latitude: 35.67725300000000
Longitude: -105.9680773000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
123	NW	0.75	3,947.70	6,761.57	FED USGS

Site No: USGS-354022105584701
Site Type: Well
Formation Type:
Date Drilled: 19710101
Well Depth: 809

Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.27.31413
Latitude: 35.67280859000000
Longitude: -105.9802997000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
131	NW	0.76	4,008.81	6,763.58	FED USGS

Site No: USGS-354023105584701
Site Type: Well
Formation Type:
Date Drilled:
Well Depth: 64.0
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.27.3121
Latitude: 35.67308636000000
Longitude: -105.9802997000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
135	NNE	0.77	4,039.88	6,878.26	FED USGS

Site No: USGS-354034105574301
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19510312
Well Depth: 725
Well Depth Unit: ft
Well Hole Depth: 1523
Well Hole Depth Unit: ft
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.26.133
Latitude: 35.67614197000000
Longitude: -105.9625216000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
153	W	0.78	4,142.17	6,754.49	FED USGS

Site No: USGS-354006105585801
Site Type: Well

Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19640710
Well Depth: 67.0
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.28.444
Latitude: 35.66836424000000
Longitude: -105.9833553000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
159	NW	0.79	4,169.85	6,768.79	FED USGS

Site No: USGS-354033105583701
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19500101
Well Depth: 39
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.27.143
Latitude: 35.67586408000000
Longitude: -105.9775219000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
170	N	0.80	4,224.38	6,809.88	FED USGS

Site No: USGS-354041105581301
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19510801
Well Depth: 740
Well Depth Unit: ft
Well Hole Depth: 740
Well Hole Depth Unit: ft
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.27.232
Latitude: 35.67808629000000
Longitude: -105.9708551000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
186	SW	0.83	4,358.06	6,768.01	FED USGS

Site No: USGS-353933105585101
Site Type: Well
Formation Type:
Date Drilled:
Well Depth: 61.3
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.34.311
Latitude: 35.65919785000000
Longitude: -105.9814108000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
220	WNW	0.90	4,729.79	6,743.45	FED USGS

Site No: USGS-354021105585901
Site Type: Well
Formation Type:
Date Drilled:
Well Depth: 50.0
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.28.42223
Latitude: 35.67253079000000
Longitude: -105.9836330000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
227	NNW	0.91	4,779.87	6,783.46	FED USGS

Site No: USGS-08316535
Site Type: Stream
Formation Type:
Date Drilled:
Well Depth:
Well Depth Unit:
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: SANTA FE RIVER AT RICARDO RD, AT SANTA FE, NM
Latitude: 35.67891957000000
Longitude: -105.9747440000000

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
237	WNW	0.92	4,872.58	6,734.98	FED USGS

Site No:	USGS-354013105590501
Site Type:	Well
Formation Type:	
Date Drilled:	
Well Depth:	
Well Depth Unit:	
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	17N.09E.28.4424
Latitude:	35.67030860000000
Longitude:	-105.9852998000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
255	WSW	0.95	5,041.83	6,734.71	FED USGS

Site No:	USGS-353947105590801
Site Type:	Well
Formation Type:	
Date Drilled:	
Well Depth:	40.0
Well Depth Unit:	ft
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	17N.09E.33.241
Latitude:	35.66308659000000
Longitude:	-105.9861330000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
256	NW	0.96	5,054.84	6,753.65	FED USGS

Site No:	USGS-354034105585201
Site Type:	Well
Formation Type:	
Date Drilled:	19470101
Well Depth:	38.0
Well Depth Unit:	ft
Well Hole Depth:	
Well Hole Depth Unit:	
Reporting Agency:	USGS New Mexico Water Science Center
Station Name:	17N.09E.27.133

Latitude: 35.67614180000000
Longitude: -105.9816886000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
263	SSE	0.97	5,110.21	6,907.11	FED USGS

Site No: USGS-353916105573201
Site Type: Well
Formation Type: Tesuque Formation, Undifferentiated Unit
Date Drilled: 19570501
Well Depth: 275
Well Depth Unit: ft
Well Hole Depth: 275
Well Hole Depth Unit: ft
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.35.343
Latitude: 35.65447590000000
Longitude: -105.9594659000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
265	WNW	0.97	5,109.43	6,730.47	FED USGS

Site No: USGS-354013105590801
Site Type: Well
Formation Type:
Date Drilled:
Well Depth: 85.0
Well Depth Unit: ft
Well Hole Depth:
Well Hole Depth Unit:
Reporting Agency: USGS New Mexico Water Science Center
Station Name: 17N.09E.28.441
Latitude: 35.67030860000000
Longitude: -105.9861331000000

Point of Diversion Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
1	NE	0.06	303.72	6,854.17	WATER WELLS

License Nb: 0
POD No: 42336
POD Rec No: 177055
POD Basin: RG
POD Suffix: POD2
Pod Sub Ba: SF
District Office S:
Surv Map:
Other Loc:
Zone :
BLK:
Percent Sh: 0

Wells and Additional Sources Detail Report

POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-42336-CLW225828/26352/RG-42	Easting:	412349.1
Pcw Rcv Da:		Northing:	3947442.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/01/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	583800.0
Static Lev:	0	Y:	1698100.0
Tract Nbr:		Point Y:	35.66696433
Map Nbr:		Point X:	-105.96844942
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
2	E	0.07	373.35	6,858.88	WATER WELLS

License Nb:	1004	District Office S:	
POD No:	42336	Surv Map:	
POD Rec No:	26352	Other Loc:	1522 Cochiti St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	8/9 4 SF
Start Date:	12/04/1984, 12:00 AM	Restrict :	0.0
Finish Date:	12/07/1984, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	12/17/1984, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	240	UTM Zone:	13
Depth of Water:	190	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412408.7
Pcw Rcv Da:		Northing:	3947365.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/05/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Indian School Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1724242.0
Static Lev:	0	Y:	1697911.0
Tract Nbr:		Point Y:	35.66627275
Map Nbr:		Point X:	-105.96778258
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
3	S	0.14	756.12	6,849.77	WATER WELLS

License Nb:	0	District Office S:	
POD No:	30681	Surv Map:	
POD Rec No:	35998	Other Loc:	
POD Basin:	RG	Zone :	C

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412283.9
Pcw Rcv Da:		Northing:	3947108.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/27/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	583600.0
Static Lev:	0	Y:	1697000.0
Tract Nbr:		Point Y:	35.66394387
Map Nbr:		Point X:	-105.96913328
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
4	SSW	0.19	982.67	6,843.35	WATER WELLS

License Nb:	0	District Office S:	
POD No:	37924	Surv Map:	
POD Rec No:	20878	Other Loc:	1608 Fourth St

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	23 13 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412156.5
Pcw Rcv Da:		Northing:	3947062.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/11/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1723427.0
Static Lev:	0	Y:	1696905.0
Tract Nbr:		Point Y:	35.66351603
Map Nbr:		Point X:	-105.97053564
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
5	NNE	0.20	1,031.79	6,851.46	WATER WELLS

License Nb:	228	District Office S:	
POD No:	14882	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	51436	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/09/1967, 12:00 AM	Restrict :	0.0
Finish Date:	05/10/1967, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	09/18/1967, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	100	UTM Zone:	13
Depth of Water:	55	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	412352.0
Pcw Rcv Da:		Northing:	3947700.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/29/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66928238
Map Nbr:		Point X:	-105.96844538
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	One Block West Osage On Agua Fria.		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
6	ESE	0.21	1,133.68	6,873.07	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	38027	Surv Map:	
POD Rec No:	12254	Other Loc:	1630 Jay St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	5 6 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412634.8
Pcw Rcv Da:		Northing:	3947294.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/18/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Young'S Mountain View Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1724987.0
Static Lev:	0	Y:	1697686.0
Tract Nbr:		Point Y:	35.66564912
Map Nbr:		Point X:	-105.965277
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
7	E	0.24	1,290.81	6,878.68	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	622	District Office S:	
POD No:	71072	Surv Map:	
POD Rec No:	146964	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412684.1
Pcw Rcv Da:		Northing:	3947423.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/12/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	584900.0
Static Lev:	0	Y:	1698050.0
Tract Nbr:		Point Y:	35.66681824
Map Nbr:		Point X:	-105.96474638
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
8	WSW	0.26	1,384.34	6,820.63	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	622	District Office S:	
POD No:	35311	Surv Map:	
POD Rec No:	47567	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/17/1980, 12:00 AM	Restrict :	0.0
Finish Date:	11/18/1980, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/01/1980, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	137	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411888.2
Pcw Rcv Da:		Northing:	3947144.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/15/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	582300.0
Static Lev:	0	Y:	1697100.0
Tract Nbr:		Point Y:	35.66422864
Map Nbr:		Point X:	-105.97350851
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
10	WSW	0.27	1,443.30	6,821.54	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	622	District Office S:	
POD No:	60866	Surv Map:	
POD Rec No:	53640	Other Loc:	1862 Cerrillos Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA SF
Start Date:	01/12/1995, 12:00 AM	Restrict :	3.0
Finish Date:	01/13/1995, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	02/14/1995, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	320	UTM Zone:	13
Depth of Water:	169	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	3.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411887.8
Pcw Rcv Da:		Northing:	3947113.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/05/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	582300.0
Static Lev:	0	Y:	1697000.0
Tract Nbr:		Point Y:	35.66395364
Map Nbr:		Point X:	-105.97350959
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

11	ESE	0.27	1,438.17	6,877.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	42118	Surv Map:	
POD Rec No:	50778	Other Loc:	1710 Lena St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	A
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412723.8
Pcw Rcv Da:		Northing:	3947268.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1725280.0
Static Lev:	0	Y:	1697605.0
Tract Nbr:		Point Y:	35.66542441
Map Nbr:		Point X:	-105.96429099
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

12	W	0.28	1,470.89	6,811.68	WATER WELLS

License Nb:	790	District Office S:	
POD No:	31371	Surv Map:	
POD Rec No:	10205	Other Loc:	1844 Hopi Road, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	NRG	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	9 2 SF
Start Date:	11/26/1979, 12:00 AM	Restrict :	0.0
Finish Date:	12/03/1979, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	12/12/1979, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	160	UTM Zone:	13
Depth of Water:	117	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411794.4
Pcw Rcv Da:		Northing:	3947346.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411794.4
Static Lev:	0	Y:	3947346.8
Tract Nbr:		Point Y:	35.66604853
Map Nbr:		Point X:	-105.97456695
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Northern Rio Grande		
Grant :	Santa Fe		
Legal:	Parcel Number 1052097243469000000		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
13	WNW	0.32	1,671.86	6,807.93	WATER WELLS

License Nb:	228	District Office S:	
POD No:	42471	Surv Map:	
POD Rec No:	27181	Other Loc:	1834 Hano Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	5 3 U4 SF
Start Date:	11/28/1984, 12:00 AM	Restrict :	0.0
Finish Date:	11/30/1984, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	01/25/1985, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	140	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411792.9
Pcw Rcv Da:		Northing:	3947617.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/07/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1722211.0
Static Lev:	0	Y:	1698710.0
Tract Nbr:		Point Y:	35.66848429
Map Nbr:		Point X:	-105.97461313
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
14	WNW	0.33	1,740.52	6,804.09	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35520	Surv Map:	
POD Rec No:	40391	Other Loc:	1223 San Felipe Ave, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	12 2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-35520-/	Easting:	411740.3
Pcw Rcv Da:		Northing:	3947546.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/03/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411740.3
Static Lev:	0	Y:	3947546.7
Tract Nbr:		Point Y:	35.66784582
Map Nbr:		Point X:	-105.97518653
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		

Wells and Additional Sources Detail Report

Legal: Parcel Number 1052098225005000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
15	NE	0.34	1,784.39	6,870.66	WATER WELLS

License Nb:	228	District Office S:	
POD No:	50802	Surv Map:	
POD Rec No:	33899	Other Loc:	1303 Camino Corrales
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/01/1991, 12:00 AM	Restrict :	0.0
Finish Date:	06/05/1991, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	06/24/1991, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	560	UTM Zone:	13
Depth of Water:	90	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412658.1
Pcw Rcv Da:		Northing:	3947774.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/20/2016, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	584800.0
Static Lev:	0	Y:	1699200.0
Tract Nbr:		Point Y:	35.66997846
Map Nbr:		Point X:	-105.96507168
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
16	W	0.34	1,770.41	6,803.58	WATER WELLS

License Nb:	228	District Office S:	
POD No:	49459	Surv Map:	
POD Rec No:	49038	Other Loc:	1913 Hopi Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3 14 SF
Start Date:	08/25/1988, 12:00 AM	Restrict :	0.0
Finish Date:	09/02/1988, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	09/09/1988, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	290	UTM Zone:	13
Depth of Water:	160	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411701.7
Pcw Rcv Da:		Northing:	3947369.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/17/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721922.0
Static Lev:	0	Y:	1697893.0
Tract Nbr:		Point Y:	35.66624218
Map Nbr:		Point X:	-105.9755935
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
17	NW	0.34	1,786.13	6,807.47	WATER WELLS

License Nb:	0	District Office S:	
POD No:	36626	Surv Map:	
POD Rec No:	189490	Other Loc:	1808 Otowi Dr.
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3 1 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411827.6
Pcw Rcv Da:		Northing:	3947728.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/22/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1722320.0
Static Lev:	0	Y:	1699076.0
Tract Nbr:		Point Y:	35.66948897
Map Nbr:		Point X:	-105.97424194
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
18	NW	0.34	1,820.14	6,805.35	WATER WELLS

License Nb:	622	District Office S:	
POD No:	31385	Surv Map:	
POD Rec No:	49565	Other Loc:	1201 San Jose Avenue, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 2 SF
Start Date:	01/30/1979, 12:00 AM	Restrict :	0.0
Finish Date:	02/01/1979, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	02/14/1979, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	140	UTM Zone:	13
Depth of Water:	117	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411891.0
Pcw Rcv Da:		Northing:	3947804.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411891.0
Static Lev:	0	Y:	3947804.9
Tract Nbr:		Point Y:	35.670187
Map Nbr:		Point X:	-105.97354992

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal: Parcel Number 1052098274080000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
19	E	0.35	1,822.77	6,887.01	WATER WELLS

License Nb:	0	District Office S:	
POD No:	44039	Surv Map:	
POD Rec No:	10092	Other Loc:	1451 Santa Cruz Dr
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 5 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412851.0
Pcw Rcv Da:		Northing:	3947370.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/26/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Linda Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1725693.0
Static Lev:	0	Y:	1697944.0
Tract Nbr:		Point Y:	35.6663525

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.96289678
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
20	WNW	0.36	1,897.50	6,801.14	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31368	Surv Map:	
POD Rec No:	291277	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411679.5
Pcw Rcv Da:		Northing:	3947512.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/11/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581600.0
Static Lev:	0	Y:	1698300.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.66753116
Map Nbr:		Point X:	-105.97585446
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
21	ESE	0.36	1,904.12	6,882.97	WATER WELLS

License Nb:	0	District Office S:	
POD No:	05264	Surv Map:	
POD Rec No:	193400	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412852.0
Pcw Rcv Da:		Northing:	3947195.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/17/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0

Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66477403
Map Nbr:		Point X:	-105.96286678
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
22	NE	0.40	2,090.52	6,881.89	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A0942	Surv Map:	
POD Rec No:	339114	Other Loc:	Vw-1
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	26
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412752.9
Pcw Rcv Da:		Northing:	3947809.2
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	12/05/2022, 12:00 AM	Latitude Second:	13.09
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	50.5

Wells and Additional Sources Detail Report

Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67030238
Map Nbr:		Point X:	-105.96402813
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
23	WNW	0.39	2,072.20	6,796.63	WATER WELLS

License Nb:	228	District Office S:	
POD No:	40698	Surv Map:	
POD Rec No:	28861	Other Loc:	1208 San Felipe Ave
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 2 U2 SF
Start Date:	03/19/1984, 12:00 AM	Restrict :	0.0
Finish Date:	03/21/1984, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	06/15/1984, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	100	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411659.2
Pcw Rcv Da:		Northing:	3947618.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/15/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre No. 5	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721772.0
Static Lev:	0	Y:	1698710.0
Tract Nbr:		Point Y:	35.66848765
Map Nbr:		Point X:	-105.97609039
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
24	W	0.40	2,090.28	6,797.28	WATER WELLS

License Nb:	214	District Office S:	
POD No:	31329	Surv Map:	
POD Rec No:	291265	Other Loc:	1944 Hopi Road, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	9 11 SF
Start Date:	05/15/1980, 12:00 AM	Restrict :	0.0
Finish Date:	05/15/1980, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	05/22/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	137	UTM Zone:	13
Depth of Water:	109	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	12	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411608.8
Pcw Rcv Da:		Northing:	3947299.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411608.8
Static Lev:	0	Y:	3947299.1
Tract Nbr:		Point Y:	35.6656019
Map Nbr:		Point X:	-105.9766121
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052097183449000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
25	SSE	0.40	2,100.33	6,854.84	WATER WELLS

License Nb:	0	District Office S:	
POD No:	00304	Surv Map:	
POD Rec No:	174796	Other Loc:	St. Michael'S Well
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	1613.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412400.7
Pcw Rcv Da:		Northing:	3946710.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/18/2001, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	584000.0
Static Lev:	0	Y:	1695700.0
Tract Nbr:		Point Y:	35.66036892
Map Nbr:		Point X:	-105.96779971
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
25	SSE	0.40	2,100.33	6,854.84	WATER WELLS

License Nb:		District Office S:	1 thru 7
POD No:	00304	Surv Map:	
POD Rec No:	174796	Other Loc:	
POD Basin:	SP	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	RG	Percent Sh:	
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:		Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:		Datum:	NAD83
CS Code:		UTM Source:	UN
Depth of Well:	0	UTM Zone:	
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0	Lat Lon AC:	
Elevation:		County:	Santa Fe
Ref :		Easting:	412400.7
Pcw Rcv Da:		Northing:	3946710.8
Sched Date:		Latitude Degree:	
Use of Wel:		Latitude Minute:	

Wells and Additional Sources Detail Report

Sys Date:		Latitude Second:	
Subdiv Nam:		Longitude Degree:	
Surface Co:		Longitude Minute:	
Ditch Name:		Longitude Second:	
Well Tag:		X:	584000
Static Lev:		Y:	1695700
Tract Nbr:		Point Y:	
Map Nbr:		Point X:	01677
Driller:			
POD Basin Desc:	Surface Permit		
POD Sub Basin Desc:			
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
26	NNW	0.40	2,121.75	6,818.46	WATER WELLS

License Nb:	228	District Office S:	
POD No:	12441	Surv Map:	
POD Rec No:	42431	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/01/1965, 12:00 AM	Restrict :	0.0
Finish Date:	04/04/1965, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	08/12/1965, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	150	UTM Zone:	13
Depth of Water:	110	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	412054.0
Pcw Rcv Da:		Northing:	3948008.0
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	10/03/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67203252
Map Nbr:		Point X:	-105.97177129
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
27	NW	0.41	2,156.96	6,800.49	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31501	Surv Map:	
POD Rec No:	57940	Other Loc:	1800 San Felipe Circle
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411726.7
Pcw Rcv Da:		Northing:	3947783.1

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/10/2019, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411726.7
Static Lev:	0	Y:	3947783.1
Tract Nbr:		Point Y:	35.66997578
Map Nbr:		Point X:	-105.9753627
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 11647104		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
28	ESE	0.41	2,164.64	6,883.76	WATER WELLS

License Nb:	0	District Office S:	
POD No:	66307	Surv Map:	
POD Rec No:	35556	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412924.6

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3947161.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/16/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	585700.0
Static Lev:	0	Y:	1697200.0
Tract Nbr:		Point Y:	35.66447663
Map Nbr:		Point X:	-105.9620611
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
29	NW	0.41	2,178.40	6,798.96	WATER WELLS

License Nb:	214	District Office S:	
POD No:	31217	Surv Map:	
POD Rec No:	325646	Other Loc:	1804 San Felipe Circle, Sf
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 2 SF
Start Date:	05/17/1980, 12:00 AM	Restrict :	0.0
Finish Date:	05/17/1980, 12:00 AM	Section:	27
Plug Date:		Township:	12N
Log File D:	05/28/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	211	UTM Zone:	13
Depth of Water:	105	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	24	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	411707.6
Pcw Rcv Da:		Northing:	3947769.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/17/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411707.6
Static Lev:	0	Y:	3947769.3
Tract Nbr:		Point Y:	35.66984966
Map Nbr:		Point X:	-105.9755722
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052098211077000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
30	E	0.41	2,180.30	6,890.57	WATER WELLS

License Nb:	0	District Office S:	
POD No:	61687	Surv Map:	
POD Rec No:	42763	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412956.8
Pcw Rcv Da:		Northing:	3947298.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/26/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	585800.0
Static Lev:	0	Y:	1697650.0
Tract Nbr:		Point Y:	35.66571184
Map Nbr:		Point X:	-105.96172016
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
31	W	0.42	2,199.52	6,794.68	WATER WELLS

License Nb:	253	District Office S:	
POD No:	30882	Surv Map:	
POD Rec No:	8325	Other Loc:	1949 Hopi Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 14 SF
Start Date:	07/20/1979, 12:00 AM	Restrict :	0.0
Finish Date:	07/21/1979, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	08/28/1979, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	155	UTM Zone:	13
Depth of Water:	98	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411573.1
Pcw Rcv Da:		Northing:	3947324.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/30/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721502.0
Static Lev:	0	Y:	1697741.0
Tract Nbr:		Point Y:	35.66582768
Map Nbr:		Point X:	-105.97700928
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
33	SW	0.43	2,277.86	6,820.56	WATER WELLS

License Nb:	0	District Office S:	
POD No:	93057	Surv Map:	
POD Rec No:	264937	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411871.0
Pcw Rcv Da:		Northing:	3946772.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	10/06/2011, 12:00 AM	Latitude Second:	39.16
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	25.17
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66087798
Map Nbr:		Point X:	-105.97365785
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
34	NW	0.43	2,278.60	6,798.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	29384	Surv Map:	
POD Rec No:	35609	Other Loc:	1803 San Felipe Circle
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3 2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411714.5
Pcw Rcv Da:		Northing:	3947826.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/11/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721945.0
Static Lev:	0	Y:	1699394.0
Tract Nbr:		Point Y:	35.67036504
Map Nbr:		Point X:	-105.97550224
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
35	SW	0.44	2,320.54	6,818.97	WATER WELLS

License Nb:	0	District Office S:	
POD No:	93057	Surv Map:	
POD Rec No:	264938	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411849.8
Pcw Rcv Da:		Northing:	3946771.8
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	10/06/2011, 12:00 AM	Latitude Second:	39.13
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	26.01
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66086977
Map Nbr:		Point X:	-105.97389196
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
36	SE	0.45	2,351.26	6,887.21	WATER WELLS

License Nb:	331	District Office S:	
POD No:	42755	Surv Map:	
POD Rec No:	9001	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/25/1984, 12:00 AM	Restrict :	0.0
Finish Date:	11/09/1984, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	11/30/1984, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	2020	UTM Zone:	13
Depth of Water:	179	UTM Accura:	10

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	6880.0	County:	Santa Fe
Ref :	RG-42755-EXPL/	Easting:	412860.5
Pcw Rcv Da:		Northing:	3946918.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/19/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	585500.0
Static Lev:	0	Y:	1696400.0
Tract Nbr:		Point Y:	35.66228028
Map Nbr:		Point X:	-105.96274293
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
37	E	0.45	2,375.27	6,896.29	WATER WELLS

License Nb:	0	District Office S:	
POD No:	43115	Surv Map:	
POD Rec No:	54438	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413017.9
Pcw Rcv Da:		Northing:	3947312.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/02/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	586000.0
Static Lev:	0	Y:	1697700.0
Tract Nbr:		Point Y:	35.66584795
Map Nbr:		Point X:	-105.96104674
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
37	E	0.45	2,375.27	6,896.29	WATER WELLS

License Nb:	0	District Office S:	
POD No:	43116	Surv Map:	
POD Rec No:	59990	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA

Wells and Additional Sources Detail Report

Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413017.9
Pcw Rcv Da:		Northing:	3947312.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/02/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	586000.0
Static Lev:	0	Y:	1697700.0
Tract Nbr:		Point Y:	35.66584795
Map Nbr:		Point X:	-105.96104674
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
38	WSW	0.46	2,437.23	6,797.48	WATER WELLS

License Nb:	0	District Office S:	
POD No:	53590	Surv Map:	
POD Rec No:	339403	Other Loc:	1975 Cerrillos Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	12/31/1950, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	5	UTM Source:	EA
Depth of Well:	13	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411581.9
Pcw Rcv Da:		Northing:	3947033.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/27/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721543.0
Static Lev:	0	Y:	1696785.0
Tract Nbr:		Point Y:	35.66320056
Map Nbr:		Point X:	-105.97688005
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
39	WNW	0.46	2,427.06	6,791.50	WATER WELLS

License Nb:	0	District Office S:	
POD No:	44661	Surv Map:	
POD Rec No:	337726	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/21/1986, 12:00 AM	Restrict :	0.0
Finish Date:	04/27/1986, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/16/1986, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	PA
Depth of Well:	195	UTM Zone:	13
Depth of Water:	95	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	4	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	8000.0	County:	Santa Fe
Ref :		Easting:	411616.9
Pcw Rcv Da:		Northing:	3947770.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411616.9
Static Lev:	0	Y:	3947770.8
Tract Nbr:		Point Y:	35.66985506
Map Nbr:		Point X:	-105.97657441
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
39	WNW	0.46	2,427.06	6,791.50	WATER WELLS

License Nb:	622	District Office S:	
POD No:	44659	Surv Map:	
POD Rec No:	37406	Other Loc:	Ramanda Ridge
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 3 SF
Start Date:	10/14/1985, 12:00 AM	Restrict :	0.0
Finish Date:	10/15/1985, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	10/21/1985, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	290	UTM Zone:	13
Depth of Water:	180	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411616.9
Pcw Rcv Da:		Northing:	3947770.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Ramanda Ridge	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	411616.9
Static Lev:	0	Y:	3947770.8
Tract Nbr:		Point Y:	35.66985506
Map Nbr:		Point X:	-105.97657441
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Lot No. 1 Of Blk 3 Of Ramanda Ridge		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
40	W	0.47	2,466.56	6,784.70	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31188	Surv Map:	
POD Rec No:	325604	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411496.1
Pcw Rcv Da:		Northing:	3947469.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/13/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581000.0
Static Lev:	0	Y:	1698150.0
Tract Nbr:		Point Y:	35.66712346
Map Nbr:		Point X:	-105.97787581
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
41	W	0.47	2,472.95	6,784.72	WATER WELLS

License Nb:	0	District Office S:	
POD No:	40295	Surv Map:	
POD Rec No:	33631	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	125	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411496.3
Pcw Rcv Da:		Northing:	3947484.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/22/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581000.0
Static Lev:	0	Y:	1698200.0
Tract Nbr:		Point Y:	35.66726051
Map Nbr:		Point X:	-105.97787527
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
42	NW	0.47	2,498.96	6,790.62	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31202	Surv Map:	
POD Rec No:	325634	Other Loc:	1828 San Felipe, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	

Wells and Additional Sources Detail Report

Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411622.4
Pcw Rcv Da:		Northing:	3947817.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/17/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581400.0
Static Lev:	0	Y:	1699300.0
Tract Nbr:		Point Y:	35.67028016
Map Nbr:		Point X:	-105.97651882
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
43	NW	0.49	2,582.95	6,802.88	WATER WELLS

License Nb:	228	District Office S:	
POD No:	39994	Surv Map:	
POD Rec No:	8067	Other Loc:	1715 Artistic Lane, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1
Start Date:	07/14/1983, 12:00 AM	Restrict :	0.0
Finish Date:	07/15/1983, 12:00 AM	Section:	27

Plug Date:		Township:	17N
Log File D:	10/24/1983, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	200	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411725.5
Pcw Rcv Da:		Northing:	3947969.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/24/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411725.5
Static Lev:	0	Y:	3947969.1
Tract Nbr:		Point Y:	35.67165248
Map Nbr:		Point X:	-105.97539636
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052098216140000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
44	W	0.49	2,570.08	6,782.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31367	Surv Map:	
POD Rec No:	291276	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411465.8
Pcw Rcv Da:		Northing:	3947484.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/11/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	580900.0
Static Lev:	0	Y:	1698200.0
Tract Nbr:		Point Y:	35.66726138
Map Nbr:		Point X:	-105.97821227
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
45	N	0.49	2,588.50	6,828.48	WATER WELLS

License Nb:	0	District Office S:	
POD No:	29514	Surv Map:	
POD Rec No:	284474	Other Loc:	Usgs 7.5' Quad "Santa Fe"
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412145.0
Pcw Rcv Da:		Northing:	3948177.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/17/2013, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	412145.0
Static Lev:	0	Y:	3948177.0
Tract Nbr:		Point Y:	35.67356419
Map Nbr:		Point X:	-105.97078436
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
46	E	0.49	2,606.24	6,905.68	WATER WELLS

License Nb:	790	District Office S:	
POD No:	52957	Surv Map:	
POD Rec No:	6730	Other Loc:	1516 Pacheco St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	NA NA T4A SF
Start Date:	09/04/1991, 12:00 AM	Restrict :	0.0
Finish Date:	09/04/1991, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	09/18/1991, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	390	UTM Zone:	13
Depth of Water:	201	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413089.1
Pcw Rcv Da:		Northing:	3947353.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/13/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1726475.0
Static Lev:	0	Y:	1697901.0
Tract Nbr:		Point Y:	35.66622746
Map Nbr:		Point X:	-105.96026463
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
47	W	0.49	2,599.99	6,782.50	WATER WELLS

License Nb:	227	District Office S:	
POD No:	41936	Surv Map:	
POD Rec No:	54566	Other Loc:	1968 Hano Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	11 3 U5 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:	07/16/1984, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	189	UTM Zone:	13
Depth of Water:	96	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411461.9
Pcw Rcv Da:		Northing:	3947515.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/21/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721129.0
Static Lev:	0	Y:	1698362.0
Tract Nbr:		Point Y:	35.66753599
Map Nbr:		Point X:	-105.97825871
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
48	WNW	0.49	2,612.73	6,785.73	WATER WELLS

License Nb:	622	District Office S:	
POD No:	32529	Surv Map:	
POD Rec No:	49938	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/10/1984, 12:00 AM	Restrict :	0.0
Finish Date:	04/11/1984, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/16/1984, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	210	UTM Zone:	13
Depth of Water:	90	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411561.1
Pcw Rcv Da:		Northing:	3947788.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/14/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581200.0
Static Lev:	0	Y:	1699200.0
Tract Nbr:		Point Y:	35.67000692
Map Nbr:		Point X:	-105.9771928
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
48	WNW	0.49	2,612.73	6,785.73	WATER WELLS

License Nb:	0	District Office S:	
POD No:	32529	Surv Map:	
POD Rec No:	333202	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411561.1
Pcw Rcv Da:		Northing:	3947788.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/14/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581200.0
Static Lev:	0	Y:	1699200.0
Tract Nbr:		Point Y:	35.67000692
Map Nbr:		Point X:	-105.9771928
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
49	W	0.50	2,616.74	6,781.63	WATER WELLS

License Nb:	790	District Office S:	
POD No:	35792	Surv Map:	
POD Rec No:	60802	Other Loc:	1231 Osage Ave
POD Basin:	RG	Zone :	C

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	16 23 SF
Start Date:	03/28/1981, 12:00 AM	Restrict :	0.0
Finish Date:	03/31/1981, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	04/06/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	138	UTM Zone:	13
Depth of Water:	98	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411445.5
Pcw Rcv Da:		Northing:	3947422.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721079.0
Static Lev:	0	Y:	1698058.0
Tract Nbr:		Point Y:	35.66670152
Map Nbr:		Point X:	-105.97842972
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
51	ESE	0.51	2,675.96	6,895.26	WATER WELLS

License Nb:	227	District Office S:	
POD No:	30564	Surv Map:	
POD Rec No:	25717	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/01/1978, 12:00 AM	Restrict :	0.0
Finish Date:	06/22/1978, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	06/28/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	356	UTM Zone:	13
Depth of Water:	261	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413044.9
Pcw Rcv Da:		Northing:	3947037.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/01/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	586100.0
Static Lev:	0	Y:	1696800.0
Tract Nbr:		Point Y:	35.66337477
Map Nbr:		Point X:	-105.9607188
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
53	SSW	0.52	2,768.03	6,818.16	WATER WELLS

License Nb:	0	District Office S:	
POD No:	93057	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	264936	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411910.0
Pcw Rcv Da:		Northing:	3946577.4
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	10/06/2011, 12:00 AM	Latitude Second:	32.84
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	23.54
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65912261
Map Nbr:		Point X:	-105.97320569
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
54	NE	0.53	2,801.35	6,895.03	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	19584	Surv Map:	
POD Rec No:	44430	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	01/01/1955, 12:00 AM	Section:	26
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	260	UTM Zone:	13
Depth of Water:	248	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:	SUBMER	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412959.0
Pcw Rcv Da:		Northing:	3947899.0
Sched Date:		Latitude Degree:	0
Use of Wel:	COM,DOM,IND	Latitude Minute:	0
Sys Date:	08/22/1991, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67113015
Map Nbr:		Point X:	-105.96176085
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
54	NE	0.53	2,801.35	6,895.03	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	41309	Surv Map:	
POD Rec No:	31584	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	26
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412959.0
Pcw Rcv Da:		Northing:	3947899.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/02/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67113015
Map Nbr:		Point X:	-105.96176085
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
55	WNW	0.53	2,779.17	6,781.11	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	790	District Office S:	
POD No:	34568	Surv Map:	
POD Rec No:	39428	Other Loc:	1919 Sanidlefonso Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1B 3 TB SF
Start Date:	10/06/1980, 12:00 AM	Restrict :	0.0
Finish Date:	10/10/1980, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	10/14/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	136	UTM Zone:	13
Depth of Water:	92	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411488.8
Pcw Rcv Da:		Northing:	3947762.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/05/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1721207.0
Static Lev:	0	Y:	1699174.0
Tract Nbr:		Point Y:	35.66976694
Map Nbr:		Point X:	-105.97798871
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
56	NW	0.54	2,857.20	6,789.48	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	228	District Office S:	
POD No:	02849	Surv Map:	
POD Rec No:	51536	Other Loc:	Barela Street-Not Numbered Yet
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/10/1959, 12:00 AM	Restrict :	0.0
Finish Date:	02/20/1959, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	02/24/1959, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	87	UTM Zone:	13
Depth of Water:	60	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7500.0	County:	Santa Fe
Ref :		Easting:	411555.0
Pcw Rcv Da:		Northing:	3947911.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	05/29/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67111343
Map Nbr:		Point X:	-105.97727368
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

57	ENE	0.55	2,899.22	6,899.62	WATER WELLS

License Nb:	0	District Office S:	
POD No:	65338	Surv Map:	
POD Rec No:	61486	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413024.9
Pcw Rcv Da:		Northing:	3947861.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/11/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	586000.0
Static Lev:	0	Y:	1699500.0
Tract Nbr:		Point Y:	35.67079339
Map Nbr:		Point X:	-105.96102867
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

58	NW	0.55	2,886.96	6,797.24	WATER WELLS

License Nb:	1004	District Office S:	
POD No:	55005	Surv Map:	
POD Rec No:	63913	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/30/1993, 12:00 AM	Restrict :	0.0
Finish Date:	05/01/1993, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	05/03/1993, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	240	UTM Zone:	13
Depth of Water:	133	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411655.6
Pcw Rcv Da:		Northing:	3948030.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/09/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581500.0
Static Lev:	0	Y:	1700000.0
Tract Nbr:		Point Y:	35.67220246
Map Nbr:		Point X:	-105.9761754
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
59	WNW	0.56	2,933.02	6,778.42	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31500	Surv Map:	
POD Rec No:	7016	Other Loc:	1944 San Ildefonso Rd.
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411413.0
Pcw Rcv Da:		Northing:	3947710.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/10/2019, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411413.0
Static Lev:	0	Y:	3947710.1
Tract Nbr:		Point Y:	35.66928955
Map Nbr:		Point X:	-105.9788204
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 10520981190530		

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
60	WNW	0.56	2,947.34	6,775.50	WATER WELLS

License Nb:	253	District Office S:	
POD No:	31598	Surv Map:	
POD Rec No:	52363	Other Loc:	1105 Osage Ave
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	19 1 NA SF
Start Date:	05/29/1981, 12:00 AM	Restrict :	0.0
Finish Date:	05/30/1981, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	06/08/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	114	UTM Zone:	13
Depth of Water:	74	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411360.7
Pcw Rcv Da:		Northing:	3947551.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/23/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411360.7
Static Lev:	0	Y:	3947551.3
Tract Nbr:		Point Y:	35.66785325
Map Nbr:		Point X:	-105.97938071
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		

Wells and Additional Sources Detail Report

Legal: Parcel Number 1-052-098-102-007

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
60	WNW	0.56	2,947.34	6,775.50	WATER WELLS

License Nb:	1472	District Office S:	
POD No:	31598	Surv Map:	
POD Rec No:	287003	Other Loc:	1105 Osage Ave
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	POD2	Subdiv Loc:	19 1 NA SF
Start Date:	10/04/2013, 12:00 AM	Restrict :	0.0
Finish Date:	10/07/2013, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	11/18/2013, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	260	UTM Zone:	13
Depth of Water:	125	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.36	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411360.7
Pcw Rcv Da:		Northing:	3947551.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/23/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411360.7
Static Lev:	0	Y:	3947551.3
Tract Nbr:		Point Y:	35.66785325
Map Nbr:		Point X:	-105.97938071
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal: Parcel Number 1-052-098-102-007

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
61	NNW	0.57	3,009.93	6,809.71	WATER WELLS

License Nb:	0	District Office S:	
POD No:	46972	Surv Map:	
POD Rec No:	7550	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 15 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411853.0
Pcw Rcv Da:		Northing:	3948216.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/07/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Barro La Canada	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67388972
Map Nbr:		Point X:	-105.97401477
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
61	NNW	0.57	3,009.93	6,809.71	WATER WELLS

License Nb:	0	District Office S:	
POD No:	45085	Surv Map:	1941 TCRS #2
POD Rec No:	67083	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	TA	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Taos
Ref :		Easting:	411853.0
Pcw Rcv Da:		Northing:	3948216.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/22/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:	16	Point Y:	35.67388972
Map Nbr:	20	Point X:	-105.97401477
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: TAOS
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
61	NNW	0.57	3,009.93	6,809.71	WATER WELLS

License Nb:	253	District Office S:	
POD No:	03611	Surv Map:	
POD Rec No:	42626	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	B TB SF
Start Date:	07/31/1959, 12:00 AM	Restrict :	0.0
Finish Date:	08/04/1959, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	09/29/1959, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	94	UTM Zone:	13
Depth of Water:	13	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411853.0
Pcw Rcv Da:		Northing:	3948216.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/05/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Small Holding Claim 413	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67388972
Map Nbr:		Point X:	-105.97401477

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
63	W	0.59	3,112.23	6,771.32	WATER WELLS

License Nb:	653	District Office S:	
POD No:	31237	Surv Map:	
POD Rec No:	8941	Other Loc:	2019 Otowi Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	5 1 SF
Start Date:	09/26/1978, 12:00 AM	Restrict :	0.0
Finish Date:	10/04/1978, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	10/16/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	105	UTM Zone:	13
Depth of Water:	68	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	18	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411298.1
Pcw Rcv Da:		Northing:	3947476.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/18/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411298.1
Static Lev:	0	Y:	3947476.3
Tract Nbr:		Point Y:	35.66717149

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.98006402
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1-052-097-083-505		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
64	NW	0.60	3,155.41	6,796.84	WATER WELLS

License Nb:	1004	District Office S:	
POD No:	55005	Surv Map:	
POD Rec No:	339490	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:	04/30/1993, 12:00 AM	Restrict :	0.0
Finish Date:	05/01/1993, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	05/03/1993, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	240	UTM Zone:	13
Depth of Water:	133	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411682.4
Pcw Rcv Da:		Northing:	3948160.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/09/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411682.4
Static Lev:	0	Y:	3948160.6

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.67337502
Map Nbr:		Point X:	-105.97589355
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number: 1052098204266000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
65	NNW	0.60	3,146.93	6,819.33	WATER WELLS

License Nb:	253	District Office S:	
POD No:	43672	Surv Map:	
POD Rec No:	45116	Other Loc:	1624 Agua Fria St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 T8D SF
Start Date:	06/15/1985, 12:00 AM	Restrict :	0.0
Finish Date:	06/17/1985, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	06/27/1985, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	230	UTM Zone:	13
Depth of Water:	154	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411970.6
Pcw Rcv Da:		Northing:	3948309.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/25/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1722765.0

Wells and Additional Sources Detail Report

Static Lev:	0	Y:	1700990.0
Tract Nbr:		Point Y:	35.67474404
Map Nbr:		Point X:	-105.97272571
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
66	W	0.60	3,179.46	6,774.52	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31273	Surv Map:	
POD Rec No:	64690	Other Loc:	2050 Hopi Rd
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 12 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411284.1
Pcw Rcv Da:		Northing:	3947224.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/09/2019, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:	NA	X:	411284.1
Static Lev:	0	Y:	3947224.7
Tract Nbr:		Point Y:	35.66490202
Map Nbr:		Point X:	-105.98019096
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Parcel Number 11041920		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
67	WNW	0.61	3,197.42	6,771.45	WATER WELLS

License Nb:	253	District Office S:	
POD No:	29321	Surv Map:	
POD Rec No:	62930	Other Loc:	1012 Osage Ave
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	8 2 SF
Start Date:	09/21/1977, 12:00 AM	Restrict :	0.0
Finish Date:	09/22/1977, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	09/27/1977, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	146	UTM Zone:	13
Depth of Water:	83	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411290.6
Pcw Rcv Da:		Northing:	3947587.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/10/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegra #10	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720564.0
Static Lev:	0	Y:	1698592.0
Tract Nbr:		Point Y:	35.66817239
Map Nbr:		Point X:	-105.98015913
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
68	ESE	0.61	3,213.65	6,896.20	WATER WELLS

License Nb:	0	District Office S:	
POD No:	43195	Surv Map:	
POD Rec No:	48042	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413134.0
Pcw Rcv Da:		Northing:	3946853.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	586400.0
Static Lev:	0	Y:	1696200.0
Tract Nbr:		Point Y:	35.66172382
Map Nbr:		Point X:	-105.95971465
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
69	NW	0.61	3,221.99	6,792.89	WATER WELLS

License Nb:	0	District Office S:	
POD No:	30061	Surv Map:	
POD Rec No:	46048	Other Loc:	1722 Agua Fria St, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411623.2
Pcw Rcv Da:		Northing:	3948138.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/17/2021, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411623.2
Static Lev:	0	Y:	3948138.5
Tract Nbr:		Point Y:	35.67317048
Map Nbr:		Point X:	-105.97654519
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052098179193000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
70	WNW	0.61	3,242.79	6,781.68	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34886	Surv Map:	
POD Rec No:	22801	Other Loc:	522 Solano
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	A SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411397.8
Pcw Rcv Da:		Northing:	3947888.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	10/14/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Cienegitas	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720903.0
Static Lev:	0	Y:	1699584.0
Tract Nbr:		Point Y:	35.67089558
Map Nbr:		Point X:	-105.97900795
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
71	NNW	0.62	3,268.60	6,811.47	WATER WELLS

License Nb:	228	District Office S:	
POD No:	44231	Surv Map:	
POD Rec No:	68074	Other Loc:	1628 Agua Fria
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 SF
Start Date:	08/01/1985, 12:00 AM	Restrict :	0.0
Finish Date:	08/02/1985, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	10/28/1985, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	260	UTM Zone:	13
Depth of Water:	190	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411893.9
Pcw Rcv Da:		Northing:	3948320.9
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	08/02/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1722513.0
Static Lev:	0	Y:	1701024.0
Tract Nbr:		Point Y:	35.67483906
Map Nbr:		Point X:	-105.97357437
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
72	WNW	0.62	3,278.27	6,775.14	WATER WELLS

License Nb:	253	District Office S:	
POD No:	23084	Surv Map:	
POD Rec No:	51166	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/23/1973, 12:00 AM	Restrict :	0.0
Finish Date:	04/26/1973, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	05/07/1973, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	52	UTM Zone:	13
Depth of Water:	17	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411348.2
Pcw Rcv Da:		Northing:	3947821.3

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/25/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	580500.0
Static Lev:	0	Y:	1699300.0
Tract Nbr:		Point Y:	35.67028621
Map Nbr:		Point X:	-105.97954854
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
73	WSW	0.62	3,289.27	6,772.75	WATER WELLS

License Nb:	653	District Office S:	
POD No:	31116	Surv Map:	
POD Rec No:	24662	Other Loc:	1228 Apache Ave
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3 2 SF
Start Date:	09/01/1978, 12:00 AM	Restrict :	0.0
Finish Date:	09/22/1978, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	09/29/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	100	UTM Zone:	13
Depth of Water:	64	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411260.9

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3947166.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/27/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720484.0
Static Lev:	0	Y:	1697208.0
Tract Nbr:		Point Y:	35.66437075
Map Nbr:		Point X:	-105.98044079
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
74	NW	0.62	3,297.47	6,792.91	WATER WELLS

License Nb:	122	District Office S:	
POD No:	27946	Surv Map:	
POD Rec No:	5776	Other Loc:	Eastern Corner Of Property
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	01/01/1913, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	90	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	9.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	411633.1
Pcw Rcv Da:		Northing:	3948177.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/21/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581420.0
Static Lev:	0	Y:	1700480.0
Tract Nbr:		Point Y:	35.67352116
Map Nbr:		Point X:	-105.97644007
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	X&Y Are Close Approximates See Santa Fe Hydrograpic Survey Sheet 21.		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
75	W	0.62	3,290.78	6,766.86	WATER WELLS

License Nb:	214	District Office S:	
POD No:	33690	Surv Map:	
POD Rec No:	52939	Other Loc:	1066 Osage Circle, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	18 1 SF
Start Date:	09/24/1980, 12:00 AM	Restrict :	0.0
Finish Date:	09/24/1980, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	09/26/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	116	UTM Zone:	13
Depth of Water:	70	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	18	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411246.2
Pcw Rcv Da:		Northing:	3947498.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/15/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411246.2
Static Lev:	0	Y:	3947498.1
Tract Nbr:		Point Y:	35.66736335
Map Nbr:		Point X:	-105.98063979
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052097064514000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
76	ESE	0.62	3,298.52	6,897.76	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35697	Surv Map:	
POD Rec No:	4922	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413164.4
Pcw Rcv Da:		Northing:	3946853.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/09/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	586500.0
Static Lev:	0	Y:	1696200.0
Tract Nbr:		Point Y:	35.66172289
Map Nbr:		Point X:	-105.95937878
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
77	WNW	0.63	3,342.42	6,769.44	WATER WELLS

License Nb:	253	District Office S:	
POD No:	36644	Surv Map:	
POD Rec No:	68392	Other Loc:	1027 Osage Circle
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	6 2 SF
Start Date:	04/17/1982, 12:00 AM	Restrict :	0.0
Finish Date:	05/17/1982, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	05/24/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	127	UTM Zone:	13
Depth of Water:	73	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	31	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411242.6
Pcw Rcv Da:		Northing:	3947573.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/22/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre #10	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720407.0
Static Lev:	0	Y:	1698543.0
Tract Nbr:		Point Y:	35.66803916
Map Nbr:		Point X:	-105.98068784
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
78	WNW	0.63	3,346.00	6,769.60	WATER WELLS

License Nb:	1035	District Office S:	
POD No:	52767	Surv Map:	
POD Rec No:	61622	Other Loc:	Ward 4
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA SF
Start Date:	08/13/1990, 12:00 AM	Restrict :	0.0
Finish Date:	08/15/1990, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	06/11/1991, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	150	UTM Zone:	13
Depth of Water:	70	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.56	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411250.0
Pcw Rcv Da:		Northing:	3947613.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/09/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Haven Terrell	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66839953
Map Nbr:		Point X:	-105.98061048
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
79	NW	0.64	3,369.72	6,790.99	WATER WELLS

License Nb:	0	District Office S:	
POD No:	27946	Surv Map:	
POD Rec No:	213917	Other Loc:	See Plat
POD Basin:	RG	Zone :	C
POD Suffix:	S	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	

Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411624.2
Pcw Rcv Da:		Northing:	3948198.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/22/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581390.0
Static Lev:	0	Y:	1700550.0
Tract Nbr:		Point Y:	35.67371419
Map Nbr:		Point X:	-105.97654076
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
80	W	0.64	3,358.28	6,765.90	WATER WELLS

License Nb:	253	District Office S:	
POD No:	29496	Surv Map:	
POD Rec No:	59389	Other Loc:	1062 Osage Circle
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	17 1 SF
Start Date:	10/15/1977, 12:00 AM	Restrict :	0.0
Finish Date:	10/17/1977, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	11/22/1977, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	102	UTM Zone:	13
Depth of Water:	62	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	28	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411223.1
Pcw Rcv Da:		Northing:	3947478.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720347.0
Static Lev:	0	Y:	1698233.0
Tract Nbr:		Point Y:	35.66718818
Map Nbr:		Point X:	-105.98089288
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
81	W	0.64	3,403.40	6,765.16	WATER WELLS

License Nb:	653	District Office S:	
POD No:	31073	Surv Map:	
POD Rec No:	49375	Other Loc:	1204 Apache Avenue, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 1 SF
Start Date:	08/08/1978, 12:00 AM	Restrict :	0.0
Finish Date:	09/06/1978, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	09/14/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	100	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	66	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	16	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411204.2
Pcw Rcv Da:		Northing:	3947390.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/30/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411204.2
Static Lev:	0	Y:	3947390.8
Tract Nbr:		Point Y:	35.66639225
Map Nbr:		Point X:	-105.98109195
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052097045481000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
82	WSW	0.65	3,427.76	6,774.25	WATER WELLS

License Nb:	0	District Office S:	
POD No:	41631	Surv Map:	
POD Rec No:	30276	Other Loc:	1315 Vitalia St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 1 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA

Wells and Additional Sources Detail Report

Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411277.0
Pcw Rcv Da:		Northing:	3946972.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/13/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Domingo	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720545.0
Static Lev:	0	Y:	1696573.0
Tract Nbr:		Point Y:	35.66262597
Map Nbr:		Point X:	-105.98024158
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
83	W	0.65	3,425.17	6,764.29	WATER WELLS

License Nb:	653	District Office S:	
POD No:	30992	Surv Map:	
POD Rec No:	32953	Other Loc:	1202 Apache Ave
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 1 SF
Start Date:	08/09/1978, 12:00 AM	Restrict :	0.0
Finish Date:	08/18/1978, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	08/29/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	5	UTM Source:	EA
Depth of Well:	100	UTM Zone:	13
Depth of Water:	58	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411198.5
Pcw Rcv Da:		Northing:	3947410.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720269.0
Static Lev:	0	Y:	1698008.0
Tract Nbr:		Point Y:	35.66657023
Map Nbr:		Point X:	-105.98115711
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
84	WSW	0.65	3,450.64	6,775.06	WATER WELLS

License Nb:	253	District Office S:	
POD No:	31193	Surv Map:	
POD Rec No:	325609	Other Loc:	1319 Vitalia St.
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 1 SF
Start Date:	09/25/1978, 12:00 AM	Restrict :	0.0
Finish Date:	09/25/1978, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	10/02/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	120	UTM Zone:	13
Depth of Water:	77	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	28	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411284.2
Pcw Rcv Da:		Northing:	3946939.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/13/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Domingo #2	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411284.2
Static Lev:	0	Y:	3946939.8
Tract Nbr:		Point Y:	35.66233362
Map Nbr:		Point X:	-105.98015846
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
85	W	0.66	3,472.89	6,766.44	WATER WELLS

License Nb:	253	District Office S:	
POD No:	37718	Surv Map:	
POD Rec No:	52690	Other Loc:	1046 Osage Circle, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	14 1 U10 SF
Start Date:	06/03/1982, 12:00 AM	Restrict :	0.0
Finish Date:	06/29/1982, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	07/07/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	133	UTM Zone:	13
Depth of Water:	69	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	42	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411197.0
Pcw Rcv Da:		Northing:	3947545.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/28/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411197.0
Static Lev:	0	Y:	3947545.2
Tract Nbr:		Point Y:	35.66778353
Map Nbr:		Point X:	-105.98118853
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052098046004000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
86	W	0.66	3,474.43	6,765.58	WATER WELLS

License Nb:	214	District Office S:	
POD No:	31305	Surv Map:	
POD Rec No:	291256	Other Loc:	1052 Osage Circle, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	15 1 SF
Start Date:	03/13/1979, 12:00 AM	Restrict :	0.0
Finish Date:	03/20/1979, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	03/30/1979, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	125	UTM Zone:	13
Depth of Water:	80	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411192.6
Pcw Rcv Da:		Northing:	3947522.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411192.6
Static Lev:	0	Y:	3947522.2
Tract Nbr:		Point Y:	35.66757579
Map Nbr:		Point X:	-105.9812346
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052097048527000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
87	W	0.66	3,492.79	6,767.41	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34773	Surv Map:	
POD Rec No:	67631	Other Loc:	1207 Vitalia St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411177.4
Pcw Rcv Da:		Northing:	3947338.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720203.0
Static Lev:	0	Y:	1697771.0
Tract Nbr:		Point Y:	35.66591924
Map Nbr:		Point X:	-105.98138227
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
88	W	0.66	3,489.79	6,765.56	WATER WELLS

License Nb:	0	District Office S:	
POD No:	37923	Surv Map:	
POD Rec No:	3071	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411192.4
Pcw Rcv Da:		Northing:	3947549.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/07/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	580000.0
Static Lev:	0	Y:	1698400.0
Tract Nbr:		Point Y:	35.66781738
Map Nbr:		Point X:	-105.98123977
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
90	W	0.67	3,543.15	6,763.29	WATER WELLS

License Nb:	253	District Office S:	
POD No:	30880	Surv Map:	
POD Rec No:	23581	Other Loc:	1201 Vitalia St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 2 SF
Start Date:	09/19/1978, 12:00 AM	Restrict :	0.0
Finish Date:	09/19/1978, 12:00 AM	Section:	34

Wells and Additional Sources Detail Report

Plug Date:		Township:	17N
Log File D:	09/22/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	100	UTM Zone:	13
Depth of Water:	63	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	24	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411162.3
Pcw Rcv Da:		Northing:	3947397.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/30/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Domingo Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720151.0
Static Lev:	0	Y:	1697964.0
Tract Nbr:		Point Y:	35.66644978
Map Nbr:		Point X:	-105.98155559
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
91	WNW	0.69	3,625.78	6,769.35	WATER WELLS

License Nb:	622	District Office S:	
POD No:	55365	Surv Map:	
POD Rec No:	48839	Other Loc:	510 Fulton Ln, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	3 SF
Start Date:	05/26/1992, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	05/26/1992, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	06/12/1992, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	95	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411282.7
Pcw Rcv Da:		Northing:	3947924.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/26/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411282.7
Static Lev:	0	Y:	3947924.8
Tract Nbr:		Point Y:	35.67121338
Map Nbr:		Point X:	-105.98028359
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052098073125000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
92	WNW	0.69	3,628.52	6,763.47	WATER WELLS

License Nb:	0	District Office S:	
POD No:	25985	Surv Map:	
POD Rec No:	50390	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411194.7
Pcw Rcv Da:		Northing:	3947731.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/29/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	580000.0
Static Lev:	0	Y:	1699000.0
Tract Nbr:		Point Y:	35.66946645
Map Nbr:		Point X:	-105.98123454
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Approx. 1000' Sw Of Osage Well		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
94	NNE	0.69	3,646.04	6,863.00	WATER WELLS

License Nb:	0	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	349483	Other Loc:	Ustb-55
POD Basin:	RG	Zone :	
POD Suffix:	POD38	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412688.5
Pcw Rcv Da:		Northing:	3948425.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/19/2024, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1725115.9
Static Lev:	0	Y:	1701400.3
Tract Nbr:		Point Y:	35.67585272
Map Nbr:		Point X:	-105.96480649
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
96	N	0.69	3,654.66	6,839.50	WATER WELLS

License Nb:	1310	District Office S:	
POD No:	71385	Surv Map:	
POD Rec No:	147918	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/26/1999, 12:00 AM	Restrict :	0.0
Finish Date:	08/31/1999, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/05/2000, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	300	UTM Zone:	13
Depth of Water:	80	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412240.8
Pcw Rcv Da:		Northing:	3948510.9
Sched Date:		Latitude Degree:	0
Use of Wel:	ONE HOUSEHOLD	Latitude Minute:	0
Sys Date:	05/23/2001, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	583400.0
Static Lev:	0	Y:	1701600.0
Tract Nbr:		Point Y:	35.67658287
Map Nbr:		Point X:	-105.96976233
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
97	WNW	0.69	3,664.53	6,764.40	WATER WELLS

License Nb:	228	District Office S:	
POD No:	36845	Surv Map:	
POD Rec No:	15451	Other Loc:	1008 Osage Circle, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	5 1 SF
Start Date:	06/04/1982, 12:00 AM	Restrict :	0.0
Finish Date:	06/10/1982, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	06/17/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	190	UTM Zone:	13
Depth of Water:	70	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	12	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-36845-/	Easting:	411177.4
Pcw Rcv Da:		Northing:	3947714.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/16/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411177.4
Static Lev:	0	Y:	3947714.3
Tract Nbr:		Point Y:	35.66930622
Map Nbr:		Point X:	-105.98142372
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052098039061000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
98	WSW	0.71	3,728.53	6,771.28	WATER WELLS

License Nb:	253	District Office S:	
POD No:	31384	Surv Map:	
POD Rec No:	15389	Other Loc:	2217 Cerrillos Road, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1B NA NA SF
Start Date:	09/26/1978, 12:00 AM	Restrict :	0.0
Finish Date:	09/26/1978, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	10/02/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	127	UTM Zone:	13
Depth of Water:	75	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411218.2
Pcw Rcv Da:		Northing:	3946880.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	El Pollo Asado	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411218.2
Static Lev:	0	Y:	3946880.5
Tract Nbr:		Point Y:	35.66179309
Map Nbr:		Point X:	-105.98088102
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052097059308000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
99	NW	0.71	3,726.88	6,766.93	WATER WELLS

License Nb:		District Office S:	1 & 6
POD No:	00304	Surv Map:	
POD Rec No:	181001	Other Loc:	
POD Basin:	RG	Zone :	C

Wells and Additional Sources Detail Report

POD Suffix:	-S	BLK:	
Pod Sub Ba:	RG	Percent Sh:	
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:		Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:		Datum:	NAD83
CS Code:		UTM Source:	UN
Depth of Well:	0	UTM Zone:	
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0	Lat Lon AC:	
Elevation:		County:	Santa Fe
Ref :		Easting:	411351.5
Pcw Rcv Da:		Northing:	3948080.4
Sched Date:		Latitude Degree:	
Use of Wel:		Latitude Minute:	
Sys Date:		Latitude Second:	
Subdiv Nam:		Longitude Degree:	
Surface Co:		Longitude Minute:	
Ditch Name:		Longitude Second:	
Well Tag:		X:	580500
Static Lev:		Y:	1700150
Tract Nbr:		Point Y:	
Map Nbr:		Point X:	00304
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:			
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
99	NW	0.71	3,726.88	6,766.93	WATER WELLS

License Nb:	0	District Office S:	
POD No:	00304	Surv Map:	
POD Rec No:	181001	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	C
POD Suffix:	-S	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	25.07
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411351.5
Pcw Rcv Da:		Northing:	3948080.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/25/2002, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	580500.0
Static Lev:	0	Y:	1700150.0
Tract Nbr:		Point Y:	35.67262232
Map Nbr:		Point X:	-105.97954063
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
100	NNW	0.71	3,729.47	6,793.78	WATER WELLS

License Nb:	547	District Office S:	
POD No:	49979	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	30331	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/04/2005, 12:00 AM	Restrict :	0.0
Finish Date:	02/07/2005, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	02/23/2005, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	120	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	27	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411782.6
Pcw Rcv Da:		Northing:	3948425.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/25/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581900.0
Static Lev:	0	Y:	1701300.0
Tract Nbr:		Point Y:	35.67577029
Map Nbr:		Point X:	-105.97481552
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
101	NNW	0.71	3,748.95	6,785.27	WATER WELLS

License Nb:	622	District Office S:	

Wells and Additional Sources Detail Report

POD No:	44622	Surv Map:	
POD Rec No:	44424	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/13/1985, 12:00 AM	Restrict :	0.0
Finish Date:	11/14/1985, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	11/26/1985, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	230	UTM Zone:	13
Depth of Water:	130	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411659.9
Pcw Rcv Da:		Northing:	3948365.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411659.9
Static Lev:	0	Y:	3948365.9
Tract Nbr:		Point Y:	35.67522381
Map Nbr:		Point X:	-105.97616468
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
102	NNE	0.71	3,758.16	6,863.82	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	336369	Other Loc:	Ustb-44
POD Basin:	RG	Zone :	
POD Suffix:	POD33	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412754.7
Pcw Rcv Da:		Northing:	3948433.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/19/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1725332.6
Static Lev:	0	Y:	1701430.0
Tract Nbr:		Point Y:	35.67593251
Map Nbr:		Point X:	-105.96407595
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
103	N	0.71	3,758.88	6,845.24	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	1310	District Office S:	
POD No:	72751	Surv Map:	
POD Rec No:	152365	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/20/2000, 12:00 AM	Restrict :	0.0
Finish Date:	01/23/2000, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	02/04/2000, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	420	UTM Zone:	13
Depth of Water:	263	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412332.6
Pcw Rcv Da:		Northing:	3948540.2
Sched Date:		Latitude Degree:	0
Use of Wel:	ONE HOUSEHOLD	Latitude Minute:	0
Sys Date:	02/14/2000, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	583700.0
Static Lev:	0	Y:	1701700.0
Tract Nbr:		Point Y:	35.67685518
Map Nbr:		Point X:	-105.96875124
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
104	ENE	0.72	3,796.21	6,919.08	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	88182	Surv Map:	
POD Rec No:	223314	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	26
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413263.0
Pcw Rcv Da:		Northing:	3947996.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/11/2006, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67203141
Map Nbr:		Point X:	-105.95841267
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

104	ENE	0.72	3,796.21	6,919.08	WATER WELLS

License Nb:	0	District Office S:	
POD No:	88182	Surv Map:	
POD Rec No:	223401	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	26
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413263.0
Pcw Rcv Da:		Northing:	3947996.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/11/2006, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67203141
Map Nbr:		Point X:	-105.95841267
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

107	W	0.72	3,795.46	6,763.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	38282	Surv Map:	
POD Rec No:	33563	Other Loc:	1207 Lujan St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	20 13 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411087.3
Pcw Rcv Da:		Northing:	3947293.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/26/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Domingo	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1719909.0
Static Lev:	0	Y:	1697620.0
Tract Nbr:		Point Y:	35.66550725
Map Nbr:		Point X:	-105.98237268
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
108	WNW	0.72	3,820.04	6,762.44	WATER WELLS

License Nb:	0	District Office S:	
POD No:	37922	Surv Map:	
POD Rec No:	16648	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411101.7
Pcw Rcv Da:		Northing:	3947611.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/07/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579700.0
Static Lev:	0	Y:	1698600.0
Tract Nbr:		Point Y:	35.66836904
Map Nbr:		Point X:	-105.98224864
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
110	S	0.72	3,824.12	6,819.31	WATER WELLS

License Nb:	0	District Office S:	
POD No:	39921	Surv Map:	
POD Rec No:	18815	Other Loc:	2055 Camino Lado, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412485.6
Pcw Rcv Da:		Northing:	3946191.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/23/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	584300.0
Static Lev:	0	Y:	1694000.0
Tract Nbr:		Point Y:	35.65569667
Map Nbr:		Point X:	-105.96680544
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
111	NNE	0.73	3,831.09	6,850.23	WATER WELLS

License Nb:	0	District Office S:	
POD No:	71263	Surv Map:	
POD Rec No:	147442	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412515.4
Pcw Rcv Da:		Northing:	3948537.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/21/1999, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	584300.0
Static Lev:	0	Y:	1701700.0
Tract Nbr:		Point Y:	35.67685068
Map Nbr:		Point X:	-105.96673125
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
113	SSW	0.73	3,850.48	6,804.33	WATER WELLS

License Nb:	0	District Office S:	
POD No:	96479	Surv Map:	
POD Rec No:	304918	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412005.0
Pcw Rcv Da:		Northing:	3946196.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/05/2017, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	412005.0
Static Lev:	0	Y:	3946196.0
Tract Nbr:		Point Y:	35.6556927
Map Nbr:		Point X:	-105.9721146
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
114	WNW	0.73	3,863.00	6,764.87	WATER WELLS

License Nb:	0	District Office S:	
POD No:	07156	Surv Map:	
POD Rec No:	194621	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411254.0
Pcw Rcv Da:		Northing:	3948016.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/09/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67203298
Map Nbr:		Point X:	-105.98061073
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
115	NNW	0.74	3,886.32	6,781.11	WATER WELLS

License Nb:	0	District Office S:	
POD No:	13068	Surv Map:	
POD Rec No:	34673	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	100	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411660.0
Pcw Rcv Da:		Northing:	3948414.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/08/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67565745
Map Nbr:		Point X:	-105.97616886

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
115	NNW	0.74	3,886.32	6,781.11	WATER WELLS

License Nb:	0	District Office S:	
POD No:	05282	Surv Map:	
POD Rec No:	193419	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411660.0
Pcw Rcv Da:		Northing:	3948414.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/17/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67565745

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.97616886
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
116	NNW	0.74	3,889.31	6,779.68	WATER WELLS

License Nb:	0	District Office S:	
POD No:	68719	Surv Map:	
POD Rec No:	139842	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411629.8
Pcw Rcv Da:		Northing:	3948396.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/12/1998, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581400.0
Static Lev:	0	Y:	1701200.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.67549968
Map Nbr:		Point X:	-105.97650064
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
117	NNE	0.74	3,897.09	6,876.04	WATER WELLS

License Nb:	0	District Office S:	
POD No:	01117	Surv Map:	
POD Rec No:	49602	Other Loc:	Santa Fe Well
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	SANTA FE WELL	Subdiv Loc:	
Start Date:	02/07/1951, 12:00 AM	Restrict :	0.0
Finish Date:	03/12/1951, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/14/1951, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	725	UTM Zone:	13
Depth of Water:	97	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:	TURBIN	XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	6807.9	County:	Santa Fe
Ref :		Easting:	412858.4
Pcw Rcv Da:		Northing:	3948426.9
Sched Date:		Latitude Degree:	0
Use of Wel:	MUN	Latitude Minute:	0
Sys Date:	09/14/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	585430.0

Wells and Additional Sources Detail Report

Static Lev:	0	Y:	1701350.0
Tract Nbr:		Point Y:	35.67588037
Map Nbr:		Point X:	-105.96292946
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Santa Fe Power Plant Yard		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
117	NNE	0.74	3,897.09	6,876.04	WATER WELLS

License Nb:		District Office S:	1 & 6
POD No:	01117	Surv Map:	
POD Rec No:	49602	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	RG	Percent Sh:	
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:		Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:		Datum:	NAD83
CS Code:		UTM Source:	UN
Depth of Well:	725	UTM Zone:	
Depth of Water:	97	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:	TURBIN	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0	Lat Lon AC:	
Elevation:	6807.9	County:	Santa Fe
Ref :		Easting:	412858.4
Pcw Rcv Da:		Northing:	3948426.9
Sched Date:		Latitude Degree:	
Use of Wel:		Latitude Minute:	
Sys Date:		Latitude Second:	
Subdiv Nam:		Longitude Degree:	
Surface Co:		Longitude Minute:	
Ditch Name:		Longitude Second:	

Wells and Additional Sources Detail Report

Well Tag:		X:	585430
Static Lev:		Y:	1701350
Tract Nbr:		Point Y:	
Map Nbr:		Point X:	01117
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:			
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
117	NNE	0.74	3,897.09	6,876.04	WATER WELLS

License Nb:		District Office S:	1 & 6
POD No:	01117	Surv Map:	
POD Rec No:	49602	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	RG	Percent Sh:	
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:		Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:		Datum:	NAD83
CS Code:		UTM Source:	UN
Depth of Well:	725	UTM Zone:	
Depth of Water:	97	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:	TURBIN	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0	Lat Lon AC:	
Elevation:	6807.9	County:	Santa Fe
Ref :		Easting:	412858.4
Pcw Rcv Da:		Northing:	3948426.9
Sched Date:		Latitude Degree:	
Use of Wel:		Latitude Minute:	
Sys Date:		Latitude Second:	
Subdiv Nam:		Longitude Degree:	
Surface Co:		Longitude Minute:	

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	
Well Tag:		X:	585430
Static Lev:		Y:	1701350
Tract Nbr:		Point Y:	
Map Nbr:		Point X:	01113
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:			
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
118	NNE	0.74	3,898.95	6,878.77	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	312000	Other Loc:	Ustb-23
POD Basin:	RG	Zone :	
POD Suffix:	POD6	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/01/2018, 12:00 AM	Restrict :	0.0
Finish Date:	05/18/2018, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	06/15/2018, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	411	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412888.2
Pcw Rcv Da:		Northing:	3948409.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/05/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1725771.9
Static Lev:	267	Y:	1701356.3
Tract Nbr:		Point Y:	35.67572614
Map Nbr:		Point X:	-105.96259832
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
119	SSE	0.74	3,888.41	6,837.53	WATER WELLS

License Nb:	253	District Office S:	
POD No:	38596	Surv Map:	
POD Rec No:	40912	Other Loc:	2067 Calle Sombra, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	21 2 U3 SF
Start Date:	05/18/1983, 12:00 AM	Restrict :	0.0
Finish Date:	05/19/1983, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	06/06/1983, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	330	UTM Zone:	13
Depth of Water:	205	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	8.75	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412613.7
Pcw Rcv Da:		Northing:	3946202.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/26/2022, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:	Casa Del Cerro	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	412613.7
Static Lev:	0	Y:	3946202.5
Tract Nbr:		Point Y:	35.65580539
Map Nbr:		Point X:	-105.96539162
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052097520103000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
120	SSW	0.74	3,898.27	6,797.62	WATER WELLS

License Nb:	1004	District Office S:	
POD No:	62759	Surv Map:	
POD Rec No:	64008	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/25/1995, 12:00 AM	Restrict :	3.0
Finish Date:	07/26/1995, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	07/31/1995, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	304	UTM Zone:	13
Depth of Water:	163	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411937.1
Pcw Rcv Da:		Northing:	3946198.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	09/06/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	582500.0
Static Lev:	0	Y:	1694000.0
Tract Nbr:		Point Y:	35.65571008
Map Nbr:		Point X:	-105.97286491
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
122	WNW	0.74	3,926.16	6,761.01	WATER WELLS

License Nb:	0	District Office S:	
POD No:	64975	Surv Map:	
POD Rec No:	58891	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411071.5
Pcw Rcv Da:		Northing:	3947626.8
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	12/16/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579600.0
Static Lev:	0	Y:	1698650.0
Tract Nbr:		Point Y:	35.66850786
Map Nbr:		Point X:	-105.98258402
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
124	E	0.75	3,962.15	6,946.48	WATER WELLS

License Nb:	0	District Office S:	
POD No:	53353	Surv Map:	
POD Rec No:	16666	Other Loc:	1435 S St Francis Dr
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	6 10 U2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413501.4
Pcw Rcv Da:		Northing:	3947425.5

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Pacheco Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1727825.0
Static Lev:	0	Y:	1698153.0
Tract Nbr:		Point Y:	35.66690918
Map Nbr:		Point X:	-105.95571746
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
125	WSW	0.75	3,972.22	6,765.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	42737	Surv Map:	
POD Rec No:	37998	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411123.3

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3946909.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/14/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579800.0
Static Lev:	0	Y:	1696300.0
Tract Nbr:		Point Y:	35.66204959
Map Nbr:		Point X:	-105.9819326
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
126	WSW	0.75	3,979.44	6,770.37	WATER WELLS

License Nb:	0	District Office S:	
POD No:	40727	Surv Map:	
POD Rec No:	23926	Other Loc:	1326 Lujan St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	411160.8
Pcw Rcv Da:		Northing:	3946824.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/17/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Domingo	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720170.0
Static Lev:	0	Y:	1696084.0
Tract Nbr:		Point Y:	35.66128488
Map Nbr:		Point X:	-105.98150894
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
127	NW	0.75	3,982.26	6,774.50	WATER WELLS

License Nb:	0	District Office S:	
POD No:	45084	Surv Map:	
POD Rec No:	40086	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411538.0
Pcw Rcv Da:		Northing:	3948367.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/22/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581100.0
Static Lev:	0	Y:	1701100.0
Tract Nbr:		Point Y:	35.67522731
Map Nbr:		Point X:	-105.97751168
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
128	NE	0.76	3,997.70	6,889.91	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	313727	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD15	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/08/2018, 12:00 AM	Restrict :	0.0
Finish Date:	09/23/2018, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/2019, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	354	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413033.2
Pcw Rcv Da:		Northing:	3948344.2
Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	40
Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	30.54
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	39.56
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67515025
Map Nbr:		Point X:	-105.96098919
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
130	W	0.76	3,998.50	6,758.34	WATER WELLS

License Nb:	1004	District Office S:	
POD No:	54398	Surv Map:	
POD Rec No:	36563	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/18/1991, 12:00 AM	Restrict :	0.0
Finish Date:	11/19/1991, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	11/25/1991, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	50	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	35	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411040.4
Pcw Rcv Da:		Northing:	3947581.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/15/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579500.0
Static Lev:	0	Y:	1698500.0
Tract Nbr:		Point Y:	35.66809667
Map Nbr:		Point X:	-105.98292259
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
132	W	0.76	4,019.35	6,755.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	37349	Surv Map:	
POD Rec No:	334455	Other Loc:	1209 Declovina St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	10 3 U3 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411024.3
Pcw Rcv Da:		Northing:	3947234.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/29/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Domingo	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1719705.0
Static Lev:	0	Y:	1697424.0
Tract Nbr:		Point Y:	35.66496968
Map Nbr:		Point X:	-105.98306214
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
133	NNW	0.76	4,026.52	6,775.33	WATER WELLS

License Nb:	1616	District Office S:	
POD No:	A1265	Surv Map:	
POD Rec No:	341362	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 NA NA
Start Date:	06/12/2023, 12:00 AM	Restrict :	0.0
Finish Date:	06/15/2023, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	06/27/2023, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PD
Depth of Well:	250	UTM Zone:	13
Depth of Water:	125	UTM Accura:	
Ground Water Src:	S	UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411582.9
Pcw Rcv Da:		Northing:	3948415.8
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	06/27/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	6226C	X:	1721488.6
Static Lev:	115	Y:	1701322.3
Tract Nbr:		Point Y:	35.67566676
Map Nbr:		Point X:	-105.97702091
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
134	NNE	0.77	4,043.37	6,882.24	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	313728	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD14	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/14/2018, 12:00 AM	Restrict :	0.0
Finish Date:	11/21/2018, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/2019, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	367	UTM Zone:	13
Depth of Water:	0	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412962.8
Pcw Rcv Da:		Northing:	3948413.6
Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	40
Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	32.77
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	42.39
Well Tag:	NA	X:	0.0
Static Lev:	275	Y:	0.0
Tract Nbr:		Point Y:	35.67576969
Map Nbr:		Point X:	-105.96177453
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
134	NNE	0.77	4,043.37	6,882.24	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	313726	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD13	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/27/2018, 12:00 AM	Restrict :	0.0
Finish Date:	12/05/2018, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/2019, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	327	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	270	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412962.8
Pcw Rcv Da:		Northing:	3948413.6
Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	40
Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	32.77
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	42.39
Well Tag:	NA	X:	0.0
Static Lev:	268	Y:	0.0
Tract Nbr:		Point Y:	35.67576969
Map Nbr:		Point X:	-105.96177453
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
134	NNE	0.77	4,043.37	6,882.24	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	313725	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD12	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	12/06/2018, 12:00 AM	Restrict :	0.0
Finish Date:	12/14/2018, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/2019, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD

Wells and Additional Sources Detail Report

Depth of Well:	287	UTM Zone:	13
Depth of Water:	270	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412962.8
Pcw Rcv Da:		Northing:	3948413.6
Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	40
Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	32.77
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	42.39
Well Tag:	NA	X:	0.0
Static Lev:	268	Y:	0.0
Tract Nbr:		Point Y:	35.67576969
Map Nbr:		Point X:	-105.96177453
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
136	NW	0.77	4,043.06	6,766.35	WATER WELLS

License Nb:	0	District Office S:	
POD No:	71011	Surv Map:	
POD Rec No:	146781	Other Loc:	959 Acequia De Las Joyas
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1B1 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411393.1
Pcw Rcv Da:		Northing:	3948268.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/27/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411393.1
Static Lev:	0	Y:	3948268.5
Tract Nbr:		Point Y:	35.6743218
Map Nbr:		Point X:	-105.97910173
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number: 1052098117243000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
137	WNW	0.76	4,033.00	6,761.14	WATER WELLS

License Nb:	1310	District Office S:	
POD No:	14882	Surv Map:	
POD Rec No:	154509	Other Loc:	2004 Agua Fria St
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA SF
Start Date:	09/25/1999, 12:00 AM	Restrict :	0.0
Finish Date:	09/27/1999, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	07/05/2000, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	80	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-14882-CLW171789/51436/RG-14	Easting:	411151.9
Pcw Rcv Da:		Northing:	3947943.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/29/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1720094.0
Static Lev:	0	Y:	1699756.0
Tract Nbr:		Point Y:	35.6713738
Map Nbr:		Point X:	-105.98173079
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	One Block West Osage On Agua Fria.		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
138	WNW	0.76	4,035.93	6,759.98	WATER WELLS

License Nb:	539	District Office S:	
POD No:	68754	Surv Map:	
POD Rec No:	139796	Other Loc:	2010 Agua Fria St. Unit D
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 SF
Start Date:	11/24/1997, 12:00 AM	Restrict :	0.0
Finish Date:	11/28/1997, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	12/12/1997, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	150	UTM Zone:	13
Depth of Water:	50	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411099.1
Pcw Rcv Da:		Northing:	3947830.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/13/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Antonio Barela Tract	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411099.1
Static Lev:	0	Y:	3947830.4
Tract Nbr:		Point Y:	35.67034582
Map Nbr:		Point X:	-105.98230159
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052098015100000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
139	WNW	0.77	4,049.09	6,758.91	WATER WELLS

License Nb:	1173	District Office S:	
POD No:	45121	Surv Map:	
POD Rec No:	338328	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/03/1987, 12:00 AM	Restrict :	0.0
Finish Date:	09/22/1987, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	10/18/1987, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	280	UTM Zone:	13
Depth of Water:	230	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	5.25	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411104.8
Pcw Rcv Da:		Northing:	3947854.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/26/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579700.0
Static Lev:	0	Y:	1699400.0
Tract Nbr:		Point Y:	35.67056721
Map Nbr:		Point X:	-105.98224132
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
140	WNW	0.77	4,084.17	6,758.55	WATER WELLS

License Nb:	214	District Office S:	
POD No:	00891	Surv Map:	
POD Rec No:	27469	Other Loc:	2006 Agua Fria St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 25 TE SF
Start Date:	05/25/1957, 12:00 AM	Restrict :	0.0
Finish Date:	05/26/1957, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	06/27/1957, 12:00 AM	Range:	09E

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	68	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411109.5
Pcw Rcv Da:		Northing:	3947893.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/11/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1719957.0
Static Lev:	0	Y:	1699588.0
Tract Nbr:		Point Y:	35.67091381
Map Nbr:		Point X:	-105.98219364
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
141	NNE	0.78	4,111.08	6,870.49	WATER WELLS

License Nb:	0	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	349484	Other Loc:	Ustb-56
POD Basin:	RG	Zone :	
POD Suffix:	POD39	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	

Wells and Additional Sources Detail Report

Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412765.8
Pcw Rcv Da:		Northing:	3948546.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/19/2024, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1725364.4
Static Lev:	0	Y:	1701801.9
Tract Nbr:		Point Y:	35.676954
Map Nbr:		Point X:	-105.96396559
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
142	SW	0.78	4,141.21	6,772.40	WATER WELLS

License Nb:	1848	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	343037	Other Loc:	Iw-1
POD Basin:	RG	Zone :	
POD Suffix:	POD7	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	IW-1	Subdiv Loc:	
Start Date:	10/23/2023, 12:00 AM	Restrict :	0.0
Finish Date:	11/06/2023, 12:00 AM	Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:	12/14/2023, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	117	UTM Zone:	13
Depth of Water:	102	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411251.6
Pcw Rcv Da:		Northing:	3946591.0
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	01/02/2024, 12:00 AM	Latitude Second:	33.07
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	49.73
Well Tag:	NA	X:	0.0
Static Lev:	102	Y:	0.0
Tract Nbr:		Point Y:	35.65918621
Map Nbr:		Point X:	-105.98048015
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
143	NE	0.78	4,133.48	6,886.32	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	312001	Other Loc:	Ustb-24
POD Basin:	RG	Zone :	
POD Suffix:	POD7	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/24/2018, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	05/18/2018, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	06/15/2018, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	327	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413017.6
Pcw Rcv Da:		Northing:	3948408.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/05/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1726196.3
Static Lev:	282	Y:	1701357.9
Tract Nbr:		Point Y:	35.67572765
Map Nbr:		Point X:	-105.96116849
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
144	SW	0.79	4,150.72	6,773.02	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	305038	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD6	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:	02/20/2017, 12:00 AM	Restrict :	0.0
Finish Date:	02/24/2017, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	03/16/2017, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	115	UTM Zone:	13
Depth of Water:	105	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411264.2
Pcw Rcv Da:		Northing:	3946570.8
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	09/21/2018, 12:00 AM	Latitude Second:	32.42
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	49.22
Well Tag:		X:	0.0
Static Lev:	104	Y:	0.0
Tract Nbr:		Point Y:	35.65900524
Map Nbr:		Point X:	-105.98033874
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
145	SW	0.79	4,150.48	6,772.18	WATER WELLS

License Nb:	1848	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	343038	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD8	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:	IW-2	Subdiv Loc:	
Start Date:	10/23/2023, 12:00 AM	Restrict :	0.0
Finish Date:	11/06/2023, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/14/2023, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	117	UTM Zone:	13
Depth of Water:	102	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411259.5
Pcw Rcv Da:		Northing:	3946577.4
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	01/02/2024, 12:00 AM	Latitude Second:	32.63
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	49.41
Well Tag:	NA	X:	0.0
Static Lev:	102	Y:	0.0
Tract Nbr:		Point Y:	35.65906432
Map Nbr:		Point X:	-105.98039138
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
146	W	0.78	4,121.88	6,755.23	WATER WELLS

License Nb:	622	District Office S:	
POD No:	79402	Surv Map:	
POD Rec No:	186588	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/02/2003, 12:00 AM	Restrict :	0.0
Finish Date:	09/02/2003, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	09/10/2003, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PD
Depth of Well:	240	UTM Zone:	13
Depth of Water:	92	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410993.9
Pcw Rcv Da:		Northing:	3947521.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/11/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579350.0
Static Lev:	0	Y:	1698300.0
Tract Nbr:		Point Y:	35.66754796
Map Nbr:		Point X:	-105.98342963
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
147	WNW	0.78	4,128.22	6,755.15	WATER WELLS

License Nb:	228	District Office S:	
POD No:	30011	Surv Map:	
POD Rec No:	21479	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/08/1978, 12:00 AM	Restrict :	0.0
Finish Date:	03/08/1978, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	03/16/1978, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	200	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411136.9
Pcw Rcv Da:		Northing:	3947976.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/07/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579800.0
Static Lev:	0	Y:	1699800.0
Tract Nbr:		Point Y:	35.67166544
Map Nbr:		Point X:	-105.9819001
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
148	SW	0.79	4,161.96	6,772.40	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	305036	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD4	BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/20/2017, 12:00 AM	Restrict :	0.0
Finish Date:	02/24/2017, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	03/16/2017, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	115	UTM Zone:	13
Depth of Water:	108	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411245.0
Pcw Rcv Da:		Northing:	3946589.8
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	09/21/2018, 12:00 AM	Latitude Second:	33.03
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	49.99
Well Tag:		X:	0.0
Static Lev:	108	Y:	0.0
Tract Nbr:		Point Y:	35.6591748
Map Nbr:		Point X:	-105.98055292
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
149	WNW	0.78	4,134.23	6,753.41	WATER WELLS

License Nb:	1004	District Office S:	
POD No:	49984	Surv Map:	
POD Rec No:	14441	Other Loc:	
POD Basin:	RG	Zone :	C

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	12/01/1988, 12:00 AM	Restrict :	0.0
Finish Date:	12/02/1988, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	12/08/1988, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	140	UTM Zone:	13
Depth of Water:	65	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411010.7
Pcw Rcv Da:		Northing:	3947642.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/25/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579400.0
Static Lev:	0	Y:	1698700.0
Tract Nbr:		Point Y:	35.66864662
Map Nbr:		Point X:	-105.98325749
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
150	WNW	0.78	4,137.02	6,756.56	WATER WELLS

License Nb:	228	District Office S:	
POD No:	01302	Surv Map:	
POD Rec No:	190920	Other Loc:	2010b Agua Fria St

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 SF
Start Date:	03/20/1991, 12:00 AM	Restrict :	0.0
Finish Date:	03/20/1991, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	03/25/1991, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	100	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-01302-CLW269040/30677/RG-01	Easting:	411091.8
Pcw Rcv Da:		Northing:	3947891.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/15/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Antonio Barela Tract	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1719899.0
Static Lev:	0	Y:	1699582.0
Tract Nbr:		Point Y:	35.67089779
Map Nbr:		Point X:	-105.98238901
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
151	NW	0.79	4,151.08	6,764.81	WATER WELLS

License Nb:	547	District Office S:	
POD No:	82271	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	200699	Other Loc:	1731 Agua Fria St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA1 SF
Start Date:	12/27/2004, 12:00 AM	Restrict :	0.0
Finish Date:	12/27/2004, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	01/05/2005, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	120	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	24	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411385.7
Pcw Rcv Da:		Northing:	3948306.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/29/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411385.7
Static Lev:	0	Y:	3948306.0
Tract Nbr:		Point Y:	35.6746592
Map Nbr:		Point X:	-105.97918762
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052098110249		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
152	E	0.79	4,146.40	6,943.24	WATER WELLS

License Nb:	253	District Office S:	

Wells and Additional Sources Detail Report

POD No:	09030	Surv Map:	
POD Rec No:	50209	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/17/1963, 12:00 AM	Restrict :	0.0
Finish Date:	05/29/1963, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	07/16/1963, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	220	UTM Zone:	13
Depth of Water:	153	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413557.0
Pcw Rcv Da:		Northing:	3947286.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	04/28/2006, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66565644
Map Nbr:		Point X:	-105.95508823
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
152	E	0.79	4,146.40	6,943.24	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	253	District Office S:	
POD No:	09030	Surv Map:	
POD Rec No:	7104	Other Loc:	Qtrs Are Projected
POD Basin:	RG	Zone :	
POD Suffix:	REPAR	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/09/1982, 12:00 AM	Restrict :	0.0
Finish Date:	11/24/1982, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	11/30/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	238	UTM Zone:	13
Depth of Water:	189	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413557.0
Pcw Rcv Da:		Northing:	3947286.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	05/17/2006, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66565644
Map Nbr:		Point X:	-105.95508823
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
154	SW	0.79	4,185.37	6,772.17	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	1848	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	343041	Other Loc:	Iw-5
POD Basin:	RG	Zone :	
POD Suffix:	POD11	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	IW-5	Subdiv Loc:	
Start Date:	10/23/2023, 12:00 AM	Restrict :	0.0
Finish Date:	11/06/2023, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/14/2023, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	118	UTM Zone:	13
Depth of Water:	102	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411257.8
Pcw Rcv Da:		Northing:	3946562.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	01/02/2024, 12:00 AM	Latitude Second:	32.15
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	49.47
Well Tag:	NA	X:	0.0
Static Lev:	102	Y:	0.0
Tract Nbr:		Point Y:	35.65893074
Map Nbr:		Point X:	-105.98040853
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
155	SW	0.79	4,184.97	6,771.45	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	1848	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	343039	Other Loc:	Iw-3
POD Basin:	RG	Zone :	
POD Suffix:	POD9	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	IW-3	Subdiv Loc:	
Start Date:	10/23/2023, 12:00 AM	Restrict :	0.0
Finish Date:	11/06/2023, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/14/2023, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	117	UTM Zone:	13
Depth of Water:	102	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411240.2
Pcw Rcv Da:		Northing:	3946585.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	01/02/2024, 12:00 AM	Latitude Second:	32.88
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	50.18
Well Tag:	NA	X:	0.0
Static Lev:	102	Y:	0.0
Tract Nbr:		Point Y:	35.6591338
Map Nbr:		Point X:	-105.98060545
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

156	SW	0.79	4,189.53	6,771.31	WATER WELLS

License Nb:	1848	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	343040	Other Loc:	Iw-4
POD Basin:	RG	Zone :	
POD Suffix:	POD10	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	IW-4	Subdiv Loc:	
Start Date:	10/23/2023, 12:00 AM	Restrict :	0.0
Finish Date:	11/06/2023, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/14/2023, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	117	UTM Zone:	13
Depth of Water:	102	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411249.1
Pcw Rcv Da:		Northing:	3946571.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	01/02/2024, 12:00 AM	Latitude Second:	32.44
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	49.82
Well Tag:	NA	X:	0.0
Static Lev:	102	Y:	0.0
Tract Nbr:		Point Y:	35.65901109
Map Nbr:		Point X:	-105.98050562
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

157	SW	0.79	4,192.06	6,772.17	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	305037	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD5	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/20/2017, 12:00 AM	Restrict :	0.0
Finish Date:	02/24/2017, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	03/21/2017, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	114	UTM Zone:	13
Depth of Water:	108	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411253.3
Pcw Rcv Da:		Northing:	3946564.5
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	08/24/2022, 12:00 AM	Latitude Second:	32.21
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	49.65
Well Tag:		X:	0.0
Static Lev:	108	Y:	0.0
Tract Nbr:		Point Y:	35.65894746
Map Nbr:		Point X:	-105.98045845
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
158	WNW	0.79	4,155.33	6,752.18	WATER WELLS

License Nb:	0	District Office S:	
POD No:	49557	Surv Map:	
POD Rec No:	15035	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	P2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411011.1
Pcw Rcv Da:		Northing:	3947673.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/17/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Pueblo Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579400.0
Static Lev:	0	Y:	1698800.0
Tract Nbr:		Point Y:	35.66892161
Map Nbr:		Point X:	-105.98325644
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
160	SW	0.80	4,201.23	6,771.33	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	304643	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	1	Subdiv Loc:	
Start Date:	10/10/2016, 12:00 AM	Restrict :	0.0
Finish Date:	10/14/2016, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	10/19/2016, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	120	UTM Zone:	13
Depth of Water:	105	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411250.3
Pcw Rcv Da:		Northing:	3946564.2
Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	39
Sys Date:	11/21/2016, 12:00 AM	Latitude Second:	32.2
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	49.77
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65894449
Map Nbr:		Point X:	-105.98049155
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
161	WNW	0.79	4,171.71	6,755.07	WATER WELLS

License Nb:	0	District Office S:	
POD No:	39459	Surv Map:	
POD Rec No:	58148	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411106.0
Pcw Rcv Da:		Northing:	3947946.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/18/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579700.0
Static Lev:	0	Y:	1699700.0
Tract Nbr:		Point Y:	35.6713913
Map Nbr:		Point X:	-105.98223816
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
162	SSW	0.79	4,181.26	6,782.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289866	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD65	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411821.8
Pcw Rcv Da:		Northing:	3946146.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	18.84
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	26.88
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6552337
Map Nbr:		Point X:	-105.97413285
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
163	NE	0.80	4,211.31	6,888.63	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	313724	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD11	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/23/2018, 12:00 AM	Restrict :	0.0
Finish Date:	10/05/2018, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/2019, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	328	UTM Zone:	13
Depth of Water:	274	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413053.0
Pcw Rcv Da:		Northing:	3948411.8
Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	40
Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	32.74
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	38.8
Well Tag:	NA	X:	0.0
Static Lev:	274	Y:	0.0
Tract Nbr:		Point Y:	35.67576142
Map Nbr:		Point X:	-105.96077773
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
163	NE	0.80	4,211.31	6,888.63	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	313723	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD10	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/05/2018, 12:00 AM	Restrict :	0.0
Finish Date:	10/19/2018, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/2019, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	290	UTM Zone:	13
Depth of Water:	274	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413053.0
Pcw Rcv Da:		Northing:	3948411.8
Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	40
Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	32.74
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	38.8
Well Tag:	NA	X:	0.0
Static Lev:	274	Y:	0.0
Tract Nbr:		Point Y:	35.67576142
Map Nbr:		Point X:	-105.96077773

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
164	NNW	0.80	4,202.95	6,771.76	WATER WELLS

License Nb:	228	District Office S:	
POD No:	55402	Surv Map:	
POD Rec No:	50580	Other Loc:	1709 Agua Fria St Unit F
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA SF
Start Date:	05/20/1992, 12:00 AM	Restrict :	0.0
Finish Date:	05/30/1992, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	06/05/1992, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	220	UTM Zone:	13
Depth of Water:	130	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411599.5
Pcw Rcv Da:		Northing:	3948490.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/13/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411599.5
Static Lev:	0	Y:	3948490.7
Tract Nbr:		Point Y:	35.67634348

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.97684573
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number: 1052098178312000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
165	W	0.80	4,199.41	6,750.85	WATER WELLS

License Nb:	1004	District Office S:	
POD No:	46868	Surv Map:	
POD Rec No:	7850	Other Loc:	2372 Camino Hualapai, Unit A
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	UA SF
Start Date:	03/17/1987, 12:00 AM	Restrict :	0.0
Finish Date:	03/18/1987, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	03/07/2005, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	138	UTM Zone:	13
Depth of Water:	65	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410961.8
Pcw Rcv Da:		Northing:	3947399.6
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	08/02/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Hualapai	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1719493.0
Static Lev:	0	Y:	1697962.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.66644973
Map Nbr:		Point X:	-105.98377082
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
166	SW	0.80	4,242.75	6,770.48	WATER WELLS

License Nb:	1848	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	343042	Other Loc:	Iw-6
POD Basin:	RG	Zone :	
POD Suffix:	POD12	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	IW-6	Subdiv Loc:	
Start Date:	10/23/2023, 12:00 AM	Restrict :	0.0
Finish Date:	11/06/2023, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/14/2023, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	116	UTM Zone:	13
Depth of Water:	102	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411242.4
Pcw Rcv Da:		Northing:	3946554.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	01/02/2024, 12:00 AM	Latitude Second:	31.87
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	50.08
Well Tag:	NA	X:	0.0

Static Lev:	102	Y:	0.0
Tract Nbr:		Point Y:	35.65885273
Map Nbr:		Point X:	-105.98057771
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
167	NNE	0.80	4,223.56	6,878.42	WATER WELLS

License Nb:		District Office S:	1 & 6
POD No:	81092	Surv Map:	
POD Rec No:	195280	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	RG	Percent Sh:	
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:		Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:		Datum:	NAD83
CS Code:		UTM Source:	UN
Depth of Well:	441	UTM Zone:	
Depth of Water:	318	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	18	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:		County:	Santa Fe
Ref :		Easting:	412926.4
Pcw Rcv Da:		Northing:	3948502.2
Sched Date:		Latitude Degree:	
Use of Wel:		Latitude Minute:	
Sys Date:		Latitude Second:	
Subdiv Nam:		Longitude Degree:	
Surface Co:		Longitude Minute:	
Ditch Name:		Longitude Second:	

Wells and Additional Sources Detail Report

Well Tag:		X:	585650
Static Lev:		Y:	1701600
Tract Nbr:		Point Y:	
Map Nbr:		Point X:	01113
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:			
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
167	NNE	0.80	4,223.56	6,878.42	WATER WELLS

License Nb:	225	District Office S:	
POD No:	81092	Surv Map:	
POD Rec No:	195280	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/06/2003, 12:00 AM	Restrict :	81.0
Finish Date:	10/14/2003, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	02/20/2004, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	441	UTM Zone:	13
Depth of Water:	318	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	18	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412926.4
Pcw Rcv Da:		Northing:	3948502.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/14/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	585650.0
Static Lev:	0	Y:	1701600.0
Tract Nbr:		Point Y:	35.67656522
Map Nbr:		Point X:	-105.96218629
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
168	SSE	0.80	4,214.65	6,838.13	WATER WELLS

License Nb:	253	District Office S:	
POD No:	38598	Surv Map:	
POD Rec No:	13204	Other Loc:	2069 Camino Lado, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	15 2 U3 SF
Start Date:	05/20/1983, 12:00 AM	Restrict :	0.0
Finish Date:	05/21/1983, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	05/31/1983, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	325	UTM Zone:	13
Depth of Water:	200	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412644.9
Pcw Rcv Da:		Northing:	3946108.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/26/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Del Cerro	Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	412644.9
Static Lev:	0	Y:	3946108.9
Tract Nbr:		Point Y:	35.65496433
Map Nbr:		Point X:	-105.96503684
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1053097005075000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
169	NW	0.80	4,236.83	6,755.30	WATER WELLS

License Nb:	228	District Office S:	
POD No:	34034	Surv Map:	SANTA FE HYDRO SURVEY VOL 1
POD Rec No:	59650	Other Loc:	**Tct 25.21
POD Basin:	RG	Zone :	C
POD Suffix:	-CLW	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/08/1980, 12:00 AM	Restrict :	0.0
Finish Date:	05/09/1980, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:	SUBMER	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411263.3
Pcw Rcv Da:	09/24/1984, 12:00 AM	Northing:	3948217.1
Sched Date:		Latitude Degree:	0
Use of Wel:	IRR & DOM	Latitude Minute:	0
Sys Date:	04/29/1991, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	580205.0
Static Lev:	0	Y:	1700595.0
Tract Nbr:	**	Point Y:	35.67384675
Map Nbr:	7	Point X:	-105.98053016
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
169	NW	0.80	4,236.83	6,755.30	WATER WELLS

License Nb:	228	District Office S:	
POD No:	34034	Surv Map:	SANTA FEY HYDRO SURVEY VOL 1
POD Rec No:	35269	Other Loc:	**Tct 25.21
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	07/01/1952, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	65	UTM Zone:	13
Depth of Water:	50	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:	SUBMER	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411263.3
Pcw Rcv Da:		Northing:	3948217.1
Sched Date:		Latitude Degree:	0
Use of Wel:	IRR	Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	04/29/1991, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	580205.0
Static Lev:	0	Y:	1700595.0
Tract Nbr:	**	Point Y:	35.67384675
Map Nbr:	7	Point X:	-105.98053016
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
171	NE	0.80	4,249.12	6,885.34	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	313721	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD8	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/31/2018, 12:00 AM	Restrict :	0.0
Finish Date:	11/09/2018, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/2019, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	290	UTM Zone:	13
Depth of Water:	272	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413023.9
Pcw Rcv Da:		Northing:	3948447.5
Sched Date:		Latitude Degree:	35

Wells and Additional Sources Detail Report

Use of Wel:	EXPL	Latitude Minute:	40
Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	33.89
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	39.97
Well Tag:	NA	X:	0.0
Static Lev:	272	Y:	0.0
Tract Nbr:		Point Y:	35.6760807
Map Nbr:		Point X:	-105.96110311
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
171	NE	0.80	4,249.12	6,885.34	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	313722	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD9	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/21/2018, 12:00 AM	Restrict :	0.0
Finish Date:	10/26/2018, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/2019, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	325	UTM Zone:	13
Depth of Water:	272	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413023.9
Pcw Rcv Da:		Northing:	3948447.5

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	40
Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	33.89
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	39.97
Well Tag:	NA	X:	0.0
Static Lev:	283	Y:	0.0
Tract Nbr:		Point Y:	35.6760807
Map Nbr:		Point X:	-105.96110311
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
173	NW	0.80	4,243.71	6,755.30	WATER WELLS

License Nb:	0	District Office S:	
POD No:	29999	Surv Map:	
POD Rec No:	10148	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411261.8

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3948218.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/07/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	580200.0
Static Lev:	0	Y:	1700600.0
Tract Nbr:		Point Y:	35.67386014
Map Nbr:		Point X:	-105.98054689
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
174	NW	0.81	4,268.23	6,764.84	WATER WELLS

License Nb:	1289	District Office S:	
POD No:	61480	Surv Map:	
POD Rec No:	34007	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/03/1995, 12:00 AM	Restrict :	0.0
Finish Date:	04/08/1995, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/14/1995, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	145	UTM Zone:	13
Depth of Water:	50	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	411385.5
Pcw Rcv Da:		Northing:	3948354.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/08/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	580600.0
Static Lev:	0	Y:	1701050.0
Tract Nbr:		Point Y:	35.67509371
Map Nbr:		Point X:	-105.97919514
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
175	SW	0.81	4,293.07	6,768.81	WATER WELLS

License Nb:	1848	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	343043	Other Loc:	Iw-7
POD Basin:	RG	Zone :	
POD Suffix:	POD13	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	IW-7	Subdiv Loc:	
Start Date:	10/23/2023, 12:00 AM	Restrict :	0.0
Finish Date:	11/06/2023, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	12/14/2023, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	115	UTM Zone:	13
Depth of Water:	102	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	2.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411223.8
Pcw Rcv Da:		Northing:	3946552.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	01/02/2024, 12:00 AM	Latitude Second:	31.8
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	50.82
Well Tag:	NA	X:	0.0
Static Lev:	102	Y:	0.0
Tract Nbr:		Point Y:	35.65883302
Map Nbr:		Point X:	-105.98078295
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
176	SW	0.81	4,295.39	6,768.46	WATER WELLS

License Nb:	1186	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	304644	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	POD2	Subdiv Loc:	
Start Date:	10/10/2016, 12:00 AM	Restrict :	0.0
Finish Date:	10/14/2016, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	10/19/2016, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	123	UTM Zone:	13
Depth of Water:	103	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411213.8
Pcw Rcv Da:		Northing:	3946563.0
Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	39
Sys Date:	11/21/2016, 12:00 AM	Latitude Second:	32.15
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	51.22
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65893039
Map Nbr:		Point X:	-105.98089461
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
177	WNW	0.81	4,263.69	6,748.95	WATER WELLS

License Nb:	0	District Office S:	
POD No:	43641	Surv Map:	
POD Rec No:	61117	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411106.8
Pcw Rcv Da:		Northing:	3948007.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/20/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579700.0
Static Lev:	0	Y:	1699900.0
Tract Nbr:		Point Y:	35.67194129
Map Nbr:		Point X:	-105.98223606
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
178	W	0.81	4,265.35	6,743.67	WATER WELLS

License Nb:	227	District Office S:	
POD No:	36500	Surv Map:	
POD Rec No:	68364	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/03/1981, 12:00 AM	Restrict :	0.0
Finish Date:	07/06/1981, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	07/14/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	96	UTM Zone:	13
Depth of Water:	46	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410943.0
Pcw Rcv Da:		Northing:	3947314.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/24/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66567634
Map Nbr:		Point X:	-105.98396904
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
179	W	0.81	4,263.19	6,752.39	WATER WELLS

License Nb:	0	District Office S:	
POD No:	66947	Surv Map:	
POD Rec No:	54204	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410947.8
Pcw Rcv Da:		Northing:	3947491.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/09/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579200.0
Static Lev:	0	Y:	1698200.0
Tract Nbr:		Point Y:	35.66727425
Map Nbr:		Point X:	-105.98393562
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
180	SW	0.81	4,300.01	6,768.46	WATER WELLS

License Nb:	0	District Office S:	
POD No:	96350	Surv Map:	
POD Rec No:	305035	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411212.1
Pcw Rcv Da:		Northing:	3946562.7
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	01/10/2017, 12:00 AM	Latitude Second:	32.14
Subdiv Nam:	College Plaza	Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	51.29
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65892753
Map Nbr:		Point X:	-105.98091336
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
181	W	0.81	4,273.61	6,752.22	WATER WELLS

License Nb:	225	District Office S:	
POD No:	11473	Surv Map:	
POD Rec No:	67733	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/05/1982, 12:00 AM	Restrict :	0.0
Finish Date:	07/05/1982, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	07/19/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	125	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	30	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410947.0
Pcw Rcv Da:		Northing:	3947516.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	09/23/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66749775
Map Nbr:		Point X:	-105.9839472
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
181	W	0.81	4,273.61	6,752.22	WATER WELLS

License Nb:	0	District Office S:	
POD No:	27890	Surv Map:	
POD Rec No:	21794	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G

Wells and Additional Sources Detail Report

Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410947.0
Pcw Rcv Da:		Northing:	3947516.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/22/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66749775
Map Nbr:		Point X:	-105.9839472
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
181	W	0.81	4,273.61	6,752.22	WATER WELLS

License Nb:	228	District Office S:	
POD No:	14291	Surv Map:	
POD Rec No:	39933	Other Loc:	Nw 1/4
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	09/04/1966, 12:00 AM	Restrict :	0.0
Finish Date:	09/05/1966, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	06/12/1967, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	0	UTM Source:	G
Depth of Well:	60	UTM Zone:	13
Depth of Water:	18	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	410947.0
Pcw Rcv Da:		Northing:	3947516.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/29/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66749775
Map Nbr:		Point X:	-105.9839472
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
181	W	0.81	4,273.61	6,752.22	WATER WELLS

License Nb:	225	District Office S:	
POD No:	11473	Surv Map:	
POD Rec No:	328592	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/05/1982, 12:00 AM	Restrict :	0.0
Finish Date:	07/05/1982, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	07/19/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	125	UTM Zone:	13
Depth of Water:	56	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	60	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410947.0
Pcw Rcv Da:		Northing:	3947516.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/23/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66749775
Map Nbr:		Point X:	-105.9839472
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
182	NNW	0.81	4,280.42	6,770.56	WATER WELLS

License Nb:	622	District Office S:	
POD No:	49153	Surv Map:	
POD Rec No:	35372	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/15/1988, 12:00 AM	Restrict :	0.0
Finish Date:	04/16/1988, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/06/1988, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	170	UTM Zone:	13
Depth of Water:	95	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	15	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411600.9
Pcw Rcv Da:		Northing:	3948519.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/06/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	581300.0
Static Lev:	0	Y:	1701600.0
Tract Nbr:		Point Y:	35.67659964
Map Nbr:		Point X:	-105.97683338
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
183	W	0.81	4,290.89	6,748.97	WATER WELLS

License Nb:	0	District Office S:	
POD No:	39859	Surv Map:	
POD Rec No:	335262	Other Loc:	2405 Maclovia Lane
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	6 3 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410947.5
Pcw Rcv Da:		Northing:	3947182.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/23/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Casa Alegre	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1719455.0
Static Lev:	0	Y:	1697248.0
Tract Nbr:		Point Y:	35.66448855
Map Nbr:		Point X:	-105.98390475
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
184	N	0.81	4,283.32	6,803.24	WATER WELLS

License Nb:		District Office S:	1 & 6
POD No:	01118	Surv Map:	
POD Rec No:	17257	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	RG	Percent Sh:	
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	

Wells and Additional Sources Detail Report

Wrats S ID:		Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:		Datum:	NAD83
CS Code:		UTM Source:	UN
Depth of Well:	740	UTM Zone:	
Depth of Water:	46	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:	TURBIN	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0	Lat Lon AC:	
Elevation:	6798.4	County:	Santa Fe
Ref :		Easting:	412106
Pcw Rcv Da:		Northing:	3948692.5
Sched Date:		Latitude Degree:	
Use of Wel:		Latitude Minute:	
Sys Date:		Latitude Second:	
Subdiv Nam:		Longitude Degree:	
Surface Co:		Longitude Minute:	
Ditch Name:		Longitude Second:	
Well Tag:		X:	582950
Static Lev:		Y:	1702190
Tract Nbr:		Point Y:	
Map Nbr:		Point X:	01118
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:			
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
184	N	0.81	4,283.32	6,803.24	WATER WELLS

License Nb:		District Office S:	1 & 6
POD No:	01118	Surv Map:	
POD Rec No:	17257	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	RG	Percent Sh:	
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	
Finish Date:		Section:	
Plug Date:		Township:	

Wells and Additional Sources Detail Report

Log File D:		Range:	
Wrats S ID:		Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:		Datum:	NAD83
CS Code:		UTM Source:	UN
Depth of Well:	740	UTM Zone:	
Depth of Water:	46	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:	TURBIN	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0	Lat Lon AC:	
Elevation:	6798.4	County:	Santa Fe
Ref :		Easting:	412106
Pcw Rcv Da:		Northing:	3948692.5
Sched Date:		Latitude Degree:	
Use of Wel:		Latitude Minute:	
Sys Date:		Latitude Second:	
Subdiv Nam:		Longitude Degree:	
Surface Co:		Longitude Minute:	
Ditch Name:		Longitude Second:	
Well Tag:		X:	582950
Static Lev:		Y:	1702190
Tract Nbr:		Point Y:	
Map Nbr:		Point X:	01113
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:			
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
184	N	0.81	4,283.32	6,803.24	WATER WELLS

License Nb:	0	District Office S:	
POD No:	01118	Surv Map:	
POD Rec No:	17257	Other Loc:	Agua Fria Well
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:	AUGA FRIA WELL	Subdiv Loc:	
Start Date:	07/09/1951, 12:00 AM	Restrict :	4865.0
Finish Date:	08/02/1951, 12:00 AM	Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:	01/18/1952, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	740	UTM Zone:	13
Depth of Water:	46	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:	TURBIN	XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	6798.4	County:	Santa Fe
Ref :		Easting:	412106.0
Pcw Rcv Da:		Northing:	3948692.5
Sched Date:		Latitude Degree:	0
Use of Wel:	MUN	Latitude Minute:	0
Sys Date:	09/14/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	582950.0
Static Lev:	0	Y:	1702190.0
Tract Nbr:		Point Y:	35.67820801
Map Nbr:		Point X:	-105.97127156
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Intersection Of Camino De La Augua Canada & Callejon Zanaida In S.F.		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
185	NW	0.82	4,320.90	6,749.01	WATER WELLS

License Nb:	214	District Office S:	
POD No:	00254	Surv Map:	
POD Rec No:	191062	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/25/1957, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	02/01/1957, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	02/15/1957, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	91	UTM Zone:	13
Depth of Water:	18	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411153.0
Pcw Rcv Da:		Northing:	3948115.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/18/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67291638
Map Nbr:		Point X:	-105.98173753
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
187	WNW	0.82	4,329.21	6,749.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	79773	Surv Map:	
POD Rec No:	188762	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410949.8
Pcw Rcv Da:		Northing:	3947643.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/22/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579200.0
Static Lev:	0	Y:	1698700.0
Tract Nbr:		Point Y:	35.66864833
Map Nbr:		Point X:	-105.98393038
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289817	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD16	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289816	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD15	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289832	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD31	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0

Wells and Additional Sources Detail Report

POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289830	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD29	BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289815	Other Loc:	
POD Basin:	RG	Zone :	

Wells and Additional Sources Detail Report

POD Suffix:	POD14	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289822	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:	POD21	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	289837	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD36	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	94602	Surv Map:	
POD Rec No:	289833	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD32	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289824	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD23	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289823	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD22	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289829	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD28	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289827	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD26	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289831	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD30	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289835	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD34	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289818	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD17	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289821	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD20	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant :

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289814	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD13	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289826	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD25	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289828	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD27	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289836	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD35	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289820	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD19	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289838	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD37	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0

Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289825	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD24	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.6

Wells and Additional Sources Detail Report

Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
188	SSW	0.82	4,339.38	6,788.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289819	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD18	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411878.4
Pcw Rcv Da:		Northing:	3946076.1
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	16.56
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	24.6
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65460049
Map Nbr:		Point X:	-105.9734999
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
189	N	0.82	4,346.01	6,847.86	WATER WELLS

License Nb:	227	District Office S:	
POD No:	18625	Surv Map:	
POD Rec No:	245161	Other Loc:	1424 Agua Fria St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	T1A SF
Start Date:	07/08/1971, 12:00 AM	Restrict :	0.0
Finish Date:	07/09/1971, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	07/21/1971, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	247	UTM Zone:	13
Depth of Water:	185	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412437.7
Pcw Rcv Da:		Northing:	3948710.2
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	12/30/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1724281.0
Static Lev:	0	Y:	1702324.0
Tract Nbr:		Point Y:	35.67839709
Map Nbr:		Point X:	-105.96760851
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
189	N	0.82	4,346.01	6,847.86	WATER WELLS

License Nb:	228	District Office S:	
POD No:	18624	Surv Map:	
POD Rec No:	56130	Other Loc:	West Alameda St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/29/1971, 12:00 AM	Restrict :	0.0
Finish Date:	04/01/1971, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	04/19/1971, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	80	UTM Zone:	13
Depth of Water:	30	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	412437.7
Pcw Rcv Da:		Northing:	3948710.2
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	12/30/2020, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1724281.0
Static Lev:	0	Y:	1702324.0
Tract Nbr:		Point Y:	35.67839709
Map Nbr:		Point X:	-105.96760851
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
190	WNW	0.83	4,372.51	6,746.44	WATER WELLS

License Nb:	0	District Office S:	
POD No:	79774	Surv Map:	
POD Rec No:	188782	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410950.5
Pcw Rcv Da:		Northing:	3947704.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	03/22/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579200.0
Static Lev:	0	Y:	1698900.0
Tract Nbr:		Point Y:	35.66919742
Map Nbr:		Point X:	-105.98392938
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
191	WNW	0.83	4,392.83	6,746.16	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35550	Surv Map:	
POD Rec No:	39567	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	12/31/1950, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	80	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410947.0
Pcw Rcv Da:		Northing:	3947716.0
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	11/03/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66930077
Map Nbr:		Point X:	-105.98396932
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
191	WNW	0.83	4,392.83	6,746.16	WATER WELLS

License Nb:	1502	District Office S:	
POD No:	74701	Surv Map:	
POD Rec No:	161618	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/13/2001, 12:00 AM	Restrict :	0.0
Finish Date:	07/14/2001, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	08/06/2001, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	115	UTM Zone:	13
Depth of Water:	33	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410947.0
Pcw Rcv Da:		Northing:	3947716.0

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/10/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66930077
Map Nbr:		Point X:	-105.98396932
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
191	WNW	0.83	4,392.83	6,746.16	WATER WELLS

License Nb:	227	District Office S:	
POD No:	35292	Surv Map:	
POD Rec No:	35766	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/31/1980, 12:00 AM	Restrict :	0.0
Finish Date:	11/04/1980, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	11/07/1980, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	70	UTM Zone:	13
Depth of Water:	20	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410947.0

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3947716.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/01/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66930077
Map Nbr:		Point X:	-105.98396932
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
191	WNW	0.83	4,392.83	6,746.16	WATER WELLS

License Nb:	0	District Office S:	
POD No:	35551	Surv Map:	
POD Rec No:	18078	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	12/31/1950, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	80	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	410947.0
Pcw Rcv Da:		Northing:	3947716.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/03/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66930077
Map Nbr:		Point X:	-105.98396932
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
192	E	0.84	4,415.97	6,938.53	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31248	Surv Map:	
POD Rec No:	8591	Other Loc:	102 La Placita Cir.
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 4 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413632.9
Pcw Rcv Da:		Northing:	3947213.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/18/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Mateo Heights	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	413632.9
Static Lev:	0	Y:	3947213.0
Tract Nbr:		Point Y:	35.66500498
Map Nbr:		Point X:	-105.9542419
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1-053-097-315-437		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
193	SSW	0.84	4,415.92	6,787.69	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289862	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD61	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411871.1
Pcw Rcv Da:		Northing:	3946053.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	15.84
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.88
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6543997
Map Nbr:		Point X:	-105.97357811
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
194	NW	0.84	4,421.84	6,761.40	WATER WELLS

License Nb:	622	District Office S:	
POD No:	44642	Surv Map:	
POD Rec No:	41405	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 TJ1 SF
Start Date:	04/17/1988, 12:00 AM	Restrict :	0.0
Finish Date:	04/18/1988, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	05/04/1988, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	UN
Depth of Well:	170	UTM Zone:	13
Depth of Water:	95	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411478.6
Pcw Rcv Da:		Northing:	3948490.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/17/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411478.6
Static Lev:	0	Y:	3948490.2
Tract Nbr:		Point Y:	35.67632813
Map Nbr:		Point X:	-105.97818147
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
195	NW	0.84	4,440.28	6,754.01	WATER WELLS

License Nb:	606	District Office S:	
POD No:	31306	Surv Map:	
POD Rec No:	9498	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/01/1979, 12:00 AM	Restrict :	0.0
Finish Date:	06/01/1979, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	06/12/1979, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	166	UTM Zone:	13
Depth of Water:	90	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	60	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411293.9
Pcw Rcv Da:		Northing:	3948340.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/17/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	580300.0
Static Lev:	0	Y:	1701000.0
Tract Nbr:		Point Y:	35.67495837
Map Nbr:		Point X:	-105.98020563
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
196	W	0.84	4,432.52	6,751.19	WATER WELLS

License Nb:	228	District Office S:	
POD No:	53601	Surv Map:	
POD Rec No:	52313	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/22/1991, 12:00 AM	Restrict :	0.0
Finish Date:	04/22/1991, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:	04/26/1991, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	240	UTM Zone:	13
Depth of Water:	110	UTM Accura:	10
Ground Water Src:	S	UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410894.9
Pcw Rcv Da:		Northing:	3947481.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/27/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1719270.0
Static Lev:	0	Y:	1698227.0
Tract Nbr:		Point Y:	35.66717932
Map Nbr:		Point X:	-105.98451892
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
197	NNW	0.84	4,448.13	6,770.09	WATER WELLS

License Nb:	622	District Office S:	
POD No:	38832	Surv Map:	
POD Rec No:	3137	Other Loc:	388 La Joya, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 1 UC SF
Start Date:	11/04/1982, 12:00 AM	Restrict :	0.0
Finish Date:	11/04/1982, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	11/19/1982, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	200	UTM Zone:	13
Depth of Water:	80	UTM Accura:	10

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411647.2
Pcw Rcv Da:		Northing:	3948602.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	La Joya	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411647.2
Static Lev:	0	Y:	3948602.6
Tract Nbr:		Point Y:	35.67735655
Map Nbr:		Point X:	-105.97633099
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052098201344000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
198	NNW	0.84	4,455.60	6,764.28	WATER WELLS

License Nb:	622	District Office S:	
POD No:	66910	Surv Map:	
POD Rec No:	4805	Other Loc:	1719 C-4 Agua Fria St
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 SF
Start Date:	04/09/1997, 12:00 AM	Restrict :	0.0
Finish Date:	04/11/1997, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	05/06/1997, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	180	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	95	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411526.0
Pcw Rcv Da:		Northing:	3948535.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/09/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411526.0
Static Lev:	0	Y:	3948535.1
Tract Nbr:		Point Y:	35.67673716
Map Nbr:		Point X:	-105.9776627
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052098155328000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
199	SSW	0.85	4,465.97	6,783.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289863	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD62	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA

Wells and Additional Sources Detail Report

Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411820.8
Pcw Rcv Da:		Northing:	3946054.4
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	15.84
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	26.88
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65439971
Map Nbr:		Point X:	-105.97413377
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
199	SSW	0.85	4,465.97	6,783.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289864	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD63	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411820.8
Pcw Rcv Da:		Northing:	3946054.4
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	15.84
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	26.88
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65439971
Map Nbr:		Point X:	-105.97413377
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
199	SSW	0.85	4,465.97	6,783.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289865	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD64	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411820.8
Pcw Rcv Da:		Northing:	3946054.4
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	15.84
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	26.88
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65439971
Map Nbr:		Point X:	-105.97413377
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
199	SSW	0.85	4,465.97	6,783.40	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289867	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD66	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411820.8
Pcw Rcv Da:		Northing:	3946054.4
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	15.84
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	26.88
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65439971
Map Nbr:		Point X:	-105.97413377
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
200	WNW	0.85	4,469.07	6,744.35	WATER WELLS

License Nb:	0	District Office S:	
POD No:	07156	Surv Map:	
POD Rec No:	194622	Other Loc:	1965 Arroyo De Las Cruces Rd
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	3

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-07156-CLW282424/194621/RG-0	Easting:	411088.7
Pcw Rcv Da:		Northing:	3948098.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/09/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1719880.0
Static Lev:	0	Y:	1700262.0
Tract Nbr:		Point Y:	35.67276544
Map Nbr:		Point X:	-105.98244615
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
201	NNE	0.85	4,499.57	6,882.35	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	313736	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD23	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/28/2019, 12:00 AM	Restrict :	0.0
Finish Date:	02/15/2019, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/2019, 12:00 AM	Range:	

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	381	UTM Zone:	13
Depth of Water:	275	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412979.1
Pcw Rcv Da:		Northing:	3948568.4
Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	40
Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	37.8
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	41.8
Well Tag:	NA	X:	0.0
Static Lev:	275	Y:	0.0
Tract Nbr:		Point Y:	35.67716668
Map Nbr:		Point X:	-105.96161118
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
201	NNE	0.85	4,499.57	6,882.35	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	313735	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD22	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/16/2019, 12:00 AM	Restrict :	0.0
Finish Date:	02/21/2019, 12:00 AM	Section:	
Plug Date:		Township:	

Wells and Additional Sources Detail Report

Log File D:	07/24/2019, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	330	UTM Zone:	13
Depth of Water:	266	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412979.1
Pcw Rcv Da:		Northing:	3948568.4
Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	40
Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	37.8
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	41.8
Well Tag:	NA	X:	0.0
Static Lev:	266	Y:	0.0
Tract Nbr:		Point Y:	35.67716668
Map Nbr:		Point X:	-105.96161118
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
202	NE	0.86	4,538.88	6,921.10	WATER WELLS

License Nb:	0	District Office S:	
POD No:	92561	Surv Map:	
POD Rec No:	259927	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413360.6
Pcw Rcv Da:		Northing:	3948244.2
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	02/24/2011, 12:00 AM	Latitude Second:	27.4
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	26.5
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67427755
Map Nbr:		Point X:	-105.95736109
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
203	NNE	0.85	4,510.99	6,878.96	WATER WELLS

License Nb:	0	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	349485	Other Loc:	Ustb-57
POD Basin:	RG	Zone :	
POD Suffix:	POD40	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412842.8
Pcw Rcv Da:		Northing:	3948645.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/19/2024, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1725612.9
Static Lev:	0	Y:	1702128.7
Tract Nbr:		Point Y:	35.67784971
Map Nbr:		Point X:	-105.9631255
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
204	WNW	0.86	4,535.01	6,748.50	WATER WELLS

License Nb:	228	District Office S:	
POD No:	30906	Surv Map:	
POD Rec No:	47012	Other Loc:	Usgs 7.5' Quad "Santa Fe, Nm"
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:	08/18/1978, 12:00 AM	Restrict :	0.0
Finish Date:	08/18/1978, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/28/1978, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	80	UTM Zone:	13
Depth of Water:	35	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	35	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410984.1
Pcw Rcv Da:		Northing:	3947947.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2015, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579300.0
Static Lev:	0	Y:	1699700.0
Tract Nbr:		Point Y:	35.67139473
Map Nbr:		Point X:	-105.9835851
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
205	SSW	0.86	4,538.84	6,788.91	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289810	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD9	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411909.4
Pcw Rcv Da:		Northing:	3946003.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	14.22
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	23.34
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65394966
Map Nbr:		Point X:	-105.97314955
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
205	SSW	0.86	4,538.84	6,788.91	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289811	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD10	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411909.4
Pcw Rcv Da:		Northing:	3946003.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	14.22
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	23.34
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65394966
Map Nbr:		Point X:	-105.97314955
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
205	SSW	0.86	4,538.84	6,788.91	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289809	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD8	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0

Wells and Additional Sources Detail Report

POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411909.4
Pcw Rcv Da:		Northing:	3946003.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	14.22
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	23.34
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65394966
Map Nbr:		Point X:	-105.97314955
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
205	SSW	0.86	4,538.84	6,788.91	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289808	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD7	BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411909.4
Pcw Rcv Da:		Northing:	3946003.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	14.22
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	23.34
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65394966
Map Nbr:		Point X:	-105.97314955
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
205	SSW	0.86	4,538.84	6,788.91	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289813	Other Loc:	
POD Basin:	RG	Zone :	

Wells and Additional Sources Detail Report

POD Suffix:	POD12	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411909.4
Pcw Rcv Da:		Northing:	3946003.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	14.22
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	23.34
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65394966
Map Nbr:		Point X:	-105.97314955
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
205	SSW	0.86	4,538.84	6,788.91	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289812	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:	POD11	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411909.4
Pcw Rcv Da:		Northing:	3946003.6
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	14.22
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	23.34
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65394966
Map Nbr:		Point X:	-105.97314955
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
206	WNW	0.87	4,596.22	6,745.58	WATER WELLS

License Nb:	0	District Office S:	
POD No:	01687	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	46451	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	01/01/1952, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	100	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:	TURBIN	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410951.0
Pcw Rcv Da:		Northing:	3947919.0
Sched Date:		Latitude Degree:	0
Use of Wel:	COM.	Latitude Minute:	0
Sys Date:	01/28/1992, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6711312
Map Nbr:		Point X:	-105.98394759
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
206	WNW	0.87	4,596.22	6,745.58	WATER WELLS

License Nb:	253	District Office S:	

Wells and Additional Sources Detail Report

POD No:	14196	Surv Map:	
POD Rec No:	67975	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2E 1 SF
Start Date:	08/01/1966, 12:00 AM	Restrict :	0.0
Finish Date:	08/04/1966, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	01/11/1967, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	47	UTM Zone:	13
Depth of Water:	19	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410951.0
Pcw Rcv Da:		Northing:	3947919.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/26/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6711312
Map Nbr:		Point X:	-105.98394759
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
206	WNW	0.87	4,596.22	6,745.58	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	228	District Office S:	
POD No:	35789	Surv Map:	
POD Rec No:	45510	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/02/1981, 12:00 AM	Restrict :	0.0
Finish Date:	03/03/1981, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	03/31/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	100	UTM Zone:	13
Depth of Water:	35	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410951.0
Pcw Rcv Da:		Northing:	3947919.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/10/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6711312
Map Nbr:		Point X:	-105.98394759
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
206	WNW	0.87	4,596.22	6,745.58	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	253	District Office S:	
POD No:	03517	Surv Map:	
POD Rec No:	26618	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/09/1959, 12:00 AM	Restrict :	0.0
Finish Date:	07/09/1959, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	10/07/1959, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	41	UTM Zone:	13
Depth of Water:	13	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410951.0
Pcw Rcv Da:		Northing:	3947919.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/04/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6711312
Map Nbr:		Point X:	-105.98394759
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
207	SSW	0.87	4,608.73	6,782.26	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	93961	Surv Map:	
POD Rec No:	283516	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	UA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411787.3
Pcw Rcv Da:		Northing:	3946020.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	04/17/2013, 12:00 AM	Latitude Second:	14.74
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	28.2
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65409471
Map Nbr:		Point X:	-105.97450013
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

208	W	0.87	4,614.78	6,741.88	WATER WELLS

License Nb:	0	District Office S:	
POD No:	09462	Surv Map:	
POD Rec No:	42505	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	33
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410844.0
Pcw Rcv Da:		Northing:	3947215.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/17/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6647749
Map Nbr:		Point X:	-105.98505176
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

208	W	0.87	4,614.78	6,741.88	WATER WELLS

License Nb:	228	District Office S:	
POD No:	01428	Surv Map:	
POD Rec No:	60986	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/14/1957, 12:00 AM	Restrict :	0.0
Finish Date:	12/18/1957, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	02/07/1958, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	233	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	410844.0
Pcw Rcv Da:		Northing:	3947215.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/16/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6647749
Map Nbr:		Point X:	-105.98505176
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
209	NE	0.88	4,661.61	6,896.68	WATER WELLS

License Nb:	214	District Office S:	
POD No:	00296	Surv Map:	
POD Rec No:	45512	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	REPAIR	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	26
Plug Date:		Township:	17N
Log File D:	09/25/1967, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	307	UTM Zone:	13
Depth of Water:	201	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413166.0
Pcw Rcv Da:		Northing:	3948497.0
Sched Date:		Latitude Degree:	0
Use of Wel:	IRR	Latitude Minute:	0
Sys Date:	01/14/1992, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67653947
Map Nbr:		Point X:	-105.95953842
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
210	SSW	0.88	4,644.47	6,787.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289871	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD70	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945981.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.5
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65375037
Map Nbr:		Point X:	-105.97360005
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
210	SSW	0.88	4,644.47	6,787.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289869	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD68	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945982.2
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.51
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65375307
Map Nbr:		Point X:	-105.97360009
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant :

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
210	SSW	0.88	4,644.47	6,787.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289872	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD71	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945981.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.5
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65375037
Map Nbr:		Point X:	-105.97360005
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
210	SSW	0.88	4,644.47	6,787.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289868	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD67	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945982.2
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.51
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65375307
Map Nbr:		Point X:	-105.97360009
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
210	SSW	0.88	4,644.47	6,787.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289870	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD69	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945981.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.5
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65375037
Map Nbr:		Point X:	-105.97360005

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
210	SSW	0.88	4,644.47	6,787.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289873	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD72	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945981.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.5
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65375037

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.97360005
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
211	W	0.88	4,640.35	6,746.47	WATER WELLS

License Nb:	0	District Office S:	
POD No:	09632	Surv Map:	
POD Rec No:	63318	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/26/1963, 12:00 AM	Restrict :	0.0
Finish Date:	08/28/1963, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	10/22/1963, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	47	UTM Zone:	13
Depth of Water:	8	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7000.0	County:	Unknown
Ref :		Easting:	410848.0
Pcw Rcv Da:		Northing:	3947617.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	07/06/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.66839934
Map Nbr:		Point X:	-105.98505209
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
211	W	0.88	4,640.35	6,746.47	WATER WELLS

License Nb:	0	District Office S:	
POD No:	80898	Surv Map:	
POD Rec No:	194224	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410848.0
Pcw Rcv Da:		Northing:	3947617.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/11/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0

Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66839934
Map Nbr:		Point X:	-105.98505209
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
211	W	0.88	4,640.35	6,746.47	WATER WELLS

License Nb:	0	District Office S:	
POD No:	01169	Surv Map:	
POD Rec No:	31900	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/01/1947, 12:00 AM	Restrict :	0.0
Finish Date:		Section:	28
Plug Date:		Township:	17N
Log File D:	07/22/1957, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	60	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410848.0
Pcw Rcv Da:		Northing:	3947617.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/08/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66839934
Map Nbr:		Point X:	-105.98505209
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289853	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD52	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289846	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD45	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289842	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD41	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289852	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD51	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39

Wells and Additional Sources Detail Report

Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289859	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD58	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289860	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD59	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289854	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD53	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289858	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD57	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289845	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD44	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289848	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD47	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289861	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD60	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289857	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD56	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Wells and Additional Sources Detail Report

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289841	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD40	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289843	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD42	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289844	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD43	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289850	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD49	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA

Wells and Additional Sources Detail Report

Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289849	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD48	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289856	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD55	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289847	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD46	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289840	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD39	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289851	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD50	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289839	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD38	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	

Wells and Additional Sources Detail Report

Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
212	SSW	0.88	4,661.95	6,787.43	WATER WELLS

License Nb:	0	District Office S:	
POD No:	94602	Surv Map:	
POD Rec No:	289855	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD54	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411868.4
Pcw Rcv Da:		Northing:	3945976.3
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	39
Sys Date:	06/10/2014, 12:00 AM	Latitude Second:	13.32
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	58
Ditch Name:		Longitude Second:	24.96
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65369988
Map Nbr:		Point X:	-105.97359944
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
213	NE	0.89	4,705.35	6,929.48	WATER WELLS

License Nb:	0	District Office S:	
POD No:	36944	Surv Map:	
POD Rec No:	51629	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	9 2 SF
Start Date:		Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:		Section:	26
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413459.0
Pcw Rcv Da:		Northing:	3948200.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/01/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Pacheco Addition	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67388772
Map Nbr:		Point X:	-105.95626915
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
214	N	0.89	4,674.47	6,846.81	WATER WELLS

License Nb:	227	District Office S:	
POD No:	11155	Surv Map:	
POD Rec No:	11927	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	REPAR	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:	07/08/1971, 12:00 AM	Restrict :	0.0
Finish Date:	07/09/1971, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	07/21/1971, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	247	UTM Zone:	13
Depth of Water:	185	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412465.0
Pcw Rcv Da:		Northing:	3948808.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	08/04/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6792812
Map Nbr:		Point X:	-105.96731751
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
214	N	0.89	4,674.47	6,846.81	WATER WELLS

License Nb:	228	District Office S:	
POD No:	11155	Surv Map:	
POD Rec No:	49017	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:	05/23/1964, 12:00 AM	Restrict :	0.0
Finish Date:	06/07/1964, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	08/05/1964, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	200	UTM Zone:	13
Depth of Water:	140	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	412465.0
Pcw Rcv Da:		Northing:	3948808.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	11/07/2005, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6792812
Map Nbr:		Point X:	-105.96731751
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
215	W	0.89	4,688.05	6,742.61	WATER WELLS

License Nb:	622	District Office S:	
POD No:	81541	Surv Map:	
POD Rec No:	197319	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/26/2004, 12:00 AM	Restrict :	0.0
Finish Date:	01/29/2004, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	01/30/2004, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	440	UTM Zone:	13
Depth of Water:	252	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	30	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410812.5
Pcw Rcv Da:		Northing:	3947348.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/30/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	578762.0
Static Lev:	0	Y:	1697726.0
Tract Nbr:	A-1C	Point Y:	35.66597557
Map Nbr:		Point X:	-105.98541453
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
216	NNE	0.89	4,702.46	6,885.11	WATER WELLS

License Nb:	0	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	335483	Other Loc:	Ustb-45
POD Basin:	RG	Zone :	
POD Suffix:	POD27	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0

Wells and Additional Sources Detail Report

POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413022.6
Pcw Rcv Da:		Northing:	3948615.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/16/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1726204.3
Static Lev:	0	Y:	1702036.8
Tract Nbr:		Point Y:	35.67759242
Map Nbr:		Point X:	-105.96113561
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
217	NW	0.89	4,705.31	6,747.31	WATER WELLS

License Nb:	253	District Office S:	
POD No:	12274	Surv Map:	
POD Rec No:	31820	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	02/25/1965, 12:00 AM	Restrict :	0.0
Finish Date:	03/09/1965, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	08/30/1965, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	64	UTM Zone:	13
Depth of Water:	28	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411258.0
Pcw Rcv Da:		Northing:	3948418.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	09/28/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67565741
Map Nbr:		Point X:	-105.98061087
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
218	NW	0.89	4,715.80	6,742.25	WATER WELLS

License Nb:	0	District Office S:	
POD No:	32525	Surv Map:	
POD Rec No:	16369	Other Loc:	
POD Basin:	RG	Zone :	

Wells and Additional Sources Detail Report

POD Suffix:	CLW	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411157.0
Pcw Rcv Da:		Northing:	3948317.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/13/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67473779
Map Nbr:		Point X:	-105.98171563
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
218	NW	0.89	4,715.80	6,742.25	WATER WELLS

License Nb:	0	District Office S:	
POD No:	32525	Surv Map:	
POD Rec No:	66191	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:	CLW2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	150	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411157.0
Pcw Rcv Da:		Northing:	3948317.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/13/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	La Era	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:	A	Point Y:	35.67473779
Map Nbr:		Point X:	-105.98171563
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
218	NW	0.89	4,715.80	6,742.25	WATER WELLS

License Nb:	1590	District Office S:	
POD No:	32525	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	3563	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/25/2004, 12:00 AM	Restrict :	0.0
Finish Date:	10/25/2004, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	11/05/2004, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	200	UTM Zone:	13
Depth of Water:	84	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	80	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411157.0
Pcw Rcv Da:	11/04/2004, 12:00 AM	Northing:	3948317.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/03/2005, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67473779
Map Nbr:		Point X:	-105.98171563
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
218	NW	0.89	4,715.80	6,742.25	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	62096	Surv Map:	
POD Rec No:	39923	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TB SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	150	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	7.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411157.0
Pcw Rcv Da:		Northing:	3948317.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/13/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	La Era	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67473779
Map Nbr:		Point X:	-105.98171563
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
219	N	0.89	4,716.25	6,855.05	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	214	District Office S:	
POD No:	16356	Surv Map:	
POD Rec No:	59074	Other Loc:	1412 Agua Fria
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TA1A SF
Start Date:	02/05/1969, 12:00 AM	Restrict :	0.0
Finish Date:	02/19/1969, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	02/28/1969, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	312	UTM Zone:	13
Depth of Water:	163	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412540.1
Pcw Rcv Da:		Northing:	3948808.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/09/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1724613.0
Static Lev:	0	Y:	1702650.0
Tract Nbr:		Point Y:	35.67928967
Map Nbr:		Point X:	-105.96648773
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Near Corner Of Agua Fria & Hickox Street.		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
221	NNE	0.90	4,754.03	6,886.05	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	311999	Other Loc:	Ustb-22
POD Basin:	RG	Zone :	
POD Suffix:	POD5	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/17/2015, 12:00 AM	Restrict :	0.0
Finish Date:	05/18/2018, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	06/15/2018, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413052.1
Pcw Rcv Da:		Northing:	3948614.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/05/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1726300.9
Static Lev:	267	Y:	1702034.5
Tract Nbr:		Point Y:	35.67758511
Map Nbr:		Point X:	-105.96080954
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
222	WNW	0.90	4,742.61	6,742.13	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	0	District Office S:	
POD No:	05840	Surv Map:	SANTA FE
POD Rec No:	47954	Other Loc:	Tract 366 Map 23
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	02/01/1945, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	50	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:	JET	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410961.0
Pcw Rcv Da:		Northing:	3948045.7
Sched Date:		Latitude Degree:	0
Use of Wel:	IRR	Latitude Minute:	0
Sys Date:	11/16/2006, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579220.0
Static Lev:	0	Y:	1700020.0
Tract Nbr:	365	Point Y:	35.67227432
Map Nbr:	23	Point X:	-105.98385113
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

222	WNW	0.90	4,742.61	6,742.13	WATER WELLS

License Nb:	253	District Office S:	
POD No:	05840	Surv Map:	
POD Rec No:	13595	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:	REPAIR	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/27/1961, 12:00 AM	Restrict :	0.0
Finish Date:	06/27/1961, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	47	UTM Zone:	13
Depth of Water:	17	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:	JET	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410961.0
Pcw Rcv Da:		Northing:	3948045.7
Sched Date:		Latitude Degree:	0
Use of Wel:	IRR	Latitude Minute:	0
Sys Date:	09/09/1991, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579220.0
Static Lev:	0	Y:	1700020.0
Tract Nbr:		Point Y:	35.67227432
Map Nbr:		Point X:	-105.98385113
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

223	NNE	0.90	4,758.79	6,886.05	WATER WELLS

License Nb:	0	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	335487	Other Loc:	Utsb-54
POD Basin:	RG	Zone :	
POD Suffix:	POD31	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413055.2
Pcw Rcv Da:		Northing:	3948614.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/16/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1726311.3
Static Lev:	0	Y:	1702036.8
Tract Nbr:		Point Y:	35.67759169
Map Nbr:		Point X:	-105.96077536
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
223	NNE	0.90	4,758.79	6,886.05	WATER WELLS

License Nb:	0	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	335486	Other Loc:	Utsb-53
POD Basin:	RG	Zone :	
POD Suffix:	POD30	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413055.2
Pcw Rcv Da:		Northing:	3948614.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/16/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1726311.3
Static Lev:	0	Y:	1702036.8
Tract Nbr:		Point Y:	35.67759169
Map Nbr:		Point X:	-105.96077536
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
224	SSE	0.90	4,741.53	6,850.49	WATER WELLS

License Nb:	228	District Office S:	
POD No:	40807	Surv Map:	
POD Rec No:	18058	Other Loc:	2077 Camino Lado, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/11/1984, 12:00 AM	Restrict :	0.0
Finish Date:	10/17/1984, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	11/26/1984, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	360	UTM Zone:	13
Depth of Water:	260	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412604.2
Pcw Rcv Da:		Northing:	3945931.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/06/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	584700.0
Static Lev:	0	Y:	1693150.0
Tract Nbr:		Point Y:	35.65335783
Map Nbr:		Point X:	-105.96546711
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
225	NNE	0.90	4,774.26	6,887.19	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	311998	Other Loc:	Ustb-21
POD Basin:	RG	Zone :	
POD Suffix:	POD4	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/17/2018, 12:00 AM	Restrict :	0.0
Finish Date:	05/18/2018, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	06/15/2018, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	300	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413056.2
Pcw Rcv Da:		Northing:	3948618.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/05/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1726314.2
Static Lev:	268	Y:	1702050.1
Tract Nbr:		Point Y:	35.67762784
Map Nbr:		Point X:	-105.96076475
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant :

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
226	WNW	0.90	4,756.64	6,739.56	WATER WELLS

License Nb:	622	District Office S:	
POD No:	14291	Surv Map:	
POD Rec No:	197472	Other Loc:	2404 Agua Fria St
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TC2 SF
Start Date:	12/15/2003, 12:00 AM	Restrict :	0.0
Finish Date:	12/17/2003, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	01/23/2004, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	3
CFS Start:		Quarter 16th:	3
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	160	UTM Zone:	13
Depth of Water:	52	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-14291-CLW289395/39933/RG-14	Easting:	410840.8
Pcw Rcv Da:		Northing:	3947747.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/29/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	410840.8
Static Lev:	0	Y:	3947747.3
Tract Nbr:		Point Y:	35.66957335
Map Nbr:		Point X:	-105.98514607
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal: Parcel Number 1051098464070000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
228	NE	0.92	4,833.52	6,896.26	WATER WELLS

License Nb:	0	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	335635	Other Loc:	Ustb-52
POD Basin:	RG	Zone :	
POD Suffix:	POD32	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413169.3
Pcw Rcv Da:		Northing:	3948561.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/29/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1726687.8
Static Lev:	0	Y:	1701866.5
Tract Nbr:		Point Y:	35.67712034
Map Nbr:		Point X:	-105.95950891
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
229	WNW	0.91	4,812.11	6,741.84	WATER WELLS

License Nb:	228	District Office S:	
POD No:	30907	Surv Map:	
POD Rec No:	30372	Other Loc:	Usgs 7.5 Quad "Santa Fe, Nm"
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/18/1978, 12:00 AM	Restrict :	0.0
Finish Date:	08/18/1978, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	08/28/1978, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	80	UTM Zone:	13
Depth of Water:	20	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	40	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410892.7
Pcw Rcv Da:		Northing:	3947949.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2015, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579000.0
Static Lev:	0	Y:	1699700.0
Tract Nbr:		Point Y:	35.67139639
Map Nbr:		Point X:	-105.98459502

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
230	NNE	0.92	4,832.84	6,888.34	WATER WELLS

License Nb:	0	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	322431	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD26	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413057.2
Pcw Rcv Da:		Northing:	3948639.7
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	07/31/2019, 12:00 AM	Latitude Second:	40.14
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	38.72
Well Tag:	NA	X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67781635

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.96075596
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
231	NNE	0.92	4,842.38	6,887.46	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	313732	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD19	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	12/15/2018, 12:00 AM	Restrict :	0.0
Finish Date:	12/21/2018, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/2019, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	285	UTM Zone:	13
Depth of Water:	271	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413084.8
Pcw Rcv Da:		Northing:	3948625.6
Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	40
Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	39.69
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	37.62
Well Tag:	NA	X:	0.0
Static Lev:	271	Y:	0.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.67769167
Map Nbr:		Point X:	-105.96044948
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
231	NNE	0.92	4,842.38	6,887.46	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	313731	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD18	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/06/2019, 12:00 AM	Restrict :	0.0
Finish Date:	01/12/2019, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/2019, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	290	UTM Zone:	13
Depth of Water:	269	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413084.8
Pcw Rcv Da:		Northing:	3948625.6
Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	40
Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	39.69
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	37.62
Well Tag:	NA	X:	0.0

Static Lev:	269	Y:	0.0
Tract Nbr:		Point Y:	35.67769167
Map Nbr:		Point X:	-105.96044948
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
232	NNE	0.92	4,854.23	6,888.12	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	311995	Other Loc:	Ustb-18
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/17/2018, 12:00 AM	Restrict :	0.0
Finish Date:	05/18/2018, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	06/15/2018, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	317	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413080.9
Pcw Rcv Da:		Northing:	3948632.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/05/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:	NA	X:	1726394.9
Static Lev:	283	Y:	1702094.2
Tract Nbr:		Point Y:	35.67774902
Map Nbr:		Point X:	-105.96049326
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
233	WNW	0.92	4,851.25	6,742.26	WATER WELLS

License Nb:	0	District Office S:	
POD No:	05841	Surv Map:	
POD Rec No:	27630	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	02/01/1945, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	50	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:	JET	XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410921.3
Pcw Rcv Da:		Northing:	3948040.1
Sched Date:		Latitude Degree:	0
Use of Wel:	DAIRY/IRR	Latitude Minute:	0
Sys Date:	10/31/2006, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579090.0
Static Lev:	0	Y:	1700000.0
Tract Nbr:		Point Y:	35.67222025
Map Nbr:		Point X:	-105.98428913
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
234	NE	0.92	4,869.48	6,889.22	WATER WELLS

License Nb:	0	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	335484	Other Loc:	Utsb-48
POD Basin:	RG	Zone :	
POD Suffix:	POD28	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413114.9
Pcw Rcv Da:		Northing:	3948614.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/16/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1726507.1
Static Lev:	0	Y:	1702039.7
Tract Nbr:		Point Y:	35.67759786
Map Nbr:		Point X:	-105.96011575
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
234	NE	0.92	4,869.48	6,889.22	WATER WELLS

License Nb:	0	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	335485	Other Loc:	Utsb-49
POD Basin:	RG	Zone :	
POD Suffix:	POD29	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413114.9
Pcw Rcv Da:		Northing:	3948614.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/16/2022, 12:00 AM	Latitude Second:	0.0

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1726507.1
Static Lev:	0	Y:	1702039.7
Tract Nbr:		Point Y:	35.67759786
Map Nbr:		Point X:	-105.96011575
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
235	WNW	0.92	4,868.51	6,736.49	WATER WELLS

License Nb:	0	District Office S:	
POD No:	83202	Surv Map:	
POD Rec No:	204248	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410839.8
Pcw Rcv Da:		Northing:	3947861.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0

Wells and Additional Sources Detail Report

Sys Date:	07/23/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	578830.0
Static Lev:	0	Y:	1699410.0
Tract Nbr:		Point Y:	35.67060098
Map Nbr:		Point X:	-105.98516974
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
236	NNE	0.93	4,888.20	6,888.07	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	313729	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD16	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/23/2019, 12:00 AM	Restrict :	0.0
Finish Date:	01/28/2019, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/2019, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	276	UTM Zone:	13
Depth of Water:	270	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413084.7
Pcw Rcv Da:		Northing:	3948641.6
Sched Date:		Latitude Degree:	35

Wells and Additional Sources Detail Report

Use of Wel:	EXPL	Latitude Minute:	40
Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	40.21
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	37.63
Well Tag:	NA	X:	0.0
Static Lev:	270	Y:	0.0
Tract Nbr:		Point Y:	35.6778359
Map Nbr:		Point X:	-105.96045231
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
236	NNE	0.93	4,888.20	6,888.07	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	313730	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD17	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/13/2019, 12:00 AM	Restrict :	0.0
Finish Date:	01/23/2019, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/2019, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	290	UTM Zone:	13
Depth of Water:	268	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413084.7
Pcw Rcv Da:		Northing:	3948641.6

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	40
Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	40.21
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	37.63
Well Tag:	NA	X:	0.0
Static Lev:	268	Y:	0.0
Tract Nbr:		Point Y:	35.6778359
Map Nbr:		Point X:	-105.96045231
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
238	N	0.92	4,877.46	6,818.21	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34710	Surv Map:	
POD Rec No:	333583	Other Loc:	1703 Callejon Emilia
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	13 11 AE SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412324.7

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3948882.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/12/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Barro Lacanada	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1723903.0
Static Lev:	0	Y:	1702883.0
Tract Nbr:		Point Y:	35.67993585
Map Nbr:		Point X:	-105.96887578
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
239	WNW	0.93	4,887.64	6,741.37	WATER WELLS

License Nb:	0	District Office S:	
POD No:	18477	Surv Map:	
POD Rec No:	35210	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	01/01/1955, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	88	UTM Zone:	13
Depth of Water:	33	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:	SUBMER	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	410951.0
Pcw Rcv Da:		Northing:	3948119.0
Sched Date:		Latitude Degree:	0
Use of Wel:	IRR	Latitude Minute:	0
Sys Date:	08/26/1991, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67293422
Map Nbr:		Point X:	-105.98396972
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
239	WNW	0.93	4,887.64	6,741.37	WATER WELLS

License Nb:	0	District Office S:	
POD No:	18478	Surv Map:	
POD Rec No:	329702	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410951.0
Pcw Rcv Da:		Northing:	3948119.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/30/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67293422
Map Nbr:		Point X:	-105.98396972
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
240	NNE	0.93	4,914.30	6,889.11	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	315719	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD25	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	PLG	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:	01/18/2019, 12:00 AM	Township:	
Log File D:	07/24/2019, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	0	UTM Zone:	13
Depth of Water:	295	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413085.5
Pcw Rcv Da:		Northing:	3948650.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	40.51
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	37.6
Well Tag:	NA	X:	0.0
Static Lev:	268	Y:	0.0
Tract Nbr:		Point Y:	35.67791981
Map Nbr:		Point X:	-105.96044448
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
241	NNE	0.93	4,920.87	6,889.11	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	313737	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD24	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/07/2019, 12:00 AM	Restrict :	0.0
Finish Date:	03/13/2019, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/2019, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	346	UTM Zone:	13
Depth of Water:	306	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413091.3
Pcw Rcv Da:		Northing:	3948649.9
Sched Date:		Latitude Degree:	35
Use of Wel:		Latitude Minute:	40
Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	40.48
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	37.37
Well Tag:	NA	X:	0.0
Static Lev:	306	Y:	0.0
Tract Nbr:		Point Y:	35.67791131
Map Nbr:		Point X:	-105.96038029
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
242	W	0.93	4,926.48	6,744.20	WATER WELLS

License Nb:	228	District Office S:	
POD No:	17516	Surv Map:	
POD Rec No:	11421	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	05/09/1970, 12:00 AM	Restrict :	0.0
Finish Date:	05/12/1970, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	07/10/1970, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	130	UTM Zone:	13
Depth of Water:	35	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	410747.0
Pcw Rcv Da:		Northing:	3947516.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	12/07/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66747968
Map Nbr:		Point X:	-105.98615671
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
243	N	0.93	4,926.58	6,803.10	WATER WELLS

License Nb:	228	District Office S:	
POD No:	36892	Surv Map:	
POD Rec No:	39599	Other Loc:	1719 Callejon Cordelia, Sf
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 7 SF
Start Date:	08/25/1981, 12:00 AM	Restrict :	0.0
Finish Date:	08/26/1981, 12:00 AM	Section:	27
Plug Date:		Township:	17N
Log File D:	09/16/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	255	UTM Zone:	13
Depth of Water:	170	UTM Accura:	
Ground Water Src:	S	UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412065.1
Pcw Rcv Da:		Northing:	3948885.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/17/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Barrio La Canada	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	412065.1
Static Lev:	0	Y:	3948885.0
Tract Nbr:		Point Y:	35.67993978
Map Nbr:		Point X:	-105.9717445
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1052098331447000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
244	WSW	0.94	4,953.36	6,747.48	WATER WELLS

License Nb:	228	District Office S:	
POD No:	03397	Surv Map:	
POD Rec No:	60094	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	06/08/1959, 12:00 AM	Restrict :	0.0
Finish Date:	06/22/1959, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	07/07/1959, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	223	UTM Zone:	13
Depth of Water:	0	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	410840.0
Pcw Rcv Da:		Northing:	3946813.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/03/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66115046
Map Nbr:		Point X:	-105.98505143
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
244	WSW	0.94	4,953.36	6,747.48	WATER WELLS

License Nb:	253	District Office S:	
POD No:	07200	Surv Map:	
POD Rec No:	6722	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/16/1962, 12:00 AM	Restrict :	0.0
Finish Date:	04/17/1962, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	02/19/1963, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	235	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	218	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410840.0
Pcw Rcv Da:		Northing:	3946813.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	09/24/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66115046
Map Nbr:		Point X:	-105.98505143
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
245	ESE	0.94	4,944.14	6,953.24	WATER WELLS

License Nb:	214	District Office S:	
POD No:	35407	Surv Map:	
POD Rec No:	60902	Other Loc:	129 Mateo Circle, Santa Fe
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 1 SF
Start Date:	12/09/1980, 12:00 AM	Restrict :	0.0
Finish Date:	12/11/1980, 12:00 AM	Section:	35
Plug Date:		Township:	17N
Log File D:	01/07/1981, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA

Wells and Additional Sources Detail Report

Depth of Well:	336	UTM Zone:	13
Depth of Water:	240	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413764.5
Pcw Rcv Da:		Northing:	3947023.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/05/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Mateo Heights	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	413764.5
Static Lev:	0	Y:	3947023.5
Tract Nbr:		Point Y:	35.66330811
Map Nbr:		Point X:	-105.95276778
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1053097360371000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
246	NE	0.94	4,977.47	6,892.25	WATER WELLS

License Nb:	0	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	336371	Other Loc:	Ustb-47
POD Basin:	RG	Zone :	
POD Suffix:	POD35	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413137.1
Pcw Rcv Da:		Northing:	3948638.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/19/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1726578.9
Static Lev:	0	Y:	1702119.0
Tract Nbr:		Point Y:	35.67781527
Map Nbr:		Point X:	-105.95987304
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
246	NE	0.94	4,977.47	6,892.25	WATER WELLS

License Nb:	0	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	336370	Other Loc:	Ustb-46
POD Basin:	RG	Zone :	
POD Suffix:	POD34	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413137.1
Pcw Rcv Da:		Northing:	3948638.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/19/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1726578.9
Static Lev:	0	Y:	1702119.0
Tract Nbr:		Point Y:	35.67781527
Map Nbr:		Point X:	-105.95987304
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
247	NNE	0.94	4,978.49	6,890.36	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	311996	Other Loc:	Ustb-19
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/11/2018, 12:00 AM	Restrict :	0.0
Finish Date:	05/18/2018, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	06/15/2018, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	

CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	266	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413103.0
Pcw Rcv Da:		Northing:	3948663.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/05/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1726466.1
Static Lev:	253	Y:	1702197.3
Tract Nbr:		Point Y:	35.67803134
Map Nbr:		Point X:	-105.96025244
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
248	W	0.94	4,968.29	6,743.18	WATER WELLS

License Nb:	0	District Office S:	
POD No:	A1503	Surv Map:	
POD Rec No:	343013	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD1	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 NA T-A2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410740.0
Pcw Rcv Da:		Northing:	3947570.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/19/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1718758.0
Static Lev:	0	Y:	1698512.1
Tract Nbr:		Point Y:	35.66796676
Map Nbr:		Point X:	-105.98624004
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
249	ESE	0.95	4,990.21	6,954.07	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34375	Surv Map:	
POD Rec No:	70667	Other Loc:	129 Mateo Circle N
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 1 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413777.2
Pcw Rcv Da:		Northing:	3947015.7
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/29/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Mateo Heights	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1728747.0
Static Lev:	0	Y:	1696820.0
Tract Nbr:		Point Y:	35.6632389
Map Nbr:		Point X:	-105.95262665
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
250	WNW	0.95	4,998.46	6,732.45	WATER WELLS

License Nb:	653	District Office S:	
POD No:	27189	Surv Map:	
POD Rec No:	25408	Other Loc:	1422 Agua Fria St
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	12 1 NA SF
Start Date:	04/29/1976, 12:00 AM	Restrict :	0.0
Finish Date:	05/03/1976, 12:00 AM	Section:	28
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:	05/20/1977, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	40	UTM Zone:	13
Depth of Water:	15	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410787.2
Pcw Rcv Da:		Northing:	3947827.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	03/15/2007, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	1718902.0
Static Lev:	0	Y:	1699359.0
Tract Nbr:	NA	Point Y:	35.67029242
Map Nbr:	NA	Point X:	-105.98574713
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
251	NNE	0.95	5,037.05	6,892.21	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	311997	Other Loc:	Ustb-20
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/06/2018, 12:00 AM	Restrict :	0.0
Finish Date:	05/18/2018, 12:00 AM	Section:	

Wells and Additional Sources Detail Report

Plug Date:		Township:	
Log File D:	06/15/2018, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	316	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413134.4
Pcw Rcv Da:		Northing:	3948663.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/05/2018, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1726568.9
Static Lev:	282	Y:	1702199.0
Tract Nbr:		Point Y:	35.67803501
Map Nbr:		Point X:	-105.95990551
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
252	WSW	0.95	5,040.66	6,751.47	WATER WELLS

License Nb:	0	District Office S:	
POD No:	41552	Surv Map:	
POD Rec No:	9522	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	12/31/1954, 12:00 AM	Section:	34
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410846.7
Pcw Rcv Da:		Northing:	3946730.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/08/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	578900.0
Static Lev:	0	Y:	1695700.0
Tract Nbr:		Point Y:	35.66040822
Map Nbr:		Point X:	-105.98496829
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
253	WNW	0.95	5,025.88	6,732.81	WATER WELLS

License Nb:	214	District Office S:	
POD No:	10296	Surv Map:	
POD Rec No:	53445	Other Loc:	W 1/2
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	

Wells and Additional Sources Detail Report

Start Date:	01/27/1964, 12:00 AM	Restrict :	0.0
Finish Date:	01/29/1964, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	03/06/1964, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	55	UTM Zone:	13
Depth of Water:	30	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410852.0
Pcw Rcv Da:		Northing:	3948020.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	08/12/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67203278
Map Nbr:		Point X:	-105.98505254
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
253	WNW	0.95	5,025.88	6,732.81	WATER WELLS

License Nb:	214	District Office S:	
POD No:	21470	Surv Map:	
POD Rec No:	68360	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	

Wells and Additional Sources Detail Report

POD Name:		Subdiv Loc:	
Start Date:	07/13/1972, 12:00 AM	Restrict :	0.0
Finish Date:	07/14/1972, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	07/17/1972, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	92	UTM Zone:	13
Depth of Water:	21	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410852.0
Pcw Rcv Da:		Northing:	3948020.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/20/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67203278
Map Nbr:		Point X:	-105.98505254
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
254	WNW	0.95	5,030.07	6,732.33	WATER WELLS

License Nb:	227	District Office S:	
POD No:	14358	Surv Map:	
POD Rec No:	18771	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	

Wells and Additional Sources Detail Report

Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/12/1978, 12:00 AM	Restrict :	0.0
Finish Date:	10/12/1978, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	10/20/1978, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	300	UTM Zone:	13
Depth of Water:	220	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	8	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410747.0
Pcw Rcv Da:		Northing:	3947716.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/19/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6692827
Map Nbr:		Point X:	-105.98617888
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
254	WNW	0.95	5,030.07	6,732.33	WATER WELLS

License Nb:	227	District Office S:	
POD No:	08110	Surv Map:	
POD Rec No:	202910	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD3	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100

Wells and Additional Sources Detail Report

POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/25/1996, 12:00 AM	Restrict :	0.0
Finish Date:	08/27/1996, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	12/31/1997, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	85	UTM Zone:	13
Depth of Water:	34	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :	RG-08110-CLW305068/14619/RG-08	Easting:	410747.0
Pcw Rcv Da:		Northing:	3947716.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/10/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6692827
Map Nbr:		Point X:	-105.98617888
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
254	WNW	0.95	5,030.07	6,732.33	WATER WELLS

License Nb:	122	District Office S:	
POD No:	08110	Surv Map:	
POD Rec No:	14619	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	

Wells and Additional Sources Detail Report

Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410747.0
Pcw Rcv Da:		Northing:	3947716.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/10/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6692827
Map Nbr:		Point X:	-105.98617888
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
254	WNW	0.95	5,030.07	6,732.33	WATER WELLS

License Nb:	214	District Office S:	
POD No:	13239	Surv Map:	
POD Rec No:	31733	Other Loc:	
POD Basin:	RG	Zone :	

Wells and Additional Sources Detail Report

POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/06/1965, 12:00 AM	Restrict :	0.0
Finish Date:	10/07/1965, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	02/11/1966, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	43	UTM Zone:	13
Depth of Water:	12	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410747.0
Pcw Rcv Da:		Northing:	3947716.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/14/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6692827
Map Nbr:		Point X:	-105.98617888
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
254	WNW	0.95	5,030.07	6,732.33	WATER WELLS

License Nb:	214	District Office S:	
POD No:	12338	Surv Map:	
POD Rec No:	48187	Other Loc:	

Wells and Additional Sources Detail Report

POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/22/1965, 12:00 AM	Restrict :	0.0
Finish Date:	03/22/1965, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	07/20/1965, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	53	UTM Zone:	13
Depth of Water:	6	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410747.0
Pcw Rcv Da:		Northing:	3947716.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	09/29/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6692827
Map Nbr:		Point X:	-105.98617888
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
254	WNW	0.95	5,030.07	6,732.33	WATER WELLS

License Nb:	228	District Office S:	
POD No:	15377	Surv Map:	

Wells and Additional Sources Detail Report

POD Rec No:	55854	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	12/12/1967, 12:00 AM	Restrict :	0.0
Finish Date:	12/14/1967, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	01/10/1968, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	52	UTM Zone:	13
Depth of Water:	18	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	410747.0
Pcw Rcv Da:		Northing:	3947716.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/16/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6692827
Map Nbr:		Point X:	-105.98617888
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
254	WNW	0.95	5,030.07	6,732.33	WATER WELLS

License Nb:	0	District Office S:	

Wells and Additional Sources Detail Report

POD No:	36666	Surv Map:	
POD Rec No:	59793	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	12/31/1953, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	50	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410747.0
Pcw Rcv Da:		Northing:	3947716.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/18/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6692827
Map Nbr:		Point X:	-105.98617888
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
254	WNW	0.95	5,030.07	6,732.33	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	228	District Office S:	
POD No:	36666	Surv Map:	
POD Rec No:	334255	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/01/1989, 12:00 AM	Restrict :	0.0
Finish Date:	08/01/1989, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	08/27/1990, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	100	UTM Zone:	13
Depth of Water:	30	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	50	Lat Lon SO:	
Casing Size:	5.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410747.0
Pcw Rcv Da:		Northing:	3947716.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/19/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6692827
Map Nbr:		Point X:	-105.98617888
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
254	WNW	0.95	5,030.07	6,732.33	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	228	District Office S:	
POD No:	14311	Surv Map:	
POD Rec No:	65759	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	28
Plug Date:		Township:	17N
Log File D:	10/09/1967, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	60	UTM Zone:	13
Depth of Water:	25	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	410747.0
Pcw Rcv Da:		Northing:	3947716.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/19/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6692827
Map Nbr:		Point X:	-105.98617888
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
254	WNW	0.95	5,030.07	6,732.33	WATER WELLS

Wells and Additional Sources Detail Report

License Nb:	214	District Office S:	
POD No:	15887	Surv Map:	
POD Rec No:	49448	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/02/1968, 12:00 AM	Restrict :	0.0
Finish Date:	07/08/1968, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	10/17/1968, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	93	UTM Zone:	13
Depth of Water:	45	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410747.0
Pcw Rcv Da:		Northing:	3947716.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/02/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6692827
Map Nbr:		Point X:	-105.98617888
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

254	WNW	0.95	5,030.07	6,732.33	WATER WELLS

License Nb:	228	District Office S:	
POD No:	16190	Surv Map:	
POD Rec No:	21212	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/01/1968, 12:00 AM	Restrict :	0.0
Finish Date:	11/30/1968, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	02/03/1970, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	40	UTM Zone:	13
Depth of Water:	8	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	410747.0
Pcw Rcv Da:		Northing:	3947716.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/05/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6692827
Map Nbr:		Point X:	-105.98617888
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Agua Fria		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB

Wells and Additional Sources Detail Report

254	WNW	0.95	5,030.07	6,732.33	WATER WELLS

License Nb:	228	District Office S:	
POD No:	08110	Surv Map:	
POD Rec No:	26393	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	CLW	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	INC	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	10/16/1962, 12:00 AM	Restrict :	0.0
Finish Date:	10/24/1962, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	12/05/1962, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	42	UTM Zone:	13
Depth of Water:	12	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	7000.0	County:	Santa Fe
Ref :		Easting:	410747.0
Pcw Rcv Da:		Northing:	3947716.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/10/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.6692827
Map Nbr:		Point X:	-105.98617888
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
257	W	0.96	5,048.72	6,739.24	WATER WELLS

License Nb:	0	District Office S:	
POD No:	42329	Surv Map:	
POD Rec No:	13294	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	33
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410702.9
Pcw Rcv Da:		Northing:	3947402.9
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/01/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	578400.0
Static Lev:	0	Y:	1697900.0
Tract Nbr:		Point Y:	35.66645608
Map Nbr:		Point X:	-105.98663136
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Wells and Additional Sources Detail Report

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
258	W	0.96	5,063.60	6,734.79	WATER WELLS

License Nb:	622	District Office S:	
POD No:	81329	Surv Map:	
POD Rec No:	196620	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/21/2004, 12:00 AM	Restrict :	0.0
Finish Date:	01/24/2004, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	01/30/2004, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	300	UTM Zone:	13
Depth of Water:	245	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	3	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410719.8
Pcw Rcv Da:		Northing:	3947631.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	01/30/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	578446.0
Static Lev:	0	Y:	1698651.0
Tract Nbr:		Point Y:	35.66851846
Map Nbr:		Point X:	-105.98647001
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			

Wells and Additional Sources Detail Report

Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
259	NNW	0.96	5,069.06	6,787.75	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34649	Surv Map:	
POD Rec No:	24462	Other Loc:	213 S El Rancho Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	12B SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411831.8
Pcw Rcv Da:		Northing:	3948879.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/06/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1722286.0
Static Lev:	0	Y:	1702853.0
Tract Nbr:		Point Y:	35.67986576
Map Nbr:		Point X:	-105.97432166
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		

Wells and Additional Sources Detail Report

Grant : Santa Fe
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
260	W	0.96	5,071.73	6,739.10	WATER WELLS

License Nb:	228	District Office S:	
POD No:	31849	Surv Map:	
POD Rec No:	36509	Other Loc:	166 Gallegos Ln
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 NA NA SF
Start Date:	02/13/1979, 12:00 AM	Restrict :	0.0
Finish Date:	02/15/1979, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	02/21/1979, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	320	UTM Zone:	13
Depth of Water:	240	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410700.6
Pcw Rcv Da:		Northing:	3947493.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/08/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Gilligan	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1718632.0
Static Lev:	0	Y:	1698259.0
Tract Nbr:		Point Y:	35.66727174
Map Nbr:		Point X:	-105.9866668
Driller:			
POD Basin Desc:	Rio Grande		

Wells and Additional Sources Detail Report

POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
261	NE	0.97	5,102.90	6,908.69	WATER WELLS

License Nb:	0	District Office S:	
POD No:	00296	Surv Map:	
POD Rec No:	60850	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	01/01/1951, 12:00 AM	Section:	26
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	250	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413366.0
Pcw Rcv Da:		Northing:	3948497.0
Sched Date:		Latitude Degree:	0
Use of Wel:	IRR	Latitude Minute:	0
Sys Date:	01/14/1992, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67655706
Map Nbr:		Point X:	-105.95732864
Driller:			

Wells and Additional Sources Detail Report

POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant :
Legal:

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
262	NNE	0.96	5,089.41	6,882.73	WATER WELLS

License Nb:	622	District Office S:	
POD No:	29206	Surv Map:	
POD Rec No:	80704	Other Loc:	1404 Camino Sierra Vista, Sf
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	1 SF
Start Date:	09/24/1977, 12:00 AM	Restrict :	0.0
Finish Date:	09/27/1977, 12:00 AM	Section:	26
Plug Date:		Township:	17N
Log File D:	10/03/1977, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	1
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	268	UTM Zone:	13
Depth of Water:	228	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	412963.3
Pcw Rcv Da:		Northing:	3948782.5
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/07/2023, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	St. Annes	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	412963.3
Static Lev:	0	Y:	3948782.5
Tract Nbr:		Point Y:	35.67909543
Map Nbr:		Point X:	-105.96180891

Wells and Additional Sources Detail Report

Driller:
POD Basin Desc: Rio Grande
POD Sub Basin Desc: Santa Fe River
Grant : Santa Fe
Legal: Parcel Number 1053098096413000000

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
264	W	0.97	5,114.75	6,730.91	WATER WELLS

License Nb:	228	District Office S:	
POD No:	35544	Surv Map:	
POD Rec No:	34019	Other Loc:	1229 Maez Road, Santa Fe
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TH SF
Start Date:	03/11/1983, 12:00 AM	Restrict :	0.0
Finish Date:	03/12/1983, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	03/28/1983, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	400	UTM Zone:	13
Depth of Water:	290	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410695.0
Pcw Rcv Da:		Northing:	3947175.8
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/03/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	410695.0
Static Lev:	0	Y:	3947175.8
Tract Nbr:		Point Y:	35.66440803

Wells and Additional Sources Detail Report

Map Nbr:		Point X:	-105.98669344
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Parcel Number 1051097404411000000		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
266	WSW	0.97	5,142.39	6,753.55	WATER WELLS

License Nb:	228	District Office S:	
POD No:	02382	Surv Map:	
POD Rec No:	36482	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/12/1958, 12:00 AM	Restrict :	0.0
Finish Date:	08/25/1958, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	11/21/1958, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	267	UTM Zone:	13
Depth of Water:	211	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410934.0
Pcw Rcv Da:		Northing:	3946510.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOM	Latitude Minute:	0
Sys Date:	05/22/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0

Wells and Additional Sources Detail Report

Tract Nbr:		Point Y:	35.65842737
Map Nbr:		Point X:	-105.98397953
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
266	WSW	0.97	5,142.39	6,753.55	WATER WELLS

License Nb:	0	District Office S:	
POD No:	01394	Surv Map:	
POD Rec No:	29277	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	07/01/1953, 12:00 AM	Restrict :	0.0
Finish Date:	07/31/1953, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	09/16/1957, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	240	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	32	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410934.0
Pcw Rcv Da:		Northing:	3946510.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	06/12/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0

Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.65842737
Map Nbr:		Point X:	-105.98397953
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
267	W	0.97	5,118.38	6,738.22	WATER WELLS

License Nb:	253	District Office S:	
POD No:	03783	Surv Map:	
POD Rec No:	50043	Other Loc:	**Tract 2-24**
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	4 TA SF
Start Date:	09/07/1959, 12:00 AM	Restrict :	0.0
Finish Date:	09/16/1959, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	01/04/1960, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	253	UTM Zone:	13
Depth of Water:	202	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410683.7
Pcw Rcv Da:		Northing:	3947455.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/06/2020, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0

Wells and Additional Sources Detail Report

Well Tag:	NA	X:	1718578.0
Static Lev:	0	Y:	1698133.0
Tract Nbr:		Point Y:	35.66692583
Map Nbr:		Point X:	-105.98684927
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
268	NNE	0.97	5,138.86	6,893.54	WATER WELLS

License Nb:	0	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	336372	Other Loc:	Ustb-50
POD Basin:	RG	Zone :	
POD Suffix:	POD36	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413135.6
Pcw Rcv Da:		Northing:	3948700.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/19/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0

Wells and Additional Sources Detail Report

Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1726571.4
Static Lev:	0	Y:	1702320.5
Tract Nbr:		Point Y:	35.67836867
Map Nbr:		Point X:	-105.95989624
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
268	NNE	0.97	5,138.86	6,893.54	WATER WELLS

License Nb:	0	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	336373	Other Loc:	Ustb-51
POD Basin:	RG	Zone :	
POD Suffix:	POD37	BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413135.6
Pcw Rcv Da:		Northing:	3948700.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/19/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0

Wells and Additional Sources Detail Report

Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1726571.4
Static Lev:	0	Y:	1702320.5
Tract Nbr:		Point Y:	35.67836867
Map Nbr:		Point X:	-105.95989624
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
269	NE	0.97	5,141.54	6,894.11	WATER WELLS

License Nb:	1664	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	313733	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD20	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/28/2018, 12:00 AM	Restrict :	0.0
Finish Date:	09/07/2018, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/2019, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	256	UTM Zone:	13
Depth of Water:	253	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413163.5
Pcw Rcv Da:		Northing:	3948682.8
Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	40
Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	41.57

Wells and Additional Sources Detail Report

Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	34.51
Well Tag:	NA	X:	0.0
Static Lev:	253	Y:	0.0
Tract Nbr:		Point Y:	35.67821427
Map Nbr:		Point X:	-105.9595861
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
269	NE	0.97	5,141.54	6,894.11	WATER WELLS

License Nb:	1446	District Office S:	
POD No:	97146	Surv Map:	
POD Rec No:	313734	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	POD21	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/22/2018, 12:00 AM	Restrict :	0.0
Finish Date:	08/28/2018, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	07/24/2019, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	PD
Depth of Well:	300	UTM Zone:	13
Depth of Water:	253	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	4.5	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413163.5
Pcw Rcv Da:		Northing:	3948682.8
Sched Date:		Latitude Degree:	35
Use of Wel:	EXPL	Latitude Minute:	40

Wells and Additional Sources Detail Report

Sys Date:	04/02/2020, 12:00 AM	Latitude Second:	41.57
Subdiv Nam:		Longitude Degree:	105
Surface Co:	0	Longitude Minute:	57
Ditch Name:		Longitude Second:	34.51
Well Tag:	NA	X:	0.0
Static Lev:	283	Y:	0.0
Tract Nbr:		Point Y:	35.67821427
Map Nbr:		Point X:	-105.9595861
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
270	WNW	0.97	5,126.42	6,729.09	WATER WELLS

License Nb:	653	District Office S:	
POD No:	27122	Surv Map:	
POD Rec No:	12170	Other Loc:	1320 Montoya Pl
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	2 SF
Start Date:	04/27/1976, 12:00 AM	Restrict :	0.0
Finish Date:	04/29/1976, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	07/13/1976, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	50	UTM Zone:	13
Depth of Water:	18	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	25	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410772.3
Pcw Rcv Da:		Northing:	3947905.8
Sched Date:		Latitude Degree:	0

Wells and Additional Sources Detail Report

Use of Wel:		Latitude Minute:	0
Sys Date:	07/21/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1718850.0
Static Lev:	0	Y:	1699615.0
Tract Nbr:		Point Y:	35.67099605
Map Nbr:		Point X:	-105.98592042
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
271	SW	0.98	5,162.32	6,749.35	WATER WELLS

License Nb:	0	District Office S:	
POD No:	78600	Surv Map:	
POD Rec No:	181277	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	UN
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	A
Pump Seria:		XY Accuracy:	M
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410965.1
Pcw Rcv Da:		Northing:	3946454.8

Wells and Additional Sources Detail Report

Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/02/2002, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	579300.0
Static Lev:	0	Y:	1694800.0
Tract Nbr:		Point Y:	35.65793254
Map Nbr:		Point X:	-105.98362988
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
272	ENE	0.98	5,149.99	6,968.98	WATER WELLS

License Nb:	0	District Office S:	
POD No:	30965	Surv Map:	
POD Rec No:	28332	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413786.7

Wells and Additional Sources Detail Report

Pcw Rcv Da:		Northing:	3947851.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	08/31/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	588500.0
Static Lev:	0	Y:	1699500.0
Tract Nbr:		Point Y:	35.67077283
Map Nbr:		Point X:	-105.95261119
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
273	WSW	0.98	5,158.98	6,736.23	WATER WELLS

License Nb:	253	District Office S:	
POD No:	08562	Surv Map:	
POD Rec No:	70300	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	03/07/1963, 12:00 AM	Restrict :	3.0
Finish Date:	03/08/1963, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	03/27/1963, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	239	UTM Zone:	13
Depth of Water:	206	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe

Wells and Additional Sources Detail Report

Ref :		Easting:	410739.0
Pcw Rcv Da:		Northing:	3946912.0
Sched Date:		Latitude Degree:	0
Use of Wel:	DOMESTIC	Latitude Minute:	0
Sys Date:	09/27/2005, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66203383
Map Nbr:		Point X:	-105.98617812
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
273	WSW	0.98	5,158.98	6,736.23	WATER WELLS

License Nb:	0	District Office S:	
POD No:	01237	Surv Map:	
POD Rec No:	46452	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/01/1947, 12:00 AM	Restrict :	0.0
Finish Date:	12/31/1947, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	08/16/1957, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	216	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	

Wells and Additional Sources Detail Report

Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410739.0
Pcw Rcv Da:		Northing:	3946912.0
Sched Date:		Latitude Degree:	0
Use of Wel:	COM/DOM	Latitude Minute:	0
Sys Date:	05/09/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66203383
Map Nbr:		Point X:	-105.98617812
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:	Corner Of Maes And Rosina Street.		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
273	WSW	0.98	5,158.98	6,736.23	WATER WELLS

License Nb:	1173	District Office S:	
POD No:	01237	Surv Map:	
POD Rec No:	47640	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	REPAR	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/17/1957, 12:00 AM	Restrict :	0.0
Finish Date:	08/20/1957, 12:00 AM	Section:	33
Plug Date:		Township:	17N
Log File D:	09/25/1957, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	239	UTM Zone:	13
Depth of Water:	197	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	

Wells and Additional Sources Detail Report

Casing Size:	6.62	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410739.0
Pcw Rcv Da:		Northing:	3946912.0
Sched Date:		Latitude Degree:	0
Use of Wel:	COMM	Latitude Minute:	0
Sys Date:	05/09/2003, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.66203383
Map Nbr:		Point X:	-105.98617812
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
274	NNW	0.98	5,171.83	6,789.94	WATER WELLS

License Nb:	228	District Office S:	
POD No:	33493	Surv Map:	
POD Rec No:	44399	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	11/05/1979, 12:00 AM	Restrict :	0.0
Finish Date:	11/08/1979, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	11/15/1979, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	440	UTM Zone:	13
Depth of Water:	300	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	

Wells and Additional Sources Detail Report

Estimate Yield:	30	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411482.1
Pcw Rcv Da:		Northing:	3948764.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	04/08/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	580900.0
Static Lev:	0	Y:	1702400.0
Tract Nbr:		Point Y:	35.67880039
Map Nbr:		Point X:	-105.97817297
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
275	WNW	0.98	5,173.78	6,729.41	WATER WELLS

License Nb:	0	District Office S:	
POD No:	40028	Surv Map:	
POD Rec No:	22336	Other Loc:	1329 Camino Carlos Rael
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	TB SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	

Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410748.8
Pcw Rcv Da:		Northing:	3947882.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/28/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1718774.0
Static Lev:	0	Y:	1699538.0
Tract Nbr:		Point Y:	35.67078478
Map Nbr:		Point X:	-105.98617747
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
276	NNW	0.98	5,174.64	6,786.97	WATER WELLS

License Nb:	0	District Office S:	
POD No:	31544	Surv Map:	
POD Rec No:	16596	Other Loc:	210 Camino Rio
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	13 2 TC2 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	

Wells and Additional Sources Detail Report

Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411914.4
Pcw Rcv Da:		Northing:	3948934.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/29/2019, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Montano	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	411914.4
Static Lev:	0	Y:	3948934.6
Tract Nbr:		Point Y:	35.68037348
Map Nbr:		Point X:	-105.97341507
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number 1-052-098-270-468		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
277	WNW	0.98	5,191.48	6,729.45	WATER WELLS

License Nb:	0	District Office S:	
POD No:	33449	Surv Map:	
POD Rec No:	50304	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	2
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	

Wells and Additional Sources Detail Report

Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410733.5
Pcw Rcv Da:		Northing:	3947854.6
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	05/06/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	410733.5
Static Lev:	0	Y:	3947854.6
Tract Nbr:		Point Y:	35.67053097
Map Nbr:		Point X:	-105.9863434
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
278	WNW	0.99	5,206.94	6,727.44	WATER WELLS

License Nb:	547	District Office S:	
POD No:	82001	Surv Map:	
POD Rec No:	199572	Other Loc:	Santa Fe Quad. Map
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7
Start Date:		Restrict :	0.0
Finish Date:		Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	0	UTM Zone:	13

Wells and Additional Sources Detail Report

Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410751.0
Pcw Rcv Da:		Northing:	3947919.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	02/13/2004, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67111312
Map Nbr:		Point X:	-105.9861572
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
278	WNW	0.99	5,206.94	6,727.44	WATER WELLS

License Nb:	0	District Office S:	
POD No:	23559	Surv Map:	
POD Rec No:	31284	Other Loc:	Pt. Of Small Holding Claim 458
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G

Wells and Additional Sources Detail Report

Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410751.0
Pcw Rcv Da:		Northing:	3947919.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	09/18/2009, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67111312
Map Nbr:		Point X:	-105.9861572
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
278	WNW	0.99	5,206.94	6,727.44	WATER WELLS

License Nb:	227	District Office S:	
POD No:	51266	Surv Map:	
POD Rec No:	53950	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	08/17/1989, 12:00 AM	Restrict :	0.0
Finish Date:	08/20/1989, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	10/10/1989, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	4
CFS Start:		Quarter 16th:	2
CFS End MD:		Quarter 64th:	3
CFS Cnv Fa:	0.0	Datum:	NAD83

Wells and Additional Sources Detail Report

CS Code:	0	UTM Source:	G
Depth of Well:	98	UTM Zone:	13
Depth of Water:	40	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	10	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410751.0
Pcw Rcv Da:		Northing:	3947919.0
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/18/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67111312
Map Nbr:		Point X:	-105.9861572
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
279	NW	0.99	5,226.89	6,776.72	WATER WELLS

License Nb:	0	District Office S:	
POD No:	30260	Surv Map:	
POD Rec No:	58344	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:		Section:	
Plug Date:		Township:	
Log File D:		Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	

Wells and Additional Sources Detail Report

CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	21	UTM Source:	PA
Depth of Well:	250	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	6.63	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411205.5
Pcw Rcv Da:		Northing:	3948585.1
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	07/16/2014, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	580000.0
Static Lev:	0	Y:	1701800.0
Tract Nbr:		Point Y:	35.67715911
Map Nbr:		Point X:	-105.98120937
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
280	E	0.99	5,239.90	6,964.16	WATER WELLS

License Nb:	0	District Office S:	
POD No:	36138	Surv Map:	
POD Rec No:	54384	Other Loc:	113 Mateo Circle
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	9 1 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	35
Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	2

Wells and Additional Sources Detail Report

CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	EA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	413890.2
Pcw Rcv Da:		Northing:	3947271.2
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	11/22/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Mateo Heights	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1729107.0
Static Lev:	0	Y:	1697663.0
Tract Nbr:		Point Y:	35.66555215
Map Nbr:		Point X:	-105.95140566
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
281	NW	0.99	5,241.82	6,736.24	WATER WELLS

License Nb:	530	District Office S:	
POD No:	00392	Surv Map:	
POD Rec No:	25444	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	REPAIR 2	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	04/22/1960, 12:00 AM	Restrict :	0.0
Finish Date:	04/22/1960, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:	05/02/1960, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2

Wells and Additional Sources Detail Report

CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	50	UTM Zone:	13
Depth of Water:	15	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:	CENTRI	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410955.0
Pcw Rcv Da:	03/30/1961, 12:00 AM	Northing:	3948321.0
Sched Date:		Latitude Degree:	0
Use of Wel:	IRR	Latitude Minute:	0
Sys Date:	01/07/2016, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67475563
Map Nbr:		Point X:	-105.98394788
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
281	NW	0.99	5,241.82	6,736.24	WATER WELLS

License Nb:	0	District Office S:	
POD No:	00392	Surv Map:	
POD Rec No:	7170	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:		Restrict :	0.0
Finish Date:	01/01/1953, 12:00 AM	Section:	28
Plug Date:		Township:	17N
Log File D:		Range:	09E

Wells and Additional Sources Detail Report

Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	50	UTM Zone:	13
Depth of Water:	0	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:	CENTRI	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410955.0
Pcw Rcv Da:		Northing:	3948321.0
Sched Date:		Latitude Degree:	0
Use of Wel:	IRR	Latitude Minute:	0
Sys Date:	01/07/2016, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67475563
Map Nbr:		Point X:	-105.98394788
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
281	NW	0.99	5,241.82	6,736.24	WATER WELLS

License Nb:	214	District Office S:	
POD No:	00392	Surv Map:	
POD Rec No:	67450	Other Loc:	
POD Basin:	RG	Zone :	
POD Suffix:	REPAIR	BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:		Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	
Start Date:	01/01/1957, 12:00 AM	Restrict :	0.0
Finish Date:	01/01/1957, 12:00 AM	Section:	28
Plug Date:		Township:	17N

Wells and Additional Sources Detail Report

Log File D:	05/09/1957, 12:00 AM	Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	4
CFS End MD:		Quarter 64th:	4
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	0	UTM Source:	G
Depth of Well:	50	UTM Zone:	13
Depth of Water:	11	UTM Accura:	
Ground Water Src:	S	UTM Error:	
Pump Type:	TURBIN	XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410955.0
Pcw Rcv Da:	05/06/1958, 12:00 AM	Northing:	3948321.0
Sched Date:		Latitude Degree:	0
Use of Wel:	IRR	Latitude Minute:	0
Sys Date:	01/07/2016, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:		Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:		X:	0.0
Static Lev:	0	Y:	0.0
Tract Nbr:		Point Y:	35.67475563
Map Nbr:		Point X:	-105.98394788
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :			
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
282	NNW	0.99	5,243.50	6,793.13	WATER WELLS

License Nb:	0	District Office S:	
POD No:	34606	Surv Map:	
POD Rec No:	35347	Other Loc:	210 El Rancho Rd
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	0
POD Status:	PEN	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	7 SF
Start Date:		Restrict :	0.0
Finish Date:		Section:	27

Wells and Additional Sources Detail Report

Plug Date:		Township:	17N
Log File D:		Range:	09E
Wrats S ID:	0	Quarter 4th:	2
CFS Start:		Quarter 16th:	1
CFS End MD:		Quarter 64th:	1
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	5	UTM Source:	PA
Depth of Well:	0	UTM Zone:	13
Depth of Water:	0	UTM Accura:	10
Ground Water Src:		UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	0	Lat Lon SO:	
Casing Size:	0.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	411778.7
Pcw Rcv Da:		Northing:	3948919.4
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/06/2021, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	1722110.0
Static Lev:	0	Y:	1702983.0
Tract Nbr:		Point Y:	35.68022431
Map Nbr:		Point X:	-105.9749128
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:			

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
283	WNW	1.00	5,274.74	6,723.55	WATER WELLS

License Nb:	790	District Office S:	
POD No:	50494	Surv Map:	
POD Rec No:	38132	Other Loc:	
POD Basin:	RG	Zone :	C
POD Suffix:		BLK:	
Pod Sub Ba:	SF	Percent Sh:	100
POD Status:	ACT	Discharge:	
Pod Sub Ba Abbr:		Aquifer:	
POD Name:		Subdiv Loc:	SF
Start Date:	04/17/1989, 12:00 AM	Restrict :	0.0

Wells and Additional Sources Detail Report

Finish Date:	04/17/1989, 12:00 AM	Section:	
Plug Date:		Township:	
Log File D:	04/25/1989, 12:00 AM	Range:	
Wrats S ID:	0	Quarter 4th:	
CFS Start:		Quarter 16th:	
CFS End MD:		Quarter 64th:	
CFS Cnv Fa:	0.0	Datum:	NAD83
CS Code:	1	UTM Source:	EA
Depth of Well:	70	UTM Zone:	13
Depth of Water:	26	UTM Accura:	10
Ground Water Src:	S	UTM Error:	
Pump Type:		XY Source:	
Pump Seria:		XY Accuracy:	
Estimate Yield:	20	Lat Lon SO:	
Casing Size:	5.0	Lat Lon AC:	
Elevation:	0.0	County:	Santa Fe
Ref :		Easting:	410748.9
Pcw Rcv Da:		Northing:	3947971.3
Sched Date:		Latitude Degree:	0
Use of Wel:		Latitude Minute:	0
Sys Date:	10/31/2022, 12:00 AM	Latitude Second:	0.0
Subdiv Nam:	Na	Longitude Degree:	0
Surface Co:	0	Longitude Minute:	0
Ditch Name:		Longitude Second:	0.0
Well Tag:	NA	X:	410748.9
Static Lev:	0	Y:	3947971.3
Tract Nbr:		Point Y:	35.67158442
Map Nbr:		Point X:	-105.9861862
Driller:			
POD Basin Desc:	Rio Grande		
POD Sub Basin Desc:	Santa Fe River		
Grant :	Santa Fe		
Legal:	Parcel Number: 1051098436141000000		

Public Water Supply Wells

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
52	SSE	0.52	2,737.20	6,869.92	PWSW

TINWSF Is No:	1948	City:	SANTA FE
No:	NM3505126	County:	SANTA FE
TINWSYS No:	380	Latitude:	35.659083
TINWSF No:	380	Longitude:	-105.965694
Alternate St No:		River Reach Ind Cd:	Yes
Stage2 CDS ID:	1880	Rvr Rch Miles Qty:	0
St Asgn Ident Cd:	05126012	Pump Type Code:	VT
Finds No:		Wtr Body Nm Txt:	

Wells and Additional Sources Detail Report

Owner Type Code:	L	External Sys No:	1948
Owner Type Desc:	Local Government	Treatment Stat Cd:	Treated
Oper Category Cd:	WS4	D Source Flag:	Yes
Operating Cat Cd:		Avg Pct Water Qty:	0
Fed Prim Src Cd:	SW	Physical Modif Dt:	
Fed Prim Src Desc:	Surface water	Water Type Code Dt:	11/26/2007
PWS Fed Type Cd:	C	Swap Report Status:	
PWS Fed Type Desc:	Community water system	Swap Rpt Status Dt:	
Type Code:	WL	Filtration Status:	
Population Count:	90810	Filtration Stat Dt:	
History Ind Cd:	C	Pump Description:	
History Ind Desc:	Current	Water Type Code:	GW
Ttl Stor Cap Msr:	36150000	Water Type Desc:	Ground water
PWS St Type Cd:	C	Horiz Ref Datum Cd:	003
Non Pipe Fac Tp Cd:		Data Collection Dt:	9/27/2010
Constructed Date:	1/1/1983	Depth of Well:	800
Surf Wtr Ratio:	20	Depth of Well UOM:	FT
Surf Wtr Pur Ratio:	40	Well Diameter:	16
Grnd Wtr Ratio:	40	Well Diameter UOM:	IN
Grnd Wtr Pur Ratio:	0	Static Water Level:	282
Grnd Wtr Udi Ratio:	0	Static Wtr Lvl UOM:	FT
Grnd Wtr Udi Purch:	0	Last Inv Updt Ts:	3/1/2024 1:46:30 PM
Availability Code:	P - Permanent Utilization	Last Snty Srv Dt:	
TINWSYS Name:	SANTA FE WATER SYSTEM (CITY OF)	Prt Gw Sr Ind Cd:	No
TINWSYS Local Nm:		Tcr Mcl Vio Dt:	
TINWSYS St Code:	NM	Inv Chg Ind Cd:	
TINWSF Name:	ST MICHAELS WELL	Dsnfct Gw Ind Cd:	
TINWSF Local Nm:		Swgudi Fl Ind Cd:	
TINWSF St Code:	NM	St Prim Src Cd:	SW
TINWSYS User ID Cd:	VGURULE	Sell Treat Ind Cd:	
TINWSYS Initial Ts:	1/7/2003 11:13:09 AM	Usgs Hydro Unit Cd:	
TINWSYS Init User:	SSWR1	Storet Ext Hydro U:	
TINWSF User ID Cd:	DRAMIREZ	Days Serving Count:	
TINWSF Initial Ts:	1/1/2005		
TINWSF Act Rsn Txt:	Well is out of service from 4-26-17 through 6-30-17 as per Wayne Jeffs.		
TINWSYS Act Rsn Txt:	Santa fe water quality division attached to city of santa fe...added 65 population and an extra 9 connections to city.		
TINWSYS Cds Trigger Ts:	2/15/2022 8:57:51 AM		
TINWSYS Cds Trigger User:	VGURULE		
TINWSF Last Updt Ts:	4/26/2017 2:54:56 PM		
TINWSF Init User ID:	SSWR1		
TINWSF Cds Trig Ts:	4/26/2017 2:54:57 PM		
TINWSF Cds Trigger User:	DRAMIREZ		
TINWSF TINWSYS St Code:	NM		
TINWSF Act Status Cd:	A		
TINWSF Act Status Desc:	Active		

Wells and Additional Sources Detail Report

TINWSF Act Date:	4/26/2017
TINWSYS Act Status Cd:	A
TINWSYS Act Status Desc:	Active
TINWSYS Act Date:	6/1/1977
TINWSF Act Reason Cd:	
TINWSYS Act Reason Cd:	
TINWSYS D Last Updt Ts:	2/15/2022 8:57:50 AM
On River Reach Ind Desc:	
New Ws Flag:	N - No, indicating the Water System has more than the minimum data valued in TINWSYS.
Directions Text:	
Memo Text:	Permitted water rights: 19,905 acre-ft/year

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
106	NW	0.72	3,798.58	6,763.66	PWSW

TINWSF Is No:	1950	City:	SANTA FE
No:	NM3505126	County:	SANTA FE
TINWSYS No:	380	Latitude:	35.672722
TINWSF No:	380	Longitude:	-105.97975
Alternate St No:		River Reach Ind Cd:	Yes
Stage2 CDS ID:	1880	Rvr Rch Miles Qty:	0
St Asgn Ident Cd:	05126016	Pump Type Code:	VT
Finds No:		Wtr Body Nm Txt:	
Owner Type Code:	L	External Sys No:	1950
Owner Type Desc:	Local Government	Treatment Stat Cd:	Treated
Oper Category Cd:	WS4	D Source Flag:	Yes
Operating Cat Cd:		Avg Pct Water Qty:	0
Fed Prim Src Cd:	SW	Physical Modif Dt:	
Fed Prim Src Desc:	Surface water	Water Type Code Dt:	6/16/2010
PWS Fed Type Cd:	C	Swap Report Status:	
PWS Fed Type Desc:	Community water system	Swap Rpt Status Dt:	
Type Code:	WL	Filtration Status:	
Population Count:	90810	Filtration Stat Dt:	
History Ind Cd:	C	Pump Description:	
History Ind Desc:	Current	Water Type Code:	GW
Ttl Stor Cap Msr:	36150000	Water Type Desc:	Ground water
PWS St Type Cd:	C	Horiz Ref Datum Cd:	003
Non Pipe Fac Tp Cd:		Data Collection Dt:	9/27/2010
Constructed Date:	1/1/1971	Depth of Well:	770
Surf Wtr Ratio:	20	Depth of Well UOM:	FT
Surf Wtr Pur Ratio:	40	Well Diameter:	16
Grnd Wtr Ratio:	40	Well Diameter UOM:	IN
Grnd Wtr Pur Ratio:	0	Static Water Level:	100
Grnd Wtr Udi Ratio:	0	Static Wtr Lvl UOM:	FT
Grnd Wtr Udi Purch:	0	Last Inv Updt Ts:	3/1/2024 1:46:30 PM
Availability Code:	P - Permanent Utilization	Last Snty Srv Dt:	

Wells and Additional Sources Detail Report

TINWSYS Name:	SANTA FE WATER SYSTEM (CITY OF)	Prt Gw Sr Ind Cd:	No
TINWSYS Local Nm:		Tcr Mcl Vio Dt:	
TINWSYS St Code:	NM	Inv Chg Ind Cd:	
TINWSF Name:	OSAGE WELL	Dsnfct Gw Ind Cd:	
TINWSF Local Nm:		Swgudi Fl Ind Cd:	
TINWSF St Code:	NM	St Prim Src Cd:	SW
TINWSYS User ID Cd:	VGURULE	Sell Treat Ind Cd:	
TINWSYS Initial Ts:	1/7/2003 11:13:09 AM	Usgs Hydro Unit Cd:	
TINWSYS Init User:	SSWR1	Storet Ext Hydro U:	
TINWSF User ID Cd:	DATAS4	Days Serving Count:	
TINWSF Initial Ts:	1/1/2005		
TINWSF Act Rsn Txt:	Inactive all of 2006. inactive date: 12/31/2005. Well was inactive for all of 2012. Well was inactive for all of 2014 IAW memo from system dated 26 Dec 2014 **Note: Many records provided by the department have a truncated [TINWSF Act Rsn Txt] field.		
TINWSYS Act Rsn Txt:	Santa fe water quality division attached to city of santa fe...added 65 population and an extra 9 connections to city.		
TINWSYS Cds Trigger Ts:	2/15/2022 8:57:51 AM		
TINWSYS Cds Trigger User:	VGURULE		
TINWSF Last Updt Ts:	6/15/2015 8:23:14 AM		
TINWSF Init User ID:	SSWR1		
TINWSF Cds Trig Ts:	6/18/2010 8:26:44 AM		
TINWSF Cds Trigger User:	KBEEZHOL		
TINWSF TINWSYS St Code:	NM		
TINWSF Act Status Cd:	A		
TINWSF Act Status Desc:	Active		
TINWSF Act Date:	6/16/2010		
TINWSYS Act Status Cd:	A		
TINWSYS Act Status Desc:	Active		
TINWSYS Act Date:	6/1/1977		
TINWSF Act Reason Cd:			
TINWSYS Act Reason Cd:			
TINWSYS D Last Updt Ts:	2/15/2022 8:57:50 AM		
On River Reach Ind Desc:			
New Ws Flag:	N - No, indicating the Water System has more than the minimum data valued in TINWSYS.		
Directions Text:			
Memo Text:	Permitted water rights: 19,905 acre-ft/year		

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
112	NNE	0.73	3,844.94	6,870.57	PWSW

TINWSF Is No:	1947	City:	SANTA FE
No:	NM3505126	County:	SANTA FE
TINWSYS No:	380	Latitude:	35.675975
TINWSF No:	380	Longitude:	-105.963521
Alternate St No:		River Reach Ind Cd:	Yes
Stage2 CDS ID:	1880	Rvr Rch Miles Qty:	0

Wells and Additional Sources Detail Report

St Asgn Ident Cd:	05126011	Pump Type Code:	SU
Finds No:		Wtr Body Nm Txt:	
Owner Type Code:	L	External Sys No:	1947
Owner Type Desc:	Local Government	Treatment Stat Cd:	Treated
Oper Category Cd:	WS4	D Source Flag:	Yes
Operating Cat Cd:		Avg Pct Water Qty:	0
Fed Prim Src Cd:	SW	Physical Modif Dt:	
Fed Prim Src Desc:	Surface water	Water Type Code Dt:	11/26/2007
PWS Fed Type Cd:	C	Swap Report Status:	
PWS Fed Type Desc:	Community water system	Swap Rpt Status Dt:	
Type Code:	WL	Filtration Status:	
Population Count:	90810	Filtration Stat Dt:	
History Ind Cd:	C	Pump Description:	
History Ind Desc:	Current	Water Type Code:	GW
Ttl Stor Cap Msr:	36150000	Water Type Desc:	Ground water
PWS St Type Cd:	C	Horiz Ref Datum Cd:	003
Non Pipe Fac Tp Cd:		Data Collection Dt:	11/26/2007
Constructed Date:	1/1/1951	Depth of Well:	1523
Surf Wtr Ratio:	20	Depth of Well UOM:	FT
Surf Wtr Pur Ratio:	40	Well Diameter:	16
Grnd Wtr Ratio:	40	Well Diameter UOM:	IN
Grnd Wtr Pur Ratio:	0	Static Water Level:	324
Grnd Wtr Udi Ratio:	0	Static Wtr Lvl UOM:	FT
Grnd Wtr Udi Purch:	0	Last Inv Updt Ts:	3/1/2024 1:46:30 PM
Availability Code:	P - Permanent Utilization	Last Snty Srv Dt:	
TINWSYS Name:	SANTA FE WATER SYSTEM (CITY OF)	Prt Gw Sr Ind Cd:	No
TINWSYS Local Nm:		Tcr Mcl Vio Dt:	
TINWSYS St Code:	NM	Inv Chg Ind Cd:	
TINWSF Name:	SANTA FE WELL	Dsnfct Gw Ind Cd:	
TINWSF Local Nm:		Swgudi Fl Ind Cd:	
TINWSF St Code:	NM	St Prim Src Cd:	SW
TINWSYS User ID Cd:	VGURULE	Sell Treat Ind Cd:	
TINWSYS Initial Ts:	1/7/2003 11:13:09 AM	Usgs Hydro Unit Cd:	
TINWSYS Init User:	SSWR1	Storet Ext Hydro U:	
TINWSF User ID Cd:	DATAS4	Days Serving Count:	
TINWSF Initial Ts:	1/1/2005		
TINWSF Act Rsn Txt:			
TINWSYS Act Rsn Txt:	Santa fe water quality division attached to city of santa fe...added 65 population and an extra 9 connections to city.		
TINWSYS Cds Trigger Ts:	2/15/2022 8:57:51 AM		
TINWSYS Cds Trigger User:	VGURULE		
TINWSF Last Updt Ts:	11/3/2014 1:02:04 PM		
TINWSF Init User ID:	SSWR1		
TINWSF Cds Trig Ts:	11/3/2014 1:02:04 PM		
TINWSF Cds Trigger User:	DATAS4		
TINWSF TINWSYS St Code:	NM		

Wells and Additional Sources Detail Report

TINWSF Act Status Cd:	I
TINWSF Act Status Desc:	Inactive
TINWSF Act Date:	9/10/2014
TINWSYS Act Status Cd:	A
TINWSYS Act Status Desc:	Active
TINWSYS Act Date:	6/1/1977
TINWSF Act Reason Cd:	
TINWSYS Act Reason Cd:	
TINWSYS D Last Updt Ts:	2/15/2022 8:57:50 AM
On River Reach Ind Desc:	
New Ws Flag:	N - No, indicating the Water System has more than the minimum data valued in TINWSYS.
Directions Text:	
Memo Text:	Permitted water rights: 19,905 acre-ft/year

Map Key	Direction	Distance (mi)	Distance (ft)	Elevation (ft)	DB
172	N	0.80	4,227.95	6,807.23	PWSW

TINWSF Is No:	1937	City:	SANTA FE
No:	NM3505126	County:	SANTA FE
TINWSYS No:	380	Latitude:	35.678083
TINWSF No:	380	Longitude:	-105.971
Alternate St No:		River Reach Ind Cd:	Yes
Stage2 CDS ID:	1880	Rvr Rch Miles Qty:	0
St Asgn Ident Cd:	05126001	Pump Type Code:	VT
Finds No:		Wtr Body Nm Txt:	
Owner Type Code:	L	External Sys No:	1937
Owner Type Desc:	Local Government	Treatment Stat Cd:	Treated
Oper Category Cd:	WS4	D Source Flag:	Yes
Operating Cat Cd:		Avg Pct Water Qty:	0
Fed Prim Src Cd:	SW	Physical Modif Dt:	
Fed Prim Src Desc:	Surface water	Water Type Code Dt:	11/26/2007
PWS Fed Type Cd:	C	Swap Report Status:	
PWS Fed Type Desc:	Community water system	Swap Rpt Status Dt:	
Type Code:	WL	Filtration Status:	
Population Count:	90810	Filtration Stat Dt:	
History Ind Cd:	C	Pump Description:	
History Ind Desc:	Current	Water Type Code:	GW
Ttl Stor Cap Msr:	36150000	Water Type Desc:	Ground water
PWS St Type Cd:	C	Horiz Ref Datum Cd:	003
Non Pipe Fac Tp Cd:		Data Collection Dt:	9/27/2010
Constructed Date:	1/1/1951	Depth of Well:	740
Surf Wtr Ratio:	20	Depth of Well UOM:	FT
Surf Wtr Pur Ratio:	40	Well Diameter:	16
Grnd Wtr Ratio:	40	Well Diameter UOM:	IN
Grnd Wtr Pur Ratio:	0	Static Water Level:	179
Grnd Wtr Udi Ratio:	0	Static Wtr Lvl UOM:	FT

Wells and Additional Sources Detail Report

Grnd Wtr Udi Purch:	0	Last Inv Updt Ts:	3/1/2024 1:46:30 PM
Availability Code:	P - Permanent Utilization	Last Snty Srv Dt:	
TINWSYS Name:	SANTA FE WATER SYSTEM (CITY OF)	Prt Gw Sr Ind Cd:	No
TINWSYS Local Nm:		Tcr Mcl Vio Dt:	
TINWSYS St Code:	NM	Inv Chg Ind Cd:	
TINWSF Name:	AGUA FRIA WELL	Dsnfct Gw Ind Cd:	
TINWSF Local Nm:		Swgudi Fl Ind Cd:	
TINWSF St Code:	NM	St Prim Src Cd:	SW
TINWSYS User ID Cd:	VGURULE	Sell Treat Ind Cd:	
TINWSYS Initial Ts:	1/7/2003 11:13:09 AM	Usgs Hydro Unit Cd:	
TINWSYS Init User:	SSWR1	Storet Ext Hydro U:	
TINWSF User ID Cd:	KBEEZHOL	Days Serving Count:	
TINWSF Initial Ts:	1/1/2005		
TINWSF Act Rsn Txt:	inactiive date: 2/13/2009: active date: 01/01/1951 **Note: Many records provided by the department have a truncated [TINWSF Act Rsn Txt] field.		
TINWSYS Act Rsn Txt:	Santa fe water quality division attached to city of santa fe...added 65 population and an extra 9 connections to city.		
TINWSYS Cds Trigger Ts:	2/15/2022 8:57:51 AM		
TINWSYS Cds Trigger User:	VGURULE		
TINWSF Last Updt Ts:	3/24/2011 1:41:30 PM		
TINWSF Init User ID:	SSWR1		
TINWSF Cds Trig Ts:	3/24/2011 1:41:30 PM		
TINWSF Cds Trigger User:	KBEEZHOL		
TINWSF TINWSYS St Code:	NM		
TINWSF Act Status Cd:	A		
TINWSF Act Status Desc:	Active		
TINWSF Act Date:	3/24/2011		
TINWSYS Act Status Cd:	A		
TINWSYS Act Status Desc:	Active		
TINWSYS Act Date:	6/1/1977		
TINWSF Act Reason Cd:			
TINWSYS Act Reason Cd:			
TINWSYS D Last Updt Ts:	2/15/2022 8:57:50 AM		
On River Reach Ind Desc:			
New Ws Flag:	N - No, indicating the Water System has more than the minimum data valued in TINWSYS.		
Directions Text:			
Memo Text:	Permitted water rights: 19,905 acre-ft/year		

Radon Information

This section lists any relevant radon information found for the target property.

Federal EPA Radon Zone for *SANTA FE* County: **1**

Zone 1: Counties with predicted average indoor radon screening levels greater than 4 pCi/L
Zone 2: Counties with predicted average indoor radon screening levels from 2 to 4 pCi/L
Zone 3: Counties with predicted average indoor radon screening levels less than 2 pCi/L

Federal Area Radon Information for *SANTA FE* County

No Measures/Homes:	73
Geometric Mean:	3.2
Arithmetic Mean:	4.6
Median:	3.5
Standard Deviation:	3.8
Maximum:	21.6
% >4 pCi/L:	41
% >20 pCi/L:	1
Notes on Data Table:	TABLE 1. Screening indoor radon data from the EPA/State Residential Radon Survey of New Mexico conducted during 1988-89. Data represent 2-7 day charcoal canister measurements from the lowest level of each home tested.

Appendix

Federal Sources

FEMA National Flood Hazard Layer — **FEMA FLOOD**

The National Flood Hazard Layer (NFHL) data incorporates Flood Insurance Rate Map (FIRM) databases published by the Federal Emergency Management Agency (FEMA), and any Letters Of Map Revision (LOMRs) that have been issued against those databases since their publication date. The FIRM Database is the digital, geospatial version of the flood hazard information shown on the published paper FIRMs. The FIRM Database depicts flood risk information and supporting data used to develop the risk data. The FIRM Database is derived from Flood Insurance Studies (FISs), previously published FIRMs, flood hazard analyses performed in support of the FISs and FIRMs, and new mapping data, where available.

Indoor Radon Data — **INDOOR RADON**

Indoor radon measurements tracked by the Environmental Protection Agency(EPA) and the State Residential Radon Survey.

Public Water Systems Violations and Enforcement Data — **PWSV**

This list of drinking water violations and enforcement actions is sourced from the U.S Environmental Protection Agency's (EPA) Enforcement and Compliance History Online (ECHO) system that incorporates Public Water Systems data from EPA's Safe Drinking Water Information System (SDWIS) database, as part of the national download of Safe Drinking Water Act (SDWA) data. SDWIS contains information on public water systems from the Public Water System Supervision (PWSS) Program, including monitoring, enforcement, and violation data related to requirements established by the SWDA. Address information provided in SWDIS may correspond either with the physical location of the water system, or with a contact address.

Radon Zone Level — **RADON ZONE**

Areas showing the level of Radon Zones (level 1, 2 or 3) by county. This data is maintained by the Environmental Protection Agency (EPA).

Safe Drinking Water Information System (SDWIS) — **SDWIS**

This national download of Safe Drinking Water Act (SDWA) data is sourced from the U.S Environmental Protection Agency's (EPA) Enforcement and Compliance History Online (ECHO) system that incorporates Public Water Systems data from EPA's Safe Drinking Water Information System (SDWIS) database. SDWIS contains information on public water systems from the Public Water System Supervision (PWSS) Program related to requirements established by the Safe Drinking Water Act (SDWA). Address information provided in SWDIS may correspond either with the physical location of the water system, or with a contact address.

Soil Survey Geographic database — **SSURGO**

The Soil Survey Geographic database (SSURGO) contains information about soil as collected by the National Cooperative Soil Survey at the Natural Resources Conservation Service (NRCS). Soil maps outline areas called map units. The map units are linked to soil properties in a database. Each map unit may contain one to three major components and some minor components.

U.S. Fish & Wildlife Service Wetland Data — **US WETLAND**

The U.S. Fish & Wildlife Service Wetland layer represents the approximate location and type of wetlands and deepwater habitats in the United States.

USGS Current Topo — **US TOPO**

US Topo topographic maps are produced by the National Geospatial Program of the U.S. Geological Survey (USGS). The project was launched in late 2009, and the term "US Topo" refers specifically to quadrangle topographic maps published in 2009 and later.

USGS Geology — **US GEOLOGY**

Seamless maps depicting geological information provided by the United States Geological Survey (USGS).

USGS National Water Information System — **FED USGS**

The U.S. Geological Survey's (USGS) National Water Information System (NWIS) is the nation's principal repository of water resources data. The data includes comprehensive information of well-construction details, time-series data for gage height, streamflow, groundwater level, and precipitation and water use data. This NWIS database information is obtained through the Water Quality Data Portal (WQP). The WQP

is a cooperative service sponsored by the USGS, the Environmental Protection Agency (EPA), and the National Water Quality Monitoring Council (NWQMC).

State Sources

Oil and Gas Wells **OGW**

Oil and Gas Well Data collected by New Mexico Oil Conservation Division.

Point of Diversion Report **WATER WELLS**

Point of Diversion report provided by the New Mexico Office of the State Engineer (OSE). This data comes from the NM Water Rights Reporting System (NMWRRS). The report returns a summary of water rights use, owner, wells, point of diversion and location and other information. This list includes declared, complete, in-progress, and plugged wells.

Public Water Supply Wells **PWSW**

A list of public water supply systems maintained by the New Mexico Environment Department (NMED), Drinking Water Bureau (DWB). This database includes active and inactive public water systems.

Liability Notice

Reliance on information in Report: The Physical Setting Report (PSR) DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as a review of environmental databases and physical characteristics for the site or adjacent properties.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS Information Inc. disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report(s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

APPENDIX E

User Provided Information

[RESERVED]

APPENDIX F

Historical Fire Insurance Maps

FIRE INSURANCE MAPS

Project Property: Danny's Cleaners
1406 2nd Street Santa Fe NM 87505
Project No: NMENV.M007.SF-WALDO
Requested By: INTERA Incorporated
Order No: 25121700732
Date Completed: December 17, 2025

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com


Listed below, please find the results of our search for historic fire insurance maps from our in-house collection, performed in conjuction with your ERIS report.

Date	City	State	Volume	Sheet Number(s)
1970	Santa Fe	New Mexico		21, 23

Individual Fire Insurance Maps for the subject property and/or adjacent sites in the United States may have been included with the ERIS Environmental Database Report. Those Fire Insurance Maps are to be used for research purposes only and cannot be resold for any commercial uses other than for use in real property analyses projects that you are undertaking. Access to and the use and copying of any Fire Insurance Maps supplied by ERIS for United States locations are conditioned upon your agreement to, and strict compliance with, the **Fire Insurance Maps-Terms and Conditions.**

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Fire Insurance Map


CERRILLOS RD.
COCHITI
MOTEL UNITS
TILE
GAS REGULATOR
10 UNITS
CLUB
AUTO SERVICE
GAR.
2ND ST.
BERRY AV.
ADD'N
BLOCK
1406
1400
1402
1404
1405
1407
1408
1409
1411
1412
1414
1416
1418
1420
1422
1424
1426
1428
1430
1432
1434
1436
1438
1440
1442
1444
1446
1448
1450
1452
1454
1456
1458
1460
1461
1462
1464
1466
1468
1470
1472
1474
1476
1478
1480
1482
1484
1486
1488
1490
1492
1494
1496
1498
1500
1502
1504
1506
1508
1510
1512
1514
1516
1518
1520
1522
1524
1526
1528
1530
1532
1534
1536
1538
1540
1542
1544
1546
1548
1550
1552
1554
1556
1558
1560
1562
1564
1566
1568
1570
1572
1574
1576
1578
1580
1582
1584
1586
1588
1590
1592
1594
1596
1598
1600
1602
1604
1606
1608
1610
1612
1614
1616
1618
1620
1622
1624
1626
1628
1630
1632
1634
1636
1638
1640
1642
1644
1646
1648
1650
1652
1654
1656
1658
1660
1662
1664
1666
1668
1670
1672
1674
1676
1678
1680
1682
1684
1686
1688
1690
1692
1694
1696
1698
1700
1702
1704
1706
1708
1710
1712
1714
1716
1718
1720
1722
1724
1726
1728
1730
1732
1734
1736
1738
1740
1742
1744
1746
1748
1750
1752
1754
1756
1758
1760
1762
1764
1766
1768
1770
1772
1774
1776
1778
1780
1782
1784
1786
1788
1790
1792
1794
1796
1798
1800
1802
1804
1806
1808
1810
1812
1814
1816
1818
1820
1822
1824
1826
1828
1830
1832
1834
1836
1838
1840
1842
1844
1846
1848
1850
1852
1854
1856
1858
1860
1862
1864
1866
1868
1870
1872
1874
1876
1878
1880
1882
1884
1886
1888
1890
1892
1894
1896
1898
1900
1902
1904
1906
1908
1910
1912
1914
1916
1918
1920
1922
1924
1926
1928
1930
1932
1934
1936
1938
1940
1942
1944
1946
1948
1950
1952
1954
1956
1958
1960
1962
1964
1966
1968
1970
1972
1974
1976
1978
1980
1982
1984
1986
1988
1990
1992
1994
1996
1998
2000
2002
2004
2006
2008
2010
2012
2014
2016
2018
2020
2022
2024
2026
2028
2030
2032
2034
2036
2038
2040
2042
2044
2046
2048
2050
2052
2054
2056
2058
2060
2062
2064
2066
2068
2070
2072
2074
2076
2078
2080
2082
2084
2086
2088
2090
2092
2094
2096
2098
2100
2102
2104
2106
2108
2110
2112
2114
2116
2118
2120
2122
2124
2126
2128
2130
2132
2134
2136
2138
2140
2142
2144
2146
2148
2150
2152
2154
2156
2158
2160
2162
2164
2166
2168
2170
2172
2174
2176
2178
2180
2182
2184
2186
2188
2190
2192
2194
2196
2198
2200
2202
2204
2206
2208
2210
2212
2214
2216
2218
2220
2222
2224
2226
2228
2230
2232
2234
2236
2238
2240
2242
2244
2246
2248
2250
2252
2254
2256
2258
2260
2262
2264
2266
2268
2270
2272
2274
2276
2278
2280
2282
2284
2286
2288
2290
2292
2294
2296
2298
2300
2302
2304
2306
2308
2310
2312
2314
2316
2318
2320
2322
2324
2326
2328
2330
2332
2334
2336
2338
2340
2342
2344
2346
2348
2350
2352
2354
2356
2358
2360
2362
2364
2366
2368
2370
2372
2374
2376
2378
2380
2382
2384
2386
2388
2390
2392
2394
2396
2398
2400
2402
2404
2406
2408
2410
2412
2414
2416
2418
2420
2422
2424
2426
2428
2430
2432
2434
2436
2438
2440
2442
2444
2446
2448
2450
2452
2454
2456
2458
2460
2462
2464
2466
2468
2470
2472
2474
2476
2478
2480
2482
2484
2486
2488
2490
2492
2494
2496
2498
2500
2502
2504
2506
2508
2510
2512
2514
2516
2518
2520
2522
2524
2526
2528
2530
2532
2534
2536
2538
2540
2542
2544
2546
2548
2550
2552
2554
2556
2558
2560
2562
2564
2566
2568
2570
2572
2574
2576
2578
2580
2582
2584
2586
2588
2590
2592
2594
2596
2598
2600
2602
2604
2606
2608
2610
2612
2614
2616
2618
2620
2622
2624
2626
2628
2630
2632
2634
2636
2638
2640
2642
2644
2646
2648
2650
2652
2654
2656
2658
2660
2662
2664
2666
2668
2670
2672
2674
2676
2678
2680
2682
2684
2686
2688
2690
2692
2694
2696
2698
2700
2702
2704
2706
2708
2710
2712
2714
2716
2718
2720
2722
2724
2726
2728
2730
2732
2734
2736
2738
2740
2742
2744
2746
2748
2750
2752
2754
2756
2758
2760
2762
2764
2766
2768
2770
2772
2774
2776
2778
2780
2782
2784
2786
2788
2790
2792
2794
2796
2798
2800
2802
2804
2806
2808
2810
2812
2814
2816
2818
2820
2822
2824
2826
2828
2830
2832
2834
2836
2838
2840
2842
2844
2846
2848
2850
2852
2854
2856
2858
2860
2862
2864
2866
2868
2870
2872
2874
2876
2878
2880
2882
2884
2886
2888
2890
2892
2894
2896
2898
2900
2902
2904
2906
2908
2910
2912
2914
2916
2918
2920
2922
2924
2926
2928
2930
2932
2934
2936
2938
2940
2942
2944
2946
2948
2950
2952
2954
2956
2958
2960
2962
2964
2966
2968
2970
2972
2974
2976
2978
2980
2982
2984
2986
2988
2990
2992
2994
2996
2998
3000
3002
3004
3006
3008
3010
3012
3014
3016
3018
3020
3022
3024
3026
3028
3030
3032
3034
3036
3038
3040
3042
3044
3046
3048
3050
3052
3054
3056
3058
3060
3062
3064
3066
3068
3070
3072
3074
3076
3078
3080
3082
3084
3086
3088
3090
3092
3094
3096
3098
3100
3102
3104
3106
3108
3110
3112
3114
3116
3118
3120
3122
3124
3126
3128
3130
3132
3134
3136
3138
3140
3142
3144
3146
3148
3150
3152
3154
3156
3158
3160
3162
3164
3166
3168
3170
3172
3174
3176
3178
3180
3182
3184
3186
3188
3190
3192
3194
3196
3198
3200
3202
3204
3206
3208
3210
3212
3214
3216
3218
3220
3222
3224
3226
3228
3230
3232
3234
3236
3238
3240
3242
3244
3246
3248
3250
3252
3254
3256
3258
3260
3262
3264
3266
3268
3270
3272
3274
3276
3278
3280
3282
3284
3286
3288
3290
3292
3294
3296
3298
3300
3302
3304
3306
3308
3310
3312
3314
3316
3318
3320
3322
3324
3326
3328
3330
3332
3334
3336
3338
3340
3342
3344
3346
3348
3350
3352
3354
3356
3358
3360
3362
3364
3366
3368
3370
3372
3374
3376
3378
3380
3382
3384
3386
3388
3390
3392
3394
3396
3398
3400
3402
3404
3406
3408
3410
3412
3414
3416
3418
3420
3422
3424
3426
3428
3430
3432
3434
3436
3438
3440
3442
3444
3446
3448
3450
3452
3454
3456
3458
3460
3462
3464
3466
3468
3470
3472
3474
3476
3478
3480
3482
3484
3486
3488
3490
3492
3494
3496
3498
3500
3502
3504
3506
3508
3510
3512
3514
3516
3518
3520
3522
3524
3526
3528
3530
3532
3534
3536
3538
3540
3542
3544
3546
3548
3550
3552
3554
3556
3558
3560
3562
3564
3566
3568
3570
3572
3574
3576
3578
3580
3582
3584
3586
3588
3590
3592
3594
3596
3598
3600
3602
3604
3606
3608
3610
3612
3614
3616
3618
3620
3622
3624
3626
3628
3630
3632
3634
3636
3638
3640
3642
3644
3646
3648
3650
3652
3654
3656
3658
3660
3662
3664
3666
3668
3670
3672
3674
3676
3678
3680
3682
3684
3686
3688
3690
3692
3694
3696
3698
3700
3702
3704
3706
3708
3710
3712
3714
3716
3718
3720
3722
3724
3726
3728
3730
3732
3734
3736
3738
3740
3742
3744
3746
3748
3750
3752
3754
3756
3758
3760
3762
3764
3766
3768
3770
3772
3774
3776
3778
3780
3782
3784
3786
3788
3790
3792
3794
3796
3798
3800
3802
3804
3806
3808
3810
3812
3814
3816
3818
3820
3822
3824
3826
3828
3830
3832
3834
3836
3838
3840
3842
3844
3846
3848
3850
3852
3854
3856
3858
3860
3862
3864
3866
3868
3870
3872
3874
3876
3878
3880
3882
3884
3886
3888
3890
3892
3894
3896
3898
3900
3902
3904
3906
3908
3910
3912
3914
3916
3918
3920
3922
3924
3926
3928
3930
3932
3934
3936
3938
3940
3942
3944
3946
3948
3950
3952
3954
3956
3958
3960
3962
3964
3966
3968
3970
3972
3974
3976
3978
3980
3982
3984
3986
3988
3990
3992
3994
3996
3998
4000
4002
4004
4006
4008
4010
4012
4014
4016
4018
4020
4022
4024
4026
4028
4030
4032
4034
4036
4038
4040
4042
4044
4046
4048
4050
4052
4054
4056
4058
4060
4062
4064
4066
4068
4070
4072
4074
4076
4078
4080
4082
4084
4086
4088
4090
4092
4094
4096
4098
4100
4102
4104
4106
4108
4110
4112
4114
4116
4118
4120
4122
4124
4126
4128
4130
4132
4134
4136
4138
4140
4142
4144
4146
4148
4150
4152
4154
4156
4158
4160
4162
4164
4166
4168
4170
4172
4174
4176
4178
4180
4182
4184
4186
4188
4190
4192
4194
4196
4198
4200
4202
4204
4206
4208
4210
4212
4214
4216
4218
4220
4222
4224
4226
4228
4230
4232
4234
4236
4238
4240
4242
4244
4246
4248
4250
4252
4254
4256
4258
4260
4262
4264
4266
4268
4270
4272
4274
4276
4278
4280
4282
4284
4286
4288
4290
4292
4294
4296
4298
4300
4302
4304
4306
4308
4310
4312
4314
4316
4318
4320
4322
4324
4326
4328
4330
4332
4334
4336
4338
4340
4342
4344
4346
4348
4350
4352
4354
4356
4358
4360
4362
4364
4366
4368
4370
4372
4374
4376
4378
4380
4382
4384
4386
4388
4390
4392
4394
4396
4398
4400
4402
4404
4406
4408
4410
4412
4414
4416
4418
4420
4422
4424
4426
4428
4430
4432
4434
4436
4438
4440
4442
4444
4446
4448
4450
4452
4454
4456
4458
4460
4462
4464
4466
4468
4470
4472
4474
4476
4478
4480
4482
4484
4486
4488
4490
4492
4494
4496
4498
4500
4502
4504
4506
4508
4510
4512
4514
4516
4518
4520
4522
4524
4526
4528
4530
4532
4534
4536
4538
4540
4542
4544
4546
4548
4550
4552
4554
4556
4558
4560
4562
4564
4566
4568
4570
4572
4574
4576
4578
4580
4582
4584
4586
4588
4590
4592
4594
4596
4598
4600
4602
4604
4606
4608
4610
4612
4614
4616
4618
4620
4622
4624
4626
4628
4630
4632
4634
4636
4638
4640
4642
4644
4646
4648
4650
4652
4654
4656
4658
4660
4662
4664
4666
4668
4670
4672
4674
4676
4678
4680
4682
4684
4686
4688
4690
4692
4694
4696
4698
4700
4702
4704
4706
4708
4710
4712
4714
4716
4718
4720
4722
4724
4726
4728
4730
4732
4734
4736
4738
4740
4742
4744
4746
4748
4750
4752
4754
4756
4758
4760
4762
4764
4766
4768
4770
4772
4774
4776
4778
4780
4782
4784
4786
4788
4790
4792
4794
4796
4798
4800
4802
4804
4806
4808
4810
4812
4814
4816
4818
4820
4822
4824
4826
4828
4830
4832
4834
4836
4838
4840
4842
4844
4846
4848
4850
4852
4854
4856
4858
4860
4862
4864
4866
4868
4870
4872
4874
4876
4878
4880
4882
4884
4886
4888
4890
4892
4894
4896
4898
4900
4902
4904
4906
4908
4910
4912
4914
4916
4918
4920
4922
4924
4926
4928
4930
4932
4934
4936
4938
4940
4942
4944
4946
4948
4950
4952
4954
4956
4958
4960
4962
4964
4966
4968
4970
4972
4974
4976
4978
4980
4982
4984
4986
4988
4990
4992
4994
4996
4998
5000
5002
5004
5006
5008
5010
5012
5014
5016
5018
5020
5022
5024
5026
5028
5030
5032
5034
5036
5038
5040
5042
5044
5046
5048
5050
5052
5054
5056
5058
5060
5062
5064
5066
5068
5070
5072
5074
5076
5078
5080
5082
5084
5086
5088
5090
5092
5094
5096
5098
5100
5102
5104
5106
5108
5110
5112
5114
5116
5118
5120
5122
5124
5126
5128
5130
5132
5134
5136
5138
5140
5142
5144
5146
5148
5150
5152
5154
5156
5158
5160
5162
5164
5166
5168
5170
5172
5174
5176
5178
5180
5182
5184
5186
5188
5190
5192
5194
5196
5198
5200
5202
5204
5206
5208
5210
5212
5214
5216
5218
5220
5222
5224
5226
5228
5230
5232
5234
5236
5238
5240
5242
5244
5246
5248
5250
5252
5254
5256
5258
5260
5262
5264
5266
5268
5270
5272
5274
5276
5278
5280
5282
5284
5286
5288
5290
5292
5294
5296
5298
5300
5302
5304
5306
5308
5310
5312
5314
5316
5318
5320
5322
5324
5326
5328
5330
5332
5334
5336
5338
5340
5342
5344
5346
5348
5350
5352
5354
5356
5358
5360
5362
5364
5366
5368
5370
5372
5374
5376
5378
5380
5382
5384
5386
5388
5390
5392
5394
5396
5398
5400
5402
5404
5406
5408
5410
5412
5414
5416
5418
5420
5422
5424
5426
5428
5430
5432
5434
5436
5438
5440
5442
5444
5446
5448
5450
5452
5454
5456
5458
5460
5462
5464
5466
5468
5470
5472
5474
5476
5478
5480
5482
5484
5486
5488
5490
5492
5494
5496
5498
5500
5502
5504
5506
5508
5510
5512
5514
5516
5518
5520
5522
5524
5526
5528
5530
5532
5534
5536
5538
5540
5542
5544
5546
5548
5550
5552
5554
5556
5558
5560
5562
5564
5566
5568
5570
5572
5574
5576
5578
5580
5582
5584
5586
5588
5590
5592
5594
5596
5598
5600
5602
5604
5606
5608
5610
5612
5614
5616
5618
5620
5622
5624
5626
5628
5630
5632
5634
5636
5638
5640
5642
5644
5646
5648
5650
5652
5654
5656
5658
5660
5662
5664
5666
5668
5670
5672
5674
5676
5678
5680
5682
5684
5686
5688
5690
5692
5694
5696
5698
5700
5702
5704
5706
5708
5710
5712
5714
5716
5718
5720
5722
5724
5726
5728
5730
5732
5734
5736
5738
5740
5742
5744
5746
5748
5750
5752
5754
5756
5758
5760
5762
5764
5766
5768
5770
5772
5774
5776
5778
5780
5782
5784
5786
5788
5790
5792
5794
5796
5798
5800
5802
5804
5806
5808
5810
5812
5814
5816
5818
5820
5822
5824
5826
5828
5830
5832
5834
5836
5838
5840
5842
5844
5846
5848
5850
5852
5854
5856
5858
5860
5862
5864
5866
5868
5870
5872
5874
5876
5878
5880
5882
5884
5886
5888
5890
5892
5894
5896
5898
5900
5902
5904
5906
5908
5910
5912
5914
5916
5918
5920
5922
5924
5926
5928
5930
5932
5934
5936
5938
5940
5942
5944
5946
5948
5950
5952
5954
5956
5958
5960
5962
5964
5966
5968
5970
5972
5974
5976
5978
5980
5982
5984
5986
5988
5990
5992
5994
5996
5998
6000
6002
6004
6006
6008
6010
6012
6014
6016
6018
6020
6022
6024
6026
6028
6030
6032
6034
6036
6038
6040
6042
6044
6046
6048
6050
6052
6054
6056
6058
6060
6062
6064
6066
6068
6070
6072
6074
6076
6078
6080
6082
6084
6086
6088
6090
6092
6094
6096
6098
6100
6102
6104
6106
6108
6110
6112
6114
6116
6118
6120
6122
6124
6126
6128
6130
6132
6134
6136
6138
6140
6142
6144
6146
6148
6150
6152
6154
6156
6158
6160
6162
6164
6166
6168
6170
6172
6174
6176
6178
6180
6182
6184
6186
6188
6190
6192
6194
6196
6198
6200
6202
6204
6206
6208
6210
6212
6214
6216
6218
6220
6222
6224
6226
6228
6230
6232
6234
6236
6238
6240
6242
6244
6246
6248
6250
6252
6254
6256
6258
6260
6262
6264
6266
6268
6270
6272
6274
6276
6278
6280
6282
6284
6286
6288
6290
6292
6294
6296
6298
6300
6302
6304
6306
6308
6310
6312
6314
6316
6318
6320
6322
6324
6326
6328
6330
6332
6334
6336
6338
6340
6342
6344
6346
6348
6350
6352
6354
6356
6358
6360
6362
6364
6366
6368
6370
6372
6374
6376
6378
6380
6382
6384
6386
6388
6390
6392
6394
6396
6398
6400
6402
6404
6406
6408
6410
6412
6414
6416
6418
6420
6422
6424
6426
6428
6430
6432
6434
6436
6438
6440
6442
6444
6446
6448
6450
6452
6454
6456
6458
6460
6462
6464
6466
6468
6470
6472
6474
6476
6478
6480
6482
6484
6486
6488
6490
6492
6494
6496
6498
6500
6502
6504
6506
6508
6510
6512
6514
6516
6518
6520
6522
6524
6526
6528
6530
6532
6534
6536
6538
6540
6542
6544
6546
6548
6550
6552
6554
6556
6558
6560
6562
6564
6566
6568
6570
6572
6574
6576
6578
6580
6582
6584
6586
6588
6590
6592
6594
6596
6598
6600
6602
6604
6606
6608
6610
6612
6614
6616
6618
6620
6622
6624
6626
6628
6630
6632
6634
6636
6638
6640
6642
6644
6646
6648
6650
6652
6654
6656
6658
6660
6662
6664
6666
6668
6670
6672
6674
6676
6678
6680
6682
6684
6686
6688
6690
6692
6694
6696
6698
6700
6702
6704
6706
6708
6710
6712
6714
6716
6718
6720
6722
6724
6726
6728
6730
6732
6734
6736
6738
6740
6742
6744
6746
6748
6750
6752
6754
6756
6758
6760
6762
6764
6766
6768
6770
6772
6774
6776
6778
6780
6782
6784
6786
6788
6790
6792
6794
6796
6798
6800
6802
6804
6806
6808
6810
6812
6814
6816
6818
6820
6822
6824
6826
6828
6830
6832
6834
6836
6838
6840
6842
6844
6846
6848
6850
6852
6854
6856
6858
6860
6862
6864
6866
6868
6870
6872
6874
6876
6878
6880
6882
6884
6886
6888
6890
6892
6894
6896
6898
6900
6902
6904
6906
6908
6910
6912
6914
6916
6918
6920
6922
6924
6926
6928
6930
6932
6934
6936
6938
6940
6942
6944
6946
6948
6950
6952
6954
6956
6958
6960
6962
6964
6966
6968
6970
6972
6974
6976
6978
6980
6982
6984
6986
6988
6990
6992
6994
6996
6998
7000
7002
7004
7006
7008
7010
7012
7014
7016
7018
7020
7022
7024
7026
7028
7030
7032
7034
7036
7038
7040
7042
7044
7046
7048
7050
7052
7054
7056
7058
7060
7062
7064
7066
7068
7070
7072
7074
7076
7078
7080
7082
7084
7086
7088
7090
7092
7094
7096
7098
7100
7102
7104
7106
7108
7110
7112
7114
7116
7118
7120
7122
7124
7126
7128
7130
7132
7134
7136
7138
7140
7142
7144
7146
7148
7150
7152
7154
7156
7158
7160
7162
7164
7166
7168
7170
7172
7174
7176
7178
7180
7182
7184
7186
7188
7190
7192
7194
7196
7198
7200
7202
7204
7206
7208
7210
7212
7214
7216
7218
7220
7222
7224
7226
7228
7230
7232
7234
7236
7238
7240
7242
7244
7246
7248
7250
7252
7254
7256
7258
7260
7262
7264
7266
7268
7270
7272
7274
7276
7278
7280
7282
7284
7286
7288
7290
7292
7294
7296
7298
7300
7302
7304
7306
7308
7310
7312
7314
7316
7318
7320
7322
7324
7326
7328
7330
7332
7334
7336
7338
7340
7342
7344
7346
7348
7350
7352
7354
7356
7358
7360
7362
7364
7366
7368
7370
7372
7374
7376
7378
7380
7382
7384
7386
7388
7390
7392
7394
7396
7398
7400
7402
7404
7406
7408
7410
7412
7414
7416
7418
7420
7422
7424
7426
7428
7430
7432
7434
7436
7438
7440
7442
7444
7446
7448
7450
7452
7454
7456
7458
7460
7462
7464
7466
7468
7470
7472
7474
7476
7478
7480
7482
7484
7486
7488
7490
7492
7494
7496
7498
7500
7502
7504
7506
7508
7510
7512
7514
7516
7518
7520
7522
7524
7526
7528
7530
7532
7534
7536
7538
7540
7542
7544
7546
7548
7550
7552
7554
7556
7558
7560
7562
7564
7566
7568
7570
7572
7574
7576
7578
7580
7582
7584
7586
7588
7590
7592
7594
7596
7598
7600
7602
7604
7606
7608
7610
7612
7614
7616
7618
7620
7622
7624
7626
7628
7630
7632
7634
7636
7638
7640
7642
7644
7646
7648
7650
7652
7654
7656
7658
7660
7662
7664
7666
7668
7670
7672
7674
7676
7678
7680
7682
7684
7686
7688
7690
7692
7694
7696
7698
7700
7702
7704
7706
7708
7710
7712
7714
7716
7718
7720
7722
7724
7726
7728
7730
7732
7734
7736
7738
7740
7742
7744
7746
7748
7750
7752
7754
7756
7758
7760
7762
7764
7766
7768
7770
7772
7774
7776
7778
7780
7782
7784
7786
7788
7790
7792
7794
7796
7798
7800
7802
7804
7806
7808
7810
7812
7814
7816
7818
7820
7822
7824
7826
7828
7830
7832
7834
7836
7838
7840
7842
7844
7846
7848
7850
7852
7854
7856
7858
7860
7862
7864
7866
7868
7870
7872
7874
7876
7878
7880
7882
7884
7886
7888
7890
7892
7894
7896
7898
7900
7902
7904
7906
7908
7910
7912
7914
7916
7918
7920
7922
7924
7926
7928
7930
7932
7934
7936
7938
7940
7942
7944
7946
7948
7950
7952
7954
7956
7958
7960
7962
7964
7966
7968
7970
7972
7974
7976
7978
7980
7982
7984
7986
7988
7990
7992
7994
7996
7998
8000
8002
8004
8006
8008
8010
8012
8014
8016
8018
8020
8022
8024
8026
8028
8030
8032
8034
8036
8038
8040
8042
8044
8046
8048
8050
8052
8054
8056
8058
8060
8062
8064
8066
8068
8070
8072
8074
8076
8078
8080
8082
8084
8086
8088
8090
8092
8094
8096
8098
8100
8102
8104
8106
8108
8110
8112
8114
8116
8118
8120
8122
8124
8126
8128
8130
8132
8134
8136
8138
8140
8142
8144
8146
8148
8150
8152
8154
8156
8158
8160
8162
8164
8166
8168
8170
8172
8174
8176
8178
8180
8182
8184
8186
8188
8190
8192
8194
8196
8198
8200
8202
8204
8206
8208
8210
8212
8214
8216
8218
8220
8222
8224
8226
8228
8230
8232
8234
8236
8238
8240
8242
8244
8246
8248
8250
8252
8254
8256
8258
8260
8262
8264
8266
8268
8270
8272
8274
8276
8278
8280
8282
8284
8286
8288
8290
8292
8294
8296
8298
8300
8302
8304
8306
8308
8310
8312
8314
8316
8318
8320
8322
8324
8326
8328
8330
8332
8334
8336
8338
8340
8342
8344
8346
8348
8350
8352
8354
8356
8358
8360
8362
8364
8366
8368
8370
8372
8374
8376
8378
8380
8382
8384
8386
8388
8390
8392
8394
8396
8398
8400
8402
8404
8406
8408
8410
8412
8414
8416
8418
8420
8422
8424
8426
8428
8430
8432
8434
8436
8438
8440
8442
8444
8446
8448
8450
8452
8454
8456
8458
8460
8462
8464
8466
8468
8470
8472
8474
8476
8478
8480
8482
8484
8486
8488
8490
8492
8494
8496
8498
8500
8502
8504
8506
8508
8510
8512
8514
8516
8518
8520
8522
8524
8526
8528
8530
8532
8534
8536
8538
8540
8542
8544
8546
8548
8550
8552
8554
8556
8558
8560
8562
8564
8566
8568
8570
8572
8574
8576
8578
8580
8582
8584
8586
8588
8590
8592
8594
8596
8598
8600
8602
8604
8606
8608
8610
8612
8614
8616
8618
8620
8622
8624
8626
8628
8630
8632
8634
8636
8638
8640
8642
8644
8646
8648
8650
8652
8654
8656
8658
8660
8662
8664
8666
8668
8670
8672
8674
8676
8678
8680
8682
8684
8686
8688
8690
8692
8694
8696
8698
8700
8702
8704
8706
8708
8710
8712
8714
8716
8718
8720
8722
8724
8726
8728
8730
8732
8734
8736
8738
8740
8742
8744
8746
8748
8750
8752
8754
8756
8758
8760
8762
8764
8766
8768
8770
8772
8774
8776
8778
8780
8782
8784
8786
8788
8790
8792
8794
8796
8798
8800
8802
8804
8806
8808
8810
8812
8814
8816
8818
8820
8822
8824
8826
8828
8830
8832
8834
8836
8838
8840
8842
8844
8846
8848
8850
8852
8854
8856
8858
8860
8862
8864
8866
8868
8870
8872
8874
8876
8878
8880
8882
8884
8886
8888
8890
8892
8894
8896
8898
8900
8902
8904
8906
8908
8910
8912
8914
8916
8918
8920
8922
8924
8926
8928
8930
8932
8934
8936
8938
8940
8942
8944
8946
8948
8950
8952
8954
8956
8958
8960
8962
8964
8966
8968
8970
8972
8974
8976
8978
8980
8982
8984
8986
8988
8990
8992
8994
8996
8998
9000
9002
9004
9006
9008
9010
9012
9014
9016
9018
9020
9022
9024
9026
9028
9030
9032
9034
9036
9038
9040
9042
9044
9046
9048
9050
9052
9054
9056
9058
9060
9062
9064
9066
9068
9070
9072
9074
9076
9078
9080
9082
9084
9086
9088
9090
9092
9094
9096
9098
9100
9102
9104
9106
9108
9110
9112
9114
9116
9118
9120
9122
9124
9126
9128
9130
9132
9134
9136
9138
9140
9142
9144
9146
9148
9150
9152
9154
9156
9158
9160
9162
9164
9166
9168
9170
9172
9174
9176
9178
9180
9182
9184
9186
9188
9190
9192
9194
9196
9198
9200
9202
9204
9206
9208
9210
9212
9214
9216
9218
9220
9222
9224
9226
9228
9230
9232
9234
9236
9238
9240
9242
9244
9246
9248
9250
9252
9254
9256
9258
9260
9262
9264
9266
9268
9270
9272
9274
9276
9278
9280
9282
9284
9286
9288
9290
9292
9294
9296
9298
9300
9302
9304
9306
9308
9310
9312
9314
9316
9318
9320
9322
9324
9326
9328
9330
9332
9334
9336
9338
9340
9342
9344
9346
9348
9350
9352
9354
9356
9358
9360
9362
9364
9366
9368
9370
9372
9374
9376
9378
9380
9382
9384
9386
9388
9390
9392
9394
9396
9398
9400
9402
9404
9406
9408
9410
9412
9414
9416
9418
9420
9422
9424
9426
9428
9430
9432
9434
9436
9438
9440
9442
9444
9446
9448
9450
9452
9454
9456
9458
9460
9462
9464
9466
9468
9470
9472
9474
9476
9478
9480
9482
9484
9486
9488
9490
9492
9494
9496
9498
9500
9502
9504
9506
9508
9510
9512
9514
9516
9518
9520
9522
9524
9526
9528
9530
9532
9534
9536
9538
9540
9542
9544
9546
9548
9550
9552
9554
9556
9558
9560
9562
9564
9566
9568
9570
9572
9574
9576
9578
9580
9582
9584
9586
9588
9590
9592
9594
9596
9598
9600
9602
9604
9606
9608
9610
9612
9614
9616
9618
9620
9622
9624
9626
9628
9630
9632
9634
9636
9638
9640
9642
9644
9646
9648
9650
9652
9654
9656
9658
9660
9662
9664
9666
9668
9670
9672
9674
9676
9678
9680
9682
9684
9686
9688
9690
9692
9694
9696
9698
9700
9702
9704
9706
9708
9710
9712
9714
9716
9718
9720
9722
9724
9726
9728
9730
9732
9734
9736
9738
9740
9742
9744
9746
9748
9750
9752
9754
9756
9758
9760
9762
9764
9766
9768
9770
9772
9774
9776
9778
9780
9782
9784
9786
9788
9790
9792
9794
9796
9798
9800
9802
9804
9806
9808
9810
9812
9814
9816
9818
9820
9822
9824
9826
9828
9830
9832
9834
9836
9838
9840
9842
9844
9846
9848
9850
9852
9854
9856
9858
9860
9862
9864
9866
9868
9870
9872
9874
9876
9878
9880
9882
9884
9886
9888
9890
9892
9894
9896
9898
9900
9902
9904
9906
9908
9910
9912
9914
9916
9918
9920
9922
9924
9926
9928
9930
9932
9934
9936
9938
9940
9942
9944
9946
9948
9950
9952
9954
9956
9958
9960
9962
9964
9966
9968
9970
9972
9974
9976
9978
9980
9982
9984
9986
9988
9990
9992
9994
9996
9998
10000
10002
10004
10006
10008
10010
10012
10014
10016
10018
10020
10022
10024
10026
10028
10030
10032
10034
10036
10038
10040
10042
10044
10046
10048
10050
10052
10054
10056
10058
10060
10062
10064
10066
10068
10070
10072
10074
10076
10078
10080
10082
10084
10086
10088
10090
10092
10094
10096
10098
10100
10102
10104
10106
10108
10110
10112
10114
10116
10118
10120
10122
10124
10126
10128
10130
10132
10134
10136
10138
10140
10142
10144
10146
10148
10150
10152
10154
10156
10158
10160
10162
10164
10166
10168
10170
10172
10174
10176
10178
10180
10182
10184
10186
10188
10190
10192
10194
10196
10198
10200
10202
10204
10206
10208
10210
10212
10214
10216
10218
10220
10222
10224
10226
10228
10230
10232
10234
10236
10238
10240
10242
10244
10246
10248
10250
10252
10254
10256
10258
10260
10262
10264
10266
10268
10270
10272
10274
10276
10278
10280
10282
10284
10286
10288
10290
10292
10294
10296
10298
10300
10302
10304
10306
10308
10310
10312
10314
10316
10318
10320
10322
10324
10326
10328
10330
10332
10334
10336
10338
10340
10342
10344
10346
10348
10350
10352
10354
10356
10358
10360
10362
10364
10366
10368
10370
10372
10374
10376
10378
10380
10382
10384
10386
10388
10390
10392
10394
10396
10398
10400
10402
10404
10406
10408
10410
10412
10414
10416
10418
10420
10422
10424
10426
10428
10430
10432
10434
10436
10438
10440
10442
10444
10446
10448
10450
10452
10454
10456
10458
10460
10462
10464
10466
10468
10470
10472
10474
10476
10478
10480
10482
10484
10486
10488
10490
10492
10494
10496
10498
10500
10502
10504
10506
10508
10510
10512
10514
10516
10518
10520
10522
10524
10526
10528
10530
10532
10534
10536
10538
10540
10542
10544
10546
10548
10550
10552
10554
10556
10558
10560
10562
10564
10566
10568
10570
10572
10574
10576
10578
10580
10582
10584
10586
10588
10590
10592
10594
10596
10598
10600
10602
10604
10606
10608
10610
10612
10614
10616
10618
10620
10622
10624
10626
10628
10630
10632
10634
10636
10638
10640
10642
10644
10646
10648
10650
10652
10654
10656
10658
10660
10662
10664
10666
10668
10670
10672
10674
10676
10678
10680
10682
10684
10686
10688
10690
10692
10694
10696
10698
10700
10702
10704
10706
10708
10710
10712
10714
10716
10718
10720
10722
10724
10726
10728
10730
10732
10734
10736
10738
10740
10742
10744
10746
10748
10750
10752
10754
10756
10758
10760
10762
10764
10766
10768
10770
10772
10774
10776
10778
10780
10782
10784
10786
10788
10790
10792
10794
10796
10798
10800
10802
10804
10806
10808
10810
10812
10814
10816
10818
10820
10822
10824
10826
10828
10830
10832
10834
10836
10838
10840
10842
10844
10846
10848
10850
10852
10854
10856
10858
10860
10862
10864
10866
10868
10870
10872
10874
10876
10878
10880
10882
10884
10886
10888
10890
10892
10894
10896
10898
10900
10902
10904
10906
10908
10910
10912
10914
10916
10918
10920
10922
10924
10926
10928
10930
10932
10934
10936
10938
10940
10942
10944
10946
10948
10950
10952
10954
10956
10958
10960
10962
10964
10966
10968
10970
10972
10974
10976
10978
10980
10982
10984
10986
10988
10990
10992
10994
10996
10998
11000
11002
11004
11006
11008
11010
11012
11014
11016
11018
11020
11022
11024
11026
11028
11030
11032
11034
11036
11038
11040
11042
11044
11046
11048
11050
11052
11054
11056
11058
11060
11062
11064
11066
11068
11070
11072
11074
11076
11078
11080
11082
11084
11086
11088
11090
11092
11094
11096
11098
11100
11102
11104
11106
11108
11110
11112
11114
11116
11118
11120
11122
11124
11126
11128
11130
11132
11134
11136
11138
11140
11142
11144
11146
11148
11150
11152
11154
11156
11158
11160
11162
11164
11166
11168
11170
11172
11174
11176
11178
11180
11182
11184
11186
11188
11190
11192
11194
11196
11198
11200
11202
11204
11206
11208
11210
11212
11214
11216
11218
11220
11222
11224
11226
11228
11230
11232
11234
11236
11238
11240
11242
11244
11246
11248
11250
11252
11254
11256
11258
11260
11262
11264
11266
11268
11270
11272
11274
11276
11278
11280
11282
11284
11286
11288
11290
11292
11294
11296
11298
11300
11302
11304
11306
11308
11310
11312
11314
11316
11318
11320
11322
11324
11326
11328
11330
11332
11334
11336
11338
11340
11342
11344
11346
11348
11350
11352
11354
11356
11358
11360
11362
11364
11366
11368
11370
11372
11374
11376
11378
11380
11382
11384
11386
11388
11390
11392
11394
11396
11398
11400
11402
11404
11406
11408
11410
11412
11414
11416
11418
11420
11422
11424
11426
11428
11430
11432
11434
11436
11438
11440
11442
11444
11446
11448
11450
11452
11454
11456
11458
11460
11462
11464
11466
11468
11470
11472
11474
11476
11478
11480
11482
11484
11486
11488
11490
11492
11494
11496
11498
11500
11502
11504
11506
11508
11510
11512
11514
11516
11518
11520
11522
11524
11526
11528
11530
11532
11534
11536
11538
11540
11542
11544
11546
11548
11550
11552
11554
11556
11558
11560
11562
11564
11566
11568
11570
11572
11574
11576
11578
11580
11582
11584
11586
11588
11590
11592
11594
11596
11598
11600
11602
11604
11606
11608
11610
11612
11614
11616
11618
11620
11622
11624
11626
11628
11630
11632
11634
11636
11638
11640
11642
11644
11646
11648
11650
11652
11654
11656
11658
11660
11662
11664
11666
11668
11670
11672
11674
11676
11678
11680
11682
11684
11686
11688
11690
11692
11694
11696
11698
11700
11702
11704
11706
11708
11710
11712
11714
11716
11718
11720
11722
11724
11726
11728
11730
11732
11734
11736
11738
11740
11742
11744
11746
11748
11750
11752
11754
11756
11758
11760
11762
11764
11766
11768
11770
11772
11774
11776
11778
11780
11782
11784
11786
11788
11790
11792
11794
11796
11798
11800
11802
11804
11806
11808
11810
11812
11814
11816
11818
11820
11822
11824
11826
11828
11830
11832
11834
11836
11838
11840
11842
11844
11846
11848
11850
11852
11854
11856
11858
11860
11862
11864
11866
11868
11870
11872
11874
11876
11878
11880
11882
11884
11886
11888
11890
11892
11894
11896
11898
11900
11902
11904
11906
11908
11910
11912
11914
11916
11918
11920
11922
11924
11926
11928
11930
11932
11934
11936
11938
11940
11942
11944
11946
11948
11950

APPENDIX G

Historical City Directories

CITY DIRECTORY

Project Property:	*Danny's Cleaners* *1406 2nd Street* *Santa Fe,NM 87505*
Project No:	*NMENV.M007.SF-WALDO*
Requested By:	*INTERA Incorporated*
Order No:	*25121700732*
Date Completed:	*December 22, 2025*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

December 22, 2025
RE: CITY DIRECTORY RESEARCH
1406 2nd Street
Santa Fe,NM 87505

Thank you for contacting ERIS for an City Directory Search for the site described above. Our staff has conducted a reverse listing City Directory search to determine prior occupants of the subject site and adjacent properties. We have provided the nearest addresses(s) when adjacent addresses are not listed. If we have searched a range of addresses, all addresses in that range found in the Directory are included.

Note: Reverse Listing Directories generally are focused on more highly developed areas. Newly developed areas may be covered in the more recent years, but the older directories will tend to cover only the "central" parts of the city. To complete the search, we have either utilized the ACPL, Library of Congress, State Archives, and/or a regional library or history center as well as multiple digitized directories. These do not claim to be a complete collection of all reverse listing city directories produced.

ERIS has made every effort to provide accurate and complete information but shall not be held liable for missing, incomplete or inaccurate information. To complete this search we used the general range(s) below to search for relevant findings. If you believe there are additional addresses or streets that require searching please contact us at 866-517-5204.

Search Criteria:
BEG-1500 of 2nd St
ALL of Berry Ave
Search Notes:

Search Results Summary

Date	Source	Comment
2023	DIGITAL BUSINESS DIRECTORY	
2020	DIGITAL BUSINESS DIRECTORY	
2016	DIGITAL BUSINESS DIRECTORY	
2012	DIGITAL BUSINESS DIRECTORY	
2008	DIGITAL BUSINESS DIRECTORY	
2003	DIGITAL BUSINESS DIRECTORY	
2000	DIGITAL BUSINESS DIRECTORY	
1996	POLKS	
1993	POLKS	
1988	POLKS	
1983	POLKS	
1978	POLKS	
1973	POLKS	
1968	HUDSPETHS	
1964	HUDSPETHS	
1960	HUDSPETHS	
1955	HUDSPETHS	
1949	HUDSPETHS	
1944	HUDSPETHS	
1940	HUDSPETHS	
1936-37	HUDSPETHS	
1930-31	HUDSPETHS	
1928-29	HUDSPETHS	

2023 2ND ST

SOURCE: DIGITAL BUSINESS DIRECTORY

1401 **RENEWAL HEALTH WELLNESS CLUB**...*BARS*
1402 **GONZALES DENTAL LABORATORY**...*LABORATORIES-DENTAL*
1402 **GONZALES DENTAL LABORATORY**...*DENTAL EQUIPMENT & SUPPLIES-MFRS*
1402 **UNIQUE EXPRESSIONS**...*BEAUTY SALONS*
1403 **BROKEN SPOKE BICYCLE REPAIR**...*BARS*
1404 **GLAMOUR NAILSPA**...*MANICURING*
1404 **HAIR BY ANTHONY VIGIL SALON**...*BEAUTY SALONS*
1404 **IN YOUR DREAMS**...*MANICURING*
1404 **IN YOUR DREAMS**...*BEAUTY SALONS*
1404 **PERSPECTIVES FINE ART FRAMING**...*PICTURE FRAMING*
1404 **PERSPECTIVES FINE ART FRAMING**...*PICTURE FRAMES-DEALERS*
1404 **PILATES PERSUASION**...*HEALTH CLUBS STUDIOS & GYMNASIUMS*
1406 **ALLEN, KELLY**...*ACUPUNCTURE*
1406 **WE THE PEOPLE COMMUNITY ACPNCT**...*CHURCHES*
1409 **NORTH CENTRAL SYSTEM ADMIN OFC**...*NONPROFIT ORGANIZATIONS*
1409 **NORTH CENTRAL SYSTEM ADMIN OFC**...*CHILD CARE SERVICE*
1409 **PRESBYTERIAN MEDICAL SVC**...*CLINICS*
1410 **JAMES HART PHOTOGRAPHY STUDIO**...*PHOTOGRAPHERS-COMMERCIAL*
1411 **EUROPEAN AUTOWERKS**...*AUTOMOBILE REPAIRING & SERVICE*
1411 **EUROPEAN AUTOWERKS**...*AUTOMOBILE RACING CAR EQUIPMENT*
1411 **YOBERRI PARK**...*MOBILE HOMES-PARKS & COMMUNITIES*
1413 **BIONIMICS SOUTHWEST**...*ENVIRONMENTAL & ECOLOGICAL SERVICES*
1413 **QUIVRIA COALITION**...*ENVIRONMENTAL CONSERVATION/ECOLOGCL ORG*
1413 **QUIVRIA COALITION**...*FEDERAL GOVERNMENT CONTRACTORS*
1413 **QUIVRIA COALITION**...*CONSTRUCTION COMPANIES*
1413 **QUIVRIA COALITION**...*ORGANIZATIONS*
1413 **SANTA FE WATERSHED ASSN**...*NON-PROFIT ORGANIZATIONS*
1413 **SANTA FE WATERSHED ASSN**...*FEDERAL GOVERNMENT CONTRACTORS*
1413 **SANTA FE WATERSHED ASSN**...*ENVIRONMENTAL CONSERVATION/ECOLOGCL ORG*
1414 **JEFF SMITH WOODWORKING**...*CABINETS-MANUFACTURERS*
1414 **SANTA FE SILVERWORKS**...*GOLDSMITH & SILVERSMITH PRODUCTS (MFRS)*
1417 **TERESA HERNANDEZ**...*RESIDENTIAL*
1420 **RAMBLIN' CAFE**...*RESTAURANTS*
1424 **BARBARA SALAS**...*RESIDENTIAL*
1424 **BEAUTIFUL SKIN**...*SKIN TREATMENTS*
1424 **BEAUTIFUL SKIN**...*NURSES-PRACTITIONERS*
1424 **BEAUTIFUL SKIN**...*CLINICS*
1424 **GERENA, SHARON**...*DIABETES INFORMATION CENTERS*
1424 **SALAS, BARBARA**...*CLINICS*
1429 **ERIZA ADMINISTRATIVE SVC**...*SERVICES NEC*
1430 **A CAKE ODYSSEY**...*RETAIL BAKERIES*
1430 **MARY WILLIAMS**...*RESIDENTIAL*

2023 BERRY AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

1601 **AMERICAN LEGION**...*VETERANS' & MILITARY ORGANIZATIONS*
1604 **GINGER SAWYER**...*RESIDENTIAL*
1604 **ST ELIZABETH CASA CERRILLOS**...*ASSOCIATIONS*
1604 **ST ELIZABETH CASA CERRILLOS**...*FEDERAL GOVERNMENT CONTRACTORS*
1607 **EUROPEAN AUTOMOTIVE SVC**...*AUTOMOBILE REPAIRING & SERVICE*

2020 2ND ST

SOURCE: DIGITAL BUSINESS DIRECTORY

1401 **RENEWAL HEALTH WELLNESS CLUB**...*BARS*
1401 **RENEWAL HEALTH & WELLNESS CLUB**...*BARS*
1402 **GONZALES DENTAL LABORATORY**...*LABORATORIES-DENTAL*
1402 **GONZALES DENTAL LABORATORY**...*DENTAL EQUIPMENT & SUPPLIES-MFRS*
1402 **UNIQUE EXPRESSIONS**...*BEAUTY SALONS*
1403 **BROKEN SPOKE BICYCLE REPAIR**...*BARS*
1404 **HAIR BY ANTHONY VIGIL SALON**...*BEAUTY SALONS*
1404 **IN YOUR DREAMS**...*MANICURING*
1404 **IN YOUR DREAMS**...*BEAUTY SALONS*
1404 **PERSPECTIVES FINE ART FRAMING**...*PICTURE FRAMING*
1404 **PERSPECTIVES FINE ART FRAMING**...*PICTURE FRAMES-DEALERS*
1404 **PILATES PERSUASION**...*PILATES*
1406 **ALLEN, KELLY**...*ACUPUNCTURE*
1406 **WE THE PEOPLE COMMUNITY ACPNCT**...*CHURCHES*
1409 **NORTH CENTRAL SYSTEM ADMIN OFC**...*CHILD CARE SERVICE*
1409 **NORTH CENTRAL SYSTEM ADMIN OFC**...*NONPROFIT ORGANIZATIONS*
1409 **PRESBYTERIAN MEDICAL SVC**...*CLINICS*
1410 **JAMES HART PHOTOGRAPHY STUDIO**...*PHOTOGRAPHERS-COMMERCIAL*
1411 **EUROPEAN AUTOWERKS**...*AUTOMOBILE RACING CAR EQUIPMENT*
1411 **EUROPEAN AUTOWERKS**...*AUTOMOBILE REPAIRING & SERVICE*
1411 **YOBERRI PARK**...*NONCLASSIFIED ESTABLISHMENTS*
1411 **YOBERRI PARK**...*MOBILE HOMES-PARKS & COMMUNITIES*
1413 **BIONIMICS SOUTHWEST**...*ENVIRONMENTAL & ECOLOGICAL SERVICES*
1413 **MOORE-GARRISON, BETHANY**...*COUNSELORS*
1413 **QUIVRIA COALITION**...*ORGANIZATIONS*
1413 **QUIVRIA COALITION**...*FEDERAL GOVERNMENT CONTRACTORS*
1413 **QUIVRIA COALITION**...*CONSTRUCTION COMPANIES*
1413 **QUIVRIA COALITION**...*ENVIRONMENTAL CONSERVATION/ECOLOGCL ORG*
1413 **SANTA FE WATERSHED ASSN**...*NON-PROFIT ORGANIZATIONS*
1413 **SANTA FE WATERSHED ASSN**...*ENVIRONMENTAL CONSERVATION/ECOLOGCL ORG*
1413 **SANTA FE WATERSHED ASSN**...*FEDERAL GOVERNMENT CONTRACTORS*
1414 **JEFF SMITH WOODWORKING**...*CABINETS-MANUFACTURERS*
1414 **SANTA FE SILVERWORKS**...*GOLDSMITH & SILVERSMITH PRODUCTS (MFRS)*
1417 **TERESA HERNANDEZ**...*RESIDENTIAL*
1420 **RAMBLIN' CAFE**...*RESTAURANTS*
1424 **BEAUTIFUL SKIN**...*SKIN TREATMENTS*
1424 **BEAUTIFUL SKIN**...*CLINICS*
1424 **BEAUTIFUL SKIN**...*NURSES-PRACTITIONERS*
1424 **GERENA, SHARON**...*DIABETES INFORMATION CENTERS*
1424 **SALAS, BARBARA**...*CLINICS*
1424 **SANTA FE NURSE PRACTITIONER**...*CLINICS*
1429 **ERIZA ADMINISTRATIVE SVC**...*SERVICES NEC*
1430 **A CAKE ODYSSEY**...*RETAIL BAKERIES*
1430 **MARY WILLIAMS**...*RESIDENTIAL*
1430 **NEW MEXICO DANCEWEAR**...*DANCING SUPPLIES*

2020 BERRY AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

1601 **AMERICAN LEGION**...*VETERANS' & MILITARY ORGANIZATIONS*
1604 **GINGER SAWYER**...*RESIDENTIAL*
1604 **ST ELIZABETH CASA CERRILLOS**...*ASSOCIATIONS*
1604 **ST ELIZABETH CASA CERRILLOS**...*FEDERAL GOVERNMENT CONTRACTORS*
1607 **EUROPEAN AUTOMOTIVE SVC**...*AUTOMOBILE REPAIRING & SERVICE*

2016 2ND ST

SOURCE: DIGITAL BUSINESS DIRECTORY

0 **EL DORADO TAI CHI**...*MARTIAL ARTS INSTRUCTION*
0 **JAMIE KIRKLAND ART**...*ART GALLERIES & DEALERS*
1401 **QUE BONITA LLC**...*COSMETICS-WHOLESALE*
1401 **RENEWAL HEALTH & WELLNESS CLUB**...*BARS*
1402 **GONZALES DENTAL LABORATORY**...*LABORATORIES-DENTAL*
1402 **GONZALES DENTAL LABORATORY**...*DENTAL EQUIPMENT & SUPPLIES-MFRS*
1402 **UNIQUE EXPRESSIONS**...*BEAUTY SALONS*
1404 **HAIR BY ANTHONY VIGIL SALON**...*BEAUTY SALONS*
1404 **IN YOUR DREAMS**...*MANICURING*
1404 **IN YOUR DREAMS**...*BEAUTY SALONS*
1404 **PERSPECTIVES FINE ART FRAMING**...*PICTURE FRAMING*
1404 **PILATES PERSUASION**...*PILATES*
1405 **I M DESIGN**...*INTERIOR DECORATORS DESIGN & CONSULTANTS*
1405 **JEFFREY WOOD**...*RESIDENTIAL*
1405 **MARISSA WOOD**...*RESIDENTIAL*
1405 **MICHELLE WOOD**...*RESIDENTIAL*
1406 **ALLEN, KELLY**...*ACUPUNCTURE*
1409 **NORTH CENTRAL SYSTEM ADMIN OFC**...*CHILD CARE SERVICE*
1409 **PRESBYTERIAN MEDICAL SVC**...*CLINICS*
1409 **VIDA LANUEVA**...*NONCLASSIFIED ESTABLISHMENTS*
1410 **JAMES HART PHOTOGRAPHY STUDIO**...*PHOTOGRAPHERS-COMMERCIAL*
1411 **EUROPEAN AUTOWERKS**...*AUTOMOBILE RACING CAR EQUIPMENT*
1411 **EUROPEAN AUTOWERKS**...*AUTOMOBILE REPAIRING & SERVICE*
1411 **SANTA FE STAFFING**...*PERSONNEL CONSULTANTS*
1411 **SANTA FE SVC INC**...*EMPLOYMENT CONTRACTORS-TEMPORARY HELP*
1411 **YOBERRI PARK**...*NONCLASSIFIED ESTABLISHMENTS*
1413 **QUIVRIA COALITION**...*FEDERAL GOVERNMENT CONTRACTORS*
1413 **QUIVRIA COALITION**...*ENVIRONMENTAL CONSERVATION/ECOLOGCL ORG*
1413 **SANTA FE WATERSHED ASSN**...*FEDERAL GOVERNMENT CONTRACTORS*
1413 **SANTA FE WATERSHED ASSN**...*ENVIRONMENTAL CONSERVATION/ECOLOGCL ORG*
1414 **JEFF SMITH WOODWORKING**...*CABINETS-MANUFACTURERS*
1417 **TERESA HERNANDEZ**...*RESIDENTIAL*
1420 **RAMBLIN' CAFE**...*RESTAURANTS*
1424 **BEAUTIFUL SKIN**...*SKIN TREATMENTS*
1424 **BEAUTIFUL SKIN**...*NURSES-PRACTITIONERS*
1424 **GERENA, SHARON**...*DIABETES INFORMATION CENTERS*
1424 **KLEBANOFF, NINA A PHD**...*NONCLASSIFIED ESTABLISHMENTS*
1424 **SALAS, BARBARA**...*CLINICS*
1424 **SANTA FE NURSE PRACTITIONER**...*CLINICS*
1429 **ERIZA ADMINISTRATIVE SVC**...*SERVICES NEC*
1430 **A CAKE ODYSSEY**...*RETAIL BAKERIES*
1430 **MARY WILLIAMS**...*RESIDENTIAL*
1430 **NEW MEXICO DANCEWEAR**...*DANCING SUPPLIES*

2016 BERRY AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

1601 **AMERICAN LEGION**...*VETERANS' & MILITARY ORGANIZATIONS*
1601 **CARDTRONICS ATM**...*AUTOMATED TELLER MACHINES*
1604 **GINGER SAWYER**...*RESIDENTIAL*
1604 **ST ELIZABETH CASA CERRILLOS**...*ASSOCIATIONS*
1607 **EUROPEAN AUTOMOTIVE SVC**...*AUTOMOBILE REPAIRING & SERVICE*

2012 2ND ST

SOURCE: DIGITAL BUSINESS DIRECTORY

1402 **GONZALES DENTAL LABORATORY**...*LABORATORIES-DENTAL*
1402 **UNIQUE EXPRESSIONS**...*BEAUTY SALONS*
1403 **BROKEN SPOKE**...*BICYCLES-DEALERS*
1404 **COMPANIONS-A BOUTIQUE & SALON**...*PET WASHING & GROOMING*
1404 **DIVINE CLOTHING**...*CLOTHING-RETAIL*
1404 **HAIR BY ANTHONY VIGIL SALON**...*BEAUTY SALONS*
1404 **IN YOUR DREAMS**...*BEAUTY SALONS*
1404 **PILATES PERSUASION**...*PILATES*
1406 **TIERNAN, MELISSA**...*ACUPUNCTURE*
1406 **WE THE PEOPLE COMMUNITY**...*ACUPUNCTURE*
1409 **NORTH CENTRAL SYSTEM ADMIN OFC**...*CHILD CARE SERVICE*
1409 **PRESBYTERIAN MEDICAL SVC**...*CLINICS*
1409 **VIDA LANUEVA**...*NONCLASSIFIED ESTABLISHMENTS*
1410 **JAMES HART PHOTOGRAPHY STUDIO**...*PHOTOGRAPHERS-COMMERCIAL*
1411 **BUFFALO BUILDERS**...*EMPLOYMENT AGENCIES & OPPORTUNITIES*
1411 **EUROPEAN AUTOWERKS**...*AUTOMOBILE REPAIRING & SERVICE*
1411 **MARCIA OWEN ASSOC LTD**...*EMPLOYMENT AGENCIES & OPPORTUNITIES*
1411 **SANTA FE SVC INC**...*EMPLOYMENT AGENCIES & OPPORTUNITIES*
1413 **EARTH WORKS INSTITUTE**...*ENVIRONMENTAL CONSERVATION/ECOLOGCL ORG*
1413 **QUIVRIA COALITION**...*ENVIRONMENTAL CONSERVATION/ECOLOGCL ORG*
1413 **SANTA FE WATERSHED ASSN**...*ENVIRONMENTAL CONSERVATION/ECOLOGCL ORG*
1414 **JEFF SMITH WOODWORKING**...*CABINETS*
1415 **CECILIA HERNANDEZ**...*RESIDENTIAL*
1417 **TERESA HERNANDEZ**...*RESIDENTIAL*
1417 **THERESA HERNANDEZ**...*RESIDENTIAL*
1420 **RAMBLIN' CAFE**...*RESTAURANTS*
1424 **BEAUTIFUL SKIN**...*NURSES-PRACTITIONERS*
1424 **GERENA, SHARON**...*DIABETES INFORMATION CENTERS*
1430 **SPECTACLE SHOP**...*OPTICAL GOODS-RETAIL*

2012 BERRY AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

1601 **CARDTRONICS ATM**...*AUTOMATED TELLER MACHINES*
1607 **EUROPEAN AUTOMOTIVE SVC**...*AUTOMOBILE REPAIRING & SERVICE*
1607 **REX GOES RACING**...*AUTOMOBILE REPAIRING & SERVICE*

2008 2ND ST

SOURCE: DIGITAL BUSINESS DIRECTORY

1402 **GONZALES DENTAL LABORATORY**...*DENTAL LABORATORY*
1402 **UNIQUE EXPRESSIONS**...*BEAUTY SHOP*
1404 **COMPANIONS**...*PET WASHING & GROOMING*
1404 **COMPANIONS-A BOUTIQUE & SALON**...*PET WASHING & GROOMING*
1404 **HAIR BY ANTHONY VIGIL**...*BEAUTY SALONS*
1404 **IN YOUR DREAMS**...*BEAUTY SALONS*
1404 **NAILS BY KARINA**...*MANICURING*
1404 **SANTA FE NAIL SALON**...*MANICURING*
1404 **TROPHIES PLUS**...*EMBROIDERY*
1406 **DANNYS CLEANERS**...*CLEANERS*
1406 **DANNYS CLEANERS**...*DRYCLEANING PLANT*
1407 **ELUTERIO BARELA**...*RESIDENTIAL*
1409 **HEADSTART**...*CHILD DAY CARE SERVICES*
1409 **NORTH CENTRAL SYSTEM**...*NONCLASSIFIED ESTABLISHMENTS*
1409 **PRESBYTERIAN MEDICAL SVC**...*CHILD CARE SERVICE*
1410 **JAMES HART PHOTOGRAPHY STUDIO**...*PHOTOGRAPHERS-COMMERCIAL*
1411 **MARCIA OWEN ASSOC LTD**...*EMPLOYMENT AGENCIES & OPPORTUNITIES*
1411 **MARCIA OWEN ASSOCIATES LTD**...*EMPLOYMENT AGENCY*
1412 **AZULITO BOUTIQUE**...*RET WOMEN'S CLOTHING*
1413 **B E YOUNG**...*RESIDENTIAL*
1413 **B LANCASTER**...*RESIDENTIAL*
1413 **BIONOMICS SOUTHWEST**...*ENVIRONMENTAL & ECOLOGICAL SERVICES*
1413 **BIONOMICS SOUTHWEST**...*BUSINESS CONSULTING SERVICES*
1413 **CLIFFORD ROSS**...*RESIDENTIAL*
1413 **EARTH WORKS INSTITUTE PLANNING**...*ENVIRONMENTAL CONSERVATION/ECOLOGCL ORG*
1413 **KRIS MUND**...*RESIDENTIAL*
1413 **QUIVIRA COALITION**...*ENVIRONMENTAL CONSERVATION/ECOLOGCL ORG*
1413 **SANTA FE WATERSHED ASSN**...*ENVIRONMENTAL CONSERVATION/ECOLOGCL ORG*
1414 **JEFF SMITH WOODWORKING**...*CABINETS*
1417 **ORLANDO A HERNANDEZ**...*RESIDENTIAL*
1420 **RAMBLIN CAFE**...*RESTAURANTS*
1420 **RAMBLIN CAFE**...*EATING PLACE*
1422 **ARNAL STUDIO**...*PHOTOGRAPHERS-PORTRAIT*
1424 **COMPREHENSIVE DENTAL CARE**...*DENTISTS*
1424 **SANTA FE NURSE PRACTITIONER**...*NURSES-PRACTITIONERS*
1429 **ERIZA ADMINISTRATIVE SVC**...*INSURANCE*
1430 **SPECTACLE SHOP**...*RET OPTICAL GOODS*

2008 BERRY AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

1601 **CORDELIAS**...*RESTAURANTS*
1601 **CORDELIAS RESTAURANT**...*RESTAURANT*
1604 **SPIRIT CLUB**...*INDIVIDUAL/FAMILY SERVICES*
1607 **BARBARA VIALPANDO**...*RESIDENTIAL*
1607 **PAUL E JARMILLO**...*RESIDENTIAL*

2003 2ND ST

SOURCE: DIGITAL BUSINESS DIRECTORY

2 **COMPANIONS-MICHELLE**
2 **UNIQUE EXPRESSIONS**
1402 **GONZALES DENTAL LABORATORY**
1403 **HAIR BY ANTHONY VIGIL**
1403 **IN YOUR DREAMS**...*BEAUTY SCHOOLS*
1404 **EDUARDO'S**
1405 **ALBERT PENA**...*RESIDENTIAL*
1406 **DANNY'S CLEANERS**...*LAUNDRY AND DRYCLEANER AGENTS*
1407 **E BARELA**...*RESIDENTIAL*
1409 **NORTH CENTRAL SYSTEM**
1409 **PRESBYTERIAN MEDICAL SVC**
1409 **SANTA FE HEAD START**
1410 **JAMES HART PHOTOGRAPHY STUDIO**
1411 **BIONOMICS SOUTHWEST**
1411 **QUIVIRA COALITION**...*DWELLING-RELATED ASSOCIATIONS*
1412 **AZULITO BOUTIQUE**
1413 **EARTH'S BIRTHDAY PROJECT**...*DWELLING-RELATED ASSOCIATIONS*
1413 **FOREST GUARDIANS**...*DWELLING-RELATED ASSOCIATIONS*
1413 **JAYE OLIVER DESIGNS**
1413 **SYNC OF SANTA FE**
1414 **BILL LIGHT CARPENTRY**
1414 **JEFF SMITH WOODWORKING**
1417 **ORLANDO A HERNANDEZ**...*RESIDENTIAL*
1420 **RAMBLIN' CAFE**...*STEAK AND BARBECUE RESTAURANTS*
1422 **ARNAL CUSTOM TILE & MASONRY**...*FOUNDATION AND RETAINING WALL CONSTRUCTION*
1422 **ARNAL STUDIO**
1424 **BOWERS GLEN L DDS**...*SPECIALIZED DENTAL PRACTITIONERS*
1424 **COMPREHENSIVE DENTAL CARE**...*SPECIALIZED DENTAL PRACTITIONERS*
1429 **ERIZA ADMINISTRATIVE SVC**
1430 **SPECTACLE SHOP**

2003 BERRY AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

1601 **CORDELIA'S**...*STEAK AND BARBECUE RESTAURANTS*
1604 **SPIRIT CLUB**
1607 **D B BHAKTA**...*RESIDENTIAL*
1607 **JAGS AUTO DETAIL**...*INTERIOR REPAIR SERVICES*

2000 2ND ST

SOURCE: DIGITAL BUSINESS DIRECTORY

416 **A V ELECTRIC**...*ELECTRIC POWER SYSTEMS CONTRACTORS*
1402 **UNIQUE EXPRESSIONS**
1403 **IN YOUR DREAMS**...*BEAUTY SCHOOLS*
1404 **BARBARA THOMAS ACCOUNTING SVC**...*ACCOUNTING SERVICES, EXCEPT AUDITING*
1404 **EDUARDO'S**
1404 **GOLD MINE BOOT & SHOE REPAIR**
1404 **GOLDEN SUN SOLAR & HEATING**
1405 **ALBERT PENA**...*RESIDENTIAL*
1406 **DANNY'S CLEANERS**...*LAUNDRY AND DRYCLEANER AGENTS*
1407 **E BARELA**...*RESIDENTIAL*
1409 **LA NUEVA VIDA**...*COMMUNITY DEVELOPMENT GROUPS*
1409 **PRESBYTERIAN MEDICAL SVC**...*PSYCHIATRISTS AND PSYCHOANALYSTS*
1410 **JAMES HART PHOTOGRAPHY STUDIO**
1413 **EARTH'S BIRTHDAY PROJECT**...*DWELLING-RELATED ASSOCIATIONS*
1413 **FOREST GUARDIANS**...*DWELLING-RELATED ASSOCIATIONS*
1413 **SYNC OF SANTA FE**
1414 **BILL LIGHT WOODWORKING**
1414 **SMITH WOODWORKING**
1417 **ORLANDO A HERNANDEZ**...*RESIDENTIAL*
1420 **RAMBLIN' CAFE**...*STEAK AND BARBECUE RESTAURANTS*
1422 **ARNAL STUDIO**
1424 **SANTA FE PRINTING**...*PROMOTIONAL PRINTING, LITHOGRAPHIC*
1429 **ERISA ADMINISTRATION SVC**
1430 **SPECTACLE SHOP**

2000 BERRY AVE

SOURCE: DIGITAL BUSINESS DIRECTORY

1601 **CORDELIA'S**...*STEAK AND BARBECUE RESTAURANTS*
1604 **SANTA FE COMMUNITY PARTNERSHIP**
1607 **D B BHAKTA**...*RESIDENTIAL*
1607 **JAGS AUTO DETAILING**

2ND ST (SF) 87505

1402 JUST NAILS ..... -3408 C057 982-4901
1402½ PAT GOODWIN'S OFFICE EQUIPMENT
..... -3408 C057 986-1881
1403 FAMILY FOOT HEALTH CTR
..... -3407 C057 988-5057
Gomez Paul ..... -3407 C057 988-5057
1404 Kreitzberg Susan ..... -3408 C057 986-0919
1404½ NATURES WAY CHILDBIRTH
..... -3408 C057 986-0919
1405 Pena Albert ..... -3407 C057 984-2836
1406 DANNY'S CLEANERS ..... -3408 C057 983-3898
1407 Barela Eluter ..... -3407 C057 982-8873
1409 LA NUEVA VIDA ..... -3486 C057 983-9521
1410 JAMES HART PHOTOGRAPHY STUDIO
..... -3408 C057 983-7945
1411 ACUPUNCTURE & ADVANCED BODY WK
..... -3486 C057 988-5688
WESTBROOK UNIVERSITY
..... -3486 C057 988-1427
Weiss Stephen P ..... -3486 C057 988-5688
1414 AMERICAN BURGLAR & FIRE ALARM
..... -3485 C057 988-4989


2ND ST to S 2ND ST

2ND ST cont'd
Address Zip+4 CarRte Phone

BILL LIGHT WOODWORKING
..... -3485 C057 982-8450
1417 Hernandez Orlando A ..... -3486 C057 982-1041
1420 RAMBLIN' CAFE ..... -3485 C057 989-1272
1422 ARNAL STUDIO ..... -3485 C057 983-2410
1424 SANTA FE PRINTING ..... -3485 C057 982-8111
1430 SPECTACLE SHOP ..... -3485 C057 983-6150
1609 Barela Joe ..... -3411 C057 984-1873
1610 Gonzales Billie ..... -3412 C057 983-6484
1614 Martinez Tommy L ..... -3412 C057 820-7277
1708 Ortega Ramon F ..... -3406 C057 982-5627
1710 Fitzsimmons Terren G ..... -3406 C057 983-0534
1714 Wischhusen Lynn ..... -3406 C057 982-8865
1718 Rublo L G ..... -3406 C057 982-6381
1719 HILL POTTERY ..... -3405 C057 984-0028
1725 Anaya Eugenio ..... -3405 C057 982-1752
1727 Sandoval Amadeo ..... -3405 C057 983-4133
1731 ALEX & MICHAEL'S HAIR SALON
..... -3405 C057 982-4208
Montoya Morris ..... -3405 C057 983-6569
Paz Esmera ..... -3405 C057 982-2530
1732 GOLD CROSS AMBULANCE SVC
..... -3406 C057 982-9881
1800 ARIUS SANTA FE ART TILE
..... -3848 C057 988-8966
ARIUS TILE CO ..... -3848 C057 988-8967
1802 OHORI'S COFFEE TEA WAREHOUSE
..... -3848 C057 984-2292
SANTA FE AUTO DETAIL INC
..... -3848 C057 984-1123
TOY AUTO MAN ..... -3848 C057 983-9463
1805 CLIFF CLOUD ART SPACE

1996 BERRY AVE

SOURCE: POLKS



1993 2ND ST

SOURCE: POLKS

2D ST –FROM 2100 CERRILLOS RD SOUTHEAST TO A T & S F RY

17

• ZIP CODE 87501
1402 JUST NAILS 982-4901
P C OFFICE EQUIPMENT INC
1403 FOOT HEALTH CENTER DE SANTA FE 988-5057
1404 GOLDEN SUN SOLAR 982-9899
DOVER ELEVATOR CO equip & sups 982-0911
1406 DANNY'S CLEANERS 983-3898
1407 Barela Eluterio & Genevieve L 9+ ◎ 982-8873
• BERRY ST INTERSECTS
1409 LA NUEVA VIDA social serv agcy 983-9521
Rear★Middleton Glen D 989-9604
1410 DIAZ ORLANDO PHOTOGRAPHY 983-7945
HART JAMES PHOTOGRAPHY 983-7945
1411 Vacant
1414 ALL AMERCICAN BURGALAR ALARM
1414½ AMERICAN BURGLAR & FIRE ALARM CO 988-4989
1415 Hernandez Joe M 9+ ◎
1417 Hernandez Orlando A 9+ ◎ 982-1041
Hernandez Theresa N 982-1041
1420 DE CHADENEDES FLOWERS LTD ret florist 982-9697
1422 ARNAL STUDIO 983-2410
1424 P I P PRINTING 982-8250
1429 Not Verified
1430 SPECTACLE SHOP THE optical 983-6160
• JAY INTERSECTS
1609 Barela Joe H 7 ◎ 984-1873
1610 CABINET & SAW FILING SHOP 983-6484
Gonzales Billy 2 ◎ 983-6484
1614 Yolando 2
1618 Not Verified
• QUAPAW INTERSECTS
1701 Zinn Damon G 9+ ◎ 982-9725
1704 Lopez Gene 9+ ◎ 983-2885
1707 Apartments
1 Vacant
3 Not Verified
1708 Ortega Ramon F & Lorenzita 9+ ◎ 982-5627
1710 No Return
1712 Segovia Jos P 2
1714 Wischhusen Lynn D 2 ◎ 982-8865
1716 Lopez Fidel 9+ ◎ 983-4318
1716½ Vacant
1718 Griego Lucy L 9+ ◎ 982-6381
Griego Mary Jane 982-6381
1719 Vacant
1721 Encinias Robert 3
1723 SECRETARY THE 984-2215
1725 DAVE'S BODY SHOP auto repr 982-1752
Anaya Dave E & Lola A 4 ◎ 982-1752
1729a-1729b Not Verified (2 Hses)
• LENA ST INTERSECTS
1731 Montoya Morris C & Rick T 2 ◎ 983-6569
Martinez Theresa 983-6569
1732 C & H AMBULANCE SERVICE 982-9881
Chavez Joseph & Lori 4
1733 Vacant
• HOPEWELL INTERSECTS
1802 SANTA FE AUTO DETAIL auto cosmetic specialists 984-1123
1805 Not Verified
1807 SECOND STREET STUDIOS real est dev 984-3000

1993 BERRY AVE
SOURCE: POLKS

BERRY AV -FROM DEAD END NORTH OF 2D SOUTHWEST TO 1501 6TH ST

• ZIP CODE 87501
1601 CORDELIA'S RESTAURANT 988-1303
1604 RECOVERY OF ALCOHOLICS PROGRAM 988-4481
1605★Carter Paul & Dorothy
1607-1609 Vacant (2 Hses)
• 2D INTERSECTS
• 3D INTERSECTS
• 4TH INTERSECTS
• 5TH INTERSECTS
• 6TH INTERSECTS
1 HOUSEHOLD
2 BUSINESSES

1988 2ND ST
SOURCE: POLKS

2D ST -FROM 2100 CERRILLOS RD SOUTHEAST TO A T & S F RY

ZIP CODE 87501
1402 Shear Artistry hairdresser 988-2280
1403 Foot Health Center De Santa Fe 988-5057
1404 Professional Service Industries Inc eng serv 984-1367
Dover Elevator Co equip & sups 982-0911
1404a Type Room The typesetting paste-up & design 982-2779
1405 Vacant
1406 Danny's Cleaners 983-3898
1407 Barela Eluterio ◎ 982-8873
1409 Katrina L Smithback Felderkrais Practitioner movement classes 983-3919
Graphic Word The graphic design studio 988-1464
1409c Morningstar Amadea nutrition counseling 984-0187
1409m Swain Irene masseuse
1409n Color Studio The cosmetic salon 982-1160
Rear★Hendler Frank
Rear★Middleton Glen
BERRY INTERSECTS
1411 El Puente Inc eng consit 982-3742
1412 Purolator Courier del serv 983-1089
1414 Croff Interiors 984-1837
Light Bill Carpentry carpentry woodshop 982-8450
1414½ American Burglar & Fire Alarm Co 988-4989
1415 Hernandez Joe M ◎ 983-3970
1417 Hernandez Theresa N ◎ 982-1041
1420 De Chadenedes Flowers Ltd ret florist 982-9697
1422 Arnal Studio 983-2410
1424 P I P Printing 982-8250
1428 C & D Signs & Rubber Stamp Co 989-8494
1430 Spectacle Shop The optical 983-6150
JAY INTERSECTS
1606 Abeyta Abel A 983-4218
1609 Barela Joe H ◎ 984-1873
1610 Gonzales Billy Carpenter & Sawfiling Shop 983-6484
Gonzales Billy ◎ 983-6484
1614★Tena Chris J 986-0958
1618 Quintana Cruz M 988-2546
QUAPAW INTERSECTS
1701 Zinn Damon G 982-9725
1704 Lopez Gene ◎ 983-2885
1707 Apartments
1 Vacant
2 Navvaiz Hiploito 988-4216
3 Vacant
1708 Ortega Ramon F ◎ 982-5627

BERRY AV -FROM DEAD END SOUTH WEST TO 1500 6TH ST

ZIP CODE 87501

1601 Cordedia's Restaurant 988-1303

1604 Recovery Of Alcoholics Program 988-7297

1607 Vacant

1609 Vacant

2D INTERSECTS

1738 White Iris Studio yoga studio 982-5399

1740 Warrier Priest Arts martial arts sch 984-8176

Santa Fe Martial Arts Supply martial arts sup 984-8176

3D INTERSECTS

4TH INTERSECTS

5TH INTERSECTS

6TH INTERSECTS

2D ST —FROM 2100 CERRILLOS RD SOUTHEAST TO A T & S F RY

ZIP CODE 87501
1402 Hair In Santa Fe beauty shop 982-3211
Dover Elevator Co install elev 982-0911
1403 Vacant
1404 A T L Engineering Servs civil eng 984-1367
Valdez Engineering & Testing civil engineering 982-8616
1404a Grand Slam Sports sporting goods 988-5605
1405 Abeyta Richd
1406 Danny's Cleaners 983-3898
1407 Barela Eluterio ◎ 982-8873
BERRY INTERSECTS
1412 Ancient City Interiors Inc carpets & rug clns 982-1862
1414 Furniture Brokers Southwest furn 984-1837
1414½ American Burglar & Fire Alarm Co 988-4989
1415 Hernandez Joe M ◎ 988-3177
1416 Anaya Plumbing & Htg 983-3535
1417 Hernandez Theresa N ◎ 982-1041
1418 Castaways Second Hand Store 983-3535
JAY INTERSECTS
1506 Under Constn
1511 Vacant
Sena Nazario ◎ 471-9280
1606★Abeyta Abel
1609 Corky's Wrecker Service Inc 983-3918
Ashbaugh Tillman H ◎ 983-3918
1610 Gonzales Billy Carpenter & Sawfiling Shop 983-6485
Gonzales Billy ◎ 983-6484
1618 Quintana Cruz M 988-2546
QUAPAW INTERSECTS
1701 Zinn Damon G 982-9725
1704 Lopez Gene ◎ 983-2885
1707★Moya Irene 983-6776
Marofo Concha
1708 Ortega Ramon F ◎ 982-5627
1710 Lopez Conelio ◎ 982-5464
1712 Larranaga Tommy ◎ 988-3265
1714 Abeyta Alfonso J ◎ 982-1609
1716 Lopez Fidel ◎ 982-1887
1718 Griego Manuel V ◎ 982-2852
1719 Tafoya Ambrosio ◎ 983-3273
1721★Encinias Robert Jr ◎
1723 Holm's Lapidary 988-4667
1725 Anaya Eugenio ◎ 982-1752
1727 Gutierrez Jose ◎
1729 Portillo Lorenzo 982-9436
1731 Chief Mike's Chain Saw Repair 983-1292
Montoya Morris 983-6520
LENA ST INTERSECTS
1732 C & H Ambulance Service Inc 982-9881
Chavez Joseph ◎ 982-9881
HOPEWELL INTERSECTS
1800 Goodman's Len Office business brokers 982-2621

BERRY AV —FROM DEAD END SOUTH WEST TO 1500 6TH ST

ZIP CODE 87501
1601 Leyba Jerry J ◎ 982-0561
1602 Romero Doroteo ◎
1607 Falaris Nick ◎ 983-6956
1609 Barela E ◎ 982-8873
2D INTERSECTS
1740★Bouravet Jim
3D INTERSECTS
4TH INTERSECTS
5TH INTERSECTS
6TH INTERSECTS

2D ST —FROM 2100 CERRILLOS RD SOUTHEAST TO A T & S F RY

ZIP CODE 87501
1402 Auto Sound
Vacant
1404 Hunter Hayes Dover Elevator Co install & mtce 982-0911
Miguel's Styling Salon 982-3211
1405★Carter Danl E ◎ 983-5188
1406 Danny's Cleaners 983-3898
1407 Barela Eluterio ◎ 982-8873
BERRY INTERSECTS
1415 Hernandez Joe M ◎ 988-3177
1416 Tee Pee Tee Vee
1417 Hernandez Theresa N
1418 Anaya Plumbing & Heating 983-3535
JAY INTERSECTS
1506★Palmanteer Ted D
1511 Sena Nazario
1606 Abeyta Arthur A ◎ 983-4218
1609 Corky's Wrecker Service Inc 983-3918
Ashbaugh Tillman H ◎ 983-3918
1610 Gonzales Billy ◎ 983-6484
Gonzales Billy Carpenter & Sawfiling Shop 983-6485
1618★Quintana Cruz 988-2546
QUAPAW INTERSECTS
1701★Martinez Rudy E
1704 Lopez Gene ◎ 983-2885
1707 No Return
Manahan David
1708 Ortega Ramon F ◎ 982-5627
1710 Lopez Conelio ◎ 982-5464
1712 Larranaga Tommy ◎ 988-3265
1714 Abeyta Alfonso J ◎ 982-1609
1716 Lopez Fidel ◎ 982-2700
1718 Griego Manuel V ◎ 982-2852
1718a Chavez Joe 982-2583
1719 Tafoya Ambrosio ◎ 983-3273
1721 Sanchez Celedonia 982-9240
1723 Holm's Lapidary 988-4667
1725 Anaya Eugenio ◎ 982-1752
1731 Josie's Best Tortillas Factory 983-6520
Montoya Morris 983-6520
LENA ST INTERSECTS
1732 C & H Ambulance Service Inc 982-2583
Chavez Joe ◎ 983-7138
HOPEWELL INTERSECTS
1800 Arius Tile 988-8966
1802 Electronic Service 983-8149
Mfrs Santa Fe Door & Window Co james a lanphere pres 982-3641
1805 Empire Block Compary bldg materials 982-9838
Fireplace Shop Inc
Architectural Products Of N M 982-3641
2021 Empire Block Co (Plant) 988-1869
end Colony Materials Inc ready mix concrete 988-9871

BERRY AV —FROM DEAD END SOUTH WEST TO 1500 6TH ST

ZIP CODE 87501
1601 Leyba Jerry J ◎ 982-0561
1602 Romero Doroteo ◎
1603 Romero Patricia A
1607 Falaris Nick ◎ 983-6956
1609 Barrela Eluterio ◎ 982-8873
1609a★Payne Danny
2D INTERSECTS
3D INTERSECTS
4TH INTERSECTS
5TH INTERSECTS
6TH INTERSECTS

2D ST —FROM 2100 CERRILLOS RD SOUTHEAST TO A T & S F RY

ZIP CODE 87501

1402 ★ Garcia Donald
1404 Hunter Hays Elevator Co install & mtce 982-0911
1405 ★ Tapia Billy
1406 Danny's Cleaners 983-3898
1415 ★ Hernandez M Jr
1417 Hernandez Adolfo ◎ 982-1041
1418 Williams Curly Auto Parts No 2 983-5446

BERRY INTERSECTS

1506 Sanchez Adrienne L Mrs ◎
1507 Associated Business Consultants tax research accts 983-1135
Gallegos Evelyn A notary public 983-1135
1511 Sena Nazario ◎ 982-8352

JAY INTERSECTS

1606 ★ Abeyta Arthur A ◎
1609 Ashbaugh T H 983-3918
1610 Gonzales Billy ◎ 983-3918
1618 ★ Aralano Evelyn

QUAPAW INTERSECTS

1701 Sandoval Edw A 983-8040
1704 Lopez Gene ◎
1707 Apartments
1 ★ Abeyta Stella F Mrs
2 Veteto Beulah 983-2609
3 Wright Manuelita 982-9298
1708 Ortega Ramon F 982-5627
1710 Lopez Cornelio ◎ 982-3370
1716 Lopez Fidel ◎
1718 ★ Griego Manuel V ◎ 982-2852
1718a ★ Griego Arthur J 988-2063
1719 Tafoya Ambrosio ◎
1721 ★ Blea Sela M Mrs ◎
1725 Anaya Eugenio ◎ 982-1752
1727 Sandoval Amadeo ◎ 983-4133
1729 Blue Feather Press 983-2776

BERRY AV —FROM DEAD END SOUTH WEST TO 1500 6TH ST

ZIP CODE 87501

1601 Leyba Jerry J ◎ 982-0561
1603 Romero Doroteo ◎ 983-9784
1607 Falaris Nick ◎ 983-6956

2D INTERSECTS

3D INTERSECTS

4TH INTERSECTS

5TH INTERSECTS

6TH INTERSECTS

1968 2ND ST

SOURCE: HUDSPETHS

31

2D ST -FROM 2100
CERRILLOS RD SOUTHEAST
TO A T & S F RY

---ZIP CODE 87501
1402 MOYA DAN • 983-3898
1404 HUNTER HAYS ELEVATOR
CO INSTALL & MTCE
982-0911
1405 BARELA ELUTERIO
983-4698
1405½ VACANT
1406 DANNY'S CLEANERS
983-3898
1417 HERNANDEZ ADOLFO JR
• 982-1041
1418 HANDY WAY MARKET &
LIQUORS GRO
983-6670
LOPEZ PATRICK •
983-6670
---BERRY INTERSECTS
1506 SANCHEZ ADRIENNE L
MRS • 982-8780
1511 SENA NAZARIO •
982-1697
---JAY INTERSECTS
1606 MERCEDES BEAUTY SHOP
982-9638
KOLB VICTOR J •
982-9638
1609 GARDNER JERRY
1610 GONZALES BILLY •
983-6484
1618 HARVEY ROBERT B •
983-9453
---QUAPAW INTERSECTS
1701 CONO IGNACIO
1704 LOPEZ GENE •
1707 APARTMENTS
1 AUSTIN FRANK
982-4910
2 VACANT
3 WIGHT MANUELITA
982-9298
1708 ORTEGA RAMON F •
943-4480
1710 LOPEZ CORENLIO •
1716 LOPEZ FIDEL •
983-6840
1718 GRIEGO MANUEL V •
983-9341
1719 TAFOYA AMBROSIO •
1721 SANCHEZ SELA MRS MRS
• 982-3321
1725 ANAYA EUGENIO •
982-1752
1727 SANDOVAL AMADEO •
983-4133

1968 BERRY AVE

SOURCE: HUDSPETHS

31

BERRY AV -FROM DEAD END
SOUTH WEST TO 1500 6TH
ST

---ZIP CODE 87501
1601 LEYBA JERRY J •
982-0561
1602 ROMERO DOROTEO •
983-9784
1607 FALARIA NICK •
983-6956
---2D INTERSECTS
---3D INTERSECTS
---4TH INTERSECTS
---5TH INTERSECTS
---6TH INTERSECTS

1964 2ND ST

SOURCE: HUDSPETHS

Tels. 982-314

17

2D ST -FROM 2100
CERRILLOS RD SOUTHEAST
TO AT&SFRY

1402 MOYA DAN • 983-3898
1405 GILLIAM BILL
1404 VACANT
1406 DANNY'S CLEANERS
983-3898
1417 HERNANDEZ ADOLFO JR
• 982-1041
HERNANDEZ JOSE •
1418 LOPEZ PATRICK •
983-6670
---BERRY INTERSECTS
1506 SANCHEZ ADRIENNE L
MRS • 982-8780
1511 SENA NAZARIO •
982-1697
---JAY INTERSECTS
1606 MERCEDE'S BEAUTY
SHOP 982-9638
KCLB VICTOR J •
982-9638
1609 HERRERA JOSE M
1610 GONZALES BILLY •
983-6484
1618 HARVEY ROBERT B •
983-9453
---QUAPAW INTERSECTS
1701 BRITO GEO E 983-7539
1704 LOPEZ GENE •
1 VACANT
2 TRIMMER LENARD E
982-2868
3 AUSTIN FRANK
1708 ORTEGA RAMON F •
943-4480
1710 MONTOYA CLYDE
1716 LOPEZ FIDEL •
983-4820
1718 GRIEGO MANUEL V •
983-9341
1719 TAFOYA AMBROSIO •
1721 SANCHEZ SELA MRS •
982-3321
1725 ANAYA EUGENIO •
982-1752
1727 SANDOVAL AMADEL •
983-4133
1729 MENDOZA SALOMON GENL
CONTR • 982-0772
1729½ ARTS & CRAFT
1800 PROKOSCH ELECTRIC
COMPANY 1800 2ND ST
982-0471
1802 VACANT
---HOPEWELL INTERSECTS
2021 WESTERN EMPIRE BLOCK
CO (PLANT) 983-6819

1964 BERRY AVE

SOURCE: HUDSPETHS

17

BERRY AV -FROM DEAD END
SOUTH WEST TO 1500 6TH

---2D INTERSECTS
---3D INTERSECTS
---4TH INTERSECTS
---5TH INTERSECTS
---6TH INTERSECTS
1601 LEYBA JERRY J •
982-0561
1602 ROMERO DOROTES •
983-9784
1607 FALARIA NICK •
983-6956

2D —From 2100 Cerrillos rd south

1402 Moya Dan ◎ ΔYU3-3898
1404 Coffee's Chain Saw Shop ΔYU3-3662
1405 Vacant
1406 Danny's Drive In Clns ΔYU3-3878
1417 Hernandez Adolfo ◎ ΔYU3-3440
1418 Handy Way Mkt gro Lopez Pat S ◎ ΔYU3-6670

Jay intersects

1506 Sanchez Adrienne Mrs ◎ ΔYU2-0322
1511 Sena Nazario ◎ ΔYU2-1697
1606 Kolb Victor J ◎
1609 Todd Kenneth L ◎ ΔYU3-3152
1610 Gonzalez Billy ◎ ΔYU3-6484
1618 Harvey Robt B ◎ ΔYU3-9453

Quapaw intersects

1701 Callahan Riley D Mrs ◎ ΔYU2-5960
1704 Lopez Gene ◎ ΔYU3-6628
1707 Ingram Buford W ◎ ΔYU3-7829
1708 Ortega Ramon F ◎ ΔYU3-4480
1710 Lopez Cornelio ◎
1716 Lopez Fidel ◎
1718 Griego Manuel V ◎ ΔYU3-9341
1719 Tafoya Ambrosio ◎
1721 Romero Carlos
1725 Anaya Eugenio ◎
1727 Abeyta J E ◎
1729 Mendoza Solomon ◎ ΔYU3-7638
1731 Vacant
1732 Leyba Benny contr ◎ ΔYU2-2370
1800 Santa Fe Stge & Transfer Co ΔYU3-7511
Aero Mayflower Transit Co ΔYU3-7511

Hopewell intersects

2022 Barela Eluterio ◎ ΔYU3-4698
end Hovey Concrete Prod Co ΔYU3-4301
Empire Block Co ΔYU3-6819

3D-
15
15
16
16
16
17
17
17
17
17
17
17
17
17
4T
1
1
1
1
1
1
1
1
1
1
1
5T
1
1
1
1

SANTA FE, N. M.

BERRY AV—From Cochiti west to 6th, 1 south of Cerrillos rd

2d intersects
3d intersects
4th intersects
5th intersects
6th intersects

13

2D—From 2100 Cerrillos rd south

1402 Moya Dan © 3-3898
1405 Roemro Pat J
1417 Hernandez Adolfo ©
1418 Handy Way Mkt gro 3-7913
Lopez Pat S ©

Jay intersects

1506 Sanchez Ernest J ©
1511 Sena Nacario ©

13

BERRY AV — From Cochiti west to 6th, 1 south of Cerrillos rd


1601 Mejia Socorro © 3-8267
1602 Romero Doroteeo
1607 Varela Eluterio ©
1609 Ortega Mariano jr 3-6997

2d intersects
3d intersects
4th intersects
5th intersects
6th intersects

2

1949 2ND ST

SOURCE: HUDSPETHS



SECOND — Begins 2100 Cerrillos rd ext south

309 Groves John D ⓪
403 Ingram Walter ⓪
1406 Oshel H D ⓪
1417 Ortiz Polly ⓪
2022 Barela Eleuterio ⓪

13

1949 BERRY AVE

SOURCE: HUDSPETHS

STREET NOT LISTED

1944 2ND ST

SOURCE: HUDSPETHS

STREET NOT LISTED

1944 BERRY AVE

SOURCE: HUDSPETHS

STREET NOT LISTED

1940 2ND ST

SOURCE: HUDSPETHS

STREET NOT LISTED

1940 BERRY AVE

SOURCE: HUDSPETHS

STREET NOT LISTED

1936-37 2ND ST

SOURCE: HUDSPETHS

STREET NOT LISTED

1936-37 BERRY AVE

SOURCE: HUDSPETHS

STREET NOT LISTED

1930-31 2ND ST

SOURCE: HUDSPETHS

STREET NOT LISTED

1930-31 BERRY AVE

SOURCE: HUDSPETHS

STREET NOT LISTED

1928-29 2ND ST

SOURCE: HUDSPETHS

STREET NOT LISTED

1928-29 BERRY AVE

SOURCE: HUDSPETHS

STREET NOT LISTED

APPENDIX H

Database Report

DATABASE REPORT

Project Property:	*Danny's Cleaners* *1406 2nd Street* *Santa Fe NM 87505*
Project No:	*NMENV.M007.SF-WALDO*
Report Type:	*Database Report*
Order No:	*25121700732*
Requested by:	*INTERA Incorporated*
Date Completed:	*December 18, 2025*

Environmental Risk Information Services
A division of Glacier Media Inc.
1.866.517.5204 | info@erisinfo.com | erisinfo.com

Table of Contents

Table of Contents.....2
Executive Summary.....3
Executive Summary: Report Summary.....4
Executive Summary: Site Report Summary - Project Property.....8
Executive Summary: Site Report Summary - Surrounding Properties.....9
Executive Summary: Summary by Data Source.....14
Map.....22
Aerial.....25
Topographic Map.....26
Detail Report.....27
Unplottable Summary.....78
Unplottable Report.....81
Appendix: Database Descriptions.....96
Definitions.....111

Notice: IMPORTANT LIMITATIONS and YOUR LIABILITY

Reliance on information in Report: This report DOES NOT replace a full Phase I Environmental Site Assessment but is solely intended to be used as database review of environmental records.

License for use of information in Report: No page of this report can be used without this cover page, this notice and the project property identifier. The information in Report(s) may not be modified or re-sold.

Your Liability for misuse: Using this Service and/or its reports in a manner contrary to this Notice or your agreement will be in breach of copyright and contract and ERIS may obtain damages for such mis-use, including damages caused to third parties, and gives ERIS the right to terminate your account, rescind your license to any previous reports and to bar you from future use of the Service.

No warranty of Accuracy or Liability for ERIS: The information contained in this report has been produced by ERIS Information Inc. ("ERIS") using various sources of information, including information provided by Federal and State government departments. The report applies only to the address and up to the date specified on the cover of this report, and any alterations or deviation from this description will require a new report. This report and the data contained herein does not purport to be and does not constitute a guarantee of the accuracy of the information contained herein and does not constitute a legal opinion nor medical advice. Although ERIS has endeavored to present you with information that is accurate, ERIS disclaims, any and all liability for any errors, omissions, or inaccuracies in such information and data, whether attributable to inadvertence, negligence or otherwise, and for any consequences arising therefrom. Liability on the part of ERIS is limited to the monetary value paid for this report.

Trademark and Copyright: You may not use the ERIS trademarks or attribute any work to ERIS other than as outlined above. This Service and Report (s) are protected by copyright owned by ERIS Information Inc. Copyright in data used in the Service or Report(s) (the "Data") is owned by ERIS or its licensors. The Service, Report(s) and Data may not be copied or reproduced in whole or in any substantial part without prior written consent of ERIS.

Executive Summary

Property Information:

Project Property:		*Danny's Cleaners* *1406 2nd Street Santa Fe NM 87505*
Project No:		*NMENV.M007.SF-WALDO*
Coordinates:		
	Latitude:	*35.66627768*
	Longitude:	*-105.96932056*
	UTM Northing:	*3,947,367.52*
	UTM Easting:	*412,269.50*
	UTM Zone:	*UTM Zone 13S*
Elevation:		*6,847 FT*

Order Information:

Order No:	*25121700732*
Date Requested:	*December 17, 2025*
Requested by:	*INTERA Incorporated*
Report Type:	*Database Report*

Historicals/Products:

Aerial Photographs	*Historical Aerials (with Project Boundaries)*
Chain of Title & Lien Searches	*ASTM E1527-21 Compliant Environmental Lien Search (back to 1980) with Historic Chain of Title (back to 1932)*
City Directory Search	*CD - 2 Street Search*
ERIS Xplorer	*ERIS Xplorer*
Excel Add-On	*Excel Add-On*
Fire Insurance Maps	*US Fire Insurance Maps*
Physical Setting Report (PSR)	*Physical Setting Report (PSR)*
Topographic Map	*Topographic Maps*

Executive Summary: Report Summary

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
Standard Environmental Records								
Federal								
NPL	Y	1	0	0	0	0	0	0
PROPOSED NPL	Y	1	0	0	0	0	0	0
DELETED NPL	Y	0.5	0	0	0	0	-	0
SEMS	Y	0.5	0	0	0	0	-	0
ODI	Y	0.5	0	0	0	0	-	0
SEMS ARCHIVE	Y	0.5	0	0	0	**1**	-	**1**
CERCLIS	Y	0.5	0	0	0	**1**	-	**1**
IODI	Y	0.5	0	0	0	0	-	0
CERCLIS NFRAP	Y	0.5	0	0	0	**1**	-	**1**
CERCLIS LIENS	Y	PO	0	-	-	-	-	0
RCRA CORRACTS	Y	1	0	0	0	0	0	0
RCRA TSD	Y	0.5	0	0	0	0	-	0
RCRA LQG	Y	0.25	0	0	0	-	-	0
RCRA SQG	Y	0.25	0	0	0	-	-	0
RCRA VSQG	Y	0.25	**1**	**3**	**2**	-	-	**6**
RCRA NON GEN	Y	0.25	0	**1**	**1**	-	-	**2**
RCRA CONTROLS	Y	0.5	0	0	0	0	-	0
FED ENG	Y	0.5	0	0	0	0	-	0
FED INST	Y	0.5	0	0	0	0	-	0
LUCIS	Y	0.5	0	0	0	0	-	0
NPL IC	Y	0.5	0	0	0	0	-	0
ERNS 1982 TO 1986	Y	PO	0	-	-	-	-	0
ERNS 1987 TO 1989	Y	PO	0	-	-	-	-	0
ERNS	Y	PO	0	-	-	-	-	0
FED BROWNFIELDS	Y	0.5	0	0	0	0	-	0
FEMA UST	Y	0.25	0	0	0	-	-	0
FRP	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
DELISTED FRP	Y	0.25	0	0	0	-	-	0
HIST GAS STATIONS	Y	0.25	0	0	0	-	-	0
REFN	Y	0.25	0	0	0	-	-	0
BULK TERMINAL	Y	0.25	0	0	0	-	-	0
SEMS LIEN	Y	PO	0	-	-	-	-	0
SUPERFUND ROD	Y	1	0	0	0	0	0	0
State								
SCS	Y	1	0	0	0	**1**	**5**	**6**
DELISTED SCS	Y	1	0	0	0	**1**	**1**	**2**
SWF/LF	Y	0.5	0	0	0	**2**	-	**2**
HIST LF	Y	0.5	0	0	0	0	-	0
RECYCLING	Y	0.5	0	0	0	0	-	0
LST	Y	0.5	0	0	0	**9**	-	**9**
DELISTED LST	Y	0.5	0	0	0	0	-	0
LUST HIST	Y	0.5	0	0	0	**9**	-	**9**
UST	Y	0.25	0	**2**	**3**	-	-	**5**
AST	Y	0.25	0	0	0	-	-	0
TANKS	Y	0.25	0	**2**	**3**	-	-	**5**
UST HIST	Y	0.25	0	**2**	**3**	-	-	**5**
AST HIST	Y	0.25	0	0	0	-	-	0
DELISTED TANK	Y	0.25	0	0	0	-	-	0
INST	Y	0.5	0	0	0	0	-	0
VCP	Y	0.5	0	0	0	**2**	-	**2**
BROWNFIELDS	Y	0.5	0	0	0	0	-	0
Tribal								
INDIAN LUST	Y	0.5	0	0	0	0	-	0
INDIAN UST	Y	0.25	0	0	0	-	-	0
DELISTED INDIAN LST	Y	0.5	0	0	0	0	-	0
DELISTED INDIAN UST	Y	0.25	0	0	0	-	-	0
County	***No County databases were selected to be included in the search.***							

Additional Environmental Records

Federal

PFAS GHG	Y	0.5	0	0	0	0	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
OSC RESPONSE	Y	0.125	0	0	-	-	-	0
FINDS/FRS	Y	PO	**1**	**2**	-	-	-	**3**
TRIS	Y	PO	0	-	-	-	-	0
PFAS NPL	Y	0.5	0	0	0	0	-	0
PFAS FED SITES	Y	0.5	0	0	0	0	-	0
PFAS SSEHRI	Y	0.5	0	0	0	0	-	0
PFAS ERNS	Y	0.5	0	0	0	0	-	0
PFAS NPDES	Y	0.5	0	0	0	0	-	0
PFAS TRI	Y	0.5	0	0	0	0	-	0
PFAS WATER	Y	0.5	0	0	0	0	-	0
PFAS TSCA	Y	0.5	0	0	0	0	-	0
PFAS E-MANIFEST	Y	0.5	0	0	0	0	-	0
PFAS IND	Y	0.5	0	0	0	0	-	0
HMIRS	Y	0.125	0	0	-	-	-	0
NCDL	Y	0.125	0	0	-	-	-	0
TSCA	Y	0.125	0	0	-	-	-	0
HIST TSCA	Y	0.125	0	0	-	-	-	0
FTTS ADMIN	Y	PO	0	-	-	-	-	0
FTTS INSP	Y	PO	0	-	-	-	-	0
PRP	Y	PO	0	-	-	-	-	0
SCRD DRYCLEANER	Y	0.5	0	0	0	0	-	0
ICIS	Y	PO	**1**	-	-	-	-	**1**
FED DRYCLEANERS	Y	0.25	**1**	**1**	0	-	-	**2**
DELISTED FED DRY	Y	0.25	0	0	0	-	-	0
FUDS	Y	1	0	0	0	0	0	0
FUDS MRS	Y	1	0	0	0	0	0	0
FORMER NIKE	Y	1	0	0	0	0	0	0
PIPELINE INCIDENT	Y	PO	0	-	-	-	-	0
MLTS	Y	PO	0	-	-	-	-	0
HIST MLTS	Y	PO	0	-	-	-	-	0
MINES	Y	0.25	0	0	0	-	-	0
SMCRA	Y	1	0	0	0	0	0	0
MRDS	Y	1	0	0	0	0	0	0
LM SITES	Y	1	0	0	0	0	0	0
ALT FUELS	Y	0.25	0	0	0	-	-	0

Database	Searched	Search Radius	Project Property	Within 0.12mi	0.125mi to 0.25mi	0.25mi to 0.50mi	0.50mi to 1.00mi	Total
CONSENT DECREES	Y	0.25	0	0	0	-	-	0
AFS	Y	PO	**1**	-	-	-	-	**1**
SSTS	Y	0.25	0	0	0	-	-	0
PCBT	Y	0.5	0	0	0	0	-	0
PCB	Y	0.5	0	0	0	0	-	0
POWER PLANTS	Y	0.125	0	0	-	-	-	0
HIST RISK	Y	0.125	0	0	-	-	-	0
State								
HAZ	Y	0.5	0	0	0	0	-	0
SPILLS	Y	0.125	0	0	-	-	-	0
SPILLS OIL	Y	0.125	0	0	-	-	-	0
CDL	Y	0.125	0	0	-	-	-	0
PFAS	Y	0.5	0	0	0	0	-	0
GW DISCHARGE	Y	PO	0	-	-	-	-	0
URANIUM	Y	0.5	0	0	0	0	-	0
Tribal	***No Tribal additional environmental record sources available for this State.***							
County	***No County additional environmental record sources available for this State.***							
Total:			***5***	***13***	***12***	***27***	***6***	***63***

**** PO – Property Only***
**** 'Property and adjoining properties' database search radii are set at 0.25 miles.***

Executive Summary: Site Report Summary - Project Property

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
1	AFS	DANNY'S CLEANERS_____ _____??	1406 SECOND STREET SANTA FE NM 87505	SE	0.00 / 0.00	1	27
1	FED DRYCLEANERS	DANNY'S CLEANERS_____ _____??	1406 SECOND STREET SANTA FE NM 87505 ***FRS Facility ID:*** *110001557716*	SE	0.00 / 0.00	1	28
1	FINDS/FRS	DANNY'S CLEANERS_____ _____??	1406 SECOND STREET SANTA FE NM 87505-3408 ***Registry ID:*** *110001557716*	SE	0.00 / 0.00	1	28
1	ICIS	DANNY'S CLEANERS_____ _____??	1406 SECOND STREET SANTA FE NM 87505 ***Registry ID:*** *110001557716*	SE	0.00 / 0.00	1	28
1	RCRA VSQG	DANNYS CLEANERS	1406 SECOND ST SANTA FE NM 87505 ***Handler ID | Recycler Activity?:*** *NMR000003756 | NO*	SE	0.00 / 0.00	1	29

Executive Summary: Site Report Summary - Surrounding Properties

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
2	FINDS/FRS	THOMAS PROPERTY	1407 3RD ST SANTA FE NM 87505 ***Registry ID:*** 110022696572	SW	0.02 / 100.26	-1	31
2	FINDS/FRS	DUNN EDWARD PAINTS NO 120	1407 THIRD STREET SANTA FE NM 87505 ***Registry ID:*** 110070206765	SW	0.02 / 100.26	-1	32
2	RCRA VSQG	DUNN EDWARD PAINTS NO 120	1407 THIRD STREET SANTA FE NM 87505 ***Handler ID | Recycler Activity?:*** NMR000022558 | NO	SW	0.02 / 100.26	-1	32
2	TANKS	THOMAS PROPERTY	1407 3RD ST SANTA FE NM 87505 ***FID | In Use AST | In Use UST:*** 49179 | 0 | 0	SW	0.02 / 100.26	-1	36
2	UST	THOMAS PROPERTY	1407 3RD ST SANTA FE NM 87505 ***Facility ID:*** 49179 ***In Use UST | Removed UST:*** 0 | 1	SW	0.02 / 100.26	-1	36
2	UST HIST	THOMAS PROPERTY	1407 3RD ST SANTA FE NM 87505 ***Facility ID:*** 49179 ***Tank ID | Tank Status:*** 33719 | REMOVED	SW	0.02 / 100.26	-1	37
3	RCRA VSQG	REX GOES RACING	1607 BERRY AVENUE SANTA FE NM 87505 ***Handler ID | Recycler Activity?:*** NMR000012286 | NO	NE	0.03 / 183.59	5	37
4	FED DRYCLEANERS	ASPEN DRY CLEANERS	1616 CERRILLOS ROAD SANTA FE NM 87505 ***FRS Facility ID:*** 110004283267	NNE	0.06 / 317.19	5	40
4	RCRA VSQG	ASPEN DRY CLEANERS	1616 CERRILLOS RD SANTA FE NM 87505 ***Handler ID | Recycler Activity?:*** NMR000004630 | NO	NNE	0.06 / 317.19	5	40
5	RCRA NON GEN	PIP PRINTING	1424 SECOND ST SANTA FE NM 87501 ***Handler ID | Recycler Activity?:*** NMD986676492 | NO	SE	0.08 / 439.73	9	43
6	TANKS	SANTA FE INDIAN HOSPITAL	1700 CERRILLOS RD SANTA FE NM 87501 ***FID | In Use AST | In Use UST:*** 30452 | 0 | 0	NNW	0.11 / 564.20	-6	45
6	UST	SANTA FE INDIAN HOSPITAL	1700 CERRILLOS RD SANTA FE NM 87501 ***Facility ID:*** 30452 ***In Use UST | Removed UST:*** 0 | 1	NNW	0.11 / 564.20	-6	46

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
6	UST HIST	SANTA FE INDIAN HOSPITAL	1700 CERRILLOS RD SANTA FE NM 87501 ***Facility ID:*** 30452 ***Tank ID | Tank Status:*** 30176 | REMOVED	NNW	0.11 / 564.20	-6	46
7	TANKS	EMPIRE BUILDERS SUPPLY CO INC	1802 CERRILLOS RD PO BOX 5134 SANTA FE NM 87502 ***FID | In Use AST | In Use UST:*** 27898 | 0 | 0	WSW	0.15 / 798.17	-13	47
7	UST	EMPIRE BUILDERS SUPPLY CO INC	1802 CERRILLOS RD PO BOX 5134 SANTA FE NM 87502 ***Facility ID:*** 27898 ***In Use UST | Removed UST:*** 0 | 2	WSW	0.15 / 798.17	-13	47
7	UST HIST	EMPIRE BUILDERS SUPPLY CO INC	1802 CERRILLOS RD SANTA FE NM 87502 ***Facility ID:*** 27898 ***Tank ID | Tank Status:*** 24180 | REMOVED, 24181 | REMOVED	WSW	0.15 / 798.17	-13	48
8	RCRA NON GEN	DON JUANS	1410 4TH ST SANTA FE NM 87501 ***Handler ID | Recycler Activity?:*** NMD982760175 | NO	SW	0.16 / 829.78	-7	48
9	RCRA VSQG	MIKE'S GARAGE	1501 5TH ST SANTA FE NM 87505 ***Handler ID | Recycler Activity?:*** NMR000017046 | NO	SW	0.18 / 925.77	-13	51
10	TANKS	VALDEZ PLUMBING AND HEATING INC	1608 4TH ST SANTA FE NM 87501 ***FID | In Use AST | In Use UST:*** 31439 | 0 | 0	SSW	0.18 / 962.82	-3	53
10	UST	VALDEZ PLUMBING AND HEATING INC	1608 4TH ST SANTA FE NM 87501 ***Facility ID:*** 31439 ***In Use UST | Removed UST:*** 0 | 1	SSW	0.18 / 962.82	-3	53
10	UST HIST	VALDEZ PLUMBING AND HEATING INC	1608 4TH ST SANTA FE NM 87501 ***Facility ID:*** 31439 ***Tank ID | Tank Status:*** 32285 | REMOVED	SSW	0.18 / 962.82	-3	54
11	RCRA VSQG	BENS AUTO BODY SERVICES	1520 5TH ST SANTA FE NM 87505 ***Handler ID | Recycler Activity?:*** NMR000006692 | NO	SW	0.23 / 1,216.90	-11	55
12	TANKS	OLD CROSS AMBULANCE SERVICE	1732 SECOND ST SANTA FE NM 87502 ***FID | In Use AST | In Use UST:*** 29740 | 0 | 0	SE	0.24 / 1,256.79	17	57
12	UST	OLD CROSS AMBULANCE SERVICE	1732 SECOND ST SANTA FE NM 87502 ***Facility ID:*** 29740 ***In Use UST | Removed UST:*** 0 | 1	SE	0.24 / 1,256.79	17	57
12	UST HIST	OLD CROSS AMBULANCE SERVICE	1732 SECOND ST SANTA FE NM 87502 ***Facility ID:*** 29740 ***Tank ID | Tank Status:*** 28376 | REMOVED	SE	0.24 / 1,256.79	17	58

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
13	LST	SQUEAKY CLEAN CAR WASH	1900 CERRILLOS RD SANTA FE NM	WSW	0.32 / 1,671.25	-30	58
			***Release ID*	*Facility ID*	*Status:*** 1484	30744	No Further Action, Confirmed Release				
13	LUST HIST	SQUEAKY CLEAN CAR WA	1900 CERRILLOS RD SANTA FE NM	WSW	0.32 / 1,671.25	-30	59
14	LST	1901 CERRILLOS CHEVRON	1901 CERRILLOS RD SANTA FE NM	WSW	0.32 / 1,675.16	-33	60
			***Release ID*	*Facility ID*	*Status:*** 4614	1031	No Further Action, Confirmed Release				
14	SWF/LF	Amigo Tire and Auto	1901 Cerrillos Road, Santa Fe, New Mexico NM	WSW	0.32 / 1,675.16	-33	61
15	LST	TECHLINE STUDIO	1418 CERRILLOS RD SANTA FE NM	NE	0.32 / 1,694.70	24	61
			***Release ID*	*Facility ID*	*Status:*** 2068	31028	No Further Action, Confirmed Release				
15	LUST HIST	TECHLINE STUDIO	1418 CERRILLOS RD SANTA FE NM	NE	0.32 / 1,694.70	24	62
16	LST	SHUTTLEJACK	1600 LENA RD SANTA FE NM	E	0.33 / 1,740.35	35	62
			***Release ID*	*Facility ID*	*Status:*** 2661	30595	No Further Action, Confirmed Release				
16	LUST HIST	SHUTTLEJACK	1600 LENA RD SANTA FE NM	E	0.33 / 1,740.35	35	64
17	LST	SANTA FE BULK PLANT	1404 CERRILLOS RD SANTA FE NM	NE	0.36 / 1,919.48	31	64
			***Release ID*	*Facility ID*	*Status:*** 1765	1778	No Further Action, Confirmed Release				
17	LUST HIST	SANTA FE BULK PLANT	1404 CERRILLOS RD SANTA FE NM	NE	0.36 / 1,919.48	31	65
18	DELISTED SCS	Fmr White Swan Laundry Facility	1368 Cerrillos Road Santa Fe NM	NE	0.40 / 2,090.82	37	65
18	VCP	White Swan Laundy	1368 Cerrillos Road Santa Fe NM	NE	0.40 / 2,090.82	37	66
19	SWF/LF	Discount Tire (Santa Fe - North)	1366 Cerrillos Road, Santa Fe, New Mexico 87505 NM	NE	0.40 / 2,134.44	31	66

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
20	CERCLIS	CONTROLS FOR ENVIRONMENTAL POLLUTION	1925 ROSINA SANTA FE NM 87501	WSW	0.41 / 2,149.62	-44	66
			Site EPA ID: NMD061277596				
20	CERCLIS NFRAP	CONTROLS FOR ENVIRONMENTAL POLLUTION	1925 ROSINA SANTA FE NM 87501	WSW	0.41 / 2,149.62	-44	68
			Site EPA ID: NMD061277596				
20	SEMS ARCHIVE	CONTROLS FOR ENVIRONMENTAL POLLUTION	1925 ROSINA SANTA FE NM 87501	WSW	0.41 / 2,149.62	-44	69
			EPA ID: NMD061277596				
21	LST	ATEX ALLSUPS #327	1899 SAINT MICHAELS DR SANTA FE NM	S	0.43 / 2,292.17	-12	69
			Release ID | Facility ID | Status: 1826 | 26541 | No Further Action, Confirmed Release				
21	LUST HIST	ATEX ALLSUPS #327	1899 SAINT MICHAELS DR SANTA FE NM	S	0.43 / 2,292.17	-12	70
22	LST	HORACE CHRYSLER JEEP AND KIA	1701 ST MICHAELS DR SANTA FE NM	SSW	0.47 / 2,487.88	-27	71
			Release ID | Facility ID | Status: 4451 | 27353 | No Further Action, Confirmed Release				
22	LUST HIST	Horace Chrysler Jeep	1701 St Michaels Dr Santa Fe NM 87501	SSW	0.47 / 2,487.88	-27	72
23	VCP	Premier Nissan	2005 St. Michael's Drive Santa Fe NM	SSE	0.47 / 2,498.58	24	72
24	LST	SPEEDY'S/1	1975 CERRILLOS RD SANTA FE NM	WSW	0.48 / 2,539.22	-51	72
			Release ID | Facility ID | Status: 1617 | 30106 | No Further Action, Confirmed Release				
24	LST	SPEEDY'S	1975 CERRILLOS RD SANTA FE NM	WSW	0.48 / 2,539.22	-51	73
			Release ID | Facility ID | Status: 172 | 30106 | No Further Action, Confirmed Release				
24	LUST HIST	SPEEDY'S	1975 CERRILLOS RD SANTA FE NM	WSW	0.48 / 2,539.22	-51	74
24	LUST HIST	SPEEDY'S/1	1975 CERRILLOS RD SANTA FE NM	WSW	0.48 / 2,539.22	-51	74
24	SCS	Jiffy Lube	1975 Cerrillos Santa Fe NM	WSW	0.48 / 2,539.22	-51	75

Map Key	DB	Company/Site Name	Address	Direction	Distance (mi/ft)	Elev Diff (ft)	Page Number
25	LUST HIST	GIANT STOPNGO	1693 ST MICHAELS DR SANTA FE NM	SSW	0.50 / 2,618.78	-25	75
26	SCS	1710 Llano	1710 Llano Santa Fe NM	SSW	0.58 / 3,069.32	-36	75
27	SCS	Berridge Distributing Co	1255 Cerrillos Rd Santa Fe NM	NE	0.59 / 3,122.26	46	75
28	SCS	Exxon Station 6-7231	2045 Cerrillos Rd Santa Fe NM	WSW	0.62 / 3,253.59	-65	76
29	SCS	PNM Baca St	North of Shoofly Street and Flagman Way, Near Baca Street and Cerrillos Road Santa Fe NM	NE	0.67 / 3,515.87	43	76
30	SCS	NMDOT Main Yard/GOC	1120 Cerrillos Road Santa Fe NM	ENE	0.70 / 3,693.89	64	76
31	DELISTED SCS	Santa Fe Well, PNM	Baca Street and Cerillos Vicinity Santa Fe NM	NE	0.76 / 4,005.64	40	77

Executive Summary: Summary by Data Source

Standard

Federal

SEMS ARCHIVE - SEMS List 8R Archive Sites

A search of the SEMS ARCHIVE database, dated Aug 27, 2025 has found that there are 1 SEMS ARCHIVE site(s) within approximately 0.50miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CONTROLS FOR ENVIRONMENTAL POLLUTION	1925 ROSINA SANTA FE NM 87501	WSW	0.41 / 2,149.62	20
	***EPA ID**: NMD061277596*			

CERCLIS - Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS

A search of the CERCLIS database, dated Oct 25, 2013 has found that there are 1 CERCLIS site(s) within approximately 0.50miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CONTROLS FOR ENVIRONMENTAL POLLUTION	1925 ROSINA SANTA FE NM 87501	WSW	0.41 / 2,149.62	20
	***Site EPA ID**: NMD061277596*			

CERCLIS NFRAP - CERCLIS - No Further Remedial Action Planned

A search of the CERCLIS NFRAP database, dated Oct 25, 2013 has found that there are 1 CERCLIS NFRAP site(s) within approximately 0.50miles of the project property.

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
CONTROLS FOR ENVIRONMENTAL POLLUTION	1925 ROSINA SANTA FE NM 87501	WSW	0.41 / 2,149.62	20
	***Site EPA ID**: NMD061277596*			

RCRA VSQG - RCRA Very Small Quantity Generators List

A search of the RCRA VSQG database, dated Sep 1, 2025 has found that there are 6 RCRA VSQG site(s) within approximately 0.25 miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
DANNYS CLEANERS	1406 SECOND ST SANTA FE NM 87505	SE	0.00 / 0.00	1
	***Handler ID	Recycler Activity?**: NMR000003756	NO*		
REX GOES RACING	1607 BERRY AVENUE SANTA FE NM 87505	NE	0.03 / 183.59	3
	***Handler ID	Recycler Activity?**: NMR000012286	NO*		

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
ASPEN DRY CLEANERS	1616 CERRILLOS RD SANTA FE NM 87505	NNE	0.06 / 317.19	4
	Handler ID* | *Recycler Activity?: *NMR000004630* | *NO*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
DUNN EDWARD PAINTS NO 120	1407 THIRD STREET SANTA FE NM 87505	SW	0.02 / 100.26	2
	Handler ID* | *Recycler Activity?: *NMR000022558* | *NO*			
MIKE'S GARAGE	1501 5TH ST SANTA FE NM 87505	SW	0.18 / 925.77	9
	Handler ID* | *Recycler Activity?: *NMR000017046* | *NO*			
BENS AUTO BODY SERVICES	1520 5TH ST SANTA FE NM 87505	SW	0.23 / 1,216.90	11
	Handler ID* | *Recycler Activity?: *NMR000006692* | *NO*			

RCRA NON GEN - RCRA Non-Generators

A search of the RCRA NON GEN database, dated Sep 1, 2025 has found that there are 2 RCRA NON GEN site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
PIP PRINTING	1424 SECOND ST SANTA FE NM 87501	SE	0.08 / 439.73	5
	Handler ID* | *Recycler Activity?: *NMD986676492* | *NO*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
DON JUANS	1410 4TH ST SANTA FE NM 87501	SW	0.16 / 829.78	8
	Handler ID* | *Recycler Activity?: *NMD982760175* | *NO*			

State

SCS - State Cleanup Sites Listing

A search of the SCS database, dated Feb 4, 2025 has found that there are 6 SCS site(s) within approximately 1.00miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Berridge Distributing Co	1255 Cerrillos Rd Santa Fe NM	NE	0.59 / 3,122.26	27
PNM Baca St	North of Shoofly Street and Flagman Way, Near Baca Street and Cerrillos Road Santa Fe NM	NE	0.67 / 3,515.87	29

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
NMDOT Main Yard/GOC	1120 Cerrillos Road Santa Fe NM	ENE	0.70 / 3,693.89	30

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Jiffy Lube	1975 Cerrillos Santa Fe NM	WSW	0.48 / 2,539.22	24
1710 Llano	1710 Llano Santa Fe NM	SSW	0.58 / 3,069.32	26
Exxon Station 6-7231	2045 Cerrillos Rd Santa Fe NM	WSW	0.62 / 3,253.59	28

DELISTED SCS - Delisted State Cleanup Sites

A search of the DELISTED SCS database, dated Feb 4, 2025 has found that there are 2 DELISTED SCS site(s) within approximately 1.00miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Fmr White Swan Laundry Facility	1368 Cerrillos Road Santa Fe NM	NE	0.40 / 2,090.82	18
Santa Fe Well, PNM	Baca Street and Cerillos Vicinity Santa Fe NM	NE	0.76 / 4,005.64	31

SWF/LF - Solid Waste Facilities

A search of the SWF/LF database, dated Oct 23, 2025 has found that there are 2 SWF/LF site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
Discount Tire (Santa Fe - North)	1366 Cerrillos Road, Santa Fe, New Mexico 87505 NM	NE	0.40 / 2,134.44	19

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
Amigo Tire and Auto	1901 Cerrillos Road, Santa Fe, New Mexico NM	WSW	0.32 / 1,675.16	14

LST - Leaking Petroleum Storage Tanks

A search of the LST database, dated Sep 16, 2025 has found that there are 9 LST site(s) within approximately 0.50miles of the project

property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
TECHLINE STUDIO	1418 CERRILLOS RD SANTA FE NM	NE	0.32 / 1,694.70	15
	Release ID* | *Facility ID* | *Status: *2068* | *31028* | *No Further Action, Confirmed Release*			
SHUTTLEJACK	1600 LENA RD SANTA FE NM	E	0.33 / 1,740.35	16
	Release ID* | *Facility ID* | *Status: *2661* | *30595* | *No Further Action, Confirmed Release*			
SANTA FE BULK PLANT	1404 CERRILLOS RD SANTA FE NM	NE	0.36 / 1,919.48	17
	Release ID* | *Facility ID* | *Status: *1765* | *1778* | *No Further Action, Confirmed Release*			

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
SQUEAKY CLEAN CAR WASH	1900 CERRILLOS RD SANTA FE NM	WSW	0.32 / 1,671.25	13
	Release ID* | *Facility ID* | *Status: *1484* | *30744* | *No Further Action, Confirmed Release*			
1901 CERRILLOS CHEVRON	1901 CERRILLOS RD SANTA FE NM	WSW	0.32 / 1,675.16	14
	Release ID* | *Facility ID* | *Status: *4614* | *1031* | *No Further Action, Confirmed Release*			
ATEX ALLSUPS #327	1899 SAINT MICHAELS DR SANTA FE NM	S	0.43 / 2,292.17	21
	Release ID* | *Facility ID* | *Status: *1826* | *26541* | *No Further Action, Confirmed Release*			
HORACE CHRYSLER JEEP AND KIA	1701 ST MICHAELS DR SANTA FE NM	SSW	0.47 / 2,487.88	22
	Release ID* | *Facility ID* | *Status: *4451* | *27353* | *No Further Action, Confirmed Release*			
SPEEDY'S	1975 CERRILLOS RD SANTA FE NM	WSW	0.48 / 2,539.22	24
	Release ID* | *Facility ID* | *Status: *172* | *30106* | *No Further Action, Confirmed Release*			
SPEEDY'S/1	1975 CERRILLOS RD SANTA FE NM	WSW	0.48 / 2,539.22	24
	Release ID* | *Facility ID* | *Status: *1617* | *30106* | *No Further Action, Confirmed Release*			

LUST HIST - Leaking Underground Storage Tanks

A search of the LUST HIST database, dated Aug 1, 2006 has found that there are 9 LUST HIST site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
TECHLINE STUDIO	1418 CERRILLOS RD SANTA FE NM	NE	0.32 / 1,694.70	15

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
SHUTTLEJACK	1600 LENA RD SANTA FE NM	E	0.33 / 1,740.35	16
SANTA FE BULK PLANT	1404 CERRILLOS RD SANTA FE NM	NE	0.36 / 1,919.48	17

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
SQUEAKY CLEAN CAR WA	1900 CERRILLOS RD SANTA FE NM	WSW	0.32 / 1,671.25	13
ATEX ALLSUPS #327	1899 SAINT MICHAELS DR SANTA FE NM	S	0.43 / 2,292.17	21
Horace Chrysler Jeep	1701 St Michaels Dr Santa Fe NM 87501	SSW	0.47 / 2,487.88	22
SPEEDY'S/1	1975 CERRILLOS RD SANTA FE NM	WSW	0.48 / 2,539.22	24
SPEEDY'S	1975 CERRILLOS RD SANTA FE NM	WSW	0.48 / 2,539.22	24
GIANT STOPNGO	1693 ST MICHAELS DR SANTA FE NM	SSW	0.50 / 2,618.78	25

UST - Underground Storage Tanks

A search of the UST database, dated Nov 3, 2025 has found that there are 5 UST site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
OLD CROSS AMBULANCE SERVICE	1732 SECOND ST SANTA FE NM 87502 ***Facility ID**: 29740* ***In Use UST | Removed UST**: 0 | 1*	SE	0.24 / 1,256.79	12

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
THOMAS PROPERTY	1407 3RD ST SANTA FE NM 87505 ***Facility ID**: 49179* ***In Use UST | Removed UST**: 0 | 1*	SW	0.02 / 100.26	2

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
SANTA FE INDIAN HOSPITAL	1700 CERRILLOS RD SANTA FE NM 87501 ***Facility ID**: 30452* ***In Use UST**	**Removed UST**: 0 | 1*	NNW	0.11 / 564.20	6
EMPIRE BUILDERS SUPPLY CO INC	1802 CERRILLOS RD PO BOX 5134 SANTA FE NM 87502 ***Facility ID**: 27898* ***In Use UST**	**Removed UST**: 0 | 2*	WSW	0.15 / 798.17	7
VALDEZ PLUMBING AND HEATING INC	1608 4TH ST SANTA FE NM 87501 ***Facility ID**: 31439* ***In Use UST**	**Removed UST**: 0 | 1*	SSW	0.18 / 962.82	10

TANKS - Petroleum Storage Tanks

A search of the TANKS database, dated Jul 9, 2019 has found that there are 5 TANKS site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
OLD CROSS AMBULANCE SERVICE	1732 SECOND ST SANTA FE NM 87502 ***FID** | **In Use AST** | **In Use UST**: 29740 | 0 | 0*	SE	0.24 / 1,256.79	12

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
THOMAS PROPERTY	1407 3RD ST SANTA FE NM 87505 ***FID** | **In Use AST** | **In Use UST**: 49179 | 0 | 0*	SW	0.02 / 100.26	2
SANTA FE INDIAN HOSPITAL	1700 CERRILLOS RD SANTA FE NM 87501 ***FID** | **In Use AST** | **In Use UST**: 30452 | 0 | 0*	NNW	0.11 / 564.20	6
EMPIRE BUILDERS SUPPLY CO INC	1802 CERRILLOS RD PO BOX 5134 SANTA FE NM 87502 ***FID** | **In Use AST** | **In Use UST**: 27898 | 0 | 0*	WSW	0.15 / 798.17	7
VALDEZ PLUMBING AND HEATING INC	1608 4TH ST SANTA FE NM 87501 ***FID** | **In Use AST** | **In Use UST**: 31439 | 0 | 0*	SSW	0.18 / 962.82	10

UST HIST - Underground Storage Tanks - Historical

A search of the UST HIST database, dated Aug 1, 2006 has found that there are 5 UST HIST site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
OLD CROSS AMBULANCE SERVICE	1732 SECOND ST SANTA FE NM 87502 ***Facility ID**: 29740* ***Tank ID** | **Tank Status**: 28376 | REMOVED*	SE	0.24 / 1,256.79	12

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
THOMAS PROPERTY	1407 3RD ST SANTA FE NM 87505 ***Facility ID**: 49179* ***Tank ID | Tank Status**: 33719 | REMOVED*	SW	0.02 / 100.26	2
SANTA FE INDIAN HOSPITAL	1700 CERRILLOS RD SANTA FE NM 87501 ***Facility ID**: 30452* ***Tank ID | Tank Status**: 30176 | REMOVED*	NNW	0.11 / 564.20	6
EMPIRE BUILDERS SUPPLY CO INC	1802 CERRILLOS RD SANTA FE NM 87502 ***Facility ID**: 27898* ***Tank ID | Tank Status**: 24180 | REMOVED, 24181 | REMOVED*	WSW	0.15 / 798.17	7
VALDEZ PLUMBING AND HEATING INC	1608 4TH ST SANTA FE NM 87501 ***Facility ID**: 31439* ***Tank ID | Tank Status**: 32285 | REMOVED*	SSW	0.18 / 962.82	10

VCP - Voluntary Remediation Program Sites

A search of the VCP database, dated Sep 30, 2025 has found that there are 2 VCP site(s) within approximately 0.50miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
White Swan Laundy	1368 Cerrillos Road Santa Fe NM	NE	0.40 / 2,090.82	18
Premier Nissan	2005 St. Michael's Drive Santa Fe NM	SSE	0.47 / 2,498.58	23

Non Standard

Federal

FINDS/FRS - Facility Registry Service/Facility Index

A search of the FINDS/FRS database, dated Oct 10, 2025 has found that there are 3 FINDS/FRS site(s) within approximately 0.02miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
DANNY'S CLEANERS_____ _??	1406 SECOND STREET SANTA FE NM 87505-3408 ***Registry ID**: 110001557716*	SE	0.00 / 0.00	1

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
DUNN EDWARD PAINTS NO 120	1407 THIRD STREET SANTA FE NM 87505 ***Registry ID**: 110070206765*	SW	0.02 / 100.26	2

Lower Elevation	Address	Direction	Distance (mi/ft)	Map Key
THOMAS PROPERTY	1407 3RD ST SANTA FE NM 87505	SW	0.02 / 100.26	2
	***Registry ID**: 110022696572*			

ICIS - Integrated Compliance Information System (ICIS)

A search of the ICIS database, dated May 3, 2025 has found that there are 1 ICIS site(s) within approximately 0.02miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
DANNY'S CLEANERS_____ _??	1406 SECOND STREET SANTA FE NM 87505	SE	0.00 / 0.00	1
	***Registry ID**: 110001557716*			

FED DRYCLEANERS - Drycleaner Facilities


A search of the FED DRYCLEANERS database, dated Jul 19, 2025 has found that there are 2 FED DRYCLEANERS site(s) within approximately 0.25miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
DANNY'S CLEANERS_____ _??	1406 SECOND STREET SANTA FE NM 87505	SE	0.00 / 0.00	1
	***FRS Facility ID**: 110001557716*			
ASPEN DRY CLEANERS	1616 CERRILLOS ROAD SANTA FE NM 87505	NNE	0.06 / 317.19	4
	***FRS Facility ID**: 110004283267*			

AFS - Air Facility System

A search of the AFS database, dated Oct 17, 2014 has found that there are 1 AFS site(s) within approximately 0.02miles of the project property.

Equal/Higher Elevation	Address	Direction	Distance (mi/ft)	Map Key
DANNY'S CLEANERS_____ _??	1406 SECOND STREET SANTA FE NM 87505	SE	0.00 / 0.00	1



Map: 1.0 Mile Radius


Order Number: 25121700732

Address: 1406 2nd Street, Santa Fe, NM

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.5 Mile Radius

Order Number: 25121700732


Address: 1406 2nd Street, Santa Fe, NM

ERIS

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Map: 0.25 Mile Radius

Order Number: 25121700732

Address: 1406 2nd Street, Santa Fe, NM

- Project Property
- Buffer Outline
- Sites with Higher Elevation
- Sites with Same Elevation
- Sites with Lower Elevation
- Sites with Unknown Elevation
- Areas with Higher Elevation
- Areas with Same Elevation
- Areas with Lower Elevation
- Areas with Unknown Elevation
- Freeways; Highways
- Traffic Circle; Ramp
- Major & Minor Arterial
- Traffic Circle; Ramp
- Local Road
- Rail
- State
- Country
- National Wetland
- Indian Reserve Land
- 100 Year Flood Zone
- 500 Year Flood Zone
- FWS Special Designation Areas
- National Priorities List (Active, Delisted, Proposed, Institutional Control)

Source: © 2021 ESRI StreetMap Premium

© ERIS Information Inc.



Aerial


Year: 2024

Order Number: 25121700732

Address: 1406 2nd Street, Santa Fe, NM

Source: ESRI World Imagery

© ERIS Information Limited Partnership



Topographic Map

Year: 2023

Order Number: 25121700732

Address: 1406 2nd Street, NM

Quadrangle(s): Agua Fria NM, Santa Fe NM

Source: USGS Topographic Map

© ERIS Information Inc.

Detail Report

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	1 of 5	SE	0.00 / 0.00	6,848.45 / 1	DANNY'S CLEANERS_____ ?? 1406 SECOND STREET SANTA FE NM 87505	AFS

Afs ID:	3504978050	**Fed Reportable:**	No
Plant ID:	971417	**Current Hpv:**	
Epa Region:	06	**Loc Contrl Region:**	00
Plant County:	Santa Fe	**Afs Gov Fac Code:**	0
State No:	35	**Operating Status:**	O
Primary Sic Code:	7216	**Epa Class Code:**	B
Secondary Sic Code:		**Epa Complian Stat:**	C
Naics Code:	812320	**State Comp Status:**	C

Afs Gov Facility Des: PRIVATELY OWNED/OPERATED
Operating Status Def: Operating
Epa Classification Des: Potential uncontrolled emissions <100 tons/year
Epa Compliance Status: In Compliance With Procedural Requirements
State Compliance Status: In Compliance With Procedural Requirements

Actions

Plant ID:	971417	**National Actn Type:**	FS
Anu1:	1	**All Air Prog Codes:**	M
Date Achieved:	19990202	**Result Code:**	01
Penalty Amount:	0	**Pollutant Code:**	
Record Updated Dt:	19990223	**Violating Poll Cds:**	
Creation Date:		**Violation Type Cds:**	
Key Action No:			
Regional Data Element:			

National Action Desc: STATE CONDUCTED FCE/ON-SITE
All Air Program Def: M-MACT (Section 63 NESHAPS)
Result Def:
Pollutant Def:
All Violating Poll Def:
All Violation Type Def:

Historical Compliance - Air Program Level

Air Program Code: M
Air Program Code Ref: MACT (Section 63 NESHAPS)
Historical Compliance Date: 0604, 0701, 0702, 0703, 0704, 0801, 0802, 0803, 0804, 0901, 0902, 0903, 0904, 1001, 1002, 1003, 1004, 1101, 1102, 1103, 1104, 1201, 1202, 1203, 1204, 1301, 1302, 1303, 1304, 1401, 1402, 1403
Historical Compliance Status: C
Historical Compliance Stat Ref: In Compliance With Procedural Requirements

Air Program

Plant ID:	971417	**Poll Classificatn:**	B
Air Program Code:	M	**Poll Compli Status:**	C
Air Program Status:	O	**Epa Class Code:**	B
Pollutant Code:	HC53	**Epa Compli Status:**	C
Chemical Abstract Service Nmbr:			
Air Program Code Subparts:			

Air Program Code Ref: MACT (Section 63 NESHAPS)

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Epa Classification Code Ref:	Potential uncontrolled emissions <100 tons/year					
Epa Compliance Status Ref:	In Compliance With Procedural Requirements					
Pollutant Code Ref:						
Pollutant Classification Ref:	Potential uncontrolled emissions <100 tons/year					
Pollutant Complian Status Ref:	In Compliance With Procedural Requirements					

1	2 of 5	SE	0.00 / 0.00	6,848.45 / 1	DANNY'S CLEANERS_____ ?? 1406 SECOND STREET SANTA FE NM 87505	FED DRYCLEANERS

FRS Facility ID:	110001557716
NPDES IDs:	
NAICS Codes:	812320
SIC Codes:	7216
Latitude:	35.66634
Longitude:	-105.96907

1	3 of 5	SE	0.00 / 0.00	6,848.45 / 1	DANNY'S CLEANERS_____ ?? 1406 SECOND STREET SANTA FE NM 87505-3408	FINDS/FRS

Registry ID:	110001557716
FIPS Code:	35049
HUC Code:	13020201
Site Type Name:	STATIONARY
Location Description:	
Supplemental Location:	
Create Date:	01-MAR-00
Update Date:	09-JAN-15
Interest Types:	AIR MINOR, STATE MASTER, VSQG
SIC Codes:	7216
SIC Code Descriptions:	DRYCLEANING PLANTS, EXCEPT RUG CLEANING
NAICS Codes:	812320
NAICS Code Descriptions:	DRYCLEANING AND LAUNDRY SERVICES (EXCEPT COIN-OPERATED).
Conveyor:	FRS-GEOCODE
Federal Facility Code:	
Federal Agency Name:	
Tribal Land Code:	
Tribal Land Name:	
Congressional Dist No:	03
Census Block Code:	350490010023007
EPA Region Code:	06
County Name:	SANTA FE
US/Mexico Border Ind:	
Latitude:	35.66634
Longitude:	-105.96907
Reference Point:	CENTER OF A FACILITY OR STATION
Coord Collection Method:	ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value:	30
Datum:	NAD83
Source:	
Facility Detail Rprt URL:	https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110001557716
Program Acronyms:	

AIR:NM0000003504978050, AIRS/AFS:3504978050, NM-TEMPO:1531, RCRAINFO:NMR000003756

1	4 of 5	SE	0.00 / 0.00	6,848.45 / 1	DANNY'S CLEANERS_____ ??	ICIS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					1406 SECOND STREET SANTA FE NM 87505	

EPA Region:	06	**Federal Fac ID:**	
Registry ID:	110001557716	**Tribal Land Code:**	
Pgm Sys ID:	NM0000003504978050	**County:**	Santa Fe
Pgm Sys Acrnm:	AIR	**Latitude 83:**	35.66634
Permit Type:		**Longitude 83:**	-105.96907

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
1	5 of 5	SE	0.00 / 0.00	6,848.45 / 1	DANNYS CLEANERS 1406 SECOND ST SANTA FE NM 87505	RCRA VSQG

Handler ID:	NMR000003756
Generator Status:	VSG
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Sep 2025.

Evaluation Details

Eval Start Date:	20070726
Eval Type Desc:	COMPLIANCE ASSISTANCE VISIT
Viol Short Desc:	
Actual Rtc Date:	
Eval Agency:	State

Eval Start Date:	20000209
Eval Type Desc:	COMPLIANCE EVALUATION INSPECTION
Viol Short Desc:	
Actual Rtc Date:	
Eval Agency:	State

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	I	**NAIC 1:**	
Seq No:	1	**NAIC 2:**	
Non Notifier:	X	**NAIC 3:**	
Receive Date:	20000221	**NAIC 4:**	
Active Site:	H----	**State:**	NM
Land Type:		**Location Latitude:**	35.664062
In Handler Univ:	Y	**Location Longitude:**	-105.966662
In A Universe:	Y	**Loc GIS Primary:**	N
Gen Status:	VSG	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	NM

Accessibility:		**State District:**	02
Region:	06		
Fed Waste Gen Owner:	HQ		
State Waste Generator Owner:			
State Waste Generator:			
Short Term Generator:	N		
Uni Waste:	N		
Universal Waste Dest Facility:	N		
Federal Universal Waste:	N		
As Federally Regulated Tsdf:	------		
As Converter Tsdf:	------		
As State Regulated Tsdf:	------		
As State Regulated Handler:	---		
Federal Indicator:	---		
Hsm:	N		
Subpart K:	----		
GPRA Permit:	N		
GPRA Renewal:	N		
Permit Renewal Wrkld:	------		
Permwrk ID:	------		
Perm Prog:	------		
Pcwrkld:	------		
Closwrkld:	------		
GPRA Ca:	N		
Cawrkld:	N		
Subjca Tsd Discretion:	N		
NCAPS:	N		
EC Indicator:	N		
Ca725 Indicator:	N		
Ca750 Indicator:	N		
Operating Tsdf:	------		
Full Enforcement:	------		
Snc:	N		
Unaddressed Snc:	N		
Addressed Snc:	N		
Snc With Comp Sched:	N		
Fa Required:	-----		
Hhandler Last Change:	20000902		
Recognized Trader Importer:	N		
Recognized Trader Exporter:	N		
Slab Importer:	N		
Slab Exporter:	N		
Manifest Broker:	N		
Subpart P:	N		
Contact Language:	EN		
Handler Name:	DANNYS CLEANERS		
Location Street No:	1406		
Location Street1:	SECOND ST		
Location Street2:			
Location City:	SANTA FE		
Location State:	NM		
Location Zip:	87505		
Location County Code:	NM049		
Location County Name:	SANTA FE		
Location Country:	US		
Contact Name:			
Contact Street No:			
Contact Street1:			
Contact Street2:			
Contact City:			
Contact State:			
Contact Zip:			
Contact Country:	US		
Contact Phone & Ext:			
Contact Fax:			
Contact Email Address:			
Contact Title:			
Owner Name:			
Owner Type:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner Seq:
Operator Name:
Operator Type:
Operator Seq:
Public Notes:

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20000221
Handler Name: DANNYS CLEANERS
Fed Waste Generator: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Implementer
TSD Activity: N

Hazardous Waste Handler Details

Seq No: 1
Receive Date: 20000221
Handler Name: DANNYS CLEANERS
Fed Waste Generator: N
Generator Code Description: Not a Generator, Verified
Source Type: Notification
TSD Activity: N

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: UNKNOWN
Dt Became Current:
Dt Ended Current:
Phone: 000-000-0000
Source Type: Notification

Street No:
Street1: UNKNOWN
Street2:
City: UNKNOWN
State: NM
Country:
Zip: 00000

Historical Handler Details

Receive Dt: 20000221
Generator Code Description: Not a Generator, Verified
Handler Name: DANNYS CLEANERS

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	1 of6	SW	0.02 / 100.26	6,846.00 / -1	THOMAS PROPERTY 1407 3RD ST SANTA FE NM 87505	FINDS/FRS

Registry ID: 110022696572
FIPS Code: 35049
HUC Code: 13020201
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 19-SEP-05
Update Date: 20-FEB-08
Interest Types: STATE MASTER
SIC Codes:
SIC Code Descriptions:
NAICS Codes:
NAICS Code Descriptions:
Conveyor: FRS-GEOCODE
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Tribal Land Name:
Congressional Dist No: 03
Census Block Code: 350490010023008
EPA Region Code: 06
County Name: SANTA FE
US/Mexico Border Ind:
Latitude: 35.66575
Longitude: -105.97001
Reference Point: CENTER OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 30
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110022696572
Program Acronyms:

NM-TEMPO:11270

2	2 of6	SW	0.02 / 100.26	6,846.00 / -1	DUNN EDWARD PAINTS NO 120 1407 THIRD STREET SANTA FE NM 87505	FINDS/FRS

Registry ID: 110070206765
FIPS Code: 35049
HUC Code: 13020201
Site Type Name: STATIONARY
Location Description:
Supplemental Location:
Create Date: 16-MAR-18
Update Date:
Interest Types: VSQG
SIC Codes:
SIC Code Descriptions:
NAICS Codes: 444120
NAICS Code Descriptions: PAINT AND WALLPAPER STORES.
Conveyor: FRS-GEOCODE
Federal Facility Code:
Federal Agency Name:
Tribal Land Code:
Tribal Land Name:
Congressional Dist No: 03
Census Block Code: 350490010023008
EPA Region Code:
County Name: SANTA FE
US/Mexico Border Ind:
Latitude: 35.66575
Longitude: -105.97001
Reference Point: CENTER OF A FACILITY OR STATION
Coord Collection Method: ADDRESS MATCHING-HOUSE NUMBER
Accuracy Value: 30
Datum: NAD83
Source:
Facility Detail Rprt URL: https://ofmpub.epa.gov/frs_public2/fii_query_detail.disp_program_facility?p_registry_id=110070206765
Program Acronyms:

RCRAINFO:NMR000022558

2	3 of6	SW	0.02 / 100.26	6,846.00 / -1	DUNN EDWARD PAINTS NO 120 1407 THIRD STREET SANTA FE NM 87505	RCRA VSQG

Handler ID: NMR000022558
Generator Status: VSG
Recycler Activity?: NO

Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Sep 2025.

Evaluation Details

Eval Start Date: 20171116
Eval Type Desc: COMPLIANCE EVALUATION INSPECTION
Viol Short Desc:
Actual Rtc Date:
Eval Agency: State

Handler Summary

Importer:	No	***Used Oil Transpor:***	No
Mixed Waste Gen:	No	***Used Oil Trans Fac:***	No
Transporter:	No	***Used Oil Processor:***	No
Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		

Used Oil Market Burner: No
Used Oil Spec Marketer: No

Additional Handler Summary Details

Source Type:	N	***NAIC 1:***	444120
Seq No:	2	***NAIC 2:***	
Non Notifier:		***NAIC 3:***	
Receive Date:	20230731	***NAIC 4:***	
Active Site:	H----	***State:***	NM
Land Type:	P	***Location Latitude:***	35.664701
In Handler Univ:	Y	***Location Longitude:***	-105.968618
In A Universe:	Y	***Loc GIS Primary:***	N
Gen Status:	VSG	***Loc GIS Origin:***	AG
Report Cycle:		***State District Owner:***	NM
Accessibility:		***State District:***	02
Region:	06		

Fed Waste Gen Owner: HQ
State Waste Generator Owner: NM
State Waste Generator: N
Short Term Generator: N
Uni Waste: N
Universal Waste Dest Facility: N
Federal Universal Waste: N
As Federally Regulated Tsdf: ------
As Converter Tsdf: ------
As State Regulated Tsdf: ------
As State Regulated Handler: ---
Federal Indicator: ---
Hsm: N
Subpart K: ----
GPRA Permit: N
GPRA Renewal: N
Permit Renewal Wrkld: ------
Permwrk ID: ------
Perm Prog: ------
Pcwrkld: ------
Closwrkld: ------

GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20230801
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	DUNN EDWARD PAINTS NO 120
Location Street No:	1407
Location Street1:	THIRD STREET
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87505
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	MOLLY BURNS
Contact Street No:	6119
Contact Street1:	E. WASHINGTON BLVD
Contact Street2:	
Contact City:	COMMERCE
Contact State:	CA
Contact Zip:	90040
Contact Country:	US
Contact Phone & Ext:	213-431-4925
Contact Fax:	
Contact Email Address:	MOLLY.BURNS@DUNNEDWARDS.COM
Contact Title:	ENVIRONMENTAL AFFAIRS MANAGER
Owner Name:	DUNN EDWARDS PAINTS
Owner Type:	P
Owner Seq:	1
Operator Name:	DUNN EDWARDS PAINTS
Operator Type:	P
Operator Seq:	2
Public Notes:	

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20160411
Handler Name:	DUNN EDWARD PAINTS NO 120
Fed Waste Generator:	3
Generator Code Description:	Very Small Quantity Generator
Source Type:	Notification
TSD Activity:	N

Waste Code Details

Waste Code:	D001
Waste Code Desc:	IGNITABLE WASTE

Waste Code: F003
Waste Code Desc: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Code Desc: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Hazardous Waste Handler Details

Seq No: 2
Receive Date: 20230731
Handler Name: DUNN EDWARD PAINTS NO 120
Fed Waste Generator: 3
Generator Code Description: Very Small Quantity Generator
Source Type: Notification
TSD Activity: N

Waste Code Details

Waste Code: D001
Waste Code Desc: IGNITABLE WASTE

Waste Code: F003
Waste Code Desc: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Waste Code: F005
Waste Code Desc: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Owner/Operator Details

Owner/Operator Ind: Current Operator
Type: Private
Name: DUNN EDWARDS PAINTS
Dt Became Current: 20010101
Dt Ended Current:
Phone: 310-489-1361
Source Type: Notification
Street No: 6119
Street1: E. WASHINGTON BLVD
Street2:
City: COMMERCE
State: CA
Country: US
Zip: 90040

Owner/Operator Ind: Current Owner
Type: Private
Name: DUNN EDWARDS PAINTS
Dt Became Current: 20010101
Street No: 6119
Street1: E. WASHINGTON BLVD
Street2:
City: COMMERCE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Dt Ended Current:		**State:**	CA
Phone:	310-489-1361	**Country:**	US
Source Type:	Notification	**Zip:**	90040
Owner/Operator Ind:	Current Operator	**Street No:**	4885
Type:	Private	**Street1:**	EAST 52ND PLACE
Name:	DUNN EDWARDS PAINTS	**Street2:**	
Dt Became Current:	20010101	**City:**	LOS ANGELES
Dt Ended Current:		**State:**	CA
Phone:	323-771-3330	**Country:**	US
Source Type:	Notification	**Zip:**	90058
Owner/Operator Ind:	Current Owner	**Street No:**	4885
Type:	Private	**Street1:**	EAST 52ND PLACE
Name:	DUNN EDWARDS PAINTS	**Street2:**	
Dt Became Current:	20010101	**City:**	LOS ANGELES
Dt Ended Current:		**State:**	CA
Phone:	323-771-3330	**Country:**	US
Source Type:	Notification	**Zip:**	90058

Historical Handler Details

Receive Dt:	20160411
Generator Code Description:	Very Small Quantity Generator
Handler Name:	DUNN EDWARD PAINTS NO 120

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	4 of6	SW	0.02 / 100.26	6,846.00 / -1	THOMAS PROPERTY 1407 3RD ST SANTA FE NM 87505	TANKS

FID:	49179	**Sold AST:**	0
In Use AST:	0	**Sold UST:**	0
In Use UST:	0	**No Data AST:**	0
Temp Out AST:	0	**No Data UST:**	0
Temp Out UST:	0	**County:**	SANTA FE
Removed AST:	0	**Owner ID:**	44722
Removed UST:	1	**City (Deliv Prohib):**	
Exempt AST:	0	**Cty (Del Prohib):**	
Exempt UST:	0		
Owner Name:	THOMAS BRAD		
Fac Name (Del Prohibition):			
Fac Owner (Deliv Prohib):			
Fac Add (Delivery Prohibition):			
Source:	All Storage Tank List		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
2	5 of6	SW	0.02 / 100.26	6,846.00 / -1	THOMAS PROPERTY 1407 3RD ST SANTA FE NM 87505	UST

Facility ID:	49179	**Facility (Active):**	
Facility Name:	THOMAS PROPERTY	**Street (Active):**	
Facility Address:	1407 3RD ST	**Street 2 (Active):**	
Address 2:		**Zip (Active):**	
City:	SANTA FE	**City (Active):**	
County:	SANTA FE	**County (Active):**	
Zip:	87505	**Fac Name (Map-In):**	THOMAS PROPERTY
Fac Name (Map):		**Fac Addr (Map-In):**	1407 3RD ST
Fac Addr (Map):		**Address 2 (Map-In):**	
Address2 (Map):		**City (Map-In):**	SANTA FE
City (Map):		**County (Map-In):**	SANTA FE
County (Map):		**Zip Cd (Map-In):**	87505
Fac ZIP (Map):		**Lat (Map-In):**	35.665823
Latitude (Map):		**Lon (Map-In):**	-105.970044
Longitude (Map):		**Fac Name (Prohib):**	
Fac Name (Map-Pro):		**Fac Addr (Prohib):**	
Fac Addr (Map-Pro):		**City (Prohib):**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

City (Map-Pro): ***County (Prohib):***
County (Map-Pro):
Data Source: NMED PSTB All Storage Tanks Report (as of 14 Oct 2025); NMED Open Data - Inactive Facilities (Map-In) (as of 3 Nov 2025)

NMED PSTB Report - Tank Detail(s) (as of October 14, 2025)

In Use UST:	0	***Sold UST:***	0
Removed UST:	1	***No Data UST:***	0
Exempt UST:	0	***Owner ID:***	44722
Temp Out UST:	0	***Owner Name:***	THOMAS BRAD

NMED Open Data - Inactive Facilities

Active:	0	***Oldest Tnk Age Type:***	
UST:	1	***AST:***	0
UST Curr in Use:	0	***AST Curr in Use:***	0
UST Exempt:	0	***AST Exempt:***	0
UST Removed:	1	***AST Removed:***	0
UST Temp Out of Use:	0	***AST Temp Out of Use:***	0
Tanks:	1	***Shape:***	
Tanks Curr in Use:	0	***Owner ID:***	44722
Tanks Exempt:	0	***Owner Size Type:***	
Tanks Removed:	1	***Owner Name:***	THOMAS BRAD
TanksTemp OutofUse:	0		

2	***6 of6***	***SW***	***0.02 / 100.26***	***6,846.00 / -1***	***THOMAS PROPERTY 1407 3RD ST SANTA FE NM 87505***	***UST HIST***

Facility ID: 49179
Facility Addr2:
Facility County: SANTA FE

Details

Tank ID:	33719	***Owner Add2:***	
Tank Type:	Underground	***Owner City:***	SANTA FE
Tank Status:	REMOVED	***Owner St:***	NM
Tank Capacity (GAL):	550	***Owner ZIP:***	87505
Tank Contents:	USED OIL	***Owner Ph:***	505-983-3217
Owner ID:	44722		
Owner Name:	THOMAS BRAD		
Owner Address:	340 EAST BURGER		

3	***1 of1***	***NE***	***0.03 / 183.59***	***6,852.47 / 5***	***REX GOES RACING 1607 BERRY AVENUE SANTA FE NM 87505***	***RCRA VSQG***

Handler ID: NMR000012286
Generator Status: VSG
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Sep 2025.

Evaluation Details

Eval Start Date: 20070301
Eval Type Desc: COMPLIANCE ASSISTANCE VISIT
Viol Short Desc:
Actual Rtc Date:
Eval Agency: State

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		

Used Oil Market Burner: No
Used Oil Spec Marketer: No

Additional Handler Summary Details

Source Type:	N	**NAIC 1:**	811111
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20070305	**NAIC 4:**	
Active Site:	H----	**State:**	NM
Land Type:	P	**Location Latitude:**	35.664991
In Handler Univ:	Y	**Location Longitude:**	-105.970459
In A Universe:	Y	**Loc GIS Primary:**	N
Gen Status:	VSG	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	NM
Accessibility:		**State District:**	02
Region:	06		

Fed Waste Gen Owner: HQ
State Waste Generator Owner: NM
State Waste Generator: N
Short Term Generator: N
Uni Waste: N
Universal Waste Dest Facility: N
Federal Universal Waste: N
As Federally Regulated Tsdf: ------
As Converter Tsdf: ------
As State Regulated Tsdf: ------
As State Regulated Handler: ---
Federal Indicator: ---
Hsm: N
Subpart K: ----
GPRA Permit: N
GPRA Renewal: N
Permit Renewal Wrkld: ------
Permwrk ID: ------
Perm Prog: ------
Pcwrkld: ------
Closwrkld: ------
GPRA Ca: N
Cawrkld: N
Subjca Tsd Discretion: N
NCAPS: N
EC Indicator: N
Ca725 Indicator: N
Ca750 Indicator: N
Operating Tsdf: ------
Full Enforcement: ------
Snc: N
Unaddressed Snc: N
Addressed Snc: N

Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20070307
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	REX GOES RACING
Location Street No:	1607
Location Street1:	BERRY AVENUE
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87505
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	JOHN CONNELL
Contact Street No:	1607
Contact Street1:	BERRY AVENUE
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87505
Contact Country:	US
Contact Phone & Ext:	505-473-0778
Contact Fax:	
Contact Email Address:	
Contact Title:	
Owner Name:	JOHN CONNELL
Owner Type:	P
Owner Seq:	1
Operator Name:	JOHN CONNELL
Operator Type:	P
Operator Seq:	2
Public Notes:	

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20070305
Handler Name:	REX GOES RACING
Fed Waste Generator:	3
Generator Code Description:	Very Small Quantity Generator
Source Type:	Notification
TSD Activity:	N

Waste Code Details

Waste Code:	D001
Waste Code Desc:	IGNITABLE WASTE
Waste Code:	D002
Waste Code Desc:	CORROSIVE WASTE
Waste Code:	D008
Waste Code Desc:	LEAD
Waste Code:	D009
Waste Code Desc:	MERCURY
Waste Code:	D018
Waste Code Desc:	BENZENE

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Waste Code: D039
Waste Code Desc: TETRACHLOROETHYLENE

Waste Code: D040
Waste Code Desc: TRICHLOROETHYLENE

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	1607
Type:	Private	**Street1:**	BERRY AVENUE
Name:	JOHN CONNELL	**Street2:**	
Dt Became Current:	19840101	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:	505-473-0778	**Country:**	US
Source Type:	Notification	**Zip:**	87505

Owner/Operator Ind:	Current Operator	**Street No:**	1607
Type:	Private	**Street1:**	BERRY AVENUE
Name:	JOHN CONNELL	**Street2:**	
Dt Became Current:	19840101	**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:	505-473-0778	**Country:**	US
Source Type:	Notification	**Zip:**	87505

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
4	1 of2	NNE	0.06 / 317.19	6,852.53 / 5	ASPEN DRY CLEANERS 1616 CERRILLOS ROAD SANTA FE NM 87505	FED DRYCLEANERS

FRS Facility ID: 110004283267
NPDES IDs:
NAICS Codes: 812320
SIC Codes: 7216
Latitude: 35.66745
Longitude: -105.96891

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
4	2 of2	NNE	0.06 / 317.19	6,852.53 / 5	ASPEN DRY CLEANERS 1616 CERRILLOS RD SANTA FE NM 87505	RCRA VSQG

Handler ID: NMR000004630
Generator Status: VSG
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Sep 2025.

Evaluation Details

Eval Start Date: 20140605
Eval Type Desc: COMPLIANCE EVALUATION INSPECTION
Viol Short Desc:
Actual Rtc Date:
Eval Agency: State

Handler Summary

Importer:	No	**Used Oil Transpor:**	No

Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		

Used Oil Market Burner:	No
Used Oil Spec Marketer:	No

Additional Handler Summary Details

Source Type:	N	**NAIC 1:**	812320
Seq No:	2	**NAIC 2:**	
Non Notifier:	X	**NAIC 3:**	
Receive Date:	20140609	**NAIC 4:**	
Active Site:	H----	**State:**	NM
Land Type:	O	**Location Latitude:**	35.661393
In Handler Univ:	Y	**Location Longitude:**	-105.979813
In A Universe:	Y	**Loc GIS Primary:**	N
Gen Status:	VSG	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	NM
Accessibility:		**State District:**	02
Region:	06		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	NM
State Waste Generator:	N
Short Term Generator:	N
Uni Waste:	N
Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20140611
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	ASPEN DRY CLEANERS

Location Street No:	1616
Location Street1:	CERRILLOS RD
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87505
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	ROBERT GONZALES
Contact Street No:	1616
Contact Street1:	CERRILLOS RD
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87505
Contact Country:	US
Contact Phone & Ext:	505-983-8448
Contact Fax:	
Contact Email Address:	
Contact Title:	OWNER
Owner Name:	ROBERT GONZALES
Owner Type:	P
Owner Seq:	1
Operator Name:	ROBERT GONZALES
Operator Type:	P
Operator Seq:	2
Public Notes:	

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	19970930
Handler Name:	ASPEN DRYCLEANING
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Notification
TSD Activity:	N

Hazardous Waste Handler Details

Seq No:	2
Receive Date:	20140609
Handler Name:	ASPEN DRY CLEANERS
Fed Waste Generator:	3
Generator Code Description:	Very Small Quantity Generator
Source Type:	Notification
TSD Activity:	N

Waste Code Details

Waste Code:	D001
Waste Code Desc:	IGNITABLE WASTE
Waste Code:	D009
Waste Code Desc:	MERCURY
Waste Code:	D039
Waste Code Desc:	TETRACHLOROETHYLENE
Waste Code:	F001
Waste Code Desc:	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF

THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	1616
Type:	Private	***Street1:***	CERRILLOS RD
Name:	ROBERT GONZALES	***Street2:***	
Dt Became Current:	19861001	***City:***	SANTA FE
Dt Ended Current:		***State:***	NM
Phone:		***Country:***	US
Source Type:	Notification	***Zip:***	87505

Owner/Operator Ind:	Current Operator	***Street No:***	1616
Type:	Private	***Street1:***	CERRILLOS RD
Name:	ROBERT GONZALES	***Street2:***	
Dt Became Current:	19861001	***City:***	SANTA FE
Dt Ended Current:		***State:***	NM
Phone:		***Country:***	US
Source Type:	Notification	***Zip:***	87505

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street1:***	UNKNOWN
Name:	UNKNOWN	***Street2:***	
Dt Became Current:		***City:***	SANTA FE
Dt Ended Current:		***State:***	NM
Phone:		***Country:***	
Source Type:	Notification	***Zip:***	87501

Historical Handler Details

Receive Dt:	19970930
Generator Code Description:	Not a Generator, Verified
Handler Name:	ASPEN DRYCLEANING

5	***1 of1***	***SE***	***0.08 / 439.73***	***6,856.15 / 9***	***PIP PRINTING 1424 SECOND ST SANTA FE NM 87501***	***RCRA NON GEN***

Handler ID:	NMD986676492
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Sep 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	***Used Oil Transpor:***	No
Mixed Waste Gen:	No	***Used Oil Trans Fac:***	No
Transporter:	No	***Used Oil Processor:***	No
Transfer Facility:	No	***Used Oil Refiner:***	No
Recycler:	No	***Used Oil Burner:***	No
Onsite Burner Exem:	No	***Commercial TSD:***	No
Furnace Exemption:	No	***Recycl Nonstorage:***	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	N	***NAIC 1:***	
Seq No:	1	***NAIC 2:***	
Non Notifier:		***NAIC 3:***	
Receive Date:	19920110	***NAIC 4:***	
Active Site:	-----	***State:***	NM
Land Type:	O	***Location Latitude:***	35.665387
In Handler Univ:	N	***Location Longitude:***	-105.96811
In A Universe:	N	***Loc GIS Primary:***	N
Gen Status:	N	***Loc GIS Origin:***	AG
Report Cycle:		***State District Owner:***	NM
Accessibility:		***State District:***	02
Region:	06		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	NM
State Waste Generator:	7
Short Term Generator:	N
Uni Waste:	N
Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20020502
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	PIP PRINTING
Location Street No:	1424
Location Street1:	SECOND ST
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87501
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	HENRYOR NORMA EVANS
Contact Street No:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Contact Street1:	1424 SECOND ST
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87501
Contact Country:	US
Contact Phone & Ext:	505-982-8250
Contact Fax:	
Contact Email Address:	
Contact Title:	
Owner Name:	PIP PRINTING
Owner Type:	P
Owner Seq:	1
Operator Name:	
Operator Type:	
Operator Seq:	
Public Notes:	

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	19920110
Handler Name:	PIP PRINTING
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Notification
TSD Activity:	N

Waste Code Details

Waste Code:	D001
Waste Code Desc:	IGNITABLE WASTE

Owner/Operator Details

Owner/Operator Ind:	Current Owner	**Street No:**	
Type:	Private	**Street1:**	1424 SECOND ST
Name:	PIP PRINTING	**Street2:**	
Dt Became Current:		**City:**	SANTA FE
Dt Ended Current:		**State:**	NM
Phone:	505-982-8250	**Country:**	
Source Type:	Notification	**Zip:**	87501

---

6 | ***1 of3*** | ***NNW*** | ***0.11 / 564.20*** | ***6,841.34 / -6*** | ***SANTA FE INDIAN HOSPITAL***
1700 CERRILLOS RD
SANTA FE NM 87501 | ***TANKS***

FID:	30452	**Sold AST:**	0
In Use AST:	0	**Sold UST:**	0
In Use UST:	0	**No Data AST:**	0
Temp Out AST:	0	**No Data UST:**	0
Temp Out UST:	0	**County:**	SANTA FE
Removed AST:	0	**Owner ID:**	17132
Removed UST:	1	**City (Deliv Prohib):**	
Exempt AST:	0	**Cty (Del Prohib):**	
Exempt UST:	0		
Owner Name:	ALBUQUERQUE AREA INDIAN HEALTH SERVICE		
Fac Name (Del Prohibition):			
Fac Owner (Deliv Prohib):			
Fac Add (Delivery Prohibition):			
Source:	All Storage Tank List		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
6	2 of3	NNW	0.11 / 564.20	6,841.34 / -6	SANTA FE INDIAN HOSPITAL 1700 CERRILLOS RD SANTA FE NM 87501	UST

Facility ID:	30452	**Facility (Active):**	
Facility Name:	SANTA FE INDIAN HOSPITAL	**Street (Active):**	
Facility Address:	1700 CERRILLOS RD	**Street 2 (Active):**	
Address 2:		**Zip (Active):**	
City:	SANTA FE	**City (Active):**	
County:	SANTA FE	**County (Active):**	
Zip:	87501	**Fac Name (Map-In):**	SANTA FE INDIAN HOSPITAL
Fac Name (Map):		**Fac Addr (Map-In):**	1700 CERRILLOS RD
Fac Addr (Map):		**Address 2 (Map-In):**	
Address2 (Map):		**City (Map-In):**	SANTA FE
City (Map):		**County (Map-In):**	SANTA FE
County (Map):		**Zip Cd (Map-In):**	87501
Fac ZIP (Map):		**Lat (Map-In):**	35.668954
Latitude (Map):		**Lon (Map-In):**	-105.970216
Longitude (Map):		**Fac Name (Prohib):**	
Fac Name (Map-Pro):		**Fac Addr (Prohib):**	
Fac Addr (Map-Pro):		**City (Prohib):**	
City (Map-Pro):		**County (Prohib):**	
County (Map-Pro):			
Data Source:	NMED PSTB All Storage Tanks Report (as of 14 Oct 2025); NMED Open Data - Inactive Facilities (Map-In) (as of 3 Nov 2025)		

NMED PSTB Report - Tank Detail(s) (as of October 14, 2025)

In Use UST:	0	**Sold UST:**	0
Removed UST:	1	**No Data UST:**	0
Exempt UST:	0	**Owner ID:**	17132
Temp Out UST:	0	**Owner Name:**	ALBUQUERQUE AREA INDIAN HEALTH SERVICE

NMED Open Data - Inactive Facilities

Active:	0	**Oldest Tnk Age Type:**	
UST:	1	**AST:**	0
UST Curr in Use:	0	**AST Curr in Use:**	0
UST Exempt:	0	**AST Exempt:**	0
UST Removed:	1	**AST Removed:**	0
UST Temp Out of Use:	0	**AST Temp Out of Use:**	0
Tanks:	1	**Shape:**	
Tanks Curr in Use:	0	**Owner ID:**	17132
Tanks Exempt:	0	**Owner Size Type:**	
Tanks Removed:	1	**Owner Name:**	ALBUQUERQUE AREA INDIAN HEALTH SERVICE
TanksTemp OutofUse:	0		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
6	3 of3	NNW	0.11 / 564.20	6,841.34 / -6	SANTA FE INDIAN HOSPITAL 1700 CERRILLOS RD SANTA FE NM 87501	UST HIST

Facility ID:	30452
Facility Addr2:	
Facility County:	SANTA FE

Details

Tank ID:	30176	**Owner Add2:**	
Tank Type:	Underground	**Owner City:**	ALBUQUERQUE
Tank Status:	REMOVED	**Owner St:**	NM
Tank Capacity (GAL):	10000	**Owner ZIP:**	87102
Tank Contents:	DIESEL	**Owner Ph:**	505-248-5463

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner ID: 17132
Owner Name: ALBUQUERQUE AREA INDIAN HEALTH SERVICE
Owner Address: 505 MARQUETTE NW

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
7	1 of3	WSW	0.15 / 798.17	6,834.11 / -13	EMPIRE BUILDERS SUPPLY CO INC 1802 CERRILLOS RD PO BOX 5134 SANTA FE NM 87502	TANKS

FID: 27898
In Use AST: 0
In Use UST: 0
Temp Out AST: 0
Temp Out UST: 0
Removed AST: 0
Removed UST: 2
Exempt AST: 0
Exempt UST: 0
Sold AST: 0
Sold UST: 0
No Data AST: 0
No Data UST: 0
County: SANTA FE
Owner ID: 15256
City (Deliv Prohib):
Cty (Del Prohib):
Owner Name: EMPIRE BUILDERS SUPPLY CO INC
Fac Name (Del Prohibition):
Fac Owner (Deliv Prohib):
Fac Add (Delivery Prohibition):
Source: All Storage Tank List

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
7	2 of3	WSW	0.15 / 798.17	6,834.11 / -13	EMPIRE BUILDERS SUPPLY CO INC 1802 CERRILLOS RD PO BOX 5134 SANTA FE NM 87502	UST

Facility ID: 27898
Facility Name: EMPIRE BUILDERS SUPPLY CO INC
Facility Address: 1802 CERRILLOS RD
Address 2: PO BOX 5134
City: SANTA FE
County: SANTA FE
Zip: 87502
Fac Name (Map):
Fac Addr (Map):
Address2 (Map):
City (Map):
County (Map):
Fac ZIP (Map):
Latitude (Map):
Longitude (Map):
Fac Name (Map-Pro):
Fac Addr (Map-Pro):
City (Map-Pro):
County (Map-Pro):
Facility (Active):
Street (Active):
Street 2 (Active):
Zip (Active):
City (Active):
County (Active):
Fac Name (Map-In): EMPIRE BUILDERS SUPPLY CO INC
Fac Addr (Map-In): 1802 CERRILLOS RD
Address 2 (Map-In): PO BOX 5134
City (Map-In): SANTA FE
County (Map-In): SANTA FE
Zip Cd (Map-In): 87502
Lat (Map-In): 35.665156
Lon (Map-In): -105.971063
Fac Name (Prohib):
Fac Addr (Prohib):
City (Prohib):
County (Prohib):
Data Source: NMED PSTB All Storage Tanks Report (as of 14 Oct 2025); NMED Open Data - Inactive Facilities (Map-In) (as of 3 Nov 2025)

NMED PSTB Report - Tank Detail(s) (as of October 14, 2025)

In Use UST: 0
Removed UST: 2
Exempt UST: 0
Temp Out UST: 0
Sold UST: 0
No Data UST: 0
Owner ID: 15256
Owner Name: EMPIRE BUILDERS SUPPLY CO INC

NMED Open Data - Inactive Facilities

Active: 0
UST: 2
UST Curr in Use: 0
Oldest Tnk Age Type:
AST: 0
AST Curr in Use: 0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

UST Exempt:	0	**AST Exempt:**	0
UST Removed:	2	**AST Removed:**	0
UST Temp Out of Use:	0	**AST Temp Out of Use:**	0
Tanks:	2	**Shape:**	
Tanks Curr in Use:	0	**Owner ID:**	15256
Tanks Exempt:	0	**Owner Size Type:**	
Tanks Removed:	2	**Owner Name:**	EMPIRE BUILDERS SUPPLY CO INC
TanksTemp OutofUse:	0		

---

7 | ***3 of3*** | ***WSW*** | ***0.15 / 798.17*** | ***6,834.11 / -13*** | ***EMPIRE BUILDERS SUPPLY CO INC***
1802 CERRILLOS RD
SANTA FE NM 87502 | ***UST HIST***

Facility ID:	27898
Facility Addr2:	PO BOX 5134
Facility County:	SANTA FE

Details

Tank ID:	24180	**Owner Add2:**	PO BOX 5134
Tank Type:	Underground	**Owner City:**	SANTA FE
Tank Status:	REMOVED	**Owner St:**	NM
Tank Capacity (GAL):	8000	**Owner ZIP:**	87502
Tank Contents:	UNLEADED GASOLINE	**Owner Ph:**	505-982-2646
Owner ID:	15256		
Owner Name:	EMPIRE BUILDERS SUPPLY CO INC		
Owner Address:	1802 CERRILLOS RD		

Details

Tank ID:	24181	**Owner Add2:**	PO BOX 5134
Tank Type:	Underground	**Owner City:**	SANTA FE
Tank Status:	REMOVED	**Owner St:**	NM
Tank Capacity (GAL):	800	**Owner ZIP:**	87502
Tank Contents:	UNLEADED GASOLINE	**Owner Ph:**	505-982-2646
Owner ID:	15256		
Owner Name:	EMPIRE BUILDERS SUPPLY CO INC		
Owner Address:	1802 CERRILLOS RD		

---

8 | ***1 of1*** | ***SW*** | ***0.16 / 829.78*** | ***6,840.67 / -7*** | ***DON JUANS***
1410 4TH ST
SANTA FE NM 87501 | ***RCRA NON GEN***

Handler ID:	NMD982760175
Generator Status:	N
Recycler Activity?:	NO
Recycler Activity Note:	This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note:	NO RECORDS: As of Sep 2025, there are no Compliance Monitoring and Enforcement (violation) records associated with this facility (EPA ID).

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No

Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		
Used Oil Market Burner:	No		
Used Oil Spec Marketer:	No		

Additional Handler Summary Details

Source Type:	N	**NAIC 1:**	
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	19890807	**NAIC 4:**	
Active Site:	-----	**State:**	NM
Land Type:	O	**Location Latitude:**	35.664678
In Handler Univ:	N	**Location Longitude:**	-105.970754
In A Universe:	N	**Loc GIS Primary:**	N
Gen Status:	N	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	NM
Accessibility:		**State District:**	02
Region:	06		

Fed Waste Gen Owner:	HQ
State Waste Generator Owner:	NM
State Waste Generator:	N
Short Term Generator:	N
Uni Waste:	N
Universal Waste Dest Facility:	N
Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20150414
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	DON JUANS
Location Street No:	1410
Location Street1:	4TH ST
Location Street2:	
Location City:	SANTA FE

Location State:	NM
Location Zip:	87501
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	CARLOS GARCIA
Contact Street No:	
Contact Street1:	1410 4TH ST
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87501
Contact Country:	US
Contact Phone & Ext:	505-984-1818
Contact Fax:	
Contact Email Address:	
Contact Title:	
Owner Name:	CARLOS GARCIA
Owner Type:	P
Owner Seq:	1
Operator Name:	GARCIA CARLOS
Operator Type:	P
Operator Seq:	2
Public Notes:	

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	19890807
Handler Name:	DON JUANS
Fed Waste Generator:	N
Generator Code Description:	Not a Generator, Verified
Source Type:	Notification
TSD Activity:	N

Waste Code Details

Waste Code:	F003
Waste Code Desc:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
Waste Code:	F005
Waste Code Desc:	THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Owner/Operator Details

Owner/Operator Ind:	Current Owner	***Street No:***	
Type:	Private	***Street1:***	UNKNOWN
Name:	CARLOS GARCIA	***Street2:***	
Dt Became Current:		***City:***	UNKNOWN
Dt Ended Current:		***State:***	NM
Phone:	000-000-0000	***Country:***	
Source Type:	Notification	***Zip:***	00000-0000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Owner/Operator Ind:	Current Operator	**Street No:**	
Type:	Private	**Street1:**	UNKNOWN
Name:	GARCIA CARLOS	**Street2:**	
Dt Became Current:		**City:**	UNKNOWN
Dt Ended Current:		**State:**	NM
Phone:	000-000-0000	**Country:**	
Source Type:	Notification	**Zip:**	00000-0000

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
9	1 of1	SW	0.18 / 925.77	6,834.22 / -13	MIKE'S GARAGE 1501 5TH ST SANTA FE NM 87505	RCRA VSQG

Handler ID: NMR000017046
Generator Status: VSG
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Sep 2025.

Evaluation Details

Eval Start Date: 20111004
Eval Type Desc: COMPLIANCE ASSISTANCE VISIT
Viol Short Desc:
Actual Rtc Date:
Eval Agency: State

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		

Used Oil Market Burner: No
Used Oil Spec Marketer: No

Additional Handler Summary Details

Source Type:	N	**NAIC 1:**	811111
Seq No:	1	**NAIC 2:**	
Non Notifier:		**NAIC 3:**	
Receive Date:	20120123	**NAIC 4:**	
Active Site:	H----	**State:**	NM
Land Type:	P	**Location Latitude:**	35.662308
In Handler Univ:	Y	**Location Longitude:**	-105.970744
In A Universe:	Y	**Loc GIS Primary:**	N
Gen Status:	VSG	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	NM
Accessibility:		**State District:**	02
Region:	06		

Fed Waste Gen Owner: HQ
State Waste Generator Owner: NM
State Waste Generator: N
Short Term Generator: N
Uni Waste: N
Universal Waste Dest Facility: N

Federal Universal Waste:	N
As Federally Regulated Tsdf:	------
As Converter Tsdf:	------
As State Regulated Tsdf:	------
As State Regulated Handler:	---
Federal Indicator:	---
Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	N
Ca750 Indicator:	N
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20120124
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	MIKE'S GARAGE
Location Street No:	1501
Location Street1:	5TH ST
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87505
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	MIKE GRIEGO
Contact Street No:	1501
Contact Street1:	5TH ST
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87505
Contact Country:	US
Contact Phone & Ext:	505-983-6577
Contact Fax:	
Contact Email Address:	
Contact Title:	OWNER
Owner Name:	ORLANDO VIGIL
Owner Type:	P
Owner Seq:	1
Operator Name:	MIKE'S GARAGE
Operator Type:	P
Operator Seq:	2
Public Notes:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20120123
Handler Name:	MIKE'S GARAGE
Fed Waste Generator:	3
Generator Code Description:	Very Small Quantity Generator
Source Type:	Notification
TSD Activity:	N

Waste Code Details

Waste Code:	D001
Waste Code Desc:	IGNITABLE WASTE
Waste Code:	D002
Waste Code Desc:	CORROSIVE WASTE
Waste Code:	D008
Waste Code Desc:	LEAD
Waste Code:	D009
Waste Code Desc:	MERCURY

Owner/Operator Details

Owner/Operator Ind:	Current Operator	***Street No:***	1501
Type:	Private	***Street1:***	5TH ST
Name:	MIKE'S GARAGE	***Street2:***	
Dt Became Current:	19960701	***City:***	SANTA FE
Dt Ended Current:		***State:***	NM
Phone:	505-983-6577	***Country:***	US
Source Type:	Notification	***Zip:***	87505
Owner/Operator Ind:	Current Owner	***Street No:***	1501
Type:	Private	***Street1:***	5TH ST
Name:	ORLANDO VIGIL	***Street2:***	
Dt Became Current:	19810101	***City:***	SANTA FE
Dt Ended Current:		***State:***	NM
Phone:	505-983-6577	***Country:***	US
Source Type:	Notification	***Zip:***	87505

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
10	1 of3	SSW	0.18 / 962.82	6,844.45 / -3	VALDEZ PLUMBING AND HEATING INC 1608 4TH ST SANTA FE NM 87501	TANKS

FID:	31439	***Sold AST:***	0
In Use AST:	0	***Sold UST:***	0
In Use UST:	0	***No Data AST:***	0
Temp Out AST:	0	***No Data UST:***	0
Temp Out UST:	0	***County:***	SANTA FE
Removed AST:	0	***Owner ID:***	15736
Removed UST:	1	***City (Deliv Prohib):***	
Exempt AST:	0	***Cty (Del Prohib):***	
Exempt UST:	0		
Owner Name:	VALDEZ PLUMBING AND HEATING INC		
Fac Name (Del Prohibition):			
Fac Owner (Deliv Prohib):			
Fac Add (Delivery Prohibition):			
Source:	All Storage Tank List		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
10	2 of3	SSW	0.18 / 962.82	6,844.45 / -3	VALDEZ PLUMBING AND HEATING INC	UST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
					1608 4TH ST SANTA FE NM 87501	

Facility ID:	31439	**Facility (Active):**	
Facility Name:	VALDEZ PLUMBING AND HEATING INC	**Street (Active):**	
Facility Address:	1608 4TH ST	**Street 2 (Active):**	
Address 2:		**Zip (Active):**	
City:	SANTA FE	**City (Active):**	
County:	SANTA FE	**County (Active):**	
Zip:	87501	**Fac Name (Map-In):**	VALDEZ PLUMBING AND HEATING INC
Fac Name (Map):		**Fac Addr (Map-In):**	1608 4TH ST
Fac Addr (Map):		**Address 2 (Map-In):**	
Address2 (Map):		**City (Map-In):**	SANTA FE
City (Map):		**County (Map-In):**	SANTA FE
County (Map):		**Zip Cd (Map-In):**	87501
Fac ZIP (Map):		**Lat (Map-In):**	35.66352
Latitude (Map):		**Lon (Map-In):**	-105.969889
Longitude (Map):		**Fac Name (Prohib):**	
Fac Name (Map-Pro):		**Fac Addr (Prohib):**	
Fac Addr (Map-Pro):		**City (Prohib):**	
City (Map-Pro):		**County (Prohib):**	
County (Map-Pro):			
Data Source:	NMED PSTB All Storage Tanks Report (as of 14 Oct 2025); NMED Open Data - Inactive Facilities (Map-In) (as of 3 Nov 2025)		

NMED PSTB Report - Tank Detail(s) (as of October 14, 2025)

In Use UST:	0	**Sold UST:**	0
Removed UST:	1	**No Data UST:**	0
Exempt UST:	0	**Owner ID:**	15736
Temp Out UST:	0	**Owner Name:**	VALDEZ PLUMBING AND HEATING INC

NMED Open Data - Inactive Facilities

Active:	0	**Oldest Tnk Age Type:**	
UST:	1	**AST:**	0
UST Curr in Use:	0	**AST Curr in Use:**	0
UST Exempt:	0	**AST Exempt:**	0
UST Removed:	1	**AST Removed:**	0
UST Temp Out of Use:	0	**AST Temp Out of Use:**	0
Tanks:	1	**Shape:**	
Tanks Curr in Use:	0	**Owner ID:**	15736
Tanks Exempt:	0	**Owner Size Type:**	
Tanks Removed:	1	**Owner Name:**	VALDEZ PLUMBING AND HEATING INC
TanksTemp OutofUse:	0		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
10	3 of3	SSW	0.18 / 962.82	6,844.45 / -3	VALDEZ PLUMBING AND HEATING INC 1608 4TH ST SANTA FE NM 87501	UST HIST

Facility ID:	31439
Facility Addr2:	
Facility County:	SANTA FE

Details

Tank ID:	32285	**Owner Add2:**	
Tank Type:	Underground	**Owner City:**	SANTA FE
Tank Status:	REMOVED	**Owner St:**	NM
Tank Capacity (GAL):	560	**Owner ZIP:**	87501
Tank Contents:	EMPTY, UNLEADED GASOLINE	**Owner Ph:**	505-983-8888
Owner ID:	15736		
Owner Name:	VALDEZ PLUMBING AND HEATING INC		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Owner Address:		1608 4TH ST				
11	1 of1	SW	0.23 / 1,216.90	6,836.11 / -11	BENS AUTO BODY SERVICES 1520 5TH ST SANTA FE NM 87505	RCRA VSQG

Handler ID: NMR000006692
Generator Status: VSG
Recycler Activity?: NO
Recycler Activity Note: This facility has not been identified as a Recycler Facility from both the RCRA Handler and Biennial Report Modules.

Violation/Evaluation Summary

Note: NO VIOLATIONS: All of the compliance records associated with this facility (EPA ID) indicate NO VIOLATIONS; Compliance Monitoring and Enforcement table dated Sep 2025.

Evaluation Details

Eval Start Date: 20020319
Eval Type Desc: COMPLIANCE ASSISTANCE VISIT
Viol Short Desc:
Actual Rtc Date:
Eval Agency: State

Handler Summary

Importer:	No	**Used Oil Transpor:**	No
Mixed Waste Gen:	No	**Used Oil Trans Fac:**	No
Transporter:	No	**Used Oil Processor:**	No
Transfer Facility:	No	**Used Oil Refiner:**	No
Recycler:	No	**Used Oil Burner:**	No
Onsite Burner Exem:	No	**Commercial TSD:**	No
Furnace Exemption:	No	**Recycl Nonstorage:**	No
Underground Injec:	No		

Used Oil Market Burner: No
Used Oil Spec Marketer: No

Additional Handler Summary Details

Source Type:	N	**NAIC 1:**	
Seq No:	1	**NAIC 2:**	
Non Notifier:	X	**NAIC 3:**	
Receive Date:	20020320	**NAIC 4:**	
Active Site:	H----	**State:**	NM
Land Type:	P	**Location Latitude:**	35.662308
In Handler Univ:	Y	**Location Longitude:**	-105.970744
In A Universe:	Y	**Loc GIS Primary:**	N
Gen Status:	VSG	**Loc GIS Origin:**	AG
Report Cycle:		**State District Owner:**	NM
Accessibility:		**State District:**	02
Region:	06		

Fed Waste Gen Owner: HQ
State Waste Generator Owner:
State Waste Generator:
Short Term Generator: N
Uni Waste: N
Universal Waste Dest Facility: N
Federal Universal Waste: N
As Federally Regulated Tsdf: ------
As Converter Tsdf: ------
As State Regulated Tsdf: ------
As State Regulated Handler: ---
Federal Indicator: ---

Hsm:	N
Subpart K:	----
GPRA Permit:	N
GPRA Renewal:	N
Permit Renewal Wrkld:	------
Permwrk ID:	------
Perm Prog:	------
Pcwrkld:	------
Closwrkld:	------
GPRA Ca:	N
Cawrkld:	N
Subjca Tsd Discretion:	N
NCAPS:	N
EC Indicator:	N
Ca725 Indicator:	
Ca750 Indicator:	
Operating Tsdf:	------
Full Enforcement:	------
Snc:	N
Unaddressed Snc:	N
Addressed Snc:	N
Snc With Comp Sched:	N
Fa Required:	-----
Hhandler Last Change:	20020403
Recognized Trader Importer:	N
Recognized Trader Exporter:	N
Slab Importer:	N
Slab Exporter:	N
Manifest Broker:	N
Subpart P:	N
Contact Language:	EN
Handler Name:	BENS AUTO BODY SERVICES
Location Street No:	1520
Location Street1:	5TH ST
Location Street2:	
Location City:	SANTA FE
Location State:	NM
Location Zip:	87505
Location County Code:	NM049
Location County Name:	SANTA FE
Location Country:	US
Contact Name:	BEN CORDOVA
Contact Street No:	
Contact Street1:	1520 5TH ST
Contact Street2:	
Contact City:	SANTA FE
Contact State:	NM
Contact Zip:	87505
Contact Country:	US
Contact Phone & Ext:	505-983-1031
Contact Fax:	
Contact Email Address:	
Contact Title:	
Owner Name:	BEN CORDOVA
Owner Type:	P
Owner Seq:	1
Operator Name:	
Operator Type:	
Operator Seq:	
Public Notes:	

Hazardous Waste Handler Details

Seq No:	1
Receive Date:	20020320
Handler Name:	BENS AUTO BODY SERVICES
Fed Waste Generator:	3

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Generator Code Description: Very Small Quantity Generator
Source Type: Notification
TSD Activity: N

Owner/Operator Details

Owner/Operator Ind: Current Owner
Type: Private
Name: BEN CORDOVA
Dt Became Current:
Dt Ended Current:
Phone: 505-983-1031
Source Type: Notification
Street No:
Street1: 1520 5TH ST
Street2:
City: SANTA FE
State: NM
Country:
Zip: 87505

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
12	1 of3	SE	0.24 / 1,256.79	6,864.54 / 17	OLD CROSS AMBULANCE SERVICE 1732 SECOND ST SANTA FE NM 87502	TANKS

FID: 29740
In Use AST: 0
In Use UST: 0
Temp Out AST: 0
Temp Out UST: 0
Removed AST: 0
Removed UST: 1
Exempt AST: 0
Exempt UST: 0
Owner Name: CHAVEZ JOE
Fac Name (Del Prohibition):
Fac Owner (Deliv Prohib):
Fac Add (Delivery Prohibition):
Source: All Storage Tank List
Sold AST: 0
Sold UST: 0
No Data AST: 0
No Data UST: 0
County: SANTA FE
Owner ID: 16772
City (Deliv Prohib):
Cty (Del Prohib):

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
12	2 of3	SE	0.24 / 1,256.79	6,864.54 / 17	OLD CROSS AMBULANCE SERVICE 1732 SECOND ST SANTA FE NM 87502	UST

Facility ID: 29740
Facility Name: OLD CROSS AMBULANCE SERVICE
Facility Address: 1732 SECOND ST
Address 2:
City: SANTA FE
County: SANTA FE
Zip: 87502
Fac Name (Map):
Fac Addr (Map):
Address2 (Map):
City (Map):
County (Map):
Fac ZIP (Map):
Latitude (Map):
Longitude (Map):
Fac Name (Map-Pro):
Fac Addr (Map-Pro):
City (Map-Pro):
County (Map-Pro):
Data Source: NMED PSTB All Storage Tanks Report (as of 14 Oct 2025); NMED Open Data - Inactive Facilities (Map-In) (as of 3 Nov 2025)
Facility (Active):
Street (Active):
Street 2 (Active):
Zip (Active):
City (Active):
County (Active):
Fac Name (Map-In): OLD CROSS AMBULANCE SERVICE
Fac Addr (Map-In): 1732 SECOND ST
Address 2 (Map-In):
City (Map-In): SANTA FE
County (Map-In): SANTA FE
Zip Cd (Map-In): 87502
Lat (Map-In): 35.663525
Lon (Map-In): -105.966214
Fac Name (Prohib):
Fac Addr (Prohib):
City (Prohib):
County (Prohib):

NMED PSTB Report - Tank Detail(s) (as of October 14, 2025)

In Use UST: 0
Removed UST: 1
Sold UST: 0
No Data UST: 0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Exempt UST:	0	**Owner ID:**	16772
Temp Out UST:	0	**Owner Name:**	CHAVEZ JOE

NMED Open Data - Inactive Facilities

Active:	0	**Oldest Tnk Age Type:**	
UST:	1	**AST:**	0
UST Curr in Use:	0	**AST Curr in Use:**	0
UST Exempt:	0	**AST Exempt:**	0
UST Removed:	1	**AST Removed:**	0
UST Temp Out of Use:	0	**AST Temp Out of Use:**	0
Tanks:	1	**Shape:**	
Tanks Curr in Use:	0	**Owner ID:**	16772
Tanks Exempt:	0	**Owner Size Type:**	
Tanks Removed:	1	**Owner Name:**	CHAVEZ JOE
TanksTemp OutofUse:	0		

12	3 of3	SE	0.24 / 1,256.79	6,864.54 / 17	**OLD CROSS AMBULANCE SERVICE** **1732 SECOND ST** **SANTA FE NM 87502**	UST HIST

Facility ID:	29740
Facility Addr2:	
Facility County:	SANTA FE

Details

Tank ID:	28376	**Owner Add2:**	
Tank Type:	Underground	**Owner City:**	SANTA FE
Tank Status:	REMOVED	**Owner St:**	NM
Tank Capacity (GAL):		**Owner ZIP:**	87502
Tank Contents:		**Owner Ph:**	505-982-9881
Owner ID:	16772		
Owner Name:	CHAVEZ JOE		
Owner Address:	PO BOX 4514		

13	1 of2	WSW	0.32 / 1,671.25	6,817.51 / -30	**SQUEAKY CLEAN CAR WASH** **1900 CERRILLOS RD** **SANTA FE NM**	LST

Release ID:	1484	**Latitude (Map):**	35.663803
Facility ID:	30744	**Longitude (Map):**	-105.974284
Status:	No Further Action, Confirmed Release	**Address (Map):**	1900 CERRILLOS RD
Address:		**Address2 (Map):**	
City:		**City (Map):**	SANTA FE
County:		**State (Map):**	NM
Address (NFA):	1900 CERRILLOS RD	**Zip (Map):**	87502
City (NFA):	SANTA FE	**Address (Priority):**	
County (NFA):	SANTA FE	**City (Priority):**	
Facility Release IDs (Map):	1484	**County (Priority):**	
Data Source:	NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)		

PSTB No Further Action Sites

Status:	No Further Action, Confirmed Release
NFA Date:	05/24/1993
NFA PDF:	https://cloud.env.nm.gov/resources/collection/9196

Leaking Petroleum Storage Tank Sites

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Status Date Dt:	1993-05-24 00:00:00 UTC	**NAPL Off Site Val:**	0
Within SWPA Val:	0	**Plume Area No:**	
Surface Water Val:	0	**Plume Area Val:**	2
Private Well Val:	0	**Max Thickness No:**	
Municipal Well Val:	0	**Max Thickness Val:**	
LUWU Sco:	0	**NAPLSco:**	0
Surficial Conc Des:		**Priority2 Sco:**	0
Surficial Conc Val:	0	**Impact Type Des:**	
Leaching Conc Des:		**Impact Type Val:**	0
Leaching Conc Val:	0	**WS Type Des:**	
Construct Conc Des:		**WS Type Val:**	0
Construct Conc Val:	0	**WTR Sys Repl Des:**	
Building Type Des:		**WTR Sys Repl Val:**	0
Building Type Val:	0	**Population No:**	
Vad Off Site Val:	1	**Population Val:**	1
Vadose Sco:	0	**WS Sco:**	0
Conc Des:		**Toxic Vapor Des:**	
Conc Val:	0	**Toxic Vapor Val:**	0
Plume Mob Des:		**Toxic Vapor Sco:**	0
Plume Mob Val:	0	**Priority1 Sco:**	0
GWDPP Off Site Val:	0	**Total Sco:**	0
Benzene Area No:		**Tempo Total Sco:**	
Benzene Area Val:	1	**Current Priority:**	
GWDPP Sco:	0	**Tempo Current Rank:**	
Priority3 Sco:	0	**Tempo Curr Priorty:**	
CSS Age Des:		**Point X:**	-105.97428400000001
CSS Age Val:	0	**Point Y:**	35.66380299999997
CSS Type Des:		**Irrigation Well Val:**	0
CSS Type Val:	0	**Subsurf Conc Des:**	
CSS Off Site Val:	1	**Subsurface Conc Val:**	0
CSS Sco:	0	**Petrol Soil Bldg Val:**	1
CSS Volume No:		**Petrol Soil Vol Val:**	0
CSS Volume Val:	3	**Hydraulic Grad Val:**	0
Release Pm:	UNKNOWN	**Depth to GW:**	
NAPL Type Des:		**Depth to GW Val:**	2
NAPL Type Val:	0	**Explosive Vapor Des:**	
NAPL Age Des:		**Explosive Vapor Val:**	0
NAPL Age Val:	0	**Explosive Vapor Sco:**	0
NAPLCondition Des:		**Eco Impact Val:**	0
NAPLCondition Val:	0	**Eco Impact Sco:**	0

Facility Name:	SQUEAKY CLEAN CARWASH
Current Status:	No Further Action, Confirmed Release
Aquifer Water Quality Des:	
Aquifer Water Quality Val:	0
Residential Property Val:	0
NAPL Plume Mobility Des:	
NAPL Plume Mobility Val:	0
Property Damage Des:	
Property Damage Val:	0
Property Damage Sco:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
13	2 of2	WSW	0.32 / 1,671.25	6,817.51 / -30	SQUEAKY CLEAN CAR WA 1900 CERRILLOS RD SANTA FE NM	LUST HIST

Form No:	1484	**Contact:**	BERRIDGE DISTRI
Facility ID:	30744	**CRC 32:**	3791299116
Status:	NFA	**Aggrav Factor Score:**	0
Facility Status:	No Further Action	**Mitigat Factor Score:**	3
Stat Date:		**Water Supply Impact:**	N
Date Reported:	21-AUG-92	**Vapor Explos Impact:**	N
SR Result:		**Prpty Damage Impact:**	N
Priority:		**Staff:**	UNK
Score:		**Unloc:**	FALSE
St:		**Latitude:**	0
Site Priority Rank:		**Longitude:**	0
Total Score:	0	**Facility County:**	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
Tie Score:	158					

14	1 of2	WSW	0.32 / 1,675.16	6,814.37 / -33	1901 CERRILLOS CHEVRON 1901 CERRILLOS RD SANTA FE NM	LST

Release ID:	4614	**Latitude (Map):**	35.664315
Facility ID:	1031	**Longitude (Map):**	-105.974589
Status:	No Further Action, Confirmed Release	**Address (Map):**	1901 CERRILLOS RD
Address:		**Address2 (Map):**	
City:		**City (Map):**	SANTA FE
County:		**State (Map):**	NM
Address (NFA):	1901 CERRILLOS RD	**Zip (Map):**	87504
City (NFA):	SANTA FE	**Address (Priority):**	
County (NFA):	SANTA FE	**City (Priority):**	
Facility Release IDs (Map):	4614	**County (Priority):**	

Data Source: NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)

PSTB No Further Action Sites

Status:	No Further Action, Confirmed Release
NFA Date:	10/06/2010
NFA PDF:	https://cloud.env.nm.gov/resources/collection/8547

Leaking Petroleum Storage Tank Sites

Status Date Dt:	2010-10-06 00:00:00 UTC	**NAPL Off Site Val:**	0
Within SWPA Val:	0	**Plume Area No:**	
Surface Water Val:	0	**Plume Area Val:**	2
Private Well Val:	0	**Max Thickness No:**	
Municipal Well Val:	0	**Max Thickness Val:**	
LUWU Sco:	0	**NAPLSco:**	0
Surficial Conc Des:		**Priority2 Sco:**	0
Surficial Conc Val:	0	**Impact Type Des:**	
Leaching Conc Des:		**Impact Type Val:**	0
Leaching Conc Val:	0	**WS Type Des:**	
Construct Conc Des:		**WS Type Val:**	0
Construct Conc Val:	0	**WTR Sys Repl Des:**	
Building Type Des:		**WTR Sys Repl Val:**	0
Building Type Val:	0	**Population No:**	
Vad Off Site Val:	1	**Population Val:**	1
Vadose Sco:	0	**WS Sco:**	0
Conc Des:		**Toxic Vapor Des:**	
Conc Val:	0	**Toxic Vapor Val:**	0
Plume Mob Des:		**Toxic Vapor Sco:**	0
Plume Mob Val:	0	**Priority1 Sco:**	0
GWDPP Off Site Val:	0	**Total Sco:**	0
Benzene Area No:		**Tempo Total Sco:**	
Benzene Area Val:	1	**Current Priority:**	
GWDPP Sco:	0	**Tempo Current Rank:**	
Priority3 Sco:	0	**Tempo Curr Priorty:**	
CSS Age Des:		**Point X:**	-105.97458899999998
CSS Age Val:	0	**Point Y:**	35.66431499999999
CSS Type Des:		**Irrigation Well Val:**	0
CSS Type Val:	0	**Subsurf Conc Des:**	
CSS Off Site Val:	1	**Subsurface Conc Val:**	0
CSS Sco:	0	**Petrol Soil Bldg Val:**	1
CSS Volume No:		**Petrol Soil Vol Val:**	0
CSS Volume Val:	3	**Hydraulic Grad Val:**	0
Release Pm:	George Beaumont	**Depth to GW:**	
NAPL Type Des:		**Depth to GW Val:**	2
NAPL Type Val:	0	**Explosive Vapor Des:**	
NAPL Age Des:		**Explosive Vapor Val:**	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

NAPL Age Val:	0	Explosive Vapor Sco:	0
NAPLCondition Des:		Eco Impact Val:	0
NAPLCondition Val:	0	Eco Impact Sco:	0
Facility Name:	1901 CERRILLOS CHEVRON		
Current Status:	No Further Action, Confirmed Release		
Aquifer Water Quality Des:			
Aquifer Water Quality Val:	0		
Residential Property Val:	0		
NAPL Plume Mobility Des:			
NAPL Plume Mobility Val:	0		
Property Damage Des:			
Property Damage Val:	0		
Property Damage Sco:	0		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
14	2 of2	WSW	0.32 / 1,675.16	6,814.37 / -33	Amigo Tire and Auto 1901 Cerrillos Road, Santa Fe, New Mexico NM	SWF/LF

Permit Reg No:		Spcl Waste Perm No:	
Status:	Open	Spcl Expire Date:	
Facility Type:	Tire Generator	Spcl Issue Date:	
Reg Type:		Spcl Type:	
Reg Issue Date:		County:	Santa Fe
Reg Expire Date:		Latitude:	
EA:	2	Longitude:	
Address:	1901 Cerrillos Road		
City:	Santa Fe		
State:	NM		
Zip:	87505		
Contact:	Eben Cohan		
Contact Phone:	505-984-0900		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
15	1 of2	NE	0.32 / 1,694.70	6,871.70 / 24	TECHLINE STUDIO 1418 CERRILLOS RD SANTA FE NM	LST

Release ID:	2068	Latitude (Map):	35.669909
Facility ID:	31028	Longitude (Map):	-105.965307
Status:	No Further Action, Confirmed Release	Address (Map):	1418 CERRILLOS RD
Address:		Address2 (Map):	
City:		City (Map):	SANTA FE
County:		State (Map):	NM
Address (NFA):	1418 CERRILLOS RD	Zip (Map):	87501
City (NFA):	SANTA FE	Address (Priority):	
County (NFA):	SANTA FE	City (Priority):	
Facility Release IDs (Map):	2068	County (Priority):	
Data Source:	NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)		

PSTB No Further Action Sites

Status:	No Further Action, Confirmed Release
NFA Date:	01/05/1994
NFA PDF:	https://cloud.env.nm.gov/resources/collection/9181

Leaking Petroleum Storage Tank Sites

Status Date Dt:	1994-01-05 00:00:00 UTC	NAPL Off Site Val:	0
Within SWPA Val:	0	Plume Area No:	
Surface Water Val:	0	Plume Area Val:	2
Private Well Val:	0	Max Thickness No:	
Municipal Well Val:	0	Max Thickness Val:	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

LUWU Sco:	0	NAPLSco:	0
Surficial Conc Des:		Priority2 Sco:	0
Surficial Conc Val:	0	Impact Type Des:	
Leaching Conc Des:		Impact Type Val:	0
Leaching Conc Val:	0	WS Type Des:	
Construct Conc Des:		WS Type Val:	0
Construct Conc Val:	0	WTR Sys Repl Des:	
Building Type Des:		WTR Sys Repl Val:	0
Building Type Val:	0	Population No:	
Vad Off Site Val:	1	Population Val:	1
Vadose Sco:	0	WS Sco:	0
Conc Des:		Toxic Vapor Des:	
Conc Val:	0	Toxic Vapor Val:	0
Plume Mob Des:		Toxic Vapor Sco:	0
Plume Mob Val:	0	Priority1 Sco:	0
GWDPP Off Site Val:	0	Total Sco:	0
Benzene Area No:		Tempo Total Sco:	
Benzene Area Val:	1	Current Priority:	
GWDPP Sco:	0	Tempo Current Rank:	
Priority3 Sco:	0	Tempo Curr Priorty:	
CSS Age Des:		Point X:	-105.965307
CSS Age Val:	0	Point Y:	35.66990900000002
CSS Type Des:		Irrigation Well Val:	0
CSS Type Val:	0	Subsurf Conc Des:	
CSS Off Site Val:	1	Subsurface Conc Val:	0
CSS Sco:	0	Petrol Soil Bldg Val:	1
CSS Volume No:		Petrol Soil Vol Val:	0
CSS Volume Val:	3	Hydraulic Grad Val:	0
Release Pm:	UNKNOWN	Depth to GW:	
NAPL Type Des:		Depth to GW Val:	2
NAPL Type Val:	0	Explosive Vapor Des:	
NAPL Age Des:		Explosive Vapor Val:	0
NAPL Age Val:	0	Explosive Vapor Sco:	0
NAPLCondition Des:		Eco Impact Val:	0
NAPLCondition Val:	0	Eco Impact Sco:	0

Facility Name:	TECHLINE STUDIO
Current Status:	No Further Action, Confirmed Release
Aquifer Water Quality Des:	
Aquifer Water Quality Val:	0
Residential Property Val:	0
NAPL Plume Mobility Des:	
NAPL Plume Mobility Val:	0
Property Damage Des:	
Property Damage Val:	0
Property Damage Sco:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
15	2 of2	NE	0.32 / 1,694.70	6,871.70 / 24	TECHLINE STUDIO 1418 CERRILLOS RD SANTA FE NM	LUST HIST

Form No:	2068	Contact:	UNKNOWN
Facility ID:	31028	CRC 32:	2665601412
Status:	NFA	Aggrav Factor Score:	0
Facility Status:	No Further Action	Mitigat Factor Score:	3
Stat Date:		Water Supply Impact:	N
Date Reported:	25-OCT-93	Vapor Explos Impact:	N
SR Result:		Prpty Damage Impact:	N
Priority:		Staff:	UNK
Score:		Unloc:	FALSE
St:		Latitude:	0
Site Priority Rank:		Longitude:	0
Total Score:	0	Facility County:	
Tie Score:	158		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
16	1 of2	E	0.33 / 1,740.35	6,881.91 / 35	SHUTTLEJACK 1600 LENA RD	LST

SANTA FE NM

Release ID:	2661	***Latitude (Map):***	35.665537
Facility ID:	30595	***Longitude (Map):***	-105.963516
Status:	No Further Action, Confirmed Release	***Address (Map):***	1600 LENA RD
Address:		***Address2 (Map):***	
City:		***City (Map):***	SANTA FE
County:		***State (Map):***	NM
Address (NFA):	1600 LENA RD	***Zip (Map):***	87501
City (NFA):	SANTA FE	***Address (Priority):***	
County (NFA):	SANTA FE	***City (Priority):***	
Facility Release IDs (Map):	2661	***County (Priority):***	

Data Source: NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)

PSTB No Further Action Sites

Status:	No Further Action, Confirmed Release
NFA Date:	11/04/1999
NFA PDF:	https://cloud.env.nm.gov/resources/collection/9220

Leaking Petroleum Storage Tank Sites

Status Date Dt:	1999-11-04 00:00:00 UTC	***NAPL Off Site Val:***	0
Within SWPA Val:	0	***Plume Area No:***	
Surface Water Val:	0	***Plume Area Val:***	2
Private Well Val:	0	***Max Thickness No:***	
Municipal Well Val:	0	***Max Thickness Val:***	
LUWU Sco:	0	***NAPLSco:***	0
Surficial Conc Des:		***Priority2 Sco:***	0
Surficial Conc Val:	0	***Impact Type Des:***	
Leaching Conc Des:		***Impact Type Val:***	0
Leaching Conc Val:	0	***WS Type Des:***	
Construct Conc Des:		***WS Type Val:***	0
Construct Conc Val:	0	***WTR Sys Repl Des:***	
Building Type Des:		***WTR Sys Repl Val:***	0
Building Type Val:	0	***Population No:***	
Vad Off Site Val:	1	***Population Val:***	1
Vadose Sco:	0	***WS Sco:***	0
Conc Des:		***Toxic Vapor Des:***	
Conc Val:	0	***Toxic Vapor Val:***	0
Plume Mob Des:		***Toxic Vapor Sco:***	0
Plume Mob Val:	0	***Priority1 Sco:***	0
GWDPP Off Site Val:	0	***Total Sco:***	0
Benzene Area No:		***Tempo Total Sco:***	
Benzene Area Val:	1	***Current Priority:***	
GWDPP Sco:	0	***Tempo Current Rank:***	
Priority3 Sco:	0	***Tempo Curr Priorty:***	
CSS Age Des:		***Point X:***	-105.96351600000003
CSS Age Val:	0	***Point Y:***	35.66553699999997
CSS Type Des:		***Irrigation Well Val:***	0
CSS Type Val:	0	***Subsurf Conc Des:***	
CSS Off Site Val:	1	***Subsurface Conc Val:***	0
CSS Sco:	0	***Petrol Soil Bldg Val:***	1
CSS Volume No:		***Petrol Soil Vol Val:***	0
CSS Volume Val:	3	***Hydraulic Grad Val:***	0
Release Pm:	Lorena Goerger	***Depth to GW:***	
NAPL Type Des:		***Depth to GW Val:***	2
NAPL Type Val:	0	***Explosive Vapor Des:***	
NAPL Age Des:		***Explosive Vapor Val:***	0
NAPL Age Val:	0	***Explosive Vapor Sco:***	0
NAPLCondition Des:		***Eco Impact Val:***	0
NAPLCondition Val:	0	***Eco Impact Sco:***	0
Facility Name:	SHUTTLEJACK		
Current Status:	No Further Action, Confirmed Release		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Aquifer Water Quality Des:
Aquifer Water Quality Val: 0
Residential Property Val: 0
NAPL Plume Mobility Des:
NAPL Plume Mobility Val: 0
Property Damage Des:
Property Damage Val: 0
Property Damage Sco: 0

---

16 | ***2 of2*** | ***E*** | ***0.33 / 1,740.35*** | ***6,881.91 / 35*** | ***SHUTTLEJACK 1600 LENA RD SANTA FE NM*** | ***LUST HIST***

Form No: 2661
Facility ID: 30595
Status: NFA
Facility Status: No Further Action
Stat Date:
Date Reported: 11-JUL-95
SR Result:
Priority:
Score:
St:
Site Priority Rank:
Total Score:
Tie Score:

Contact: SENA
CRC 32: 1535353042
Aggrav Factor Score:
Mitigat Factor Score:
Water Supply Impact: U
Vapor Explos Impact: U
Prpty Damage Impact: U
Staff: LLG
Unloc: FALSE
Latitude: 0
Longitude: 0
Facility County:

---

17 | ***1 of2*** | ***NE*** | ***0.36 / 1,919.48*** | ***6,878.48 / 31*** | ***SANTA FE BULK PLANT 1404 CERRILLOS RD SANTA FE NM*** | ***LST***

Release ID: 1765
Facility ID: 1778
Status: No Further Action, Confirmed Release
Address:
City:
County:
Address (NFA): 1404 CERRILLOS RD
City (NFA): SANTA FE
County (NFA): SANTA FE
Facility Release IDs (Map): 1765

Latitude (Map): 35.670183
Longitude (Map): -105.964556
Address (Map): 1404 CERRILLOS RD
Address2 (Map):
City (Map): SANTA FE
State (Map): NM
Zip (Map): 87504
Address (Priority):
City (Priority):
County (Priority):

Data Source: NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)

PSTB No Further Action Sites

Status: No Further Action, Confirmed Release
NFA Date: 11/17/1993
NFA PDF: https://cloud.env.nm.gov/resources/collection/10748

Leaking Petroleum Storage Tank Sites

Status Date Dt: 1993-11-17 00:00:00 UTC
Within SWPA Val: 0
Surface Water Val: 0
Private Well Val: 0
Municipal Well Val: 0
LUWU Sco: 0
Surficial Conc Des:
Surficial Conc Val: 0
Leaching Conc Des:
Leaching Conc Val: 0
Construct Conc Des:

NAPL Off Site Val: 0
Plume Area No:
Plume Area Val: 2
Max Thickness No:
Max Thickness Val:
NAPLSco: 0
Priority2 Sco: 0
Impact Type Des:
Impact Type Val: 0
WS Type Des:
WS Type Val: 0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Construct Conc Val:	0	**WTR Sys Repl Des:**	
Building Type Des:		**WTR Sys Repl Val:**	0
Building Type Val:	0	**Population No:**	
Vad Off Site Val:	1	**Population Val:**	1
Vadose Sco:	0	**WS Sco:**	0
Conc Des:		**Toxic Vapor Des:**	
Conc Val:	0	**Toxic Vapor Val:**	0
Plume Mob Des:		**Toxic Vapor Sco:**	0
Plume Mob Val:	0	**Priority1 Sco:**	0
GWDPP Off Site Val:	0	**Total Sco:**	0
Benzene Area No:		**Tempo Total Sco:**	
Benzene Area Val:	1	**Current Priority:**	
GWDPP Sco:	0	**Tempo Current Rank:**	
Priority3 Sco:	0	**Tempo Curr Priorty:**	
CSS Age Des:		**Point X:**	-105.96455600000002
CSS Age Val:	0	**Point Y:**	35.67018300000001
CSS Type Des:		**Irrigation Well Val:**	0
CSS Type Val:	0	**Subsurf Conc Des:**	
CSS Off Site Val:	1	**Subsurface Conc Val:**	0
CSS Sco:	0	**Petrol Soil Bldg Val:**	1
CSS Volume No:		**Petrol Soil Vol Val:**	0
CSS Volume Val:	3	**Hydraulic Grad Val:**	0
Release Pm:	Gerard Schoeppner	**Depth to GW:**	
NAPL Type Des:		**Depth to GW Val:**	2
NAPL Type Val:	0	**Explosive Vapor Des:**	
NAPL Age Des:		**Explosive Vapor Val:**	0
NAPL Age Val:	0	**Explosive Vapor Sco:**	0
NAPLCondition Des:		**Eco Impact Val:**	0
NAPLCondition Val:	0	**Eco Impact Sco:**	0

Facility Name:	SANTA FE BULK PLANT
Current Status:	No Further Action, Confirmed Release
Aquifer Water Quality Des:	
Aquifer Water Quality Val:	0
Residential Property Val:	0
NAPL Plume Mobility Des:	
NAPL Plume Mobility Val:	0
Property Damage Des:	
Property Damage Val:	0
Property Damage Sco:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
17	2 of2	NE	0.36 / 1,919.48	6,878.48 / 31	SANTA FE BULK PLANT 1404 CERRILLOS RD SANTA FE NM	LUST HIST

Form No:	1765	**Contact:**	BREWER OIL CO
Facility ID:	1778	**CRC 32:**	2651988082
Status:	NFA	**Aggrav Factor Score:**	
Facility Status:	No Further Action	**Mitigat Factor Score:**	
Stat Date:		**Water Supply Impact:**	U
Date Reported:	05-MAR-93	**Vapor Explos Impact:**	U
SR Result:		**Prpty Damage Impact:**	U
Priority:		**Staff:**	GAS
Score:		**Unloc:**	FALSE
St:		**Latitude:**	0
Site Priority Rank:		**Longitude:**	0
Total Score:		**Facility County:**	
Tie Score:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
18	1 of2	NE	0.40 / 2,090.82	6,884.10 / 37	Fmr White Swan Laundry Facility 1368 Cerrillos Road Santa Fe NM	DELISTED SCS

Title:	Active State Cleanup Sites
Size (Acres):	1.5
County:	Santa Fe
Latitude:	35.670472

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Longitude: -105.964247
Original Source: SCS
Record Date: 01-JAN-2023

---

18 | **2 of2** | **NE** | **0.40 / 2,090.82** | **6,884.10 / 37** | **White Swan Laundy**
1368 Cerrillos Road
Santa Fe NM | **VCP**

VRP ID: 53241003
CERCLIS No:
Status: Active
County: Santa Fe
Latitude: 35.67
Longitude: -105.964
Township Range: T17N, R9E, Section 26
Size (Acres): 0.6
Applicant: Elisia LLLP
Project Manager: Morgan
Cov Not to Sue CNS:
Cmpt RPT Apprv:
Condl Cert of Comp:
Contamination Type: Chloronated solvents: PCE, TCE, DCE, vinyl chloride
Institutional Engineering Cont:
Land Use Restrictions:
Final Work Plan Approved: 4/23/2025

Application Rcvd: 7/18/2024
Cert of Completion:
Final Work Plan Rc'd: 4/18/2025
Transfer CNS:
Public Notice: 10/30/2024
Conditional Elig: 10/30/2024
Final Eligibility: 1/13/2025
VRA Signed: 1/22/2025
Termination:
Recission:
Rejection:

---

19 | **1 of1** | **NE** | **0.40 / 2,134.44** | **6,878.09 / 31** | **Discount Tire (Santa Fe - North)**
1366 Cerrillos Road, Santa Fe,
New Mexico 87505
NM | **SWF/LF**

Permit Reg No:
Status: Open
Facility Type: Tire Generator
Reg Type:
Reg Issue Date:
Reg Expire Date:
EA: 2
Address: 8220 San Pedro Drive NE, Suite 440
City: Albuquerque
State: NM
Zip: 87113
Contact: Jerry Coscarelli, District Manager
Contact Phone: 505-984-0626

Spcl Waste Perm No:
Spcl Expire Date:
Spcl Issue Date:
Spcl Type:
County: Santa Fe
Latitude:
Longitude:

---

20 | **1 of3** | **WSW** | **0.41 / 2,149.62** | **6,803.44 / -44** | **CONTROLS FOR ENVIRONMENTAL POLLUTION**
1925 ROSINA
SANTA FE NM 87501 | **CERCLIS**

Site ID: 0600835
Site EPA ID: NMD061277596
Site Street Address 2:
Site County Name: SANTA FE
Site FIPS Code: 35049
Region Code: 06
Site SMSA No.:
Site Prim. Latitude: 35D40M36S
Site Prim. Longitude: 105D57M00S
Lat Long Source:
RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information

RNPL Status Code: N
NPL Status: Not on the NPL
RFED Facility Code: N
RFED Facility Desc: Not a Federal Facility
USGS Hydro Unit No.: 13020201
Site Cong. Dist. Code: 01
ROT Desc: Other
FR NPL Update No.:
RFRA Code:

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	
Act Code ID:		***Act Start Date:***	
RAT Code:		***Act Complete Date:***	
RAT Short Name:		***AGT Order No.:***	0
RAT Name:		***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:		***SH Seq:***	
RAT Level:		***SH Start Date:***	
RAT DEF OU:		***SH Complete Date:***	
RFBS Code:		***SH Lead:***	
SPA Code:			
RAT Def:			
Site Desc:	No description available .		
Site Alias:	No alias data available		

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	EPA Fund
Act Code ID:	001	***Act Start Date:***	
RAT Code:	DS	***Act Complete Date:***	1/1/1981 00:00:00
RAT Short Name:	DISCVRY	***AGT Order No.:***	10
RAT Name:	DISCOVERY	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:		***SH Lead:***	
SPA Code:	13		
RAT Def:	The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.		
Site Desc:			
Site Alias:			

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	EPA In-House
Act Code ID:	001	***Act Start Date:***	
RAT Code:	VS	***Act Complete Date:***	3/1/1981 00:00:00
RAT Short Name:	ARCH SITE	***AGT Order No.:***	1500
RAT Name:	ARCHIVE SITE	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:		***SH Lead:***	
SPA Code:	13		
RAT Def:	The decision is made that no further activity is planned at the site.		
Site Desc:			
Site Alias:			

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	EPA Fund
Act Code ID:	001	***Act Start Date:***	3/1/1981 00:00:00
RAT Code:	PA	***Act Complete Date:***	3/1/1981 00:00:00
RAT Short Name:	PA	***AGT Order No.:***	130
RAT Name:	PRELIMINARY ASSESSMENT	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:	P	***SH Lead:***	

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SPA Code: 13
RAT Def: Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.
Site Desc:
Site Alias:

---

20 **2 of3** **WSW** **0.41 / 2,149.62** **6,803.44 / -44**

CONTROLS FOR ENVIRONMENTAL POLLUTION
1925 ROSINA
SANTA FE NM 87501

CERCLIS NFRAP

Site ID: 600835
Site EPA ID: NMD061277596
Site Parent ID:
Site County Name: SANTA FE
Parent Site Name:

Site FIPS Code: 35049
Region Code: 6
Site Cong. Dist. Code: 1
Federal Facility:

CERCLIS-NFRAP Assess History

OU ID: 0
Act Code ID: 1
RAT Code: PA
RAT Short Name: PA
RAT Name: PRELIMINARY ASSESSMENT
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU: 00
RFBS Code: P
SPA Code: 13
RALT Short Name: EPA Fund
RAT Def: Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.
RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information

Act Start Date: 3/1/1981
Act Complete Date: 3/1/1981
AGT Order No.: 130
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:
SH Qual:
RAQ Act. Qual Short: NFRAP
RNPL Status Code: N

CERCLIS-NFRAP Assess History

OU ID: 0
Act Code ID: 1
RAT Code: DS
RAT Short Name: DISCVRY
RAT Name: DISCOVERY
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU: 00
RFBS Code:
SPA Code: 13
RALT Short Name: EPA Fund
RAT Def: The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.
RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information

Act Start Date:
Act Complete Date: 1/1/1981
AGT Order No.: 10
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:
SH Qual:
RAQ Act. Qual Short:
RNPL Status Code: N

CERCLIS-NFRAP Assess History

OU ID: 0
Act Code ID: 1
RAT Code: VS
RAT Short Name: ARCH SITE
RAT Name: ARCHIVE SITE
RAT Hist. Only Flag:
RAT NSI Indicator: B
RAT Level: 1
RAT DEF OU: 00
RFBS Code:

Act Start Date:
Act Complete Date: 3/1/1981
AGT Order No.: 1500
SH OU:
SH Code:
SH Seq:
SH Start Date:
SH Complete Date:
SH Lead:
SH Qual:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

SPA Code: 13
RAQ Act. Qual Short:
RALT Short Name: EPA In-House
RNPL Status Code: N
RAT Def: The decision is made that no further activity is planned at the site.
RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information

---

20 | **3 of3** | **WSW** | **0.41 / 2,149.62** | **6,803.44 / -44** | **CONTROLS FOR ENVIRONMENTAL POLLUTION**
1925 ROSINA
SANTA FE NM 87501
SEMS ARCHIVE

Site ID: 0600835
EPA ID: NMD061277596
Superfund Alte Agr: No
Federal Facility: No
FF Docket: No
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information
FIPS Code: 35049
Cong District: 01
Region: 06
County: SANTA FE

Action Information

Operable Units: 00
Action Code: DS
Action Name: DISCVRY
Start Actual: 1/1/1981 5:00:00 AM
Finish Actual: 1/1/1981 5:00:00 AM
Curr Action Lead: EPA Perf
NPL: N
Qual:
SEQ: 1
FF: No
FF Docket: No
Region: 06

Operable Units: 00
Action Code: PA
Action Name: PA
Start Actual: 3/1/1981 5:00:00 AM
Finish Actual: 3/1/1981 5:00:00 AM
Curr Action Lead: EPA Perf
NPL: N
Qual: N
SEQ: 1
FF: No
FF Docket: No
Region: 06

Operable Units: 00
Action Code: VS
Action Name: ARCH SITE
Start Actual:
Finish Actual: 3/1/1981 5:00:00 AM
Curr Action Lead: EPA Perf In-Hse
NPL: N
Qual:
SEQ: 1
FF: No
FF Docket: No
Region: 06

---

21 | **1 of2** | **S** | **0.43 / 2,292.17** | **6,834.88 / -12** | **ATEX ALLSUPS #327**
1899 SAINT MICHAELS DR
SANTA FE NM
LST

Release ID: 1826
Facility ID: 26541
Status: No Further Action, Confirmed Release
Address:
City:
County:
Address (NFA): 1899 SAINT MICHAELS DR
City (NFA): SANTA FE
County (NFA): SANTA FE
Facility Release IDs (Map): 1826
Latitude (Map): 35.659652
Longitude (Map): -105.970103
Address (Map): 1899 SAINT MICHAELS DR
Address2 (Map):
City (Map): SANTA FE
State (Map): NM
Zip (Map): 87501
Address (Priority):
City (Priority):
County (Priority):
Data Source: NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)

PSTB No Further Action Sites

Status: No Further Action, Confirmed Release

NFA Date: 10/26/1993
NFA PDF: https://cloud.env.nm.gov/resources/collection/10811

Leaking Petroleum Storage Tank Sites

Status Date Dt:	1993-10-26 00:00:00 UTC	**NAPL Off Site Val:**	0
Within SWPA Val:	0	**Plume Area No:**	
Surface Water Val:	0	**Plume Area Val:**	2
Private Well Val:	0	**Max Thickness No:**	
Municipal Well Val:	0	**Max Thickness Val:**	
LUWU Sco:	0	**NAPLSco:**	0
Surficial Conc Des:		**Priority2 Sco:**	0
Surficial Conc Val:	0	**Impact Type Des:**	
Leaching Conc Des:		**Impact Type Val:**	0
Leaching Conc Val:	0	**WS Type Des:**	
Construct Conc Des:		**WS Type Val:**	0
Construct Conc Val:	0	**WTR Sys Repl Des:**	
Building Type Des:		**WTR Sys Repl Val:**	0
Building Type Val:	0	**Population No:**	
Vad Off Site Val:	1	**Population Val:**	1
Vadose Sco:	0	**WS Sco:**	0
Conc Des:		**Toxic Vapor Des:**	
Conc Val:	0	**Toxic Vapor Val:**	0
Plume Mob Des:		**Toxic Vapor Sco:**	0
Plume Mob Val:	0	**Priority1 Sco:**	0
GWDPP Off Site Val:	0	**Total Sco:**	0
Benzene Area No:		**Tempo Total Sco:**	
Benzene Area Val:	1	**Current Priority:**	
GWDPP Sco:	0	**Tempo Current Rank:**	
Priority3 Sco:	0	**Tempo Curr Priorty:**	
CSS Age Des:		**Point X:**	-105.970103
CSS Age Val:	0	**Point Y:**	35.659651999999994
CSS Type Des:		**Irrigation Well Val:**	0
CSS Type Val:	0	**Subsurf Conc Des:**	
CSS Off Site Val:	1	**Subsurface Conc Val:**	0
CSS Sco:	0	**Petrol Soil Bldg Val:**	1
CSS Volume No:		**Petrol Soil Vol Val:**	0
CSS Volume Val:	3	**Hydraulic Grad Val:**	0
Release Pm:	UNKNOWN	**Depth to GW:**	
NAPL Type Des:		**Depth to GW Val:**	2
NAPL Type Val:	0	**Explosive Vapor Des:**	
NAPL Age Des:		**Explosive Vapor Val:**	0
NAPL Age Val:	0	**Explosive Vapor Sco:**	0
NAPLCondition Des:		**Eco Impact Val:**	0
NAPLCondition Val:	0	**Eco Impact Sco:**	0

Facility Name: ALLSUP'S # 102344
Current Status: No Further Action, Confirmed Release
Aquifer Water Quality Des:
Aquifer Water Quality Val: 0
Residential Property Val: 0
NAPL Plume Mobility Des:
NAPL Plume Mobility Val: 0
Property Damage Des:
Property Damage Val: 0
Property Damage Sco: 0

---

21 | ***2 of2*** | ***S*** | ***0.43 / 2,292.17*** | ***6,834.88 / -12*** | ***ATEX ALLSUPS #327 1899 SAINT MICHAELS DR SANTA FE NM*** | ***LUST HIST***

Form No:	1826	**Contact:**	ALLSUPS CONVENI
Facility ID:	26541	**CRC 32:**	12648962
Status:	NFA	**Aggrav Factor Score:**	
Facility Status:	No Further Action	**Mitigat Factor Score:**	
Stat Date:		**Water Supply Impact:**	U
Date Reported:	29-APR-93	**Vapor Explos Impact:**	U
SR Result:		**Prpty Damage Impact:**	U

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Priority:		**Staff:**	UNK
Score:		**Unloc:**	FALSE
St:		**Latitude:**	0
Site Priority Rank:		**Longitude:**	0
Total Score:		**Facility County:**	
Tie Score:			

22	1 of2	SSW	0.47 / 2,487.88	6,820.20 / -27	HORACE CHRYSLER JEEP AND KIA 1701 ST MICHAELS DR SANTA FE NM	LST

Release ID:	4451	**Latitude (Map):**	35.659963
Facility ID:	27353	**Longitude (Map):**	-105.972394
Status:	No Further Action, Confirmed Release	**Address (Map):**	1701 ST MICHAELS DR
Address:		**Address2 (Map):**	
City:		**City (Map):**	SANTA FE
County:		**State (Map):**	NM
Address (NFA):	1701 ST MICHAELS DR	**Zip (Map):**	87501
City (NFA):	SANTA FE	**Address (Priority):**	
County (NFA):	SANTA FE	**City (Priority):**	
Facility Release IDs (Map):	4451	**County (Priority):**	

Data Source: NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)

PSTB No Further Action Sites

Status:	No Further Action, Confirmed Release
NFA Date:	12/22/2008
NFA PDF:	https://cloud.env.nm.gov/resources/collection/10867

Leaking Petroleum Storage Tank Sites

Status Date Dt:	2008-12-22 00:00:00 UTC	**NAPL Off Site Val:**	0
Within SWPA Val:	0	**Plume Area No:**	
Surface Water Val:	0	**Plume Area Val:**	2
Private Well Val:	0	**Max Thickness No:**	
Municipal Well Val:	0	**Max Thickness Val:**	
LUWU Sco:	0	**NAPLSco:**	0
Surficial Conc Des:		**Priority2 Sco:**	0
Surficial Conc Val:	0	**Impact Type Des:**	
Leaching Conc Des:		**Impact Type Val:**	0
Leaching Conc Val:	0	**WS Type Des:**	
Construct Conc Des:		**WS Type Val:**	0
Construct Conc Val:	0	**WTR Sys Repl Des:**	
Building Type Des:		**WTR Sys Repl Val:**	0
Building Type Val:	0	**Population No:**	
Vad Off Site Val:	1	**Population Val:**	1
Vadose Sco:	0	**WS Sco:**	0
Conc Des:		**Toxic Vapor Des:**	
Conc Val:	0	**Toxic Vapor Val:**	0
Plume Mob Des:		**Toxic Vapor Sco:**	0
Plume Mob Val:	0	**Priority1 Sco:**	0
GWDPP Off Site Val:	0	**Total Sco:**	0
Benzene Area No:		**Tempo Total Sco:**	
Benzene Area Val:	1	**Current Priority:**	
GWDPP Sco:	0	**Tempo Current Rank:**	
Priority3 Sco:	0	**Tempo Curr Priorty:**	
CSS Age Des:		**Point X:**	-105.97239400000001
CSS Age Val:	0	**Point Y:**	35.659963000000005
CSS Type Des:		**Irrigation Well Val:**	0
CSS Type Val:	0	**Subsurf Conc Des:**	
CSS Off Site Val:	1	**Subsurface Conc Val:**	0
CSS Sco:	0	**Petrol Soil Bldg Val:**	1

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

CSS Volume No:		**Petrol Soil Vol Val:**	0
CSS Volume Val:	3	**Hydraulic Grad Val:**	0
Release Pm:	Susan Von Gonten	**Depth to GW:**	
NAPL Type Des:		**Depth to GW Val:**	2
NAPL Type Val:	0	**Explosive Vapor Des:**	
NAPL Age Des:		**Explosive Vapor Val:**	0
NAPL Age Val:	0	**Explosive Vapor Sco:**	0
NAPLCondition Des:		**Eco Impact Val:**	0
NAPLCondition Val:	0	**Eco Impact Sco:**	0
Facility Name:	HORACE CHRYSLER JEEP AND KIA		
Current Status:	No Further Action, Confirmed Release		
Aquifer Water Quality Des:			
Aquifer Water Quality Val:	0		
Residential Property Val:	0		
NAPL Plume Mobility Des:			
NAPL Plume Mobility Val:	0		
Property Damage Des:			
Property Damage Val:	0		
Property Damage Sco:	0		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
22	2 of2	SSW	0.47 / 2,487.88	6,820.20 / -27	Horace Chrysler Jeep 1701 St Michaels Dr Santa Fe NM 87501	LUST HIST

Form No:	4451	**Contact:**	
Facility ID:	27353	**CRC 32:**	2210281871
Status:	PI-C	**Aggrav Factor Score:**	
Facility Status:	Pre-Investigation, Confirmed release	**Mitigat Factor Score:**	
Stat Date:	04/15/2005	**Water Supply Impact:**	
Date Reported:	04/15/2005	**Vapor Explos Impact:**	
SR Result:		**Prpty Damage Impact:**	
Priority:		**Staff:**	Susan Von Gonten
Score:		**Unloc:**	
St:	NM	**Latitude:**	
Site Priority Rank:		**Longitude:**	
Total Score:		**Facility County:**	Santa Fe
Tie Score:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
23	1 of1	SSE	0.47 / 2,498.58	6,870.84 / 24	Premier Nissan 2005 St. Michael's Drive Santa Fe NM	VCP

VRP ID:	53062001	**Application Rcvd:**	4/6/2006
CERCLIS No:		**Cert of Completion:**	6/2/2006
Status:	Closed	**Final Work Plan Rc'd:**	
County:	Santa Fe	**Transfer CNS:**	10/22/2010
Latitude:	35.6596	**Public Notice:**	
Longitude:	-105.9663	**Conditional Elig:**	
Township Range:	T17N, R9E, Sec 34	**Final Eligibility:**	5/31/2006
Size (Acres):	2.9	**VRA Signed:**	
Applicant:	Omega Automotive Real Estate, LLC	**Termination:**	
Project Manager:	Bynum	**Recission:**	
Cov Not to Sue CNS:	6/2/2006	**Rejection:**	
Cmpt RPT Apprv:			
Condl Cert of Comp:			
Contamination Type:	Petroleum hydrocarbons associated with hydraulic lifts and sump.		
Institutional Engineering Cont:			
Land Use Restrictions:			
Final Work Plan Approved:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
24	1 of5	WSW	0.48 / 2,539.22	6,796.61 / -51	SPEEDY'S/1 1975 CERRILLOS RD SANTA FE NM	LST

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Release ID:	1617	**Latitude (Map):**	
Facility ID:	30106	**Longitude (Map):**	
Status:	No Further Action, Confirmed Release	**Address (Map):**	
Address:		**Address2 (Map):**	
City:		**City (Map):**	
County:		**State (Map):**	
Address (NFA):	1975 CERRILLOS RD	**Zip (Map):**	
City (NFA):	SANTA FE	**Address (Priority):**	
County (NFA):	SANTA FE	**City (Priority):**	
Facility Release IDs (Map):		**County (Priority):**	

Data Source: NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025)

PSTB No Further Action Sites

Status: No Further Action, Confirmed Release
NFA Date: 12/20/1990
NFA PDF: https://cloud.env.nm.gov/resources/collection/10132

24	2 of5	WSW	0.48 / 2,539.22	6,796.61 / -51	SPEEDY'S 1975 CERRILLOS RD SANTA FE NM	LST

Release ID:	172	**Latitude (Map):**	35.66307
Facility ID:	30106	**Longitude (Map):**	-105.976895
Status:	No Further Action, Confirmed Release	**Address (Map):**	1975 CERRILLOS RD
Address:		**Address2 (Map):**	
City:		**City (Map):**	SANTA FE
County:		**State (Map):**	NM
Address (NFA):	1975 CERRILLOS RD	**Zip (Map):**	87501
City (NFA):	SANTA FE	**Address (Priority):**	
County (NFA):	SANTA FE	**City (Priority):**	
Facility Release IDs (Map):	172,1617	**County (Priority):**	

Data Source: NM ED PTSB No Further Action Sites (NFA) (as of 15 Aug 2025); NM ED Open Data Leaking Petroleum Storage Tank Sites Map (Map) (as of 16 Sep 2025)

PSTB No Further Action Sites

Status: No Further Action, Confirmed Release
NFA Date: 01/05/1993
NFA PDF:

Leaking Petroleum Storage Tank Sites

Status Date Dt:	1993-01-05 00:00:00 UTC	**NAPL Off Site Val:**	0
Within SWPA Val:	0	**Plume Area No:**	
Surface Water Val:	0	**Plume Area Val:**	2
Private Well Val:	0	**Max Thickness No:**	
Municipal Well Val:	0	**Max Thickness Val:**	
LUWU Sco:	0	**NAPLSco:**	0
Surficial Conc Des:		**Priority2 Sco:**	0
Surficial Conc Val:	0	**Impact Type Des:**	
Leaching Conc Des:		**Impact Type Val:**	0
Leaching Conc Val:	0	**WS Type Des:**	
Construct Conc Des:		**WS Type Val:**	0
Construct Conc Val:	0	**WTR Sys Repl Des:**	
Building Type Des:		**WTR Sys Repl Val:**	0
Building Type Val:	0	**Population No:**	
Vad Off Site Val:	1	**Population Val:**	1
Vadose Sco:	0	**WS Sco:**	0
Conc Des:		**Toxic Vapor Des:**	
Conc Val:	0	**Toxic Vapor Val:**	0
Plume Mob Des:		**Toxic Vapor Sco:**	0
Plume Mob Val:	0	**Priority1 Sco:**	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

GWDPP Off Site Val:	0	**Total Sco:**	0
Benzene Area No:		**Tempo Total Sco:**	
Benzene Area Val:	1	**Current Priority:**	
GWDPP Sco:	0	**Tempo Current Rank:**	
Priority3 Sco:	0	**Tempo Curr Priorty:**	
CSS Age Des:		**Point X:**	-105.97689500000001
CSS Age Val:	0	**Point Y:**	35.663070000000005
CSS Type Des:		**Irrigation Well Val:**	0
CSS Type Val:	0	**Subsurf Conc Des:**	
CSS Off Site Val:	1	**Subsurface Conc Val:**	0
CSS Sco:	0	**Petrol Soil Bldg Val:**	1
CSS Volume No:		**Petrol Soil Vol Val:**	0
CSS Volume Val:	3	**Hydraulic Grad Val:**	0
Release Pm:	Anna Richards	**Depth to GW:**	
NAPL Type Des:		**Depth to GW Val:**	2
NAPL Type Val:	0	**Explosive Vapor Des:**	
NAPL Age Des:		**Explosive Vapor Val:**	0
NAPL Age Val:	0	**Explosive Vapor Sco:**	0
NAPLCondition Des:		**Eco Impact Val:**	0
NAPLCondition Val:	0	**Eco Impact Sco:**	0

Facility Name:	QUINTANA GARRETT
Current Status:	No Further Action, Confirmed Release
Aquifer Water Quality Des:	
Aquifer Water Quality Val:	0
Residential Property Val:	0
NAPL Plume Mobility Des:	
NAPL Plume Mobility Val:	0
Property Damage Des:	
Property Damage Val:	0
Property Damage Sco:	0

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
24	3 of5	WSW	0.48 / 2,539.22	6,796.61 / -51	SPEEDY'S 1975 CERRILLOS RD SANTA FE NM	LUST HIST

Form No:	172	**Contact:**	QUINTANA
Facility ID:	30106	**CRC 32:**	3076684626
Status:	NFA	**Aggrav Factor Score:**	0
Facility Status:	No Further Action	**Mitigat Factor Score:**	1
Stat Date:		**Water Supply Impact:**	N
Date Reported:	18-JAN-89	**Vapor Explos Impact:**	N
SR Result:		**Prpty Damage Impact:**	N
Priority:		**Staff:**	AMR
Score:		**Unloc:**	FALSE
St:		**Latitude:**	0
Site Priority Rank:		**Longitude:**	0
Total Score:	0	**Facility County:**	
Tie Score:	158		

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
24	4 of5	WSW	0.48 / 2,539.22	6,796.61 / -51	SPEEDY'S/1 1975 CERRILLOS RD SANTA FE NM	LUST HIST

Form No:	1617	**Contact:**	JACKSON ASSOC
Facility ID:	30106	**CRC 32:**	3076684626
Status:	NFA	**Aggrav Factor Score:**	
Facility Status:	No Further Action	**Mitigat Factor Score:**	
Stat Date:		**Water Supply Impact:**	U
Date Reported:	01-JAN-88	**Vapor Explos Impact:**	U
SR Result:		**Prpty Damage Impact:**	U
Priority:		**Staff:**	UNK
Score:		**Unloc:**	FALSE
St:		**Latitude:**	0
Site Priority Rank:		**Longitude:**	0
Total Score:		**Facility County:**	
Tie Score:			

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
24	5 of5	WSW	0.48 / 2,539.22	6,796.61 / -51	Jiffy Lube 1975 Cerrillos Santa Fe NM	SCS

County: Santa Fe
Latitude: 35.663583
Longitude: -105.975493
Data source(s): Closed/Inactive State Cleanup Sites(Closed)

Closed Detail

Status: closed
Date : 6/27/2005
Discharge Dt: 4/26/2005
Event: 500 gal tank overflowed with windshield wash containing isopropyl alcohol
Action Taken: City removed 35 gal

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
25	1 of1	SSW	0.50 / 2,618.78	6,822.00 / -25	GIANT STOPNGO 1693 ST MICHAELS DR SANTA FE NM	LUST HIST

Form No: 1987
Facility ID: 28317
Status: NFA
Facility Status: No Further Action
Stat Date:
Date Reported: 05-AUG-93
SR Result:
Priority:
Score:
St:
Site Priority Rank: 743
Total Score: 0
Tie Score: 150

Contact: GIANT INDUSTRIE
CRC 32: 2974526887
Aggrav Factor Score: 0
Mitigat Factor Score: 5
Water Supply Impact: N
Vapor Explos Impact: N
Prpty Damage Impact: N
Staff: UNK
Unloc: FALSE
Latitude: 0
Longitude: 0
Facility County:

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
26	1 of1	SSW	0.58 / 3,069.32	6,811.53 / -36	1710 Llano 1710 Llano Santa Fe NM	SCS

County: Santa Fe
Latitude: 35.65815228
Longitude: -105.97307434
Data source(s): Active State Cleanup Sites

Active Detail

Project Manager: Noel
Depth To Water (Ft): unknown
Flow Direction: unknown
Media Impacted: Soil Vapor
Regulatory Status: CAR 1203.A
Size Acres: <1
Contam of Concern: PCE, TCE
Assmnt/Abatement: Passive Soil Vapor Survey conducted, RP is reviewing remedial options

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
27	1 of1	NE	0.59 / 3,122.26	6,893.02 / 46	Berridge Distributing Co 1255 Cerrillos Rd Santa Fe NM	SCS

County: Santa Fe

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Latitude: 35.673615
Longitude: -105.960259
Data source(s): Closed/Inactive State Cleanup Sites(Closed)

Closed Detail

Status: closed
Date : 12/06/1995
Discharge Dt: 10/27/1995
Event: former bulk plant
Action Taken: soil excavation

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
28	1 of1	WSW	0.62 / 3,253.59	6,782.25 / -65	Exxon Station 6-7231 2045 Cerrillos Rd Santa Fe NM	SCS

County: Santa Fe
Latitude: 35.662774
Longitude: -105.977086
Data source(s): Closed/Inactive State Cleanup Sites(Closed)

Closed Detail

Status: closed
Date : 1/03/1989
Discharge Dt: unknown
Event: petroleum contamination
Action Taken: Settlement Agreement
directed remediation

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
29	1 of1	NE	0.67 / 3,515.87	6,890.64 / 43	PNM Baca St North of Shoofly Street and Flagman Way, Near Baca Street and Cerrillos Road Santa Fe NM	SCS

County: Santa Fe
Latitude: 35.675372
Longitude: -105.961277
Data source(s): Active State Cleanup Sites

Active Detail

Project Manager: Kate
Depth To Water (Ft): 240-312
Flow Direction: Generally E to W with localized variability and a recovering cone of depression
Media Impacted: GW
Regulatory Status: Stage 1 AP
Size Acres: 15
Contam of Concern: PSTB Regulated: LNAPL
and petroleum : benzene, toluene, ethylbenzene, total xylenes, 1,2- dibromoethane EDB, EDC, naphthalene;
GWQB Regulated: PCE, TCE, 1,1,
Assmnt/Abatement: Ongoing site characterization. GW monitoring in progress

---

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB
30	1 of1	ENE	0.70 / 3,693.89	6,911.42 / 64	NMDOT Main Yard/GOC 1120 Cerrillos Road Santa Fe NM	SCS

County: Santa Fe
Latitude: 35.673806
Longitude: -105.958712
Data source(s): Active State Cleanup Sites

Map Key	Number of Records	Direction	Distance (mi/ft)	Elev/Diff (ft)	Site	DB

Active Detail

Project Manager: Kate
Depth To Water (Ft): 350, 127 perched zone (2011)
Flow Direction: W
Media Impacted: Soil, Soil Vapor
Regulatory Status: CAR 1203.A
Size Acres: 5
Contam of Concern: PCE, TCE
Assmnt/Abatement: Vapor Intrusion assessment needed.

31	1 of1	NE	0.76 / 4,005.64	6,887.37 / 40	Santa Fe Well, PNM Baca Street and Cerillos Vicinity Santa Fe NM	DELISTED SCS

Title: Active State Cleanup Sites
Size (Acres): 5
County: Santa Fe
Latitude: 35.675426
Longitude: -105.96139
Original Source: SCS
Record Date: 13-APR-2016

Unplottable Summary

Total: 34 Unplottable sites

DB	Company Name/Site Name	Address	City	Zip	ERIS ID
CERCLIS	NAVAJO - UPPER FRUITLAND DUMP	NAVAJO RESERVATION ***Site EPA ID:*** NND986667525	FRUITLAND NM	87416	805438979
CERCLIS	NAMBE OPEN DUMP	NAMBE PUEBLO ***Site EPA ID:*** NM0000016535	SANTE FE NM	87501	805435223
CERCLIS NFRAP	NAMBE OPEN DUMP	NAMBE PUEBLO ***Site EPA ID:*** NM0000016535	SANTE FE NM	87501	805484362
HIST RISK	Townsend Petroleum Co	Cerrillos rd	Santa FE NM		926055593
HIST RISK	Irby's Texaco Service	Cerrillos rd	Santa FE NM		926056706
HIST RISK	Bitz J D	ns Cerrillos rd 6 w AT & SF Ry	Santa FE NM		926061440
HIST RISK	STANDARD OIL CO OF TEXAS	ns Cerrillos rd 4 w AT & SF Ry	Santa FE NM		926067640
HIST RISK	Sierra Vista Park	ns Cerrillos rd 1 w D & R G W R R	Santa FE NM		926096476
HIST RISK	Texas Co	ns Cerrillos rd 4 s AT&SF Ry	Santa FE NM		926175413
HIST RISK	Bill's Super Service	Cerrillos Rd	Santa FE NM		926288306
HIST RISK	Independent Service Station	Cerrillos rd	Santa FE NM		926288672
HIST RISK	SINCLAIR REFINING CO	ns Cerrillos rd 2 e D&RG W RR	Santa FE NM		926299810

HIST RISK	Byrne Petroleum Co	ss Cerrillos rd 2 w AT&SF Ry	Santa FE NM		926380170
HIST RISK	Irby C H	Cerrillos rd	Santa FE NM		926411093
HIST RISK	TEXAS COMPANY THE	Cerrillos rd	Santa FE NM		926468808
HIST RISK	Phillips Petroleum Co	Cerrillos rd	Santa FE NM		926555949
HIST RISK	Austin Joseph	ss Cerrillos rd 13 w AT & SF Ry	Santa FE NM		926558211
HIST RISK	Knight's Repair Shop	Cerrillos rd	Santa FE NM		926564428
HIST RISK	TEXAS COMPANY THE	ns CERRILLOS RD 5 w AT&SF Ry	Santa FE NM		926591386
INDIAN UST	Cochiti Pueblo Golf Course	Located at Cochiti Pueblo ***Facility ID:*** 0119NM	Santa Fe NM	87501	814914470
SEMS ARCHIVE	NAMBE OPEN DUMP	NAMBE PUEBLO ***EPA ID:*** NM0000016535	SANTE FE NM	87501	828853875
SPILLS		houses and property affected are those proximal to the arroyo where the main sewer line runs in the Avenida de las Americas community off Cerrillos Road on ***Notification ID | Status:*** 19018 | No Further Action Needed - Complaint Closed	Avenida de las Americas (behind Denver Mattress). Santa Fe NM		928012855
TANKS	GSA FLEET SERVICE	W AVE AND CERRILLOS RD ***FID | In Use AST | In Use UST:*** 28416 | 0 | 0	SANTA FE NM	87501	820361655
TANKS	OLIVAS VIRGIL AND KATHLEEN	TESUQUE ST PO BOX 1925 TESUQUE ***FID | In Use AST | In Use UST:*** 29783 | 0 | 0	SANTA FE NM	87504	820363740
TANKS	BUREAU OF INDIAN AFFAIRS BRANCH OF ROADS	EASTERN NAVAJO AGENCY PO BOX 328	CROWNPOINT NM	87313	820363261

		***FID	In Use AST	In Use UST:*** 1003 | 0 | 0			
TANKS	NMDOT SANTA FE PATROL YARD 45 46	NM 14 MP 48 4 CERRILLOS RD ***FID	In Use AST	In Use UST:*** 26236 | 1 | 0	SANTA FE NM	87502	820363229
TANKS	SANTA FE WAREHOUSE AREA	E OF CERRILLOS RD ***FID	In Use AST	In Use UST:*** 30470 | 0 | 0	SANTA FE NM	87504	820364569
UST	SANTA FE WAREHOUSE AREA	E OF CERRILLOS RD ***Facility ID:*** 30470 ***In Use UST	Removed UST:*** 0 | 1	SANTA FE NM	87504	878812521
UST	OLIVAS VIRGIL AND KATHLEEN	TESUQUE ST PO BOX 1925 TESUQUE ***Facility ID:*** 29783 ***In Use UST	Removed UST:*** 0 | 0	SANTA FE NM	87504	878815763
UST	GSA FLEET SERVICE	W AVE AND CERRILLOS RD ***Facility ID:*** 28416 ***In Use UST	Removed UST:*** 0 | 2	SANTA FE NM	87501	878813015
UST HIST	GSA FLEET SERVICE	W AVE AND CERRILLOS RD ***Facility ID:*** 28416 ***Tank ID	Tank Status:*** 25463 | REMOVED, 25464 | REMOVED	SANTA FE NM	87501	891534551
UST HIST	SANTA FE WAREHOUSE AREA	E OF CERRILLOS RD ***Facility ID:*** 30470 ***Tank ID	Tank Status:*** 30209 | REMOVED	SANTA FE NM	87504	891536070
UST HIST	BUREAU OF INDIAN AFFAIRS BRANCH OF ROADS	EASTERN NAVAJO AGENCY ***Facility ID:*** 1003 ***Tank ID	Tank Status:*** 33950 | EXEMPT, 33951 | EXEMPT	CROWNPOINT NM	87313	891536005
UST HIST	OLIVAS VIRGIL AND KATHLEEN	TESUQUE ST ***Facility ID:*** 29783 ***Tank ID	Tank Status:*** 28460 | EXEMPT	SANTA FE NM	87504	891534680

Unplottable Report

Site: ***NAVAJO - UPPER FRUITLAND DUMP***
NAVAJO RESERVATION FRUITLAND NM 87416

CERCLIS

Site ID:	0904038	***RNPL Status Code:***	N
Site EPA ID:	NND986667525	***NPL Status:***	Not on the NPL
Site Street Address 2:		***RFED Facility Code:***	N
Site County Name:	SAN JUAN	***RFED Facility Desc:***	Not a Federal Facility
Site FIPS Code:	35045	***USGS Hydro Unit No.:***	14080105
Region Code:	09	***Site Cong. Dist. Code:***	03
Site SMSA No.:		***ROT Desc:***	
Site Prim. Latitude:	36D41M30S	***FR NPL Update No.:***	
Site Prim. Longitude:	108D50M24S	***RFRA Code:***	
Lat Long Source:			
RNON NPL Status Desc:	PA Start Needed		

CERCLIS Site Contact Name(s)

Person ID:	13003811.00
First Name:	Svetlana
Last Name:	Zenkin
Phone No.:	4159723085
Email:	zenkin.svetlana@epa.gov

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	State (Fund)
Act Code ID:	001	***Act Start Date:***	
RAT Code:	DS	***Act Complete Date:***	2/1/1989 00:00:00
RAT Short Name:	DISCVRY	***AGT Order No.:***	10
RAT Name:	DISCOVERY	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:		***SH Lead:***	
SPA Code:	13		
RAT Def:	The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.		
Site Desc:			
Site Alias:			

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	
Act Code ID:		***Act Start Date:***	
RAT Code:		***Act Complete Date:***	
RAT Short Name:		***AGT Order No.:***	0
RAT Name:		***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:		***SH Seq:***	
RAT Level:		***SH Start Date:***	
RAT DEF OU:		***SH Complete Date:***	
RFBS Code:		***SH Lead:***	
SPA Code:			
RAT Def:			
Site Desc:	No description available .		
Site Alias:	No alias data available		

Site: ***NAMBE OPEN DUMP***
NAMBE PUEBLO SANTE FE NM 87501

CERCLIS

Site ID:	0604785	***RNPL Status Code:***	N
Site EPA ID:	NM0000016535	***NPL Status:***	Not on the NPL
Site Street Address 2:		***RFED Facility Code:***	N
Site County Name:	SANTA FE	***RFED Facility Desc:***	Not a Federal Facility
Site FIPS Code:	35049	***USGS Hydro Unit No.:***	13020201
Region Code:	06	***Site Cong. Dist. Code:***	01
Site SMSA No.:		***ROT Desc:***	Unknown
Site Prim. Latitude:	35D40M36S	***FR NPL Update No.:***	
Site Prim. Longitude:	105D57M00S	***RFRA Code:***	
Lat Long Source:			

RNON NPL Status Desc: NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	Tribal
Act Code ID:	001	***Act Start Date:***	
RAT Code:	PA	***Act Complete Date:***	10/7/1993 00:00:00
RAT Short Name:	PA	***AGT Order No.:***	130
RAT Name:	PRELIMINARY ASSESSMENT	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:	P	***SH Lead:***	
SPA Code:	13		

RAT Def: Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.

Site Desc:
Site Alias:

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	
Act Code ID:		***Act Start Date:***	
RAT Code:		***Act Complete Date:***	
RAT Short Name:		***AGT Order No.:***	0
RAT Name:		***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:		***SH Seq:***	
RAT Level:		***SH Start Date:***	
RAT DEF OU:		***SH Complete Date:***	
RFBS Code:		***SH Lead:***	
SPA Code:			

RAT Def:

Site Desc: THE SITE IS LOCATED UP-GRADIENT OF THE PUEBLO'S WATER SUPPLY.

.

Site Alias: No alias data available

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	Tribal
Act Code ID:	001	***Act Start Date:***	
RAT Code:	DS	***Act Complete Date:***	10/1/1993 00:00:00
RAT Short Name:	DISCVRY	***AGT Order No.:***	10
RAT Name:	DISCOVERY	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:		***SH Lead:***	
SPA Code:	13		

RAT Def: The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.

Site Desc:

Site Alias:

CERCLIS Assess History

OU ID:	00	***RALT Short Name:***	EPA In-House
Act Code ID:	001	***Act Start Date:***	
RAT Code:	VS	***Act Complete Date:***	10/7/1993 00:00:00
RAT Short Name:	ARCH SITE	***AGT Order No.:***	1500
RAT Name:	ARCHIVE SITE	***SH OU:***	
RAT Hist. Only Flag:		***SH Code:***	
RAT NSI Indicator:	B	***SH Seq:***	
RAT Level:	1	***SH Start Date:***	
RAT DEF OU:	00	***SH Complete Date:***	
RFBS Code:		***SH Lead:***	
SPA Code:	13		
RAT Def:	The decision is made that no further activity is planned at the site.		
Site Desc:			
Site Alias:			

Site: ***NAMBE OPEN DUMP***
NAMBE PUEBLO SANTE FE NM 87501

CERCLIS NFRAP

Site ID:	604785	***Site FIPS Code:***	35049
Site EPA ID:	NM0000016535	***Region Code:***	6
Site Parent ID:		***Site Cong. Dist. Code:***	1
Site County Name:	SANTA FE	***Federal Facility:***	
Parent Site Name:			

CERCLIS-NFRAP Assess History

OU ID:	0	***Act Start Date:***	
Act Code ID:	1	***Act Complete Date:***	10/7/1993
RAT Code:	PA	***AGT Order No.:***	130
RAT Short Name:	PA	***SH OU:***	
RAT Name:	PRELIMINARY ASSESSMENT	***SH Code:***	
RAT Hist. Only Flag:		***SH Seq:***	
RAT NSI Indicator:	B	***SH Start Date:***	
RAT Level:	1	***SH Complete Date:***	
RAT DEF OU:	00	***SH Lead:***	
RFBS Code:	P	***SH Qual:***	
SPA Code:	13	***RAQ Act. Qual Short:***	NFRAP
RALT Short Name:	Tribal	***RNPL Status Code:***	N
RAT Def:	Collection of diverse existing information about the source and nature of the site hazard. It is EPA policy to complete the preliminary assessment within one year of site discovery.		
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information		

CERCLIS-NFRAP Assess History

OU ID:	0	***Act Start Date:***	
Act Code ID:	1	***Act Complete Date:***	10/1/1993
RAT Code:	DS	***AGT Order No.:***	10
RAT Short Name:	DISCVRY	***SH OU:***	
RAT Name:	DISCOVERY	***SH Code:***	
RAT Hist. Only Flag:		***SH Seq:***	
RAT NSI Indicator:	B	***SH Start Date:***	
RAT Level:	1	***SH Complete Date:***	
RAT DEF OU:	00	***SH Lead:***	
RFBS Code:		***SH Qual:***	
SPA Code:	13	***RAQ Act. Qual Short:***	
RALT Short Name:	Tribal	***RNPL Status Code:***	N
RAT Def:	The process by which a potential hazardous waste site is brought to the attention of the EPA. The process can occur through the use of several mechanisms such as a phone call or referral by another government agency.		
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information		

CERCLIS-NFRAP Assess History

OU ID:	0	***Act Start Date:***	

Act Code ID:	1	***Act Complete Date:***	10/7/1993
RAT Code:	VS	***AGT Order No.:***	1500
RAT Short Name:	ARCH SITE	***SH OU:***	
RAT Name:	ARCHIVE SITE	***SH Code:***	
RAT Hist. Only Flag:		***SH Seq:***	
RAT NSI Indicator:	B	***SH Start Date:***	
RAT Level:	1	***SH Complete Date:***	
RAT DEF OU:	00	***SH Lead:***	
RFBS Code:		***SH Qual:***	
SPA Code:	13	***RAQ Act. Qual Short:***	
RALT Short Name:	EPA In-House	***RNPL Status Code:***	N
RAT Def:	The decision is made that no further activity is planned at the site.		
RNON NPL Status Desc:	NFRAP-Site does not qualify for the NPL based on existing information		

Site: ***Townsend Petroleum Co***
Cerrillos rd Santa FE NM

HIST RISK

Historic Potential Business Activity Risk

Year:	1940
Directory Publisher:	HUDSPETHS
Broad Term:	Fuel and Automotive
Directory Heading:	1940
Listing:	Townsend Petroleum Co
Address:	Cerrillos rd
Address2:	
City:	Santa FE
State:	NM
Zip:	

Site: ***Irby's Texaco Service***
Cerrillos rd Santa FE NM

HIST RISK

Historic Potential Business Activity Risk

Year:	1940
Directory Publisher:	HUDSPETHS
Broad Term:	Fuel and Automotive
Directory Heading:	1940
Listing:	Irby's Texaco Service
Address:	Cerrillos rd
Address2:	
City:	Santa FE
State:	NM
Zip:	

Site: ***Bitz J D***
ns Cerrillos rd 6 w AT & SF Ry Santa FE NM

HIST RISK

Historic Potential Business Activity Risk

Year:	1940
Directory Publisher:	HUDSPETHS
Broad Term:	Fuel and Automotive
Directory Heading:	1940
Listing:	Bitz J D
Address:	ns Cerrillos rd 6 w AT & SF Ry
Address2:	
City:	Santa FE
State:	NM
Zip:	

Site: ***STANDARD OIL CO OF TEXAS***
ns Cerrillos rd 4 w AT & SF Ry Santa FE NM

HIST RISK

Historic Potential Business Activity Risk

Year:	1944
Directory Publisher:	HUDSPETHS
Broad Term:	Fuel and Automotive
Directory Heading:	1944
Listing:	STANDARD OIL CO OF TEXAS
Address:	ns Cerrillos rd 4 w AT & SF Ry
Address2:	
City:	Santa FE
State:	NM
Zip:	

Site: ***Sierra Vista Park***
ns Cerrillos rd 1 w D & R G W R R Santa FE NM

HIST RISK

Historic Potential Business Activity Risk

Year:	1928-29
Directory Publisher:	HUDSPETHS
Broad Term:	Fuel and Automotive
Directory Heading:	1928-29
Listing:	Sierra Vista Park
Address:	ns Cerrillos rd 1 w D & R G W R R
Address2:	
City:	Santa FE
State:	NM
Zip:	

Site: ***Texas Co***
ns Cerrillos rd 4 s AT&SF Ry Santa FE NM

HIST RISK

Historic Potential Business Activity Risk

Year:	1932-33
Directory Publisher:	HUDSPETHS
Broad Term:	Fuel and Automotive
Directory Heading:	1932-33
Listing:	Texas Co
Address:	ns Cerrillos rd 4 s AT&SF Ry
Address2:	
City:	Santa FE
State:	NM
Zip:	

Site: ***Bill's Super Service***
Cerrillos Rd Santa FE NM

HIST RISK

Historic Potential Business Activity Risk

Year:	1949
Directory Publisher:	HUDSPETHS
Broad Term:	Fuel and Automotive
Directory Heading:	1949
Listing:	Bill's Super Service
Address:	Cerrillos Rd
Address2:	
City:	Santa FE

State: NM
Zip:

Site: ***Independent Service Station***
Cerrillos rd Santa FE NM

HIST RISK

Historic Potential Business Activity Risk

Year: 1940
Directory Publisher: HUDSPETHS
Broad Term: Fuel and Automotive
Directory Heading: 1940
Listing: Independent Service Station
Address: Cerrillos rd
Address2:
City: Santa FE
State: NM
Zip:

Site: ***SINCLAIR REFINING CO***
ns Cerrillos rd 2 e D&RG W RR Santa FE NM

HIST RISK

Historic Potential Business Activity Risk

Year: 1932-33
Directory Publisher: HUDSPETHS
Broad Term: Fuel and Automotive
Directory Heading: 1932-33
Listing: SINCLAIR REFINING CO
Address: ns Cerrillos rd 2 e D&RG W RR
Address2:
City: Santa FE
State: NM
Zip:

Site: ***Byrne Petroleum Co***
ss Cerrillos rd 2 w AT&SF Ry Santa FE NM

HIST RISK

Historic Potential Business Activity Risk

Year: 1932-33
Directory Publisher: HUDSPETHS
Broad Term: Fuel and Automotive
Directory Heading: 1932-33
Listing: Byrne Petroleum Co
Address: ss Cerrillos rd 2 w AT&SF Ry
Address2:
City: Santa FE
State: NM
Zip:

Site: ***Irby C H***
Cerrillos rd Santa FE NM

HIST RISK

Historic Potential Business Activity Risk

Year: 1940
Directory Publisher: HUDSPETHS
Broad Term: Fuel and Automotive
Directory Heading: 1940

Listing:	Irby C H
Address:	Cerrillos rd
Address2:	
City:	Santa FE
State:	NM
Zip:	

Site: ***TEXAS COMPANY THE***
Cerrillos rd Santa FE NM

HIST RISK

Historic Potential Business Activity Risk

Year:	1940
Directory Publisher:	HUDSPETHS
Broad Term:	Fuel and Automotive
Directory Heading:	1940
Listing:	TEXAS COMPANY THE
Address:	Cerrillos rd
Address2:	
City:	Santa FE
State:	NM
Zip:	

Site: ***Phillips Petroleum Co***
Cerrillos rd Santa FE NM

HIST RISK

Historic Potential Business Activity Risk

Year:	1932-33
Directory Publisher:	HUDSPETHS
Broad Term:	Fuel and Automotive
Directory Heading:	1932-33
Listing:	Phillips Petroleum Co
Address:	Cerrillos rd
Address2:	
City:	Santa FE
State:	NM
Zip:	

Site: ***Austin Joseph***
ss Cerrillos rd 13 w AT & SF Ry Santa FE NM

HIST RISK

Historic Potential Business Activity Risk

Year:	1936-37
Directory Publisher:	HUDSPETHS
Broad Term:	Fuel and Automotive
Directory Heading:	1936-37
Listing:	Austin Joseph
Address:	ss Cerrillos rd 13 w AT & SF Ry
Address2:	
City:	Santa FE
State:	NM
Zip:	

Site: ***Knight's Repair Shop***
Cerrillos rd Santa FE NM

HIST RISK

Historic Potential Business Activity Risk

Year: 1949
Directory Publisher: HUDSPETHS
Broad Term: Fuel and Automotive
Directory Heading: 1949
Listing: Knight's Repair Shop
Address: Cerrillos rd
Address2:
City: Santa FE
State: NM
Zip:

Site: ***TEXAS COMPANY THE***
ns CERRILLOS RD 5 w AT&SF Ry Santa FE NM

HIST RISK

Historic Potential Business Activity Risk

Year: 1944
Directory Publisher: HUDSPETHS
Broad Term: Fuel and Automotive
Directory Heading: 1944
Listing: TEXAS COMPANY THE
Address: ns CERRILLOS RD 5 w AT&SF Ry
Address2:
City: Santa FE
State: NM
Zip:

Site: ***Cochiti Pueblo Golf Course***
Located at Cochiti Pueblo Santa Fe NM 87501

INDIAN UST

Facility ID: 0119NM
Latitude: 35.6879266
Longitude: -105.9434674
Tribe: Pueblo of Cochiti, New Mexico
Land Status: Indian Land
Region: 6
Loc Name: Cochiti Pueblo Golf Course

Tank

Tank Name: Tank 1

Region 6 UST Tank Info

Tank Status: Permanently Out of Use
Date Installed: 6/1/1950
Tnk Status Chng Dt:
Substance Description: Gasoline (containing <=10% ethanol)
Tank Capacity: 1000
Fed Reg Tank: TRUE

Region 6 UST Tank Compartments Info

Compartment Nm: Tank 1 Compartment
Compartment Stat: Permanently Out of Use
Tnk Status Chng Dt:
Compartment Cap: 1000
Substance Desc: Gasoline (containing <=10% ethanol)
Overfill Installed: FALSE
Spill Installed: Unknown
Fed Regulated: TRUE

Tank

Tank Name: Tank 2

Region 6 UST Tank Info

Tank Status: Permanently Out of Use
Date Installed: 6/1/1950
Tnk Status Chng Dt:
Tank Capacity: 3000
Fed Reg Tank: TRUE

Substance Description: Gasoline (containing <=10% ethanol)

Region 6 UST Tank Compartments Info

Compartment Nm:	Tank 2 Compartment	***Overfill Installed:***	FALSE
Compartment Stat:	Permanently Out of Use	***Spill Installed:***	Unknown
Tnk Status Chng Dt:		***Fed Regulated:***	TRUE
Compartment Cap:	3000		
Substance Desc:	Gasoline (containing <=10% ethanol)		

Site: ***NAMBE OPEN DUMP***
NAMBE PUEBLO SANTE FE NM 87501

SEMS ARCHIVE

Site ID:	0604785	***FIPS Code:***	35049
EPA ID:	NM0000016535	***Cong District:***	01
Superfund Alte Agr:	No	***Region:***	06
Federal Facility:	No	***County:***	SANTA FE
FF Docket:	No		
NPL:	Not on the NPL		
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information		

Action Information

Operable Units:	00	***Qual:***	
Action Code:	DS	***SEQ:***	1
Action Name:	DISCVRY	***FF:***	No
Start Actual:	10/1/1993 4:00:00 AM	***FF Docket:***	No
Finish Actual:	10/1/1993 4:00:00 AM	***Region:***	06
Curr Action Lead:	Tr Perf		
NPL:	N		

Operable Units:	00	***Qual:***	
Action Code:	VS	***SEQ:***	1
Action Name:	ARCH SITE	***FF:***	No
Start Actual:		***FF Docket:***	No
Finish Actual:	10/7/1993 4:00:00 AM	***Region:***	06
Curr Action Lead:	EPA Perf In-Hse		
NPL:	N		

Operable Units:	00	***Qual:***	N
Action Code:	PA	***SEQ:***	1
Action Name:	PA	***FF:***	No
Start Actual:		***FF Docket:***	No
Finish Actual:	10/7/1993 4:00:00 AM	***Region:***	06
Curr Action Lead:	Tr Perf		
NPL:	N		

Site:
houses and property affected are those proximal to the arroyo where the main sewer line runs in the Avenida de las Americas community off Cerrillos Road on Avenida de las Americas (behind Denver Mattress). Santa Fe NM

SPILLS

Notification ID:	19018	***Nearest City:***	Santa Fe
Notification Type:	Spills	***County:***	Santa Fe
Notification Date:	3/17/2025 11:18:30 AM	***Incident District:***	
Notificat Priority:		***Field Office:***	
EJ Issue:		***Created by:***	
Assigned Bureau:	Surface Water Quality Bureau	***Date Created:***	
Assigned Staff:	nafis.fuad@env.nm.gov	***Entered Sep ID:***	
Status Date:	4/24/2025 10:00:45 AM		
Status:	No Further Action Needed - Complaint Closed		
Suspect Resp Party:	City of Santa Fe Utilities (wastewater)		
Resp Party Address1:			
Resp Party Address2:			
Resp Party City:	Santa Fe		
Resp Party State:	NM		
Resp Party Zip:			

Resp Party Phone:
Reporter Name:
Reporter Address 1:
Reporter Address 2:
Reporter City:
Reporter State:
Reporter Zip:
Reporter Phone:
Reporter Email:
Description: On Saturday 03.15.2025 raw sewage backed up frim a main line downstream from the subdivision and came through >8 homes and out into the streets and storm water impoundment. The sewage spilled in the Avenida de las Americas neighborhood. Sewage flowed for approximately five hours from 11:00 am-4:00 pm until City of Santa Fe came with vac-truck to clear the line. Estimating >5,0000 gallons were released into the environment during this event and several homes were inundated >4". No follow up from city to homeowners to date although the city was called several times. Requesting NMED follow up with the City to ensure proper notification, adequate cleanup and remedial action is initiated with homeowners and the HOA property in which the City's line runs.
Location: houses and property affected are those proximal to the arroyo where the main sewer line runs in the Avenida de las Americas community off Cerrillos Road on Avenida de las Americas (behind Denver Mattress).
Data Source: Environmental Notification Reporting - Spills Reported From January to May 2025 (as of 31 May 2025)

Site: ***GSA FLEET SERVICE***
W AVE AND CERRILLOS RD SANTA FE NM 87501

TANKS

FID:	28416	***Sold AST:***	0
In Use AST:	0	***Sold UST:***	0
In Use UST:	0	***No Data AST:***	0
Temp Out AST:	0	***No Data UST:***	0
Temp Out UST:	0	***County:***	SANTA FE
Removed AST:	0	***Owner ID:***	14924
Removed UST:	2	***City (Deliv Prohib):***	
Exempt AST:	0	***Cty (Del Prohib):***	
Exempt UST:	0		

Owner Name: GENERAL SERVICES ADMINISTRATION
Fac Name (Del Prohibition):
Fac Owner (Deliv Prohib):
Fac Add (Delivery Prohibition):
Source: All Storage Tank List

Site: ***OLIVAS VIRGIL AND KATHLEEN***
TESUQUE ST PO BOX 1925 TESUQUE SANTA FE NM 87504

TANKS

FID:	29783	***Sold AST:***	0
In Use AST:	0	***Sold UST:***	0
In Use UST:	0	***No Data AST:***	0
Temp Out AST:	0	***No Data UST:***	0
Temp Out UST:	0	***County:***	SANTA FE
Removed AST:	0	***Owner ID:***	15226
Removed UST:	0	***City (Deliv Prohib):***	
Exempt AST:	0	***Cty (Del Prohib):***	
Exempt UST:	1		

Owner Name: BOYD BARBARA
Fac Name (Del Prohibition):
Fac Owner (Deliv Prohib):
Fac Add (Delivery Prohibition):
Source: All Storage Tank List

Site: ***BUREAU OF INDIAN AFFAIRS BRANCH OF ROADS***
EASTERN NAVAJO AGENCY PO BOX 328 CROWNPOINT NM 87313

TANKS

FID:	1003	***Sold AST:***	0
In Use AST:	0	***Sold UST:***	0
In Use UST:	0	***No Data AST:***	0
Temp Out AST:	0	***No Data UST:***	0
Temp Out UST:	0	***County:***	MCKINLEY
Removed AST:	0	***Owner ID:***	323
Removed UST:	0	***City (Deliv Prohib):***	
Exempt AST:	0	***Cty (Del Prohib):***	
Exempt UST:	2		

Owner Name: BUREAU OF INDIAN AFFAIRS (BIA) BRANCH OF RD
Fac Name (Del Prohibition):
Fac Owner (Deliv Prohib):
Fac Add (Delivery Prohibition):
Source: All Storage Tank List

Site: ***NMDOT SANTA FE PATROL YARD 45 46***
NM 14 MP 48 4 CERRILLOS RD SANTA FE NM 87502

TANKS

FID:	26236	***Sold AST:***	0
In Use AST:	1	***Sold UST:***	0
In Use UST:	0	***No Data AST:***	0
Temp Out AST:	0	***No Data UST:***	0
Temp Out UST:	0	***County:***	SANTA FE
Removed AST:	0	***Owner ID:***	15155
Removed UST:	2	***City (Deliv Prohib):***	
Exempt AST:	0	***Cty (Del Prohib):***	
Exempt UST:	0		

Owner Name: NEW MEXICO (STATE OF) NMDOT DIST 5
Fac Name (Del Prohibition):
Fac Owner (Deliv Prohib):
Fac Add (Delivery Prohibition):
Source: All Storage Tank List

Site: ***SANTA FE WAREHOUSE AREA***
E OF CERRILLOS RD SANTA FE NM 87504

TANKS

FID:	30470	***Sold AST:***	0
In Use AST:	0	***Sold UST:***	0
In Use UST:	0	***No Data AST:***	0
Temp Out AST:	0	***No Data UST:***	0
Temp Out UST:	0	***County:***	SANTA FE
Removed AST:	0	***Owner ID:***	15126
Removed UST:	1	***City (Deliv Prohib):***	
Exempt AST:	0	***Cty (Del Prohib):***	
Exempt UST:	0		

Owner Name: SANTA FE NATIONAL FOREST
Fac Name (Del Prohibition):
Fac Owner (Deliv Prohib):
Fac Add (Delivery Prohibition):
Source: All Storage Tank List

Site: ***SANTA FE WAREHOUSE AREA***
E OF CERRILLOS RD SANTA FE NM 87504

UST

Facility ID:	30470	***Facility (Active):***	
Facility Name:	SANTA FE WAREHOUSE AREA	***Street (Active):***	
Facility Address:	E OF CERRILLOS RD	***Street 2 (Active):***	
Address 2:		***Zip (Active):***	
City:	SANTA FE	***City (Active):***	
County:	SANTA FE	***County (Active):***	
Zip:	87504	***Fac Name (Map-In):***	SANTA FE WAREHOUSE AREA
Fac Name (Map):		***Fac Addr (Map-In):***	E OF CERRILLOS RD
Fac Addr (Map):		***Address 2 (Map-In):***	
Address2 (Map):		***City (Map-In):***	SANTA FE
City (Map):		***County (Map-In):***	SANTA FE
County (Map):		***Zip Cd (Map-In):***	87504
Fac ZIP (Map):		***Lat (Map-In):***	
Latitude (Map):		***Lon (Map-In):***	
Longitude (Map):		***Fac Name (Prohib):***	
Fac Name (Map-Pro):		***Fac Addr (Prohib):***	
Fac Addr (Map-Pro):		***City (Prohib):***	
City (Map-Pro):		***County (Prohib):***	
County (Map-Pro):			

Data Source: NMED PSTB All Storage Tanks Report (as of 14 Oct 2025); NMED Open Data - Inactive Facilities (Map-In) (as of 3 Nov 2025)

NMED PSTB Report - Tank Detail(s) (as of October 14, 2025)

In Use UST:	0	***Sold UST:***	0
Removed UST:	1	***No Data UST:***	0
Exempt UST:	0	***Owner ID:***	15126
Temp Out UST:	0	***Owner Name:***	SANTA FE NATIONAL FOREST

NMED Open Data - Inactive Facilities

Active:	0	***Oldest Tnk Age Type:***	
UST:	1	***AST:***	0
UST Curr in Use:	0	***AST Curr in Use:***	0
UST Exempt:	0	***AST Exempt:***	0
UST Removed:	1	***AST Removed:***	0
UST Temp Out of Use:	0	***AST Temp Out of Use:***	0
Tanks:	1	***Shape:***	
Tanks Curr in Use:	0	***Owner ID:***	15126
Tanks Exempt:	0	***Owner Size Type:***	
Tanks Removed:	1	***Owner Name:***	SANTA FE NATIONAL FOREST
TanksTemp	0		
OutofUse:			

Site: ***OLIVAS VIRGIL AND KATHLEEN***
TESUQUE ST PO BOX 1925 TESUQUE SANTA FE NM 87504 UST

Facility ID:	29783	***Facility (Active):***	
Facility Name:	OLIVAS VIRGIL AND KATHLEEN	***Street (Active):***	
Facility Address:	TESUQUE ST	***Street 2 (Active):***	
Address 2:	PO BOX 1925 TESUQUE	***Zip (Active):***	
City:	SANTA FE	***City (Active):***	
County:	SANTA FE	***County (Active):***	
Zip:	87504	***Fac Name (Map-In):***	OLIVAS VIRGIL AND KATHLEEN
Fac Name (Map):		***Fac Addr (Map-In):***	TESUQUE ST
Fac Addr (Map):		***Address 2 (Map-In):***	PO BOX 1925 TESUQUE
Address2 (Map):		***City (Map-In):***	SANTA FE
City (Map):		***County (Map-In):***	SANTA FE
County (Map):		***Zip Cd (Map-In):***	87504
Fac ZIP (Map):		***Lat (Map-In):***	
Latitude (Map):		***Lon (Map-In):***	
Longitude (Map):		***Fac Name (Prohib):***	
Fac Name (Map-Pro):		***Fac Addr (Prohib):***	
Fac Addr (Map-Pro):		***City (Prohib):***	
City (Map-Pro):		***County (Prohib):***	
County (Map-Pro):			
Data Source:	NMED PSTB All Storage Tanks Report (as of 14 Oct 2025); NMED Open Data - Inactive Facilities (Map-In) (as of 3 Nov 2025)		

NMED PSTB Report - Tank Detail(s) (as of October 14, 2025)

In Use UST:	0	***Sold UST:***	0
Removed UST:	0	***No Data UST:***	0
Exempt UST:	1	***Owner ID:***	15226
Temp Out UST:	0	***Owner Name:***	BOYD BARBARA

NMED Open Data - Inactive Facilities

Active:	0	***Oldest Tnk Age Type:***	
UST:	1	***AST:***	0
UST Curr in Use:	0	***AST Curr in Use:***	0
UST Exempt:	1	***AST Exempt:***	0
UST Removed:	0	***AST Removed:***	0
UST Temp Out of Use:	0	***AST Temp Out of Use:***	0
Tanks:	1	***Shape:***	
Tanks Curr in Use:	0	***Owner ID:***	15226
Tanks Exempt:	1	***Owner Size Type:***	
Tanks Removed:	0	***Owner Name:***	BOYD BARBARA
TanksTemp	0		
OutofUse:			

Site: ***GSA FLEET SERVICE***
W AVE AND CERRILLOS RD SANTA FE NM 87501

UST

Facility ID:	28416	***Facility (Active):***	
Facility Name:	GSA FLEET SERVICE	***Street (Active):***	
Facility Address:	W AVE AND CERRILLOS RD	***Street 2 (Active):***	
Address 2:		***Zip (Active):***	
City:	SANTA FE	***City (Active):***	
County:	SANTA FE	***County (Active):***	
Zip:	87501	***Fac Name (Map-In):***	GSA FLEET SERVICE
Fac Name (Map):		***Fac Addr (Map-In):***	W AVE AND CERRILLOS RD
Fac Addr (Map):		***Address 2 (Map-In):***	
Address2 (Map):		***City (Map-In):***	SANTA FE
City (Map):		***County (Map-In):***	SANTA FE
County (Map):		***Zip Cd (Map-In):***	87501
Fac ZIP (Map):		***Lat (Map-In):***	35.655699
Latitude (Map):		***Lon (Map-In):***	-105.980854
Longitude (Map):		***Fac Name (Prohib):***	
Fac Name (Map-Pro):		***Fac Addr (Prohib):***	
Fac Addr (Map-Pro):		***City (Prohib):***	
City (Map-Pro):		***County (Prohib):***	
County (Map-Pro):			

Data Source: NMED PSTB All Storage Tanks Report (as of 14 Oct 2025); NMED Open Data - Inactive Facilities (Map-In) (as of 3 Nov 2025)

NMED PSTB Report - Tank Detail(s) (as of October 14, 2025)

In Use UST:	0	***Sold UST:***	0
Removed UST:	2	***No Data UST:***	0
Exempt UST:	0	***Owner ID:***	14924
Temp Out UST:	0	***Owner Name:***	GENERAL SERVICES ADMINISTRATION

NMED Open Data - Inactive Facilities

Active:	0	***Oldest Tnk Age Type:***	
UST:	2	***AST:***	0
UST Curr in Use:	0	***AST Curr in Use:***	0
UST Exempt:	0	***AST Exempt:***	0
UST Removed:	2	***AST Removed:***	0
UST Temp Out of Use:	0	***AST Temp Out of Use:***	0
Tanks:	2	***Shape:***	
Tanks Curr in Use:	0	***Owner ID:***	14924
Tanks Exempt:	0	***Owner Size Type:***	
Tanks Removed:	2	***Owner Name:***	GENERAL SERVICES ADMINISTRATION
TanksTemp	0		
OutofUse:			

Site: ***GSA FLEET SERVICE***
W AVE AND CERRILLOS RD SANTA FE NM 87501

UST HIST

Facility ID:	28416
Facility Addr2:	
Facility County:	SANTA FE

Details

Tank ID:	25463	***Owner Add2:***	
Tank Type:	Underground	***Owner City:***	FORT WORTH
Tank Status:	REMOVED	***Owner St:***	TX
Tank Capacity (GAL):	10000	***Owner ZIP:***	76102
Tank Contents:	GASOLINE UNKNOWN TYPE	***Owner Ph:***	
Owner ID:	14924		
Owner Name:	GENERAL SERVICES ADMINISTRATION		
Owner Address:	819 TAYLOR ST		

Details

Tank ID:	25464	***Owner Add2:***	
Tank Type:	Underground	***Owner City:***	FORT WORTH
Tank Status:	REMOVED	***Owner St:***	TX
Tank Capacity (GAL):	550	***Owner ZIP:***	76102
Tank Contents:	USED OIL	***Owner Ph:***	
Owner ID:	14924		
Owner Name:	GENERAL SERVICES ADMINISTRATION		
Owner Address:	819 TAYLOR ST		

Site: ***SANTA FE WAREHOUSE AREA***
E OF CERRILLOS RD SANTA FE NM 87504

UST HIST

Facility ID:	30470
Facility Addr2:	
Facility County:	SANTA FE

Details

Tank ID:	30209	***Owner Add2:***	
Tank Type:	Underground	***Owner City:***	SANTA FE
Tank Status:	REMOVED	***Owner St:***	NM
Tank Capacity (GAL):	500	***Owner ZIP:***	87505
Tank Contents:	UNLEADED GASOLINE	***Owner Ph:***	505-438-7840
Owner ID:	15126		
Owner Name:	SANTA FE NATIONAL FOREST		
Owner Address:	1474 RODEO ROAD		

Site: ***BUREAU OF INDIAN AFFAIRS BRANCH OF ROADS***
EASTERN NAVAJO AGENCY CROWNPOINT NM 87313

UST HIST

Facility ID:	1003
Facility Addr2:	PO BOX 328
Facility County:	MCKINLEY

Details

Tank ID:	33950	***Owner Add2:***	PO BOX 328
Tank Type:	Underground	***Owner City:***	CROWNPOINT
Tank Status:	EXEMPT	***Owner St:***	NM
Tank Capacity (GAL):	1000	***Owner ZIP:***	87313
Tank Contents:	EMPTY	***Owner Ph:***	505-786-5350
Owner ID:	323		
Owner Name:	BUREAU OF INDIAN AFFAIRS (BIA) BRANCH OF RD		
Owner Address:	EASTERN NAVAJO AGENCY		

Details

Tank ID:	33951	***Owner Add2:***	PO BOX 328
Tank Type:	Underground	***Owner City:***	CROWNPOINT
Tank Status:	EXEMPT	***Owner St:***	NM
Tank Capacity (GAL):	6000	***Owner ZIP:***	87313
Tank Contents:	EMPTY	***Owner Ph:***	505-786-5350
Owner ID:	323		
Owner Name:	BUREAU OF INDIAN AFFAIRS (BIA) BRANCH OF RD		
Owner Address:	EASTERN NAVAJO AGENCY		

Site: ***OLIVAS VIRGIL AND KATHLEEN***
TESUQUE ST SANTA FE NM 87504

UST HIST

Facility ID:	29783
Facility Addr2:	PO BOX 1925 TESUQUE
Facility County:	SANTA FE

Details

Tank ID:	28460	***Owner Add2:***	
Tank Type:	Underground	***Owner City:***	WILSALL
Tank Status:	EXEMPT	***Owner St:***	MT
Tank Capacity (GAL):	1500	***Owner ZIP:***	59086
Tank Contents:	DIESEL	***Owner Ph:***	406-578-4488
Owner ID:	15226		
Owner Name:	BOYD BARBARA		
Owner Address:	ROUTE 2 BOX 431		

Appendix: Database Descriptions

Environmental Risk Information Services (ERIS) can search the following databases. The extent of historical information varies with each database and current information is determined by what is publicly available to ERIS at the time of update. ERIS updates databases as set out in ASTM Standard E1527-13 and E1527-21, Section 8.1.8 Sources of Standard Source Information:

"Government information from nongovernmental sources may be considered current if the source updates the information at least every 90 days, or, for information that is updated less frequently than quarterly by the government agency, within 90 days of the date the government agency makes the information available to the public."

Standard Environmental Record Sources

Federal

National Priority List: NPL

The U.S. Environmental Protection Agency (EPA)'s National Priorities List (NPL) includes the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program, based primarily on the score a site receives from EPA's Hazard Ranking System. A site must be on the NPL to receive money from the Superfund Trust Fund for remedial action. This data includes NPL sites represented as polygons, where available, that can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS), and is limited to those sites where the NPL Status reflects the site is 'Currently on the Final NPL (F)' and/or the 'Site is Part of NPL Site (A)'. These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. As site investigation and remediation progress, OUs may be added, modified or refined. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Sep 6, 2025

National Priority List - Proposed: PROPOSED NPL

Sites proposed by the U.S. Environmental Protection Agency (EPA), the state agency, or concerned citizens for addition to the National Priorities List (NPL) due to contamination by hazardous waste and identified by the EPA as a candidate for cleanup because it poses a risk to human health and/or the environment. Sites represented as polygons, where available, can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Sep 6, 2025

Deleted NPL: DELETED NPL

Sites deleted from the U.S. Environmental Protection Agency (EPA)'s National Priorities List (NPL). The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate. Sites represented as polygons, where available, can be sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). These site boundaries represent the footprint of a whole site, the sum of all the Operable Units (OUs) and the current understanding of the full extent of contamination; for Federal Facility sites, the total site polygon may be the Facility boundary. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Sep 6, 2025

SEMS List 8R Active Site Inventory: SEMS

The U.S. Environmental Protection Agency's (EPA) Superfund Program has deployed the Superfund Enterprise Management System (SEMS), which integrates multiple legacy systems into a comprehensive tracking and reporting tool. This inventory contains active sites evaluated by the Superfund program that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The Active Site Inventory Report displays site and location information at active SEMS sites. An active site is one at which site assessment, removal, remedial, enforcement, cost recovery, or oversight activities are being planned or conducted. This data includes SEMS sites from the List 8R Active file as well as applicable sites from the EPA's Facility Registry Service map tool. This data may also include applicable sites represented as polygons sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS), and is limited to those sites where the NPL Status reflects the site is 'Not on the NPL (N)' , 'Removed from Proposed (R)', and/or 'Pre-Proposal Site (S)'. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Aug 27, 2025

Inventory of Open Dumps, June 1985: ODI

The Resource Conservation and Recovery Act (RCRA) provides for publication of an inventory of open dumps. The Act defines "open dumps" as facilities which do not comply with EPA's "Criteria for Classification of Solid Waste Disposal Facilities and Practices" (40 CFR 257).

Government Publication Date: Jun 1985

SEMS List 8R Archive Sites: SEMS ARCHIVE

The U.S. Environmental Protection Agency's (EPA) Superfund Enterprise Management System (SEMS) Archived Site Inventory displays site and location information at sites archived from SEMS. An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. This data includes sites from the List 8R Archived site file. This data may also include applicable sites represented as polygons sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS), and is limited to those sites where the NPL Status reflects the site is 'Not on the NPL (N)' , 'Removed from Proposed (R)', and/or 'Pre-Proposal Site (S)'. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes. Where there is no polygon boundary data available for a given site, the site is represented as a point.

Government Publication Date: Aug 27, 2025

Comprehensive Environmental Response, Compensation and Liability Information System - CERCLIS: CERCLIS

Superfund is a program administered by the United States Environmental Protection Agency (EPA) to locate, investigate, and clean up the worst hazardous waste sites throughout the United States. CERCLIS is a database of potential and confirmed hazardous waste sites at which the EPA Superfund program has some involvement. It contains sites that are either proposed to be or are on the National Priorities List (NPL) as well as sites that are in the screening and assessment phase for possible inclusion on the NPL. The EPA administers the Superfund program in cooperation with individual states and tribal governments; this database is made available by the EPA.

Government Publication Date: Oct 25, 2013

EPA Report on the Status of Open Dumps on Indian Lands: IODI

Public Law 103-399, The Indian Lands Open Dump Cleanup Act of 1994, enacted October 22, 1994, identified congressional concerns that solid waste open dump sites located on American Indian or Alaska Native (AI/AN) lands threaten the health and safety of residents of those lands and contiguous areas. The purpose of the Act is to identify the location of open dumps on Indian lands, assess the relative health and environment hazards posed by those sites, and provide financial and technical assistance to Indian tribal governments to close such dumps in compliance with Federal standards and regulations or standards promulgated by Indian Tribal governments or Alaska Native entities.

Government Publication Date: Dec 31, 1998

CERCLIS - No Further Remedial Action Planned: CERCLIS NFRAP

An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. The Archive designation means that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL). This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Government Publication Date: Oct 25, 2013

CERCLIS Liens: CERCLIS LIENS

A Federal Superfund lien exists at any property where EPA has incurred Superfund costs to address contamination ("Superfund site") and has provided notice of liability to the property owner. A Federal CERCLA ("Superfund") lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. This database is made available by the United States Environmental Protection Agency (EPA). This database was provided by the United States Environmental Protection Agency (EPA). Refer to SEMS LIEN as the current data source for Superfund Liens.

Government Publication Date: Jan 30, 2014

RCRA CORRACTS-Corrective Action: RCRA CORRACTS

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. At these sites, the Corrective Action Program ensures that cleanups occur. EPA and state regulators work with facilities and communities to design remedies based on the contamination, geology, and anticipated use unique to each site.

Government Publication Date: Sep 1, 2025

RCRA non-CORRACTS TSD Facilities: RCRA TSD

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. This database includes Non-Corrective Action sites that have indicated engagement in the treatment, storage, or disposal of hazardous waste which requires a RCRA hazardous waste permit.

Government Publication Date: Sep 1, 2025

RCRA Generator List: RCRA LQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Large Quantity Generators (LQGs) generate 1,000 kilograms per month or more of hazardous waste or more than one kilogram per month of acutely hazardous waste. This list also includes RCRAInfo sites that have notified as LQGs that do not have a registered Site Manager or Certifier in RCRAInfo.

Government Publication Date: Sep 1, 2025

RCRA Small Quantity Generators List: RCRA SQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Small Quantity Generators (SQGs) generate more than 100 kilograms, but less than 1,000 kilograms, of hazardous waste per month. This list also includes RCRAInfo sites that have notified as SQGs that do not have a registered Site Manager or Certifier in RCRAInfo.

Government Publication Date: Sep 1, 2025

RCRA Very Small Quantity Generators List: RCRA VSQG

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Very Small Quantity Generators (VSQG) generate 100 kilograms or less per month of hazardous waste, or one kilogram or less per month of acutely hazardous waste. Additionally, VSQG may not accumulate more than 1,000 kilograms of hazardous waste at any time.

Government Publication Date: Sep 1, 2025

RCRA Non-Generators: RCRA NON GEN

RCRA Info is the U.S. Environmental Protection Agency's (EPA) comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRA Info replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS) and the Biennial Reporting System (BRS). A hazardous waste generator is any person or site whose processes and actions create hazardous waste (see 40 CFR 260.10). Non-Generators do not presently generate hazardous waste.

Government Publication Date: Sep 1, 2025

RCRA Sites with Controls: RCRA CONTROLS

List of Resource Conservation and Recovery Act (RCRA) facilities with institutional controls in place. RCRA gives the U.S. Environmental Protection Agency (EPA) the authority to control hazardous waste from the "cradle-to-grave." This includes the generation, transportation, treatment, storage, and disposal of hazardous waste. RCRA also set forth a framework for the management of non-hazardous solid wastes. The 1986 amendments to RCRA enabled EPA to address environmental problems that could result from underground tanks storing petroleum and other hazardous substances.

Government Publication Date: Sep 1, 2025

Federal Engineering Controls-ECs: FED ENG

List of Engineering controls (ECs) made availabe by the United States Environmental Protection Agency (EPA). ECs encompass a variety of engineered and constructed physical barriers (e.g., soil capping, sub-surface venting systems, mitigation barriers, fences) to contain and/or prevent exposure to contamination on a property. The EC listing includes remedy component data from Superfund decision documents for applicable sites on the final or deleted on the National Priorities List (NPL); and sites with a Superfund Alternative Approach (SAA) Agreement in place. The only sites included that are not on the NPL; proposed for NPL; or removed from proposed NPL, are those with an SAA Agreement in place.

Government Publication Date: Sep 29, 2025

Federal Institutional Controls- ICs: FED INST

List of Institutional controls (ICs) made available by the United States Environmental Protection Agency (EPA). ICs are non-engineered instruments, such as administrative and legal controls, that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Although it is EPA's expectation that treatment or engineering controls will be used to address principal threat wastes and that groundwater will be returned to its beneficial use whenever practicable, ICs play an important role in site remedies because they reduce exposure to contamination by limiting land or resource use and guide human behavior at a site. The IC listing includes remedy component data from Superfund decision documents for applicable sites on the final or deleted on the National Priorities List (NPL); and sites with a Superfund Alternative Approach (SAA) Agreement in place. The only sites included that are not on the NPL; proposed for NPL; or removed from proposed NPL, are those with an SAA Agreement in place.

Government Publication Date: Sep 29, 2025

Land Use Controls Information System: LUCIS

The Land Use Controls Information System (LUCIS) database is sourced from the U.S. Department of the Navy (DON). This data contains information for former Base Realignment and Closure (BRAC) properties across the United States. DON's BRAC office was tasked with tracking certain base closures while requiring the prevention of risks to human health and the environment of those properties with LUCs in place. Regarding currently available LUC Sites data, the sites listing is limited to centroid point locations for the overall installation property boundaries. Formerly obtained LUC Sites data may reflect site details that applied previously for a BRAC property.

Government Publication Date: Jun 13, 2024

Institutional Control Boundaries at NPL sites: NPL IC

These boundaries of Institutional Control areas at sites on the U.S. Environmental Protection Agency's (EPA) National Priorities List (NPL), or as Proposed or Deleted, are sourced from the EPA NPL Superfund Site Boundaries dataset, refreshed by the Shared Enterprise Geodata and Services (SEGS). The EPA's NPL includes the most serious uncontrolled or abandoned hazardous waste sites identified for possible long-term remedial action under the Superfund program. Institutional controls are non-engineered instruments such as administrative and legal controls that help minimize the potential for human exposure to contamination and/or protect the integrity of the remedy. Data provided by external parties is not independently verified by EPA. This boundary data is made available to the public strictly for informational purposes.

Government Publication Date: Sep 6, 2025

Emergency Response Notification System: ERNS 1982 TO 1986

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1982-1986

Emergency Response Notification System: ERNS 1987 TO 1989

Database of oil and hazardous substances spill reports controlled by the National Response Center. The primary function of the National Response Center is to serve as the sole national point of contact for reporting oil, chemical, radiological, biological, and etiological discharges into the environment anywhere in the United States and its territories.

Government Publication Date: 1987-1989

Emergency Response Notification System: ERNS

Database of oil and hazardous substances spill reports made available by the United States Coast Guard National Response Center (NRC). The NRC fields initial reports for pollution and railroad incidents and forwards that information to appropriate federal/state agencies for response. These data contain initial incident data that has not been validated or investigated by a federal/state response agency.

Government Publication Date: Sep 7, 2025

The Assessment, Cleanup and Redevelopment Exchange System (ACRES) Brownfield Database: FED BROWNFIELDS

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties protects the environment, reduces blight, and takes development pressures off greenspaces and working lands. This data is provided by the United States Environmental Protection Agency (EPA) and includes Brownfield sites from the Cleanups in My Community (CIMC) web application.

Government Publication Date: Sep 8, 2025

FEMA Underground Storage Tank Listing: FEMA UST

The Federal Emergency Management Agency (FEMA) of the Department of Homeland Security maintains a list of FEMA owned underground storage tanks.

Government Publication Date: Dec 31, 2017

Facility Response Plan: FRP

This listing contains facilities that have submitted Facility Response Plans (FRPs) to the U.S. Environmental Protection Agency (EPA). Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit FRPs. Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments. The list includes FRP facilities sourced from the EPA FOIA office and from previously available Homeland Infrastructure Foundation-Level Data (HIFLD) file/s. Disclaimer: Per the EPA FOIA Office, the verification process for current requested FRP data is undergoing review and revision, and any similar reporting will be made public in Fiscal Year 2026. For this reason, the latest available FOIA file may be incomplete.

Government Publication Date: Jun 1, 2025

Delisted Facility Response Plans: DELISTED FRP

Facilities that once appeared in - and have since been removed from - the list of facilities that have submitted Facility Response Plans (FRP) to EPA. Facilities that could reasonably be expected to cause "substantial harm" to the environment by discharging oil into or on navigable waters are required to prepare and submit Facility Response Plans (FRPs). Harm is determined based on total oil storage capacity, secondary containment and age of tanks, oil transfer activities, history of discharges, proximity to a public drinking water intake or sensitive environments.

Government Publication Date: Jun 1, 2025

Historical Gas Stations: HIST GAS STATIONS

This historic directory of service stations is provided by the Cities Service Company. The directory includes Cities Service filling stations that were located throughout the United States in 1930.

Government Publication Date: Jul 1, 1930

Petroleum Refineries: REFN

This list of petroleum refineries is sourced from the U.S. Energy Information Administration (EIA), Refinery Capacity Report. The listing includes operating and idle petroleum refineries (including new refineries under construction) and refineries shut down during the previous year. The geographic area the report covers is the 50 States, the District of Columbia, Puerto Rico, the U.S. Virgin Islands, Guam, and other U.S. possessions. Per the EIA, the facility location data represents the approximate location based on research of publicly available information from sources such as Federal agencies, company websites, and satellite images on public websites.

Government Publication Date: Oct 31, 2024

Petroleum Product and Crude Oil Rail Terminals: BULK TERMINAL

A list of petroleum product and crude oil rail terminals from the U.S. Energy Information Administration (EIA), as well as petroleum terminals sourced from Oak Ridge National Laboratory hosted by the Homeland Infrastructure Foundation-Level Database. Data includes operable bulk petroleum product terminals with a total bulk shell storage capacity of 50,000 barrels or more, and/or the ability to receive volumes from tanker, barge, or pipeline; also rail terminals handling the loading and unloading of crude oil with activity between 2017 and 2018. EIA petroleum product terminal data comes from the EIA-815 Bulk Terminal and Blender Report, which includes working, shell in operation, and shell idle for several major product groupings.

Government Publication Date: Jun 5, 2025

LIEN on Property: SEMS LIEN

The U.S. Environmental Protection Agency's (EPA) Superfund Enterprise Management System (SEMS) provides Lien details on applicable properties, such as the Superfund lien on property activity, the lien property information, and the parties associated with the lien.

Government Publication Date: Aug 27, 2025

Superfund Decision Documents: SUPERFUND ROD

This database contains a list of decision documents for Superfund sites. Decision documents serve to provide the reasoning for the choice of (or) changes to a Superfund Site cleanup plan. The decision documents include completed Records of Decision (ROD), ROD Amendments, Explanations of Significant Differences (ESD) for active and archived sites stored in the Superfund Enterprise Management System (SEMS), along with other associated memos and files. This information is maintained and made available by the U.S. Environmental Protection Agency.

Government Publication Date: Oct 30, 2025

State

State Cleanup Sites Listing: SCS

List of active and closed State Clean Up Sites made available by the Ground Water Quality Bureau's Remediation Oversight Section of the New Mexico Environment Department (NMED). The Remediation Oversight Section encourages and oversees voluntary efforts to clean up contaminated sites, and administers the Water Quality Control Commission Regulations that require responsible parties to clean up contaminated soil and ground water. This database serves a purpose similar to that of the federal Superfund Enterprise Management System (SEMS), functioning as a state-level counterpart for tracking potential hazardous substance release sites.

Government Publication Date: Feb 4, 2025

Delisted State Cleanup Sites: DELISTED SCS

List of sites removed from State Clean Up Sites made available by the Ground Water Quality Bureau's Remediation Oversight Section of the New Mexico Environment Department (NMED).

Government Publication Date: Feb 4, 2025

Solid Waste Facilities: SWF/LF

List of currently or formerly permitted/registered facilities in New Mexico, including haulers, landfills, transfer stations, collection centers, generators, recycling facilities, and composting facilities. This list includes facilities that are currently open and reporting as well as facilities that are closed but previously held a permit. This list is made available by the New Mexico Environment Department (NMED)'s Solid Waste Bureau.

Government Publication Date: Oct 23, 2025

Historical Solid Waste Landfills: HIST LF

List of historical landfill sites provided by the New Mexico Environment Department (NMED) Solid Waste Bureau, and sites from the Bureau of Land Management which were closed prior to 1984. Public Land Survey System (PLSS) locations provided by the source are subject to accuracy limitations inherent to the PLSS system.

Government Publication Date: Aug 21, 2014

Recycling Centers: RECYCLING

List of registered recycling centers made available by the New Mexico Environment Department's (NMED) Solid Waste Bureau.

Government Publication Date: Jul 7, 2025

Leaking Petroleum Storage Tanks: LST

This list of Leaking Petroleum Storage Tank sites is made available by the New Mexico Environment Department's (NMED) Petroleum Storage Tank Bureau (PSTB). Includes records from PSTB listings, and records from the NMED Open Map Portal.

Government Publication Date: Sep 16, 2025

Delisted Active and No Further Action Leaking Tanks: DELISTED LST

This database contains a list of leaking storage tank sites that were removed from the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau.

Government Publication Date: Sep 16, 2025

Leaking Underground Storage Tanks: LUST HIST

Historical list of leaking underground leaking tanks provided by the New Mexico Environment Department (NMED). This list was last updated in August of 2006.

Government Publication Date: Aug 1, 2006

Underground Storage Tanks: UST

List of Underground Storage Tank sites made available by the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau (PSTB). Includes Underground Storage Tank Facilities from the NMED Open Data Portal.

Government Publication Date: Nov 3, 2025

Aboveground Storage Tanks: AST

List of Aboveground Storage Tank sites made available by the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau (PSTB). Includes Aboveground Storage Tank Facilities from the NMED Open Data Portal.

Government Publication Date: Nov 3, 2025

Petroleum Storage Tanks: TANKS

List of Storage Tank Sites made available by the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau. Includes sites with underground and aboveground tanks.

Government Publication Date: Jul 9, 2019

Underground Storage Tanks - Historical: UST HIST

Historical listing of underground storage tanks registered with the New Mexico Environment Department (NMED). This data was last updated in August 2006.

Government Publication Date: Aug 1, 2006

Aboveground Storage Tanks - Historical: AST HIST

Historical listing of aboveground storage tank facilities registered with the New Mexico Environment Department (NMED. This data was last updated in August 2006.

Government Publication Date: Aug 4, 2006

Delisted Tanks: DELISTED TANK

List of Storage Tank Sites removed from the New Mexico Environment Department (NMED)'s Petroleum Storage Tank Bureau's list of underground and aboveground tanks.

Government Publication Date: Nov 3, 2025

Sites with Institutional and Engineering Controls: INST

List of sites in the New Mexico Environment Department (NMED)'s Public Record of Voluntary Remediation Program (VRP) Sites with institutional and/or engineering controls.

Government Publication Date: Sep 30, 2025

Voluntary Remediation Program Sites: VCP

Public Record of Voluntary Remediation Program (VRP) Sites made available by the New Mexico Environment Department (NMED). New Mexico's Voluntary Remediation Program (VRP) provides incentives for the voluntary cleanup of contaminated properties and encourages their redevelopment. VRP participants that complete the program successfully will receive site closure documentation from the NMED including a Certificate of Completion or Conditional Certificate of Completion.

Government Publication Date: Sep 30, 2025

Targeted Brownfields Assessment Sites: BROWNFIELDS

List of Targeted Brownfields Assessment Sites made available by the New Mexico Environment Department (NMED). Brownfields are properties whose redevelopment is complicated by the presence or potential presence of hazardous substances or petroleum products. NMED provides no-cost environmental assessments of brownfield sites to local or tribal governments. NMED also manages a Brownfields Revolving Loan Fund providing low-interest loans for brownfield cleanups where redevelopment is planned.

Government Publication Date: Sep 30, 2025

Tribal

Leaking Underground Storage Tanks on Tribal/Indian Lands: INDIAN LUST

This list of leaking underground storage tanks (LUSTs) on Tribal/Indian Lands in Region 6, which includes New Mexico, is provided by the United States Environmental Protection Agency (EPA).

Government Publication Date: Apr 21, 2025

Underground Storage Tanks on Tribal/Indian Lands: INDIAN UST

This list of underground storage tanks (USTs) on Tribal/Indian Lands in Region 6, which includes New Mexico, is provided by the United States Environmental Protection Agency (EPA).

Government Publication Date: Apr 21, 2025

Delisted Tribal Leaking Storage Tanks: DELISTED INDIAN LST

Leaking Underground Storage Tank (LUST) facilities which once appeared on - and have since been removed from - the Regional Tribal/Indian LUST lists made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: May 22, 2025

Delisted Tribal Underground Storage Tanks: DELISTED INDIAN UST

Underground Storage Tank (UST) facilities which once appeared on - and have since been removed from - the Regional Tribal/Indian UST lists made available by the United States Environmental Protection Agency (EPA).

Government Publication Date: May 22, 2025

County

No County databases were selected to be included in the search.

Additional Environmental Record Sources

Federal

PFAS Greenhouse Gas Emissions Data: PFAS GHG

The U.S. Environmental Protection Agency's (EPA) Greenhouse Gas Reporting Program (GHGRP) collects Greenhouse Gas (GHG) data from large emitting facilities (25,000 metric tons of carbon dioxide equivalent (CO2e) per year), and suppliers of fossil fuels and industrial gases that results in GHG emissions when used. This dataset is sourced from the EPA's PFAS Analytic Tools, and it includes GHG emissions data for facilities that emit or have emitted since 2010 chemicals identified as PFAS based on EPA's CompTox Chemicals Dashboard lists of PFAS with defined and undefined structures. PFAS emissions data has been identified for facilities engaged in the following industrial processes: Aluminum Production (GHGRP Subpart F), HCFC-22 Production and HFC-23 Destruction (Subpart O), Electronics Manufacturing (Subpart I), Fluorinated Gas Production (Subpart L), Magnesium Production (Subpart T), Electrical Transmission and Distribution Equipment Use (Subpart DD), and Manufacture of Electric Transmission and Distribution Equipment (Subpart SS). Over time, other industrial processes with required GHGRP reporting may include PFAS emissions data and the list of reportable gases may change over time. Note that some regulatory programs have specified chemical structure requirements that define PFAS differently than the lists in EPA's CompTox Chemicals Dashboard.

Government Publication Date: Oct 7, 2025

On-Scene Coordinator Response Sites: OSC RESPONSE

This list of On-Scene Coordinator (OSC) Response Sites is provided by the U.S. Environmental Protection Agency (EPA). OSCs are the federal officials responsible for monitoring or directing responses to all oil spills and hazardous substance releases reported to the federal government. OSCs coordinate all federal efforts with, and provide support and information to local, state, and regional response communities. An OSC is an agent of either EPA or the U.S. Coast Guard (USCG), depending on where the incident occurs. EPA's OSCs have primary responsibility for spills and releases to inland areas and waters. USCG OSCs have responsibility for coastal waters and the Great Lakes. In general, an OSC has the following key responsibilities during and after a response: Assessment, Monitoring, Response Assistance, and Evaluation.

Government Publication Date: Oct 8, 2025

Facility Registry Service/Facility Index: FINDS/FRS

The Facility Registry Service (FRS) is a centrally managed database that identifies facilities, sites, or places subject to environmental regulations or of environmental interest. FRS creates high-quality, accurate, and authoritative facility identification records through rigorous verification and management procedures that incorporate information from program national systems, state master facility records, and data collected from EPA's Central Data Exchange registrations and data management personnel. This list is made available by the U.S. Environmental Protection Agency (EPA).

Government Publication Date: Oct 10, 2025

Toxics Release Inventory (TRI) Program: TRIS

The U.S. Environmental Protection Agency's Toxics Release Inventory (TRI) is a database containing data on disposal or other releases of toxic chemicals from U.S. facilities and information about how facilities manage those chemicals through recycling, energy recovery, and treatment. There are currently 770 individually listed chemicals and 33 chemical categories covered by the TRI Program. Facilities that manufacture, process or otherwise use these chemicals in amounts above established levels must submit annual reporting forms for each chemical. Note that the TRI chemical list does not include all toxic chemicals used in the U.S. One of TRI's primary purposes is to inform communities about toxic chemical releases to the environment. This database includes TRI Reporting Data for calendar years 1987 through 2021 and Preliminary Data for 2022.

Government Publication Date: Sep 20, 2023

PFOA/PFOS Contaminated Sites: PFAS NPL

This list of Superfund Sites with Per- and Polyfluoroalkyl Substances (PFAS) detections is made available by the U.S. Environmental Protection Agency (EPA) in their PFAS Analytic Tools data, previously the list was obtained by EPA FOIA requests. EPA's Office of Land and Emergency Management and EPA Regional Offices maintain what is known about site investigations, contamination, and remedial actions under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) where PFAS is present in the environment. Limitations: Detections of PFAS at National Priorities List (NPL) sites do not mean that people are at risk from PFAS, are exposed to PFAS, or that the site is the source of the PFAS. The information in the Superfund NPL and Superfund Alternative Agreement (SAA) PFAS detection site list is years old and may not be accurate today. Site information such as site name, site ID, and location has been confirmed for accuracy; however, PFAS-related information such as media sampled, drinking water being above the health advisory, or mitigation efforts has not been verified. For Federal Facilities data, the other Federal agencies (OFA) are the lead agency for their data and provided them to EPA.

Government Publication Date: Sep 26, 2025

Federal Agency Locations with Known or Suspected PFAS Detections: PFAS FED SITES

This list of federal agency locations with known or suspected detections of Per- and Polyfluoroalkyl Substances (PFAS) is made available by the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools data. The EPA outlines that these data are gathered from several federal entities, such as the federal Superfund program, Department of Defense (DOD), National Aeronautics and Space Administration (NASA), Department of Transportation (DOT), and Department of Energy (DOE). The dates this data was extracted for the PFAS Analytic Tools range from 2022 to 2025 per agency entity dataset. Sites on this list do not necessarily reflect the source/s of PFAS contamination and detections do not indicate level of risk or human exposure at the site. Agricultural notifications in this data are limited to DOD sites only. At this time, the EPA is aware that this list is not comprehensive of all Federal agencies.

Government Publication Date: May 30, 2025

SSEHRI PFAS Contamination Sites: PFAS SSEHRI

This PFAS Contamination Site Tracker database is compiled by the PFAS Project Lab, part of the Social Science Environmental Health Research Institute (SSEHRI) at Northeastern University. According to the SSEHRI, the database records qualitative and quantitative data from each known site of PFAS contamination, including timeline of discovery, sources, levels, health impacts, community response, and government response. The goal of this database is to compile information and support public understanding of the rapidly unfolding issue of PFAS contamination. All data presented was extracted from government websites, news articles, or publicly available documents. Locations for the Known PFAS Contamination Sites are sourced from the PFAS Sites and Community Resources Map by the PFAS-REACH team, credited to PFAS Project Lab, Silent Spring Institute, and PFAS Exchange. Disclaimer: The source conveys the data undergoes regular updates as new information becomes available, some sites may be missing and/or contain information that is incorrect or outdated, as well as their information represents all contamination sites SSEHRI is aware of, not all possible contamination sites. This data is not intended to be used for legal purposes. Access the following source link for the most current information: https://pfasproject.com/pfas-sites-and-community-resources/

Government Publication Date: Aug 1, 2025

National Response Center PFAS Spills: PFAS ERNS

This Per- and Poly-Fluoroalkyl Substances (PFAS) Spills dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The National Response Center (NRC), operated by the U.S. Coast Guard, is the designated federal point of contact for reporting all oil, chemical, and other discharges into the environment, for the United States and its territories. This dataset contains NRC spill information from 1990 to the present that is restricted to records associated with PFAS and PFAS-containing materials. Incidents are filtered to include only records with a "Material Involved" or "Incident Description" related to Aqueous Film Forming Foam (AFFF). The keywords used to filter the data included "AFFF," "Fire Fighting Foam," "Aqueous Film Forming Foam," "Fire Suppressant Foam, "PFAS," "PERFL," "PFOA," "PFOS," and "Genx." Limitations: The data from the NRC website contains initial incident data that has not been validated or investigated by a federal/state response agency. Keyword searches may misidentify some incident reports that do not contain PFAS. This dataset should also not be considered to be exhaustive of all PFAS spills/release incidents.

Government Publication Date: Dec 1, 2025

PFAS NPDES Discharge Monitoring: PFAS NPDES

This list of National Pollutant Discharge Elimination System (NPDES) permitted facilities with required monitoring for Per- and Polyfluoroalkyl (PFAS) Substances is made available via the U.S. Environmental Protection Agency (EPA)'s PFAS Analytic Tools. Any point-source wastewater discharger to waters of the United States must have a NPDES permit, which defines a set of parameters for pollutants and monitoring to ensure that the discharge does not degrade water quality or impair human health. This list includes NPDES permitted facilities associated with permits that monitor for Per- and Polyfluoroalkyl Substances (PFAS), limited to the years 2007 - present. EPA further advises the following regarding these data: currently, fewer than half of states have required PFAS monitoring for at least one of their permittees, and fewer states have established PFAS effluent limits for permittees. For states that may have required monitoring, some reporting and data transfer issues may exist on a state-by-state basis.

Government Publication Date: Dec 16, 2024

Perfluorinated Alkyl Substances (PFAS) from Toxic Release Inventory: PFAS TRI

List of Toxics Release Inventory (TRI) facilities at which the reported chemical is a per- or polyfluoroalkyl (PFAS) substance included in the U.S. Environmental Protection Agency's (EPA) consolidated PFAS Master List of PFAS Substances. Encompasses Toxics Release Inventory records included in the EPA PFAS Analytic Tools. The EPA's TRI database currently tracks information on disposal or releases of 770 individually listed toxic chemicals and 33 chemical categories from thousands of U.S. facilities and details about how facilities manage those chemicals through recycling, energy recovery, and treatment. This listing includes TRI Reporting Data for calendar years 1987 through 2021 and Preliminary Data for 2022.

Government Publication Date: Sep 20, 2023

PFAS Water Quality Portal Sampling Data: PFAS WATER

This Per- and Poly-Fluoroalkyl Substances (PFAS) Environmental Media Sampling Data is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The Water Quality Portal (WQP), as a cooperative service sponsored by the United States Geological Survey, the EPA, and the National Water Quality Monitoring Council, is part of a modernized repository storing ambient sampling data for all environmental media and tissue samples. A wide range of federal, state, tribal and local governments, academic and non-governmental organizations, and individuals submit project details and sampling results to this public repository. Limitations: EPA did not carry out the sampling or testing of a majority of the data in the WQP PFAS dataset. EPA can only speak to the accuracy and completeness of the data from projects like the National Aquatic Resource Surveys for which EPA is the data owner/organization. Data may exist within the file on Quality Assurance Project Plans (QAPPs) and the approving agency of the QAPP, if a QAPP is entered.

Government Publication Date: Jul 21, 2025

PFAS TSCA Manufacture and Import Facilities: PFAS TSCA

The U.S. Environmental Protection Agency (EPA) issued the Chemical Data Reporting (CDR) Rule under the Toxic Substances Control Act (TSCA) and requires chemical manufacturers and facilities that manufacture or import chemical substances to report data to EPA. This list is specific only to TSCA Manufacture and Import Facilities with reported per- and poly-fluoroalkyl (PFAS) substances. Data file is sourced from EPA's PFAS Analytic Tools TSCA dataset which includes CDR/Inventory Update Reporting data from 1998 up to 2020. Disclaimer: This data file includes production and importation data for chemicals identified in EPA's CompTox Chemicals Dashboard list of PFAS without explicit structures and list of PFAS structures in DSSTox. Note that some regulations have specific chemical structure requirements that define PFAS differently than the lists in EPA's CompTox Chemicals Dashboard. Reporting information on manufactured or imported chemical substance amounts should not be compared between facilities, as some companies claim Chemical Data Reporting Rule data fields for PFAS information as Confidential Business Information.

Government Publication Date: Jan 5, 2023

PFAS Waste Transfers from RCRA e-Manifest: PFAS E-MANIFEST

This Per- and Poly-Fluoroalkyl Substances (PFAS) Waste Transfers dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. Every shipment of hazardous waste in the U.S. must be accompanied by a shipment manifest, which is a critical component of the cradle-to-grave tracking of wastes mandated by the Resource Conservation and Recovery Act (RCRA). According to the EPA, currently no Federal Waste Code exists for any PFAS compounds. To work around the lack of PFAS waste codes in the RCRA database, EPA developed the PFAS Transfers dataset by mining e-Manifest records containing at least one of these common PFAS keywords: • PFAS • PFOA • PFOS • PERFL • AFFF • GENX • GEN-X (plus the Vermont state-specific waste codes). Limitations: Amount or concentration of PFAS being transferred cannot be determined from the manifest information. Keyword searches may misidentify some manifest records that do not contain PFAS. This dataset should also not be considered to be exhaustive of all PFAS waste transfers.

Government Publication Date: Oct 4, 2025

PFAS Industry Sectors: PFAS IND

This Per- and Poly-Fluoroalkyl Substances (PFAS) Industry Sectors dataset is made available via the U.S. Environmental Protection Agency's (EPA) PFAS Analytic Tools. The EPA developed the dataset from various sources that show which industries may be handling PFAS including: EPA's Enforcement and Compliance History Online (ECHO) records restricted to potential PFAS-handling industry sectors; ECHO records for Fire Training Sites identified where fire-fighting foam may have been used in training exercises; and 14 CFR Part 139 Airports compiled from historic and current records from the FAA Airport Data and Information Portal. Since July 2006, all certificated Part 139 Airports are required to have fire-fighting foam onsite that meet certain military specifications, which to date have been fluorinated (Aqueous Film Forming Foam). Limitations: Inclusion in this dataset does not indicate that PFAS are being manufactured, processed, used, or released by the facility. Listed facilities potentially handle PFAS based on their industrial profile, but are unconfirmed by the EPA. Keyword searches in ECHO for Fire Training sites may misidentify some facilities and should not be considered to be an exhaustive list of fire training facilities in the U.S.

Government Publication Date: Sep 1, 2025

Hazardous Materials Information Reporting System: HMIRS

The Hazardous Materials Incident Reporting System (HMIRS) database contains unintentional hazardous materials release information reported to the U.S. Department of Transportation, Pipeline and Hazardous Materials Safety Administration.

Government Publication Date: May 28, 2025

National Clandestine Drug Labs: NCDL

The U.S. Department of Justice ("the Department"), Drug Enforcement Administration (DEA), provides this data as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy.

Government Publication Date: Nov 30, 2023

Toxic Substances Control Act: TSCA

The U.S. Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule. The CDR enables EPA to collect and publish information on the manufacturing, processing, and use of commercial chemical substances and mixtures (referred to hereafter as chemical substances) on the TSCA Chemical Substance Inventory (TSCA Inventory). This includes current information on chemical substance production volumes, manufacturing sites, and how the chemical substances are used. This information helps the Agency determine whether people or the environment are potentially exposed to reported chemical substances. EPA publishes submitted CDR data that is not Confidential Business Information (CBI). EPA CDR collections occur approximately every four years and reporting requirements change per collection.

Government Publication Date: May 12, 2022

Hist TSCA: HIST TSCA

The Environmental Protection Agency (EPA) is amending the Toxic Substances Control Act (TSCA) section 8(a) Inventory Update Reporting (IUR) rule and changing its name to the Chemical Data Reporting (CDR) rule.
The 2006 IUR data summary report includes information about chemicals manufactured or imported in quantities of 25,000 pounds or more at a single site during calendar year 2005. In addition to the basic manufacturing information collected in previous reporting cycles, the 2006 cycle is the first time EPA collected information to characterize exposure during manufacturing, processing and use of organic chemicals. The 2006 cycle also is the first time manufacturers of inorganic chemicals were required to report basic manufacturing information.

Government Publication Date: Dec 31, 2006

FTTS Administrative Case Listing: FTTS ADMIN

An administrative case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

FTTS Inspection Case Listing: FTTS INSP

An inspection case listing from the Federal Insecticide, Fungicide, & Rodenticide Act (FIFRA) and Toxic Substances Control Act (TSCA), together known as FTTS. This database was obtained from the Environmental Protection Agency's (EPA) National Compliance Database (NCDB). The FTTS and NCDB was shut down in 2006.

Government Publication Date: Jan 19, 2007

Potentially Responsible Parties List: PRP

Early in the site cleanup process, the U.S. Environmental Protection Agency (EPA) conducts a search to find the Potentially Responsible Parties (PRPs). The EPA looks for evidence to determine liability by matching wastes found at the site with parties that may have contributed wastes to the site. This listing contains PRPs, Noticed Parties, at sites in the EPA's Superfund Enterprise Management System (SEMS).

Government Publication Date: Sep 29, 2025

State Coalition for Remediation of Drycleaners Listing: SCRD DRYCLEANER

The State Coalition for Remediation of Drycleaners (SCRD) was established in 1998, with support from the U.S. Environmental Protection Agency (EPA) Office of Superfund Remediation and Technology Innovation. Coalition members are states with mandated programs and funding for drycleaner site remediation. Current members are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin. Since 2017, the SCRD no longer maintains this data, refer to applicable state source data where available.

Government Publication Date: Nov 08, 2017

Integrated Compliance Information System (ICIS): ICIS

The Integrated Compliance Information System (ICIS) database contains integrated enforcement and compliance information across most of U.S. Environmental Protection Agency's (EPA) programs. The vision for ICIS is to replace EPA's independent databases that contain enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions and a subset of the Permit Compliance System (PCS), which supports the National Pollutant Discharge Elimination System (NPDES). This information is maintained by the EPA Headquarters and at the Regional offices. A future release of ICIS will completely replace PCS and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities that support compliance and enforcement programs, including incident tracking, compliance assistance, and compliance monitoring.

Government Publication Date: May 3, 2025

Drycleaner Facilities: FED DRYCLEANERS

A list of drycleaner facilities from Enforcement and Compliance History Online (ECHO) data as made available by the U.S. Environmental Protection Agency (EPA), sourced from the ECHO Exporter file. This EPA source file tracks facilities that possess NAICS and SIC codes that classify businesses as drycleaner establishments.

Government Publication Date: Jul 19, 2025

Delisted Drycleaner Facilities: DELISTED FED DRY

List of sites which once appeared on - and have since been removed from - the list of drycleaner facilities included in Enforcement and Compliance History Online (ECHO) data as made available by the U.S. Environmental Protection Agency (EPA), sourced from the ECHO Exporter file. This EPA source file tracks facilities that possess NAICS and SIC codes that classify businesses as drycleaner establishments.

Government Publication Date: Jul 19, 2025

Formerly Used Defense Sites: FUDS

Formerly Used Defense Sites (FUDS) are properties that were formerly owned by, leased to, or otherwise possessed by and under the jurisdiction of the Secretary of Defense prior to October 1986, where the Department of Defense (DOD) is responsible for an environmental restoration. The FUDS Annual Report to Congress (ARC) is published by the U.S. Army Corps of Engineers (USACE). This data is compiled from the USACE's Geospatial FUDS data layers and Homeland Infrastructure Foundation-Level Data (HIFLD) FUDS dataset which applies to the Fiscal Year 2021 FUDS Inventory.

Government Publication Date: May 15, 2023

FUDS Munitions Response Sites: FUDS MRS

Boundaries of Munitions Response Sites (MRS), published with the Formerly Used Defense Sites (FUDS) Annual Report to Congress (ARC) by the U.S. Army Corps of Engineers (USACE). An MRS is a discrete location within a Munitions response area (MRA) that is known to require a munitions response. An MRA means any area on a defense site that is known or suspected to contain unexploded ordnance (UXO), discarded military munitions (DMM), or munitions constituents (MC). This data is compiled from the USACE's Geospatial MRS data layers and Homeland Infrastructure Foundation-Level Data (HIFLD) MRS dataset.

Government Publication Date: May 15, 2023

Former Military Nike Missile Sites: FORMER NIKE

This information was taken from report DRXTH-AS-IA-83A016 (Historical Overview of the Nike Missile System, 12/1984) which was performed by Environmental Science and Engineering, Inc. for the U.S. Army Toxic and Hazardous Materials Agency Assessment Division. The Nike system was deployed between 1954 and the mid-1970's. Among the substances used or stored on Nike sites were liquid missile fuel (JP-4); starter fluids (UDKH, aniline, and furfuryl alcohol); oxidizer (IRFNA); hydrocarbons (motor oil, hydraulic fluid, diesel fuel, gasoline, heating oil); solvents (carbon tetrachloride, trichloroethylene, trichloroethane, stoddard solvent); and battery electrolyte. The quantities of material a disposed of and procedures for disposal are not documented in published reports. Virtually all information concerning the potential for contamination at Nike sites is confined to personnel who were assigned to Nike sites. During deactivation most hardware was shipped to depot-level supply points. There were reportedly instances where excess materials were disposed of on or near the site itself at closure. There was reportedly no routine site decontamination.

Government Publication Date: Dec 2, 1984

PHMSA Pipeline Safety Flagged Incidents: PIPELINE INCIDENT

This list of flagged pipeline incidents is made available by the U.S. Department of Transportation (US DOT) Pipeline and Hazardous Materials Safety Administration (PHMSA). PHMSA regulations require incident and accident reports for five different pipeline system types. Accidents reported on hazardous liquid gravity lines (§195.13) and reporting-regulated-only hazardous liquid gathering lines (§195.15) and incidents reported on Type R gas gathering (§192.8(c)) are not included in the flagged incident file data.

Government Publication Date: Jul 10, 2025

Material Licensing Tracking System (MLTS): MLTS

A list of sites that store radioactive material subject to the Nuclear Regulatory Commission (NRC) licensing requirements. This list is maintained by the NRC. As of September 2016, the NRC no longer releases location information for sites. Site locations were last received in July 2016.

Government Publication Date: May 11, 2021

Historic Material Licensing Tracking System (MLTS) sites: HIST MLTS

A historic list of sites that have inactive licenses and/or removed from the Material Licensing Tracking System (MLTS). In some cases, a site is removed from the MLTS when the state becomes an "Agreement State". An Agreement State is a State that has signed an agreement with the Nuclear Regulatory Commission (NRC) authorizing the State to regulate certain uses of radioactive materials within the State.

Government Publication Date: Jan 31, 2010

Mines Master Index File: MINES

The Master Index File (MIF) is provided by the United States Department of Labor, Mine Safety and Health Administration (MSHA). This file, which was originally created in the 1970's, contained many Mine-IDs that were invalid. MSHA removes invalid IDs from the MIF upon discovery. MSHA applicable data includes the following: all Coal and Metal/Non-Metal mines under MSHA's jurisdiction since 1/1/1970; mine addresses for all mines in the database except for Abandoned mines prior to 1998 from MSHA's legacy system (addresses may or may not correspond with the physical location of the mine itself); violations that have been assessed penalties as a result of MSHA inspections beginning on 1/1/2000; and violations issued as a result of MSHA inspections conducted beginning on 1/1/2000.

Government Publication Date: Aug 8, 2025

Surface Mining Control and Reclamation Act Sites: SMCRA

This inventory of land and water impacted by past mining (primarily legacy coal mining operations) is maintained by the U.S. Department of the Interior's Office of Surface Mining Reclamation and Enforcement (OSMRE), as it provides information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). This inventory contains information on the type and extent of Abandoned Mine Land (AML) Problems, as well as information on the cost associated with the reclamation of those problems. The data is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed. Disclaimer: Per the OSMRE, States and tribes who enter their data into e-AMLIS (AML Inventory System) may truncate their latitude and longitude so the precise location of usually dangerous AMLs is not revealed in an effort to protect the public from searching for these AMLs, most of which are on private property. If more precise location information is needed, please contact the applicable state/tribe of interest.

Government Publication Date: Oct 30, 2025

Mineral Resource Data System: MRDS

The Mineral Resource Data System (MRDS) is a collection of reports describing metallic and nonmetallic mineral resources throughout the world. Included are deposit name, location, commodity, deposit description, geologic characteristics, production, reserves, resources, and references. This database contains the records previously provided in the Mineral Resource Data System (MRDS) of USGS and the Mineral Availability System/Mineral Industry Locator System (MAS/MILS) originated in the U.S. Bureau of Mines, which is now part of USGS. The USGS has ceased systematic updates of the MRDS database with their focus more recently on deposits of critical minerals while providing a well-documented baseline of historical mine locations from USGS topographic maps.

Government Publication Date: Mar 15, 2016

DOE Legacy Management Sites: LM SITES

The U.S. Department of Energy (DOE) Office of Legacy Management (LM) currently manages radioactive and chemical waste, environmental contamination, and hazardous material at over 100 sites across the U.S. The LM manages sites with diverse regulatory drivers (statutes or programs that direct cleanup and management requirements at DOE sites) or as part of internal DOE or congressionally-recognized programs, such as but not limited to: Formerly Utilized Sites Remedial Action Program (FUSRAP), Uranium Mill Tailings Radiation Control Act (UMTRCA Title I, Tile II), Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), Resource Conservation and Recovery Act (RCRA), Decontamination and Decommissioning (D&D), Nuclear Waste Policy Act (NWPA). The intent of the site location is to provide a general reference point to the site on a national scale. The coordinates of each site point can be the location of a site monument, the centroid of the site boundary, or a general location of the site. This site listing includes data exported from the DOE Office of LM's Geospatial Environmental Mapping System (GEMS). GEMS Data disclaimer: The DOE Office of LM makes no representation or warranty, expressed or implied, regarding the use, accuracy, availability, or completeness of the data presented herein.

Government Publication Date: Nov 6, 2025

Alternative Fueling Stations: ALT FUELS

This list of alternative fueling stations is sourced from the Alternative Fuels Data Center (AFDC). The U.S. Department of Energy's Office of Energy Efficiency & Renewable Energy launched the AFDC in 1991 as a repository for alternative fuel vehicle performance data, which provides a wealth of information and data on alternative and renewable fuels, advanced vehicles, fuel-saving strategies, and emerging transportation technologies. The data includes Biodiesel (B20 and above), Compressed Natural Gas (CNG), Electric, Ethanol (E85), Hydrogen, Liquefied Natural Gas (LNG), Propane (LPG), and Renewable Diesel (R20 and above) fuel type locations.

Government Publication Date: Aug 1, 2025

Superfunds Consent Decrees: CONSENT DECREES

This list of Superfund consent decrees is provided by the Department of Justice, Environment & Natural Resources Division (ENRD) through a Freedom of Information Act (FOIA) applicable file. This listing includes Cases filed since 2010 limited to the following: Consent Decrees for CERCLA or Superfund Sites filed and/or as proposed within the ENRD's Case Management System (CMS); and applicable ENRD's Environmental Defense Section (EDS) CERCLA Cases with "Consent" in History Note. CMS may not reflect the latest developments in a case, nor can the agency guarantee the accuracy of the data. ENRD Disclaimer: Congress excluded three discrete categories of law enforcement and national security records from the requirements of the FOIA; response is limited to those records that are subject to the requirements of the FOIA; however, this should not be taken as an indication that excluded records do, or do not, exist.

Government Publication Date: Jun 26, 2024

Air Facility System: AFS

This EPA retired Air Facility System (AFS) dataset contains emissions, compliance, and enforcement data on stationary sources of air pollution. Regulated sources cover a wide spectrum; from large industrial facilities to relatively small operations such as dry cleaners. AFS does not contain data on facilities that are solely asbestos demolition and/or renovation contractors, or landfills. ECHO Clean Air Act data from AFS are frozen and reflect data as of October 17, 2014; the EPA retired this system for Clean Air Act stationary sources and transitioned to ICIS-Air.

Government Publication Date: Oct 17, 2014

Registered Pesticide Establishments: SSTS

This national list of active EPA-registered foreign and domestic pesticide and/or device-producing establishments is based on data from the Section Seven Tracking System (SSTS). The Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) Section 7 requires that each producing establishment must place its EPA establishment number on the label or immediate container of each pesticide, active ingredient or device produced. An EPA establishment number on a pesticide product label identifies the EPA registered location where the product was produced. The list of establishments is made available by the U.S. Environmental Protection Agency (EPA).

Government Publication Date: Sep 26, 2025

Polychlorinated Biphenyl (PCB) Transformers: PCBT

Locations of Transformers Containing Polychlorinated Biphenyls (PCBs) registered with the United States Environmental Protection Agency. PCB transformer owners must register their transformer(s) with EPA. Although not required, PCB transformer owners who have removed and properly disposed of a registered PCB transformer may notify EPA to have their PCB transformer de-registered. Data made available by EPA.

Government Publication Date: Oct 15, 2019

Polychlorinated Biphenyl (PCB) Notifiers: PCB

Facilities included in the national list of facilities that have notified the United States Environmental Protection Agency (EPA) of Polychlorinated Biphenyl (PCB) activities. Any company or person storing, transporting or disposing of PCBs or conducting PCB research and development must notify the EPA and receive an identification number.

Government Publication Date: May 23, 2024

Power Plants: POWER PLANTS

This list of power plants is provided by the U.S. Energy Information Administration (EIA). The listing includes operable electric generating plants in the United States by energy source, originating from the EIA-860, Annual Electric Generator Report; EIA-860M, Monthly Update to the Annual Electric Generator Report; and EIA-923, Power Plant Operations Report. It includes all operable plants by energy source with a combined nameplate capacity of 1 megawatt or more that are operating, are on standby, or out of service for short- or long-term.

Government Publication Date: Jun 5, 2025

Historical Business Activity Risk: HIST RISK

Proprietary list of sites identified as potentially having engaged in business activity that poses a higher-than-normal risk of contamination. Records originate from historical city directories, and are included in this list based on broad business categories Potentially Hazardous Chemical Users and Fuel and Automotive, including but not limited to Dry Cleaners and Fuel Stations, Garages, etc. Inclusion in this listing does not indicate that there is or ever has been contamination; rather, sites are included in this list due to their potential for having engaged in a business activity presenting an elevated risk of contamination. The list was compiled from various city directories including Polks, Millers, Mullin Kille, Interstate Directory, and State Directory Co; spanning roughly 1920s through 1960 depending on information available by city.

Government Publication Date: Jan 1, 1960

State

Hazardous Waste Facilities: HAZ

List of hazardous waste generators and treatment, storage, and disposal facilities overseen by the Hazardous Waste Bureau (HWB), New Mexico Environment Department (NMED).

Government Publication Date: Apr 24, 2018

Spills: SPILLS

A listing of spills included in the New Mexico Environment Department's Environmental Notification Tracking System.

Government Publication Date: May 31, 2025

Spills and Incidents - Oil Conservation Division: SPILLS OIL

List of Spills and Incidents made available by the State of New Mexico Oil Conservation Division.

Government Publication Date: Oct 23, 2025

Clandestine Drug Lab Discoveries: CDL

List of addresses of locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. The sources of the entries are law enforcement agencies, and although the list is made available by the New Mexico Environment Department (NMED), NMED has not verified the data and does not guarantee its accuracy. Sites listed were seized prior to January 1, 2008, were not subject to the New Mexico Clandestine Drug Lab Cleanup Rule.

Government Publication Date: May 17, 2018

Per- and Polyfluoroalkyl Substances (PFAS): PFAS

List of PFAS/PFOS sites of concern and sampling locations made available by the New Mexico Environment Department (NMED). Includes sites known to the NMED where PFAS/PFOS containing material may be of concern, as well as USGS PFAS groundwater sampling locations.

Government Publication Date: Feb 4, 2025

Ground Water Discharge Permits: GW DISCHARGE

The Ground Water Pollution Prevention Section of the New Mexico Environment Department reviews and approves discharges that have the potential to impact ground water quality pursuant to Subparts III and V of the Water Quality Control Commission (WQCC) regulations (20.6.2 NMAC). Ground water discharge permits address a wide variety of discharges including domestic wastewater treatment plants, commercial septic tank leach fields, power generating plants, commercial laundries not served by sanitary sewers, dairies, food processing plants, commercial land farms for treatment of contaminated soil, industrial discharges, injection wells and ground water remediation systems. This list does not include permits for mines or agricultural facilities.

Government Publication Date: Dec 20, 2024

Southwest Research and Information Center Uranium Sites: URANIUM

This database contains information on Northwestern New Mexico uranium projects located in Navajo Country and is maintained by the Southwest Research and Information Center. This organization was founded in 1971 for the purpose of providing information to the public on the effects of energy development and resource exploitation on the people and their cultures, lands, water, and air of New Mexico and the Southwest.

Government Publication Date: Oct 18, 2006

Tribal

No Tribal additional environmental record sources available for this State.

County

No County additional environmental record sources available for this State.

Definitions

Database Descriptions: This section provides a detailed explanation for each database including: source, information available, time coverage, and acronyms used. They are listed in alphabetic order.

Detail Report: This is the section of the report which provides the most detail for each individual record. Records are summarized by location, starting with the project property followed by records in closest proximity.

Distance: The distance value is the distance between plotted points, not necessarily the distance between the sites' boundaries. All values are an approximation.

Direction: The direction value is the compass direction of the site in respect to the project property and/or center point of the report.

Elevation: The elevation value is taken from the location at which the records for the site address have been plotted. All values are an approximation. Source: Google Elevation API.

Executive Summary: This portion of the report is divided into 3 sections:

'Report Summary'- Displays a chart indicating how many records fall on the project property and, within the report search radii.

'Site Report Summary'-Project Property'- This section lists all the records which fall on the project property. For more details, see the 'Detail Report' section.

'Site Report Summary-Surrounding Properties'- This section summarizes all records on adjacent properties, listing them in order of proximity from the project property. For more details, see the 'Detail Report' section.

Map Key: The map key number is assigned according to closest proximity from the project property. Map Key numbers always start at #1. The project property will always have a map key of '1' if records are available. If there is a number in brackets beside the main number, this will indicate the number of records on that specific property. If there is no number in brackets, there is only one record for that property.

The symbol and colour used indicates 'elevation': the red inverted triangle will dictate 'ERIS Sites with Lower Elevation', the yellow triangle will dictate 'ERIS Sites with Higher Elevation' and the orange square will dictate 'ERIS Sites with Same Elevation.'

Unplottables: These are records that could not be mapped due to various reasons, including limited geographic information. These records may or may not be in your study area, and are included as reference.

APPENDIX I

Supplemental Records

[RESERVED]

APPENDIX J

Photographic Log



Photograph 1. View of Subject Property taken from the northeast facing southeast across 2nd Street with overhead electrical service lines visible serving the primary Site building.



Photograph 2. Additional View of Subject Property taken from the northern sidewalk along 2nd Street facing south across 2nd Street with easternmost commercial suite visible in left of photograph.



Photograph 3. View of Subject Property exterior taken from the northwestern Subject Property boundary facing southeast.



Photograph 4. View of Subject Property interior taken from the northeastern Subject Property boundary facing southwest.



Photograph 5. View of Subject Property interior taken from the southeastern Subject Property boundary facing northwest.



Photograph 6. View of Subject Property interior taken from the southwestern Subject Property boundary facing northeast.



Photograph 7. View of gas meters along the western exterior of the primary Site building.



Photograph 8. View of the westernmost commercial suite located in the primary Site building.



Photograph 9. View of a commercial suite located in the primary Site building immediately east of the suite from Photograph 8.



Photograph 10. View of a commercial suite located in the primary Site building immediately east of the suite from Photograph 9.



Photograph 11. View of a commercial suite located in the primary Site building immediately east of the suite from Photograph 10 with gas meters visible in the left of the photograph.



Photograph 12. Additional view of gas meters on the northern exterior of the primary Site building.



Photograph 13. View of a commercial suite located in the primary Site building immediately east of the suite from Photograph 11 with 1406 address marker visible on post in center left of photograph.



Photograph 14. View of a commercial suite located in the primary Site building immediately east of the suite from Photograph 12 with 1406 address markers visible on mailbox.



Photograph 15. View of the east adjoining property, Santa Fe Self Storage. Photograph taken from the 2nd Street frontage facing west-southwest.



Photograph 16. Additional view of the east adjoining property taken from the exterior of the property from the northeastern corner of the Berry Avenue and 3rd Street intersection facing northeast.



Photograph 17. View of a vacant commercial space adjoining to the northeast across the intersection of Berry Avenue and 2nd Street, located at 1409 2nd Street.



Photograph 18. View of one of the north adjoining residential properties located at 1407 2nd Street.



Photograph 19. View of one of the north adjoining commercial properties located at 1405 2nd Street which is an office space.



Photograph 20. View of Get Framed picture framing shop located at 1403 2nd Street.



Photograph 21. View of Medina's Rustic Furniture located at 1708 2nd Street.



Photograph 22. View of a vacant commercial property to the west of the Subject Property, located at 1710 2nd Street.



Photograph 22. View of the south adjoining property, Dunn-Edwards Paints. Photograph taken from 3rd Street facing north.



Photograph 23. View of the Dunn-Edwards Paints building's eastern exterior. Photograph taken from 3rd Berry Avenue facing west.



Photograph 24. View of the intersection of Cerrillos Road and 2nd Street west of the Subject Property. Photograph taken from the northeastern corner of the intersection facing southwest.



Photograph 25. View of Aspen Dry Cleaners located northwest of the Subject Property at 1616 Cerrillos Road.

APPENDIX K

Interviews

1140 - P. Gutierrez & A. Murphy on site @ Lopez Cleaners
↳ 57°F/Sunny

Objectives - Complete site recon/access for five former dry cleaner sites in SF w/ one site ~~access~~ recon @ New Method Dry Cleaner.

1143 - TGSM complete, take photos & begin

838 E Palace Ave / Lopez Cleaners
- Residential w/ 2nd structure in rear
- E adjoining = Palace Grocery (853-A E Palace)
- Left ltr/access package in entryway gate after knocking w/ no answer
- All other props = residential

1150 - Depart for 622 Canyon Rd.

1154 - @ 622 Canyon Rd / Universal Cleaners
- Access not granted, photos from dirt rd/alley way
- W adjoining = 622 residence
- N adjoining = 626 w/ const. permit displayed for addition
- S adjoining = residential through alley
- E adjoing = 630 Canyon Olive Rush Studios Art Center

1205 - Depart for 105 E. Water St.

1215 - @ E. Water St. / New Method DC
- Josh owner of business w/ other partners
- Café Pasquel's Gallery = N adjoining
- Municipal PK Lot = S adj

E Water St. / New Method DC
- E adj = The Chile Shop
- W adj = Tonic cocktails / Jazz Cafe
- Per Josh Robert Spitz of the Spitz Brothers owns the bldg, but he's in his 80s & uses prop mgmt co.
- If DC on site, likely 1970s
- He'll pass paperwork on

1236 - Depart for 328 E Sandoval

1240 @ 328 E Sandoval / Master Cleaners Sandoval
- Spoke w/ Greg & prop owners still in AZ for winters
- Drop off ltr/access packet for him to pass on
- 330 = S adj / physically contiguous SF Biscochito Co.
- N adj (across Aztec) = Rainbow Gate (home goods)
- E adj = SF Judical Complex
- W adj = residential / single family 310 Aztec

1251 - Depart for 1406 2nd St.

1302 @ 1406 2nd St. / Danny's Cleaners
- Gave paperwk to Auto sales employee she'll pass to prop owner
- N adj = residental on N side 2nd St.
- E adj = SF Self Storage
- S adj = Dunn Edwards Paints
- W adj = All Tangled Up Salon

1307 - Depart 2nd St.
↳ @ 2nd St. to meet owner


1340 - 1956 Mova dug foundation. Dry cleaning fence & E. Used petroleum based cleaner. Waste haules ABQ 1958 to 25 years ago. Sold all eqp (boilers, etc). No UST & ~~drums~~ 100 gal tank to newer

2nd St. Would fill. In gd H_2O drains. ~~No~~ PCE/TCE in solvents? Said shut down before "envt'l ppl". Commercial rentals since closed Accupunture, skin treatments, etc. Brother & sister own W adj. Hist. cleaner on Palace Ave closed 50 yrs ago. Walked interior w/ tenant - std b'room & H_2O heater

1412 - @ 1911 St. Mike's/New Method DC
- Bob ortega's 90 yr old mother owns the property & Lawerence Romero is tenant running business
- Romero took over business ~2000 & removed PERC machine & is on 3rd set of machinery currently
- Manufacturer = Union
- Solvent = Seitz Intense (see photo)
- Muck from unit hauled off 2x month by ABQ operator. Drum w/ lock ring outside. Evaporated ultimately
- Machine has fan, H_2O sep, still, & pumps
- 15 HP boiler (recently re-piped) in rear powers machines
- Air comp for small pneumatics on vacs for presses
- 8 yrs ago? sampling done along N prop boundary w "hoses out of ground" from spill next door Hyundai?
- vac system overhead for lint collection
- ortega owns entire strip mall & 5 unit tenant commercial prop.

1450 - Call w/ M. Hubbard (PM) re: status of all site visits. Head offsite.

Summary - Dropped 2nd copy of access agreement paperwork w/ tenants @ Water St & Sandoval sites to be delivered to prop. owners. E Palace Ave left paperwork in entryway gate. Photos taken @ 622 Canyon Rd. & 2nd St & St. Mike's sites walked/met w/ owners & tenants.



APPENDIX L

Qualifications of Environmental Professionals



Matt Hubbard
Senior Environmental Scientist

Years of Experience: 14

Education:

- BS, Environmental Science, University of Texas at Austin

Professional Registrations/Affiliations:

- TCEQ Leaking Petroleum Storage Tank (LPST) Project Manager, License No. PM0000720, 2022

Professional History:

2026 – Present	Senior Environmental Scientist – INTERA Incorporated, Austin, TX
2018 – 2025	Environmental Scientist – INTERA Incorporated, Austin, TX
2017 – 2018	Environmental Specialist – City of Austin, Development Services Department, Austin, TX
2013 – 2017	Project Manager / Engineering and Corrective Action Specialist – Texas Commission on Environmental Quality, Remediation Division, Superfund Section, Austin, TX
2012 – 2013	Work Lead / Licensed Electrician – Wells Solar and Electrical Services, Austin, TX
2012	Field Research Assistant – University of Texas, Austin, TX

Training:

- MSHA Part 48 Surface New Miner Training, 2019-2023
- 40-Hour General Site Workers Training, OSHA 29 CFR 1910.120(e)(3), 2013
- 8-Hour Refresher, OSHA 29 CFR 1910.120, 2013 – 2025
- Hydrogen Sulfide (H2S) Training, 2018
- CPR, First Aid, and Bloodborne Pathogens Training, 29 CFR 1910.1030, 2024
- ArcGIS Pro, WinSitu, Strater®, Grapher™, Surfer®, PLog, LogPlot
- Land Science® Certified Vapor Barrier Inspector, 2020

Matt Hubbard is a Senior Environmental Scientist at INTERA with a BS degree in environmental science and 14 years of experience investigating and remediating contaminated sites. He serves in several capacities including Project Manager, Technical Lead, Field Lead, and Health and Safety Lead. Matt develops and implements highly technical work plans for complex technical projects and provides subject matter expertise to clients and senior leadership. His project experience includes state and federal Superfund, Brownfields, voluntary cleanup program (VCP), petroleum storage tank (PST), Phase I and Phase II Environmental Site Assessment (ESA), and imminent threat/removal assessments. Matt is an expert in field methods including sampling of surface and subsurface environmental media, field screening techniques, environmental drilling, and well construction. He has worked on contaminated sites associated with metals including hexavalent chromium, petroleum hydrocarbons, chlorinated solvents, polychlorinated biphenyls (PCBs), organochlorine and organophosphorus compounds (pesticides and herbicides), dioxins/furans, and per- and polyfluoroalkyl substances (PFAS). Matt has significant experience designing assessments and implementing innovative methods, including incremental sampling methodology (ISM), field portable x-ray fluorescence (XRF), passive soil gas (PSG), ground-penetrating radar (GPR), and electromagnetic mapping. He is also experienced in water resources development, including oversight and support of production well drilling and installation, aquifer performance analysis, dynamic flow profiling, and mass balance chemical analysis.

Project Experience – Environmental

ChemFab Phase I Environmental Site Assessment, ChemFab, LLC., Clute, TX. 2026. *Project Manager.* Conducted a Phase I ESA for a fabrication facility and an adjoining property in accordance with ASTM Standard Practice E1527-21.

Southside Storage Phase I Environmental Site Assessments, Southside Wrecker, Inc., Austin, TX. 2025 – 2026. *Project Manager.* Conducted two Phase I ESAs: one at a vacant property that was previously a sand and gravel mine and subsequently filled via unpermitted landfilling operations and another at an automotive repair and maintenance facility. The Phase I ESAs were conducted in accordance with ASTM Standard Practice E1527-21.

Hornsby Bend Biosolids Management Plant, City of Austin Water, TX. 2023 – 2026. *Project Manager.* Coordinated and led quarterly groundwater monitoring and annual soil sampling in support of the requirements of the Texas Commission on Environmental Quality (TCEQ) permit to process wastewater treatment plant sewer sludge, land apply wastewater treatment plant sewage sludge, and irrigate lagoon supernatant under provisions of Chapter 26 of the Texas Water Code, Chapter 361.121 of the Texas Health and Safety Code, and Chapter 312 of the Texas Administrative Code. Conducted independent data usability review for each quarterly groundwater event. Prepared quarterly updates to groundwater potentiometric elevation maps.

Prepared annual report for submittal to the TCEQ. Performed supplemental historical data review and assessment in support of additional reporting requested by special provision of the 2025 permit renewal and was the primary author of the supplemental report.

Jensen Drive Scrap State Superfund Site, 3603 Jensen Drive LLC, Harris County, TX. 2018 – 2026. *Environmental Scientist and Field Lead.* Drafted Annual Post Closure Care Report and Data Usability Summary for annual 2018, 2019, 2020, and 2025 site activities, which included groundwater monitoring, potentiometric mapping, and engineer's inspection of the site waste containment unit. Coordinated and conducted 2019, 2020, and 2025 groundwater monitoring events, including low-flow sampling for PCBs.

BAE TRACOR Phase I and Phase II Environmental Site Assessment, City of Austin Brownfields, TX. 2025. *Project Manager.* Conducted a Phase I ESA for the City of Austin (COA) Brownfields Program in accordance with ASTM Standard Practice E1527-21. The approximately 140-acre facility had 12 permanent structures and was formerly used for military research and development. Coordinated all aspects of project work to meet the City's expedited timeline within the 120-day due diligence period. Developed the rationale and scope of the Phase II ESA and designed the sampling plan. Soil and groundwater investigation included the installation of soil borings and monitor wells for sampling and analysis of soil and groundwater for contaminants including PFAS and nitroaromatics and nitramines. Directed the INTERA team and subcontractors for the multi-phased progressive tasks in support of the overall objective and made necessary and defensible modifications to the plan, as needed, to meet budget and scheduling restraints. Authored the Phase II ESA and provided support to the COA during negotiations leading up to and culminating with the acquisition of the property.

411 Chicon, City of Austin Brownfields, TX. 2024 – 2025. *Project Manager.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice E1527-21. Oversaw a geophysical survey of the subsurface and an exploratory investigation to determine the presence or absence of underground storage tanks.

Former Travis County Landfill, Moo Moo Meadows, LLC., Austin, TX. 2024 – 2025. *Project Manager.* Reviewed available data to determine groundwater conditions and assess landfill permittee's responsibilities for management. Provided expert environmental support in a contested dispute for site development under 30 Texas Administrative Code (TAC) 330 Subchapter T – Use of Land Over Closed Municipal Solid Waste Landfills.

Austin Bergstrom International Airport Augmented Staff, City of Austin Aviation Department, TX. 2023 – 2025. *Environmental Scientist and Field Lead.* Provided as-needed consulting and field assistance in support of ongoing development at Austin Bergstrom International Airport. Conducted liquid and solid waste sampling for disposal and consulting for the remediation of bulk PFAS chemical and PFAS-containing water in emergency response vehicles. Provided oversight and project coordination for PFAS-contaminated stockpile relocation, monitor well drilling and installation, and soil and groundwater sampling for PFAS.

In-Situ Anaerobic Bioremediation Pilot Study, Chemical Waste Management, Corpus Christi, TX. 2024. *Environmental Scientist.* Conducted baseline groundwater monitoring in support of the pilot study that was performed to evaluate in-situ anaerobic bioremediation as a remedial method groundwater contamination.

Pollution Prevention Plan, Precise Hard Chrome, LLC., Waco, TX. 2024. *Environmental Scientist.* Authored the five-year Pollution Prevention Plan for the Precise Hard Chrome facility in Waco, Texas in accordance with 30 TAC Chapter 335, Subchapter Q (*Pollution Prevention: Source Reduction and Waste Management*). The plan identified all activities that generated hazardous waste or resulted in a release of Toxic Release Inventory reportable chemicals and a prioritized list of economically and technologically feasible source reduction and waste minimization projects.

Peaceful Hill, Graham Development, Austin, TX. 2024. *Project Manager.* Assessed the regulatory framework for proposed stormwater injection to aquifer recharge wells on a commercial development (Class V Injection Well). The assessment included siting and hydrogeologic analysis and provided recommendations for additional investigation in support of implementation.

Rio Grande Coop Phase I Environmental Site Assessment, City of Austin Brownfields, TX. 2024. *Project Manager.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice E1527-21.

Anita Ferrales Coy Phase I Environmental Site Assessment and Asbestos/Lead Survey, City of Austin Brownfields, TX. 2024. *Project Manager.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice

E1527-21. Facilitated asbestos containing material and lead-containing paint survey and preparation of project remediation specifications.

McAlpine Lease Third Party Release Assessment Review, E&W Law, Stanton, TX. 2024. *Environmental Scientist and Data Reviewer.* Conducted data usability review of laboratory analytical results and senior review of the assessment review report for a crude oil and produced water release. Evaluated data relative to Railroad Commission of Texas (RRC) guidance.

Town Lake Metro Park Youth Hostel Phase I Environmental Site Assessment, City of Austin Parks and Recreation Department, TX. 2024. *Environmental Scientist.* Conducted a Phase I ESA in accordance with ASTM Standard Practice E1527-21 in support of planned redevelopment.

Environmental Impacts Assessment, Cooks Branch Conservancy, Montgomery, TX. 2024. *Environmental Scientist.* Oversaw drilling and installation of three monitoring wells. Lithologically logged each well in accordance with ASTM D2488-17e1 and Unified Soil Classification System (USCS). Conducted groundwater and surface water sampling and assessment for a range of analytes to determine impacts from a nearby mining operation. Provided technical support and senior review of data and deliverables.

Geotechnical Investigation for a Potential Compost Facility, Confidential Client, TX. 2024. *Environmental Scientist.* To determine a proposed site's suitability for TCEQ permitting of a compost facility, conducted a subsurface investigation focused on identifying shallow, low permeability clays suitable for use as an in-situ clay liner. Installed and lithologically logged 12 soil borings using the USCS. Collected soil samples from each boring at low permeability clay intervals based on field observations. Sent select samples to a geotechnical laboratory for analysis.

North Railroad Avenue Plume Superfund Site, New Mexico Environment Department, Española, NM. 2024. *Environmental Scientist and Field Lead.* Served as field lead for roto-sonic drilling and installation of a monitoring well in support of an New Mexico Environmental Department (NMED)-led cleanup at a former drycleaner site contaminated with tetrachloroethene (PCE) and its degradation products. Logged continuous core (ASTM D2488-17e1 / USCS) to 257 feet below ground surface (bgs), screened heated headspace soil samples with a photoionization detector, collected push-ahead groundwater samples at discrete depth intervals during drilling, and oversaw analysis of push-ahead groundwater samples via a FROG-5000 portable gas chromatograph. Identified the target hydrostratigraphic unit and informed the selection of the well screen interval. Assisted in work plan creation and annual reporting including software-based boring logs and potentiometric surface elevation mapping.

Per- and Polyfluorinated Substances Risk Assessment, California American Water, Duarte, CA. 2023 – 2024. *Environmental Scientist.* Assisted in the development of custom-built vadose-zone PFAS analytical solution tool to assess the vulnerability of existing and potential well sites to contamination. Identified potential contamination sources by evaluating records on former and current regulated facilities with current or former operations known to be or commonly associated with the use of PFAS. This information was used together with the spatial vulnerability analysis to assess the relative risk of PFAS contamination to existing and potential well sites. The analysis was used to develop recommendations for engineering and operational measures to mitigate the risk and impacts of future contamination. Measures could include changes in operation of existing wells, treatment, or replacement of wells that have reached the end of their service life. Prioritized recommendations for investigation and test drilling at new well sites based on operational benefits, cost, and risk of current or future contamination. The environmental data gathered for the study was provided for future use in permitting selected well sites.

JV DIRT, American AllWaste, Austin, TX. 2023 – 2024. *Environmental Scientist.* Conducted video well survey with a downhole camera. Conducted groundwater sampling. Prepared an update and revision to the site geologic/hydrogeologic report and groundwater protection plan in support of a permit renewal application for composting activities.

Remedial Investigation at Scrub-A-Dubb Barrel Company Site, Texas Commission on Environmental Quality, Lubbock, TX. 2020 – 2024. *Environmental Scientist.* Designed and conducted a remedial investigation, which was a targeted surface soil assessment in compliance with the site-specific field sampling plan (FSP) and the quality assurance program plan developed for the former drum recycling site utilizing ISM for the TCEQ Superfund Section. The primary contaminants of concern included volatile organic compounds (VOCs), semi-volatile organic compounds (SVOCs), and metals. Used direct-push methodology to collect over 700 soil increments (aliquots) to generate data to assess soils down to five feet bgs for the entirety of the five-acre site during one field mobilization. Collected replicate data to determine statistically if data generated for each ISM decision unit (DU) were representative and defensible. The field activity report was finalized and approved by the TCEQ in March 2022.

Data evaluation confirmed the success of the ISM approach. Authored an affected property assessment report for the TCEQ Remediation Division, compiling data from assessment over an approximately five-year span including soil, sediment, and groundwater.

Voluntary Cleanup Program Post-Response Assistance, Ice Man, Inc., Belton, TX. 2023. *Environmental Scientist.* Conducted on-site review and documentation of the condition of the side slope of an engineering control cap constructed and the adjacent creek bank at a TCEQ VCP site as part of the required post-response care actions. Prepared a memorandum describing the observations made and recommended future actions.

St. Johns Redevelopment Site, City of Austin Economic Development Department via the Austin Brownfield Revitalization Office, TX. 2023. *Project Manager.* Designed and implemented a Limited Phase II ESA for the assessment of a former industrial facility and TCEQ Leaking Petroleum Storage Tank site for planned redevelopment as residential multifamily affordable housing. The assessment included (1) third-party review and assessment of previous site investigation data to identify potential data gaps and areas of concern relative to potential contaminant impacts and (2) soil gas sampling and assessment to assess the potential vapor exposure risk to occupants of future site buildings. Installed a grid of 31 passive soil gas sampling devices over the former site operations area and assessed the laboratory analytical results after a 14-day uptake period, compared to United States Environmental Protection Agency (EPA) Vapor Intrusion Screening Levels. Prepared report documenting the assessment and recommended future actions and guidelines for the Austin Economic Development Department's agreement with the site developer.

Fairfield Lake State Park Environmental Assessment, Texas Parks and Wildlife Department, Freestone County, TX. 2023. *Environmental Scientist.* Provided technical support in discussions with client regarding conduct of Phase I and Phase II ESAs in aid of State of Texas eminent domain condemnation procedures for approximately 5,000 acres, including Fairfield Lake and the immediate surrounding property that was formerly designated as Fairfield Lake State Park. Of specific concern was possible impacts to surface water, sediments, and aquatic life from heavy metals and PCBs related to a former coal-fired power plant located along the northern end of the property. Conducted the site reconnaissance and prepared the Phase I ESA (ASTM Standard E1527-21), which identified several Recognized Environmental Conditions (RECs); however, additional work to address the RECs was halted when Texas Parks and Wildlife Department decided to end condemnation procedures.

Langford Elementary Phase I Environmental Site Assessment, City of Ausitn Brownfields Program, TX. 2023. *Environmental Scientist.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice E1527-21.

Whisper Valley, City of Austin Brownfields Program, TX. 2023. *Environmental Scientist.* Conducted a Phase I ESA for the COA Brownfields Program in accordance with ASTM Standard Practice E1527-21.

Emergency Response Waste Sampling at the Mexican American Cultural Center, City of Austin, TX. 2023. *Environmental Scientist.* Conducted emergency sampling of uncovered landfill waste material during the redevelopment of the Mexican American Cultural Center in downtown Austin, Texas.

Limited Phase II Environmental Site Assessment, American AllWaste, Lake Charles, LA. 2023. *Environmental Scientist.* Developed and sampled groundwater for VOCs, SVOCs, metals, petroleum hydrocarbons, pesticides, herbicides, PCBs, and PFAS. Prepared the report documenting the analytical results including a data usability summary. Provided recommendations for additional assessment based on the client's proposed property transaction.

Austin Nature Science Center Outpost, Soil Assessment, City of Austin Parks Department, TX. 2022 – 2023. *Environmental Scientist.* Performed soil assessment to delineate polycyclic aromatic hydrocarbons and heavy metals to Texas Risk Reduction Program (TRRP) Tier 1 Residential Total-soil-combined protective concentrations levels (PCLs) related to former skeet and firing range operations. This work was conducted in support of the implementation of a forthcoming removal action to restore the site to residential standards. Sampling approaches included ISM and ex-situ XRF methods. Authored the work plan and assessment report for this project.

Limited Phase II Environmental Site Assessment for Shield Park, Texas Commission on Environmental Quality Brownfields Program, Galveston, TX. 2022 – 2023. *Project Manager*. Oversaw completion of a geophysical survey implementing GPR and electromagnetic mapping to assess the presence of suspected underground storage tanks (USTs). Provided technical review and implemented TCEQ's soil assessment strategy including installing, screening, and sampling 20 soil borings. Logged each

boring according to the USCS. Prepared the Limited Phase II ESA report documenting site activities and analytical results for VOCs, SVOCs, metals, PCBs, and total petroleum hydrocarbons (TPH). Conducted technical data review and usability assessment and prepared a memorandum in accordance with the TCEQ Quality Assurance Project Plan and applicable EPA guidance.

Limited Phase II Environmental Site Assessment for Hargrave Fleet Services Property, City of Austin Brownfields Program, TX. 2022 – 2023. *Environmental Scientist.* The scope of the Phase II ESA included a full asbestos and lead-containing paint inspection survey, soil gas, surface soil, and groundwater assessment. Contaminants of concern included heavy metals, VOCs, SVOCs, dioxins/furans, and PFAS. Authored the work plan and led the field event to install passive soil gas sampling devices, groundwater monitoring wells, and soil borings. Categorized the groundwater in the shallow groundwater bearing in accordance with TRRP guidelines.

Phase I and II Environmental Site Assessment, Foundation Communities Brownfields Redevelopment Project - Airport Boulevard, Austin, TX. 2022. *Environmental Scientist.* Performed Phase II ESA in preparation for the development of an affordable housing apartment complex by Foundation Communities. Activities assessed two vapor encroachment conditions and two RECs. Deployed a total of 20 PSGs to assess soil gas. Installed four soil borings to assess site soils and the shallow groundwater-bearing unit.

Phase I Environmental Site Assessment, Tract 1-B: Paseo del Pueblo Sur and Los Pandos Road, Taos Hotel Associates, LLC., Taos, NM. 2022. *Environmental Scientist.* Conducted and prepared a Phase I ESA report in accordance with ASTM Standard E1527-21 and resultant volume estimate for a proposed removal of identified petroleum-contaminated soil more than the NMED action level of 100 parts per million by volume.

Scrub-A-Dubb Barrell Company Proposed State Superfund Site, Texas Commission on Environmental Quality, Lubbock County, TX. 2019 – 2023. *Environmental Scientist.* Drafted the TCEQ State Superfund FSP to implement assessment of on- and off-site soils for metals and VOCs referencing Interstate Technology Regulatory Council ISM. The ISM protocol would be used to assess risk to nearby human health and sensitive environmental receptors and to support a potential removal action. Results were compared to TRRP action levels.

Groundwater Sampling & Reporting, Chemical Waste Management, Port Arthur, Texas. 2022. *Environmental Scientist*. Conducted quarterly groundwater monitoring activities for a closed hazardous waste landfill facility. Sampling included groundwater collection at approximately 30 site monitoring wells for VOCs and arsenic.

Gem Dandy 14 Phase I Environmental Site Assessment, Texas Commission on Environmental Quality Brownfields Program, Hamilton, TX. 2022 – 2023. *Project Manager.* Conducted a Phase I ESA for the TCEQ Brownfields Program in accordance with ASTM Standard Practice E1527-21. Oversaw completion of a geophysical survey implementing GPR and electromagnetic mapping to confirm the presence of a UST. Conducted removal of one 12,000-gallon UST and associated infrastructure. Prepared and submitted a report in accordance with TCEQ Regulatory Guidance (RG) 411 documenting removal and restoration activities.

IWC Winters Landfill, Texas Commission on Environmental Quality Superfund Site Discovery and Assessment Program, Orange, TX. 2022 – 2023. *Project Manager.* Designed and conducted initial assessment of this former industrial waste landfill that had become partially submerged and had a history of fires near Adams Bayou in Orange, TX. Sampling of soil, sediment, groundwater, and surface water was conducted for VOCs, SVOCs, organochlorine and organophosphorus pesticides, metals, PCBs, dioxins/furans, and PFAS. Prepared the assessment report including technical data review in accordance with the TCEQ Quality Assurance Project Plan and applicable EPA guidance for all media and analytes.

Former Frank Ortiz Landfill, City of Santa Fe Environmental Services Division, NM. 2021 – 2023. *Environmental Scientist*. Prepared Stage 1 Abatement Plan Quarterly Monitoring Reports detailing ongoing monitoring efforts at the site including soil vapor sampling, groundwater monitoring, and landfill gas monitoring.

Rockwool Industries Federal Superfund Site, Texas Commission on Environmental Quality, Bell County, TX. 2018 – 2023. *Project Manager.* Conducted annual groundwater monitoring and semi-annual site inspections, provided oversight for site maintenance, and drafted the annual reports including potentiometric surface and isoconcentration maps, documenting all site activities, and providing conclusions and recommendations for future site activities.

Calhoun and Griggs Soil Assessment, Texas Commission on Environmental Quality, Houston, TX. 2022. *Project Manager.* Designed and conducted a soils assessment for metals and prepared a report documenting the findings.

Magic Tunnel Geophysical Survey, Texas Commission on Environmental Quality Brownfields Program, Texarkana, TX. 2022. *Project Manager*. Oversaw the completion of a geophysical survey implementing GPR and electromagnetic mapping to determine the presence of suspected USTs.

Former Nursing Home Phase I Environmental Site Assessment, Texas Commission on Environmental Quality Brownfields Program, Hamilton, TX. 2022. *Project Manager.* Conducted a Phase I ESAs for the TCEQ Brownfields Program in accordance with ASTM Standard Practice E1527-21.

Kirtland Air Force Base Environmental Baseline Surveys, Albuquerque Bernalillo County Water Utility Authority, NM. 2020 – 2022. *Environmental Scientist.* Authored and certified two Environmental Baseline Survey (EBS) Reports to meet appropriate property due diligence practices for the easement between Albuquerque Bernalillo County Water Utility Authority (ABCWUA) and Kirtland Air Force Base (KAFB), in accordance with Air Force Instruction 32-7066. The property locations included a 5.29-mile-long easement and a 24-acre parcel, all located on KAFB and Department of Energy property. The project included installing an interceptor pipeline and booster station by ABCWUA, with INTERA responsible for all federal due diligence requirements associated with construction projects occurring on federal facilities. Air Force EBS reports are generally comparable to an environmental due diligence report (Phase I ESA) but also include National Environmental Policy Act review, including cultural natural/biological resource review. Updated the sewer interceptor line easement in February 2022. The EBS reports were approved by the ABCWUA and KAFB in 2022.

Former Santa Fe Generating Station, Public Service Company of New Mexico, Santa Fe County, NM. 2018 – 2022. *Environmental Scientist*. Provided data review services of laboratory analytical and field and laboratory quality assurance/quality control for periodic groundwater monitoring. Reviewed figures and tables and created contaminant trends time series data visualizations with Grapher™ software for quarterly progress reporting (2019-2022). Conducted groundwater monitoring (2021) for VOCs and nitrate/nitrite utilizing piston driven Bennett Pump. Conducted a detailed review of historical aerial photographs for evidence of potential sources to petroleum contamination at the site. Drafted a report including a detailed spatiotemporal summary of findings with correlation to historical documentation.

South State Highway 16, Texas Commission on Environmental Quality Superfund Site Discovery and Assessment Program, San Antonio, TX. 2021. *Project Manager.* Designed and conducted a Superfund Site Discovery and Assessment Program (SSDAP) Eligibility Sampling groundwater assessment in the vicinity of a former illegal dump site used by a pesticide applicator to assess impacts to nearby human health receptors at target sole source water wells.

Airline & Aldine, Texas Commission on Environmental Quality Superfund Site Discovery and Assessment Program, Houston, TX. 2021. *Project Manager.* Designed and conducted a State Screening groundwater assessment in the vicinity of a former public water supply well with chlorinated solvent contamination to assess impacts to human health receptors at target sole source water wells.

Elm Street Phase I Environmental Site Assessments, Texas Commission on Environmental Quality Brownfields Program, Texarkana, TX. 2021. *Environmental Scientist.* Conducted two Phase I ESAs for the TCEQ Brownfields Program in accordance with ASTM Standard Practice E1527-13.

Site Investigation of Former Drilling Fluids Disposal Pit, Mo-Vac Service Company, Alice, TX. 2021. *Environmental Scientist.* Conducted a site investigation of a former drilling fluids disposal pit pursuant to an RRC letter to INTERA's client. Conducted a pump test to properly classify the groundwater and conducted groundwater sampling.

Covenant Testing Technologies Railroad Commission of Texas Pit Closure, Covenant Testing Technologies, Midland, TX. 2021. *Environmental Scientist*. Conducted sampling event to close an in-ground steel tank and wash pads that were used to collect hydrocarbon contaminated equipment wash water. Assisted in preparing submittal to the RRC documenting that the site met RRC closure criteria.

Wally's Flying Service Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Uvalde County, TX. 2020. *Environmental Scientist.* Prepared the site-specific health and safety plan (SSHASP) and FSP. Conducted field event including groundwater sampling for SVOCs by method 8270E, organochlorine pesticides by method 8081B, and organophosphorus pesticides by method 8141B. Target contaminants of concerns, glyphosate and endothall, were also sampled and analyzed via EPA drinking water methods 547 and 548.1, respectively. Prepared the final SSDAP Letter Report documenting sampling and comparing analytical results to TRRP PCLs.

G&L Spraying Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Tom Green County, TX. 2020 – 2021. *Project Manager.* Designed and conducted a State Screening groundwater assessment in the vicinity of a former pesticide applicator with a history of releases to the ground surface to assess impacts to human health receptors at target sole source water wells. Conducted groundwater sampling for metals (primarily arsenic) and SVOC pesticides pendimethalin and trifluralin.

Jain Lane / Govalle Soil Vapor Assessment and Vapor Intrusion Mitigation Assistance, Cesar Chavez Foundation, Austin, TX. 2019 – 2021. *Environmental Scientist.* Prepared an updated FSP to conduct soil vapor assessment for a proposed multi-unit residential development. Conducted soil vapor sampling to assess soil vapor impacts from hydrocarbon-affected groundwater from an adjoining, upgradient site. Prepared a Limited Phase II Report for soil vapor assessment concluding potential risk of vapor intrusion to the proposed development and provided recommendations for a vapor barrier system to mitigate potential impacts. Provided mitigation design assistance during the planning stages for construction. Provided certified third party inspection during vapor barrier and venting system installation for a multi-tenant residential complex. Provided final report documenting mitigation effort to satisfy requirements to obtain financial assistance.

Former First Baptist Church, University of New Mexico, Albuquerque, NM. 2020. *Environmental Scientist.* Prepared and submitted a Phase I ESA Report in accordance with ASTM Standard Practice E1527-13. Reviewed available historical records evaluated site visit findings to identify, to the extent possible, any RECs, as defined by ASTM. The Subject Property consisted of mixed use educational, residential, and creative space development. The development is in a highly developed area of Albuquerque and is also immediately south of a chlorinated solvent groundwater plume that is part of a federal superfund site on the national priority list.

Hospital Drive, Anchorum St. Vincent c/o Colliers International, Santa Fe, NM. 2020. *Environmental Scientist.* Prepared and submitted a Phase I ESA Report in accordance with ASTM Standard Practice E1527-13. Reviewed available historical records evaluated site visit findings to identify, to the extent possible, any RECs, as defined by ASTM. The Subject Property consisted of an outpatient medical facility in a mixed commercial and residential area.

Oltorf Street Phase I Environmental Site Assessment, City of Austin, TX. 2020. *Environmental Scientist*. Prepared and submitted a Phase I ESA Report in accordance with ASTM Standard Practice E1527-13. Reviewed available historical records conducted site visit to identify, to the extent possible, any RECs, as defined by ASTM. The Subject Property consisted of a 2.57-mile corridor through commercial and residential areas for a proposed reclaimed water main project.

Loco Ocho Hydrogeologic Assessment, Confidential Client, Wimberly, TX. 2020. *Environmental Scientist*. Conducted groundwater sampling at a private water supply well to establish baseline water quality.

Frank's Conoco, New Mexico Environmental Department Petroleum Storage Tank Bureau, Las Cruces, NM. 2020.
Environmental Scientist. Prepared Groundwater Monitoring Report for a petroleum hydrocarbons release site where INTERA gauged depth to water/light non-aqueous phase liquid (LNAPL) collected groundwater samples. Groundwater was analyzed for VOCs. Reporting included calculating and graphically depicting the groundwater gradient and potentiometric surface. Analytical results were compared to New Mexico Water Quality Control Commission (NMWQCC) standards.

Highway Texaco, New Mexico Environmental Department Petroleum Storage Tank Bureau, Las Cruces, NM. 2020.
Environmental Scientist. Prepared a work plan and cost estimate to conduct a single groundwater monitoring event including monitoring well gauging, sampling, and analysis for dissolved iron and manganese, and VOCs. Analytical results were compared to NMWQCC standards. The sampling monitored petroleum hydrocarbon contaminants in groundwater associated with releases from a former gasoline service station.

Corrales Chevron, New Mexico Environmental Department Petroleum Storage Tank Bureau, Corrales, NM. 2020.
Environmental Scientist. Prepared a work plan and cost estimate to conduct a semi-annual groundwater monitoring at an active gasoline service station with historical releases from the former operations of a preceding service station. The scope of work for this project included monitoring petroleum hydrocarbon contamination in groundwater from a series of 10 monitoring wells and from six nearby water supply wells (i.e., wells with a sealed wellhead). Analytical results of sampling conducted for VOCs were compared to NMWQCC standards.

Caldwell Motor Company, New Mexico Environmental Department Petroleum Storage Tank Bureau, Belen, NM. 2020.
Environmental Scientist. Prepared a work plan and cost estimate to conduct a semi-annual groundwater monitoring at a

former gasoline service station with a historical presence of LNAPL and an undefined dissolved phase contaminant plume. The sampling monitored the contaminant plume from the existing four monitoring wells and compared analytical results to NMWQCC standards.

Old Exxon Jobber Site, Texas Commission on Environmental Quality, San Patricio County, TX. 2019 – 2020. *Environmental Scientist.* Conducted site reconnaissance and scoping meeting with TCEQ to facilitate preparation of the FSP for tank removal activities and release determination sampling. Prepared FSP in accordance with TCEQ Regulatory Guidance 411 (RG-411) to conduct permanent tank removal activities for two registered 22,000-gallon USTs, and all associated components, and to conduct confirmation and surface release assessment. Conducted field oversight for removal of the tanks and collected confirmation samples for petroleum hydrocarbon contaminants including benzene, toluene, ethylbenzene, xylenes (BTEX), methyl-tert butyl ether (MTBE) via EPA Method 8260/5035, polycyclic aromatic hydrocarbons (PAHs) via EPA Method 8270D, and TPH via TCEQ Method 1005. Prepared and submitted a Release Determination Report in accordance with applicable standard (TCEQ-00621)

Union Pacific Rail Yard, Texas Commission on Environmental Quality, Cameron County, TX. 2019. *Environmental Scientist*. Conducted a Phase I ESA and prepared and submitted a Phase I ESA Report in accordance with ASTM Standard Practice E1527-13. Reviewed available historical records and conducted a site visit to identify, to the extent possible, any RECs, as defined by ASTM. The Subject Property consisted of approximately 25.5 acres of land within an urban mixed residential and commercial industrial area that was formerly a train depot and railway switchyard.

Texaco Building, Texas Commission on Environmental Quality, Cameron County, TX. 2019. *Environmental Scientist.* Conducted a Limited Phase II ESA in which 8,000-gallon steel tank and one 12,000-gallon steel tank and associated piping and conducted sampling and analysis in accordance with TCEQ RG-411. Collected confirmation samples for petroleum hydrocarbon contaminants including BTEX, MTBE via EPA Method 8260/5035, PAHs via EPA Method 8270D, and TPH via TCEQ Method 1005. Prepared and submitted an Release Determination Report in accordance with applicable standard (TCEQ-00621).

City of Hondo Landfill Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Medina County, TX. 2019. *Environmental Scientist.* Prepared the SSHASP and FSP. Conducted field event including groundwater sampling for metals, VOCs, SVOCs, and PCBs. Prepared the final SSDAP Letter Report documenting sampling and comparing analytical results to TRRP PCLs.

Russell Flying Service Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Medina County, TX. 2019. *Environmental Scientist.* Prepared the SSHASP and FSP. Conducted field event including groundwater sampling for metals including hexavalent chromium, SVOCs, VOCs, pesticides, and herbicides. Prepared the final SSDAP Letter Report documenting sampling and comparing analytical results to TRRP PCLs.

The Word Church Phase II Environmental Site Assessment, Texas Commission on Environmental Quality, Bexar County, TX. 2019. *Environmental Scientist.* Provided oversight of drilling via solid stem auger and installation of a monitoring well. Conducted well development and collected a representative groundwater sample via low-flow technique.

Sand Hill Energy Center Release Assessment in Support of Affected Property Assessment Report, City of Austin, TX. 2019. *Environmental Scientist.* Provided oversight for hydro-vac to clear utilities down to six feet at the facility, drilling via hollow-stem auger, and installing and developing three monitoring wells. Collected soil and groundwater samples for analysis of TPH and PAHs. Assisted in preparing an affected property assessment report for submission to TCEQ.

Mineral Wool Insulation Manufacturing Company Proposed State Superfund Site Additional Offsite Evaluation in Support of Remediation, Texas Commission on Environmental Quality, Bell County, TX. 2018 – 2019. *Environmental Scientist.* Conducted detailed overland migration characterization and subsurface sediment sampling using a gravity core sampling device deployed from a boat. Drafted report documenting field activities and providing comprehensive descriptions of the migration pathway with estimation of anticipated volumes for removal based on impacted soils above site specific ecological PCLs. Also collected agricultural samples for nutrient analysis to determine the viability and practicality of repurposing on and offsite soils in the design of a containment cell cap with effective vegetative growth.

Schumann Property Petroleum Storage Tank Removal and Brownfields Site Assessment, Texas Commission on Environmental Quality, Concho County, TX. 2018. *Environmental Scientist.* Prepared the FSP based on TCEQ Regulatory Guidance RG-411. Implemented the FSP including oversight of PST removal (550-gallon "ghost tank"), conducted field screening and

confirmation sampling. Prepared the Release Determination Report documenting removal activities and analytical results with respect to PST Action Levels.

Hamlin Municipal Development District Phase I Environmental Site Assessment, Texas Commission on Environmental Quality, Jones County, TX. 2018. *Environmental Scientist.* Conducted the Phase I ESA site reconnaissance to identify and document RECs.

West Texas Phase I Environmental Site Assessment, Confidential Client, Loving County, TX. 2018. *Environmental Scientist.* Provided historical document review and drafted the historical portion of the Phase I ESA Report for approximately 50 square miles of property in accordance with Standard Practice E2247-16 of ASTM International.

Medical Drive Groundwater Plume Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Bexar County, TX. 2018. *Environmental Scientist.* Conducted groundwater sampling at public and domestic drinking water wells for PCE on rapid 24-hour turnaround time (EPA Drinking Water Method 524.2) and drafted the report to document the release and impacts to receptors in the critical pathway of exposure to facilitate Hazard Ranking System scoring.

South Austin Regional Wastewater Treatment Plant Phase I Environmental Site Assessment, City of Austin Public Works, TX. 2018. *Environmental Scientist*. Conducted the Phase I ESA historical document review and site reconnaissance to identify and document RECs.

The Word Church Phase II Environmental Site Assessment, Texas Commission on Environmental Quality, Bexar County, TX. 2018. *Environmental Scientist*. Provided oversight of environmental borehole drilling with direct push technology for the collection of soil samples to a depth of 15 feet. Assisted in lithological logging, field screened and sampled for VOCs or petroleum products. Drafted the Phase II ESA Report. Work was conducted in accordance with Standard Practice E1903-11 of ASTM International. Provided oversight of drilling via solid stem auger and installation of a monitoring well. Conducted well development and collected a representative groundwater sample via low-flow technique.

Cass County Treating Company State Superfund Site Immediate Removal Action, Texas Commission on Environmental Quality, Cass County, TX. 2016 – 2017. *Project Manager*. Coordinated and provided oversight for removal of soils affected with pentachlorophenol and dioxins/furans at a residential property. The scope of the project included air sampling for the development of protective particulate monitoring action levels, confirmation sampling via ISM including development of a pentachlorophenol screening level concentration indicative of dioxins/furans concentrations as a screening tool, and site restoration.

North Andrews Highway Health and Safety Plan and Preliminary Assessment, U.S. Environmental Protection Agency, Ector County, TX. 2016 – 2017. *Project Manager*. Developed the site health and safety plan. Authored the preliminary assessment report based on research and available site information, including consolidating and analyzing historical site knowledge and analytical data, describing the geologic setting and aquifer characteristics, evaluating major migration and exposure pathways, and producing figures and tables.

Harvey Industries State Superfund Site, Texas Commission on Environmental Quality, Henderson County, TX. 2016 – 2017. *Project Manager*. Coordinated and oversaw operations and maintenance activities at the site including soil gas monitoring and cap inspection/maintenance.

First Quality Cylinders State Superfund Site, Texas Commission on Environmental Quality, Bexar County, TX. 2014 – 2017. *Assistant Project Manager and Project Manager.* Coordinated and provided oversight for the continuous removal of affected groundwater contained behind a slurry wall from on-site extraction wells. Reviewed engineering documents and assisted in project management for the implementation of the final remedy which included groundwater remediation via direct push in-situ chemical reduction of hexavalent chromium in the shallow groundwater bearing unit and the installation of a continuous onsite pump and treat system. Managed operations and maintenance activities for the on-site treatment system.

Jerrell B Thompson Battery State Superfund Site, Texas Commission on Environmental Quality, Van Zandt County, TX. 2013 – 2017. *Project Manager.* Conducted annual inspection to ensure site controls for waste remained undisturbed and in good condition as part of operations and maintenance activities.

JCS Company State Superfund Site, Texas Commission on Environmental Quality, Van Zandt County, TX. 2013 – 2017. *Project Manager.* Coordinated and provided oversight for annual operations and maintenance activities at the site including cap inspection and maintenance as well as groundwater monitoring activities.

Deepwater Horizon RESTORE Act Proposal Evaluations, Texas Commission on Environmental Quality Natural Resource Damage Assessment, Austin, TX. 2016. *Evaluator.* Was selected to be part of a six-member interdisciplinary committee that evaluated more than 200 proposals requesting funds allocated to the state by the RESTORE Act for the Deepwater Horizon oil spill.

Schaefer Road Drum Immediate Removal Action, Texas Commission on Environmental Quality, Bexar County, TX. 2016. *Project Manager.* Coordinated and provided oversight for HAZCAT classification, removal, and proper disposal of abandoned bulk and containerized wastes, and affected site soils. Authored legal documents for cost recovery.

Methodist Hospital Health and Safety Plan and Preliminary Assessment, U.S. Environmental Protection Agency, Bexar County, TX. 2016. *Project Manager*. Developed the site health and safety plan. Authored the preliminary assessment report based on site reconnaissance, research, and available site information including consolidating and analyzing historical site knowledge and analytical data, describing the geologic setting and aquifer characteristics, evaluating major migration/exposure pathways, and producing figures and tables.

Highway 18 Groundwater Plume Expanded Site Investigation, U.S. Environmental Protection Agency, Winkler County, TX. 2016. *Field Project Manager.* Responsible for the field event, which included coordination and sampling of soils at potential source locations and sampling sole source water wells for evaluation of impact to human health receptors in the groundwater migration pathway.

Lane Plating Works Site Investigation, U.S. Environmental Protection Agency, Dallas County, TX. 2016. *Field Project Manager*. Acted as Project Manager for the field event, which included identifying representative sampling locations in the field and sampling of soils, sediments, and surface water.

Southwestern Plating Works Immediate Removal 2015, Texas Commission on Environmental Quality, Lubbock County, TX. 2015 – 2016. *Project Manager*. Coordinated and provided oversight for the classification, removal, and proper disposal of abandoned plating vats and containerized wastes. Conducted SSDAP state screening activities, including soil and groundwater sampling and analysis and authored legal documents for cost recovery.

Ector Drum Site Investigation, U.S. Environmental Protection Agency, Ector County, TX. 2015 – 2016. *Project Manager*. Conducted the field effort, including sampling of residential and commercial sole source groundwater wells. Analyzed the collected groundwater data, compared data to EPA Maximum Concentration Levels, and authored the final technical report.

Absolute Fuels Superfund Site, Texas Commission on Environmental Quality, Lamb County, TX. 2015. *Project Manager*. Coordinated and provided oversight for the assessment and investigation of impact to human health receptors via the groundwater pathway and the completion of the final Removal Action Report. Authored legal documents, including a property lien for cost recovery.

Industrial Waste Control Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Orange County, TX. 2015. *Project Manager*. Coordinated and provided oversight for the assessment and investigation of impact to human health receptors in the groundwater migration pathway. Analyzed and compared data to TRRP PCLs to provide conclusions and site recommendations.

Browning Ferris Industries Landfill Superfund Site Discovery and Assessment Program Site, Texas Commission on Environmental Quality, Orange County, TX. 2015. *Project Manager.* Coordinated and provided oversight for the assessment and investigation of impact to human health receptors in the groundwater migration pathway. Analyzed data, compared data to TRRP PCLs, and provided conclusions and site recommendations.

Lonesome Trail Site Investigation, U.S. Environmental Protection Agency, Bexar County, TX. 2014. *SI Team Member*. Conducted soil and groundwater sampling to assist in the completion of the Site Investigation.

River City Metal Finishing Superfund Site, Texas Commission on Environmental Quality, Bexar County, TX. 2014. *Project Manager.* Conducted closeout activities, including authoring legal documents and notices including a restrictive covenant and property lien.

Battery Recyclers of Houston Superfund Site, Texas Commission on Environmental Quality, Brazoria County, TX. 2014. *Project Manager.* Coordinated and provided oversight for the assessment and investigation of impact to human health receptors in the groundwater and soils migration pathways. Analyzed data, compared data to TRRP protective concentration levels, and provided conclusions and site recommendations.

Sampling of Vegetation Transects in the Okavango Delta, Dr. Kelley Crews and Dr. Thoralf Meyer, Undergraduate Research, Botswana, Africa. 2012. *Field Research Assistant.* Conducted sampling in remote parts of Botswana, Africa as part of a ground truthing effort for remotely sensed data. Responsibilities included gathering data using high resolution spectral imagery as well as identifying and measuring woody vegetation across ecological regimes. Applied data gathered for analyzing carbon sequestration in above ground woody biomass using the allometric relation of basal area to biomass.

Project Experience – Water Resources

Vertical Flow Profiling for Production Well, Porter Special Utility District, TX. 2021. *Environmental Scientist.* Provided oversight for "lift and shift" and ultimately the complete removal and reinstallation of a 560 ft, 10-inch pump column. Conducted vertical flow profiling utilizing BESST's upgraded and proprietary version of the U.S. Geological Survey tracer flowmeter and targeted depth interval groundwater sampling using the BESST HydroBooster sampling pump. Analytes included hydrogen sulfide (H2S), adenosine triphosphate (ATP), sulfate reducing bacteria (SRBs), iron reducing bacteria (IRBs), dissolved sulfide, total sulfides, total iron, total organic carbon, methane, chloride, sodium, oxidation/reduction potential (ORP), and specific conductivity. Field testing was also performed including H2S, ORP, dissolved oxygen (DO), pH, temperature, turbidity, and specific conductivity. Wellhead samples were also collected, representing blended composites of zonal chemical mass contribution from each contributing flow interval.

Evangeline Laguna Borehole Surveys and Pump Testing, Confidential Client, San Patricio County, TX. 2020. *Environmental Scientist*. Performed video surveys of wells to determine conditions and screened intervals. Conducted oversight of pump removal and installation and 36-hour pump tests in three wells with In-Situ Trolls and WinSitu software while obtaining manual water level and flow measurements. Collected water samples to analyze water chemistry before, during, and after pump tests.

Dynamic Flow and Water Chemistry Profiling, West Harris County Municipal Utility District, Houston and Katy, TX. 2020. *Environmental Scientist.* Conducted downhole investigation at two public water supply wells to: (1) measure zonal flow contribution within the well under steady-state pumping conditions; (2) characterize zonal chemical contribution of arsenic, iron, and exsolved methane; and (3) determine viable economical options to physically modify the well screen to reduce or eliminate treatment for arsenic and iron and to mitigate methane influx. Conducted dynamic flow profiling to calculate zonal flow contributions over hundreds of feet of intermittently perforated well screen by injecting rhodamine dye at discrete depth intervals and measuring peak return rates at the surface via fluorometer. Conducted depth-dependent groundwater sampling to characterize zonal chemical contribution.

New Braunfels Utilities Aquifer Storage and Recovery Monitoring, ARCADIS, New Braunfels, TX. 2020. *Environmental Scientist.* Provided oversight for drop pipe and transducer installation at monitoring wells supporting aquifer storage and recovery monitoring.

Constant Rate Test for Turtle Creek No. 3 Pump Station, San Antonio Water System, Bexar County, TX. 2019. *Environmental Scientist.* Provided oversight for the constant rate test at 7,000 gallons per minute.

El Dorado Sand Mine Water Supply Wells Development and Performance Analysis, Black Mountain Sand, Winkler County, TX. 2019. *Environmental Scientist.* Provided well development (bailing and airlifting) and pump installation oversight, including water quality monitoring; conducted step drawdown tests to assess supply well performance; and collected aquifer test data for four wells using water level meters and multiple transducers. Collected data using In-Situ Trolls and WinSitu software.

Observation Well Drilling Oversight and Sampling - Oversight for Vertical Flow Profiling for Production Well, Confidential Client, San Patricio County, TX. 2018 – 2019. *Environmental Scientist.* Provided oversight for well drilling activities of observation well to depth greater than 1,000 feet bgs and collected mud rotary cuttings samples for sieve analysis. Provided oversight for BESST, Inc. implementing their ambient flow profiling service using the DyeTracer system developed by the U.S. Geological Survey.

Bigfoot Sand Mine Water Supply Well Installation, Turnkey Processing Solutions, Atascosa County, TX. 2018. *Environmental Scientist.* Provided well drilling and installation oversight. Logged drilling cuttings, conducted step drawdown tests, and collected aquifer test data using water level meters and multiple transducers.



Joseph Tracy, PG

Principal Geologist | Senior Vice President

Years of Experience: 31

Education:

- BS, 1993, Environmental Geology, Ohio University

Professional Registrations/Affiliations:

- Professional Geologist, AZ, 2003, No. 38741
- Professional Geologist, TN, 1999, No. TN4417
- Professional Geologist, TX, 2013, No. 11588

Professional History:

2000 – Present	Senior Vice President, Principal Geologist – INTERA Incorporated, Albuquerque, NM
1999 – 2000	Environmental Specialist – GeoTek Insite, Albuquerque, NM
1997 – 1999	Staff Geologist – Professional Services Industries, Inc. (PSI), Cleveland, OH
1994 – 1997	Staff Geologist – Terranext, Inc., Denver, CO

Training:

- OSHA Health and Safety Training, 29 CFR 1910.120, (40-Hour), 1994
- OSHA Health and Safety Training, Annual Refresher, (8-Hour), current
- DOT HM 126 Hazardous Material Transportation Training, 49 CFR 172.700, 1996
- Confined Space Entry Training, 29 CFR 1910.140, 1995
- National Ground Water Association – Fate and Transport of Light Non-Aqueous Phase Liquids/Dense Non-Aqueous Phase Liquids (LNAPLs/DNAPLs) Training, 1995
- Asbestos Inspector and Management Planner (Toxic Substance Control Act Sec. 206, Title II) Training, 1997
- Asbestos Contractor Supervisor (Toxic Substance Control Act Title II and AHERA) Training, 2000
- Vapor Intrusion Training, 2011
- Red Cross First Aid/CPR Training, current
- Sulfuric Acid Handling Training, 2013
- Interstate Technology Regulatory Council (ITRC) Training – Vapor Intrusion Pathway: Investigative Approaches for Typical Scenarios (2008)

Joseph "Joe" Tracy is a Principal Geologist and Senior Vice President at INTERA with a BS degree in environmental geology and over three decades of consulting experience focused on environmental assessments, site investigations, remedial planning, and site remediation. He has evaluated the environmental impacts to soil and groundwater at leaking petroleum storage tank (PST) sites, Superfund sites, Brownfield sites, and a variety of operational and former industrial properties and facilities. Mr. Tracy leads multidisciplinary teams of scientists and engineers to complete investigations and remediation of contaminants that include petroleum hydrocarbons, heavy metals, chlorinated solvents, polychlorinated biphenyls (PCBs), per- and polyfluoroalkyl substance (PFAS), and asbestos. He develops remedial plans under voluntary remediation and Superfund programs and prepares and implements work plans, quality assurance project plans, and remedial action plans for Brownfields and other redevelopment projects. Mr. Tracy's experience also includes performing investigations and related work at municipal landfills where activities have included the installation and monitoring of landfill gas (LFG) probes, preparing landfill management plans, operation and maintenance of LFG extraction/destruction systems, developing and implementing grading and drainage plans, and profiling the nature and extent of landfill wastes. Mr. Tracy is a Senior Vice President within INTERA's Southwest Region, where he oversees multi-site contracts with state, county, and municipal agencies, and is responsible for directing all environmental services marketing efforts within the INTERA Mining and Environmental Line of Business Unit.

Project Experience – Environmental

Santa Fe County Investigation of Per- and Polyfluoroalkyl Substance Contaminants in Domestic Wells, Santa Fe County, NM. 2024 – Present.

Project Manager. Santa Fe County The sampling and analysis of drinking water in October 2023 from six domestic wells within the communities of La Cienega and La Cieneguilla, Santa Fe County discovered PFAS at concentrations above the safe drinking water standards recently established by the USEPA. Driven by the health concerns related to this discovery, the County, in collaboration with the New Mexico Environment Department (NMED) Construction Programs Bureau (CPB) and the City of Santa Fe, successfully acted to obtain a USEPA grant to help fund the assessment of the potential PFAS impacts to area groundwater. Mr. Tracy is leading the INTERA Team to achieve the overarching project goals of determining the extent of the PFAS contamination in groundwater and developing alternatives for mitigation and/or remediation of the contamination. Mr. Tracy is currently assisting the County with the initial project activities including the development of a conceptual site model (CSM) and selecting additional domestic wells for PFAS sampling. In addition, Mr. Tracy is working with INTERA subcontractor, John Shomaker and Associates, Inc. (JSAI), in the development of a groundwater flow model, in an effort to determine preferential flow paths for underlying PFAS contamination in ground water.

Environmental Investigations, City of Albuquerque – Department of Municipal Development, Albuquerque, NM. 2005 – 2018 and 2023 – Present. *Contract Manager and Project Manager.* Contract Manager City of Albuquerque Department of Municipal Development Environmental On-Call Services contract. Performed Phase I and Phase II Environmental Site Assessments (ESAs) for the City of Albuquerque (COA) as part of this contract. In addition, provided environmental assistance to the COA Department of Municipal Development on an as-needed basis as project environmental issues develop. Environmental issues included extraction well evaluation at the former Los Angeles Landfill, maintenance and monitoring services at the former Los Angeles Landfill, geophysical investigations in the downtown Albuquerque area, micro-turbine analysis at the former Los Angeles Landfill, engineering evaluation/cost analysis (EE/CA) for the Hotel La Posada del Albuquerque, conducting a soil vapor survey at the City of Albuquerque 1st and Central Site which is located adjacent to the former BNSF East Bound Fueling Facility, ambient air monitoring within residential houses in the Albuquerque area, and asbestos and lead-based paint surveys at several city facilities (i.e., Los Duranes Community Center, Jeanne Bellamah Community Center, Holiday Park Community Center, Barelas Community Center, Mesa Verde Community Center, APD Education Building, Dennis Chavez Community Center, Rio Grande Fire House, Pino Yard Senior Games Building, North Valley Senior Center, Palo Duro Senior Center, Environmental Health Department offices), city-owned former historic hotels (El Vado and De Anza), and city-acquired properties (Brown Property, Caravan Building, Loan Pawn Shop). Facilitated on-call projects such as the development of a CSM for the Kirtland Air Force Base Fuel Spill, development of a voluntary remediation approach for at the Marble-Arno Property and the downtown Railyard, locating a new COA storm water facility, conducting an archaeological survey at the Singing Arrow Community Center, and several landfill maintenance projects for the COA Solid Waste Division Cerro Colorado landfill. Currently projects for the COA include the assessment of asbestos and lead-based paint in several buildings at the COA BioPark (Zoo), which is undergoing a full-scale remodeling and renovation, as well as continuing groundwater monitoring activities at the Marble-Arno Property under the Voluntary Remediation Program (VRP). Secured an additional environmental services on-call contract with the COA in late 2023 and work began in 2024. Mr. Tracy is currently leading the environmental surveys associated with the renovation of the COA Gibson Health Hub (GHH) and several COA community centers and libraries.

Santa Fe Well-S (Santa Fe Generating Station) Petroleum Storage Tank Investigation, Public Service Company of New Mexico, Santa Fe, NM. 2018 – Present. *Project Principal.* Providing contract support for the investigation of fuel and chlorinated solvent release at a former power generating station and other, off-site sources. The release(s) have impacted a City of Santa Fe municipal supply well, causing production of drinking water from this well to be discontinued. The investigation includes the installation of 25 monitoring wells to depths ranging from approximately 300 to over 400 feet using roto-sonic drilling and sampling techniques. Portable gas chromatography and a photoionization detector are being used to analyze soil and groundwater samples in the field so that contaminated zones can be identified, and real-time, informed decisions can be made concerning screen intervals. The results of the in-field screening have identified zones, some as thin as three feet, containing mobile light non-aqueous phase liquid (LNAPL) and conveying highly contaminated groundwater. Responsibilities have included contract and technical discussions with the client and project team as well as attending several scoping and status meetings with Public Service Company of New Mexico, the City, and NMED representatives. In addition to providing support of environmental services associated with the fuel plume, also reviewing efforts associated with State 1 abatement plan (S1AP) investigations regarding chlorinated solvents and nitrates contamination present in ground water at the site.

Hop Canyon/Waldo Mill Site Phase II Site Investigation and Voluntary Remediation Program Activities, ASARCO, Magdalena, NM. 2000 – 2002 and 2018 – Present. *Project Principal, Project Manager, and Staff Geologist.* Implemented a Work Plan to characterize an American former Smelting and Refining Company (ASARCO) mining mill tailings site in Magdalena, New Mexico. The voluntary remediation activities included characterization and removal of affected soil and construction of an onsite tailings impoundment capped with clean soil. Surface drainage issues included interfacing with the U.S. Army Corps of Engineers to present erosion of the impoundment cap and surrounding soils. Initiated additional work at this site on behalf of the ASARCO Trust in 2018. INTERA is currently responsible for Site Caretaker Operations, which are essentially weekly Site visits to make certain the tailings impoundment cover remains in good condition. INTERA will prepare a VRP Work Plan to guide the repair work of the tailing impoundment cover. NMED and/or the ASARCO Trust identified several areas of the tailings impoundment cover in 2017 that are recommended for repair. The remainder of the ASARCO property at the site was legally transferred into ASARCO Trust ownership in late 2023. Currently working with ASARCO Trust representatives and the INTERA Project Team to design and conduct cap repair activities and secure a VRP Conditional Certificate of Completion (CCOC).

Las Vegas Patrol Yard Groundwater Remediation System Operation and Maintenance, New Mexico Department of Transportation, Las Vegas, NM. 2017 – Present. *Project Principal.* Began operation and maintenance (O&M) activities of a groundwater remediation system associated with the two contaminant plumes: an inorganic (chloride and total dissolved solids [TDS]) plume and organic (petroleum and chlorinated compound) plume located at the New Mexico Department of Transportation (NMDOT) Las Vegas Patrol Yard. The groundwater remediation system was originally operated by another firm but due to performance issues INTERA was asked to conduct O&M activities at the site. The groundwater remediation system consists of five interceptor trenches (four of the trenches focus on capturing the inorganic and petroleum plume and one focuses on capturing the chlorinated solvent plume) which capture contaminated groundwater and convey the water to two treatment containers. The treatment system consists of a filter media capable of removing iron and manganese, an air stripper which targets volatile organic compounds (VOCs), and reverse osmosis (RO) membranes which removes TDS and chlorides. The treated groundwater is reinjected into the subsurface via three infiltration trenches. Monthly influent and effluent samples are collected from the groundwater remediation system to ensure the system is operating effectively and that the effluent water quality meets the approved discharge permit requirements. O&M activities include maintaining all parts (pumps, inline sensors, filters) of the system, monitoring the dosing rate of the system additives (sodium hypochlorite, sodium metabisulfite, caustic soda, and anti-scaling agent), analyzing field water quality parameters/compounds (pH, TDS, free chlorine, total iron, total manganese) using handheld meters or Hach kits, replacing filters, monitoring system pressures, maintaining adequate additive volumes in vessels, and performing high- and low-pH cleaning of the RO membranes when necessary. The data collected during O&M activities and recorded remotely using a programmable logic controller is tracked and analyzed on a weekly basis to make sure the system is operating as designed. Treatment system operation has been suspended in recent years due to a discharge permit issue, but are estimated to be re-started in 2024.

Investigation of the Former Frank Ortiz Landfill, City of Santa Fe, NM. 2016 – Present. *Project Manager.* The Frank Ortiz Landfill operated as a City of Santa Fe municipal landfill between 1954 to 1968. Since no solid waste management regulations were in place during this period of operation, the landfill is not regulated by the NMED Solid Waste Bureau. The landfill site was re-developed by the city with soccer fields from 1987 to 1993 and currently serves as a dog park. In April 1993, soil vapor samples were collected from the fill and soil cover areas. Laboratory analysis of the samples showed that they contained hydrocarbons, chlorinated solvents, and chlorinated solvent degradation products. Concentrations of some of the contaminants exceeded 1,000 parts per billion. A single groundwater monitoring well (Ortiz Park No. 1) was installed approximately 500 feet southwest of the landfill in 2004. A groundwater sample collected from the well indicated that groundwater had been impacted from VOCs, hydrocarbons, metals, and nitrogen believed to have originated at the landfill site. Periodic groundwater and soil vapor sampling have continued at the site since 2004. An S1AP was developed for the Site in 2010 and submitted to NMED for review and approval. In 2013, NMED issued a letter noting several deficiencies in the S1AP including: the lack of a plan for maintenance of a two-foot cap over the former landfill; inadequate definition of the nature and extent of the landfill waste; inadequate definition of contaminant concentrations in the vadose zone below the waste; inadequate definition of the potential contaminant impacts to groundwater; the lack of a long-term monitoring program; and the need for a quality assurance project plan, health and safety plan, and a schedule for implementing the additional investigation activities and analyses necessary to address the identified deficiencies.

In 2015, at the request of NMED, the City conducted a geophysical investigation to define the areal extent of buried waste at the landfill. INTERA was awarded a contract from the City in September 2016 to help address the remaining S1AP deficiencies. Helped develop and reviewed an integrated Sampling and Analysis Plan (SAP)/Quality Assurance Project Plan (QAPP) for the former landfill that was submitted to and approved by NMED. The SAP outlined several steps for the City to address the noted NMED concerns, including: installation of test pits to determine type and extent of waste; the collection of soil samples to determine the impact to soil immediately below the buried waste (extent of contamination in the vadose zone); installation of groundwater monitoring wells; groundwater sample collection; and an approach for a long-term groundwater monitoring program. Field sampling activities associated with the SAP/QAPP were completed in July 2017. Met with the NMED to go over the report findings and discuss recommendations for next steps. The investigation revealed the approximate extent and depth of buried waste, determined the extent of the vapor plume, and provided information on the landfill cover content and thickness. To address NMED's final concern, additional groundwater monitoring wells co-located with three soil vapor monitoring wells and an additional soil vapor monitoring well were recommended and the approximate locations were determined.

The additional wells were installed at the Ortiz Landfill in late 2019 and early 2020 and a final report was submitted to by INTERA to NMED in May 2020. The report findings indicated a direct impact to Site soil vapor likely from the presence of the buried waste, but it appears that Site groundwater is largely unimpacted. INTERA has successfully negotiated with NMED a period of monitoring work for the three years and includes the addition of Surface Emission Monitoring (SEM) on a quarterly basis of the entire Ortiz Landfill property (historic fill area and adjacent land within the property boundary). Once this period has expired, Mr. Tracy will work with City and NMED representatives to determine the need and location(s) for any future additional groundwater and soil vapor monitoring well installations.

The INTERA former Frank Ortiz Landfill work is being conducted in concert with additional investigation and monitoring activities at the adjacent Paseo de Vista (PDV) Landfill. The monitoring and maintenance of the PDV Landfill was added to the INTERA Ortiz Landfill contract by the City in 2019. The work at PDV has largely been conducted by personnel from INTERA's partner, Parkhill, under INTERA oversight. All PDV deliverables are prepared by Parkhill and reviewed by Mr. Tracy prior to submittal to the City and NMED. Mr. Tracy currently leads the long-term monitoring (LTM) activities at both landfills on behalf of the City and manages subcontractor Parkhill. The City of Santa Fe has requested that INTERA assist with NMED updated S1AP activities which are scheduled to begin in July 2025. This will consist of the installation of an additional ground water monitoring well, several LFG monitoring wells, and sampling ground water for PFAS in addition to the required analysis suite.

North Railroad Avenue Plume Superfund Project, New Mexico Environment Department - Groundwater Quality Bureau, Española, NM. 2016 – Present. *Project Principal*. A bio-amendment injection event was performed to remediate residual contamination (tetrachloroethene [PCE] and daughter products) in discrete intervals of fine-grained material identified in the source area (SA) and hot spot (HS) of the site. INTERA evaluated available data, identified six treatment areas, determined targeted treatment intervals, selected emulsified soybean oil as the carbon substrate, and devised an injection method to ensure that the substrate is delivered precisely. INTERA oversaw the bio-amendment substrate injection event which was conducted in two separate events: the first was completed in April 2017 via a direct-push injection tool within sonic casing and the second event was conducted with direct sonic injection in September 2017. INTERA conducted follow-up performance groundwater monitoring. Results of the performance monitoring events confirmed the successful distribution of the carbon substrate through the presence of the dye tracer (Rhodamine WT) and elevated total organic carbon (TOC) in monitoring wells within the anticipated radius of influence (ROI). Additionally, the groundwater analytical results from the first performance monitoring event provided evidence that in-situ reductive dichlorination was enhanced through the injection of the carbon substrate. Performance monitoring is currently ongoing. Serves as a Project Principal for INTERA's NMED contract, which includes INTERA's work at the NRAP site as well as INTERA's work at the Eagle Picher site in Socorro, New Mexico.

Former Central Works Equipment Facility Remediation Activities "COA Rail Yards," City of Albuquerque, NM. 2006 – Present. *Project Manager.* Managed the removal of contaminated soil at the former Central Works Equipment (CWE) facility in Albuquerque, New Mexico. The project included the removal of approximately 600 cubic yards of lead-contaminated soil previously stockpiled at the site. Developed a Work Plan to investigate petroleum-hydrocarbon and metals contamination at this site using Targeted Brownfields Assessment (TBA) funding. Led an additional Phase II investigation at the site in 2012. The Phase II investigation consisted of surface and subsurface soil sampling, building sub-slab vapor sampling, and groundwater sampling. This effort was conducted to determine what impacts (if any) the historical operations of the site as a railyard would have on future redevelopment. It was determined that a petroleum-hydrocarbon plume was present at the southwest corner of the site. Limited impacts were present in surface and subsurface soils. Developed several cost estimates for the remediation of soil and groundwater at the site for the city to use depending on the redevelopment scenario they selected. Further site investigation work was completed in 2012 as the city moved toward redevelopment of the site. Served as Project Manager for an Additional Site Investigation (ASI) that included completing a data evaluation/remediation options document to compile and analyze all existing contaminant data for the entire city railyard, which included former tank areas, oil/water separator, and a former locomotive roundhouse, among others. The evaluation resulted in identifying several data gaps which were investigated during the ASI. Contaminants of concern for this site included VOCs, TPH, PAHs, lead, and arsenic. The site investigation included (1) collecting surface soil samples from thirteen locations, (2) drilling oversight of 18 soil borings using direct push technology methods, (3) collection and screening of soils samples using a photoionization detector (PID) and Dexsil PetroFLAG field test kit to aid in selection of samples for laboratory analysis, (4) collection of eleven groundwater samples with the SP-16 sampler, temporary monitoring wells, and

existing monitoring wells, (5) installation of a soil vapor sample point, and (6) collection of a soil vapor sample using a Vapor PinTM. INTERA provided the client with a completed report, which included several remediation scenarios based on various redevelopment options.

Oversaw the remediation of the Blacksmith Shop building at the CWE facility in 2013. The remediation work consisted of the abatement of asbestos as well as the encapsulation of lead-based paint on the ceiling of the Blacksmith Shop. The Blacksmith Shop was redeveloped by COA into an open-air market following remediation activities. The redeveloped Blacksmith Shop opened in June 2013.

Worked with the COA selected developer, Samitaur, on a VRP approach for all portions of the Railyard property. This included a multi-option remediation approach as several redevelopment options (residential, commercial, open space) will be implemented at the site. Oversaw the development of a CSM for the site. INTERA compiled all available information related to environmental site conditions such as historical soil and groundwater data to help determine the nature and extent of the contamination across the site with regard to depth and COCs in the CSM to provide a foundation for remedial action decisions. Activities completed as part of the CSM included developing a database in Microsoft Access, connecting the database to ArcGIS to allow for visual data analysis, and identifying key data gaps. The CSM was also used as a foundation for development of a remediation work plan required to address data gaps at the site. The remediation work plan was developed in conjunction with potential redevelopment scenarios identified for the site. Implementation of the remediation work plan was completed early 2017 and included the collection of soil samples, soil vapor samples, groundwater samples, sub-slab soil vapor samples, and the completion of asbestos and lead-based paint surveys on all site buildings. The results of the data collection were compiled into ten different reports, one for each of the 10 railyard parcels. The intent of separate reporting for each of the 10 parcels was to allow phased development of the site over a lengthier time period than is customary under the VRP.

Contracted in late 2018 to develop a revised VRP Application and Preliminary Work Plan for the COA Rail Yards, splitting the COA Rail Yards into two VRP sites (COA Rail Yards North and COA Rail Yards South). Currently, the COA Rail Yards North has received conditional eligibility to enter the VRP and Public Notice and a Public Meeting was held in April 2019 to outline for the public the proposed remedial actions. Assisted with the Public Notice requirements for the COA Environmental Health Department personnel. The COA implemented soil removal activities within the COA Rail Yards North in May and June 2019.

Contracted in early 2020 to help the COA develop a VRCR for the COA Rail Yards North and to implement an off-Site groundwater monitoring well installation Preliminary Work Plan for the COA Rail Yards South. INTERA developed a VRCR for the COA Rail Yards North and submitted it to NMED in September 2020. INTERA also, as requested by the COA, developed, submitted to NMED, and received NMED approval for a Contaminated Soil Management Plan (SMP) in July 2020. This SMP will be followed as additional impacted soil is excavated at the COA Rail Yards. Either developed or provided final review of this documents. INTERA installed 5 ground water monitoring wells at off-site locations surrounding the COA Rail Yards South. These monitoring wells were installed in February 2021. Provided interface with the client during the field work and also provided daily direction to the INTERA field team. Finally, INTERA will work with the COA's Rail Yards management team to develop the remediation approaches for the COA Rail Yards South depending on the selected future development. Secured a VRP CCOC for the Rail Yards North in 2021. Currently leading the LTM activities associated with ground water and soil vapor at the Site and leading efforts to secure a CCOC for the Rail Yards South. In addition to LTM activities, currently providing quality assurance inspections for the installation of a soil vapor mitigation system in the Boiler Shop, prior to it's redevelopment as a movie studio for CNM (abqrailyards.com).

Technical Support Services for the Red Hill Bulk Fuel Storage Facility, Honolulu Board of Water Supply, Honolulu, HI. 2015 – Present.
Project Manager. Providing third-party technical review of technical documents and data produced and collected by the U.S. Navy and its contractors at the Red Hill Bulk Fuel Storage Facility (RHBFSF). The RHBFSF contains 20 large field-constructed underground storage tanks, each containing approximately 12.5 million gallons of fuel. These tanks are located at depths ranging from 120 to 175 feet below ground surface within the Koolau Basalt and lie 100 feet above the aquifer. Fuel leaks from the facility both historic and recent (January 2014 – 27,000-gallon release) have impacted the underlying EPA-designated Sole Source Southern Oahu Basal Aquifer and are potentially threatening the Honolulu Board of Water Supply (BWS) water supply wells and production shaft. The 2014 release resulted in the Navy, the EPA, and the Hawaii Department of Health (DOH) signing an Administrative Order on Consent (AOC) to assess the RHBFSF and determine what impact this release and previous releases have had on the environment and to determine what the appropriate tank

upgrade solution may be. Activities included reviewing technical reports and extracting and compiling data collected at the RHBFSF from these reports. Reviewed and provided over 135 comment letters to date to the DOH and the EPA on various Navy work plans and reports. Led the INTERA Team's development of a CSM that describes the processes and features controlling the migration of fuel contamination and identifies potential exposure pathways and receptors. Additionally, supported the development of a Monitoring Well Construction and Installation Plan, sampling plan, and quality assurance plan for several sentinel wells installed by INTERA for the BWS. The first monitoring well was completed in 2017, and quarterly groundwater monitoring was in 2017 and 2018. Semi-annual sampling of this monitoring well began in 2019 and continues in 2021. Hired Exponent as a subcontractor and oversee their technical work associated with tank infrastructure, release detection, corrosion and metal fatigue, risk assessment, and toxicology services. This expertise has been needed on various comment letters developed by INTERA for the BWS since the initiation of the contract. Representing BWS interest in numerous technical working meetings associated with the Red Hill AOC and the AOC Statement of Work (SOW) since contract initiation in 2015. Participates in Groundwater Modeling Working Group meetings to review the progress of the Navy's flow and transport groundwater model. Assists the BWS with the development of community meeting and BWS Board presentations and regularly attends all public meetings in California and/or Hawaii held by the EPA, DOH, and the Navy on the Red Hill matter. Negotiated a 2020 contract renewal with BWS that extended INTERA's work on this project for the next several years.

Led INTERA's efforts in 2021 and 2022 to support the BWS in response to the Red Hill Hawaii Department of Health (DOH) Emergency Order which requires the complete defueling of the facility by June 2024 (defueling was completed by the Navy in March 2024). These efforts have included reviewing and commenting on Navy deliverables (Defueling Plan, Closure Plan, Notice of Intent [NOI] data reports, groundwater flow model reports, etc.) and providing this information to BWS. In addition, because of the May and November 2021 fuel releases at Red Hill, the BWS has been forced to shut down several drinking water sources in the area. Mr. Tracy is currently focused on supporting the BWS with the identification of monitoring well and exploratory production well sites and working with the INTERA Project Team to design each monitoring and exploratory well and exploratory well pumping tests. INTERA has developed well designs for over ten monitoring wells and four exploratory well locations and is currently developing the drilling plans and testing plans associated with these wells. Assisting the BWS with the development of bid documents to procure drilling services for monitoring and exploratory well installations. Providing management and scheduling assistance for INTERA field teams overseeing well installation activities by BWS general and drilling contractors.

Sites Assessments, New Mexico Department of Transportation, Various Locations, NM. 2015 – Present. *Principal in Charge.* Provides senior technical review of Initial Site Assessments (ISAs), preliminary site investigations (PSIs) and Detailed Site Investigations (DSI) at several NMDOT construction project sites in New Mexico. These NMDOT projects involve the evaluation of properties either NMDOT-owned or NMDOT right-of-way (ROW) acquisitions as part of highway improvement projects. The ISAs completed generally follow the ASTM Standard E1527-13 and the NMDOT Handbook for site assessments. The PSIs and DSI include Phase II activities (investigative excavations, soil boring drilling, soil sampling, and geophysical surveys) for further evaluation of NMDOT property. Supervises the field teams conducting this work and provides senior technical review of all project deliverables. Manages overall contract issues and interfaces directly with the INTERA Project Manager and NMDOT management. Most of these assessments are completed in areas where NMDOT is going to expand their infrastructure with either additional traffic lanes or an upgrading of their maintenance yards.

Site Monitoring and Emergency Response Contract, New Mexico Environment Department - Petroleum Storage Tank Bureau, Various Locations, NM. 2014 – Present. *Project Principal.* Providing administrative and technical review of work conducted for contaminant characterization investigations and groundwater monitoring activities. These activities seek to determine the nature and extent of subsurface petroleum hydrocarbon contamination originating from above ground and underground storage tank sites. Investigations include the analysis of soil, groundwater, and soil vapor impacts to these various sites across New Mexico. Work includes the following partial listing of INTERA Petroleum Storage Tank Bureau (PSTB) state-led sites: Barelas Bridge Site in Albuquerque, New Mexico; Bell Gas Site in Truth or Consequences, New Mexico; Brewer Self-Serve Site in Roswell, New Mexico; City Market Site in San Miquel, New Mexico; Frank's Conoco Site in Bernalillo, New Mexico; Corrales Chevron in Corrales, New Mexico; Robinson Texaco in Taos, New Mexico; Rodgers Drilling Site in Albuquerque, New Mexico; Village Market and the Former Caldwell Motors sites in Belen, New Mexico; and the Montoya Well Site in El Prado, New Mexico.

Dry Cleaning Site Investigation and Remediation of Tetrachloroethene Contamination, Elite Laundry and Cleaning, Gallup, NM. 2013 – Present. *Project Manager.* Leading efforts to investigate and remediate groundwater impacted by PCE as a result of previous releases from this operating dry-cleaning facility. The impacted groundwater was discovered during a Phase II ESA conducted on an adjacent property. In response to a letter from NMED to address the contamination, efforts have included providing technical support and advice to Elite Laundry and Cleaners representatives to determine the most appropriate path forward. This included addressing the identified contamination under the NMED VRP. Prepared and submitted a VRP work plan and VRP application to NMED. The proposed VRP investigation activities include the installation of monitoring well on- and offsite to characterize and delineate the PCE in groundwater contamination. The field activities identified in the VRP Work Plan were initiated in late 2018 and early 2019, which included the installation of additional monitoring wells as well as subsurface soil and indoor air vapor sampling activities. Off-site passive vapor sampling activities were completed by INTERA under Mr. Tracy's oversight at the Site and within the area in 2020. Additional site characterization activities and preliminary design for a remediation system to prevent the off-site migration of contaminants in soil vapor and ground water are planned for 2025, including the installation of a soil vapor extraction system for the removal of VOCs in soil gas to prevent the potential for offsite migration.

Judge Steve Herrera Judicial Complex Site Investigation, Remediation, and Monitoring, Santa Fe County, NM. 2009 – Present. *Contract Manager and Project Manager.* Leads INTERA's efforts to develop a remedial solution for the Santa Fe County Judicial Complex which involves interfacing with both the NMED VRP and PSTB. INTERA was contracted by Santa Fe County in March 2009 to support their efforts to re-develop a Brownfields property comprising a three-story judicial complex and associated plaza and subsurface parking garage in downtown Santa Fe, New Mexico. A large excavation and steel/wood shoring system was constructed beginning in the fall of 2008. During shoring activities, a two-foot layer of LNAPL was discovered near the water table. INTERA performed additional site investigation activities and determined that the LNAPL plume was predominately present in the proposed location of a subsurface two-story parking garage. Construction of the garage and associated judicial complex was delayed, enabling the county and NMED's PSTB to develop an appropriate response action. PSTB subsequently designed and is operating a soil vapor extraction system for the areas outside of the judicial complex excavation to remediate the historic contamination. The county was responsible for the remediation of their property even though they were not a responsible party. Led the development of a petroleum contaminated soil (PCS) work plan including development of a dewatering plan, excavation and removal of over 20,000 tons of PCS, installation of a vapor intrusion/ground water barrier (liner) on all parts of the development located below grade, and development of a vapor monitoring system for the final development of the site. The Work Plan was approved by VRP and PSTB. The excavation work is complicated because of two primary factors: (1) soil must be excavated below the water table requiring dewatering for safe removal; and (2) construction activities are scheduled to take place immediately following soil remediation efforts, requiring that dewatering continue for several months until construction infrastructure can be put in place below the water table for the two-story parking garage. Helped initiate the development of a soil gas passive venting system around the subsurface parking garage and initiated the installation of this system in January 2012.

Additionally, prepared and submitted a VRP application to secure a certificate of completion for the remediation work; supervised risk assessors in the development of a document pertaining to future building occupancy and currently participates in numerous stakeholder meetings with the county and PSTB representatives. Either conducted or supervised INTERA staff employees or subcontractors in assessing, reviewing, and selecting mitigation measures for the complex; identifying and developing measures to isolate the proposed infrastructure from contacting LNAPL remaining in the plume around the building (i.e. liner selection process); LNAPL sampling and characterization; air emissions testing and permitting; waste profiling; preparation and submittal of a groundwater discharge permit application; LNAPL removal and disposal; LNAPL bail-down testing; a Phase I ESA of the site; slug testing to determine aquifer properties; weekly VRP update reporting, and subcontractor oversight of remediation activities. The PCS removal activities were completed at the site in February 2011. Continues to work with the county to develop a VRP Completion Report and secure a CCOC for the site. The judicial complex was completed in February 2013 and began operating in June 2013. Continues to oversee quarterly groundwater monitoring activities at the site as part of the county's VRP Work Plan. Secured a Voluntary Remediation Agreement (VRA) for the site on July 9, 2015. Completed the Voluntary Remediation Completion Report (VRCR) for the site in February 2016 and assisted the county in obtaining a VRP CCOC from NMED also in February 2016. Groundwater monitoring activities were completed by INTERA at the site in October 2016. Currently assisting the county by reviewing the work conducted by the PSTB at the site and providing status reports to the county. For example, observed multi-dual phase extraction activities conducted by PSTB and their contractor at the site in 2017. The final goal is to assist the county in

securing a VRP CCOC with only a land use restriction in 2024. Helped the County discontinue the NMED judicial complex discharge permit (NMED DP-1747) in late 2023 and currently negotiating on the County's behalf with NMED to modify the VRP CCOC in 2025.

SunZia Transmission Line Phase I Environmental Site Assessment, New Mexico and Arizona Approximate 550-Mile Corridor. 2021 – 2024. *Project Principal*. INTERA was retained by SunZia Transmission, LLC located in Albuquerque, New Mexico to perform a Phase I ESA for a 550-mile corridor starting southeast of Phoenix, Arizona and terminating in Corona, New Mexico. The proposed transmission line would ultimately aid in the transportation of wind farm produced electricity across New Mexico and into the Tucson area of Arizona. Provided Project Principal review and contract management duties for the project. Worked with the Project Team to develop Phase II site characterization goals for the recognized environmental conditions (RECs) identified during the Phase I ESA work. The Phase II recommendations included geophysical surveys for two former bombing ranges that the Project Corridor intersects in New Mexico and for soil cleanup of an above-ground storage tank release at a commercial agriculture operation at a property in Arizona. The geophysical investigations for the two former bombing ranges were completed in 2023 (no mitigation needed) and the soil cleanup for the Arizona commercial agriculture operation is scheduled to be conducted in 2024.

Data Gap Monitoring Well for the Albuquerque Bernalillo County Water Utility Authority, Albuquerque, NM. 2022 – 2023. *Project Manager.* The Albuquerque Bernalillo County Water Utility Authority (ABCWUA) received funding from the State of New Mexico CPB in 2021 to drill, install, and sample a monitoring well downgradient of the ethylene dibromide (EDB) and petroleum hydrocarbon plumes in groundwater migrating offsite from Kirtland Air Force Base (KAFB). Provided technical input on recommended location and design of a >500-ft deep monitoring well to address a potential data gap toward the distal end of the known EDB plume. Led the installation of the monitoring well (sonic drilling methods) and initial well development which was completed in April 2022. Led initial one-year long-term monitoring activities of the data gap monitoring well in late 2022 and early 2023 until the LTM duties were shifted from INTERA to an ABCWUA on-call contractor.

Kirtland Air Force Base Environmental Baseline Surveys, Albuquerque Bernalillo County Water Utility Authority, NM. 2018 – 2022. *Project Principal.* Provided technical oversight and review of final deliverables for the INTERA effort to conduct two Environmental Baseline Surveys (EBS) for the ABCWUA to meet appropriate property due diligence practices for the easement agreement between ABCWUA and KAFB. The property locations included a 5.29-mile-long easement and a 24-acre parcel, all located on KAFB and Department of Energy (DOE) property. The project includes the ABCWUA installing an interceptor pipeline and booster station and INTERA is responsible for all federal due diligence requirements associated with construction projects occurring on federal facilities. Responsible for internal team communications, client meetings, and final review of the two EBS reports. The EBS reports were completed and approved by the ABCWUA and KAFB in 2022.

Phase I Environmental Site Assessment of Mt. Chalchihuitl and Cerrillos Gravel Products Properties, Santa Fe County, Cerrillos, NM. 2004 – 2022. *Project Manager.* Project Manager for the Phase I ESA of the combined 745-acre Mt. Chalchihuitl and Cerrillos Gravel Products properties. Assessment activities are being conducted using the EPA's All Appropriate Inquiry (AAI) and ASTM Standard E1527-05 as guidance. Performed risk assessment and remediation alternative analysis activities at the Mt. Chalchihuitl portion of the site (545 acres) in 2004. The entire site was historically used for mining activities, located at the center of the Cerrillos Mining District South area. Santa Fe County plans to re-develop the site as open space by incorporating it into the Cerrillos Hills Historic Park, and INTERA continues to work with Santa Fe County to determine remediation options for the site. The development objective is to include these properties in the Cerrillos Hills Mining District Open Space Park.

Developed a VRP Work Plan for the site in 2012, which selected a previously determined remedial option and submitted the Work Plan to Santa Fe County for review. The selected remediation includes the construction of tailings impoundment and cap in a former gravel pit and long-term monitoring to make certain the cap integrity is secured. The remainder of the site will be used as a public open space, allowing the public to observe some of the oldest mines in North America. Completed and submitted the VRP Application and Preliminary VRP Work Plan for this Site in September 2017. The county would like to acquire the properties in 2018 and begin soil remediation as soon as possible after property acquisition. Currently assisting the county legal team with the development of a VRA between the county and NMED. Also, were recently awarded a contract to sample soils in the arroyo to the south of the Cerrillos Gravel Products property and to sample three area drinking water wells to determine any potential water quality impacts.

Responded to a Letter of Interest (LOI) released by the County in 2019 to assess ground water conditions at the Mt. Chal site. After selection by the County in response to the LOI, led the INTERA Team in sampling an upgradient private water well and a monitoring well at the Cerrillos Gravel Products property. Determined elevated metals concentrations are present in site groundwater and offered recommendation to the County for addition work at the site and the potential installation of a new monitoring well in a down gradient location. Due to a disagreement on overall value with the landowner (both property and mineral rights), the County passed a resolution and discontinued their Mt. Chalchihuitl acquisition initiatives in 2022.

Redevelopment of the Former First Baptist Church Site, Lobo Development, Albuquerque, NM. 2013 – 2021. *Project Manager.* Provided oversight for voluntary remediation activities associated with redevelopment of this property in downtown Albuquerque. Previously conducted Phase I and II ESAs and identified subsurface soil and groundwater contamination that was believed to be the result of a diesel fuel release at the adjacent Burlington Northern Santa Fe (BNSF) Railway Railyard. Evaluated site investigation data and determined that the property had been impacted by both off-site sources and historic site uses that required limited remediation prior to site redevelopment. The site was entered in the NMED VRP to secure a Certification of Completion (COC) to facilitate redevelopment. Activities included interaction with NMED to ensure the COC was issued in a timely manner and assisting in obtaining a Covenant Not to Sue (CNS). After receiving the COC and CNS, Lobo Development acquired the property in 2014 and the site was re-developed as part of the City of Albuquerque's "Innovate ABQ" development initiative. Worked with the Innovate ABQ development team to manage the environmental risks associated with the planned redevelopment of the Site. Assisted the Site developer (Signet) with renovation and demolition activities completed within the former First Baptist Church in 2016. Assisted the developer with VRP reporting activities in 2016, 2017, and 2018 associated with the construction of a three-story building at the site. VRP reporting activities are required in order to maintain the COC by guiding the developer to implement the proper engineering controls. The newly constructed three-story commercial building is known as the "Lobo Rainforest" and serves as an entrepreneur center for business associated with "Innovate ABQ," a downtown Albuquerque technology park. Led a team that updated the Phase I ESA in 2020 on behalf of the University of New Mexico (UNM). Also helped secure a U.S. Environmental Protection Agency (EPA) "Comfort Letter" for UNM and a CNS prior to the property transfer. UNM assumed ownership of the site in late December 2020.

Redevelopment of the Former Galles Chevrolet Automobile Dealership Property, University of New Mexico, Albuquerque, NM. 2018 – 2020. *Project Manager.* Provided oversight for voluntary remediation activities associated with redevelopment of this property in the UNM area of Albuquerque. Previously conducted Phase I and II ESAs identified subsurface soil and groundwater contamination that was believed to be the result of gasoline and diesel fuel releases from former underground storage tanks (USTs) located at the property. Additional environmental contamination was also identified by the operation of over 70 underground hydraulic lifts as well as five former oil/water separators (OWS) in use at the property. Evaluated site investigation data and determined that the property has been impacted by historic site uses that required limited remediation prior to site redevelopment. The site was entered in the NMED VRP to secure a COC to facilitate redevelopment. Activities included interaction with the NMED to ensure the COC was issued in a timely manner and assisting in obtaining a CNS. The issuance of the COC and CNS are still pending. Conducted an on-site soil vapor survey to determine areas of elevated soil vapor concentrations and developed a plan for the construction and use of vapor intrusion barriers for any newly constructed buildings at the Site. Evaluated the remediation activities conducted by the landowner (Sandia Corporation) to determine what impact, if any, the remedial work may have on future UNM activities at the site. Worked with subcontractor DC Environmental to prepare a cost estimate associated with the asbestos and lead-based paint abatement at current Site buildings prior to demolition and/or renovation. UNM leased the property in late 2019. Worked with UNM Medical Center personnel to assist with the development of short-term uses for the site prior to full-scale redevelopment.

Investigation of the Santa Fe River Targeted Brownfields Assessment Area, City of Santa Fe, NM. 2010 – 2019. *Project Manager.* Led an investigation in the downtown Santa Fe area to (1) develop a better understanding of groundwater flow within the area so that appropriate decisions can be made about remediation of petroleum hydrocarbons and other groundwater contaminants, (2) determine what impact, if any, will occur within the shallow groundwater aquifer if stream flow in the Santa Fe River is increased, and (3) determine the nature and extent of petroleum hydrocarbon contamination so engineering controls can be evaluated for future development within the TBA area. Activities included developing a geologic model and implementing a drilling program to confirm model accuracy. Field investigations showed that the

geologic model is accurate, and the City of Santa Fe and NMED used the geologic model to guide additional investigations being conducted by NMED and EPA in the downtown Santa Fe area. These investigations were completed to identify sources of petroleum hydrocarbon as well as chlorinated hydrocarbon contamination in ground water in the downtown Santa Fe area. Activities in 2016 and 2017 included the installation of additional groundwater monitoring wells, groundwater sampling, installation of soil vapor monitoring wells, soil vapor sampling, indoor air sampling, and groundwater sampling of additional monitoring wells owned by several different entities in the downtown Santa Fe area to determine groundwater characteristics and the potential sources of identified contamination. Subsurface soil gas sampling was conducted at this Site in June 2019 using "Waterloo Membrane Samplers" placed at several facilities within the TBA area that may have been sources of the underlying ground water contamination. Helped NMED develop a report for the 2019 sampling event and discussed the findings with NMED.

Proposed Belen Fire Station Property Investigation and Remediation, Molzen Corbin, Belen, NM. 2017 – 2018. *Project Manager.* Supervised Site investigation and remediation services at the proposed new Belen Fire Station property located in Belen, New Mexico. Prior to site redevelopment activities, Molzen Corbin Engineers contracted INTERA to conduct site investigation activities to determine if any impact from petroleum hydrocarbons occurred at the Site during historical activities (automobile repair activities) and to conduct geophysical investigation work to determine if any relic USTs were present at the site. INTERA advanced 15 soil borings at the site using geoprobe investigation methods to collect soil and groundwater samples. Investigation results determined that approximately 2,800 cubic yards of PCS were present at the site and one UST was in the northwest corner of the property. INTERA provided a map of the locations of the PCS and the UST. The PCS and UST were removed by City of Belen contractors in 2017. In addition, groundwater impacts by petroleum hydrocarbons were also verified, but no concentrations identified were above New Mexico Water Quality Control Commission (NMWQCC) standards or PSTB action levels. Continued to provide consulting services to Molzen Corbin at the Site as Fire Station building construction was initiated in 2017. INTERA recommended removal of the PCS and installation of a vapor intrusion barrier and sub-slab venting system to protect future building occupants and Site users. INTERA developed specification documents for both PCS removal and vapor intrusion barrier installation and provided to Molzen Corbin Engineers to include in the general contractor bid package. Construction of the Belen Fire Station was completed in 2018. The Belen Fire Station redevelopment project received the "Environmental" award from the New Mexico Chapter of the American Council of Engineering Companies in September 2020.

Investigation of Perchloroethylene Contamination at the Griggs and Walnut Superfund Site, Confidential Client, Las Cruces, NM. 2015 – 2018. *Senior Scientist.* Assisted the technical team evaluating the release timing and locations of PCE contamination in the area of the Griggs Street and Walnut Avenue intersection in the northern section of the City of Las Cruces. The timing information was critical in demonstrating occurrences for insurance reimbursement purposes. Assisted in the development of the CSM for the potential release sites in the area. The CSM would be used by Dona Ana County and the City to help further their understanding of the Superfund site.

Facility Environmental Audits and Stormwater Management Plans, Wood Group/TurboCare Generator Services/Ethos Energy, Farmington, NM. 2010 – 2018. *Project Manager.* Performed environmental audits of three electric generator parts manufacturing facilities, focused on determining volumes of hazardous waste generated at each facility. Reviewed information to calculate volumes to determine the correct generator status (conditionally exempt, small or large), obtain a correct hazardous waste generator identification number, and calculate and pay the associated hazardous waste fees to the NMED Hazardous Waste Bureau for each facility. After calculating these volumes, the Wood Group reported previous quantities of generated waste and paid current and past hazardous waste-generation fees, bringing the facilities back into regulatory compliance. Prepared stormwater pollution protection plans (SWPPPs) for each facility and provided ongoing support with stormwater issues. Due to facility operator transfer and the closing of the two of the facilities, worked with INTERA staff in 2017 and 2018 to update the SWPPP and file Notice of Termination of discharge and NOI to discharge for the new ownership group (Ethos Energy).

Reclamation of the San Vicente Mill Site, New Mexico Environment Department, Silver City, NM. 2013 – 2016. *Project Manager.* Led environmental investigation and remediation/reclamation activities to address an above-grade tailings pile, resulting from former milling and smelting operations for lead, silver, copper, and gold that operated from the 1880s to the 1940s. The tailings pile contained metals (e.g., arsenic and lead) at levels exceeding established human health standards. Water quality had been impacted by the erosion of the tailings pile and the subsequent transport of contaminated material to an adjacent creek. Groundwater also contains elevated concentrations of metals. Project activities included negotiating access

agreements, as portions of the site were on private property; determining the extent of tailings and contaminated soils on-site and offsite; organizing and holding a community meeting to inform property owners as well as Town of Silver City representatives and citizens of potential community impacts; providing contractor oversight for removal of contaminated materials (approximately 50,000 cubic yards); transporting and disposing of contaminated materials at a nearby operational mine site; restoring disturbed areas with placement of soil cover; and reseeding with a native seed mixture. Implemented a reclamation approach that included performing additional characterization efforts while removal of the main tailings area material was being conducted. The single mobilization resulted in cost savings and a project that was completed ahead of schedule. Responsible for developing the Final Removal Assessment Report which documented the quantity of tailings removed and the restoration activities including clean fill placement, grading, and institution of property engineering controls.

Environmental Site Assessments, Los Alamos County, NM. 2005 – 2016. *Contract Manager and Project Manager.* Served as Contract Manager for Los Alamos On-Call Services contract. Investigated and characterized the environmental conditions at several Los Alamos County and Los Alamos School District properties. These properties were formerly operated by Los Alamos National Laboratory. Currently managing this work, which includes Phase I and Phase II ESAs, asbestos and lead-based paint surveys, archaeological investigations, archaeological stabilization activities, surface water sampling, and other general environmental consulting activities. Special projects have included a hazardous materials survey at the Los Alamos County Golf Course, an Environmental Assessment (EA) of the Los Alamos County Canyon Dam site, and a NMED VRP application for the Los Alamos County Trinity Redevelopment site.

Designed and constructed a stormwater detention pond engineering controls at the Trinity Redevelopment site in 2012. The pond was constructed as a solution to an NMED action that required the county to control stormwater runoff into the canyon to the south of the site. Managed the project that included engineering design, construction, and reporting to NMED. Following the construction of the drainage improvement, Los Alamos County began redeveloping the site with a shopping center to include a grocery store, small businesses, and restaurants.

Provided oversight of the removal of a historic OWS from the Trinity Redevelopment Site in 2013. The OWS was discovered during redevelopment construction activities. Secured a subcontractor and provided the county with expedited services during the OWS removal and subsequent sampling so that the construction activities scheduled for the site were not compromised.

Former Eubank Landfill Assessment of Remediation Alternatives, City of Albuquerque/New Mexico Environment Department, NM. 2003 – 2016. *Project Manager.* Led an effort on behalf of the COA and NMED to characterize the nature and extent of landfill gas contamination at the former Eubank Landfill (northeast fill area). Also worked at this site on behalf of Albuquerque Public Schools, an owner of an adjacent property; Bernalillo County, a stakeholder related to the Eubank Landfill; the U.S. Army Corps of Engineers; and the New Mexico State Land Office. The northeast fill area of the former COA Eubank Landfill was operated between 1963 and 1973 on property leased from the New Mexico State Land Office. The Eubank Landfill northeast fill area was unlined and covered approximately 21 acres, with a waste depth in the range of approximately 30 to 40 feet. Material placed at the Eubank Landfill was reported to be mainly residential and commercial waste.

Conducted an assessment of the former Eubank Landfill southwest fill area in 2011 for the proposed future development as a solar panel system field. Worked for a private solar development company along with the COA to evaluate this use of the site and how this use may be impacted by the potential migration of landfill gas. Also worked with INTERA engineers in the development of a final landfill gas management plan as well as a surface grading and drainage plan. In 2012, managed the project, which included additional grading plans for several types of solar panel designs selected for the site. This included the development of a Waste Excavation Plan (WEP). The WEP included the use of waste as fill material, the first of its kind in the State of New Mexico.

Developed an approach for Emcore Solar Power to install and operate a solar panel field at the surface of the former Eubank Landfill southwest fill area. This included LFG investigation activities as well as a geotechnical investigation conducted in order to develop recommendations for landfill gas control measures as well as geotechnical foundation of the solar panel trackers. This work included communicating with civil engineers, architects, electricians, and others to facilitate the successful project. The solar field is currently online and provides power to the Emcore manufacturing facility located

adjacent to the former landfill. Responsible for final reporting and periodic site inspections concerning the condition of the landfill surface.

Hyder Property Site Investigation, City of Albuquerque, NM. 2003 – 2016. *Project Manager.* Developed the investigation work plan at this Brownfield redevelopment property which was the site of a former dry-cleaning facility. The work plan included the execution of a geophysical survey as well as investigative digging to find historic underground solvent storage tanks. Investigative excavations were constructed at the Hyder property, and six USTs were discovered. Conducted a Phase II site investigation at the Hyder property, which included the collection of surface soil, subsurface soil, soil gas, and groundwater samples. Wrote the VRP Completion Report for this site; property received a Certificate of Completion from the NMED VRP. Worked with the site developer, YES Housing, to oversee excavation of soils to determine if contamination was present during construction in late 2014. Site redevelopment as the Imperial Building began in early 2015. Worked with the construction contractor to address environmental contamination (removal of petroleum-contaminated soils and two underground storage tanks) during building excavation and construction work. Submitted the VRCR for the site to NMED in December 2015. Assisted the site developer in securing a CNS from the NMED VRP in early 2016. The Imperial Building includes residential housing on the two upper floors and a community garden on the roof, with commercial spaces (including a grocery store) on the first floor. One level of parking is included in a subsurface parking lot located below the building. The Imperial Building officially opened in September 2016.

500 Copper Square Property Soil Vapor Investigation, First Financial, Albuquerque, NM. 2014 – 2015. *Project Manager.* Led efforts to determine presence of VOCs in site soil vapor. Collected sub-slab soil gas samples at locations within the building basement and compared analytical results to EPA's recommended commercial and residential vapor intrusion screening levels (VISLs) to determine whether VOC contaminants were impacting air quality in the building. Tetrachloroethene (PERC)—a dry cleaning solvent—was present in several of the soil vapor samples, but concentrations did not exceed applicable VISLs for PERC. Entered site into the state VRP in order to obtain a COC to document that current conditions meet applicable environmental quality standards and provide liability protection for lenders. NMED issued at COC in 2015, and a CNS can be transferred to any lender or future owner of the property.

Former Sterling Manufactured Gas Plant Voluntary Cleanup Program Site, Centennial Mental Health Center, Sterling, CO. 2014 – 2015. *Senior Technical Advisor.* Assisted with additional site investigation activities within the VCP investigation and remediation activities at the former Sterling Manufactured Gas Plant site. This site was remediated through the Colorado Department of Public Health and the Environment (CDPHE) VCP for future development into a parking lot for use by the future landowner and neighboring facility, Centennial Mental Health Center. The initial site investigation and targeted brownfields assessment were completed by CDPHE and identified polyaromatic hydrocarbons (PAH) organics and metals contamination above the regulatory limits in the site soils. Project tasks have included potholing of site soils to define further the extent of soil contamination, sampling of an upgradient groundwater monitoring well to determine if metals contamination can be attributed to an off-site source, determination of the most cost-effective method to sample near and around a transformer on site, and completion of the work plan, cost estimate, and health and safety plan for the excavation of site contaminated soils. To accommodate funding schedules, the remediation activities, which consisted of excavation, hauling, and off-site disposal of 814.5 cubic yards of soils contaminated with PAHs, were performed using a phased approach and were completed in 2015. A No Action Determination (NAD) was submitted and formal acceptance of the NAD by CDPHE was received in December 2015.

Characterization and Remediation of the Former Bell Trading Post Property, City of Albuquerque, NM. 2001 – 2005 and 2015. *Project Manager.* Developed a Work Plan to characterize this facility adequately for ultimate inclusion into the VRP. The Bell Trading Post building was formerly a jewelry manufacturing facility as well as a photograph development facility. Heavy metals and solvents were in use at this historic facility. The Work Plan included Geoprobe soil boring installations, subsurface soil sampling, and groundwater sample collection. In addition, on behalf of the COA, supervised a subcontractor conducting a limited asbestos survey at the Bell Trading Post facility building. Completed the VRP Application for this site and developed a VRP Work Plan for the remedial work, which included an integrated QAPP. The remediation consisted of contaminated soil removal as well as the remediation of asbestos and lead-based paint. This was the first Work Plan/QAPP developed for asbestos/lead-based paint remediation in EPA Region VI. Provided oversight of the remediation work and documented the progress on behalf of the COA and its developer, Family Housing Development Corporation. Remediation work completed included the cleaning of a substantial amount of pigeon droppings, asbestos and lead-based paint abatement, lead-in-soil removal, and the removal of all light ballasts from the building. Wrote the VRCR for this facility and

helped the COA obtain a Certificate of Completion from the NMED VRP. This facility was later renovated and developed with residential housing units and commercial office space. Lead a soil vapor intrusion assessment of the renovated building on behalf of the NMED in 2015.

Municipal Separate Storm Sewer System Audit and Application, Santa Fe County, NM. 2012 – 2013. *Project Manager.* Led efforts to assist the county in submitting a municipal separate storm sewer system (MS4) application to the EPA. Reviewed and evaluated documents regarding the history of the MS4 and the NOI Plan; prepared summary report for the county to document current status of the EPA requirements for the MS4 Plan and NOI and define options, deliverables, action items, and schedules/timelines; and helped the county resubmit the MS4 Application to EPA. By working cooperatively with both the county and EPA, helped avoid financial penalties for the county.

Phase I and Phase II Assessments, Northwest New Mexico Council of Governments, Gallup, NM. 2010 – 2013. *Contract Manager and Project Manager.* Contract Manager for Northwest New Mexico Council of Governments (NWNMCOG) On-Call Services contract. This contract was established by the NWNMCOG to evaluate potential Brownfields within the NWNMCOG area (Gallup, San Juan, and Cibola counties). Performed Phase I and Phase II Assessments for the NWNMCOG as part of this contract. Brownfield site characterization activities are the general focus of the contract for those sites located within the NWNMCOG area. Phase II activities conducted under this contract included hollow-stem and air rotary drilling, geophysical survey using electromagnetic (EM) and ground-penetrating radar (GPR) equipment, surface and subsurface soil sampling, groundwater sampling, and investigative excavations using a backhoe.

An example of a NWNMCOG project is the Coal & Puerco Site in Gallup, New Mexico. This site is proposed to be redeveloped with a live/work facility by Community Area Resource Enterprise 66. A dry-cleaning facility is located immediately north of the site. Led INTERA's efforts to investigate the redevelopment site and determine what remedial actions or engineering controls would need to be implemented at the site to although for safe and cost-effective redevelopment. INTERA conducted surface and subsurface soil sampling, soil vapor sampling, and groundwater sampling at the site. PERC was identified in site groundwater and soil vapor. Based on findings of the investigation, recommended that a vapor intrusion barrier be placed below the proposed site building to prevent impacted soil vapor from entering building indoor air. Additionally, worked with the NWNMCOG and NMED to investigate impacts to groundwater in the immediate area surrounding the site and determined that PERC was present in several off-site areas. INTERA is currently working with NMED and the responsible party to determine the vertical and lateral extent of the PCE groundwater plume and determine remedial options.

4407 Lomas Boulevard Site Investigation, Parnell Lomas, Albuquerque, NM. 2012. *Project Manager.* Led a Phase II Site Investigation at this site to determine if former operations as a gasoline service station had negatively impacted soil, soil vapor, or groundwater. The site included an office building and the client was trying to decide whether to purchase the property. After the investigation, it was determined that the site had not been negatively impacted by former operation as a gasoline service station, but that soil vapor was impacted with PCE, most likely from off-site historical dry cleaners. It was concluded that PCE could enter the current office building at levels above EPA screening levels. A proposal was prepared for a vapor mitigation system. Client decided not to purchase the property due to the cost of implementing the vapor mitigation system and associated ongoing monitoring.

Former Tulip Drive Landfill Phase I ESA and Phase II Site Investigation Activities, Luna County, Deming, NM. 2010 – 2012. *Project Manager.* Served as INTERA's Project Manager for the performance of a Phase II ESA performed at the 75-acre tract of land, including the Former Tulip Drive Landfill, located in Deming, Luna County, New Mexico. The Phase II ESA was performed for the county and city using funds provided by the EPA Brownfields Assessment Grant Program. Responsible for the development of a site-specific SAP, which guided field activities. The site was a vacant tract of land owned by the city located southeast of the intersection of New Mexico Highway 26 and U.S. Highway 180, along the Mimbres River. It was the city's and county's intent to redevelop the site as recreational open space; therefore, the objective of the Phase II ESA was twofold: (1) obtain additional information regarding the character of the former Tulip Landfill, such as cover thickness, depths and types of waste, and the extent of the former Tulip Landfill area, and (2) determine if soil and/or groundwater impacts exist from the recognized environmental concerns identified as part of the Phase I ESA completed by INTERA in 2011. INTERA conducted the following Phase II ESA field activities in 2012: (1) investigative excavation of 15 test pits located within the footprint of the former Tulip Drive Landfill, (2) hollow-stem auger (HSA) drilling and sampling of eight shallow exploratory soil borings, (3) HSA drilling and sampling of three deep soil borings, (4) installation and development of three

groundwater monitoring wells (within the deep soil borings), and (5) a single groundwater sampling event. Due to only minimal exceedances of applicable standards in site soil and no exceedances in site groundwater, recommended proceeding with site development upon completion of the following additional remediation/characterization activities:

- Consolidation of the numerous surface litter and debris piles scattered through the vacant lot to within the confines of the former Tulip Drive Landfill
- Preparation of preliminary design and installation of an evapotranspirative cap over the consolidation area to (a) minimize exposure to potentially harmful waste and (b) stabilize waste to deter further offsite transport of site contaminants via surficial processes (i.e., storm water, wind)
- Provision of bank stabilization and erosion control of property land located along the Mimbres River to mitigate the negative effects of progressive undercutting by seasonal surficial processes and help minimize future transport of site contaminants off-site
- Securing the site to prevent future indiscriminate dumping
- Installation of at least one additional ground water monitoring well in the northeast corner of the site to confirm groundwater remained unimpacted by the presence of the landfill
- Completion of one or more additional groundwater sampling events to further assess and monitor groundwater site conditions
- Completion of all additional site remediation/characterization efforts through participation in the NMED VRP.

Hotel La Posada de Albuquerque Redevelopment, City of Albuquerque, NM. 2007 – 2011. *Project Manager.* Developed a QAPP and asbestos specifications for the removal of asbestos from the Hotel La Posada de Albuquerque. Also developed an EE/CA that evaluated the remediation options for the renovation of this historic hotel. Significant quantities of asbestos and lead-based paint were present within La Posada. The EE/CA was used to support the use of the COA Brownfields Cleanup Revolving Loan Fund for a portion of the remediation. Through the EE/CA report, documented the alternative selection process for a non-time-critical removal action that was completed in accordance with 40 CFR 300.415 of the National Oil and Hazardous Substances Pollution Contingency Plan. The Hotel La Posada de Albuquerque was successfully remediated, renovated, and reopened as the Andaluz Hotel in October 2009. Prepared a self-certification document in 2011 that was submitted to the EPA for the voluntary remediation conducted at this building. Site was renamed the "Hotel Andaluz."

Casa Grande Property/El Vado Hotel Phase I Environmental Site Assessment, and Phase II Site Investigation, City of Albuquerque, NM. 2009 – 2010. *Project Manager.* Led an environmental evaluation of the Casa Grande Property on behalf of the COA. The COA proposed redeveloping the Casa Grande Property/El Vado Hotel located at 2500 Central Avenue with mixed use development (residential/commercial) and contracted INTERA to perform a National Environmental Policy Act (NEPA) Environmental Assessment, a Phase I ESA, and a Phase II Site Investigation at the site. The Phase I ESA and Phase II Site Investigation were performed with support from other key INTERA staff members. The Phase I ESA identified a historical property use (gasoline pumps at the El Vado Hotel) and a historic gasoline release at the Casa Grande Chevron located across the street as potential recognized environmental conditions and recommended subsurface soil borings as well as a geophysical investigation be completed at the property. Eight subsurface soil borings were completed at the site in areas believed to have been potentially impacted by historical property and area uses. No impact from petroleum hydrocarbons in soils and/or groundwater was identified. In addition, the geophysical investigation, conducted by Sunbelt Geophysics, did not identify any evidence of abandoned USTs at the site.

Managed the completion of a NEPA Environmental Assessment at the site as prescribed by the lead federal agency, which in this case was the Department of Housing and Urban Development. The EA was completed with support from Parametrix (cultural and biological surveys). The ESA was required to release Community Development Block Grant funds for the property purchase and additional property redevelopment work.

New Mexico Rail Runner Site Assessments, Parsons Brinckerhoff Quade & Douglas, Santa Fe, NM. 2006 – 2009. *Project Manager.* INTERA was retained by Parsons Brinckerhoff Quade & Douglas (PB) in 2006 to perform ISAs for Phase 2 of the Mid-Region Council of Governments/ NMDOT Belen to Santa Fe New Mexico Rail Runner Express Commuter Rail Project. Performed an ISA for the existing BNSF railroad line from Bernalillo to Lamy, New Mexico, and an ISA for the proposed commuter rail line from La Bajada Hill to downtown Santa Fe, New Mexico. Acted as the designated INTERA Project Manager for each ISA

project. The ISA included the assessment of existing railroad lines and facilities (BNSF and Santa Fe Southern), as well as several miles of railroad tracks constructed on undeveloped ranch land to facilitate commuter rail service between Albuquerque and Santa Fe. Project management duties included developing and implementing the schedule for the records reviews, field reconnaissance, and report development. Led field activities for each ISA (the combined assessment length of the two ISA totals over 70 miles) and coordinated with the PB Project Manager, the NMDOT Environmental Geology Section representatives, and NMDOT legal counsel with the finals of each ISA Report. The New Mexico Rail Runner Express began operations in 2009.

Landfill Gas Assessment of Five Formerly City-Owned and/or Operated Landfills, New Mexico Environmental Health Department, Albuquerque, NM. 2003 – 2009. *Contract Manager and Project Manager.* Contract Manager for INTERA's COA landfill gas assessment project. Over 100 landfill gas monitoring wells have been installed to monitor landfill gas migration at five of the COA formerly owned and/or operated solid waste landfills under direction. Managed the landfill gas monitoring well installation and supervised landfill gas sample collection. Other duties conducted include contract budget tracking, future landfill gas monitoring well locating, and landfill gas sample results interpretation. Developed the current COA landfill gas well installation report format as well as the format used for the landfill gas monitoring reports. Also developed landfill management plans to guide development on and adjacent to the former Eubank and San Antonio landfills.

Former Peru Hill Mill Site Phase I Environmental Site Assessment and Phase II Site Investigation and Remediation, New Mexico Environment Department, Deming, NM. 2001 – 2008. *Project Manager.* Performed a Phase I ESA and Phase II Site Investigation of the former Peru Hill Mill mining mill facility in Deming, New Mexico. The Peru Hill Mill primarily processed zinc sulfide ore. Peru Mining Company, a subsidiary of Illinois Zinc Company, constructed the Peru Hill Mill and operated it from 1928 to 1967. Barite of America acquired the facility in 1979 and operated it intermittently until 1985, when the company filed for bankruptcy. Luna County acquired the property in 2001 and deeded it to the City of Deming. The major environmental concerns at the site were uncontained tailings in a 104-acre impoundment and redistributed tailings transported from the impoundment by wind erosion and surface water runoff. The tailings formed dunes around the impoundment that blanketed an area of approximately 161 acres. The total area of the tailings impoundment and redistributed tailings was approximately 265 acres.

Prior to initiating the site investigation, a Phase I ESA was completed at the site. Used the results of the Phase I efforts to complete a work plan and QAPP for the Phase II Site Investigation. Soil sampling results indicated lead, arsenic, and zinc concentrations in surficial soils were in excess of NMED soil screening levels (SSLs). Recommended that surficial soils containing metals concentrations above SSLs be placed within a site tailings impoundment area and that the tailings be capped with soil to prevent further migration by wind and/or water erosion. Secured an engineering firm to design the tailings impoundment cap and a soil consolidation plan. Prior to implementation, the City ultimately used the Phase I ESA report and the information in the site investigation report to submit a VRP application to NMED.

Excavation activities were completed by the City and the tailings were excavated and redistributed to the designated tailings impoundment area. Helped develop a confirmation soil sampling plan to assure that the tailings removal effort was successful. Directed Neptune and Company (subcontractor) in the development of a site-specific remedial action goal for arsenic at the site. Remediation efforts were completed according to plan at Peru Hill Mill and a VRP Completion Report was developed for this facility in 2008. The site received a Conditional Certificate of Completion from VRP in 2009.

Plaza Del Sol Property Site Investigation, City of Albuquerque, NM. 2001 – 2008. *Project Manager.* Led the investigation of this Brownfields redevelopment site, which was believed to be impacted by a historic petroleum hydrocarbon release in the local area. Investigation activities included the preparation of a Phase I ESA, installation of monitoring wells, and groundwater sample collection. Completed additional work at this site on behalf of the COA and private developers in 2008 and developed a VRP Completion Report for the site. The site received a Certificate of Completion from the NMED VRP in 2008 and has since been developed with residential housing.

City of Santa Fe Railyard (including Phillips Petroleum) Brownfields Investigation, City of Santa Fe/New Mexico Environment Department, NM. 2000 – 2008. *Project Manager.* Led several stages of work completed at the City of Santa Fe Railyard for either the City of Santa Fe or the NMED. The work included the development of a Phase I ESA for a 33-acre portion of the site, a preliminary evaluation of groundwater impacts, a subsurface soil clean-up of tar, and the development of a VRP Completion Report. The Phase I ESA focused on identifying more fully potential responsible parties so that the City could consider this information in its Brownfields redevelopment strategies. The City development plan was to redevelop the underutilized

railyard with a railyard park to include open space and trails, green space, and a farmer's market area. A VRP Application and Work Plan were developed by the City and the site was accepted into the VRP.

Construction at the site began in 2006, and tar was discovered in subsurface soils during archaeological excavation work being conducted at the site. Provided the planning and oversight of the removal of subsurface soil containing tar at the site in 2006 and 2007. Developed a report which was submitted to NMED documenting the tar removal activities completed on behalf of the City.

Performed a Phase I ESA at the Phillips Petroleum site, which is located within the Santa Fe Railyard. Completed a VRP application and developed a work plan to address petroleum hydrocarbon contamination in surface soils located at the Phillips Petroleum site. The work plan included additional groundwater monitoring, but no other work was recommended. The Phillips Petroleum site was incorporated into the Santa Fe Railyard Certificate of Completion once the VRP Completion Report was developed and submitted. After receiving a NMED VRP Certificate of Completion and Covenant Not to Sue, this site is now completely redeveloped.

Tender Loving Care Cleaners Phase I Environmental Site Assessment, New Mexico Department of Transportation, Belen, NM. 2006. *Project Manager.* Conducted a Phase I ESA at the former Tender Loving Care (TLC) Dry Cleaning facility located in Belen, New Mexico. Conducted the Phase I ESA to meet the assessment and EPA AAI requirements of the ASTM Standard E1527-05, "Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process" and the reporting requirements of the NMDOT 1999 Hazardous Waste Assessment Handbook. The site operated as a dry cleaner under the name "Sunshine Cleaners" from 1987 to 1990 and as TLC Cleaners from approximately 1990 to 1997. NMED conducted a Phase II Site Investigation at the facility and determined that chlorinated solvent contamination was present in subsurface soils and groundwater. The Phase I ESA developed recommended additional sampling to delineate the extent of soil and groundwater contamination. NMDOT ultimately decided not to acquire the property for use as a New Mexico Rail Runner stop.

Former Hillcrest Hospital Facility Site Characterization, New Mexico Environment Department, Silver City, NM. 2004 – 2006. *Project Manager.* Managed the characterization of an abandoned hospital building proposed to be redeveloped as a library. The site characterization included the evaluation of the building for the presence of asbestos and lead-based paint. Additional work included the characterization of site soils for asbestos contamination as well as excavations completed to find an abandoned petroleum storage tank. Developed the QAPP to guide sampling to adequately characterize the facility. Prepared the integrated work plan for the remedial efforts and assisted the Town of Silver City in the selection of a remediation contractor. Managed the remediation work which included asbestos and lead-based paint abatement, as well as a clean-up for pigeon droppings. After successful remediation, the building was demolished and the site was considered ready for redevelopment.

Proposed Rio Grande Silvery Minnow Sanctuary, U.S. Department of Interior - Bureau of Reclamation, Albuquerque, NM. 2005. *Project Manager.* Served as the project manager for a Phase II site investigation evaluating a proposed site for use as a minnow sanctuary. Developed the work plan and provided oversight for the field work consisting of soil, subsurface soil, surface water, and groundwater sampling. Performed an additional site investigation using biological testing of fish to further evaluate the site for suitability as a minnow sanctuary. The site was ultimately selected by the Bureau of Reclamation for the location of the Rio Grande Silvery Minnow Sanctuary.

Phase II Site Investigation and Soil Remediation Activities at Former Araho Well Injection Disposal Facility, New Mexico Oil Conservation Division, Lovington, NM. 2003 – 2005. *Project Manager.* Managed a Phase II site investigation and subsequent soil remediation activities at a former well injection facility. Evaluated the site for the presence of petroleum hydrocarbons and chloride content in soil and then developed a work plan for remediation. Supervised the soil remediation efforts including soil excavation, transportation, and disposal and the subsequent placement of clean fill. Assisted engineers in the development of a cap for the site and provided oversight for the cap construction.

Former San Antonio Landfill Phase II Site Investigation, City of Albuquerque, NM. 2002 – 2003. *Project Manager.* Led a geophysical investigation at the former San Antonio Landfill on behalf of the COA and NMED to determine the volume of waste and thickness of cover at the site. The landfill consisted of approximately 42.5 acres in northeast Albuquerque in an area that was once on the outskirts of town but later became a residential and commercial area. Owned partially by the COA and partially by private landowners, the landfill reportedly accepted municipal waste from 1968 until 1970, at which time it was

capped and informally closed. Data from the geophysical survey provided enough evidence to conclude that the depth of soil cover across the San Antonio Landfill ranged from 2 to 6 feet. Based on the geophysical evidence of the thickness of the soil cover, it was determined it was very unlikely that landfill-related waste was present in surface soils at the site. The results of this investigation were subsequently used several times to help the COA guide development work on and near the former landfill.

Voluntary Remediation Program Assistance (Brownfields Awareness), New Mexico Environment Department, Santa Fe, NM. 2002. *Project Manager.* Managed a NMED project to increase awareness of the number of brownfields sites within New Mexico and the funding assistance available to New Mexico municipalities for brownfields site investigation and remediation. Project included extensive file review, database management, and coordination of a conference for public and private sector representatives. Consistent interaction with the VRP manager and VRP staff was essential to complete this task.

Historic Waterworks Property Site Investigation, New Mexico Environment Department, Silver City, NM. 2002. *Project Manager.* Led investigation to characterize site for inclusion in the state VRP. Site characterization activities included surface soil sampling, soil boring installation, subsurface soil sampling, and groundwater sample collection. In addition, asbestos and lead-based paint sampling were conducted in the historic building located on the site. Site characterization activities required interaction with NMED and the State Historic Preservation Officer.

Old Silver City Landfill Site Investigation, Town of Silver City, NM. 2000 – 2002. *Project Manager.* Led a Phase II Site Investigation of the closed municipal waste landfill known as the Old Silver City Landfill on behalf of the Town of Silver City and the NMED in 2000. The landfill operated from 1968 to 1993 and was historically used by the Town of Silver City and Grant County residents and businesses. The landfill was unlined and placed over arroyos and suspected to be serving as a source for methane gas and groundwater contaminants. Performed an evaluation of potential sources for chlorinated solvents in the vicinity of the landfill that might have been related to groundwater contamination in the area. This task was completed by collecting surface soil samples at an onsite machine shop; subsequent analysis of these samples showed the machine shop was not a source of the contamination.

In addition, the Town of Silver City and NMED asked for an evaluation of viability of harnessing the methane gas from the landfill for energy purposes to be conducted. As a first stage of this work, performed a site reconnaissance of the landfill with landfill engineers, collected landfill gas samples, and reviewed all the available existing records on disposal history and methane gas detection. This information was used to estimate the landfill gas volume and methane concentration using industry-accepted methods. It was determined that there was not enough landfill gas available to provide a viable energy source.