

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
1000 Park Ave SE	1000 Park Ave SE	Albuquerque	Bernalillo	35.085469	-106.658788	soil vapor sampling for chlorinated solvents	unknown	samples results were below action levels	closed	7/23/2007
14th & Coal	14th and Coal	Albuquerque	Bernalillo	35.082147	-106.664078	Dewatering sewer line, BTEX	6/7/1984	water was properly disposed	closed	6/6/1984
14th and Coal trench dewatering	14th and Coal	Albuquerque	Bernalillo	35.08241	-106.67648	during a sewer line trench dewatering project BTEX was found	6/6/1984	dewatering and discharge to storm drain was ceased	closed	6/1/1984
2nd & Headingly Diesel Release	2nd & Headingly	Albuquerque	Bernalillo	35.12291003	-106.6408883	200 gallon diesel spill, 20-30 gallons entered city stormwater drain	5/20/2021	excavation/flushing storm drains	closed	11/3/2021
204 Murray Street	204 Murray St.	Albuquerque	Bernalillo	35.006384	-106.655359	PCE discovered in GW from PSTB MWs	unknown	MNA	closed	11/9/2006
215 Hartline St.	215 Hartline St.	Albuquerque	Bernalillo	35.070256	-106.668919	Domestic well sampling following illegal dumping across street	1/8/2014	COA removed soil	inactive	10/27/2014
312 Central Ave NE	312 Central Ave NE	Albuquerque	Bernalillo	35.083411	-106.64401	Dry Cleaning chlorinated solvent release to soil vapor/groundwater	unknown	Transferred to VRP, ID 53211004	Transfer to VRP	2/16/2022
38 Los Suenos	38 Los Suenos	Sandia Park	Bernalillo	35.154747	-106.29762	environmental complaint	n/a	site visit, no violations noted.	closed	6/2/2022
830 Broadway	830 Broadway	Albuquerque	Bernalillo	35.091401	-106.642371	Automotive repair shop with dry well, BTEX and solvents in soil	unknown	Source removal, MW installed	referred to VRP (Marble Arno)	11/17/2015
A.S. Horner	6280 SR 303 SE	Albuquerque	Bernalillo	35.08241	-106.67648	Spill, AST Refueling	5/16/2000	CAR approval	closed	8/26/2002
ABF Freight Systems	4800 Lincoln NE	Albuquerque	Bernalillo	35.141948	-106.588733	200 gal acetic acid spill	10/22/1996	acetic acid neutralized and absorbent removed	closed	1/17/1997
Aceves Domestic Well	4329 Meade SW	Albuquerque	Bernalillo	35.08241	-106.67648	sampling	unknown	results below stds	closed	4/9/2007
Advance Manufacturing	700 N Hill Rd	Bernalillo	Bernalillo	35.332468	-106.523316	cutting oil discharges and presence of solvents	1991	soil excavation and GW monitoring	closed	9/6/2000
Albright Oil Co	1800 4th Street NW	Albuquerque	Bernalillo	35.102021	-106.648201	petroleum contaminated soil	pre 1995	soil excavation	closed	3/28/1996
Albuquerque Excavators	Isleta and Celeste	Albuquerque	Bernalillo	35.08241	-106.67648	heavy equipment company with hydrocarbon contaminated soil throughout yard	pre 2004	HWB took lead and 3 MWs installed under GWQB oversight	referred	
Albuquerque Metals Co.	3339 2nd Street SW	Albuquerque	Bernalillo	35.116881	-106.642093	Well, Supply contaminated	6/23/1985	sampled	inactive	
Albuquerque Metals Recycling	3339 2nd Street SW	Albuquerque	Bernalillo	35.116881	-106.642093	metals recycling facility reported to puncture auto gas tanks and spill on ground	1997	Soil sampling showed no contamination. CERCLA pre-screen showed As in a MW upgradient to the ATSF Tie Treating facility	inactive	
Albuquerque Metals Recycling	3339 2nd Street SW	Albuquerque	Bernalillo	35.116881	-106.642093	Fire suppression water - heavy metals	7/25/2011	Direct push soil and ground	closed	11/10/2011
Alfred Luna Home	101 Woodland NW	Albuquerque	Bernalillo	35.111477	-106.642781	concern of pesticide disposal on property	pre 1/00	samples showed no evidence of pesticides	closed	8/16/2000
Alta Transportation	7920 Ranchitos Loop NE	Albuquerque	Bernalillo	35.170602	-106.612682	Loss of 1300 gal of dyed diesel from tanker,	4/19/2015	soil excavation	close	6/16/2016
Aluminum Sales Corp	1928 7th Street NW	Albuquerque	Bernalillo	35.104194	-106.65281	TPH soil contamination from a Phase 2 ESA	pre 1996	sampling showed continued TPH in soil	inactive	
AmeriGas/Van Waters & Rogers	3301 Edmonds Ave	Albuquerque	Bernalillo	35.08241	-106.67648	Discharge, CI-solvents		CERCLA site	CERCLA	
APD Parking lot	4th Street and Marquette NW	Albuquerque	Bernalillo	35.088208	-106.650931	discovery of petroleum contaminated soil	pre 10/2/2000	soil borings showed contaminated was contained by a clay layer	closed	11/17/2000
Approved/Mesa Oil	4532 Broadway SE	Albuquerque	Bernalillo	35.08241	-106.67648	old used oil AST, oil release to soil and AMAFCA channel	4/5/2004	soil excavation, removal of ASTs	closed	7/14/2005
Arnie's Cleaners	8217 Menaul Blvd NE	Albuquerque	Bernalillo	35.109492	-106.552295	Release of PCE from Dry Cleaners	unknown	assessment	transferred to VRP	4/24/2018
ATA San Jose Pipeline	3300 Broadway Blvd SE	Albuquerque	Bernalillo	35.044684	-106.647418	petroleum hydrocarbons pipeline fuel release discovered in late 1980's	unknown	pipeline replacement and long term soil vapor extraction system	closed	5/7/2009
Atex LUST	3501 Isleta	Albuquerque	Bernalillo	35.08241	-106.67648	LUST	1983	referred to PSTB	referred	
Atlas Oil Diesel Spill	7843 Tramway Blvd NE	Albuquerque	Bernalillo	35.172	-103.497257	37 gallons of diesel spill at gas station during dump, flowed into drain on to AMFCA RoW	4/20/2015	Excavation of impacted soil beside tank field and below outfall	closed	6/12/2015
ATSF Auto Unloading	Appr 2000 ft S of Woodward and Williams	Albuquerque	Bernalillo	35.041445	-106.65295	Fuel release from ASTs	unknown	product recovery and GW monitoring	closed	8/1/2000
ATSF Tie Treating Facility	3300 2nd Street SW	Albuquerque	Bernalillo	35.044191	-106.654897	creosote tie treating facility	1908-1972	referred to CERCLA-SOS	referred	
Ayala Residence	7516 Vista del Arroyo NE	Albuquerque	Bernalillo	35.137549	-106.561535	oil pant waste supposedly discharge to soil	Jul-95	sampling showed no solvents or paint waste	closed	6/1/1997
Barcelona Mobile Home Park	Coors and Barcelona T9N,R2E,3.4	Albuquerque	Bernalillo	35.08241	-106.67648	septic tank leach field study	1988	report published	closed	6/12/1988
Barr St., Charlene Warwick property	110 Barr Rd SE	Albuquerque	Bernalillo	35.08241	-106.67648	meth lab discharged to septic system	pre 7/15/04	3 MW installed and GW was clean	closed	1/26/2005
Bass LUST Site - TCE	4257 Isleta SW	Albuquerque	Bernalillo	35.08241	-106.67648	PSTB sampling showed low levels of TCE	unknown	GWQB investigation and domestic well sampling showed all results BLD	closed	5/1/2010
BCK Hydraulics	3405 Stanford NE	Albuquerque	Bernalillo	35.119542	-106.616765	phase 2 showed TPH, Cd, Pb in soil fill	8/19/1992	unknown	inactive	
Bell Gas	2200 Isleta NE	Albuquerque	Bernalillo	35.08241	-106.67648	Spill, leaking tank	6/2/1995		inactive	

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Bernalillo County E. Mountain Transfer Station	I-40 and Zuzak Exit	Tijeras	Bernalillo	35.089549	-106.372506	TPH soil contamination	Apr-91	soil borings, soil, domestic well samples collected. All ND	closed	7/19/1999
Bernalillo County Equipment Yard	Edith and Ritchfield NW	Albuquerque	Bernalillo	35.08241	-106.67648	diesel contaminated soil	pre 9/98	soil excavation	closed	11/10/1998
Big Chief Fina	9700 2nd Street NW	Albuquerque	Bernalillo	35.134801	-106.638023	TPH in soils and PSTB site	unknown	soil excavation of surficial soil contamination, referred to PSTB	closed	10/1/2007
BNSF Trumbull Spill	100 Trumbull Ave SW	Albuquerque	Bernalillo	35.068288	-106.651047	150 gal of used oil spilled during offloading	6/26/1999	soil excavation	closed	8/26/1999
Bogan Ave Contaminated soil	Tract 5-A-1, Reindeer Addition	Albuquerque	Bernalillo	35.135729	-106.600827	during excavation contaminated soil was discovered	pre 4/7/97	soil excavated, some capped with asphalt	closed	9/23/1997
Brake Masters	1200 Juan Tabo NE	Albuquerque	Bernalillo	35.092261	-106.51471	Historic spill of hydraulic oil from pressure release lines	pre 9/6/2016	Lifts taken out of service, soil removal, cleaning of impermeable surfaces	closed	11/23/2016
Brothers Plating Co.	6817 4th St NW	Albuquerque	Bernalillo	35.158502	-106.637733	metal contaminated soil	Feb-92	SOS- Emergency Removal	closed	6/14/1992
Cal Gas Propane Co	4120 Broadway SE	Albuquerque	Bernalillo	35.08241	-106.67648	analytical data	unknown	results indicate below standards	closed	
Cal-Maine Egg Farm	9100 Broadway SE	Albuquerque	Bernalillo	34.953753	-106.669908	Nitrate, chloride, sulfate and TDS loading to soil and groundwater from excess chicken manure and egg washing	unknown	Multiple investigations and wells installed	referred to VRP	1/6/2017
Candelaria Well #3	3715 Edith NE	Albuquerque	Bernalillo	35.08241	-106.67648	citizen complaint of hydrocarbon odor after well cap had been removed	8/31/1992	analytical results showed ND	closed	
Capital Recycling	2330 2nd Street SW	Albuquerque	Bernalillo	35.068489	-106.652231	contaminated soil near AST	pre 8/15/94	soil excavation	closed	8/24/1994
Carmuel NO3	115 Coyote Springs	Albuquerque	Bernalillo	35.08241	-106.67648	non-point source showing NO3 in domestic wells	unknown	sample domestic wells	inactive	
Carmuel-Dead Man's Curve (Hertzler well)	37 Atencio Rd	Carmuel	Bernalillo			gas, MTBE, nitroaromatics, NO3	pre 1988	CERCLA/PSTB investigation	referred	
Casa Chevrolet and Collision One	7201 and 7501 Lomas NE	Albuquerque	Bernalillo	35.087312	-106.564159	vehicle hydraulic lift leaks	pre 8/5/98	soil borings and concrete cap	closed	1/12/1999
CCI U-Joints, Inc.	4220 Edith Blvd. NE	Albuquerque	Bernalillo	35.125422	-106.632451	TPH, DRO, benzo (a) pyrene and PCE detected in soil samples collected for a Phase 2 ESA	7/12/2010	direct push soil investigation	closed	2/2/2012
Charles D Payne Addition, BernCo water study	Coors Blvd and Coors PI	Albuquerque	Bernalillo	35.199515	-106.660823	evaluation of GW for contaminants	Aug-88	Study results	closed	
Childers Manufacturing	6th Street and Bezemek Ave.	Albuquerque	Bernalillo	35.104392	-106.650663	water heater manufacturer discharged into a dry well	pre 1995	soil excavation, GW monitoring	closed	6/26/1998
City of ABQ Sewer line break, KAFB	Tijeras Arroyo Sanitary Sewer	Albuquerque	Bernalillo	35.02975	-106.57199	interceptor line collapse spilling raw sewage	5/6/2004	replace line, excavate soil, soil samples to 40'	closed	1/26/2005
Clubhouse Inn	1315 Menaul NE	Albuquerque	Bernalillo	35.109211	-106.629927	Phase 2 showed TPH soils	pre 5/98	MW and soil samples collected. ND in GW. Site overlaid with asphalt	closed	8/24/1998
CNM (formerly TVI) Paint shop	525 Buena Vista SE	Albuquerque	Bernalillo	35.076746	-106.624129	Limited Phase 2 showed low levels of metals in soil from dry well discharges.	unknown	review of Phase 2 did not show any significant vadose zone contamination	closed	5/1/2010
Conoco Phillips North (currently Holy Energy), Albuquerque, NM	4036 Broadway SE	Albuquerque	Bernalillo	35.08241	-106.67648	Discovery of soil and ground water contamination with petroleum products at Bulk Terminal in early 90s and subsequent releases	pre 1990s	air sparging, SVES, MNA	closed	9/11/2012
Continental Express Trucking	I-40 and mile 150	Albuquerque	Bernalillo	35.08241	-106.67648	150 gal of diesel spill	12/30/1994	soil excavation	closed	1/27/1995
Coronado Center, Suite 900	6600 Menaul	Albuquerque	Bernalillo	35.111341	-106.64961	Oil water separator hydraulic fluid release discovery	unknown	soil excavation	closed	2/7/2014
Coronado Landfill	I-25 and Alameda	Albuquerque	Bernalillo			Low levels of TCE in ground water. City of Almq continues monitoring. Part of landfill excavated by private company under revolving loan fund.	unknown	GW monitoring	inactive	
Corrales Apple Orchard	Corrales Rd/ Camino de Lucia	Corrales	Bernalillo			Pesticide Application	pre-1996	CAR approval	closed	11/23/1998
Cottonwood Die Off, Margaret Armstrong	209 Villa Oriada	Corrales	Bernalillo	35.239335	-106.622588	GW investigation to determine if GW quality was impacting cottonwood die off	NA	sampling of 4 GW grab samples and domestic well. No GW impacts associated with tree die off	closed	7/19/2007
Cummings Southwest Albuquerque	NW corner of Broadway and McKnight Rd	Albuquerque	Bernalillo	35.103322	-106.642418	ESA identified petroleum releases to soil; groundwater impact detected caused by upgradient sources	unknown	Removal of petroleum contaminated soil during reconstruction of site	closed	9/4/2001
Custom Commercial Dry Cleaners	8915 Adams St. NE	Albuquerque	Bernalillo	35.187244	-106.595103	PCE soil vapor	unknown	natural attenuation/dissipation of soil vapor	closed	3/8/2022
Don Ward & Co. of New Mexico	Tijeras Canyon, Montoya School/ Ideal Cement	Tijeras	Bernalillo			Spill, AST leak	1988	sampled, school supply	inactive	6/11/1988

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Duke City Lumber	1224 Bellamah NW	Albuquerque	Bernalillo	35.10092	-106.659049	petroleum hydrocarbon release	unknown	soil excavation	closed	
Dunn Edwards Paint (Wellborn)	215 Rossmoor Rd SW	Albuquerque	Bernalillo	35.030661	-106.660389	Release from paint manufacturer's AST ad spills.	pre 2013	assessment	referred to VRP	1/26/2017
Earthgrains Baking Co.	111 Montaño NE	Albuquerque	Bernalillo	35.137631	-106.632703	hydraulic lifts in garage caused soil contamination	unknown	soil sampling and excavation	closed	1/21/2010
Ed Amonette	5715 El Prado NW	Albuquerque	Bernalillo	35.08241	-106.67648	Complaint	Oct-89	Sampled domestic well	closed	12/4/1989
El Barato Junk Yard	3010 Tower SE	Albuquerque	Bernalillo	35.08241	-106.67648	inspection to show pollution prevention for business license	Aug-00	inspection	closed	
Enchantment Electronics	500 Isleta SW	Albuquerque	Bernalillo	35.08241	-106.67648	phase 2 showed TPH	pre 2/2/02	soil borings and MW installed. Some diesel cont. soil @14 feet	closed	4/26/2002
Environmental Management	Woodward SE and 2nd Street	Albuquerque	Bernalillo	35.049505	-106.656767	traffic accident and 120 gal of diesel spilt	4/13/1999	soil excavation	closed	11/12/1999
Eppies Motorcycle Shop	7201 4th Street NW	Albuquerque	Bernalillo	35.149777	-106.639222	used oil spill	pre 2/05	soil excavation	closed	3/7/2005
Ernest Chavez Trucking	10508 Menaul NE	Albuquerque	Bernalillo	35.108892	-106.523512	truck accident spilt diesel	10/15/1992	soil excavation	closed	1/13/1993
Ever-Ready Oil Co.	101 Anderson SE	Albuquerque	Bernalillo	35.063036	-106.650331	AST overflow caused 1239 gal of diesel spill	5/12/1996	soil excavation, storm drain cleaning	closed	6/23/1996
Ever-Ready Oil Co.	4600 Edith NE	Albuquerque	Bernalillo	35.125944	-106.632281	unloading diesel spill cause 120 gal	1/22/1996	containing and absorbing spill	closed	3/20/1996
FFE Transportation Services Truck Accident	4911 Jefferson NE	Albuquerque	Bernalillo	35.137686	-106.593563	75 gal of diesel release from an accident	1/13/2000	absorbed fuel	closed	2/9/2000
Firestone Service Center	1912 2nd Street NW	Albuquerque	Bernalillo	35.103348	-106.645031	Soil contamination from Oil/Water Separator	2/1/2012	soil excavation	closed	7/27/2012
First Native American Corp.	609 Broadway NE	Albuquerque	Bernalillo	35.078583	-106.645694	possible UST trespassing plume	Mar-93	referred to PSTB	inactive	
Foley's Dept. Store	6600 Menaul NE	Albuquerque	Bernalillo	35.109054	-106.570941	hydraulic oil release from elevator	pre 2/16/00	soil excavation	closed	8/25/2000
Forke Bros. Auctioneers	13510 Central SW	Albuquerque	Bernalillo	35.068101	-106.497254	petroleum contaminated soil and sandblasting residue	pre June 99	soil excavation	closed	11/12/1999
Former Amity Leather	6700 Bluewater NW	Albuquerque	Bernalillo	35.086192	-106.713128	Soil vapor survey showed low levels of TCE	unknown	assessment	closed	3/13/2001
Former Dion's Pizza	5939 4th Street NW	Albuquerque	Bernalillo	35.143138	-106.640452	A limited Phase 2 showed TPH at 20 feet in subsurface	unknown	Additional sampling showed no further contamination	closed	7/13/2011
Former Friendly Cadillac site	1601 Central NE	Albuquerque	Bernalillo	35.090344	-106.665	hydraulic lift contaminated soil	pre 3/92	given dtw and TPH concentrations @ 30 ft, no excavation was required	closed	3/1/1992
Former Pintura Paint	6536 4th Street NW	Albuquerque	Bernalillo	35.149059	-106.639207	fire fighting waste water had VOCs	7/16/1996	soil excavation and MW installation; ground water was below standards	closed	3/30/1998
Former Woody's Truck Stop	Sedillo Hill	Sedillo	Bernalillo	35.092049	-106.285778	petroleum hydrocarbon spill AST	1986	CAR	closed	6/8/1986
Fox Candelaria	2501 Candelaria NE	Albuquerque	Bernalillo	35.115653	-106.616697	Superfund SI conducted from past solvent release	pre 2/2/05	sample MW, clean	closed	9/15/2005
Francis Home - VOC Vapors	8404 Rio Verde Pl, NW	Albuquerque	Bernalillo	35.179006	-106.681763	Low levels of BTEX and Cl solvents found in soil vapor at private residence	unknown	additional soil vapor sampling showed detections but very low to not warrant further corrective action.	closed	2/3/2012
Friedman Recycling	5020 Edith Blvd.NE	Albuquerque	Bernalillo	35.13204500	-106.63263100	Discharge of mil-spec AFFF that contains PFAS	9/29/2020	subsurface investigation / sampling	closed	3/11/2022
Frito Lay	1550 Mission Ave	Albuquerque	Bernalillo	35.140284	-106.60812	Spill, motor oil	12/15/2000	CAR approval	closed	2/20/2001
Gallegos, Michael domestic well	PO Box 11, Star Route	Albuquerque	Bernalillo			domestic well sample taken	unknown	samples showed ND and installed new well	closed	
Gardner Zemke	4600 Lincoln	Albuquerque	Bernalillo	35.142028	-106.592131	Discovery of Chlorinated Solvents in Soil	1994	Soil Vapor analysis	closed	7/1/1998
GE Apparatus	4420 McLeod Road NE	Albuquerque	Bernalillo	35.13662	-106.5957	PCB's, metals and Chlorinated solvents discovered in soils	unknown	soil excavation and GW monitoring	referred to EPA / closed	2006
GE Aviation Plan Building 9 Oil Sump Pit	Woodward and Broadway SE	Albuquerque	Bernalillo	35.048847	-106.646552	oil sump with TPH	unknown	assessment and soil remov	closed	4/14/2008
GE Plant		Albuquerque	Bernalillo			Cutzon WS5050 coolant spill	Nov-87	see CERCLA file	referred	
General Waste	3049 Edith NE	Albuquerque	Bernalillo	35.115461	-106.634997	discovery of petroleum stained soil in 4/03	unknown	soil excavation and samplin	closed	9/1/2003
Giant Mid-Continent - Apr '04 Diesel Spill	3209 Broadway Blvd SE	Albuquerque	Bernalillo	35.045118	-106.64833	Reversed valve seat allowed release of 5200 gallons of diesel. 5000 gallons recovered with remaining in soil	4/29/2004	soil excavation	closed	12/10/2004

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Giant Mid-Continent - Sep 05 Spill	3209 Broadway Blvd SE	Albuquerque	Bernalillo	35.045118	-106.64833	Overfill of tank 25930, release of 500 gal unleaded gasoline.	9/26/2005	soil excavation	closed	
Giant Mid-Continent - Sep 05 Spill	3209 Broadway Blvd SE	Albuquerque	Bernalillo	35.045118	-106.64833	Leak from pressure activated valve of tank 25931. Loss of 5-10 gallons of unleaded gasoline	2/28/2005	soil excavation		
Gino's Restaurant & Lounge	1401 Coors SW	Albuquerque	Bernalillo	35.100503	-106.707039	Sampling, nitrate	pre 92		inactive	
Gino's Restaurant and Lounge	unknown	Albuquerque	Bernalillo			high NO3 in water sample	pre 93	installed treatment system	closed	
Graves Oil and Butane	105 Dale Ave SE	Albuquerque	Bernalillo	35.08241	-106.67648	Adjacent RekChem site disposed of hazardous waste in UST	pre 7/90	UST was emptied and removed; soil samples below showed no contamination	closed	6/12/1992
Groendyke Aviation fuel spill	6346 St Rd 47	Albuquerque	Bernalillo	34.985046	-106.655357	tanker truck accident and 3000 gal spill	7/11/2005	soil excavation	closed	11/8/2005
Gulfstream Lomas	111 Lomas NW	Albuquerque	Bernalillo	35.09081	-106.646922	BTEX reportedly found in well	unknown	no source found and 6 MWs installed with MNA as abatement	closed	12/11/2009
Harrison Contractors	4201 Broadway SE	Albuquerque	Bernalillo	35.08241	-106.67648	Complaint	May-87	sampled domestic wells	closed	5/1/1987
Hertz Co.	3601 Osuna	Albuquerque	Bernalillo	35.154279	-106.602679	50 gal of gasoline spilt from AST	4/1/1998	soil excavation	closed	5/15/1998
Holiday Park Cleaners	2917 Juan Tabo NE	Albuquerque	Bernalillo	35.115684	-106.516069	PCE soil vapor	unknown	natural attenuation/dissipation of soil vapor	closed	2/1/2021
Honeywell	8500 Bluewater Rd NW	Albuquerque	Bernalillo	35.082083	-106.726552	non-PCB transformer oil leak	9/15/1998	soil excavation	closed	12/22/1998
Hutchinson Fruit Co. (same as Sun Valley Fruit Co)	7110 2nd Street NW	Albuquerque	Bernalillo			petroleum hydrocarbon contaminated soil	pre 9/91	Phase 2 ESA report	closed	see Sun Valley Fruit Co. 2006
I-25 Gasoline Spill	I-25, 2.5 miles N of Tramway on Sandia Pueblo	Albuquerque	Bernalillo	35.238766	-106.569257	a Truck accident caused a 2000 gal release of gasoline	10/31/1990	soil excavation, passive soil vapor extraction, GW monitoring	closed	post 7/93. Pueblo had jurisdiction
I-40 Frontage Rd in Carnuel	16908 E. I-40 Frontage Rd	Albuquerque	Bernalillo	35.08241	-106.67648	Limited Phase 3 showed TPH in soil at a maximum concentration of 180 ppm.	unknown	soil results showed no threat to GW	closed	11/1/2008
Idaho Timber LLC	6300 St Hwy 47	Albuquerque	Bernalillo	34.985448	-106.655271	during Phase 2 ESA contaminated soil was encountered @ 50'	pre 5/3/06	MW show GW was clean	closed	7/14/2006
Illegal dumping of used oil drums	east of 98th and I-40	Albuquerque	Bernalillo			illegal dumping of 6 drums caused used oil discharge	12/4/2000	soil excavation by property owner	closed	2/9/2001
Ink Spot		Bernalillo	Bernalillo			lined wastewater pond was removed	pre 1997	sampling below liner showed clean soils	closed	8/7/1997
Isleta & Don Felipe SW USGS Monitor Well	Isleta & Don Felipe	Albuquerque	Bernalillo	34.992126	-106.695641	Well contamination (isopropyl toluene), USGS, SOS	Dec-94	CERCLA screen	inactive	
Jack's Auto Parts	4320 Broadway SE	Albuquerque	Bernalillo	35.08241	-106.67648	burying of used oil and antifreeze	pre 12/00	soil excavation	closed	3/30/2001
JB Cleaners	1615 Eubank NE	Albuquerque	Bernalillo	35.098395	-106.532883	during Phase 2 ESA PCE found in soil vapor	pre 1/4/06	soil vapor samples and calculations showed no potential to contaminate GW @ 600'	closed	4/16/2006
JF McGill Contracting Co (emulsified asphalt plant)	4959 Edith NE	Albuquerque	Bernalillo	35.08241	-106.67648	petroleum contaminated soil	pre 95	soil excavation per Fire Marshall	closed	6/17/1995
JM Thomas Forest Products	5851 Edith NE	Albuquerque	Bernalillo	35.08241	-106.67648	250 gal diesel fuel release	8/18/2003	soil excavation	closed	9/26/2003
JMF Transmission CO	6629 Lomas NE	Albuquerque	Bernalillo	35.087357	-106.573781	vehicle hydraulic lift releases	pre 2006	soil sampling	closed	12/8/2006
Joe's Trucking	SR S. 14, 1/4 mile S of Buckboard Rd	Tijeras	Bernalillo	35.089549	-106.372506	370 gal of diesel spilt when AST tipped over	5/31/1994	soil excavation	closed	6/30/1994
JR Hale Contracting	505 Carmony Rd NE	Albuquerque	Bernalillo	35.127841	-106.623706	TPH soil contamination from a Phase 2 ESA	pre 3/30/05	soil excavation	closed	7/30/2007
KAFB / SNL Burn Site	Lurance Canyon Burn Site	Albuquerque	Bernalillo	35.00513	-106.409207	SNL fuel burning testing facility - BTEX, PAH, NO3, perchlorate contamination in ground water, site is called Burn Site Groundwater (BSG)	unknown	HWB RCRA permit oversight	referred	
KAFB /SNL HCL Release	Bldg. 858, NE Section of SNL Tech Area 1	Albuquerque	Bernalillo	35.049856	-106.536783	discovery of HCL release from an acid tank	4/10/2000	neutralization of soil	closed	4/24/2000
KAFB BFF accidental soil release	south of Randolph Road, in situ bioremediation plot	Albuquerque	Bernalillo	35.050654	-106.577978	release of 0.25 to 0.5 CY of semi-saturated soil cuttings from drilling KAFB-106MW2	43490	soil excavation	closed	3/8/2017
KAFB BFF Condensate Release	Fuels Drive	Albuquerque	Bernalillo	35.049858	-106.579153	30 gallons of a mixture of water and condensate were released during the dismantling of an SVE system	2/1/2017	soil excavation	closed	11/28/2017
KAFB BFF Drilling fluids leak, KAFB-106239	BFF IDW yard, south of Ridgecrest Drive SE	Albuquerque	Bernalillo	35.050625	-106.568784	50 gallon leak of drilling fluid (water) from lined roll-off	3/20/2017	soil excavation	closed	4/28/2017
KAFB BFF Well development water KAFB-106239	Ridgecrest Drive SE just east of San Pedro Drive	Albuquerque	Bernalillo	35.054816	-106.576549	Spill of 150 gal of well development water from KAFB-106239	1/8/2017	soil excavation	closed	3/17/2017
KAFB Bldg. 20220	Kirtland Air Force Base	Albuquerque	Bernalillo	35.0548	-106.5568	sewage overflow at Bldg. 20220	1/19/2000	sewage recovery and disinfection	closed	4/18/2000
KAFB Dielectric oil release	arroyo north of High Energy Research Technology Facility	Albuquerque	Bernalillo	34.974	-106.446	release of 10 gal of oil	8/22/1995	soil excavation	closed	6/17/1995
KAFB Fuel Depot (also called Bulk Fuels Facility)	Fuels Drive & Randolph Drive, Kirtland Air Force Base, Albuquerque, New Mexico	Albuquerque	Bernalillo	35.050229	-106.57928	Aviation gasoline discharges caused vadose zone and GW contamination with LNAPL to 500 ft bgs.	unknown	SVES since 2000 and LNAPL recovery since 2007. HWB assumed regulatory oversight in 2010 by RCRA Permit	referred	

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
KAFB Golf Course Pond Cleaning Coolant Leak	KAFB Golf Course Pond	Albuquerque	Bernalillo	35.023396	-106.528257	Spill of ~2.5 gallons of water and ethylene glycol from vehicle	7/11/2017	soil excavation	closed	8/11/2017
KAFB Hangar 1002	SW of Randolph Drive and San Mateo Boulevard	Albuquerque	Bernalillo	35.0493	-106.5888	water line break flowed to oil water separator, releasing water and petroleum product into Tijeras arroyo	8/8/1999	OWS cleaning and soil sampling	closed	10/29/1999
KAFB heating oil	Manzano Administration Area	Albuquerque	Bernalillo	35.0071	-106.5049	closure and capping of old heating oil lines	n/a	closure of lines and soil sampling was ND	closed	6/1/1996
KAFB McCormick Ranch	McCormick Ranch, SW corner of base	Albuquerque	Bernalillo	34.9548	-106.5771	use of NH4-NO3 for explosives	unknown	HWB RCRA permit oversight	referred	
KAFB MH-13 Sewage Release	KAFB	Albuquerque	Bernalillo	35.04956389	-106.56965	Sewage Release from Manhole 13 due to root intrusion impacted a MW with nitrate	unknown	MNA	cl	11/30/2022
KAFB NC-135	Short and Randolph Drive	Albuquerque	Bernalillo	35.049927	-106.582633	Spill of diesel or jet fuel	10/20/2017	soil excavation	closed	3/15/2018
Karen Box property	204 Murry SE	Albuquerque	Bernalillo	35.08241	-106.67648	old MWs from a LUST site showed PCE ~30	pre 8/31/04	PSTB conducted further investigation and PCE attenuated to below stds.	closed	11/9/2006
Keers Environmental	1701 Broadway SE	Albuquerque	Bernalillo	35.066636	-106.645543	truck accident caused 20 gal of diesel release	8/24/1999	soil excavation	closed	1/13/2000
Kelley's Transmission	1816 Central SW	Albuquerque	Bernalillo	35.091666	-106.666658	vehicle hydraulic lift releases, and oil water separator releases	pre 4/05	12 lift removals, OWS removal, soil excavation, MW sampling	closed	3/23/2007
KKOB Transmitter site	2nd Street NW Transmitter location	Albuquerque	Bernalillo	35.08241	-106.67648	vandalism caused 25 gal of diesel spill	3/20/1997	soil excavation	closed	7/8/1997
K-Mart Automotive	4th Street and Menaul	Albuquerque	Bernalillo	35.110931	-106.646553	hydraulic lifts in garage caused soil contamination	pre 1999	soil excavation	closed	11/19/1999
Larry H Miller Commercial Property	8528 Lomas NE	Albuquerque	Bernalillo	35.087296	-106.551516	During building demolition hydraulic lift contamination found	unknown	soil excavation and capping	closed	9/23/2011
Layton Bros. Drums	608 General Chenaut	Albuquerque	Bernalillo	35.068411	-106.544423	drum cleaning and recycling center had sump with possible leakage	9/6/1984	samples showed no evidence of soil contamination and disposal according to HWB regs	closed	6/13/1985
Leatherback	100 Trumbull Ave SE	Albuquerque	Bernalillo	35.067341	-106.649666	Petroleum impacted soil discovered during property transfer, likely from historical tar paper manufacturing	before 1998	Monitoring wells did not show contamination	closed	3/6/2001
Lee's Automotive	2401 Wyoming Blvd NE	Albuquerque	Bernalillo	35.111214	-106.551176	Spill from 5 hydraulic lifts	11/22/2016	soil excavation	closed	1/31/2017
Lewis St Sewer Line Overflow	Lewis Av. Between Arno and Broadway	Albuquerque	Bernalillo	35.07157	-106.644984	1.2 million gallons of sewer overflow into stormwater pond	3/14/2007	pump sewage to WWTP	closed	5/25/2007
Lobo Engine	900-902 2nd Street NW	Albuquerque	Bernalillo	35.076582	-106.65081	soil investigation showed TPH	pre 95	soil borings and MW showed below stds	closed	6/17/1995
M&S Chevron	5640 4th Street	Albuquerque	Bernalillo	35.13912	-106.641125	release of 242 gal of gas during UST filling discharging into storm drain	7/17/2002	pumping of 30000 gal of water to storm drain to clean	closed	11/1/2002
Martinez Town Sewage Spill	Arno and Edith NE	Albuquerque	Bernalillo	35.08241	-106.67648	Stormwater flowed into sewer line causing overland flow	7/31/2006	Repaired stormwater line that flowed into sewer line and soil excavation	closed	6/7/2010
Mary Medina MB Oil	119 Marlowe Lane NE I-40 MM 151	Albuquerque	Bernalillo	34.166233	-106.026069	Sampling, private well	5/21/1987	sampled well	inactive	
McDonalds	Eubank and Candelaria	Albuquerque	Bernalillo	35.072592	-106.773154	truck accident released 1000 gal of diesel	1/6/1999	soil excavation	closed	5/24/1999
McDonalds	Eubank and Candelaria	Albuquerque	Bernalillo	35.116175	-106.533236	subsurface investigation showed low levels of acetone	Aug-90	soil sample results showed no threat	closed	1/10/1991
MCT Industries	I-25 and Stadium (Cesar Chavez)	Albuquerque	Bernalillo	35.08241	-106.67648	150 gal of diesel spill	6/8/1994	absorbed fuel	closed	7/26/1994
Melloy Dodge Commercial Property	1200 Lomas NE	Albuquerque	Bernalillo	35.092014	-106.631305	Limited Phase 3 showed TPH in soil.	unknown	soil excavation and soil samples collected to depth.	closed	4/5/2010
Mesa del Sol Landfill	S. Broadway Landfill, E of I-40 S of Tijeras Arroyo	Albuquerque	Bernalillo	35.01053	-106.635418	former landfill	unknown	closure under SWB	referred	
Montessa Park Convenience Center	3512 Los Picaros SW	Albuquerque	Bernalillo	35.08241	-106.67648	during fueling and lubrication of vehicles, petroleum hydrocarbon was discharged	pre 94	soil excavation	closed	6/16/1994
Motor Cargo	11030 Cochiti SE	Albuquerque	Bernalillo	35.069977	-106.524471	Spill, hydrazine	3/6/2000	CAR approval	closed	6/30/2000
North Albuquerque Acres Landfill	Elena Dr and Barstow, NE	Albuquerque	Bernalillo	35.08241	-106.67648	Developer conducted excavation from former landfill under SWB regulations	unknown	Neighbors were concerned with landfill exposure and ground water concerns. Subsequent sampling showed no soil contamination	closed	1/1/2007
Oil Sludge Disposal Trenches	5100 Broadway SE	Albuquerque	Bernalillo	35.004338	-106.649403	discovery of TPH-tar disposal trenches	1980s	soil excavation	closed	11/9/2010
One Executive Center/ WHEXC	8500 Menaul Blvd. NE	Albuquerque	Bernalillo	35.109187	-106.549626	Spill, elevator hydraulic leak	1/4/2000	CAR approval	closed	2/7/2000
One Park Place	2125 Louisiana NE	Albuquerque	Bernalillo	35.10026	-106.568829	Spill, elevator hydraulic leak	9/27/2000	CAR approval	closed	10/10/2000
Pam Ebeltoft	509 Jefferson SE	Albuquerque	Bernalillo	35.072814	-106.593405	Complaint	3/9/2000	inspection/letter	closed	4/12/2000
Pep Boys Store #696	5651 San Mateo NE	Albuquerque	Bernalillo	35.144001	-106.586535	hydraulic lift contaminated soil	pre 2000	soil excavation	closed	2/7/2000
Petroglyph Plaza Dry Cleaner	8201 Golf Course Rd	Albuquerque	Bernalillo	35.177291°	-106.688349°	Chlorinated solvent release	unknown	Soil vapor extraction	closed with conditions	5/20/2021

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Phillips Semi Conductor	9201 Pan American Freeway	Albuquerque	Bernalillo	35.188273	-106.580418	subsurface investigation showed low levels of chlorinated solvents	unknown	contamination related to a former landfill, HWB jurisdiction	referred/closed	
Placitas Pipeline Spill/Cedar Creek	Cedar Creek Subdivision	Placitas	Bernalillo	35.331468	-106.448952	Spill, jet fuel	12/1/1999	CAR approval, trans to SWQB	transferred	7/7/2002
PNM Albq. Service Center	4201 Edith NE	Albuquerque	Bernalillo	35.125488	-106.634609	leak from UST line	1986	referred to PSTB	referred	
PNM Albq. Service Center	4201 Edith NE	Albuquerque	Bernalillo	35.125488	-106.634609	petroleum hydrocarbon contaminated soil	pre 1995	soil excavation	closed	6/17/1995
PNM Manufactured Gas Plant	Central and John St.	Albuquerque	Bernalillo	35.083824	-106.645877	old MPG plant discovered	pre 1950	major soil excavation	closed	6/26/2002
PNM Person Generating Station	3800 Broadway Blvd SE	Albuquerque	Bernalillo	35.027618	-106.642479	Multiple releases of chlorinated, petroleum and metals	various	Remediation via RCRA Permit	referred to HWB	
PNM Reeves Station	4400 Paseo del Norte NE	Albuquerque	Bernalillo	35.170482	-106.601132	alleged PNM landfill with possible drums	pre 94	soil vapor survey and 3 MWs installed showed no stds violation	closed	6/17/1996
Ponderosa Products Inc.	1701 Bellamah St. NW	Albuquerque	Bernalillo	35.100827	-106.664441	Discharge, WW/nitrates, formaldehyde	1/16/1984	Settlement agreement, 1/4 sampling	closed	2/2/2002
Postal Service Main Yard	1135 Broadway NE	Albuquerque	Bernalillo	35.072184	-106.645711	tar release from old tank	pre 1980	soil excavation	closed	6/20/2001
Presbyterian Hospital Energy Center	1100 Central SE	Albuquerque	Bernalillo	35.082586	-106.636228	transfer of diesel caused 50 gal release	4/17/2000	soil excavation	closed	5/17/2000
Prime Inc.	4531 Wyoming NE	Albuquerque	Bernalillo	35.131112	-106.551064	truck accident and 150 gal of diesel split	10/27/1997	soil excavation	closed	2/20/1998
Pronto Service Co.	1107 Coors SW	Albuquerque	Bernalillo	35.098989	-106.707658	PCB oils contaminated soil	pre 1982	soil excavation and GW monitoring	closed	6/5/1985
Pronto Waste Oil Recycling	4700 Broadway St. SE	Albuquerque	Bernalillo	35.08241	-106.67648	Spill, PCBs	1983	EPA Removal	closed	6/5/1983
Quality Jeep Eagle Chrysler Plymouth	8101 Lomas Blvd	Albuquerque	Bernalillo	35.087382	-106.556788	hydraulic lift contaminated soil	pre 95	lift removal and soil excavation	closed	4/4/1996
Quality Pontiac	1300 Lomas NE	Albuquerque	Bernalillo	35.091873	-106.629952	petroleum hydrocarbon contaminated soil	pre 2001	soil and soil vapor sampling showed no threat to GW or human exposure	closed	3/1/2003
Quality Pontiac	1300 Lomas NE	Albuquerque	Bernalillo	35.091873	-106.629952	Demolition of buildings on property	NA	Removal of hydraulic lifts and Oil-Water Separator - No contamination noted.	closed	3/31/2014
Ray's Automotive	1909 4th Street NW	Albuquerque	Bernalillo	35.103998	-106.64797	during solvent investigation in area the auto shop had visual discharge areas. 2 MWs were installed to determine if site was a source.	unknown	analytical results from upgradient MW showed the site was not a source of the solvent plume.	closed	9/28/2006
REK Chem- Graves Oil	105 Dale St.	Albuquerque	Bernalillo	35.004	-106.6611	Illegal Dumping	1988	UST removed, legal action	semi-orphan	
Ritchie Bros. Auctioneers	Alameda and Edith NE	Albuquerque	Bernalillo	35.192186	-106.603756	petroleum contaminated soil and sandblasting residue	pre 1998	soil excavation	closed	3/5/2001
Robert's Oil Truck Accident	Broadway and Rio Bravo	Albuquerque	Bernalillo	35.08241	-106.64664	truck accident lost 8700 gal of gas	4/14/1999	soil excavation	closed	7/21/1999
Robert's Oil Truck Accident	Gibson and Mulberry	Albuquerque	Bernalillo	35.059182	-106.635439	2000 gal of gasoline spill	9/30/1995	soil excavation	closed	3/30/1996
Rubi's Metals, Inc.	2227 Mayflower Rd	Albuquerque	Bernalillo	35.08241	-106.67648	high Pb in shop and concern over employee exposure. 40ft well on-site showed 6.41 ppb Pb.	pre 1981	testing of blood.	inactive	
Rust Tractor	4000 Osuna Rd NE	Albuquerque	Bernalillo	35.151456	-106.623269	diesel spill into unlined pond	Jul-85	inspection	closed	6/7/1985
Rust Tractor	4000 Osuna Rd NE	Albuquerque	Bernalillo	35.151456	-106.623269	old evaporative lagoon showed hydrocarbon contamination	pre 1988	soil excavation and boring to 100 feet was clean	closed	6/8/1997
Sacramento Landfill	Paseo del Norte and I-25	Albuquerque	Bernalillo	35.17429	-106.583738	Triage scoring showed medium concern for bldg. of Albq. Sports Store	pre 95	triage score and letter	inactive	7/11/1995
Safety Clean Truck Accident	Hwy 66, off I-40 East	Albuquerque	Bernalillo			Truck accident discharged waste oil.	5/7/1996	soil excavation	closed	
San Jose Community Awareness Council Private well survey	San Jose Community	Albuquerque	Bernalillo	35.08241	-106.67648	sampling to evaluate VOC impacts in domestic wells		results showed no VOC impacts	closed	10/1/1992
Sanchez Well	2138 Raymac Rd	Los Padillas	Bernalillo	34.166233	-106.026069	Sampling, private well	9/26/1983	results showed no impact	closed	6/5/1983
Sandia Dye and Cartridge/Herzler	37 Atencio Rd	Carnuel	Bernalillo	35.062357	-106.455818	petroleum and arms wastes may have been introduced in a domestic well	pre 1995	soil and site assessment	closed	2/5/1997
Sandia Peak Services	Primrose Lift Station	Albuquerque	Bernalillo			25,000 gal of sewage overflow	11/2/1994	soil excavation and disinfection	closed	1/1/1995
Sandia Peak Services	Primrose Lift Station	Albuquerque	Bernalillo			5000 gal of sewage spill from lift station malfunction	8/10/2000	pump to Albq. WWTP and soil disinfection	closed	1/8/2001
Sandia Peak Services	Tennyson and Tramway	Albuquerque	Bernalillo			400 gal of sewage spill due to pump failure	12/12/1999	soil disinfection	closed	4/21/2000
Seven Bar Airport	Cottonwood Mall	Albuquerque	Bernalillo	35.08241	-106.67648	petroleum hydrocarbon spill	1990?	soil excavation	closed	2/27/1995
SHB Agra	4700 Lincoln NE	Albuquerque	Bernalillo	35.141957	-106.590893	use of solvents and soil investigation	pre 1994	soil survey and soil gas sampling showed no impacts	closed	6/20/1996
Sigma Minerals Corp	UNM South Golf Course Landfill	Albuquerque	Bernalillo			Lab and Milling Co Disposed of residual ore and waste in landfill	pre 1957	data did not show contamination concern	closed	
Smith's Fuel Center	111 Coors NW	Albuquerque	Bernalillo	35.083232	-106.710796	During pre-construction for a gas station TPH soils were encountered in the parking lot run off depression.	unknown	soil excavation and sampling	closed	9/24/2008

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Soil Contamination	Eubank and Candelaria	Albuquerque	Bernalillo	35.116175	-106.533236	discovery of petroleum contaminated soil from UST	pre 2/22/90	refer to PSTB	referred	
Solv-Ex	2121 Menaul NE	Albuquerque	Bernalillo	35.109218	-106.621611	shallow surface contaminated with petroleum hydrocarbons		direct push soil investigation	closed	10/31/2005
South Valley Livestock Auction	7715 Broadway SE	Albuquerque	Bernalillo	34.977911	-106.659444	domestic well samples showed elevated nitrates.	unknown	well results showed nitrate above standards	inactive	
South Valley Superfund Site	Woodward and Broadway SE	Albuquerque	Bernalillo	35.048847	-106.646552	Chlorinated solvents found in City productions well	unknown	referred to Superfund	referred	
Southern Pueblo Agency	1881 8th St	Albuquerque	Bernalillo	35.103592	-106.654348	Maintenance yard with AST and TCE in MWs	2000	NOD sent 6-00	inactive	
Southwest Energy Distributors	Broadway and Rio Bravo	Albuquerque	Bernalillo	35.08241	-106.67648	truck accident at intersection caused release of 4,100 gallons of diesel	4/1/1997	soil excavation	closed	5/15/1997
Steamatic Commercial Property	3007 San Pedro NE	Albuquerque	Bernalillo	35.116479	-106.577708	PCE discovered in soils on-site	pre 1996	small SVES operation.	closed	7/14/1996
Steer Tank Lines	4508 Broadway SE	Albuquerque	Bernalillo	35.08241	-106.67648	diesel contaminated soil	pre 99	soil excavation	closed	1/22/2001
Sun Valley Fruit Co	7110 2nd Street NW	Albuquerque	Bernalillo			Phase 2 ESA showed VOCs in soil	pre 8/30/06	soil excavation	closed	9/22/2006
Sunbell Property	7500 Bluewater NW	Albuquerque	Bernalillo	35.085384	-106.717135	jewelry and plating shop showed metals and solvents in vadose zone	pre 1990	soil venting with SVES and GW monitoring	closed	12/3/1999
Sundance Mechanical & Utility Co.	San Diego and San Mateo	Albuquerque	Bernalillo	35.193194	-106.5865	truck accident lost 300 gal of diesel	4/21/2000	soil excavation	closed	8/8/2000
Sunport Transportation Corridor Study	Woodward and I-25	Albuquerque	Bernalillo	35.08241	-106.67648	study of South Valley Superfund site and Chevron Bulk Terminal wells to be abandoned if new interstate exit is built.	NA	study still in progress		
Sunshine Buick	2801 Carlisle	Albuquerque	Bernalillo	35.112989	-106.60425	hydraulic lift contaminated soil	pre 6/22/1995	soil excavation and hydraulic lift removal	closed	6/20/1995
Sunshine Buick - Expertech	5501 McLeod and 5200 San Mateo	Albuquerque	Bernalillo	35.13865	-106.584151	hydraulic lift contaminated soil	pre 4/28/99	soil excavation and capping	closed	5/1/1999 and 5/23/14
Swift Transportation	I40- and Exit 158	Albuquerque	Bernalillo	35.08241	-106.67648	truck accident lost 100 gal of diesel	8/27/98	soil excavation	closed	6/20/1998
Texaco Bulk Plant (Former)	3209 Broadway SW	Albuquerque	Bernalillo	35.04603333	-106.64811944	diesel, gasoline - depth to water 20-30 feet bgs	1995	Soil Vapor Extraction System (closed), ground water pump and treat completed. Compliance monitoring completed. Agreement terminated with NMED and Chevron soil assessment and pipeline integrity showed no impacts to GW.	completed closed	3/23/2016
Trans World Airlines	Albq Airport	Albuquerque	Bernalillo	35.08241	-106.67648	site assessments showed jet fuel in soil	1988		closed	6/13/1988
Treeland Nursery	308 Osuna NE	Albuquerque	Bernalillo	35.08241	-106.67648	during Phase 2 contaminated soil was discovered	pre 97	soil excavation and no GW stds exceeded in MWs	closed	12/1/1998
Truly Nolan	510 Candelaria NE	Albuquerque	Bernalillo	35.116555	-106.634497	pesticide soil contamination discovered.	unknown	soil excavation and sampling	closed	3/15/2009
Twin Mountain Construction	Juan Tabo and I-40	Albuquerque	Bernalillo	35.076628	-106.515142	50 gal of hydraulic oil spill	7/9/1997	soil excavation	closed	9/26/1997
Twin Mountain Construction	Springer Track: Paseo del Norte, Alameda, Edith	Albuquerque	Bernalillo	35.08241	-106.67648	site assessment showed some metals and TPH in surface soils	7/1/1999	soil excavation	closed	6/21/1999
United Road	2501 University Blvd	Albuquerque	Bernalillo	35.111452	-106.62475	40 gallon of diesel spilled from ruptured saddle tank	8/29/2016	Sorbent applied to asphalt	closed	11/23/2016
UNM football stadium	Stadium and University	Albuquerque	Bernalillo	35.06847	-106.630898	gas spills from lawn equipment	pre 2001	soil excavation prior to building new stands	closed	2/15/2001
UNM Hospital	Lomas and Campus	Albuquerque	Bernalillo	35.08241	-106.67648	diesel supply line damaged and 120 gal spilled	1/14/1999	soil excavation	closed	2/26/1999
UNM Hospital Chill Water Tank	UNMH	Albuquerque	Bernalillo			chill water tank showed leaks and loss of Mn based coolant	pre 1995	GW monitoring	closed	6/18/1998
UNM South Golf Course	University and I-25	Albuquerque	Bernalillo	35.08241	-106.67648	well analysis to determine potential impacts from Persons Generating Station	NA	analytical results were below laboratory detection limits	closed	9/15/1994
UNM, Centennial Engineering Bldg.	CEC Bldg., near Martin Luther King Blvd, Redondo W. Dr.	Albuquerque	Bernalillo	35.083268	-106.625612	during construction hydraulic oil spill from equipment	pre 11/06	soil excavation	closed	2/14/2007
US Forest Service 12th St. Yard well	12th St	Albuquerque	Bernalillo	35.08241	-106.67648	phenols in FS well pre 1990	pre 1990	sampled in 97 and ND	closed	7/22/1997
US Postal Service	1135 Broadway NE	Albuquerque	Bernalillo	35.072184	-106.645711	spill of 50 gal of diesel	7/14/2000	soil excavation	closed	8/25/2000
US Postal Service	1135 Broadway NE	Albuquerque	Bernalillo	35.072184	-106.645711	During excavation for a new building footings, TPH contaminated soil was discovered.	unknown	soil excavation	closed	9/23/2008
Van Atta Holding Co.	1414 4th Street NW	Albuquerque	Bernalillo	35.098178	-106.648935	9 yards of petroleum contaminated soils	pre 1993	soil excavation	closed	9/13/1993
Vista Del Norte	Track T-4, Vista Del Norte, Atlas D-16-Z	Albuquerque	Bernalillo			discovery of petroleum contaminated soil	pre 4/26/06	soil excavation	closed	5/12/2006
Waste Management	Hwy 217, 3 mile S of Hwy 66	Sedillo	Bernalillo			truck accident caused 160 gal diesel spill	11/2/1998	soil excavation	closed	12/14/1998

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
West Mesa Petrol Yard	8502 Volcano NW	Albuquerque	Bernalillo	35.076393	-106.72811	Petroleum tank removal	8/16/1991	tank removal	referred	
Western Disposal	5014 Broadway SE	Albuquerque	Bernalillo	35.08241	-106.67648	discovery of TPH-tar disposal trenches	1980s	soil excavation	closed	11/9/2010
Western Refining	3209 Broadway SE	Albuquerque	Bernalillo	35.114345	-106.6369	pin hole in commingle pipeline release discovered in 3/07 at bulk fuel terminal	unknown	soil excavation	closed	12/14/2012
Western Refining - Ethanol	3209 Broadway Blvd SE	Albuquerque	Bernalillo	35.045118	-106.64833	Tracer test of tank indicated failure, no evidence of release.	7/18/2007	AST repair	closed	7/3/2008
Western Refining (former Chevron) Asphalt Plant	2050 S. 2nd Street SW	Albuquerque	Bernalillo	35.064819	-106.652507	discovery in late 80s of LNAPL on GW	unknown	SVES, soil excavation, LNAPL recovery and monitoring under a settlement agreement	closed	1/8/2013
Western Truck School	424 Kinley Ave NE	Albuquerque	Bernalillo	35.096732	-106.641183	hydrocarbon soils discovered	pre 91	soil excavation	closed	7/31/1997
Windmill Ranch	6400 Coors Blvd	Albuquerque	Bernalillo	35.163252	-106.67727	diesel contaminated soil	pre 97	passive SVES, GW monitoring	closed	5/4/1999
Wittler Automotive	121 Elizabeth NE	Albuquerque	Bernalillo	35.071307	-106.524898	Phase 2 ESA showed TPH in shallow soils	unknown	Soil analytical results showed no further corrective action needed	closed	8/23/2013
Woodward and 2nd Street, Groendyke Accident	Woodward and 2nd Street	Albuquerque	Bernalillo	35.049505	-106.656767	truck accident spilt 120 gal of diesel	4/13/1999	soil excavation	closed	11/12/1999
Zangara Dodge	8528 Lomas NE	Albuquerque	Bernalillo	35.086664	-106.551889	Phase I/ Phase II ESA conducted	Before 1996	Unknown	inactive	unknown
Galles Facility (former)	1601 Lomas Blvd. NE	Albuquerque	Bernalillo	35.091514	-106.626458	VOCs, PAHs from spills of petroleum hydrocarbons during years of operation (1963-2017). 10 acre site	unknown	soil excavation and SVES. Concurrent action performed under VRP (No. 53181004)	closed	3/5/2019
4321 Coors Boulevard SE - SCS Transport	4321 Coors Boulevard SE	Albuquerque	Bernalillo	35.01207700	-106.71689100	Spill of gasoline to surface of gas station due to auto running over drop hose to avoid police. Soil borings indicated no subsurface impacts	12/19/2019	Investigation	closed	10/21/2020
Sunport / PNM Transformer Fire	2200 Sunport Blvd SE	Albuquerque	Bernalillo	35.04937100	-106.62012400	Mineral oil discharge from transformer fire, PFAS contamination from AFFF discharge	12/21/2020	Vacuum residual fire suppression fluids, soil excavation, transformer removal	closed	3/4/2021
United Petroleum Transport - Broadway and I-25	Broadway SE	Albuquerque	Bernalillo	34.95313800	-106.66215700	2,300 gallon unleaded gasoline tanker spill	7/4/2019	Soil excavation and backfilling	closed	10/19/2021
West Direct Oil	Central and Locust	Albuquerque	Bernalillo	35.08180600	-106.63750400	diesel spill	8/18/2021	Soil excavation, collection and disposal of potentially impacted stormwater	closed	7/30/2021
NMDOT Datil	US 60 & NM 12	Datil	Catron	34.1449	-107.84289	PCE found in area monitor wells below WQCC standard	unknown	Nearby NMDOT facilities didn't use PCE. PSTB is investigating other facilities in area.	closed	4/11/2006
USFS fuel spill	Reserve Administrative Site	Reserve	Catron	33.708918	-108.761348	mobile AST with fuel for prescribed burns leaked	12/1/94	soil excavation	closed	2/1/1995
ABC Propane	813 N. Virginia	Roswell	Chaves	33.401215	-104.521064	bulk plant investigation	none	No tanks over 55K gals.	closed	Feb. 2006
BNSF Chisum Siding	RR mil 119.5, 4.6 mi NW of Dexter	Dexter	Chaves	33.195659	-104.366833	locomotive tank leak of 2000 gal diesel	12/25/1998	soil excavation	closed	7/19/1999
Denios Cleaners	514 W. 2nd Street	Roswell	Chaves	33.394021	-104.529985	PCE in ground water.	unknown	Referred to Superfund Oversight Section.	referred	6/26/2015
Great SW Aviation	100 Southwest Way - Airport	Roswell	Chaves	33.306242	-104.527442	bulk plant investigation	none	No tanks over 55K gals.	closed	Feb. 2006
Hagerman Lead in Soil	T14S R24E	Hagerman	Chaves			concerns about lead in quarries on SLO land	none	XRF Sampling, results below Std	closed	7/14/1997
Helena Chemical Co.	504 Lake Arthur Hwy	Lake Arthur	Chaves	33.000835	-104.363886	windshield washer and herbicide sprayed on soil		soil excavation and sampling	closed	6/15/2009
Merio Well	Brown Rd West of Roswell, 4718 W. 2nd Street	Roswell	Chaves	33.394133	-104.584149	BTEX reportedly found in well	4/4/1977	if new data shows BTEX is present will be referred to PSTB	inactive	
New Mexico Machinery	2801 SE Main	Roswell	Chaves	33.343611	-104.5075	AST leaked diesel	discovered 7/8/15	soil excavation	closed	10/20/2015
New Products and Development Company	4301 SE Main St.	Roswell	Chaves	33.361961	-104.512111			closed	closed	7/1/1990
Nova Bus	46 E. Martin	Roswell	Chaves	33.31489	-104.519161	50 gal of diesel spill from overfilling truck	5/30/2000	soil excavation	closed	8/4/2000
PCE Roswell, Bell Texaco/Union Plaza Conoco		Roswell	Chaves	33.39441	-104.535776	suspected false positive or cross-contamination of consultant's sample from 411 N. Kansas, Roswell		confirmation negative	closed	September '05 sampling event
Richard Distributing Co.	1500 N Garden Ave	Roswell	Chaves	33.408763	-104.514431	old small AST with soil contamination	pre 88	GW monitoring	closed	3/6/1998
Robinson Custom Harvesting	Darby Rd near Dexter	Dexter	Chaves	33.285835	-104.435562	washing of trucks and discharge of manure, TPH to field and road	Jul-93	DP required letter sent 5-26-94	referred to permitting	unknown
Roswell Central	Downtown Roswell	Roswell	Chaves	33.394825	-104.522765	PCE in ground water	unknown	Monitoring. Referred to Superfund Oversight Section.	referred	6/26/2015
Roswell International Air Center	Mathis and Gail Harris St.	Roswell	Chaves	33.310979	-104.522428	Jet fuel spill from aircraft accident. Soil contamination of 80x100 ft	4/2/2011	microblaze application and MNA of soil	closed	2/20/2014
Roswell Landfill	3006 W. Brasher	Roswell	Chaves	33.350117	-104.572143	PCE/TCE measured in landfill monitoring wells	unknown	Solid Waste Bureau jurisdiction	referred	2/10/2010
Roswell Sonic	1209 W. 2nd Street	Roswell	Chaves	33.394671	-104.535282	PCE in ground water.	unknown	Trespassing plume. Referred to Superfund Oversight Section.	referred	6/26/2015

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Southwest Radiographs	519 E. Chisum St	Roswell	Chaves	33.376351	-104.516285	x-ray machine and spill of AgNO3	pre 97	soil excavation	closed	3/30/1998
Steere Tank Lines	S. Main and Hobson	Roswell	Chaves	33.321365	-104.523267	tank truck spill lost 2500 gal of JP-8	7/7/1998	soil excavation	closed	7/27/1998
Transportation Manufacturing Corp	T11S, R24E, S32 and 33	Roswell	Chaves			phase 2 showed low levels of TPH in soil	pre 95	unknown	inactive	
NMARNG Roswell North Range MRS (NM545-001-R-01)	approximately 10 miles east and 4 miles north of the center of Roswell, NM	Roswell	Chaves	33.452994°	-104.365612°	metals associated with small arms ammunition (Pb, Sb, Cu, and Zn) at gun range used from mid 1965 to 2000	Pre 2000	Risk assesment of soil to GW and ecological receptors.	closed	2/14/2020
Blakes Lotaburger	619 W 66th	Milan	Cibola	35.189406	-107.892015	old UST sump	pre5/98	samples showed clean	closed	7/1/1999
BNSF Grants (formerly Ramsey Oil)	210 W. Santa Fe Avenue	Grants	Cibola	35.149859	-107.84895	Diesel, BTEX in ground water.	pre 2002	Enhanced in-situ bioremediation - under Voluntary Remediation Program.	referred	1/17/2002
Dwight Small	1512 Ice Caves Rd	Grants	Cibola	35.145944	-107.87601	improper solid waste disposal suspected potential ground water contaminant releases	pre 2010	GWQB sampled soil and found minimal detections. SWB jurisdiction	referred	
Ever Ready Oil - Milan	817 W. Hwy 66	Milan	Cibola	35.189406	-107.892015	runoff from service station is trespassing on neighbor's property	pre 2008	SWB required stormwater control	referred	
Ramah Ranch	El Moro	El Moro	Cibola	35.102076	-108.275521	discovery of solid rocket fuel on ranch from inerrant DOD rocket, perchlorate	unknown	site assessment and referral to HWB	referred	
TA - Petro Truck Stop #13	I-40 and Horizon Blvd	Milan	Cibola	35.182408	-107.9009	diesel spill at AST truck stop	1996	soil excavation	closed	6/18/1996
USFS Lobo Canyon herbicide	Cibola FS, 4 miles NW of Grants	Grants	Cibola			30 drums buried in 70s	pre 70	soil removal	closed	4/21/2004
WW Construction Inc.	Hwy 125 mile 4.5	McCarty	Cibola			truck accident that spilled 250 gal of diesel	8/2/2000	soil excavation	closed	8/25/2000
Duran Oil Co.	700 Woodrow Ave	Raton	Colfax	36.872509	-104.447263	small AST farm with overflow of 3500 gal of diesel	10/15/1997	soil excavation	closed	6/20/1997
Highlight Motor Group	Highway 56, 2 Mile Marker T35	Springer	Colfax	36.320231	-104.419537	Approx. 2000 Gallon Fromic Acid spil into Chico Creek	9/18/2021	GWQB advised on soil sampling and defered to SWQB for corrective action oversight	closed	Jan-2023
Jaritas Ranch	~12mi E of Springer on Hwy 56	Springer	Colfax	36.241597	-104.383099	livestock dipping vat soil contamination	pre 7/5/05	soil excavation	closed	1/10/2006
Kaiser Steel ASTs	York Canyon Mine Complex, Box 100 Raton, 87740	Raton	Colfax	36.863688	-104.920637	unauthorized discharge of diesel		NOD sent	closed	9/1/1998
Knight Transportation	I-25 mile 453	Raton	Colfax	36.882972	-104.438322	truck accident caused 100 gal diesel spill	8/4/2008	soil excavation	closed	12/15/2008
Perkins Well, Eagle Nest	32 County Road B11	Eagle Nest	Colfax	36.551956	-105.257437	domestic well sample showed low levels of MTBE. Unknown source	unknown	monitoring	inactive	
Prices Mobile Home Park	1135 Price St	Raton	Colfax	36.88633	-104.436158	report of tenant spraying oil on ground	2/8/2011	stopped practice	closed	2/28/2011
QCD Trucking/700 Clayton Rd.	Near 700 Clayton Rd.	Raton	Colfax	36.885271	-104.428153	fuel spill, excavation of impacted areas via skid-steer sweeper and hand digging followed by application of clay absorbent to the asphalt lot and resweeping to remove any residue	Septemebr 2020	Source removal	closed	1/20/2022
Raton ASTs	I-25 and 2nd exit heading N	Raton	Colfax			AST spills	10/15/1997	soil excavation	closed	6/19/1998
Raton Car Crushing	637 Lincoln	Raton	Colfax	36.909523	-104.431644	report of car and refrigerator crushing activities and fluids on ground	unknown	investigation and collaborated with Raton code enforcement shown no threat to ground water	closed	12/1/2013
Raton City Maintenance Yard	4th Ave and Cedar St.	Raton	Colfax	36.897428	-104.429521	400 of emulsion oil was buried on yard	pre 1993	soil excavation	closed	post 1994
Springer - Esquibel Fuel Release	SR 21 and Frontage Rd	Springer	Colfax	36.366014	-104.591194	Report of fuel release from an unregistered UST	1996	installation of trenches, soil sampling, and passive vent removal. Results showed no contamination	closed	11/4/2014
Texaco Bulk Plant	945 2nd Street	Raton	Colfax	36.913038	-104.435949	bulk terminal investigation showed low levels of fuel	pre 1992	subsurface investigation	closed	5/4/1992
Texaco Bulk Plant	Colbert Ave and 11th St	Springer	Colfax	36.366014	-104.591194	Phase 2 ESA showed VOCs in soil and in one MW	pre 1992	GWQB responded saying that prioritization ranking was low would not be assigned	inactive	
Total Truck Stop	Hwy 87 and I-25	Raton	Colfax	36.88595	-104.428181	80 gal of diesel spill from faulty equipment	11/11/1996	soil excavation	closed	1/3/1997
Angel Fire LLC/Milwaukee Jewish Federation (Former Creosote Treatment Plant)	Immediately east of intersection of 64 and 434	Angel Fire	Colfax	36.430228	-105.294503	Conducted geoprobe gw investigation, release of creosote and pentachlorophenol	Pre 1995	AST removal.	Transferred to VRP 53191002	2/7/2020
Atrazine in Domestic well	1672 Hwy 60/84, 1725 CR 11	Clovis	Curry	34.419211	-103.225374	report of Atrazine spill from farmer	pre 2001	sampling of wells were ND for Atrazine and no evidence of discharge	closed	12/18/2001
Barnett and Sons Paving Contractor	2405 W. 7th	Clovis	Curry	34.404644	-103.234562	report of used oil, pesticides, drum burial near south pit	pre 99	inspection revealed no evidence of discharge.	closed	10/7/1999
Cannon AFB	Melrose Bombing	Melrose	Curry	34.431081	-103.629579	275 heating oil UST leaked	pre 11/94	unknown	inactive	
Clovis pipeline terminal	34° 22' 52.68"N, 103° 12' 30.36"W	Clovis	Curry	34.3814	-103.2083	undocumented release(s)	unknown	none	closed	9/23/2008
Clovis POTW	SR 318 (Brady Ave) and Hwy 84	Clovis	Curry	34.453936	-103.198495	GW contaminated from POTW and Landfill DP-79	unknown	Referred to SWB and PPS		

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Cook's Truck Stop	East of Clovis	Clovis	Curry	34.394706	-103.144082	letter from Dist. office saying NO3 levels in truck stop well is improving following sewage line extension	unknown	monitoring	closed	
Koch Pipeline/ Clovis	1/2-mi. S of W. Brady and S. Thornton	Clovis	Curry			former bulk terminal showed petroleum hydrocarbons in soil	unknown	soil assessment to depth	closed	5/1/2009
Melugin Spill	East 7th Street and Schepps Blvd	Clovis	Curry	34.404903	-103.168397	Discovery of leaking drums, possible pesticides	unknown	soil excavation	closed	7/17/1995
Payless Rental	620 East 21st St.	Clovis	Curry	34.41937	-103.198646	report of small used oil spill with TPH at 475	6/6/2000	soil excavation	closed	6/27/2000
Professional Flight Training	Eco Tank Services, Box 27116	Clovis	Curry			jet fuel spill	pre 1995	soil excavation	closed	12/5/1995
Rajen Dairy LUST site	Rt1 Box 264b	Clovis	Curry	34.393324	-103.288349	soil contamination below dairy lust site. Not PSTB related	pre 1992	soil sampling showed contamination	referred	
Southwestern Public Service Center	Clovis Yard	Clovis	Curry	34.394485	-103.176984	soil vapor survey looking for chlorinated solvents	pre 1994	soil vapor results and inventory showed no contamination and not related to low level solvents found in municipal well	closed	6/16/1998
Southwestern Public Service Center	Norris St, T2N, R36E,	Clovis	Curry	34.453936	-103.198495	low hits of PCE in supply wells lead investigation to SPS Center and Clovis Landfill	pre 1988	soil vapor survey and site inventory showed no solvents	closed	3/13/1995
United Petroleum Transport	50 yd. N of Hwy 70 on Hwy 60	Texico	Curry	34.389272	-103.04441	5000 diesel spill from truck accident	9/20/06	soil excavation and land farming	closed	12/1/2006
Village of Texico - Well KKR	Hamlin and College St.	Texico	Curry	34.389858	-103.054028	discovery of carbon tetrachloride in new supply well at conc. ~7 ppb	unknown	redevelop well	closed	August-91
Xcel Energy right-of-way	913 Cypress St.	Clovis	Curry	34.407139	-103.226072	trespass dumping of used motor oil	on-going by trespasser	soil excavation and posted "no dumping" signs	closed	in process
Zia Spraying Services	Clovis Airport	Clovis	Curry	34.453936	-103.198495	long term pesticide spills referred to ROS in 1995	1980s to possibly 1995		inactive	
BNSF Clovis - WWTP	BNSF Clovis Yard	Clovis	Curry	34.395971	-103.20823	Release of approximately 2000 gallons of stormwater impacted with locomotive lubricating oil and fuels.	11/14/2018	Excavation of 28.99 tons of petroleum impacted soil.	closed	4/8/2019
Savage Trucking	SW corner of intersection of South Prince Street and East First Street	Clovis	Curry	34.398361, 34.396250	-103.197024, -103.183458°	Spill of 3024 gallons of diesel from pup tanker trailer entered storm sewer and discharged at outfall 0.75 miles away on BNSF property	6/23/2018	Excavation at both spill locations, decon of storm sewer	closed	5/17/2019
BNSF Clovis - Recovery Well 6	Main Street, Clovis, New Mexico	Clovis	Curry	34.39548	-103.211721	Release of diesel contaminated groundwater from recovery well piping,	43992	Soil excavation	closed	
BNSF Clovis - WWTP	BNSF Clovis Yard	Clovis	Curry	34.39666	-103.20921	Release of an estimated 270 gallons of water containing a small amount of lubricant oil (presumed to be approximately 5 gallons but no more than 30).	12/26/2019	Soil excavation	closed	5/21/2020
American Freightways	US 60 and 6th Street	Fort Sumner	De Baca	34.474712	-104.258786	truck accident 400 gal of diesel	Oct-00	soil excavation	closed	12/20/2000
Fort Sumner Truck Stop	US 84 and St. Rt 212	Fort Sumner	De Baca	34.477593	-104.236148	small AST Truck stop with soil and GW contamination	pre 93	site assessment and referral to PSTB	referred	
Fort Sumner Truck Stop	West Fort Sumner Ave	Fort Sumner	De Baca	34.47187	-104.260836	orphaned AST	pre 1985	referred to PSTB 9-02	referred	6/24/1997
El Paso Elec. Co.	108 W. Afton	La Mesa	Doña Ana	32.082544	-106.683886	transformer oil	1/3/2017	soil excavation	closed	1/18/2017
El Paso Elec. Co.	3901 Watson Place	Las Cruces	Doña Ana	32.265178	-106.769028	transformer oil	1/12/2017	soil excavation	closed	1/27/2017
El Paso Electric Co.	311 S. Main St.,	Las Cruces	Doña Ana	32.30757	-106.777714	Release of mineral oil from electrical transformer	10/20/2019	Soil excavation	closed	2/10/2020
El Paso Electric Co.	3200 Del Rey Blvd	Las Cruces	Doña Ana	32.35458	-106.76765	Release of mineral oil from electrical transformer	43272	Soil excavation	closed	2/7/2019
El Paso Electric Co.	2130 Rosedale Dr	Las Cruces	Doña Ana	32.32946	-106.79373	Release of mineral oil from electrical transformer	8/17/2018	Soil excavation	closed	2/7/2019
El Paso Electric Co.	305 Corona Dr	Chaparral	Doña Ana	32.01743	-106.3293995	Release of mineral oil from electrical transformer	10/7/2018	Soil excavation	closed	2/7/2019
El Paso Electric Co.	1795 East Griggs	Las Cruces	Doña Ana	32.31464	-106.760894	Release of mineral oil from electrical transformer	12/13/2018	Soil excavation	closed	2/7/2019
abandoned truckstop	2500 W. Picacho Ave.	Las Cruces	Doña Ana	32.310786	-106.811265	historic spills of diesel fuel dispensed from ASTs at old truck stop	pre-1988	soil excavation	closed	7/25/2007
Agri-Tech	1730 W. Picacho Ave.	Las Cruces	Doña Ana	32.312042	-106.801821	motor oil spill discovered by neighbor	10/6/05	soil excavation	closed	8/11/2006
AIG Environmental	I-25 mile 32.2	Rincon	Doña Ana	32.672395	-107.073291	truck accident caused release of diesel	8/28/1998	soil excavation	closed	10/30/1998
Alameda Laundry & Dry Cleaners	Alameda & Main Street	Las Cruces	Doña Ana	32.30347800	-106.77799800	PCE in soil gas in vicinity needs next Tier of Assessment	unknown	soil vapor	transferred to Superfund	4/21/2016
All About Kars	1695 Picacho Ave.	Las Cruces	Doña Ana	32.311415	-106.801447	PSTB site where P&T through zeolite was proposed	unknown	referred to PSTB	referred	
Amador Auto Body and Paint shop	821 Amador	Las Cruces	Doña Ana	32.308722	-106.770454	HWB concern over stains in bldg.	pre 1992	unknown	referred to HWB	
Anthony Water and Sanitation District WWTP	4th Street	Anthony	Doña Ana	32.02185900	-106.60025700	nitrate, TDS	NA	Site is regulated under an active DP.	Referred to PPS	4/8/2016
Antix Cabinets	717 W. Organ Ave.	Las Cruces	Doña Ana	32.307779	-106.785841	overflow of waste barrel	Sep-08	soil removal	closed	
Atomic Towing	5605 Bataan Memorial	Las Cruces	Doña Ana	32.307779	-106.785841	environmental complaint	Aug-08	n/a, no release occurred	closed	8/25/2008
B&H Mechanical	3701 Doña Ana Rd	Las Cruces	Doña Ana	32.334762	-106.795368	mineral spirit-based oil	10/15/2010	soil excavation	closed	9/7/12
Border International	1670 S. Valley	Las Cruces	Doña Ana	32.288473	-106.783028	petroleum	5/28/2008	soil excavation, MW sampling	closed	5/9/14
Caballo Emergency Truck Repair	14436 NM-187	Caballo	Doña Ana	32.93705658	-107.3150671	BTEX, TPH releases from improper disposal	unknown	soil excavation	closed	4/10/09
Cabrera Automotive		Las Cruces	Doña Ana			soil contamination	2003	site visit and soil excavation	closed	6/25/2004

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Cervantes Enterprises	9926 Hwy. 478	Vado	Doña Ana	32.127955	-106.673269	anonymous caller claimed 4000 gal. spill of liquid fertilizer	2/2/2006	inspected site, no liquid fertilizer tanks on site, no evidence of spill found	closed	2/7/2007
Chevron/Jornada Range pipeline spill	7 miles NW of Las Cruces	Las Cruces	Doña Ana			diesel	unknown	soil excavation	inactive	
Crop Production Services	1300 B.B. Romig	Hatch	Doña Ana	32.6786	-107.2001	fertilizers & diesel fuel	4/7/2009	soil excavation	closed	1/24/2014
DAC Fleet Maintenance Yard, Las Cruces	2025 E. Griggs	Las Cruces	Doña Ana	32.314312	-106.760527	multiple areas of soil contamination	unknown	soil excavation	closed	9/7/2012
DAC Health Center	5595 Elks Dr.	Doña Ana	Doña Ana	32.394934	-106.817516	backhoe vandalized, spilled hydraulic fluid and diesel fuel	9/2/04	soil excavation	closed	10/27/2006
DC Carriers	MM 17 and 18, Hwy 213	White Sands	Doña Ana			truck rollover lost 5,700 gallons of diesel	10/12/12	soil excavation	closed	2/8/2013
Dick's Café de Mesilla	2000 Hwy. 292	Mesilla	Doña Ana	32.278214	-106.796874	wastewater from restaurant discharging onto property next door	3/7/2007	inspected site, verified discharge, referred to EHD	closed	3/8/2007
Dona Ana Colonias	Los Palmeras Subdivision	Mesquite	Doña Ana	32.165699	-106.68724	Domestic Well Sampling	10/1/1994	Results showed high TDS and Sulfate	closed	2/1/1996
Doña Ana Mutual Water and Sewer Cooperative Assoc.	5041 El Camino Real	Doña Ana	Doña Ana	32.39493400	-106.81751600	sewer main rupture	12/15/07	soil removal	closed	6/18/2008
Doña Ana Mutual Water and Sewer Cooperative Assoc.	750-ft downstream of Barela lateral diversion, E side of canal	Doña Ana	Doña Ana			sewer main rupture	9/11/2007	soil removal	closed	11/9/2007
El Paso Electric Co.	11327 Dona Ana Rd	Las Cruces	Doña Ana	32.47851	-106.90158	9 gal. mineral oil spill	7/13/2021	soil removal	closed	2/11/2022
E. Lohman Landfill	E. Lohman Ave & Roadrunner Parkway	Las Cruces	Doña Ana	32.32127700	-106.731195	No Further Action	none	No further Action	Closed	5/9/2016
El Paso Electric Co.	724 N. 4th Street	Anthony	Doña Ana	32.006667	106.6025	transformer oil	Aug-15	soil excavation	closed	4/15/2016
El Paso Electric Co.	5158 Canary Ct.	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil	10/14/2005	soil excavation	closed	7/3/2008
El Paso Electric Co.	5223 Calle del Rancho	Las Cruces	Doña Ana	32.389638	-106.695342	transformer oil	6/13/2008	soil excavation	closed	7/3/2008
El Paso Electric Co.	620 Richardson	Mesilla Park	Doña Ana	34.166233	-106.026069	transformer oil	6/17/2013	soil excavation	closed	7/30/13
El Paso Electric Co.	1415 Anthony Rd	Anthony	Doña Ana	32.019592	-106.603446	2 gal transformer oil spill	6/21/2017	soil excavation	closed	5/23/2018
El Paso Electric Co.	Westside Canal Rd & Gavilan Avenue	La Mesa	Doña Ana	32.139617	-106.731256	8 gal transformer oil spill	1/8/2018	soil excavation	closed	5/23/2018
El Paso Electric Co.	301 N. Roadrunner Parkway	Las Cruces	Doña Ana	32.3275	-106.73972	10 gal mineral oil spill	7/26/2021	soil excavation	closed	2/11/2022
El Paso Electric Co.	4124 Macaw Circle	Las Cruces	Doña Ana	32.265273	-106.750566	2 gal transformer oil spill	6/18/2017	soil excavation	closed	5/23/2018
El Paso Electric Co.	4849 E. Lohman Avenue	Las Cruces	Doña Ana	32.332964	-106.71219	30 gal transformer oil spill	7/6/2017	soil excavation	closed	5/23/2018
El Paso Electric Co.	435 Ithaca Court	Las Cruces	Doña Ana	32.325531	-106.733203	12 gal transformer oil spill	8/25/2017	soil excavation	closed	5/23/2018
El Paso Electric Co.	2027 Chateau Drive	Las Cruces	Doña Ana	32.3266	-106.79695	10 gal transformer oil spill	9/4/2017	soil excavation	closed	5/23/2018
El Paso Electric Co.	Fairway Village Drive & Picacho Hills Drive	Las Cruces	Doña Ana	32.309579	-106.859413	20 gal transformer oil spill	9/10/2017	soil excavation	closed	5/23/2018
El Paso Electric Co.	NM Hwy. 478 & Salopek Rd	Las Cruces	Doña Ana	32.220833	-106.731986	10 gal transformer oil spill	4/10/2018	soil excavation	closed	5/23/2018
El Paso Electric Co.	2644 Cody Circle	Las Cruces	Doña Ana	32.335338	-106.744129	5 gal transformer oil spill	4/24/2018	soil excavation	closed	5/23/2018
El Paso Electric Co.	295 Quinella Rd	Sunland Park	Doña Ana	31.803142	-106.571595	8 gal transformer oil spill	12/12/2017	soil excavation	closed	5/23/2018
El Paso Electric Co.	1130 Dairy Farm Rd	Anthony	Doña Ana	32.012901	-106.606193	transformer oil	1/17/2011	soil excavation	closed	6/30/2011
El Paso Electric Co.	1310 N. 4th Street	Anthony	Doña Ana	32.01747	-106.600905	transformer oil	7/8/2014	soil excavation	closed	8/5/14
El Paso Electric Co.	147 Shrode	Anthony	Doña Ana	32.012901	-106.606193	transformer oil	6/11/2010	soil excavation	closed	6/30/2011
El Paso Electric Co.	4895 N. Vinton	Anthony	Doña Ana	32.012901	-106.606193	transformer oil spill	6/24/08	soil excavation	closed	6/30/2011
El Paso Electric Co.	4901 Vinton	Anthony	Doña Ana	32.012901	-106.606193	transformer oil	7/5/2007	soil excavation	closed	7/3/2008
El Paso Electric Co.	800 W. Washington	Anthony	Doña Ana	32.012901	-106.606193	hydraulic fuel & transformer oil	9/5/2013	soil excavation	closed	9/30/13
El Paso Electric Co.	Hwy. 213 & Hwy. 404	Anthony	Doña Ana	32.03561	-106.463804	transformer oil	11/2/2007	soil excavation	closed	7/3/2008
El Paso Electric Co.	5205 Hwy. 28	Anthony	Doña Ana	31.981123	-106.653221	transformer oil	5/26/2016	soil excavation	closed	7/8/2016
El Paso Electric Co.	1590 N. 4th Street	Anthony	Doña Ana	32.0225	106.6025	capacitor oil	7/2/2015	soil excavation	closed	4/15/2016
El Paso Electric Co.	1010 Leifeste	Anthony	Doña Ana	32.034075	-106.600624	transformer oil	10/6/2016	soil excavation	closed	10/25/2016
El Paso Electric Co.	1590 N. 4th Street	Anthony	Doña Ana	32.024111	-106.602014	30 gal. Transformer/Bushing oil spill	1/31/2017	soil excavation	closed	7/7/2017
El Paso Electric Co.	1590 N. 4th Street	Anthony	Doña Ana	32.024111	-106.602014	100 gal. Regulator oil spill	2/3/2017	soil excavation	closed	7/7/2017
El Paso Electric Co.	1590 N. 4th Street	Anthony	Doña Ana	32.024111	-106.602014	11 gal. Capacitor oil spill	2/14/2017	soil excavation	closed	7/7/2017
El Paso Electric Co.	400 N. Anthony Drive	Anthony	Doña Ana	32.003589	-106.606087	2 gal. Hydraulic oil spill	5/23/2017	soil excavation	closed	7/7/2017
El Paso Electric Co.	10801 Hwy. 28	Chamberino	Doña Ana	32.055005	-106.67554	transformer oil	6/23/2010	soil excavation	closed	6/30/2011
El Paso Electric Co.	644 Hermosa	Chaparral	Doña Ana	32.016565	-106.39368	transformer oil	7/25/2010	soil excavation	closed	6/30/2011
El Paso Electric Co.	654 Paseo Real	Chaparral	Doña Ana	32.023247	-106.378631	transformer oil	2/12/2013	soil excavation	closed	3/1/13
El Paso Electric Co.	656 Luna Azul	Chaparral	Doña Ana	32.030935	-106.37986	hydraulic fluid leak from EPEC truck	5/11/05	soil excavation	closed	09/23/05
El Paso Electric Co.	753 Broadmoor	Chaparral	Doña Ana	32.008464	-106.372555	transformer oil spill	12/5/05	soil excavation	closed	1/27/2006
El Paso Electric Co.	768 Nogales	Chaparral	Doña Ana	32.03213	-106.368859	transformer oil	1/6/2014	soil excavation	closed	1/30/14
El Paso Electric Co.	804 Jennifer Nicole	Chaparral	Doña Ana	32.043056	-106.3675	transformer oil	1/13/2016	soil excavation	closed	2/15/2016
El Paso Electric Co.	511 NM Hwy. 213	Chaparral	Doña Ana	32.007379	-106.446867	15 gal. Transformer oil spill	3/28/2017	soil excavation	closed	7/7/2017
El Paso Electric Co.	Grimsley Loop	Chaparral	Doña Ana	32.07306	-106.30611	80 gal hydraulic oil spill	8/4/2021	soil excavation	closed	2/11/2022
El Paso Electric Co.	250 Nightwatchers	Garfield	Doña Ana	32.757087	-107.261363	transformer oil	8/5/2011	soil excavation	closed	8/23/2011
El Paso Electric Co.	2617 Loma Parda	Garfield	Doña Ana	32.75744	-107.264851	transformer oil	8/5/2011	soil excavation	closed	8/23/2011
El Paso Electric Co.	56753 W. Barker	Hatch	Doña Ana	32.650378	-107.198495	transformer oil spill	4/4/05	soil excavation	closed	09/23/05
El Paso Electric Co.	607 Franklin	Hatch	Doña Ana	32.673563	-107.154668	transformer oil spill	7/1/2003	soil excavation	closed	2/22/2005
El Paso Electric Co.	700 Franklin	Hatch	Doña Ana	32.674593	-107.155231	transformer oil	7/10/2000	soil excavation	closed	11/15/2000
El Paso Electric Co.	SS Packing Plant	Hatch	Doña Ana	32.650378	-107.198495	transformer oil	8/16/2001	soil excavation	closed	9/17/2001
El Paso Electric Co.	1229 County Rd	La Mesa	Doña Ana	32.124785	-106.708078	hydraulic fluid leak from EPEC truck	12/21/04	soil excavation	closed	1/27/2006
El Paso Electric Co.	15795 Hwy. 28	La Mesa	Doña Ana	32.115567	-106.703215	tar	8/5/2010	soil excavation	closed	6/30/2011

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
El Paso Electric Co.	15795 Hwy. 28	La Mesa	Doña Ana	32.115567	-106.703215	tar	8/5/2010	soil excavation	closed	6/30/2011
El Paso Electric Co.	190 Victoria	La Mesa	Doña Ana	32.136111	106.716389	transformer oil	11/16/2015	soil excavation	closed	4/15/2016
El Paso Electric Co.	108 W. Afton Rd	La Mesa	Doña Ana	32.082636	-106.684458	13 gal. Transformer oil spill	1/3/2017	soil excavation	closed	7/17/2017
El Paso Electric Co.	1443 S. Alvarez	La Union	Doña Ana	31.931512	-106.661436	transformer oil	6/5/2010	soil excavation	closed	6/30/2011
El Paso Electric Co.	1640 County Rd	La Union	Doña Ana			transformer oil	8/20/2014	soil excavation	closed	9/19/14
El Paso Electric Co.	4301 Azalea	Las Cruces	Doña Ana	32.35243	-106.78604	mineral oil	8/24/2020	soil excavation	closed	2/16/2021
El Paso Electric Co.	4807 El Camino Real	Las Cruces	Doña Ana	32.371872	-106.805809	transformer oil	4/29/2016	soil excavation	closed	7/8/2016
El Paso Electric Co.	1053 Hayner	Las Cruces	Doña Ana	32.308615	-106.791494	transformer oil	7/29/2003	soil excavation	closed	9/23/2003
El Paso Electric Co.	110 Onnies Acres Rd	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil spill	5/21/09	soil excavation	closed	6/30/2011
El Paso Electric Co.	1115 May	Las Cruces	Doña Ana	32.311133	-106.768318	transformer oil spill	7/1/08	soil excavation	closed	6/30/2011
El Paso Electric Co.	1300 Lujan Hills	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil spill	12/23/08	soil excavation	closed	6/30/2011
El Paso Electric Co.	1404 Diana Maura	Las Cruces	Doña Ana	32.300515	-106.749788	transformer oil	8/19/2014	soil excavation	closed	9/19/14
El Paso Electric Co.	1410 Jeanie Ct.	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil	11/9/09	soil excavation	closed	6/30/2011
El Paso Electric Co.	1490 6th St.	Las Cruces	Doña Ana	32.318207	-106.797366	transformer oil	3/2/2012	soil excavation	closed	4/5/2012
El Paso Electric Co.	1551 Avenida de Mesilla	Las Cruces	Doña Ana	32.283098	-106.795406	transformer oil spill	4/5/05	soil excavation	closed	09/23/05
El Paso Electric Co.	1785 Walden	Las Cruces	Doña Ana	32.297077	-106.751935	transformer oil	12/3/2012	soil excavation	closed	12/20/12
El Paso Electric Co.	1815 & 1825 Baldwin	Las Cruces	Doña Ana	32.296078	-106.752556	transformer oil	7/22/2010	soil excavation	closed	6/30/2011
El Paso Electric Co.	18151 Hwy. 70 East	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil	7/23/2008	soil excavation	closed	6/30/2011
El Paso Electric Co.	18205 Hwy. 70 East	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil	4/28/2011	soil excavation	closed	6/30/2011
El Paso Electric Co.	2050 Amador	Las Cruces	Doña Ana	32.299677	-106.804204	transformer oil spill	7/22/04	soil excavation	closed	1/27/2006
El Paso Electric Co.	2102 Desert Greens	Las Cruces	Doña Ana	32.295562	-106.729012	transformer oil	8/16/2011	soil excavation	closed	9/12/2011
El Paso Electric Co.	2111-2115 Jordan	Las Cruces	Doña Ana	32.289738	-106.751934	transformer oil spill	4/17/10	soil excavation	closed	6/30/2011
El Paso Electric Co.	2218 S. Valley	Las Cruces	Doña Ana	32.285344	-106.776166	transformer oil	8/18/2006	soil excavation	closed	7/3/2008
El Paso Electric Co.	2250 Hixon Dr.	Las Cruces	Doña Ana	32.283862	-106.766923	transformer oil	5/10/2013	soil excavation	closed	6/19/13
El Paso Electric Co.	2330 E. Nevada, Bldg. #8	Las Cruces	Doña Ana	32.30837	-106.750449	transformer oil	9/11/2006	soil excavation	closed	7/3/2008
El Paso Electric Co.	2720 Sunrise Point	Las Cruces	Doña Ana	32.339112	-106.748205	transformer oil	5/25/2007	soil excavation	closed	7/3/2008
El Paso Electric Co.	2958 Sundance	Las Cruces	Doña Ana	32.311353	-106.739047	transformer oil	9/5/2006	soil excavation	closed	7/3/2008
El Paso Electric Co.	2962 Sundance	Las Cruces	Doña Ana	32.311388	-106.738976	transformer oil	9/5/2006	soil excavation	closed	7/3/2008
El Paso Electric Co.	301 Roadrunner Parkway	Las Cruces	Doña Ana	32.322561	-106.732877	transformer oil spill	7/8/03	soil excavation	closed	2/22/2005
El Paso Electric Co.	3010 Thurmond	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil spill	6/26/08	soil excavation	closed	6/30/2011
El Paso Electric Co.	3011 N. Main	Las Cruces	Doña Ana	32.340734	-106.775898	transformer oil	7/19/2007	soil excavation	closed	7/3/2008
El Paso Electric Co.	3108 Pebble Beach	Las Cruces	Doña Ana	32.295714	-106.73352	transformer oil spill	5/23/05	soil excavation	closed	09/23/05
El Paso Electric Co.	3200 Bowman	Las Cruces	Doña Ana	32.274435	-106.772298	transformer oil	6/26/2012	soil excavation	closed	9/12/12
El Paso Electric Co.	331 Capri Arc	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil	7/8/2012	soil excavation	closed	8/6/12
El Paso Electric Co.	3519 Foothills Rd	Las Cruces	Doña Ana	32.314887	-106.738595	transformer oil spill	7/22/03	soil excavation	closed	2/22/2005
El Paso Electric Co.	3601 Doña Ana Rd	Las Cruces	Doña Ana	32.334762	-106.795368	transformer oil	5/3/2012	soil excavation	closed	5/17/2012
El Paso Electric Co.	3785 N. Valley	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil	9/13/2013	soil excavation	closed	10/1/13
El Paso Electric Co.	3819 Stoney Brook Circle	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil	4/4/2007	soil excavation	closed	7/3/2008
El Paso Electric Co.	400 Milton	Las Cruces	Doña Ana	32.286681	-106.769729	transformer oil spill	9/17/09	soil excavation	closed	6/30/2011
El Paso Electric Co.	4261 Pacana Trail	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil	8/10/2011	soil excavation	closed	8/25/2011
El Paso Electric Co.	4440 Los Arboles	Las Cruces	Doña Ana	32.317475	-106.726135	transformer oil	6/27/2012	soil excavation	closed	8/6/12
El Paso Electric Co.	4849 Lohman Ave	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil	11/4/2005	soil excavation	closed	7/3/2008
El Paso Electric Co.	4849 Lohman Ave	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil	6/18/2008	soil excavation	closed	7/3/2008
El Paso Electric Co.	4849 Lohman Ave	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil	11/2/2011	soil excavation	closed	6/30/2011
El Paso Electric Co.	4849 Lohman Ave	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil	7/27/2014	soil excavation	closed	9/2/14
El Paso Electric Co.	4905 Snow	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil	12/11/2006	soil excavation	closed	7/3/2008
El Paso Electric Co.	4930 Pina Place	Las Cruces	Doña Ana	32.37231	-106.80955	hydraulic oil	7/1/2020	soil excavation	closed	2/16/2021
El Paso Electric Co.	5005 Big Tree Rd	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil spill	6/5/03	soil excavation	closed	2/22/2005
El Paso Electric Co.	5300 Vista Sureste	Las Cruces	Doña Ana	32.375754	-106.732052	transformer oil spill	7/12/05	soil excavation	closed	1/27/2006
El Paso Electric Co.	750 N. Solano	Las Cruces	Doña Ana	32.317544	-106.768685	transformer oil	12/5/2006	Not on soil, replaced transformer.	closed	7/3/2008
El Paso Electric Co.	760 Scenic View	Las Cruces	Doña Ana	32.31553	-106.734287	transformer oil	6/26/2014	soil excavation	closed	7/11/14
El Paso Electric Co.	813 Morton	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil	7/22/2010	soil excavation	closed	6/30/2011
El Paso Electric Co.	850 Holly Rd, Space #B45	Las Cruces	Doña Ana	32.35099	-106.785069	transformer oil spill	5/9/05	soil excavation	closed	09/23/05
El Paso Electric Co.	Holman Rd & Millard Ave.	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil	1/2/2011	soil excavation	closed	6/30/2011
El Paso Electric Co.	Hwy. 28 & Pajaro	Las Cruces	Doña Ana	32.240606	-106.764942	hydraulic fluid spill	9/7/2006	soil excavation	closed	7/3/2008
El Paso Electric Co.	I-10, exit 116	Las Cruces	Doña Ana	32.337077	-106.819454	transformer oil	6/29/2011	soil excavation	closed	8/8/2011
El Paso Electric Co.	Main & Conway	Las Cruces	Doña Ana	32.27756	-106.768011	transformer oil	3/15/2002	soil excavation	closed	4/26/2002
El Paso Electric Co.	Twin Peaks Mtn.	Las Cruces	Doña Ana			transformer oil spill	4/7/09	soil excavation	closed	6/30/2011
El Paso Electric Co.	Twin Peaks Mtn.	Las Cruces	Doña Ana			transformer oil	4/27/2011	soil excavation	closed	6/30/2011
El Paso Electric Co.	1230 Tamony Ln.	Las Cruces	Doña Ana	32.374538	-106.794239	transformer oil	5/2/2014	soil excavation	closed	6/6/14
El Paso Electric Co.	664 Rouault	Las Cruces	Doña Ana	32.340556	106.785833	transformer oil	5/17/2015	soil excavation	closed	4/15/2016
El Paso Electric Co.	1767 Defiance	Las Cruces	Doña Ana	32.321667	106.757778	transformer oil	7/24/2015	soil excavation	closed	4/15/2016
El Paso Electric Co.	5866 S. Main	Las Cruces	Doña Ana	32.239444	106.743889	transformer oil	7/28/2015	soil excavation	closed	4/15/2016
El Paso Electric Co.	3928 Marble View	Las Cruces	Doña Ana	32.377778	106.742778	transformer oil	8/17/2015	soil excavation	closed	4/15/2016
El Paso Electric Co.	1351 N. Alameda	Las Cruces	Doña Ana	32.321667	106.785556	transformer oil	12/23/2015	soil excavation	closed	4/15/2016
El Paso Electric Co.	3850 E. Lohman	Las Cruces	Doña Ana	32.318885	-106.734353	transformer oil	8/18/2016	soil excavation	closed	9/2/2016
El Paso Electric Co.	3901 Watson Place	Las Cruces	Doña Ana	32.265191	-106.769231	2 gal. Transformer oil spill	1/12/2017	soil excavation	closed	7/17/2017
El Paso Electric Co.	307 Pawnee	Las Cruces	Doña Ana	32.36363	-106.78332	5 gal. Transformer oil spill	2/22/2017	soil excavation	closed	7/17/2017

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
El Paso Electric Co.	3406 Harrelson Street	Las Cruces	Doña Ana	32.273561	-106.766914	2 gal. Transformer oil spill	3/8/2017	soil excavation	closed	7/7/2017
El Paso Electric Co.	2022 Westwind Rd	Las Cruces	Doña Ana	32.355153	-106.830024	5 gal. Transformer oil spill	3/11/2017	soil excavation	closed	7/7/2017
El Paso Electric Co.	18205 San Augustin Drive	Las Cruces	Doña Ana	32.385331	-106.726794	2 gal. Transformer oil spill	4/5/2017	soil excavation	closed	7/7/2017
El Paso Electric Co.	3700 Shalem Colony Trail	Las Cruces	Doña Ana	32.33078	-106.84756	12 gal. mineral oil spill	8/26/2020	soil excavation	closed	2/16/2021
El Paso Electric Co.	1595 Windmill Rd.	Las Cruces	Doña Ana	32.38911	-106.79579	5 gal. Transformer oil spill	8/29/2020	soil excavation	closed	2/16/2021
El Paso Electric Co.	1025 Glendale Drive	Las Cruces	Doña Ana	32.347167	-106.780424	20 gal. Transformer oil spill	4/29/2017	soil excavation	closed	7/7/2017
El Paso Electric Co.	1210 Rancho Algodones	Las Cruces	Doña Ana	32.3906	-106.83841	2 gal. Transformer oil spill	8/31/2020	soil excavation	closed	2/16/2021
El Paso Electric Co.	S. Triviz and Entrada del Sol	Las Cruces	Doña Ana	32.31143	-106.74703	13 gal. mineral oil spill	10/2/2021	soil excavation	closed	2/11/2022
El Paso Electric Co.	470 Boutz Rd.	Las Cruces	Doña Ana	32.28993	-106.7809	5 gal. Transformer oil spill	12/7/2020	soil excavation	closed	2/16/2021
El Paso Electric Co.	Hwy. 478 & MM19	Mesilla	Doña Ana			transformer oil	5/27/08	soil excavation	closed	7/3/2008
El Paso Electric Co.	108 St. Thomas	Mesquite	Doña Ana	32.166485	-106.697165	transformer oil	7/19/2012	soil excavation	closed	9/28/12
El Paso Electric Co.	12560 Stern	Mesquite	Doña Ana	32.165699	-106.68724	transformer oil	5/13/2002	soil excavation	closed	6/7/2002
El Paso Electric Co.	13116 Smokey Rd	Mesquite	Doña Ana	32.165699	-106.68724	transformer oil	4/1/2010	soil excavation	closed	6/30/2011
El Paso Electric Co.	13950 Stern	Mesquite	Doña Ana	32.165699	-106.68724	transformer oil spill	4/1/10	soil excavation	closed	6/30/2011
El Paso Electric Co.	14310 Stern	Mesquite	Doña Ana	32.165699	-106.68724	transformer oil spill	6/7/10	soil excavation	closed	6/30/2011
El Paso Electric Co.	4000 Hwy. 478	Mesquite	Doña Ana	32.057562	-106.628909	transformer oil	3/14/2013	soil excavation	closed	5/30/13
El Paso Electric Co.	36000 Rincon Mtn.	Rincon	Doña Ana	32.672395	-107.073291	transformer oil	5/15/2007	soil excavation	closed	7/3/2008
El Paso Electric Co.	Rincon Mtn.	Rincon	Doña Ana	32.672395	-107.073291	transformer oil	3/24/2008	soil excavation	closed	7/3/2008
El Paso Electric Co.	5301 McNutt	Santa Teresa	Doña Ana	31.848786	-106.6259	transformer oil spill	7/20/04	soil excavation	closed	1/27/2006
El Paso Electric Co.	101 Feathermoon	Santa Teresa	Doña Ana	31.843086	-106.651727	transformer oil	6/26/2006	soil excavation	closed	7/3/2008
El Paso Electric Co.	102 Casas Bella	Santa Teresa	Doña Ana	31.869318	-106.673361	transformer oil spill	12/16/09	soil excavation	closed	6/30/2011
El Paso Electric Co.	142 Feather Moon	Santa Teresa	Doña Ana	31.843809	-106.651399	transformer oil spill	7/23/03	soil excavation	closed	2/22/2005
El Paso Electric Co.	2750 Airport	Santa Teresa	Doña Ana	31.870534	-106.698905	transformer oil	12/27/2006	soil excavation	closed	7/3/2008
El Paso Electric Co.	300 Feather Moon	Santa Teresa	Doña Ana	31.843102	-106.653659	transformer oil	7/12/2000	soil excavation	closed	11/15/2000
El Paso Electric Co.	5535 Country Club Rd	Santa Teresa	Doña Ana	31.869318	-106.673361	transformer oil	4/8/2010	soil excavation	closed	6/30/2011
El Paso Electric Co.	6909 Binaltonal Ave.	Santa Teresa	Doña Ana	31.869318	-106.673361	transformer oil	6/4/2013	soil excavation	closed	6/30/2011
El Paso Electric Co.	7001 Pete Domenici	Santa Teresa	Doña Ana	31.869318	-106.673361	transformer oil	11/1/2006	soil excavation	closed	7/3/2008
El Paso Electric Co.	808 Green Bluff Ln.	Santa Teresa	Doña Ana	31.869318	-106.673361	transformer oil	11/12/2008	soil excavation	closed	7/3/2008
El Paso Electric Co.	Desert Pointe Apartments	Santa Teresa	Doña Ana	31.852359	-106.63602	transformer oil	1/21/2002	soil excavation	closed	3/21/2002
El Paso Electric Co.	105 Comerciantes	Santa Teresa	Doña Ana	31.872778	106.653889	transformer oil	7/21/2015	soil excavation	closed	4/15/2016
El Paso Electric Co.	1 Ardovino Lane	Sunland Park	Doña Ana	31.792268	-106.55726	transformer oil	8/30/2000	soil excavation	closed	11/15/2000
El Paso Electric Co.	107 Quinella	Sunland Park	Doña Ana	31.805225	-106.56627	transformer oil spill	8/24/09	soil excavation	closed	6/30/2011
El Paso Electric Co.	3005 McNutt	Sunland Park	Doña Ana	31.805686	-106.587042	transformer oil	11/8/2012	soil excavation	closed	11/20/12
El Paso Electric Co.	383 Riverside	Sunland Park	Doña Ana	31.817387	-106.598058	transformer oil	6/23/2011	soil excavation	closed	8/8/2011
El Paso Electric Co.	Diablo Substation	Sunland Park	Doña Ana	31.805155	-106.546437	transformer oil	10/1/2003	soil excavation	closed	10/28/2003
El Paso Electric Co.	Diablo Substation	Sunland Park	Doña Ana	31.805155	-106.546437	transformer oil	7/14/2003	soil excavation	closed	10/22/2003
El Paso Electric Co.	104 Del Prado	Sunland Park	Doña Ana	31.798889	106.583611	transformer oil	6/23/2015	soil excavation	closed	4/15/2016
El Paso Electric Co.	1400 Lechuga	Vado	Doña Ana	32.127537	-106.656504	transformer oil spill	4/25/05	soil excavation	closed	09/23/05
El Paso Electric Co.	8710 Highline	Vado	Doña Ana	32.127537	-106.656504	transformer oil	9/23/2001	soil excavation	closed	10/12/2001
El Paso Electric Co.	Apollo Substation	White Sands Test Facility	Doña Ana	32.505556	106.611944	dielectric fluid	8/1/2015	soil excavation	closed	4/15/2016
El Paso Electric Co.	6305 Dona Ana Rd	Las Cruces	Doña Ana	32.39642	-106.8327406	Release of mineral oil from electrical transformer	2/27/2019	Soil excavation	closed	7/5/2019
El Paso Electric Co.	510 S. Telshor	Las Cruces	Doña Ana	32.31408	-106.745122	Release of mineral oil from electrical transformer	3/21/2019	Soil excavation	closed	7/5/2019
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan Rd	Sunland Park	Doña Ana	31.834487	-106.588466	200 gal. diesel spill from pipeline	5/19/03	soil excavation	closed	2/22/2005
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan Rd	Sunland Park	Doña Ana	31.834487	-106.588466	compressor oil	8/18/2014	soil excavation	closed	9/18/14
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan Rd	Sunland Park	Doña Ana	31.834487	-106.588466	transformer oil	4/29/2008	soil excavation	closed	7/3/2008
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan Rd	Sunland Park	Doña Ana	31.834487	-106.588466	transformer oil	2/23/10	soil excavation	closed	6/30/2011
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan Rd	Sunland Park	Doña Ana	31.834487	-106.588466	transformer oil	9/13/2013	soil excavation	closed	1/10/14
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan Rd	Sunland Park	Doña Ana	31.834487	-106.588466	diesel fuel	5/7/2013	soil excavation	closed	1/10/14
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan Rd	Sunland Park	Doña Ana	31.834487	-106.588466	turbine oil	2/26/2015	soil excavation	closed	4/15/2016
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan Rd	Sunland Park	Doña Ana	31.834487	-106.588466	turbine oil	3/25/2015	soil excavation	closed	4/15/2016
El Paso Electric Co. (Rio Grande Power Plant)	3501 Doniphan Rd	Sunland Park	Doña Ana	31.834487	-106.588466	fuel oil	1990s	soil excavation	closed	6/17/2016
El Paso Electric Co., Rio Grande Power Plant, Sunland Park	3501 Doniphan Rd	Sunland Park	Doña Ana	31.8044	-106.5464778	~12,000 gals. of fuel oil (#2) spilled around AST #3, Soil excavation completed, GW monitoring completed	2/25/2006	Soil excavation completed, GW monitoring completed	closed	6/17/2016
Eubank Cleaners (former)	705 N. Main	Las Cruces	Doña Ana	32.31455123	-106.780294	Former Dry Cleaning facility. PCE release discovered by USGS in 2002 in relation to Griggs and Walnut Superfund site. Soil vapor sample contained PCE at 250,000 ug/m3, in excess of VISL. Passive soil vapor survey in 2022 showed no VISL exceedances.	unknown	diffusion, natural attenuation	closed	12/28/2022

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Esslinger Trucking, Mesilla Park	3201 S. Harrelson	Mesilla Park	Doña Ana	34.166233	-106.026069	dry fertilizer release during transfer from rail car to hopper to trucks	unknown	soil excavation and ceased	closed	1/31/2011
Evergreen MHP	6345 Doña Ana Rd	Las Cruces	Doña Ana	32.397657	-106.834205	untreated surfacing sewage	1/9/2007	sent Notification of Discharge letter on 2/9/07	referred	2/16/2007
Evergreen MHP	6345 N. Doña Ana Rd	Las Cruces	Doña Ana	32.397657	-106.834205	report asking for temporary DP until final DP is approved		referred to permitting	referred	
Flying P Cattle Co.	S. of Hwy 70 2.5 miles on Baylor Canyon Rd	Las Cruces	Doña Ana	32.337077	-106.819454	Small public supply well showed intermittent NO3 contamination.	unknown	site investigation and sampling did not reveal a source. If more info becomes available, than re-assessment will occur	closed	1/25/2011
Former Charter Hospital (Alliance Hospital)	100 Charter Court	Santa Teresa	Doña Ana	31.869318	-106.673361	emergency generator diesel spill	pre 2002	soil excavation	closed	7/22/2004
Fort Bliss, Doña Ana Range Camp	Fort Bliss	Fort Bliss	Doña Ana	34.166233	-106.026069	hydraulic lift leak in 1995	pre 1995	soil excavation	closed	6/17/1995
Gale Property	931 Bleimyer	Las Cruces	Doña Ana	32.37835173	-106.8015078	Residential Diesel Spill	Apr-11	Excavation, failed to submit CAR.	Closed	11/16/2022
City of Las Cruces Gas Spill to storm drain	1501 E. Amador	Las Cruces	Doña Ana	32.310363	-106.763447	unleaded. Gas	1/22/2010	pumped out stormwater runoff pond	closed	4/28/2011
Golden West Truck Stop	I-10 and Vado Exit	Vado	Doña Ana			report of fuel spill	10/27/1995	refer to PSTB	referred	
Graves Oil and Butane	202 S Compress Rd, and 801 W. Organ	Las Cruces	Doña Ana	32.306495	-106.787876	oil spill on Compress, and contaminated soil on W. Organ from small AST farm	pre 2000	soil excavation	closed	5/23/2000
Harrelson Spill, Mesilla Park	110 Hanks	Mesilla Park	Doña Ana	34.166233	-106.026069	motor oil release from leaking 55-gal barrel	unknown	soil excavation	closed	1/31/2011
Heil Pump Sales	255 Carver	Mesilla Park	Doña Ana	34.166233	-106.026069	various petroleum spills throughout	12/21/04	soil excavation, soil & supply well sampling	closed	8/4/2006
Helena Chemical	251 John Grisham	Mesquite	Doña Ana	32.164167	-106.6972	small diesel spill found on northern property	2/5/07	soil excavation	closed	6/15/2007
Helena Chemical	251 John Grisham	Mesquite	Doña Ana	32.164167	-106.6972	30 pounds of sulfur dry fertilizer spill	8/23/07	sulfur removal	closed	7/3/2008
Helena Chemical Co.	2537 Hwy. 140	Rincon	Doña Ana	32.67299444	-107.06410556	liquid fertilizers	5/3/07 and 4/14/08	soil excavation	closed	9/23/13
Helweg and Farmer Transportation Co.	533 N 17th St.	Las Cruces	Doña Ana	32.307136	-106.804901	35 gal of diesel spill	9/11/2000	soil excavation	closed	10/18/2000
Home Depot	Telshor and Lohman	Las Cruces	Doña Ana	32.318605	-106.746607	diesel fuel spill	pre 1/11/99	soil excavation	closed	1/11/1999
Hope Lumber (L&P Properties)	101 Archuleta Rd	Las Cruces	Doña Ana	32.303582	-106.794731	diesel contaminated soil	before 7/29/1999	soil excavation	closed	8/30/1999
HORVAC grease disposal	DP 1355 on west mesa near Afton siding; county rd. B007	Whitman	Doña Ana			2,000 gals of grease trap liquid waste spill	5/21/2007	Health threat mitigated by blading contaminated soil into berm along bar ditch	closed	8/21/2007
Idaho Street and Solano Street	Las Cruces		Doña Ana			report showing PID hits in one borehole but GW below laboratory detection in grab sample	unknown	data did not show contamination concern	inactive	
Illegal sludge dumping	west of San Miguel		Doña Ana			spill report and one sample on VOCs (ND)	Jan-88	unknown	inactive	
Lane Property	1285 W. San Miguel	La Mesa	Doña Ana	32.124785	-106.708078	petroleum	10/2/2009	soil excavation	closed	8/30/2011
City of Las Cruces Roadrunner Transit Facility	1501 E. Hadley Ave	Las Cruces	Doña Ana	32.31731945	-106.7658262	215 diesel gallon spill at pump island	10/25/2006	soil excavation	closed	8/17/2007
Lead in soil, Organ		Organ	Doña Ana			health dept samples showing high lead in horse dog and woman	pre 1995	soil excavation through CERCLA	referred	
Legends West Subdivision	un-named lot	Las Cruces	Doña Ana	32.3193702	-106.8188683	naphthenic petroleum oil mixture release from vandalism.	2008	soil excavation	closed	9/22/2008
Lopez complaint	1154 Sandpiper	Santa Teresa	Doña Ana	31.869318	-106.673361	concerns over petroleum contaminated soil	Aug-92	inspection showed small area and not threat to GW	closed	9/10/1992
McAnally Egg Facility	415 San Benito Rd	Berino	Doña Ana	32.073485	-106.619825	Egg farm operation from '70s to 2011, impacted gw with nitrate, chloride, TDS	unknown	assessment	transferred to VRP	2/12/2016
Memorial Medical Center	2450 South Telshor Blvd	Las Cruces	Doña Ana	32.292391	-106.735035	20 gal of diesel spilled	3/30/2002	soil excavation	closed	4/6/2001
Mesa Feed	2424 Rincon Rd	Rincon	Doña Ana	32.673312	-107.062865	Spills of cattle feed supplements, primarily urea and molasses	unknown	soil excavation	closed	7/14/2017
Mesilla Valley Tyre	6375 W. Picacho	Las Cruces	Doña Ana	32.287187	-106.875272	petroleum hydrocarbons	ongoing, discovered June 2008	soil excavation	closed	4/10/2009
Mesquite Area Wells		Mesquite	Doña Ana			Sampling of domestic wells in village	unknown	Sampling of domestic wells	inactive	1978
Mesquite Mutual Domestic Water Consumers and Mutual Sewage Works Association	St. Thomas Avenue	Mesquite	Doña Ana	32.165699	-106.68724	6,000 gal of sewage spill	11/17/2007	soil excavation and disinfection	closed	7/3/2008
Milagro Colonia	near Hatch	Hatch	Doña Ana	32.650378	-107.198495	leachfield overflow	continuous	sampld leachate for VOCs, major ions, nitrate, TKN, ammonia, metals	referred to EHD	
NASA Well "I"	NASA Johnson Space Center WSTF	Organ	Doña Ana	32.424566	-106.599794	oil in supply well	1964 to present	well maintenance	closed	12/4/2008
New Aces Pecan Company	2455 Entrada del Sol	Las Cruces	Doña Ana	32.31000000	-106.74750000	nitrate in temporary unauthorized discharge	April 2015-April 2016	Characterized discharge, installed pretreatment improvements to prevent overflow	closed	5/31/2016
NMSU Boneyard	1/4 mile north of Geothermal Rd and Aggie Rodeo Drive	Las Cruces	Doña Ana	32.289369	-106.711759	Soil contamination from various petroleum releases	unknown	soil excavation	closed	8/5/2014
El Paso Electric Co.	451 North Roadrunner Parkway	Las Cruces	Doña Ana	32.32838	-106.74111	10 gal. mineral oil spill	4/29/2022	soil excavation	closed	7/12/2022

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Organ Mt. TCE and NO3		Organ	Doña Ana			TCE showed up in water supply back before 84, NO3 concerns due to WWTP		monitoring by PPS	inactive	
Pena's Tile	817 Quesenberry	Las Cruces	Doña Ana	32.309012	-106.80451	motor oil spill	ongoing, discovered July 2008	soil excavation	closed	4/10/2009
Pep Boys Las Cruces	1203 Lohman Av	Las Cruces	Doña Ana	32.308605	-106.766096	O/W separator removal with low TPH	1997	soil excavation	closed	6/19/2005
Pete Kaiser Well	Hatch Elementary School	Hatch	Doña Ana	32.650378	-107.198495	report of LNAPL in well	2/22/2002	well sample showed clean	closed	2/2/2007
Picacho Hills Fluoride	Butterfield Ridge Subdivison	Las Cruces	Doña Ana	32.32235949	-106.8769356	Private wells with high Fluoride	source unknown	wells sampled	closed	2007-2008
Placitas Gravel Pit	1.5 miles W of Hatch (T19S, R3W, S18.22)	Hatch	Doña Ana			diesel	unknown	soil excavation	closed	11/13/1996
PNM Afton Gen. Station	10100 W. Afton Rd	La Mesa	Doña Ana	32.124785	-106.708078	bulk plant investigation	none	Inspected 1M gal. tank and piping. No leaks observed.	closed	3/6/2006
Pony Carburator	112 Westgate	Las Cruces	Doña Ana	32.30059022	-106.8067704	environmental complaint	referred to HWB	referred to HWB	closed	7/19/2006
Qwest	Doña Ana School Rd and El Camino Real intersection	Doña Ana	Doña Ana	32.382821	-106.814994	disposal of drilling mud in EBID right-of-way	2/14/07	Excavation contractor returned to clean-up neighbor's yard	closed	2/20/2007
Ramon's Garage	1500 E. Kansas	Las Cruces	Doña Ana	32.308285	-106.762785	spill of used oil and antifreeze	pre 2001	soil excavation	closed	6/24/2003
Rea Magnet Wire	301 Rea Blvd.	Las Cruces	Doña Ana	32.337077	-106.819454	2,300 gal. mineral oil spill from broken pipe	Nov. 2005	pipe repaired, soil excavated & sampled	closed	6/6/2006
Reliable Carriers Diesel Release	diesel release - US Hwy 70 east San Augustin Pass rest area	Las Cruces/Organ	Doña Ana			Truck was leaking diesel from saddle tanks.	12/22/2008	soil excavation and removal	closed	5/15/2009
Rexene Products	Sunland Park	Doña Ana	Doña Ana			draft AOC about old refinery with LNAPL	before 1991	unknown	inactive	
Ritchie Chevron	2205 S. Valley	Las Cruces	Doña Ana	32.328184	-106.805259	motor oil spillage from overturned 55-gal. drums	Dec. 2005	soil excavation	closed	3/6/2006
Ritter Distributing Bulk Plant	W. Hall St.	Hatch	Doña Ana	32.66527377	-107.15586	report of diesel cont. soil	before 7-95	unknown	Referred to PSTB	July-95
Salopek Farms	1950 W. Berino Blvd.	Berino	Doña Ana	32.068064	-106.622724	nitrate	unknown	soil excavation and sampling; final report not yet submitted	inactive	1/5/13
Santa Fe Pacific Pipeline Partners		Anthony	Doña Ana			500 gal of diesel spilt during pipeline relocation	7/28/1992	soil excavation	closed	11/1/1992
Sara Lee Hosiery	T24SR2E 9	Las Cruces	Doña Ana			mineral oil spill	1992	SWQB oversaw corrective action	closed	1/8/1993
Shook Tire	717 N. Main	Las Cruces	Doña Ana	32.315277	-106.780262	hydraulic fluid	pre-2012	soil excavation	closed	11/19/2013
SLO trespass dumping	32.431671; -106.706373	East Mesa	Doña Ana	32.431671	-106.706373	drums of waste oil released near city well	undetermined	City of LC hired Terracon, SLO performing CA through Rhino	closed	
SLO trespass dumping	32.431671; -106.706373	East Mesa	Doña Ana	32.431671	-106.706373	drums of waste oil released near city well	undetermined	City of LC hired Terracon, SLO performing CA through Rhino	closed	
SLO trespass dumping	32.095847; -106.767828	West Mesa	Doña Ana	32.095847	-106.767828	drums of waste oil and antifreeze	undetermined	SLO hired contractors	closed	
Sonoma Elementary	4201 Northrise Drive	Las Cruces	Doña Ana	32.337077	-106.819454	curdled milk from dairy load lost by eqpt malfunction on vacuum septic pumper	1/4/07	septage spill on property cleaned up by Southwest Envirotech	closed	2/5/2007
Soto Oil, Sharp Oil		Anthony	Doña Ana			phase 2 showed low levels of TPH in soil	3/4/1999	soil sampling	closed	5/4/1999
Southwest Envirotech	DP-1355	Afton siding	Doña Ana			spill of grease trap waste (2000 gal) from vac truck missing outlet cap	5/21/07	road grading	closed	
State Land Office Trespass Dumping	32.43203056,-106.7048167	Las Cruces	Doña Ana	32.43203056	-106.7048167	petroleum lubricants	unknown	soil excavation	closed	1/25/2011
Swift Transportation	I-10 (westbound), approximately ¼ mile east of exit 135	Las Cruces	Doña Ana			diesel spill	7/30/2008	soil excavation	closed	4/30/2009
Tommy's Garage	18617 S. Hwy. 28	San Miguel	Doña Ana	32.149927	-106.727513	various car fluids (motor oil, antifreeze) spilled on soil	4/12/05	Conducted site inspection, verified contamination.	referred to HWB	3/20/2006
United Agri Products	NM 478 (200 yds. south of UAP)	Vado	Doña Ana	32.127537	-106.656504	small spill of dry fertilizer on road	1/26/07	fertilizer swept up & reused	closed	3/9/2007
United Petroleum Transport	I-10 and Hwy. 404	Anthony	Doña Ana	32.02459	-106.588781	truck accident lost 7,300 gals. of diesel	7/11/04	soil excavation	closed	12/21/2004
Valle del Rio subdivision	32.209243; -106.761349	Rio Grande floodplain	Doña Ana	32.209243	-106.761349	spots in field with no vegetation growing	undetermined	SLD eliminated Roundup but is analyzing for presence of other herbicides	closed	8/21/2007
Welch Dirt Work	3615 W. Picacho	Las Cruces	Doña Ana	32.30867694	-106.8310156	petroleum hydrocarbon contaminated soil	unknon	soil excavation	closed	8/17/2007
Western Blend Peacan Farm	7000 N. Valley	Las Cruces	Doña Ana	32.3998397	-106.8491533	environmental compliant - sulfuric acid tanks	n/a	n/a, no release occurred	closed	11/19/2008
Westside Recyclers	1961-81 Copper Loop	Las Cruces	Doña Ana	32.306008	-106.805226	Poor practices resulted in vehicle fluid spills	unknown	soil excavation and improved practices	closed	1/25/2011

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
WSMR Heating Oil	UST at LC-33	White Sands	Doña Ana			heating oil release from LUST	pre 1998	soil excavation	closed	6/20/1998
El Paso Electric Co.	144 Camino De Nosotros	Las Cruces	Doña Ana	32.37386	-106.80975	Release of mineral oil from electrical transformer	4/4/2019	Soil excavation	closed	7/5/2019
El Paso Electric Co.	Frank Maes Ave. and Spitz Ave	Las Cruces	Doña Ana	32.37386	-106.80975	Release of mineral oil from electrical transformer	4/4/2019	Soil excavation	closed	7/5/2019
El Paso Electric Co.	3501 Doniphan Dr., Sunland Park, NM	Sunland Park	Doña Ana	31.80475	-106.547661	Release of Diesel #2	10/1/2019	Soil excavation	closed	2/10/2020
El Paso Electric Co.	Highway 26	Placitas	Doña Ana	32.64106	-107.218555	10 gallon spill of hydraulic oil	1/16/2020	Soil excavation	closed	12/11/2020
El Paso Electric Co.	Highway 28	Vado	Doña Ana	32.09147	-106.682611	5 gallon spill of mineral oil	3/13/2020	Soil excavation	closed	12/11/2020
El Paso Electric Co.	1105 E University Ave	Las Cruces	Doña Ana	32.28476	-106.754267	10 gallon spill of mineral oil	3/16/2020	Soil excavation	closed	12/11/2020
El Paso Electric Co.	EPEC Rio Grande Power Plant	Sunland Park	Doña Ana	31.80578	-106.547478	8 galling spill of transformer oil	6/4/2020	Soil excavation	closed	12/11/2020
Former Model Cleaners	113-135 West Griggs Street	Las Cruces	Doña Ana	32.309274	-106.779339	Former Dry Cleaning facility. Soil vapor samples contained PCE at 33,000 ug/m3, in excess of VISL. Submission required letter issued 5-14-2020.	unknown	Needs assesment	applied to VRP	7/13/2020
SFPP Falc Trucking Yard	Two areas: 435 E. Joy Drive and 32.038181, -106.613336	Anthony	Doña Ana	03975332.038181	-106.609678-106.613336	Pacific pipeline spill transported to site. Soil removed from site, soil beneath piles sampled to confirm no impact.	1/1/2019	Soil excavation	closed	7/30/2020
Comet Cleaners - Las Cruces	2001 E. Lohman	Las Cruces	Doña Ana	32.31107400	-106.756651	Soil vapor investigation from 2002 reevaluated with respect to VISIs in 2018, identified release. Soil gas and indoor air investigation identified shallow vapor plume. Soil Vapor extraction system removed vapor plume.	pre 2002	Soil Vapor Extraction	closed	7/2/2020
El Paso Electric Co.	1237 North Tornillo Street	Las Cruces	Doña Ana	32.32074000	-106.77623000	Mineral oil discharge from transformer	2/10/2021	Soil excavation	closed	8/3/2021
El Paso Electric Co.	2873 Cloudcroft Circle	Las Cruces	Doña Ana	32.33809100	-106.74487000	Mineral oil discharge from transformer	5/28/2021	soil excavation	closed	8/3/2021
El Paso Electric Co.	East Foster and East Hill Street	Hatch	Doña Ana	32.66778000	-107.14972000	Mineral oil discharge from transformer	1/20/2021	Soil excavation	closed	8/3/2021
502 North Canal St, Carlsbad	502 North Canal St	Carlsbad	Eddy	32.415338	-104.228683	Phase I ESA and Phase II indicated release of petroleum and chlorinated solvents, but below reportable level	unknown	soil excavation	closed	8/17/2017
American Auto & Equipment Auctions	1400 San Jose	Carlsbad	Eddy	32.397259	-104.215582	report of petroleum hydrocarbon releases from salvage yard	unknown	new property owner and no further releases of automotive fluids	inactive	
Artesia old landfill	Commerce and Pecos St	Artesia	Eddy	32.874234	-104.386688	surficial petroleum dumping on old landfill initiated subsurface investigation	unknown	MW installation and GW monitoring	closed	12/10/2013
Asphalt Terminal (Holly Asphalt Co.)	2411 N. Freeman	Artesia	Eddy	32.848005	-104.414958	bulk plant investigation	none	Large tanks have liquid asphalt only.	closed	Feb. 2006
ATSF derailment		Loving	Eddy			locomotive tank leak of 700 gal of diesel	5/13/93	soil excavation and on-site treatment	closed	6/28/1993
Ballard Wells	T25S, R24E, 34.1	Carlsbad	Eddy	32.0912437	-104.491745	natural gas in domestic wells	1989	sampled of wells and results showed no GW contamination	closed	6/11/1989
Beker Industries		Carlsbad	Eddy			well samples with high TKN	1977	unknown	inactive	
Carlsbad Ford	2802 W. Pierce St.	Carlsbad	Eddy	32.445405	-104.262263	CAR / property transfer. Investigation/ clean up and refinancing of Carlsbad Ford dealership to new owner	unknown	CAR reports conditionally approved and investigation and abatement completed	closed	7/25/2014
Carlsbad Municipal Water Wells		Carlsbad	Eddy			Evaluation of City wellfields		evaluation of wellfield	inactive	12/15/1987
Carlsbad Pesticides	4409 Ferguson	Carlsbad	Eddy	32.371136	-104.140744	neighbor complaint about possible contamination	unknown	sampled soil and various tanks/drums for VOCs, SVOCs, pesticides, metals	referred to HWB	
Chaparral Cattle Co.	5300 Seven Rivers Hwy	Carlsbad	Eddy	32.611059	-104.417576	motor oil and chlorinated pesticides discharged on-site	pre 1998	soil excavation and GW monitoring	closed	2/5/1998
Chevron Helbing Federal Oil Well	T22S, R23E, 15.1		Eddy			site assessment of oil well sent to OCD	Aug-94	part of OCD case load	referred	
Dowell Schlumberger Facility	500 E. Richey Ave	Artesia	Eddy	32.857246	-104.361297	chlorinated solvents found in GW during a PSTB investigation	pre 1993	GWQB began site assessment and discovered site was OCDs	referred to OCD	3/12/1996
Dowell Schlumberger Facility	Artesia	Artesia	Eddy			chlorinated solvents found at LUST site	pre 1994	NOD sent 9-8-94	refer to OCD	unknown
F-4E AF plane crash near Hope	T19S, R21E, 15	Hope	Eddy			cont. soil from plane crash	12/12/1995	soil excavation	closed	3/5/1996
former Enertech Wireline Service Facility	6551 Seven Rivers Highway	Artesia	Eddy	32.81738	-104.395324	septic tank sample showed low levels of PCE	unknown	soil borings by tank and leachfield showed ND for all VOCs	closed	2/2/2010

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
former SW Purity Water	201 Blodgett St	Carlsbad	Eddy	32.432081	-104.227492	discharge of water softener waste	pre 1997	soil excavation and practice change	closed	4/26/1999
Fronk Oil Co.	4021 Iron Horse Dr.	Carlsbad	Eddy	32.370932	-104.228076	2,000 gallon diesel release	44420	soil excavation and Goldcrew® (biodegradation agent) application	closed	12/15/2021
Gnome underground nuclear test	25 mi SE of Carlsbad, T23S,R30E,34	Carlsbad	Eddy	32.2631	-103.86646	nuclear test site in 1961, 3-kiloton bomb	1961	assessment and soil removal	VRP site	ongoing
Harris well	1205 Central Ave	Carlsbad	Eddy	32.397259	-104.215582	cont. water from domestic well possibly from Oil well	1976	referred complaint to OCD	referred	
Intrepid Potash East Plant	210 Red Cloud	Carlsbad	Eddy	32.397259	-104.215582	diesel	2/7/2012	soil excavation	closed	2/10/2012
Mel Foley Ranch	56 miles west of	Artesia	Eddy	32.848005	-104.414958	215 gal diesel spill	10/22/1998	soil excavation	closed	12/21/1998
Moffat Hay Company	2216 Smedley Rd	Carlsbad	Eddy	32.397259	-104.215582	8 barrels of leaking used oil	pre 3/1993	soil excavation	closed	7/8/1993
MPI East	210 Red Cloud	Carlsbad	Eddy	32.397259	-104.215582	bulk plant investigation	none	Has 60K tank but is empty and hasn't been used for a while.	closed	Feb. 2006
MPI West	1996 Potash Mines Rd	Carlsbad	Eddy	32.397259	-104.215582	bulk plant investigation	none	No tanks over 55K gals.	closed	Feb. 2006
Navajo Refinery	T17S, R26E, 8 and 9	Artesia	Eddy			synopsis of petroleum cont. at refinery	1985	synopsis refers to HWB and OCD oversight	referred	
N-Ren Plant	5 mile E of Carlsbad on Hwy 62/180	Carlsbad	Eddy			old fertilizer plant showed high Nitrogen in soil and GW	pre 1992	site assessment showed unusual high N background	inactive	6/15/1995
Odorless Cleaners	405 West Fox	Carlsbad	Eddy	32.419117	-104.23036	discovery of old USTB MWs	pre 1993	resampled MWs and below standards	referred to PSTB	11/5/2012
PCE Artesia, DP#550 monitor wells	2411 North Freeman	Artesia	Eddy	32.874441	-104.39726	discovery of PCE in MWs shows a trespassing plume on permitted site	unknown	determine source of PCE	inactive	
Standpipe Rd NO3 contamination	Standpipe road	Carlsbad	Eddy	32.397259	-104.215582	22 domestic wells had high nitrate presumably from septic systems	pre 1992	presumed connection to city water	inactive	
Steere Tank Lines	1713 Roselawn	Artesia	Eddy	32.848005	-104.414958	small AST farm with historic spills	pre 99	LNAPL recovery and MNA in GW - referred to PSTB with new regs	referred	6/24/2001
Tebuthiuron Herbicide - BLM	11 miles W of Malaga on Black River Village Rd	Malaga	Eddy			Aerial application of herbicide by BLM on 1/20/03. Storm 2 days later caused runoff to get into irrigation ditch killing crop of corn	7/18/03	NMCD sampled domestic and a public well along with Black River and found GWQB responded saying that prioritization ranking was low would not be assigned	closed	3/19/2003
Texaco Bulk Plant	306 N. First St.	Artesia	Eddy	32.844564	-104.397723	Phase 2 ESA showed VOCs in soil and in one MW	pre 1992	GWQB responded saying that prioritization ranking was low would not be assigned	inactive	1/11/1992
WIPP site		Carlsbad	Eddy	32.372121	-103.79556	25 gal sewage spill	10/3/1995	disinfected soil	closed	
WIPP site		Carlsbad	Eddy	32.372121	-103.79556	70 gal of diesel spill	9/10/94	soil excavation and land farming	closed	11/1/1994
Holly Energy, MP-14	Dinkus Ranch	Artesia	Eddy	32.764605	-104.575335	petroleum hydrocarbons pipeline release	2/13/2019	soil remediation	closed	9/30/2021
BNSF Carlsbad	108 East Hagerman Street	Carlsbad	Eddy	32.425229°	-104.225250°	Release of 20 gallons of diesel from locomotive overnight	2/28/2019	soil excavation, GW sampling	closed	2/28/2020
Pico Propane - Expert Analysis	2739 Pecos Hwy	Carlsbad	Eddy	32.35190600	-104.17138900	100 gallon diesel overflow of mobile AST.	5/28/2020	Soil excavation	closed	12/11/2020
Crop Production Services	60 E. Compress Rd	Artesia	Eddy	32.848005	-104.414958	petroleum contaminated soils and fertilizer	unknown	soil excavation and GW monitoring	closed	10/1/2009
Allen Peterson Trailer Park	2108 N. Cactus Dr.	Silver City	Grant	32.786226	-108.270278	septic system overflow	May-96	leachfield replaced	closed	6/18/1996
Arenas Valley Solvents	W of Central	Arenas Valley	Grant			domestic wells with TCA hits	before 7-16-97	sampling showed low concentrations	inactive	
A&R Garage	101 E. College Ave	Silver City	Grant	32.77474193	-108.2759802	CVOCs discovered in MWs at PSTB site	unknown	Monitoring, unknown source	Deferred to CERCLA	
Cameron Creek	T17S, R13W, S2	Fort Bayard	Grant			anonymous dumping of used oil in arroyo	pre 11/03	soil results showed no threat to GW	closed	7/30/2004
Camino Seco Meth Lab	19 Camino Seco	Silver City	Grant	32.76966042	-108.2218349	meth waste discharged to septic	1995	Septic Pumped	closed	1996
CTS Dry Cleaners	1330 N. Pope	Silver City	Grant	32.779054	-108.275676	PCE	unknown	soil vapor monitoring	closed	3/2/2011
Domestic well low VOC hits		Silver City	Grant			results of butanone in domestic well	Jan-90	unknown	inactive	
Ford Lincoln Mercury Dealer	Silver City Dealer	Silver City	Grant			during a LUST investigation additional contaminated soil was discovered	pre 2/92	soil excavation	closed	post 1992
former San Man & Sons Construction	3535 Railroad Drive	Silver City	Grant	32.724981	-108.245265	illegal storage of motor oil waste and releases	undetermined	investigation of soil contamination and stockpiled waste oil removed	closed	in process
Housely Distributing, Inc.	123 S. Railroad	Silver City	Grant			petroleum	unknown	ASTs	referred to PSTB	
Lake Roberts	33 01' 57"N, 108 10' 02"W	Silver City	Grant	33.0325	-108.1672	Sediment placed by cabins near lake had some Pb.	Dec-98	NMED sampled domestic wells and soil and results were ND	closed	8/19/1999

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
P&R Mobile Home Park	3795 Hwy 90 South	Silver City	Grant	32.7215392	-108.297804	Domestic wastewater spill	unknon	Mobile Home Park Closed and went into bankruptcy	closed	11/30/1989
Southwest Rail Road Hurley Railyard	Diaz Ave. and 4th St.	Hurley	Grant	32.70159100	-108.13242600	Widespread oil and diesel contamination due to poor management practices.	unknown	soil excavation, drilling	closed	5/4/2021
Separ siding on Union Pacific RR	Separ Exit, north side of I-10	Separ	Grant	32.202034	-108.422699	report of floating product in supply well	historic, anecdotal	Contractor exposed reported well with oil and well was dry. Well and adjacent producing well were P&A'd by D&J Drilling out of Deming. Inspected site: truck stop and 100 gal diesel tank unknown	closed	4/5/2006
Separ Truck stop	I-10 and Exit 42	Separ	Grant	32.202034	-108.422699	bulk plant investigation	none		closed	3/6/2006
Verlane Jones	29 Rodeo Rd	Silver City	Grant	32.772986	-108.261418	report of petroleum hydrocarbon	10/8/1996		inactive	
Air Road Express Truck Accident	I-40 mile 242	Santa Rosa	Guadalupe	34.930632	-104.672144	truck accident caused 150 gal of diesel spill	9/6/2000	soil excavation	closed	10/18/2000
ATA pipeline Spill -Milagro Pump Station	R9N, R16E, S3	Milagro	Guadalupe	34.166233	-106.026069	pipeline spill due to backhoe activities. Lost 938 barrels of diesel spilt	2/5/1990	soil excavation	closed	6/14/1990
BNSF Locomotive Derailment	mile post 792.7 5 mile W of Vaughn)	Tejon	Guadalupe	34.166233	-106.026069	locomotive derailment spilt diesel fuel1	12/20/1995	soil excavation	closed	4/1/1996
Diamond Shamrock Cuervo Pump Station	11 miles N of Cuervo	Cuervo	Guadalupe			50 barrels of diesel and turbine fuel spilt when pump on pipeline failed	7/2/1999	soil excavation and MNA of soil	closed	4/1/2003
DOD Air Force F-16 Jet Crash	T5N, R17E, S5	Vaughn	Guadalupe			F-16 crash spilling jet fuel	5/12/1997	MNA of soil was shown through sampling	closed	9/5/1997
FAA Moon Ranch LUST	Hwy 84, 6 miles N of I-40,	Dilia	Guadalupe			diesel generator UST for FAA	pre 1992	soil excavation	closed	5/30/2003
Forward Air Inc Truck Accident	I-40 MM 300	Newkirk	Guadalupe	35.062549	-104.265827	truck accident released 100 gallon of diesel	9/22/2013	soil excavation	closed	6/27/2014
Puerto de Luna Acequia Diesel spill	Puerto de Luna Acequia	Puerto de Luna	Guadalupe			sheen seen on Pecos River that came from a diesel irrigation pump used to supply water to acequia	5/28/2008	pump repaired and high flows in river diluted carried residual contaminated soil downstream.	closed	7/31/2008
Santa Rosa School District Heating oil Tank		Santa Rosa	Guadalupe			heating oil release from UST	6/19/1995	initial soil results showed low levels of TPH adjacent to UST.	closed	2/2000
Schneider National Truck Accident	I-40 and mile 305		Guadalupe			truck accident caused 100 gal diesel spill	10/15/2000	soil excavation	closed	1/3/2001
Waggoners Trucking	Derby Rd near Dexter Hwy 54 and Hwy 60, .7 mi e of Vaughn	Santa Rosa	Guadalupe			truck accident, 200 gal diesel	7/13/2000	soil excavation	closed	4/11/2001
XL Insurance		Vaughn	Guadalupe	34.595125	-105.177295	Tuck accident with diesel release	2/1/2005	soil excavation	closed	5/4/2005
AmeriGas Solano	1-2 miles SE of Solano	Solano	Harding	35.838448	-104.050256	Phase II investigation showed petroleum hydrocarbons in GW at former CO2 facility	pre 1989	GW investigation	closed	6/16/1989
BOC Gasses	1463 Hwy 102	Bueyeros	Harding	34.166233	-106.026069	Former liquid CO2 and Dry ice manufacturing plant had residual diesel soil contamination	unknown	soil excavation	closed	2/15/2007
		Solano	Harding			domestic well sampling including Rad		domestic sampling	inactive	8/1/1998
El Paso Electric Co.	Hidalgo Substation	Lordsburg	Hidalgo	32.40303	-108.600173	Release of mineral oil from electrical transformer	11/26/2018	Soil excavation	closed	2/7/2019
BJ Cecil Trucking	Hwy 70 and SR464	Lordsburg	Hidalgo	32.397246	-108.725992	truck accident caused release of 1600 gal of H2SO4	8/20/1999	soil excavation	closed	5/19/2000
Pyramid (Tri-State) Gen. Station	53 Ramos Farms	Lordsburg	Hidalgo	32.346903	-108.702482	bulk plant investigation	none	Inspected site. 1.5M gal. tank, berms, and liner in excellent condition. No leaks observed.	closed	3/6/2006
Pyramid Generating Station	No. 53 Ramos Ranch	Lordsburg	Hidalgo	32.346903	-108.702482	historic discovery of diesel spill and lube oil	pre 11/03	soil excavation	closed	4/16/2004
Steer Tank Lines	Hwy 70 mile 1	Lordsburg	Hidalgo			truck accident caused release of 8200 of diesel	6/7/1998	soil excavation	closed	6/20/1998
USA Petroleum #802	I-10 and Hwy. 80	Road Forks	Hidalgo	32.233572	-108.952767	spillage of diesel fuel from ASTs	Nov. 2003	soil excavation	closed	8/30/2005
Western Refining	US 70, MM 24	Lordsburg	Hidalgo	32.346903	-108.702482	diesel	8/16/2008	soil excavation	closed	4/5/11
Araho Well Site	5 mile S Hwy 18	Loving	Lea	32.707293	-103.115658	Assist City of Lovington on clean up of disposal well.	unknown	referred to OCD		12/15/99
Axelson Facility	2730 W Maryland	Hobbs	Lea	32.739668	-103.127573	report of 95 soil and GW cont. at the oil field service co.	9/14/1995	refer to OCD	referred	9/21/1995
Bar4 Dairy/Hobbs Drive-In Dairy	3600 Dal Paso	Hobbs	Lea	32.449053	-103.191296	pre 77 dairy that had modifications	pre 77	referred to PPS	referred	
Bell Gas Truck Accident	17.7 mi E of Hwy 62 on St Rd 176	Eunice	Lea			truck accident spilled 1000 gal gasoline	9/11/2005	soil excavation	closed	3/11/1999
Bulldog Services Accident Spill	Hwy 176, 4 mi W of Hwy8, 10 mi W of Eunice	Eunice	Lea			traffic accident,300 gal diesel, 200 gal anti-freeze	8/27/1998	soil excavation	closed	1/10/2003
Climax Chemical Co. Bankruptcy	313 W. Marland		Lea			Climax bankrupt/NMED, Public land commissioner got \$45K, property got sold. Probably transferred to OCD	pre 96	refer to OCD	referred	
Cline		Hobbs	Lea			spill of 60 gal of used oil	pre 1991	soil excavation	closed	post 1991
Conoco Travel Center	3305 W. Marland	Hobbs	Lea	32.696558	-103.178561	diesel and wash down water accumulated in stormwater pond contaminating soil	2/7/2000	soil excavation	closed	3/17/2003

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Davis Gas Plant	4 mi S of Hobbs Hwy 18	Lovington	Lea			bulk plant investigation	none	Is being regulated by OCD since it's a natural gas processing plant.	closed	Feb. 2006
Domestic well NO3 cont.	Hobbs Airport	Nadine	Lea	32.624197	-103.10777	domestic well results showing high NO3, source is old Custom Slaughter and Meat Co.	3/12/1987	referred to permitting	referred	
Fire Training Pits	Lot 7-18, Block 35	Hobbs	Lea	32.727533	-103.16204	discovery of petroleum contaminated soil from former fire training pits	pre 1991	soil excavation	closed	post 1991
former Hobbs Spring Works	Turner and Roxana	Hobbs	Lea	32.694344	-103.135978	upon foreclosure petroleum contaminated soil was discovered	pre 1992	soil excavation	closed	post 1992
Hines Super Shell	Lea County Airport	Hobbs	Lea			chlorinated solvents detected in ground water at adjacent PSTB site	unknown	interviewed plant foreman and found out that there is a Discharge Plan.	referred to OCD	Aug. 2005
Hobbs Airport Firepit	adjacent to Hwy 62-180 in airport	Hobbs	Lea			fire training pit had soil contamination from fuels ignited and put out in training	pre 89	1320 yds of soil removed	closed	12/16/1991
Hobbs Municipal wells	various	Hobbs	Lea			Memo of petroleum concerns in city production wells			referred to PSTB	7/4/1984
Hondo Chemical Facility	railroad siding	Eunice	Lea	32.449053	-103.191296	sulfur slurry improperly contained	pre 2002	removal of slurry and BMP	closed	2/19/2002
Kealing Distributing Co.	2900 W. Marland	Hobbs	Lea	32.696516	-103.172692	5000 gal diesel spill from AST vandalism	3/26/1999	soil excavation	closed	9/24/1999
Koch Hobbs	2121 French Dr.	Hobbs	Lea	32.722992	-103.162103	900 gal diesel release in '92, soil removal	Jul-92	soil excavating	closed	3/12/1998
KW Fuels	US 62/180 mile 93	Hobbs/Carlsbad	Lea	34.166233	-106.026069	5000 gal of gasoline release in an accident	10/17/2000	soil excavation	closed	3/6/2001
Lea County Brine Contamination Report (OCD)			Lea			Report to Water Quality Control Commission on Brine Contamination				8/15/1973
Marathon Oil, Lea Co	T20S, R37E,S5.33	Hobbs	Lea			Stage 2 AP required by OCD	8/21/2000	referred to OCD	referred	
Melot Oil Company	1200 W. County Rd	Hobbs	Lea	32.702477	-103.176074	AST spill release in 91	pre 91	NOV of 1/17/91	inactive	
Melot Oil Truck Accident	Hwy 18, 4.5 miles E of Hobbs	Nadine	Lea			truck accident lost 6000 gal of gasoline	pre 1989	soil excavation and well sampling in 98 showed ND	closed	7/27/1998
Mixon Domestic Well	T19S, R37E, S29	Lovington	Lea			Concern over dark domestic well water and greasy residue	unknown	well sampled for VOC, SVOC, and FE, Mn. Results BDL with exception of Fe	closed	11/9/2011
Monument Well Water	T12S, R38E, S18.2	Monument	Lea			monument water supply well contaminated with crude	pre 84	referred to OCD	referred	
Nadine Nitrate Water Wells		Nadine	Lea			Custom Slaughter and Meat Packing suspected of causing nitrate contamination	1987	sampling of domestic wells	inactive	
O7 Ranch produce water pits	Sanger + West Co. Rd intersection		Lea			complaint of produce water pits and OCD not taking action	pre 1971	referred to OCD	referred	9/1/2002
Texas Fueling Services	Hwy 128, mile marker 53	Jal	Lea	32.122707	-103.177834	truck accident, 4,200 gallon red-dye diesel spill on north side of hwy 128 at mile marker 53	11/27/2020	soil excavation	closed	8/9/2021
Wagner Equipment (formerly RUST Tractor)	1005 NW County Rd	Hobbs	Lea	32.710494	-103.176078	sewer overflow	unknown	ground water monitoring	closed	2/1/2006
Western Bar and Grill	10 miles E of Tatum on Hwy 380	Tatum	Lea	33.257159	-103.14843	AST with aviation fuel was blown over in the 50s spilling fuel.	1950s	sampling of new well in 1999 showed ND	closed	11/29/1999
Windmill Oil Company	4001 Mahan	Hobbs	Lea	32.727533	-103.16204	water windmill wells began pumping product off the water table in the 60s and group formed a company to sell the	unknown	Windmill company stopped pumping in the 80s and Oil	referred	
Circle K Truck Spill	unknown	Ruidoso Downs	Lincoln			20 gal of gasoline spilled	6/20/2000	adsorbed fuel	closed	8/4/2000
DOD Air Force F-16 Jet Crash	2 miles NE of Village of Lincoln	Lincoln	Lincoln			jet cash and 120 gal of Jet fuel was lost	12/8/1997	most volatilized and location was remote with dtw >100 ft	closed	2/20/1998
Domestic wells contamination with gasoline	127 Reese Dr.	Ruidoso	Lincoln	33.323924	-105.63678	analytical results of 2 domestic wells showed BTEX	pre 10/82	referred to PSTB	referred	
Gavilan Creek, suspected petroleum	by Gavilan Canyon Trailer Park	Ruidoso	Lincoln			report of spill into creek. No evidence of such	pre 7/12/96	inspection showed no evidence of spill	closed	8/15/1996
McCarty Construction	Walnut Dr and Gavilan Canyon	Ruidoso	Lincoln	33.324702	-105.629283	UST remediation	1988	UST remediation	referred	
Miele Well	Airport Rd	Ruidoso	Lincoln			concerns of domestic well quality affecting health	6/26/2000	sampling of well showed high TDS only	closed	6/29/2000
Prime Inc. truck accident	Hwy 380 mile 53	Carrizozo	Lincoln			truck accident caused small fuel, oil, and antifreeze spill	1/21/2001	soil excavation	closed	3/8/2001
Safe Haven RV Park	Hwy 70 West	Ruidoso	Lincoln	33.310581	-105.640152	sewage lift pump constantly failing	pre 1993	facility went out of business	closed	6/20/1994
Sierra Blanca Regional Airport	313 Cree Meadows Dr.	Ruidoso	Lincoln	33.348452	-105.665067	spillage of motor oil, filters, residual fluids	4/2/99	airport changed directors, no knowledge of spills or location	inactive	11/30/2006
Transwestern Pipeline Co.		Corona	Lincoln			old pipeline pumping stations showed petroleum contaminated soil	pre 1990	EPA took lead and soil was excavated	closed	6/12/1995
Village of Ruidoso WWTP spill	26675 U.S. Highway 70	Ruidoso Downs	Lincoln	33.359913	-105.552728	300 gal of sewage spill	3/4/1991	soil disinfection	closed	9/13/1991
Desert Fuels Tanker spill	101 Camino Entrada	Los Alamos	Los Alamos	35.876377	-106.249798	Spill of 50-100 gal of gasoline on concrete pad during fuel delivery	1/4/2018	application of absorbent, removal	closed	3/9/2018

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
El Cajete Pumice Mine	15 miles W of Los Alamos off Highway 4	Los Alamos	Los Alamos	35.815374	-106.568931	refueling area (underlined with a HDPE liner) of the mine had contaminated soil	4/29/1999	soil excavation	closed	5/27/1999
Ethylene Glycol spill	off Orange St.	Los Alamos	Los Alamos	35.891922	-106.290042	discovery of antifreeze in canyon	pre 3/93	unknown	closed	post 1993
Las Ventanas	29 Short Drive	Los Alamos	Los Alamos	35.880191	-106.305551	sewage backup in townhome showed sewer line was never connected to municipal line	6/21/2007	soil excavation and connect sewer line	closed	11/13/2007
Beacon Truck Stop	I-10 exit 68	Deming	Luna	32.272465	-107.755722	AST samples showed TPH at 59,300 ppm	pre 1/94	unknown	inactive	
Kinder Morgan Booster Station	5815 Baker	Deming	Luna	32.272465	-107.755722	petroleum contaminated soil discovered	5/16/2006	soil excavation	closed	9/22/2007
Meth lab	T26S, R9W, S1.1	Deming	Luna			meth waste discharged to septic	pre 7/89	samples were below detection limits	closed	7/1/1989
MSJ Trucking Inc., truck accident	I-10 mile 97	Deming	Luna			truck accident spilled diesel and sulfuric acid from batteries	8/26/2002	adsorbed fuel	closed	10/4/2002
NM National Guard	Early Identification Team Site	Columbus	Luna			temporary fueling area secondary containment area had a low volume leak. Unknown volume	unknown	soil excavation	closed	7/10/2007
NM National Guard Storage Yard	300 yards east of Transfer Station	Columbus	Luna	31.813464	-107.641664	release of 66 gallons of diesel from a stuck flow valve	5/31/2007	soil excavation	closed	7/10/2007
NMDOT Deming	2912 E. Pine	Deming	Luna	32.268645	-107.726122	chlorinated solvents flushed down septic system	unknown	septic system removed, SVE system installed, GW sampling	closed	5/10/2005
PNM Transformer oil spill	1214 E. Motel Dr.	Deming	Luna	32.26878	-107.747265	transformer oil leak when vehicle accidentally hit transformer	4/21/1999	soil excavation	closed	5/3/1999
PNM Transformer oil spill	6475 Columbus Hwy SE	Deming	Luna	32.272465	-107.755722	transformer oil leak	7/23/2000	7 gal of oil leaked with <1ppm PCB oil. Soil excavation	closed	10/10/2000
Porter Oil AST Bulk Plant	2701 East Pine ST.	Deming	Luna	32.268757	-107.725026	Spill reports from ASTs	1990	repair pumps	referred	
Savoy Truck stop	14150 Hwy. 418, 13 miles W of Las Uvas Valley Rd., Luna County, NM	Deming	Luna	32.238445	-107.994283	bulk plant investigation	unknown	inspected 420K gal. tank	closed	3/6/2006
El Paso Electric Co.	Cattleman Road	Deming	Luna	32.45806	-107.369722	Release of mineral oil from electrical transformer	9/30/2019	Soil excavation	closed	2/10/2020
El Paso Electric Co.	Cattleman Road	Deming	Luna	32.49102	-107.355826	45 gallon spill of transformer oil	6/6/2020	Soil excavation	closed	
Alpine Lumber	104 North 2nd Street	Gallup	McKinley	35.529822	-108.742849	BTEX leak from UST	unknown	assessment	transferred to VRP - AC Houston	12/2/2016
BNSF Gallup - HCL spill	West of Gallup, MP 161.3	Gallup	McKinley	35.512102	-108.800096	HCL spill from rollover of car NATX210000	43284	neutralization of soil, assessment of leaching potential	closed	12/14/2018
BNSF Gallup - NGL Energy	T15N, R18W, S16	Gallup	McKinley	35.524905	-108.755899	5 barrels of crude spilt at yard by a contractor	11/4/14	soil excavation	closed	1/5/2015
BNSF Thoreau	High Ridge Trucking Facility, mile marker 125.6	Thoreau	McKinley			spill of potassium hydroxide	8/16/1999	material removed	closed	9/6/1999
Church Rock Uranium Mill Tailing Spill	United Uranium Church Rock Location	Church Rock	McKinley	35.642757	-108.508493	Mine tailing dam burst releasing millions of gallons	7/16/79	excavation and extensive assessment		
City of Gallup Transformers	1898 Warehouse Lane	Gallup	McKinley	35.521636	-108.769067	PCB oils contaminated soil	pre 2000	soil excavation	closed	5/10/2001
Contractor Freighters, Inc	Thriftway store, 9 mi N of Gallup	Gallup	McKinley			70 gal of diesel spill	10/15/1998	soil excavation	closed	2/15/1999
Dial Oil	FR 456, 2 miles N of San Mateo	Thoreau	McKinley			Truck accident lost 1500 gal of diesel	4/19/2004	soil excavation	closed	8/1/2004
DOT Ramah Patrol Yard	DOT Ramah Patrol Yard	Ramah	McKinley	35.143947	-108.491909	gas spill reported	pre 1992	soil excavation	closed	8/1/1992
Elite Cleaners	208 U.S. Rt. 66, Gallup, NM	Gallup	McKinley	35.528699	-108.739865	Adjacent Brownfields investigation showed solvents in GW	unknown	site entered into the VRP	referred	10/29/2013
Former Commercial Drivers License facility	North CR 1	Gallup	McKinley	35.522459	-108.723478	truck washing at a warehouse 5 miles NW of Gallup had diesel spill	unknown	site sampling and soil excavation	closed	8/27/2004
Ft. Wingate Depot	Ft. Wingate	Gallup	McKinley	35.522459	-108.723478	munitions decommissioning discharge volumes of TNT to unlined lagoons	pre 1980	referred to HWB		
Gallup Truck Stop	Giant Travel Plaza, I-40 and exit 39	Jamestown	McKinley	35.4807	-108.4363	etching solution spilling from a truck	10/21/1997	material removed	closed	3/20/1998
Giant Refinery - Ciniza Refinery	17miles East of Gallup exit 39 I40	Gallup	McKinley	35.489543	-108.426666	Multiple fuel releases	1983	referred to OCD		
JR Theroux Mobile Home Park	Navajo Rt 12, mile 56/65	Navajo	McKinley	35.903824	-109.031633	truck accident spilled 80 gal of diesel	8/31/2000	soil removal	closed	2/23/2001
Just Getting By Inc. Truck Accident	I40 exit 36	Gallup	McKinley	35.522459	-108.723478	truck accident spilled 50 gal diesel	8/21/2000	soil excavation	closed	9/19/2000
Lobo Canyon	NE of Grants on NF	Grants	McKinley	35.150067	-107.848006	20 drums of herbicide dumped in 70's	1970s	FS to do non emergency CERCLA clean up	closed	6/18/1997
Love's Truckstop	I40 exit 16	Gallup	McKinley	35.522459	-108.723478	truck accident caused 200 gal of diesel spill	3/27/1999	soil excavation	closed	2/4/2005
Ojo Encino Heating Oil release	BIA School	Ojo Encino	McKinley			1000 gal heating oil released when truck hit tank	Nov-00	soil excavation	closed	9/26/2003
P&J Mobile Home Park	416 W. Coal Ave	Gallup	McKinley	35.523742	-108.753463	surfacing sewage from a lift station	9/12/1995	city of Gallup fixed pump	closed	10/18/1995
Prewitt Refinery	1/2 mi W of Prewitt PO	Prewitt	McKinley			refinery showed GW cont.	pre 83	referred to CERCLA	closed	
Steere Tank Lines	Escarbada Canyon	Gallup	McKinley	35.522459	-108.723478	truck accident spilled JP-4 fuel	4/6/1993	soil excavation and MW installation	closed	post 1993
Stever Trucking	I-40 at Mile Marker 48	Gallup	McKinley	35.522459	-108.723478	diesel spill of 300 gal	11/2/1998	soil excavation	closed	2/26/1999
Unocal 76/Burns Bo. Truck stop	West of Gallup	Gallup	McKinley			evaporative ponds at truck stop showed TPH in soil samples	pre 1992	soil excavation	closed	6/14/1994

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Cebolla Springs domestic well samples	Cebolla Springs Subdivision		Mora			domestic wells show some oil,	pre 91	unknown	inactive	
Former Levi's Texaco/66	Hwy 85	Wagon Mound	Mora	36.012021	-104.706015	LUST investigation showed DCE below stds and concerns of Pb from old batteries	Nov-94	P&T wanted to discharge to villages WWTP and solicited GWQB's input	inactive	5/24/1995
Ortiz Well	PO Box 11	Sapello	Mora	34.166233	-106.026069	concern over fire retardant discharge	Oct-00	sampled well and below laboratory detecting limits	closed	10/31/2000
Ross Oil Company, truck accident	St Rd 121, mi 7 and 8	Chacon	Mora	34.166233	-106.026069	truck accident spilled 225 gal of gasoline	9/13/1997	clean up spill on surface	closed	6/20/1997
El Paso Electric Co.	Amrad Substation, White Sands Missile Range	Oro Grande	Otero	32.51942	-106.137975	Release of mineral oil from electrical transformer	5/23/2018	Soil excavation	closed	2/7/2019
Alamo Disposal waste oil	W. Arnold + Lawndale	Alamogordo	Otero	32.914000	-105.965342	Poor practices resulted in vehicle fluid spills	unknown	soil excavation	closed	1/25/2011
Alamogordo Maintenance Yard	2600 N. Florida	Alamogordo	Otero	32.923706	-105.952261	discovery of contaminated soil below service pit #1	pre 12/99	soil excavation	closed	1/18/2000
Big A Auto Parts	400 N White Sands	Alamogordo	Otero	32.893901	-105.960111	septic tank leak with petroleum	pre 96	MW installation and soil removal	closed	1/16/1996
Black Hills Aviation	Alamogordo Airport	Alamogordo	Otero	32.88315	-105.967276	used oil spillage from barrels	unknown	soil excavation	closed	8/5/1991
Blankenship Sand & Gravel, La Luz	177 Griffin	La Luz	Otero	32.96981	-105.930262	various spills of motor oil, diesel fuel, & hydraulic fluid	4/7/2008	soil excavation	closed	5/8/2012
City of Alamogordo, Test well T-4660	T12S,R10E, S31, by Snake Tank	Alamogordo	Otero			complaint of test well causing salt water intrusion	1/12/2007	review and respond to technical report	closed	3/16/2007
CS McCrossan Construction	Highway 380, 20 miles w. of Carrizozo	Carrizozo	Otero			1000 gal of diesel spilt when AST vandalized	1/18/1999	soil excavation	closed	8/31/1999
Diamond Shamrock Piñon Pump Station	17 miles S-SE of Piñon	Piñon	Otero			75 gal of gasoline released from faulty pipeline connections	11/14/2000	soil excavation	closed	1/3/2001
DOT Alamogordo	RR and overpass of Hwy 70	Alamogordo	Otero	32.88315	-105.967276	oil and tar seeping from a pit on DOT property.	unknown	unknown	inactive	
EEM Scrap Metal	2611 S. Walker	Alamogordo	Otero	32.855244	-105.980272	report of illegal smelter causing air pollution on dioxin fall out	pre 2008	sampling of soil and domestic wells showed no contamination. Facility stopped smelting and implemented best management practices	closed	5/1/2008
Former Child Development Center, HAFB	Bldg. 790	Holloman AFB	Otero			heating oil (diesel or kerosene)	3/31/2010	soil excavation	closed	4/25/13
Groendyke Transport Truck Accident	Hwy 54 , 10 mile S of Alamogordo	Alamogordo	Otero			3200 gal of gas spill from truck accident	1/22/2000	ignition of spilled gas, soil excavation	closed	8/27/2001
High Energy Laser System Test Facility		White Sands Missile Range	Otero	32.631413	-106.332851	spill of 100 gal of diesel from pump error from ASTs	11/10/98	soil excavation	closed	12/18/1998
Holloman AFB contaminated soil	Hensel-Phelps Construction Yard	Alamogordo	Otero			discovery of petroleum contaminated soil	1/29/1993	soil excavation	closed	3/17/1993
Holloman AFB Jet Crash	NW of HAFB	Alamogordo	Otero	32.88315	-105.967276	F-117A jet crash caused soil contamination with jet fuel	unknown	soil excavation	closed	7/23/1993
Holloman AFB LNAPL	Holloman AFB	Holloman AFB	Otero	32.88315	-105.967276	report showing LNAPL	pre 81	referred to HWB	referred	5/1/1981
Holloman AFB, UST	541 New Mexico Ave.	Holloman AFB	Otero	32.8406	-106.0792	petroleum contaminated soil		soil excavation	closed	4/25/13
Jet Crash at WSMR	WSMR remote location	White Sands	Otero			Jet crash and spill of 6500 pounds JP-8	10/14/1998	soil excavation	closed	5/5/2000
Mesa Verde Enterprises/Coastal Transport	Mesa Verde Ranch Rd, La Luz/10955 Railroad Drive	La Luz	Otero	32.96981	-105.930262	spill of 850 gals diesel during fuel delivery overflow to AST at gravel quarry	9/25/05	RP hired VIVA Environmental same day as spill occurred. Response and cleanup was rapid after tank overflow.	closed	2/1/2006
Mesilla Valley Transport Truck Accident	Mesilla Valley Transport US70 and US54	Tularosa	Otero	33.073455	-106.014916	truck accident caused 100 gal of diesel spill	9/20/07	soil excavation	closed	11/19/2007
Otero Electric Co-OP	402 burro Ave	Cloudcroft	Otero	32.95883603	-105.7438449	gasoline discharge from historic UST	1940-1950's	Excavation of 186 tons of contaminated soil	closed	8/31/2015
Panama Ranch Garbage Dump, USFS	T22S, R19E, S8	Carlsbad	Otero			Old cave where pesticides had been dumped along with trash	pre 1997	USFS conducted a removal under CERCLA emergency funds	closed	6/20/1997
Presto Products Manufacturing	1301 La Velle Rd	Alamogordo	Otero	32.874026	-105.975311	release of petroleum from an oil water separator	pre 9/98	soil excavation	closed	10/30/1998
Rudolph Automotive	2600 N. White Sands Blvd.	Alamogordo	Otero	32.929059	-105.961593	hydraulic lift contaminated soil	pre 1994	unknown		
WSMR Russ Site	White Sands Missile Range	White Sands	Otero			300 gal of diesel spilt from vandalized fuel pod	5/1/1998	soil excavation and land farming	closed	10/5/1998
El Paso Electric Co.	White Sands Missile Range Substation	White Sands	Otero	32.51923	-106.138568	200 gallon spill of mineral oil	12/12/2019	Soil excavation	closed	2/10/2020
El Paso Electric Co.	Holloman Air Force Base	Holloman AFB	Otero	32.83291	-106.06761	5 gallon spill of transformer oil	4/30/2020	Soil excavation	closed	12/11/2020
Arch Hurley Conservation District Yard	101 E High St.	Tucumcari	Quay	35.176007	-103.726073	report of waste oil spill	pre 97	inspection showed no known contamination. MW associated with Worley Mills on-site is clean	closed	4/23/1997

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Curry Ranch, Valero Logistics Operations	13 W. of Tucumcari	Tucumcari	Quay	35.130926	103.940644	pipeline break	16-Oct-95	soil treatment and passive vapor well	closed	10/27/2003
Diamond Shamrock Block Valve 72	Hwy 392, 11 miles NE of San Jon	San Jon	Quay	35.215342	-103.164012	84 gal of diesel/gas spill	5/1/2001	soil excavation	closed	7/27/2001
FFE Transportation Services Truck Accident	Hwy 469 and 54	Logan	Quay	35.342026	-103.422879	truck accident lost 20 gal of diesel	12/16/2000	soil excavation	closed	1/30/2001
House Co-Op AST	Hwy 252	House	Quay	34.647933	-103.899801	report of spills and broken line at small AST	pre 97	inspection showed no contamination and domestic wells nearby were clean	closed	8/7/1997
Logan Ute Lake, NO3	NW part of town Hwy 540	Logan	Quay	35.360894	-103.485781	domestic well sampling showed NO3 above standards	8/16/1978	Water system improvements	closed	
Nara Vista Water Association Coop, NO3	T16N, R36E, S22.2	Nara Vista	Quay	35.605619	-103.101734	supply well impacted and recommended deeper well	pre 76	unknown	closed	
NMARNG Tucumcari Training Area MRS (NMC00-001R-02)	5 miles northwest of Tucumcari	Tucumcari	Quay	35.218248°	-103.780965°	metals associated with small arms ammunition (Pb, Sb, Cu, and Zn) at gun range used from 1951 to the 80's	Pre 80's	Risk assesment of soil to GW and ecological receptors.	closed	pending
Southern Pacific RR Spill	SP Tucumcari Depot	Tucumcari	Quay	35.171747	-103.745728	unknown amount of diesel spill at RR yard	3/14/1995	soil excavation and borings	closed	6/2/1995
Swift Transportation	I-40, MM310	Tucumcari	Quay	35.142183	-103.814182	50 gal of diesel spill from truck accident	12/20/2015	excavation & Confirmation Sampling	Closed	4/1/2016
Terry's Service Center	NW corner Frontage Rd and Hwy 469	San Jon	Quay	35.115371	-103.336084	petroleum contaminated soil discovered	12/1/1998	soil excavation	closed	8/1/1999
Versatile Construction Asphalt Plant	West Maple St.	Tucumcari	Quay	35.185971	-103.73472	35 gal of diesel spill	6/21/1999	soil excavation	closed	8/17/1999
Worley Mills	702 West Campbell Ave	Tucumcari	Quay	35.182106	-103.734559	Carbon Tetrachloride contamination in groundwater from grain elevator operation	unknown	monitoring	closed	8/31/2004
Velarde Fuel Spill (DC Carriers)	Hwy. 68, MM 16	Velarde	Rio Arriba	36.1892	-105.9789	Diesel, BTEX, and PAHs in soil	12/22/2015	soil excavation	closed	2/8/2019
Arriba Construction	2246 State Rd 17	Chama	Rio Arriba	36.889834	-106.583581	report of diesel spill entering wetland	7/13/2001	sampling of wetland showed low TPH levels and no threat	closed	7/13/2005
AT&T Lucent Technologies Equipment Compound	2000 N Riverside Dr	Española	Rio Arriba	36.028793	-106.064195	discovery of PCE in soil	pre 1996	soil excavation	closed	8/1/1996
Big Rock Shopping Center		Española	Rio Arriba			discovery of BTEX in soil	Feb-84	referred to PSTB		
Black Mesa Quarry	11 mi N of Lyden Hwy 582	Lyden	Rio Arriba			Quarry diesel spill	pre 97	none	closed	
Chama Sawmill	10th and Pine St	Chama	Rio Arriba	36.898096	-106.584022	AST diesel spill	98	soil removal and GW samples	closed	9/16/1999
Chamita Domestic wells		Chamita	Rio Arriba			high NO3 in domestic wells	Nov-95	continued monitoring	inactive	
Cumbres & Toltec Scenic RR	500 S. Terrace Ave.	Chama	Rio Arriba	36.90079700	-106.57825500	petroleum diesel, naphthalenes below NMED SSLs	2003	no further action < SSLs	closed	4/14/2016
El Llano Solvents		Española	Rio Arriba			discovery of low concentration PCE	pre 1/94	closed since no new data indicates above stds.	closed	
English Tank Grazing Allotment	Mesa Vallejos, Carson NF	Canjilon	Rio Arriba	36.481983	-106.430287	report of hauled livestock water containing petroleum	7/19/2011	interviews and water sample indicate no soil or groundwater concerns	closed	8/9/2011
Española Domestic Well logs		Española	Rio Arriba			well logs				
Española Transmix Co.	PO Box 38	Española	Rio Arriba	36.00366	-106.069046	fish kill in pond and discharge to Rio Grande	May-89	pond taken out of commission	closed	
Española Valley Nursing & Rehabilitation Center, Española	720 Hacienda Street	Española	Rio Arriba	36.005065	-106.060835	small diesel AST spill from mid 90s	mid 90s	soil excavation and MNA	closed	7/1/2009
Garcia Property	PO Box 280	Velarde	Rio Arriba	36.160919	-105.967131	septage hauler alledged dumping	pre 2000	referred to PPS for a discharge permit	referred	7/15/2000
Hacienda Home Center		Española	Rio Arriba	35.987888	-106.064872	500 gal of diesel spill	8/24/1994	soil excavation	closed	10/6/1994
Illegal Subdivision	T21N, R8Em S25.3	Española	Rio Arriba			domestic wells with slightly above stds for NO3	Aug-87	recommend city water	inactive	
John Professional Transmissions	406 Calle Chavez	Española	Rio Arriba	35.989034	-106.078492	complaint of spilled transmission oil from 5 barrels	2/31/2000	no evidence of discharge	closed	
John's Transmission Shop	Chavez St, behind Cook's Mercantile	Española	Rio Arriba	35.989034	-106.078492	complaint of motor oil dumping	May-95		closed	
KAFB F-18 Jet Crash	10 miles NE of Canjilon Ranger Station, 25 miles SE of Chama	Canjilon	Rio Arriba			900 gallons of JP-5 jet fuel from jet crash	5/19/1995	soil monitoring	closed	
Lower San Pedro Community	by Rio Grande and Santa Cruz river	Española	Rio Arriba			domestic wells with benzene	Jul-89	connect to City water and refer to PSTB	referred	
N. Riverside, Española	716 N. Riverside Drive	Española	Rio Arriba	36.028915	-106.064206	used oil tank spillage	7/19/2007	soil excavation	closed	7/3/2008
O'Reilly Truck Accident	MM 17 Hwy 68	Embudo	Rio Arriba	34.166233	-106.026069	truck accident lost 175 gallon diesel	1/4/2012	soil excavation	closed	12/7/2012
Parker Mine Storage yard	N of Fairview between Riverside Dr. and Hwy 285	Española	Rio Arriba	36.00366	-106.069046	AST spill	pre 97	soil removal and GW samples	closed	2/10/2003
Plateau Thriftway Gas Station #183	Hwy 68 and Riverside Dr.	Española	Rio Arriba			1800 gal of leaded gas from LUST	Jan-87	referred to PSTB	referred	

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Velarde Domestic wells, Emilio Martinez	Postmaster, PO Box	Velarde	Rio Arriba	36.160919	-105.967131	high BTEX, MTBE in domestic well	Aug-87	referred to PSTB		
J.D. Heiskell Maintenance Facility	117 East Commercial Drive	Portales	Roosevelt	34.188224	-103.33736	6,000 gals of mineral oil spilled by vandals from AST. The discharge flowed southeast from the maintenance shop onto North and South Abilene Avenues terminating approximately 0.23 mile from the Site.	1/25/2018	soil excavation	closed	5/15/2018
Nunn Peanut Co.	T1S, R35E, S26.413	Portales	Roosevelt			377 gallons of diesel spill	2/9/1994	soil	closed	
Portales Oxidation Ponds	Portales WWTP	Portales	Roosevelt	34.169413	-103.365248	study of oxidation ponds		referred to PPS	referred	9/23/1977
Used oil dumping	Rt 1 Box 201 F	Dora	Roosevelt	33.931017	-103.335798	dumping of 3 barrels of used oil	Aug-93	referred to HWB	referred	9/23/1993
Farmington Electric Utility System	2012 North Huntzinger Ave	Farmington	San Juan	36.748892	-108.177279	Release of non-PCB containing oil from downed pole transformer.	43545	Soil excavation	closed	5/17/2019
Action Auto (Hi Country Leasing)	4320 W. Main St.	Farmington	San Juan	36.731687	-108.232338	Report of intentional burying of waste and barrels of used oil/fuel	unknown	following NOV soil excavation occurred in 2 phases	closed	5/11/2010
Basin Disposal Inc.		Farmington	San Juan	36.741075	-108.170869	Alleged Disposal of oil services waste	9/10/1987	soil boring to 60' showed no contamination	closed	11/18/1987
Basin Tire & Auto	2700 E. Main St.	Farmington	San Juan	36.74165	-108.26327	Phase II discovered Soil Contamination	pre-2014	soil excavation, soil and groundwater sampling	closed	5/14/2014
Berean Mission	Star Route 4, Box 4500	Bloomfield	San Juan			Water Supply sampling suspected hydrocarbons	unknown	Analytical results showed below regulatory levels	closed	9/23/1984
BLM Aztec Landfill	1.9 miles south of Aztec	Aztec	San Juan	36.805715	-107.987801	BLM transferred land patent to City of Aztec for construction of bypass around town. Aztec acknowledged acceptance of environmental liability for old dump	unknown	assessment only	inactive	5/25/2017
Brady Trucking	4000 Lomas St	Farmington	San Juan	36.741108	-108.262541	Phase II soil Investigation	3/1/2013	soil investigation for used oil and OWS	closed	6/25/2013
Consolidated Construction	3995 Cliffside Dr	Farmington	San Juan	36.755883	-108.157512	spill, stockpiled soil	Sep-00	soil excavation	closed	6/22/2004
Consolidated Construction	3995 Cliffside Dr.	Farmington	San Juan	36.755883	-108.157512	petroleum hydrocarbon contaminated soil	pre 2004	soil excavation	closed	5/14/2004
Corky's Tractor	8300 East Main Street	Farmington	San Juan	36.79480800	-108.0950140	petroleum hydrocarbon contaminated soil	unknown	Soil sampling, then transfer to the VRP	referred	1/5/2022
D&D Oil	road to Aztec from Bloomfield	Bloomfield	San Juan			HWB letter about soil results	pre 98	referred to HWB	referred	
Dial Oil	Hwy 94 2.5 miles east of Navajo	Navajo	San Juan	36.72723	-107.981551	truck accident caused fuel release	10/1/1992	soil excavation	closed	post 1992
Dirt Bandit	101 E. Piñon	Farmington	San Juan	36.723063	-108.205548	water and asphalt emulsion spill when transfer pump failed	8/26/2009	Soil excavation and pump repair	closed	9/21/2009
Domestic well results		Cedar Hill	San Juan			results from domestic well	Jun-84	nothing above stds	closed	
Farmington CR5290 Sewage Seep	66 CR5290	Farmington	San Juan	36.710125	-108.053756	seepage of liquid waste into arroyo	Sep-13	sample collection and referral to LWP	referred	10/18/2013
Farmington Fire Pit	710 S. Tucker Ave.	Farmington	San Juan	36.73549	-108.17732	discovery of TPH and oily soil when a gas line was installed	unknown	soil excavation at private business and along Animas River green belt	closed	2/10/2010
Farmington solvents in domestic wells	Melba Lane and Hydro Plant Rd	Farmington	San Juan	36.724421	-108.194895	domestic wells showed some PCE ~15 ppb	pre 1990	homes connected to city water and no source identified	closed	6/18/1997
Fieldsted explosives	T30N, R16W, S35.3	Waterflow	San Juan			5000 gal of diesel and NH4NO3 was spilled	pre 1992	soil excavation on-site treatment	closed	post 1992
Flora Vista MWDA well study		Flora Vista	San Juan			supply well showed oil impact, 5 MWs installed and clean	1986		closed	
Four Way Co.	1558 Hwy 550	Aztec	San Juan	36.826717	-108.013095	dozer release of 210 gal diesel	3/25/1993	soil excavation	closed	4/23/1993
Four-Four Inc. truck accident	St Rd 539 1/2 mile south of Navajo Dam	San Juan river	San Juan	34.166233	-106.026069	truck accident spilled 600 diesel 200 gal oil	1998	soil excavation	closed	6/20/1998
Foutz Laundry	Calle Barrio Nuevo and Camino del Pueblo	Kirtland	San Juan	36.743679	-108.353392	laundry unlined wash water pond	pre 1983	DP required	referred	
GE Facility Sump discharges	3009 E. Main St	Farmington	San Juan	36.742743	-108.167904	discharges into drywell/sump	pre 1996	soil excavation	closed	6/19/1996
Grieder Property - Salt Release	6673 Hwy 64	Bloomfield	San Juan	36.72723	-107.981551	Salt accumulation in farmer's field alleged from adjacent property runoff	unknown	site inspection and soil sampling did not indicate salt accumulation in adjacent business. Recommended BMP for business	closed	7/24/2014
High Desert Auto	1700 E. San Juan Blvd.	Farmington	San Juan	36.733913	-108.186534	hydraulic oil release from auto lifts	pre 2000	soil excavation, LNAPL recovery	closed	1/10/2003
Holly Energy Bulk Fuel Terminal	170 CR 4980	Bloomfield	San Juan	36.72723	-107.981551	bulk terminal inspection	none	inspection of facility revealed no discharges	closed	7/12/2007
Hubbard Acres Tank Farm	Hubbard Acres	Farmington	San Juan			soil contamination from former bulk terminal	pre 1993	soil excavation and on-site treatment	closed	11/12/1993
Hubbard property	W of Aztec Ruins	Aztec	San Juan			clean up batteries, drums, and soil	pre 8/00	soil excavation	closed	8/25/2000
Industrial Repair Service	1113 Camina Entrada	Farmington	San Juan	36.719164	-108.185628	evaporation pit from wash bay floor drain	pre 2000	soil excavation	closed	12/20/2000
JP-4 Steere Tank Lines, truck accident	north of Blanco, mile marker 84, Highway 64	Blanco	San Juan	36.726589	-107.843084	tanker truck spill 4900 gal of jet fuel	4/6/1993	soil excavation	closed	

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Lower Valley Lagoon Decommissioning	CR6100 and CR6263	Kirtland	San Juan	36.743679	-108.353392	During a wastewater project to decommission DP-1116, soil borings identified petroleum hydrocarbon contamination	unknown	Identified that the soil contamination was associated with the former Caribou refining under OCD jurisdiction	referred	6/23/2014
Milagro Gas Plant Septic Tank Leachfield	T29N, R11W, S11	Bloomfield	San Juan			non domestic waste sent to leachfield	pre 1996	soil excavation and OCD jurisdiction	referred	
Nielson's Gravel Quarry	north of Farmington	Farmington	San Juan			petroleum contaminated soil	pre 86	soil excavation	closed	
Phoenix Fuel Bulk Plant	2405 E. Main St.	Farmington	San Juan	36.739541	-108.175387	Phase 2 showed soil contamination associated with adjacent fuel bulk plant	unknown	PSTB jurisdiction and oversight	referred	11/3/2007
Plateau Refinery	Sullivan and Wooten Rd	Bloomfield	San Juan	36.698596°	-107.972990°	Sampling of seep and refinery inspection	unknown	referred to OCD	referred	6/6/1995
PNM's San Juan Generating Station	CR 6800	Kirtland	San Juan	36.743679	-108.353392	bulk terminal inspection	none	inspection of facility revealed no discharges	closed	7/11/2007
Private well BTEX cont. Navajo Nation			San Juan			high BTEX in domestic well	pre 4/85	refer to Navajo Nation	referred	4/2/1985
Rag Top's Sportswear	500 Electric Ave	Farmington	San Juan	36.737877	-108.17527	report of discharges of solvent on site	pre 2000	inspection, soil vapor and soil sampling showed no contamination	closed	8/21/2002
RO Company	2517 E San Juan Blvd.	Farmington	San Juan	36.736658	-108.179719	old auto paint and body shop showed historic contaminated soil	pre 1999	soil excavation, and MNA for GW	closed	11/15/2000
Rust Tractor Farmington	1000 Troy King Rd	Farmington	San Juan	36.740388	-108.265557	Evaporative lagoon closure report	pre 1992	site associated with a LUST PSTB site. Soil excavation	closed	
San Juan County Oil and Gas	various	various	San Juan			analytical results from sumps		referred to OCD	closed	6/7/1995
San Juan Medical Foundation	622 W. Maple	Farmington	San Juan	36.724379	-108.211919	discovery of TPH contaminated soil	34394	soil excavation	closed	3/31/1994
San Juan Spring Co.	1516 W. Main St.	Farmington	San Juan	36.7282	-108.201	petroleum hydrocarbon contaminated soil	pre 2002	soil excavation	closed	3/15/2002
Sears Facility #2597	4601 E. Main St.	Farmington	San Juan	36.76441	-108.153358	hydraulic oil release	pre 96	soil investigation was clean away from bldg.	closed	3/30/1998
Serrano's Septic	Serrano's Septic SVC 13 Rd 4904	Bloomfield	San Juan	36.72723	-107.981551	report of dumping solid waste and truck wash waste in wetlands	unknown	site inspection and soil and groundwater sampling showed no GWQB corrective action required. Referred to HWB	closed	12/15/2009
Sewage Seepage	66 CR 5290	Farmington	San Juan	36.76642	-108.190183	Field Office report of sewage seepage into adjacent arroyo	7/1/2013	Collection of samples for fecal coliforms, VOC, SVOC, major ions, nitrogen species. Results indicate sewage.	referred to EHD	10/29/2013
Sierra West Truck Accident	Hwy 64 mile 72.8	Blanco	San Juan			truck accident lost 7200 gal of diesel that flowed into irrigation ditch	4/28/2002	soil excavation, LNAPL removal, and MNA	closed	7/4/2004
Steer Tank Lines Truck Accident	3205 Bloomfield Hwy	Farmington	San Juan	36.719204	-108.167359	loss of 1000 gal JP-4 fuel	12/1/1992	soil excavation	closed	6/15/1992
Steere Tank Lines	Hwy 64 between Farmington and Bloomfield	Farmington	San Juan			1500 gal asphalt emulsion spilt	6/9/1993	removal	closed	6/28/1993
Sullivan AST	301 Ash	Aztec	San Juan	36.825033	-107.99715	limited Phase 2 showed some soil contamination	unknown	soil excavation	closed	6/24/1996
Target Store	E. Main St and English Rd	Farmington	San Juan	36.766903	-108.148599	oil water separator discovered during property development	12/1/1994	removal and soil excavation	closed	12/16/1994
Teffeller	5420 US Hwy 64	Farmington	San Juan	36.715606	-108.150454	PSTB MW showed PCE concentrations ~1000 ppb	unknown	trespassing plume. Referred to OCD	referred	8/7/2007
Thriftway Trucking	Broadway and 1st St.	Bloomfield	San Juan	36.711341	-107.979122	truck accident spill of 150 gallons of gasoline	9/28/1993	soil excavation at SW corner of intersection	closed	10/6/1993
Transmission Headquarters	445 S. Browning Parkway	Farmington	San Juan	36.726846	-108.160573	oil sump with TPH	pre 96	soil excavation	closed	
Unknown Diesel Release	Hwy 550 and CR 2621	Aztec	San Juan	36.76642	-108.190183	Report of diesel fuel in an irrigation ditch	unknown	HWB emergency funds provided assessment and soil excavation of unknown source of diesel release	closed	3/18/2010
W & C Contracting Property	5000 E. Main St.	Farmington	San Juan	36.768507	-108.145971	petroleum hydrocarbon contaminated soil	pre-1994	soil excavation	closed	unknown
Watson Subdivision	Carlton Avenue	Farmington	San Juan	36.764022	-108.153856	TPH contaminated soil <100 mg/kg	pre 92	none	closed	9/10/1992
Webb Automotive Group	3911 E. Main St.	Farmington	San Juan	36.76642	-108.190183	wash bay and sludge oil improper disposal	pre 2002	soil excavation	closed	7/8/2002
Whiteway Laundry	E. Murray and Camina Entrada	Farmington	San Juan	35.594352	-105.219833	report of dry cleaning waste disposal	pre 2003	inspection did not reveal obvious releases	inactive	
Halliburton	4109 East Main Street	Farmington	San Juan	36.758034	-108.153397	Phase 2 showed soil contamination associated with an abandoned sump in the welding shop building	unknown	building demolition, soil excavation and GW sampling	closed	6/16/2020
San Juan Springs Company	409 East Broadway	Farmington	San Juan	36.727247°	-108.200691°	Soil and groundwater impacts from chrome plating facility. Abatement site began following 2008 Phase II investigation	unknown	Excavation, In-Situ Lactaid Injections	closed	12/17/2020

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Halliburton Farmington	4109 East Main Street	Farmington	San Juan	36.75803400	-108.15339700	Release from old OWS - Naphthalene and metals in soil and groundwater	3/2/2021	Soil excavation, application of Klozur CR®	closed	5/25/2021
San Juan Springs Company	409 East Broadway	Farmington	San Juan	36.72818900	-108.20140000	chromium, metals, petroleum hydrocarbon discharge	unknown	Remediation	closed	12/17/2021
APEX Gasoline	Alamo and Grand Ave	Las Vegas	San Miguel			100 gal diesel fuel from accident	4/3/1992	during fire suppression runoff made it to the Gallinas River. Containment	closed	post 1992
Artic Express Truck Accident	I-25 and Hwy 84	Romeroville	San Miguel	35.520489	-105.250019	truck accident spilled various VOCs	12/1/1999	soil removal and GW monitoring	closed	11/24/2003
BCSO Helicopter Crash	East of Chapelle, NM	Chapelle	San Miguel	35.38004	-105.23736	Helicopter crash releasing ~40 gal of aviation fuel	7/16/2022	Soil removal	closed	12/15/2022
Bernucci Property	Ilfeld-Rowe Fire and Rescue	Rowe	San Miguel			AST showing soil contamination	pre 99	soil removal	closed	8/27/1999
Carlos and Pepe Valles Garage	15 La Jara Lane	Pecos	San Miguel	35.577749	-105.679814	complaint of antifreeze and used oil discharges	pre 8/10/05	HWB referral and site practices were improved along with minor soil excavation	referred	9/15/2005
Franken Oil	503 12th St	Las Vegas	San Miguel	35.591633	-105.221494	report showing contaminated soil from LUST	Pre 92	refer to PSTB	referred	
Heating Oil LUST, Don Wales	1213 6th St	Las Vegas	San Miguel	35.602231	-105.219929	old heating oil LUST	pre 96	removed tank and soil	closed	8/4/1997
Mills Plaza	200-250 Mills Ave.	Las Vegas	San Miguel	35.599953	-105.233099	former dry cleaner releases	unknown	excavation, monitoring, referred to VRP	closed VRP	7/15/2012
New Mexico Adhesives	ATSF railyard	Las Vegas	San Miguel			a glue vat hardened and runoff from vat was drunk by cows and they died	88	soil removal	closed	
Oliver and Dolores Maddux	108 Pecos St	Las Vegas	San Miguel	35.587981	-105.212978	allege sewer hook up to 60 ft well	pre 96	following search warrant PPS addressed discharge	closed	
Pino Gas Station	Grand Ave and Columbia	Las Vegas	San Miguel	35.59978	-105.212941	discharges from LUST	pre 95	refer to PSTB	referred	
PNM Las Vegas Transformer Station		Las Vegas	San Miguel			PRC deposition from Lavery of PNM about environmental assessment if decommissioned	unknown	PRC decided to keep station as an emergency station. Hale from PNM stated there was no known discharges	closed	11/26/2007
Sealy Mattress truck accident	I-25 mile 321, south of Tecolote	Tecolote	San Miguel			100 gal diesel fuel from accident	May-99	soil removal	closed	7/6/1999
South Conchas Lodge		Conchas Dam	San Miguel			250 gal of gasoline leaked into Conchas Lake	8/12/1991	preventative measures taken for future mishaps	closed	post 1991
Advanced Manufacturing	850 S. Hill Rd	Bernalillo	Sandoval	35.300634	-106.540839	MW showed high DCE and Toluene	1992	unknown	inactive	
Archie's Auto (former)	6331 Highway 550	Cuba	Sandoval	36.01215	-106.968423	Used Oil spill around 500 gallon AST	unknown	soil excavation and AST removal	closed	4/18/2022
Arroyo del Tuerto	N 35 23.159; W 106 18.138	BLM land	Sandoval	35.3858	-106.3022	report of dumped sludge	pre 2004	discharge was old molasses to attract wildlife for poaching. BLM removed the molasses.	closed	2/15/2004
Arroyo Largo Mercury	T14N, R6E, S25.343		Sandoval			Concerns over mercury in soils in arroyo	4-1-992	soil sampling showed ND	closed	5/1/1992
BNSF Bernalillo Oil Spill	BNSF ROW at S. Oak St.	Bernalillo	Sandoval	35.301708	-106.547817	250 gal of hydraulic oil spilled	2/14/1997	soil excavation	closed	3/20/1997
Budaghers Outlet Mall	I-25 and Budaghers exit	Algodones	Sandoval	35.455369	-106.347036	AST had past releases	5/4/1993	soil excavation	closed	7/1/1993
Chevron (former) Bulk Plant #5735323	318 Railroad Track Rd	Bernalillo	Sandoval	35.30457	-106.546732	Spill, AST	10/30/1994	CAR approval	closed	7/22/1998
Corrales Domestic Well Results	Corrales	Corrales	Sandoval	35.239335	-106.622588	Domestic well sampling throughout community	6/27/1995	Report to community resulted in partial sewer line installation		
Evanston Home	2100 Gazelle Rd	Rio Rancho	Sandoval	35.269519	-106.695733	resident was concerned city water was impacted home water quality	2003	water samples and inspection revealed problem was due to construction	closed	6/25/2003
Former Duke City Lumber	1/4 mile from CR 11, 1 mile SE of Cuba	Cuba	Sandoval			diesel contaminated soil	Aug-99	soil removal	closed	9/10/1999
Gary Williams Energy Truck Accident	Hwy 44 mile 55		Sandoval			truck accident	Dec-89	soil excavation	closed	2/1/1991
Jemez Pueblo Water System	Jemez Pueblo	Jemez	Sandoval	35.606401	-106.737633	NMED invited to assist in water system contaminants	Jul-92	sample collection and consultation	closed	Jul-92
Jemez Valley HS	Canyon by Jemez pueblo	Jemez	Sandoval	35.657789	-106.7372	transformer oil spill	1994	soil excavation	closed	
KL Stevens Co.	300 B Frontage Rd	Rio Rancho	Sandoval	35.286948	-106.716105	report petroleum and metal polishing waste discharges	pre 11/06	joint inspection with HWB showed no evidence of discharge. HWB followed up on haz waste disposal	closed	12/1/2006
L-Bar Ranch	40 miles NW of Rio Rancho		Sandoval			ENTS 7774 showed spilt diesel in low volumes at a pump jack domestic well and leaking barrels of used oil	unknown	soil excavation and P2 measures on pump jack; soil excavation around leaking barrels	closed	6/10/2011

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used .

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
NM Utilities	Highway 528 and Sandoval County line	Rio Rancho	Sandoval	35.217394°	-106.662745°	5000 gal sewage spill	5/16/1994	sewage recovery and disinfection	closed	7/15/1994
Placitas Landfill	41 Dusty Trails Dr.	Placitas	Sandoval	35.311765	-106.498968	neighborhood concern of leachfields over former landfill	pre 1989	soil sampling and liquid waste and well data review showed no impact	inactive	5/7/2007
Plains Electric-Algodones Generating Station.	1500 NM Highway 313	Algodones	Sandoval	35.384706	-106.464711	Spill, fuel oil, pipe	7/9/1996	dig and haul, land applied	closed	6/18/1996
PNM Transformer oil spill	385 W Hwy 44	Bernalillo	Sandoval	35.320337	-106.551168	transformer oil leak	1/2/1997	soil excavation	closed	6/19/1997
PNM Transformer oil spill	Calle Barrio Nuevo and Camino del Pueblo	Bernalillo	Sandoval	35.310237	-106.55292	40 gal of transformer oil spilled	4/18/2000	soil excavation	closed	8/8/2000
PNM Transformer oil spill	1977 Lee Loop	Rio Rancho	Sandoval	35.284772	-106.71146	transformer oil leak	5/16/2011	soil excavation	closed	6/14/2011
Richard Martinez property	35 Guadalupe St	Bernalillo	Sandoval	35.310237	-106.55292	trash, sewage, use oil spill on domestic property	pre 2/2/05	removal via SWB oversight	closed	9/8/2006
Rio Rancho sewer line break	500 ft south of Co. Line St Rd 528	Rio Rancho	Sandoval	35.286948	-106.716105	sewer line manhole overflow, ~5000 gallons	5/17/1994	removal	closed	7/15/1994
Rio Rancho Sewer line Installation Testing	Main Feed Sewer Line manhole #5 and #6	Rio Rancho	Sandoval	35.286948	-106.716105	alleged sewer line test was rigged	Jun-93	line was video taped and no evidence of leakage	closed	8/1/1994
Rio Rancho WWTP sewer line break	Montoya Arroyo and Hwy 528	Rio Rancho	Sandoval	35.286948	-106.716105	due to large storm sewer line broke.	8/5/2006	soil excavation and sampling	closed	9/30/2006
Rio West	Near Alamo Ranch	Rio Rancho	Sandoval	35.285782	-106.914581	Artesian Brine well leaked, releasing approximately 3.6M gallons (11.05 acre feet) of brine water	11/1/2016	repaired wellhead, upgraded containment, soil investigations	closed	3/22/2022
Roberts Oil Truck spill - Regina	NM 96, MP 6.3	Regina	Sandoval	36.194414	-106.942162	Tanker truck accident caused soil contamination in arroyo	11/1/00	soil excavation and assessment	inactive	6/10/2010
Rocor Trucking	I-25 and mile 247	Algodones	Sandoval	35.38843	-106.47972	truck accident released 50 gal of diesel	12/17/1996	soil excavation	closed	3/24/1997
Rosario Sludge Compost Plant	Santa Domingo Pueblo	Santo Domingo	Sandoval			proposed sludge composting plant		Comments on proposed plant	closed	7/1/1993
Sunco Sign Lighting Co. Truck Accident	100 Frontage Rd	Rio Rancho	Sandoval	35.257784	-106.640747	truck accident lost 100 gal of gasoline	1/22/1998	soil excavation	closed	3/30/1998
Willow Creek Bosque, Rio Rancho Bosque	Rio Rancho Open Space	Rio Rancho	Sandoval	35.286948	-106.716105	shallow MWs showed high TDS	unknown	sampling of MWs and no identification of RP	closed	7/30/2006
Affordable Housing Associates	158 Calle Lazo Errante	Santa Fe	Santa Fe	35.670974	-106.001899	hydrocarbon soils discovered	pre 2001	soil excavation	closed	8/9/2001
Army reserve Center	Santa Fe	Santa Fe	Santa Fe	35.670974	-106.001899	20 gal diesel spill	9/21/1995	soil excavation	closed	9/21/1995
Associated Asphalt & Materials	3810 Oliver Rd	Santa Fe	Santa Fe	35.670974	-106.001899	300 gal of used oil spill	4/1/1999	soil excavation	closed	3/26/2003
Bennies Gulf Station	525 Riverside Dr.	Española	Santa Fe	35.98828	-106.064106	referral from PSTB about old leaky ASTs		NOD sent 7-7-95	inactive	
Berridge Distributing Co	1255 Cerrillos Rd	Santa Fe	Santa Fe	35.673615	-105.960259	former bulk plant	10/27/1995	soil excavation	closed	12/6/1995
Buckman Well #8 Transformer spill		Santa Fe	Santa Fe			transformer 100 gal spill	1999	soil excavation	closed	3/10/2000
CAMPR Partners Ltd	1061 Pen Rd	Santa Fe	Santa Fe	35.676346	-105.954737	hydrocarbon soils discovered	pre 1992	soil excavation	closed	3/20/1992
CAMPR Partners Ltd	1096 St. Francis Dr.	Santa Fe	Santa Fe	35.716328	-105.936272	hydrocarbon soils discovered	pre 1992	soil excavation	closed	3/20/1992
Canoncito Area	Canoncito Area	Santa Fe	Santa Fe	35.663722	-105.992498	low levels of Atrazine found in water samples	7/6/1987	resampled showed ND	closed	12/1/1987
Capital Scrap Metals	1162 Cooks Ln	Santa Fe	Santa Fe	35.647034	-105.956449	contaminated soil from car crushing operations	pre 1999	soil excavation	closed	11/9/1999
Capshaw Jr. High Water Well	St. Francis and East Zia Rd	Santa Fe	Santa Fe	35.670974	-106.001899	Water Investigation at Jr. High School	6/1/1989	Corrected school's plumbing and disinfected water line	closed	7/1/1989
Catellus Development Corp.	SF well (Baca Street)	Santa Fe	Santa Fe	35.662256	-105.991448	6 drums of used oil dumped near CAT-1 well	12/16/1996	removal and soil excavation	closed	5/14/1997
Copola Concrete Supply	2820 Industrial Rd	Santa Fe	Santa Fe	35.670974	-106.001899	AST spill released diesel	pre 8/99	soil excavation	closed	10/25/1999
DOT Santa Fe	St. Michaels and Old Pecos Trail	Santa Fe	Santa Fe	35.688537	-105.97862	weathered hydrocarbons found at site from past DOT activities	7/13/1993	soil excavation	closed	6/15/1994
Edwin Hyde	1708 Paseo de la Conquistadora	Santa Fe	Santa Fe			used oil spill	7/26/2000	soil excavation	closed	12/27/2002
El Llano Landfill	2 mi E of Rio Grande and Española	Española	Santa Fe	35.992923	-106.035463	report of GW concerns from landfill	Jul-89	referred to SWB since closed after 5-89	closed	
Eldorado Domestic Well	1 Azul Loop	Santa Fe	Santa Fe	34.166233	-106.026069	Benzene detected in domestic well	4/1/2010	resampling showed benzene below standards. ND in all neighbor domestic wells	closed	5/1/2010
Ellis Well	Near Lamy Junction	Lamy	Santa Fe	35.485056	-105.884353	suspected domestic well contamination	1986	results showed no contamination	closed	6/8/1986
Exxon Station 6-7231	2045 Cerrillos Rd	Santa Fe	Santa Fe	35.662774	-105.977086	petroleum contamination	unknown	Settlement Agreement directed remediation	closed	1/3/1989
former Eberline - Thermo Fisher	5981 Airport Rd	Santa Fe	Santa Fe	35.637054	-106.035498	in the process to develop a decommissioning plan to terminate radioactive materials license, soil samples were collected	unknown	soil results showed no threat to GW	referred to HWB	7/7/2009
Garcia Honda	607 Cerrillos	Santa Fe	Santa Fe	35.6823	-105.945349	used oil LUST site	12/11/1989	soil excavation	closed	7/26/1990
Geizer Domestic Well	Rt 5 Box 3600	Santa Fe	Santa Fe	35.670974	-106.001899	suspected domestic well contamination	Jan-83	Analytical results showed below regulatory levels	closed	5/1/1983
General Parts Inc.	Rt 6, 89A Agua Fria Rd	Santa Fe	Santa Fe	35.670974	-106.001899	drums of petroleum hydrocarbons	Dec-93	drum removal by HWB	closed	6/16/1996
Jiffy Lube	1975 Cerrillos	Santa Fe	Santa Fe	35.663583	-105.975493	500 gal tank overflowed with windshield wash containing isopropyl alcohol	4/26/2005	City removed 35 gal	closed	6/27/2005

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Santa Fe County Arroyo Seco Yard	1 The Law Road	Arroyo Seco	Santa Fe	35.963871	-106.033416	Discharge from an AST after theft	8/22/2021	soil excavation	closed	9/30/2021
La Bajada Mine	Santa Fe River Canyon, La Bajada Hill	La Bajada	Santa Fe	35.54944167	-106.20791944	sulfate, TDS, Ur - MW3 exceeds standards TDS, Sulfate and Ur in MW-3 continue to exceed WQCC HHS standards. TDS and sulfate concentrations have decreased since prior sampling, Ur concentrations have increased	Pre 1950s	Mine Reclamation performed ~1997-1999	Referred to MECS. File transferred 4/8/16	4/8/2016
La Cienega Nitrate Study		La Cienega	Santa Fe	35.624764	-106.026378	Concerns about CSF WWTP	9/1/1999	Analytical results showed below regulatory levels	closed	9/1/2000
La Puerta Origin Ltd	4523 State Hwy. 14	Santa Fe	Santa Fe	35.679508	-105.955765	used oil spill	pre 11/22/04	soil excavation	closed	12/10/2004
Martha Frank Water Sample	704 Onate Place	Santa Fe	Santa Fe	35.679416	-105.955569	Complaint of odors in water system	11/1/1989	samples were below detection limits	closed	12/21/1989
Masters Cleaners	238 Sandoval St.	Santa Fe	Santa Fe	35.68626	-105.943017	Phase 2 showed PCE of 12 mg/kg at 1-5 ft.	unknown	3 soil borings to 50 and 100 ft showed no GW and ND for VOCs, soil vapor at 25' showed 19 ug/air.	closed	1/18/2006
Mesa Gravel Inc	Arroyo Seco	Arroyo Seco	Santa Fe			diesel and oil spilled during gravel mining	pre 93	samples	closed	7/1/1994
NMDOT Cuyamungue	Mystic Lande, east of US84, 1/2 mile north of mile marker 177	Cuyamungue	Santa Fe	35.866691	-106.008022	Surface spill from diesel AST entered MW-2	6/1/1999	spare and vent, LNAPL recovery, soil excavation	closed	5/31/2006
One Hour Martinizing, Santa Fe, WIRTCO	1091 St. Francis Dr.	Santa Fe	Santa Fe	35.674314	-105.953562	Release of PCE from Dry Cleaners	unknown	assessment	transferred to VRP	3/9/2018
Osage Well		Santa Fe	Santa Fe			Soil sampling showed <100 ppm TPH	6/1/1995	no corrective action required	closed	7/5/1995
Paradise Trucking	I-25 and Exit 294	Santa Fe	Santa Fe	35.670974	-106.001899	truck accident lost 100 gal of diesel	8/20/1999	soil excavation	closed	1/13/2000
Phase One Realty	Tano Rd and N. Ridgetop Rd	Santa Fe	Santa Fe			kerosene spill	4/9/2001	soil excavation	closed	2/28/2002
PKG Building	218 Montezuma	Santa Fe	Santa Fe	35.684341	-105.94241	indoor air and soil vapor showed low levels of CCl2F2	1984		closed	6/15/1984
PNM Transformer oil spill	United Parcel Service on Camino Ortiz	Santa Fe	Santa Fe			transformer oil spill	4/11/1994	soil excavation	closed	4/19/1994
Pojoaque Pueblo Well Report Quick Car Wash #8	Pojoaque Pueblo 995 Rodeo Dr.	Santa Fe	Santa Fe	35.670974	-106.001899	Domestic well sampling RE: Uranium		soil excavation	closed	1/1/1998
		Santa Fe	Santa Fe	35.638859	-105.934851	dumping of petroleum contaminated soil	12/29/1999		closed	2/2/2000
Rabbit Rd Soil	253 Rabbit Rd	Santa Fe	Santa Fe	35.62786	-105.95551	Concern of creosote runoff from RR ties	5/27/2009	Sample results showed concentrations below guidance levels	closed	7/14/2009
Rancho Encantado	State Rd 592	Tesuque	Santa Fe	35.753513	-105.915371	heating oil release from LUST	pre 1995	soil excavation and subsurface soil samples allowed some TPH to remain in place	closed	4/20/1995
Robertson Well	T15N, R8E, S25.234	Santa Fe	Santa Fe			Domestic Well sampling	5/1/1987	Sample results showed low results	closed	5/1/1987
Rocky Mt. Motors	4480 Cerrillos Rd	Santa Fe	Santa Fe			hydraulic lift contaminated soil	pre 1998	soil excavation	closed	5/22/1998
Ruben Well	Camino Sin Nombre and Camino San Acacio, 623 Camino Rancheros	Santa Fe	Santa Fe			PCE discovered in domestic well	pre 1997	CERCLA conducting an investigation to discover sources sampling of domestic wells in area. No source or RP identified. Concentrations have decreased over time.	referred to SOS	
Santa Fe Airport Jet fuel release	1000 ft N-new of runway 33	SF County Airport	Santa Fe			350 gal of jet fuel from accident	2/1/2000	soil excavation	closed	
Santa Fe Beaver Reintroduction by Forest Guardians	312 Montezuma	Santa Fe	Santa Fe	35.684628	-105.94441	beaver dam created by beaver reintroduction project creating diversion of potentially contaminated water making a reported threat to residents	unknown	investigation showed no ground water concerns	referred to SWQB	2/1/2014
Santa Fe Chevrolet	4450 Cerrillos Rd	Santa Fe	Santa Fe	35.629593	-106.023096	motor oil release from an oil water separator	pre 1998	soil borings showed low levels of contamination	closed	6/17/1998
Santa Fe County Groundwater Study		Santa Fe	Santa Fe	35.641931	-105.960488	Groundwater analyses of well across county	9/1/1986	Report to county commission	closed	9/1/1986
Santa Fe County Maintenance Yard	2600 Galisteo	Santa Fe	Santa Fe	35.670974	-106.001899	diesel fuel LUST	Apr-07	soil borings	closed	3/4/2002
Santa Fe KOA campground	Rt 3 Box 95-A	Santa Fe	Santa Fe	35.670974	-106.001899	nitrate up to 11 ppm in well	pre 1996	refer to DWB	closed	
Santa Fe Racing Landfill	Santa Fe Racetrack	Santa Fe	Santa Fe			sampling of domestic wells to evaluate impact of manure landfill	Oct-00	sample results and refer to SWB		
Santa Fe Summit Homeowner's Association	Bent Hill Rd and Summit Dr.	Santa Fe	Santa Fe			at least 3 sewage spills due to grinder pump failure	pre 2006	equipment repair, best management practices established, certified operator hired	closed	5/25/2007

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Santa Fe WWTP	Santa Fe	Santa Fe	Santa Fe	35.670974	-106.001899	sampling of domestic wells near WWTP	Mar-87	none, no results above stds.		
Santa Nino Lane	Santa Nino Lane	Santa Cruz	Santa Fe	35.994874	-106.037202	Domestic well sampling event	1985	samples collected	closed	1985
SDC Country Club Estates Well		Santa Fe	Santa Fe			Sangre de Cristo's well showed PCE	1993	investigation showed PCE came from water system and not aquifer	closed	
Southwestern College	3952 San Felipe Rd	Santa Fe	Santa Fe	35.63634	-106.053093	Soil contamination from leaking heating oil UST	3/19/2015	soil excavation	closed	5/8/2015
Stone Forest Warehouse	4525 Agua Fria Street	Santa Fe	Santa Fe	35.653291	-106.030948	suspected unauthorized discharge of wastewater to unlined stormwater pond	unknown	soil sampling for RCRA 8 metals. Results below soil screening levels	closed	8/20/2021
Sullivan well testing	Rt 7 Box 113-S	Santa Fe	Santa Fe	35.670974	-106.001899	Domestic well sampling	1/10/1990	sample results showed high sulfate and TDS	closed	1/23/1990
Sutters Trucking	US 84/285 & CR 103	Pojoaque	Santa Fe	35.894657	-106.015167	tanker truck spill of 7000 gal gasoline.	1998	soil excavation and LNAPL recovery in cooperation with Pueblo	closed	6/26/2000
Tesuque Environmental Survey	Tesuque Valley	Tesuque	Santa Fe	35.753513	-105.915371	Survey showed domestic well impacts of fecal coliform and nitrate	5/1/1974	eventual connection to WWTP	closed	
Tesuque Hill Diesel Spill	Hwy 285 near flea market	Tesuque	Santa Fe			50 gal of diesel spill from truck accident	8/16/1999	soil excavation	closed	9/22/1999
Thompson Water Well	Rt. 5 Box 266B	Tesuque	Santa Fe			petroleum contaminated runoff	3/1/1998	Soil Excavation	closed	5/1/1998
Wifred Padilla Fina	624 Old Las Vegas Hwy	Santa Fe	Santa Fe	35.634111	-105.92582	Reports of RV sewage dumping in a PSTB monitoring well	pre April 2007	allegations of disposing of RV waste into a monitoring well could not be confirmed	closed	4/1/2007
Caballo Emergency Truck Repair	I-25, exit 63	Caballo	Sierra	32.978676	-107.306234	motor oil spill	discovered Dec. 2007	soil excavation	closed	4/10/2009
Chavez Property	1409 N. Date	Truth or Consequences	Sierra	34.166233	-106.026069	tack oil spill	3/12/2007	soil excavation	closed	3/21/2007
Chevron Redi-Mart	Broadway and Van Patton	Williamsburg	Sierra	33.113028	-107.293657	Utility pole excavation discovered release	pre 1987	refined petroleum-all types	regulated by PSTB	10/6/1997
El Paso Electric Co.	I-25 & Exit 59	Arrey	Sierra	32.847659	-107.320483	hydraulic fuel	10/17/2007	soil excavation	closed	7/3/2008
Essery Scrapyard	Animas Creek		Sierra			55-gal barrels and burning of electrical wires	pre 1992	soil sampling	closed	6/14/1993
Evergreen Farm	HC 32, Box 31	Caballo	Sierra			junk area with tar sludge, solid waste	pre 1994	soil excavation	closed	8/11/1995
Francione's Welding	1606 Glenn St	Truth or Consequences	Sierra	33.14817653	-107.2266326	Home Welding Shop, Oil on ground, Supply Well tested for VOCs/SVOCs. Results Clean	1/23/2009	supply well tested	closed	1/28/2009
Hanna Towing	CR B-076	Las Palomas	Sierra	33.059489	-107.297054	inspection revealed gasoline and oily contaminated soil	unknown	soil excavation and sampling; final report not yet submitted	inactive	1/5/2013
El Paso Electric Co.	I-25	Caballo	Sierra	32.91282	-107.3185	Car accident into EPEC owned transformer releasing motor oil, diesel, and hydraulic oil	7/6/2020	Soil excavation, 18 yds ³	closed	2/16/221
Loughridge Spill	N. Hwy. 181 (north of Desertaire Estates, Lot #24)	Truth or Consequences	Sierra	34.166233	-106.026069	spillage of diesel fuel from old tank	12/16/2004	soil excavation	closed	Mar. 2005
Martin Motors	CR B-076	Las Palomas	Sierra	33.059489	-107.297054	inspection revealed gasoline and oily contaminated soil	unknown	soil excavation and sampling; final report not yet submitted	inactive	1/5/2013
Naval Space Surveillance Station	38 miles NE of Tor C	Elephant Butte	Sierra	33.183165	-107.229883	TPH surface soils	pre 1998	soil excavation	closed	1/15/2003
NuWay Cleaners	301 Jones St.	Truth or Consequences	Sierra	33.12956241	-107.2533783	GWQB as part of Dry Cleaner Project discovered Vinly Chloride/DCE in GW (DTW <5 ft bgs) and Vinyl Chloride Vapor exceedances. Dry Cleaner first recorded at property on 1940's Sanborn	unknown	referred to CERCLA-SOS	Referred to CERCLA	11/14/2022
Porter Oil	I-25 and mile 57	Derry	Sierra			8000 gal of gas spill from truck accident	6/3/1992	soil excavation and MNA of GW	closed	6/21/1999
Stovall residence	1365 E. Riverside	Truth or Consequences	Sierra	34.166233	-106.026069	excavation of unregulated UST	pre-1970	removal of tank and confirmatory sampling	closed	3/6/2006
Swift Transportation	I-25 Exit 89	Cuchillo	Sierra	34.166233	-106.026069	Truck Accident - release of 80 gal of diesel - ENTS#3803	Dec.7 2008	soil excavation	closed	2/15/2009
Turtleback Mtn. Partners	120 Stagecoach Drive	Elephant Butte	Sierra	33.165212	-107.219048	discharge of water exceeding Mn std.	1/16/07	installation of monitor wells and sampling	closed	7/8/2008
Bailey Well		Lemitar	Socorro			Determination of cause of anerobic domestic well downgradient of DP-108	1981	sampled well and below laboratory detecting limits	closed	1981
BNSF Derailment Bosque del Apache NWR	10 miles south of San Antonio	San Antonio	Socorro			derailment released ~56,938 gallons of Vacuum Gas Oil	7/27/2010	soil excavation, LNAPL recovery, soil and ground water investigation	closed	8/31/2011
BNSF San Antonio Derailment	1 mile N. of San Antonio	San Antonio	Socorro			1000 gal of diesel spilt during locomotive derailment	9/18/1998	soil excavation, LNAPL removal, and MNA	closed	12/1/1999
BNSF San Antonio Lube Oil Spill	1/2 mile S. of San Antonio	San Antonio	Socorro			Locomotive engine block failure caused 25 gallons of lube oil release	6/30/2007	soil excavation and sampling	closed	7/3/2008
Circle W Station	1104 S. California	Socorro	Socorro	34.071647	-106.89325	200 gal of diesel spill and 500 gal of water	7/29/1998	soil excavation	closed	9/20/1998
L&L Gas and Oil	716 Bagley St	Socorro	Socorro	34.049433	-106.901234	spill of gasoline and diesel while unloading	10/8/1996	soil excavation	closed	1/17/1997

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Magdalena Airport	Magdalena	Magdalena	Socorro	34.107071	-107.234449	old well show low levels of BTEX	1998	sampling in 2003 showed no contamination	closed	6/25/2002
Prime Inc. Truck Accident	I-25 South bound Mile 158	Lemitar	Socorro	34.155235	-106.911183	truck accident caused 80 gal of diesel spill	8/7/2009	soil excavation and sampling	closed	6/23/2009
Socorro Armory	NM Army National Guard, BTRYA, 3rd Battalion	Socorro	Socorro	34.060462	-106.90235	460 gallon diesel spill	2/13/1997	soil excavation	closed	5/15/1997
SW Tire	1001 Grefco	Socorro	Socorro	34.060462	-106.90235	Tire fire in 2000 caused soil contamination	5/1/2000	GWQB installed MWs for SWB and has conducted annual sampling of groundwater monitoring	referred	
USFS Magdalena	203 1st St	Magdalena	Socorro	34.121087	-107.232156	discovery of heating oil release	unknown		inactive	
USFW Bosque del Apache	1001 Hwy 1	San Antonio	Socorro	33.915168	-106.870816	discovery of 250 gal of diesel release for a building heater	unknown	soil and ground water analysis showed no impact	closed	9/15/2010
Village of Magdalena	103 Chestnut St.	Magdalena	Socorro	34.119092	-107.238868	500 gal of sewage spill	8/24/1998	repair sewer and disinfect soil	closed	9/23/1998
Burtis Property, Former Scheid Motor	237 Paseo del Pueblo Sur	Taos	Taos	36.402432	-105.57454	NMDOT PSI identified TPH impacts to ROW, but no individual constituents above standards in groundwater. No assessment of potential chlorinated vapors of remainder of property.	unknown	assessment only	closed	3/6/2018
Exxon Station 6-7241	501 Paseo del Pueblo Norte	Taos	Taos	36.38925	-105.581578	BTEX plume from lust		remediation system	closed	11/13/2001
Navajo Express Diesel Spill	next to McDonald's	Taos	Taos	36.38925	-105.581578	200 gal of diesel spill	12/16/2004	soil removal	closed	1/10/1995
Ogleby Mica Mine	T23N, R12E, S24	Picuris Pueblo	Taos			Discovery of petroleum contaminated soil from former mica mine.	unknown	soil excavation and referral to GWQB's Mining Env. Compliance Section	referred	9/2/2008
Taos Area Domestic Nitrate Study		Taos	Taos			Domestic Well Sampling	1986	Sampled Domestic wells	closed	1986
Taos Drug Lab	Weimar and Talpa Rd	Taos	Taos	36.38925	-105.581578	methylene chloride in soil	pre 88	remediation and soil removal via HWB funds	closed	8/24/1993
Taos Ski Valley		Taos Ski Valley	Taos			AST and LUST sites	pre 95	soil excavation	closed	10/19/1995
USFS Tres Piedras herbicide	Carson FS	Tres Piedras	Taos			4 drums of herb vandalized	pre 70	soil removal	closed	4/21/2004
Ayers Trucking Accident		Clines Corners	Torrance			spill of 500 gal of gasoline	11/25/1998	soil excavation	closed	3/31/1999
BNSF Lube Oil Release - Pedernal	10 miles west of Encino	Pedernal	Torrance	34.643149	-105.622965	Spill of 100 gal of lube oil from retention tank	1/25/2014	soil excavation	closed	5/8/2015
Clipper Rd Services	I-40 Mile 208	Moriarty	Torrance	35.006703	-106.061411	truck accident caused 200 gal of diesel spill	8/14/1999	soil excavation	closed	10/26/1999
Conway Oil	2 miles NE of Duran on Hwy 54	Duran	Torrance			AST overfill	2/15/2001	soil excavation	closed	4/10/2001
Federal Aviation Admin. VORTAC	1 mile SE of Cedarville	Corona	Torrance			release of 125 gal of diesel from generator	8/26/1992	soil excavation	closed	post 1992
Keers Proposed Asbestos Landfill		Mountainair	Torrance			Proposed Asbestos Landfill	1986	determination if asbestos landfill is permissible	closed	1986
McCall Land and Cattle	Glorieta and Manzano streets	Moriarty	Torrance	35.006703	-106.061411	EPA complaint. Silage pile is leaking fluids causing problem - report of impacts to drinking water wells - follow up with water company indicated unrelated E.coli issues only	unknown	site visit indicated no leachate threat to ground water	closed	11/11/2013
Meteor Store/H&M Service	Hwy 41	Estancia	Torrance			Phase 2 showed TPH at 0.5 feet	3/2/2002	site inspection showed no need for corrective action	closed	6/3/2002
Moriarty Air Force Station (former)	T9N, R11E, S6.4	Moriarty	Torrance	35.0339	-105.8117	LUST with heating oil release	pre 4/13/04	soil excavation	closed	5/10/2006
Mt. States Constructors	T9N, R9E, S27.43	Moriarty	Torrance	34.9758	-105.9707	blasting in gravel pit was concern for fuel pipeline and domestic wells became silted	pre 1993	gravel pit ceased operations	closed	6/16/1993
Pilot Travel Center #475	305 abrahames Road	Moriarty	Torrance	35.011192	-106.044503	City of Moriarty ift station failure caused the OWS to overflow, 200 gal sewage discharge	12/18/2021	Cleanup using vacuum truck and absorbents	closed	3/11/2022
Salinas NP Offices	105 E. Ripley	Mountainair	Torrance	34.520344	-106.241947	discovery of hydraulic lift and automotive sump with TPH in soil	unknown	soil excavation and sampling	closed	3/18/2013
Susan's Laundry	713 Broadway Avenue	Moriarty	Torrance	35.006703	-106.061411	ESA showed some solvent contamination in soil vapor.	pre 2006	site assessment	closed	5/31/2007
Transwestern Pipeline Co.	Mountainair Compressor Station	Mountainair	Torrance	34.52045	-106.243296	evaporative ponds at the compressor station	pre 1990	OCD and EPA had lead. Determination was made that waste was non-hazardous	referred	7/1/1990
Travel Centers of America	1014 Central Avenue	Moriarty	Torrance	35.006703	-106.061411	diesel release from AST and dispensers	pre 2006	site assessment and soil excavation	closed	1/11/2012

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used.

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Tucker Enterprises	Us 285 and Hwy 60	Encino	Torrance	34.65556	-105.475551	truck accident caused 200 gal of diesel spill	10/7/1998	soil excavation	closed	11/2/1999
Yellow Freight Trucking Co	I-40 E of Moriarty	Moriarty	Torrance	35.006703	-106.061411	truck accident and 500 gal of fuel additive spilled	2/29/2000	soil excavation	closed	5/24/2000
NMARNG Clayton Old Gun Range MRS (NMHQ-004-R-01)	2.5 miles east of Clayton on Highway 56	Clayton	Union	36.461953	-103.145035	metals associated with small arms ammunition (Pb, Sb, Cu, and Zn) at gun range used from mid '70s to 1995	Pre 1995	Risk assesment of soil to GW and ecological receptors.	closed	9/5/2019
Ennis Transportation Co.	Hwy 87 mile 379.5	Des Moines	Union			improper disposal of road marking paint	9/20/1999	soil excavation	closed	11/12/1999
Phillip's 66	Hwy 64/87	Des Moines	Union			site assessment on old AST services station	unknown	soil borings	closed	7/11/1998
Union County Feedlot		Clayton	Union			50,000 gal storm runoff from a feedlot	6/1/1992	repair of lagoon	closed	6/14/1993
BNSF Belen - OWS	BNSF Belen Yard	Belen	Valencia	34.653055°, -34.649090°	-106.765926°, -106.766896°	Release of oily water from Oil/Water Separator, with second related release on August 1, 2018	7/5/2018	Fluid removal and soil excavation	closed	2/22/2019
BNSF Belen MP 897.5	BNSF Belen Yard	Belen	Valencia	34.638763°	-106.771546°	Release of approximately 100 gallons of diesel fuel between Main Tracks 5 and 6 (Westbound)	4/9/2019	Soil excavation	closed	7/5/2019
Ace Automotive	2100 Bosque Farms Blvd	Bosque Farms	Valencia	34.845167	-106.691274	report of oil discharges	pre 1996	inspection and on-site MW showed no evidence of contamination	closed	9/1/1996
Akin Oil Gas Station	1489 S. Main St.	Belen	Valencia	34.639334	-106.780881	discharges of used oil	1997	soil excavation and best management practices. PSTB has primary jurisdiction due to LUST and AST spills.	referred	
Belen Water Fair		Belen	Valencia			Water Fair testing	1991		closed	1991
BNSF Belen QRS Release	106 N First St	Belen	Valencia	34.65966	-106.768404	20 gal of diesel spilled	10/12/2009	soil excavation and sampling	closed	1/29/2010
BNSF Belen River Yard	SE portion of Yard	Belen	Valencia	34.687144	-106.786922	discovery of old boxcar conditioning area	1950s til 1970	soil excavation, GW monitoring	closed	2/2/2010
Bosque Farms Water Fair		Bosque Farms	Valencia			Water Fair testing	1988		closed	1988
Cason Residence Well	120 Edeal Rd	Los Lunas	Valencia	34.78851	-106.721205	report of diazinon discharges	pre 97	sample of domestic well showed up to 19 ppb diazinon	inactive	3/1/1997
Chevron pipeline leak	Hwy 47, E of El Farol Mission Loop, Sec 6,T6N, R3E	Belen	Valencia			unleaded gas from pipeline leak	31589	pipe repaired and soil removal	closed	10/15/1986
Circle K Diazinon Spill	Store #762, Rt 6, Box 71	Los Lunas	Valencia			diazinon spill diluted with 6800 gall water	32848	sampling of wells	closed	5/15/1990
Egan Well		Becker	Valencia			Sampled domestic well	1996	samples showed high TDS and chloride - likely from geothermal source	closed	1996
Isleta Pueblo	Pueblo (Hells Canyon)	Isleta Pueblo	Valencia			High NO3 in windmill	1987	none	dependent on Pueblo	
James Hamilton Construction	402 Hwy 304	La Joya	Valencia	34.346564	-106.847146	report of buried waste from a road construction	1999	soil excavation	closed	4/12/2000
Los Lunas Fina Station Emergency	Los Fuentes and Main St.	Los Lunas	Valencia	34.808562	-106.771126	Vapor migrated along storm sewer and exploded during construction	1986	referred to PSTB	referred	1986
Los Lunas Meth lab	734 Carrasco	Los Lunas	Valencia	34.820432	-106.725478	pit with meth lab waste	pre 88	pit pumped and waste disposed	closed	6/10/1998
Mid Valley Aviation Hanger	4303 Elaine Dr. SE	Los Lunas	Valencia	34.808562	-106.771126	paint stripping of small planes contaminated shallow GW	1997	MW installation and MNA of GW	closed	2/1/2005
Mt. West Golfscapes	3608 Hwy 47	Peralta	Valencia	34.829837	-106.688326	30 gal herbicide spill	40260	soil excavation and domestic well sampling	closed	8/4/2010
Paul's Place, Hodges Oil	Hwy 47	Tome	Valencia			investigation of release from Hodges Oil - Paul's place	1983	confirmed release, referred	referred	1983
Piping Contractor, Warden Industries	I-25 By pass and Don Felipe	Belen	Valencia	34.687144	-106.786922	report of contractor installing water line buried used oil		County dug up a 55-gal barrel and 5 5 gal buckets of buried used oil. District attorney did not pursue criminal case.	closed	8/2/2003
Road Runner Industrial Works	3581 Hwy 47	Peralta	Valencia	34.822266	-106.69216	Small fuel spill required pollution prevention	36768	P2 measures	closed	8/30/2000
BNSF Carlsbad, La Huerta Yard	East of Muscatel Ave, Track 7110, Milepost 0.5	Carlsbad	Eddy	32.440274	-104.215729	Release of 220 -1,800 gallons of diesel from parked locomotive	44008	vacuum and absorbants of pooled liquid; Soil removal to 5 ft bgs or less, application of 6%microbaze - elevated arsenic still present along track in soils	CAR approved	4/22/2022

New Mexico Environment Department - Ground Water Quality Bureau - Closed/Inactive State Clean Up Sites - January 2023

¹ Latitude and Longitude accuracy may vary. Coordinates may have been determined using google earth, but other less accurate methods may have been used .

² Sites are listed by city, then county, then alphabetically by Site Name.

³ Status may consist of closed/no further action or CAR approved, or referred to another program for processing such as SOS/CERCLA, HWB/RCRA, SWB/RCRA etc. Files for sites closed prior to 2000 may be archived or transferred with the referral.

Site Name ²	Location	City ²	County ²	Latitude ¹	Longitude ¹	Event	Discharge Date	Action Taken	Status ³	Date
Sanchez Drain MRGCD, Padilla Farm	Hwy 107 south of RR crossing	Belen	Valencia			report of dark TPH soil from irrigation ditch maintenance	unknown	inspection and sampling showed reducing organic matter caused dark soil stain from irrigation ditch	closed	9/10/2005
Shamrock Foods Truck Accident	I-25 South, mile 196	Belen	Valencia	34.687144	-106.786922	traffic accident caused 100 gal of diesel spill	39692	soil excavation and sampling	closed	6/23/2009
Swift Transportation	I-25 and mile 195	Belen	Valencia	34.708169	-106.791122	truck accident lost 150 gal of diesel	38308	soil excavation	closed	2/11/2005
USPS Belen	400 N. Main St.	Belen	Valencia	34.669234	-106.774688	LUST contaminated soil and GW	pre 91	referred to PSTB	referred	