

## SAN MATEO - EXHIBIT S



The photos at the left, taken on July 31, 2020, during the kayak-based inspection, depict two discrete deposits of light-tan, pudding-like sediment identified by Vertex and Respondents that match the deposits Impac Labs confirmed were caliche, not bentonite.

