

SAN MATEO - EXHIBIT K

PHOTOS TAKEN BY NM DEPT. OF GAME & FISH, FEBRUARY 25, 2020



Figure 1. Black River and Pecos River confluence, looking up Black River. 2-25-20 approximately 3 river miles below incident.



Figure 2. Looking up stream at railroad bridge crossing. 2-25-20 approximately 1.2 river miles below incident.

SAN MATEO - EXHIBIT K

PHOTOS TAKEN BY NM DEPT. OF GAME & FISH, FEBRUARY 25, 2020



Figure 3. Approximately 350 yards below incident. 2-25-20.



Figure 4. Approximately 350 yards below incident. 2-25-20. Same location as Figure 3.

SAN MATEO - EXHIBIT K

PHOTOS TAKEN BY NM DEPT. OF GAME & FISH, FEBRUARY 25, 2020



Figure 5. Approximately 50 yards below incident. 2-25-20.



Figure 6. Approximately 50 yards below incident. 2-25-20. Same location as Figure 5. This zone is approximately 100-200 yards long.

SAN MATEO - EXHIBIT K

PHOTOS TAKEN BY NM DEPT. OF GAME & FISH, FEBRUARY 25, 2020



Figure 7. Incident location 2-25-20. Location is zone 13 585615mE 3567256mN.



Figure 8. Incident location (same as Figure 7). 2-25-20.