



Inspection Date: September 28, 2018	DP #: 465
	Facility Name: S & R Septic

Facility Contact Information – Scheduling Inspection

Scheduled Inspection - provide contact information Unannounced Inspection

Person Contacted: Steve Rael

Phone Number: 575-770-1001

Facility Description

Waste Type: Surface Disposal Site

Directions to Facility: Tune Drive off US-64 North of Taos.

Inspection Information

Start Time: 10:45 am **End Time:** 12:00 pm

NMED Inspector(s): Avery Olshefski and Jason Herman

Verify that NMED identification was presented: Yes No

Facility Representative(s) present during the Inspection/Discussion: NO SHOW

Reason for Inspection: other

NMED field office in Taos notified the GWQB of improper disposal of FOG

Discussion, Observations and Information Obtained

NMED arrived onsite at 10:45 am observed the gate to be locked. Signs remain improperly posted and no apparent progress has been made on any of the compliance issues stated in the NONC. The smell of septage and a very strong FOG smell was coming from the facility. Jason Herman called Steve Rael to announce the inspection. Mr. Rael stated that he was driving toward Albuquerque and that there was no one in the area that could grant access to facility. Mr. Rael stated that he would discuss this with his lawyer and hung up the phone. After 30 minutes NMED supervisor notified the inspectors that access would not be granted and instructed them to return to the office. A second inspection to include management will be conducted on Monday October 1, 2018.

The attached photos were taken from the facility entrance through a break in the gate material.

As the inspectors drove away from the facility they observed owner Loretta Rael in a S & R Septic work van on Tune Drive near US-64.



Photographic Documentation

Photos Taken? Yes - see attached No

Sample Information

Samples Collected? Yes No

Samples Collected by: N/A

Sample Id #s and locations:

Were samples split between permittee and NMED? Yes No N/A

Did the Facility Representative request copies of NMED's sampling results? Yes No N/A

Monitoring Well Camera Inspection

Monitoring well camera inspection conducted? Yes - see attached report(s) No

Initials of Report Preparer: JGH







