

Inspection Date:	October 1, 2018	DP #:	465	
		Facility Name:	S & R Septic	
Facility Contact Information – Scheduling Inspection				
Scheduled Inspection - provide contact information		🗌 Unan	nounced Inspection	
Person Contact	ted: Steve Rael			
Phone Number	575-770-1001			
Facility Descriptio	<u>n</u>			
Waste Type: Surface Disposal Site				
Directions to Facility: Tune Drive North West of Taos				
Inspection Inform	ation			
Start Time: 10:2	20 E	nd Time:	13:30	
NMEDMelanie Sandoval and Jason HermanInspector(s):Image: Constraint of the sector of the s				
Verify that NMED identification was resented:				
Facility Representative(s) present during the Inspection/Discussion:			Steve Rael	
Reason for Inspection: other				
Follow-up to refusal of entry on September 28, 2018 for FOG complaint				

Discussion, Observations and Information Obtained

NMED arrived onsite at 10:20 am and contacted Steve Rael who arrived 20 minutes later at the facility. Mr. Rael unlocked the facility and allowed the inspectors inside. Mr. Rael stated that the southernmost cells were the most recently used for disposal and that no dumping occurred on Friday when NMED attempted to inspect the facility. NMED noticed a distinct FOG smell around cells 13 and 11. Cell 13 had obviously been covered in fresh dirt within the last 72 hours. NMED determined that Cell 13 would need to be sampled and took duplicate samples to split with Mr. Rael at his request. The inspectors observed signage changes at each cell that included new numerical identification and unreadable waste type identifications. The inspectors informed Mr. Rael that the signs would need to be re-done so they would be readable. The inspectors requested manifests for the previous week including all additional pumping of grease trap waste and the ultimate disposal site for any grease trap waste. Mr. Rael stated that he would provide all disposal records for Thursday and Saturday of the previous week.



Photographic Documentation				
Photos Taken? Ves - see attached No				
Sample Information				
Samples Ves No Collected?				
Samples Collected by: NMED Staff				
Sample Id #s and locations:				
Id #2417332 Cell # 13				
Were samples split between permittee and ✓ Yes No N/A NMED? □ Yes ✓ No Did the Facility Representative request copies of NMED's sampling results? □ Yes ✓ No				
Monitoring Well Camera Inspection				
Monitoring well camera inspection conducted? Yes - see attached report(s)				
No				
Initials of Report Preparer: JGH				

Page 2 of 10













Inspection Report Form

Page 5 of 10



















