

**From:** [Herrmann, Grace](#)  
**To:** [Romero, D.Renee, NMENV](#)  
**Cc:** [Macneil, Katherine, NMENV](#); [Golden, Tom](#); [King, Christopher](#)  
**Subject:** [EXTERNAL] Former Y Station - System Installation Weekly Progress Update  
**Date:** Tuesday, January 4, 2022 9:26:49 AM  
**Attachments:** [Week 1.pdf](#)

---

**CAUTION: This email originated outside of our organization. Exercise caution prior to clicking on links or opening attachments.**

Hi Renee,

This email serves as a summary of work completed at the Former Y Station in Clovis, NM for remediation system installation December 28-30, 2021.

The following tasks were accomplished:

- Mobilized to the site; moved recycling containers; set up temporary security fencing for equipment storage
- Marked and sawcut trench from equipment compound toward MW-16, stopping at South driveway near Albertson's front door

The following work is planned for this week:

- Complete sawcut from equipment compound to MW-16
- Continue saw cutting all trenches onsite

I have attached photos of work at the site, which include comments to assist in interpretation. Please let me know if you have any questions.

Regards,

**Grace Herrmann, EI**

Staff Engineer

***Daniel B. Stephens & Associates, Inc.***

Hydrology | Engineering | Geoscience

A Geo-Logic Company

***Providing solutions for water, natural resources, and the environment***

6020 Academy Road NE, Suite 100 | Albuquerque, New Mexico 87109  
T (505) 822-9400 | D (505) 353-9051 | M (505) 379-0934 | F (505) 822-8877  
[www.dbstephens.com](http://www.dbstephens.com)