

PERMIT ATTACHMENT J HAZARDOUS WASTE MANAGEMENT UNITS

J.1 Unit Description

The Hazardous Waste Management Unit (HWMU) subject to post-closure care under this Permit is limited to the capped surface impoundment and listed in Table J-1. The capped surface impoundment is a RCRA Regulated Unit.

TABLE J-1: Unit Subject to the Permit Undergoing Post-Closure Care (Process Code S04)			
<i>Unit Identifier</i>	<i>Regulatory Status</i>	<i>Operating Capacity</i>	<i>General Information</i>
Capped Surface Impoundment.	Post-Closure Care Permitted Unit.	Since the Facility is not operating the requirements of this capacity are not applicable.	The capped Surface Impoundment (SI) was constructed in 1975, and operated until August 1983. The SI accepted aqueous plating waste for storage before off-site shipment. The SI was Closed with Waste-In-Place in 1986, since subsurface soils were not removed during closure.

The following closed units listed in Table J-2 do not require post-closure care and are not subject to the requirements of this Permit. Therefore, Table J-2 is for informational purposes only.

TABLE J-2: Closed Units not requiring Post-Closure Care			
Unit Identifier	Process Codes	Regulatory Status	General Information
Old Drum Container Storage Area	S01	Clean Closed	The Old Drum Container Storage Unit was clean closed in 2001.
New Drum Container Storage Area	S01	Certified Closed	The New Drum Container Storage Unit was certified closed in 1986.