

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites -January 2023

Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the New Mexico Ground and Surface Water Protection Regulations (20.6.2 NMAC).
 Abbreviations: "1203.A" = Section 20.6.2.1203.A Spill Notification and Corrective Action, NMAC; "AP" = Abatement Plan 20.6.2.4101-4114 NMAC; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.

Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option
Alamogordo Terminal (Epic Midstream, NuStar/STS Energy Pipeline Terminal)	Chamberlain	6026 Highway 54	Alamogordo	Otero	32.81379722	-105.97729170	unknown	petroleum, JP-4, Jet A	70	S-SE	Soil and GW	Stage 2 AP	LNAPL Recovery, MNA, air sparging
Finney Refinery	Chamberlain	#28 County Rd.5050	Bloomfield	San Juan	36.68626300	-107.99374100	4	BTX, Naphthalenes	unknown	unknown	Soil	CAR 1203.A	CAR required / injunction in progress
Precision Engine	Chamberlain	1706 E. Main Street	Farmington	San Juan	36.73731100	-108.18605100	<1	petroleum, PCE, TCE	9	unknown	Soil and GW	CAR 1203.A	Inactive
8635 Rio Grande Blvd.	Chamberlain	8635 Rio Grande	Albuquerque	Bernalillo	35.18395600	-106.645014	<1	petroleum hydrocarbons	15	E-SE	GW	CAR 1203.A	ISCO injections, groundwater monitoring
3002 Monte Vista	Chamberlain	3002 Monte Vista Blvd. NE	Albuquerque	Bernalillo	35.08130300	-106.611864	unknown	PCE, TCE	Unknown	unknown	Soil	CAR 1203.A	Assessment Pending
Kirtland Cleaners	Chamberlain	241 Wyoming Blvd. SE	Albuquerque	Bernalillo	35.07137100	-106.550828	unknown	PCE, TCE	unknown	unknown	unknown	CAR 1203.A	Assessment Pending
Mt. View Nitrate plume	Chamberlain	2nd St. and Tijeras Arroyo	Albuquerque	Bernalillo	35.00242778	-106.66257778	>500	nitrate	40-120	E	Soil and GW	INACTIVE ORPHAN SITE - No viable RP	MNA, annual monitoring
NuStar Albq Terminal	Chamberlain	6738 State Rd. 47	Albuquerque	Bernalillo	34.99199065	-106.65709655	15	petroleum hydrocarbons	100	E-SE	GW	Stage 2 AP	LNAPL recovery and MNA
Phillips 66 Terminal (formerly ConocoPhillips South Phillips Pipeline)	Chamberlain	6356 State Rd. 47	Albuquerque	Bernalillo	34.99101944	-106.65957222	10	diesel, BTEX, EDC	80	E	Soil and GW	Admin Compliance Order / Stage 2 AP	Semi-annual GW monitoring; ISCO injections
UNM well 5	Chamberlain	UNM Main Campus	Albuquerque	Bernalillo	35.08402778	-106.61803333	20	TCE	300	N-NE	GW	Voluntary Stage 1	MNA, Semi-Annual Monitoring
AmeriPride	Chamberlain	515 North Virginia Avenue	Roswell	Chaves	33.39789800	-104.52082300	<5	BTEX, PCE, TCE, cis1,2-DCE, VC	15-20	E/NE	Soil and GW	Stage 2 AP	Semi-Annual Monitoring; ISCO injection efficacy is being evaluated
NM ANG - Roswell North MRS	Chamberlain	Dulce Rd	Roswell	Chaves	33.45327900	-104.36544200	245	Metals, UXO	unknown	unknown	soil	CAR 1203.A	Abatement options under consideration; NM ANG Lead
NM ANG - Roswell Readiness Center	Chamberlain	1 West Earl Cummings Loop	Roswell	Chaves	33.32020700	-104.53509900	unknown	PFOS, PFOA	unknown	unknown	unknown	CAR 1203.A	Assessment pending, NM ANG lead
Helena Chemical, Lake Arthur	Chamberlain	504 Lake Arthur Highway	Lake Arthur	Chaves	32.93167500	-104.38724722	3	nitrate, TDS	20-25	E	Soil and GW	Stage 2 AP	Source removal and BMPs; MNA Semi-annual monitoring
Nutrien - Crop Production Services (former Agrilliance), Vado	Chamberlain	8601 Highway 478	Vado	Doña Ana	32.11561400	-106.66533900	2	nitrate, TDS, fluoride, Fe, Mn	9.00	SE	Soil and GW	Stage 2 AP	Enhanced ISBR injections
Nutrien - Crop Production Services (former UAP), Vado	Chamberlain	8524 Highway 478	Vado	Doña Ana	32.11550300	-106.66408400	2.6	nitrate, TDS, fluoride, Fe, Mn	10	SE	Soil and GW	Stage 2 AP	MNA, semi-annual monitoring
Helena Chemical, Mesquite	Chamberlain	251 John Grisham Drive	Mesquite	Doña Ana	32.16449444	-106.69751944	14	nitrate, TDS	10	S	Soil and GW	Stage 2 AP	Stage 2 Remediation/Abatement - Enhanced bioremediation with source removal
Nutrien - Crop Production Services (former Agrilliance), Artesia	Chamberlain	103 E. Mill Road	Artesia	Eddy	32.86853800	-104.39869200	3.5	nitrate, sulfate, TDS, Cl, fluoride, Fe, Mn	24	SE	Soil and GW	Stage 2 AP	Enhanced ISBR injections
Loving Salt, Malaga	Chamberlain	1624 Pecos Highway	Malaga	Eddy	32.223766	-104.072735	unknown	salt	17	S	Soil and GW	Stage 1 AP	Pending Transfer to VRP
Federal Aviation Administration RCLR Facility	Chamberlain	12 mi NW of Deming, NM	Deming	Grant	32.41575600	-107.893753	<1	Lead	200	unknown	Soil	CAR 1203.A	Soil excavation
Ladshaw Explosives	Chamberlain	0.7 mi W-SW of Hwy 18 on W Hiap Entrance Rd.	Hobbs	Lea	32.76321200	-103.19792700	30	nitrate	60	SE	GW	Stage 1 AP	Semi-annual monitoring
Lee Ranch Coal Mine	Chamberlain	Approx. 9 miles N from 192 Rd. and Rd.556	Grants	McKinley	35.50401000	-107.64556600	3	diesel	19-58	unknown	soil	Stage 1 AP SI	LNAPL perched on clay layer above GW. LNAPL recovery ongoing.
ACME Hometown Cleaners (Former)	Chamberlain	901 E. 10th St.	Alamogordo	Otero	32.90019500	-105.95112200	unknown	PCE, TCE	55-60	SW	Soil Vapor, Soil, GW	Compliance Order	SVE system and air sampling; install additional MWs and monitor
ATA Montoya (T4 Ranch) Valero	Chamberlain	Montoya, NM & Interstate 40	Montoya	Quay	35.12715000	-104.07488056	30-70	refined petroleum - all types	20	E	GW	CAR 1203.A	LNAPL recovery and MNA

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites -January 2023

Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the New Mexico Ground and Surface Water Protection Regulations (20.6.2 NMAC).
 Abbreviations: "1203.A" = Section 20.6.2.1203.A Spill Notification and Corrective Action, NMAC; "AP" = Abatement Plan 20.6.2.4101-4114 NMAC; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.

Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option
Diamond Shamrock Endee	Chamberlain	Endee New Mexico	San Jon	Quay	35.21526944	-103.23739444	4	diesel	25	SE	GW	Stage 2 AP	LNAPL recovery and MNA
Diamond Shamrock, Tucumcari	Chamberlain	3.5 miles E-NE of Tucumcari	Tucumcari	Quay	35.20498056	-103.65754444	13	gasoline & diesel	13-70	SW	Soil and GW	Stage 2 AP	Monitored Natural Attenuation
Shell Truck Stop (AST) Tucumcari	Chamberlain	Eastern I-40 Tucumcari Exit	Tucumcari	Quay	35.15787222	-103.77209167	unknown	LNAPL, petroleum hydrocarbons	20	NE	soil and GW	INACTIVE ORPHAN SITE - No viable RP	Needs further assessment and remediation
Tucumcari Landfill (Old)	Chamberlain	QR65 and Q Ap	Tucumcari	Quay	35.20238100	-103.73520000	15	PCE, TCE	70	NW	Soil and GW	INACTIVE ORPHAN SITE - No viable RP	Needs further assessment
Tucumcari Power Plant (Xcel Energy)	Chamberlain	301 W. Railroad Ave.	Tucumcari	Quay	35.178984	-103.729155	1	diesel	37	NW	GW	Stage 2 AP	LNAPL Recovery, MNA for dissolved plume
NM ANG - Rio Rancho	Chamberlain	4001 NW Loop Rd NE	Rio Rancho	Sandoval	35.36982000	-106.65344	unknown	PFOS, PFOA	unknown	unknown	unknown	CAR 1203.A	Assessment pending, NM ANG lead
Comet 1 Cleaners	Chamberlain	2810 East 20th Street	Farmington	San Juan	36.7485972	-108.1687972	3	PCE	25	S	GW	Stage 2 AP	Enhanced in-situ bioremediation
Downs RV Park	Chamberlain	5701 U.S. Hwy 64	Farmington	San Juan	36.70272900	-108.10488500	8	TDS, chloride, nitrate	30	S-SW	GW	Stage 1 AP	Quarterly Groundwater Monitoring
913 Old Pecos Trail	Chamberlain	913 Old Pecos Trail	Santa Fe	Santa Fe	35.67508100	-105.93676100	<1	PCE, TCE, VOCs	unknown	unknown	Soil Vapor	CAR 1203.A	Assessment in progress
NM ANG Army Aviation Support Facility	Chamberlain	Huey Road	Santa Fe	Santa Fe	35.62502700	-106.08741400	32	PFOS, PFOA	200	W	under investigation	CAR 1203.A	Assessment pending, NM ANG lead
Truth or Consequences Landfill (ToC) (Former)	Chamberlain	T13S R4W S22	T or C/Elephant Butte	Sierra	33.16299300	-107.23229700	30	NO3, Cl, Mn	12-24'	S-SE	GW	CAR 1203.A	Site Investigation/Property Transfer
Veguita, Abo Valley	Chamberlain	Wheeler Rd. and State Rd. 304	Socorro	Socorro	34.52008333	-106.75120278	unknown	nitrate	45	S	GW	No RP identified, ORPHAN SITE - INACTIVE	Monitoring of Orphan Plume
120 West Picacho, Model Cleaners	Chamberlain	120 West Picacho	Las Cruces	Doña Ana	32.31706800	-106.78119400	unknown	PCE	unknown	unknown	Soil Vapor	CAR 1203.A	Passive sub-slab venting
D&D Mountain Air Cleaners	Chamberlain	309 South Paseo de Oñate	Espanola	Río Arriba	35.99070800	-106.07627800	8	PCE, TCE, Cis-DCE	10	south	Groundwater	Stage 1 AP	Needs further assessment
CNMCF Honor Farm	Chamberlain	1525 Morris Rd.	Los Lunas	Valencia	34.77311200	-106.76853200	35	nitrate	30	E-SE	groundwater	Stage 1 AP	Needs further assessment
BNSF Albuquerque	Herrell	Between Copper and Iron; 1st and Edith	Albuquerque	Bernalillo	35.08051500	-106.64805100	54	diesel	35-90	east	soil and GW	Voluntary Stage 1 AP	Site Investigation and characterization ongoing including routine GW monitoring
Chava Trucking	Herrell	6313 State Rd. 47 (6020 Industrial Way) SE	Albuquerque	Bernalillo	34.99354722	-106.66135833	15	petroleum hydrocarbons	40-65	E	Soil and GW	Settlement Agreement	Excavation, soil investigation; inactive
Chevron Bulk Fuels Terminal (FORMER)	Herrell	3200 Broadway SE	Albuquerque	Bernalillo	35.04656000	-106.64610800	9	petroleum hydrocarbons	25	E-SE	Soil and GW	Hydrocarbon Remediation Agreement	Monitored Natural Attenuation (MNA) Semi-annual GW monitoring.
Gulton Industries	Herrell	14800 Central Avenue SE	Albuquerque	Bernalillo	35.06375000	-106.48549444	10	TCE and daughter products	20-120	S-SW	GW	Consent Decree	In-situ bioremediation with injection of HRC® under Discharge Permit.
Los Angeles Landfill	Herrell	Paseo Del Norte and North Diversion Channel	Albuquerque	Bernalillo	35.18059000	-106.60253200	200	VOCs	120	E-SE	Soil and GW	Voluntary Stage 2 AP	Dissolved phase pump and treat, SVE, air sparging. Source control with landfill gas extraction and soil vapor extraction.
Sparton Technologies	Herrell	9621 Coors Blvd NW	Albuquerque	Bernalillo	35.18955278	-106.66187222	500	TCE, chromium	90-220	W-NW	Soil and GW	Consent Decree	Ground water pump and treat. NMED HWB is lead. Vapor Impact delineation needed
TA - Petro Truckstop, Milan	Herrell	I-40 & Horizon Blvd.	Milan	Cibola	35.17950800	-107.90317900	~35	diesel	100+		Soil	CAR 1203.A Conditional NFA	Inactive - Final source removal to be performed when AST is taken out of service
USDA Forest Service, Shuree Ponds	Herrell	Valle Vidal Unit, Carson National Forest	Shuree Ponds	Colfax	36.77182600	-105.19395700	25	iron and manganese from TPH	5-10	E-SE	GW	Stage 1 AP SI	Quarterly GW monitoring; assessing for potentially elevated background of Mg and closure
DeGraaf/Wholesome Dairy (Former)	Herrell	Acosta Rd. and I-10	Anthony	Doña Ana	32.01761100	-106.59322100	~350	nitrate, Cl, TDS, sulfate	46-116	SW (perched) SE (deep)	Soil and GW	Stage 1 AP SI	Stage 1 AP Site Investigation for nitrates, chloride, TDS; semi-annual GW monitoring ongoing

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites -January 2023

Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the New Mexico Ground and Surface Water Protection Regulations (20.6.2 NMAC).
 Abbreviations: "1203.A" = Section 20.6.2.1203.A Spill Notification and Corrective Action, NMAC; "AP" = Abatement Plan 20.6.2.4101-4114 NMAC; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.

Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option
911 West Main, Artesia	Herrell	911 West Main, Artesia	Artesia	Eddy	32.84186700	-104.40814600	<1	chlorinated solvents	45	unknown	GW, soil vapor	CAR 1203.A	soil vapor and groundwater assessment ongoing
BNSF Gallup	Herrell	811 Roundhouse	Gallup	McKinley	35.52603889	-108.75312222	>25	diesel	7	NE	Soil and GW	Voluntary Stage 2 AP	Performing remediation, LNAPL recovery trenches and wells, MNA for dissolved phase.
Union Pacific, Alamogordo	Herrell	S. of Lawndale and 8th St.	Alamogordo	Otero	32.89618000	-105.96573300	25	Creosote, PAHs, DNAPL	45	W-SW	Soil and GW	Stage 1 AP SI	Semi-Annual Monitoring
BNSF Clovis	Herrell	Main Street, Clovis, New Mexico	Clovis	Curry	34.39589167	-103.20850556	500	diesel	300	S-SE	Soil and GW	Voluntary Stage 2 AP	Performing Remediation/Abatement - LNAPL recovery through 4 wells & DAF treatment of Groundwater to POTW for up to 7 feet of free product on groundwater.
Alta Fuels Hwy 17 Tanker Truck Spill	Herrell	Highway 17, 7.5 mi north of Chama, SB (West) Lane	Chama	Rio Arriba	36.99004800	-106.50508100	1	gasoline & diesel	45-52	unknown	Soil	CAR 1203.A	Groundwater monitoring following source removal
Conoco Phillips (AST) - Bernalillo	Herrell	Calle Duranes and railroad tracks	Bernalillo	Sandoval	35.30303300	-106.54693800	1	gasoline and Mn	7	SW	GW	Stage 2 AP	LNAPL recovery, MNA in GW.
NMDOT Main Yard/GOC	Herrell	1120 Cerrillos Road	Santa Fe	Santa Fe	35.67380600	-105.95871200	5	PCE, TCE	350, 127 perched zone (2011)	W	Soil, Soil Vapor	CAR 1203.A	Vapor Intrusion assessment needed.
Ortiz Landfill (Former)	Herrell	Camino de las Crucitas and Buckman Road	Santa Fe	Santa Fe	35.69644444	-105.96433333	~35	metals, nitrate, VOCs, PAHs, landfill gas	340-375	NE	Soil and GW	Stage 1 AP	Ongoing site characterization. Monitoring of GW and Vapor in progress
PNM Baca St	Herrell	North of Shoofly Street and Flagman Way, Near Baca Street and Cerrillos Road	Santa Fe	Santa Fe	35.67537200	-105.96127700	15	PSTB Regulated: LNAPL and petroleum : benzene, toluene, ethylbenzene, total xylenes, 1,2-dibromoethane EDB, EDC, naphthalene; GWQB Regulated: PCE, TCE, 1,1,-DCE, VC, MC, CTET, nitrate	240-312	Generally E to W with localized variability and a recovering cone of depression	GW	Stage 1 AP	Ongoing site characterization. GW monitoring in progress
La Unica Dry Cleaners No. 1	Herrell	647 Cerrillos Road	Santa Fe	Santa Fe	35.68031100	-105.94738600	0.18	chlorinated solvents, particularly PCE	unknown; estimated at less than 50 ft bgs	unknown; suspected N	Soil, Soil Vapor; possibly GW	CAR 1203.A	Assessment in progress
Fmr White Swan Laundry Facility	Herrell	1368 Cerrillos Road	Santa Fe	Santa Fe	35.67047200	-105.96424700	1.5	chlorinated solvents, particularly PCE	unknown; estimated at 200 ft bgs	unknown; suspected NNW	Soil Vapor; possibly Soil and GW	CAR 1203.A	Assessment in progress
Santa Fe Railyard/ConocoPhillips/Fmr La Unica Dry Cleaners @825 Cerrillos	Herrell	760 & 825 Cerrillos Road	Santa Fe	Santa Fe	35.67857700	-105.95154800	<50	PCE	70-130	E	GW	CAR 1203.A	GW and Vapor impacts confirmed. One or more Sites in transition to VRP.
Salome Property	Herrell	327 McCutcheon Ave.	Socorro	Socorro	34.05544800	-106.89531200	<1	PCBs	unknown	unknown	Soil	CAR 1203.A	Soil removal and disposal.
Travel Centers of America, Moriarty	Herrell	1700 U.S. Route 66 West	Moriarty	Torrance	35.00770800	-106.06644700	<1	Diesel	145	unknown	Soil	CAR 1203.A Conditional NFA	Inactive - Final source removal to be performed when AST is taken out of service
Dry Cleaners, Clayton	Herrell	20 Peach Street	Clayton	Union	36.45488500	-103.18689700	<5	PCE, BTEX	40-45	S	Soil and GW	INACTIVE ORPHAN SITE - No viable RP	Monitoring and SV survey needed.
BNSF Belen Fueling Facility	Herrell	106 N. 1st St.	Belen	Valencia	34.65448333	-106.76809722	>100	diesel, Mn, Fe	5 to 15	S	Soil and GW	Stage 2 AP	Performing Remediation/abatement. LNAPL recovery trenches and wells, MNA for dissolved constituents. DP-278 for evap. lagoons to receive sump wastewater. DP-1715 for injection wells to receive extracted ground water for LNAPL recovery.
BNSF Derailment Spill, Vado	Herrell	BNSF ROW; NE of intersection of Hwy 189 and Waterfront Rd	Vado	Doña Ana	32.11555000	-106.66587500	~3	diesel fuel	12 to 15	W	Soil, GW	CAR 1203.A	8 quarter GW monitoring plan toward closure in progress
Acoma Business Enterprises - Carnuel	Herrell	I-40 overpass of NM-333, east of Carnuel	Carnuel	Bernalillo	35.06580300	-106.42457100	<1	gasoline and diesel	6	unknown	bedrock	Stage 1 AP	Ongoing site characterization. Fracture Flow. Delineation and Monitoring of GW impacts in progress
Karler Packing (Former)	Herrell	9151 Broadway SE	Albuquerque	Bernalillo	34.96129400	-106.66127300	50	nitrate	65	SE-E	GW	Stage 1 AP INACTIVE	Inactive due to Bankruptcy.

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites -January 2023

Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the New Mexico Ground and Surface Water Protection Regulations (20.6.2 NMAC).
 Abbreviations: "1203.A" = Section 20.6.2.1203.A Spill Notification and Corrective Action, NMAC; "AP" = Abatement Plan 20.6.2.4101-4114 NMAC; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.

Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option
Laun-Dry Company, Inc	Herrell	1500 12th St NW	Albuquerque	Bernalillo	35.10255556	-106.65795833	90+	PCE, TCE, Cis & trans DCE	35	E	Soil and GW	Stage 2 AP	Enhanced in-situ bioremediation with MNA and Long Term Monitoring. Additional downgradient impact delineation ongoing
1710 Llano	Smith	1710 Llano	Santa Fe	Santa Fe	35.65815228	-105.97307434	<1	PCE, TCE	unknown	unknown	Soil Vapor	CAR 1203.A	Passive Soil Vapor Survey conducted, RP is reviewing remedial options
250 W Las Cruces St, Cothorn Cleaners	Smith	250 W Las Cruces	Las Cruces	Doña Ana	32.31124900	-106.78092700	unknown	PCE	unknown	unknown	Soil Vapor	CAR 1203.A	Needs further assessment
705 North Main, Eubank Cleaners	Smith	705 North Main St.	Las Cruces	Doña Ana	32.31450100	-106.78048200	unknown	PCE	unknown	unknown	Soil Vapor	CAR 1203.A	Needs further assessment
American Linen	Smith	525 and 550 North Church Street	Las Cruces	Doña Ana	32.313307 32.313820	-106.779019 -106.778286	unknown	PCE	unknown	unknown	Soil Vapor	CAR 1203.A	Needs further assessment
American Pride Cleaners	Smith	1349 San Mateo Blvd SE	Albuquerque	Bernalillo	35.06040272	-106.58678079	<1	CVOCs	unknown	unknown	soil vapor	CAR 1203.A	Needs further assessment
Davis Cleaners	Smith	2906 Juan Tabo NE	Albuquerque	Bernalillo	35.114673	-106.514196	1	chlorinated solvents	700	unknown	Soil Vapor	CAR 1203.A	Needs further assessment
Digital/Compaq/HP (Former)	Smith	5600 Jefferson NE	Albuquerque	Bernalillo	35.14318333	-106.59482500	50	TCA, DCE, 1,4 Dioxane	170-250	SE	GW and Soil Vapor	Admin Order Consent (AOC)	Quarterly monitoring. Pump & Treat system operated 1998 - 2009, address most of VOCs. DCE remains. Soil Vapor addressed with SVES. Assessment of 1,4 Dioxane ongoing
Farmington Iron & Metal	Smith	4805 Herrera Rd	Farmington	San Juan	36.75463990	-108.14783033	3	Petroleum Hydrocarbons/metals	<10	seasonal variation	Soil and GW	CAR 1203.A	Source Removal ongoing, Quarterly Monitoring
Fox & Associates	Smith	3412 Bryn Mawr Drive NE	Albuquerque	Bernalillo	35.12080278	-106.60924444	1	TCE	50-220	E	Soil and GW	Stage 2 AP	SVES operated March 2009-2012, Semi-annual GW monitoring. AP area defined as regional plume. Source property abatement completed.
George's Dry Cleaners (former)	Smith	619 Amherst Dr NE	Albuquerque	Bernalillo	35.08693900	-106.60583600	unknown	chlorinated solvents	unknown	unknown	soil vapor	CAR 1203.A	Needs further assessment
GTE Lenkurt/Copper Pointe Facility	Smith	10500 Copper Ave NE	Albuquerque	Bernalillo	35.080006	-106.53236700	47	PCE	600	unknown	Soil vapor and GW	CAR 1203.A	Needs further assessment. Phase 2 work revealed soil vapor intrusion with chlorinated solvents.
Holly Energy, Artesia	Smith	US 82 (3 miles E. of Artesia)	Artesia	Eddy	32.84234722	-104.35640000	1	gas, diesel, jet fuel	8	SE	Soil and GW	Stage 2 AP	Remediation/Abatement - soil excavation, mobile dual-phase extraction, hyd. peroxide injection, Semi-annual GW monitoring with annual reporting in January of each year
Hooter Browns (aka ELCO Mfg. Inc), Raton	Smith	931 Clayton Road	Raton	Colfax	36.88546400	-104.42839300	<5	chlorinated solvents	25	S-SE	Soil Vapor and GW	Stage 1 AP	Revised S1AP approved May 2022, Semi-annual monitoring
KAFB ST-105 Nitrate Plumes	Smith	Near Wyoming and Randolph	Albuquerque	Bernalillo	35.04956389	-106.56965000	200	nitrate	250-550	various	GW	Stage 2 AP	Stage 2 AP Modification pending
McCatham Dairy	Smith	6363 State Rd. 47	Albuquerque	Bernalillo	34.98839900	-106.65918300	25	TDS, chloride, nitrate	80	E-SE	Soil and GW	Stage 2 AP	phytoremediation, quarterly monitoring
Mesa Oil	Smith	20 Lucero Rd.	Belen	Valencia	34.59728900	-106.73192000	5	petroleum hydrocarbons	80	S	Soil	CAR 1203.A	Under 2010 ACO
NMDOT La Cueva Patrol Yard	Smith	NM 518, MM 23.6	Las Vegas	Mora	35.93458000	-105.25272900	<50	TDS, chloride	5-30	SW	Soil and GW	Stage 2 AP	Source removal, RO System/Reinjection, MNA
NMDOT District 4 Service Center, Las Vegas Patrol Yard	Smith	I-25 Frontage Rd, MM 344	Las Vegas	San Miguel	35.56902900	-105.22470500	>100	TCA, DCE, TDS, chloride, BTEX, MTBE	15-40	SE	Soil and GW	Stage 2 AP	Recovery trench, RO treatment, re-injection
Plains Electric/PNM, Algodones	Smith	1500 NM Highway 313	Algodones	Sandoval	35.38441700	-106.46454400	45	manganese, TDS, sulfate	30-40	W-SW	GW	CAR 1203.A	bi-annual monitoring

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites -January 2023

Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the New Mexico Ground and Surface Water Protection Regulations (20.6.2 NMAC).
 Abbreviations: "1203.A" = Section 20.6.2.1203.A Spill Notification and Corrective Action, NMAC; "AP" = Abatement Plan 20.6.2.4101-4114 NMAC; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.

Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option
Prewitt Pit	Smith	Off I-40 between Grants and Thoreau (T13N R11W, Sec. 34)	Prewitt	McKinley	35.312357	-107.98518800		unknown	190	unknown	Soil and GW	CAR 1203.A	Notification of discharge sent to RP regarding alleged buried drums. Solid Waste Bureau lead agency
Prices Dairy (Former)	Smith	618 Highway 528	Bernalillo	Bernalillo	35.31506500	-106.57204100	50	TDS, chloride, nitrate, sulfate	25 and 85	E-SE	GW	Stage 2 AP	Surface soil remediation completed under VRP. Groundwater extraction performed. Alternative Abatement Standards (AAS) Petition approved by WQCC for Valley Fill Aquifer. Annual monitoring of Upper Santa Fe Aquifer remains.
ProFab	Smith	1040 Bosque Farms Blvd	Bosque Farms	Valencia	34.86014007	-106.68918399	<1	Metals and Inorganic	<10	seasonal variation	Soil and GW	CAR 1203.A	Needs further assessment
Quality Laundry, Bernalillo	Smith	107 Calle Del Presidente	Bernalillo	Sandoval	35.30547778	-106.54777500	3	PCE	6	SW	GW	Stage 1 AP	Revised S1AP approved: VI assessment and evaluation of groundwater conditions. AP completion possible with 8 consecutive sampling events
Rek Chem (former)	Smith	105 Dale St. SE	Albuquerque	Bernalillo	35.00298056	-106.66074167	3	TCE	55	E	GW	Stage 1 AP SI	Semi-annual GW monitoring
Roadrunner Laundry	Smith	512 Courthouse Rd.	Los Lunas	Valencia	34.80137500	-106.73296389	<1	PCE	5	S-SE	Soil and GW	Stage 1 AP	Revised S1AP approved: VI assessment and evaluation of groundwater conditions. AP completion possible with 8 consecutive sampling events
Santa Fe Pacific Pipeline (SFPP) Spill - Anthony	Smith	near 4217 3 Saints Road	Anthony	Doña Ana	32.06152500	-106.649422	7	gasoline	10-12	unknown	Soil and GW	Stage 1 AP	soil contamination address by excavation. Quarterly GW monitoring
Sierra Vista Growers, La Mesa	Smith	12701 Highway 28	La Mesa	Doña Ana	32.08773056	-106.68566940	unknown	nitrate, Cl, TDS	10	unknown	GW	Stage 1 AP	GW monitoring for nitrates, Cl, TDS.
TLC Dry Cleaner	Smith	230 E. Reinken	Belen	Valencia	34.66099444	-106.76421944	3	PCE	5	S	GW	Stage 1 AP	Revised S1AP required, Abatement Completion may be possible if 8 Qtrs. of samples collected.
UniFirst	Smith	215 Altez St. SE	Albuquerque	Bernalillo	35.07112609	-106.53985293	2	CVOCs	unknown	unknown	soil vapor	CAR 1203.A	Needs further assessment
Urban Biology	Smith	3600 Los Picaros Rd. SE.	Albuquerque	Bernalillo	35.01686800	-106.59897200	<2	PCE/TCE	unknown	unknown	soil vapor	CAR 1203.A	SVE system
Walker AFB (former)/Roswell Air Center	Smith	1 Jerry Smith Cir	Roswell	Chaves	33.307559	-104.517753	>2,000	TCE	40-120	E	Soil and GW	DOD Potential Responsible Party	NMED is waiting on eventual Federal Court decision for a determination of settlement amount that must precede further assessment of the site for abatement.
Western Terrace	Smith	Powers Way and Murchenson	Albuquerque	Bernalillo	34.97418333	-106.7293056	50	nitrate	70-120	S-SE	GW	No RP identified ORPHAN SITE - INACTIVE	Probable source is septic tank/drain fields or former dairy