

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites - Update 9/9/16

Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the Water Quality Control Commission Regulations, 20.6.2 NMAC.

Abbreviations: "1203.A" = Section 20.6.2.1203.A Spill Notification and Corrective Action, NMAC; "AP" = Abatement Plan 20.6.2.4101-4114 NMAC; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.

Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option
ACME Hometown Cleaners (Former)	Montes	901 E. 10th St.	Alamogordo	Otero	32.90020	-105.95112	unknown	PCE, TCE	55-60	SW	Soil Vapor, Soil, GW	CAR 1203.A	Initial site assessment proposed
Alta Fuels Hwy 17 Tanker Truck Spill	Unassigned	Hwy 17, 7.5 mi north of Chama, SB (West) Lane	Chama	Rio Arriba	36.99005	-106.50508	1	gasoline & diesel	~45-52	unknown	Soil	CAR 1203.A	Groundwater monitoring following source removal
AmeriPride	Montes	515 North Virginia Avenue	Roswell	Chaves	33.39790	-104.52082	<5	BTEX, PCE, TCE, cis1,2-DCE, VC	15-20	E/NE	Soil and GW	Stage 2 AP	Additional Site Investigation pending, including vapor intrusion pathway
Angel Fire LLC/Milwaukee Jewish Federation (Former Creosote Treatment Plant)	Unassigned	unknown	Angel Fire	Colfax	36.430228°	-105.294503°	unknown	Creosote, PAHs, DRO	10	Est East	unknown	CAR 1203.A	Notice of Unauthorized Discharge Pending
ATA Montoya (T4 Ranch) Valero	Unassigned	Montoya, NM & interstate 40	Montoya	Quay	35.12715	-104.07488	30-70	refined petroleum - all types	20	E	GW	CAR 1203.A	LNAPL recovery and MNA
BNSF Albuquerque	Ball	Between Copper and Iron; 1st and Edith	Albuquerque	Bernalillo	35.08052	-106.64805	54	diesel	35-90	east	soil and GW	Voluntary Stage 1 AP	Additional Site Investigation pending
BNSF Belen Fueling Facility	Ball	106 N. 1st St.	Belen	Valencia	34.65448	-106.76810	>100	diesel	5 to 15	S	Soil and GW	Stage 2 AP & CARs	Performing Remediation/abatement. LNAPL recovery trenches and wells, MNA for dissolved constituents. DP-278 for evap lagoons to receive sump wastewater. DP-1715 for injection wells to receive extracted ground water for LNAPL recovery.
BNSF Clovis	Ball	Main Street, Clovis, New Mexico	Clovis	Quay	34.39589	-103.20851	500	diesel	300	S-SE	Soil and GW	Voluntary Stage 2 AP	Performing Remediation/Abatement - LNAPL recovery through 4 wells & DAF treatment of Groundwater to POTW for up to 7 feet of free product on groundwater.
BNSF Gallup	Ball	811 Roundhouse	Gallup	McKinley	35.52604	-108.75312	>25	diesel	7	NE	Soil and GW	Voluntary Stage 2 AP	Performing remediation, LNAPL recovery trenches and wells, MNA for dissolved phase.
Chava Trucking	Unassigned	6313 St. Rd. 47 (6020 Industrial Way) SE	Albuquerque	Bernalillo	34.99355	-106.66136	15	petroleum hydrocarbons	40-65	E	Soil and GW	Settlement Agreement	Excavation, soil investigation
Chevron Bulk Fuels Terminal (FORMER)	Unassigned	3200 Broadway SE	Albuquerque	Bernalillo	35.04656	-106.64611	9	petroleum hydrocarbons	25	east	Soil and GW	Hydrocarbon Remediation Agreement	Monitored Natural Attenuation (MNA) Semi-annual GW monitoring.
Comet 1 Cleaners	Ball	2810 East 20th Street	Farmington	San Juan	36.74860	-108.16880	3	PCE	25	S	GW	Stage 2 AP	Enhanced in-situ bioremediation
Conoco Phillips (AST) Bernalillo, NM	Unassigned	Calle Duranes and railroad tracks	Bernalillo	Sandoval	35.30600	-106.54664	1	gasoline	7	SW	GW	Stage 2 AP	LNAPL recovery. MNA in GW.
ConocoPhillips South (formerly Phillips Pipeline)	Unassigned	6356 State Rd. 47	Albuquerque	Bernalillo	34.99102	-106.65957	10	diesel, BTEX, EDC	80	E	Soil and GW	Admin Compliance Order	Insitu Chemical Oxidation Pilot test ongoing, semi-annual GW monitoring.

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites - Update 9/9/16

Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the Water Quality Control Commission Regulations, 20.6.2 NMAC.

Abbreviations: "1203.A" = Section 20.6.2.1203.A Spill Notification and Corrective Action, NMAC; "AP" = Abatement Plan 20.6.2.4101-4114 NMAC; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.

Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option
Crop Production Services (former Agriliance), Artesia	Montes	103 E. Mill Road	Artesia	Eddy	32.86854	-104.39869	3.5	nitrate, sulfate, TDS, Cl, fluoride, Fe, Mn	24	SE	Soil and GW	Stage 2 AP	Performing Remediation - soil excavation, pilot study with GW monit.
Crop Production Services (former Agriliance), Vado	Montes	8601 Hwy. 478	Vado	Doña Ana	32.11561	-106.66534	2	nitrate, TDS, fluoride, Fe, Mn	9.00	SE	Soil and GW	Stage 2 AP	Performing Remediation - soil excavation, pilot study with GW monit.
Crop Production Services (former UAP), Vado	Montes	8524 Highway 478	Vado	Doña Ana	32.11476	-106.53331	2.6	nitrate, TDS, fluoride, Fe, Mn	10	SE	Soil and GW	Stage 2 AP	Performing Remediation - soil excavation, pilot study with GW monit.
DeGraaf/Wholesome Dairy (Former)	Montes	Acosta Rd and I-10	Anthony	Doña Ana	32.01617	-106.59031	unknown	nitrate, Cl, TDS	46-116	SW	Soil and GW	Stage 1 AP SI	Stage 1 AP Site Investigation for nitrates, chloride, TDS
Diamond Shamrock Endee	Unassigned	Endee New Mexico	San Jon	Quay	35.21527	-103.23739	4	diesel	25	SE	GW	Stage 2 AP	LNAPL recovery and MNA
Diamond Shamrock, Tucumcari	Unassigned	3.5 miles E-NE of Tucumcari	Tucumcari	Quay	35.20498	-103.65754	13	gasoline & diesel	13-70	SW	Soil and GW	Stage 2 AP	Monitored Natural Attenuation
Digital/Compaq/HP (Former)	Ball	5600 Jefferson NE, Albuquerque, NM	Albuquerque	Bernalillo	35.14318	-106.59483	50	TCA, DCE	170-250	SE	GW	Admin Order Consent (AOC)	Semi-Annual Monitoring
Downs RV Park	Unassigned	5701 U.S. Hwy 64	Farmington	San Juan	36.70273	-108.10489	unknown	TDS, chloride, nitrate	30	S-SW	GW	CAR 1203.A Report	Quarterly Groundwater Monitoring
Dry Cleaners, Clayton	Unassigned	20 Peach Street	Clayton	Union	36.45503	-103.18734	<5	PCE, BTEX	40-45	S	Soil and GW	INACTIVE ORPHAN SITE - No viable RP	Monitoring and SV survey needed.
Dunn Edwards Paint	Ball	215 Rossmore Rd., SW	Albuquerque	Bernalillo	35.03066	-106.66039	6	BTEX, 1-1-2, Trichloroethane, Napthalenes, Arsenic, Barium, Chromium, Mercury	12	E	Soil and GW	CAR 1203.A Report	Quarterly Groundwater Monitoring, additional site investigation needed
Epic Midstream (former NuStar/STS Energy Pipeline Terminal)	Montes	6026 Hwy. 54	Alamogordo	Otero	32.81380	-105.97729	unknown	petroleum, JP-4, Jet A	70	S-SE	Soil and GW	Stage 2 AP	LNAPL Recovery with MNA. Air Sparge Pilot test ongoing
Fox & Associates	Unassigned	Bryn Mawr St, Albuquerque, NM.	Albuquerque	Bernalillo	35.12080	-106.60924	1	TCE	50-220	E	Soil and GW	Stage 2 AP	SVES operated March 2009-2012.
Gulton Industries	Unassigned	14800 Central Avenue SE	Albuquerque	Bernalillo	35.06375	-106.48549	10	TCE	20-120	E	GW	Consent Decree	In-situ bioremediation with injection of HRC® under Discharge Permit.
Helena Chemical, Lake Arthur	Montes	504 Lake Arthur Hwy.	Lake Arthur	Chaves	32.93168	-104.38725	3	nitrate, TDS	20-25	E	Soil and GW	Stage 2 AP	Stage 2 Abatement Plan Approved. Site Investigation - soil excavation and MW installation.
Helena Chemical, Mesquite	Montes	251 John Grisham Drive	Mesquite	Doña Ana	32.16449	-106.69752	14	nitrate, TDS	10	S	Soil and GW	Stage 2 AP	Stage 2 Remediation/Abatement - Enhanced biodenitrification with soil excavation/source removal
Holly Energy, Artesia	Montes	US 82 (3 miles E. of Artesia)	Artesia	Eddy	32.84235	-104.35640	1	gas, diesel, jet fuel	8	SE	Soil and GW	Stage 2 AP	Remediation/Abatement - soil excavation, mobile dual-phase extraction, hyd. peroxide injection, GW monit.
Hooter Browns (aka ELCO Mfg Inc), Raton	Ball	931 Clayton Road	Raton	Colfax	36.88546	-104.42839	<5	chlorinated solvents	25	S-SE	Soil and GW	Stage 1 AP INACTIVE	Inactive due to Bankruptcy.
KAFB Nitrate Plumes	Unassigned	Near Wyoming and Randolph, Kirtland Air Force Base	Albuquerque	Bernalillo	35.04956	-106.56965	200	nitrate	250-550	various	GW	Stage 2 AP	Stage 2 AP Modification Requested by NMED Fall 2015. Current approved plan is MNA with pump and use.

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites - Update 9/9/16

Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the Water Quality Control Commission Regulations, 20.6.2 NMAC.

Abbreviations: "1203.A" = Section 20.6.2.1203.A Spill Notification and Corrective Action, NMAC; "AP" = Abatement Plan 20.6.2.4101-4114 NMAC; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.

Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option
Karler Packing (Former)	Ball	9151 Broadway SE	Albuquerque	Bernalillo	34.96129	-106.66127	50	nitrate	65	SE-E	GW	Stage 1 AP INACTIVE	Inactive due to Bankruptcy.
Ladshaw	Montes	0.7 mi W-SW of Hwy 18 on W Hiap Entrance Rd.	Hobbs	Lea	32.76321	-103.19793	30	nitrate	60	SE	GW	Settlement Agreement - INACTIVE	Inactive due to Bankruptcy.
Laun-Dry Company, Inc	Ball	1500 12th St NW, Albuquerque, NM	Albuquerque	Bernalillo	35.10256	-106.65796	90+	PCE, TCE, Cis & trans DCE	35	E	Soil and GW	Stage 1 AP, FSIR Approved	Stage 2 AP submitted, open for public comment.
Lee Ranch Coal Mine	Unassigned	Approx 9 miles N from 192 Rd and Rd 556	Grants	McKinley	35.50401	-107.64557	3	diesel	19-58	unknown	soil	Stage 1 AP SI	Site Investigation - LNAPL perched on clay layer above GW. LNAPL recovery ongoing.
Los Angeles Landfill	Ball	Paseo Del Norte and North Diversion Channel	Albuquerque	Bernalillo	35.18118	-106.78078	200	VOCs	120	E-SE	Soil and GW	Voluntary Stage 2 AP	Dissolved phase pump and treat, SVE, air sparging. Source control with landfill gas extraction and soil vapor extraction.
McCatharn Dairy	Unassigned	6363 St. Rd 47	Albuquerque	Bernalillo	34.98840	-106.65918	25	TDS, chloride, nitrate	80	E-SE	Soil and GW	Stage 1 AP FSIR Revised FSIR pending with ST2 AP	Stage 2 proposal in development.
Mesa Feed	Montes	2424 Rincon Rd.	Rincon	Doña Ana	32.67345	-107.06348		nitrate			soil	CAR 1203.A	Soil removal and sampling.
Mesa Oil	Ball	20 Lucero Rd.	Belen	Valencia	34.59729	-106.73192	5	petroleum hydrocarbons	80	S	Soil	CAR 1203.A	Under 2010 ACO
Mt. View Nitrate plume	Ball	2nd St. and Tijeras Arroyo	Albuquerque	Bernalillo	35.00243	-106.66258	>500	nitrate	40-120	E	Soil and GW	ONRT project	In-situ bioremediation pilot study
NMDOT District 4 Service Center	Unassigned	I-25 Frontage Rd, MP 344	Las Vegas	San Miguel	35.56903	-105.22471	>100	TCA, DCE, TDS, chloride, BTEX, MTBE	15-40	SE	Soil and GW	Stage 2 AP	Recovery trench, RO treatment, re-injection
NMDOT La Cueva Patrol Yard	Unassigned	NM 518, MP 23.6	Las Vegas, Mora Co.	Mora	35.93458	-105.25273	<50	TDS, chloride	5-30	SW	Soil and GW	Stage 2 AP	Source removal, MNA
NMDOT Main Yard/GOC	Ball	1120 Cerrillos Road	Santa Fe	Santa Fe	36.67409	-105.95727	5	PCE, TCE	350, 127 perched zone (2011)	W	Soil, Soil Vapor	CAR 1203.A	Vapor Intrusion assessment needed.
One Hour Martinizing, Santa Fe	Ball	1091 St. Francis Dr.	Santa Fe	Santa Fe	35.67431	-105.95356	<10	PCE	60-70	S-SE	Soil Vapor and GW	1999 Workplan/Voluntary Abatement	Additional Site Investigation pending, including vapor intrusion pathway
Ortiz Landfill (Former)	Unassigned	Camino de las Crucitas and Buckman Road	Santa Fe	Santa Fe	35.69644	-105.96433	unknown	nitrate, VOCs	360	SE	Soil and GW	Stage 1 AP	Additional site characterization needed for GW, vapor
Plains Electric/PNM, Algodones	Unassigned	1500 State Highway 313	Algodones	Sandoval	35.38442	-106.46454	45	manganese, TDS, sulfate	30-40	W-SW	GW	CAR 1203.A	Monitoring on a 5 year basis

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites - Update 9/9/16

Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the Water Quality Control Commission Regulations, 20.6.2 NMAC.

Abbreviations: "1203.A" = Section 20.6.2.1203.A Spill Notification and Corrective Action, NMAC; "AP" = Abatement Plan 20.6.2.4101-4114 NMAC; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.

Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option
Prewitt Pit	Unassigned	Off I-40 between Grants and Thoreau. T 13N 11W Sec 34.	Prewitt	McKinley	35.31236	-107.98519		unknown	190	unknown	Soil and GW	CAR 1203.A	Notification of discharge sent to RP regarding alleged buried drums. Solid Waste Bureau lead agency
Prices Dairy (Former)	Unassigned	618 NM Highway 528	Bernalillo	Bernalillo	35.31507	-106.57204	50	TDS, chloride, nitrate, sulfate	25 and 85	E-SE	GW	Stage 2 AP	Surface soil remediation completed under VRP. Groundwater extraction performed. Alternative Abatement Standards (AAS) Petition approved by WQCC.
Quality Laundry, Bernalillo	Unassigned	107 Calle Del Presidente, Bernalillo, New Mexico (Site)	Bernalillo	Sandoval	35.30548	-106.54778	3	PCE	6	SW	GW	Stage 1 AP	Stage 2 AP needed.
Rek Chem	Unassigned	105 Dale St., SE	Albuquerque	Bernalillo	35.00298	-106.66074	3	TCE	55	E	GW	Stage 1 AP SI	4 MWs, more site investigation needed.
Roadrunner Laundry	Unassigned	512 Courthouse Rd.	Los Lunas	Valencia	34.80138	-106.73296	<1	PCE	5	S-SE	Soil and GW	Stage 1 AP halted: Completion of Abatement Possible INACTIVE	5 MWs. GW sampling performed by NMED in 2007 and 2011. Abatement Completion may be possible if 8 Qtrs of samples collected.
Salome Property	Montes	327 McCutheon	Socorro	Socorro	34.05545	-106.89531	<1	PCBs	unknown	unknown	Soil	CAR 1203.A	Soil removal and disposal.
San Juan Springs Company	Ball	409 East Broadway	Farmington	San Juan	36.72819	-108.201400	<5	chromium, metals, petroleum hydrocarbons	10-12	S	Soil and GW	Stage 2 AP	In-situ bioremediation and MNA.
Santa Fe Railyard/ConocoPhillips/La Unica Dry Cleaners	Unassigned	760 Cerrillos Road	Santa Fe	Santa Fe	35.67884	-105.95095	<50	PCE	70-130	E	GW	Stage 1 AP	File under review.
Shell Truck Stop (AST) Tucumcari	Unassigned	Eastern I-40 Tucumcari Exit	Tucumcari	Quay	35.15787	-103.77209	<3	petroleum hydrocarbons	20	NE	unknown	CAR 1203.A	Needs further assessment
Sierra Vista Growers, La Mesa	Montes	12701 Hwy. 28	La Mesa	Doña Ana	32.08773	-106.68567	unknown	nitrate	10	unknown	GW	CAR 1203.A	GW monitoring for nitrates.
Sparton Technologies	Unassigned	7701 Coors Road NW, Albuquerque, NM.	Albuquerque	Bernalillo	35.18955	-106.66187	500	TCE, chromium	90-220	W-NW	Soil and GW	Consent Decree	Ground water pump and treat. NMED HWB is lead.
TLC Dry Cleaner	Unassigned	230 E. Reinken	Belen	Valencia	34.66099	-106.76422	3	PCE	5	S	GW	Stage 1 AP	Natural attenuation has addressed PCE. Cis-DCE remains. Additional investigation and remediation needed.
Travel Centers of America, Moriarty	Unassigned	1700 U.S. Route 66 West	Moriarty	Torrance	35.00771	-106.06645	<1	Diesel	145	unknown	Soil	CAR 1203.A Conditional NFA	Final source removal to be performed when AST is taken out of service
Truth or Consequences Landfill (TorC) (Former)	Montes	T13S R4W S22	T or C/Elephant Butte	Sierra	33.16299	-107.23230	30	NO3, Cl, Mn	12-24'	S-SE	GW	CAR 1203.A	Site Investigation/Property Transfer
Tucumcari Landfill	Unassigned	QR65 and Qr Ap	Tucumcari	Quay	35.20238	-103.73520	15	PCE, TCE	70	NW	Soil and GW	CAR 1203.A	Needs further assessment
Tucumcari Power Plant (Xcel Energy)	Unassigned	301 W. Railroad Ave.	Tucumcari	Quay	35.17913	-106.72656	1	diesel	37	NW	GW	Stage 2 AP	LNAPL Recovery, MNA for dissolved plume
Union Pacific Alamogordo	Montes	S. of Lawndale and 8th St.	Alamogordo	Otero	32.89618	-105.96573	25	Creosote, PAHs DNAPL	45	W-SW	Soil and GW	Stage 1 AP SI	Semi-Annual Monitoring
UNM well 5	Ball	UNM Main Campus	Albuquerque	Bernalillo	35.08403	-106.61803	20	TCE	300	N-NE	GW	Voluntary Stage 1	Semi-Annual Monitoring
USDA Forest Service, Shuree Ponds	Unassigned	Valle Vidal Unit, Carson National Forest	Shuree Ponds	Colfax	36.77097	-106.19420	25	diesel (iron and manganese)	5-10	E-SE	GW	Stage 1 AP SI	Annual monitoring
Veguita, Abo Valley	Ball	Wheeler Rd. and St.Rd 304	Socorro	Socorro	34.52008	-106.75120	>100	nitrate	45	S	GW	No RP identified, ORPHAN SITE - INACTIVE	Monitoring of Orphan Plume

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites - Update 9/9/16

Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the Water Quality Control Commission Regulations, 20.6.2 NMAC.

Abbreviations: "1203.A" = Section 20.6.2.1203.A Spill Notification and Corrective Action, NMAC; "AP" = Abatement Plan 20.6.2.4101-4114 NMAC; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.

Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option
Velarde Fuel Spill (DC Carriers)	Unassigned	Hwy 68 MM 16	Velarde	Rio Arriba	36.1892°N	-105.9789°W	<1 ac	Diesel, BTEX, and PAHs	~15	West/Southwest	Soil	CAR 1203.A	Groundwater monitoring following source removal
Walker AFB	Montes		Roswell	Chaves	33.30756	-104.51775	>2,000	TCE	40-120	E	Soil and GW	DOD Potential Responsible Party	NMED is waiting on eventual Federal Court decision for a determination of settlement amount that must precede further assessment of the site for abatement.
Western Terrace	Unassigned	Powers Way and Murchenson	Albuquerque	Bernalillo	34.97418	-106.72931	50	nitrate	70-120	S-SE	GW	No RP identified ORPHAN SITE - INACTIVE	Probable source is septic tank/drain fields or former dairy
Brake Masters - Juan Tabo	Ball	1200 Juan Tabo NE	Albuquerque	Bernalillo	35.09226	-106.51471	<1	hydraulic oil	750	W	Soil	CAR 1203.A	Assessment required