

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites													Last update on 2/8/16	
Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the Water Quality Control Commission Regulations, 20.6.2 NMAC. Abbreviations: "1203.A" = Section 20.6.2.1203.A NMAC; "AP" = Abatement Plan; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.														
Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option	Comments
ACME Hometown Cleaners (Former)	Montes/Kilgore	901 E. 10th St.	Alamogordo	Otero	32.90019500	-105.95112200	unknown	PCE, TCE	55-60	SW	soil, GW	CAR 1203.A	Soil vapor & GW monitoring.	Letter sent in January 25, 2016 notifying of vapor intrusion concern. RP may submit a voluntary AP or enter VRP.
Alameda & Main PCE	Montes	Alameda and Main St.	Las Cruces	Doña Ana	32.30347800	-106.77799800	unknown	PCE	40	S-SE	GW	No RP identified	Soil vapor monitoring	Working with Superfund on source.
Alpine Lumber (Former)	Kilgore	104 N. 2nd St.	Gallup	McKinley	35.52938600	-108.74315200	10	BTEX	25	NW	Soil and GW	CAR 1203.A	Groundwater Investigation Workplan submitted to NMED for review August 2015. Reassigned to Kilgore 2/1/16. Revisions/Changes requested 2/2/16 and approval to proceed with changes granted via email. Notified via email 2/3/16 of property transfer to City of Gallup in Oct 2015 and workplan no longer requested by Alpine. NMED requested Official Notice of Property transfer from Morrison on 2/3/16 by email in accordance with NMAC 20.6.2.4104.B	
AmeriPride	Montes/Kilgore	515 North Virginia Avenue	Roswell	Chaves	33.39789800	-104.52082300	<5	BTEX, PCE, TCE, cis 1,2-DCE, VC	15-20	E/NE	soil and GW	Stage 2 AP	Monitoring wells installed and sampled. Shallow GW affected PCE above Sid. One-time insitu treatment performed via injection. Additional treatment needed to complete reaction pathway and off-site investigation also requested. Requested vapor and GW pathways and receptor information from RP.	Most apparent contamination is accumulation of turbine oil (TPI) on groundwater from Old Ameripride on-site water supply well. One-time injection treatment of PCE in GW resulted in reduced PCE, but cis 1,2-DCE and VC remain in GW with off-site migration observed in one monitor well. Request for modified Stage 2 AP sent 1/22/16 to address remaining constituents of concern. AmeriPride response is due April 1, 2016. Transferred from Ball to Montes 2/1/16.
Anthony Water and Sanitation District WWTP	Montes	4th Street	Anthony	Doña Ana	32.02185900	-106.60025700	4	nitrate, TDS	55	SW	GW	CAR 1203.A	DP-450	
ATA Montoya (T4 Ranch) Valero	Ball	Montoya, NM & interstate 40	Montoya	Quay	35.12715000	-104.07488056	30-70	refined petroleum - all types	20	E	GW	CAR 1203.A	LNAPL recovery and MNA	Semi-Annual Sampling and reporting to NMED.
BNSF Albuquerque	Kilgore	Between Copper and Iron, 1st and Edith	Albuquerque	Bernalillo	35.08051500	-106.64805100	54	diesel	35	east	soil and GW	Stage 1 AP	Stage 1 Abatement Plan Modification approved by NMED 9/1/04 and Second Modification Approved 4/24/2006. 08/28/14 Workplan for Adh Wells approved by NMED on 9/12/14.	Performing semi-annual GW Monitoring at Fueling Area. Transferred to Kilgore 2/1/16.
BNSF Belen Fueling Facility	Ball/Kilgore	106 N. 1st St.	Belen	Valencia	34.65448333	-106.76809722	>100	diesel	5 to 15	S	soil, GW	Stage 2 AP & CARs	> 90 MWs, LNAPL recovery trenches and wells, MNA for dissolved constituents. DP-278 for evap lagoons to receive sump wastewater. DP-1715 for injection wells to receive extracted ground water for LNAPL recovery.	Fen 2000 Stage 1 and 2 AP Approval by NMED. 5 large LNAPL plumes. 600,000 gallons recovered with wells and interceptor trenches by 2015. 120 monitoring wells. Dissolved plume is being addressed via MNA. Regulation began in 1992. Abatement plan modifications include dewatering LNAPL recovery system, installation of new LNAPL recovery wells and trenches and injection and extraction wells. Semi-Annual GW Monitoring dissolved phase (wells wo LNAPL) for 5 wells on Marquez Property, 3 on BNSF property.
BNSF Clovis	Kilgore	Main Street, Clovis, New Mexico	Clovis	Quay	34.39589167	-103.20850556	500	diesel	300	S-SE	soil and GW	Stage 2 AP	LNAPL recovery through 4 wells & DAF operation. Annual reports provided for Abatement activities. Up to 7 feet of free product on groundwater.	>10 million gallons diesel recovered over more than 15 years operation. Annual reports provided for Abatement activities. Annual recovery for 2015 - 18,000 gallons of diesel. Transferred to Kilgore 2/1/16.
BNSF Gallup	Kilgore	811 Roundhouse	Gallup	McKinley	35.52603889	-108.75312222	>25	diesel	7	NE	soil, GW	Stage 2 AP	~25 MWs, LNAPL recovery trenches and wells, MNA for dissolved phase.	Stage 2 Abatement Plan Monitoring Program Modification approved by NMED June 26, 2015. Transferred to Kilgore 2/1/16.
Cal Main Eggs	Ball	9615 Broadway SE	Albuquerque	Bernalillo	34.95480700	-106.66738600	25	nitrate	20-75	S-SW	soil and GW	Stage 2 AP	MNA proposed	FSIR approved 10/24/2014. PN on S2 proposal closed 4/30/15. Revised proposal expected based on prospective purchaser's redevelopment plans. Site being sold with new buyer planning enter into VRP in early 2016.
Chava Trucking	Ball	6313 St. Rd. 47 (6020 Industrial Way) SE	Albuquerque	Bernalillo	34.99354722	-106.66135833	15	petroleum hydrocarbons	40-65	E	soil and GW	Settlement Agreement	Excavation, soil investigation.	Admin Compliance Order issued April 24, 2008. Settlement Agreement 9/13/2011. MWs never installed, but RP in bankruptcy. Nearby Mt. View MWs indicate no ground water contamination.
Comet 1 Cleaners	Ball/Kilgore	2810 East 20th Street	Farmington	San Juan	36.7485972	-108.1687972	3.00	PCE	25.00	S	GW	Stage 2 AP	Enhanced in-situ bioremediation	Second round of HRC® injected Feb. 2009
Conoco Phillips (AST) Bernalillo, NM	Ball	Calle Duranes and railroad tracks	Bernalillo	Sandoval	35.30600000	-106.54664167	1	gasoline	7	SW	GW	Stage 2 AP	LNAPL recovery. MNA in GW.	Only Mn remaining. Conoco likely to propose TI by end of 2016.
ConocoPhillips South (formerly Phillips Pipeline)	Ball	6356 State Rd. 47	Albuquerque	Bernalillo	34.99101944	-106.65957222	10	diesel, BTEX, EDC	80	E	NA	Admin Compliance Order	Remediation ongoing	SVES installed in mid 2010 for jet fuel spill has been shutdown. EDC plume being addressed with ISCO pilot test
Crop Production Services (former Agriliance), Artesia	Montes	103 E. Mill Road	Artesia	Eddy	32.86853800	-104.39869200	3.5	nitrate	24	SE	soil and GW	Stage 2 AP	soil excavation, 2-year Pilot Study with Qtrly GW monitoring for 1 year.	liquid fertilizer distribution facility. Stage 2 Abatement Plan approved by NMED on 1/9/2015.
Crop Production Services (former Agriliance), Vado	Montes	8601 Hwy. 478	Vado	Doña Ana	32.11561400	-106.66533900	2	nitrate	9.00	SE	soil and GW	Stage 2 AP	soil excavation, GW monitoring	
Crop Production Services (former UAP), Vado	Montes	8524 Highway 478	Vado	Doña Ana	32.11475560	-106.53331110	2.6	nitrate, TDS	10	SE	soil and GW	Stage 2 AP	soil excavation, GW monitoring	
Cuba Solvents	Ball	Main Street and Salazar	Cuba	Sandoval	36.01634400	-109.96218600	unknown	PCE, TCE	28	S-SW	GW	No RP identified	Not under Abatement Plan or CAR	Suspected source now seems unlikely, refer to SOS
Cumbres & Toltec R.R.	Ball/Kilgore	500 S. Terrace Ave.	Chama	Rio Arriba	36.90079700	-106.57825500	<5	petroleum hydrocarbons, solvents	unknown	unknown	Soil	CAR 1203.A	Site Investigation under CAR	Preliminary soil samples collected indicate soil contamination
Diamond Shamrock Endee	Ball	Endee New Mexico	San Jon	Quay	35.21526944	-103.23739444	4	diesel	25	SE	GW	Stage 2 AP	LNAPL recovery and MNA	
Diamond Shamrock, Tucumcari	Ball	3.5 miles E-NE of Tucumcari	Tucumcari	Quay	35.20498056	-103.65754444	13	gasoline & diesel	13-70	SW	soil and GW	Stage 2 AP	Monitored Natural Attenuation	
Downs RV Park	Kilgore	5701 U.S. Hwy 64	Farmington	San Juan	36.70272900	-108.10488500	unknown	TDS, chloride, nitrate	30	S-SW	GW	CAR 1203.A	Workplan for Site Investigation	Referred from PPS (DP-958). County notified 5/8/2015 of 1203 requirements. Site visit 6/11/2015. Work plan approved on 12/11/2015 for installation of monitoring wells. Well installation initiated in 2016. Transferred to Kilgore 2/1/16.
Dry Cleaners, Clayton	Ball/Kilgore	20 Peach Street	Clayton	Union	36.45502700	-103.18734100	<5	PCE, BTEX	40-45	S	Soil and GW	No viable RP	Monitoring	Need soil vapor survey
Dunn Edwards Paint	Ball	215 Rosmore Rd., SW	Albuquerque	Bernalillo	35.030661	-106.66038900	3	toluene, xylene	12	E	soil and GW	CAR 1203.A	Site Investigation under CAR	4/18/2015 CA approved by NMED. CAR Soil and Groundwater Sampling Report for installation of additional borings dated December 18, 2015 received by NMED January 14, 2016 by NMED and under review.

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites													Last update on 2/8/16	
Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the Water Quality Control Commission Regulations, 20.6.2 NMAC. Abbreviations: "1203.A" = Section 20.6.2.1203.A NMAC; "AP" = Abatement Plan; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.														
Site Name	Project Manager	Site Address	City/Town/County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option	Comments	
El Paso Electric Co., Rio Grande Power Plant, Sunland Park	Montes	3501 Doniphan Road	Sunland Park	Doña Ana	31.80440000	-106.54647778	unknown	fuel oil, diesel	7	S	soil and GW	Stage 1 AP, Abatement Completion In Progress	soil excavation completed, GW monitoring completed in January 2016. Source removal for source control completed. Biocells with former Discharge Permits (DPs) were terminated. Obtained 8 quarters of data meeting standards. Abatement Completion Report requested by NMED mid-January 2016. Due in 60 days. Mn is above standards up gradient of site under background conditions.	
(Former) BLM Landfill, Las Cruces	Montes	Roadrunner Pkwy. & E. Lohman	Las Cruces	Doña Ana	32.21313889	-106.72907500	unknown		180	W	unknown	CAR 1203.A	investigation	City of LC, City of ABQ, and BLM are in negotiations over liability.
(Former) BLM Landfill, T or C	Montes	T13S R4W S22	T or C/ Elephant Butte	Sierra	33.16299300	-107.23229700	30	Manganese, TDS, potential landfill leachates	12	E-SE	GW	CAR 1203.A		BLM is trying to transfer land to City of TorC.
(Former) Chevron Bulk Fuels Terminal	Ball	3200 Broadway SE	Albuquerque	Bernalillo	35.04656000	-106.64610800	9	petroleum hydrocarbons	25	east	soil and GW	Hydrocarbon Remediation Agreement - Unilateral Administrative Order (AOC) 1997, 2013 Remedial Action	Monitored Natural Attenuation (MNA) Evaluation NMED Approval 09/2014. Semi-annual GW monitoring. MNA evaluation of effectiveness. MNA began 04/2013. The MNA document recommended semi annual monitoring and was approved by NMED.	
DeGraaf/Wholesome Dairy (Former)	Montes	Acosta Rd and I-10	Anthony	Doña Ana	32.01616667	-106.59030560	unknown	nitrate, Cl, TDS	46-116	SW	soil and GW	Stage 1 AP	Stage 1 Abatement plan dated 06/14/2013 approved by NMED on September 10, 2013. Sampling 9 monitoring wells on a semi-annual basis.	
Digital/Compaq/HP (Former)	Ball/Kilgore	5600 Jefferson NE, Albuquerque, NM	Albuquerque	Bernalillo	35.14318333	-106.59482500	50	TCA, DCE	170-250	SE	GW	Admin Order Consent (AOC)	Closed GW pump & treat system. Active GW monitoring. Vapor Intrusion (VI) assessment discussed with RP in January 2016. P&T system operated 1998 - 2009. SVE performed at site in vicinity of former sump on south side of building. Cleanup std DCE = 7 ppb. 7/15/2015 proposal for technical infeasibility under review by NMED. NMED is requesting assessment for Soil Vapor Intrusion (VI).	
Fox & Associates	Ball	Bryn Mawr St. Albuquerque, NM.	Albuquerque	Bernalillo	35.12080278	-106.60924444	1	TCE	50-220	E	soil and GW	Stage 2 AP	Regional GW is clean. Perched zone is contaminated. 5 regional MWs, 1 perched MW. SVES operated March 2009-2012. Soil Vapor Extraction reduced concentrations in the perched groundwater for dissolved-phase. Additional Vapor Intrusion (VI) assessment will be requested by NMED.	
Gulton Industries	Ball	14800 Central Avenue SE	Albuquerque	Bernalillo	35.06375000	-106.48549444	10	TCE	20-120	E	GW	Consent Decree	In-situ bioremediation with injection of HRC® under Discharge Permit. Fractured Bedrock. Bankruptcy with consent Decree. DP for injection.	
Helena Chemical, Lake Arthur	Montes	504 Lake Arthur Hwy.	Lake Arthur	Chaves	32.93167500	-104.38724722	3	nitrate, TDS	20-25	E	soil and GW	Stage 1 AP	Stage 1 Abatement Plan Mod Approved by NMED on 3/6/2015. Stage 2 Plan approved by NMED 12/18/2015.	
Helena Chemical, Mesquite	Montes	251 John Grisham Drive	Mesquite	Doña Ana	32.16449444	-106.69751944	14	nitrate, TDS	10	S	soil and GW	Stage 2 AP	Enhanced bioremediation with soil excavation/source removal	
Holly Energy, Artesia	Montes	US 82 (3 miles E. of Artesia)	Artesia	Eddy	32.84234722	-104.35640000	1	gas, diesel, jet fuel	8	SE	soil and GW	Stage 2 AP	soil excavation, mobile dual-phase extraction, hyd. peroxide injection, GW monit.	
Hooter Browns, Raton	Ball/Kilgore	931 Clayton Road	Raton	Colfax	36.88546400	-104.42839300	<5	chlorinated solvents	25	S-SE	Soil and GW	Stage 1 AP INACTIVE	Needs further assessment	RP is bankrupt, sold property w/o notification required by 4014B. Former operator left state
Hwy 17 Tanker Truck Spill	Ball/Kilgore	Hwy 17,	Chama	Rio Arriba	36.99004800	-106.50508100	1	gasoline & diesel	unknown	unknown	Soil	CAR 1203.A	Soil removal and disposal.	7,900 gals released. Transferred from leather to burt now to Justin.
Karler Packing (Former)	Ball	9151 Broadway SE	Albuquerque	Bernalillo	34.96129400	-106.66127300	50	nitrate	65	SE-E	GW	Stage 1 AP INACTIVE	Needs further assessment	RP went bankrupt, property transferred due to wrongful death settlement and was recently in jeopardy of back taxes sale. Prospective purchaser may enter VRP.
KAFB Nitrate Plumes	SCP Leader/McQuillan	Near Wyoming and Randolph, Kirtland Air Force Base	Albuquerque	Bernalillo	35.04956389	-106.56965000	200	nitrate	250-550	various	GW	Stage 2 AP	Stage 2 AP approved by NMED in 2007. Site contains 3 plumes; 1 perched and 2 in regional aquifer. Nitrate concentrations in GW in 2014 report between 0.22 and ~79 mg/l. Bulk Fuels treated water now being injected into KAFB 7. Modified abatement plan needed for cessation of use of KAFB 7 and current reliance on MNA. Contamination Site Investigation Report received by NMED in 2014. Long term monitoring plan also received in 2014. Modified abatement plan will be required.	
La Bajada Mine	Ball/Kilgore	Santa Fe River Canyon, La Bajada Hill	La Bajada	Santa Fe	35.54944167	-106.20791944	20	sulfate	10-300	S	soil and GW	CAR 1203.A	USFS is responsible to determine continued impacts	City owns the land. NMED to check with DWB on nitrate levels in City's production wells. Consider requiring action of new owner.
Ladshaw	Montes	0.7 mi W-SW of Hwy 18 on W Hiap Entrance Rd.	Hobbs	Lea	32.76321200	-103.19792700	30	nitrate	60	SE	GW	Settlement Agreement - INACTIVE	Stage 2 AP approved by NMED in 2007. Apparent denitrification. RP performed monitoring but went bankrupt in 2005, sold to new owner. Monitoring ceased.	Dry Cleaner supply company operated since 1959. Workplan has been approved for assessing neighborhood properties for vapor intrusion (VI). Obtaining consent forms from residents is in process with vapor sampling scheduled to commence in 2/2016.
Laun-Dry Company, Inc	Ball/Hunter	1500 12th St NW, Albuquerque, NM	Albuquerque	Bernalillo	35.10255556	-106.65795833	>5	PCE, TCE	35	E	soil and GW	Stage 1 AP	Groundwater plume with PCE and TCE. 34 MW installed; site investigation is in progress to define and characterize the site. Stage 1 Abatement Plan Approval for Vapor Intrusion and Indoor Air Work Plan approved by NMED 12/14/2016.	
Lee Ranch Coal Mine	Ball	Aprox 9 miles N from 192 Rd and Rd 556	Grants	McKinley	35.50401000	-107.64556600	3	diesel	unknown	unknown	soil	Stage 1 AP	LNAPL perched on clay layer above GW. LNAPL recovery ongoing. 4 gallons of diesel removed in 2015. No pumpage occurred in 2nd half of 2015. Semi-annual sampling.	Semi Annual Abatement Report received for July 15, 2015 and December 29, 2015 and assigned to Justin Ball for review. Review comments and status update to SCP due 2/29/16.
Los Angeles Landfill	Ball	Paseo Del Norte and North Diversion Channel	Albuquerque	Bernalillo	35.18118333	-106.78078056	200	VOCs	120	E-SE	soil and GW	Voluntary Stage 2 AP	Dissolved phase pump and treat, SVE, air sparging.	Difficulties encountered with GW injection wells. City rehabilitating and replacing existing wells for added injection capacity.
Loving Salt, Malaga	Montes	1624 Pecos Highway	Malaga	Eddy	32.22520000	-104.07202778	unknown	TDS, Cl	17	S	soil and GW	Stage 1 AP	soil excavation, GW monitoring	Request to suspend Stage 1 AP has been received; suspension of AP is pending application and acceptance into VRP.
McAnally Enterprises, Berino	Montes	415 San Benito Rd.	Berino	Doña Ana	32.07220278	-106.62200560	239	nitrate, chloride, TDS	20-60	SE	soil and GW	Stage 2 AP	soil excavation, GW monitoring	Site has been sold & new owner is considering VRP.
McCatharn Dairy	Kilgore	6363 St. Rd 47	Albuquerque	Bernalillo	34.98839900	-106.65918300	25	TDS, chloride, nitrate	80	E-SE	soil, GW	Stage 1 AP FSIR	Stage 2 proposal in development.	NOV followed by dispute resolution and letter of agreement. Monitor wells installed as agreed. FSIR and initial Stage 2 proposal received Dec 2, 2015. FSIR deficiency letter sent 1/22/16. Extension granted until June 1, 2016 for Revised FSIR and Stage 2 proposal.

New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites														Last update on 2/8/16	
Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the Water Quality Control Commission Regulations, 20.6.2 NMAC. Abbreviations: "1203.A" = Section 20.6.2.1203.A NMAC; "AP" = Abatement Plan; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.															
Site Name	Project Manager	Site Address	City/Town/County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option	Comments		
Mesa Oil	Ball	20 Lucero Rd.	Belen	Valencia	34.59728900	-106.73192000	5	petroleum hydrocarbons	80	S	soil	CAR 1203.A	Under 2010 ACO	2010 ACO can be closed; being left open pending HWB actions upon stormwater pond found with waste oil present in Feb 15	
Mt. View Nitrate plume	Ball	2nd St. and Tijeras Arroyo	Albuquerque	Bernalillo	35.00242778	-106.66257778	>500	nitrate	40-120	E	soil, GW	ONRT project	In-situ bioremediation pilot study	ONRT is funding remediation of plume, NMED will monitor site following end of contract.	
NMDOT District 4 Service Center	Ball/Kilgore	I-25 Frontage Rd, MP 344	Las Vegas	San Miguel	35.56902900	-105.22470500	>100	TCA, DCE, TDS, chloride, BTEX, MTBE	15-40	SE	Soil and GW	Stage 2 AP	Recovery trench, RO treatment, re-injection	BTEX treatment, no action on TDS	
NMDOT La Cueva Patrol Yard	Ball/Kilgore	NM 518, MP 23.6	Las Vegas, Mora Co.	Mora	35.93458000	-105.25272900	<50	TDS, chloride	5-30	SW	Soil and GW	Stage 2 AP	Source removal, MNA	Salt pile containment, evaporation pond construction ongoing	
NMDOT Main Yard.GOC	Kilgore	1120 Cerrillos Road	Santa Fe	Santa Fe	36.67409200	-105.95727000	5	PCE, TCE	350	unknown	soil	CAR 1203.A	Monitoring completed. GW well plugged. Next steps under development. 1203 Request sent 12/4/15 by NMED for Vapor Intrusion. Extension granted until 3/25/16. DOT provided additional information and requested reports for neighboring properties which were provided in Jan 2016 with additional info in 2/2016. Searching for source of halogenated compounds in SV and excavation of UST after sprinkler malfunctioned and flooded excavation.	1203 Request sent 12/4/15 by NMED for Vapor Intrusion. Extension granted until 3/25/16. DOT provided additional information and requested reports for neighboring properties which were provided in Jan 2016 with additional info in 2/2016. Searching for source of halogenated compounds in SV and excavation of UST after sprinkler malfunctioned and flooded excavation.	
NuStar Albq Terminal	Ball	6738 St. Rd. 47	Albuquerque	Bernalillo	34.99199065	-106.6570966	15	diesel, turbine and jet fuels	100	E-SE	GW	Stage 2 AP	LNAPL recovery and MNA		
NuStar Energy Pipeline Terminal	Montes	6026 Hwy 54 South	Alamogordo	Otero	32.81379722	-105.97729170	unknown	petroleum	70	S-SE	soil and GW	Stage 2 AP	Assessment and remediation ongoing	RP is installing additional downgradient well and pilot testing LNAPL recovery.	
One Hour Martinizing, Santa Fe	Kilgore	1091 St. Francis Dr.	Santa Fe	Santa Fe	35.67431400	-105.95356200	<10	PCE	60-70	S	Soil and GW	1999 Workplan/Voluntary Abatement	RP's consultant monitoring performed 2000-2006. NMED results 2007. Stage 1 CAP or VRP application required.	Initial Groundwater Monitoring and SV testing performed 1999-2003. Stage 1 Abatement Plan CAP or VRP application is required. Assigned to Kilgore 12/31/16. File review completed 2/4/16 by Kilgore. VI is concern based on concentrations as is GW with off-site detections to S/SE (100 ug/l PCE in 4/2015). Contacting RP in February 2016 to renew activities.	
Ortiz Landfill (Former)	Kilgore	Camino de las Cruces and Buckman Road	Santa Fe	Santa Fe	35.69644444	-105.96433333	unknown	nitrate, VOCs	360	SE	soil and GW	Stage 1 AP	Geophysical survey, ground water monitoring. Needs further assessment.	Assessed landfill limits via geophysical methods. Modified SIAP proposal is past due. Assigned to Kilgore 01/31/16.	
Plains Electric/PNM, Algodones	Ball	1500 State Highway 313	Algodones	Sandoval	35.38441700	-106.46454400	45	manganese, TDS, sulfate	30-40	W-SW	GW	CAR 1203.A	Monitoring on a 5 year basis		
PNM Gen. Station, Lordsburg	Montes	#2 Power Plant Rd.	Lordsburg	Hidalgo	32.34968056	-108.70873060	22	metals	100	unknown	GW	Stage 1 AP	Monitoring		
Prewitt Pit	Ball	Off I-40 between Grants and Thoreau. T 13N 11W Sec 34.	Prewitt	McKinley	35.3123257	-107.98518800		unknown	190		soil	CAR 1203.A	Notification of discharge sent 5/21/15 regarding alleged buried drums.	owners and operators contesting responsibility. Under legal review.	
Prices Dairy (Former)	Ball/Kilgore	618 NM Highway 528	Bernalillo	Bernalillo	35.31506500	-106.57204100	50	TDS, chloride, nitrate, sulfate	25 and 85	E-SE	GW	Stage 2 AP	Surface soil remediation completed under VRP. Groundwater extraction performed. Alternative abatement standards proposed.	45 acft of water has been extracted and is basis of alternative abatement request submitted to NMED 2/1/16.	
Quality Laundry, Bernalillo	Ball	107 Calle Del Presidente, Bernalillo, New Mexico (Site)	Bernalillo	Sandoval	35.30547778	-106.54777500	3	PCE	6	SW	GW	Stage 1 AP	MNA	Monitoring Program revised 9/16/2014 - standards may be achieved with 8 quarters. S2 never proposed.	
Rek Chem	Ball	105 Dale St., SE	Albuquerque	Bernalillo	35.00298056	-106.66074167	3	TCE	55	E	GW	Stage 1 AP	4 MWs, more assessment required.	Low priority, given low levels and RP refusal. Continue monitoring 2 Mt. View wells annually for VOCs.	
Roadrunner Laundry	Ball	512 Courthouse Rd.	Los Lunas	Valencia	34.80137500	-106.73296389	<1	PCE	5	S-SE	soil and GW	Stage 1 AP halted: Completion of Abatement Possible INACTIVE	5 MWs, GW sampling performed by NMED in 2007 and 2011. Abatement Completion may be possible if 8 Qtrs of samples collected.	Owner stopped monitoring in 2011 when property sold. SCP sampled groundwater in 2008 and 2011. 8 qtrs of sampling below standards required for abatement completion determination	
Salome Property	Ball	327 McCutcheon	Socorro	Socorro	34.05544800	-106.89531200	<1	PCBs	unknown	unknown	soil	CAR 1203.A	Soil removal and disposal.	Soil is stockpiled, but no final CAR on disposal.	
San Juan Springs Company	Kilgore	409 East Broadway	Farmington	San Juan	36.72818900	-108.201400	<5	chromium, metals, petroleum hydrocarbons	10-12	S	soil and GW	Stage 2 AP	In-situ bioremediation and MNA.	Sister site at 1516 West Main St. in Farmington	
Santa Fe Railyard/ConocoPhillips/La Unica Dry Cleaners	Ball/Kilgore	769 Cerrillos Road	Santa Fe	Santa Fe	35.67884200	-105.95095200	<50	PCE	70-130	E	GW	Stage 1 AP	Needs assessment	Issue a NOD to LaUnica owners (former operators, current owner)	
Santa Fe Well, PNM	Kilgore	Baca Street and Cerrillos Vicinity	Santa Fe	Santa Fe	35.67542600	-105.96139000	5	VOCs	90	SE	GW	PTSB MOU	Petroleum isosotes to be addressed under a 12/22/15 MOU between PNM and NMED PTSB. GWB letter to be sent regarding nitrates.	Two decade old settlement agreement dissolved with new 12-22-15 MOU. Technical Advisory Group (TAG) also dissolved. Petroleum issues to be addressed by PSTB and CAF. Investigation will include full 8260 (chlorinated solvents included in analytical methods). Nitrate discharge occurred during active DP.	
Shell Truck Stop (AST) Tucumcari	Ball	Eastern I-40 Tucumcari Exit	Tucumcari	Quay	35.15787222	-103.77209167	<3	petroleum hydrocarbons	20	NE	unknown	CAR 1203.A	Needs further assessment	NOV issued, ACO was drafted in 2010, did not go out.	
Sierra Vista Growers, La Mesa	Montes	12701 Hwy. 28	La Mesa	Doña Ana	32.08773056	-106.68566940	unknown	nitrate	10	unknown	unknown	CAR 1203.A	GW monitoring.		
Spartan Technologies	Ball/Kilgore	7701 Coors Road NW, Albuquerque, NM.	Albuquerque	Bernalillo	35.18955278	-106.66187222	500	TCE, chromium	90-220	W-NW	soil and GW	Consent Decree	Ground water pump and treat.	HWB is lead.	
Texas Bulk Fuels Terminal (Former)	Ball	3209 Broadway SW, Albuquerque, NM	Albuquerque	Bernalillo	35.04603333	-106.64811944	50	diesel, gasoline	20-60	E	soil and GW	Hydrocarbon Remediation Agreement Terminated	Soil Vapor Extraction System (closed), ground water pump and treat completed. Compliance monitoring completed.	Final termination document has been sent to Chevron for this site in January 2016. This agreement is to be signed by both Chevron and NMED.	
TLC Dry Cleaner	Ball	230 E. Reinken	Belen	Valencia	34.66099444	-106.76421944	3	PCE	5	S	GW	Stage 1 AP	Natural attenuation has addressed PCE. cisDCE remains.		
Travel Centers of America, Moriarty	Ball	1700 U.S. Route 66 West	Moriarty	Torrance	35.00770800	-106.06563300	23	Diesel	70	unknown	Soil	CAR 1203.A	Source Removal - Excavate and Haul impacted soil for offsite disposal.	RP submitted CAR's and plan to line secondary containment around site AST. CAR approval letter to be drafted holding RP to excavating impacted soil beneath and immediately adjacent to AST left in place.	
Tucumcari Landfill	Ball	QR65 and Or Ap	Tucumcari	Quay	35.20238100	-103.73520000	15	PCE, TCE	70	NW	soil and GW	CAR 1203.A			
Tucumcari Power Plant (Xcel Energy)	Ball	301 W. Railroad Ave.	Tucumcari	Quay	35.17912778	-106.72655556	1	diesel	37	NW	GW	Stage 2 AP	LNAPL Recovery, MNA for dissolved plume	Downgradient plume delineation not happening due to railroad access issues	
UNM well 5	Ball	UNM Main Campus	Albuquerque	Bernalillo	35.08402778	-106.61803333	20	TCE	300	N-NE	GW	Voluntary Stage 1	Monitoring	Low concentration of TCE, monitoring only.	
USDA Forest Service, Sharee Ponds	Ball	Valle Vidal Unit, Carson National Forest	Sharee Ponds	Colfax	36.77097100	-106.19420000	25	diesel (iron and manganese)	5-10	E-SE	GW	Stage 1 AP	Annual monitoring		
Veguita, Abo Valley	Ball	Wheeler Rd. and St.Rd 304	Socorro	Socorro	34.52008333	-106.75120278	>100	nitrate	45	S	GW	No RP identified	Monitoring of Orphan Plume	Orphan plume. NMED has been sampling groundwater wells in the area periodically. Sampled in 2008 and 2010.	
Union Pacific Alamogordo	Ball to Montes	S. of Lawndale and 8th St.	Alamogordo	Otero	32.89618000	-105.96573300	25	Creosote, DNAPL	45	W-SW	soil and GW	Stage 1 AP	Additional Assessment needed	RP terminated from VRP in 2010, RP is sampling 2 MW's Semi-Annually. Transferred to Montes 2/1/16.	

**New Mexico Environment Department - Ground Water Quality Bureau - State Clean Up Program (SCP) Sites**

*Last update on 2/8/16*

Investigation and remediation at the listed sites is overseen by staff in the Remediation Oversight Section under the authority of the Water Quality Control Commission Regulations, 20.6.2 NMAC.  
 Abbreviations: "1203.A" = Section 20.6.2.1203.A NMAC; "AP" = Abatement Plan; "GW" = ground water; "RP" = responsible party; "VOC" = volatile organic compounds.

Site Name	Project Manager	Site Address	City/Town/	County	Latitude	Longitude	Size (acres)	Contaminant(s) of Concern	Depth to Water (ft)	Flow Direction	Media Impacted	Regulatory Status	Assessment or Abatement Option	Comments
(DC Carriers) Velarde Fuel Spill	Kilgore	Hwy 68 MM 16	Velarde	Rio Arriba	36.1892°N	-105.9789°W	<1 ac	Diesel, Unleaded Gas	-15	West/Southwes	Soil	CAR 1203.A	Source removal appears 90% complete. Assessing options for further removal or in situ treatment for 2 remaining areas: 1 in north swale, 1 along west shoulder. Soil Vapor ND. GW ND at river terrace.	RP plans to complete activities under CA 1203 if possible. Source removal actions had conflict with Fiber Optic Line and cobbles and boulders, resulting in inability for RP to complete source removal. Plan of action pending as of 1/22/16. LMH Requested extension of CAR submittal. Date proposed by LMH for submittal of either interim CAR or final CAR was requested back by NMED on 2/2/16.
Walker AFB	Ball		Roswell	Chaves	33.30755900	-104.51775300	>2,000	TCE	40-120	E	soil and GW	DOD PRP	As of 1-2016 NMED is waiting on a pending Federal Court decision for a determination of settlement amount that must precede further assessment of the site for abatement.	USACE has investigated site under PRP process. City of Roswell will be left with liability following judgement of court, when NMED will begin regulation of site. USACE conducted grab ground water sampling to vert and horizontally delineate TCE plume. 139 samples collected.
Western Terrace	Ball	Powers Way and Murchenson	Albuquerque	Bernalillo	34.97418333	-106.72930556	50	nitrate	70-120	S-SE	GW	No RP identified	Probable source is septic tank/drain fields or former dairy	